3810 W 81st Pl Chicago, IL 60652

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1954	2	70,461	\$5,040,441
2-Classroom Modular	1997	1	3,402	\$83,348
2-Classroom Modular	1997	1	3,402	\$93,083
2-Classroom Modular	1999	1	3,402	\$78,588
2-Classroom Modular	1999	1	3,402	\$91,730
SITE				\$435,683
Campus Total			84,069	\$5,822,874

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	e						
	Entrance Control - Audio and Video	1	1	EA	5	\$1,567	monitor not working
	Exterior Doors - Exterior Steel Door	1	3	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	2	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	3	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	5	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	6	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	8	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	4	3	EA	5	\$4,024	
	Exterior Doors - Exterior Wood Door	7	1	EA	4	\$3,823	deteriorated
	Exterior Doors - Exterior Wood Door	9	1	EA	5	\$1,341	
	Exterior Doors - Side lite	6	2	EA	6	\$627	
	Exterior Doors - Transom Lite	1	3	EA	6	\$940	
	Exterior Doors - Transom Lite	2	3	EA	6	\$940	
	Exterior Doors - Transom Lite	4	3	EA	6	\$940	
	Exterior Doors - Transom Lite	6	4	EA	6	\$1,253	
	Exterior Stairs - Concrete	5	60	LF	6	\$4,906	

3810 W 81st Pl Chicago, IL 60652

Building: Main

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand		Location	Quantity	Oilit	Italik	COSI	Comments
Lilliand	Exterior Stairs - Concrete	6	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	8	65	LF	6	\$5,315	
	Exterior Stairs - Concrete Exterior Stairs - Steel or Aluminum	2	2	LF	4		crack
	Exterior Stairs - Steel or Aluminum Exterior Stairs - Steel or Aluminum	7	12	LF	6	\$46	Clack
	Exterior Stairs - Stone	1	144	LF	6	\$16,270	
	Exterior Stairs - Stone	2	58	LF	6	\$6,553	
	Exterior Stairs - Stone	3	16	LF	5	\$4,339	
	Exterior Stairs - Stone	4	72	LF	5	\$19,524	
	Ramp Handrail - Steel_Ramp Handrail	3	72	LF	5	\$763	
	Ramps - Concrete	3	33	LF	5	\$17,543	
	Stair Handrail - Steel_Stair Handrail	1	16	LF	7	\$17,545	
	Stair Handrail - Steel_Stair Handrail	4	4	LF	6	\$35	
	Stair Handrail - Steel_Stair Handrail	7	12	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	8	28	LF	6	\$243	
	Stall Hallurali - Steel_Stall Hallurali	0	20	LI	O	Ψ243	
Founda	tion						
	Foundation - Concrete	Entire Building	1,097	LF	7	\$0	
	Foundation - Concrete	Entire Building	20	LF	7	\$0	seepage per building engineer
	Superstructure - Steel with Clay Tile Arch	Entire Building	70,461	SF	7	\$0	
Lightin	a						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	19	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building	2	EΑ	6	\$577	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	\$0	
Roof S		Ŭ					
KOOI S		D.	20			Ф20 ГГ 0	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	В	32	LF	6	\$30,550	ates and the detectorated contra
	Chimney - Brick Chimney- Concrete/ Mortar Liner	В	8	LF	4	\$45,056	step cracking, deteriorated mortar
	Coping - Metal	A	1,037	LF	6	\$33,306	
	Coping - Stone	В	123	LF	6	\$3,950	
	Downspouts - Interior Downspouts	A	180	LF	6	\$5,982	
	Downspouts - Interior Downspouts	В	54	LF	6	\$1,795	
	Parapet - 16" - 30" Height	В	55	LF	6	\$2,197	
	Parapet - Parapet < 16" Height	A	983	LF	6	\$20,945	
	Parapet - Parapet < 16" Height	В	68	LF	6	\$1,449	
	Parapet - Parapet > 30"	A	54	LF	6	\$3,452	
	Roof Structure - Concrete	A	27,554	SF	7	\$0	
	Roof Structure - Concrete	В	3,402	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	A	27,554	SF	6	\$280,150	



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	rstem						
	Roof - Asphalt Gravel Ballast	В	3,402	SF	6	\$34,589	
	Roof - Modified Bitumen	Α	40	SF	6	\$376	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	688	SF	5	\$69,312	
	Cheek-Wall - Concrete	Entire Building	96	SF	6	\$984	
	Cheek-Wall - Stone	Entire Building	1	SF	4	\$194	cracked
	Cheek-Wall - Stone	Entire Building	119	SF	6	\$1,220	
	Exterior Walls - Brick	Entire Building	12,402	SF	6	\$83,354	
	Exterior Walls - Brick	Entire Building	9,068	SF	5	\$191,656	
	Exterior Walls - Brick	Entire Building	1,200	SF	4	\$197,580	cracked, deteriorated mortar joints
	Exterior Walls - Stone-Cast	Entire Building	2,060	SF	6	\$13,845	
	Exterior Walls - Stone-Cast	Entire Building	200	SF	4	\$36,322	cracked, chipped
Windov	vs.						
	Lintels - Steel	Entire Building	1,353	LF	6	\$39,276	
	Windows - Sash Aluminum Double-pane	Entire Building	8,580	SF	6	\$64,046	
	Windows - Sash Aluminum Double-pane	Entire Building	120	SF	4	\$15,751	inoperable per building engineer

Building Exterior Subtotal:

\$1,279,050

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Mechanical Room / Basement	1	EA	7	\$0	
	Emergency A/C Power - Corridors and Stairs	Entire Building	12,189	SF	6	\$3,660	
	Emergency A/C Power - Gym	Entire Building	2,394	SF	6	\$890	
	Emergency A/C Power - Lunchrooms	Entire Building	1,600	SF	6	\$595	
	Emergency A/C Power - Students Toilets	Entire Building	1,364	SF	6	\$507	
	Emergency Generator- Outdoor- Diesel - Below 60 KW	Courtyard	1	EA	7	\$0	Generac (2007): Mod#:8170520100; 30 KW
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	6	\$2,995	
	Exit Signs - Gym	Entire Building	6	EΑ	6	\$945	
	Exit Signs - Lunchroom	Entire Building	2	EΑ	6	\$299	
	Security System - CCTV	Entire Building	70,461	SF	5	\$55,418	Per engineer, system works well. 2 cameras are down.
	Security System - Intrusion Detection	Entire Building	70,461	SF	5	\$70,531	



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Main Service								
Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	\$0	Siemens (2007); 2000A; 208/120		
PA System	Entire Building	70,461	SF	5	\$48,364	Per engineer, PA system works fine but old		
Power Distribution								
Lighting and Power Panels - 100 A	Entire Building	11	EA	7	\$0			
Lighting and Power Panels - Above 100 A	Entire Building	11	EA	7	\$0			
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	\$0			
Electrical System Subtotal: \$184,205								

Building: Main

Category: Safty System

Group Item - Type	Location	Quantity Unit Ra	ank Cost	Comments
Fire Alarm				
Fire Alarm Panel	Entire Building	1 EA	4 \$49,477	National Time (no date). Panel is greater than 20 years of age and cannot be upgraded.
Fire Alarm Strobe Lights	Entire Building	70,461 SF	4 \$95,721	Strobes not installed in all areas
Fire Alarm_System	Entire Building	70,461 SF	4 \$140,055	Serves main only

Safty System Subtotal: \$285,253

Building: Main

Category: Mechanical System

	or yr moonamour oyotom								
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Air Con	nditioning								
	Condensing Unit- Ground Mounted - 11-20 tons	Courtyard	1	EA	7	\$0	Date not available		
Air Han	Air Handling Systems								
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room / 2nd Floor	1	EA	5	\$24,083	AHU Serves gym; Approx 4800 cfm		
	Air Handling Unit- Built Up- Single Zone- Steam Coils - Less than 4000 cfm	Mechanical Room / Basement	1	EA	5	\$21,278	Serves kitchen; approx 3000 cfm;		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	\$55,649	Approx 30,000 cfm; Bishop and Babcock fan; Serves classrooms in north section of school		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	\$71,321	Approx 38,400 cfm; Serve classes in south section of building; Bishop and Babcock Co		
	Air Handling Unit- Package Single Zone- Outdoor Ground Mounted- Electric and DX Cooling Coil - 4000-8000 cfm	Lower Area	1	EA	7	\$0	Carrier split system; Mod#:40RM-016-B611HK; 4,500cfm		
	Air Intake	Lower Area / Courtyard	1	EA	6	\$5,765			
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765			



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Mechanical System

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	dling Systems	Location	Quantity	Oilit	Ivalik	COSI	Comments
All Hall	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
		Mechanical Room / Roof	1	EA	6		
	Air Intake		•	EA		\$5,765	O eterro esile 40 LID mester
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1		5		2 steam coils, 10 HP motor
	Auxiliaries - 4000 - 8000 cfm	Mechanical Room / 2nd Floor	1	EA	5	\$13,523	0 4 11 40 110 4
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5		2 steam coils; 10 HP motor
	Auxiliaries - Less than 4000 cfm	Mechanical Room / Basement	1	EA	5	\$11,187	
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	2nd Floor	1	EA	4	\$15,024	Serves gym AHU; Approx 3600 cfm; Fan is damaged and in poor condition
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	8	EA	5	\$34,306	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	10	EA	5	\$42,883	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	5	\$131,341	No return duct
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	\$131,341	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	\$131,341	No return duct
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room / 2nd Floor	30	LF	6	\$14,722	
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	7	\$0	Carrier (2008); Mod#:50TM-014-A-501; Serial#:1506G30637; 12.5 Tons
	Zone Dampers	Mechanical Room	21	EΑ	5	\$44,649	
	Zone Dampers	Mechanical Room	4	EA	4	\$19,171	Damper is missing an actuator
	Zone Dampers	Mechanical Room	27	EA	5	\$57,406	
	Zone Dampers	Mechanical Room	5	EA	4	\$23,963	Dampers are missing actuators
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	4	\$32,880	Boiler auxiliaries are in poor condition. Boiler auxiliaries show signs of corrosion and is in poor condition. Boiler suffered damage from flood.
	Chemical Feed System	Boiler Room	2	EA	4	\$13,973	Engineer has issues with the controls. System has no feed water tank. Chemicals are fed into vacuum pump assembly
	Chemical Feeder	Boiler Room	1	EA	5	\$3,075	Chemical pot feeder on vacuum pump assembly
	Combustion Dampers	Boiler Room	2	EA	5	\$5,104	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	4	\$106,661	Boilers show significant signs of wear and are in poor condition. Boiler room suffered a flood three feet deep. Much of boiler equipment was damaged.
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	4	\$72,478	Piping is old and in poor condition
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	4	\$114,680	Piping is old and in poor condition
	Steam Traps	Boiler Room	52	EA	5	\$68,375	School steam traps are old, but in okay condition
	Vacuum Pump	Boiler Room	1	EA	4	\$36,909	Assembly has significant significant signs of corrosion suffered damage from flood. Assembly is also serving as the feed water tank.



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Gas Booster						
Gas Booster	Boiler Room	1	EA	5	\$12,593	
Heating Devices						
Radiators - Steam	Entire Building	18	EA	5	\$30,156	Old steam radiators
Temperature Control						
DDC System	Entire Building	70,461	SF	4	\$446,363	Engineer has issues with DDC system. System requires adjustments and manual operation
Thermostats - DDC	Entire Building	61	EA	4	\$49,968	Engineer has issues with thermostats controlling properly
Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Attic	4	EA	4	\$16,978	Fan is greater than 15 years of age and in poor conditon
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	\$1,185	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	4	\$12,784	Fan is greater than 15 years of age and in poor conditon
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	3	\$6,392	Fan not working
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	\$592	
Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	3	\$9,916	hood does not have sufficient length

Mechanical System Subtotal:

\$1,950,633

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	\$2,249	Raypak (1992); Mod#:KFD200-91-1; 199,900 btu/hr
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	7	\$0	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	70,461	SF	4	\$50,380	Piping is greater than 50 years of age, and galvanized.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	70,461	SF	4	\$101,767	Piping is greater than 50 years of age, and galvanized.
	Domestic Piping-Cold Water Risers	Entire Building	70,461	SF	4	\$56,425	Piping is greater than 50 years of age, and galvanized.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	70,461	SF	4	\$38,289	Piping is greater than 50 years of age, and galvanized.



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	70,461	SF	4	\$90,683	Piping is greater than 50 years of age, and galvanized.
	Domestic Piping-Hot Water Return Lines	Entire Building	70,461	SF	4	\$60,456	Piping is greater than 50 years of age, and galvanized.
	Domestic Piping-Hot Water Return Risers	Entire Building	70,461	SF	4	\$34,258	Piping is greater than 50 years of age, and galvanized.
	Sanitary Piping	Entire Building	70,461	SF	6	\$64,486	
	Storm Piping	Entire Building	70,461	SF	6	\$61,463	
	Vent Piping	Entire Building	70,461	SF	6	\$47,357	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	2	EA	5	\$17,873	5 HP
	Pumps - Ejector-Duplex	Entire Building	2	EA	6	\$2,774	Operate well per engineer
	Pumps - Sump-Duplex	Entire Building	1	EA	3	\$15,749	One pump is broken, shaft is also broken
	Pumps - Sump-Simplex	Entire Building	3	EA	6	\$2,235	Operate well per engineer

Plumbing System Subtotal:

\$646,444

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #100 (Office)						
	AC Units		1	EA	7	\$0	
	Ceiling - Plaster/Drywall		354	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		354	SF	7	\$0	
	Lighting - Pendent/Surface		10	EA	7	\$0	
	Storage/ Closet		12	SF	6	\$87	
	Walls - Plaster/Drywall		677	SF	6	\$1,868	
	Work Sink		1	EA	6	\$379	
Classro	om #101 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		37	LF	5	\$7,736	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	6	\$1,982	

3810 W 81st Pl Chicago, IL 60652

Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #101 (Regular Classroom)						
	Marker Board		22	LF	7	\$0	
	Student Lockers - One Tier		11	EA	5	\$1,542	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
lassro	om #102 (Office)						
	AC Units		2	EA	7	\$0	
	Casework		50	LF	6	\$1,263	
	Ceiling - Plaster/Drywall		925	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		925	SF	7	\$0	
	Lighting - Pendent/Surface		24	EA	6	\$2,973	
	Marker Board		22	LF	7	\$0	
	Storage/ Closet		40	SF	6	\$290	
	Walls - Plaster/Drywall		989	SF	7	\$0	
lassro	om #103 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall		725	SF	6	\$2,509	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Student Lockers - One Tier		6	EA	6	\$557	
	Walls - Plaster/Drywall		900	SF	7	\$0	
lassro	om #104 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		37	LF	6	\$934	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	7	\$0	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Student Lockers - One Tier		6	EA	5	\$841	Not functioning properly
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
lassro	om #105 (Regular Classroom)						
	AC Units		1	EA	6	\$496	



3810 W 81st Pl Chicago, IL 60652

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	oom #105 (Regular Classroom)	Location	Quantity	Oilit	IXAIIK	0031	Commence
Classic	Casework		5	LF	6	\$126	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		75	SF	4	\$973	large cracks, missing
	Floor - Tile		650	SF	6	\$1,422	large oracito, missing
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #106 (Regular Classroom)					- ,	
Classic	AC Units		1	EA	7	\$0	
	Casework		30	LF	5	\$6,272	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	6	\$1,982	
	Marker Board		22	LF	7	\$0	
	Student Lockers - One Tier		11	EA	6	\$1,021	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
						4 –,	
Classro	oom #107 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		8	LF	6	\$202	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #108 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		30	LF	6	\$758	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #108 (Regular Classroom)						
	Student Lockers - One Tier		11	EA	6	\$1,021	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #109 (Regular Classroom)						
	AC Units		1	EΑ	7	\$0	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #112 (Regular Classroom)						
	AC Units		2	EA	6	\$991	
	Casework		49	LF	6	\$1,237	
	Ceiling - Plaster/Drywall		1,050	SF	6	\$3,634	
	Doors - Steel Doors incl hw		1	EΑ	6	\$301	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain		25	SF	5	\$399	
	Floor - Tile/Sheet		1,025	SF	7	\$0	
	Lighting - Pendent/Surface		25	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Storage/ Closet		40	SF	6	\$290	
	Walls - Plaster/Drywall		950	SF	6	\$2,622	
	Walls - Tile Ceramic/ Porcelain		125	SF	6	\$282	
	Work Sink		1	EA	6	\$379	
Classro	oom #113 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		17	LF	6	\$429	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		20	EΑ	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #114 (Regular Classroom)		•				
	AC Units		2	EA	6	\$991	
	Casework		49	LF	5	\$10,245	
	Ceiling - Plaster/Drywall		1,050	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EΑ	5	\$2,348	
	Floor - Carpet		125	SF	5	\$642	
	Floor - Tile Ceramic/ Porcelain		25	SF	6	\$53	
	Floor - Tile/Sheet		900	SF	7	\$0	
	Lighting - Pendent/Surface		28	EA	6	\$3,469	
	Marker Board		22	LF	7	\$0	
	Storage/ Closet		40	SF	6	\$290	
	Walls - Plaster/Drywall		950	SF	6	\$2,622	
	Walls - Tile Ceramic/ Porcelain		125	SF	6	\$282	
	Work Sink		1	EA	7	\$0	
Classr	oom #116 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		17	LF	6	\$429	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EΑ	5	\$1,174	
	Floor - Tile/Sheet		725	SF	7	\$0	
	Lighting - Pendent/Surface		20	EΑ	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
	Work Sink		1	EA	5	\$1,508	
Classr	oom #118 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EΑ	6	\$301	
	Floor - Tile/Sheet		725	SF	7	\$0	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	5	\$6,821	
Classr	oom #120 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #120 (Regular Classroom)	Location	Quantity	Offic	Nair	CUSI	Comments
Ciassic	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	7	\$1,174	
	Lighting - Pendent/Surface		20	EA	7 7	\$0 \$0	
	Marker Board		22	LF	7	\$0 \$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
			900	SI	O	Ψ2,404	
Classro	oom #122 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		17	LF	5	\$3,554	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	5	\$6,821	
Classro	oom #200 (Special Education)						
	AC Units		1	EA	7	\$0	
	Ceiling - Plaster/Drywall		350	SF	7	\$0	
	Chalk Board		4	LF	4	\$367	
	Doors - Wood Doors inclu hw		1	EΑ	6	\$301	
	Floor - Tile		350	SF	6	\$766	
	Lighting - Pendent/Surface		8	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		675	SF	6	\$1,863	
Classro	oom #201 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		29	LF	5	\$6,063	
	Ceiling - Plaster/Drywall		700	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EΑ	6	\$602	
	Floor - Tile/Sheet		450	SF	7	\$0	Sheet Vinyl flooring material
	Floor - Tile/Sheet		250	SF	7	\$0	
	Lighting - Pendent/Surface		15	EA	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #202 (Regular Classroom)						
	AC Units		1	EA	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #202 (Regular Classroom)						
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #203 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #204 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	6	\$2,509	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	7	\$0	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #205 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	6	\$1,982	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #206 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #207 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #208 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	5	\$1,464	
	Ceiling - Plaster/Drywall		725	SF	6	\$2,509	
	Chalk Board		22	LF	4	\$2,020	Obsolete Material
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #209 (Computer Lab)						
	AC Units		2	EA	7	\$0	
	Casework		16	LF	6	\$404	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Carpet		725	SF	6	\$1,545	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	

3810 W 81st Pl Chicago, IL 60652

Building: Main

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssroc	om #210 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	6	\$2,509	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		725	SF	6	\$1,586	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
ssroc	om #212 (Computer Lab)						
	AC Units		2	EA	7	\$0	
	Casework		58	LF	6	\$1,465	
	Ceiling - Splined		925	SF	6	\$754	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Carpet		925	SF	4	\$8,505	worn and zippering @ seam
	Lighting - Pendent/Surface		36	EA	6	\$4,460	
	Walls - Plaster/Drywall		1,051	SF	6	\$2,901	
	Wireless System		1	EA	6	\$372	
ssroc	om #213 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		17	LF	6	\$429	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
ssroc	om #214 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		7	LF	6	\$177	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		20	EA	6	\$2,478	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	



3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #214 (Regular Classroom)						
	Work Sink		1	EA	6	\$379	
Classro	oom #216 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		16	LF	5	\$3,345	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Chalk Board		22	LF	4	\$2,020	obsolete material
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	7	\$0	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #218 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		16	LF	6	\$404	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	7	\$0	
	Lighting - Pendent/Surface		20	EA	7	\$0	
	Marker Board		44	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #220 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		10	LF	6	\$253	
	Ceiling - Splined		650	SF	6	\$530	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		650	SF	6	\$651	
	Lighting - Pendent/Surface		15	EA	6	\$1,858	
	Marker Board		12	LF	7	\$0	
	Walls - Plaster/Drywall		880	SF	6	\$2,429	
Classro	oom #222 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		7	LF	6	\$177	
	Ceiling - Splined		725	SF	6	\$591	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile/Sheet		725	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #222 (Regular Classroom)						
	Lighting - Pendent/Surface		20	EA	6	\$2,478	
	Marker Board		24	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
Classro	oom #224 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		17	LF	5	\$3,554	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EΑ	5	\$1,174	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		20	EΑ	7	\$0	
	Marker Board		34	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	7	\$0	
Classro	oom #226 (Regular Classroom)						
	AC Units		1	EA	6	\$496	
	Casework		27	LF	6	\$682	
	Ceiling - Plaster/Drywall		725	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EΑ	5	\$1,174	
	Floor - Tile/Sheet		725	SF	6	\$726	
	Lighting - Pendent/Surface		18	EA	6	\$2,230	
	Marker Board		36	LF	7	\$0	
	Walls - Plaster/Drywall		900	SF	6	\$2,484	
	no ama Culatatal					*07C 0CC	

Classrooms Subtotal: \$276,366

Building: Main

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dministrative Suites/Offices						
Ceiling - Plaster/Drywall	102B Nurse's Waiting / Exam Room	110	SF	7	\$0	
Floor - Tile	102B Nurse's Waiting / Exam Room	110	SF	7	\$0	
Lighting - Pendent/Surface	102B Nurse's Waiting / Exam Room	2	EA	7	\$0	
Power Distribution	102B Nurse's Waiting / Exam Room	2	EA	7	\$0	
Walls - Plaster/Drywall	102B Nurse's Waiting / Exam Room	378	SF	7	\$0	
Work Sink	102B Nurse's Waiting / Exam Room	1	EA	7	\$0	
AC Unit	110 Adjustment Room	1	EA	6	\$496	
Ceiling - Plaster/Drywall	110 Adjustment Room	354	SF	6	\$1,225	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Doors - Wood Doors inclu hw	110 Adjustment Room	2	EA	6	\$602	
	Floor - Tile	110 Adjustment Room	354	SF	6	\$775	
	Lighting - Pendent/Surface	110 Adjustment Room	8	EA	7	\$0	
	Power Distribution	110 Adjustment Room	18	EA	6	\$38,248	
	Walls - Plaster/Drywall	110 Adjustment Room	677	SF	7	\$0	
	AC Unit	111	1	EA	3	\$6,086	AC unit is not installed per MEP guidelines.
	Ceiling - Plaster/Drywall	111	300	SF	7	\$0	
	Doors - Wood Doors inclu hw	111	1	EA	6	\$301	
	Floor - Carpet	111	300	SF	4	\$2,758	stained, warped & zippering @ seams
	Lighting - Pendent/Surface	111	5	EA	6	\$619	
	Power Distribution	111	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	111	635	SF	6	\$1,753	
	AC Unit	201A Teachers' Lounge	1	EΑ	7	\$0	
	Ceiling - Plaster/Drywall	201A Teachers' Lounge	350	SF	7	\$0	
	Doors - Wood Doors inclu hw	201A Teachers' Lounge	1	EΑ	6	\$301	
	Floor - Tile/Sheet	201A Teachers' Lounge	350	SF	7	\$0	
	Lighting - Pendent/Surface	201A Teachers' Lounge	8	EΑ	6	\$991	
	Power Distribution	201A Teachers' Lounge	10	EA	7	\$0	
	Walls - Plaster/Drywall	201A Teachers' Lounge	675	SF	7	\$0	
	Ceiling - Plaster/Drywall	212A	150	SF	5	\$1,375	
	Doors - Wood Doors inclu hw	212A	2	EΑ	6	\$602	
	Floor - Tile	212A	119	SF	7	\$0	
	Lighting - Pendent/Surface	212A	2	EΑ	7	\$0	
	Power Distribution	212A	2	EΑ	7	\$0	
	Walls - Plaster/Drywall	212A	310	SF	6	\$856	
	Work Sink	212A	1	EΑ	6	\$508	
	Ceiling - Plaster/Drywall	212B (Book Storage on plan)	172	SF	7	\$0	
	Doors - Steel Doors incl hw	212B (Book Storage on plan)	1	EΑ	6	\$301	
	Floor - Carpet	212B (Book Storage on plan)	172	SF	5	\$883	
	Lighting - Pendent/Surface	212B (Book Storage on plan)	3	EΑ	7	\$0	
	Power Distribution	212B (Book Storage on plan)	4	EA	7	\$0	
	Walls - Plaster/Drywall	212B (Book Storage on plan)	282	SF	7	\$0	
	Ceiling - Plaster/Drywall	221 Teacher Work Room (Store Room on plan)	139	SF	6	\$481	
	Doors - Wood Doors inclu hw	221 Teacher Work Room (Store Room on plan)	1	EA	6	\$301	
	Floor - Tile	221 Teacher Work Room (Store Room on plan)	139	SF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: Main

rative Suites/Offices Lighting - Pendent/Surface Power Distribution Walls - Concrete Block	221 Teacher Work Room (Store Room on plan) 221 Teacher Work Room (Store Room	2	EA			
Power Distribution	on plan)	2	FΔ			
	221 Teacher Work Room (Store Room		LA	7	\$0	
Walls - Concrete Block	on plan)	2	EA	7	\$0	
	221 Teacher Work Room (Store Room on plan)	363	SF	7	\$0	
Ceiling - Plaster/Drywall	2nd FIr SE Office (Across from 212B)	71	SF	7	\$0	
Doors - Wood Doors inclu hw	2nd FIr SE Office (Across from 212B)	1	EA	6	\$301	
Floor - Tile	2nd Flr SE Office (Across from 212B)	71	SF	7	\$0	
Lighting - Pendent/Surface	2nd Flr SE Office (Across from 212B)	1	EA	7	\$0	
Power Distribution	2nd Flr SE Office (Across from 212B)	2	EA	7	\$0	
Walls - Plaster/Drywall	2nd Flr SE Office (Across from 212B)	291	SF	6	\$803	
Ceiling - Plaster/Drywall	Admin Vault/Storage Rm	60	SF	7	\$0	
Doors - Steel Doors incl hw	Admin Vault/Storage Rm	1	EA	7	\$0	
Floor - Tile	Admin Vault/Storage Rm	60	SF	6	\$131	
Lighting - Pendent/Surface	Admin Vault/Storage Rm	1	EA	7	\$0	
Walls - Concrete Block	Admin Vault/Storage Rm	315	SF	6	\$923	
AC Unit	Engineer Office	1	EA	3	\$6,086	AC unit not installed per MEP guidelines.
Ceiling - Exposed	Engineer Office	84	SF	7	\$0	
Doors - Wood Doors inclu hw	Engineer Office	1	EA	6	\$301	
Floor - Tile	Engineer Office	84	SF	6	\$184	
Lighting - Pendent/Surface	Engineer Office	1	EA	7	\$0	
Power Distribution	Engineer Office	6	EA	7	\$0	
Storage/ Closet	Engineer Office	16	SF	6	\$116	
Walls - Concrete Block	Engineer Office	122	SF	6	\$358	
Ceiling - Plaster/Drywall	Gym Office	75	SF	7	\$0	
Doors - Wood Doors inclu hw	Gym Office	1	EA	6	\$301	
Floor - Concrete Epoxy/ Painted	Gym Office	75	SF	6	\$40	
Lighting - Pendent/Surface	Gym Office	1	EA	7	\$0	
Power Distribution	Gym Office	2	EA	7	\$0	
Walls - Plaster/Drywall	Gym Office	347	SF	7	\$0	
Ceiling - Plaster/Drywall	Kitchen Office	168	SF	7	\$0	
Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	\$301	
Floor - Tile	Kitchen Office	168	SF	6	\$368	
Lighting - Pendent/Surface	Kitchen Office	2	EA	7	\$0	
Power Distribution	Kitchen Office	2	EA	7	\$0	
Walls - Concrete Block	Kitchen Office	411	SF	6	\$1,205	
AC Unit	Main Office	1	EA	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Ceiling - Plaster/Drywall	Main Office	365	SF	7	\$0	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	\$602	
	Floor - Carpet	Main Office	247	SF	5	\$1,268	stained and warped carpet
	Floor - Tile	Main Office	118	SF	7	\$0	
	Lighting - Pendent/Surface	Main Office	8	EA	7	\$0	
	Power Distribution	Main Office	18	EA	7	\$0	
	Walls - Plaster/Drywall	Main Office	698	SF	7	\$0	
	AC Unit	Principal's Office	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Principal's Office	172	SF	7	\$0	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	6	\$602	
	Floor - Carpet	Principal's Office	172	SF	5	\$883	worn and stained carpet
	Lighting - Pendent/Surface	Principal's Office	2	EA	7	\$0	
	Power Distribution	Principal's Office	10	EA	7	\$0	
	Walls - Plaster/Drywall	Principal's Office	402	SF	7	\$0	
Gymna	sia						
	Ceiling - Plaster/Drywall	1st Floor	552	SF	7	\$0	
	Ceiling - Splined	1st Floor	2,394	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	5	EA	6	\$1,505	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	2,394	SF	7	\$0	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	9	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	14	EA	6	\$1,735	
	Stage	1st Floor	552	SF	7	\$0	
	Stage-Stairs - Asphalt	1st Floor	60	LF	6	\$557	Concrete stairs
	Storage/ Closet	1st Floor	70	SF	6	\$508	
	Walls - Plaster/Drywall	1st Floor	1,512	SF	6	\$4,173	stage plaster wall
	Walls - Structural Glazed Tile	1st Floor	3,239	SF	6	\$10,190	
Kitchen							
	Ceiling - Splined	Basement	934	SF	5	\$6,651	
	Doors - Wood Doors inclu hw	Basement	1	EA	5	\$1,174	
	Floor - Tile	Basement	934	SF	6	\$2,043	
	Lighting - Pendent/Surface	Basement	16	EA	7	\$0	
	Serving Line	Basement	19	LF	7	\$0	
	Walls - Concrete Block	Basement	630	SF	7	\$0	
	Walls - Structural Glazed Tile	Basement	687	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

up i	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ch &	Multipurpose Room						
(Ceiling - Splined	Basement	1,600	SF	5	\$11,394	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	\$301	
	Floor - Tile/Sheet	Basement	1,600	SF	6	\$1,602	
	Lighting - Pendent/Surface	Basement	36	EA	7	\$0	
,	Walls - Concrete Block	Basement	2,229	SF	7	\$0	
F_IDF	:						
	AC Unit	211	1	EA	4	\$6,086	not functional
	Doors - Steel Doors incl hw	211	1	EA	7	\$0	
	Finishes	211	146	SF	6	\$1,042	
	Ventilation and Cooling	211	1	EA	5		not supplying sufficient cooling for this room
	-					, ,	3
	cal/ Service Rooms	=					0.00
	Janitor's Closet	1st Floor	44	SF	6	\$315	
	Janitor's Closet	1st Floor	39	SF	6	\$279	entry
	Janitor's Closet	1st Floor	50	SF	6	\$358	north
	Storage Room	1st Floor	430	SF	5	\$6,936	north
	Storage Room	1st Floor	175	SF	7	\$0	adjacent to 111
	Janitor's Closet	2nd Floor	28	SF	6	\$201	SE
,	Janitor's Closet	2nd Floor	28	SF	6	\$201	north
	Janitor's Closet	2nd Floor	44	SF	6	\$315	SW
	Mechanical/ Service Rooms	2nd Floor	162	SF	7	\$0	212 Fan Room
;	Storage Room	2nd Floor	55	SF	6	\$394	adjacent to 211
,	Storage Room	2nd Floor	150	SF	6	\$1,075	211
	Boiler Room	Basement	1,500	SF	6	\$10,746	
,	Janitor's Closet	Basement	44	SF	6	\$315	
	Janitor's Closet	Basement	28	SF	6	\$201	
	Mechanical/ Service Rooms	Basement	175	SF	6	\$1,254	Air Chamber Turbine Room
	Mechanical/ Service Rooms	Basement	77	SF	7	\$0	Electrical Room South
	Mechanical/ Service Rooms	Basement	350	SF	5	\$5,646	Room A; exposed insulation @ pipes
	Mechanical/ Service Rooms	Basement	663	SF	6	\$4,750	Fan Room South
	Mechanical/ Service Rooms	Basement	250	SF	5	\$4,033	Basement Engineer's Workshop
	Mechanical/ Service Rooms	Basement	2,690	SF	6		Air Chamber (South Basement)
	Mechanical/ Service Rooms	Basement	550	SF	6		North Fan Room
	Mechanical/ Service Rooms	Basement	2,482	SF	6		N air chamber
;	Storage Room	Basement	200	SF	5		south stair used as storage
stroon							-
0011	···						

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Ceiling - Plaster/Drywall	102A	21	SF	7	\$0	
	Doors - Wood Doors inclu hw	102A	1	EA	5	\$1,174	
	Floor - Tile/Sheet	102A	21	SF	6	\$21	
	Lighting - Pendent/Surface	102A	1	EA	7	\$0	
	Walls - Plaster/Drywall	102A	189	SF	6	\$522	
	Water Closet	102A	1	EA	6	\$336	
	Accessories	111A East Teachers Toilet in Copy Room	65	SF	6	\$600	mirror, toilet paper, soap dispenser.
	Ceiling - Plaster/Drywall	111A East Teachers Toilet in Copy Room	65	SF	7	\$0	
	Doors - Wood Doors inclu hw	111A East Teachers Toilet in Copy Room	1	EA	7	\$0	
	Floor - Tile	111A East Teachers Toilet in Copy Room	65	SF	7	\$0	
	Hand Dryer	111A East Teachers Toilet in Copy Room	1	EA	7	\$0	
	Lavatory	111A East Teachers Toilet in Copy Room	1	EA	7	\$0	
	Lighting - Pendent/Surface	111A East Teachers Toilet in Copy Room	1	EA	7	\$0	
	Lighting - Wall Mounted	111A East Teachers Toilet in Copy Room	1	EA	6	\$124	
	Walls - Plaster/Drywall	111A East Teachers Toilet in Copy Room	267	SF	7	\$0	
	Water Closet	111A East Teachers Toilet in Copy Room	1	EA	7	\$0	
	Accessories	112A	17	SF	7	\$0	
	Ceiling - Plaster/Drywall	112A	17	SF	7	\$0	
	Doors - Wood Doors inclu hw	112A	1	EA	6	\$301	
	Floor - Tile/Sheet	112A	17	SF	7	\$0	
	Lighting - Pendent/Surface	112A	1	EA	7	\$0	
	Walls - Plaster/Drywall	112A	147	SF	7	\$0	
	Water Closet	112A	1	EA	6	\$336	
	Accessories	114A	17	SF	6	\$157	
	Ceiling - Plaster/Drywall	114A	17	SF	7	\$0	
	Doors - Wood Doors inclu hw	114A	1	EA	6	\$301	
	Floor - Tile/Sheet	114A	17	SF	7	\$0	
	Lighting - Pendent/Surface	114A	1	EA	7	\$0	
	Walls - Plaster/Drywall	114A	147	SF	6	\$406	
	Water Closet	114A	1	EA	6	\$336	



3810 W 81st Pl Chicago, IL 60652

Building: Main

	ltem - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc							
	Accessories	1st Flr East Men near Gym	101	SF	7	\$0	soap dispenser, mirror.
	Ceiling - Plaster/Drywall	1st Flr East Men near Gym	101	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Flr East Men near Gym	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Flr East Men near Gym	101	SF	6	\$214	
	Hand Dryer	1st Flr East Men near Gym	1	EA	7	\$0	
	Lavatory	1st Flr East Men near Gym	1	EΑ	7	\$0	
	Lighting - Pendent/Surface	1st Flr East Men near Gym	1	EΑ	7	\$0	
	Lighting - Pendent/Surface	1st Flr East Men near Gym	1	EΑ	5	\$183	not functioning
	Lighting - Wall Mounted	1st Flr East Men near Gym	1	EA	5	\$169	not functioning
	Partitions	1st Flr East Men near Gym	2	EA	7	\$0	
	Urinals	1st Flr East Men near Gym	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Flr East Men near Gym	88	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Flr East Men near Gym	287	SF	7	\$0	
	Water Closet	1st Flr East Men near Gym	1	EΑ	7	\$0	
	Accessories	1st Flr East Women near Gym	85	SF	7	\$0	mirror, soap dispenser, toilet paper.
	Ceiling - Plaster/Drywall	1st Flr East Women near Gym	85	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Flr East Women near Gym	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Flr East Women near Gym	85	SF	7	\$0	
	Hand Dryer	1st Flr East Women near Gym	1	EA	7	\$0	
	Lavatory	1st Flr East Women near Gym	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Flr East Women near Gym	2	EA	7	\$0	
	Partitions	1st Flr East Women near Gym	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Flr East Women near Gym	36	SF	6	\$99	
	Walls - Structural Glazed Tile	1st Flr East Women near Gym	245	SF	7	\$0	
	Water Closet	1st Flr East Women near Gym	1	EA	6	\$336	
	Accessories	1st Flr North	275	SF	7	\$0	mirror, soap dispenser
	Accessories	1st Flr North	350	SF	7	\$0	soap dispenser, mirror, toilet paper.
	Ceiling - Plaster/Drywall	1st Flr North	350	SF	6	\$1,211	
	Ceiling - Plaster/Drywall	1st Flr North	275	SF	7	\$0	
	Floor Drain	1st Flr North	1	EA	6	\$1,059	
	Floor Drain	1st Flr North	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Flr North	275	SF	6	\$582	
	Floor - Tile Ceramic/ Porcelain	1st Flr North	350	SF	6	\$741	
	Hand Dryer	1st Flr North	2	EA	6	\$460	
	Hand Dryer	1st Flr North	2	EA	6	\$460	
	Lavatory	1st Flr North	2	EA	7	\$0	
	Lavatory	1st Flr North	2	EA	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	• •						
	Lighting - Pendent/Surface	1st Flr North	3	EA	6	\$372	
	Lighting - Pendent/Surface	1st Flr North	4	EΑ	7	\$0	
	Partitions	1st Flr North	5	EΑ	7	\$0	
	Partitions	1st Flr North	2	EΑ	7	\$0	
	Urinals	1st Flr North	3	EA	7	\$0	
	Walls - Plaster/Drywall	1st Flr North	250	SF	6	\$690	
	Walls - Plaster/Drywall	1st Flr North	225	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Flr North	425	SF	6	\$1,337	
	Walls - Structural Glazed Tile	1st Flr North	575	SF	7	\$0	
	Water Closet	1st Flr North	2	EA	6	\$672	
	Water Closet	1st Flr North	5	EA	7	\$0	
	Accessories	1st Flr South	275	SF	6	\$2,536	mirror, soap dispenser.
	Accessories	1st Flr South	275	SF	7	\$0	mirror, soap dispenser
	Ceiling - Plaster/Drywall	1st Flr South	275	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Flr South	275	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Flr South	1	EA	6	\$301	
	Floor Drain	1st Flr South	1	EA	7	\$0	
	Floor Drain	1st Flr South	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Flr South	275	SF	6	\$582	
	Floor - Tile Ceramic/ Porcelain	1st Flr South	275	SF	6	\$582	
	Hand Dryer	1st Flr South	2	EA	7	\$0	
	Hand Dryer	1st Flr South	2	EA	6	\$460	
	Lavatory	1st Flr South	2	EA	7	\$0	
	Lavatory	1st Flr South	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Flr South	3	EA	7	\$0	
	Lighting - Pendent/Surface	1st Flr South	3	EA	7	\$0	
	Partitions	1st Flr South	5	EA	7	\$0	
	Partitions	1st Flr South	2	EA	7	\$0	
	Urinals	1st Flr South	3	EA	7	\$0	
	Walls - Plaster/Drywall	1st Flr South	225	SF	7	\$0	
	Walls - Plaster/Drywall	1st Flr South	225	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Flr South	425	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Flr South	425	SF	6	\$1,337	
	Water Closet	1st Flr South	2	EA	7	\$0	
	Water Closet	1st Flr South	5	EA	7	\$0	
	Accessories	211A East Teachers Toilet (Across from 218)	65	SF	7	\$0	mirror, soap dispenser.

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	••						
	Ceiling - Plaster/Drywall	211A East Teachers Toilet (Across from 218)	67	SF	7	\$0	
	Doors - Wood Doors inclu hw	211A East Teachers Toilet (Across from 218)	1	EA	7	\$0	
	Floor - Tile	211A East Teachers Toilet (Across from 218)	67	SF	7	\$0	
	Hand Dryer	211A East Teachers Toilet (Across from 218)	1	EA	7	\$0	
	Lavatory	211A East Teachers Toilet (Across from 218)	1	EA	7	\$0	
	Lighting - Pendent/Surface	211A East Teachers Toilet (Across from 218)	1	EA	7	\$0	
	Walls - Plaster/Drywall	211A East Teachers Toilet (Across from 218)	267	SF	7	\$0	
	Water Closet	211A East Teachers Toilet (Across from 218)	1	EA	7	\$0	
	Accessories	220A	59	SF	6	\$544	
	Ceiling - Splined	220A	59	SF	6	\$48	
	Doors - Wood Doors inclu hw	220A	1	EΑ	6	\$301	
	Floor Drain	220A	1	EΑ	6	\$1,059	
	Floor - Tile/Sheet	220A	59	SF	7	\$0	
	Lavatory	220A	1	EΑ	5	\$1,590	
	Lighting - Pendent/Surface	220A	1	EΑ	6	\$124	
	Showers	220A	1	EA	6	\$311	
	Walls - Plaster/Drywall	220A	336	SF	6	\$927	
	Water Closet	220A	1	EA	6	\$336	
	Accessories	2nd Flr North	350	SF	7	\$0	mirror, soap dispenser,
	Accessories	2nd Flr North	275	SF	7	\$0	mirror, soap dispenser, toilet paper.
	Ceiling - Plaster/Drywall	2nd Flr North	350	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Flr North	275	SF	7	\$0	
	Floor Drain	2nd Flr North	1	EA	6	\$1,059	missing cover
	Floor Drain	2nd Flr North	1	EA	6	\$1,059	cover missing
	Floor - Tile Ceramic/ Porcelain	2nd Flr North	350	SF	6	\$741	
	Floor - Tile Ceramic/ Porcelain	2nd Flr North	275	SF	6	\$582	
	Hand Dryer	2nd Flr North	2	EA	7	\$0	
	Hand Dryer	2nd Flr North	2	EA	7	\$0	
	Lavatory	2nd Flr North	2	EA	7	\$0	
	Lavatory	2nd Flr North	2	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Flr North	3	EA	6	\$372	
	Lighting - Pendent/Surface	2nd Flr North	4	EA	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Partitions	2nd Flr North	2	EA	7	\$0	
	Partitions	2nd Flr North	5	EA	7	\$0	
	Urinals	2nd Flr North	3	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Flr North	263	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Flr North	225	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Flr North	575	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Flr North	425	SF	6	\$1,337	
	Water Closet	2nd Flr North	5	EA	6	\$1,680	
	Water Closet	2nd Flr North	2	EA	7	\$0	
	Accessories	2nd Flr South	275	SF	7	\$0	
	Accessories	2nd Flr South	275	SF	7	\$0	mirror, soap dispenser.
	Ceiling - Plaster/Drywall	2nd Flr South	275	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Flr South	275	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Flr South	1	EA	6	\$301	
	Floor Drain	2nd Flr South	1	EA	7	\$0	
	Floor Drain	2nd Flr South	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd Flr South	275	SF	6	\$582	
	Floor - Tile Ceramic/ Porcelain	2nd Flr South	275	SF	6	\$582	
	Hand Dryer	2nd Flr South	2	EA	7	\$0	
	Hand Dryer	2nd Flr South	2	EA	7	\$0	
	Lavatory	2nd Flr South	2	EA	7	\$0	
	Lavatory	2nd Flr South	2	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Flr South	3	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Flr South	3	EA	7	\$0	
	Partitions	2nd Flr South	5	EA	7	\$0	
	Partitions	2nd Flr South	2	EA	7	\$0	
	Urinals	2nd Flr South	3	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Flr South	225	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Flr South	225	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Flr South	425	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Flr South	425	SF	7	\$0	
	Water Closet	2nd Flr South	2	EA	6	\$672	
	Water Closet	2nd Flr South	5	EA	7	\$0	
	Accessories	Basement Kitchen Unisex	69	SF	7	\$0	paper towel, mirror, soap dispenser.
	Ceiling - Plaster/Drywall	Basement Kitchen Unisex	14	SF	4	\$246	peeling paint, water damage
	Ceiling - Plaster/Drywall	Basement Kitchen Unisex	55	SF	5	\$504	
	Doors - Wood Doors inclu hw	Basement Kitchen Unisex	1	EA	5	\$1,174	

3810 W 81st Pl Chicago, IL 60652

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
strooi	m						
	Floor - Tile	Basement Kitchen Unisex	69	SF	6	\$151	
	Hand Dryer	Basement Kitchen Unisex	1	EA	7	\$0	
	Lavatory	Basement Kitchen Unisex	1	EA	7	\$0	
	Lighting - Pendent/Surface	Basement Kitchen Unisex	2	EA	7	\$0	
	Walls - Concrete Block	Basement Kitchen Unisex	285	SF	6	\$835	
	Water Closet	Basement Kitchen Unisex	1	EA	6	\$336	
	Accessories	Boiler Locker/Toilet Room	150	SF	6	\$1,384	mirror, soap dispenser
	Ceiling - Exposed	Boiler Locker/Toilet Room	150	SF	7	\$0	exposed concrete
	Doors - Wood Doors inclu hw	Boiler Locker/Toilet Room	2	EΑ	5	\$2,348	
	Floor - Concrete Epoxy/ Painted	Boiler Locker/Toilet Room	150	SF	6	\$79	painted concrete
	Lavatory	Boiler Locker/Toilet Room	1	EΑ	6	\$320	
	Lighting - Pendent/Surface	Boiler Locker/Toilet Room	2	EA	7	\$0	
	Walls - Concrete Block	Boiler Locker/Toilet Room	550	SF	6	\$1,612	
	Water Closet	Boiler Locker/Toilet Room	1	EA	6	\$336	
	Accessories	Engineer Toilet Room	25	SF	6	\$231	mirror
	Ceiling - Plaster/Drywall	Engineer Toilet Room	25	SF	7	\$0	
	Doors - Wood Doors inclu hw	Engineer Toilet Room	1	EA	5	\$1,174	
	Floor - Tile	Engineer Toilet Room	25	SF	4	\$215	damaged floor
	Lavatory	Engineer Toilet Room	1	EA	7	\$0	
	Lighting - Pendent/Surface	Engineer Toilet Room	1	EA	7	\$0	
	Lighting - Wall Mounted	Engineer Toilet Room	1	EA	6	\$124	
	Student Lockers - One Tier	Engineer Toilet Room	1	EA	7	\$0	
	Walls - Concrete Block	Engineer Toilet Room	129	SF	7	\$0	
	Walls - Plaster/Drywall	Engineer Toilet Room	50	SF	6	\$138	
	Water Closet	Engineer Toilet Room	1	EA	6	\$336	
	Accessories	in 2nd FIr SE Office (Across from 212B)	52	SF	7	\$0	
	Ceiling - Plaster/Drywall	in 2nd Flr SE Office (Across from 212B)	52	SF	7	\$0	
	Doors - Wood Doors inclu hw	in 2nd Flr SE Office (Across from 212B)	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	in 2nd Flr SE Office (Across from 212B)	52	SF	7	\$0	
	Hand Dryer	in 2nd Flr SE Office (Across from 212B)	1	EA	7	\$0	
	Lavatory	in 2nd Flr SE Office (Across from 212B)	1	EA	7	\$0	
	Lighting - Pendent/Surface	in 2nd Flr SE Office (Across from 212B)	1	EA	7	\$0	
	Walls - Plaster/Drywall	in 2nd Flr SE Office (Across from 212B)	279	SF	6	\$770	
	Water Closet	in 2nd Flr SE Office (Across from 212B)	1	EA	7	\$0	
	Accessories	Main Office/ Principal's Office Toilet	30	SF	7	\$0	toilet paper, mirror, soap available.
	Ceiling - Plaster/Drywall	Main Office/ Principal's Office Toilet	30	SF	7	\$0	
	Doors - Wood Doors inclu hw	Main Office/ Principal's Office Toilet	1	EΑ	6	\$301	

3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor - Tile	Main Office/ Principal's Office Toilet	30	SF	7	\$0	
	Lavatory	Main Office/ Principal's Office Toilet	1	EA	7	\$0	
	Lighting - Pendent/Surface	Main Office/ Principal's Office Toilet	1	EA	7	\$0	
	Lighting - Wall Mounted	Main Office/ Principal's Office Toilet	1	EA	5	\$169	
	Walls - Plaster/Drywall	Main Office/ Principal's Office Toilet	210	SF	7	\$0	
	Water Closet	Main Office/ Principal's Office Toilet	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$280,917

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Plaster/Drywall	1st Floor South	2,050	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor South	5	EA	7	\$0	
	Doors - Wood Doors include hw	1st Floor South	4	EA	6	\$1,204	
	Drinking Fountains - Double Fountain	1st Floor South	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor South	2,050	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor South	32	EA	7	\$0	
	Student Lockers - One Tier	1st Floor South	123	EA	6	\$11,419	
	Walls - Plaster/Drywall	1st Floor South	1,500	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor South	1,375	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st North	2,475	SF	7	\$0	
	Doors - Steel Doors incl hw	1st North	5	EA	7	\$0	
	Doors - Wood Doors include hw	1st North	4	EA	6	\$1,204	
	Drinking Fountains - Double Fountain	1st North	2	EA	6	\$672	
	Floor - Tile/Sheet	1st North	2,475	SF	7	\$0	
	Lighting - Pendent/Surface	1st North	32	EA	7	\$0	
	Student Lockers - One Tier	1st North	140	EΑ	6	\$12,997	
	Walls - Plaster/Drywall	1st North	1,500	SF	7	\$0	
	Walls - Structural Glazed Tile	1st North	1,500	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd North	2,475	SF	7	\$0	
	Drinking Fountains - Double Fountain	2nd North	2	EΑ	6	\$672	
	Floor - Tile/Sheet	2nd North	2,475	SF	6	\$1,345	
	Lighting - Pendent/Surface	2nd North	32	EA	7	\$0	
	Student Lockers - One Tier	2nd North	150	EA	6	\$13,925	
	Walls - Plaster/Drywall	2nd North	2,475	SF	6	\$10,972	

3810 W 81st Pl Chicago, IL 60652

Building: Main

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orrido	r						
	Walls - Structural Glazed Tile	2nd North	3,000	SF	6	\$9,438	
	Ceiling - Plaster/Drywall	2nd South	2,300	SF	7	\$0	
	Drinking Fountains - Double Water Cooler	2nd South	1	EΑ	7	\$0	
	Drinking Fountains - Single Fountain	2nd South	1	EΑ	6	\$276	
	Floor - Tile/Sheet	2nd South	2,300	SF	7	\$0	
	Lighting - Pendent/Surface	2nd South	32	EΑ	7	\$0	
	Student Lockers - One Tier	2nd South	144	EΑ	6	\$13,368	
	Walls - Plaster/Drywall	2nd South	1,500	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd South	1,375	SF	7	\$0	
	Ceiling - Plaster/Drywall	Admin Corridor	62	SF	7	\$0	
	Doors - Wood Doors include hw	Admin Corridor	1	EA	6	\$301	
	Floor - Carpet	Admin Corridor	12	SF	5	\$62	
	Floor - Tile/Sheet	Admin Corridor	50	SF	7	\$0	
	Lighting - Pendent/Surface	Admin Corridor	2	EA	7	\$0	
	Walls - Plaster/Drywall	Admin Corridor	273	SF	7	\$0	
	Ceiling - Plaster/Drywall	Basement Main	270	SF	6	\$1,672	
	Doors - Steel Doors incl hw	Basement Main	1	EΑ	6	\$301	
	Floor - Tile/Sheet	Basement Main	270	SF	7	\$0	
	Lighting - Pendent/Surface	Basement Main	2	EΑ	7	\$0	
	Walls - Concrete Block	Basement Main	626	SF	7	\$0	
	Ceiling - Splined	Entry Lobby @ South Vestibule	805	SF	6	\$2,325	
	Doors - Steel Doors incl hw	Entry Lobby @ South Vestibule	3	EΑ	5	\$4,137	
	Doors - Wood Doors include hw	Entry Lobby @ South Vestibule	3	EΑ	5	\$3,522	
	Drinking Fountains - Single Fountain	Entry Lobby @ South Vestibule	1	EΑ	6	\$276	
	Floor - Terrazzo	Entry Lobby @ South Vestibule	805	SF	6	\$6,757	
	Lighting - Pendent/Surface	Entry Lobby @ South Vestibule	13	EΑ	6	\$1,611	
	Walls - Structural Glazed Tile	Entry Lobby @ South Vestibule	1,242	SF	6	\$3,907	
	Ceiling - Plaster/Drywall	Gym Corridor @ West	262	SF	7	\$0	
	Doors - Wood Doors include hw	Gym Corridor @ West	2	EA	7	\$0	
	Floor - Tile/Sheet	Gym Corridor @ West	262	SF	7	\$0	
	Lighting - Pendent/Surface	Gym Corridor @ West	6	EA	7	\$0	
	Walls - Plaster/Drywall	Gym Corridor @ West	260	SF	7	\$0	
	Walls - Structural Glazed Tile	Gym Corridor @ West	260	SF	7	\$0	
	Ceiling - Plaster/Drywall	Passage by Basement Rm	350	SF	7	\$0	
	Doors - Wood Doors include hw	Passage by Basement Rm	1	EA	5	\$1,174	
	Floor - Concrete Epoxy/ Painted	Passage by Basement Rm	150	SF	6	\$73	
	Floor - Tile/Sheet	Passage by Basement Rm	200	SF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	••	2004.1011	quartity	01	rtuint	0000	Commente
Joine	Lighting - Pendent/Surface	Passage by Basement Rm	4	EA	7	\$0	
	Walls - Concrete Block	Passage by Basement Rm	1,016	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule @112	77	SF	7	\$0	
	Doors - Steel Doors incl hw	Vestibule @112	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	Vestibule @112	- 77	SF	6	\$215	
	Lighting - Pendent/Surface	Vestibule @112	1	EA	7	\$0	
	Walls - Tile Ceramic/ Porcelain	Vestibule @112	178	SF	6	\$560	
				٠.	· ·	φοσσ	
Safety							
	Camera Viewing Station	Office/MDF Room	1	EA	6	\$683	Monitoring is in office but broken. Working the
	Convito Comona	Office IN ADE Decem	40	_^	0	#2.40 F	MDF Room
	Security Cameras	Office/MDF Room	16	EA	6	\$3,105	
Stairs							
	Ceiling - Plaster/Drywall	Central Stair down to Cafeteria	42	SF	6	\$308	
	Floor - Concrete Epoxy/ Painted	Central Stair down to Cafeteria	16	SF	6	\$8	
	Handrails	Central Stair down to Cafeteria	50	LF	6	\$433	
	Lighting - Pendent/Surface	Central Stair down to Cafeteria	1	EA	7	\$0	
	Lighting - Wall Mounted	Central Stair down to Cafeteria	3	EA	7	\$0	
	Stairs - Concrete	Central Stair down to Cafeteria	81	LF	6	\$672	
	Walls - Plaster/Drywall	Central Stair down to Cafeteria	558	SF	6	\$1,540	
	Ceiling - Plaster/Drywall	Northeast Stair	261	SF	7	\$0	
	Floor - Terrazzo	Northeast Stair	193	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Northeast Stair	75	SF	6	\$503	
	Handrails	Northeast Stair	5	LF	5	\$57	broken section
	Handrails	Northeast Stair	51	LF	6	\$442	
	Lighting - Pendent/Surface	Northeast Stair	1	EΑ	7	\$0	
	Lighting - Wall Mounted	Northeast Stair	1	EΑ	6	\$124	
	Stairs - Terrazzo	Northeast Stair	105	LF	6	\$974	
	Walls - Plaster/Drywall	Northeast Stair	550	SF	7	\$0	
	Walls - Structural Glazed Tile	Northeast Stair	550	SF	6	\$1,730	
	Ceiling - Plaster/Drywall	Northwest Stair	403	SF	7	\$0	
	Floor - Terrazzo	Northwest Stair	311	SF	6	\$2,611	
	Handrails	Northwest Stair	56	LF	7	\$0	
	Lighting - Pendent/Surface	Northwest Stair	1	EA	6	\$124	
	Stairs - Terrazzo	Northwest Stair	105	LF	6	\$974	
	Walls - Plaster/Drywall	Northwest Stair	600	SF	7	\$0	
	Walls - Structural Glazed Tile	Northwest Stair	600	SF	7	\$0	
	Ceiling - Plaster/Drywall	Southeast Stair	415	SF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Floor - Terrazzo	Southeast Stair	359	SF	6	\$3,013	
	Floor - Tile Ceramic/ Porcelain	Southeast Stair	102	SF	6	\$684	
	Handrails	Southeast Stair	56	LF	7	\$0	
	Lighting - Pendent/Surface	Southeast Stair	7	EA	7	\$0	
	Lighting - Wall Mounted	Southeast Stair	1	EA	7	\$0	
	Stairs - Terrazzo	Southeast Stair	105	LF	5	\$5,694	
	Walls - Plaster/Drywall	Southeast Stair	667	SF	7	\$0	
	Walls - Structural Glazed Tile	Southeast Stair	667	SF	7	\$0	
	Ceiling - Plaster/Drywall	Southwest Stair	395	SF	7	\$0	
	Floor - Terrazzo	Southwest Stair	343	SF	6	\$2,879	
	Handrails	Southwest Stair	56	LF	7	\$0	
	Lighting - Pendent/Surface	Southwest Stair	3	EΑ	7	\$0	
	Lighting - Wall Mounted	Southwest Stair	1	EΑ	7	\$0	
	Stairs - Terrazzo	Southwest Stair	105	LF	5	\$5,694	
	Walls - Plaster/Drywall	Southwest Stair	617	SF	7	\$0	
	Walls - Structural Glazed Tile	Southwest Stair	617	SF	7	\$0	
Buildi	ng Interior Subtotal:				\$	137,573	

Building Interior Subtotal:

Total Building Cost \$5,040,441

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Exterior Doors - Exterior Steel Door	M1 - Main	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M1 - Main	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M1 - Main	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M1 - Main	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M10 - Main	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	M10 - Main	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	M10 - Main	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	M10 - Main	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	M11	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M11	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	M11	1	EA	6	\$481	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance	Location	Quantity	Oint	Rum	0031	Comments
Exterior Doors - Exterior Steel Door	M11	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M12	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M12	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M12	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M12	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M2	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M2	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M2	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M2	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M3	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M3	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door		1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M3 M3	1	EA	6		
		1	EA		\$481	
Exterior Doors - Exterior Steel Door	M4 - Main	•		6	\$481	
Exterior Doors - Exterior Steel Door	M4 - Main	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M4 - Main	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M4 - Main	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M5	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M5	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M5	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	M5	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	m6	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	m6 -	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	m6 -	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	m6	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M7 - Main	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M7 - Main	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M7 - Main	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M7 - Main	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M8	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M8	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M8	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M8	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M9	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M9	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M9	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	M9	1	EA	6	\$481	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
intranc	•	20041011	quantity	Oint	. will	0031	Commonto
	Exterior Stairs - Steel or Aluminum	M11	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M11	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M11	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M11	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M12	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M12	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M12	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M12	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M2	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M2	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M2	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M2	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M3	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M3	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M3	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M3	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M4 - Main	20	LF	6	\$77	
	Exterior Stairs - Steel or Aluminum	M4 - Main	20	LF	6	\$77	
	Exterior Stairs - Steel or Aluminum	M4 - Main	20	LF	6	\$77	
	Exterior Stairs - Steel or Aluminum	M4 - Main	20	LF	6	\$77	
	Exterior Stairs - Steel or Aluminum	M5	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M5	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M5	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M5	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	m6	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	m6	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	m6	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	m6	24	LF	6	\$92	
	Exterior Stairs - Steel or Aluminum	M7 - Main	16	LF	6	\$62	
	Exterior Stairs - Steel or Aluminum	M7 - Main	16	LF	6	\$62	
	Exterior Stairs - Steel or Aluminum	M7 - Main	16	LF	6	\$62	
	Exterior Stairs - Steel or Aluminum	M7 - Main	16	LF	6	\$62	
	Exterior Stairs - Steel or Aluminum	M8	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M8	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M8	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M8	24	LF	7	\$0	
	Exterior Stairs - Steel or Aluminum	M9	24	LF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

	Hom Type	Location	Quantity	Linit	Donk	Coct	Comments
•	Item - Type	Location	Quantity	Unit	Kank	Cost	Comments
Entranc		MO		1.5			
	Exterior Stairs - Steel or Aluminum	M9	24	LF	7	\$0 \$0	
	Exterior Stairs - Steel or Aluminum	M9	24	LF	7	\$0 \$0	
	Exterior Stairs - Steel or Aluminum	M9	24	LF	7	\$0 \$0	
	Ramp Handrail - Steel_Ramp Handrail	M4 - Main	68	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M4 - Main	68	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M4 - Main	68	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M4 - Main	68	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M7 - Main	68	LF . –	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M7 - Main	68	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M7 - Main	68	LF . –	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	M7 - Main	68	LF	7	\$0	
	Ramps - Steel or Aluminum	M4 - Main	33	LF	7	\$0	
	Ramps - Steel or Aluminum	M4 - Main	33	LF	7	\$0	
	Ramps - Steel or Aluminum	M4 - Main	33	LF	7	\$0	
	Ramps - Steel or Aluminum	M4 - Main	33	LF	7	\$0	
	Ramps - Steel or Aluminum	M7 - Main	33	LF	6	\$4,958	
	Ramps - Steel or Aluminum	M7 - Main	33	LF	6	\$4,958	
	Ramps - Steel or Aluminum	M7 - Main	33	LF	6	\$4,958	
	Ramps - Steel or Aluminum	M7 - Main	33	LF	6	\$4,958	
	Stair Handrail - Steel_Stair Handrail	M11	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M11	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M11	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M11	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M12	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M12	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M12	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M12	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M2	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M2	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M2	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M2	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M3	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M3	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M3	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M3	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	M4 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M4 - Main	16	LF	7	\$0	
			.5		-	ΨΟ	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	e						
	Stair Handrail - Steel_Stair Handrail	M4 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M4 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M5	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M5	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M5	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M5	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	m6	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	m6	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	m6	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	m6	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M7 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M7 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M7 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M7 - Main	16	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M8	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M8	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M8	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M8	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M9	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M9	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M9	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	M9	20	LF	7	\$0	
Founda	tion						
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Founda	tion						
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
	Superstructure - Steel	Entire Building	3,402	SF	7	\$0	
Lightin	n						
Ligitiii	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	\$0	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	\$0	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	\$0	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
Roof S	ystem						
	Downspouts - Exterior Downspouts	D	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	D	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	D	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	D	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	E	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	E	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	E	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	E	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	F	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	F	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	F	22	LF	6	\$731	
	Downspouts - Exterior Downspouts	F	22	LF	6	\$731	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Exterior

Category: Building Exterior						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof System						
Downspouts - Exterior Downspouts	G	22	LF	6	\$731	
Downspouts - Exterior Downspouts	G	22	LF	6	\$731	
Downspouts - Exterior Downspouts	G	22	LF	6	\$731	
Downspouts - Exterior Downspouts	G	22	LF	6	\$731	
Roof Structure - Steel / Metal Deck/ Concrete Topping	D	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	D	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	D	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	D	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	E	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	E	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	E	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	E	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	F	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	F	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	F	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	F	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	G	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	G	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	G	3,402	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete Topping	G	3,402	SF	7	\$0	
Roof - Metal	D	3,402	SF	6	\$45,584	
Roof - Metal	D	3,402	SF	6	\$45,584	
Roof - Metal	D	3,402	SF	6	\$45,584	
Roof - Metal	D	3,402	SF	6	\$45,584	
Roof - Metal	E	3,402	SF	6	\$45,584	
Roof - Metal	E	3,402	SF	6	\$45,584	
Roof - Metal	E	3,402	SF	6	\$45,584	
Roof - Metal	E	3,402	SF	6	\$45,584	
Roof - Metal	F	3,402	SF	6	\$45,584	
Roof - Metal	F	3,402	SF	6	\$45,584	
Roof - Metal	F	3,402	SF	6	\$45,584	
Roof - Metal	F	3,402	SF	6	\$45,584	
Roof - Metal	G	3,402	SF	6	\$45,584	
Roof - Metal	G	3,402	SF	6	\$45,584	
Roof - Metal	G	3,402	SF	6	\$45,584	
Roof - Metal	G	3,402	SF	6	\$45,584	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Exterior

_	Item - Type	Location	Quantity	Unit	Dank	Cost	Comments
Group	item - Type	Location	Quantity	Onit	Nalik	Cost	Comments
Walls	Estation Walla - Wood Cidina	Entire Duilding	200	C.E.		ΦO 4.0.4	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	300	SF	5	\$2,184	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	Exterior Walls - Wood Siding	Entire Building	50	SF	5	\$364	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,916	SF	6	\$6,137	
	Exterior Walls - Wood Siding	Entire Building	1,666	SF	6	\$5,337	
	•	•	,				
Windov							
	Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
	Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
	Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
	Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Windows						
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Guard - Guards wire guard	Entire Building	96	SF	6	\$1,226	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Lintels - Steel	Entire Building	37	LF	6	\$1,074	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	
Windows - Louver	Entire Building	6	SF	6	\$45	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Windows								
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Louver	Entire Building	6	SF	6	\$45		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
	Windows - Sash Aluminum Double-pane	Entire Building	96	SF	6	\$717		
Buildi	ng Exterior Subtotal:				;	971,440		

Building: 2-Classroom Modular

Category: Electrical System

Froup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
mergency System						
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Electrical System

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	ency System	Loudion	Quantity	Oint	Rank	OUSI	Commond
Linerge	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EΑ	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EΑ	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Main So	ervice						
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Main S	ervice						
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building	1	EA	6	\$3,570	Main service located on exterior of modular building. Panel has no electrical info available.
Power	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
=	deal Contama Contatatal					# 00 000	

Electrical System Subtotal:

\$69,089

Building: 2-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkl	er System						
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkle	er System						
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Heads	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Sprinkler Piping	Entire Building	3,402	SF	7	\$0	
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. Operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. Operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. Operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	System serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.



\$14,011

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkl	er System						
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	System serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	Serves modular only. Operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	System serves modular only. System operates on city pressure.
	Wet Sprinkler System	Entire Building	3,402	SF	6	\$876	System serves modular only. System operates on city pressure.

Building: 2-Classroom Modular

Category: Mechanical System

Safty System Subtotal:

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Tempe	rature Control						
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Controls	Entire Building	3,402	SF	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular Category: Mechanical System

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	rature Control	Location	Qualitity	Oill	Nank	CUSI	- Comments
remper	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
	Electric Thermostat	Entire Building	2	EA	6	\$0	
		9	_			**	
Unit Ve	ntilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Unit Ve	ntilation								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0			
Ventilation									
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592			

Mechanical System Subtotal:

\$9,478

Building: 2-Classroom Modular

Category: Plumbing System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water						
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	Rheem; Mod#:81VP6S; 2000 W; 6 gal; Date not available
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$681	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402		6	\$827	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular Category: Plumbing System

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
iping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	3,402	SF	6	\$827	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Cold Water Risers	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,402	SF	6	\$535	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	3,402	SF	6	\$632	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Lines	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Domestic Piping-Hot Water Return Risers	Entire Building	3,402	SF	6	\$486	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Sanitary Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	



Building: 2-Classroom Modular Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Storm Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
	Vent Piping	Entire Building	3,402	SF	7	\$0	
<u> </u>	sing System Systemaly				•	70 442	

Plumbing System Subtotal:

\$79,413

Building: 2-Classroom Modular

Category: Classrooms

Group Item - Type Location Quantity Unit Rank **Cost Comments**

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #301 (Regular Classroom)						
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
Classro	oom #302 (Regular Classroom)						
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Doors - Steel Doors incl hw		1	EA	6	\$301	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #302 (Regular Classroom)						
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Floor - Tile		650	SF	7	\$0	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Lighting - Pendent/Surface		22	EA	6	\$2,726	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
Classro	om #303 (Regular Classroom)						
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Ceiling - Plaster/Drywall		650	SF	7	\$0	
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EΑ	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #303 (Regular Classroom)	Location	Qualitity	Jint	Naiin	CUSI	Commence
CidooiC	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Walls - Vinyl Coated Gypsum Panel		850	SF	7	\$2,002	
	Walls - Vinyl Coated Gypsum Panel		850	SF	7	\$0 \$0	
	Walls - Vinyl Coated Gypsum Panel		850	SF	7	\$0 \$0	
	Walls - Vinyl Coated Gypsum Panel		850	SF	7	\$0 \$0	
	vvalis - viriyi Obaled Gypsum r anel		630	OI .	,	φυ	
Classro	om #304 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Lighting - Pendent/Surface	3rd Floor	24	EA	6	\$2,973	
	Lighting - Pendent/Surface	3rd Floor	24	EA	6	\$2,973	
	Lighting - Pendent/Surface	3rd Floor	24	EA	6	\$2,973	
	Lighting - Pendent/Surface	3rd Floor	24	EA	6	\$2,973	
	Marker Board	3rd Floor	2	LF	7	\$0	
	Marker Board	3rd Floor	2	LF	7	\$0	
	Marker Board	3rd Floor	2	LF	7	\$0	
	Marker Board	3rd Floor	2	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	• • • • • • • • • • • • • • • • • • • •						



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #304 (Regular Classroom)						
Classroom #305 (Regular Classroom)						
Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	\$0	
Floor - Tile	3rd Floor	650	SF	6	\$1,422	
Floor - Tile	3rd Floor	650	SF	6	\$1,422	
Floor - Tile	3rd Floor	650	SF	6	\$1,422	
Floor - Tile	3rd Floor	650	SF	6	\$1,422	
Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
Marker Board	3rd Floor	12	LF	7	\$0	
Marker Board	3rd Floor	12	LF	7	\$0	
Marker Board	3rd Floor	12	LF	7	\$0	
Marker Board	3rd Floor	12	LF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
Classroom #306 (Regular Classroom)						
Ceiling - Plaster/Drywall	3rd Floor	650	SF	6	\$2,249	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	6	\$2,249	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	6	\$2,249	
Ceiling - Plaster/Drywall	3rd Floor	650	SF	6	\$2,249	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #306 (Regular Classroom)						
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	650	SF	7	\$0	
	Floor - Tile	3rd Floor	650	SF	7	\$0	
	Floor - Tile	3rd Floor	650	SF	7	\$0	
	Floor - Tile	3rd Floor	650	SF	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	7	\$0	
Classro	om #307 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	7	\$0	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #307 (Regular Classroom)	Loudion	quantity	Oilit	rain	0031	Commence
J10331 C	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Floor - Tile	3rd Floor	650	SF	5	\$2,919	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	\$2,478	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	\$2,478	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	\$2,478	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	\$2,478	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Marker Board	3rd Floor	12	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel Walls - Vinyl Coated Gypsum Panel	3rd Floor	850	SF	6	\$2,346	
	wais - vinyi Coaled Gypsum Pariei	310 F1001	830	SF	0	\$2,340	
Classro	oom #308 (Regular Classroom)						
	Ceiling - Plaster/Drywall		650	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall		650	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall		650	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall		650	SF	7	\$0	FRP
	Doors - Steel Doors incl hw		2	EΑ	6	\$602	
	Doors - Steel Doors incl hw		2	EΑ	6	\$602	
	Doors - Steel Doors incl hw		2	EΑ	6	\$602	
	Doors - Steel Doors incl hw		2	EΑ	6	\$602	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	
	Floor - Tile		650	SF	5	\$2,919	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Lighting - Pendent/Surface		21	EA	6	\$2,602	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Marker Board		12	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
	* **						



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Classrooms

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #308 (Regular Classroom)						
Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	
Walls - Vinyl Coated Gypsum Panel		850	SF	6	\$2,346	

Classrooms Subtotal: \$192,947

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	25	SF	6	\$179	
	Mechanical/ Service Rooms	1st Floor	25	SF	6	\$179	
	Mechanical/ Service Rooms	1st Floor	25	SF	6	\$179	
	Mechanical/ Service Rooms	1st Floor	25	SF	6	\$179	
	Mechanical/ Service Rooms	Building Support Rooms	85	SF	6	\$609	
	Mechanical/ Service Rooms	Building Support Rooms	85	SF	6	\$609	
	Mechanical/ Service Rooms	Building Support Rooms	85	SF	6	\$609	
	Mechanical/ Service Rooms	Building Support Rooms	25	SF	6	\$179	SW
	Mechanical/ Service Rooms	Building Support Rooms	25	SF	6	\$179	SW
	Mechanical/ Service Rooms	Building Support Rooms	25	SF	6	\$179	SW
	Mechanical/ Service Rooms	Building Support Rooms	25	SF	6	\$179	SW
	Mechanical/ Service Rooms	Building Support Rooms	85	SF	6	\$609	
	Mechanical/ Service Rooms	NW Module - Mechanical	35	SF	6	\$251	
	Mechanical/ Service Rooms	NW Module - Mechanical	35	SF	6	\$251	
	Mechanical/ Service Rooms	NW Module - Mechanical	35	SF	6	\$251	
	Mechanical/ Service Rooms	NW Module - Mechanical	35	SF	6	\$251	
Restro	om						
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, mirror, toilet paper.
	Accessories	East Boys	50	SF	6	\$461	toilet paper,mirror, soap available.
	Accessories	East Boys	50	SF	6	\$461	toilet paper,mirror, soap available.
	Accessories	East Boys	50	SF	6	\$461	toilet paper,mirror, soap available.
	Accessories	East Boys	50	SF	6	\$461	toilet paper,mirror, soap available.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, mirror, toilet paper.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, mirror, toilet paper.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, mirror, toilet paper.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, toilet paper, mirror, paper towel dispenser.



3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro							
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, toilet paper, mirror, paper towel dispenser.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, toilet paper, mirror, paper towel dispenser.
	Accessories	East Boys	50	SF	7	\$0	soap dispenser, toilet paper, mirror, paper towel dispenser.
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Boys	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	East Boys	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Boys	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Boys	1	EA	6	\$301	
	Floor - Tile	East Boys	50	SF	7	\$0	
	Floor - Tile	East Boys	50	SF	7	\$0	
	Floor - Tile	East Boys	50	SF	7	\$0	
	Floor - Tile	East Boys	50	SF	7	\$0	
	Floor - Tile	East Boys	1	SF	7	\$0	
	Floor - Tile	East Boys	1	SF	7	\$0	
	Floor - Tile	East Boys	1	SF	7	\$0	
	Floor - Tile	East Boys	1	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom						
Floor - Tile	East Boys	50	SF	7	\$0	
Floor - Tile	East Boys	50	SF	7	\$0	
Floor - Tile	East Boys	50	SF	7	\$0	
Floor - Tile	East Boys	50	SF	7	\$0	
Hand Dryer	East Boys	1	EA	7	\$0	
Hand Dryer	East Boys	1	EA	7	\$0	
Hand Dryer	East Boys	1	EA	7	\$0	
Hand Dryer	East Boys	1	EA	6	\$230	
Hand Dryer	East Boys	1	EA	6	\$230	
Hand Dryer	East Boys	1	EA	6	\$230	
Hand Dryer	East Boys	1	EA	6	\$230	
Hand Dryer	East Boys	1	EΑ	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EΑ	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EΑ	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EΑ	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lavatory	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	6	\$124	
Lighting - Pendent/Surface	East Boys	1	EA	6	\$124	
Lighting - Pendent/Surface	East Boys	1	EA	6	\$124	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	7	\$0	
Lighting - Pendent/Surface	East Boys	1	EA	6	\$124	
Walls - Plaster/Drywall	East Boys	200	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro							
	Walls - Plaster/Drywall	East Boys	200	SF	7	\$0	
	Walls - Plaster/Drywall	East Boys	200	SF	7	\$0	
	Walls - Plaster/Drywall	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	East Boys	200	SF	7	\$0	
	Water Closet	East Boys	1	EA	7	\$0	
	Water Closet	East Boys	1	EA	6	\$336	
	Water Closet	East Boys	1	EA	6	\$336	
	Water Closet	East Boys	1	EA	6	\$336	
	Water Closet	East Boys	1	EA	6	\$336	
	Water Closet	East Boys	1	EΑ	7	\$0	
	Water Closet	East Boys	1	EΑ	7	\$0	
	Water Closet	East Boys	1	EΑ	7	\$0	
	Water Closet	East Boys	1	EA	7	\$0	
	Water Closet	East Boys	1	EA	7	\$0	
	Water Closet	East Boys	1	EA	7	\$0	
	Water Closet	East Boys	1	EΑ	7	\$0	
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, paper towel dispenser, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, paper towel dispenser, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, paper towel dispenser, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, paper towel dispenser, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, soap.
	Accessories	East Girls	50	SF	7	\$0	toilet paper, mirror, soap.
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Girls	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	East Girls	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Girls	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Girls	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Girls	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Girls	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	East Girls	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Girls	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	East Girls	1	EA	6	\$301	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Floor - Tile	East Girls	50	SF	7	\$0	
	Hand Dryer	East Girls	1	EA	5	\$590	Not working
	Hand Dryer	East Girls	1	EA	6	\$230	
	Hand Dryer	East Girls	1	EA	5	\$590	Not working
	Hand Dryer	East Girls	1	EA	6	\$230	
	Hand Dryer	East Girls	1	EA	5	\$590	Not working
	Hand Dryer	East Girls	1	EA	6	\$230	
	Hand Dryer	East Girls	1	EA	5	\$590	Not working
	Hand Dryer	East Girls	1	EA	6	\$230	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lavatory	East Girls	1	EA	7	\$0	
	Lighting - Pendent/Surface	East Girls	1	EA	7	\$0	
	Lighting - Pendent/Surface	East Girls	1	EA	7	\$0	
	Lighting - Pendent/Surface	East Girls	1	EA	6	\$124	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom						
Lighting - Pendent/Surface	East Girls	1	EA	6	\$124	
Lighting - Pendent/Surface	East Girls	1	EA	6	\$124	
Lighting - Pendent/Surface	East Girls	1	EA	7	\$0	
Lighting - Pendent/Surface	East Girls	1	EA	7	\$0	
Lighting - Pendent/Surface	East Girls	1	EA	6	\$124	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Walls - Vinyl Coated Gypsum Panel	East Girls	200	SF	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EA	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EΑ	7	\$0	
Water Closet	East Girls	1	EA	7	\$0	
Accessories	West Boys	50	SF	6	\$461	soap dispenser, mirror, toilet paper.
Accessories	West Boys	50	SF	6	\$461	soap dispenser, mirror, toilet paper.
Accessories	West Boys	50	SF	6	\$461	soap dispenser, mirror, toilet paper.
Accessories	West Boys	50	SF	6	\$461	soap dispenser, mirror, toilet paper.
Ceiling - Plaster/Drywall	West Boys	50	SF	7	\$0	
Ceiling - Plaster/Drywall	West Boys	50	SF	7	\$0	
Ceiling - Plaster/Drywall	West Boys	50	SF	7	\$0	
Ceiling - Plaster/Drywall	West Boys	50	SF	7	\$0	
Doors - Wood Doors inclu hw	West Boys	1	EA	5	\$1,174	
Doors - Wood Doors inclu hw	West Boys	1	EA	5	\$1,174	
Doors - Wood Doors inclu hw	West Boys	1	EA	5	\$1,174	
Doors - Wood Doors inclu hw	West Boys	1	EA	5	\$1,174	
Floor - Tile	West Boys	50	SF	7	\$0	
Floor - Tile	West Boys	50	SF	7	\$0	
Floor - Tile	West Boys	50	SF	7	\$0	
Floor - Tile	West Boys	50	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Hand Dryer	West Boys	1	EA	7	\$0	
	Hand Dryer	West Boys	1	EA	7	\$0	
	Hand Dryer	West Boys	1	EA	7	\$0	
	Hand Dryer	West Boys	1	EA	7	\$0	
	Lavatory	West Boys	1	EA	7	\$0	
	Lavatory	West Boys	1	EA	7	\$0	
	Lavatory	West Boys	1	EA	7	\$0	
	Lavatory	West Boys	1	EA	7	\$0	
	Lighting - Pendent/Surface	West Boys	1	EA	7	\$0	
	Lighting - Pendent/Surface	West Boys	1	EA	7	\$0	
	Lighting - Pendent/Surface	West Boys	1	EA	7	\$0	
	Lighting - Pendent/Surface	West Boys	1	EΑ	7	\$0	
	Walls - Plaster/Drywall	West Boys	200	SF	7	\$0	
	Walls - Plaster/Drywall	West Boys	200	SF	7	\$0	
	Walls - Plaster/Drywall	West Boys	200	SF	7	\$0	
	Walls - Plaster/Drywall	West Boys	200	SF	7	\$0	
	Water Closet	West Boys	1	EA	7	\$0	
	Water Closet	West Boys	1	EΑ	7	\$0	
	Water Closet	West Boys	1	EΑ	7	\$0	
	Water Closet	West Boys	1	EA	7	\$0	
	Accessories	West Girls	50	SF	7	\$0	soap, toilet paper, mirror.
	Accessories	West Girls	50	SF	7	\$0	soap, toilet paper, mirror.
	Accessories	West Girls	50	SF	7	\$0	soap, toilet paper, mirror.
	Accessories	West Girls	50	SF	7	\$0	soap, toilet paper, mirror.
	Accessories	West Girls	50	SF	6	\$461	soap dispenser, toilet paper, mirror.
	Accessories	West Girls	50	SF	6	\$461	soap dispenser, toilet paper, mirror.
	Accessories	West Girls	50	SF	6	\$461	soap dispenser, toilet paper, mirror.
	Accessories	West Girls	50	SF	6	\$461	soap dispenser, toilet paper, mirror.
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	
	Ceiling - Plaster/Drywall	West Girls	50	SF	7	\$0	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro							
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	West Girls	1	EA	5	\$1,174	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Floor - Tile	West Girls	50	SF	7	\$0	
	Hand Dryer	West Girls	1	EA	7	\$0	
	Hand Dryer	West Girls	1	EA	7	\$0	
	Hand Dryer	West Girls	1	EA	7	\$0	
	Hand Dryer	West Girls	1	EA	7	\$0	
	Hand Dryer	West Girls	1	EA	6	\$230	
	Hand Dryer	West Girls	1	EA	6	\$230	
	Hand Dryer	West Girls	1	EA	6	\$230	
	Hand Dryer	West Girls	1	EA	6	\$230	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lavatory	West Girls	1	EA	7	\$0	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface Lighting - Pendent/Surface Lighting - Pendent/Surface	West Girls West Girls West Girls	1 1 1	EA EA	6 6 6	\$124 \$124 \$124	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Lighting - Pendent/Surface	West Girls	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	West Girls	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	200	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	850	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	West Girls	850	SF	7	\$0	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	
	Water Closet	West Girls	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$39,243

Building: 2-Classroom Modular

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Plaster/Drywall	NE	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	NE	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	NE	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	NE	90	SF	7	\$0	
	Doors - Steel Doors incl hw	NE	1	EA	6	\$301	
	Doors - Steel Doors incl hw	NE	1	EA	6	\$301	
	Doors - Steel Doors incl hw	NE	1	EA	6	\$301	
	Doors - Steel Doors incl hw	NE	1	EA	6	\$301	
	Drinking Fountains - Single Fountain	NE	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	NE	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	NE	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	NE	1	EA	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Interior

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rrido	r						
	Floor - Tile/Sheet	NE	90	SF	7	\$0	
	Floor - Tile/Sheet	NE	90	SF	7	\$0	
	Floor - Tile/Sheet	NE	90	SF	7	\$0	
	Floor - Tile/Sheet	NE	90	SF	7	\$0	
	Lighting - Pendent/Surface	NE	1	EA	6	\$124	
	Lighting - Pendent/Surface	NE	1	EA	6	\$124	
	Lighting - Pendent/Surface	NE	1	EA	6	\$124	
	Lighting - Pendent/Surface	NE	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	NE	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	NE	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	NE	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	NE	275	SF	7	\$0	
	Ceiling - Plaster/Drywall	North West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	North West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	North West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	North West	90	SF	7	\$0	
	Doors - Steel Doors incl hw	North West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	North West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	North West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	North West	1	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	North West	1	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	North West	1	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	North West	1	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	North West	1	EA	7	\$0	
	Floor - Tile/Sheet	North West	90	SF	7	\$0	
	Floor - Tile/Sheet	North West	90	SF	7	\$0	
	Floor - Tile/Sheet	North West	90	SF	7	\$0	
	Floor - Tile/Sheet	North West	90	SF	7	\$0	
	Lighting - Pendent/Surface	North West	1	EA	6	\$124	
	Lighting - Pendent/Surface	North West	1	EA	6	\$124	
	Lighting - Pendent/Surface	North West	1	EA	6	\$124	
	Lighting - Pendent/Surface	North West	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	North West	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	North West	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	North West	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	North West	275	SF	7	\$0	
	Ceiling - Plaster/Drywall	SE Modular	90	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Interior

	Itom - Type	Location	Quantity	l Ini4	Dank	Cont	Comments
-	Item - Type	Location	Quantity	Unit	Kank	Cost	Comments
Corrido		OF Madular	00	C.E.	7	ф О	
	Ceiling - Plaster/Drywall	SE Modular	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	SE Modular	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	SE Modular	90	SF	7	\$0	
	Doors - Steel Doors incl hw	SE Modular	1	EA	6	\$301	
	Doors - Steel Doors incl hw	SE Modular	1	EA	6	\$301	
	Doors - Steel Doors incl hw	SE Modular	1	EA	6	\$301	
	Doors - Steel Doors incl hw	SE Modular	1	EA	6	\$301	
	Drinking Fountains - Single Fountain	SE Modular	1	EA	6	\$276	
	Drinking Fountains - Single Fountain	SE Modular	1	EA	6	\$276	
	Drinking Fountains - Single Fountain	SE Modular	1	EA	6	\$276	
	Drinking Fountains - Single Fountain	SE Modular	1	EA	6	\$276	
	Floor - Tile/Sheet	SE Modular	90	SF	7	\$0	
	Floor - Tile/Sheet	SE Modular	90	SF	7	\$0	
	Floor - Tile/Sheet	SE Modular	90	SF	7	\$0	
	Floor - Tile/Sheet	SE Modular	90	SF	7	\$0	
	Lighting - Pendent/Surface	SE Modular	1	EA	5	\$183	insufficient illumination
	Lighting - Pendent/Surface	SE Modular	1	EA	5	\$183	insufficient illumination
	Lighting - Pendent/Surface	SE Modular	1	EA	5	\$183	insufficient illumination
	Lighting - Pendent/Surface	SE Modular	1	EA	5	\$183	insufficient illumination
	Walls - Vinyl Coated Gypsum Panel	SE Modular	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	SE Modular	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	SE Modular	275	SF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	SE Modular	275	SF	7	\$0	
	Ceiling - Plaster/Drywall	South West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	South West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	South West	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	South West	90	SF	7	\$0	
	Doors - Steel Doors incl hw	South West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	South West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	South West	1	EA	7	\$0	
	Doors - Steel Doors incl hw	South West	1	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	South West	1	EA	6	\$317	
	Drinking Fountains - Single Water Cooler	South West	1	EA	6	\$317	
	Drinking Fountains - Single Water Cooler	South West	1	EA	6	\$317	
	Drinking Fountains - Single Water Cooler	South West	1	EA	6	\$317	
	Floor - Tile/Sheet	South West	90	SF	7	\$0	
	Floor - Tile/Sheet	South West	90	SF	7	\$0	
	Floor - File/Offeet	South West	90	SF	,	Φ0	



\$1,386,996

3810 W 81st Pl Chicago, IL 60652

Building: 2-Classroom Modular

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost (Comments
Corrido	or .						
	Floor - Tile/Sheet	South West	90	SF	7	\$0	
	Floor - Tile/Sheet	South West	90	SF	7	\$0	
	Lighting - Pendent/Surface	South West	1	EA	7	\$0	
	Lighting - Pendent/Surface	South West	1	EA	7	\$0	
	Lighting - Pendent/Surface	South West	1	EA	7	\$0	
	Lighting - Pendent/Surface	South West	1	EA	7	\$0	
	Walls - Plaster/Drywall	South West	275	SF	6	\$1,219	
	Walls - Plaster/Drywall	South West	275	SF	6	\$1,219	
	Walls - Plaster/Drywall	South West	275	SF	6	\$1,219	
	Walls - Plaster/Drywall	South West	275	SF	6	\$1,219	
Buildi	ing Interior Subtotal:					\$11,375	

Total Building Cost

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/D	rainage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	7	\$0	
	Civil/ Drainage - Site Drain	Entire Site / Site North	2	EA	7	\$0	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	7	\$0	
Fencin	g						
	Fencing - Chain Link	Entire Site	1,547	LF	6	\$29,046	
	Fencing - Chain Link	Entire Site	220	LF	5	\$13,418	
	Fencing - Chain Link	Entire Site / North West	354	LF	4	\$32,499	bent, damaged
	Fencing - Guard Rail	Entire Site / North West	60	LF	6	\$693	
Lands	cape						
	Benches	Entire Site	27	EA	6	\$11,611	
	Benches	Entire Site / Site - East	4	EA	5	\$3,549	
	Landscape - Grass	Entire Site	19,026	SF	7	\$0	
	Landscape - Hardscape- Concrete	Entire Site	3,852	SF	7	\$0	
	Landscape - Hardscape- Concrete	Entire Site / Site North	280	SF	4	\$5,962	cracked, broken
	Parkway trees	Entire Site	57	EA	7	\$0	
	Planting Beds/ Area	Entire Site	3,199	SF	7	\$0	

3810 W 81st Pl Chicago, IL 60652

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Landsc	аре						
	Play Area - Asphalt/ Hardscape	Entire Site	68,786	SF	6	\$166,235	
	Play Area - Asphalt/ Hardscape	Entire Site / Site North	684	SF	6	\$2,152	
	Retaining Wall - Concrete	Entire Site / East Façade	576	SF	6	\$13,500	
	Trash Receptacles	Entire Site	3	EA	6	\$937	
	Trash Receptacles	Entire Site / Main Entrance	1	EA	5	\$505	
Parking	Lot						
	Surface - Asphalt	Northwest	25,680	SF	6	\$62,061	
	Trash Compactor	Northwest	1	EA	6	\$0	
	Trash Enclosure - Chain Links	Northwest	629	SF	7	\$0	
Playgro	und						
	Equipment - Pre K 3-5	Northeast	1	EA	6	\$3,546	
	Equipment - School Age 5-12	Southeast	2	EA	6	\$7,092	
	Equipment - School Age 5-12	West	1	EA	6	\$3,546	
	Equipment - Swingset	West	1	EA	6	\$1,182	
	Surface - Square Rubber Mats	West	4,640	SF	5	\$46,845	
	Surface - Square Rubber Mats	West	95	SF	4	\$1,660	warped, deteriorated
	Surface - Wood Chips	Northeast	3,000	SF	4	\$19,262	worn, no longer provide adequate coverage
	Surface - Wood Chips	Southeast	1,617	SF	4	\$10,382	warn, no logner provide adequate coverage
Sidewa	lks						
	Sidewalks - Perimeter Sidewalks	Entire Site	13,160	SF	7	\$0	
Signage	•						
	Flag Pole - Flag Pole	Entire Site / Main Entrance	1	EA	7	\$0	site south
	Marquee - Free Standing Back Lighted	Entire Site / South East	1	EA	6	\$0	
Site S	ubtotal:					\$435,683	
Total	Site Cost					\$435,683	

Campus Total ^{2 3} \$6,863,121

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.



3810 W 81st Pl Chicago, IL 60652

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



3810 W 81st Pl Chicago, IL 60652

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main														1
Computer Lab	Regular Classroom		209	209	725	15	28	76	200	100	50	N	Υ	N
Computer Lab	Library		212	212	925	1	36	72	230	115	40	N	Υ	N
Office	Regular Classroom		100	100	366	3	2	4	100	50	50	N	Υ	N
Office	Kindergarten		102	102	965	1	1	12	250	175	50	N	Υ	N
Regular Classroom	Regular Classroom		101	101	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		103	103	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		104	104	725	1	1	8	200	100	50	N	Υ	Υ
Regular Classroom	Regular Classroom		105	105	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		106	106	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		107	107	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		108	108	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		109	109	725	1	1	8	200	100	50	N	N	Υ
Regular Classroom	Kindergarten		112	112	1,090	1	1	14	250	125	50	N	Υ	N
Regular Classroom	Regular Classroom		113	113	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Kindergarten		114	114	1,090	1	1	8	250	125	50	N	Υ	N
Regular Classroom	Regular Classroom		116	116	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		118	118	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		120	120	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		122	122	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		201	201	700	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		202	202	725	1	1	10	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		203	203	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		204	204	725	1	1	10	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		205	205	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		206	206	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		207	207	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		208	208	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		210	210	725	1	1	10	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		213	213	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		214	214	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		216	216	725	1	0	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		218	218	725	1	1	8	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		220	220	650	0	0	8	200	100	50	N	N	N
Regular Classroom	Regular Classroom		222	222	725	1	0	8	200	100	50	N	N	N
Regular Classroom	Regular Classroom		224	224	725	1	1	10	200	100	50	N	Υ	N
Regular Classroom	Regular Classroom		226	226	725	1	0	8	200	100	50	N	Υ	N
Special Education	Regular Classroom		200	219	350	1	1	6	100	50	50	N	Υ	N



3810 W 81st Pl Chicago, IL 60652

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main														

2-Classroom Modular														
Regular Classroom	Regular Classroom		301	301	650	2	1	16	16	8	40	N	Υ	N
Regular Classroom	Regular Classroom		302	302	650	1	1	16	16	8	40	N	Υ	N
Regular Classroom	Regular Classroom		303	303	650	1	1	16	16	8	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	650	2	1	16	16	8	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	650	1	1	16	16	8	0	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	650	2	1	16	16	8	0	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	650	1	1	8	16	8	40	N	Υ	N
Regular Classroom	Regular Classroom		308	308	650	1	2	16	16	8	40	N	Υ	N