

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1915	3	70,878	\$3,660,614
Addition	1973	3	34,396	\$1,546,251
SITE				\$350,087
Campus Total		•	105,274	\$5,556,952

Building: Main

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntranc	e						
	Entrance Control - Audio	#5 - SW	1	EA	6	\$497	
	Entrance Control - Audio and Video	#1 - main entance - E	1	EA	6	\$702	
	Entrance Control - Audio and Video	#4 - NW	1	EA	6	\$702	
	Exterior Doors - Exterior FRP Door	#1 - main entance - E	3	EA	6	\$1,894	
	Exterior Doors - Exterior FRP Door	#2 - E	3	EA	6	\$1,894	
	Exterior Doors - Exterior FRP Door	#3 - NE	4	EA	6	\$2,526	
	Exterior Doors - Exterior FRP Door	#4 - NW	4	EA	6	\$2,526	
	Exterior Doors - Exterior FRP Door	#5 - SW	3	EA	6	\$1,894	
	Exterior Doors - Exterior FRP Door	#6 - S	2	EA	6	\$1,263	
	Exterior Doors - Side lite	#2 - E	1	EA	6	\$313	
	Exterior Doors - Side lite	#5 - SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#2 - E	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#3 - NE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#4 - NW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#5 - SW	3	EA	6	\$940	
	Exterior Stairs - Concrete	#1 - main entance - E	45	LF	6	\$3,680	
	Exterior Stairs - Concrete	#2 - E	20	LF	5	\$2,192	cracks
	Exterior Stairs - Concrete	#3 - NE	85	LF	6	\$6,950	
	Exterior Stairs - Concrete	#4 - NW	75	LF	6	\$6,133	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e e						
	Exterior Stairs - Concrete	#5 - SW	20	LF	5	\$2,192	pitting, spalling
	Power Door Operator and Controls	#1 - main entance - E	2	EA	6	\$0	
	Power Door Operator and Controls	#4 - NW	2	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	#1 - main entance - E	90	LF	6	\$780	
	Ramp Handrail - Steel_Ramp Handrail	#4 - NW	90	LF	6	\$780	
	Ramps - Concrete	#1 - main entance - E	40	LF	6	\$6,009	
	Ramps - Concrete	#4 - NW	40	LF	6	\$6,009	
	Stair Handrail - Steel_Stair Handrail	#1 - main entance - E	24	LF	6	\$208	
	Stair Handrail - Steel_Stair Handrail	#4 - NW	24	LF	6	\$208	
Founda	tion						
	Foundation - Masonry	Entire Building	644	LF	7	\$0	
	Superstructure - Heavy Timber	Entire Building	70,878	SF	7	\$0	
Lighting	3						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building / North Façade	2	EA	6	\$1,073	
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	\$4,620	
Roof Sy	vstem						
	Cell Tower	Low Ct Yd roof	1	EA	6	\$736	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low Ct Yd roof	80	LF	6	\$76,375	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low Ct Yd roof	20	LF	5	\$57,031	efflorescence
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	53	LF	6	\$50,598	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	53	LF	6	\$50,598	
	Chimney - Brick Chimney- Stainless Steel Liner	Low Ct Yd roof	53	LF	6	\$50,598	rust
	Coping - Metal	Main Roof / Courtyard	257	LF	6	\$8,254	
	Coping - Metal	Mid Ct Yd roof	58	LF	6	\$1,863	
	Coping - Metal	Upper roof / South	40	LF	6	\$1,285	
	Coping - Terra Cotta	Low NE roof	30	LF	6	\$964	
	Coping - Terra Cotta	Low NW roof	30	LF	6	\$964	
	Coping - Terra Cotta	Main Roof	628	LF	6	\$20,170	
	Coping - Terra Cotta	Upper roof	220	LF	6	\$7,066	
	Downspouts - Exterior Downspouts	Main Roof	52	LF	6	\$1,728	
	Downspouts - Exterior Downspouts	Mid Ct Yd roof	27	LF	6	\$897	
	Downspouts - Interior Downspouts	Low Ct Yd roof	26	LF	6	\$864	
	Downspouts - Interior Downspouts	Low NE roof	18	LF	6	\$598	
	Downspouts - Interior Downspouts	Low NW roof	18	LF	6	\$598	
	Downspouts - Interior Downspouts	Main Roof	200	LF	6	\$6,647	
	Downspouts - Interior Downspouts	Upper roof	10	LF	6	\$332	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof S	ystem						
	Parapet - 16" - 30" Height	Main Roof	336	LF	5	\$58,133	efflorescence
	Parapet - 16" - 30" Height	Main Roof	292	LF	6	\$13,976	
	Parapet - 16" - 30" Height	Upper roof	50	LF	6	\$1,998	
	Parapet - Parapet < 16" Height	Upper roof	170	LF	6	\$3,622	
	Parapet - Parapet > 30"	Low NE roof	30	LF	6	\$1,918	
	Parapet - Parapet > 30"	Low NW roof	30	LF	6	\$1,918	
	Roof Structure - Steel with Clay Tile Arch	Low Ct Yd roof	3,223	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Low NE roof	335	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Low NW roof	335	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	18,672	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Mid Ct Yd roof	900	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Upper roof	4,171	SF	7	\$0	
	Roof - Metal	Low Ct Yd roof	195	SF	6	\$2,613	
	Roof - Metal	Upper roof	324	SF	6	\$4,341	
	Roof - Modified Bitumen	Low Ct Yd roof	3,028	SF	6	\$28,492	algae, some water ponding
	Roof - Modified Bitumen	Low NE roof	335	SF	6	\$3,152	not accessible - algae is present
	Roof - Modified Bitumen	Low NW roof	335	SF	6	\$3,152	not accessible
	Roof - Modified Bitumen	Main Roof	18,672	SF	6	\$175,692	some water ponding
	Roof - Modified Bitumen	Mid Ct Yd roof	900	SF	6	\$8,468	
	Roof - Modified Bitumen	Upper roof	3,846	SF	6	\$36,189	some bubbles
Walls							
	Cheek-Wall - Stone	Entire Building	44	SF	6	\$451	
	Cheek-Wall - Stone	Entire Building	44	SF	6	\$451	
	Cheek-Wall - Stone	Entire Building	44	SF	6	\$451	
	Cheek-Wall - Stone	Entire Building	44	SF	6	\$451	
	Cornice - Masonry Projecting Limestone	Entire Building	1,932	LF	6	\$66,997	some chips and open joints
	Exterior Walls - Brick	Entire Building	36,612	SF	6	\$246,069	some open joints
	Exterior Walls - Brick	Entire Building	550	SF	5	\$13,095	efflorescence
	Exterior Walls - Brick	Entire Building / Central Courtyard	10	SF	5	\$238	loose mortar, step cracks
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	440	SF	6	\$2,498	
	Exterior Walls - Stone-Cast	Entire Building	3,220	SF	6	\$21,642	some open joints
Window	vs						
	Guard - Guards perforated	Entire Building / 1st Floor	2,176	SF	6	\$27,787	
	Lintels - Steel	Entire Building	980	LF	6	\$28,448	
	Lintels - Stone	Entire Building	40	LF	6	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building	7,840	SF	6	\$58,522	
		U U	,			,	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Build	ing Exterior Subtotal:				\$	1,207,108	
Build	ing: Main						
Cateo	gory: Electrical System						
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System		-				
	Automatic Transfer Switch	Electrical Room	1	EA	6	\$408	Also serves the Addition
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building / 1st Floor	4,993	SF	6	\$2,642	
	Emergency A/C Power - Corridors and Stairs	Entire Building	17,835	SF	6	\$5,356	
	Emergency A/C Power - Gym	Entire Building / 3rd Floor	3,138	SF	6	\$1,167	
	Emergency A/C Power - Students Toilets	Entire Building	1,914	SF	6	\$712	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	6	EA	6	\$1,215	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	4	EA	6	\$810	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 2nd Floor	4	EA	6	\$810	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 3rd Floor	4	EA	6	\$810	
	Emergency Battery Packs - Gym	Entire Building / 3rd Floor	2	EA	6	\$405	
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	Parking lot	1	EA	7	\$0	No Other Data Avilable
	Exit Signs - Auditoium	Entire Building / 1st Floor	12	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	7	\$0	
	Exit Signs - Gym	Entire Building / 3rd Floor	2	EA	7	\$0	
	Security System - CCTV	Entire Building	70,878	SF	6	\$21,285	
	Security System - Intrusion Detection	Entire Building	70,878	SF	6	\$18,244	
Main S	ervice						
	Independent Electrical Service for emergency power	Outside by the ComED transformer	1	EA	7	\$0	Also serves the Addition
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	7	\$0	
	PA System	Entire Building	70,878	SF	6	\$23,312	Serves Both Buildings
Power	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: MDF Room
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	4	\$4,849	Location: MDF Room
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: MDF Room
	Lighting and Power Panels - 100 A	Entire Building / Boiler Room	1	EA	4	\$4,849	
	Lighting and Power Panels - 100 A	Entire Building / Boiler Room	1	EA	4	\$4,849	
	Lighting and Power Panels - 100 A	Entire Building / Boiler Room	1	EA	4	\$4,849	
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Outside Boy's Restrrom
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Outside Girl's Restroom
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Outside Girl's Restroom



Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power	Distribution						
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Outside Boy's Restroom
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Outside Boy's Restroom
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Outside Girl's Restroom
	Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	1	EA	7	\$0	Location: Assembly Hall (Meter: 141241909)
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Electrical Room	1	EA	7	\$0	Location: Assembly Hall
	Transformers - 120/240 - 120/208	Entire Building / Electrical Room	1	EA	7	\$0	Also serves the Addition

Electrical System Subtotal:

\$96,572

\$59,800

Building: Main

Category: Safty System

Fire Alarm	roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	re Alarm						
Fire Alarm Strobe LightsElectrical Room / Entire Building70,878SF6\$25,339	Fire Alarm Strobe Lights	Electrical Room / Entire Building	70,878	SF	6	\$25,339	
Fire Alarm_System Electrical Room / Entire Building 70,878 SF 6 \$34,461	Fire Alarm_System	Electrical Room / Entire Building	70,878	SF	6	\$34,461	

Safty System Subtotal:

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Cor	ditioning						
	Condensing Unit- Roof Mounted - 5-10 tons	Roof / Lower Roof	1	EA	5	\$9,590	Serves Kitchen, Hanging Univent Below Ceiling
Air Han	dling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils and DX Cooling Coils - Greater than 35000 cfm	1st Floor	1	EA	6	\$8,716	Also serves the addition
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Boiler Room	1	EA	5	\$95,595	Also serves the addition
	Air Intake	1st Floor / Lower Roof	1	EA	6	\$5,765	
	Air Intake	Boiler Room / Lower Roof	1	EA	4	\$17,616	
	Auxiliaries - Greater than 35000 cfm	1st Floor	1	EA	6	\$8,716	
	Auxiliaries - Greater than 35000 cfm	Boiler Room	1	EA	6	\$8,716	require maintenance
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor / Entire Building	100	LF	5	\$96,198	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Boiler Room	100	LF	5	\$96,198	



Category: Mechanical System

Zone Boiler System Boiler HP Cherr Comb Feed Non C Boiler Piping Stean Gas Booster	Dampers Dampers	1st Floor Boiler Room / 1st Floor Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room / Entire Building Boiler Room / Entire Building	16 20 2 1 2 1 2 2 50 60	EA EA EA EA EA EA EA EA	6 6 5 5 6 6	\$13,329 \$16,661 \$5,091 \$3,075 \$5,104 \$2,545 \$5,091	Also serves the addition
Zone Boiler System Boiler HP Cherr Comb Feed Non C Boiler Piping Stean Gas Booster	Dampers ns r Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 nical Feed System bustion Dampers Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room / 1st Floor Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room / Entire Building	20 2 1 2 1 2 2 50	EA EA EA EA EA EA	6 5 5 6 6	\$16,661 \$5,091 \$3,075 \$5,104 \$2,545 \$5,091	Also serves the addition
Boiler System Boiler HP Cherr Comb Feed Non C Boiler Piping Stean Gas Booster	ns r Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 nical Feed System bustion Dampers Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room / Entire Building	2 1 2 1 2 250	EA EA EA EA EA	6 5 5 6	\$5,091 \$3,075 \$5,104 \$2,545 \$5,091	Also serves the addition
Boiler HP Cherr Comb Feed Non C Boiler Piping Stean	r Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 nical Feed System bustion Dampers Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room Boiler Room Boiler Room / Entire Building	1 2 1 2 250	EA EA EA EA	5 5 6	\$3,075 \$5,104 \$2,545 \$5,091	Also serves the addition
HP Cherr Comb Feed Non 0 Boiler Piping Stean	nical Feed System bustion Dampers Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room Boiler Room Boiler Room / Entire Building	1 2 1 2 250	EA EA EA EA	5 5 6	\$3,075 \$5,104 \$2,545 \$5,091	Also serves the addition
Comb Feed Non O Boiler Piping Stean	bustion Dampers Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room Boiler Room / Entire Building	2 1 2 250	EA EA EA	5 6 6	\$5,104 \$2,545 \$5,091	Also serves the addition
Feed Non C Boiler Piping Stean	Water Pumps and Tank Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room Boiler Room / Entire Building	1 2 250	EA EA	6 6	\$2,545 \$5,091	Also serves the addition
Non O Boiler Piping Stean	Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room Boiler Room / Entire Building	2 250	EA	6	\$5,091	Also serves the addition
Boiler Piping Stear Gas Booster	r - 151 - 200 HP g - Steam Pipe- Steel	Boiler Room / Entire Building	250				Also serves the addition
Stean Gas Booster				LF	-		
Gas Booster	n Traps	Boiler Room / Entire Building	60		5	\$3,521	
				EA	5	\$78,894	
Gas E							
	Booster	Boiler Room	2	EA	5	\$25,186	
Heating Devic	es						
Cabir	net Heaters - With Electric Coil	Entire Building	2	EA	4	\$6,720	
Cabir	net Heaters - With Electric Coil	Entire Building	9	EA	6	\$3,210	
Fin T	ube - Steam	3rd Floor	4	LF	6	\$38	
Radia	ators - Steam	Entire Building	4	EA	6	\$1,111	
Unit H	Heater - Steam	Boiler Room	2	EA	4	\$3,511	
Mechanical Pl	lumbing						
Cond	lenser Pump - Less than 10	Mechanical Room	2	EA	6	\$2,222	
Hot V	Vater Pump - 10 - 20 HP	Boiler Room	2	EA	6	\$2,485	
Temperature (Control						
DDC	System	Entire Building	70,878	SF	5	\$116,559	
Therr	mostats - DDC	Entire Building	33	EA	4	\$27,032	Approx: 16 Serve North Plenun & 17 Serve South Plenun
Ventilation							
Exhai	ust Fans- Roof Mounted - 500 - 1500 CFM	Roof	5	EA	7	\$0	Labeled: EF-12
Mechanica	I System Subtotal:					\$668,490	

Category: Plumbing System



John Fiske Elementary School

6020 S Langley Ave Chicago, IL 60637

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	••	Location	Quantity	Onit	Nank	COSI	Comments
	Electric Heater - 20 - 50 KW	Boiler Room	1	EA	4	\$11,353	Corrosion Present Top & Bottom (Leaking) Also
						* () * *	serves the Addition
	Electric Heater - 20 - 50 KW	Boiler Room	1	EA	4	\$11,353	Leaking Also serves the Addition
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	70,878	SF	6	\$14,190	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	70,878	SF	6	\$17,230	
	Domestic Piping-Cold Water Risers	Entire Building	70,878	SF	6	\$13,176	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	70,878	SF	6	\$11,149	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	70,878	SF	6	\$13,176	
	Domestic Piping-Hot Water Return Lines	Entire Building	70,878	SF	6	\$10,136	
	Domestic Piping-Hot Water Return Risers	Entire Building	70,878	SF	6	\$10,136	
	Sanitary Piping	Entire Building	70,878	SF	6	\$64,868	
	Storm Piping	Entire Building	70,878	SF	6	\$61,827	
	Vent Piping	Entire Building	70,878	SF	6	\$47,637	
D		-					
				EA	7	^	
Pumps				LΩ			Also serves the Addition
Plumb	Pumps - Domestic Booster Pump-Duplex bing System Subtotal:	Boiler Room	1		7	\$0 \$286,231	
Plumk Buildi	bing System Subtotal: ing: Main	Boller Room			7	· ·	
Plumk Buildi Categ	bing System Subtotal:	Location	Quantity			\$286,231	Comments
Plumb Buildi Categ Group	oing System Subtotal: ing: Main lory: Classrooms					\$286,231	
Plumb Buildi Categ Group	oing System Subtotal: ing: Main lory: Classrooms Item - Type					\$286,231	
Plumb Buildi Categ Group	bing System Subtotal: ing: Main ory: Classrooms Item - Type bom #101 (Special Program) Casework	Location	Quantity	Unit	Rank	\$286,231 Cost	
Plumk Buildi Categ Group	oing System Subtotal: ing: Main ory: Classrooms Item - Type oom #101 (Special Program)	Location 1st Floor	Quantity 10	Unit	Rank 6	\$286,231 Cost	
Plumb Buildi Categ Group	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall	Location 1st Floor 1st Floor	Quantity 10 615	Unit LF SF	Rank 6 6	\$286,231 Cost \$253 \$2,128 \$669	Comments
Plumk Buildi Categ Group	bing System Subtotal: ing: Main bory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite	Location 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40	Unit LF SF SF	Rank 6 6 6 6	\$286,231 Cost \$253 \$2,128	Comments
Plumb Buildi Categ Group	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40 1	Unit LF SF SF EA	Rank 6 6 6 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301	Comments
Plumb Buildi Categ Group	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40 1 456	Unit LF SF SF EA SF	Rank 6 6 6 6 6 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0	Comments
Plumb Buildi Categ Group	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40 1 456 8	Unit LF SF SF EA SF EA	Rank 6 6 6 6 6 7	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998	Comments
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21	Unit LF SF EA SF EA SF EA SF	Rank 6 6 6 6 6 7 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$00 \$152	Comments
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main ory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School)	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870	Unit SF SF EA SF EA SF SF	Rank 6 6 6 6 7 6 6 6 6 7 6 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161	Comments
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main ory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School) AC Units	Location 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870 1	Unit LF SF EA SF EA SF SF SF	Rank 6 6 6 6 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161 \$496	Comments
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main ory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School) AC Units Ceiling - Plaster/Drywall	Location 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870 1 801	Unit LF SF EA SF EA SF SF SF EA SF	Rank 6 6 6 6 7 6 6 6 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161 \$496 \$2,772	Comments 2- Wood panels w/ glazing inserts
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School) AC Units Ceiling - Plaster/Drywall	Location 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870 1 801 15	Unit SF SF EA SF EA SF SF EA SF SF	Rank 6 6 6 6 7 6 6 6 6 6 6 5	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161 \$152 \$5,161 \$496 \$2,772 \$187	Comments
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School) AC Units Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Doors - Transom Window	Location 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870 1 801 15 16	Unit SF SF EA SF EA SF SF EA SF SF SF	Rank 6 6 6 6 7 6 6 6 6 5 5 6	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161 \$152 \$5,161 \$496 \$2,772 \$187 \$271	Comments 2- Wood panels w/ glazing inserts
Plumk Buildi Categ Group Classro	bing System Subtotal: ing: Main pory: Classrooms Item - Type bom #101 (Special Program) Casework Ceiling - Plaster/Drywall Doors - Side-lite Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall bom #102 (Pre School) AC Units Ceiling - Plaster/Drywall	Location 1st Floor 1st Floor	Quantity 10 615 40 1 456 8 21 1,870 1 801 15	Unit SF SF EA SF EA SF SF EA SF SF	Rank 6 6 6 6 7 6 6 6 6 6 6 5	\$286,231 Cost \$253 \$2,128 \$669 \$301 \$998 \$0 \$152 \$5,161 \$152 \$5,161 \$496 \$2,772 \$187	Comments 2- Wood panels w/ glazing inserts



Building: Main

oup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
ssroom #102 (Pre School)							
Floor - Wood		1st Floor	800	SF	6	\$5,640	
Lighting - Pendent/Surf	ace	1st Floor	13	EA	7	\$0	
Lighting - Pendent/Surf	ace	1st Floor	1	EA	6	\$124	missing cover
Storage/ Closet		1st Floor	58	SF	6	\$421	
Walls - Plaster/Drywall		1st Floor	896	SF	6	\$2,473	
ssroom #103 (Kindergarten)							
AC Units		1st Floor	1	EA	6	\$496	
Casework		1st Floor	6	LF	6	\$152	
Ceiling - Plaster/Drywal		1st Floor	5	SF	5	\$62	peeling
Ceiling - Plaster/Drywal		1st Floor	816	SF	6	\$2,824	
Doors - Transom Windo	W	1st Floor	8	SF	6	\$135	at the room itself
Doors - Wood Doors inc	lu hw	1st Floor	1	EA	6	\$301	
Floor - Tile		1st Floor	16	SF	6	\$35	
Floor - Wood		1st Floor	810	SF	6	\$5,710	
Lighting - Pendent/Surf	ace	1st Floor	14	EA	7	\$0	
Marker Board		1st Floor	12	LF	7	\$0	
Storage/ Closet		1st Floor	66	SF	6	\$479	
Walls - Plaster/Drywall		1st Floor	5	SF	5	\$26	peeling
Walls - Plaster/Drywall		1st Floor	1,552	SF	6	\$4,283	
ssroom #104 (Special Progr	am)						
AC Units		1st Floor	1	EA	6	\$496	
Casework		1st Floor	16	LF	6	\$404	
Ceiling - Plaster/Drywal		1st Floor	653	SF	6	\$2,260	
Doors - Transom Windo		1st Floor	8	SF	6	\$135	
Doors - Wood Doors inc	lu hw	1st Floor	1	EA	6	\$301	
Floor - Wood		1st Floor	653	SF	6	\$4,604	
Lighting - Pendent/Surf	ace	1st Floor	11	EA	7	\$0	
Marker Board		1st Floor	6	LF	7	\$0	
Storage/ Closet		1st Floor	16	SF	6	\$116	
Walls - Plaster/Drywall		1st Floor	1,382	SF	6	\$3,814	
ssroom #105 (Regular Class	room)						
AC Units		1st Floor	1	EA	6	\$496	
AC Units		1st Floor	2	EA	4		not working
Casework		1st Floor	28	LF	6	\$707	
Casework							
Ceiling - Plaster/Drywal		1st Floor	800	SF	6	\$2,768	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #105 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	800	SF	6	\$1,750	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	16	SF	6	\$116	
	Walls - Plaster/Drywall	1st Floor	1,552	SF	6	\$4,283	
Classro	oom #106 (Science)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	6	\$758	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	6	\$2,768	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Eye Wash Station	1st Floor	1	EA	6	\$336	
	Floor - Tile	1st Floor	800	SF	6	\$1,750	
	Gas Line	1st Floor	1	EA	6	\$509	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	16	SF	6	\$116	
	Walls - Plaster/Drywall	1st Floor	1,559	SF	6	\$4,303	
	Work Sink	1st Floor	2	EA	6	\$758	
Classro	oom #107 (Kindergarten)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	6	LF	6	\$152	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	\$2,824	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Storage/ Closet	1st Floor	16	SF	6	\$116	
	Walls - Plaster/Drywall	1st Floor	1,552	SF	6	\$4,283	
Classro	oom #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	1st Floor	805	SF	6	\$2,786	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #108 (Regular Classroom)		•				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	805	SF	6	\$1,761	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	20	SF	6	\$145	
	Walls - Plaster/Drywall	1st Floor	61	SF	6	\$236	wood panel wainscot
	Walls - Plaster/Drywall	1st Floor	1,581	SF	6	\$4,363	
Classrc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	29	LF	6	\$732	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	\$2,838	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	820	SF	6	\$5,781	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classrc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	29	LF	6	\$732	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	\$2,824	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	\$1,174	door sticks & is hard to open
	Floor - Wood	2nd Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classrc	oom #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	\$2,824	
	Chalk Board	2nd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Building: Main

	Itom - Tupo	Location	Quantity	Unit	Dank	Cost	Commonts
	Item - Type	Location	Quantity	Unit	Kalik	Cost	Comments
Classro	bom #203 (Regular Classroom)	and Flags	010	05	6	ድ ማር ማር ዓ	
	Floor - Wood	2nd Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	\$0	and the second
	Lighting - Pendent/Surface	2nd Floor	1	EA	6		cover cracked
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,551	SF	6	\$4,281	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	hole in plaster
Classro	oom #204 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	17	LF	6	\$429	
	Ceiling - Plaster/Drywall	2nd Floor	653	SF	6	\$2,260	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	653	SF	6	\$4,604	
	Lighting	2nd Floor	11		7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,382	SF	6	\$3,814	
Classro	oom #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	\$2,803	
	Chalk Board	2nd Floor	16	LF	6	\$357	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	810	SF	6	\$5,710	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	\$124	cover missing
	Marker Board	2nd Floor	25	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classro	oom #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	\$2,824	
	Chalk Board	2nd Floor	30	LF	6	\$669	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #206 (Regular Classroom)						
	Floor - Wood	2nd Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	\$124	cover missing
	Marker Board	2nd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classro	oom #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	\$2,824	
	Chalk Board	2nd Floor	23	LF	4	\$2,112	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classro	oom #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	35	LF	6	\$884	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	\$2,768	
	Chalk Board	2nd Floor	21	LF	4	\$1,928	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	800	SF	6	\$5,640	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,552	SF	6	\$4,283	
Classro	oom #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	41	LF	6	\$1,035	
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	\$2,852	
	Chalk Board	3rd Floor	19	LF	4	\$1,744	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	824	SF	6	\$5,809	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #301 (Regular Classroom)						
	Marker Board	3rd Floor	48	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	
	Work Sink	3rd Floor	1	EA	6	\$379	
lassro	oom #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	\$2,852	
	Chalk Board	3rd Floor	34	LF	4	\$3,121	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	824	SF	6	\$5,809	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	\$124	missing cover
	Marker Board	3rd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	
lassro	oom #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	\$2,852	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	824	SF	6	\$5,809	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	\$124	missing cover
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	\$0	
	Marker Board	3rd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	
assro	oom #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	24	LF	6	\$606	
	Ceiling - Plaster/Drywall	3rd Floor	819	SF	6	\$2,834	
	Chalk Board	3rd Floor	14	LF	4	\$1,285	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	819	SF	6	\$5,774	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	\$0	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #305 (Regular Classroom)						
	Marker Board	3rd Floor	25	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	
Classro	oom #306 (Science)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	3rd Floor	6,815	SF	6	\$23,584	
	Chalk Board	3rd Floor	32	LF	4	\$2,938	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Transom Window	3rd Floor	8	SF	5	\$339	Inner transom is broken, needs glass replaced
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	816	SF	6	\$5,753	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	
Classro	oom #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	3rd Floor	817	SF	6	\$2,827	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	817	SF	6	\$5,760	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,566	SF	6	\$4,322	
Classro	oom #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	31	LF	6	\$783	
	Ceiling - Plaster/Drywall	3rd Floor	826	SF	6	\$2,858	
	Doors - Transom Window	3rd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	826	SF	6	\$5,823	
	Lighting - Pendent/Surface	3rd Floor	3	EA	6	\$372	2 missing cover, 1 broken cover
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	\$0	-
	Marker Board	3rd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,552	SF	6	\$4,283	



Category: Classrooms

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroom #309 (Music Room)						
AC Units	3rd Floor	2	EA	6	\$991	
Ceiling - Plaster/Drywall	3rd Floor	1,482	SF	6	\$5,129	
Chalk Board	3rd Floor	14	LF	4	\$1,285	
Doors - Side-lite	3rd Floor	56	SF	6	\$936	
Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
Doors - Transom Window	3rd Floor	16	SF	6	\$271	
Floor - Tile	3rd Floor	1,482	SF	6	\$3,242	
Lighting - Pendent/Surface	3rd Floor	25	EA	7	\$0	
Marker Board	3rd Floor	22	LF	7	\$0	
Storage/ Closet	3rd Floor	83	SF	6	\$602	
Storage/ Closet	3rd Floor	152	SF	6	\$1,102	
Walls - Plaster/Drywall	3rd Floor	1,927	SF	6	\$5,318	

Classrooms Subtotal:

\$390,560

Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices						
Ceiling - Plaster/Drywall	1st- Asst Engineer Office in Boiler room	99	SF	5	\$907	peeling
Doors - Wood Doors inclu hw	1st- Asst Engineer Office in Boiler room	1	EA	6	\$301	handle is missing
Floor - Tile/Sheet	1st- Asst Engineer Office in Boiler room	6	SF	5	\$35	missing/damaged
Floor - Tile/Sheet	1st- Asst Engineer Office in Boiler room	93	SF	6	\$93	
Lighting - Pendent/Surface	1st- Asst Engineer Office in Boiler room	3	EA	7	\$0	
Power Distribution	1st- Asst Engineer Office in Boiler room	8	EA	6	\$16,999	
Walls - Masonry	1st- Asst Engineer Office in Boiler room	169	SF	6	\$532	
Walls - Plaster/Drywall	1st- Asst Engineer Office in Boiler room	350	SF	6	\$966	
AC Unit	1st- Engineer Office (inside Boiler Room)	1	EA	4	\$6,086	
Ceiling - Plaster/Drywall	1st- Engineer Office (inside Boiler Room)	341	SF	5	\$3,126	peeling
Doors - Steel Doors incl hw	1st- Engineer Office (inside Boiler Room)	1	EA	6	\$301	
Floor - Carpet	1st- Engineer Office (inside Boiler Room)	341	SF	5	\$1,751	stained/worn
Lighting - Pendent/Surface	1st- Engineer Office (inside Boiler Room)	4	EA	4	\$2,163	T-12
Power Distribution	1st- Engineer Office (inside Boiler Room)	6	EA	6	\$12,749	
Storage/ Closet	1st- Engineer Office (inside Boiler Room)	224	SF	6	\$1,624	one door is missing the handle
Walls - Masonry	1st- Engineer Office (inside Boiler Room)	20	SF	5	\$1,144	efflorescence
Walls - Masonry	1st- Engineer Office (inside Boiler Room)	483	SF	6	\$1,520	
Walls - Plaster/Drywall	1st- Engineer Office (inside Boiler Room)	125	SF	6	\$345	



oup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
ministrative Suites/	Offices						
Ceiling - Plast	er/Drywall	2nd- 205.5 Business Office	276	SF	6	\$955	
Doors - Transo	om Window	2nd- 205.5 Business Office	14	SF	6	\$237	
Doors - Wood	Doors inclu hw	2nd- 205.5 Business Office	1	EA	6	\$301	
Floor - Concre	te	2nd- 205.5 Business Office	267	SF	6	\$141	asphalt
Lighting - Pen	dent/Surface	2nd- 205.5 Business Office	4	EA	6	\$496	missing covers
Power Distribu	ition	2nd- 205.5 Business Office	12	EA	6	\$25,499	
Walls - Plaster	r/Drywall	2nd- 205.5 Business Office	921	SF	6	\$2,542	
Ceiling - Plast	er/Drywall	3rd- 303.5 Office	217	SF	6	\$751	
Doors - Transo	om Window	3rd- 303.5 Office	9	SF	6	\$152	
Doors - Wood	Doors inclu hw	3rd- 303.5 Office	1	EA	6	\$301	
Floor - Wood		3rd- 303.5 Office	217	SF	6	\$1,530	
Lighting - Pen	dent/Surface	3rd- 303.5 Office	2	EA	6	\$248	missing covers
Power Distribu		3rd- 303.5 Office	4	EA	6	\$8,500	-
Walls - Plaster	r/Drywall	3rd- 303.5 Office	693	SF	6	\$1,913	
AC Unit	-	3rd- 304 Asst Principal	1	EA	6	\$496	
Ceiling - Plast	er/Drywall	3rd- 304 Asst Principal	680	SF	6	\$2,353	
-	Doors inclu hw	3rd- 304 Asst Principal	1	EA	6	\$301	
Floor - Wood		3rd- 304 Asst Principal	680	SF	6	\$4,794	
Lighting - Pen	dent/Surface	3rd- 304 Asst Principal	13	EA	7	\$0	
Power Distribu	Ition	3rd- 304 Asst Principal	6	EA	6	\$12,749	
Walls - Plaster	r/Drywall	3rd- 304 Asst Principal	1,589	SF	6	\$4,385	
Ceiling - Plast	er/Drywall	3rd- 305.5 Speech Office	208	SF	6	\$720	
Doors - Side-li	te	3rd- 305.5 Speech Office	36	SF	6	\$602	
Doors - Transo	om Window	3rd- 305.5 Speech Office	9	SF	6	\$152	
Doors - Wood	Doors inclu hw	3rd- 305.5 Speech Office	2	EA	6	\$602	
Floor - Wood		3rd- 305.5 Speech Office	208	SF	6	\$1,466	
Lighting - Pen	dent/Surface	3rd- 305.5 Speech Office	3	EA	6	\$372	missing covers
Power Distribu	ition	3rd- 305.5 Speech Office	4	EA	6	\$8,500	
Walls - Plaster	r/Drywall	3rd- 305.5 Speech Office	667	SF	6	\$1,841	
AC Unit		3rd- 310 Resource Center	1	EA	6	\$496	
Ceiling - Plast	er/Drywall	3rd- 310 Resource Center	680	SF	6	\$2,353	
Doors - Transo	om Window	3rd- 310 Resource Center	14	SF	6	\$237	
Doors - Wood	Doors inclu hw	3rd- 310 Resource Center	1	EA	6	\$301	
Floor - Wood		3rd- 310 Resource Center	680	SF	6	\$4,794	
Lighting - Pen	dent/Surface	3rd- 310 Resource Center	7	EA	7	\$0	
Power Distribu	ition	3rd- 310 Resource Center	12	EA	6	\$25,499	
Walls - Plaster	r/Drwall	3rd- 310 Resource Center	1,485	SF	6	\$4,098	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	3rd- 311 PE Office	453	SF	6	\$1,568	
	Doors - Transom Window	3rd- 311 PE Office	14	SF	6	\$237	
	Doors - Wood Doors inclu hw	3rd- 311 PE Office	1	EA	6	\$301	
	Floor - Wood	3rd- 311 PE Office	453	SF	6	\$3,194	
	Lighting - Pendent/Surface	3rd- 311 PE Office	4	EA	7	\$0	
	Power Distribution	3rd- 311 PE Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	3rd- 311 PE Office	602	SF	6	\$1,661	
Audito	rium & Theater						
	Balcony Seating	1st Floor	23	EA	6	\$4,000	
	Ceiling - Plaster/Drywall	1st Floor	6,625	SF	6	\$55,232	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	\$3,612	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,969	SF	6	\$1,042	
	Floor - Tile/Sheet	1st Floor	2,204	SF	6	\$2,206	
	Floor - Wood	1st Floor	2,452	SF	6	\$17,286	stage floor 820 & balcony floor 1632
	Lighting - Pendent/Surface	1st Floor	21	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	14	EA	7	\$0	
	Main Floor Seating	1st Floor	442	EA	6	\$76,871	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	820	SF	6	\$4,737	
	Stage Curtain	1st Floor	8	EA	6	\$0	
	Stage Lift	1st Floor	1	EA	6	\$6,510	
	Stage Lighting System	1st Floor	1	EA	6	\$8,077	
	Stage-Stairs - Wood	1st Floor	8	LF	6	\$94	
	Stairs - Tile	1st Floor	6	LF	6	\$56	
	Walls - Concrete Block	1st Floor	243	SF	6	\$712	
	Walls - Plaster/Drywall	1st Floor	7,623	SF	6	\$36,300	
Gymna	sia						
	Ceiling - Plaster/Drywall	3rd Floor	3,138	SF	6	\$17,321	
	Doors - Steel Doors incl hw	3rd Floor	4	EA	6	\$1,204	
	Doors - Transom Window	3rd Floor	54	SF	6	\$914	
	Floor - Wood	3rd Floor	3,138	SF	6	\$22,123	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	16	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	4,928	SF	6	\$13,601	
Library							
	Casework	2nd Floor	104	LF	6	\$2,626	
	Ceiling - Plaster/Drywall	2nd Floor	1,373	SF	6	\$4,751	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ibrary							
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	28	SF	6	\$474	
	Floor - Carpet	2nd Floor	1,373	SF	6	\$2,925	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	\$0	
	Storage/ Closet	2nd Floor	138	SF	6	\$1,001	work room
	Walls - Plaster/Drywall	2nd Floor	2,055	SF	6	\$5,672	
Mechar	nical/ Service Rooms						
	Air Tunnel	1st Floor	954	SF	6	\$5,907	Engine Room
	Auditorium Plenums	1st Floor	819	SF	6	\$5,071	
	Boiler Room	1st Floor	1,336	SF	6	\$9,572	
	Coal Room	1st Floor	603	SF	6	\$4,320	
	Interior Stairs	1st Floor	24	LF	6	\$217	boiler room stairs
	Janitor's Closet	1st Floor	14	SF	6	\$100	by Girl's RR
	Janitor's Closet	1st Floor	14	SF	6	\$100	
	Mechanical/ Service Rooms	1st Floor	631	SF	5	\$10,178	Tank room- peeling paint & water on floor
	Mechanical/ Service Rooms	1st Floor	64	SF	6	\$459	Elevator Mechanical Room
	Storage Room	1st Floor	492	SF	5	\$7,936	Boiler Room Storage Mezzanine- peeling paint & T-12's
	Storage Room	1st Floor	35	SF	6	\$251	105A
	Vaults	1st Floor	124	SF	6	\$888	ComEd elect vault
	Janitor's Closet	2nd Floor	14	SF	6	\$100	by Boy's RR
	Janitor's Closet	2nd Floor	14	SF	6	\$100	by Girl's RR
	Storage Room	2nd Floor	132	SF	6	\$946	West side of stage
	Storage Room	2nd Floor	132	SF	5	\$2,129	East side of stage- peeling paint
	Janitor's Closet	3rd Floor	14	SF	6	\$100	by Boy's RR
	Janitor's Closet	3rd Floor	14	SF	6	\$100	By Girl's RR
Restroc	om						
	Accessories	1st Floor	319	SF	6	\$2,942	
	Accessories	1st Floor	319	SF	6	\$2,942	
	Ceiling - Plaster/Drywall	1st Floor	319	SF	6	\$1,104	
	Ceiling - Plaster/Drywall	1st Floor	319	SF	6	\$1,104	
	Doors - Side-lite	1st Floor	7	SF	6	\$117	solid panel
	Doors - Side-lite	1st Floor	7	SF	6	\$117	solid panel
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	-
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	



b Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
oom						
Floor - Tile Ceramic/ Porcelain	1st Floor	319	SF	6	\$675	
Floor - Tile Ceramic/ Porcelain	1st Floor	319	SF	6	\$675	
Hand Dryer	1st Floor	2	EA	6	\$460	
Hand Dryer	1st Floor	2	EA	6	\$460	
Lavatory	1st Floor	3	EA	6	\$959	
Lavatory	1st Floor	3	EA	6	\$959	
Lighting - Lay-in	1st Floor	3	EA	7	\$0	
Lighting - Lay-in	1st Floor	3	EA	7	\$0	
Partitions	1st Floor	2	EA	6	\$594	
Partitions	1st Floor	4	EA	6	\$1,188	
Urinals	1st Floor	3	EA	6	\$1,008	
Walls - Plaster/Drywall	1st Floor	164	SF	6	\$453	
Walls - Plaster/Drywall	1st Floor	164	SF	6	\$453	
Walls - Structural Glazed Tile	1st Floor	420	SF	6	\$1,321	
Walls - Structural Glazed Tile	1st Floor	420	SF	6	\$1,321	
Walls - Tile Ceramic/ Porcelain	1st Floor	319	SF	6	\$721	
Walls - Tile Ceramic/ Porcelain	1st Floor	319	SF	6	\$721	
Water Closet	1st Floor	5	EA	6	\$1,680	
Water Closet	1st Floor	2	EA	6	\$672	
Accessories	1st- Inside room 101	43	SF	6	\$397	
Ceiling - Plaster/Drywall	1st- Inside room 101	43	SF	6	\$149	
Doors - Wood Doors inclu hw	1st- Inside room 101	1	EA	6	\$301	
Floor Drain	1st- Inside room 101	1	EA	6	\$1,059	
Floor - Tile	1st- Inside room 101	43	SF	6	\$94	
Lavatory	1st- Inside room 101	1	EA	6	\$320	
Lighting - Pendent/Surface	1st- Inside room 101	1	EA	7	\$0	
Walls - Plaster/Drywall	1st- Inside room 101	358	SF	6	\$988	
Water Closet	1st- Inside room 101	1	EA	6	\$336	
Accessories	1st- Inside room 102	58	SF	6	\$535	
Ceiling - Plaster/Drywall	1st- Inside room 102	58	SF	6	\$201	
Doors - Wood Doors inclu hw	1st- Inside room 102	1	EA	6	\$301	
Floor Drain	1st- Inside room 102	1	EA	6	\$1,059	
Floor - Epoxy/ Painted	1st- Inside room 102	58	SF	6	\$31	
Lavatory	1st- Inside room 102	1	EA	6	\$320	
Lighting - Pendent/Surface	1st- Inside room 102	1	EA	7	\$0	
Walls - Plaster/Drywall	1st- Inside room 102	396	SF	6	\$1,093	
Water Closet	1st- Inside room 102	1	EA	6	\$336	



р	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
roo							
	Accessories	1st- Teacher's Toilet	44	SF	6	\$406	
	Ceiling - Lay-in	1st- Teacher's Toilet	44	SF	6	\$132	
	Doors - Wood Doors inclu hw	1st- Teacher's Toilet	1	EA	6	\$301	
	Floor - Sport Flooring	1st- Teacher's Toilet	24	SF	6	\$52	Rubber
	Floor - Tile	1st- Teacher's Toilet	20	SF	6	\$44	
	Lavatory	1st- Teacher's Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Teacher's Toilet	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Teacher's Toilet	305	SF	6	\$842	
	Water Closet	1st- Teacher's Toilet	1	EA	6	\$336	
	Accessories	2nd Floor	319	SF	6	\$2,942	
	Accessories	2nd Floor	319	SF	6	\$2,942	
	Ceiling - Plaster/Drywall	2nd Floor	319	SF	6	\$1,104	
	Ceiling - Plaster/Drywall	2nd Floor	319	SF	6	\$1,104	
	Doors - Side-lite	2nd Floor	7	SF	6	\$117	solid panel
	Doors - Wood Doors inclu hw	2nd Floor	7	EA	6	\$2,107	solid panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	319	SF	6	\$675	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	319	SF	6	\$675	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Lavatory	2nd Floor	3	EA	6	\$959	
	Lavatory	2nd Floor	3	EA	6	\$959	
	Lighting - Lay-in	2nd Floor	3	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	\$0	
	Partitions	2nd Floor	4	EA	6	\$1,188	
	Partitions	2nd Floor	2	EA	6	\$594	
	Urinals	2nd Floor	3	EA	6	\$1,008	
	Walls - Plaster/Drywall	2nd Floor	164	SF	6	\$453	
	Walls - Plaster/Drywall	2nd Floor	164	SF	6	\$453	
	Walls - Structural Glazed Tile	2nd Floor	420	SF	6	\$1,321	
	Walls - Structural Glazed Tile	2nd Floor	420	SF	6	\$1,321	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	319	SF	6	\$721	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	319	SF	6	\$721	
	Water Closet	2nd Floor	2	EA	6	\$672	



Building: Main

A A							
A A							
А	Nater Closet	2nd Floor	5	EA	6	\$1,680	
	Accessories	3rd Floor	319	SF	6	\$2,942	
С	Accessories	3rd Floor	319	SF	6	\$2,942	
	Ceiling - Plaster/Drywall	3rd Floor	319	SF	6	\$1,104	
C	Ceiling - Plaster/Drywall	3rd Floor	319	SF	6	\$1,104	
D	Doors - Side-lite	3rd Floor	7	SF	6	\$117	solid panel
D	Doors - Side-lite	3rd Floor	7	SF	6	\$117	solid panel
D	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
D	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
F	Floor Drain	3rd Floor	1	EA	6	\$1,059	
F	Floor Drain	3rd Floor	1	EA	6	\$1,059	
F	Floor - Tile Ceramic/ Porcelain	3rd Floor	319	SF	6	\$675	
F	Floor - Tile Ceramic/ Porcelain	3rd Floor	319	SF	6	\$675	
Н	Hand Dryer	3rd Floor	2	EA	6	\$460	
Н	Hand Dryer	3rd Floor	2	EA	6	\$460	
L	_avatory	3rd Floor	3	EA	6	\$959	
L	_avatory	3rd Floor	3	EA	6	\$959	
Li	_ighting - Lay-in	3rd Floor	3	EA	7	\$0	
Li	_ighting - Lay-in	3rd Floor	3	EA	7	\$0	
Р	Partitions	3rd Floor	4	EA	6	\$1,188	
Р	Partitions	3rd Floor	1	EA	6	\$297	
U	Jrinals	3rd Floor	3	EA	6	\$1,008	
V	Walls - Plaster/Drywall	3rd Floor	164	SF	6	\$453	
V	Nalls - Plaster/Drywall	3rd Floor	164	SF	6	\$453	
V	Walls - Structural Glazed Tile	3rd Floor	420	SF	6	\$1,321	
V	Walls - Structural Glazed Tile	3rd Floor	420	SF	6	\$1,321	
V	Nalls - Tile Ceramic/ Porcelain	3rd Floor	319	SF	6	\$721	
V	Nalls - Tile Ceramic/ Porcelain	3rd Floor	319	SF	6	\$721	
V	Water Closet	3rd Floor	1	EA	5	\$1,344	out of order
V	Water Closet	3rd Floor	1	EA	6	\$336	
V	Water Closet	3rd Floor	5	EA	6	\$1,680	
А	Accessories	3rd- Women's Teacher's Toilet	64	SF	6	\$590	
С	Ceiling - Plaster/Drywall	3rd- Women's Teacher's Toilet	64	SF	6	\$221	
D	Doors - Wood Doors inclu hw	3rd- Women's Teacher's Toilet	1	EA	6	\$301	
F	Floor - Tile Ceramic/ Porcelain	3rd- Women's Teacher's Toilet	64	SF	6	\$135	
L	_avatory	3rd- Women's Teacher's Toilet	1	EA	6	\$320	
Li	_ighting - Pendent/Surface	3rd- Women's Teacher's Toilet	1	EA	7	\$0	



\$641,194

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Partitions	3rd- Women's Teacher's Toilet	1	EA	6	\$297	
	Walls - Plaster/Drywall	3rd- Women's Teacher's Toilet	10	SF	5	\$51	peeling
	Walls - Plaster/Drywall	3rd- Women's Teacher's Toilet	429	SF	6	\$1,184	
	Water Closet	3rd- Women's Teacher's Toilet	1	EA	6	\$336	
	Ceiling - Exposed	Boiler Room Toilet	19	SF	6	\$28	
	Doors - Wood Doors inclu hw	Boiler Room Toilet	1	EA	6	\$301	
	Floor - Concrete	Boiler Room Toilet	19	SF	6	\$10	
	Lavatory	Boiler Room Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	Boiler Room Toilet	1	EA	4	\$541	T12
	Walls - Metal Panel	Boiler Room Toilet	138	SF	5	\$4,221	peeling, water protrusion & holes
	Water Closet	Boiler Room Toilet	1	EA	4	\$7,669	missing

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Plaster/Drywall	1st Floor	5,397	SF	6	\$33,418	
	Doors - Side-lite	1st Floor	30	EA	6	\$502	
	Doors - Transom Window	1st Floor	88	EA	6	\$1,490	
	Doors - Wood Doors include hw	1st Floor	6	EA	6	\$1,806	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	6	\$1,103	
	Floor - Tile/Sheet	1st Floor	2	SF	5	\$12	
	Floor - Tile/Sheet	1st Floor	6,207	SF	6	\$3,373	
	Lighting - Pendent/Surface	1st Floor	50	EA	7	\$0	
	Stairs	1st Floor	4	LF	6	\$0	
	Walls - Plaster/Drywall	1st Floor	8,730	SF	6	\$38,700	
	Walls - Structural Glazed Tile	1st Floor	132	SF	6	\$415	
	Ceiling - Plaster/Drywall	2nd Floor	5,057	SF	6	\$31,312	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	6	\$1,103	
	Floor - Asphalt Floor	2nd Floor	5,057	SF	6	\$7,665	
	Lighting - Pendent/Surface	2nd Floor	38	EA	6	\$4,708	
	Walls - Plaster/Drywall	2nd Floor	7,957	SF	6	\$35,273	
	Ceiling - Plaster/Drywall	3rd Floor	5,169	SF	6	\$32,006	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	6	\$1,103	
	Floor - Asphalt Floor	3rd Floor	5,129	SF	6	\$7,775	



Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Lighting - Pendent/Surface	3rd Floor	40	EA	7	\$0	
	Stairs	3rd Floor	8	LF	6	\$0	
	Student Lockers - Two Tiers	3rd Floor	108	EA	6	\$5,013	
	Walls - Plaster/Drywall	3rd Floor	8,087	SF	6	\$35,850	
Safety							
	Metal Dedector	Entire Building / 1st Floor	1	EA	6	\$881	
	Security Cameras	Entire Building	4	EA	6	\$776	quantity is an estimate
	Security Cameras	Entire Building	6	EA	6	\$1,164	
Stairs							
	Ceiling - Plaster/Drywall	North East	452	SF	6	\$3,309	
	Floor - Asphalt	North East	360	SF	6	\$2,790	
	Handrails	North East	128	LF	6	\$1,109	
	Lighting - Pendent/Surface	North East	3	EA	7	\$0	
	Stairs - Asphalt	North East	64	LF	6	\$594	
	Walls - Plaster/Drywall	North East	2,470	SF	6	\$6,817	
	Ceiling - Plaster/Drywall	North West	452	SF	6	\$3,309	
	Floor - Asphalt	North West	360	SF	6	\$2,790	
	Handrails	North West	128	LF	6	\$1,109	
	Lighting - Pendent/Surface	North West	3	EA	7	\$0	
	Stairs - Asphalt	North West	64	LF	6	\$594	
	Walls - Plaster/Drywall	North West	2,470	SF	6	\$6,817	
	Ceiling - Plaster/Drywall	South East	400	SF	6	\$2,929	
	Floor - Asphalt	South East	360	SF	6	\$2,790	
	Handrails	South East	126	LF	6	\$1,092	
	Lighting - Pendent/Surface	South East	4	EA	7	\$0	
	Stairs - Asphalt	South East	64	LF	6	\$594	
	Walls - Plaster/Drywall	South East	2,622	SF	6	\$7,236	
	Ceiling - Plaster/Drywall	South West	400	SF	6	\$2,929	
	Floor - Asphalt	South West	360	SF	6	\$2,790	
	Handrails	South West	126	LF	6	\$1,092	
	Lighting - Pendent/Surface	South West	4	EA	7	\$0	
	Stairs - Asphalt	South West	64	LF	6	\$594	
	Walls - Plaster/Drywall	South West	2,622	SF	6	\$7,236	
Vertica	I Conveyance						
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	6	\$6,690	



Category:	Building	Interior

Group Item - Type	Location	Quantity Unit Rank Cost	Comments
Building Interior Subtotal:		\$310,658	
Total Building Cost		\$3,660,614	

Building: Addition

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
intrance								
Exterior Doors - Exterior FRP Door	#6.5 - W	2	EA	6	\$1,263			
Exterior Doors - Exterior FRP Door	#7 - SW	1	EA	6	\$631			
Exterior Doors - Exterior FRP Door	#8 - SE	1	EA	6	\$631			
Exterior Doors - Exterior FRP Door	#9 - SE	3	EA	6	\$1,894			
Exterior Doors - Transom Lite	#6.5 - W	2	EA	6	\$627			
Exterior Doors - Transom Lite	#7 - SW	1	EA	6	\$313			
Exterior Stairs - Concrete	#6.5 - W	15	LF	6	\$1,227			
Exterior Stairs - Concrete	#7 - SW	15	LF	6	\$1,227			
Exterior Stairs - Concrete	#8 - SE	16	LF	5	\$1,753	spalling		
Exterior Stairs - Concrete	#9 - SE	40	LF	5	\$4,383	spalling		
Exterior Stairs - Stone	#8 - SE	3	LF	6	\$339			
Exterior Stairs - Stone	#9 - SE	10	LF	6	\$1,130			
Ramp Handrail - Steel_Ramp Handrail	#6.5 - W	50	LF	6	\$433			
Ramp Handrail - Steel_Ramp Handrail	#7 - SW	80	LF	6	\$693			
Ramps - Concrete	#6.5 - W	25	LF	6	\$3,756			
Ramps - Concrete	#7 - SW	40	LF	6	\$6,009			
Stair Handrail - Steel_Stair Handrail	#6.5 - W	40	LF	6	\$347			
Stair Handrail - Steel_Stair Handrail	#7 - SW	25	LF	6	\$217			
Stair Handrail - Steel_Stair Handrail	#8 - SE	15	LF	4	\$2,254	missing		
Stair Handrail - Steel_Stair Handrail	#9 - SE	10	LF	6	\$87			
oundation								
Foundation - Concrete	Entire Building	503	LF	7	\$0			
Superstructure - Steel	Entire Building	34,396	SF	7	\$0			
ighting								
Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	\$5,365			
Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866			



Category: Building Exterior

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
of Sys	tem						
	Coping - Metal	Elevator roof	51	LF	6	\$1,638	
	Coping - Metal	Low SW roof	114	LF	6	\$3,661	
	Coping - Metal	Main Roof	461	LF	6	\$14,806	
	Downspouts - Exterior Downspouts	Elevator roof	6	LF	6	\$199	
	Downspouts - Interior Downspouts	Low SW roof	14	LF	6	\$465	
	Downspouts - Interior Downspouts	Main Roof	72	LF	6	\$2,393	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Elevator roof	189	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Low SW roof	1,975	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	10,744	SF	7	\$0	
	Roof - Modified Bitumen	Elevator roof	189	SF	5	\$3,976	poor seams, water ponding
	Roof - Modified Bitumen	Low SW roof	1,975	SF	5	\$41,545	poor seams, some water ponding
	Roof - Modified Bitumen	Main Roof	10,744	SF	5	\$226,003	poor seams, water ponding
alls							
	Canopy - Metal	Entire Building	115	SF	6	\$2,829	flaking paint
	Canopy - Metal	Entire Building	130	SF	6	\$2,792	
	Cheek-Wall - Concrete	Entire Building	16	SF	6	\$164	
	Exterior Walls - Brick	Entire Building	18,091	SF	6	\$121,590	some open joints
	Exterior Walls - Brick	Entire Building	4	SF	5	\$95	cracks, open joints
	Exterior Walls - Brick	Entire Building	10	SF	5	\$238	vertical cracks, spalling
	Exterior Walls - Brick	Entire Building / Main Entrance	3	SF	5	\$71	spalling, open joints
ndows							
	Curtain wall - Insulated Panel	Entire Building	704	SF	6	\$7,893	
	Curtain wall - Louver	Entire Building	357	SF	6	\$4,002	
	Guard - Guards perforated	Entire Building / 1st Floor	1,280	SF	6	\$16,345	
	Lintels - Steel	Entire Building	420	LF	6	\$12,192	
	Windows - Sash Aluminum Double-pane	Entire Building	3,360	SF	6	\$25,081	
		Entire Building / South Facade	160	SF	6	\$1,194	

Building: Addition

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System						
Emergency A/C Power - Corridors and Stairs	Entire Building	7,000	SF	6	\$2,102	
Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	1,724	SF	6	\$641	



Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Emergency A/C Power - Students Toilets	Entire Building	1,599	SF	6	\$595	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	7	\$0	
	Emergency Battery Packs - Lunchrooms	Entire Building / 1st Floor	2	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	7	\$0	
	Exit Signs - Lunchroom	Entire Building / 1st Floor	2	EA	7	\$0	
	Security System - CCTV	Entire Building	34,396	SF	6	\$10,329	
	Security System - Intrusion Detection	Entire Building	34,396	SF	6	\$8,854	
Main Se	ervice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	\$0	Meter#: 1745024266
	PA System	Entire Building	34,396	SF	6	\$11,313	Serves Both Buildings
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Location: Corridor
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Locaion: Corridor
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Location: Kitchen
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Location: Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Location: Lunchroom
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Location: Kitchen (Emergency Panel)
	Lighting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Equipment Room
	Lighting and Power Panels - 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	7	\$0	Location: Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 328
	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	4	\$6,578	
	Main Distribution Panels - 400 - 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Kitchen
	Main Distribution Panels - 400 - 600 amp	Entire Building / 1st Floor	1	EA	7	\$0	Location: Kitchen
	Main Distribution Panels - 400 - 600 amp	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Equipment Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / 2nd Floor	1	EA	7	\$0	Location: Equipment Room
	Main Distribution Panels - 400 - 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 324
	Main Distribution Panels - 400 - 600 amp	Entire Building / 3rd Floor	1	EA	7	\$0	Location: Room 324
	Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	1	EA	4	\$13,694	

Electrical System Subtotal:

\$89,779

Building: Addition Category: Safty System



John Fiske Elementary School

6020 S Langley Ave Chicago, IL 60637

Comments
Iso serves the Main Building

Safty System Subtotal:

\$35,426

Building: Addition

Category: Mechanical System

Group Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
Heating Devices							
Cabinet Heaters - With Ele	ctric Coil	Entire Building	18	EA	6	\$6,419	
Fin Tube - Electric		Entire Building	15	LF	6	\$142	
Wall Heater - Electric		1st Floor and Entire Building / 1st Floor	2	EA	5	\$1,073	
Wall Heater - Electric		1st Floor and Entire Building / Entire Building	12	EA	6	\$1,667	
Temperature Control							
DDC System		Entire Building	34,396	SF	5	\$56,564	
Thermostats - DDC		Entire Building	29	EA	4	\$23,755	control univents
Unit Ventilation							
Unit Ventilators- Floor Mour Self Contained Compresso	nted- Electric Heating & DX Cooling Coil W/	Entire Building	29	EA	6	\$36,184	
Unit Ventilators- Floor Mour Self Contained Compresso	nted- Electric Heating & DX Cooling Coil W/	Entire Building	5	EA	5	\$49,404	
Ventilation							
Ventilation Exhaust Fans- Roof Mounte	ed - 500 - 1500 CFM	Roof and 1st Floor Kitchen / Roof	5	EA	6	\$2,962	
Ventilation Exhaust Fans- Roof Mount Exhaust Fans- Roof Mount		Roof and 1st Floor Kitchen / Roof Roof and 1st Floor Kitchen / Roofs	5 1	EA EA	6 7	\$2,962 \$0	

Mechanical System Subtotal:

\$179,418

Building: Addition

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	34,396	SF	6	\$6,886	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	34,396	SF	6	\$8,362	
	Domestic Piping-Cold Water Risers	Entire Building	34,396	SF	6	\$6,394	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	34,396	SF	6	\$5,410	



Building: Addition

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	34,396	SF	6	\$6,394	
	Domestic Piping-Hot Water Return Lines	Entire Building	34,396	SF	6	\$4,919	
	Domestic Piping-Hot Water Return Risers	Entire Building	34,396	SF	6	\$4,919	
	Sanitary Piping	Entire Building	34,396	SF	6	\$31,479	
	Storm Piping	Entire Building	34,396	SF	6	\$30,004	
	Vent Piping	Entire Building	34,396	SF	6	\$23,118	
Plum	ing System Subtotal:					\$127,884	

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #122 (Pre School)						
	Casework	1st Floor	128	LF	6	\$3,232	
	Ceiling - Lay-in	1st Floor	1,050	SF	6	\$3,153	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,050	SF	6	\$2,297	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Storage/ Closet	1st Floor	44	SF	6	\$319	
	Student Lockers - One Tier	1st Floor	8	EA	6	\$743	
	Walls - Concrete Block	1st Floor	1,097	SF	6	\$3,216	
	Walls - Plaster/Drywall	1st Floor	33	SF	6	\$91	Lay-In ceiling tiles used on wall
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #124 (Kindergarten)						
	Casework	1st Floor	29	LF	6	\$732	
	Ceiling - Lay-in	1st Floor	1,140	SF	6	\$3,423	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,140	SF	6	\$2,494	
	Lighting - Lay-in	1st Floor	27	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Student Lockers - One Tier	1st Floor	8	EA	6	\$743	
	Walls - Concrete Block	1st Floor	1,241	SF	6	\$3,638	
	Walls - Plaster/Drywall	1st Floor	50	SF	6	\$138	lay-in tile over lockers
	Work Sink	1st Floor	2	EA	6	\$758	1 sink in base cabinet / 1 water fountain

Building: Addition

Group Item - Type Cotal Comments Classroom 221 (Regular Classroom) Camework 2nd Poor 78 8 5 5 52.20 Caller Call		Home Turne	Leasting	Ourseller	I losit	Daula	0	Commente
Casework 2nd Floor 16 LF 6 \$466 Calling - Lay-in 2nd Floor 76 5F 6 \$22.40 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Ploor 1 EA 6 \$301 \$501 \$501 Upfing - Lay-in 2nd Floor 12 EA 7 \$30 Walls - Concrete Block 2nd Floor 20 EA 7 \$30 Walls - Flaster/Dywall 2nd Floor 19 LF 6 \$480 Casework 2nd Floor 19 LF 6 \$480 Calling - Lay-in 2nd Floor 19 LF 6 \$480 Casework 2nd Floor 12 LF 6 \$2,294 Construct hw 2nd Floor 12 LF 6 \$2,294 Construct hw 2nd Floor 12 LF 6 \$2,294 Construct hw 2nd Floor 12 EA	-		Location	Quantity	Unit	Rank	Cost	Comments
Calling - Layin 2nd Floor 74 8F 6 \$22.40 Calling C- Layin 2nd Floor 1 6A 6 \$51.63 Floor - Tile 2nd Floor 70 2F 6 \$51.632 Lighting L-Jayin 2nd Floor 70 2F 6 \$52.697 Walle - Concrete Block 2nd Floor 70 2F 6 \$52.697 Walle - Concrete Block 2nd Floor 70 2F 6 \$52.497 Walle - Concrete Block 2nd Floor 70 2F 6 \$52.497 Calling L-Jayin 2nd Floor 71 2F 6 \$52.497 Calling L-Jayin 2nd Floor 71 2F 6 \$52.491 Consort M22 (Rogutar Classtroom) 2nd Floor 71 2F 6 \$52.491 Consort M22 (Rogutar Classtroom) 2nd Floor 71 2F 7 \$50 Consort M22 (Rogutar Classtroom) 2nd Floor 71 2F 6 \$52.41 Uphi	Classro	,						
Chaik Board2nd Floor1F451.63Doors inclu hw2nd Floor7657653.01Floor Tile2nd Floor20EA750.07Walls - Concrete Block2nd Floor200EA750.07Walls - Concrete Block2nd Floor200EA750.07Casework2nd Floor200EA654.097Casework2nd Floor764SF654.097Calling - Lay-in2nd Floor764SF654.017Chaik Board2nd Floor764SF654.017Chaik Board2nd Floor764SF654.017Doors - Wood Doors inclu hw2nd Floor704SF654.017Lighting - Lay-in2nd Floor704SF651.017Lighting - Lay-in2nd Floor716SF750Marke Board2nd Floor717LF750Student Lockers - One Tir2nd Floor712SF651.014Walls - Plaster/Drywall2nd Floor712SF651.024Walls - Plaster/Drywall2nd Floor712SF651.014Walls - Mater/Day2nd Floor712SF651.014Walls - Plaster/Drywall2nd Floor712SF651.014Walls - Mater/Day2nd Floor712SF651.014Walls - Mater/Day2nd Floor								
Doors Wood Doors incluitive 2nd Floor 1 EA 6 \$\$1,632 Lighting (-Layin) 2nd Floor 20 EA 7 \$0 Walls - Concrete Block 2nd Floor 20 EA 7 \$0 Walls - Concrete Block 2nd Floor 20 EA 6 \$2,097 Walls - Concrete Block 2nd Floor 45 6 \$2,294 Casework 2nd Floor 70 8 8 \$2,224 Chaik Board 2nd Floor 70 8 \$2,224 Chaik Board 2nd Floor 70 \$8 \$1,672 Chaik Board 2nd Floor 70 \$8 \$1,672 Chaik Board 2nd Floor 70 \$301 Floor - Tile 2nd Floor 70 \$160 Marke Board 2nd Floor 70 \$20 Walls - Concrete Block 2nd Floor 70 \$20 Walls - Concrete Block 2nd Floor 70 \$20 Walls - Concre								
Floor - Tile2nd Floor7405F6\$1,612Lighting - Lay-in2nd Floor2005F6\$2,637College - Concete Block2nd Floor2005F6\$2,848College - Concete Block2nd Floor5F6\$2,848College - Concete Block2nd Floor7615F6\$2,849College - Concete Block2nd Floor7645F6\$2,849College - Colspan="4">College - Colspan="4">College - Colspan="4">College - Colspan="4">Colspan="								
Lighting - Lay-in 2nd Floor 20 EA 7 S0 Walls - Concrete Block 2nd Floor 90 95 6 \$3.83 lay-in tile above lockers Classroom Casework 2nd Floor 76 \$5 6 \$5.224 Caling - Lay-in 2nd Floor 764 \$5 6 \$5.224 Doors - Wood Doors inclu hw 2nd Floor 764 \$5 6 \$5.172 Doors - Wood Doors inclu hw 2nd Floor 764 \$5 6 \$1.14 Floor - Tile 2nd Floor 71 \$5 \$5 6 \$1.14 Maker Board 2nd Floor 71 \$5 \$5 6 \$1.14 Maker Board 2nd Floor 71 \$5 \$5 6 \$1.31 Walls - Concrete Block 2nd Floor 72 \$5 6 \$1.32 Walls - Metal Panel 2nd Floor 72 \$5 6 \$1.33 lay-in tile above lockers Caling								
Walls - Concrete Block 2nd Floor 200 SF 6 \$2,637 Walls - Plaster/Dywall 2nd Floor 5F 6 \$2,138 kay-in the above lockers Construction 2nd Floor 16 1 1 6 \$4,40 Caling - Lay-in 2nd Floor 76 SF 6 \$2,234 Doors - Wood Doors inclu hw 2nd Floor 76 SF 6 \$2,324 Doors - Wood Doors inclu hw 2nd Floor 76 SF 6 \$2,301 Lighting - Lay-in 2nd Floor 76 SF 6 \$1,672 5 Marker Board 2nd Floor 77 SF 6 \$1,673 5 Marker Board 2nd Floor 71 LF 7 S0 5 Walls - Concrete Block 2nd Floor 715 SF 6 \$1,313 kay-in the above lockers Walls - Meat Panel 2nd Floor 715 SF 6 \$1,314 jau-in the above lockers Caing - Lay-in					-			
Walls - Plaster/Dywall 2nd Floor SF 6 \$138 lay-in the above lockers Casework 2nd Floor 19 LF 6 \$400 Caling - Lay-in 2nd Floor 23 LF 4 \$2,214 Chark Board 2nd Floor 23 LF 4 \$2,112 Doors - Wood Doors inclut hw 2nd Floor 74 SF 6 \$2,167 Doors - Wood Doors inclut hw 2nd Floor 74 SF 6 \$1,672 Lighting - Lay-in 2nd Floor 74 SF 6 \$1,672 Marker Board 2nd Floor 7 S0 \$1,672 \$1,672 Student Lockers - One Tier 2nd Floor 72 SF 6 \$2,087 Walls - Meal Panel 2nd Floor 28 S 6 \$1,314 ay-in tile above lockers Walls - Plaster/Dywall 2nd Floor 19 LF 6 \$1,324 ay-in tile above lockers Casework 2nd Floor 19 LF								
Variation of the second						6	\$2,697	
Casework 2nd Floor 19 LF 6 \$429 Celling - Lay-in 2nd Floor 724 SF 6 \$2294 Dors - Wood Doors inclu hw 2nd Floor 72 SF 6 \$22112 Dors - Wood Doors inclu hw 2nd Floor 74 SF 6 \$301 Floor - Tile 2nd Floor 76 SF 6 \$11672 Lighting - Lay-in 2nd Floor 70 SF 6 \$11672 Marker Board 2nd Floor 72 SF 6 \$2114 Walls - Ocnerete Block 2nd Floor 712 SF 6 \$21674 Walls - Meal Panel 2nd Floor 72 SF 6 \$2174 Walls - Plaster/Dynwall 2nd Floor 728 SF 6 \$21764 Celling - Lay-in 2nd Floor 799 SF 6 \$21764 Colling - Lay-in 2nd Floor 798 SF 6 \$2179 Colling - Lay-in 2nd Floor		Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	lay-in tile above lockers
Ceiling - Lay-in 2nd Floor 764 SF 6 \$2,294 Chaik Board 2nd Floor 1 E 4 \$2,112 Doors Wood Doors inclu hw 2nd Floor 1 E 6 \$301 Floor - Tile 2nd Floor 764 SF 6 \$51,672 Lighting - Lay-in 2nd Floor 712 SF 6 \$51,071 Marker Board 2nd Floor 12 EA 6 \$51,174 Student Lockers - One Tier 2nd Floor 12 SF 6 \$51,474 Walls - Concrete Block 2nd Floor 712 SF 6 \$51,474 Walls - Metal Panel 2nd Floor 205 SF 6 \$51,374 Walls - Plaster/Drywall 2nd Floor 705 SF 6 \$51,374 Ceiling - Lay-in 2nd Floor 79 SF 6 \$2,279 Chaik Board 2nd Floor 19 LF 4 \$51,836 Doors - Wood Doors inclu hw	Classro	oom #222 (Regular Classroom)						
Chaik Board 2nd Floor 23 LF 4 \$2,112 Doors - Wood Doors inclu hw 2nd Floor 64 \$56 6 \$1,612 Lighting - Lay-in 2nd Floor 20 EA 7 \$00 Marker Board 2nd Floor 17 LF 7 \$00 Student Lockers - One Tier 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 205 SF 6 \$2,087 Walls - Metal Panel 2nd Floor 205 SF 6 \$1318 lay-in tile above lockers Casework 2nd Floor 701 SF 6 \$2,087 Celling - Lay-in 2nd Floor 75 SF 6 \$2,081 Colarson Wood Doors inclu hw 2nd Floor 70 \$26 \$301 Floor - Tile 2nd Floor 75 SF 6 \$310 Colarson Mode Doors inclu hw 2nd Floor 75 \$5 6 \$310		Casework	2nd Floor	19	LF	6	\$480	
Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Tile 2nd Floor 764 SF 6 \$1,672 Lighting - Lay-in 2nd Floor 2nd Floor 7 SO Marker Board 2nd Floor 17 LF 7 SO Student Lockers - One Tier 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 225 SF 6 \$1,54 Walls - Metal Panel 2nd Floor 205 SF 6 \$1,54 Casework 2nd Floor 19 LF 6 \$1,54 Casework 2nd Floor 19 LF 6 \$22,75 Chark Board 2nd Floor 19 LF 6 \$24,75 Chark Board 2nd Floor 19 LF 6 \$301 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Tile 2nd Floor 1 EA 6 \$31,41 Marker Board 2nd Floor 1 EA <td></td> <td>Ceiling - Lay-in</td> <td>2nd Floor</td> <td>764</td> <td>SF</td> <td>6</td> <td>\$2,294</td> <td></td>		Ceiling - Lay-in	2nd Floor	764	SF	6	\$2,294	
Floor - Tile 2nd Floor 764 SF 6 \$1,672 Lighting - Lay-in 2nd Floor 20 EA 7 S0 Marker Board 2nd Floor 17 LF 7 S0 Student Lockers - One Tier 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 215 6 \$2,087 Walls - Metal Panel 2nd Floor 235 5 6 \$1,314 Walls - Plaster/Dywall 2nd Floor 235 5 6 \$2,087 Casswork 2nd Floor 29 SF 6 \$440 Ceiling - Lay-in 2nd Floor 19 LF 6 \$440 Doors - Wood Doors inclu hw 2nd Floor 20 LF 4 \$1,852 Doors - Wood Doors inclu hw 2nd Floor 20 LF 4 \$1,851 Lighting - Lay-in 2nd Floor 18 LF 7 \$00 Student Lockers - One Tier 2nd Floor		Chalk Board	2nd Floor	23	LF	4	\$2,112	
Lighting - Lay-in 2nd Floor 2nd Floor 7 \$0 Marker Board 2nd Floor 17 E 7 \$0 Student Lockers - One Tier 2nd Floor 12 E 6 \$1,114 Walls - Concrete Block 2nd Floor 12 E 6 \$2,087 Walls - Detate/Dryvall 2nd Floor 205 6 \$2,1754 Walls - Plater/Dryvall 2nd Floor 205 6 \$2,087 Classroom Classroom Classroom Ceiling - Lay-in 2nd Floor 79 \$F 6 \$400 Coling - Lay-in 2nd Floor 70 \$F 6 \$130 Doors - Wood Doors inclu hw 2nd Floor 7 \$6 \$130 Floor 716 \$F 6 \$161 Lighting - Lay-in 2nd Floor 7 \$10 \$161 Lighting - Lay-in 2nd Floor 18 \$F 7 \$0 Student Lockers - One Tier 2nd Floor 12 \$F 6 \$1,114 <		Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Marker Board 2nd Floor 17 LF 7 \$0 Student Lockers - One Tier 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 72 SF 6 \$2,087 Walls - Metal Panel 2nd Floor 235 SF 6 \$1,754 Walls - Metal Panel 2nd Floor 55 6 \$138 lay-in tile above lockers Classroom#224 (Regular Classroom) 55 6 \$48.09 \$48.00 \$48.00 Ceiling - Lay-in 2nd Floor 19 LF 6 \$2,279 \$55.00 6 \$2,279 Chak Board 2nd Floor 19 LF 6 \$2,279 \$55.00 6 \$2,279 Chak Board 2nd Floor 18 EA 6 \$2,279 \$55.00 6 \$2,279 Chak Board 2nd Floor 18 EA 7 \$50.00 \$55.00 \$55.00 \$55.00 \$55.00 \$55.00 \$55.00 \$55.00 \$55.00<		Floor - Tile	2nd Floor	764	SF	6	\$1,672	
Student Lockers - One Tier 2nd Floor 12 FA 6 \$1,14 Walls - Concrete Block 2nd Floor 712 SF 6 \$2,087 Walls - Plaster/Drywall 2nd Floor 235 SF 6 \$1,754 Walls - Plaster/Drywall 2nd Floor 205 SF 6 \$138 lay-in tile above lockers Casework Ceiing - Lay-in 2nd Floor 19 LF 6 \$42279 Chalk Board 2nd Floor 19 LF 6 \$4301 Doors - Wood Doors inclu hw 2nd Floor 10 LF 4 \$1,836 Floor - Tile 2nd Floor 10 LA 5 \$1,836 Lighting - Lay-in 2nd Floor 79 SF 6 \$1,114 Marker Board 2nd Floor 18 LF 7 \$00 Marker Board 2nd Floor 18 LF 7 \$1,144 Walls - Concrete Block 2nd Floor 705 SF 6 \$1,114 Walls - Master/Drywall 2nd Floor 18 <td< td=""><td></td><td>Lighting - Lay-in</td><td>2nd Floor</td><td>20</td><td>EA</td><td>7</td><td>\$0</td><td></td></td<>		Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
Walls - Concrete Block2nd Floor712SF6\$2,087Walls - Metal Panel2nd Floor235SF6\$1,754Walls - Plaster/Drywall2nd Floor50SF6\$138 Casework Casework2nd Floor19LF6\$480Chalk Board2nd Floor709SF6\$2,279Chalk Board2nd Floor700LF4\$1,836Doors - Wood Doors inclu hw2nd Floor700LF4\$1,836Floor - Tile2nd Floor759SF6\$3,011Lighting - Lay-in2nd Floor759SF6\$1,611Adriker Board2nd Floor759SF6\$1,611Jud Floor2nd Floor759SF6\$1,611Highting - Lay-in2nd Floor705SF6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Matal Panel2nd Floor705SF6\$1,134Walls - Matal Panel2nd Floor705SF6\$1,379Walls - Matal Panel2nd Floor705SF6\$1,379Walls - Matal Panel2nd Floor705SF6\$1,379Walls - Matal Panel2nd Floor705SF6\$1,379Walls - Plaster/Drywall2nd Floor705SF6\$1,379Walls - Plaster/Drywall2nd Floor705SF <t< td=""><td></td><td>Marker Board</td><td>2nd Floor</td><td>17</td><td>LF</td><td>7</td><td>\$0</td><td></td></t<>		Marker Board	2nd Floor	17	LF	7	\$0	
Walls - Metal Panel2nd Floor235SF6\$1,754Walls - Plaster/Drywall2nd Floor50SF6\$133lay-in tile above lockersClassroom#224 (Regular ClassroomCasework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor759SF6\$2,279Chalk Board2nd Floor20LF4\$1,836Doors - Wood Doors inclu hw2nd Floor759SF6\$1,661Floor - Tile2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor759SF6\$1,616Harker Board2nd Floor759SF6\$1,616Joors - Wood Doors inclu hw2nd Floor759SF6\$1,616Highting - Lay-in2nd Floor18LF7\$00Marker Board2nd Floor18LF7\$00Marker Board2nd Floor18LF7\$00Student Lockers - One Tier2nd Floor18LF7\$00Malls - Concrete Block2nd Floor233SF6\$1,714Walls - Plaster/Drywall2nd Floor5556\$1,318Walls - Plaster/Drywall2nd Floor5556\$1,318Walls - Plaster/Drywall2nd Floor5556\$1,318Walls - Plaster/Drywall2nd Floor5556\$1,318 <trr>Walls - Plaster</trr>		Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
Walls - Plaster/Drywall2nd Floor50SF6\$13.8lay-in tile above lockersClassroom #224 (Regular Classroom)Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor20LF4\$1,836Chalk Board2nd Floor20LF4\$1,836Doors - Wood Doors inclu hw2nd Floor20LF4\$1,836Floor - Tile2nd Floor759SF6\$301Floor - Tile Aug-in2nd Floor20EA7\$00Marker Board2nd Floor20EA7\$00Marker Board2nd Floor10EA6\$1,114Walls - Concrete Block2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor12EA6\$1,739Walls - Plaster/Drywall2nd Floor13SF6\$1,739Walls - Plaster/Drywall2nd Floor203SF6\$1,739Walls - Plaster/Drywall2nd Floor203SF6\$1,739Casework2nd Floor203SF6\$1,739Walls - Plaster/Drywall2nd Floor203SF6\$1,739Casework2nd Floor556\$1,308Iuter above lockersCasework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor1		Walls - Concrete Block	2nd Floor	712	SF	6	\$2,087	
Classroom Classroom Casework 2nd Floor 9 LF 6 \$480 Ceiling - Lay-in 2nd Floor 759 SF 6 \$2,279 Chalk Board 2nd Floor 20 LF 4 \$1,836 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Tile 2nd Floor 759 SF 6 \$1,611 Lighting - Lay-in 2nd Floor 759 SF 6 \$1,611 Lighting - Lay-in 2nd Floor 78 SF 6 \$1,611 Marker Board 2nd Floor 18 LF 7 \$0 Student Lockers - One Tier 2nd Floor 12 EA 6 \$1,114 Walls - Concrete Block 2nd Floor 12 EA 6 \$1,138 Walls - Plaster/Drywall 2nd Floor 123 SF 6 \$1,38 Walls - Plaster/Drywall 2nd Floor 50 SF 6 \$138 Walls - Plaster/Drywall 2nd Floor 19		Walls - Metal Panel	2nd Floor	235	SF	6	\$1,754	
Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor759SF6\$2,279Chalk Board2nd Floor20LF4\$1,836Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Tile2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor18LF7\$0Marker Board2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor12EA6\$1,114Walls - Metal Panel2nd Floor23SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersCasework2nd Floor19LF6\$480Casework2nd Floor753SF6\$1,739Casework2nd Floor50SF6\$138lay-in tiles above lockersCasework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	lay-in tile above lockers
Ceiling - Lay-in2nd Floor759SF6\$2,279Chalk Board2nd Floor2nd Floor2ndLF4\$1,836Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Tile2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor2nd Floor2ndEA7\$0Marker Board2nd Floor2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor2nd Floor2nd FloorSF6\$1,739Walls - Plaster/Drywall2nd Floor2nd FloorSF6\$1,318lay-in tiles above lockersCasework2nd Floor19LF6\$480Casework2nd Floor19LF6\$42,01Casework2nd Floor19LF6\$42,01Casework2nd Floor19LF6\$480Casework2nd	Classro	oom #224 (Regular Classroom)						
Chalk Board2nd Floor2nd Floor2nd Floor2nd Floor1EA6\$301Doors - Wood Doors inclu hw2nd Floor2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor2nd Floor20EA7\$0Marker Board2nd Floor2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor2nd Floor2nd FloorSF6\$1,739Walls - Plaster/Drywall2nd Floor2nd FloorSF6\$1,38Iay-in tiles above lockersCasework2nd Floor2nd Floor19LF6\$480Walls - Concrete Block2nd Floor2nd FloorSF6\$2,067Walls - Plaster/Drywall2nd Floor2nd FloorSF6\$1,739Walls - Plaster/Drywall2nd Floor2nd FloorSF6\$138Casework2nd Floor2nd FloorSF6\$138Casework2nd Floor19LF6\$480Casework2nd Floor19LF6\$480Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Casework	2nd Floor	19	LF	6	\$480	
Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Tile2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor2nd Floor20EA7\$0Marker Board2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersCassework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Ceiling - Lay-in	2nd Floor	759	SF	6	\$2,279	
Floor - Tile2nd Floor759SF6\$1,661Lighting - Lay-in2nd Floor20EA7\$0Marker Board2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor556\$138lay-in tiles above lockersCasework2nd Floor19LF6\$480Casework2nd Floor19SF6\$2,261		Chalk Board	2nd Floor	20	LF	4	\$1,836	
Lighting - Lay-in2nd Floor20EA7\$0Marker Board2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroomCasework2nd Floor19LF6\$480Caling - Lay-in2nd Floor19SF6\$2,261		Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Marker Board2nd Floor18LF7\$0Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroom#226 (Regular Classroom)Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Floor - Tile	2nd Floor	759	SF	6	\$1,661	
Student Lockers - One Tier2nd Floor12EA6\$1,114Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroomCasework2nd Floor19LF6\$480Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
Walls - Concrete Block2nd Floor705SF6\$2,067Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroom #226 (Regular Classroom)Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Marker Board	2nd Floor	18	LF	7	\$0	
Walls - Metal Panel2nd Floor233SF6\$1,739Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroom #226 (Regular Classroom)Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
Walls - Plaster/Drywall2nd Floor50SF6\$138lay-in tiles above lockersClassroom #226 (Regular Classroom)Casework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Walls - Concrete Block	2nd Floor	705	SF	6		
ClassroomCasework2nd Floor19LF6\$480Ceiling - Lay-in2nd Floor753SF6\$2,261		Walls - Metal Panel	2nd Floor	233	SF	6	\$1,739	
Casework 2nd Floor 19 LF 6 \$480 Ceiling - Lay-in 2nd Floor 753 SF 6 \$2,261		Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	lay-in tiles above lockers
Casework 2nd Floor 19 LF 6 \$480 Ceiling - Lay-in 2nd Floor 753 SF 6 \$2,261	Classro	oom #226 (Regular Classroom)						
			2nd Floor	19	LF	6	\$480	
		Ceiling - Lay-in	2nd Floor	753	SF	6	\$2,261	
			2nd Floor		LF	4		

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Pank	Cost	Comments
-	om #226 (Regular Classroom)	Eocation	Quantity	Unit	Marik	0031	Comments
Classion	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	753	SF	6	\$301 \$1,647	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$1,047 \$0	
	Marker Board	2nd Floor	20 17		7	\$0 \$0	
	Student Lockers - One Tier	2nd Floor	17	EA	6	₄₀ \$1,114	
	Walls - Concrete Block	2nd Floor	934	SF	6	\$1,114 \$2,738	
	Walls - Plaster/Drywall	2nd Floor	934 50	SF	6		lay-in tile above lockers
		2110 11001	50	5	0	φ130	lay-in the above lockers
Classro	om #227 (Regular Classroom)						
	Casework	2nd Floor	22	LF	6	\$556	
	Ceiling - Lay-in	2nd Floor	731	SF	6	\$2,195	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	731	SF	6	\$1,599	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
	Walls - Concrete Block	2nd Floor	909	SF	6	\$2,665	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	Lay-in tiles above lockers
Classro	om #228 (Regular Classroom)						
	Casework	2nd Floor	19	LF	6	\$480	
	Ceiling - Lay-in	2nd Floor	739	SF	6	\$2,219	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	739	SF	6	\$1,617	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
	Walls - Concrete Block	2nd Floor	919	SF	6	\$2,694	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	lay-in tiles above lockers
Classro	om #229 (Office)						
	Casework	2nd Floor	18	LF	6	\$455	
	Ceiling - Lay-in	2nd Floor	708	SF	6	\$2,126	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	708	SF	6	\$1,549	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	



Building: Addition

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	om #229 (Office)						
	Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
	Walls - Concrete Block	2nd Floor	910	SF	6	\$2,668	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	\$138	lay-in tiles over lockers
assro	om #321 (Regular Classroom)						
	Casework	3rd Floor	18	LF	6	\$455	
	Ceiling - Lay-in	3rd Floor	743	SF	6	\$2,231	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	743	SF	6	\$1,626	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	12	EA	6	\$1,114	
	Walls - Concrete Block	3rd Floor	918	SF	6	\$2,691	
	Walls - Plaster/Drywall	3rd Floor	50	SF	6	\$138	lay-in tile over lockers
assro	om #324, 322 (Computer Lab)						
	Casework	3rd Floor	25	LF	6	\$631	
	Ceiling - Lay-in	3rd Floor	1,506	SF	6	\$4,523	
	Charging Station	3rd Floor	6	EA	6	\$2,908	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile	3rd Floor	1,506	SF	6	\$3,295	
	Lighting - Lay-in	3rd Floor	40	EA	7	\$0	
	Marker Board	3rd Floor	31	LF	7	\$0	
	Student Lockers - One Tier	3rd Floor	24	EA	6	\$2,228	
	Walls - Concrete Block	3rd Floor	1,861	SF	6	\$5,456	
	Walls - Metal Panel	3rd Floor	450	SF	6	\$3,359	Folding partition between Room 315 & 317
	Walls - Plaster/Drywall	3rd Floor	100	SF	6	\$276	lay-in tile over lockers
	Wireless System	3rd Floor	1	EA	6	\$372	
assro	om #326 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	755	SF	6	\$2,267	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	755	SF	6	\$1,652	
	Lighting - Lay-in	3rd Floor	20	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	766	SF	6	\$2,246	
	Walls - Plaster/Drywall	3rd Floor	215	SF	6	\$593	
	Wireless System	3rd Floor	1	EA	6	\$372	

Category: Classrooms

up Item - Ty	уре	Location	Quantity	Unit	Rank	Cost	Comments
ssroom #327	(Regular Classroom)						
Casewor	ŕk	3rd Floor	21	LF	6	\$530	
Ceiling -	- Lay-in	3rd Floor	736	SF	6	\$2,210	
Chalk Bo	bard	3rd Floor	20	LF	4	\$1,836	
Doors - \	Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - T	ile	3rd Floor	736	SF	6	\$1,610	
Lighting	- Lay-in	3rd Floor	20	EA	7	\$0	
Marker E	Board	3rd Floor	17	LF	7	\$0	
Student	Lockers - One Tier	3rd Floor	12	EA	6	\$1,114	
Walls - C	Concrete Block	3rd Floor	917	SF	6	\$2,688	
Walls - F	Plaster/Drywall	3rd Floor	50	SF	6	\$138	lay-in tile over locders
Work Sir	nk	3rd Floor	1	EA	6	\$379	
ssroom #328	(Regular Classroom)						
Casewor	ŕk	3rd Floor	18	LF	6	\$455	
Ceiling -	- Lay-in	3rd Floor	743	SF	6	\$2,231	
Doors - \	Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - T	ile	3rd Floor	743	SF	6	\$1,626	
Lighting	- Lay-in	3rd Floor	20	EA	7	\$0	
Marker E	Board	3rd Floor	36	LF	7	\$0	
Student	Lockers - One Tier	3rd Floor	12	EA	6	\$1,114	
Walls - C	Concrete Block	3rd Floor	926	SF	6	\$2,715	
Walls - F	Plaster/Drywall	3rd Floor	50	SF	6	\$138	lay-in tile over lockers
ssroom #329	(Store Room)						
Casewor	ŕk	3rd Floor	18	LF	6	\$455	
Ceiling -	- Lay-in	3rd Floor	708	SF	6	\$2,126	
Doors - \	Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - T	ile	3rd Floor	708	SF	6	\$1,549	
Lighting	- Lay-in	3rd Floor	20	EA	7	\$0	
Marker E	Board	3rd Floor	36	LF	7	\$0	
Student	Lockers - One Tier	3rd Floor	12	EA	6	\$1,114	
Walls - C	Concrete Block	3rd Floor	910	SF	6	\$2,668	
Walls - F	Plaster/Drywall	3rd Floor	50	SF	6	\$138	lay-in tiles over lockers
ssrooms	Subtotal:					\$168,743	

Building: Addition



John Fiske Elementary School

6020 S Langley Ave Chicago, IL 60637

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	strative Suites/Offices						
	Ceiling - Lay-in	1st - 127 Case Manager	358	SF	6	\$1,075	
	Ceiling - Lay-in	1st - 127 Case Manager	2	SF	5	\$16	tile damaged
	Doors - Wood Doors inclu hw	1st - 127 Case Manager	1	EA	6	\$301	
	Floor - Tile	1st - 127 Case Manager	360	SF	6	\$788	
	Lighting - Lay-in	1st - 127 Case Manager	10	EA	7	\$0	
	Power Distribution	1st - 127 Case Manager	2	EA	6	\$4,250	
	Walls - Concrete Block	1st - 127 Case Manager	748	SF	6	\$2,193	
	Walls - Plaster/Drywall	1st - 127 Case Manager	20	SF	6	\$55	lay-in tile over lockers
	Ceiling - Lay-in	1st - 129 Nurse	362	SF	6	\$1,087	
	Doors - Wood Doors inclu hw	1st - 129 Nurse	1	EA	6	\$301	
	Floor - Tile	1st - 129 Nurse	362	SF	6	\$792	
	Lighting - Lay-in	1st - 129 Nurse	10	EA	7	\$0	
	Power Distribution	1st - 129 Nurse	10	EA	6	\$21,249	
	Walls - Concrete Block	1st - 129 Nurse	753	SF	6	\$2,207	
	Walls - Plaster/Drywall	1st - 129 Nurse	15	SF	6	\$41	lay-in tile over lockers
	Ceiling - Lay-in	1st - Assistant Principal Office	297	SF	6	\$892	
	Doors - Wood Doors inclu hw	1st - Assistant Principal Office	2	EA	6	\$602	
	Floor - Tile	1st - Assistant Principal Office	297	SF	6	\$650	
	Lighting - Lay-in	1st - Assistant Principal Office	6	EA	7	\$0	
	Power Distribution	1st - Assistant Principal Office	9	EA	6	\$19,124	
	Storage/ Closet	1st - Assistant Principal Office	13	SF	6	\$94	
	Walls - Concrete Block	1st - Assistant Principal Office	893	SF	6	\$2,618	
	Work SInk	1st - Assistant Principal Office	1	EA	6	\$508	
	Ceiling - Lay-in	1st - Child Parent Center	247	SF	6	\$742	
	Ceiling - Lay-in	1st - Child Parent Center	4	SF	5	\$32	stained
	Doors - Wood Doors inclu hw	1st - Child Parent Center	2	EA	6	\$602	
	Floor - Tile	1st - Child Parent Center	251	SF	6	\$549	
	Lighting - Lay-in	1st - Child Parent Center	7	EA	7	\$0	
	Power Distribution	1st - Child Parent Center	4	EA	6	\$8,500	
	Walls - Concrete Block	1st - Child Parent Center	729	SF	6	\$2,137	
	Ceiling - Lay-in	1st - Main Office	359	SF	6	\$1,078	
	Doors - Side-lite	1st - Main Office	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	1st - Main Office	1	EA	6	\$301	
	Floor - Tile	1st - Main Office	359	SF	6	\$785	
	Lighting - Lay-in	1st - Main Office	6	EA	7	\$0	
	Power Distribution	1st - Main Office	12	EA	6	\$25,499	
	Walls - Concrete Block	1st - Main Office	729	SF	6	\$2,137	
	Walls - Plaster/Drywall	1st - Main Office	37	SF	6	\$102	lay-in tile over lockers
	Ceiling - Lay-in	1st - Principal Office inside Main Office	167	SF	6	\$502	
						+	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admin	istrative Suites/Offices						
	Floor - Tile	1st - Principal Office inside Main Office	167	SF	6	\$365	
	Lighting - Lay-in	1st - Principal Office inside Main Office	4	EA	7	\$0	
	Power Distribution	1st - Principal Office inside Main Office	4	EA	6	\$8,500	
	Walls - Concrete Block	1st - Principal Office inside Main Office	490	SF	6	\$1,436	
	Walls - Plaster/Drywall	1st - Principal Office inside Main Office	23	SF	6	\$63	lay-in tiles over lockers
	Ceiling - Lay-in	2nd - Teachers Lounge	262	SF	6	\$787	
	Doors - Wood Doors inclu hw	2nd - Teachers Lounge	2	EA	6	\$602	
	Floor - Tile	2nd - Teachers Lounge	262	SF	6	\$573	
	Lighting - Lay-in	2nd - Teachers Lounge	5	EA	7	\$0	
	Power Distribution	2nd - Teachers Lounge	6	EA	6	\$12,749	
	Walls - Concrete Block	2nd - Teachers Lounge	785	SF	6	\$2,301	
	Ceiling - Lay-in	3rd - Teachers Lounge	262	SF	6	\$787	
	Doors - Wood Doors inclu hw	3rd - Teachers Lounge	2	EA	6	\$602	
	Floor - Tile	3rd - Teachers Lounge	262	SF	6	\$573	
	Lighting - Lay-in	3rd - Teachers Lounge	5	EA	7	\$0	
	Power Distribution	3rd - Teachers Lounge	6	EA	6	\$12,749	
	Walls - Concrete Block	3rd - Teachers Lounge	787	SF	6	\$2,307	
Kitche	n						
	Ceiling - Plaster/Drywall	1st Floor	879	SF	6	\$3,042	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	127	SF	6	\$278	
	Floor - Tile Ceramic/ Porcelain	1st Floor	752	SF	6	\$1,592	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
	Serving Line	1st Floor	20	LF	6	\$1,190	
	Storage/ Closet	1st Floor	210	SF	6	\$1,523	
	Walls - Structural Glazed Tile	1st Floor	1,064	SF	6	\$3,347	
Locker	/Shower Room						
	Ceiling - Plaster/ Drywall	1st - back of kitchen	63	SF	6	\$218	
	Doors - Wood Doors inclu hw	1st - back of kitchen	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st - back of kitchen	63	SF	6	\$133	
	Lighting - Pendent/Surface	1st - back of kitchen	1	EA	7	\$0	
	Student Lockers - One Tier	1st - back of kitchen	8	EA	6	\$743	
	Walls - Structural Glazed Tile	1st - back of kitchen	186	SF	6	\$585	
Lunch	& Multipurpose Room						
	Ceiling - Lay-in	1st - 128 Lunchroom	1,724	SF	6	\$5,177	
	Doors - Wood Doors inclu hw	1st - 128 Lunchroom	2	EA	6	\$602	double door



Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch	& Multipurpose Room						
	Floor - Tile	1st - 128 Lunchroom	1,724	SF	6	\$3,772	
	Lighting - Lay-in	1st - 128 Lunchroom	51	EA	7	\$0	
	Walls - Structural Glazed Tile	1st - 128 Lunchroom	1,664	SF	6	\$5,235	
MDF_I	DF						
	AC Unit	2nd Floor	1	EA	2	\$6,086	Improper bracing (plywood) & unusual insulation (mop heads)
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Finishes	2nd Floor	200	SF	6	\$1,427	
Mecha	nical/ Service Rooms						
	Janitor's Closet	1st Floor	55	SF	6	\$394	next to unisex bath
	Mechanical/ Service Rooms	1st Floor	200	SF	6	\$1,433	Electrical equiptment Room (N of 115)
	Vaults	1st Floor	66	SF	6	\$473	inside main office - used as storage
	Janitor's Closet	2nd Floor	55	SF	5	\$887	next to men staff bath / ceiling stained & peeling
	Storage Room	2nd Floor	286	SF	6	\$2,049	next to 229
	Janitor's Closet	3rd Floor	55	SF	6	\$394	next to unisex toilet
	Storage Room	3rd Floor	285	SF	6	\$2,042	next to classroom 329
	Storage Room	3rd Floor	198	SF	6	\$1,419	next to new stairs to old building adjacent to elevator
Restro	om						
	Accessories	1st - bath inside Assistant Principal Office	34	SF	6	\$314	
	Ceiling - Plaster/Drywall	1st - bath inside Assistant Principal Office	34	SF	6	\$118	
	Doors - Wood Doors inclu hw	1st - bath inside Assistant Principal Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st - bath inside Assistant Principal Office	34	SF	6	\$72	
	Lavatory	1st - bath inside Assistant Principal Office	1	EA	6	\$320	
	Lighting - Lay-in	1st - bath inside Assistant Principal Office	1	EA	7	\$0	
	Walls - Concrete Block	1st - bath inside Assistant Principal Office	197	SF	6	\$578	
	Water Closet	1st - bath inside Assistant Principal Office	1	EA	6	\$336	
	Accessories	1st - Boys Bath	277	SF	6	\$2,555	
	Ceiling - Plaster/Drywall	1st - Boys Bath	277	SF	6	\$959	
	Doors - Wood Doors inclu hw	1st - Boys Bath	1	EA	6	\$301	
	Floor Drain	1st - Boys Bath	1	EA	6	\$1,059	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estro	om						
	Floor - Tile Ceramic/ Porcelain	1st - Boys Bath	277	SF	6	\$586	
	Hand Dryer	1st - Boys Bath	2	EA	6	\$460	
	Lavatory	1st - Boys Bath	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st - Boys Bath	5	EA	7	\$0	
	Partitions	1st - Boys Bath	1	EA	6	\$297	
	Urinals	1st - Boys Bath	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	1st - Boys Bath	728	SF	6	\$2,290	
	Water Closet	1st - Boys Bath	2	EA	6	\$672	
	Accessories	1st - Girls Bath	256	SF	6	\$2,361	
	Ceiling - Plaster/Drywall	1st - Girls Bath	256	SF	6	\$886	
	Doors - Wood Doors inclu hw	1st - Girls Bath	1	EA	6	\$301	
	Floor Drain	1st - Girls Bath	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st - Girls Bath	256	SF	6	\$542	
	Hand Dryer	1st - Girls Bath	2	EA	6	\$460	
	Lavatory	1st - Girls Bath	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st - Girls Bath	5	EA	7	\$0	
	Partitions	1st - Girls Bath	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	1st - Girls Bath	592	SF	6	\$1,862	
	Water Closet	1st - Girls Bath	5	EA	6	\$1,680	
	Accessories	1st - inside Child Parent Center - used as storage	93	SF	6	\$858	
	Ceiling - Plaster/Drywall	1st - inside Child Parent Center - used as storage	93	SF	6	\$322	
	Doors - Wood Doors inclu hw	1st - inside Child Parent Center - used as storage	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st - inside Child Parent Center - used as storage	93	SF	6	\$197	
	Lavatory	1st - inside Child Parent Center - used as storage	1	EA	6	\$320	
	Lighting - Lay-in	1st - inside Child Parent Center - used as storage	1	EA	7	\$0	
	Partitions	1st - inside Child Parent Center - used as storage	1	EA	6	\$297	
	Walls - Concrete Block	1st - inside Child Parent Center - used as storage	324	SF	6	\$950	
	Water Closet	1st - inside Child Parent Center - used as storage	2	EA	5	\$2,688	broke
	Accessories	1st - inside Classroom 124	47	SF	6	\$434	
	Ceiling - Plaster/Drywall	1st - inside Classroom 124	47	SF	6	\$163	
	Doors - Wood Doors inclu hw	1st - inside Classroom 124	1	EA	6	\$301	



-	Item - Type	Location	Quantity	Unit	Rank	Rank Cost	Comments		
Restroc			,						
	Floor Drain	1st - inside Classroom 124	1	EA	6	\$1,059			
	Floor - Tile	1st - inside Classroom 124	47	SF	6	\$103			
	Lavatory	1st - inside Classroom 124	1	EA	6	\$320			
	Lighting - Pendent/Surface	1st - inside Classroom 124	1	EA	7	\$0			
	Walls - Concrete Block	1st - inside Classroom 124	230	SF	6	\$674			
	Water Closet	1st - inside Classroom 124	1	EA	6	\$336			
	Accessories	1st - inside locker room at back of kitchen	25	SF	6	\$231			
	Ceiling - Plaster/Drywall	1st - inside locker room at back of kitchen	25	SF	6	\$87			
	Doors - Wood Doors inclu hw	1st - inside locker room at back of kitchen	1	EA	6	\$301			
	Floor - Tile Ceramic/ Porcelain	1st - inside locker room at back of kitchen	25	SF	6	\$53			
	Lavatory	1st - inside locker room at back of kitchen	1	EA	6	\$320			
	Lighting - Wall Mounted	1st - inside locker room at back of kitchen	1	EA	7	\$0			
	Walls - Structural Glazed Tile	1st - inside locker room at back of kitchen	180	SF	6	\$566			
	Water Closet	1st - inside locker room at back of kitchen	1	EA	6	\$336			
	Accessories	1st - inside Main Office	46	SF	6	\$424			
	Ceiling - Plaster/Drywall	1st - inside Main Office	46	SF	6	\$159			
	Doors - Wood Doors inclu hw	1st - inside Main Office	1	EA	6	\$301			
	Floor - Tile Ceramic/ Porcelain	1st - inside Main Office	46	SF	6	\$97			
	Lavatory	1st - inside Main Office	1	EA	6	\$320			
	Lighting - Lay-in	1st - inside Main Office	1	EA	7	\$0			
	Walls - Concrete Block	1st - inside Main Office	233	SF	6	\$683			
	Water Closet	1st - inside Main Office	1	EA	6	\$336			
	Accessories	1st - Unisex Bath	61	SF	6	\$563			
	Ceiling - Plaster/Drywall	1st - Unisex Bath	61	SF	6	\$211			
	Doors - Wood Doors inclu hw	1st - Unisex Bath	1	EA	6	\$301			
	Floor - Tile Ceramic/ Porcelain	1st - Unisex Bath	61	SF	6	\$129			
	Lavatory	1st - Unisex Bath	1	EA	6	\$320			
	Lighting - Lay-in	1st - Unisex Bath	1	EA	7	\$0			
	Walls - Structural Glazed Tile	1st - Unisex Bath	263	SF	6	\$827			
	Water Closet	1st - Unisex Bath	1	EA	6	\$336			
	Accessories	1st- Inside room 122	47	SF	6	\$434			
	Ceiling - Plaster/Drywall	1st- Inside room 122	47	SF	6	\$163			



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro			-				
	Doors - Wood Doors inclu hw	1st- Inside room 122	1	EA	6	\$301	
	Floor Drain	1st- Inside room 122	1	EA	6	\$1,059	
	Floor - Tile	1st- Inside room 122	47	SF	6	\$103	
	Lavatory	1st- Inside room 122	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Inside room 122	1	EA	7	\$0	
	Walls - Concrete Block	1st- Inside room 122	227	SF	6	\$665	
	Water Closet	1st- Inside room 122	1	EA	6	\$336	
	Accessories	2nd - Boys Bath	277	SF	6	\$2,555	
	Ceiling - Plaster/Drywall	2nd - Boys Bath	277	SF	6	\$959	
	Doors - Wood Doors inclu hw	2nd - Boys Bath	1	EA	6	\$301	
	Floor Drain	2nd - Boys Bath	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd - Boys Bath	277	SF	6	\$586	
	Hand Dryer	2nd - Boys Bath	2	EA	6	\$460	
	Lavatory	2nd - Boys Bath	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd - Boys Bath	5	EA	7	\$0	
	Partitions	2nd - Boys Bath	1	EA	6	\$297	
	Urinals	2nd - Boys Bath	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	2nd - Boys Bath	728	SF	6	\$2,290	
	Water Closet	2nd - Boys Bath	2	EA	6	\$672	
	Accessories	2nd - Girls Bath	256	SF	6	\$2,361	
	Ceiling - Plaster/Drywall	2nd - Girls Bath	256	SF	6	\$886	
	Doors - Wood Doors inclu hw	2nd - Girls Bath	1	EA	6	\$301	
	Floor Drain	2nd - Girls Bath	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd - Girls Bath	256	SF	6	\$542	
	Hand Dryer	2nd - Girls Bath	2	EA	6	\$460	
	Lavatory	2nd - Girls Bath	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd - Girls Bath	5	EA	7	\$0	
	Partitions	2nd - Girls Bath	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	2nd - Girls Bath	592	SF	6	\$1,862	
	Water Closet	2nd - Girls Bath	5	EA	6	\$1,680	
	Accessories	2nd - Men staff Bath	61	SF	6	\$563	
	Ceiling - Plaster/Drywall	2nd - Men staff Bath	61	SF	6	\$211	
	Doors - Wood Doors inclu hw	2nd - Men staff Bath	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd - Men staff Bath	61	SF	6	\$129	
	Lavatory	2nd - Men staff Bath	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Men staff Bath	1	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd - Men staff Bath	263	SF	6	\$827	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Water Closet	2nd - Men staff Bath	1	EA	6	\$336	
	Accessories	2nd - Women bath inside Teachers Lounge	78	SF	6	\$719	
	Ceiling - Plaster/Drywall	2nd - Women bath inside Teachers Lounge	78	SF	6	\$270	
	Doors - Wood Doors inclu hw	2nd - Women bath inside Teachers Lounge	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd - Women bath inside Teachers Lounge	78	SF	6	\$165	
	Lavatory	2nd - Women bath inside Teachers Lounge	1	EA	6	\$320	
	Lighting - Lay-in	2nd - Women bath inside Teachers Lounge	1	EA	7	\$0	
	Lighting - Wall Mounted	2nd - Women bath inside Teachers Lounge	1	EA	6	\$124	no cover
	Partitions	2nd - Women bath inside Teachers Lounge	1	EA	6	\$297	
	Walls - Plaster/Drywall	2nd - Women bath inside Teachers Lounge	302	SF	6	\$833	
	Water Closet	2nd - Women bath inside Teachers Lounge	1	EA	6	\$336	
	Accessories	3rd - Boys Bath	277	SF	6	\$2,555	
	Ceiling - Plaster/Drywall	3rd - Boys Bath	277	SF	6	\$959	
	Doors - Wood Doors inclu hw	3rd - Boys Bath	1	EA	6	\$301	
	Floor Drain	3rd - Boys Bath	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd - Boys Bath	277	SF	6	\$586	
	Hand Dryer	3rd - Boys Bath	2	EA	6	\$460	
	Lavatory	3rd - Boys Bath	3	EA	6	\$959	
	Lighting - Pendent/Surface	3rd - Boys Bath	5	EA	7	\$0	
	Partitions	3rd - Boys Bath	1	EA	6	\$297	
	Urinals	3rd - Boys Bath	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	3rd - Boys Bath	724	SF	6	\$2,278	
	Water Closet	3rd - Boys Bath	2	EA	6	\$672	
	Accessories	3rd - Girls Bath	256	SF	6	\$2,361	
	Ceiling - Plaster/Drywall	3rd - Girls Bath	256	SF	6	\$886	
	Doors - Wood Doors inclu hw	3rd - Girls Bath	1	EA	6	\$301	
	Floor Drain	3rd - Girls Bath	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd - Girls Bath	256	SF	6	\$542	
	Hand Dryer	3rd - Girls Bath	2	EA	6	\$460	
	Lavatory	3rd - Girls Bath	3	EA	6	\$959	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	em - Type Location Q		Unit	Rank	Cost	Comments
Restroc	om de la companya de						
	Lighting - Pendent/Surface	3rd - Girls Bath	5	EA	7	\$0	
	Partitions	3rd - Girls Bath	4	EA	6	\$1,188	
	Walls - Structural Glazed Tile	3rd - Girls Bath	688	SF	6	\$2,164	
	Water Closet	3rd - Girls Bath	5	EA	6	\$1,680	
	Accessories	3rd - Men's Staff Bath	61	SF	6	\$563	
	Ceiling - Plaster/Drywall	3rd - Men's Staff Bath	61	SF	6	\$211	
	Doors - Wood Doors inclu hw	3rd - Men's Staff Bath	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd - Men's Staff Bath	61	SF	6	\$129	
	Lavatory	3rd - Men's Staff Bath	1	EA	6	\$320	
	Lighting - Lay-in	3rd - Men's Staff Bath	1	EA	7	\$0	
	Walls - Structural Glazed Tile	3rd - Men's Staff Bath	263	SF	6	\$827	
	Water Closet	3rd - Men's Staff Bath	1	EA	6	\$336	
	Accessories	3rd - women bath inside 3rd Teachers Lounge	78	SF	6	\$719	
	Ceiling - Plaster/Drywall	3rd - women bath inside 3rd Teachers Lounge	78	SF	6	\$270	
	Doors - Wood Doors inclu hw	3rd - women bath inside 3rd Teachers Lounge	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	3rd - women bath inside 3rd Teachers Lounge	78	SF	6	\$165	
	Lavatory	3rd - women bath inside 3rd Teachers Lounge	1	EA	6	\$320	
	Lighting - Lay-in	3rd - women bath inside 3rd Teachers Lounge	1	EA	7	\$0	
	Lighting - Wall Mounted	3rd - women bath inside 3rd Teachers Lounge	1	EA	7	\$0	
	Partitions	3rd - women bath inside 3rd Teachers Lounge	1	EA	6	\$297	
	Walls - Concrete Block	3rd - women bath inside 3rd Teachers Lounge	302	SF	6	\$885	
	Water Closet	3rd - women bath inside 3rd Teachers Lounge	2	EA	6	\$672	

Rooms (Other Than Classrooms) Subtotal:

\$293,376

Building: Addition

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Corridor			
Ceiling - Lay-in	1st Floor	1,957 SF 6	\$5,877



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Plaster/Drywall	1st Floor	263	SF	6	\$1,628	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	\$1,204	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	
	Floor - Terrazzo	1st Floor	889	SF	6	\$7,462	
	Floor - Tile Ceramic/ Porcelain	1st Floor	174	SF	6	\$485	
	Floor - Tile/Sheet	1st Floor	1,408	SF	6	\$765	
	Walls - Concrete Block	1st Floor	1,222	SF	6	\$3,582	
	Walls - Structural Glazed Tile	1st Floor	3,250	SF	6	\$10,225	
	Lighting - Lay-in	1st Floor	29	EA	7	\$0	
	Ceiling - Lay-in	2nd Floor	1,993	SF	6	\$5,985	
	Ceiling - Plaster/Drywall	2nd Floor	89	SF	6	\$551	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	6	\$551	
	Floor - Terrazzo	2nd Floor	665	SF	6	\$5,582	
	Floor - Tile/Sheet	2nd Floor	1,393	SF	6	\$757	
	Lighting - Lay-in	2nd Floor	29	EA	6	\$3,450	
	Stairs - Terrazzo	2nd Floor	6	LF	6	\$56	
	Walls - Concrete Block	2nd Floor	1,523	SF	6	\$4,465	
	Walls - Structural Glazed Tile	2nd Floor	2,395	SF	6	\$7,535	
	Ceiling - Lay-in	3rd Floor	2,082	SF	6	\$6,252	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	6	\$551	
	Floor - Terrazzo	3rd Floor	689	SF	6	\$5,784	
	Floor - Tile/Sheet	3rd Floor	1,393	SF	6	\$757	
	Lighting - Lay-in	3rd Floor	29	EA	7	\$0	
	Stairs - Terrazzo	3rd Floor	12	LF	6	\$111	
	Walls - Concrete Block	3rd Floor	1,523	SF	6	\$4,465	
	Walls - Structural Glazed Tile	3rd Floor	2,395	SF	6	\$7,535	
Safety							
	Camera Viewing Station	Entire Building	1	EA	6	\$683	viewed downtown
	Security Cameras	Entire Building	4	EA	6	\$776	qty is an estimate
	Security Cameras	Entire Building	3	EA	6	\$582	
Stairs							
	Ceiling - Lay-in	North East	287	SF	6	\$862	
	Ceiling - Plaster/Drywall	North East	106	SF	6	\$776	
	Floor - Terrazzo	North East	193	SF	6	\$1,620	
	Handrails	North East	118	LF	6	\$1,023	
	Lighting - Lay-in	North East	6	EA	7	\$0	



Category: Building Interior

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
irs									
Stairs - Terrazzo	North East	40	LF	6	\$371				
Walls - Structural Glazed Tile	North East	1,630	SF	6	\$5,128				
Ceiling - Lay-in	South East	287	SF	6	\$862				
Ceiling - Plaster/Drywall	South East	106	SF	6	\$776				
Floor - Terrazzo	South East	193	SF	6	\$1,620				
Handrails	South East	118	LF	6	\$1,023				
Lighting - Lay-in	South East	6	EA	7	\$0				
Stairs - Terrazzo	South East	40	LF	6	\$371				
Walls - Structural Glazed Tile	South East	1,630	SF	6	\$5,128				
tical Conveyance									
Elevator - Hydraulic Elevator	1st Floor	1	EA	6	\$19,238	Location: Elevator Room			
ilding Interior Subtotal:		\$127,005							

Total Building Cost

\$1,546,251

SITE

Category: Site

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ivil/Dra	ainage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	\$0	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	7	\$0	
encing							
	Fencing - Chain Link	Entire Site / Site West	141	LF	6	\$2,647	
	Fencing - Chain Link	Entire Site / Site West	50	LF	5	\$3,049	bent
	Fencing - New Standard Ornamental	Entire Site	1,227	LF	6	\$39,145	
andsca	ape						
	Benches	Entire Site / North East	2	EA	6	\$860	
	Landscape - Grass	Entire Site / Site North	6,793	SF	6	\$5,634	
	Landscape - Hardscape- Concrete	Entire Site	3,505	SF	6	\$18,094	Location: at trash enclosure
	Parkway trees	Entire Site	48	EA	6	\$31,682	
	Planting Beds/ Area	Entire Site / Site North	24	SF	6	\$39	
	Play Area - Asphalt/ Hardscape	Entire Site / Site - East	6,729	SF	6	\$18,764	
	Play Area - Asphalt/ Hardscape	Entire Site / Site South	16,376	SF	6	\$39,576	

SITE

Category: Site Group Item - Type Location Quantity Unit Rank **Cost Comments** Parking Lot Concrete Curbs NW parking lot 668 1 F 6 \$8.578 LF 6 \$2.553 Interior Plantings NW parking lot 60 NW parking lot Surface - Asphalt 10.511 SF 6 \$25.402 SF Trash Enclosure - Chain Links NW parking lot 3.505 5 \$111.019 bent poles Playground Equipment - Pre K 3-5 NE site 1 ΕA 6 \$3.546 Surface - Poured Surface NE site 1,479 SF 6 \$10.829 Sidewalks Sidewalks - Internal Walks Entire Site LF 5 Location: door 3 - cracks 20 \$1.155 Sidewalks - Internal Walks Entire Site 325 LF 6 \$3.904 SF Sidewalks - Perimeter Sidewalks Entire Site 11.461 6 \$22.781 Signage Flag Pole - Building Mounted Flag Pole Entire Site / East Facade ΕA 6 \$828 1 Marguee - Free Standing Back Lighted Entire Site / North East ΕA 6 \$0 1 Monument - Building Mounted Cut Letter Sign Entire Site / North ΕA 6 \$0 1 Site Subtotal: \$350,087 **Total Site Cost** \$350,087

C	Campus Total ^{2 3}	\$5,556,952

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.



- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main			-	-			1	· ·			_	1		4
Kindergarten	Regular Classroom	1st Floor	103	103	826	1	1	6	165	57	40	Ν	Y	Y
Kindergarten	Art Room	1st Floor	107	109	816	1	1	6	165	57	40	Ν	Y	Y
Music Room	Music Room	3rd Floor	309	314	1,482	1	1	6	440	88	40	Ν	Y	Y
Other Instructional Use	Regular Classroom	2nd Floor	204	201	653	1	1	6	198	57	40	Ν	Y	Ν
Pre School	Kindergarten	1st Floor	102	104	816	1	0	4	156	54	40	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	105	112	800	1	1	14	147	57	40	Ν	Y	Y
Regular Classroom	Kindergarten	1st Floor	108	108	805	1	1	10	165	57	40	Ν	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	205	820	1	1	4	198	57	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	202	204	816	1	1	4	198	57	40	Ν	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	816	1	1	4	198	57	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	205	212	810	1	1	4	198	57	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	206	210	816	3	1	8	198	57	40	Ν	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	209	816	1	1	4	165	57	40	Ν	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	800	1	1	10	165	57	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	301	305	824	2	2	8	198	54	40	Ν	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	302	304	824	1	1	6	198	54	40	Ν	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	824	1	1	4	156	54	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	305	312	819	3	4	8	198	54	40	Ν	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	309	817	3	3	8	198	54	40	Ν	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	826	2	3	20	198	54	40	Ν	Y	Y
Science	Regular Classroom	1st Floor	106	110	800	3	9	46	165	57	40	Ν	Y	Y
Science	Regular Classroom	3rd Floor	306	310	816	3	3	8	198	54	40	Ν	Y	Y
Special Program	Faculty Lounge	1st Floor	101	NA	615	1	0	6	509	170	40	Ν	N	Ν
Special Program	Regular Classroom	1st Floor	104	101	653	1	1	10	165	57	40	Ν	Y	Ν
Addition														
Computer Lab	Regular Classroom	3rd Floor	324, 322	317, 315	1,506	1	2	58	208	104	40	Ν	Y	Y
Computer Lab	Regular Classroom	3rd Floor	326	319	755	5	44	84	104	52	40	Ν	N	N
Kindergarten	Kindergarten	1st Floor	124	119	1,140	1	1	8	104	52	40	N	Y	Ν
Office	Regular Classroom	2nd Floor	229	220	708	1	1	4	104	52	40	N	N	Ν
Pre School	Kindergarten	1st Floor	122	115	1,050	1	1	10	90	45	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	221	216	746	1	1	6	104	52	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	222	215	764	1	1	6	104	52	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	224	217	759	1	1	4	104	52	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	226	219	753	1	1	4	104	52	40	N	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	227	218	731	1	1	4	104	33	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	228	221	739	1	1	4	104	52	40	N	Y	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Addition														
Regular Classroom	Regular Classroom	3rd Floor	321	316	743	1	1	4	104	52	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	327	318	736	1	1	6	104	52	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	328	321	743	1	1	4	104	52	40	Ν	Y	Ν
Store Room	Regular Classroom	3rd Floor	329	320	708	1	1	6	104	52	40	Ν	Y	Ν