

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1913	3	62,706	\$3,810,489
SITE				\$174,668
Campus Total			62,706	\$3,985,157

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	e						
	Entrance Control - Audio and Video	1 - Main	1	EA	7	\$0	
	Entrance Control - Audio and Video	2	1	EA	7	\$0	
	Entrance Control - Audio and Video	3	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	2	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	3	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	5	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	4	5	EA	5	\$6,707	deteriorated doors and frames
	Exterior Doors - Store Front	1 - Main	4	EA	7	\$0	
	Exterior Doors - Transom Lite	1 - Main	4	EA	7	\$0	
	Exterior Doors - Transom Lite	2	3	EA	6	\$940	
	Exterior Doors - Transom Lite	3	3	EA	6	\$940	
	Exterior Doors - Transom Lite	4	5	EA	6	\$1,567	
	Exterior Stairs - Concrete	1 - Main	16	LF	6	\$1,308	
	Exterior Stairs - Concrete	2	24	LF	6	\$1,962	
	Exterior Stairs - Concrete	3	36	LF	6	\$2,944	
	Exterior Stairs - Concrete	4	120	LF	6	\$9,812	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	50	LF	7	\$0	
	Ramps - Concrete	1 - Main	24	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	1 - Main	15	LF	7	\$0	



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Founda	ation						
	Foundation - Masonry	Entire Building	817	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	62,706	SF	7	\$0	
Lighting	a						
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	\$1,732	
Roof Sy	vstem	Ū.					
	Chimney - Brick Chimney- Stainless Steel Liner	A / East Façade	30	LF	4	\$159.553	vertical cracking, deteriorated mortar throughout
	Coping - Metal	A	108	LF	4	\$9,563	
	Coping - Metal	A	486	LF	5	\$20,544	
	Coping - Metal	В	60	LF	6	\$1,927	
	Coping - Stone	В	208	LF	6	\$6,681	
	Coping - Stone	С	203	LF	6	\$6,520	
	Downspouts - Interior Downspouts	А	348	LF	6	\$11,565	
	Downspouts - Interior Downspouts	В	52	LF	6	\$1,728	
	Downspouts - Interior Downspouts	С	54	LF	6	\$1,795	
	Parapet - 16" - 30" Height	А	122	LF	6	\$4,874	
	Parapet - 16" - 30" Height	В	218	LF	6	\$8,710	
	Parapet - 16" - 30" Height	С	84	LF	6	\$3,356	
	Parapet - Parapet < 16" Height	В	50	LF	6	\$1,065	
	Parapet - Parapet < 16" Height	C / East Façade	19	LF	6	\$405	
	Parapet - Parapet > 30"	A	100	LF	4	\$107,440	spalled, deteriorating masonry and mortar throughout
	Parapet - Parapet > 30"	A	372	LF	6	\$23,779	-
	Parapet - Parapet > 30"	С	100	LF	6	\$6,392	
	Roof Structure - Steel with Clay Tile Arch	А	50,388	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	В	8,178	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	С	4,140	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	A	50,388	SF	6	\$512,310	
	Roof - Asphalt Gravel Ballast	B / South	50	SF	4	\$1,401	leaking into gym
	Roof - Asphalt Gravel Ballast	С	4,140	SF	6	\$42,093	
	Roof - Asphalt Shingle	В	8,128	SF	6	\$37,310	
Walls							
	Cheek-Wall - Stone	Entire Building	135	SF	6	\$1,384	
	Cornice - Cast Stone	Entire Building / Lower Roofs	225	LF	6	\$7,802	
	Cornice - Masonry Projecting Limestone	Entire Building	594	LF	5	\$88,493	
	Exterior Walls - Brick	Entire Building	35,782	SF	7	\$0	



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Exterior Walls - Brick	Entire Building	5	SF	4	\$823	step crack, deteriorated mortar
	Exterior Walls - Brick	Entire Building / East Façade	100	SF	5	\$2,381	
	Exterior Walls - Stone-Cast	Entire Building	3,268	SF	6	\$21,964	
Windo	ws						
	Guard - Guards perforated	Entire Building	1,691	SF	5	\$25,922	
	Guard - Guards wire guard	Entire Building / East Façade	21	SF	6	\$268	louver
	Lintels - Steel	Entire Building	427	LF	7	\$0	
	Lintels - Steel	Entire Building	300	LF	5	\$101,390	corroded
	Storefront Windows	Entire Building / Boiler Room	81	SF	6	\$908	
	Windows - Louver	Entire Building / East Façade	114	SF	6	\$851	
	Windows - Sash Aluminum Double-pane	Entire Building	5,789	SF	6	\$43,213	steel

Building Exterior Subtotal:

\$1,296,552

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Mechanical Room / Electrical Room	2	EA	7	\$0	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,464	SF	6	\$3,443	
	Emergency A/C Power - Gym	Entire Building / 1st Floor	5,611	SF	6	\$2,086	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	8	EA	6	\$1,620	
	Emergency Battery Packs - Gym	Entire Building / 1st Floor	3	EA	6	\$608	
	Emergency Generator- Indoor- Natural Gas - Below 60 KW	Generator Room / Mechanical Room	1	EA	6	\$6,086	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	7	\$0	
	Exit Signs - Gym	Entire Building / 1st Floor	6	EA	7	\$0	
	Exit Signs - Lunchroom	Entire Building / 1st Floor	2	EA	7	\$0	
	Security System - CCTV	Boiler Room / Entire Building	62,706	SF	6	\$18,831	4 cameras total, all functional
	Security System - Intrusion Detection	Boiler Room / Entire Building	62,706	SF	6	\$16,141	
/lain S	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	Note: Existing meter was replaced with new
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	4	\$39,073	Old panel, deteriorated
	PA System	1st Floor / Entire Building	62,706	SF	6	\$20,624	



Building: Main

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	6	\$299	
Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Switches covered with tape, box deformed
Lighting and Power Panels - 100 A	Entire Building	5	EA	6	\$1,496	
Lighting and Power Panels - 100 A	Entire Building	2	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Entire Building / Mechanical Room	5	EA	7	\$0	
Main Distribution Panels - 400 - 600 amp	Entire Building / Mechanical Room	2	EA	6	\$1,055	
Main Distribution Panels - Greater than 600 amp	Entire Building / Mechanical Room	1	EA	7	\$0	
Main Distribution Panels - Less than 400 amp	Entire Building / Mechanical Room	1	EA	7	\$0	
Main Distribution Panels - Less than 400 amp	Entire Building / Mechanical Room	1	EA	6	\$503	

Electrical System Subtotal:

\$119,784

Building: Main

Category: Safty System

roup Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
re Alarm						
Fire Alarm Panel	Boiler Room / Mechanical Room	1	EA	6	\$6,406	
Fire Alarm_System	Boiler Room / Entire Building	62,706	SF	6	\$30,488	

Safty System Subtotal:

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Pressure Fill System	Boiler Room	1	EA	6	\$1,405	Applies to boiler system, not chilled water system.
Air Han	dling Systems						
	Air Handling Unit- Built Up- Multi Zone- Hot Water Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	\$78,608	Motor old, fan housing deteriorated, all rooms need to be sealed
	Air Handling Unit- Built Up- Multi Zone- Hot Water Coils $$ - Greater than 35000 cfm	Mechanical Room	1	EA	5	\$95,595	Motor old, fan housing deteriorated, all rooms need to be sealed
	Air Intake	Mechanical Room / Central Courtyard	2	EA	5	\$14,941	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	2	EA	5	\$33,155	
	Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM	Roof	1	EA	6	\$2,077	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	60	LF	7	\$0	



Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Hanc	dling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - Less than 5 tons	Roof	1	EA	6	\$1,265	
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - Less than 5 tons	Roof	1	EA	6	\$1,265	
	Zone Dampers	Mechanical Room / Entire Building	32	EA	6	\$26,657	No known issues according to building engineer
Boiler S	systems						
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	\$1,996	
	Chemical Pot Feeder	Boiler Room	1	EA	5	\$1,685	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Hot Water Pump	Boiler Room	2	EA	6	\$748	
	Hot Water Pump	Boiler Room	2	EA	6	\$748	
	Non Condensing- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	7	\$0	
Gas Boo	oster						
	Gas Booster	Mechanical Room	3	EA	5	\$37,779	
Heating	Devices						
	Fin Tube - Electric	Entire Building	34	LF	6	\$321	
	Unit Heater - Gas	Boiler Room	1	EA	4	\$3,234	
	Wall Heater - Electric	Entire Building / 1st Floor	1	EA	5	\$537	
	Wall Heater - Electric	Entire Building / 1st Floor	1	EA	4	\$1,083	Cover Removed
	Wall Heater - Electric	Entire Building	6	EA	7	\$0	
	Wall Heater - Electric	Entire Building	4	EA	6	\$556	
Mechan	ical Plumbing						
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	\$2,485	
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	\$2,222	
	Hydronic Supply and Return - Galvanized	Entire Building	300	LF	6	\$23,196	
Tempera	ature Control						
	Electric Controls	Entire Building / 1st Floor	1	SF	7	\$0	
	Hybrid Pneumatic/DDC System	Entire Building	62,706	SF	4	\$513,807	Controls work but BAS indication does not.
	Thermostats - Pneumatic	Entire Building	30	EA	6	\$0	
Ventilati	ion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	EM Generator Room	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	1	EA	4	\$11,390	Corroded and deformed
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	1	EA	6	\$296	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mecha	nical System Subtotal:					\$859,054	
Buildi	ng: Main						
Catego	ory: Plumbing System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	\$0	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	6	\$678	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	62,706	SF	4	\$44,835	Piping galvanized and greater than 50 y.o
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	62,706	SF	4	\$90,566	Piping galvanized and greater than 50 y.o
	Domestic Piping-Cold Water Risers	Entire Building	62,706	SF	4	\$50,215	Piping galvanized and greater than 50 y.o
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	62,706	SF	4	\$34,074	Piping galvanized and greater than 50 y.o
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	62,706	SF	4	\$80,703	Piping galvanized and greater than 50 y.o
	Domestic Piping-Hot Water Return Lines	Entire Building	62,706	SF	4	\$53,802	Piping galvanized and greater than 50 y.o
	Domestic Piping-Hot Water Return Risers	Entire Building	62,706	SF	4	\$30,488	Piping galvanized and greater than 50 y.o
	Sanitary Piping	Entire Building	62,706	SF	6	\$57,389	
	Storm Piping	Entire Building	62,706	SF	6	\$54,698	
	Vent Piping	Entire Building	62,706	SF	6	\$42,145	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Pump Room off the Boiler Room	1	EA	5	\$8,937	
Plumb	ing System Subtotal:					\$548,529	
						. ,	
Buildi	ng: Main						
Catego	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #106 (Office)						
	AC Units		1	EA	7	\$0	

Cias					
	AC Units	1	EA	7	\$0
	Casework	4	LF	6	\$101
	Ceiling - Plaster/Drywall	804	SF	6	\$2,782
	Doors - Side-lite	9	SF	6	\$150
	Doors - Transom Window	6	SF	6	\$102
	Doors - Wood Doors inclu hw	1	EA	6	\$301
	Floor - Tile	804	SF	6	\$1,759
	Lighting - Pendent/Surface	14	EA	7	\$0



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #106 (Office)		quantity			0001	
5.00010	Marker Board		40	LF	6	\$857	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,385	SF	6	\$3,822	
			,			+ - / -	
Classro	oom #107 (Pre School)						
	AC Units		2	EA	7	\$0	
	Ceiling - Plaster/Drywall		918	SF	6	\$3,177	
	Doors - Side-lite		9	SF	6	\$150	
	Doors - Transom Window		6	SF	6	\$102	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		918	SF	6	\$2,008	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Storage/ Closet		162	SF	6	\$1,175	
	Walls - Plaster/Drywall		1,174	SF	6	\$3,240	
	Work Sink		1	EA	6	\$379	
Classro	oom #108 (Office)						
	AC Units		1	EA	7	\$0	
	Casework		4	LF	6	\$101	
	Ceiling - Plaster/Drywall		816	SF	5	\$7,480	
	Doors - Side-lite		9	SF	6	\$150	
	Doors - Transom Window		6	SF	6	\$102	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	6	\$1,785	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		34	LF	6	\$728	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,399	SF	5	\$10,603	Water damage @ S/W corner
Classro	oom #109 (Kindergarten)						
	AC Units		2	EA	7	\$0	
	Casework		16	LF	6	\$404	
	Ceiling - Plaster/Drywall		972	SF	6	\$3,364	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		972	SF	6	\$2,127	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		13	LF	6	\$278	
	Storage/ Closet		73	SF	6	\$529	
	-						



Building: Main

Catego	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #109 (Kindergarten)						
	Walls - Plaster/Drywall		1,440	SF	5	\$10,914	
Classro	om #201 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		836	SF	7	\$0	
	Chalk Board		18	LF	4	\$1,653	obsolete material
	Doors - Transom Window		10	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		836	SF	5	\$3,754	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		12	LF	6	\$257	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,422	SF	6	\$3,925	
Classro	om #202 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		816	SF	6	\$2,824	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	5	\$3,664	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		34	LF	6	\$728	
	Storage/ Closet		54	SF	5	\$871	
	Walls - Plaster/Drywall		1,446	SF	5	\$10,959	
Classro	om #203 (Office)						
	AC Units		1	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		828	SF	6	\$2,865	
	Chalk Board		18	LF	4	\$1,653	Partially covered, obsolete material
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		828	SF	6	\$1,812	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Storage/ Closet		24	SF	6	\$174	
	Walls - Plaster/Drywall		1,387	SF	6	\$3,828	

Building: Main

Group Item - Type Location Quanty Units Rank Cost Comments AC Units 2 EA 7 50 512		Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
AC Units 6 L F 5 Casework 6 K 6 S2.782 Callade 23 L F 6 S2.782 Challs Bard 23 L F 6 S2.712 Partially covered, obadete material Doors - Transom Window 10 SF 6 S163 Doors - Transom Window 11 EA 6 S3.732 Upting - PendemSurface 12 LF 6 S2.57 Marker Doord 12 LF 6 S2.57 Storage Clocet 12 LF 6 S2.57 Bater/Drywall 13/38 SF 6 S3.92 Valle - Plaster/Drywall 13/38 SF 7 S0 Doors - Transom Window 10 SF 7 S0 Doors - Transom Window 10 SF 6 S3.61 Doors - Transom Window 10 SF 6 S3.61 Doors - Transom Window 10 </th <th>-</th> <th></th> <th>Location</th> <th>Quantity</th> <th>Onit</th> <th>Kalik</th> <th>0031</th> <th>oonimenta .</th>	-		Location	Quantity	Onit	Kalik	0031	oonimenta .
Casework 66 57 6 5152 Celling Poster/Dywall 23 LF 4 52.112 Partally covered, cbsolete material Doors - Transon Window 10 LF 4 52.112 Partally covered, cbsolete material Doors - Vood Doors indu hw 1 LF 6 53.179 Engine Pardent/Stafface 14 LF 6 52.77 Storage Closet 14 LF 6 52.75 Vallis - Plaster/Dywall 1389 F 6 52.75 Casework 14 LF 6 51.52 Casework 14 LF 7 50 Casework 16 LF 6 51.52 Casework 16 LF 7 50 Casework 16 LF 6 53.12 Casework 16 LF 7 50 Casework 16 LF 7 50 Doors - Nord Dors indu hw 14 LA </td <td>0103310</td> <td></td> <td></td> <td>2</td> <td>FΔ</td> <td>7</td> <td>02</td> <td></td>	0103310			2	FΔ	7	02	
Caling - Plaster/Dywail 804 8F 6 42.72 Chaik Board 20 52.112 Partially covered, obsolete material Doors - Transon Window 1 EA 6 \$3.01 Doors - Transon Window 1 EA 6 \$3.01 Floor - Tile 804 EA 6 \$3.1759 Floor - Tile 804 EA 6 \$3.1759 Markar Board 12 EA 6 \$3.02 Walls - Plaster/Dywail 24 FB 6 \$3.02 Walls - Plaster/Dywail 54 F 6 \$3.02 Carring - Raster/Dywail 55 F 7 \$0 Casework 6 F 7 \$0 \$0 Casework 10 SF 6 \$1569 \$152 Casework 10 SF 6 \$3.01 \$1500 Doors - Transon Window 10 SF 6 \$3.01 \$15000000000000000000000000000000000000								
Chaik Goard CP 4 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$								
Doors - Transom Window 1 F 6 \$169 Doors - Wood Doors inclu hw 1 F 6 \$301 Pioor - Tile 804 SF 6 \$3175 Lighting - Pendent/Surface 12 F 6 \$3272 Marker Board 128 F 6 \$3292 Walls - Puster/Drywall 1,38 SF 6 \$3292 Cascom Z25 (Regular Classroom) 5 5 \$10,329 \$100 AC Units AC Units K 7 \$00 Castom Window 1 EA 7 \$01 Doors - Vood Doors inclu hw 1 EA 7 \$02 Caling - Plaster/Drywall 616 SF 6 \$193 Doors - Vood Doors inclu hw 1 EA 6 \$5174 Lighting - Pendent/Surface 14 EA 7 \$02 Doors - Vood Doors inclu hw 1 EA 6 \$5174 Lighting - Pendent/Surface 1 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>Partially covered obsolete material</td></t<>								Partially covered obsolete material
Doors - Wood Doors inclu Iw 1 EA 6 \$\$1,735 Lighting - Pendent/Surface 12 L/F 6 \$\$2,775 Storage/ Closet 12 L/F 6 \$\$2,775 Storage/ Closet 138 S/F 5 \$\$10,527 Marker Board 1,38 S/F 5 \$\$10,527 Cassmont 205 (Reguit Classroom) 8 F 6 \$\$17,55 Cassmont X05 (Reguit Classroom) 8 S/F 7 \$\$0 Cassmont X05 (Reguit Classroom) 8 S/F 7 \$\$0 Cassmont X0 1 EA 7 \$\$0 Doors Transom Window 11 EA 6 \$\$17,85 Doors Transom Window 11 EA 6 \$\$17,85 Lighting - Pendent/Surface 24 EF 6 \$\$17,45 Lighting - Pendent/Surface 24 EF 6 \$\$17,45 Uighting - Pendent/Surface 24 EF 6 \$17,45 Walls - Plaster/Dry								
Ficor Tile 804 Fi 6 \$17,79 Lighting - Pendent/Surface 14 E 6 \$2,727 Marker Board 12 LF 6 \$2,327 Marker Board 1,38 SF 6 \$3,392 Walls - Plaster/Dywall 1,38 SF 6 \$3,392 Casework 6 LF 6 \$5,1735 Casework 6 LF 6 \$5,1735 Casework 6 LF 6 \$5,1735 Doors - Fransom Window 10 SF 6 \$5,1785 Doors - Transom Window 10 SF 6 \$5,1785 Doors - Transom Window 11 SF 6 \$5,1785 Doors - Trais On Window 14 EA 7 \$5,000000000000000000000000000000000000					-			
Lighting - Pendem/Surface 14 EA 6 \$17.35 Marker Board 12 LF 6 \$25.7 Storage/ Closet 25 \$10.527 \$10.527 Casework 6 \$15.2 \$10.527 AC Units 1 EA 7 \$0 Casework 6 \$15.2 \$10.527 Constructed (eguina Classroom) 18 \$57 \$10 Casework 6 \$15.2 \$10.527 Constructed (eguina Classroom) 10 \$57 \$10 Doors - Transom Window 10 \$57 \$10 Doors - Wood Doors inclu two 1 \$24 \$10 Floor - Tile 816 \$57 \$30 Marker Board 1.24 \$6 \$3174 Walls - Plaster/Dywall 1.39 \$6 \$557 Storage/ Closet \$28 \$6 \$5172 Act Units \$6 \$5172 \$50 Casework \$6 \$5152 \$5152 <								
Marker Board 12 F 6 \$257 Storage/ Closet 58 5 \$392 Valis - Baster/Drywall 1.39 \$7 5 Classroom 2 7 \$50 Cassroom #205 (Regular Classroom) 1 EA 7 \$50 Casework 1 EA 7 \$50 Casework 1 EA 7 \$50 Doors - Transon Window 10 SF 6 \$152 Doors - Wood Doors inclu hw 11 EA 7 \$50 Doors - Wood Doors inclu hw 11 EA 6 \$\$1745 Lighting - Pendent/Surface 24 EF 6 \$\$1745 Marker Board 24 SF 6 \$\$1745 Walls - Plaster/Drywall 24 SF 6 \$\$1745 Octast 24 SF 6 \$\$1745 Octast 24 SF 6 \$\$152 Caling - Plaster/Drywall 28								
Storage/ Closet Walls - Plaster/Dywall SF 6 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$								
Walls - Plaster/Dryvall 1,389 % 5 5 \$ \$10,527 Classroom. A C Units 1 K A 7 \$0 Caework 6 \$152 \$169 \$169 Doors - Transom Window 10 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1745 Lighting - Pendent/Surface 14 EA 7 \$00 Marker Board 24 SF 6 \$1745 Walls - Plaster/Dryvall 28 6 \$174 Walls - Plaster/Dryvall 28 6 \$174 Walls - Plaster/Dryvall 28 6 \$174 Walls - Plaster/Dryvall 19 8F 6 \$174 A C Units K 6 \$174 \$174 Caework 6 \$152 \$174 \$174 Caework 6 \$152 \$174 \$174 Doors - Transom Window 10 SF 6 \$152 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
Classroom #205 (Regular Classroom) I EA 7 S0 AC Units 6 LF 6 \$152 Celling - Plaster/Dywall 816 SF 7 \$0 Doors - Transom Window 10 SF 6 \$162 Doors - Wood Doors inclu hw 1 EA 6 \$3162 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$17.45 Lighting - Pendent/Surface 14 EA 7 \$00 Marker Board 28 LF 6 \$5174 Walls - Plaster/Drywall 1, 99 SF 6 \$3180 1 EA 7 \$00 1 EA 7 \$00 Cassroom #201 (Regular Classroom) 1 EA 7 \$00 Cassroom Window 10 SF 6 \$122 Doors - Wood Doors inclu hw 1		-						
AC Units 1 EA 7 \$0 Casework 6 LF 6 \$152 Ceiling - Plaster/Drywall 816 \$F 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$159 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 \$F 6 \$312 Lighting - Pendent/Surface 41 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 24 \$F 6 \$174 Walls - Plaster/Drywall 1,39 \$F 6 \$152 Casework 24 \$F 6 \$174 Walls - Plaster/Drywall 1,39 \$F 6 \$152 Casework 6 LF 6 \$152 Casework 6 LF 6 \$152 Caling - Plaster/Drywall 816 \$F 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$301 Ploor - Tile </td <td></td> <td></td> <td></td> <td>.,</td> <td>0.</td> <td>Ũ</td> <td>¢.0,0⊥.</td> <td></td>				.,	0.	Ũ	¢.0,0 ⊥ .	
Casework 6 LF 6 5152 Ceiling - Plaster/Drywall 816 SF 7 \$00 Doors - Transom Window 10 SF 6 \$169 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$3175 Lighting - Pendent/Surface 14 EA 7 \$00 Marker Board 24 FF 6 \$174 Walls - Plaster/Drywall 318 F 6 \$174 Casework 1 EA 7 \$00 Casework 6 \$152 \$ \$152 Ceiling - Plaster/Drywall 816 SF 6 \$28,24 Doors - Wood Doors inclu hw 1 EA 7 <t< td=""><td>Classro</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>	Classro							
Ceiling - Plaster/Drywall 816 SF 7 \$0 Doors - Transom Window 1 SF 6 \$160 Doors - Transom Window 1 EA 6 \$101 Doors - Transom Window 1 EA 6 \$101 Doors - Trile 816 SF 6 \$11,785 Lighting - Pendent/Surface 14 EA 7 \$00 Marker Board 24 SF 6 \$17,47 Valls - Plaster/Drywall 1,399 SF 6 \$17,47 Walls - Plaster/Drywall 1,399 SF 6 \$17,47 Cessroom#207 (Regular Classroom) 24 SF 6 \$17,47 Cassework 6 S152 \$152 \$152 Ceiling - Plaster/Drywall 816 SF 6 \$2,824 Doors - Transom Window 10 SF 6 \$2,824 Doors - Transom Window 11 EA 7 \$00 Doors - Wood Doors inclu hw 1 EA 7 \$0 Doors - Wood Doors inclu hw 1								
Doors Transom Window 10 SF 6 \$169 Doors Vood Doors inclu hw 1 EA 6 \$3.01 Floor - Tile 816 SF 6 \$17.85 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$17.45 Storage/ Closet 24 SF 6 \$17.45 Walls - Plaster/Drywall 1.9 SF 6 \$17.45 Casework 2.8 S 6 \$17.45 Casework 6 LF 6 \$15.2 Ceiling - Plaster/Drywall 816 SF 6 \$2,824 Doors - Transom Window 1 SF 6 \$3152 Ceiling - Plaster/Drywall 816 SF 6 \$3161 Doors - Transom Window 1 SF 6 \$3174 Doors - Transom Window 1 SF 6 \$3161 Lighting - Pendent/Surface 14								
Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 24 SF 6 \$557 Storage/ Closet 24 SF 6 \$14 Walls - Plaster/Drywall 1,39 SF 6 \$314 Classroom #207 (Regular Classroom) AC Units 1 EA 7 \$0 Casework 6 LF 6 \$22,824 Doors - Transon Window 10 SF 7 \$00 Doors - Wood Doors inclu hw 1 EA 7 \$00 Doors - Transon Window 10 SF 6 \$2,824 Doors - Transon Window 10 SF 6 \$301 Floor - Tile 816 SF 6 \$301 Grawer All - Floor - Tile 816 SF 6 \$301 Grawer Closet 26 LF 6 \$357 Marker Board 26 LF 6 \$326 Walls - Plaster/Drywall <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$00 Marker Board 26 LF 6 \$57 Storage/ Closet 24 SF 6 \$3,861 Walls - Plaster/Dryvall 1,99 SF 6 \$3,861 Classroom #207 (Regular Classroom) AC Units 1 EA 7 \$00 Casework 6 LF 6 \$152 Ceiling - Plaster/Dryvall 816 SF 6 \$3,01 Doors - Transom Window 10 SF 6 \$3,01 Floor - Tile 816 SF 6 \$3,01 Floor - Tile 816 SF 6 \$3,01 Floor - Tile 816 SF 6 \$3,01 Highting - Pendent/Surface 14 EA 7 \$00 Marker Board 26 LF 6 \$1,89 Storage/ Closet 26 LF 6 \$3,92 Walls - Plaster/Drywall 1,99 S				10				
Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 24 SF 6 \$174 Walls - Plaster/Drywall 1,99 SF 6 \$3,861 Classroom #207 (Regular Classroom) U U S 6 \$3,861 Classroom #207 (Regular Classroom) 1 EA 7 \$0 Cassroom Kor 6 LF 6 \$152 Castro Kork 6 SF 7 \$0 Doors - Transom Window 10 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Lighting - Pendent/Surface 24 EF 6 \$3361 Walls - Plaster/Drywall 13.99 SF 6 \$3382 Walls - Plaster/Drywall				1				
Marker Board 26 LF 6 \$\$557 Storage/ Closet 24 SF 6 \$\$174 Walls - Plaster/Drywall 1,39 SF 6 \$\$3,861 Classroom #207 (Regular Classroom) Classroom/Casework AC Units 1 EA 7 \$\$0 Casework 6 \$\$152 \$\$152 \$\$152 Doors - Transom Window 10 SF 6 \$\$2,824 Doors - Wood Doors inclu hw 1 EA 6 \$\$301 Floor - Tile 816 SF 6 \$\$312 Lighting - Pendent/Surface 14 EA 7 \$\$0 Marker Board 26 \$\$1785 \$\$ \$\$ \$\$ Marker Board 26 \$\$ \$\$ \$\$ \$\$ \$\$ Marker Board 24 SF \$\$ \$\$ \$\$ \$\$ Storage/Closet 1399 SF \$\$ \$\$ \$\$ \$\$								
Storage/ Closet Walls - Plaster/Drywall245F6\$174ClassroomClassroomAC Units1EA7\$0Casework6LF6\$152Ceiling - Plaster/Drywall816SF6\$2,824Doors - Transom Window10SF7\$0Doors - Wood Doors inclu hw11EA6\$316Floor - Tile64SF6\$317Lighting - Pendent/Surface14EA7\$0Marker Board26LF6\$557Storage/ Closet54SF6\$3392Walls - Plaster/Drywall1,399SF6\$33861Classroom14EA7\$0Marker Board139SF6\$3392Marker Board1399SF6\$33861Classroom14SF6\$3392Walls - Plaster/Drywall1399SF6\$33861								
Walls - Plaster/Drywall 1,399 SF 6 \$3,861 Classroom #207 (Regular Classroom) Ed 7 \$0 AC Units 1 EA 7 \$0 Casework 6 LF 6 \$152 Ceiling - Plaster/Drywall 816 SF 7 \$0 Doors - Transom Window 10 SF 7 \$0 Doors - Transom Window 1 EA 7 \$0 Doors - Transom Window 1 EA 6 \$3,301 Floor - Tile 816 SF 6 \$3,301 Floor - Tile 816 SF 6 \$3,301 Lighting - Pendent/Surface 816 SF 6 \$3,301 Marker Board 26 Lighting - Storage/ Closet 57 50 Walls - Plaster/Drywall 819 SF 6 \$3,361 Classroom #209 (Regular Classroom) 85 6 \$3,361 Marker Board 25 6 \$3,361 Marker Board 26 53,361 \$3,861 \$4				26		6		
Classroom #207 (Regular Classroom) AC Units 1 EA 7 \$0 Casework 6 LF 6 \$152 Ceiling - Plaster/Drywall 816 SF 6 \$2,824 Doors - Transom Window 10 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$3392 Walls - Plaster/Drywall 1,399 SF 6 \$33,861		-						
AC Units 1 EA 7 \$0 Casework 6 LF 6 \$152 Ceiling - Plaster/Drywall 816 SF 6 \$2,824 Doors - Transom Window 10 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$3392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861		Walls - Plaster/Drywall		1,399	SF	6	\$3,861	
AC Units 1 EA 7 \$0 Casework 6 LF 6 \$152 Ceiling - Plaster/Drywall 816 SF 6 \$2,824 Doors - Transom Window 10 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$3392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861	Classro	oom #207 (Regular Classroom)						
Ceiling · Plaster/Drywall 816 SF 6 \$2,824 Doors · Transom Window 10 SF 7 \$0 Doors · Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$332 Walls - Plaster/Drywall 1,399 SF 6 \$3381				1	EA	7	\$0	
Doors - Transom Window 10 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$357 Storage/ Closet 54 SF 6 \$392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861		Casework		6	LF	6	\$152	
Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$392 Walls - Plaster/Drywall 1,399 SF 6 \$33,861		Ceiling - Plaster/Drywall		816	SF	6	\$2,824	
Floor - Tile 816 SF 6 \$1,785 Lighting - Pendent/Surface 14 EA 7 \$0 Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861		Doors - Transom Window		10	SF	7	\$0	
Lighting - Pendent/Surface14EA7\$0Marker Board26LF6\$557Storage/ Closet54SF6\$392Walls - Plaster/Drywall1,399SF6\$3,861Classroom #209 (Regular Classroom)AC Units1EA7\$0		Doors - Wood Doors inclu hw		1	EA	6	\$301	
Marker Board 26 LF 6 \$557 Storage/ Closet 54 SF 6 \$392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861 Classroom #209 (Regular Classroom) AC Units 1 EA 7 \$0		Floor - Tile		816	SF	6	\$1,785	
Storage/ Closet 54 5F 6 \$392 Walls - Plaster/Drywall 1,399 SF 6 \$3,861 Classroom #209 (Regular Classroom) AC Units 1 EA 7 \$0		Lighting - Pendent/Surface		14	EA	7	\$0	
Walls - Plaster/Drywall 1,399 SF 6 \$3,861 Classroom #209 (Regular Classroom) Image: SF 1 EA 7 \$0		Marker Board		26	LF	6	\$557	
Classroom #209 (Regular Classroom) AC Units 1 EA 7 \$0		Storage/ Closet		54	SF	6	\$392	
AC Units 1 EA 7 \$0		Walls - Plaster/Drywall		1,399	SF	6	\$3,861	
	Classro	oom #209 (Regular Classroom)						
				1	EA	7	\$0	
		Casework		6	LF	6		

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #209 (Regular Classroom)						
	Ceiling - Plaster/Drywall		816	SF	6	\$2,824	
	Chalk Board		6	LF	4	\$551	obsolete material
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	5	\$3,664	
	Lighting - Pendent/Surface		14	EA	6	\$1,735	
	Marker Board		40	LF	6	\$857	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,399	SF	6	\$3,861	
Classro	oom #210 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		864	SF	6	\$2,990	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		864	SF	6	\$1,890	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		36	LF	6	\$771	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,446	SF	6	\$3,991	
Classro	oom #301 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		838	SF	5	\$7,681	
	Chalk Board		16	LF	4	\$1,469	obsolete material
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		838	SF	6	\$1,833	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,338	SF	6	\$3,693	
Classro	oom #302 (Multi Purpose Room)						
	AC Units		2	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		824	SF	7	\$0	
	Chalk Board		32	LF	4	\$2,938	Partially covered, obsolete material

Building: Main

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #302 (Multi Purpose Room)						
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		824	SF	6	\$1,803	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		16	LF	6	\$343	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,350	SF	6	\$3,726	
Classro	oom #303 (Regular Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		12	LF	6	\$303	
	Ceiling - Plaster/Drywall		816	SF	6	\$2,824	
	Chalk Board		16	LF	4	\$1,469	obsolete material
	Doors - Transom Window		10	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	6	\$1,785	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		16	LF	6	\$343	
	Storage/ Closet		28	SF	6	\$203	
	Walls - Plaster/Drywall		1,341	SF	6	\$3,701	
Classro	oom #304 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		6	LF	5	\$1,254	
	Ceiling - Plaster/Drywall		810	SF	6	\$2,803	
	Chalk Board		10	LF	4	\$918	obsolete material
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		810	SF	6	\$1,772	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,334	SF	5	\$10,110	
Classro	oom #305 (Science Classroom)						
	AC Units		1	EA	7	\$0	
	Casework		38	LF	5	\$7,945	
	Ceiling - Plaster/Drywall		816	SF	6	\$2,824	
	Chalk Board		6	LF	4	\$551	obsolete material
	Doors - Transom Window		10	SF	6	\$169	

Building: Main

roun	Item - Type	Location	Quantity	l Ini+	Pank	Cost	Comments
-	ntern - Type pom #305 (Science Classroom)	LUCATION	Quantity	Unit	Ralik	Cost	Comments
102210	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	6	\$1,785	
	Lighting - Pendent/Surface		14	EA	7	\$1,785 \$0	
	Marker Board		8	LF	6	φ0 \$171	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,341	SF	6	\$3,701	
	Work Sink		4	EA	6	\$1,516	
				273	Ũ	ψ1,010	
lassro	oom #306 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		810	SF	6	\$2,803	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		810	SF	6	\$1,772	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		16	LF	6	\$343	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,334	SF	6	\$3,682	
lassro	oom #307 (Art Room)						
	AC Units		1	EA	7	\$0	
	Casework		6	LF	6	\$152	
	Ceiling - Plaster/Drywall		824	SF	7	\$0	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		824	SF	6	\$1,803	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		30	LF	6	\$643	
	Storage/ Closet		54	SF	6	\$392	
	Walls - Plaster/Drywall		1,350	SF	6	\$3,726	
lassro	oom #308 (Regular Classroom)						
	AC Units		2	EA	7	\$0	
	Ceiling - Plaster/Drywall		816	SF	7	\$0	
	Doors - Transom Window		10	SF	6	\$169	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		816	SF	6	\$1,785	
	Lighting - Pendent/Surface			EA	6	\$2,602	

Building: Main

Category: Classrooms

Group I	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroor	m #308 (Regular Classroom)						
Ν	Marker Board		16	LF	6	\$343	
5	Storage/ Closet		54	SF	6	\$392	
١	Walls - Plaster/Drywall		1,341	SF	6	\$3,701	
Classroor	n #309 (Computer Lab)						
ŀ	AC Units		2	EA	6	\$991	
(Ceiling - Plaster/Drywall		864	SF	6	\$2,990	
[Doors - Transom Window		10	SF	6	\$169	
[Doors - Wood Doors inclu hw		1	EA	6	\$301	
F	Floor - Tile		10	SF	4	\$130	Broken tiles
F	Floor - Tile		854	SF	6	\$1,868	
L	ighting - Pendent/Surface		14	EA	7	\$0	
N	Marker Board		50	LF	6	\$1,071	
5	Storage/ Closet		54	SF	6	\$392	
١	Walls - Plaster/Drywall		1,394	SF	6	\$3,847	
lassroor	n #310 (Regular Classroom)						
ŀ	AC Units		2	EA	7	\$0	
(Casework		15	LF	5	\$3,136	
(Ceiling - Plaster/Drywall		828	SF	7	\$0	
[Doors - Transom Window		10	SF	6	\$169	
[Doors - Wood Doors inclu hw		1	EA	6	\$301	
F	Floor - Tile		828	SF	6	\$1,812	
L	ighting - Pendent/Surface		14	EA	7	\$0	
N	Marker Board		20	LF	6	\$428	
5	Storage/ Closet		54	SF	6	\$392	
١	Nalls - Plaster/Drywall		1,354	SF	5	\$10,262	
2100000	ome Subtotal:					\$205 121	

Classrooms Subtotal:

\$295,131

Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Administrative Suites/Offices					
Ceiling - Plaster/Drywall	1st Floor gym office off stage	284	SF	6	\$983
Doors - Wood Doors inclu hw	1st Floor gym office off stage	2	EA	6	\$602
Floor - Tile	1st Floor gym office off stage	284	SF	6	\$621
Lighting - Pendent/Surface	1st Floor gym office off stage	2	EA	7	\$0



up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Suites/Offices						
Walls - Plaster/Drywall	1st Floor gym office off stage	703	SF	6	\$1,940	
Ceiling - Plaster/Drywall	2nd Floor office 211	338	SF	7	\$0	
Doors - Wood Doors inclu hw	2nd Floor office 211	1	EA	6	\$301	
Floor - Epoxy/ Painted	2nd Floor office 211	338	SF	5	\$580	
Lighting - Pendent/Surface	2nd Floor office 211	2	EA	7	\$0	
Walls - Plaster/Drywall	2nd Floor office 211	930	SF	6	\$2,567	
Ceiling - Plaster/Drywall	3rd floor office #311	340	SF	7	\$0	
Doors - Wood Doors inclu hw	3rd floor office #311	1	EA	6	\$301	
Floor - Epoxy/ Painted	3rd floor office #311	340	SF	5	\$583	
Lighting - Pendent/Surface	3rd floor office #311	2	EA	6	\$248	
Walls - Plaster/Drywall	3rd floor office #311	885	SF	6	\$2,443	
Ceiling - Exposed	Custodian office outside gym	302	SF	6	\$449	
Doors - Steel Doors incl hw	Custodian office outside gym	1	EA	6	\$301	
Floor - Tile	Custodian office outside gym	302	SF	6	\$661	
Lighting - Pendent/Surface	Custodian office outside gym	2	EA	6	\$248	
Walls - Plaster/Drywall	Custodian office outside gym	883	SF	5	\$6,692	
AC Unit	Engineer's office	1	EA	4	\$6,086	Old unit
Ceiling - Plaster/Drywall	Engineer's office	203	SF	6	\$703	
Doors - Wood Doors inclu hw	Engineer's office	1	EA	6	\$301	
Floor - Concrete	Engineer's office	203	SF	5	\$348	Deteriorated finish and cracks
Lighting - Pendent/Surface	Engineer's office	5	EA	6	\$619	
Walls - Plaster/Drywall	Engineer's office	794	SF	5	\$6,018	Cracks and peeling paint
Work SInk	Engineer's office	1	EA	6	\$508	
Ceiling - Lay-in	Lunchroom office	40	SF	6	\$120	
Doors - Wood Doors inclu hw	Lunchroom office	1	EA	6	\$301	
Floor - Terrazzo	Lunchroom office	40	SF	6	\$88	
Walls - Plaster/Drywall	Lunchroom office	171	SF	6	\$472	
AC Unit	main office	1	EA	6	\$496	
Ceiling - Plaster/Drywall	main office	486	SF	6	\$1,682	
Doors - Wood Doors inclu hw	main office	1	EA	6	\$301	
Floor - Tile	main office	486	SF	6	\$1,063	
Lighting - Pendent/Surface	main office	7	EA	6	\$867	
Storage/ Closet	main office	57	SF	6	\$413	
Walls - Plaster/Drywall	main office	830	SF	6	\$2,291	
Ceiling - Plaster/Drywall	office 300, floor 3.5b	260	SF	6	\$900	
Doors - Transom Window	office 300, floor 3.5b	70	SF	6	\$1,185	
Doors - Wood Doors inclu hw	office 300, floor 3.5b	1	EA	6	\$301	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	strative Suites/Offices		,				
	Floor - Tile/Sheet	office 300, floor 3.5b	260	SF	4	\$2.513	Peeling, cracks and broken tiles
	Lighting - Pendent/Surface	office 300, floor 3.5b	3	EA	6	\$372	
	Walls - Plaster/Drywall	office 300, floor 3.5b	591	SF	5	\$4,479	
	Ceiling - Plaster/Drywall	Office 308b, floor3.5	270	SF	5	\$2,475	
	Doors - Wood Doors inclu hw	Office 308b, floor3.5	1	EA	5	\$1,174	
	Floor - Tile	Office 308b, floor3.5	270	SF	6	\$591	
	Lighting - Pendent/Surface	Office 308b, floor3.5	3	EA	7	\$0	
	Walls - Plaster/Drywall	Office 308b, floor3.5	572	SF	6	\$1,579	
	Ceiling - Plaster/Drywall	Principal's office	232	SF	6	\$803	
	Doors - Wood Doors inclu hw	Principal's office	2	EA	6	\$602	
	Floor - Tile	Principal's office	232	SF	6	\$508	
	Lighting - Pendent/Surface	Principal's office	4	EA	7	\$0	
	Walls - Plaster/Drywall	Principal's office	718	SF	6	\$1,982	
Cumpo							
Gymna	Bleacher Seating	1st Floor	367	EA	6	\$10,622	
	Ceiling - Plaster/Drywall	1st Floor	5,354	SF	6	\$29,553	
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	\$2,709	
	Floor - Tile	1st Floor	5,354	SF	6	\$11,714	
	Lighting - Pendent/Surface	1st Floor	50	EA	6	\$6,195	
	Scoreboards	1st Floor	1	EA	6	\$2,244	
	Stage	1st Floor	1,374	SF	6	\$7,938	
	Stage Curtain	1st Floor	3	EA	6	\$0	
	Stage Lighting System	1st Floor	1	EA	6	\$12,369	
	Stage-Stairs - Tile	1st Floor	42	LF	5	\$753	
	Storage/ Closet	1st Floor	136	SF	6	\$986	
	Walls - Plaster/Drywall	1st Floor	5,756	SF	5	\$43,625	
Kitah au							
Kitcher	Ceiling - Plaster/Drywall	1st Floor	472	SF	5	\$4,326	
	Floor - Tile	1st Floor	472	SF	6	\$4,320 \$1,033	
	Lighting - Lay-in	1st Floor	472	EA	6	\$833	Recessed lights
	Lighting - Pendent/Surface	1st Floor	7	EA	7	\$033 \$0	
	Walls - Concrete Block	1st Floor	50	SF	6	پ 0 \$147	
	Walls - Plaster/Drywall	1st Floor	407	SF	5	\$3,085	
			101	0.	Ŭ	ψ0,000	
Library			-	= .	_	<u>^</u>	
	AC Unit	2nd Floor	2	EA	7	\$0	
	Casework	2nd Floor	92	LF	6	\$2,323	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Library							
	Ceiling - Plaster/Drywall	2nd Floor	1,663	SF	6	\$5,755	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,651	SF	6	\$3,612	
	Floor - Tile	2nd Floor	12	SF	4	\$156	Broken and chipped tiles
	Lighting - Pendent/Surface	2nd Floor	29	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,910	SF	6	\$5,271	
Lunch &	& Multipurpose Room						
	AC Unit	1st Floor	2	EA	6	\$991	
	Ceiling - Lay-in	1st Floor	1,199	SF	6	\$3,601	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Floor - Tile	1st Floor	1,199	SF	6	\$2,623	
	Lighting - Lay-in	1st Floor	25	EA	6	\$2,974	
	Serving Line	1st Floor	20	LF	6	\$1,190	
	Storage/ Closet	1st Floor	135	SF	6	\$979	
	Walls - Plaster/Drywall	1st Floor	1,341	SF	5	\$10,163	
MDF_ID	DF						
	AC Unit	2nd Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Finishes	2nd Floor	100	SF	6	\$714	
Mechan	nical/ Service Rooms						
	Boiler Room	1st Floor	1,325	SF	6	\$9,493	
	Janitor's Closet	1st Floor	11	SF	5	\$177	@ Boys Toilet
	Mechanical/ Service Rooms	1st Floor	331	SF	6	\$2,371	Tank Room
	Mechanical/ Service Rooms	1st Floor	677	SF	5	\$10,920	North
	Mechanical/ Service Rooms	1st Floor	2,282	SF	6	\$16,349	Engine Room
	Storage Room	1st Floor	64	SF	5	\$1,032	South Corridor
	Janitor's Closet	2nd Floor	57	SF	5	\$919	@ Girls Toilet
	Janitor's Closet	2nd Floor	15	SF	5	\$242	@ Boys Toilet
	Janitor's Closet	3rd Floor	18	SF	5	\$290	
Restroo	om						
	Accessories	107a	45	SF	6		toilet paper holder
	Ceiling - Lay-in	107a	23	SF	6	\$69	
	Ceiling - Lay-in	107a	22	SF	4	\$249	Water damage and broken tiles
	Doors - Wood Doors inclu hw	107a	1	EA	6	\$301	
	Floor - Tile	107a	45	SF	5	\$202	



RestroomLavatory107aLighting - Lay-in107aWalls - Plaster/Drywall107aWalls - Tile Ceramic/ Porcelain107aWater Closet107aCeiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysFloor Drain1st Floor boys	1 1 87 87 1	EA EA SF	6 6	\$320 \$119	
Lighting - Lay-in107aWalls - Plaster/Drywall107aWalls - Tile Ceramic/ Porcelain107aWater Closet107aCeiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1 87 87	EA			
Walls - Plaster/Drywall107aWalls - Tile Ceramic/ Porcelain107aWater Closet107aCeiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	87 87		6	\$119	
Walls - Tile Ceramic/ Porcelain107aWater Closet107aCeiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	87	SF		φιισ	
Water Closet107aCeiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boys			6	\$240	
Ceiling - Plaster/Drywall109aDoors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	SF	6	\$197	
Doors - Wood Doors inclu hw109aFloor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	6	\$336	
Floor - Tile109aLavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	38	SF	6	\$132	
Lavatory109aLighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	5	\$1,174	
Lighting - Pendent/Surface109aPartitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	38	SF	6	\$83	
Partitions109aWalls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	6	\$320	
Walls - Plaster/Drywall109aWalls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	6	\$124	
Walls - Plaster/Drywall109aWalls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	6	\$297	
Walls - Structural Glazed Tile109aWater Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	130	SF	6	\$359	FRP
Water Closet109aAccessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	110	SF	5	\$486	
Accessories1st Floor boysCeiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	10	SF	6	\$31	
Ceiling - Plaster/Drywall1st Floor boysDoors - Wood Doors inclu hw1st Floor boys	1	EA	6	\$336	
Doors - Wood Doors inclu hw 1st Floor boys	341	SF	6	\$3,145	soap dispenser, mirror
	341	SF	5	\$3,126	
Floor Drain 1st Floor boys	2	EA	4	\$6,826	Deteriorated with holes
	2	EA	6	\$2,118	
Floor - Tile Ceramic/ Porcelain 1st Floor boys	341	SF	6	\$722	
Hand Dryer 1st Floor boys	1	EA	6	\$230	
Lavatory 1st Floor boys	1	EA	6	\$320	
Lighting - Pendent/Surface 1st Floor boys	9	EA	7	\$0	
Partitions 1st Floor boys	6	EA	6	\$1,782	
Urinals 1st Floor boys	10	EA	6	\$3,360	
Walls - Plaster/Drywall 1st Floor boys	477	SF	6	\$1,316	
Walls - Structural Glazed Tile 1st Floor boys	477	SF	6	\$1,501	
Water Closet 1st Floor boys	6	EA	6	\$2,016	
Accessories 1st Floor girls	336	SF	6	\$3,099	soap dispenser, paper towel dispenser, mirror
Ceiling - Plaster/Drywall 1st Floor girls	336	SF	6	\$1,163	
Doors - Wood Doors inclu hw 1st Floor girls	2	EA	5	\$2,348	
Floor Drain 1st Floor girls	1	EA	6	\$1,059	
Floor - Terrazzo 1st Floor girls	308	SF	6	\$674	
Floor - Tile/Sheet 1st Floor girls	28	SF	6	\$28	
Hand Dryer 1st Floor girls	A				
Lavatory 1st Floor girls	1	EA	6	\$230	
Lighting - Pendent/Surface 1st Floor girls	1	EA EA	6 6	\$230 \$320	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Partitions	1st Floor girls	12	EA	6	\$3,563	
	Walls - Plaster/Drywall	1st Floor girls	509	SF	5	\$3,858	
	Walls - Structural Glazed Tile	1st Floor girls	509	SF	5	\$25,861	
	Water Closet	1st Floor girls	12	EA	6	\$4,032	
	Accessories	2nd Floor boys	424	SF	6	\$3,911	mirror
	Ceiling - Plaster/Drywall	2nd Floor boys	424	SF	6	\$1,467	
	Doors - Wood Doors inclu hw	2nd Floor boys	2	EA	6	\$602	
	Floor Drain	2nd Floor boys	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	2nd Floor boys	424	SF	6	\$897	
	Hand Dryer	2nd Floor boys	1	EA	6	\$230	
	Lavatory	2nd Floor boys	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor boys	9	EA	7	\$0	
	Partitions	2nd Floor boys	6	EA	6	\$1,782	
	Urinals	2nd Floor boys	10	EA	6	\$3,360	
	Walls - Plaster/Drywall	2nd Floor boys	515	SF	6	\$1,421	
	Walls - Structural Glazed Tile	2nd Floor boys	515	SF	6	\$1,620	
	Water Closet	2nd Floor boys	6	EA	6	\$2,016	
	Accessories	2nd Floor girls	316	SF	6	\$2,915	mirror, soap dispenser, paper towel dispenser
	Ceiling - Plaster/Drywall	2nd Floor girls	316	SF	5	\$2,897	
	Doors - Wood Doors inclu hw	2nd Floor girls	3	EA	5	\$3,522	Deteriorated wood doors
	Floor Drain	2nd Floor girls	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd Floor girls	316	SF	6	\$691	
	Hand Dryer	2nd Floor girls	1	EA	6	\$230	
	Lavatory	2nd Floor girls	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor girls	5	EA	7	\$0	
	Partitions	2nd Floor girls	10	EA	6	\$2,969	
	Walls - Plaster/Drywall	2nd Floor girls	408	SF	5	\$3,092	
	Walls - Structural Glazed Tile	2nd Floor girls	408	SF	6	\$1,284	
	Water Closet	2nd Floor girls	10	EA	6	\$3,360	
	Accessories	3rd floor accessible unisex, north end	90	SF	7	\$0	mirror, toilet paper holder, soap dispenser
	Ceiling - Plaster/Drywall	3rd floor accessible unisex, north end	90	SF	7	\$0	
	Doors - Wood Doors inclu hw	3rd floor accessible unisex, north end	1	EA	7	\$0	
	Floor Drain	3rd floor accessible unisex, north end	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd floor accessible unisex, north end	90	SF	6	\$190	
	Hand Dryer	3rd floor accessible unisex, north end	1	EA	7	\$0	
	Lavatory	3rd floor accessible unisex, north end	1	EA	7	\$0	
	Lighting - Pendent/Surface	3rd floor accessible unisex, north end	1	EA	7	\$0	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Walls - Plaster/Drywall	3rd floor accessible unisex, north end	452	SF	6	\$1,247	
	Water Closet	3rd floor accessible unisex, north end	1	EA	7	\$0	
	Accessories	3rd Floor boys	426	SF	6	\$3,929	mirror
	Ceiling - Plaster/Drywall	3rd Floor boys	426	SF	6	\$1,474	
	Doors - Wood Doors inclu hw	3rd Floor boys	4	EA	4	\$13,652	Deteriorated and broken
	Floor Drain	3rd Floor boys	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	3rd Floor boys	426	SF	6	\$902	
	Hand Dryer	3rd Floor boys	1	EA	7	\$0	
	Lavatory	3rd Floor boys	6	EA	6	\$1,918	
	Lighting - Pendent/Surface	3rd Floor boys	9	EA	7	\$0	
	Partitions	3rd Floor boys	6	EA	6	\$1,782	
	Urinals	3rd Floor boys	8	EA	6	\$2,688	
	Walls - Plaster/Drywall	3rd Floor boys	496	SF	6	\$1,369	
	Walls - Structural Glazed Tile	3rd Floor boys	496	SF	6	\$1,560	
	Water Closet	3rd Floor boys	6	EA	6	\$2,016	
	Accessories	3rd Floor girls	316	SF	6	\$2,915	mirror, soap dispenser, paper towel dispenser
	Ceiling - Plaster/Drywall	3rd Floor girls	316	SF	6	\$1,094	
	Doors - Wood Doors inclu hw	3rd Floor girls	4	EA	6	\$1,204	
	Floor Drain	3rd Floor girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd Floor girls	316	SF	6	\$669	
	Hand Dryer	3rd Floor girls	1	EA	6	\$230	
	Lavatory	3rd Floor girls	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd Floor girls	5	EA	7	\$0	
	Partitions	3rd Floor girls	10	EA	6	\$2,969	
	Walls - Plaster/Drywall	3rd Floor girls	328	SF	6	\$905	
	Walls - Structural Glazed Tile	3rd Floor girls	328	SF	6	\$1,032	
	Water Closet	3rd Floor girls	10	EA	6	\$3,360	
	Accessories	boiler room toilet	14	SF	6	\$129	toilet paper holder
	Ceiling - Plaster/Drywall	boiler room toilet	14	SF	6	\$48	
	Doors - Steel Doors incl hw	boiler room toilet	1	EA	6	\$301	
	Floor - Concrete	boiler room toilet	14	SF	6	\$7	
	Lighting - Pendent/Surface	boiler room toilet	1	EA	6	\$124	
	Walls - Plaster/Drywall	boiler room toilet	129	SF	6	\$356	
	Water Closet	boiler room toilet	1	EA	6	\$336	
	Floor - Concrete	Engineer's toilet	12	SF	6	\$6	This is a toilet inside the engineer's office divided by wooden partitions.
	Partitions	Engineer's toilet	1	EA	6	\$297	· · ·
	Water Closet	Engineer's toilet	1	EA	6	\$336	



Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Accessories	Lunch Room Toilet	25	SF	6	\$231	soap dispenser, toilet paper holder, mirror
	Ceiling - Plaster/Drywall	Lunch Room Toilet	25	SF	6	\$87	
	Doors - Wood Doors inclu hw	Lunch Room Toilet	1	EA	5	\$1,174	
	Floor - Tile/Sheet	Lunch Room Toilet	25	SF	6	\$25	
	Lavatory	Lunch Room Toilet	1	EA	6	\$320	
	Lighting - Wall Mounted	Lunch Room Toilet	1	EA	6	\$124	
	Walls - Plaster/Drywall	Lunch Room Toilet	70	SF	6	\$193	
	Walls - Tile Ceramic/ Porcelain	Lunch Room Toilet	70	SF	6	\$158	
	Water Closet	Lunch Room Toilet	1	EA	6	\$336	
	Accessories	Main office toilet room	52	SF	6	\$480	mirror, paper towel dispenser, toilet paper holder
	Ceiling - Plaster/Drywall	Main office toilet room	52	SF	6	\$180	
	Doors - Wood Doors inclu hw	Main office toilet room	1	EA	6	\$301	
	Floor - Tile	Main office toilet room	52	SF	6	\$114	
	Lavatory	Main office toilet room	1	EA	6	\$320	
	Lighting - Wall Mounted	Main office toilet room	1	EA	6	\$124	
	Partitions	Main office toilet room	1	EA	6	\$297	
	Walls - Plaster/Drywall	Main office toilet room	328	SF	6	\$905	
	Water Closet	Main office toilet room	1	EA	6	\$336	
	Accessories	Principal's toilet	98	SF	6	\$904	mirror, paper towel dispenser, toilet paper holder
	Ceiling - Plaster/Drywall	Principal's toilet	98	SF	6	\$339	
	Doors - Wood Doors inclu hw	Principal's toilet	1	EA	6	\$301	
	Floor - Tile	Principal's toilet	98	SF	6	\$214	
	Lavatory	Principal's toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	Principal's toilet	1	EA	7	\$0	
	Walls - Plaster/Drywall	Principal's toilet	443	SF	6	\$1,223	
	Water Closet	Principal's toilet	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$467,948

Building: Main

Category: Building Interior

Group Item - Type	Location	Quantity	Unit	Rank	Cost C	Comments
Corridor						
Ceiling - Plaster/Drywall	1st Floor	3,946	SF	6	\$24,433	
Doors - Steel Doors incl hw	1st Floor	10	EA	6	\$3,010	
Doors - Wood Doors include hw	1st Floor	10	EA	6	\$3,010	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	



Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	Dr.						
	Drinking Fountains - Triple Fountain	1st Floor	1	EA	7	\$0	
	Floor - Epoxy/ Painted	1st Floor	30	SF	6	\$16	
	Floor - Tile/Sheet	1st Floor	3,916	SF	6	\$2,128	
	Lighting - Pendent/Surface	1st Floor	33	EA	7	\$0	
	Stairs - Concrete Stairs	1st Floor	40	LF	6	\$332	
	Walls - Plaster/Drywall	1st Floor	5,412	SF	6	\$23,991	
	Walls - Structural Glazed Tile	1st Floor	75	SF	6	\$236	
	Ceiling - Lay-in	2nd Floor	926	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor	1,781	SF	6	\$11,028	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	6	\$336	
	Drinking Fountains - Triple Fountain	2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	2,707	SF	6	\$1,471	
	Lighting - Lay-in	2nd Floor	6	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	5,242	SF	6	\$23,238	
	Ceiling - Lay-in	3rd Floor	144	SF	6	\$432	
	Ceiling - Plaster/Drywall	3rd Floor	2,563	SF	7	\$0	
	Drinking Fountains - Triple Fountain	3rd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	3rd Floor	2,707	SF	6	\$1,471	
	Lighting - Lay-in	3rd Floor	1	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	153	EA	6	\$14,204	
	Walls - Plaster/Drywall	3rd Floor	5,242	SF	6	\$23,238	
	Ceiling - Plaster/Drywall	Auditorium Vestibule	257	SF	6	\$1,591	
	Doors - Steel Doors incl hw	Auditorium Vestibule	5	EA	6	\$1,505	
	Floor - Concrete Epoxy/ Painted	Auditorium Vestibule	188	SF	6	\$91	
	Lighting - Pendent/Surface	Auditorium Vestibule	5	EA	6	\$619	
	Stairs - Concrete Stairs	Auditorium Vestibule	92	LF	6	\$763	
	Walls - Structural Glazed Tile	Auditorium Vestibule	482	SF	6	\$1,516	
Safety							
	Camera Viewing Station		2	EA	7	\$0	
	Security Cameras		4	EA	7	\$0	
Stairs							
	Ceiling - Plaster/Drywall	North	1,035	SF	6	\$7,578	
	Floor - Tile	North	958	SF	6	\$521	
	Handrails	North	172	LF	6	\$1,491	



Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Lighting - Lay-in	North	1	EA	6	\$119	
	Lighting - Pendent/Surface	North	8	EA	7	\$0	
	Stairs - Concrete	North	390	LF	6	\$3,235	
	Walls - Plaster/Drywall	North	3,129	SF	6	\$8,636	
	Walls - Structural Glazed Tile	North	64	SF	5	\$3,252	
	Ceiling - Plaster/Drywall	South	1,035	SF	6	\$7,578	
	Floor - Tile	South	958	SF	6	\$521	
	Handrails	South	172	LF	6	\$1,491	
	Lighting - Lay-in	South	1	EA	6	\$119	
	Lighting - Pendent/Surface	South	8	EA	6	\$991	
	Stairs - Concrete	South	390	LF	6	\$3,235	
	Walls - Plaster/Drywall	South	3,129	SF	6	\$8,636	
	Walls - Structural Glazed Tile	South	64	SF	6	\$201	
Build	ing Interior Subtotal:					\$186,597	

Building Interior Subtotal:

Total Building Cost

\$3,810,489

SITE

Category: Site

Group	Item - Type	Location	Location Quantity		Rank	Cost	Comments
ivil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	\$0	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	\$310	lightwell
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	\$0	
encing							
	Fencing - Chain Link	Entire Site / South East	27	LF	6	\$507	
	Fencing - New Standard Ornamental	Entire Site	635	LF	5	\$90,424	
	Fencing - New Standard Ornamental	Entire Site	482	LF	7	\$0	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site / South East	20	LF	5	\$1,583	around chain link
.andsca	pe						
	Landscape - Grass	Entire Site	2,783	SF	7	\$0	
	Landscape - Hardscape- Concrete	Entire Site / Site West	300	SF	7	\$0	
	Parkway trees	Entire Site	30	EA	7	\$0	
	Planting Beds/ Area	Entire Site	3,318	SF	7	\$0	

SITE

Category: Site

iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
andsc	ape						
	Play Area - Synthetic Turf Play Field	Entire Site / Site South	10,165	SF	7	\$0	
	Trash Receptacles	Entire Site / Site South	2	EA	7	\$0	
Parking	Lot						
	Concrete Curbs	North	493	LF	6	\$6,331	
	Interior Plantings	North	5	LF	7	\$0	
	Surface - Asphalt	North	13,915	SF	6	\$33,628	
	Surface - Asphalt	North / Site - East	2,125	SF	5	\$11,091	
	Trash Enclosure - Chain Links	North	1,450	SF	6	\$25,442	
	Vehicular Screening	North	268	LF	7	\$0	
Playgro	und						
	Equipment - School Age 5-12	South	2	EA	7	\$0	
	Surface - Poured Surface	South	3,000	SF	7	\$0	
Sidewal	ks						
	Sidewalks - Perimeter Sidewalks	Entire Site	15,009	SF	7	\$0	
	Sidewalks - Perimeter Sidewalks	Entire Site / North East	200	SF	4	\$3,218	cracked
	Sidewalks - Perimeter Sidewalks	Entire Site / Site North	50	SF	5	\$478	
ignage							
	Flag Pole - Flag Pole	Entire Site / Site West	1	EA	6	\$1,657	at main entry
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site / South West	1	EA	7	\$0	
Site S	ubtotal:					\$174,668	
otal	Site Cost					\$174,668	

Campus Total ^{2 3}

\$3,985,157

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main								•				•	ł	
Art Room	Regular Classroom		307	307	878	1	0	16	165	75	50	Ν	Y	Ν
Computer Lab	Regular Classroom		309	309	918	1	63	74	150	60	50	Ν	Y	N
Kindergarten	Kindergarten		109	109	1,045	1	0	10	160	60	50	Ν	Y	N
Multi Purpose Room	Regular Classroom		302	302	878	1	2	10	150	60	50	Ν	Y	N
Office	Regular Classroom		106	106	858	1	2	10	160	60	50	Ν	Y	N
Office	Regular Classroom		108	108	870	1	8	31	160	60	50	Ν	Y	N
Office	Regular Classroom		203	203	852	1	2	22	165	45	50	Ν	Y	N
Pre School	Pre School		107	107	1,080	1	2	10	120	40	50	Ν	Y	N
Regular Classroom	Regular Classroom		201	201	890	1	2	22	165	75	50	Ν	Y	N
Regular Classroom	Regular Classroom		202	202	870	1	2	10	150	60	50	Ν	Y	N
Regular Classroom	Regular Classroom		204	204	858	1	2	10	150	60	50	Ν	Y	N
Regular Classroom	Regular Classroom		205	205	840	1	2	22	165	45	50	Ν	Y	N
Regular Classroom	Regular Classroom		207	207	870	1	3	26	165	75	50	Ν	Y	N
Regular Classroom	Regular Classroom		209	209	870	1	2	10	165	75	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		210	210	918	1	2	10	150	60	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		301	301	892	1	0	10	165	75	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		303	303	844	1	1	14	165	75	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		304	304	864	1	2	10	150	60	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		306	306	864	1	2	14	150	60	50	Ν	Y	N
Regular Classroom	Regular Classroom		308	308	870	1	2	16	150	60	50	Ν	Y	Ν
Regular Classroom	Regular Classroom		310	310	882	1	2	22	150	60	50	Ν	Y	N
Science Classroom	Regular Classroom		305	305	870	1	1	19	165	75	50	Ν	Y	N