

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1927	3	77,900	\$2,571,956
2-Classroom Modular	0	1	1,750	\$107,690
2-Classroom Modular	0	1	1,750	\$104,937
2-Classroom Modular	0	1	1,750	\$96,629
2-Classroom Modular	0	1	1,750	\$88,694
Annex	1996	1	14,000	\$489,598
Branch_North	1996	2	9,925	\$655,726
Branch_South	1996	1	12,600	\$670,895
SITE				\$392,420
Campus Total			121,425	\$5,178,545

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Entrance Control - Audio and Video	Entrance 16 - NW	1	EA	6	\$702	
	Entrance Control - Audio and Video	Entrance 18 - NE	1	EA	6	\$702	
	Entrance Control - Audio and Video	Entrance 5 - SE	1	EA	6	\$702	
	Entrance Control - Audio and Video	Main Entrance 1 - NE	1	EA	6	\$702	
	Exterior Doors - Exterior FRP Door	Entrance 13 - SW	1	EA	6	\$631	Door glass lite cracked
	Exterior Doors - Exterior FRP Door	Entrance 14 - SW	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	Entrance 16 - NW	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	Entrance 17 - NW	1	EA	6	\$631	
	Exterior Doors - Exterior FRP Door	Entrance 5 - SE	1	EA	6	\$631	
	Exterior Doors - Exterior Steel Door	Entrance 15 - West	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Entrance 2 - NE at Detached Boiler Building	1	EA	6	\$481	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Exterior Doors - Exterior Steel Door	Entrance 3 - West - At detached boiler building	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Entrance 4 - East	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Main Entrance 1 - NE	1	EA	6	\$481	
	Exterior Doors - Store Front	Entrance 18 - NE	1	EA	6	\$546	
	Exterior Doors - Transom Lite	Entrance 13 - SW	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Entrance 14 - SW	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Entrance 15 - West	1	EA	6	\$313	
	Exterior Doors - Transom Lite	Entrance 16 - NW	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Entrance 17 - NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	Entrance 18 - NE	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Entrance 2 - NE at Detached Boiler Building	1	EA	6	\$313	Dented throughout
	Exterior Doors - Transom Lite	Entrance 4 - East	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Entrance 5 - SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	Main Entrance 1 - NE	1	EA	7	\$0	
	Exterior Stairs - Concrete	Entrance 13 - SW	73	LF	7	\$0	
	Exterior Stairs - Concrete	Entrance 14 - SW	65	LF	7	\$0	
	Exterior Stairs - Concrete	Entrance 16 - NW	65	LF	7	\$0	
	Exterior Stairs - Concrete	Entrance 17 - NW	65	LF	6	\$5,315	
	Exterior Stairs - Concrete	Entrance 18 - NE	5	LF	7	\$0	
	Exterior Stairs - Concrete	Entrance 2 - NE at Detached Boiler Building	4	LF	6	\$327	
	Exterior Stairs - Concrete	Entrance 5 - SE	5	LF	6	\$409	
	Exterior Stairs - Stone	Entrance 14 - SW	8	LF	7	\$0	
	Exterior Stairs - Stone	Entrance 15 - West	4	LF	6	\$452	
	Exterior Stairs - Stone	Entrance 16 - NW	8	LF	7	\$0	
	Exterior Stairs - Stone	Entrance 17 - NW	8	LF	6	\$904	
	Exterior Stairs - Stone	Entrance 4 - East	18	LF	7	\$0	
	Exterior Stairs - Stone	Main Entrance 1 - NE	18	LF	6	\$2,034	
	Power Door Operator and Controls	Entrance 18 - NE	1	EA	6	\$0	
	Power Door Operator and Controls	Entrance 5 - SE	1	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 18 - NE	106	LF	7	\$0	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 5 - SE	106	LF	6	\$919	
	Ramps - Concrete	Entrance 18 - NE	58	LF	7	\$0	
	Ramps	Entrance 5 - SE	58	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	Entrance 13 - SW	20	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	Entrance 14 - SW	20	LF	7	\$0	



	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran		Location	Quantity	Unit	nann	COSI	Comments
Enuano	Stair Handrail - Steel Stair Handrail	Entrance 16 - NW	20	LF	7	\$0	
	—	Entrance 17 - NW		LF	6	ہ ں \$173	
	Stair Handrail - Steel_Stair Handrail	Entrance 17 - NW Entrance 18 - NE	20 22	LF	6 7	\$173 \$0	
	Stair Handrail - Steel_Stair Handrail		22	LF	7	+ -	
	Stair Handrail - Steel_Stair Handrail	Entrance 5 - SE	25	LF	/	\$0	
Founda	ition						
	Foundation - Concrete	Main / Detached Boiler Building	1,400	LF	7	\$0	
	Superstructure - Concrete	Main / Detached Boiler Building	77,900	SF	7	\$0	1 0
							habitable space
Lightin	g						
	Exterior Lighting - Parapet or Roof Mounted	Main / Detached Boiler Building	11	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Main / Detached Boiler Building	6	EA	6	\$1,732	
	Exterior Lighting - Wall Mounted	Main / Detached Boiler Building	2	EA	5	\$855	Not working at entrances 13,15
Roof S	vstem						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 17 - Detached Boiler Building	60	LF	7	\$0	
	Coping - Metal	Roof 1	245	LF	7	\$0	At top of sloped asphalt slope on west side
	Coping - Metal	Roof 10	8	LF	7	\$0	
	Coping Metal	Roof 11	8	LF	7	\$0	
	Coping - Metal	Roof 7	8	LF	7	\$0	
	Coping - Metal	Roof 8	8	LF	7	\$0	
	Coping - Stone	Roof 1	150	LF	6	\$4,818	Peeling occurring at majority of east side above
			100		0	φ-1,010	ponding area
	Coping - Stone	Roof 4 - NE	20	LF	7	\$0	
	Coping - Stone	Roof 6 - NE	20	LF	7	\$0	
	Coping - Terra Cotta	Roof 1	890	LF	7	\$0	
	Coping - Terra Cotta	Roof 17 - Detached Boiler Building	190	LF	7	\$0	
	Coping - Terra Cotta	Roof 2 - SW	60	LF	7	\$0	
	Coping - Terra Cotta	Roof 3 - NW	60	LF	7	\$0	
	Coping - Terra Cotta	Roof 5 - NE	30	LF	7	\$0	
	Coping - Terra Cotta	Roof 9	32	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 10	35	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 11	12	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 5 - NE	25	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 7	35	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 8	12	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 1	360	LF	5	\$79,670	Ponding occurring at all roof drains due to debris
	Downspouts - Interior Downspouts	Roof 17 - Detached Boiler Building	18	LF	6	\$598	
	· ·	5					



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	vstem						
	Downspouts - Interior Downspouts	Roof 4 - NE	12	LF	6	\$399	
	Downspouts - Interior Downspouts	Roof 6 - NE	12	LF	6	\$399	Debris around strainer
	Parapet - 16" - 30" Height	Roof 1	655	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 17 - Detached Boiler Building	110	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 3 - NW	30	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 5 - NE	30	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 1	20	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 17 - Detached Boiler Building	40	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 2 - SW	30	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 3 - NW	30	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 4 - NE	20	LF	6	\$426	
	Parapet - Parapet < 16" Height	Roof 6 - NE	20	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 9	32	LF	6	\$682	
	Parapet - Parapet > 30"	Roof 1	365	LF	7	\$0	
	Parapet - Parapet > 30"	Roof 17 - Detached Boiler Building	50	LF	7	\$0	
	Roof Structure - Concrete	Roof 1	27,145	SF	7	\$0	
	Roof Structure - Concrete	Roof 10	45	SF	7	\$0	
	Roof Structure - Concrete	Roof 11	150	SF	7	\$0	
	Roof Structure - Concrete	Roof 17 - Detached Boiler Building	2,750	SF	7	\$0	
	Roof Structure - Concrete	Roof 2 - SW	225	SF	7	\$0	
	Roof Structure - Concrete	Roof 3 - NW	225	SF	7	\$0	
	Roof Structure - Concrete	Roof 5 - NE	100	SF	7	\$0	
	Roof Structure - Concrete	Roof 7	45	SF	7	\$0	
	Roof Structure - Concrete	Roof 8	150	SF	7	\$0	
	Roof Structure - Concrete	Roof 9	115	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4 - NE	100	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 6 - NE	100	SF	7	\$0	
	Roof - Asphalt Shingle	Roof 1	2,615	SF	7	\$0	At west side
	Roof - Modified Bitumen	Roof 1	23,530	SF	6	\$221,403	
	Roof - Modified Bitumen	Roof 1	1,000	SF	6	\$19,419	Ponding occurring at east side around parapet light
	Roof - Modified Bitumen	Roof 10	45	SF	7	\$0	
	Roof - Modified Bitumen	Roof 11	150	SF	6	\$1,411	Ponding occurring - not accessible.
	Roof - Modified Bitumen	Roof 17 - Detached Boiler Building	2,750	SF	7	\$0	
	Roof - Modified Bitumen	Roof 2 - SW	220	SF	7	\$0	
	Roof - Modified Bitumen	Roof 2 - SW	5	SF	6	\$97	Ponding occurring at SE corner
	Roof - Modified Bitumen	Roof 3 - NW	225	SF	7	\$0	
	Roof - Modified Bitumen	Roof 4 - NE	100	SF	7	\$0	



Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof S	ystem						
	Roof - Modified Bitumen	Roof 5 - NE	100	SF	7	\$0	
	Roof - Modified Bitumen	Roof 6 - NE	100	SF	7	\$0	
	Roof - Modified Bitumen	Roof 7	45	SF	7	\$0	
	Roof - Modified Bitumen	Roof 8	150	SF	6	\$1,411	Ponding occurring due to no slope to gutter - roof not accessible
	Roof - Modified Bitumen	Roof 9	115	SF	6	\$1,082	
Walls							
	Cheek-Wall - Concrete	Main / Detached Boiler Building	150	SF	7	\$0	At entrances 13, 14, 16, 17
	Exterior Walls - Brick	Main / Detached Boiler Building	29,890	SF	7	\$0	
	Exterior Walls - Terra Cotta	Main / Detached Boiler Building	5,370	SF	7	\$0	
Windov	vs						
	Clerestory - Glass Single-Pane	Main / Detached Boiler Building	300	SF	7	\$0	At south elevation in gym / At north elevation at Auditorium
	Guard - Guards perforated	Main / Detached Boiler Building	3,080	SF	6	\$39,331	
	Lintels - Steel	Main / Detached Boiler Building	790	LF	6	\$22,933	
	Lintels - Terra Cotta	Main / Detached Boiler Building	425	LF	6	\$0	
	Windows - Decorative	Main / Detached Boiler Building	150	SF	7	\$0	
	Windows - Insulated Panel	Main / Detached Boiler Building	50	SF	6	\$373	At north elevation of detached boiler building - dented throughout
	Windows - Louver	Main / Detached Boiler Building	95	SF	6	\$709	
	Windows - Sash Aluminum Double-pane	Main / Detached Boiler Building	4,200	SF	6	\$31,351	
						<u></u>	

Building Exterior Subtotal:

\$449,800

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	3	EA	7	\$0	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	4,359	SF	7	\$0	
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,670	SF	7	\$0	
	Emergency A/C Power - Gym	Entire Building	3,350	SF	7	\$0	
	Emergency A/C Power - Students Toilets	Entire Building	2,155	SF	7	\$0	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	4	EA	6	\$810	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / Basement	3	EA	6	\$608	
	Emergency Generator- Indoor- Natural Gas - Below 60 KW	Basement	1	EA	7	\$0	
	Exit Signs - Auditoium	Entire Building	5	EA	6	\$749	



Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	6	\$3,145	
	Exit Signs - Gym	Entire Building	2	EA	6	\$315	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	\$299	
	Security System - CCTV	Entire Building	77,900	SF	6	\$23,393	
	Security System - Intrusion Detection	Entire Building	77,900	SF	6	\$20,051	
Main S	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	\$5,078	
	Main Electrical Service - 1200 A 277/480/3PH	Electrical Room	1	EA	6	\$5,346	serves Motor Control Center only
	PA System	Entire Building	77,900	SF	6	\$25,621	
Power	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	\$299	Emergency Fuse Panel
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	\$4,849	live front and heavily deteriorated panel, label is not legible
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	\$2,094	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	\$4,849	Panel has been in service over 40 years and new breakers are not available
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	\$6,578	Panel has been in service over 40 years and new breakers are not available
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	\$3,479	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	Motor Control Center
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	2	EA	6	\$1,460	
	Main Distribution Panels - Less than 400 amp	Entire Building / Basement	1	EA	6	\$503	
	Transformers - 277/480 - 120/208	Entire Building	3	EA	6	\$3,795	

Electrical System Subtotal:

Building: Main

\$114,053

Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building / Basement	1	EA	6	\$6,406	
Fire Alarm Strobe Lights	Entire Building	77,900	SF	7	\$0	
Fire Alarm_System	Entire Building	77,900	SF	6	\$37,875	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	System Subtotal:		-			\$44,281	
Buildi	ng: Main						
Categ	ory: Mechanical System						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chemical Pot Feeder	Entire Building / Boiler Room	1	EA	6	\$725	
	Chiller-Water Cooled- Absorber - 101 - 200 tons	Entire Building / Boiler Room	2	EA	5	\$127,335	
	Cooling Tower - Closed Cell- 101 - 200 tons	Entire Building / Roof	2	EA	6	\$9,938	
	Pipes - Chilled Water Pipe- Steel	Entire Building	300	LF	6	\$566	
Air Hane	dling Systems						
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coil and Chilled Water Coils - Greater than 30,000 cfm	Basement	1	EA	6	\$3,350	serves north end of building only
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coil and Chilled Water Coils - Greater than 30,000 cfm	Entire Building	1	EA	6	\$3,350	serves south end of building only
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 4000-8000 cfm	Basement	1	EA	6	\$3,350	serves gym only
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 8001-12000 cfm	Basement	1	EA	6	\$3,350	serves auditorium only
	Air Intake	Basement	1	EA	6	\$5,765	
	Air Intake	Basement	1	EA	6	\$5,765	
	Air Intake	Basement	1	EA	6	\$5,765	
	Air Intake	Entire Building	1	EA	6	\$5,765	
	Fan Coil Unit- Celing Mounted - Steam	Entire Building	21	EA	6	\$33,744	
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Basement	1	EA	6	\$1,857	serves auditorium AHU
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Basement	1	EA	6	\$2,433	serves south end AHU
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Basement	1	EA	6	\$2,433	serves north end AHU
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Basement	1	EA	6	\$1,282	serves gym AHU
	Zone Dampers	Basement	18	EA	6	\$14,995	
	Zone Dampers	Entire Building	15	EA	6	\$12,495	
oiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Entire Building / Boiler Room	2	EA	6	\$1,996	
	Chemical Feed System	Entire Building / Boiler Room	1	EA	6	\$1,078	
	Chemical Feeder	Entire Building / Boiler Room	1	EA	6	\$1,078	
	Combustion Dampers	Entire Building / Boiler Room	2	EA	6	\$818	



Building: Main

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Condensate Pump	Entire Building / Boiler Room	1	EA	6	\$2,021	
Feed Water Pumps and Tank	Entire Building / Boiler Room	1	EA	6	\$2,545	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Entire Building / Boiler Room	2	EA	6	\$1,996	Boilers shells are completely insulated and labeling is not accessible.
Piping - Condensate Pipe- Steel	Entire Building	500	LF	6	\$944	
Piping - Steam Pipe- Steel	Entire Building	500	LF	6	\$944	
Steam Traps	Entire Building	75	EA	5	\$98,617	
Heating Devices						
Cabinet Heaters - With Steam Coil	Entire Building	5	EA	6	\$1,783	
Duct Heater - Hot Water	Basement	29		6	\$13,992	
Fin Tube - Steam	Entire Building	24	LF	6	\$227	
Radiators - Steam	Entire Building	14	EA	6	\$3,889	
Unit Heater - Electric	Entire Building	6	EA	4	\$12,007	Heater has been in service for more than 20 years and is not working.
Unit Heater - Electric	Entire Building	3	EA	6	\$833	-
Unit Heater - Gas	Entire Building / Boiler Room	1	EA	6	\$278	
Unit Heater - Steam	Entire Building	6	EA	6	\$1,667	
Wall Heater - Electric	Entire Building	1	EA	5	\$537	
Wall Heater - Electric	Entire Building	6	EA	6	\$833	
Mechanical Plumbing						
Chilled Water Pump - 10 - 20 HP	Boiler Room	2	EA	6	\$2,485	
Condenser Pump - Less than 10	Boiler Room	2	EA	6	\$2,222	
Temperature Control						
DDC System	Entire Building	38,950	SF	5	\$64,053	controls FCU's and some Exhaust Fans
DDC System	Entire Building	38,950	SF	5	\$64,053	Monitors AHU's, Chillers, Boilers & some Exhaust Fans
Thermostats - DDC	Entire Building	43	EA	6	\$0	
Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Boiler Room	1	EA	6	\$592	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	5	EA	7	\$0	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	7	\$0	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	7	\$0	
Type II Exhaust Hood- Warming Kitchen	Entire Building / 1st Floor	1	EA	6	\$920	
Mechanical System Subtotal:					\$526,670	



Building: Main

Category: Plumbing System

b Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
/ater						
Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	\$310	
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	77,900	SF	6	\$15,596	
Domestic Piping-Cold Water Horizontal Lines	Entire Building	77,900	SF	6	\$18,937	
Domestic Piping-Cold Water Risers	Entire Building	77,900	SF	6	\$14,482	
Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,900	SF	6	\$12,254	
Domestic Piping-Hot Water Horizontal Lines	Entire Building	77,900	SF	6	\$14,482	
Domestic Piping-Hot Water Return Lines	Entire Building	77,900	SF	6	\$11,140	
Domestic Piping-Hot Water Return Risers	Entire Building	77,900	SF	6	\$11,140	
Sanitary Piping	Entire Building	77,900	SF	6	\$71,294	
Storm Piping	Entire Building	77,900	SF	6	\$71,294 \$67,952	
Vent Piping	Entire Building	77,900	SF	6	\$52,357	
		11,300	0	0	ψυ2,007	
S						
	Entire Building / Electrical Room	1	EA	5	\$7,535	
Pumps - Ejector-Duplex hbing System Subtotal: ding: Main					\$297,477	
nbing System Subtotal: ding: Main gory: Classrooms		0	11-14	Deule		Commente
nbing System Subtotal: ding: Main gory: Classrooms o Item - Type	Location	Quantity	Unit	Rank		Comments
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten)	Location	-			Cost	Comments
hbing System Subtotal: ding: Main gory: Classrooms tem - Type room #110 (Kindergarten) Casework	Location 1st Floor	10	LF	6	Cost \$253	Comments
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in	Location 1st Floor 1st Floor	10 715	LF SF	6 6	Cost \$253 \$2,147	Comments
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board	Location 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45	LF SF LF	6 6 4	Cost \$253 \$2,147 \$4,131	Comments
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45 8	LF SF LF SF	6 6 4 6	\$253 \$2,147 \$4,131 \$135	Comments
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45 8 1	LF SF LF SF EA	6 6 4 6	Cost \$253 \$2,147 \$4,131 \$135 \$301	
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45 8 1 715	LF SF LF SF EA SF	6 6 4 6 5	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210	Comments cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45 8 1 715 14	LF SF LF SF EA SF EA	6 6 4 6 5 6	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666	cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall	Location 1st Floor 1st Floor	10 715 45 8 1 715 14 5	LF SF LF EA SF EA SF	6 4 6 5 6 5	\$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666 \$26	
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Vood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	10 715 45 8 1 715 14	LF SF LF SF EA SF EA	6 6 4 6 5 6	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666	cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall	Location 1st Floor 1st Floor	10 715 45 8 1 715 14 5	LF SF LF EA SF EA SF	6 4 6 5 6 5	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666 \$26 \$3,339	cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Plaster/Drywall room #112 (Regular Classroom) Casework	Location 1st Floor 1st Floor	10 715 45 8 1 715 14 5	LF SF EA SF EA SF SF	6 4 6 5 6 5	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666 \$26 \$3,339 \$253	cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Plaster/Drywall room #112 (Regular Classroom) Casework Ceiling - Lay-in	Location 1st Floor 1st Floor	10 715 45 8 1 715 14 5 1,210	LF SF EA SF EA SF SF LF	6 6 6 5 6 5 6	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666 \$26 \$3,339 \$253 \$2,147	cracking throughout
hbing System Subtotal: ding: Main gory: Classrooms b Item - Type room #110 (Kindergarten) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Plaster/Drywall room #112 (Regular Classroom) Casework	Location 1st Floor 1st Floor	10 715 45 8 1 715 14 5 1,210	LF SF EA SF EA SF SF	6 4 6 5 6 5 6	Cost \$253 \$2,147 \$4,131 \$135 \$301 \$3,210 \$1,666 \$26 \$3,339 \$253	cracking throughout



Building: Main

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroc	om #112 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	5	\$3,210	cracking throughout
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	
	Marker Board	1st Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,215	SF	6	\$3,353	
sroc	om #116 (Kindergarten)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	1,010	SF	6	\$3,033	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,010	SF	5	\$4,535	cracking throughout
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	
	Marker Board	1st Floor	10	LF	7	\$0	
	Storage/ Closet	1st Floor	55	SF	6	\$399	
	Walls - Plaster/Drywall	1st Floor	1,550	SF	6	\$4,278	
sroc	om #117 (Regular Classroom)						
	Casework	1st Floor	45	LF	6	\$1,136	
	Ceiling - Lay-in	1st Floor	715	SF	6	\$2,147	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	5	\$3,210	cracking throughout
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	
	Marker Board	1st Floor	20	LF	7	\$0	
	Storage/ Closet	1st Floor	30	SF	6	\$218	
	Walls - Plaster/Drywall	1st Floor	1,215	SF	6	\$3,353	
	Work Sink	1st Floor	1	EA	6	\$379	
sroc	om #118 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	715	SF	6	\$2,147	
	Chalk Board	1st Floor	25	LF	4	\$2,295	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	



Building: Main

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #118 (Regular Classroom)						
	Marker Board	1st Floor	28	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,215	SF	6	\$3,353	
lassro	oom #119 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	715	SF	6	\$2,147	
	Chalk Board	1st Floor	18	LF	4	\$1,653	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	6	\$1,564	
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	
	Marker Board	1st Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,210	SF	6	\$3,339	
lassro	oom #120 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	715	SF	6	\$2,147	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	715	SF	5	\$3,210	cracking throughout
	Lighting - Lay-in	1st Floor	14	EA	6	\$1,666	
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,215	SF	6	\$3,353	
lassro	oom #208 (Special Program)						
	Ceiling - Lay-in	2nd Floor	480	SF	6	\$1,441	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	\$1,174	
	Floor - Tile/Sheet	2nd Floor	480	SF	6	\$480	
	Lighting - Lay-in	2nd Floor	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,086	SF	6	\$2,997	
lassro	oom #210 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #210 (Regular Classroom)	Location	Quantity	Onit	Nain	0031	Commente
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	¢/ 10 \$0	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
		211011001	000	01	0	ψ2,000	
	om #211 (Store Room)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	6	\$214	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
lassroo	om #212 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
lassroo	om #213 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	18	LF	4	\$1,653	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	



Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	boom #214 (Computer Lab)	Loodion	quantity	onit	Num	0031	Comments
010001	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Charging Station	2nd Floor	1	EA	6	\$485	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	80	SF	5	\$394	Broken and crack tiles
	Floor - Tile/Sheet	2nd Floor	635	SF	6	\$636	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0 \$0	
	Marker Board	2nd Floor	10	LF	6	\$214	
	Storage/ Closet	2nd Floor	15	SF	5	\$242	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
		21011001	300	01	0	ψ2,000	
Classro	oom #215 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	6	\$171	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
Classro	oom #216 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	6	\$214	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
Classro	oom #217 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #217 (Regular Classroom)						
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
assro	om #218 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
assro	om #219 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	28	LF	4	\$2,571	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	6	\$171	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	
ssro	om #220 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	715	SF	6	\$2,147	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	6	\$214	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	960	SF	6	\$2,650	



Building: Main

Category: Classrooms

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assroom #222 (Regular Classroom)						
Ceiling - Lay-in	2nd Floor	770	SF	6	\$2,312	
Chalk Board	2nd Floor	12	LF	6	\$268	
Doors - Transom Window	2nd Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	770	SF	6	\$771	Broken piece of tile and shows evidence of wear and tear
Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
Marker Board	2nd Floor	10	LF	6	\$214	
Storage/ Closet	2nd Floor	20	SF	6	\$145	
Walls - Plaster/Drywall	2nd Floor	980	SF	6	\$2,705	

Classrooms Subtotal:

\$203,553

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor-103A Art Room Office	130	SF	6	\$450	
	Doors - Wood Doors inclu hw	1st Floor-103A Art Room Office	1	EA	6	\$301	
	Floor - Carpet	1st Floor-103A Art Room Office	130	SF	5	\$667	ripped, dirty
	Lighting - Pendent/Surface	1st Floor-103A Art Room Office	1	EA	6	\$124	
	Power Distribution	1st Floor-103A Art Room Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st Floor-103A Art Room Office	470	SF	6	\$1,297	
	Ceiling - Plaster/Drywall	1st Floor-103B Music Office	88	SF	5	\$807	cracks
	Doors - Wood Doors inclu hw	1st Floor-103B Music Office	1	EA	6	\$301	
	Floor - Carpet	1st Floor-103B Music Office	88	SF	5	\$452	dirty, ripped
	Lighting - Pendent/Surface	1st Floor-103B Music Office	1	EA	6	\$124	
	Power Distribution	1st Floor-103B Music Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st Floor-103B Music Office	390	SF	6	\$1,076	
	Ceiling - Lay-in	1st Floor-108 Office	465	SF	6	\$1,396	
	Doors - Transom Window	1st Floor-108 Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor-108 Office	1	EA	6	\$301	
	Floor - Tile	1st Floor-108 Office	460	SF	6	\$1,006	
	Floor - Tile	1st Floor-108 Office	2	SF	5	\$12	missing/broken
	Floor - Tile	1st Floor-108 Office	3	SF	5	\$17	cracked
	Lighting - Lay-in	1st Floor-108 Office	8	EA	6	\$952	
	Power Distribution	1st Floor-108 Office	10	EA	6	\$21,249	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	trative Suites/Offices						
	Walls - Plaster/Drywall	1st Floor-108 Office	955	SF	6	\$2,636	
	Walls - Plaster/Drywall	1st Floor-108 Office	5	SF	5	\$26	cracking
	Ceiling - Lay-in	1st Floor-114 Resource Room	370	SF	6	\$1,111	
	Ceiling - Plaster/Drywall	1st Floor-114 Resource Room	48	SF	6	\$166	
	Doors - Wood Doors inclu hw	1st Floor-114 Resource Room	2	EA	6	\$602	
	Floor - Terrazzo	1st Floor-114 Resource Room	48	SF	6	\$105	
	Floor - Tile	1st Floor-114 Resource Room	370	SF	5	\$1,661	cracking throughout
	Lighting - Lay-in	1st Floor-114 Resource Room	6	EA	6	\$714	
	Lighting - Pendent/Surface	1st Floor-114 Resource Room	2	EA	6	\$248	
	Power Distribution	1st Floor-114 Resource Room	10	EA	6	\$21,249	
	Storage/ Closet	1st Floor-114 Resource Room	98	SF	4	\$2,731	asbestos, missing floor tiles
	Storage/ Closet	1st Floor-114 Resource Room	38	SF	6	\$276	
	Walls - Plaster/Drywall	1st Floor-114 Resource Room	1,016	SF	6	\$2,804	
	Ceiling - Plaster/Drywall	1st Floor-114B Learning Center	150	SF	6	\$519	
	Doors - Wood Doors inclu hw	1st Floor-114B Learning Center	1	EA	6	\$301	
	Floor - Terrazzo	1st Floor-114B Learning Center	100	SF	6	\$219	
	Floor - Tile Ceramic/ Porcelain	1st Floor-114B Learning Center	50	SF	6	\$106	
	Lighting - Pendent/Surface	1st Floor-114B Learning Center	2	EA	6	\$248	
	Power Distribution	1st Floor-114B Learning Center	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st Floor-114B Learning Center	740	SF	6	\$2,042	
	Ceiling - Lay-in	1st Floor-115B Principal's Office	125	SF	6	\$375	
	Doors - Wood Doors inclu hw	1st Floor-115B Principal's Office	1	EA	6	\$301	
	Floor - Carpet	1st Floor-115B Principal's Office	125	SF	6	\$266	dirty, ripped
	Lighting - Lay-in	1st Floor-115B Principal's Office	3	EA	6	\$357	
	Power Distribution	1st Floor-115B Principal's Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st Floor-115B Principal's Office	485	SF	6	\$1,339	
	Ceiling - Lay-in	1st Floor-121 Kitchen Office/Prep Room	570	SF	6	\$1,712	
	Doors - Steel Doors incl hw	1st Floor-121 Kitchen Office/Prep Room	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-121 Kitchen Office/Prep Room	3	EA	6	\$903	
	Floor - Tile	1st Floor-121 Kitchen Office/Prep Room	570	SF	6	\$1,247	
	Lighting - Lay-in	1st Floor-121 Kitchen Office/Prep Room	10	EA	6	\$1,190	
	Power Distribution	1st Floor-121 Kitchen Office/Prep Room	12	EA	6	\$25,499	
	Storage/ Closet	1st Floor-121 Kitchen Office/Prep Room	85	SF	6	\$616	Storage 121B
	Walls - Plaster/Drywall	1st Floor-121 Kitchen Office/Prep Room	1,035	SF	6	\$2,856	
	Ceiling - Lay-in	1st Floor-124 Teacher's Lounge	375	SF	6	\$1,126	
	Doors - Transom Window	1st Floor-124 Teacher's Lounge	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor-124 Teacher's Lounge	1	EA	6	\$301	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	strative Suites/Offices						
	Floor - Carpet	1st Floor-124 Teacher's Lounge	375	SF	5	\$1,925	dirty, ripped
	Lighting - Lay-in	1st Floor-124 Teacher's Lounge	5	EA	6	\$595	
	Power Distribution	1st Floor-124 Teacher's Lounge	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	1st Floor-124 Teacher's Lounge	985	SF	6	\$2,719	
	Ceiling - Lay-in	1st Floor-Main Office	275	SF	6	\$826	
	Doors - Transom Window	1st Floor-Main Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	6	\$301	
	Floor - Carpet	1st Floor-Main Office	110	SF	5	\$565	dirty, ripped
	Floor - Tile	1st Floor-Main Office	165	SF	5	\$741	cracking throughout
	Lighting - Lay-in	1st Floor-Main Office	6	EA	6	\$714	
	Power Distribution	1st Floor-Main Office	6	EA	6	\$12,749	
	Storage/ Closet	1st Floor-Main Office	160	SF	6	\$1,160	Storage 115A
	Storage/ Closet	1st Floor-Main Office	10	SF	6	\$73	
	Walls - Plaster/Drywall	1st Floor-Main Office	790	SF	6	\$2,180	
	Ceiling - Lay-in	2nd floor - Resource Office	448	SF	6	\$1,345	
	Doors - Wood Doors inclu hw	2nd floor - Resource Office	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor - Resource Office	448	SF	6	\$448	
	Lighting - Lay-in	2nd floor - Resource Office	6	EA	6	\$714	
	Power Distribution	2nd floor - Resource Office	4	EA	5	\$15,407	
	Storage/ Closet	2nd floor - Resource Office	30	SF	6	\$218	
	Walls - Plaster/Drywall	2nd floor - Resource Office	845	SF	6	\$2,332	
	Ceiling - Plaster/Drywall	2nd Floor-Balcony Administration Office	95	SF	6	\$329	
	Doors - Wood Doors inclu hw	2nd Floor-Balcony Administration Office	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	2nd Floor-Balcony Administration Office	95	SF	6	\$50	
	Lighting - Pendent/Surface	2nd Floor-Balcony Administration Office	1	EA	6	\$124	
	Power Distribution	2nd Floor-Balcony Administration Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd Floor-Balcony Administration Office	410	SF	6	\$1,132	
	Ceiling - Plaster/Drywall	Engineer's Office	116	SF	6	\$401	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	\$301	
	Floor - Tile/Sheet	Engineer's Office	116	SF	6	\$116	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	6	\$124	
	Power Distribution	Engineer's Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	Engineer's Office	356	SF	6	\$983	
	Work Sink	Engineer's Office	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	Office 230	136	SF	6	\$471	
	Doors - Wood Doors inclu hw	Office 230	1	EA	6	\$301	
	Floor - Tile/Sheet	Office 230	136	SF	6	\$136	



up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninis	strative Suites/Offices						
	Lighting - Pendent/Surface	Office 230	2	EA	7	\$0	
	Power Distribution	Office 230	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	Office 230	420	SF	6	\$1,159	
	Ceiling - Lay-in	Part of room 226 IDF	362	SF	6	\$1,087	
	Doors - Wood Doors inclu hw	Part of room 226 IDF	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	Part of room 226 IDF	362	SF	6	\$766	
	Lighting - Lay-in	Part of room 226 IDF	5	EA	7	\$0	
	Power Distribution	Part of room 226 IDF	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	Part of room 226 IDF	260	SF	6	\$718	
	Walls - Structural Glazed Tile	Part of room 226 IDF	700	SF	6	\$2,202	
	Work SInk	Part of room 226 IDF	1	EA	6	\$508	
itori	ium & Theater						
	Balcony Seating	1st Floor-103 Auditorium	66	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor-103 Auditorium	4,378	SF	6	\$36,499	
	Doors - Wood Doors inclu hw	1st Floor-103 Auditorium	4	EA	6	\$1,204	
	Floor - Concrete Epoxy/ Painted	1st Floor-103 Auditorium	3,756	SF	6	\$1,987	
	Floor - Terrazzo	1st Floor-103 Auditorium	182	SF	6	\$398	
	Floor - Wood	1st Floor-103 Auditorium	460	SF	6	\$3,243	
	Lighting - Pendent/Surface	1st Floor-103 Auditorium	28	EA	6	\$3,469	
	Lighting - Wall Mounted	1st Floor-103 Auditorium	7	EA	6	\$867	
	Main Floor Seating	1st Floor-103 Auditorium	286	EA	7	\$0	
	Sound System	1st Floor-103 Auditorium	1	EA	6	\$10,721	
	Stage	1st Floor-103 Auditorium	460	SF	6	\$2,658	
	Stage Curtain	1st Floor-103 Auditorium	9	EA	6	\$0	
	Stage Lift	1st Floor-103 Auditorium	1	EA	6	\$6,510	
	Stage Lighting System	1st Floor-103 Auditorium	2	EA	6	\$16,154	
	Stage-Stairs - Terrazzo	1st Floor-103 Auditorium	4	LF	6	\$31	
	Stage-Stairs - Wood	1st Floor-103 Auditorium	8	LF	6	\$94	
	Stairs - Asphalt	1st Floor-103 Auditorium	60	LF	6	\$557	balcony stairs
	Stairs - Terrazzo	1st Floor-103 Auditorium	18	LF	6	\$138	to balcony
	Walls - Plaster/Drywall	1st Floor-103 Auditorium	6,095	SF	6	\$29,024	-
	Walls - Plaster/Drywall	1st Floor-103 Auditorium	70	SF	6	\$456	Marble
nnas	sia						
	Ceiling - Plaster/Drywall	1st Floor-128 Gym	2,800	SF	6	\$15,455	
	Doors - Wood Doors inclu hw	1st Floor-128 Gym	2	EA	6	\$602	
	Floor - Wood	1st Floor-128 Gym	2,800	SF	6	\$19,740	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymna	sia						
	Lighting - Lay-in	1st Floor-128 Gym	12	EA	6	\$1,428	
	Scoreboards	1st Floor-128 Gym	1	EA	6	\$2,244	
	Walls - Masonry	1st Floor-128 Gym	1,530	SF	6	\$4,813	
	Walls - Plaster/Drywall	1st Floor-128 Gym	3,800	SF	6	\$10,488	
Kitcher	1						
	Ceiling - Lay-in	1st Floor-123 Kitchen	695	SF	6	\$2,087	
	Doors - Transom Window	1st Floor-123 Kitchen	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor-123 Kitchen	1	EA	6	\$301	
	Floor - Tile	1st Floor-123 Kitchen	695	SF	6	\$1,521	
	Lighting - Lay-in	1st Floor-123 Kitchen	8	EA	6	\$952	
	Storage/ Closet	1st Floor-123 Kitchen	85	SF	6	\$616	
	Walls - Plaster/Drywall	1st Floor-123 Kitchen	950	SF	6	\$2,622	
	Walls - Tile Ceramic/ Porcelain	1st Floor-123 Kitchen	255	SF	6	\$576	
Library							
	Casework	1st Floor-122 Library	50	LF	6	\$1,263	
	Ceiling - Lay-in	1st Floor-122 Library	700	SF	6	\$2,102	
	Doors - Side-lite	1st Floor-122 Library	70	SF	6	\$1,170	
	Doors - Transom Window	1st Floor-122 Library	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor-122 Library	1	EA	6	\$301	
	Floor - Carpet	1st Floor-122 Library	700	SF	5	\$3,594	ripped, dirty
	Lighting - Lay-in	1st Floor-122 Library	14	EA	6	\$1,666	
	Walls - Plaster/Drywall	1st Floor-122 Library	1,200	SF	6	\$3,312	
MDF_IC	DF						
	Doors - Wood Doors inclu hw	226 IDF	1	EA	6	\$301	
	Finishes	226 IDF	518	SF	6	\$3,696	Glaze masonry
	Finishes	226 IDF	98	SF	6	\$699	Dry wall/Plaster
Mechar	nical/ Service Rooms						
	Crawl Space - Unfinished	1st Floor	4,670	SF	6	\$28,916	
	Janitor's Closet	1st Floor	80	SF	6	\$573	
	Janitor's Closet	1st Floor	80	SF	6	\$573	
	Mechanical/ Service Rooms	1st Floor	7,600	SF	6	\$54,449	Fan Room
	Mechanical/ Service Rooms	1st Floor	105	SF	6	\$752	136 Elevator Equipment
	Storage Room	1st Floor	340	SF	6	\$2,436	126 Storage
	Janitor's Closet	2nd Floor	30	SF	6	\$215	Sourheast location
	Janitor's Closet	2nd Floor	42	SF	6	\$301	Southwest location



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mecha	nical/ Service Rooms						
	Boiler Room	Basement	2,739	SF	6	\$19,623	
	Mechanical/ Service Rooms	Basement	40	SF	6	\$287	Electrical switchgear area
	Mechanical/ Service Rooms	Basement	408	SF	6	\$2,923	Generac area
	Storage Room	Basement	936	SF	6	\$6,706	
	Storage Room	Storage 208A - In room 208	104	SF	6	\$745	
Restro	om						
	Accessories	1st Floor-121 Kitchen Office Restroom	40	SF	6	\$369	
	Ceiling - Plaster/Drywall	1st Floor-121 Kitchen Office Restroom	40	SF	6	\$138	
	Doors - Wood Doors inclu hw	1st Floor-121 Kitchen Office Restroom	1	EA	5	\$1,174	wood chipping
	Floor - Tile	1st Floor-121 Kitchen Office Restroom	40	SF	6	\$88	
	Lavatory	1st Floor-121 Kitchen Office Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-121 Kitchen Office Restroom	1	EA	4	\$541	T-12, missing cover
	Partitions	1st Floor-121 Kitchen Office Restroom	1	EA	6	\$297	
	Student Lockers - Two Tiers	1st Floor-121 Kitchen Office Restroom	4	EA	6	\$186	
	Walls - Plaster/Drywall	1st Floor-121 Kitchen Office Restroom	380	SF	6	\$1,049	
	Water Closet	1st Floor-121 Kitchen Office Restroom	1	EA	6	\$336	
	Accessories	1st Floor-124 Teacher's Lounge Restroom	85	SF	6	\$784	
	Ceiling - Plaster/Drywall	1st Floor-124 Teacher's Lounge Restroom	85	SF	6	\$294	
	Doors - Wood Doors inclu hw	1st Floor-124 Teacher's Lounge Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-124 Teacher's Lounge Restroom	85	SF	6	\$180	
	Hand Dryer	1st Floor-124 Teacher's Lounge Restroom	1	EA	6	\$230	
	Lavatory	1st Floor-124 Teacher's Lounge Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-124 Teacher's Lounge Restroom	1	EA	6	\$124	
	Partitions	1st Floor-124 Teacher's Lounge Restroom	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st Floor-124 Teacher's Lounge Restroom	505	SF	6	\$1,394	
	Water Closet	1st Floor-124 Teacher's Lounge Restroom	2	EA	6	\$672	
	Accessories	1st Floor-E Boy's Restroom	250	SF	6	\$2,306	
	Ceiling - Plaster/Drywall	1st Floor-E Boy's Restroom	250	SF	6	\$865	
	Doors - Wood Doors inclu hw	1st Floor-E Boy's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-E Boy's Restroom	1	EA	6	\$1,059	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor - Tile Ceramic/ Porcelain	1st Floor-E Boy's Restroom	250	SF	6	\$529	
	Hand Dryer	1st Floor-E Boy's Restroom	2	EA	6	\$460	
	Lavatory	1st Floor-E Boy's Restroom	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor-E Boy's Restroom	6	EA	6	\$743	
	Partitions	1st Floor-E Boy's Restroom	5	EA	6	\$1,485	
	Urinals	1st Floor-E Boy's Restroom	3	EA	6	\$1,008	
	Walls - Masonry	1st Floor-E Boy's Restroom	275	SF	6	\$865	
	Walls - Plaster/Drywall	1st Floor-E Boy's Restroom	500	SF	6	\$1,380	
	Walls - Structural Glazed Tile	1st Floor-E Boy's Restroom	68	SF	6	\$214	
	Water Closet	1st Floor-E Boy's Restroom	2	EA	6	\$672	
	Accessories	1st Floor-E Girl's Restroom	275	SF	6	\$2,536	
	Ceiling - Plaster/Drywall	1st Floor-E Girl's Restroom	275	SF	6	\$952	
	Doors - Wood Doors inclu hw	1st Floor-E Girl's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-E Girl's Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-E Girl's Restroom	275	SF	6	\$582	
	Hand Dryer	1st Floor-E Girl's Restroom	2	EA	6	\$460	
	Lavatory	1st Floor-E Girl's Restroom	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor-E Girl's Restroom	6	EA	6	\$743	
	Partitions	1st Floor-E Girl's Restroom	5	EA	6	\$1,485	
	Walls - Masonry	1st Floor-E Girl's Restroom	520	SF	6	\$1,636	
	Walls - Plaster/Drywall	1st Floor-E Girl's Restroom	520	SF	6	\$1,435	
	Walls - Structural Glazed Tile	1st Floor-E Girl's Restroom	68	SF	6	\$214	
	Water Closet	1st Floor-E Girl's Restroom	5	EA	6	\$1,680	
	Accessories	1st Floor-Principal's Office Restroom	25	SF	6	\$231	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office Restroom	25	SF	6	\$87	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Principal's Office Restroom	25	SF	6	\$53	
	Lavatory	1st Floor-Principal's Office Restroom	1	EA	6	\$320	
	Lighting - Lay-in	1st Floor-Principal's Office Restroom	1	EA	4	\$336	T-12 lightbulb, missing cover
	Walls - Plaster/Drywall	1st Floor-Principal's Office Restroom	280	SF	6	\$773	
	Water Closet	1st Floor-Principal's Office Restroom	1	EA	6	\$336	
	Accessories	1st Floor-W Boy's Restroom	250	SF	6	\$2,306	
	Ceiling - Plaster/Drywall	1st Floor-W Boy's Restroom	250	SF	6	\$865	
	Doors - Wood Doors inclu hw	1st Floor-W Boy's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-W Boy's Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-W Boy's Restroom	250	SF	6	\$529	
	Hand Dryer	1st Floor-W Boy's Restroom	2	EA	6	\$460	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Lavatory	1st Floor-W Boy's Restroom	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor-W Boy's Restroom	6	EA	6	\$743	
	Partitions	1st Floor-W Boy's Restroom	5	EA	6	\$1,485	
	Urinals	1st Floor-W Boy's Restroom	3	EA	6	\$1,008	
	Walls - Masonry	1st Floor-W Boy's Restroom	275	SF	6	\$865	
	Walls - Plaster/Drywall	1st Floor-W Boy's Restroom	500	SF	6	\$1,380	
	Walls - Structural Glazed Tile	1st Floor-W Boy's Restroom	68	SF	6	\$214	
	Water Closet	1st Floor-W Boy's Restroom	2	EA	6	\$672	
	Accessories	1st Floor-W Girl's Restroom	275	SF	6	\$2,536	
	Ceiling - Plaster/Drywall	1st Floor-W Girl's Restroom	275	SF	6	\$952	
	Doors - Wood Doors inclu hw	1st Floor-W Girl's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-W Girl's Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-W Girl's Restroom	275	SF	6	\$582	
	Hand Dryer	1st Floor-W Girl's Restroom	2	EA	6	\$460	
	Lavatory	1st Floor-W Girl's Restroom	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st Floor-W Girl's Restroom	6	EA	6	\$743	
	Partitions	1st Floor-W Girl's Restroom	5	EA	6	\$1,485	
	Walls - Masonry	1st Floor-W Girl's Restroom	520	SF	6	\$1,636	
	Walls - Plaster/Drywall	1st Floor-W Girl's Restroom	520	SF	6	\$1,435	
	Walls - Structural Glazed Tile	1st Floor-W Girl's Restroom	68	SF	6	\$214	
	Water Closet	1st Floor-W Girl's Restroom	5	EA	6	\$1,680	
	Accessories	2nd Floor Boys Northeast	225	SF	6	\$2,075	
	Ceiling - Plaster/Drywall	2nd Floor Boys Northeast	225	SF	6	\$779	
	Doors - Transom Window	2nd Floor Boys Northeast	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor Boys Northeast	2	EA	6	\$602	
	Floor Drain	2nd Floor Boys Northeast	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Northeast	225	SF	6	\$476	
	Hand Dryer	2nd Floor Boys Northeast	2	EA	6	\$460	
	Lavatory	2nd Floor Boys Northeast	2	EA	6	\$639	One lavatory pulling away from wall
	Lighting - Pendent/Surface	2nd Floor Boys Northeast	6	EA	7	\$0	
	Partitions	2nd Floor Boys Northeast	5	EA	6	\$1,485	
	Urinals	2nd Floor Boys Northeast	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	2nd Floor Boys Northeast	440	SF	6	\$1,214	
	Walls - Structural Glazed Tile	2nd Floor Boys Northeast	350	SF	6	\$1,101	
	Walls - Structural Glazed Tile	2nd Floor Boys Northeast	35	SF	5	\$2,234	Missing structural glazed tile at plumbing wall
	Water Closet	2nd Floor Boys Northeast	2	EA	6	\$672	
	Accessories	2nd Floor Boys Northwest	225	SF	6	\$2,075	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om de la companya de						
	Ceiling - Plaster/Drywall	2nd Floor Boys Northwest	225	SF	6	\$779	
	Doors - Transom Window	2nd Floor Boys Northwest	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor Boys Northwest	2	EA	6	\$602	
	Floor Drain	2nd Floor Boys Northwest	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Northwest	225	SF	6	\$476	
	Hand Dryer	2nd Floor Boys Northwest	2	EA	6	\$460	
	Lavatory	2nd Floor Boys Northwest	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor Boys Northwest	6	EA	7	\$0	
	Partitions	2nd Floor Boys Northwest	2	EA	6	\$594	
	Urinals	2nd Floor Boys Northwest	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	2nd Floor Boys Northwest	440	SF	6	\$1,214	
	Walls - Structural Glazed Tile	2nd Floor Boys Northwest	385	SF	6	\$1,211	
	Water Closet	2nd Floor Boys Northwest	2	EA	6	\$672	
	Accessories	2nd Floor Girls Southeast	305	SF	6	\$2,813	
	Ceiling - Plaster/Drywall	2nd Floor Girls Southeast	305	SF	6	\$1,055	
	Doors - Transom Window	2nd Floor Girls Southeast	10	SF	6	\$169	Wood panel
	Doors - Wood Doors inclu hw	2nd Floor Girls Southeast	1	EA	6	\$301	
	Floor Drain	2nd Floor Girls Southeast	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Southeast	305	SF	6	\$646	
	Hand Dryer	2nd Floor Girls Southeast	2	EA	6	\$460	
	Lavatory	2nd Floor Girls Southeast	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor Girls Southeast	6	EA	7	\$0	
	Partitions	2nd Floor Girls Southeast	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	2nd Floor Girls Southeast	500	SF	6	\$1,380	
	Walls - Structural Glazed Tile	2nd Floor Girls Southeast	405	SF	6	\$1,274	
	Water Closet	2nd Floor Girls Southeast	5	EA	6	\$1,680	
	Accessories	2nd Floor Girls Southwest	350	SF	6	\$3,228	
	Ceiling - Plaster/Drywall	2nd Floor Girls Southwest	350	SF	6	\$1,211	
	Doors - Wood Doors inclu hw	2nd Floor Girls Southwest	1	EA	6	\$301	
	Floor Drain	2nd Floor Girls Southwest	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Southwest	350	SF	6	\$741	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Southwest	50	SF	5	\$921	Damage floor tile
	Hand Dryer	2nd Floor Girls Southwest	2	EA	6	\$460	
	Lavatory	2nd Floor Girls Southwest	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor Girls Southwest	6	EA	6	\$743	
	Partitions	2nd Floor Girls Southwest	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	2nd Floor Girls Southwest	500	SF	6	\$1,637	



\$691,380

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Walls - Plaster/Drywall	2nd Floor Girls Southwest	500	SF	6	\$1,637	
	Water Closet	2nd Floor Girls Southwest	5	EA	6	\$1,680	
	Accessories	2nd Floor Unisex	88	SF	6	\$812	
	Ceiling - Lay-in	2nd Floor Unisex	88	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor Unisex	1	EA	6	\$301	
	Floor Drain	2nd Floor Unisex	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex	88	SF	6	\$186	
	Hand Dryer	2nd Floor Unisex	1	EA	6	\$230	
	Lavatory	2nd Floor Unisex	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor Unisex	2	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor Unisex	250	SF	6	\$690	
	Walls - Structural Glazed Tile	2nd Floor Unisex	50	SF	6	\$157	
	Water Closet	2nd Floor Unisex	1	EA	6	\$336	
	Accessories	Locate in engineer office	20	SF	6	\$184	
	Ceiling - Plaster/Drywall	Locate in engineer office	20	SF	6	\$69	
	Doors - Wood Doors inclu hw	Locate in engineer office	1	EA	6	\$301	
	Floor - Tile/Sheet	Locate in engineer office	20	SF	6	\$20	
	Lighting - Pendent/Surface	Locate in engineer office	1	EA	6	\$124	
	Walls - Plaster/Drywall	Locate in engineer office	228	SF	6	\$629	
	Water Closet	Locate in engineer office	1	EA	6	\$336	
	Accessories	Located in Boiler room	15	SF	6	\$138	
	Ceiling - Plaster/Drywall	Located in Boiler room	1	SF	6	\$3	
	Doors - Wood Doors inclu hw	Located in Boiler room	1	EA	6	\$301	
	Floor - Tile/Sheet	Located in Boiler room	15	SF	6	\$15	
	Lighting - Pendent/Surface	Located in Boiler room	1	EA	6	\$124	
	Walls - Plaster/Drywall	Located in Boiler room	200	SF	6	\$552	
	Water Closet	Located in Boiler room	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Corridor					
Ceiling - Lay-in	1st Floor	4,525	SF	6	\$13,589
Ceiling - Plaster/Drywall	1st Floor	275	SF	6	\$1,703
Doors - Wood Doors include hw	1st Floor	8	EA	6	\$2,408



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Drinking Fountains - Double Fountain	1st Floor	2	EA	6	\$672	
	Floor - Terrazzo	1st Floor	1,190	SF	6	\$9,989	
	Floor - Tile/Sheet	1st Floor	4,720	SF	6	\$2,565	
	Lighting - Lay-in	1st Floor	48	EA	6	\$5,711	
	Lighting - Pendent/Surface	1st Floor	6	EA	6	\$743	
	Lighting - Wall Mounted	1st Floor	4	EA	6	\$496	
	Stairs - Terrazzo	1st Floor	4	LF	6	\$37	
	Stairs - Terrazzo	1st Floor	4	LF	6	\$37	
	Student Lockers - One Tier	1st Floor	205	EA	6	\$19,031	
	Walls - Masonry	1st Floor	670	SF	6	\$2,108	
	Walls - Plaster/Drywall	1st Floor	8,340	SF	6	\$36,971	
	Ceiling - Lay-in	2nd Floor	4,662	SF	6	\$14,000	
	Ceiling - Lay-in	2nd Floor	8	SF	5	\$71	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	6	\$672	
	Floor - Terrazzo	2nd Floor	715	SF	6	\$6,002	
	Floor - Tile/Sheet	2nd Floor	3,955	SF	6	\$2,149	
	Lighting - Lay-in	2nd Floor	44	EA	6	\$5,235	
	Student Lockers - One Tier	2nd Floor	275	EA	6	\$25,530	
	Walls - Plaster/Drywall	2nd Floor	6,505	SF	6	\$28,837	
Safety							
Salety	Camera Viewing Station	Entire Building	1	EA	6	\$683	
	Metal Dedector	Entire Building	1	EA	6 6	\$683 \$881	
	Security Cameras	Entire Building	4	EA	6	\$001 \$776	
	Security Gameras		4	LA	0	9110	
Stairs							
	Ceiling - Lay-in	#1 SE Stair	240	SF	6	\$721	
	Floor - Terrazzo	#1 SE Stair	8	SF	5	\$419	
	Floor - Terrazzo	#1 SE Stair	100	SF	6	\$839	
	Handrails	#1 SE Stair	72	LF	6	\$624	
	Lighting - Lay-in	#1 SE Stair	4	EA	6	\$476	
	Stairs - Terrazzo	#1 SE Stair	22	LF	6	\$204	
	Walls - Plaster/Drywall	#1 SE Stair	1,940	SF	6	\$5,354	
	Ceiling - Lay-in	#2 SW Stair	240	SF	6	\$721	
	Floor - Terrazzo	#2 SW Stair	108	SF	6	\$907	
	Handrails	#2 SW Stair	72	LF	6	\$624	
	Lighting - Lay-in	#2 SW Stair	4	EA	6	\$476	
	Stairs - Terrazzo	#2 SW Stair	22	LF	6	\$204	



Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs			,				
	Walls - Plaster/Drywall	#2 SW Stair	1,940	SF	6	\$5,354	
	Ceiling - Lay-in	#3 NW Stair	250	SF	6	\$751	
	Floor - Terrazzo	#3 NW Stair	108	SF	6	\$907	
	Handrails	#3 NW Stair	72	LF	6	\$624	
	Lighting - Lay-in	#3 NW Stair	2	EA	6	\$238	
	Stairs - Terrazzo	#3 NW Stair	22	LF	6	\$204	
	Walls - Plaster/Drywall	#3 NW Stair	1,950	SF	6	\$5,382	
	Ceiling - Lay-in	#4 NE Stair	250	SF	6	\$751	
	Floor - Terrazzo	#4 NE Stair	108	SF	6	\$907	
	Handrails	#4 NE Stair	72	LF	6	\$624	
	Lighting - Lay-in	#4 NE Stair	2	EA	6	\$238	
	Stairs - Terrazzo	#4 NE Stair	22	LF	6	\$204	
	Walls - Plaster/Drywall	#4 NE Stair	1,950	SF	6	\$5,382	
	Ceiling - Plaster/Drywall	Gym Stairs	40	SF	6	\$293	
	Floor - Terrazzo	Gym Stairs	25	SF	6	\$210	
	Handrails	Gym Stairs	40	LF	6	\$347	
	Lighting - Pendent/Surface	Gym Stairs	1	EA	6	\$124	
	Stairs - Terrazzo	Gym Stairs	20	LF	6	\$186	
	Walls - Plaster/Drywall	Gym Stairs	1,315	SF	6	\$3,629	
Vertical	I Conveyance						
	Elevator - Hydraulic Elevator		1	EA	6	\$19,238	
	Wheelchair Lift - Platform Lift		1	EA	6	\$6,690	
Buildi	ing Interior Subtotal:					\$244,743	
Total	Building Cost					2,571,956	
TOtai	Building Cost				4	2,371,330	
Buildi	ing: 2-Classroom Modular						
Cateo	ory: Building Exterior						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand		Location	Quantity	Onit	Nank	0031	oonimenta .
Lindan	Exterior Doors - Exterior Steel Door	Entrance 10 - South	1	EA	4	\$3,823	Bottom of door and frame rusting with holes / scraping on metal landing
	Exterior Doors - Exterior Steel Door	Entrance 10 - South	1	EA	4	\$3,823	Bottom of door and frame rusting with holes / scraping on metal landing
	Exterior Doors - Exterior Steel Door	Entrance 10 - South	1	EA	4	\$3,823	Bottom of door and frame rusting with holes / scraping on metal landing



Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance						
Exterior Doors - Exterior Steel Door	Entrance 10 - South	1	EA	4	\$3,823	Bottom of door and frame rusting with holes / scraping on metal landing
Exterior Doors - Exterior Steel Door	Entrance 10A - NW	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10A - NW	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10A - NW	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10A - NW	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10B - NE	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10B - NE	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10B - NE	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 10B - NE	1	EA	4	\$3,823	Bottom of door and frame rusted with holes / scraping metal landing
Exterior Doors - Exterior Steel Door	Entrance 11 - North	1	EA	5	\$1,341	Bottom of door and frame rusting
Exterior Doors - Exterior Steel Door	Entrance 11 - North	1	EA	5	\$1,341	Bottom of door and frame rusting
Exterior Doors - Exterior Steel Door	Entrance 11 - North	1	EA	5	\$1,341	Bottom of door and frame rusting
Exterior Doors - Exterior Steel Door	Entrance 11 - North	1	EA	5	\$1,341	Bottom of door and frame rusting
Exterior Doors - Exterior Steel Door	Entrance 11A - SW	1	EA	5	\$1,341	Hole on inside of threshold
Exterior Doors - Exterior Steel Door	Entrance 11A - SW	1	EA	5	\$1,341	Hole on inside of threshold
Exterior Doors - Exterior Steel Door	Entrance 11A - SW	1	EA	5	\$1,341	Hole on inside of threshold
Exterior Doors - Exterior Steel Door	Entrance 11A - SW	1	EA	5	\$1,341	Hole on inside of threshold
Exterior Doors - Exterior Steel Door	Entrance 11B - SE	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 11B - SE	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 11B - SE	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 11B - SE	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12 - South	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12 - South	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12 - South	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12 - South	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12A - NW	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12A - NW	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12A - NW	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12A - NW	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12B - NE	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 12B - NE	1	EA	6	\$481	



Category: Building Exterior

Group Iter	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance							
Ex	terior Doors - Exterior Steel Door	Entrance 12B - NE	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 12B - NE	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9 - North	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9 - North	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9 - North	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9 - North	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9A - SW	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9A - SW	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9A - SW	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9A - SW	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9B - SE	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9B - SE	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9B - SE	1	EA	6	\$481	
Ex	terior Doors - Exterior Steel Door	Entrance 9B - SE	1	EA	6	\$481	
Ex	terior Stairs - Steel or Aluminum	Entrance 10A - NW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10A - NW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10A - NW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10A - NW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10B - NE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10B - NE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10B - NE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 10B - NE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9 - North	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9 - North	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9 - North	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9 - North	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9A - SW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9A - SW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9A - SW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9A - SW	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9B - SE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9B - SE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9B - SE	25	LF	6	\$96	
Ex	terior Stairs - Steel or Aluminum	Entrance 9B - SE	25	LF	6	\$96	
Ex	terior Stairs - Wood	Entrance 11 - North	25	LF	6	\$96	
Ex	terior Stairs - Wood	Entrance 11 - North	25	LF	6	\$96	
Ex	terior Stairs - Wood	Entrance 11 - North	25	LF	6	\$96	



Category: Building Exterior

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
trand				•			
	Exterior Stairs - Wood	Entrance 11 - North	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 11A - SW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 11A - SW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 11A - SW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 11A - SW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 11B - SE	5	LF	6	\$19	
	Exterior Stairs - Wood	Entrance 11B - SE	5	LF	6	\$19	
	Exterior Stairs - Wood	Entrance 11B - SE	5	LF	6	\$19	
	Exterior Stairs - Wood	Entrance 11B - SE	5	LF	6	\$19	
	Exterior Stairs - Wood	Entrance 12A - NW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12A - NW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12A - NW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12A - NW	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12B - NE	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12B - NE	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12B - NE	25	LF	6	\$96	
	Exterior Stairs - Wood	Entrance 12B - NE	25	LF	6	\$96	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 11 - North	80	LF	6	\$693	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 11 - North	80	LF	6	\$693	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 11 - North	80	LF	6	\$693	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 11 - North	80	LF	6	\$693	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 9 - North	110	LF	6	\$953	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 9 - North	110	LF	6	\$953	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 9 - North	110	LF	6	\$953	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 9 - North	110	LF	6	\$953	
	Ramps - Steel or Aluminum	Entrance 9 - North	50	LF	6	\$7,512	
	Ramps - Steel or Aluminum	Entrance 9 - North	50	LF	6	\$7,512	
	Ramps - Steel or Aluminum	Entrance 9 - North	50	LF	6	\$7,512	
	Ramps - Steel or Aluminum	Entrance 9 - North	50	LF	6	\$7,512	
	Ramps - Wood Ramp	Entrance 11 - North	35	LF	6	\$5,258	
	Ramps - Wood Ramp	Entrance 11 - North	35	LF	6	\$5,258	
	Ramps - Wood Ramp	Entrance 11 - North	35	LF	6	\$5,258	
	Ramps - Wood Ramp	Entrance 11 - North	35	LF	6	\$5,258	
	Stair Handrail - Steel_Stair Handrail	Entrance 10A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 10A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 10A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 10A - NW	25	LF	6	\$217	



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran			y	.			
	Stair Handrail - Steel_Stair Handrail	Entrance 10B - NE	25	LF	6	\$217	
	Stair Handrail - Steel Stair Handrail	Entrance 10B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 10B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 10B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11 - North	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	Entrance 11 - North	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	Entrance 11 - North	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	Entrance 11 - North	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	Entrance 11A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 11B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12A - NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 12B - NE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9 - North	15	LF	6	\$130	
	Stair Handrail - Steel_Stair Handrail	Entrance 9 - North	15	LF	6	\$130	
	Stair Handrail - Steel_Stair Handrail	Entrance 9 - North	15	LF	6	\$130	
	Stair Handrail - Steel_Stair Handrail	Entrance 9 - North	15	LF	6	\$130	
	Stair Handrail - Steel_Stair Handrail	Entrance 9A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9A - SW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9B - SE	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	Entrance 9B - SE	25	LF	6	\$217	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Founda	tion						
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Foundation - Concrete	Entire Building	190	LF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
	Superstructure - Steel	Entire Building	1,750	SF	7	\$0	
Lighting	3						
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444	



Category: Building Exterior

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Lighting		Location	Quantity	Unit	Nullk	0031		
Lighting	Exterior Lighting - Wall Mounted Entire Building 5 EA 6 \$1,444							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444 \$1,444		
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444 \$1,444		
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444		
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	\$577	Not working at south / north elevations	
		Entire Building	5	EA	6	\$1,444	Not working at south / north elevations	
	Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444 \$1,444		
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	\$1,444 \$1,444		
		Entire Building	3	EA	7	\$1,444		
	Exterior Lighting - Wall Mounted		3	EA	7	\$0 \$0		
	Exterior Lighting - Wall Mounted	Entire Building Entire Building	3	EA	7	\$0 \$0		
	Exterior Lighting - Wall Mounted	Ũ	3	EA		\$0 \$0		
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7		Not working at a with (north alovations	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6		Not working at south / north elevations	
	Exterior Lighting - Wall Mounted	Entire Building			6	\$1,444	Not working at a with (north alovations	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA EA	6	\$577 ¢577	Not working at south / north elevations	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	\$577	Not working at south / north elevations	
Roof S	ystem							
	Coping - Metal	Roof 12	190	LF	6	\$6,102		
	Coping - Metal	Roof 12	190	LF	6	\$6,102		
	Coping - Metal	Roof 12	190	LF	6	\$6,102		
	Coping - Metal	Roof 12	190	LF	6	\$6,102		
	Coping - Metal	Roof 13	190	LF	6	\$6,102		
	Coping - Metal	Roof 13	190	LF	6	\$6,102		
	Coping - Metal	Roof 13	190	LF	6	\$6,102		
	Coping - Metal	Roof 13	190	LF	6	\$6,102		
	Coping - Metal	Roof 14	190	LF	6	\$6,102		
	Coping - Metal	Roof 14	190	LF	6	\$6,102		
	Coping - Metal	Roof 14	190	LF	6	\$6,102		
	Coping - Metal	Roof 14	190	LF	6	\$6,102		
	Coping - Metal	Roof 15	140	LF	6	\$4,496		
	Coping - Metal	Roof 15	140	LF	6	\$4,496		
	Coping - Metal	Roof 15	140	LF	6	\$4,496		
	Coping - Metal	Roof 15	140	LF	6	\$4,496		
	Downspouts - Exterior Downspouts	Roof 12	160	LF	6	\$5,317		
	Downspouts - Exterior Downspouts	Roof 12	160	LF	6	\$5,317		
	Downspouts - Exterior Downspouts	Roof 12	160	LF	6	\$5,317		
	Downspouts - Exterior Downspouts	Roof 12	160	LF	6	\$5,317		
						• •		



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	vstem						
	Downspouts - Exterior Downspouts	Roof 13	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 13	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 13	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 13	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 14	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 14	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 14	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 14	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 15	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 15	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 15	160	LF	6	\$5,317	
	Downspouts - Exterior Downspouts	Roof 15	160	LF	6	\$5,317	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 12	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 12	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 12	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 12	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 13	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 13	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 13	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 13	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 14	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 14	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 14	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 14	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 15	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 15	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 15	1,750	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 15	1,750	SF	7	\$0	
	Roof - Metal	Roof 12	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 12	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 12	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 12	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 13	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 13	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 13	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 13	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 14	1,750	SF	6	\$23,448	



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	vstem						
	Roof - Metal	Roof 14	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 14	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 14	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 15	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 15	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 15	1,750	SF	6	\$23,448	
	Roof - Metal	Roof 15	1,750	SF	6	\$23,448	
Walls							
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	6	\$322	
	Canopy - Metal	Entire Building	15	SF	7	\$0	
	Canopy - Metal	Entire Building	15	SF	7	\$0	
	Canopy - Metal	Entire Building	15	SF	7	\$0	
	Canopy - Metal	Entire Building	15	SF	7	\$0	
	Canopy - Metal	Entrance Ramp	15	SF	6	\$322	
	Canopy - Metal	Entrance Ramp	15	SF	6	\$322	
	Canopy - Metal	Entrance Ramp	15	SF	6	\$322	
	Canopy - Metal	Entrance Ramp	15	SF	6	\$322	
	Exterior Walls - Wood Siding	Entire Building	10	SF	5	\$73	Area at east elevation cracked, rotting with holes
	Exterior Walls - Wood Siding	Entire Building	10	SF	5	\$73	Area at east elevation cracked, rotting with holes
	Exterior Walls - Wood Siding	Entire Building	1,657	SF	6	\$5,308	Evidence of vandalism at east elevation
	Exterior Walls - Wood Siding	Entire Building	1,657	SF	6	\$5,308	Evidence of vandalism at east elevation
	Exterior Walls - Wood Siding	Entire Building	10	SF	5	\$73	Area at east elevation cracked, rotting with holes
	Exterior Walls - Wood Siding	Entire Building	10	SF	5	\$73	Area at east elevation cracked, rotting with holes
	Exterior Walls - Wood Siding	Entire Building	1,657	SF	6	\$5,308	Evidence of vandalism at east elevation
	Exterior Walls - Wood Siding	Entire Building	1,657	SF	6	\$5,308	Evidence of vandalism at east elevation
	Exterior Walls - Wood Siding	Entire Building	1,362	SF	6	\$4,363	
	Exterior Walls - Wood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - Wood Siding	Entire Building	1,362	SF	6	\$4,363	
	Exterior Walls - Wood Siding	Entire Building	1,362	SF	6	\$4,363	
	Exterior Walls - Wood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter



Building: 2-Classroom Modular

Group	Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
Walls								
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	1,357	SF	6	\$4,347	
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	1,357	SF	6	\$4,347	
	Exterior Walls - W	Vood Siding	Entire Building	1,362	SF	6	\$4,363	
	Exterior Walls - W	Vood Siding	Entire Building	1,357	SF	6	\$4,347	
	Exterior Walls - W	Vood Siding	Entire Building	285	SF	6	\$913	At lower 1'-6" around perimeter
	Exterior Walls - W	Vood Siding	Entire Building	1,357	SF	6	\$4,347	
	Exterior Walls - W	Vood Siding	Entire Building / South West	15	SF	5	\$109	At SE and NW corners - Corner wood trim and siding cracked, missing, rotting wood, with holes
	Exterior Walls - W	Vood Siding	Entire Building / South West	15	SF	5	\$109	At SE and NW corners - Corner wood trim and siding cracked, missing, rotting wood, with holes
	Exterior Walls - W	Vood Siding	Entire Building / South West	15	SF	5	\$109	At SE and NW corners - Corner wood trim and siding cracked, missing, rotting wood, with holes
	Exterior Walls - W	Vood Siding	Entire Building / South West	15	SF	5	\$109	At SE and NW corners - Corner wood trim and siding cracked, missing, rotting wood, with holes
	Exterior Walls - W	Vood Siding	Entrance Ramp	1,655	SF	6	\$5,301	
	Exterior Walls - W	Vood Siding	Entrance Ramp	1,655	SF	6	\$5,301	
	Exterior Walls - W	Vood Siding	Entrance Ramp	1,655	SF	6	\$5,301	
	Exterior Walls - W	Vood Siding	Entrance Ramp	1,655	SF	6	\$5,301	
Windov	vs							
	Guard - Guards w	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards w	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards w	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards w	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wi	ire quard	Entire Building	180	SF	6	\$2,299	



Category: Building Exterior

5825 S Kostner Ave Chicago, IL 60629

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lindows	6						
	Guard - Guards wire guard	Entire Building	180	SF	6	\$2,299	
	Guard - Guards wire guard	Entire Building	180	SF	6	\$2,299	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Louver	Entire Building	6	SF	6	\$45	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	Windows - Sash Aluminum Double-pane	Entire Building	180	SF	6	\$1,344	
	a Exterior Subtotal	-				\$858 673	

Building Exterior Subtotal:

\$858,673



Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Emergency System									
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	\$810			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	\$810			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	\$810			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	\$810			
	Emergency Battery Packs - Students Toilets	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Students Toilets	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Students Toilets	Entire Building / 1st Floor	2	EA	6	\$405			
	Emergency Battery Packs - Students Toilets	Entire Building / 1st Floor	2	EA	6	\$405			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	1	EA	7	\$0			
	Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building		



Category: Electrical System

5825 S Kostner Ave Chicago, IL 60629

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Emergency System										
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - CCTV	Entire Building	1,750	SF	3	\$6,256	No CCTV service in building				
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	4	\$4,930	motion sensors are not activated				
Security System - Intrusion Detection	Entire Building	1,750	SF	6	\$450					
Power Distribution										
Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994					
Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994					
Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994					
Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994					
Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994					
DACTEUD						According to Date: C/45				



\$168,768

Building: 2-Classroom Modular

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Power I	ower Distribution									
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994				
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994				

Electrical System Subtotal:

Building: 2-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Comments				
Fire Ala	ire Alarm									
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
	Fire Alarm_System	Entire Building	1,750	SF	6	\$851				
Sprinkle	er System									
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				



Building: 2-Classroom Modular

Category: Safty System

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Sprink	Sprinkler System									
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Heads	Entire Building	1,750	SF	7	\$0				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Sprinkler Piping	Entire Building	1,750	SF	6	\$325				
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
	Wet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			



\$26,026

Building: 2-Classroom Modular

Category: Safty System

Group I	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Sprinkler	Sprinkler System									
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
١	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			
\	Vet Sprinkler System	Entire Building	1,750	SF	6	\$450	City pressure			

Safty System Subtotal:

Building: 2-Classroom Modular

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
emperature Control									
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	1	EA	6	\$0				
Electric Thermostat	Entire Building	2	EA	7	\$0				



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Temper	ature Control						
	Electric Thermostat	Entire Building	2	EA	7	\$0	
	Electric Thermostat	Entire Building	1	EA	7	\$0	
	Electric Thermostat	Entire Building	1	EA	7	\$0	
	Electric Thermostat	Entire Building	1	EA	6	\$0	
Unit Ve	ntilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	2	EA	6	\$0	
Ventilat	ion						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592	
DASTE		Page 42 of 97	2	LA	0	\$J92	Assessment Date:



Building: 2-Classroom Modular

Category: Mechanical System

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
entilation									
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889				
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	2	EA	6	\$592				

Mechanical System Subtotal:

\$21,326

Building: 2-Classroom Modular

Category: Plumbing System



Category: Plumbing System

5825 S Kostner Ave Chicago, IL 60629

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	••		_,,				
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	\$2,443	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,750	SF	6	\$425	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	



Building: 2-Classroom Modular

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	1,750	SF	6	\$325	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Domestic Piping-Hot Water Return Lines	Entire Building	1,750	SF	6	\$250	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	



Building: 2-Classroom Modular

Category: Plumbing System

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Sanitary Piping	Entire Building	1,750	SF	6	\$1,602	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Storm Piping	Entire Building	1,750	SF	6	\$1,527	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	
	Vent Piping	Entire Building	1,750	SF	6	\$1,176	



Category: Plumbing System			
Group Item - Type	Location	Quantity Unit Rank Cost Comments	
Piping			
Vent Piping	Entire Building	1,750 SF 6 \$1,176	
Plumbing System Subtotal:		\$123,970	

Building: 2-Classroom Modular

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
assroom #M401 (Regular Classroom)									
Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
Floor - Tile/Sheet	1st Floor	765	SF	6	\$766				
Floor - Tile/Sheet	1st Floor	765	SF	6	\$766				
Floor - Tile/Sheet	1st Floor	765	SF	6	\$766				
Floor - Tile/Sheet	1st Floor	765	SF	6	\$766				
Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
Marker Board	1st Floor	14	LF	6	\$300				
Marker Board	1st Floor	14	LF	6	\$300				
Marker Board	1st Floor	14	LF	6	\$300				
Marker Board	1st Floor	14	LF	6	\$300				
Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
room #M402 (Regular Classroom)									
Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415				
Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415				
Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415				



Building: 2-Classroom Modular

p Item	- Туре	Location	Quantity	Unit	Rank	Cost	Comments
room #	M402 (Regular Classroom)						
Ceili	ng - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
Doo	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Doo	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Doo	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Doo	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Floo	r - Tile/Sheet	1st Floor	698	SF	6	\$699	
Floo	r - Tile/Sheet	1st Floor	698	SF	6	\$699	
Floo	r - Tile/Sheet	1st Floor	698	SF	6	\$699	
Floo	r - Tile/Sheet	1st Floor	698	SF	6	\$699	
Ligh	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
-	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
-	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
-	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
-	ker Board	1st Floor	14	LF	6	\$300	
Marl	ker Board	1st Floor	14	LF	6	\$300	
Marl	ker Board	1st Floor	14	LF	6	\$300	
Marl	ker Board	1st Floor	14	LF	6	\$300	
Wal	s - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	s - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	s - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	s - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	M403 (Special Program)		705	05	0	¢0.047	
	ng - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	ng - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	ng - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	ng - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	rs - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	r - Tile/Sheet	1st Floor	765	SF	6	\$766	
	r - Tile/Sheet	1st Floor	765	SF	6	\$766	
	r - Tile/Sheet	1st Floor	765	SF	6	\$766	
	r - Tile/Sheet	1st Floor	765	SF	6	\$766	
-	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
•	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	
Ligh	ting - Pendent/Surface	1st Floor	20	EA	7	\$0	



	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassroo	m #M403 (Special Program)						
l	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
I	Marker Board	1st Floor	14	LF	6	\$300	
I	Marker Board	1st Floor	14	LF	6	\$300	
I	Marker Board	1st Floor	14	LF	6	\$300	
l	Marker Board	1st Floor	14	LF	6	\$300	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
lassroo	m #M404 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
l	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
l	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
l	Marker Board	1st Floor	14	LF	6	\$300	
l	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	828	SF	6	\$2,285	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	828	SF	6	\$2,285	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	828	SF	6	\$2,285	
,	Walls - Vinyl Coated Gypsum Panel	1st Floor	828	SF	6	\$2,285	
lassroo	m #M501 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #M501 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
Classro	om #M502 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Floor - Tile/Sheet	1st Floor	50	SF	5	\$288	Some broken and crack tiles
	Floor - Tile/Sheet	1st Floor	50	SF	5	\$288	Some broken and crack tiles
				-	-	,	



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Classro	lassroom #M502 (Regular Classroom)									
	Floor - Tile/Sheet	1st Floor	50	SF	5	\$288	Some broken and crack tiles			
	Floor - Tile/Sheet	1st Floor	50	SF	5	\$288	Some broken and crack tiles			
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Marker Board	1st Floor	14	LF	6	\$300				
	Marker Board	1st Floor	14	LF	6	\$300				
	Marker Board	1st Floor	14	LF	6	\$300				
	Marker Board	1st Floor	14	LF	6	\$300				
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368				
Classro	oom #M503 (Regular Classroom)									
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
	Ceiling - Plaster/Drywall	1st Floor	765	SF	6	\$2,647				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602				
	Floor - Tile/Sheet	1st Floor	24	SF	6	\$49	Broken tile			
	Floor - Tile/Sheet	1st Floor	741	SF	6	\$742				
	Floor - Tile/Sheet	1st Floor	24	SF	6	\$49	Broken tile			
	Floor - Tile/Sheet	1st Floor	24	SF	6	\$49	Broken tile			
	Floor - Tile/Sheet	1st Floor	24	SF	6	\$49	Broken tile			
	Floor - Tile/Sheet	1st Floor	741	SF	6	\$742				
	Floor - Tile/Sheet	1st Floor	741	SF	6	\$742				
	Floor - Tile/Sheet	1st Floor	741	SF	6	\$742				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0				
	Marker Board	1st Floor	14	LF	6	\$300				



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #M503 (Regular Classroom)						
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	858	SF	6	\$2,368	
lassro	oom #M504 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Ceiling - Plaster/Drywall	1st Floor	698	SF	6	\$2,415	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Floor - Tile/Sheet	1st Floor	698	SF	6	\$699	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Marker Board	1st Floor	14	LF	6	\$300	
	Storage/ Closet	1st Floor	26	SF	6	\$189	
	Storage/ Closet	1st Floor	26	SF	6	\$189	
	Storage/ Closet	1st Floor	26	SF	6	\$189	
	Storage/ Closet	1st Floor	26	SF	6	\$189	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	794	SF	6	\$2,191	



. ... - -.

Building: 2-Classroom Modular						
Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classrooms Subtotal:					\$208,430	
Building: 2-Classroom Modular						
Category: Rooms (Other Than Classrooms)						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechanical/ Service Rooms						
Mechanical/ Service Rooms	In room M402	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M402	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M402	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M402	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M404	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M404	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M404	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M404	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M501	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M501	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M501	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M501	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M504	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M504	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M504	26	SF	6	\$186	
Mechanical/ Service Rooms	In room M504	26	SF	6	\$186	
Restroom						
Accessories	1st Floor-E Unisex Restroom	45	SF	6	\$415	
Accessories	1st Floor-E Unisex Restroom	45	SF	6	\$415	
Accessories	1st Floor-E Unisex Restroom	45	SF	6	\$415	
Accessories	1st Floor-E Unisex Restroom	45	SF	6	\$415	
Ceiling - Plaster/Drywall	1st Floor-E Unisex Restroom	45	SF	6	\$156	
Ceiling - Plaster/Drywall	1st Floor-E Unisex Restroom	45	SF	6	\$156	
Ceiling - Plaster/Drywall	1st Floor-E Unisex Restroom	45	SF	6	\$156	

Ceiling - Plaster/Drywall

Doors - Wood Doors inclu hw

Floor Drain

Floor Drain

1st Floor-E Unisex Restroom

SF

45

1 ΕA

1 ΕA

1 ΕA

1 ΕA

1 ΕA

1 ΕA 6

6

6

6

6

6

6

\$156

\$301

\$301

\$301

\$301

\$1,059

\$1,059



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Restroc	estroom									
	Floor Drain	1st Floor-E Unisex Restroom	1	EA	6	\$1,059				
	Floor Drain	1st Floor-E Unisex Restroom	1	EA	6	\$1,059				
	Floor - Tile	1st Floor-E Unisex Restroom	45	SF	6	\$98				
	Floor - Tile	1st Floor-E Unisex Restroom	45	SF	6	\$98				
	Floor - Tile	1st Floor-E Unisex Restroom	45	SF	6	\$98				
	Floor - Tile	1st Floor-E Unisex Restroom	45	SF	6	\$98				
	Lavatory	1st Floor-E Unisex Restroom	1	EA	6	\$320				
	Lavatory	1st Floor-E Unisex Restroom	1	EA	6	\$320				
	Lavatory	1st Floor-E Unisex Restroom	1	EA	6	\$320				
	Lavatory	1st Floor-E Unisex Restroom	1	EA	6	\$320				
	Lighting - Pendent/Surface	1st Floor-E Unisex Restroom	1	EA	6	\$124				
	Lighting - Pendent/Surface	1st Floor-E Unisex Restroom	1	EA	6	\$124				
	Lighting - Pendent/Surface	1st Floor-E Unisex Restroom	1	EA	6	\$124				
	Lighting - Pendent/Surface	1st Floor-E Unisex Restroom	1	EA	6	\$124				
	Walls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Restroom	215	SF	6	\$593				
	Walls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Restroom	215	SF	6	\$593				
	Walls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Restroom	215	SF	6	\$593				
	Walls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Restroom	215	SF	6	\$593				
	Water Closet	1st Floor-E Unisex Restroom	1	EA	6	\$336				
	Water Closet	1st Floor-E Unisex Restroom	1	EA	6	\$336				
	Water Closet	1st Floor-E Unisex Restroom	1	EA	6	\$336				
	Water Closet	1st Floor-E Unisex Restroom	1	EA	6	\$336				
	Accessories	1st Floor-E Unisex Staff Restroom	45	SF	6	\$415				
	Accessories	1st Floor-E Unisex Staff Restroom	45	SF	6	\$415				
	Accessories	1st Floor-E Unisex Staff Restroom	45	SF	6	\$415				
	Accessories	1st Floor-E Unisex Staff Restroom	45	SF	6	\$415				
	Ceiling - Plaster/Drywall	1st Floor-E Unisex Staff Restroom	45	SF	6	\$156				
	Ceiling - Plaster/Drywall	1st Floor-E Unisex Staff Restroom	45	SF	6	\$156				
	Ceiling - Plaster/Drywall	1st Floor-E Unisex Staff Restroom	45	SF	6	\$156				
	Ceiling - Plaster/Drywall	1st Floor-E Unisex Staff Restroom	45	SF	6	\$156				
	Doors - Wood Doors inclu hw	1st Floor-E Unisex Staff Restroom	1	EA	6	\$301				
	Doors - Wood Doors inclu hw	1st Floor-E Unisex Staff Restroom	1	EA	6	\$301				
	Doors - Wood Doors inclu hw	1st Floor-E Unisex Staff Restroom	1	EA	6	\$301				
	Doors - Wood Doors inclu hw	1st Floor-E Unisex Staff Restroom	1	EA	6	\$301				
	Floor Drain	1st Floor-E Unisex Staff Restroom	1	EA	6	\$1,059				
	Floor Drain	1st Floor-E Unisex Staff Restroom	1	EA	6	\$1,059				
	Floor Drain	1st Floor-E Unisex Staff Restroom	1	EA	6	\$1,059				



oup It	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom							
F	loor Drain	1st Floor-E Unisex Staff Restroom	1	EA	6	\$1,059	
F	loor - Tile	1st Floor-E Unisex Staff Restroom	45	SF	6	\$98	
F	loor - Tile	1st Floor-E Unisex Staff Restroom	45	SF	6	\$98	
F	loor - Tile	1st Floor-E Unisex Staff Restroom	45	SF	6	\$98	
F	loor - Tile	1st Floor-E Unisex Staff Restroom	45	SF	6	\$98	
L	avatory	1st Floor-E Unisex Staff Restroom	1	EA	6	\$320	
L	avatory	1st Floor-E Unisex Staff Restroom	1	EA	6	\$320	
L	avatory	1st Floor-E Unisex Staff Restroom	1	EA	6	\$320	
L	avatory	1st Floor-E Unisex Staff Restroom	1	EA	6	\$320	
Li	ighting - Pendent/Surface	1st Floor-E Unisex Staff Restroom	1	EA	6	\$124	
Li	ighting - Pendent/Surface	1st Floor-E Unisex Staff Restroom	1	EA	6	\$124	
Li	ighting - Pendent/Surface	1st Floor-E Unisex Staff Restroom	1	EA	6	\$124	
Li	ighting - Pendent/Surface	1st Floor-E Unisex Staff Restroom	1	EA	6	\$124	
Μ	Valls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Staff Restroom	215	SF	6	\$593	
Μ	Valls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Staff Restroom	215	SF	6	\$593	
Μ	Valls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Staff Restroom	215	SF	6	\$593	
Μ	Valls - Vinyl Coated Gypsum Panel	1st Floor-E Unisex Staff Restroom	215	SF	6	\$593	
Ν	Vater Closet	1st Floor-E Unisex Staff Restroom	1	EA	6	\$336	
Μ	Vater Closet	1st Floor-E Unisex Staff Restroom	1	EA	6	\$336	
Ν	Vater Closet	1st Floor-E Unisex Staff Restroom	1	EA	6	\$336	
Ν	Vater Closet	1st Floor-E Unisex Staff Restroom	1	EA	6	\$336	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
A	ccessories	1st Floor-Men's Restroom	50	SF	6	\$461	
С	eiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	eiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	eiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	ceiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	ceiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	ceiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
С	ceiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	
0	eiling - Plaster/Drywall	1st Floor-Men's Restroom	50	SF	6	\$173	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lestroc	om						
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Men's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Men's Restroom	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor-Men's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Men's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Men's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Men's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Men's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Men's Restroom	2	SF	5	\$105	cracks
	Floor - Terrazzo	1st Floor-Men's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Men's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Men's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Men's Restroom	2	SF	5	\$105	cracks
	Floor - Terrazzo	1st Floor-Men's Restroom	2	SF	5	\$105	cracks
	Floor - Terrazzo	1st Floor-Men's Restroom	2	SF	5	\$105	cracks
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Men's Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Men's Restroom	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Men's Restroom	240	SF	6	\$662	
	Water Closet	1st Floor-Men's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Men's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Men's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Men's Restroom	1	EA	6	\$336	
	Accessories	1st Floor-W Unisex Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Restroom	45	SF	6	\$415	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Restroom	45	SF	6	\$156	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Restroom	45	SF	6	\$156	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Restroom	45	SF	6	\$156	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Restroom	45	SF	6	\$156	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-W Unisex Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-W Unisex Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-W Unisex Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-W Unisex Restroom	1	EA	6	\$1,059	
	Floor - Tile	1st Floor-W Unisex Restroom	45	SF	6	\$98	
	Floor - Tile	1st Floor-W Unisex Restroom	45	SF	6	\$98	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Floor - Tile	1st Floor-W Unisex Restroom	45	SF	6	\$98	
	Floor - Tile	1st Floor-W Unisex Restroom	45	SF	6	\$98	
	Lavatory	1st Floor-W Unisex Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-W Unisex Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Restroom	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Restroom	215	SF	6	\$593	frame falling at panel joint
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Restroom	215	SF	6	\$593	frame falling at panel joint
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Restroom	215	SF	6	\$593	frame falling at panel joint
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Restroom	215	SF	6	\$593	frame falling at panel joint
	Water Closet	1st Floor-W Unisex Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Restroom	1	EA	6	\$336	
	Accessories	1st Floor-W Unisex Staff Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Staff Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Staff Restroom	45	SF	6	\$415	
	Accessories	1st Floor-W Unisex Staff Restroom	45	SF	6	\$415	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	43	SF	6	\$149	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	43	SF	6	\$149	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	43	SF	6	\$149	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	43	SF	6	\$149	
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	2	SF	5	\$25	water discoloration
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	2	SF	5	\$25	water discoloration
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	2	SF	5	\$25	water discoloration
	Ceiling - Plaster/Drywall	1st Floor-W Unisex Staff Restroom	2	SF	5	\$25	water discoloration
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Staff Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Staff Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Staff Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-W Unisex Staff Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-W Unisex Staff Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-W Unisex Staff Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-W Unisex Staff Restroom	1	EA	6	\$1,059	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	m						
	Floor Drain	1st Floor-W Unisex Staff Restroom	1	EA	6	\$1,059	
	Floor - Tile	1st Floor-W Unisex Staff Restroom	45	SF	6	\$98	
	Floor - Tile	1st Floor-W Unisex Staff Restroom	45	SF	6	\$98	
	Floor - Tile	1st Floor-W Unisex Staff Restroom	45	SF	6	\$98	
	Floor - Tile	1st Floor-W Unisex Staff Restroom	45	SF	6	\$98	
	Lavatory	1st Floor-W Unisex Staff Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Staff Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Staff Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-W Unisex Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-W Unisex Staff Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Staff Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Staff Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-W Unisex Staff Restroom	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Staff Restroom	215	SF	6	\$593	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Staff Restroom	215	SF	6	\$593	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Staff Restroom	215	SF	6	\$593	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-W Unisex Staff Restroom	215	SF	6	\$593	
	Water Closet	1st Floor-W Unisex Staff Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Staff Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Staff Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-W Unisex Staff Restroom	1	EA	6	\$336	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Accessories	1st Floor-Women's Restroom	50	SF	6	\$461	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom	50	SF	6	\$173	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Women's Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor Drain	1st Floor-Women's Restroom	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor-Women's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Women's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Women's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Women's Restroom	2	SF	5	\$105	cracked
	Floor - Terrazzo	1st Floor-Women's Restroom	50	SF	6	\$109	
	Floor - Terrazzo	1st Floor-Women's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Women's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Women's Restroom	48	SF	6	\$105	
	Floor - Terrazzo	1st Floor-Women's Restroom	2	SF	5	\$105	cracked
	Floor - Terrazzo	1st Floor-Women's Restroom	2	SF	5	\$105	cracked
	Floor - Terrazzo	1st Floor-Women's Restroom	2	SF	5	\$105	cracked
	Floor - Terrazzo	1st Floor-Women's Restroom	48	SF	6	\$105	
	Lavatory	1st Floor-Women's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Women's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Women's Restroom	1	EA	4	\$7,342	falling off wall
	Lavatory	1st Floor-Women's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Women's Restroom	1	EA	4	\$7,342	falling off wall
	Lavatory	1st Floor-Women's Restroom	1	EA	4	\$7,342	falling off wall
	Lavatory	1st Floor-Women's Restroom	1	EA	6	\$320	
	Lavatory	1st Floor-Women's Restroom	1	EA	4	\$7,342	falling off wall
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor-Women's Restroom	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Walls - Vinyl Coated Gypsum Panel	1st Floor-Women's Restroom	240	SF	6	\$662	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	
	Water Closet	1st Floor-Women's Restroom	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$141,765

Building: 2-Classroom Modular

Quantity Unit Rank Cost Comments 125 SF 6 \$774
125 SF 6 \$774
125 SF 6 \$774
125 SF 6 \$774
125 SF 6 \$774
125 SF 6 \$774
95 SF 6 \$588
95 SF 6 \$588
95 SF 6 \$588



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	\$588	
	Ceiling - Plaster/Drywall	1st Floor	125	SF	6	\$774	
	Ceiling - Plaster/Drywall	1st Floor	125	SF	6	\$774	
	Ceiling - Plaster/Drywall	1st Floor	125	SF	6	\$774	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	\$588	
	Ceiling - Plaster/Drywall	1st Floor	125	SF	6	\$774	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	\$588	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	\$588	
	Ceiling - Plaster/Drywall	1st Floor	95	SF	6	\$588	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Terrazzo	1st Floor	95	SF	6	\$797	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	



Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Floor - Tile/Sheet	1st Floor	125	SF	6	\$68	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	410	SF	6	\$1,132	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	390	SF	6	\$1,076	



Building: 2-Classroom Modular

Category: Building Interior		
Group Item - Type	Location	Quantity Unit Rank Cost Comments
Building Interior Subtotal:		\$42,842
Total Building Cost		\$1,591,799
Building: Annex		
Category: Building Exterior		
Group Item - Type	Location	Quantity Unit Rank Cost Comments

Group	item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Exterior Doors - Exterior Steel Door	Entrance 6 - North	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Entrance 7 - East	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Entrance 8 - South	1	EA	6	\$481	
	Exterior Stairs - Concrete	Entrance 7 - East	3	LF	6	\$245	
	Power Door Operator and Controls	Entrance 6 - North	1	EA	6	\$0	
	Power Door Operator and Controls	Entrance 8 - South	1	EA	6	\$0	
Founda	ation						
	Foundation - Concrete	Entire Building	540	LF	7	\$0	
	Superstructure - Steel	Entire Building	14,000	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building / North	1	EA	6	\$289	Damaged and missing cover
Roof S	ystem						
	Coping - Metal	Roof 16	556	LF	6	\$17,857	
	Downspouts - Exterior Downspouts	Roof 16	580	LF	6	\$19,275	
	Downspouts - Exterior Downspouts	Roof 16	20	LF	5	\$1,615	Sections at west elevation bent, missing supports
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 16	14,000	SF	7	\$0	
	Roof - Metal	Roof 16	15,095	SF	7	\$0	
Walls							
	Canopy - Metal	Entire Building	50	SF	6	\$1,074	Bird droppings all over entrance 6 with nests throughout with areas of peeling throughout
	Exterior Walls - Brick	Entire Building	1,456	SF	7	\$0	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	20	SF	6	\$153	Several areas around perimeter dented / NE corner damaged, bent, coming off
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,080	SF	7	\$0	
	Exterior Walls - Stone-Cast	Entire Building	75	SF	7	\$0	
	Exterior Walls - Stone-Cut	Entire Building	128	SF	7	\$0	



Building: Annex

Category: Building Exterior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lindows						
Guard - Guards perforated	Entire Building	1,544	SF	6	\$19,717	
Guard - Guards perforated	Entire Building	6	SF	5	\$0	Vandalism at east / west elevations
Lintels - Steel	Entire Building	415	LF	7	\$0	
Windows - Louver	Entire Building	160	SF	7	\$0	
Windows - Sash Aluminum Double-pane	Entire Building	1,544	SF	7	\$0	
Windows - Sash Aluminum Double-pane	Entire Building	6	SF	5	\$0	Vandalism at east / west elevations
uilding Exterior Subtotal:					\$61,667	

Building: Annex

Category: Electrical System

Group Ite	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency	v System						
Au	tomatic Transfer Switch	Electrical Room	1	EA	6	\$408	
Em	nergency A/C Power - Corridors and Stairs	Entire Building	1,834	SF	6	\$551	
Ex	it Signs - Corridors and Stairs	Entire Building	5	EA	2	\$2,727	Exit signs have no battery back up
Se	ecurity System - CCTV	Entire Building	14,000	SF	3	\$50,050	No CCTV service in building.
Se	ecurity System - Intrusion Detection	Entire Building	14,000	SF	6	\$3,604	
Main Servic	ce						
Inc	dependent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
Ma	ain Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	6	\$3,570	
PA	A System	Entire Building	14,000	SF	6	\$4,605	
Power Distr	ribution						
Lig	ghting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	Emergency Fuse Panel
Lig	ghting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	
Lig	ghting and Power Panels - Above 100 A	Electrical Room	4	EA	6	\$1,988	
Ma	ain Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	6	\$730	
Electrica	l System Subtotal:					\$71,752	

Building: Annex Category: Safty System Group Item - Type Location Quantity Unit Rank Cost Comments Fire Alarm Fire Alarm Panel Entire Building / Electrical Room 1 EA 6 \$6,406



Building: Annex

Category: Safty System

roup Item - Type	Location	Quantity	Unit	Rank	Cost C	Comments
re Alarm						
Fire Alarm Strobe Lights	Entire Building	14,000	SF	6	\$5,005	
Fire Alarm_System	Entire Building	14,000	SF	6	\$6,807	
prinkler System						
Sprinkler Heads	Entire Building	14,000	SF	7	\$0	
Sprinkler Piping	Entire Building	14,000	SF	6	\$2,603	
Wet Sprinkler System	Entire Building	14,000	SF	6	\$3,604	
afty System Subtotal:					\$24,424	

Building: Annex

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	Boiler Room	1	EA	5	\$20,373	serves corridor
	Air Intake	Boiler Room	1	EA	6	\$5,765	
	Auxiliaries - Less than 4000 cfm	Boiler Room	1	EA	6	\$0	
Boiler S	Systems						
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	\$4,093	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	\$1,996	
	Water Fill System	Boiler Room	1	EA	6	\$1,168	
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building / 1st Floor	6	EA	6	\$2,126	
	PTAC - Electric Heating and Self Contained Cooling	1st Floor	1	EA	6	\$241	
	Unit Heater - Hot Water	Entire Building	2	EA	6	\$558	
Mechar	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	\$2,222	
	Hydronic Supply and Return - Galvanized	Entire Building	300	LF	6	\$23,196	
Temper	ature Control						
	Electric Thermostat	Entire Building	9	EA	7	\$0	Thermostats are built into equipment



Building: Annex

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Unit Ve	ntilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	12	EA	6	\$14,973	Univents have built-in thermostats
Ventilat	ion						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	1	EA	6	\$592	
Mecha	anical System Subtotal:					\$79,306	

Building: Annex

Category: Plumbing System

iroup Item - Type	Location	Quantity	Unit	Rank	Cost C	Comments
lot Water						
Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	6	\$310	
liping						
Domestic Piping-Cold Water Horizontal Lines	Entire Building	14,000	SF	6	\$3,403	
Domestic Piping-Hot Water Horizontal Lines	Entire Building	14,000	SF	6	\$2,603	
Domestic Piping-Hot Water Return Lines	Entire Building	14,000	SF	6	\$2,002	
Sanitary Piping	Entire Building	14,000	SF	6	\$12,813	
Storm Piping	Entire Building	14,000	SF	6	\$12,212	
Vent Piping	Entire Building	14,000	SF	6	\$9,409	

Building: Annex

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #301 (Regular Classroom)						
	Casework	3rd Floor	25	LF	6	\$631	
	Ceiling - Lay-in	3rd Floor	870	SF	6	\$2,613	
	Chalk Board	3rd Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	870	SF	6	\$871	
	Lighting - Lay-in	3rd Floor	9	EA	7	\$0	
	Marker Board	3rd Floor	12	LF	6	\$257	
	Storage/ Closet	3rd Floor	48	SF	6	\$348	



Building: Annex

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #301 (Regular Classroom)						
	Walls - Concrete Block	3rd Floor	780	SF	6	\$2,287	
	Walls - Plaster/Drywall	3rd Floor	250	SF	6	\$690	
lassro	om #302 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	780	SF	6	\$2,287	
	Walls - Plaster/Drywall	1st Floor	250	SF	6	\$690	
assro	om #303 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	480	SF	6	\$1,407	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	\$1,518	
assro	om #304 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	480	SF	6	\$1,407	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	\$1,518	

Building: Annex

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #305 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	740	SF	6	\$2,169	
	Walls - Plaster/Drywall	1st Floor	290	SF	6	\$800	
assro	oom #306 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	480	SF	6	\$1,407	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	\$1,518	
assro	oom #307 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	870	SF	6	\$871	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	6	\$257	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	530	SF	6	\$1,554	
	Walls - Plaster/Drywall	1st Floor	500	SF	6	\$1,380	
assro	oom #308 (Regular Classroom)						
	Casework	1st Floor	25	LF	6	\$631	
	Ceiling - Lay-in	1st Floor	870	SF	6	\$2,613	
	Chalk Board	1st Floor	12	LF	4	\$1,102	

Building: Annex

Ilar Classroom) Doors inclu hw eet in t tete Block /Drywall Ilar Classroom) n Doors inclu hw eet in	1st Floor 1st Floor	1 870 9 12 48 530 500 500 25 870 12	EA SF EA LF SF SF SF	6 6 6 6 6	\$301 \$871 \$0 \$257 \$348 \$1,554 \$1,380 \$631	
eet in t tete Block /Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor	870 9 12 48 530 500 500 25 870 12	SF EA LF SF SF SF	6 7 6 6 6	\$871 \$0 \$257 \$348 \$1,554 \$1,380 \$631	
in t ete Block /Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor	9 12 48 530 500 25 870 12	EA LF SF SF SF	7 6 6 6 6	\$0 \$257 \$348 \$1,554 \$1,380 \$631	
t ete Block /Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	12 48 530 500 25 870 12	LF SF SF SF	6 6 6	\$257 \$348 \$1,554 \$1,380 \$631	
ete Block /Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	48 530 500 25 870 12	SF SF SF LF	6 6 6	\$348 \$1,554 \$1,380 \$631	
ete Block /Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	530 500 25 870 12	SF SF LF	6 6 6	\$1,554 \$1,380 \$631	
/Drywall I lar Classroom) n Doors inclu hw eet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	500 25 870 12	SF	6	\$1,380 \$631	
n Doors inclu hw	1st Floor 1st Floor 1st Floor 1st Floor	25 870 12	LF	6	\$631	
n Doors inclu hw æt	1st Floor 1st Floor 1st Floor	870 12				
Doors inclu hw eet	1st Floor 1st Floor 1st Floor	870 12				
Doors inclu hw eet	1st Floor 1st Floor	12	SF	-		
eet	1st Floor			6	\$2,613	
eet			LF	4	\$1,102	
	1ct Floor	1	EA	6	\$301	
in	ISt FIOU	870	SF	6	\$871	
	1st Floor	9	EA	7	\$0	
	1st Floor	12	LF	6	\$257	
t	1st Floor	48	SF	6	\$348	
ete Block	1st Floor	870	SF	6	\$2,550	
/Drywall	1st Floor	250	SF	6	\$690	
lar Classroom)						
	1st Floor	25	LF	6	\$631	
ı	1st Floor	870	SF	6	\$2,613	
	1st Floor	12	LF	4	\$1,102	
Doors inclu hw	1st Floor	1	EA	6	\$301	
eet	1st Floor	870	SF	6	\$871	
in	1st Floor	9	EA	7	\$0	
	1st Floor	12	LF	6	\$257	
t	1st Floor	48	SF	6	\$348	
te Block	1st Floor	780	SF	6	\$2,287	
/Drywall	1st Floor	250	SF	6	\$690	
otal:					\$91,008	
	ete Block r/Drywall ular Classroom) n Doors inclu hw eet -in et ete Block r/Drywall total:	tete Block1st Floorr/Drywall1st Floorular Classroom)1st Floorn1st Floorn1st FloorDoors inclu hw1st Flooreet1st Flooreet1st Floor-in1st Floorot1st Flooret1st Flooret1s	tet Block 1st Floor 870 r/Drywall 1st Floor 250 ular Classroom) 1st Floor 25 n 1st Floor 870 n 1st Floor 870 Doors inclu hw 1st Floor 12 Doors inclu hw 1st Floor 12 of tet Block 1st Floor 870 -in 1st Floor 870 -t 1st Floor 12 of tet Block 1st Floor 870 ete Block 1st Floor 870 r/Drywall 1st Floor 780 r/Drywall 1st Floor 780 stor 1st Floor 250	ete Block1st Floor870SFr/Drywall1st Floor250SFular Classroom)1st Floor25LFn1st Floor870SF1st Floor12LFDoors inclu hw1st Floor12LFeet1st Floor1EAeet1st Floor9EAin1st Floor12LFot st Floor1SFSFete Block1st Floor12LFot st Floor12SFete Block1st Floor780SFr/Drywall1st Floor780SF	tet Block 1st Floor 870 SF 6 r/Drywall 1st Floor 250 SF 6 ular Classroom) 1st Floor 25 LF 6 n 1st Floor 870 SF 6 n 1st Floor 870 SF 6 n 1st Floor 870 SF 6 no 1st Floor 870 SF 6 no 1st Floor 12 LF 4 Doors inclu hw 1st Floor 1 EA 6 eet 1st Floor 1 EA 7 in 1st Floor 9 EA 7 ist Floor 12 LF 6 ete Block 1st Floor 48 SF 6 ete Block 1st Floor 780 SF 6 r/Drywall 1st Floor 780 SF 6	tet Block 1st Floor 870 SF 6 \$2,550 r/Drywall 1st Floor 250 SF 6 \$690 ular Classroom) 1st Floor 25 LF 6 \$631 n 1st Floor 25 LF 6 \$631 n 1st Floor 870 SF 6 \$2,613 1st Floor 15 LF 4 \$1,102 Doors inclu hw 1st Floor 1 EA 6 \$301 eet 1st Floor 870 SF 6 \$871 rin 1st Floor 1 EA 6 \$301 eet 1st Floor 9 EA 7 \$0 st Floor 12 LF 6 \$257 et 1st Floor 12 LF 6 \$257 et 1st Floor 48 SF 6 \$248 ete Block 1st Floor 780 SF 6 \$248 ete Block 1st Floor 780 SF 6 \$248<



Building: Annex

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
Ceiling - Lay-in	1st Floor-300 Main Office	360	SF	6	\$1,081	
Doors - Steel Doors incl hw	1st Floor-300 Main Office	1	EA	6	\$301	
Floor - Tile	1st Floor-300 Main Office	360	SF	5	\$1,616	cracking throughout
Lighting - Lay-in	1st Floor-300 Main Office	4	EA	6	\$476	
Power Distribution	1st Floor-300 Main Office	8	EA	6	\$16,999	
Walls - Concrete Block	1st Floor-300 Main Office	240	SF	6	\$704	
Walls - Plaster/Drywall	1st Floor-300 Main Office	600	SF	6	\$1,656	
Ceiling - Lay-in	1st Floor-Administration Office	175	SF	6	\$526	
Doors - Steel Doors incl hw	1st Floor-Administration Office	1	EA	6	\$301	
Floor - Tile	1st Floor-Administration Office	175	SF	6	\$383	
Lighting - Lay-in	1st Floor-Administration Office	2	EA	6	\$238	
Power Distribution	1st Floor-Administration Office	6	EA	6	\$12,749	
Walls - Concrete Block	1st Floor-Administration Office	425	SF	6	\$1,246	
Walls - Plaster/Drywall	1st Floor-Administration Office	290	SF	6	\$800	
nanical/ Service Rooms						
Mechanical/ Service Rooms	1st Floor	250	SF	6	\$1,791	
Mechanical/ Service Rooms	1st Floor	350	SF	6	\$2,508	electrical
room						
Accessories	1st Floor-Boy's Restroom	470	SF	6	\$4,335	
Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	470	SF	6	\$1,626	
Floor Drain	1st Floor-Boy's Restroom	2	EA	6	\$2,118	
Floor - Concrete Epoxy/ Painted	1st Floor-Boy's Restroom	470	SF	6	\$249	
Hand Dryer	1st Floor-Boy's Restroom	2	EA	6	\$460	
Lavatory	1st Floor-Boy's Restroom	3	EA	6	\$959	
Lighting - Lay-in	1st Floor-Boy's Restroom	5	EA	6	\$595	
Partitions	1st Floor-Boy's Restroom	3	EA	6	\$891	
Urinals	1st Floor-Boy's Restroom	6	EA	6	\$2,016	
Walls - Concrete Block	1st Floor-Boy's Restroom	1,295	SF	6	\$3,796	
Water Closet	1st Floor-Boy's Restroom	3	EA	6	\$1,008	
Accessories	1st Floor-E Staff Unisex Restroom	45	SF	6	\$415	
Ceiling - Plaster/Drywall	1st Floor-E Staff Unisex Restroom	45	SF	6	\$156	
Doors - Steel Doors incl hw	1st Floor-E Staff Unisex Restroom	1	EA	6	\$301	
Floor Drain	1st Floor-E Staff Unisex Restroom	1	EA	6	\$1,059	
Floor - Tile	1st Floor-E Staff Unisex Restroom	45	SF	6	\$98	
		1	EA	6	\$230	
Hand Dryer	1st Floor-E Staff Unisex Restroom	1	LA	0	φ230	



Building: Annex

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Lighting - Lay-in	1st Floor-E Staff Unisex Restroom	1	EA	6	\$119	
	Walls - Concrete Block	1st Floor-E Staff Unisex Restroom	120	SF	6	\$352	
	Water Closet	1st Floor-E Staff Unisex Restroom	1	EA	6	\$336	
	Accessories	1st Floor-Girl's Restroom	410	SF	6	\$3,782	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	410	SF	6	\$1,419	
	Floor Drain	1st Floor-Girl's Restroom	2	EA	6	\$2,118	
	Floor - Concrete Epoxy/ Painted	1st Floor-Girl's Restroom	410	SF	6	\$217	
	Hand Dryer	1st Floor-Girl's Restroom	2	EA	6	\$460	
	Lavatory	1st Floor-Girl's Restroom	3	EA	6	\$959	
	Lighting - Lay-in	1st Floor-Girl's Restroom	5	EA	6	\$595	
	Partitions	1st Floor-Girl's Restroom	9	EA	6	\$2,672	
	Walls - Concrete Block	1st Floor-Girl's Restroom	1,275	SF	6	\$3,738	
	Water Closet	1st Floor-Girl's Restroom	9	EA	6	\$3,024	
	Accessories	1st Floor-W Staff Unisex Restroom	45	SF	6	\$415	
	Ceiling - Plaster/Drywall	1st Floor-W Staff Unisex Restroom	45	SF	6	\$156	
	Doors - Steel Doors incl hw	1st Floor-W Staff Unisex Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-W Staff Unisex Restroom	1	EA	6	\$1,059	
	Floor - Tile	1st Floor-W Staff Unisex Restroom	45	SF	6	\$98	
	Hand Dryer	1st Floor-W Staff Unisex Restroom	1	EA	6	\$230	
	Lavatory	1st Floor-W Staff Unisex Restroom	1	EA	6	\$320	
	Lighting - Lay-in	1st Floor-W Staff Unisex Restroom	1	EA	6	\$119	
	Walls - Concrete Block	1st Floor-W Staff Unisex Restroom	120	SF	6	\$352	
	Water Closet	1st Floor-W Staff Unisex Restroom	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$87,182

Building: Annex

Group Item - Type	Location	Quantity	Unit	Pank	Cost Comme
Sloup Remi-Type	Location	Quantity	Unit	Nalik	Cost Comme
Corridor					
Ceiling - Lay-in	1st Floor	2,605	SF	6	\$7,823
Ceiling - Plaster/Drywall	1st Floor	165	SF	6	\$1,022
Ceiling - Plaster/Drywall	1st Floor	5	SF	5	\$87
Doors - Store Front	1st Floor	4	EA	6	\$4,833
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336
Floor - Tile Ceramic/ Porcelain	1st Floor	165	SF	6	\$460
Floor - Tile/Sheet	1st Floor	2,610	SF	6	\$1,418



Building: Annex

Category: Building Interior

Group Ite	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor							
Lig	hting - Lay-in	1st Floor	20	EA	6	\$2,380	
Wa	alls - Concrete Block	1st Floor	4,370	SF	6	\$12,811	
Wa	alls - Concrete Block	1st Floor	12	SF	5	\$169	Location: S Vestibule
Wa	alls - Concrete Block	1st Floor	12	SF	5	\$169	Location: N Vestibule
Building	Interior Subtotal:					\$31,507	
	Iding Cost					\$489,598	

Building: Branch_North

Category: Building Exterior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntrance						
Entrance Control - Audio	Main Entrance 1 - South	1	EA	6	\$497	
Exterior Doors - Exterior Stainless Steel Door	Entrance 3 - West	1	EA	6	\$546	
Exterior Doors - Exterior Stainless Steel Door	Main Entrance 1 - South	1	EA	6	\$546	
Exterior Doors - Exterior Wood Door	Entrance 2 - North	1	EA	6	\$481	
Exterior Stairs - Concrete	Entrance 2 - North	3	LF	6	\$245	
Exterior Stairs - Concrete	Entrance 3 - West	6	LF	6	\$491	
Ramp Handrail - Steel_Ramp Handrail	Main Entrance 1 - South	30	LF	7	\$0	At sloped walkway
oundation						
Foundation - Concrete	Entire Building	255	LF	7	\$0	
Superstructure - Concrete	Entire Building	9,925	SF	7	\$0	
ighting						
Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	\$1,610	
Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	\$289	
oof System						
Coping - Metal	Roof 1	30	LF	6	\$964	At east side
Coping - Metal	Roof 2	16	LF	6	\$514	
Coping - Stone	Roof 1	260	LF	6	\$8,351	
Downspouts - Exterior Downspouts	Roof 2	8	LF	6	\$266	
Downspouts - Interior Downspouts	Roof 1	25	LF	6	\$831	
Parapet - Parapet < 16" Height	Roof 1	260	LF	6	\$5,540	
Roof Structure - Concrete	Roof 1	4,965	SF	7	\$0	
Roof Structure - Concrete	Roof 2	56	SF	7	\$0	



Building: Branch_North

Category: Building Exterior

	Location	Quantity	Unit	Rank	Cost	Comments				
of System										
	Roof 1	4,965	SF	6	\$46,718					
	Roof 2	56	SF	6	\$463	Cracking throughout				
	Entire Building	4,935	SF	6	\$33,168					
	Entire Building	85	SF	6	\$571					
	Entire Building	240	LF	7	\$0					
	Entire Building	4	SF	7	\$0	At Entrance 3 - west vestibule				
	Entire Building	32	SF	6	\$239					
puble-pane	Entire Building	1,550	SF	6	\$11,570					
	puble-pane	Roof 1 Roof 2 Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	Roof 1 4,965 Roof 2 56 Entire Building 4,935 Entire Building 85 Entire Building 240 Entire Building 4 Entire Building 32	Roof 14,965SFRoof 256SFEntire Building4,935SFEntire Building85SFEntire Building240LFEntire Building4SFEntire Building4SFEntire Building32SF	Roof 14,965SF6Roof 256SF6Entire Building4,935SF6Entire Building85SF6Entire Building240LF7Entire Building4SF7Entire Building32SF6	Roof 14,965SF6\$46,718Roof 256SF6\$463Entire Building4,935SF6\$33,168Entire Building85SF6\$571Entire Building240LF7\$0Entire Building4SF7\$0Entire Building32SF6\$239				

Building Exterior Subtotal:

\$113,897

Building: Branch_North

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	\$408	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	15	EA	6	\$3,038	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	\$810	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	6	\$1,198	
Main Se	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
	Main Electrical Service- Live Front - 1200 A 120/208/3PH	Electrical Room	1	EA	6	\$0	serves North and South Branch Buildings, Panel has more than 40 years of service
	PA System	Entire Building	9,925	SF	5	\$6,813	serves North and South Branches
Power [Distribution						
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	Emergency fuse panel, panel has more than 40 years of service
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	panel has more than 40 years of service
	Lighting and Power Panels - Above 100 A	Electrical Room / Entire Building	2	EA	6	\$994	
	Lighting and Power Panels - Above 100 A	Electrical Room / Entire Building	2	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EA	6	\$1,055	panel has more than 40 years of service



J						
Category: Electrical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Electrical System Subtotal:					\$17,835	
Building: Branch_North						
Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm	Loodion	quantity	onne	T Carine	0031	Comments
Fire Alarm Panel	Entire Building / 1st Floor	1	EA	3	\$49,477	Panel has 20 years of service
Fire Alarm Strobe Lights	Entire Building	9,925	SF	6	\$3,548	
Fire Alarm_System	Entire Building	9,925	SF	6	\$4,826	
	<u> </u>					
Safty System Subtotal:					\$57,850	
Building: Branch_North						
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning		-				
Chiller-Air Cooled- Recipricating-Ground Mounted - 50 - 100 tons	Entire Building / Site South	1	EA	6	\$3,659	serves North and South Branches
Pressure Fill System	Entire Building / Basement	1	EA	6	\$1,405	
Air Handling Systems						
Fan Coil Unit- Floor Mounted - Dual Temperature Coil	Entire Building / 1st Floor	2	EA	6	\$3,586	
Fan Coil Unit- Floor Mounted - Dual Temperature Coil	Entire Building / 1st Floor	1	EA	4	\$16,927	office heater chassis is heavily rusted from condensed water formation on the coil
Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	5	\$22,527	
Boiler Systems						
Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Boiler Room	3	EA	6	\$6,139	
Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	2	\$86,073	boiler has fire damage and needs to be replacement
Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	\$1,996	·
Piping - Chilled Water Pipes- Copper	Boiler Room / Entire Building	200	LF	7	\$0	
	Deilar Deem / Entire Duilding	500	LF	6	\$944	
Piping - Dual Temperature Pipes- Steel	Boiler Room / Entire Building					
	Boiler Room / Entire Building	1	EA	7	\$0	
Piping - Dual Temperature Pipes- Steel	-		EA	7	\$0	
Piping - Dual Temperature Pipes- Steel Water Fill System	-		EA	7	\$0 \$2,574	Damaged and leaking



Building: Branch_North

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechan	ical Plumbing						
	Daul Temperature Pump - 10 - 20 HP	Basement	2	EA	6	\$2,485	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	\$30,711	
Temper	ature Control						
	DDC System	Entire Building	9,925	SF	6	\$5,677	Outsourced IT management
	Electric Thermostat	Entire Building	1	EA	6	\$0	controls Bell room univent
	Thermostats - DDC	Entire Building	1	EA	4	\$819	damaged thermostat
	Thermostats - DDC	Entire Building	9	EA	6	\$0	
Unit Ve	ntilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building / 1st Floor	1	EA	6	\$1,242	Bell room univent
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	8	EA	6	\$9,939	classroom univents
Ventilat	ion						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	5	EA	6	\$2,962	
Mecha	anical System Subtotal:					\$200,116	

Building: Branch_North

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Wa	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	9,925	SF	6	\$1,987	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	9,925	SF	6	\$2,413	
	Domestic Piping-Cold Water Risers	Entire Building	9,925	SF	6	\$1,845	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	9,925	SF	6	\$1,561	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	9,925	SF	6	\$1,845	
	Domestic Piping-Hot Water Return Lines	Entire Building	9,925	SF	6	\$1,419	
	Domestic Piping-Hot Water Return Risers	Entire Building	9,925	SF	6	\$1,419	
	Sanitary Piping	Entire Building	9,925	SF	6	\$9,083	
	Storm Piping	Entire Building	9,925	SF	6	\$8,658	
	Vent Piping	Entire Building	9,925	SF	6	\$6,671	
umps							
	Pumps - Sump-Simplex	Electrical Room	1	EA	6	\$745	



Category: Plumbing System	Leastion	Ouentitue	l lmit	Denk	Cast	Corre
Group Item - Type	Location	Quantity	Unit	капк	Cost	Comme
Pumps						
Plumbing System Subtotal:					\$37,956	
Building: Branch_North						
Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #2 (Regular Classroom)						
Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	32	LF	6	\$685	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Student Lockers - One Tier	1st Floor	12	EA	6	\$1,114	
Walls - Plaster/Drywall	1st Floor	705	SF	6	\$1,946	
Walls - Plaster/Drywall	1st Floor	10	SF	6	\$39	peeling paint
Walls - Structural Glazed Tile	1st Floor	160	SF	6	\$503	
Classroom #701 (Regular Classroom)						
Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	

room #701 (Regular Classroom)					
Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301
Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716
Lighting - Pendent/Surface	2nd Floor	12	EA	6	\$1,487
Marker Board	2nd Floor	32	LF	6	\$685
Storage/ Closet	2nd Floor	50	SF	6	\$363
Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114
Walls - Plaster/Drywall	2nd Floor	715	SF	6	\$1,973
Walls - Structural Glazed Tile	2nd Floor	160	SF	6	\$503
room #702 (Regular Classroom)					
Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301
Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716
Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0
Marker Board	2nd Floor	32	LF	6	\$685
Storage/ Closet	2nd Floor	50	SF	6	\$363
Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114
Walls - Plaster/Drywall	2nd Floor	715	SF	6	\$1,973

Building: Branch_North

Category:	Classrooms
-----------	------------

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #702 (Regular Classroom)						
	Walls - Structural Glazed Tile	2nd Floor	160	SF	6	\$503	
Classro	oom #703 (Regular Classroom)						
0.000.0	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	32	LF	6	φ0 \$685	
	Storage/ Closet	2nd Floor	50	SF	6	\$363	
	Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
	Walls - Plaster/Drywall	2nd Floor	710	SF	6	\$1,960	
	Walls - Plaster/Drywall	2nd Floor	5	SF	6	\$19	Peeling paint
	Walls - Structural Glazed Tile	2nd Floor	160	SF	6	\$503	
		21011001	100	01	0	ψ000	
Classro	oom #704 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	32	LF	6	\$685	
	Storage/ Closet	2nd Floor	50	SF	6	\$363	
	Student Lockers - One Tier	2nd Floor	12	EA	6	\$1,114	
	Walls - Plaster/Drywall	2nd Floor	715	SF	6	\$1,973	
	Walls - Structural Glazed Tile	2nd Floor	160	SF	6	\$503	
Classro	oom #801 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	32	LF	6	\$685	
	Storage/ Closet	1st Floor	50	SF	6	\$363	
	Student Lockers - One Tier	1st Floor	12	EA	6	\$1,114	
	Walls - Plaster/Drywall	1st Floor	715	SF	6	\$1,973	
	Walls - Structural Glazed Tile	1st Floor	160	SF	6	\$503	
Classro	oom #803 (Regular Classroom)						
5105510	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
			I		J	ψυσι	

Category: Classrooms

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #803 (Regular Classroom)						
Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	32	LF	6	\$685	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Student Lockers - One Tier	1st Floor	12	EA	6	\$1,114	
Walls - Plaster/Drywall	1st Floor	715	SF	6	\$1,973	
Walls - Structural Glazed Tile	1st Floor	160	SF	6	\$503	
Classroom #804 (Regular Classroom)						
Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	32	LF	6	\$685	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Student Lockers - One Tier	1st Floor	12	EA	6	\$1,114	
Walls - Plaster/Drywall	1st Floor	715	SF	6	\$1,973	
Walls - Structural Glazed Tile	1st Floor	160	SF	6	\$503	

Classrooms Subtotal:

\$66,541

Building: Branch_North

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Co	comments
Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	2nd Floor-Counselor's Office 9	130	SF	6	\$450	
	Doors - Wood Doors inclu hw	2nd Floor-Counselor's Office 9	1	EA	6	\$301	
	Floor - Carpet	2nd Floor-Counselor's Office 9	130	SF	6	\$277	
	Lighting - Pendent/Surface	2nd Floor-Counselor's Office 9	1	EA	6	\$124	
	Power Distribution	2nd Floor-Counselor's Office 9	4	EA	6	\$8,500	
	Storage/ Closet	2nd Floor-Counselor's Office 9	10	SF	6	\$73	
	Walls - Plaster/Drywall	2nd Floor-Counselor's Office 9	400	SF	6	\$1,104	
	Ceiling - Plaster/Drywall	2nd Floor-Dean's Office 13	110	SF	6	\$381	
	Doors - Wood Doors inclu hw	2nd Floor-Dean's Office 13	1	EA	6	\$301	
	Floor - Carpet	2nd Floor-Dean's Office 13	110	SF	6	\$234	
	Lighting - Pendent/Surface	2nd Floor-Dean's Office 13	1	EA	6	\$124	
	Power Distribution	2nd Floor-Dean's Office 13	4	EA	6	\$8,500	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	istrative Suites/Offices						
	Storage/ Closet	2nd Floor-Dean's Office 13	10	SF	6	\$73	
	Walls - Plaster/Drywall	2nd Floor-Dean's Office 13	350	SF	6	\$966	
	Ceiling - Splined	Main Office	560	SF	6	\$456	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	\$602	
	Floor - Carpet	Main Office	560	SF	6	\$1,193	
	Lighting - Pendent/Surface	Main Office	12	EA	7	\$0	
	Power Distribution	Main Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	Main Office	705	SF	6	\$1,946	
	Ceiling - Plaster/Drywall	Office locate under stair next to rm. 804	75	SF	7	\$0	
	Doors - Wood Doors inclu hw	Office locate under stair next to rm. 804	1	EA	6	\$301	
	Floor - Carpet	Office locate under stair next to rm. 804	75	SF	6	\$160	
	Lighting - Pendent/Surface	Office locate under stair next to rm. 804	1	EA	7	\$0	
	Power Distribution	Office locate under stair next to rm. 804	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	Office locate under stair next to rm. 804	10	SF	5	\$51	water damage and peeling paint at window
	Walls - Plaster/Drywall	Office locate under stair next to rm. 804	276	SF	6	\$762	
MDF_I	DF						
	AC Unit	2nd Floor	1	EA	6	\$496	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Finishes	2nd Floor	85	SF	6	\$607	
Mecha	nical/ Service Rooms						
	Janitor's Closet	1st floor JC next to Girls	15	SF	6	\$107	
	Janitor's Closet	2nd floor JC next to Boys	60	SF	6	\$430	
Restro	om						
	Accessories	1st Floor Boys	200	SF	6	\$1,845	
	Ceiling - Plaster/Drywall	1st Floor Boys	200	SF	6	\$692	
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys	200	SF	6	\$423	
	Lavatory	1st Floor Boys	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor Boys	2	EA	7	\$0	
	Partitions	1st Floor Boys	3	EA	6	\$891	
	Urinals	1st Floor Boys	2	EA	6	\$672	
	Walls - Plaster/Drywall	1st Floor Boys	245	SF	6	\$676	
	Walls - Structural Glazed Tile	1st Floor Boys	395	SF	6	\$1,243	
	Water Closet	1st Floor Boys	3	EA	6	\$1,008	
	Accessories	1st Floor Girls	185	SF	6	\$1,706	
	Ceiling - Plaster/Drywall	1st Floor Girls	185	SF	6	\$640	



цр	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
troo	m						
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	185	SF	6	\$392	
	Lavatory	1st Floor Girls	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor Girls	2	EA	7	\$0	
	Partitions	1st Floor Girls	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	1st Floor Girls	245	SF	6	\$676	
	Walls - Structural Glazed Tile	1st Floor Girls	395	SF	6	\$1,243	
	Water Closet	1st Floor Girls	4	EA	6	\$1,344	
	Accessories	2nd Floor Boys	170	SF	6	\$1,568	
	Ceiling - Plaster/Drywall	2nd Floor Boys	170	SF	6	\$588	
	Doors - Wood Doors inclu hw	2nd Floor Boys	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	170	SF	6	\$360	
	Lavatory	2nd Floor Boys	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor Boys	2	EA	7	\$0	
	Partitions	2nd Floor Boys	3	EA	6	\$891	
	Urinals	2nd Floor Boys	2	EA	6	\$672	
	Walls - Plaster/Drywall	2nd Floor Boys	243	SF	6	\$671	
	Walls - Plaster/Drywall	2nd Floor Boys	2	SF	6	\$8	Crack along wall
	Walls - Structural Glazed Tile	2nd Floor Boys	395	SF	6	\$1,243	
	Water Closet	2nd Floor Boys	4	EA	6	\$1,344	
	Accessories	2nd Floor Girls	185	SF	6	\$1,706	
	Ceiling - Plaster/Drywall	2nd Floor Girls	185	SF	6	\$640	
	Doors - Wood Doors inclu hw	2nd Floor Girls	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	184	SF	6	\$389	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	1	SF	6	\$4	Damage floor tile
	Lavatory	2nd Floor Girls	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor Girls	2	EA	7	\$0	
	Partitions	2nd Floor Girls	4	EA	6	\$1,188	
	Walls - Plaster/Drywall	2nd Floor Girls	245	SF	6	\$676	
	Walls - Structural Glazed Tile	2nd Floor Girls	395	SF	6	\$1,243	
	Water Closet	2nd Floor Girls	6	EA	6	\$2,016	
	Accessories	Main Office	21	SF	6	\$194	
	Ceiling - Plaster/Drywall	Main Office	21	SF	6	\$73	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Main Office	21	SF	6	\$44	
	Lavatory	Main Office	1	EA	6	\$320	
	Lighting - Pendent/Surface	Main Office	1	EA	7	\$0	



Building: Branch_North

Category: Rooms (Other Than Classrooms)

p Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
oom						
Walls - Plaster/Drywall	Main Office	60	SF	6	\$196	
Walls - Plaster/Drywall	Main Office	60	SF	6	\$196	
Water Closet	Main Office	1	EA	6	\$336	

Building: Branch_North

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	pr						
	Ceiling - Plaster/Drywall	1st Floor	885	SF	6	\$5,480	
	Doors - Store Front	1st Floor	3	EA	6	\$3,625	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	6	\$276	
	Floor - Carpet	1st Floor	45	SF	6	\$96	
	Floor - Concrete	1st Floor	50	SF	6	\$26	
	Floor - Tile/Sheet	1st Floor	835	SF	6	\$454	
	Lighting - Lay-in	1st Floor	1	EA	6	\$119	
	Lighting - Pendent/Surface	1st Floor	9	EA	6	\$1,115	
	Stairs - Terrazzo	1st Floor	3	LF	6	\$28	
	Walls - Masonry	1st Floor	280	SF	6	\$881	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	6	\$4,788	
	Walls - Structural Glazed Tile	1st Floor	1,400	SF	6	\$4,404	
	Ceiling - Plaster/Drywall	2nd Floor	650	SF	6	\$4,025	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	6	\$276	
	Floor - Tile/Sheet	2nd Floor	650	SF	6	\$353	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	\$743	
	Walls - Plaster/Drywall	2nd Floor	985	SF	6	\$4,367	
	Walls - Structural Glazed Tile	2nd Floor	995	SF	6	\$3,130	
Safety							
	Security Cameras	Entire Building	2	EA	6	\$388	
Stairs							
	Ceiling - Plaster/Drywall	#1 S Stair	205	SF	6	\$1,501	
	Floor - Terrazzo	#1 S Stair	75	SF	6	\$630	
	Floor - Tile	#1 S Stair	85	SF	6	\$46	
	Handrails	#1 S Stair	54	LF	6	\$468	
	Lighting - Pendent/Surface	#1 S Stair	2	EA	6	\$248	



Building: Branch_North

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Stairs - Terrazzo	#1 S Stair	22	LF	6	\$204	
	Walls - Plaster/Drywall	#1 S Stair	650	SF	6	\$1,794	
	Walls - Structural Glazed Tile	#1 S Stair	650	SF	6	\$2,045	
	Ceiling - Plaster/Drywall	#2 N Stair	175	SF	6	\$1,281	
	Floor - Terrazzo	#2 N Stair	75	SF	6	\$630	
	Floor - Tile	#2 N Stair	20	SF	6	\$11	
	Handrails	#2 N Stair	54	LF	6	\$468	
	Lighting - Pendent/Surface	#2 N Stair	2	EA	6	\$248	
	Stairs - Terrazzo	#2 N Stair	32	LF	6	\$297	
	Walls - Plaster/Drywall	#2 N Stair	5	SF	5	\$31	
	Walls - Plaster/Drywall	#2 N Stair	645	SF	6	\$1,780	
	Walls - Structural Glazed Tile	#2 N Stair	650	SF	6	\$2,045	
	Ceiling - Splined	Office Stairs	100	SF	6	\$289	
	Floor - Carpet	Office Stairs	60	SF	6	\$128	
	Floor - Tile	Office Stairs	85	SF	6	\$46	
	Handrails	Office Stairs	42	LF	6	\$364	
	Lighting - Pendent/Surface	Office Stairs	1	EA	6	\$124	
	Stairs - Terrazzo	Office Stairs	22	LF	6	\$204	
	Walls - Plaster/Drywall	Office Stairs	700	SF	6	\$1,932	
Buildi	ing Interior Subtotal:					\$51,386	
Total	Building Cost					\$655,726	
Buildi	ing: Branch_South						
Categ	ory: Building Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	ce						
	Exterior Doors - Exterior Steel Door	2nd floor fire escape	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Entrance 4 - North	1	EA	5	\$1,341	Bottom of door, frame, threshold are rusted, bent with areas of peeling on door
	Exterior Doors - Exterior Steel Door	Entrance 5 - West	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Exit 8 - 1st Floor Fire Escape	1	EA	5	\$1,341	Bottom of door, frame, threshold rusted
	Exterior Doors - Exterior Steel Door	Main Entrance 7 - East	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	Entrance 6 - South	1	EA	6	\$481	
	Exterior Stairs - Concrete	Entrance 6 - South	20	LF	6	\$1,635	
	Exterior Stairs - Concrete	Main Entrance 7 - East	32	LF	7	\$0	



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Ramp Handrail - Steel_Ramp Handrail	Main Entrance 7 - East	75	LF	7	\$0	
	Ramps - Concrete	Main Entrance 7 - East	40	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	Main Entrance 7 - East	15	LF	7	\$0	
Fire Es	саре						
	Fire Escape	North Façade	50	LF	6	\$31,588	
Founda	ation						
	Foundation - Concrete	Entire Building	325	LF	7	\$0	
	Superstructure - Concrete	Entire Building	12,600	SF	7	\$0	
Lighting	g						
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	\$1,732	
Roof Sy	ystem						
	Coping - Metal	Roof 4	45	LF	6	\$1,445	
	Coping - Metal	Roof 5	30	LF	6	\$964	At south elevation
	Coping - Metal	Roof 6	105	LF	6	\$3,372	
	Coping - Stone	Roof 5	70	LF	6	\$2,248	
	Coping - Terra Cotta	Roof 3	35	LF	6	\$1,124	
	Coping - Terra Cotta	Roof 4	30	LF	6	\$964	
	Coping - Terra Cotta	Roof 5	85	LF	6	\$2,730	At east elevation
	Downspouts - Exterior Downspouts	Roof 3	4	LF	6	\$133	
	Downspouts - Exterior Downspouts	Roof 4	65	LF	6	\$2,160	
	Downspouts - Exterior Downspouts	Roof 5	140	LF	6	\$4,653	
	Downspouts - Exterior Downspouts	Roof 6	30	LF	6	\$997	
	Parapet - 16" - 30" Height	Roof 5	30	LF	6	\$1,199	
	Parapet - 16" - 30" Height	Roof 6	75	LF	6	\$2,997	
	Parapet - Parapet < 16" Height	Roof 3	96	LF	6	\$2,045	
	Parapet - Parapet < 16" Height	Roof 4	30	LF	6	\$639	
	Parapet - Parapet < 16" Height	Roof 5	30	LF	6	\$639	
	Parapet - Parapet < 16" Height	Roof 6	30	LF	6	\$639	
	Parapet - Parapet > 30"	Roof 5	40	LF	6	\$2,557	Areas of loose and missing mortar throughout
	Roof Structure - Concrete	Roof 3	1,050	SF	7	\$0	ů ů
	Roof Structure - Concrete	Roof 4	495	SF	7	\$0	
	Roof Structure - Concrete	Roof 5	2,550	SF	7	\$0	
	Roof Structure - Concrete	Roof 6	2,250	SF	7	\$0	
	Roof - Modified Bitumen	Roof 3	1,050	SF	6	\$9,880	Ponding occurring at west end of roof
	Roof - Modified Bitumen	Roof 4	495	SF	6	\$4,658	



Building: Branch_South

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	vstem						
	Roof - Modified Bitumen	Roof 5	2,550	SF	6	\$23,994	Roof access ladder not bolted properly at top - loose
	Roof - Modified Bitumen	Roof 6	2,250	SF	6	\$21,171	
	Roof - Tile Shingle	Roof 5	425	SF	6	\$3,428	At east elevation
Walls							
	Canopy - Metal	Entire Building	16	SF	6	\$344	Above entrance 5
	Exterior Walls - Brick	Entire Building	10	SF	5	\$238	Area above windows at NE corner with loose and missing mortar joints
	Exterior Walls - Brick	Entire Building	8,045	SF	6	\$54,070	
	Exterior Walls - Stone-Cast	Entire Building	205	SF	6	\$1,378	
	Exterior Walls - Stone-Cut	Entire Building	60	SF	6	\$403	At south elevation
Window	vs						
	Lintels - Steel	Entire Building	275	LF	6	\$7,983	
	Lintels - Stone	Entire Building	5	LF	6	\$0	Above entrance 6 - south
	Windows - Decorative	Entire Building	75	SF	6	\$560	At west elevation
	Windows - Louver	Entire Building	35	SF	6	\$261	
	Windows - Sash Aluminum Double-pane	Entire Building	1,856	SF	6	\$13,854	

Building Exterior Subtotal:

\$213,288

Building: Branch_South

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency Battery Packs - Corridors and Stairs	Entire Building	25	EA	6	\$5,063	
	Emergency Battery Packs - Lunchrooms	Entire Building / 1st Floor	4	EA	6	\$810	
	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	5	EA	6	\$1,013	
	Emergency Battery Packs - Students Toilets	Entire Building / 1st Floor	2	EA	6	\$405	
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	\$1,797	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	\$299	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	\$299	
Main Se	ervice						
	PA System	Entire Building	12,600	SF	6	\$4,144	served from Branch North building
Power [Distribution						
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	\$3,479	



Category: Electrical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Electrical System Subtotal:					\$17,309	
Building: Branch_South						
-						
Category: Safty System	Le contrar	Owentites	11	Daula	0 1	0
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm		4		0	¢ 40 477	
Fire Alarm Panel	Entire Building / Boiler Room	1	EA	3		Panel has over 20 years of service.
Fire Alarm Strobe Lights	Entire Building	12,600	SF	6	\$4,505	
Fire Alarm_System	Entire Building	12,600	SF	6	\$6,126	
Safty System Subtotal:					\$60,107	
Building: Branch_South						
-						
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Handling Systems						
Fan Coil Unit- Celing Mounted - Dual Temperature Coil	2nd Floor	1	EA	6	\$1,866	Manufacturer's information not accessible
Boiler Systems						
Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 H	HP Boiler Room	1	EA	5	\$8,508	
Combustion Dampers	Boiler Room	1	EA	6	\$409	
Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure	Boiler Room	1	EA	5	\$8,508	Boiler serves heat exchanger only.
Boiler - 50 - 75 HP					,	
Piping - Condensate Pipe- Steel	Boiler Room	20	LF	6	\$38	
Piping - Steam Pipe- Steel	Boiler Room	20	LF	6	\$38	
Steam Traps	Boiler Room	3	EA	5	\$3,945	
Heat Exchangers						
Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	6	\$0	
Heating Devices			= .		Aa = :	
Cabinet Heaters - With Hot Water Coil	2nd Floor	1	EA	6	\$354	
Fin Tube - Hot Water	1st Floor	20	LF	6	\$189	
Fin Tube - Hot Water Radiators - Hot Water	1st Floor 1st Floor	1	EA	5	\$1,622	
Fin Tube - Hot Water	1st Floor					



Building: Branch_South

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical Plumbing						
	Daul Temperature Pump - Less than 10	Boiler Room	1	EA	6	\$1,111	
	Hydronic Supply and Return - Galvanized	Entire Building	300	LF	6	\$23,196	
Temper	rature Control						
	DDC System	Entire Building	12,600	SF	6	\$7,207	Managed by outsourced IT company
	Thermostats - DDC	Entire Building	9	EA	6	\$0	
Unit Ve	ntilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	9	EA	6	\$11,181	
Ventilat	tion						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof / 1st Floor	2	EA	6	\$1,185	serve the auditorium
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	\$592	outdoor wall-mounted
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof / Lower Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof / Main Roof	2	EA	6	\$1,185	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof / Lower Roof	1	EA	6	\$592	
	Roof Mounted Duct Work	Roof / Main Roof	50	LF	6	\$18,951	
	Type I Exhaust Hood- Kitchen	Roof / 1st Floor	1	EA	2	\$28,265	Hood does not completely cover all cooking equipment

Mechanical System Subtotal:

\$126,292

Building: Branch_South

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	ter						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	13,750	SF	6	\$2,753	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	13,750	SF	6	\$3,343	
	Domestic Piping-Cold Water Risers	Entire Building	13,750	SF	6	\$2,556	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	13,750	SF	6	\$2,163	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	13,750	SF	6	\$2,556	
	Domestic Piping-Hot Water Return Lines	Entire Building	13,750	SF	6	\$1,966	
	Domestic Piping-Hot Water Return Risers	Entire Building	13,750	SF	6	\$1,966	
	Sanitary Piping	Entire Building	13,750	SF	6	\$12,584	
	Storm Piping	Entire Building	13,750	SF	6	\$11,994	



Category: Plumbing System Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Piping Vent Piping	Entire Building	13,750 SF 6	\$9,241
Plumbing System Subtotal:		\$	\$51,432

Building: Branch_South

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #2N (Other Instructional Use)						
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	\$2,547	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	Wood panel
	Floor - Tile/Sheet	2nd Floor	736	SF	6	\$737	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Storage/ Closet	2nd Floor	22	SF	6	\$160	
	Storage/ Closet	2nd Floor	46	SF	6	\$334	Wardrobe
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	6	\$2,760	
	Walls - Plaster/Drywall	2nd Floor	170	SF	5	\$751	Peeling paint
assro	om #2S (Computer Lab)						
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	\$2,547	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	2nd Floor	736	SF	6	\$737	
	Floor - Transom Window	2nd Floor	24	SF	6	\$406	Wood panel
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Storage/ Closet	2nd Floor	22	SF	6	\$160	
	Storage/ Closet	2nd Floor	46	SF	6	\$334	Wardrobe
	Walls - Plaster/Drywall	2nd Floor	1,170	SF	6	\$3,229	
assro	om #705 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	736	SF	6	\$2,547	
	Chalk Board	3rd Floor	17	LF	4	\$1,561	
	Doors - Transom Window	3rd Floor	24	SF	6	\$406	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	736	SF	6	\$737	
ACTEI		Dage 88 of 0	_				Accomment Date: 6/1

\$40,683

5825 S Kostner Ave Chicago, IL 60629

Building: Branch_South

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #705 (Regular Classroom)						
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	6	\$428	
	Storage/ Closet	3rd Floor	22	SF	6	\$160	
	Storage/ Closet	3rd Floor	46	SF	6	\$334	Wardrobe
	Walls - Plaster/Drywall	3rd Floor	1,170	SF	6	\$3,229	
Classro	om #706 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	736	SF	6	\$2,547	
	Chalk Board	3rd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	3rd Floor	24	SF	6	\$406	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	700	SF	6	\$701	
	Floor - Tile/Sheet	3rd Floor	36	SF	5	\$207	Missing and broken tiles
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	16	LF	6	\$343	
	Storage/ Closet	3rd Floor	22	SF	6	\$160	
	Storage/ Closet	3rd Floor	46	SF	6	\$334	Wardrobe
	Walls - Plaster/Drywall	3rd Floor	1,164	SF	6	\$3,213	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	\$31	Wood broder missing

Classrooms Subtotal:

Building: Branch_South

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
mnasia						
Ceiling - Plaster/Drywall	1st Floor	8	SF	5	\$160	water discoloration
Ceiling - Plaster/Drywall	1st Floor	2,062	SF	6	\$11,382	
Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
Floor - Tile	1st Floor	2,068	SF	6	\$4,525	
Floor - Tile	1st Floor	2	SF	5	\$12	broken
Lighting - Pendent/Surface	1st Floor	31	EA	6	\$3,841	
Stage	1st Floor	250	SF	6	\$1,444	
Stage Curtain	1st Floor	3	EA	6	\$0	
Stage-Stairs - Tile	1st Floor	2	LF	6	\$19	
Storage/ Closet	1st Floor	100	SF	5	\$1,613	mold
Walls - Metal Panel	1st Floor	716	SF	6	\$5,345	wood panel



Building: Branch_South

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
mnas	sia						
	Walls - Plaster/Drywall	1st Floor	1,875	SF	6	\$5,175	
chen							
	Ceiling - Splined	1st Floor	200	SF	6	\$163	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Concrete	1st Floor	200	SF	6	\$106	
	Lighting - Lay-in	1st Floor	4	EA	6	\$476	
	Walls - Tile Ceramic/ Porcelain	1st Floor	660	SF	6	\$1,491	
						+ , -	
nch ð	Multipurpose Room	4 ·	4 7 40	05		.	
	Ceiling - Splined	1st Floor	1,740	SF	6	\$1,418	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Tile	1st Floor	1,740	SF	5		cracking throughout
	Lighting - Lay-in	1st Floor	27	EA	6	\$3,212	
	Walls - Metal Panel	1st Floor	975	SF	6		wood panel
	Walls - Plaster/Drywall	1st Floor	975	SF	6	\$2,691	
chan	ical/ Service Rooms						
	Janitor's Closet	JC south corner of corridor	22	SF	6	\$158	
stroo	m						
	Accessories	1st Floor	166	SF	6	\$1,531	
	Accessories	1st Floor	166	SF	6	\$1,531	
	Ceiling - Plaster/Drywall	1st Floor	166	SF	6	\$574	
	Ceiling - Plaster/Drywall	1st Floor	166	SF	6	\$574	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	166	SF	6	\$351	
	Floor - Tile Ceramic/ Porcelain	1st Floor	166	SF	6	\$351	
	Hand Dryer	1st Floor	2	EA	6	\$460	
	Hand Dryer	1st Floor	2	EA	6	\$460	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	\$0	
	Partitions	1st Floor	2	EA	6	\$594	
	Partitions	1st Floor	4	EA	6	\$1,188	



Category: Rooms (Other Than Classrooms)

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom						
Urinals	1st Floor	5	EA	6	\$1,680	
Walls - Plaster/Drywall	1st Floor	144	SF	6	\$397	
Walls - Plaster/Drywall	1st Floor	144	SF	6	\$397	
Walls - Structural Glazed Tile	1st Floor	405	SF	6	\$1,274	
Walls - Structural Glazed Tile	1st Floor	405	SF	6	\$1,274	
Water Closet	1st Floor	2	EA	6	\$672	
Water Closet	1st Floor	4	EA	6	\$1,344	
ooms (Other Than Classrooms) Subtotal:					\$79,167	

Building: Branch_South

Category: Building Interior

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orrido	r						
	Ceiling - Plaster/Drywall	1st Floor	72	SF	6	\$446	
	Ceiling - Splined	1st Floor	790	SF	6	\$2,282	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	\$903	
	Doors - Wood Doors include hw	1st Floor	1	EA	6	\$301	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	6	\$317	
	Floor - Tile/Sheet	1st Floor	955	SF	5	\$4,288	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Lighting - Wall Mounted	1st Floor	2	EA	6	\$248	
	Walls - Plaster/Drywall	1st Floor	810	SF	6	\$4,263	
	Walls - Plaster/Drywall	1st Floor	920	SF	6	\$4,078	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,475	SF	6	\$4,071	
	Ceiling - Plaster/Drywall	2nd Floor	565	SF	6	\$3,498	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Transom Window	2nd Floor	30	EA	6	\$508	
	Floor - Tile/Sheet	2nd Floor	565	SF	6	\$307	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	\$496	
	Walls - Plaster/Drywall	2nd Floor	2,110	SF	6	\$9,354	
	Ceiling - Plaster/Drywall	3rd Floor	565	SF	6	\$3,498	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Doors - Transom Window	3rd Floor	30	EA	6	\$508	
	Floor - Concrete Epoxy/ Painted	3rd Floor	565	SF	6	\$275	
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	\$496	
	Walls - Plaster/Drywall	3rd Floor	2,110	SF	6	\$9,354	



\$670,895

5825 S Kostner Ave Chicago, IL 60629

Building: Branch_South

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
Stairs							
	Ceiling - Plaster/Drywall	W Stair	530	SF	6	\$3,880	
	Floor - Concrete	W Stair	325	SF	6	\$172	
	Handrails	W Stair	98	LF	6	\$849	
	Lighting - Pendent/Surface	W Stair		EA	6	6 \$372 6 \$427 6 \$5,465	
	Stairs - Asphalt	W Stair		LF	6		
	Walls - Plaster/Drywall	W Stair	1,980	SF	6		
	Walls - Plaster/Drywall	W Stair	5	SF	5	\$31	
	Walls - Plaster/Drywall	W Stair	10	SF	5	\$62	
Vertica	Conveyance						
	Elevator - Hydraulic Elevator	Entire Building	1	EA	6	\$19,238	
Buildi	ng Interior Subtotal:					\$82,616	

Total Building Cost

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dr	ainage						
	Civil/ Drainage - Catch Basin	Branch - 5426 S. Lockwood Ave. / Entire Site	17	EA	6	\$18,595	
	Civil/ Drainage - Catch Basin	Main Campus - 5825 S. Kostner Ave / Entire Site	4	EA	6	\$4,375	
	Civil/ Drainage - Site Manhole	Branch - 5426 S. Lockwood Ave. / Entire Site	4	EA	6	\$5,971	
	Civil/ Drainage - Site Manhole	Main Campus - 5825 S. Kostner Ave / Entire Site	8	EA	7	\$0	
Fencing	9						
	Fencing - Chain Link	Main Campus - 5825 S. Kostner Ave	85	LF	6	\$1,596	
	Fencing - New Standard Ornamental	Branch - 5426 S. Lockwood Ave.	840	LF	7	\$0	
	Fencing - New Standard Ornamental	Main Campus - 5825 S. Kostner Ave	865	LF	6	\$27,596	
	Fencing - New Standard Ornamental	Main Campus - 5825 S. Kostner Ave / East	30	LF	5	\$4,272	Majority of sections north of trash enclosure and in between soccer field bent, missing balusters, cracked
	Fencing - Old Standard Ornamental	Main Campus - 5825 S. Kostner Ave	30	LF	6	\$1,553	SE corner of main in between annex with gate



SITE

Category: Site

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fencing			~~~·,	•••••			
	Fencing - Wood Fencing w/ Steel Frame	Branch - 5426 S. Lockwood Ave.	315	LF	7	\$0	North side of both sites
Landsc		Dranch 5400 C Lookurand Ave / North	0		0	¢000	
	Benches	Branch - 5426 S. Lockwood Ave. / North East	2	EA	6	\$860	
	Benches	Main Campus - 5825 S. Kostner Ave / North West	2	EA	6	\$860	At NW corner adjacent to flagpole
	Landscape - Grass	Branch - 5426 S. Lockwood Ave.	16,115	SF	6	\$13,366	
	Landscape - Grass	Main Campus - 5825 S. Kostner Ave	21,430	SF	6	\$17,774	
	Landscape - Hardscape- Asphalt	Main Campus - 5825 S. Kostner Ave	4,525	SF	7	\$0	
	Landscape - Hardscape- Asphalt	Main Campus - 5825 S. Kostner Ave / East			6	\$2,417	Several areas east of main building and in between annex / soccer field / detached boiler building cracked, sinking, potholes with ponding
	Landscape - Hardscape- Concrete	Main Campus - 5825 S. Kostner Ave	19,960	SF	6	\$103,040	
	Parkway trees	Branch - 5426 S. Lockwood Ave.	19	EA	6	\$12,541	
	Parkway trees	Main Campus - 5825 S. Kostner Ave	27	EA	6	\$17,821	
	Planting Beds/ Area	Main Campus - 5825 S. Kostner Ave	6,810	SF	6	\$11,199	
	Retaining Wall - Concrete	Main Campus - 5825 S. Kostner Ave / East	30	SF	6	\$703	At NE corner of detached boiler building
Parking	Lot						
	Concrete Curbs	Branch - 5426 S. Lockwood Ave Far West	780	LF	7	\$0	
	Concrete Curbs	Branch - 5426 S. Lockwood Ave Middle West	1,185	LF	7	\$0	
	Concrete Curbs	Branch - 5426 S. Lockwood Ave North	85	LF	7	\$0	
	Concrete Curbs	Main Campus - 5825 S. Kostner Ave - NE / North	405	LF	7	\$0	At parking lot entry drive
	Interior Plantings	Branch - 5426 S. Lockwood Ave Middle West / North West	60	LF	7	\$0	
	Surface - Asphalt	Branch - 5426 S. Lockwood Ave Far West	25,790	SF	7	\$0	
	Surface - Asphalt	Branch - 5426 S. Lockwood Ave Middle West	31,185	SF	7	\$0	
	Surface - Asphalt	Branch - 5426 S. Lockwood Ave North	2,570	SF	7	\$0	
	Surface - Asphalt	Main Campus - 5825 S. Kostner Ave - NE	200	SF	5	\$1,181	Cracking with potholes at driveway entry
	Surface - Asphalt	Main Campus - 5825 S. Kostner Ave - NE	25,900	SF	6	\$62,593	Cracking throughout at east and west drive aisles
	Surface - Concrete	Main Campus - 5825 S. Kostner Ave - NE	2,825	SF	6	\$6,827	



SITE

Category: Site

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
arking	Lot						
	Trash Enclosure - Chain Links	Main Campus - 5825 S. Kostner Ave - NE	1,935	SF	6	\$33,952	At South side of detached boiler building
	Trash Enclosure - Masonry	Branch - 5426 S. Lockwood Ave North	305	SF	7	\$0	
idewall	<s< td=""><td></td><td></td><td></td><td></td><td></td><td></td></s<>						
	Sidewalks - Internal Walks	Branch - 5426 S. Lockwood Ave.	830	LF	7	\$0	
	Sidewalks - Internal Walks	Main Campus - 5825 S. Kostner Ave	50	LF	4	\$4,859	At entrance 15 - West concrete walk down to public walk - Cracked with sinking and holes throughout / At NE corner of annex down to pub asphalt walk in between soccer field - Steep sloped asphalt with potholes, cracked, sinking, upheaving areas throughout / At NE corner of main adjacent to parking driveway entry - Cracked with missing areas
	Sidewalks - Internal Walks	Main Campus - 5825 S. Kostner Ave / Entire Site	1,190	LF	6	\$14,294	
	Sidewalks - Perimeter Sidewalks	Branch - 5426 S. Lockwood Ave.	20,390	SF	7	\$0	
	Sidewalks - Perimeter Sidewalks	Main Campus - 5825 S. Kostner Ave	10,495	SF	6	\$20,861	Location: N,W,S sides of site
ignage							
	Flag Pole - Flag Pole	Branch - 5426 S. Lockwood Ave. / East	1	EA	6	\$1,657	
	Flag Pole - Flag Pole	Main Campus - 5825 S. Kostner Ave / North West	1	EA	6	\$1,657	At Entrance 17 - NE
	Marquee - Free Standing Back Lighted	Main Campus - 5825 S. Kostner Ave / North West	1	EA	6	\$0	At Entrance 17 - NE
	Monument - Building Mounted Cut Letter Sign	Main Campus - 5825 S. Kostner Ave / West Façade	1	EA	6	\$0	
	Monument - Sign	Branch - 5426 S. Lockwood Ave.	3	EA	6	\$0	At west elevation of north - "Midway Academy", south elevation of north "Pasteur Elementary Branch" / At east elevation of south
ite Su	ubtotal:					\$392,420	
otal S	Site Cost					\$392,420	
amp	ous Total ^{2 3}				\$6.3	372,394	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.



² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main											1			1
Computer Lab	Regular Classroom	2nd Floor	214	214	715	22	34	76	140	85	40	Ν	Y	Ν
Kindergarten	Regular Classroom	1st Floor	110	110	715	0	0	8	160	105	40	N	Y	N
Kindergarten	Regular Classroom	1st Floor	116	116	1,010	0	0	10	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	112	112	715	0	0	8	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	117	117	715	2	2	12	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	118	118	715	2	2	12	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	119	119	715	2	2	12	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	120	120	715	2	2	12	160	105	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	715			6	140	85	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	715	0	0	6	140	85	40	N	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	213	213	715	0	0	6	140	85	40	Ν	Y	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	715	2	2	12	140	85	40	Ν	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	715	0	0	6	140	85	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	715	0	0	6	140	85	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	715	0	0	6	140	85	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	715	0	0	6	140	85	40	Ν	Y	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	715	0	0	6	140	85	40	N	Y	Ν
Regular Classroom	Special Program	2nd Floor	222	222	770	2	2	12	140	85	40	N	Y	Ν
Special Program	Regular Classroom	2nd Floor	208	208	480	2	15	50	60	20	40	N	Ν	Ν
Store Room	Regular Classroom	2nd Floor	211	211	715	0	0	6	140	85	40	Ν	Y	Ν
2-Classroom Mod	ular													
Regular Classroom	Regular Classroom	1st Floor	M401	M401	765	1	1	16	42	18	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	M402	M402	698	1	1	16	42	18	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	M404	M404	698	1	1	16	42	18	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	M501	M501	698	1	1	16	42	18	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	M502	M502	765	1	1	16	42	18	40	Y	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	M503	M503	765	1	1	16	42	18	40	Y	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	M504	M504	698	1	1	16	42	18	40	Y	Y	N
Special Program	Regular Classroom	1st Floor	M403	M403	765	1	1	16	42	18	40	Y	Y	Ν
Annex														
Regular Classroom	Regular Classroom	3rd Floor	301	122	870	1	8	18	102	54	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	302	121	870	1	8	18	102	54	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	303	108	870	1	8	18	102	54	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	304	104	870	1	8	18	102	54	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	305	107	870	1	8	18	102	54	40	N	Y	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Annex			-			•	•			•		•	<u>.</u>	+
Regular Classroom	Regular Classroom	1st Floor	306	103	870	1	8	18	102	54	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	307	106	870	1	8	18	102	54	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	308	102	870	1	8	18	102	54	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	309	105	870	1	8	18	102	54	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	310	101	870	1	8	18	102	54	40	Ν	Y	Ν
Branch_North														
Regular Classroom	Regular Classroom	1st Floor	2	802	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	701	701	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	702	702	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	703	703	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	704	704	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	801	801	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	803	803	715	0	0	6	119	20	40	Y	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	804	804	715	0	0	6	119	20	40	Y	Y	Ν
Branch_South														
Computer Lab	Computer Lab	2nd Floor	2S		736	0	0	64	120	20	40	Ν	Y	Ν
Other Instructional Use	Art Room	2nd Floor	2N		736	0	0	6	120	20	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	705	705	736	0	0	6	120	20	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	706	706	736	0	0	6	120	20	40	Ν	Y	Ν