

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1926	2	76,131	\$2,225,135
Annex	1996	1	16,560	\$836,450
Modular 1	0	1	6,000	\$257,521
Modular 2-500	0	1	6,000	\$229,887
Modular 3-400	0	1	6,000	\$185,447
SITE				\$410,907
Campus Total	· · · · · · · · · · · · · · · · · · ·		110,691	\$4,145,347

Building: Main

Category: Building Exterior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntrance						
Entrance Control - Audio and Video	Entrance 1-SW	1	EA	6	\$702	
Entrance Control - Audio and Video	Main Entrance 3-NW	1	EA	6	\$702	
Exterior Doors - Exterior FRP Door	Entrance 1-SW	2	EA	6	\$1,263	
Exterior Doors - Exterior FRP Door	Entrance 2-SW / Multi-Purpose	2	EA	6	\$1,263	
Exterior Doors - Exterior FRP Door	Entrance 4-NE	2	EA	6	\$1,263	
Exterior Doors - Exterior FRP Door	Entrance 5-SE / Gym	2	EA	6	\$1,263	
Exterior Doors - Exterior FRP Door	Entrance 6-SE	2	EA	6	\$1,263	
Exterior Doors - Exterior FRP Door	Exit 7-South / In classroom	1	EA	6	\$631	
Exterior Doors - Exterior FRP Door	Main Entrance 3-NW	2	EA	6	\$1,263	
Exterior Doors - Exterior Steel Door	Entrance 16-North / Boiler house	1	EA	6	\$481	
Exterior Doors - Exterior Steel Door	Entrance 17-South / Boiler House	1	EA	6	\$481	
Exterior Doors - Transom Lite	Entrance 16-North / Boiler house	2	EA	7	\$0	
Exterior Doors - Transom Lite	Entrance 17-South / Boiler House	2	EA	7	\$0	
Exterior Doors - Transom Lite	Entrance 1-SW	1	EA	7	\$0	Decorative
Exterior Doors - Transom Lite	Entrance 2-SW / Multi-Purpose	1	EA	7	\$0	Decorative
Exterior Doors - Transom Lite	Entrance 4-NE	1	EA	7	\$0	Decorative



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Exterior Doors - Transom Lite	Entrance 5-SE / Gym	1	EA	7	\$0	Decorative
	Exterior Doors - Transom Lite	Entrance 6-SE	1	EA	7	\$0	Decorative
	Exterior Doors - Transom Lite	Exit 7-South / In classroom	1	EA	7	\$0	
	Exterior Doors - Transom Lite	Main Entrance 3-NW	1	EA	7	\$0	Decorative
	Exterior Stairs - Concrete	Entrance 1-SW	75	LF	6	\$6,133	
	Exterior Stairs - Concrete	Entrance 6-SE	90	LF	6	\$7,359	
	Exterior Stairs - Concrete	Exit 7-South / In classroom	15	LF	6	\$1,227	
	Exterior Stairs - Stone	Entrance 16-North / Boiler house	5	LF	6	\$565	
	Exterior Stairs - Stone	Entrance 2-SW / Multi-Purpose	56	LF	6	\$6,327	
	Exterior Stairs - Stone	Entrance 5-SE / Gym	56	LF	6	\$6,327	
	Exterior Stairs - Stone	Exit 7-South / In classroom	3	LF	6	\$339	
	Power Door Operator and Controls	Entrance 1-SW	1	EA	6	\$0	
	Power Door Operator and Controls	Main Entrance 3-NW	1	EA	6	\$0	
	Stair Handrail - Steel_Stair Handrail	Entrance 1-SW	30	LF	6	\$260	
	Stair Handrail - Steel_Stair Handrail	Entrance 2-SW / Multi-Purpose	35	LF	6	\$303	
	Stair Handrail - Steel_Stair Handrail	Entrance 5-SE / Gym	35	LF	6	\$303	
	Stair Handrail - Steel_Stair Handrail	Entrance 6-SE	10	LF	5	\$115	Damaged - bent and leaning
	Stair Handrail - Steel_Stair Handrail	Entrance 6-SE	30	LF	6	\$260	
	Stair Handrail - Steel_Stair Handrail	Exit 7-South / In classroom	20	LF	6	\$173	
Founda	ation						
	Foundation - Concrete	Entire Building	1,165	LF	7	\$0	
	Foundation - Concrete	Entire Building	30	LF	6	\$5,827	Seepage at tunnel and south side of boiler house
	Superstructure - Concrete	Entire Building	76,131	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Wall Mounted	Entire Building	29	EA	6	\$8,374	
Roof S	ystem						
	Chimney - Metal Flue	Roof 3 - Boiler House	125	LF	7	\$0	
	Coping - Stone	Roof 1	80	LF	6	\$2,569	
	Coping - Terra Cotta	Roof 1	780	LF	6	\$25,052	
	Coping - Terra Cotta	Roof 1	100	LF	6	\$8,167	Several pieces cracked, chipped with loose and missing mortar joints
	Coping - Terra Cotta	Roof 3 - Boiler House	215	LF	6	\$6,905	
	Downspouts - Exterior Downspouts	Roof 1	415	LF	6	\$13,792	
	Downspouts - Interior Downspouts	Roof 1	180	LF	6	\$5,982	
	Downspouts - Interior Downspouts	Roof 3 - Boiler House	20	LF	6	\$665	
	Parapet - 16" - 30" Height	Roof 1	390	LF	6	\$15,582	



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Sy	/stem						
	Parapet - 16" - 30" Height	Roof 3 - Boiler House	215	LF	6	\$8,590	
	Parapet - Parapet < 16" Height	Roof 1	200	LF	6	\$4,261	
	Parapet - Parapet > 30"	Roof 1	370	LF	6	\$23,651	
	Roof Structure - Concrete	Roof 1	24,360	SF	7	\$0	
	Roof Structure - Concrete	Roof 3 - Boiler House	2,860	SF	7	\$0	
	Roof Structure - Heavy Timber	Roof 1	5,125	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Roof 1	22,360	SF	6	\$227,341	
	Roof - Asphalt Gravel Ballast	Roof 1	2,000	SF	5	\$53,911	Several areas blistering, bubbling, worn out throughout / Ripping with open seams occurring throughout
	Roof - Asphalt Shingle	Roof 1	5,125	SF	6	\$23,525	
	Roof - PVC Membrane	Roof 3 - Boiler House	2,860	SF	6	\$23,639	
Walls							
	Cheek-Wall - Concrete	Entire Building	95	SF	6	\$974	Entrances 2, 5, 6
	Cheek-Wall - Concrete	Entire Building	5	SF	6	\$51	Entrance 5 - Cracked, chipped
	Cornice - Terra Cotta	Entire Building	405	LF	6	\$14,044	
	Exterior Walls - Brick	Entire Building	24,715	SF	6	\$166,110	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,240	SF	6	\$7,040	Dent and bent throughout
	Exterior Walls - Stone-Cast	Entire Building	1,960	SF	6	\$13,173	
	Exterior Walls - Terra Cotta	Entire Building	2,505	SF	6	\$16,836	
Windov	<i>i</i> s						
	Clerestory - Glass Single-Pane	Entire Building	1,220	SF	6	\$11,427	
	Guard - Guards perforated	Entire Building	2,875	SF	6	\$36,713	
	Guard - Guards wire guard	Entire Building	785	SF	6	\$10,024	
	Lintels - Steel	Entire Building	285	LF	6	\$8,273	
	Lintels - Stone	Entire Building / South Façade	360	LF	6	\$0	
	Lintels - Terra Cotta	Entire Building	250	LF	6	\$0	
	Windows - Decorative	Entire Building	250	SF	6	\$1,866	
	Windows - Louver	Entire Building	155	SF	6	\$1,157	
	Windows - Sash Aluminum Double-pane	Entire Building	5,885	SF	6	\$43,929	
	Windows - Sash Lexan	Entire Building	175	SF	6	\$1,306	
Buildi	ng Exterior Subtotal:					\$831,022	

Building: Main

Category: Electrical System



Ferdinand Peck Elementary School

3826 W 58th St Chicago, IL 60629

Group I	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergen	cy System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	12,175	SF	5	\$0	Served from Emergency power from ComEd / no UPS or Generator
I	Emergency A/C Power - Multipurpose Room	Entire Building / 1st Floor	2,114	SF	5	\$0	Served from Emergency power from ComEd / no UPS or Generator
I	Emergency Battery Packs - Corridors and Stairs	Entire Building	43	EA	6	\$8,708	
I	Emergency Battery Packs - Gym	Entire Building / 1st Floor	6	EA	6	\$1,215	
I	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	16	EA	6	\$3,240	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	\$1,620	
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	2	\$12,001	no self contained battery, no generator
	Exit Signs - Gym	Entire Building / 1st Floor	2	EA	2	\$1,157	no self contained battery, no generator
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	4	EA	2	\$2,182	no self contained battery, no generator
:	Security System - CCTV	Entire Building	76,131	SF	6	\$22,862	
:	Security System - Intrusion Detection	Entire Building	76,131	SF	6	\$19,596	
Main Ser	vice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	Another feed from ComEd
I	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	\$0	
I	PA System	Entire Building	76,131	SF	6	\$25,039	
Power Di	stribution						
l	Lighting and Power Panels - 100 A	Entire Building / Electrical Room	1	EA	6	\$299	Emergency panel Fuse type
	Lighting and Power Panels - 100 A	Entire Building / Electrical Room	2	EA	6	\$598	Emergency panel
	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	10	EA	7	\$0	
1	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	6	\$497	Emergency Light panel
I	Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	8	EA	7	\$0	
I	Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	3	EA	7	\$0	
1	Main Distribution Panels - Greater than 600 amp	Entire Building / Electrical Room	2	EA	7	\$0	
I	Main Distribution Panels - Less than 400 amp	Entire Building / Electrical Room	1	EA	7	\$0	
Electric	cal System Subtotal:					\$99.014	

Electrical System Subtotal:

\$99,014

Building: Main

Category:	Safty	System
-----------	-------	--------

Fire Alarm Fire Alarm Panel Entire Building / Mechanical Fire Alarm Panel		
Fire Alarm Panel Entire Building / Mechanical F		
	Room 1 EA 7 \$0	
Fire Alarm Strobe Lights Entire Building	76,131 SF 7 \$0	
Fire Alarm_System Entire Building	76,131 SF 7 \$0	



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chiller-Air Cooled-Scroll Type-Ground Mounted - 101 - 150 tons	Mechanical Building/Central Plant	1	EA	7	\$0	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	\$0	Serves MDF room
	Glycol Feed	Mechanical Building/Central Plant / Mechanical Room	1	EA	7	\$0	
	Pipes - Dual Temperature Pipe- Steel	Mechanical Building/Central Plant	100	LF	7	\$0	
	Pressure Fill System	Mechanical Building/Central Plant / Mechanical Room	1	EA	7	\$0	
Air Han	dling Systems						
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 4000 - 8000 cfm	Mechanical room G / Mechanical Room	1	EA	6	\$3,321	Serves Gym
	Air Handling Unit- Built Up- Single Zone- Daul Temperature Coils - 4000 - 8000 cfm	Mechanical room MP / Mechanical Room	1	EA	6	\$3,321	serves nulti-purpose room
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - 15001 - 25000 cfm	mechanical room 2W / Mechanical Room	1	EA	6	\$5,788	serves west side of building
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Daul Temperature Coils - 15001 - 25000 cfm	Mechanical room 3 / Mechanical Room	1	EA	6	\$5,788	Serves East side of building
	Air Intake	mechanical room 2W / Roof	1	EA	7	\$0	
	Air Intake	Mechanical room 3 / Roof	1	EA	7	\$0	
	Air Intake	Mechanical room G / Roof	1	EA	7	\$0	
	Air Intake	Mechanical room MP / Roof	1	EA	7	\$0	
	Auxiliaries - 15001 - 25000 cfm	mechanical room 2W / Mechanical Room	1	EA	6	\$5,788	
	Auxiliaries - 4000 - 8000 cfm	Mechanical room G / Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 4000 - 8000 cfm	Mechanical room MP / Mechanical Room	1	EA	7	\$0	
	Auxiliaries - 8001 - 15000 cfm	Mechanical room 3 / Mechanical Room	1	EA	7	\$0	
	Fan Coil Unit- Floor Mounted - Dual Temperature Coil	Entire Building / 1st Floor	2	EA	6	\$3,586	
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	10	EA	7	\$0	Dual Tempature
	Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM	Entire Building / Mechanical Room	1	EA	6	\$1,282	
	Outdoor Return Fans- inline Centrifugal - 5000 - 10000 CFM	Roof	2	EA	7	\$0	Return/Exhaust for building
	Reheat Boxes - Reheat Boxes with Hot Water Coil	mechanical room 2W / Plenum	7	EA	6	\$6,899	-
	Reheat Boxes - Reheat Boxes with Hot Water Coil	Mechanical room 3 / Mechanical Room	6	EA	6	\$5,914	Serves AH-3
	Return Duct Work - Indoor- Vertical Shaft and Ducts	mechanical room 2W / Entire Building	200	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room 3 / Mechanical Room	200	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room G / Mechanical Room	100	LF	7	\$0	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical room MP / Entire Building	100	LF	7	\$0	
	Zone Dampers	mechanical room 2W / Plenum	17	EA	6		serve AH-2
	Zone Dampers	Mechanical room 3 / Mechanical Room	17	EA	7	. ,	Serves AH-3



Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Mechanical Building/Central Plant / Boiler Room	2	EA	7	\$0	
Condensing- Hot Water Boiler - 1001 - 2000 MBH	Mechanical Building/Central Plant / Boiler Room	2	EA	7	\$0	
Dual Temperature Pump	Mechanical Building/Central Plant / Mechanical Room	2	EA	6	\$748	
Glycol Feed System	Mechanical Building/Central Plant / Mechanical Room	1	EA	7	\$0	
Piping - Dual Temperature Pipes- Copper	Mechanical Building/Central Plant / Entire Building	800	LF	7	\$0	
Piping - Dual Temperature Pipes- Steel	Mechanical Building/Central Plant / Mechanical Room	100	LF	7	\$0	
Heating Devices						
Fin Tube - Hot Water	Entire Building	100	LF	6	\$944	
Unit Heater - Electric	Electrical Room	1	EA	6	\$278	
Unit Heater - Gas	Mechanical Room	1	EA	6	\$278	
Wall Heater - Electric	Entire Building / 1st Floor	11	EA	7	\$0	
Temperature Control						
DDC System	Entire Building	76,131	SF	7	\$0	
Electric Thermostat	Entire Building	2	EA	6	\$0	
Thermostats - DDC	Entire Building	48	EA	7	\$0	
Ventilation						
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	4	EA	7	\$0	
Roof Mounted Duct Work	Entire Building / Roof	120	LF	7	\$0	Stainless for Return/Exhaust fans
Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	7	\$0	
Mechanical System Subtotal:					\$58,095	
Building: Main						
Category: Plumbing System						

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Hot Water					
Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	7	\$0
Piping					
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	76,131	SF	6	\$15,241
Domestic Piping-Cold Water Horizontal Lines	Entire Building	76,131	SF	6	\$18,507



Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water Risers	Entire Building	76,131	SF	6	\$14,153	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	76,131	SF	6	\$11,975	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	76,131	SF	6	\$14,153	
	Domestic Piping-Hot Water Return Lines	Entire Building	76,131	SF	6	\$10,887	
	Domestic Piping-Hot Water Return Risers	Entire Building	76,131	SF	6	\$10,887	
	Sanitary Piping	Entire Building	76,131	SF	6	\$69,675	
	Storm Piping	Entire Building	76,131	SF	6	\$66,409	
	Vent Piping	Entire Building	76,131	SF	6	\$51,168	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	\$1,977	
	Pumps - Ejector-Duplex	Mechanical Room	2	EA	6	\$2,774	
	Pumps - Sump-Duplex	Mechanical Room	3	EA	6	\$4,161	
Plum	bing System Subtotal:					\$291,967	

Plumbing System Subtotal:

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssroc	om #108 (Special Education)						
	Ceiling - Lay-in	1st Floor	470	SF	6	\$1,411	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	470	SF	6	\$470	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	\$991	
	Marker Board	1st Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,040	SF	6	\$2,870	
ssroc	om #110 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	



oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assroom #110 (Regular Classroom)						
assroom #112 (Regular Classroom)						
Casework	1st Floor	10	LF	6	\$253	
Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
Chalk Board	1st Floor	20	LF	4	\$1,836	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Wood	1st Floor	723	SF	6	\$5,097	
Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
Marker Board	1st Floor	16	LF	7	\$0	
Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	
assroom #114 (Regular Classroom)						
Casework	1st Floor	10	LF	6	\$253	
Ceiling - Lay-in	1st Floor	740	SF	6	\$2,222	
Doors - Transom Window	1st Floor	1	SF	6	\$17	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Floor - Tile/Sheet	1st Floor	740	SF	6	\$741	
Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
Marker Board	1st Floor	8	LF	7	\$0	
Walls - Plaster/Drywall	1st Floor	1,030	SF	6	\$2,843	
assroom #116 (Regular Classroom)						
Casework	1st Floor	10	LF	6	\$253	
Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
Chalk Board	1st Floor	20	LF	4	\$1,836	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
Lighting - Pendent/Surface	1st Floor	16	EA	6	\$1,982	
Marker Board	1st Floor	8	LF	7	\$0	
Walls - Plaster/Drywall	1st Floor	1,125	SF	6	\$3,105	
ssroom #117 (Regular Classroom)						
Casework	1st Floor	32	LF	6	\$808	
Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
Chalk Board	1st Floor	32	LF	4	\$2,938	
Doors - Transom Window	1st Floor	8	SF	6	\$135	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #117 (Regular Classroom)						
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	
Classro	oom #118 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	
Classro	oom #119 (Regular Classroom)						
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
	Chalk Board	1st Floor	32	LF	6	\$714	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	
Classro	oom #120 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	723	SF	6	\$2,171	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	965	SF	6	\$2,663	



Group Item - Type Localion Quality Unit Rank Cot Comments Casework 1st Floor 18 LF 6 \$455 Caliero - Transom Window 1st Floor 8 SF 6 \$313 Doors - Transom Window 1st Floor 12 SF 6 \$313 Doors - Wood Doors inclutu/w 1st Floor 12 SF 6 \$374 Upting - Pendent/Statee 1st Floor 12 SF 6 \$32,65 Marker Board 1st Floor 16 LF 7 \$50 Casework 1st Floor 12 LF 6 \$32,03 Doors - Transom Window 1st Floor 12 LF 6 \$32,01 Upting - PendentSurface 1st Floor<	-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Casework 1st Floor 12 LF 6 \$455 Calling - Layin 1st Floor 72 SF 6 \$5135 Doars - Yraeson Wardow 1st Floor 1 EA 6 \$5135 Doars - Wood Doars inclu hw 1st Floor 72 SF 6 \$5724 Liphing - Pender/Sufface 1st Floor 12 EA 6 \$5135 Walls - Ploster/Toywell 1st Floor 15 Floor 16 L 7 \$0 Walls - Plaster/Toywell 1st Floor 16 L 7 \$0 Calling - Layin 1st Floor 72 SF 6 \$2301 Calling - Layin 1st Floor 72 SF 6 \$2301 Doars - Yraeon Window 1st Floor 72 SF 6 \$2301 Doars - Yraeon Window 1st Floor 72 SF 6 \$2301 Doars - Yraeon Window 1st Floor 72 SF 6 \$2301 Uph			Looaton	Quantity	onne	T Carinx	0051	Comments				
claing - Lupin 1s Floor 78 8F 6 \$2.171 Doose - Transom Window 1st Floor 1 E 6 \$3.03 Doose - Transom Window 1st Floor 12 EF 6 \$3.724 Lighting - Pendent/Suface 1st Floor 12 EF 6 \$3.724 Marker Board 1st Floor 12 EF 6 \$3.724 Classword 1st Floor 12 EF 6 \$3.744 Classword 1st Floor 12 EF 6 \$3.04 Celling - Lupin 1st Floor 12 EF 6 \$3.01 Doose - Transom Window 1st Floor 12 EF 6 \$3.01 Doose - Transom Window 1st Floor 12 EF 6 \$3.01 Doose - Transom Window 1st Floor 12 EF 6 \$3.01 Upting - Pendent/Surface 1st Floor 12 EF 6 \$3.01 Upting - Pendent/Surface 1st Floor 12 EF 6 \$3.01 Upting - Lupin <td< td=""><td>0103310</td><td></td><td>1st Floor</td><td>18</td><td>IF</td><td>6</td><td>\$455</td><td></td></td<>	0103310		1st Floor	18	IF	6	\$455					
Daos - Traisen Window 1st Floor 1 F 6 \$3301 Pioor - TiadShaat 1st Floor 723 SF 6 \$3241 Liphing - PendentSurlace 1st Floor 12 EA 6 \$1247 Marker Beard 1st Floor 12 EA 6 \$2487 Walle - Plaster/Dynail 1st Floor 12 EA 6 \$2487 Casework 1st Floor 12 EA 6 \$2487 Casework 1st Floor 12 EA 6 \$3301 Doors - Transom Window 1st Floor 12 EA 6 \$3301 Doors - Transom Window 1st Floor 12 EA 6 \$3301 Doors - Wood Doors inclu hw 1st Floor 12 EA 6 \$3301 Doors - Wood Doors inclu hw 1st Floor 12 EA 6 \$3301 Doors - Wood Doors inclu hw 1st Floor 12 EA 6 \$31487 Doors - Wood Doors inclu hw 1st Floor 12 EA 6 \$32.001 Doors -												
baces Wood Doors inclu hw 1s Floor 1s Floor 1 EA 6 \$\$724 Lighting 1st Floor 12 EA 6 \$\$1487 Marker Exard 1st Floor 12 EA 6 \$\$1487 Wales Pendert/Syndia 1st Floor 12 EA 6 \$\$2,463 Classwork 1st Floor 12 E 6 \$\$2,171 Doors - Mood Doors inclu hw 1st Floor 72 \$\$ 6 \$\$301 Doors - Mood Doors inclu hw 1st Floor 72 \$\$ 6 \$\$301 Doors - Mood Doors inclu hw 1st Floor 72 \$\$ 6 \$\$301 Floor - Wood 1st Floor 72 \$\$ 6 \$\$301 Floor - Wood 1st Floor 72 \$\$ 6 \$\$207 Uphting - Pendert/Surface 1st Floor 72 \$\$ 6 \$\$207 Uphting - Pendert/Surface 1st Floor 72 \$\$ \$ \$\$200 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>												
Floor - Tile Sheet1st Floor723SF65724Lighting - Pendent/Surface1st Floor12LF6\$1.487Marker Board1st Floor96SF6\$2.083Callence Action StrongCallence Action Calle Ac												
Lighing - Penden/Surface 1st Floor 12 Kater Board 5 6 \$1,477 Marker Board 1st Floor 16 Kater Board 5 6 \$2,263 Casework 1st Floor 7 6 \$2,263 Casework 1st Floor 72 K 6 \$2,171 Doors - Transon Window 1st Floor 72 K 6 \$3303 Doors - Transon Window 1st Floor 72 K 6 \$3503 Doors - Transon Window 1st Floor 72 K 6 \$5007 Doors - Transon Window 1st Floor 72 K 6 \$5007 Lighting - Penden/Surface 1st Floor 72 K 6 \$2,263 Walles - Plaster/Drywall 1st Floor 72 K 6 \$2,263 Casework And Floor 72 K 6 \$2,263 Casework And Floor 72 K 6 \$2,114 Doors -				-								
Marker Board1st Fioor16LF7\$0Walls - Plaster/Dryvall1st Fioor656\$2,661Casework1st Fioor723\$F6\$303Celing - Layin1st Fioor723\$F6\$315Doors - Transom Window1st Fioor723\$F6\$301Doors - Wood Doors inclu hw1st Fioor723\$F6\$301Doors - Wood Doors inclu hw1st Fioor723\$F6\$301Harker Board1st Fioor723\$F6\$314Marker Board1st Fioor12LF7\$00Walls - Plaster/Drywall1st Fioor12LF7\$00Walls - Plaster/Drywall1st Fioor12LF7\$00Walls - Plaster/Drywall2nd Fioor723\$F6\$2,171Chark Board2nd Fioor723\$F6\$2,163Doors - Transom Window2nd Fioor723\$F6\$2,171Chark Board2nd Fioor723\$F6\$2,171Doors - Transom Window2nd Fioor723\$F6\$2,171Doors - Transom Window2nd Fioor723\$F6\$3119Doors - Transom Window2nd Fioor723\$F6\$301Doors - Transom Window2nd Fioor723\$F6\$326Doors - Transom Window2nd Fioor723\$F6\$336Walls - Plaster/Dr												
Walls - Plaster/Dynall 1st Floor 95 8 8 8 8 Casework 1st Floor 12 LF 6 \$303 Caling - Layin 1st Floor 8 5 6 \$2171 Doors - Transon Window 1st Floor 8 5 6 \$2171 Doors - Wood Doors inclu hw 1st Floor 8 5 6 \$503 Doors - Wood Doors inclu hw 1st Floor 72 87 6 \$5047 Lighting - Pendent%urface 1st Floor 72 87 6 \$5047 Marker Board 1st Floor 72 87 6 \$2057 Marker Board 1st Floor 72 87 6 \$22,663 Casework 2nd Floor 72 87 6 \$22,663 Casework 2nd Floor 72 87 6 \$22,663 Casework 2nd Floor 7 8 5 5 5 5 5 5 5 5 5 5 5 5 5 5												
Classroom #123 (Regular Classroom) 1st Floor 12 LF 6 \$303 Celling - Lay-in 1st Floor 723 SF 6 \$22,171 Doors - Transom Window 1st Floor 723 SF 6 \$303 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor - Wood 1st Floor 12 EA 6 \$304 Harker Board 1st Floor 12 EA 6 \$5,097 Lighting - Pendent/Surface 1st Floor 12 LF 7 \$00 Walls - Plaster/Dywall 1st Floor 12 LF 7 \$01 Casework 2nd Floor 9 LF 6 \$227 Casework 2nd Floor 723 SF 6 \$2171 Chalk Board 2nd Floor 7 SF 6 \$2171 Chalk Board 2nd Floor 723 SF 6 \$2171 Chastore 2nd Floor 723												
Casework 1st Floor 12 LF 6 \$303 Celling - Lay-in 1st Floor 723 SF 6 \$2,171 Doors - Transom Window 1st Floor 8 SF 6 \$301 Doors - Wood Doors inclu hw 1st Floor 723 SF 6 \$301 Floor - Wood 1st Floor 723 SF 6 \$5,097 Lighting - Pendent/Surface 1st Floor 72 EA 6 \$1,487 Marker Board 1st Floor 72 EA 6 \$2,171 Marker Board 1st Floor 72 EF 7 \$0 Walls - Plaster/Drywall 1st Floor 72 SF 6 \$2,27 Caling - Lay-in 2nd Floor 7 SF 6 \$119 Doors - Transom Window 2nd Floor 7 SF 6 \$119 Doors - Wood Doors inclu hw 2nd Floor 7 SF 6 \$301 Floor - Wood 2nd Floor <t< td=""><td>Classro</td><td></td><td></td><td></td><td>-</td><td></td><td>*)</td><td></td></t<>	Classro				-		*)					
Ceiling - Lay-in 1st Floor 723 SF 6 \$2,171 Doors - Transon Window 1st Floor 1 8 5 6 \$3301 Floor - Wood Doors inclu hw 1st Floor 723 SF 6 \$5001 Floor - Wood 1st Floor 723 SF 6 \$5001 Highting - Pendent/Surface 1st Floor 12 EA 6 \$5101 Marker Board 1st Floor 12 EA 6 \$52,607 Walls - Plaster/Drywall 1st Floor 12 EA 6 \$52,663 Catework 2nd Floor 28 F 6 \$22,171 Cating - Lay-in 2nd Floor 72 SF 6 \$22,171 Coling - Lay-in 2nd Floor 72 SF 6 \$22,171 Doors - Wood Doors inclu hw 2nd Floor 72 SF 6 \$22,171 Doors - Wood Doors inclu hw 2nd Floor 72 SF 6 \$22,031	0183510		1st Floor	12	IF	6	\$303					
bors - Transom Window 1st Floor 8 8 F 6 \$136 Doors - Wood Doors indu hw 1st Floor 1 EA 6 \$5097 Lighting - Pendent/Surface 1st Floor 12 EA 6 \$5097 Lighting - Pendent/Surface 1st Floor 12 EA 6 \$5197 Walks - Plaster/Drywall 1st Floor 12 EA 6 \$5107 Casework 1st Floor 12 EA 6 \$5263 Casework 2nd Floor 9 LF 6 \$227 Chalk Board 2nd Floor 72 SF 6 \$2111 Doors - Transom Window 2nd Floor 74 KF 6 \$2203 Doors - Transom Window 2nd Floor 74 KF 6 \$301 Doors - Wood Doors inclu hw 2nd Floor 78 KF 6 \$301 Floor 10007 73 SF 6 \$5097 Lighting - Pendent/Surface												
Doors - Wood Doors inclu hw 1st Floor 1st Floor 723 SF 6 \$55,097 Lighting - Pendent/Surface 1st Floor 12 EA 6 \$51,497 Marker Board 1st Floor 12 EA 6 \$52,693 Walls - Plaster/Drywall 1st Floor 12 EA 6 \$52,693 Conserved Casseroom #210 (Regular Classroom) Casework 2nd Floor 95 6 \$52,171 Chast Board 2nd Floor 24 LF 6 \$2171 Chast Board 2nd Floor 24 LF 6 \$5197 Doors - Transom Window 2nd Floor 25 6 \$5197 Doors - Transom Window 2nd Floor 25 6 \$5197 Doors - Transom Window 2nd Floor 25 6 \$5197 Doors - Wood Doors inclu hw 2nd Floor 25 6 \$5197 Lighting - Pendent/Surface 2nd Floor 26 \$5 5 Marker Board 2nd Floor 12 EA 7 \$00 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>												
Floor - Wood1st Floor723SF6\$5,097Lighting - Pendent/Surface1st Floor12EA6\$1,487Marker Board1st Floor12EA6\$2,683Classwork1st Floor12EA6\$2,683Classwork2nd Floor9E6\$227Classwork2nd Floor9E6\$227Classwork2nd Floor9E6\$22,171Chaik Board2nd Floor723SF6\$119Doors - Transom Window2nd Floor7SF6\$5,097Doors - Wood Doors inclu hw2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor16L7\$0Addrew Board2nd Floor16L7\$0Storage/ Closet2nd Floor16SF6\$2,644ClassworkQad Floor16L7\$0Storage/ Closet\$16\$2,644Classwork2nd Floor16S\$1Qad Floor16L7\$0Classwork2nd Floor16\$2,12 <td <="" colspan="4" td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td>	<td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>											
Lighting - Pendent/Surface1st Floor12EA6\$1,487Marker Board1st Floor12LF7\$0Walls - Plaster/Drywall1st Floor12KF6\$2,63Casework2nd Floor9LF6\$22,71Celling - Lay-in2nd Floor23SF6\$21,11Doors - Transom Window2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor73SF6\$301Floor - Wood Doors inclu hw2nd Floor73SF6\$5,097Lighting - Pendent/Surface2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor723SF6\$5,097Marker Board2nd Floor723SF6\$5,097Marker Board2nd Floor74SF6\$3,01Marker Board2nd Floor73SF6\$2,644Casework2nd Floor5SF6\$3,01Marker Board2nd Floor5SF6\$2,244Casework2nd Floor5SF6\$2,244Casework2nd Floor5SF6\$2,244Casework2nd Floor5SF6\$2,244Casework2nd Floor5SF6\$2,132Chalk Board2nd Floor710SF6\$2,132Cha				-								
Marker Board Walls - Plaster/Drywall1st Floor12LF7\$0Caseroom #210 (Regular Classroom)Casework Ceiling - Lay-in2nd Floor73SF6\$22,71Chak Board Doors - Transom Window2nd Floor73SF6\$22,171Doors - Vood Doors inclu hw2nd Floor74LF4\$2,203Doors - Vood Doors inclu hw2nd Floor73SF6\$301Floor - Wood2nd Floor73SF6\$5097Lighting - Pendent/Surface2nd Floor72SF6\$5097Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor12EA7\$0Storage/ Closet2nd Floor12EA7\$0Marker Board2nd Floor18SF6\$23,64Valle - Plaster/Drywall2nd Floor18SF6\$23,64Casework2nd Floor20LF6\$26,64Casework2nd Floor70SF6\$26,64Casework2nd Floor20LF6\$23,64Casework2nd Floor20LF6\$26,132Chark Board2nd Floor710SF6\$21,32Chark Board2nd Floor710SF6\$21,32Chark Board2nd Floor74LF4\$22,203Doors - Transom Window2nd Floor74LF <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>												
Walls - Plaster/Drywall 1st Floor 965 SF 6 \$2,663 Classroom #210 (Regular Classroom) 2nd Floor 9 LF 6 \$22,71 Casework 2nd Floor 2nd Floor 24 LF 6 \$2,203 Chaile Board 2nd Floor 24 LF 6 \$2,203 Doors - Transom Window 2nd Floor 7 SF 6 \$310 Doors - Wood Doors inclu hw 2nd Floor 7 SF 6 \$301 Eloor - Wood 2nd Floor 723 SF 6 \$301 Doors - Wood Doors inclu hw 2nd Floor 723 SF 6 \$301 Lighting - Pendent/Surface 2nd Floor 723 SF 6 \$301 Marker Board 2nd Floor 723 SF 6 \$301 Storage/ Closet 2nd Floor 16 LF 7 \$0 Storage/ Closet 2nd Floor 70 SF 6 \$2,644 Casework Casework SF 6 \$2,644 \$2,203 Chair												
Classroom #210 (Regular Classroom) Casework 2nd Floor 9 LF 6 \$227 Ceiling - Lay-in 2nd Floor 723 SF 6 \$22,171 Chalk Board 2nd Floor 24 LF 4 \$2,203 Doors - Transom Window 2nd Floor 7 SF 6 \$119 Doors - Transom Window 2nd Floor 7 SF 6 \$301 Doors - Wood Doors inclu hw 2nd Floor 723 SF 6 \$5,097 Lighting - Pendent/Surface 2nd Floor 12 EA 7 \$00 Marker Board 2nd Floor 16 LF 7 \$0 Storage/ Closet 2nd Floor 58 SF 6 \$36 Walls - Plaster/Drywall 2nd Floor 58 SF 6 \$2,644 Ceiling - Lay-in 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd 57 6 \$2,132 Chak Board 2nd Floor 2nd Floor 20 LF 4 \$2,2132 Ceiling - Lay-in <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>												
Casework 2nd Floor 9 LF 6 \$227 Ceiling - Lay-in 2nd Floor 723 SF 6 \$2,171 Chalk Board 2nd Floor 24 LF 4 \$2,203 Doors - Transom Window 2nd Floor 7 SF 6 \$119 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 12 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor 12 EA 7 \$0 Marker Board 2nd Floor 12 EA 7 \$0 Storage/ Closet 2nd Floor 5 SF 6 \$36 Walls - Plaster/Dnywall 2nd Floor 958 SF 6 \$2,644 2nd Floor 20 LF 6 \$505 Ceiling - Lay-in 2nd Floor 70 SF 6 \$2,132 Chalk Board 2nd Floor 74 LF		-		000	01	0	φ2,000					
Ceiling - Lay-in2nd Floor723SF6\$2,171Chalk Board2nd Floor24LF4\$2,203Doors - Transon Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor7SF6\$301Floor - Wood2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor16LF7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor5SF6\$361Walls - Plaster/Drywall2nd Floor5SF6\$362Casework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor20LF6\$2132Doors - Transon Window2nd Floor71SF6\$2132Doors - Transon Window2nd Floor74LF4\$22,033Doors - Transon Window2nd Floor7SF6\$119Doors - Transon Window2nd Floor7SF6\$119Doors - Transon Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor7SF6\$361Floor - Wood2nd Floor71SF6\$361Floor - Wood <td>Classro</td> <td>oom #210 (Regular Classroom)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Classro	oom #210 (Regular Classroom)										
Chalk Board2nd Floor2dLF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor3d Floor5F6\$2,64Walls - Plaster/Drywall2nd Floor98SF6\$2,64Casework2nd Floor2nd Floor96\$55Cailing - Lay-in2nd Floor710SF6\$2,132Chaik Board2nd Floor710SF6\$2,203Doors - Transom Window2nd Floor74SF6\$119Doors - Transom Window2nd Floor74SF6\$2,132Chaik Board2nd Floor74SF6\$2,132Doors - Transom Window2nd Floor74SF6\$119Doors - Wood Doors inclu hw2nd Floor710SF6\$301Floor - Wood2nd Floor<			2nd Floor		LF	6						
Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor16KF6\$361Walls - Plaster/Drywall2nd Floor5SF6\$361Casework2nd Floor5SF6\$2,644Casework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor20LF6\$512Chas Board2nd Floor70SF6\$119Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor7SF6\$301Floor - Wood2nd Floor7SF6\$2,132Chalk Board2nd Floor7SF6\$2,103Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor7SF6\$301Floor - Wood2nd Floor7SF6\$301Floor - Wood2nd Floor7SF6\$301Floor - Wood2nd Floor7SF <t< td=""><td></td><td>Ceiling - Lay-in</td><td>2nd Floor</td><td>723</td><td>SF</td><td>6</td><td></td><td></td></t<>		Ceiling - Lay-in	2nd Floor	723	SF	6						
Doors - Wood Doors inclu hw2nd Floor2nd Floor1EA6\$301Floor - Wood2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor5SF6\$361Walls - Plaster/Drywall2nd Floor58SF6\$2,644Casework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor2nd Floor710SF6\$2,132Chalk Board2nd Floor2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor70SF6\$119Doors - Wood Doors inclu hw2nd Floor710SF6\$301Floor - Wood2nd Floor710SF6\$119Doors - Transom Window2nd Floor710SF6\$301Floor - Wood2nd Floor710SF6\$301Floor - Wood2nd Floor710SF6\$301		Chalk Board	2nd Floor	24	LF	4						
Floor - Wood2nd Floor723SF6\$5,097Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor5SF6\$36Walls - Plaster/Drywall2nd Floor958SF6\$2,644ClassroomCasework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor710SF6\$2,132Chalk Board2nd Floor74LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Doors - Transom Window	2nd Floor	7	SF	6	\$119					
Lighting - Pendent/Surface2nd Floor12EA7\$0Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor5SF6\$36Walls - Plaster/Drywall2nd Floor958SF6\$2,644Casswork2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor2nd Floor710SF6\$2,132Chalk Board2nd Floor2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor77SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Doors - Wood Doors inclu hw	2nd Floor	1		6	\$301					
Marker Board2nd Floor16LF7\$0Storage/ Closet2nd Floor5SF6\$36Walls - Plaster/Drywall2nd Floor958SF6\$2,644Casswork2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor2nd Floor710SF6\$2,132Chalk Board2nd Floor2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor71SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Floor - Wood	2nd Floor	723	SF	6	\$5,097					
Storage/ Closet Walls - Plaster/Drywall2nd Floor5SF6\$362nd Floor958SF6\$2,644Classroom #211 (Regular Classroom)Casework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor2nd Floor710SF6\$2,132Chalk Board2nd Floor2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$3,005		Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0					
Walls - Plaster/Drywall2nd Floor958SF6\$2,644ClassroomCasework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor710SF6\$2,132Chalk Board2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Marker Board	2nd Floor	16	LF	7	\$0					
ClassroomCasework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor710SF6\$2,132Chalk Board2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Storage/ Closet	2nd Floor	5		6	\$36					
Casework2nd Floor20LF6\$505Ceiling - Lay-in2nd Floor710SF6\$2,132Chalk Board2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Walls - Plaster/Drywall	2nd Floor	958	SF	6	\$2,644					
Ceiling - Lay-in2nd Floor710SF6\$2,132Chalk Board2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005	Classro	oom #211 (Regular Classroom)										
Chalk Board2nd Floor24LF4\$2,203Doors - Transom Window2nd Floor7SF6\$119Doors - Wood Doors inclu hw2nd Floor1EA6\$301Floor - Wood2nd Floor710SF6\$5,005		Casework	2nd Floor	20	LF	6	\$505					
Doors - Transom Window 2nd Floor 7 SF 6 \$119 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 710 SF 6 \$5,005		Ceiling - Lay-in	2nd Floor	710	SF	6	\$2,132					
Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 710 SF 6 \$5,005		Chalk Board	2nd Floor	24	LF	4	\$2,203					
Floor - Wood 2nd Floor 710 SF 6 \$5,005		Doors - Transom Window	2nd Floor	7	SF	6	\$119					
		Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301					
Lighting - Pendent/Surface 2nd Floor 12 EA 7 \$0		Floor - Wood	2nd Floor	710	SF	6	\$5,005					
		Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0					



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #211 (Regular Classroom)						
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	6	\$2,785	
assro	oom #212 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	958	SF	6	\$2,644	
assro	oom #213 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	710	SF	6	\$2,132	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	710	SF	6	\$5,005	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	6	\$2,785	
assro	oom #214 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	965	SF	6	\$2,663	



-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #215 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	710	SF	6	\$2,132	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	710	SF	6	\$5,005	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	6	\$2,785	
assro	oom #216 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	965	SF	6	\$2,663	
assro	oom #217 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	710	SF	6	\$2,132	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	710	SF	6	\$5,005	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	6	\$2,785	
assro	oom #218 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	

Group	Itom Type	Location	Quantitut	l Ini+	Bonk	Cost	Comments
-	Item - Type	Location	Quantity	Unit	Ralik	COST	Comments
Classro	boom #218 (Regular Classroom)	Ond Floor	~	05	0	0440	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119 \$301	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6		
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0 \$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	965	SF	6	\$2,663	
Classro	oom #219 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	1,009	SF	6	\$2,785	
Classro	oom #220 (Regular Classroom)						
0183510	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	723	SF	6	\$2,171	
	Chalk Board	2nd Floor	16	LF	4	\$1,469	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	, 1	EA	6	\$301	
	Floor - Wood	2nd Floor	723	SF	6	\$5,097	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	¢0,007 \$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Storage/ Closet	2nd Floor	5	SF	6	\$36	
	Walls - Plaster/Drywall	2nd Floor	965	SF	6	\$2,663	
				0.	Ũ	<i><i><i>q</i>₂,000</i></i>	
Classro	oom #222 (Regular Classroom)						
	Casework	2nd Floor	5	LF	6	\$126	
	Ceiling - Lay-in	2nd Floor	517	SF	6	\$1,553	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile Quarry	2nd Floor	517	SF	6	\$1,094	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	\$0	



Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #222 (Regular Classroom)						
	Marker Board	2nd Floor	24	LF	7	\$0	
	Storage/ Closet	2nd Floor	9	SF	6	\$65	
	Walls - Plaster/Drywall	2nd Floor	840	SF	6	\$2,318	
Classro	om #224 (Regular Classroom)						
	Casework	2nd Floor	5	LF	6	\$126	
	Ceiling - Lay-in	2nd Floor	683	SF	6	\$2,051	
	Doors - Transom Window	2nd Floor	7	SF	6	\$119	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile Quarry	2nd Floor	683	SF	6	\$1,446	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	32	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	\$2,705	
Class	rooms Subtotal:					\$281,082	

Classrooms Subtotal:

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	105 Nurse Office	97	SF	6	\$336	
	Doors - Wood Doors inclu hw	105 Nurse Office	1	EA	6	\$301	
	Floor - Tile/Sheet	105 Nurse Office	97	SF	6	\$97	
	Lighting - Lay-in	105 Nurse Office	2	EA	6	\$238	
	Power Distribution	105 Nurse Office	8	EA	7	\$0	
	Walls - Plaster/Drywall	105 Nurse Office	520	SF	6	\$1,435	
	Ceiling - Plaster/Drywall	115 Main Office	441	SF	6	\$1,526	
	Doors - Transom Window	115 Main Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	115 Main Office	1	EA	6	\$301	
	Floor - Tile/Sheet	115 Main Office	441	SF	6	\$441	
	Lighting - Pendent/Surface	115 Main Office	6	EA	6	\$743	
	Power Distribution	115 Main Office	12	EA	6	\$25,499	
	Walls - Concrete Block	115 Main Office	678	SF	6	\$1,988	
	Ceiling - Plaster/Drywall	115A Principals Office	239	SF	6	\$827	
	Doors - Wood Doors inclu hw	115A Principals Office	2	EA	6	\$602	
	Floor - Tile/Sheet	115A Principals Office	239	SF	6	\$239	
	Lighting - Pendent/Surface	115A Principals Office	4	EA	6	\$496	



Pow Wal							
Wal							
		115A Principals Office	20	EA	7	\$0	
Coili	Ils - Plaster/Drywall	115A Principals Office	828	SF	6	\$2,285	
Cell	ling - Lay-in	124 Faculty Lounge	326	SF	6	\$979	
Doc	ors - Transom Window	124 Faculty Lounge	8	SF	6	\$135	
Doo	ors - Wood Doors inclu hw	124 Faculty Lounge	1	EA	6	\$301	
Floc	or - Tile/Sheet	124 Faculty Lounge	326	SF	6	\$326	
Ligh	hting - Lay-in	124 Faculty Lounge	5	EA	6	\$595	
Pow	ver Distribution	124 Faculty Lounge	8	EA	7	\$0	
Wal	Ils - Concrete Block	124 Faculty Lounge	745	SF	6	\$2,184	
Ceil	ling - Plaster/Drywall	131 Gym Office	600	SF	6	\$2,076	
Doc	ors - Wood Doors inclu hw	131 Gym Office	2	EA	6	\$602	
Floc	or - Tile/Sheet	131 Gym Office	600	SF	6	\$601	
Ligh	hting - Pendent/Surface	131 Gym Office	14	EA	6	\$1,735	
Pow	ver Distribution	131 Gym Office	8	EA	7	\$0	
Wal	ills - Plaster/Drywall	131 Gym Office	358	SF	6	\$988	
Wal	ills - Tile	131 Gym Office	415	SF	6	\$908	
Ceil	ling - Plaster/Drywall	Engineers Office	97	SF	6	\$336	
Doo	ors - Wood Doors inclu hw	Engineers Office	1	EA	6	\$301	
Floc	or - Tile/Sheet	Engineers Office	97	SF	6	\$97	
Ligh	hting - Pendent/Surface	Engineers Office	1	EA	6	\$124	
Pow	ver Distribution	Engineers Office	4	EA	7	\$0	
Wal	Ils - Concrete Block	Engineers Office	287	SF	6	\$841	
Ceil	ling - Plaster/Drywall	Room 208	360	SF	6	\$1,246	
Doc	ors - Transom Window	Room 208	7	SF	6	\$119	
Doo	ors - Wood Doors inclu hw	Room 208	1	EA	6	\$301	
Floc	or - Terrazzo	Room 208	360	SF	6	\$788	
Ligh	hting - Pendent/Surface	Room 208	6	EA	7	\$0	
Pow	ver Distribution	Room 208	16	EA	7	\$0	
Wal	Ils - Plaster/Drywall	Room 208	1,040	SF	6	\$2,870	
Ceil	ling - Plaster/Drywall	Room 227	210	SF	6	\$727	
Doo	ors - Wood Doors inclu hw	Room 227	1	EA	6	\$301	
Floc	or - Tile/Sheet	Room 227	210	SF	6	\$210	
Ligh	hting - Pendent/Surface	Room 227	4	EA	7	\$0	
-	ver Distribution	Room 227	8	EA	7	\$0	
Wal	Ils - Concrete Block	Room 227	555	SF	6	\$1,627	
Wal	ills - Plaster/Drywall	Room 227	124	SF	6	\$342	
Ceil	ling - Plaster/Drywall	Room 231	132	SF	6	\$457	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	strative Suites/Offices						
	Doors - Wood Doors inclu hw	Room 231	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 231	132	SF	6	\$132	
	Lighting - Pendent/Surface	Room 231	3	EA	6	\$372	
	Power Distribution	Room 231	6	EA	7	\$0	
	Walls - Concrete Block	Room 231	113	SF	6	\$331	
	Walls - Masonry	Room 231	71	SF	6	\$355	Brick
	Walls - Masonry	Room 231	290	SF	6	\$912	
	Ceiling - Plaster/Drywall	Room 233	423	SF	6	\$1,464	
	Doors - Wood Doors inclu hw	Room 233	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 233	423	SF	6	\$423	
	Lighting - Pendent/Surface	Room 233	5	EA	6	\$619	
	Power Distribution	Room 233	12	EA	7	\$0	
	Walls - Concrete Block	Room 233	119	SF	6	\$349	
	Walls - Masonry	Room 233	437	SF	6	\$2,187	Brick
	Walls - Masonry	Room 233	523	SF	6	\$1,645	Concrete
uditori	ium & Theater						
	Balcony Seating	100 Multipurpose Room	92	EA	6	\$16,000	
	Ceiling - Plaster/Drywall	100 Multipurpose Room	2,114	SF	6	\$17,624	
	Doors - Wood Doors inclu hw	100 Multipurpose Room	4	EA	6	\$1,204	
	Floor - Tile/Sheet	100 Multipurpose Room	2,114	SF	6	\$2,116	
	Lighting - Pendent/Surface	100 Multipurpose Room	31	EA	6	\$3,841	
	Lighting - Wall Mounted	100 Multipurpose Room	10	EA	6	\$1,239	
	Sound System	100 Multipurpose Room	1	EA	6	\$10,721	
	Stage	100 Multipurpose Room	422	SF	6	\$2,438	
	Stage Curtain	100 Multipurpose Room	8	EA	6	\$0	
	Stage Lift	100 Multipurpose Room	1	EA	6	\$6,510	
	Stage Lighting System	100 Multipurpose Room	1	EA	6	\$8,077	
	Stage-Stairs - Wood	100 Multipurpose Room	10	LF	6	\$117	
	Walls - Plaster/Drywall	100 Multipurpose Room	4,645	SF	6	\$22,119	
/mnas	sia						
	Ceiling - Lay-in	128 Gymnasium	2,541	SF	6	\$7,631	
	Doors - Wood Doors inclu hw	128 Gymnasium	2	EA	6	\$602	
	Floor - Wood	128 Gymnasium	2,541	SF	6	\$17,914	
	Lighting - Metal Halide/Sodium Vapor	128 Gymnasium	12	EA	6	\$1,605	
	Sound System	128 Gymnasium	1	EA	6	\$41,654	
	Walls - Concrete Block	128 Gymnasium	1,946	SF	6	\$5,705	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymna	sia						
	Walls - Plaster/Drywall	128 Gymnasium	2,920	SF	6	\$8,059	
Kitcher							
	Ceiling - Lay-in	122 Kitchen	789	SF	6	\$2,369	
	Doors - Transom Window	122 Kitchen	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	122 Kitchen	1	EA	6	\$301	
	Floor - Concrete	122 Kitchen	789	SF	6	\$417	
	Lighting - Lay-in	122 Kitchen	12	EA	6	\$1,428	
	Walls - Plaster/Drywall	122 Kitchen	1,130	SF	6	\$3,119	
MDF_I)F						
	AC Unit	137 MDF_IDF inside 135	1	EA	6	\$496	
	Doors - Wood Doors inclu hw	137 MDF_IDF inside 135	1	EA	6	\$301	
	Finishes	137 MDF_IDF inside 135	109	SF	6	\$778	
Mechar	nical/ Service Rooms						
	Janitor's Closet	1st Floor	28	SF	6	\$201	107 Janitor Closet
	Storage Room	1st Floor	194	SF	6	\$1,390	133, 135 Storage
	Janitor's Closet	2nd Floor	30	SF	6	\$215	207 janitor closet
	Janitor's Closet	2nd Floor	38	SF	6	\$272	Janitor closet 225
	Mechanical/ Service Rooms	2nd Floor	68	SF	6	\$487	203 Elevator Machine room
	Storage Room	2nd Floor	99	SF	6	\$709	Next to rm 231
	Storage Room	2nd Floor	86	SF	6	\$616	201A in staff restroom
	Storage Room	2nd Floor	96	SF	6	\$688	208A in rm 208
	Air Tunnel	Basement	3,901	SF	6	\$24,155	
	Boiler Room	Basement	2,450	SF	6	\$17,553	
	Coal Room	Basement	602	SF	6	\$4,313	
	Interior Stairs	Basement	16	LF	6	\$144	
	Mechanical/ Service Rooms	Basement	1,772	SF	6	\$12,695	Engine Room
	Storage Room	Basement	405	SF	6	\$2,902	
Restro	om						
	Accessories	104 Unisex Toilet	110	SF	6	\$1,015	
	Ceiling - Plaster/Drywall	104 Unisex Toilet	110	SF	6	\$381	
	Doors - Steel Doors incl hw	104 Unisex Toilet	1	EA	6	\$301	
	Floor Drain	104 Unisex Toilet	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	104 Unisex Toilet	110	SF	6	\$233	
	Lavatory	104 Unisex Toilet	1	EA	6	\$320	
	Lighting - Lay-in	104 Unisex Toilet	1	EA	6	\$119	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om de la companya de						
	Walls - Structural Glazed Tile	104 Unisex Toilet	336	SF	6	\$1,057	
	Water Closet	104 Unisex Toilet	1	EA	6	\$336	
	Accessories	105A Girls Toilet	275	SF	6	\$2,536	
	Ceiling - Plaster/Drywall	105A Girls Toilet	275	SF	6	\$952	
	Floor Drain	105A Girls Toilet	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	105A Girls Toilet	275	SF	6	\$582	
	Hand Dryer	105A Girls Toilet	3	EA	6	\$690	
	Lavatory	105A Girls Toilet	2	EA	6	\$639	
	Lighting - Lay-in	105A Girls Toilet	8	EA	6	\$952	
	Partitions	105A Girls Toilet	4	EA	6	\$1,188	
	Walls - Concrete Block	105A Girls Toilet	642	SF	6	\$1,882	
	Water Closet	105A Girls Toilet	4	EA	6	\$1,344	
	Accessories	107A Boys Toilet	265	SF	6	\$2,444	
	Ceiling - Plaster/Drywall	107A Boys Toilet	265	SF	6	\$917	
	Floor Drain	107A Boys Toilet	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	107A Boys Toilet	265	SF	6	\$561	
	Hand Dryer	107A Boys Toilet	3	EA	6	\$690	
	Lavatory	107A Boys Toilet	2	EA	6	\$639	
	Lighting - Lay-in	107A Boys Toilet	8	EA	6	\$952	
	Partitions	107A Boys Toilet	1	EA	6	\$297	
	Walls - Concrete Block	107A Boys Toilet	642	SF	6	\$1,882	
	Water Closet	107A Boys Toilet	2	EA	6	\$672	
	Accessories	124A Unisex Staff Restroom	110	SF	6	\$1,015	
	Ceiling - Plaster/Drywall	124A Unisex Staff Restroom	110	SF	6	\$381	
	Doors - Wood Doors inclu hw	124A Unisex Staff Restroom	1	EA	6	\$301	
	Floor Drain	124A Unisex Staff Restroom	1	EA	6	\$1,059	
	Floor - Tile/Sheet	124A Unisex Staff Restroom	110	SF	6	\$110	
	Hand Dryer	124A Unisex Staff Restroom	1	EA	6	\$230	
	Lavatory	124A Unisex Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	124A Unisex Staff Restroom	1	EA	6	\$124	
	Walls - Plaster/Drywall	124A Unisex Staff Restroom	406	SF	6	\$1,121	
	Water Closet	124A Unisex Staff Restroom	1	EA	6	\$336	
	Accessories	129A Girls Toilet	275	SF	6	\$2,536	
	Ceiling - Plaster/Drywall	129A Girls Toilet	275	SF	6	\$952	
	Floor Drain	129A Girls Toilet	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	129A Girls Toilet	275	SF	6	\$582	
	Hand Dryer	129A Girls Toilet	3	EA	6	\$690	
			Ũ		÷	<i>4000</i>	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Lavatory	129A Girls Toilet	2	EA	6	\$639	
	Lighting - Lay-in	129A Girls Toilet	8	EA	6	\$952	
	Partitions	129A Girls Toilet	4	EA	6	\$1,188	
	Walls - Concrete Block	129A Girls Toilet	642	SF	6	\$1,882	
	Water Closet	129A Girls Toilet	4	EA	6	\$1,344	
	Accessories	135A Boys Toilet	265	SF	6	\$2,444	
	Ceiling - Plaster/Drywall	135A Boys Toilet	265	SF	6	\$917	
	Floor Drain	135A Boys Toilet	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	135A Boys Toilet	265	SF	6	\$561	
	Hand Dryer	135A Boys Toilet	3	EA	6	\$690	
	Lavatory	135A Boys Toilet	2	EA	6	\$639	
	Lighting - Lay-in	135A Boys Toilet	8	EA	6	\$952	
	Partitions	135A Boys Toilet	1	EA	6	\$297	
	Urinals	135A Boys Toilet	2	EA	6	\$672	
	Walls - Concrete Block	135A Boys Toilet	642	SF	6	\$1,882	
	Water Closet	135A Boys Toilet	2	EA	6	\$672	
	Accessories	2nd Floor Boys Room Across from rm 208	210	SF	6	\$1,937	
	Ceiling - Plaster/Drywall	2nd Floor Boys Room Across from rm 208	210	SF	6	\$727	
	Floor Drain	2nd Floor Boys Room Across from rm 208	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Room Across from rm 208	210	SF	6	\$444	
	Hand Dryer	2nd Floor Boys Room Across from rm 208	3	EA	6	\$690	
	Lavatory	2nd Floor Boys Room Across from rm 208	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor Boys Room Across from rm 208	11	EA	7	\$0	
	Partitions	2nd Floor Boys Room Across from rm 208	2	EA	6	\$594	
	Urinals	2nd Floor Boys Room Across from rm 208	2	EA	6	\$672	
	Walls - Structural Glazed Tile	2nd Floor Boys Room Across from rm 208	700	SF	6	\$2,202	
	Water Closet	2nd Floor Boys Room Across from rm 208	2	EA	6	\$672	
	Accessories	2nd Floor Boys Room Across from rm 224	210	SF	6	\$1,937	



_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Ceiling - Plaster/Drywall	2nd Floor Boys Room Across from rm 224	210	SF	6	\$727	
	Floor Drain	2nd Floor Boys Room Across from rm 224	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Room Across from rm 224	210	SF	6	\$444	
	Hand Dryer	2nd Floor Boys Room Across from rm 224	3	EA	6	\$690	
	Lavatory	2nd Floor Boys Room Across from rm 224	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor Boys Room Across from rm 224	11	EA	7	\$0	
	Partitions	2nd Floor Boys Room Across from rm 224	2	EA	6	\$594	
	Urinals	2nd Floor Boys Room Across from rm 224	2	EA	6	\$672	
	Walls - Structural Glazed Tile	2nd Floor Boys Room Across from rm 224	700	SF	6	\$2,202	
	Water Closet	2nd Floor Boys Room Across from rm 224	2	EA	6	\$672	
	Accessories	2nd Floor Girls Room Across from rm 231	291	SF	6	\$2,684	
	Ceiling - Plaster/Drywall	2nd Floor Girls Room Across from rm 231	291	SF	6	\$1,007	
	Floor Drain	2nd Floor Girls Room Across from rm 231	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Room Across from rm 231	291	SF	6	\$616	
	Hand Dryer	2nd Floor Girls Room Across from rm 231	3	EA	6	\$690	
	Lavatory	2nd Floor Girls Room Across from rm 231	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor Girls Room Across from rm 231	12	EA	7	\$0	
	Partitions	2nd Floor Girls Room Across from rm 231	4	EA	6	\$1,188	
	Walls - Concrete Block	2nd Floor Girls Room Across from rm 231	950	SF	6	\$2,785	
	Water Closet	2nd Floor Girls Room Across from rm 231	4	EA	6	\$1,344	
	Accessories	2nd Floor Girls Room next to staff restroom	291	SF	6	\$2,684	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Ceiling - Plaster/Drywall	2nd Floor Girls Room next to staff restroom	291	SF	6	\$1,007	
	Floor Drain	2nd Floor Girls Room next to staff restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Room next to staff restroom	291	SF	6	\$616	
	Hand Dryer	2nd Floor Girls Room next to staff restroom	3	EA	6	\$690	
	Lavatory	2nd Floor Girls Room next to staff restroom	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor Girls Room next to staff restroom	12	EA	7	\$0	
	Partitions	2nd Floor Girls Room next to staff restroom	4	EA	6	\$1,188	
	Walls - Concrete Block	2nd Floor Girls Room next to staff restroom	950	SF	6	\$2,785	
	Water Closet	2nd Floor Girls Room next to staff restroom	4	EA	6	\$1,344	
	Accessories	2nd Floor Unisex Staff Restroom	110	SF	6	\$1,015	
	Ceiling - Plaster/Drywall	2nd Floor Unisex Staff Restroom	110	SF	6	\$381	
	Doors - Wood Doors inclu hw	2nd Floor Unisex Staff Restroom	1	EA	6	\$301	
	Floor Drain	2nd Floor Unisex Staff Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex Staff Restroom	110	SF	6	\$233	
	Lavatory	2nd Floor Unisex Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor Unisex Staff Restroom	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor Unisex Staff Restroom	424	SF	6	\$1,170	
	Walls - Structural Glazed Tile	2nd Floor Unisex Staff Restroom	63	SF	6	\$198	
	Water Closet	2nd Floor Unisex Staff Restroom	1	EA	6	\$336	
	Accessories	Boiler Room	22	SF	6	\$203	
	Ceiling - Plaster/Drywall	Boiler Room	22	SF	6	\$76	
	Floor - Tile/Sheet	Boiler Room	22	SF	6	\$22	
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	\$124	
	Walls - Plaster/Drywall	Boiler Room	156	SF	6	\$431	
	Water Closet	Boiler Room	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$426,677

Building: Main Category: Building Interior



Ferdinand Peck Elementary School

3826 W 58th St Chicago, IL 60629

Dri Flc Flc Lig Stu Wa	eiling - Lay-in rinking Fountains - Triple Fountain oor - Terrazzo	1st Floor	Quantity				
Dri Flc Flc Lig Stu Wa	rinking Fountains - Triple Fountain	1st Floor					
Dri Flc Flc Lig Stu Wa	rinking Fountains - Triple Fountain		5,850	SF	6	\$17,568	
Flc Flc Lig Stu Wa	o	1st Floor	2	EA	6	\$887	
Flc Lig Lig Stu Wa		1st Floor	1,000	SF	6	\$8,394	
Lig Lig Stu Wa	oor - Tile/Sheet	1st Floor	4,850	SF	6	\$2,635	
Lig Stu Wa	ghting - Lay-in	1st Floor	60	EA	7	\$0	
Stu Wa	ghting - Wall Mounted	1st Floor	4	EA	6	\$496	
Wa	udent Lockers - One Tier	1st Floor	262	EA	6	\$24,323	
	alls - Plaster/Drywall	1st Floor	7,469	SF	6	\$33,110	
Ce	alls - Structural Glazed Tile	1st Floor	180	SF	6	\$566	
00	eiling - Lay-in	2nd Floor	5,850	SF	6	\$17,568	
Dri	rinking Fountains - Triple Fountain	2nd Floor	2	EA	6	\$887	Fountains located in main corridor across from rooms 208,224
Flo	oor - Terrazzo	2nd Floor	1,000	SF	6	\$8,394	
Flo	oor - Tile/Sheet	2nd Floor	4,850	SF	6	\$2,635	
Liç	ghting - Lay-in	2nd Floor	45	EA	7	\$0	
Sta	airs - Terrazzo	2nd Floor	5	LF	6	\$46	
Sti	udent Lockers - One Tier	2nd Floor	266	EA	6	\$24,694	
W	alls - Plaster/Drywall	2nd Floor	7,931	SF	6	\$35,158	
W;	alls - Structural Glazed Tile	2nd Floor	180	SF	6	\$566	
Safety							
Ca	amera Viewing Station	Entire Building / 1st Floor	3	EA	6	\$2,048	Viewing stations are in the maintenance office, security desk at entrance by stairwell A, Principals office
Se	ecurity Cameras	Entire Building	7	EA	6	\$1,358	
	ecurity Cameras	Entire Building	12	EA	6	\$2,328	
	ecurity Cameras	Entire Building	3	EA	5	\$2,063	Old generation - Not working properly
Se	ecurity Cameras	Entire Building	2	EA	5	\$1,375	Not working properly
Stairs							
Ce	eiling - Lay-in	Stair A level 2	275	SF	6	\$826	
Flo	oor - Terrazzo	Stair A level 2	275	SF	6	\$2,308	
Ha	andrails	Stair A level 2	68	LF	6	\$589	
Liç	ghting - Lay-in	Stair A level 2	6	EA	7	\$0	
Sta	airs - Terrazzo	Stair A level 2	27	LF	6	\$251	
W	alls - Plaster/Drywall	Stair A level 2	950	SF	6	\$2,622	
Ce	eiling - Lay-in	Stair B level 2	275	SF	6	\$826	
Flo	oor - Terrazzo	Stair B level 2	275	SF	6	\$2,308	
Ha	andrails	Stair B level 2	68	LF	6	\$589	
Liç	ghting - Lay-in	Stair B level 2	6	EA	7	\$0	
Sta	airs - Terrazzo	Stair B level 2	27	LF	6	\$251	
W	alls - Plaster/Drywall	Stair B level 2	950	SF	6	\$2,622	



Category: Building Interior

-	Item - Type	Location	Quantity	Unit	Pank	Cart	Comments
roup tairs	Item - Type	Location	Quantity	Unit	Rank	COST	Comments
iali 5	Ceiling - Plaster/Drywall	Stair C level 2	54	SF	5	\$794	
	Handrails	Stair C level 2	38	LF	5 6	\$794	
	Lighting - Wall Mounted	Stair C level 2	1	EA	7	\$0 \$0	
	Stairs - Terrazzo	Stair C level 2	19	LF	6	\$176	
	Walls - Plaster/Drywall	Stair C level 2	745	SF	6	\$2,056	
	Ceiling - Lay-in	Stair D level 2	275	SF	6	\$826	
	Floor - Terrazzo	Stair D level 2	275	SF	6	\$2,308	
	Handrails	Stair D level 2	68	LF	6	\$589	
	Lighting - Lay-in	Stair D level 2	6	EA	6	\$389 \$714	
	Stairs	Stair D level 2	27	LF	6	\$0	
	Walls - Plaster/Drywall	Stair D level 2	950	SF	6	\$0 \$2,622	
		Stair E level 2	950 275	SF		\$2,622 \$1,813	
	Ceiling - Lay-in			SF SF	5		
	Floor - Terrazzo Handrails	Stair E level 2 Stair E level 2	275 68	SF LF	6 6	\$2,308 \$589	
	Lighting - Lay-in	Stair E level 2	6	EA	7	\$0 \$0	
	Stairs	Stair E level 2	27	LF	6	\$0	
	Walls - Plaster/Drywall	Stair E level 2	950	SF	6	\$2,622	
ertical	Conveyance						
	Elevator - Hydraulic Elevator	Entire Building	1	EA	6	\$19,238	
uildi	ng Interior Subtotal:					\$237,279	
otal	Building Cost				\$	2,225,135	
	-						
	ng: Annex						
-	ory: Building Exterior					-	
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntranc						•	
	Entrance Control - Audio and Video	Entrance 13-West	1	EA	6	\$702	
	Exterior Doors - Exterior Steel Door	Entrance 12-East	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Entrance 13-West	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Exit 12A-North	1	EA	5	\$1,341	Not working properly - hard to open and close
	Power Door Operator and Controls	Entrance 13-West	1	EA	6	\$0	
ounda	tion						
	Foundation - Concrete	Entire Building	604	LF	7	\$0	
PFCK		Page 23 of s	52				Assessment Date:



3826 W 58th St Chicago, IL 60629

Building: Annex

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Foundation						
Superstructure - Steel	Entire Building	16,560	SF	7	\$0	
Lighting						
Exterior Lighting - Wall Mounted	Entire Building	18	EA	6	\$5,197	
Roof System						
Chimney - Metal Flue	Roof 4	30	LF	6	\$4,744	2-flues at 15ft each
Coping - Metal	Roof 4	615	LF	6	\$19,752	
Downspouts - Exterior Downspouts	Roof 4	685	LF	6	\$22,765	
Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	17,140	SF	7	\$0	
Roof - Metal	Roof 4	17,140	SF	6	\$229,661	
Walls						
Canopy - Metal	Entire Building	70	SF	6	\$1,504	
Exterior Walls - Brick	Entire Building	4,260	SF	6	\$28,631	
Exterior Walls - Precast Panel Wall	Entire Building	1,208	SF	6	\$8,119	
Exterior Walls - Stone-Cast	Entire Building	110	SF	6	\$739	
Exterior Walls - Stone-Cut	Entire Building	110	SF	6	\$739	
Windows						
Guard - Guards perforated	Entire Building	1,850	SF	6	\$23,624	
Lintels - Steel	Entire Building	280	LF	6	\$8,128	
Windows - Louver	Entire Building	205	SF	6	\$1,530	
Windows - Sash Aluminum Double-pane	Entire Building	1,850	SF	6	\$13,810	
Building Exterior Subtotal:					\$372,909	
Duilding, Annov						
Building: Annex						
Category: Electrical System						

3 , ,						
Group Item - Type	Location	Quantity U	Jnit	Rank	Cost	Comments
Emergency System						
Automatic Transfer Switch	Electrical Room	1 E	EA	6	\$408	
Emergency A/C Power - Corridors and Stairs	Entire Building	2,694	SF	4	\$5,278	No UPS or Generator only Independent feed
Emergency A/C Power - Students Toilets	Entire Building	1,020	SF	4	\$1,998	No UPS or Generator only Independent feed
Exit Signs - Corridors and Stairs	Entire Building	7 E	EA	2	\$3,818	
Security System - CCTV	Entire Building	16,560	SF	6	\$4,973	
Security System - Intrusion Detection	Entire Building	16,560	SF	7	\$0	



Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Main Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	Emergency feed from ComEd
Main Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	7	\$0	
PA System	Entire Building	16,560	SF	5	\$11,367	Served From Main building
Power Distribution						
Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	Emergency/ fuse type
Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	\$0	
Lighting and Power Panels - Above 100 A	Electrical Room	3	EA	7	\$0	
Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	7	\$0	

Electrical System Subtotal:

Building: Annex

Category: Safty System

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
e Alarm						
Fire Alarm Panel	Entire Building / Electrical Room	1	EA	6	\$6,406	
Fire Alarm Strobe Lights	Entire Building	16,560	SF	6	\$5,920	
Fire Alarm_System	Entire Building	16,560	SF	7	\$0	
rinkler System						
Sprinkler Heads	Entire Building	16,560	SF	7	\$0	
Sprinkler Piping	Entire Building	16,560	SF	7	\$0	
Wet Sprinkler System	Entire Building	16,560	SF	7	\$0	Served from City water supply (no pump)
afty System Subtotal:					\$12,326	

\$31,062

Building: Annex

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Conditioning						
Condensing Unit- Ground Mounted - 5-10 tons	1st Floor / East	1	EA	7	\$0	Serves MDF room
Air Handling Systems						
Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less th cfm	an 6000 Mechanical Room	1	EA	6	\$3,350	Air intake served from the roof.



Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler S	ystems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	6	\$6,176	
	Chemical Pot Feeder	Boiler Room	1	EA	6	\$725	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	6	\$1,996	
	Glycol Feed System	Boiler Room / Mechanical Room	1	EA	6	\$539	
	Hot Water Pump	Boiler Room	1	EA	6	\$374	
	Hot Water Pump	Boiler Room	1	EA	6	\$374	
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	\$2,126	
	Unit Heater - Hot Water	Mechanical Room	2	EA	6	\$558	
Mechan	ical Plumbing						
	Hydronic Supply and Return - Galvanized	Entire Building	200	LF	6	\$15,464	Hot water only
Unit Ver	ntilation						
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	2	EA	4	\$45,878	Broken and close to end of life 20 years
	Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors	Entire Building	12	EA	5	\$118,569	
Ventilati	ion						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	4	EA	6	\$2,370	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
Mecha	anical System Subtotal:					\$199,909	
Buildi	ng: Annex						
Catego	ory: Plumbing System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	er						
Hot Wat	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	\$2,249	
Hot Wat		Mechanical Room	1	EA	5	\$2,249	
		Mechanical Room Entire Building	1	EA	5	\$2,249	

Sanitary Piping

Storm Piping

Vent Piping

7

7

7

SF

SF

SF

16,560

16,560

16,560

\$0

\$0

\$0

Entire Building

Entire Building

Entire Building



Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Plumbing System Subtotal:					\$2,249	
Building: Annex						
Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #301 (Regular Classroom)		•				
Casework	1st Floor	20	LF	6	\$505	
Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
Lighting - Lay-in	1st Floor	9	EA	7	\$0	
Marker Board	1st Floor	12	LF	7	\$0	
Storage/ Closet	1st Floor	10	SF	6	\$73	
Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
Classroom #302 (Regular Classroom)						
Casework	1st Floor	20	LF	6	\$505	
Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
Lighting - Lay-in	1st Floor	9	EA	7	\$0	
Marker Board	1st Floor	12	LF	7	\$0	
Storage/ Closet	1st Floor	10	SF	6	\$73	
Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
Classroom #303 (Regular Classroom)						
Casework	1st Floor	20	LF	6	\$505	
Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
Lighting - Lay-in	1st Floor	9	EA	7	\$0	
Marker Board	1st Floor	12	LF	7	\$0	
Storage/ Closet	1st Floor	10	SF	6	\$73	
Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	



iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #304 (Kindergarten)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
assro	oom #305 (Kindergarten)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	32	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
assro	oom #306 (Computer Lab)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Charging Station	1st Floor	1	EA	6	\$485	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	730	SF	6	\$2,140	
	Walls - Plaster/Drywall	1st Floor	257	SF	6	\$709	
	Wireless System	1st Floor	1	EA	6	\$372	
lassro	oom #307 (Computer Lab)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	



-		1 1	•		D - 1	•	0
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #307 (Computer Lab)						
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Charging Station	1st Floor	1	EA	6	\$485	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	730	SF	6	\$2,140	
	Walls - Plaster/Drywall	1st Floor	257	SF	6	\$709	
	Wireless System	1st Floor	1	EA	6	\$372	
issro	om #308 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
ssro	om #309 (Kindergarten)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
assro	om #310 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	



Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #310 (Regular Classroom)						
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
Classro	oom #311 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	475	SF	6	\$1,392	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
Classro	oom #312 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Lay-in	1st Floor	890	SF	6	\$2,673	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	890	SF	6	\$891	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Concrete Block	1st Floor	7,475	SF	6	\$21,913	
	Walls - Plaster/Drywall	1st Floor	595	SF	6	\$1,642	
Class	rooms Subtotal:					\$117,091	

Classrooms Subtotal:

Building: Annex

Group	Item - Type	Location	Quantity U	nit	Rank	Cost Comments
Adminis	strative Suites/Offices					
	Ceiling - Lay-in	Main Office	360 5	ŝF	6	\$1,081
	Doors - Steel Doors incl hw	Main Office	1 E	A	6	\$301
	Floor - Tile/Sheet	Main Office	360 5	ŝF	6	\$360



oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Suites/Offices						
Lighting - Lay-in	Main Office	4	EA	7	\$0	
Power Distribution	Main Office	10	EA	7	\$0	
Walls - Concrete Block	Main Office	248	SF	6	\$727	
Walls - Plaster/Drywall	Main Office	599	SF	6	\$1,653	
Ceiling - Lay-in	Teachers Resource Room	192	SF	6	\$577	
Doors - Steel Doors incl hw	Teachers Resource Room	1	EA	6	\$301	
Floor - Tile/Sheet	Teachers Resource Room	192	SF	6	\$192	
Lighting - Lay-in	Teachers Resource Room	3	EA	7	\$0	
Power Distribution	Teachers Resource Room	8	EA	7	\$0	
Walls - Concrete Block	Teachers Resource Room	429	SF	6	\$1,258	
Walls - Plaster/Drywall	Teachers Resource Room	297	SF	6	\$820	
F_IDF						
AC Unit	In electrical room	1	EA	6	\$496	
Doors - Steel Doors incl hw	In electrical room	1	EA	6	\$301	
Finishes	In electrical room	79	SF	6	\$564	
Ventilation and Cooling	In electrical room	1	EA	6	\$1,855	
chanical/ Service Rooms						
Boiler Room	1st Floor	470	SF	6	\$3,367	
Janitor's Closet	1st Floor	34	SF	6	\$244	
Mechanical/ Service Rooms	1st Floor	63	SF	6	\$451	
Mechanical/ Service Rooms	1st Floor	200	SF	6	\$1,433	Electrical room
stroom						
Accessories	Boys restroom	568	SF	6	\$5,239	
Ceiling - Plaster/Drywall	Boys restroom	568	SF	6	\$1,966	
Floor Drain	Boys restroom	2	EA	6	\$2,118	
Floor - Tile/Sheet	Boys restroom	568	SF	6	\$569	
Hand Dryer	Boys restroom	1	EA	6	\$230	
Lavatory	Boys restroom	4	EA	6	\$1,278	
Lighting - Lay-in	Boys restroom	5	EA	7	\$0	
Partitions	Boys restroom	5	EA	6	\$1,485	
Urinals	Boys restroom	8	EA	6	\$2,688	
Walls - Concrete Block	Boys restroom	1,646	SF	6	\$4,825	
Water Closet	Boys restroom	3	EA	6	\$1,008	
Accessories	Girls Restroom	568	SF	6	\$5,239	
Ceiling - Plaster/Drywall	Girls Restroom	568	SF	6	\$1,966	
-	Girls Restroom	2	EA	6	\$2,118	



\$67,846

Building: Annex

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om de la companya de						
	Floor - Tile/Sheet	Girls Restroom	568	SF	6	\$569	
	Hand Dryer	Girls Restroom	1	EA	6	\$230	
	Lavatory	Girls Restroom	4	EA	6	\$1,278	
	Lighting - Lay-in	Girls Restroom	5	EA	7	\$0	
	Partitions	Girls Restroom	11	EA	6	\$3,266	
	Walls - Concrete Block	Girls Restroom	1,646	SF	6	\$4,825	
	Water Closet	Girls Restroom	11	EA	6	\$3,696	
	Accessories	Mens Staff Restroom	44	SF	6	\$406	
	Ceiling - Plaster/Drywall	Mens Staff Restroom	44	SF	6	\$152	
	Doors - Steel Doors incl hw	Mens Staff Restroom	1	EA	6	\$301	
	Floor Drain	Mens Staff Restroom	1	EA	6	\$1,059	
	Floor - Tile/Sheet	Mens Staff Restroom	44	SF	6	\$44	
	Hand Dryer	Mens Staff Restroom	1	EA	6	\$230	
	Lavatory	Mens Staff Restroom	1	EA	6	\$320	
	Lighting - Lay-in	Mens Staff Restroom	1	EA	7	\$0	
	Walls - Concrete Block	Mens Staff Restroom	269	SF	6	\$789	
	Water Closet	Mens Staff Restroom	1	EA	6	\$336	
	Accessories	Women's staff restroom	44	SF	6	\$406	
	Ceiling - Plaster/Drywall	Women's staff restroom	44	SF	6	\$152	
	Doors - Steel Doors incl hw	Women's staff restroom	1	EA	6	\$301	
	Floor Drain	Women's staff restroom	1	EA	6	\$1,059	
	Floor - Tile/Sheet	Women's staff restroom	44	SF	6	\$44	
	Hand Dryer	Women's staff restroom	1	EA	6	\$230	
	Lavatory	Women's staff restroom	1	EA	6	\$320	
	Lighting - Lay-in	Women's staff restroom	1	EA	7	\$0	
	Walls - Concrete Block	Women's staff restroom	269	SF	6	\$789	
	Water Closet	Women's staff restroom	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

Building: Annex

Category: Building Interior

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Corridor					
Ceiling - Lay-in	1st Floor	2,220	SF	6	\$6,667
Ceiling - Plaster/Drywall	1st Floor	80	SF	6	\$495
Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204



Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	pr						
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	Across from electrical room
	Floor - Tile Ceramic/ Porcelain	1st Floor	80	SF	6	\$223	
	Floor - Tile/Sheet	1st Floor	2,220	SF	6	\$1,206	
	Lighting - Lay-in	1st Floor	22	EA	7	\$0	
	Walls - Concrete Block	1st Floor	6,992	SF	6	\$20,497	
Safety							
	Camera Viewing Station	Entire Building / 1st Floor	1	EA	6	\$683	Main office
	Security Cameras	Entire Building	2	EA	6	\$388	
	Security Cameras	Entire Building	7	EA	6	\$1,358	
Build	ing Interior Subtotal:					\$33,057	

Total Building Cost

\$836,450

Building: Modular 1

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Entranc	Intrance									
	Entrance Control - Audio and Video	Entrance 15-North	1	EA	6	\$702				
	Exterior Doors - Exterior Steel Door	Entrance 14-South	2	EA	6	\$961				
	Exterior Doors - Exterior Steel Door	Entrance 15-North	2	EA	6	\$961				
	Exterior Stairs - Steel or Aluminum	Entrance 14-South	16	LF	6	\$62				
	Exterior Stairs - Steel or Aluminum	Entrance 15-North	20	LF	6	\$77				
	Ramp Handrail - Steel_Ramp Handrail	Entrance 15-North	125	LF	6	\$1,083				
	Ramps - Steel or Aluminum	Entrance 15-North	60	LF	6	\$9,014				
	Stair Handrail - Steel_Stair Handrail	Entrance 14-South	35	LF	6	\$303				
	Stair Handrail - Steel_Stair Handrail	Entrance 15-North	15	LF	6	\$130				
Founda	tion									
	Foundation - Concrete	Entire Building	320	LF	7	\$0				
	Superstructure - Steel	Entire Building	6,000	SF	7	\$0				
Lighting]									
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	\$2,599				
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	\$427	Not working properly			



Building: Modular 1

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Roof S	loof System										
	Coping - Metal	Roof 2	320	LF	6	\$10,278					
	Downspouts - Exterior Downspouts	Roof 2	275	LF	6	\$9,139					
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2	6,000	SF	7	\$0					
	Roof - EPDM/ Synthetic Rubber	Roof 2	5,000	SF	6	\$42,328					
	Roof - EPDM/ Synthetic Rubber	Roof 2	1,000	SF	5	\$19,348	Ponding occurring at E, W sides				
Walls											
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,570	SF	6	\$14,590					
Windov	vs										
	Guard - Guards wire guard	Entire Building	540	SF	6	\$6,896					
	Windows - Sash Aluminum Double-pane	Entire Building	540	SF	6	\$4,031					
Buildi	ng Exterior Subtotal:					\$122,929					

Building: Modular 1

Category: Electrical System

Group Ite	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency	/ System						
En	mergency A/C Power - Corridors and Stairs	Entire Building	6,000	SF	6	\$1,802	Independent feed from ComEd
En	mergency Battery Packs - Corridors and Stairs	Entire Building	20	EA	6	\$4,050	
Ex	kit Signs - Corridors and Stairs	Entire Building	8	EA	4	\$4,364	No Generator or UPS , self contained battery
Main Servio	ce						
Inc	dependent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	Emergency feed from ComEd
Power Dist	ribution						
Lig	ghting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
Lig	ghting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	Emergency panel
Electrica	Il System Subtotal:	\$10,216					

Electrical System Subtotal:

Building: Modular 1

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	6,000	SF	4	\$8,151	
Fire Alarm_System		6,000	SF	6	\$2,917	fire alarm panel in main building, has sprinklers



3826 W 58th St Chicago, IL 60629

Building: Modular 1

Categ	ory: Safty System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkle	er System						
	Sprinkler Heads	Entire Building	6,000	SF	7	\$0	
	Sprinkler Piping	Entire Building	6,000	SF	7	\$0	
	Wet Sprinkler System	Entire Building	6,000	SF	7	\$0	Served from City supply
Safty	System Subtotal:					\$11,068	
Buildi	ng: Modular 1						
Categ	ory: Mechanical System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Unit Ve	ntilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	6	EA	7	\$0	
Ventilat	ion						
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	6	EA	7	\$0	
Mecha	anical System Subtotal:					\$0	
	ng: Modular 1 ory: Plumbing System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	ter						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
	Sanitary Piping	Entire Building	6,000	SF	7	\$0	
	Vent Piping	Entire Building	6,000	SF	7	\$0	
Plumb	bing System Subtotal:					\$682	
Buildi	ng: Modular 1						
Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #601 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	
PECK		Page 35 of 52					Assessment Date: 10/5/1

3826 W 58th St Chicago, IL 60629

Building: Modular 1

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassroom #601 (Regular Classroom)		/				
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Metal Panel	1st Floor	791	SF	6	\$5,904	
lassroom #602 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Metal Panel	1st Floor	791	SF	6	\$5,904	
lassroom #603 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Metal Panel	1st Floor	791	SF	6	\$5,904	
lassroom #604 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Metal Panel	1st Floor	791	SF	6	\$5,904	
lassroom #605 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
Marker Board	1st Floor	10	LF	6	\$214	
Walls - Metal Panel	1st Floor	791	SF	6	\$5,904	
lassroom #606 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	624	SF	6	\$1,874	

Category: Classrooms

roup Item	- Туре	Location	Quantity	Unit	Rank	Cost	Comments
lassroom #6	606 (Regular Classroom)						
Doors	s - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor	r - Tile/Sheet	1st Floor	624	SF	6	\$625	
Lighti	ing - Lay-in	1st Floor	12	EA	6	\$1,428	
Mark	er Board	1st Floor	10	LF	6	\$214	
Walls	s - Metal Panel	1st Floor	791	SF	6	\$5,904	
lacaroom						¢60.075	
lassroom	ns Subtotal:					\$62,075	

Classrooms Subtotal:

Building: Modular 1

Category: Rooms (Other Than Classrooms)

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
cha	nical/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	50	SF	6	\$358	Mechanical
	Storage Room	1st Floor	125	SF	6	\$896	Storage
stro	om						
	Accessories	602-1 Unisex Toilet In room 602	61	SF	6	\$563	
	Ceiling - Lay-in	602-1 Unisex Toilet In room 602	61	SF	6	\$183	
	Doors - Wood Doors inclu hw	602-1 Unisex Toilet In room 602	1	EA	6	\$301	
	Floor Drain	602-1 Unisex Toilet In room 602	1	EA	6	\$1,059	
	Floor - Tile/Sheet	602-1 Unisex Toilet In room 602	61	SF	6	\$61	
	Hand Dryer	602-1 Unisex Toilet In room 602	1	EA	6	\$230	
	Lavatory	602-1 Unisex Toilet In room 602	1	EA	6	\$320	
	Lighting - Lay-in	602-1 Unisex Toilet In room 602	1	EA	6	\$119	
	Walls - Metal Panel	602-1 Unisex Toilet In room 602	288	SF	6	\$2,150	
	Water Closet	602-1 Unisex Toilet In room 602	1	EA	6	\$336	
	Accessories	602A Boys Toilet	188	SF	6	\$1,734	
	Ceiling - Plaster/Drywall	602A Boys Toilet	188	SF	6	\$651	
	Doors - Wood Doors inclu hw	602A Boys Toilet	1	EA	6	\$301	
	Floor Drain	602A Boys Toilet	1	EA	6	\$1,059	
	Floor - Epoxy/ Painted	602A Boys Toilet	188	SF	6	\$99	
	Hand Dryer	602A Boys Toilet	1	EA	6	\$230	
	Lavatory	602A Boys Toilet	2	EA	6	\$639	
	Lighting - Pendent/Surface	602A Boys Toilet	2	EA	6	\$248	
	Partitions	602A Boys Toilet	4	EA	6	\$1,188	
	Urinals	602A Boys Toilet	3	EA	6	\$1,008	
	Walls - Metal Panel	602A Boys Toilet	752	SF	6	\$5,613	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Water Closet	602A Boys Toilet	1	EA	6	\$336	
	Accessories	604A Girls Toilet	188	SF	6	\$1,734	
	Ceiling - Plaster/Drywall	604A Girls Toilet	188	SF	6	\$651	
	Doors - Wood Doors inclu hw	604A Girls Toilet	1	EA	6	\$301	
	Floor Drain	604A Girls Toilet	1	EA	6	\$1,059	
	Floor - Epoxy/ Painted	604A Girls Toilet	188	SF	6	\$99	
	Hand Dryer	604A Girls Toilet	1	EA	6	\$230	
	Lavatory	604A Girls Toilet	2	EA	6	\$639	
	Lighting - Pendent/Surface	604A Girls Toilet	2	EA	6	\$248	
	Partitions	604A Girls Toilet	3	EA	6	\$891	
	Walls - Metal Panel	604A Girls Toilet	752	SF	6	\$5,613	
	Water Closet	604A Girls Toilet	4	EA	6	\$1,344	

Rooms (Other Than Classrooms) Subtotal:

\$32,491

Building: Modular 1

Category: Building Interior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor						
Ceiling - Lay-in	1st Floor	772	SF	6	\$2,318	
Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
Floor - Tile/Sheet	1st Floor	772	SF	6	\$420	
Lighting - Lay-in	1st Floor	11	EA	6	\$1,309	
Walls - Metal Panel	1st Floor	1,645	SF	6	\$12,279	
afety						
Security Cameras	Entire Building	1	EA	6	\$194	
uilding Interior Subtotal:					\$18,060	
otal Building Cost					\$257,521	
uilding: Modular 2-500						
ategory: Building Exterior						



Category: Building Exterior

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntranc	e						
	Exterior Doors - Exterior Steel Door	Entrance 11-South	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Entrance 9-North	2	EA	6	\$961	
	Exterior Stairs - Concrete	Entrance 11-South	2	LF	5	\$219	Cracked, chipped with missing area at vertical handrail penetration
	Exterior Stairs - Concrete	Entrance 11-South	22	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	Entrance 11-South	25	LF	6	\$217	Peeling throughout
ounda	tion						
	Foundation - Masonry	Entire Building	320	LF	7	\$0	
	Superstructure - Steel	Entire Building	6,000	SF	7	\$0	
ghting	3						
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	\$2,887	
oof Sy	rstem						
	Coping - Metal	Roof 6	320	LF	7	\$0	
	Downspouts - Exterior Downspouts	Roof 6	275	LF	6	\$9,139	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 6	6,000	SF	7	\$0	
	Roof - EPDM/ Synthetic Rubber	Roof 6	500	SF	6	\$4,233	Ponding occurring at E, W sides
	Roof - Modified Bitumen	Roof 6	5,500	SF	6	\$51,752	
alls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,570	SF	6	\$14,590	
indow	/S						
	Guard - Guards wire guard	Entire Building	540	SF	6	\$6,896	
	Windows - Sash Aluminum Double-pane	Entire Building	540	SF	6	\$4,031	
uildi	ng Exterior Subtotal:					\$95,886	

Building: Modular 2-500

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,000	SF	6	\$1,802	Independent power from ComEd
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	\$3,240	
	Exit Signs - Corridors and Stairs	Entire Building	8	EA	4	\$4,364	No Generator or UPS, self contained battery
	Security System - Intrusion Detection	Entire Building	6,000	SF	7	\$0	



Buildi	ng: Modular 2-500						
Categ	ory: Electrical System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Main Se	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	Emergency feed from ComEd
Power [Distribution						
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	\$0	Emergency panel
Electr	ical System Subtotal:					\$12,326	
Buildi	ng: Modular 2-500						
Categ	ory: Safty System						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Ala	ırm						
	Fire Alarm Strobe Lights	Entire Building	6,000	SF	4	\$8,151	fire alarm panel in main building
	Fire Alarm_System	Entire Building	6,000	SF	6	\$2,917	
Sprinkle	er System						
	Sprinkler Heads	Entire Building	6,000	SF	7	\$0	
	Sprinkler Piping	Entire Building	6,000	SF	7	\$0	
	Wet Sprinkler System	Entire Building	6,000	SF	7	\$0	Served from City supply
Safty	System Subtotal:					\$11,068	
Buildi	ng: Modular 2-500						
	ory: Mechanical System						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	ntilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	6	EA	6	\$0	

Ventilation Exhaust Fans- Roof Mounted - Less than 500 CFM Entire Building / Roof \$0 6 EA 7 Mechanical System Subtotal: \$0

Building: Modular 2-500

Category: Plumbing System

Group Item - Type

Quantity Unit Rank

Cost Comments

Location



Building: Modular 2-500

Category: Plumbing System

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Vater						
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
g						
Domestic Piping-Cold Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
Domestic Piping-Hot Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
Sanitary Piping	Entire Building	6,000	SF	7	\$0	
Vent Piping	Entire Building	6,000	SF	7	\$0	

Building: Modular 2-500

Category: Classrooms

1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	653 1 653 12 8	SF EA SF EA	6 6 6	\$1,961 \$301 \$654	
1st Floor 1st Floor 1st Floor 1st Floor	1 653 12 8	EA SF	6	\$301	
1st Floor 1st Floor 1st Floor	12 8	SF			
1st Floor 1st Floor	12 8	-	6	\$654	
1st Floor	8	EA			
			6	\$1,428	
1st Floor		LF	6	\$171	
	809	SF	6	\$6,039	
1st Floor	653	SF	6	\$1,961	
1st Floor	1	EA	6	\$301	
1st Floor	653	SF	6	\$654	
1st Floor	12	EA	6	\$1,428	
1st Floor	8	LF	6	\$171	
1st Floor	809	SF	6	\$6,039	
1st Floor	653	SF	6	\$1,961	
1st Floor	1	EA	6	\$301	
1st Floor	653	SF	6	\$654	
1st Floor	12	EA	6	\$1,428	
1st Floor	8	LF	6	\$171	
1st Floor	809	SF	6	\$6,039	
1st Floor	653	SF	6	\$1,961	
_	1st Floor 1st Floor	1st Floor 1 1st Floor 653 1st Floor 12 1st Floor 8 1st Floor 809 1st Floor 653 1st Floor 653 1st Floor 1 1st Floor 12 1st Floor 8 1st Floor 8 1st Floor 8 1st Floor 8 1st Floor 809	1st Floor1EA1st Floor653SF1st Floor12EA1st Floor8LF1st Floor809SF1st Floor653SF1st Floor1EA1st Floor1EA1st Floor1EA1st Floor12EA1st Floor12EA1st Floor809SF	1st Floor 1 EA 6 1st Floor 653 SF 6 1st Floor 12 EA 6 1st Floor 8 LF 6 1st Floor 809 SF 6 1st Floor 653 SF 6 1st Floor 653 SF 6 1st Floor 1 EA 6 1st Floor 8 SF 6 1st Floor 8 LF 6 1st Floor 8 LF 6 1st Floor 809 SF 6	1st Floor 1 EA 6 \$301 1st Floor 653 SF 6 \$654 1st Floor 12 EA 6 \$1,428 1st Floor 8 LF 6 \$171 1st Floor 809 SF 6 \$6,039 Ist Floor 1st Floor 653 SF 6 \$1,961 1st Floor 1 EA 6 \$301 1st Floor 12 EA 6 \$1,428 1st Floor 12 EA 6 \$1,428 1st Floor 8 LF 6 \$1,428 1st Floor 809 SF 6 \$6,039

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroo	om #504 (Regular Classroom)						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	653	SF	6	\$3,418	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Marker Board	1st Floor	8	LF	6	\$171	
	Walls - Metal Panel	1st Floor	809	SF	6	\$6,039	
Classroo	om #505 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	653	SF	6	\$1,961	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Floor - Tile/Sheet	1st Floor	653	SF	6	\$654	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Marker Board	1st Floor	8	LF	6	\$171	
	Walls - Metal Panel	1st Floor	809	SF	6	\$6,039	
Classroo	om #506 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	653	SF	6	\$1,961	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	653	SF	6	\$4,604	
	Lighting - Lay-in	1st Floor	12	EA	6	\$1,428	
	Marker Board	1st Floor	8	LF	6	\$171	
	Walls - Metal Panel	1st Floor	809	SF	6	\$6,039	
0	anna Subtatali					¢70.627	

Classrooms Subtotal:

\$70,637

Building: Modular 2-500

Category: Rooms (Other Than Classrooms)

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
chanical/ Service Rooms								
	Mechanical/ Service Rooms	1st Floor	50	SF	6	\$358	Mechanical room	
	Storage Room	1st Floor	125	SF	6	\$896	Storage	
troor	n							
	Accessories	503A Boys Toilet	142	SF	6	\$1,310		
	Ceiling - Lay-in	503A Boys Toilet	142	SF	6	\$426		
	Doors - Wood Doors inclu hw	503A Boys Toilet	1	EA	6	\$301		
	Floor Drain	503A Boys Toilet	1	EA	6	\$1,059		
	Floor - Epoxy/ Painted	503A Boys Toilet	142	SF	6	\$75		
	Hand Dryer	503A Boys Toilet	1	EA	6	\$230		



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Lavatory	503A Boys Toilet	2	EA	6	\$639	
	Lighting - Lay-in	503A Boys Toilet	1	EA	6	\$119	
	Partitions	503A Boys Toilet	4	EA	6	\$1,188	
	Urinals	503A Boys Toilet	2	EA	6	\$672	
	Walls - Metal Panel	503A Boys Toilet	403	SF	6	\$3,008	
	Water Closet	503A Boys Toilet	2	EA	6	\$672	
	Accessories	504A Girls Toilet	177	SF	6	\$1,633	
	Ceiling - Lay-in	504A Girls Toilet	177	SF	6	\$532	
	Doors - Wood Doors inclu hw	504A Girls Toilet	1	EA	6	\$301	
	Floor Drain	504A Girls Toilet	1	EA	6	\$1,059	
	Floor - Epoxy/ Painted	504A Girls Toilet	177	SF	6	\$94	
	Hand Dryer	504A Girls Toilet	1	EA	6	\$230	
	Lavatory	504A Girls Toilet	2	EA	6	\$639	
	Lighting - Lay-in	504A Girls Toilet	2	EA	6	\$238	
	Partitions	504A Girls Toilet	3	EA	6	\$891	
	Walls - Metal Panel	504A Girls Toilet	470	SF	6	\$3,508	
	Water Closet	504A Girls Toilet	4	EA	6	\$1,344	

Rooms (Other Than Classrooms) Subtotal:

Building: Modular 2-500

Category: Building Interior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor						
Ceiling - Lay-in	1st Floor	772	SF	6	\$2,318	
Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
Floor - Tile/Sheet	1st Floor	772	SF	6	\$420	
Lighting - Lay-in	1st Floor	11	EA	6	\$1,309	
Walls - Metal Panel	1st Floor	1,645	SF	6	\$12,279	
uilding Interior Subtotal:					\$17,866	
otal Building Cost					\$229,887	

Building: Modular 3-400

\$21,421



Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance	e						
	Exterior Doors - Exterior Steel Door	Entrance 10-South	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Entrance 8-North	2	EA	6	\$961	
	Exterior Stairs - Concrete	Entrance 10-South	24	LF	6	\$1,962	
	Stair Handrail - Steel_Stair Handrail	Entrance 10-South	25	LF	6	\$217	Peeling throughout
Foundat	ion						
	Foundation - Masonry	Entire Building	320	LF	7	\$0	
	Superstructure - Steel	Entire Building	6,000	SF	7	\$0	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	\$2,887	
Roof Sy	stem						
	Coping - Metal	Roof 5	320	LF	6	\$10,278	
	Downspouts - Exterior Downspouts	Roof 5	275	LF	6	\$9,139	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 5	6,000	SF	7	\$0	
	Roof - EPDM/ Synthetic Rubber	Roof 5	500	SF	6	\$6,299	Ponding occurring at E, W sides
	Roof - EPDM/ Synthetic Rubber	Roof 5	5,500	SF	6	\$46,561	
Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,570	SF	6	\$14,590	
Window	s						
	Guard - Guards perforated	Entire Building	540	SF	6	\$6,896	
	Windows - Sash Aluminum Double-pane	Entire Building	540	SF	6	\$4,031	
Buildir	ng Exterior Subtotal:					\$104,782	

Building: Modular 3-400

Category: Electrical System

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nergency System						
Emergency A/C Power - Corridors and Stairs	Entire Building	6,000	SF	6	\$1,802	Independent power feed from ComEd
Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	\$3,240	
Exit Signs - Corridors and Stairs	Entire Building	8	EA	4	\$4,364	No Generator or UPS, self contained battery
Security System - Intrusion Detection	Entire Building	6,000	SF	7	\$0	
ain Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	7	\$0	Feed from ComEd

Category: Electrical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution						
Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	Emergency panel
Lighting and Power Panels - Above 100 A	Entire Building / Electrical Room	1	EA	7	\$0	
Electrical System Subtotal:					\$9,406	
Building: Modular 3-400						
Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	6,000	SF	4	\$8,151	
Fire Alarm_System	Entire Building	6,000	SF	6	\$2,917	fire alarm panel in main building
Sprinkler System						
Sprinkler Heads	Entire Building	6,000	SF	7	\$0	
Sprinkler Piping	Entire Building	6,000	SF	7	\$0	
Wet Sprinkler System	Entire Building	6,000	SF	7	\$0	Served from City supply
Safty System Subtotal: Building: Modular 3-400					\$11,068	
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Unit Ventilation						
Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	6	EA	6	\$0	
Ventilation						
Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	6	EA	7	\$0	
Mechanical System Subtotal:					\$0	
Building: Modular 3-400						
Category: Plumbing System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Water						
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	



Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	6,000	SF	7	\$0	
	Sanitary Piping	Entire Building	6,000	SF	7	\$0	
	Vent Piping	Entire Building	6,000	SF	7	\$0	
Plumb	ing System Subtotal:					\$682	

Building: Modular 3-400

Category: Classrooms

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssro	om #401 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
ssro	om #402 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
ssro	om #403 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
	Lighting - Chandelier, Incandescent	1st Floor	1	EA	4	\$1,057	Incandescent fixture in closet
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	10	LF	6	\$214	
	Storage/ Closet	1st Floor	50	SF	6	\$363	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
ssro	om #404 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	

Category: Classrooms

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroom #404 (Regular Classroom)						
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
Lighting - Chandelier, Incandescent	1st Floor	1	EA	4	\$1,057	Incandescent fixture in closet
Lighting - Lay-in	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	10	LF	7	\$0	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
sroom #405 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
Lighting - Chandelier, Incandescent	1st Floor	1	EA	6	\$478	Incandescent fixture in closet
Lighting - Lay-in	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	10	LF	7	\$0	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
sroom #406 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	650	SF	6	\$1,952	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	650	SF	6	\$651	
Lighting - Chandelier, Incandescent	1st Floor	1	EA	4	\$1,057	Incandescent fixture in closet
Lighting - Lay-in	1st Floor	12	EA	7	\$0	
Marker Board	1st Floor	10	LF	7	\$0	
Storage/ Closet	1st Floor	50	SF	6	\$363	
Walls - Vinyl Coated Gypsum Panel	1st Floor	750	SF	6	\$2,070	
ssrooms Subtotal:					\$35,153	

Building: Modular 3-400

Category: Rooms (Other Than Classrooms)

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Mechanical/ Service Rooms			
Mechanical/ Service Rooms	1st Floor	52 SF 6	\$373 In between rooms 404,406. Accessible through either room



Category: Rooms (Other Than Classrooms)

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
om						
Accessories	Boys restroom	135	SF	6	\$1,245	
Ceiling - Plaster/Drywall	Boys restroom	135	SF	6	\$467	
Doors - Wood Doors inclu hw	Boys restroom	1	EA	6	\$301	
Floor Drain	Boys restroom	1	EA	6	\$1,059	
Floor - Tile/Sheet	Boys restroom	135	SF	6	\$135	
Hand Dryer	Boys restroom	1	EA	6	\$230	
Lavatory	Boys restroom	2	EA	6	\$639	
Lighting - Pendent/Surface	Boys restroom	1	EA	7	\$0	
Partitions	Boys restroom	4	EA	6	\$1,188	
Urinals	Boys restroom	2	EA	6	\$672	
Walls - Vinyl Coated Gypsum Panel	Boys restroom	403	SF	6	\$1,112	
Water Closet	Boys restroom	2	EA	6	\$672	
Accessories	Girls restroom	178	SF	6	\$1,642	
Ceiling - Plaster/Drywall	Girls restroom	178	SF	6	\$616	
Doors - Wood Doors inclu hw	Girls restroom	1	EA	6	\$301	
Floor Drain	Girls restroom	1	EA	6	\$1,059	
Floor - Tile/Sheet	Girls restroom	178	SF	6	\$178	
Hand Dryer	Girls restroom	1	EA	6	\$230	
Lavatory	Girls restroom	2	EA	6	\$639	
Lighting - Lay-in	Girls restroom	1	EA	7	\$0	
Partitions	Girls restroom	3	EA	6	\$891	
Walls - Vinyl Coated Gypsum Panel	Girls restroom	445	SF	6	\$1,228	
Water Closet	Girls restroom	4	EA	6	\$1,344	

Rooms (Other Than Classrooms) Subtotal:

\$16,221

Building: Modular 3-400

Category: Building Interior

ltem - Type	Location	Quantity	Unit	Rank	Cost	Comments
lor						
Ceiling - Lay-in	1st Floor	911	SF	6	\$2,736	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	Next to room 403
Floor - Tile/Sheet	1st Floor	911	SF	6	\$495	
Lighting - Lay-in	1st Floor	11	EA	7	\$0	
Walls - Vinyl Coated Gypsum Panel	1st Floor	1,600	SF	6	\$4,416	
Walls - Vinyl Coated Gypsum Panel	1st Floor	20	SF	5	\$152	Damaged walls, holes, peeling vinyl coating



Category: Building Interior			
Group Item - Type	Location	Quantity Unit Rank Cost Comments	
Building Interior Subtotal:		\$8,134	
Total Building Cost		\$185,447	

SITE

Cal		-		c:	40
Cat	rea	orv	11	51	Te.

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dr	ainage						
	Civil/ Drainage - Catch Basin	Entire Site	15	EA	6	\$16,408	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	\$5,971	
Fencing	3						
	Fencing - Chain Link	Entire Site	483	LF	6	\$9,069	
	Fencing - Guard Rail	Entire Site	40	LF	6	\$462	
	Fencing - New Standard Ornamental	Entire Site	1,710	LF	6	\$54,555	
Landsc	ape						
	Benches	Entire Site	8	EA	6	\$3,440	At west garden/sitting area
	Landscape - Grass	Entire Site	5,800	SF	6	\$4,811	
	Landscape - Hardscape- Asphalt	Entire Site	1,000	SF	6	\$2,417	North of modular 1 - Cracked, chipped areas with gaps throughout / Ponding occurring in between annex and modulars 2, 3
	Landscape - Hardscape- Asphalt	Entire Site	19,200	SF	6	\$46,401	
	Landscape - Hardscape- Concrete	Entire Site	2,000	SF	6	\$10,325	
	Parkway trees	Entire Site	41	EA	6	\$27,062	
	Planting Beds/ Area	Entire Site	11,050	SF	6	\$18,172	
	Play Area - Asphalt/ Hardscape	Entire Site	23,545	SF	6	\$56,901	
	Trash Receptacles	Entire Site	1	EA	6	\$312	
Parking	Lot						
	Concrete Curbs	Entire Site	215	LF	6	\$2,761	
	Surface - Asphalt	Entire Site	22,270	SF	6	\$53,820	
	Surface - Asphalt	Entire Site	1,000	SF	5	\$5,906	Several areas cracked, sinking with potholes throughout
	Trash Enclosure - Chain Links	Entire Site	1,190	SF	6	\$20,880	
	Trash Enclosure - Chain Links	Entire Site	200	SF	5	\$6,335	SW corner - Area of concrete slab cracked, missing with vegetation and gravel
	Vehicular Screening	Entire Site	255	LF	6	\$20,078	Around trash enclosure

SITE

Category: Site

iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
idewal	ks						
	Sidewalks - Internal Walks	Entire Site	652	LF	6	\$7,832	
	Sidewalks - Internal Walks	Entire Site	20	LF	6	\$315	Exit 7-South - Areas cracked, chipped, spalling
	Sidewalks - Perimeter Sidewalks	Entire Site	17,202	SF	6	\$34,192	
ignage	•						
	Flag Pole - Building Mounted Flag Pole	Entire Site / South Façade	1	EA	6	\$828	
	Flag Pole - Flag Pole	Entire Site	1	EA	6	\$1,657	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	\$0	
ite S	ubtotal:					\$410,907	

Total Site Cost

Campus Total ² ³

\$4,145,347

\$410.907

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main			-	+		1						1		4
Regular Classroom	Regular Classroom	1st Floor	110	110	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Kindergarten	1st Floor	114	114	740	1	6	18	140	70	50	Ν	Y	Ν
Regular Classroom	Kindergarten	1st Floor	116	116	890	1	6	18	175	88	50	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	117	117	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	118	118	723	1	6	18	175	88	50	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	119	119	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	120	120	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	121	121	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	1st Floor	123	123	723	1	6	18	175	88	50	Ν	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	723	1	6	18	165	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	211	211	710	1	6	18	132	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	212	212	723	1	6	18	165	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	213	213	710	1	6	18	132	10	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	214	214	723	1	6	18	165	10	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	215	215	710	1	6	18	132	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	216	216	723	1	6	18	165	10	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	217	217	710	1	6	18	132	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	218	218	723	1	6	18	165	10	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	219	219	723	1	6	18	132	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	220	220	723	1	6	18	165	10	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	222	222	517	1	6	14	140	8	50	Y	Y	Ν
Regular Classroom	Regular Classroom	2nd Floor	224	224	683	1	6	18	8	8	50	Y	Y	Ν
Special Education	Office	1st Floor	108	108	470	1	6	12	70	35	50	Ν	Y	Y
Annex														
Computer Lab	Regular Classroom	1st Floor	306	306	890	1	4	16	150	75	50	Ν	Y	Ν
Computer Lab	Computer Lab	1st Floor	307	307	890	1	40	40	120	48	50	N	Y	Ν
Kindergarten	Regular Classroom	1st Floor	304	304	890	1	4	16	120	48	50	Ν	Y	Ν
Kindergarten	Regular Classroom	1st Floor	305	305	890	1	4	16	120	48	50	Ν	Y	Ν
Kindergarten	Kindergarten	1st Floor	309	309	890	1	6	16	120	48	50	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	301	301	890	0	6	16	120	48	40	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	302	302	890	1	4	16	120	48	50	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	303	303	890	1	4	16	120	48	50	N	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	308	308	890	1	2	16	120	48	50	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	310	310	890	1	6	16	120	48	50	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	311	311	890	1	6	16	120	48	50	Ν	Y	Ν

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Annex			+	+	•	•							1	+
Regular Classroom	Regular Classroom	1st Floor	312	312	890	1	6	16	120	48	50	Ν	Y	Ν
Modular 1														
Regular Classroom	Regular Classroom	1st Floor	601	601	624	1	2	8	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	602	602	624	1	2	8	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	603	603	624	1	2	8	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	604	604	624	1	2	8	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	605	605	624	1	2	8	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	606	606	624	1	2	8	60	24	40	Ν	Y	Ν
Modular 2-500														
Regular Classroom	Regular Classroom	1st Floor	501	501	653	1	2	8	60	24	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	502	502	653	1	2	8	60	24	40	Ν	N	Ν
Regular Classroom	Regular Classroom	1st Floor	503	503	653	1	2	16	60	24	40	Ν	N	Ν
Regular Classroom	Regular Classroom	1st Floor	504	504	653	1	2	16	60	24	40	Ν	N	Ν
Regular Classroom	Regular Classroom	1st Floor	505	505	653	1	2	16	60	24	40	Ν	N	Ν
Regular Classroom	Regular Classroom	1st Floor	506	506	653	1	2	16	60	24	40	Ν	Ν	Ν
Modular 3-400														
Regular Classroom	Regular Classroom	1st Floor	401	401	650	0	0	10	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	402	402	650	0	0	10	60	24	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	403	403	650	0	0	12	60	24	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	404	404	650	0	0	10	60	24	40	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	405	405	650	0	0	10	60	24	40	Ν	Y	N
Regular Classroom	Regular Classroom	1st Floor	406	406	650	0	0	10	60	24	40	Ν	Y	Ν