

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	2009	3	127,162	\$3,259,123
SITE				\$356,412
Campus Total			127,162	\$3,615,535

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entranc	e						
	Entrance Control - Audio and Video	Door 1 - Southeast Main Entrance	2	EA	6	\$1,403	
	Entrance Control - Audio and Video	Door 2 - West	1	EA	6	\$702	
	Entrance Control - Audio and Video	Door 9 - North	1	EA	6	\$702	
	Exterior Doors - Exterior Steel Door	Door 4 - North	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 5 - West	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	Door 6 - West	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Door 8 - North	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Door 9 - North	2	EA	6	\$961	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 7 - Northwest	1	EA	6	\$1,433	
	Exterior Doors - Store Front	Door 1 - Southeast Main Entrance	5	EA	6	\$2,730	
	Exterior Doors - Store Front	Door 10 - East north	2	EA	6	\$1,092	
	Exterior Doors - Store Front	Door 11 - East south	2	EA	6	\$1,092	
	Exterior Doors - Store Front	Door 2 - West	2	EA	6	\$1,092	
	Exterior Doors - Store Front	Door 3 - North	4	EA	6	\$2,184	
	Exterior Doors - Transom Lite	Door 2 - West	2	EA	6	\$627	
	Exterior Doors - Transom Lite	Door 3 - North	2	EA	6	\$627	
	Exterior Stairs - Concrete	Door 1 - Southeast Main Entrance	120	LF	6	\$9,812	
	Power Door Operator and Controls	Door 1 - Southeast Main Entrance	2	EA	6	\$0	
	Power Door Operator and Controls	Door 2 - West	1	EA	6	\$0	
	Power Door Operator and Controls	Door 3 - North	1	EA	6	\$0	
	Stair Handrail - Steel_Stair Handrail	Door 1 - Southeast Main Entrance	36	LF	6	\$312	



Build	ing: Main						
Cateo	gory: Building Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
Founda	ation						
	Foundation - Concrete	Entire Building	1,447	LF	7	\$0	
	Superstructure - Steel	Entire Building	127,162	SF	7	\$0	
Lightin	ng						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building / Roof	15	EA	6	\$8,048	
	Exterior Lighting - Wall Mounted	Entire Building	24	EA	6	\$6,930	
Roof S	vstem						
	Chimney - Metal Flue	Roof 1	23	LF	7	\$0	
	Coping - Metal	Roof 1	1,050	LF	6	\$33,724	
	Coping - Metal	Roof 2	127	LF	6	\$4,079	
	Coping - Metal	Roof 3	216	LF	6	\$6,937	
	Coping - Metal	Roof 4	75	LF	6	\$2,409	
	Coping - Metal	Roof 5	156	LF	6	\$5,010	
	Coping - Metal	Roof 6	170	LF	6	\$5,460	
	Downspouts - Interior Downspouts	Roof 1	1,300	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 2	116	LF	6	\$3,855	
	Downspouts - Interior Downspouts	Roof 3	354	LF	6	\$11,765	
	Downspouts - Interior Downspouts	Roof 4	60	LF	6	\$1,994	
	Downspouts - Interior Downspouts	Roof 5	256	LF	6	\$8,508	
	Downspouts - Interior Downspouts	Roof 6	192	LF	6	\$6,381	
	Parapet - 16" - 30" Height	Roof 1	30	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 3	216	LF	6	\$8,630	
	Parapet - 16" - 30" Height	Roof 4	75	LF	6	\$2,997	
	Parapet - Parapet < 16" Height	Roof 1	40	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 2	127	LF	6	\$2,706	
	Parapet - Parapet > 30"	Roof 1	980	LF	7	\$0	
	Parapet - Parapet > 30"	Roof 5	156	LF	6	\$9,972	
	Parapet - Parapet > 30"	Roof 6	170	LF	6	\$10,867	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	30,404	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2	1,013	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3	2,783	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	687	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 5	5,746	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 6	2,472	SF	7	\$0	
	Roof - PVC Membrane	Roof 1	30,404	SF	6	\$251,301	Partial green roof
	Roof - PVC Membrane	Roof 2	1,013	SF	6	\$8,373	



Category: Building Exterior

Group It	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof Syst	em						
R	Roof - PVC Membrane	Roof 3	2,783	SF	6	\$23,003	
R	Roof - PVC Membrane	Roof 4	687	SF	6	\$5,678	
R	Roof - PVC Membrane	Roof 5	5,746	SF	6	\$47,493	Green roof
R	Roof - PVC Membrane	Roof 6	2,472	SF	6	\$20,432	Partial green roof
Walls							
E	Exterior Walls - Brick	Entire Building	53,243	SF	6	\$357,846	
E	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,237	SF	6	\$8,066	
E	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	5,962	SF	6	\$33,847	
Vindows							
С	Curtain wall - Glazed Double Pane	Entire Building / Main Entrance	2,561	SF	6	\$28,712	
G	Guard - Guards perforated	Entire Building / 1st Floor	2,156	SF	6	\$27,532	
G	Guard - Guards wire guard	Entire Building	293	SF	6	\$3,742	
L	intels - Steel	Entire Building	1,185	LF	6	\$34,399	
V	Vindows - Sash Aluminum Double-pane	Entire Building	3,353	SF	6	\$25,029	
Building	g Exterior Subtotal:				\$	1,043,376	

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Emerge	nergency System									
	Automatic Transfer Switch	ATS Room, Elevator Machine Room	2	EA	6	\$816	ATS Room			
	Automatic Transfer Switch	ATS Room, Elevator Machine Room	1	EA	6	\$408	Elevator Machine Room.			
	Emergency A/C Power - Corridors and Stairs	Entire Building	23,372	SF	6	\$7,019				
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	5,388	SF	6	\$2,003				
	Emergency A/C Power - Multipurpose Room	Entire Building / 1st Floor	5,860	SF	6	\$2,179				
	Emergency A/C Power - Students Toilets	Entire Building	3,846	SF	6	\$1,430				
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	7	\$0	ATS Room, Generator Room, Engineer's office, Electrical Room.			
	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	2	EA	7	\$0	Located at the stage.			
	Emergency Generator- Indoor- Natural Gas - 101 - 150 KW	Generator Room	1	EA	7	\$0	Generator Room			
	Exit Signs - Corridors and Stairs	Entire Building	37	EA	7	\$0				
	Exit Signs - Lunchroom	Entire Building / 1st Floor	5	EA	7	\$0				
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	4	EA	7	\$0				
	Security System - CCTV	Entire Building	127,162	SF	6	\$38,187	1 camera is not working. See Interior tab			
	Security System - Intrusion Detection	Entire Building	127,162	SF	6	\$32,731				



Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	UPS - Less than 30 KW	MDF Room	1	EA	6	\$7,886	
Main Se	rvice						
	Independent Electrical Service for emergency power	Pump Room	1	EA	7	\$0	Secondary service for the fire pump.
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	7	\$0	
	PA System	Entire Building	127,162	SF	6	\$41,824	
Power D	Distribution						
	Lighting and Power Panels - 100 A	Electrical Room / 2nd Floor	1	EA	7	\$0	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	\$299	Fuses, emergency power.
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical Room	13	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Electrical Room	8	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	3	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	7	\$0	
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	7	\$0	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	\$0	ATS Room.
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	\$0	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	\$0	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	6	\$1,265	

Electrical System Subtotal:

Category: Safty System

Building: Main

\$136,047

Group Item - Type Location Quantity Unit Rank **Cost Comments** Fire Alarm Electrical Room Fire Alarm Panel 1 EA 6 \$6,406 Fire Alarm Strobe Lights Electrical Room / Entire Building 127,162 SF 6 \$45,460 Fire Alarm_System Electrical Room / Entire Building SF 6 \$61,826 127.162 Fire Pump Controller Electrical Room 1 EA 7 \$0 Pump Room Pump Room Assembly Fire Pump - 25-50 hp Pump Room ΕA 7 \$0 Pump Room 1 Jockey Pump Pump Room 1 EA 7 \$0 Pump Room



Item - Type	Location	Quantity l	Jnit	Rank	Cost Comments			
inkler System								
Sprinkler Heads	Entire Building	127,162	SF	7	\$0			
Sprinkler Piping	Entire Building	127,162	SF	7	\$0			
Wet Sprinkler System	Entire Building	127,162	SF	7	\$0			

Safty System Subtotal:

\$113,692

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chemical Pot Feeder	Lower Roof / Boiler Room	1	EA	6	\$725	
	Chiller-Air Cooled-Scroll Type-Roof Mounted - 151 - 200 tons	Lower Roof	2	EA	6	\$8,628	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	\$3,334	Serves the MDF Room.
	Pipes - Chilled Water Pipe- Galvanized	Lower Roof / Mechanical Room	200	LF	6	\$378	
Air Han	dling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	\$3,350	Serves the 3rd floor classrooms and offices.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	\$3,350	Serves the 2nd floor classrooms and offices.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	\$3,350	Serves the 1st floor offices
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	6	\$3,350	Serves the gym.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	6	\$3,350	Serves the lunchroom, kitchen and engineer's office.
	Air Intake	Mechanical Room / West Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / West Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / West Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / West Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / West Façade	1	EA	6	\$5,765	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	\$1,857	Serves AHU-1.
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	\$1,857	Serves AHU-2.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	\$2,433	Serves AHU-4.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	\$2,433	Serves AHU-5.
	VAV Box	Mechanical Room / 1st Floor	29	EA	6	\$8,096	No reheat coils.
	VAV Box	Mechanical Room / 1st Floor	4	EA	6	\$1,117	No reheat coils.
	VAV Box	Mechanical Room / 2nd Floor	24	EA	6	\$6,700	No reheat coils.
	VAV Box	Mechanical Room / 3rd Floor	22	EA	6	\$6,142	No reheat coils.



3510 W 55th St Chicago, IL 60632

Building: Main

Category: Mechanical System

iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ir Han	dling Systems						
oiler S	Systems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	3	EA	6	\$9,263	
	Chemical Pot Feeder	Boiler Room	1	EA	6	\$725	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	3	EA	6	\$2,994	
	Glycol Feed System	Boiler Room	1	EA	6	\$539	Shared with chilled water system.
leating	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EA	6	\$4,961	
	Radiator Panels - Hot Water	Entire Building	201	EA	6	\$55,839	4' modular panels.
	Unit Heater - Electric	Entire Building / Electrical Room	4	EA	6	\$1,111	Unit mounted thermostats.
	Unit Heater - Hot Water	Entire Building	10	EA	6	\$2,792	Unit mounted thermostats.
lechan	nical Plumbing						
	Chilled Water Pump - 21 - 50 HP	Boiler Room	2	EA	6	\$2,485	
	Hot Water Pump - 21 - 50 HP	Boiler Room	2	EA	6	\$2,485	
	Hydronic Supply and Return - Copper	Entire Building	1,000	LF	7	\$0	
	Hydronic Supply and Return - Galvanized	Entire Building	200	LF	7	\$0	
emper	ature Control						
	DDC System	Entire Building	127,162	SF	6	\$72,737	
	Electric Thermostat	Entire Building / 2nd Floor	2	EA	6	\$0	MDF Room split system and generator room general exhaust fan.
	Thermostats - DDC	Entire Building	80	EA	6	\$0	
entilat	ion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / Mechanical Room	1	EA	7	\$0	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Electrical Room	1	EA	7	\$0	Generator room.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	5	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	3	EA	7	\$0	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	1	EA	7	\$0	
	Type II Exhaust Hood- Warming Kitchen	Entire Building / 1st Floor	1	EA	7	\$0	
lecha	anical System Subtotal:					\$245,200	
	-						
Buildi	ng: Main						
ateg	ory: Plumbing System						
. –	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments



Category: Plumbing System

Jatego							
iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Wat	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	\$620	
iping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Cold Water Risers	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	127,162	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	127,162	SF	7	\$0	
	Sanitary Piping	Entire Building	127,162	SF	7	\$0	
	Storm Piping	Entire Building	127,162	SF	7	\$0	
	Vent Piping	Entire Building	127,162	SF	6	\$85,466	
umps							
umps	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	\$1,977	Pump Room.
umps	Pumps - Domestic Booster Pump-Duplex Pumps - Sump-Simplex	Entire Building Entire Building / 1st Floor	1	EA EA	6 6	\$1,977 \$745	Pump Room. Elevator sump pump.
-		-	-				
Plumb	Pumps - Sump-Simplex	-	-			\$745	
Plumb Buildir	Pumps - Sump-Simplex ing System Subtotal:	-	-			\$745	
Plumb Buildir Catego	Pumps - Sump-Simplex sing System Subtotal: ng: Main	-	-	EA	6	\$745 \$88,807	
Buildii Catego Group	Pumps - Sump-Simplex sing System Subtotal: ng: Main ory: Classrooms	Entire Building / 1st Floor	1	EA	6	\$745 \$88,807	Elevator sump pump.
Plumb Buildir Catego Froup	Pumps - Sump-Simplex sing System Subtotal: ng: Main ory: Classrooms Item - Type	Entire Building / 1st Floor	1	EA	6	\$745 \$88,807	Elevator sump pump.
Plumb Buildir Catego Froup	Pumps - Sump-Simplex sing System Subtotal: ng: Main ory: Classrooms Item - Type om #116 (Regular Classroom)	Entire Building / 1st Floor	Quantity	EA	6 Rank	\$745 \$88,807 Cost	Elevator sump pump.
Plumb Buildir Catego Froup	Pumps - Sump-Simplex sing System Subtotal: ng: Main ory: Classrooms Item - Type om #116 (Regular Classroom) Casework	Entire Building / 1st Floor Location 1st Floor	Quantity 29	EA Unit	6 Rank 6	\$745 \$88,807 Cost \$732	Elevator sump pump.
Plumb Buildir Catego Group	Pumps - Sump-Simplex ing System Subtotal: ng: Main ory: Classrooms Item - Type om #116 (Regular Classroom) Casework Ceiling - Lay-in	Entire Building / 1st Floor Location 1st Floor 1st Floor 1st Floor	1 Quantity 29 1,506	EA Unit	6 Rank 6 6	\$745 \$88,807 Cost \$732 \$4,523	Elevator sump pump.
Plumb Buildii Catego Group	Pumps - Sump-Simplex sing System Subtotal: ng: Main bry: Classrooms Item - Type om #116 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite	Entire Building / 1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor	1 Quantity 29 1,506 18	EA Unit LF SF SF	6 Rank 6 6 6 6	\$745 \$88,807 Cost \$732 \$4,523 \$301	Elevator sump pump.
Plumb Buildir Catego Group	Pumps - Sump-Simplex sing System Subtotal: ng: Main ory: Classrooms Item - Type om #116 (Regular Classroom) Casework Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	Entire Building / 1st Floor Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 Quantity 29 1,506 18 4	EA Unit LF SF SF EA	6 Rank 6 6 6 6 6	\$745 \$88,807 Cost \$732 \$4,523 \$301 \$1,204	Elevator sump pump.

Storage/ Closet

Work Sink

Casework

Walls - Concrete Block

Walls - Metal Panel

Classroom #118 (Regular Classroom)

SF

SF

SF

40

2,040

290

1 EA

29 LF

6

6

6

6

6

\$290

\$5,980

\$2,165

\$379

\$732

1st Floor

1st Floor

1st Floor

1st Floor

1st Floor



Category:	Classrooms
-----------	------------

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	bom #118 (Regular Classroom)	Location	Quantity	Unit	Marik	0031	Commenta
0103310	Ceiling - Lay-in	1st Floor	729	SF	6	\$2,189	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	\$301	
	Floor - Tile	1st Floor	729	SF	6	\$1,595	
	Lighting - Lay-in	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	10	LF	7	\$0 \$0	
	Walls - Concrete Block	1st Floor	708	SF	6	\$2,076	
	Walls - Metal Panel	1st Floor	290	SF	6	\$2,070 \$2,165	
	Work Sink	1st Floor	230	EA	6	\$379	
		13111001	I	LA	0	ψ010	
Classro	oom #119 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
Classro	oom #120 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
Classro	oom #121 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	



3510 W 55th St Chicago, IL 60632

-	ory: Classrooms						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssro	om #121 (Regular Classroom)						
ssro	om #122 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
eero	om #123 (Regular Classroom)						
3310	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
			,-			+-, -	
ssro	om #124 (Regular Classroom) Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor		SF		\$1,237 \$2,517	
	Doors - Side-lite	1st Floor	838 9	SF	6 6	\$2,517 \$150	
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	\$150	
	Floor - Tile	1st Floor	838	SF	6	\$301 \$1,833	
	Lighting - Lay-in	1st Floor	030 11	EA	7	۵۱,۵۵۵ \$0	
	Marker Board	1st Floor	24		7	\$0 \$0	
	Walls - Concrete Block	1st Floor	1,074	SF	6	₄₀ \$3,148	
		13(1100)	1,074	0	0	ψ0, 140	
ssro	oom #125 (Regular Classroom)					.	
	Casework	1st Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
	Doors - Side-lite	1st Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	838	SF	6	\$839	
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	



gory: Classrooms		- · ·			-	•
Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
oom #125 (Regular Classroom)						
Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
oom #126 (Regular Classroom)						
Casework	1st Floor	49	LF	6	\$1,237	
Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
Doors - Side-lite	1st Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile	1st Floor	838	SF	6	\$1,833	
Lighting - Lay-in	1st Floor	11	EA	7	\$0	
Marker Board	1st Floor	24	LF	7	\$0	
Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
oom #127 (Regular Classroom)						
Casework	1st Floor	49	LF	6	\$1,237	
Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
Doors - Side-lite	1st Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile	1st Floor	838	SF	6	\$1,833	
Lighting - Lay-in	1st Floor	11	EA	7	\$0	
Marker Board	1st Floor	24	LF	7	\$0	
Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
ann #128 (Berryler Classroom)					. ,	
oom #128 (Regular Classroom) Casework	1st Floor	49	LF	6	\$1,237	
	1st Floor	49 838	SF		\$1,237 \$2,517	
Ceiling - Lay-in				6		
Doors - Side-lite Doors - Wood Doors inclu hw	1st Floor	9	SF EA	6	\$150 \$201	
Floor - Tile	1st Floor 1st Floor	1 838	EA SF	6 6	\$301 \$1,833	
	1st Floor 1st Floor	838	EA	6 7	\$1,833	
Lighting - Lay-in Marker Board	1st Floor 1st Floor	24	LF	7	\$0 \$0	
Walks - Concrete Block	1st Floor 1st Floor	24 1,074	SF	6	\$0 \$3,148	
		1,074	SF	U	JJ, 140	
oom #129 (Regular Classroom)						
Casework	1st Floor	49	LF	6	\$1,237	
Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
Doors - Side-lite	1st Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile	1st Floor	838	SF	6	\$1,833	
Lighting - Lay-in	1st Floor	11	EA	7	\$0	

-	ry: Classrooms	Lesster.	0	11-14	Davis	• •••	0
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	m #129 (Regular Classroom)			. –		^	
	Marker Board	1st Floor	24	LF	7	\$0	
1	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
sroo	m #130 (Regular Classroom)						
1	Casework	1st Floor	49	LF	6	\$1,237	
1	Ceiling - Lay-in	1st Floor	838	SF	6	\$2,517	
I	Doors - Side-lite	1st Floor	9	SF	6	\$150	
I	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
1	Floor - Tile	1st Floor	838	SF	6	\$1,833	
1	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
1	Marker Board	1st Floor	24	LF	7	\$0	
١	Walls - Concrete Block	1st Floor	1,074	SF	6	\$3,148	
eroo	m #200 (Science Lab Level 3)						
	Casework	2nd Floor	29	LF	6	\$732	
	Ceiling - Lay-in	2nd Floor	1,609	SF	6	\$4,832	
	Doors - Side-lite	2nd Floor	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	- 1	EA	6	\$336	
	Floor - Tile	2nd Floor	1,609	SF	6	\$3,520	
	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	28	LF	7	\$0	
	Science Lab Elements	2nd Floor	18	SF	6	\$122	
,	Walls - Concrete Block	2nd Floor	768	SF	6	\$2,251	
	Walls - Plaster/Drywall	2nd Floor	768	SF	6	\$2,120	
	Work Sink	2nd Floor	3	EA	6	\$1,137	
sroo	m #201 (Science Lab Level 3)						
	Casework	2nd Floor	29	LF	6	\$732	
(Ceiling - Lay-in	2nd Floor	1,609	SF	6	\$4,832	
	Doors - Side-lite	2nd Floor	18	SF	6	\$301	
1	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
1	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile	2nd Floor	1,609	SF	6	\$3,520	
(Gas Line	2nd Floor	1	EA	6	\$509	
ł	Lighting - Lay-in	2nd Floor	21	EA	7	\$0	
	Marker Board	2nd Floor	28	LF	7	\$0	
;	Science Lab Elements	2nd Floor	18	SF	6	\$122	
,	Walls - Concrete Block	2nd Floor	768	SF	6	\$2,251	

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
om #201 (Science Lab Level 3)						
Walls - Plaster/Drywall	2nd Floor	768	SF	6	\$2,120	
Work Sink	2nd Floor	3	EA	6	\$1,137	
					+ , -	
om #210 (Regular Classroom)						
Casework	2nd Floor	49	LF	6	\$1,237	
Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
Doors - Side-lite	2nd Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile	2nd Floor	838	SF	6	\$1,833	
Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
Marker Board	2nd Floor	24	LF	7	\$0	
Walls - Concrete Block	2nd Floor	806	SF	6	\$2,363	
Walls - Plaster/Drywall	2nd Floor	268	SF	6	\$740	
om #212 (Regular Classroom)						
Casework	2nd Floor	49	LF	6	\$1,237	
Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
Doors - Side-lite	2nd Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
Floor - Tile	2nd Floor	838	SF	6	\$1,833	
Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
Marker Board	2nd Floor	24	LF	7	\$0	
Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
om #213 (Computer Lab)						
Casework	2nd Floor	3	LF	6	\$76	
Ceiling - Lay-in	2nd Floor	1,245	SF	6	\$3,739	
Doors - Side-lite	2nd Floor	18	SF	6	\$301	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
Floor - Tile	2nd Floor	1,245	SF	6	\$2,724	
Lighting - Lay-in	2nd Floor	.,_ 10	EA	7	\$0	
Marker Board	2nd Floor	28	LF	7	\$0	
Walls - Concrete Block	2nd Floor	720	SF	6	\$2,111	
Walls - Plaster/Drywall	2nd Floor	720	SF	6	\$1,987	
Wireless System	2nd Floor	1	EA	6	\$372	
				-	<i>+-/</i>	
om #214 (Science Lab Level 3) Casework	2nd Floor	26	LF	6	\$657	



Category: Classrooms

•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #214 (Science Lab Level 3)						
	Ceiling - Lay-in	2nd Floor	1,378	SF	6	\$4,138	
	Doors - Side-lite	2nd Floor	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Eye Wash Station	2nd Floor	1	EA	6	\$336	
	Floor - Tile	2nd Floor	1,378	SF	6	\$3,015	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Science Lab Elements	2nd Floor	18	SF	6	\$122	
	Walls - Concrete Block	2nd Floor	741	SF	6	\$2,172	
	Walls - Plaster/Drywall	2nd Floor	741	SF	6	\$2,045	
	Work Sink	2nd Floor	3	EA	6	\$1,137	
assro	oom #215 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
assro	oom #216 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	5	\$4,985	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
assro	oom #217 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
Classro	oom #217 (Regular Classroom)						
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
Classro	oom #218 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
lassro	oom #219 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
lassro	oom #220 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	



Category: Classrooms

un	Item - Type	Location	Quantity	l Ini+	Pank	Cost	Comments
		Location	Quantity	Unit	капк	Cost	Comments
ssro	om #221 (Regular Classroom)	and Floor	40		6	¢4 007	
	Casework	2nd Floor 2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in		838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
ssro	om #222 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
ssro	om #223 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
	om #224 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
				<u> </u>		÷1,000	



-	ory: Classrooms Item - Type	Location	Quantity	Unit	Park	Cost	Comments
		Location	Quantity	Unit	капк	Cost	Comments
lassio	om #224 (Regular Classroom) Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
Classroo	om #225 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	\$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,482	
laceror	om #226 (Regular Classroom)						
1055100	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$1,237 \$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	9	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$1,835 \$0	
	Marker Board	2nd Floor	24	LF	7	\$0 \$0	
	Walls - Concrete Block	2nd Floor	537	SF	6	₄₀ \$1,574	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	\$1,374 \$1,482	
	Walls - Flastel/Drywall	2110 F1001	557	SF	0	Φ1,40 Ζ	
Classroo	om #228 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Lay-in	2nd Floor	838	SF	6	\$2,517	
	Doors - Side-lite	2nd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	838	SF	6	\$1,833	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	806	SF	6	\$2,363	
	Walls - Plaster/Drywall	2nd Floor	268	SF	6	\$740	
lasero	om #310 (Science Classroom)						
1033100	Ceiling - Lay-in	3rd Floor	1,378	SF	6	\$4,138	



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	om #310 (Science Classroom)						
	Doors - Side-lite	3rd Floor	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	\$903	
	Floor - Tile	3rd Floor	1,378	SF	6	\$3,015	
	Lighting - Lay-in	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Storage/ Closet	3rd Floor	201	SF	6	\$1,457	RM 310A
	Walls - Masonry	3rd Floor	635	SF	6	\$1,998	
	Walls - Plaster/Drywall	3rd Floor	635	SF	6	\$1,753	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
assro	om #313 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	1,245	SF	6	\$3,739	
	Doors - Side-lite	3rd Floor	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile	3rd Floor	1,245	SF	6	\$2,724	
	Lighting - Lay-in	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	603	SF	6	\$1,768	
	Walls - Plaster/Drywall	3rd Floor	603	SF	6	\$1,664	
	Wireless System	3rd Floor	1	EA	6	\$372	
assro	om #314 (Science Lab Level 3)						
	Ceiling - Lay-in	3rd Floor	1,378	SF	6	\$4,138	
	Doors - Side-lite	3rd Floor	18	SF	6	\$301	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	\$903	
	Eye Wash Station	3rd Floor	1	EA	6	\$336	
	Floor - Tile	3rd Floor	1,378	SF	6	\$3,015	
	Gas Line	3rd Floor	1	EA	6	\$509	
	Lighting - Lay-in	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	635	SF	6	\$1,862	
	Walls - Plaster/Drywall	3rd Floor	635	SF	6	\$1,753	
	Work Sink	3rd Floor	3	EA	6	\$1,137	
assro	om #315 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	



	ng. mani						
Categ	ory: Classrooms						
iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #315 (Regular Classroom)						
	Floor - Tile	3rd Floor	895	SF	6	\$1,958	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
lassro	om #316 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	895	SF	6	\$1,958	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
lassro	om #317 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	895	SF	6	\$896	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
assro	om #318 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	895	SF	6	\$896	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor		SF	6	\$1,410	



Category: Classrooms

-	Item - Type	Location	Quantity	l Ini+	Pank	Cost	Comments
		Location	Quantity	Unit	Rank	Cost	Comments
assro	oom #319 (Regular Classroom)	2rd Floor	40	1.5	6	¢4 040	
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	895	SF	6	\$1,958	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
assro	om #320 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	895	SF	6	\$1,958	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
assro	om #321 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	895	SF	6	\$1,958	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
	Marker Board	3rd Floor	28	LF	7	\$0	
	Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
assro	om #322 (Regular Classroom)						
	Casework	3rd Floor	48	LF	6	\$1,212	
	Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
	Doors - Side-lite	3rd Floor	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	895	SF	6	\$896	
	Lighting - Lay-in	3rd Floor	11	EA	7	\$0	



n Itom Tuno	Location	Quentity	Unit	Donk	Cont	Comments
p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroom #322 (Regular Classroom)	-				^	
Marker Board	3rd Floor	28	LF	7	\$0	
Walls - Concrete Block	3rd Floor	511	SF	6	\$1,498	
Walls - Plaster/Drywall	3rd Floor	511	SF	6	\$1,410	
sroom #323 (Art Room)						
Casework	3rd Floor	22	LF	6	\$556	
Ceiling - Lay-in	3rd Floor	1,268	SF	6	\$3,808	
Doors - Side-lite	3rd Floor	18	SF	6	\$301	
Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	\$1,204	
Floor - Tile	3rd Floor	1,268	SF	6	\$2,774	
Kiln	3rd Floor	1	EA	6	\$2,321	
Lighting - Lay-in	3rd Floor	17	EA	7	\$0	
Marker Board	3rd Floor	14	LF	7	\$0	
Storage/ Closet	3rd Floor	440	SF	6	\$3,190	closet, rm 323A, rm 323A-1
Walls - Concrete Block	3rd Floor	567	SF	6	\$1,662	
Walls - Plaster/Drywall	3rd Floor	567	SF	6	\$1,565	
Work Sink	3rd Floor	2	EA	6	\$758	
sroom #324 (Regular Classroom)						
Casework	3rd Floor	48	LF	6	\$1,212	
Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
Doors - Side-lite	3rd Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	895	SF	6	\$1,958	
Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
Marker Board	3rd Floor	28	LF	7	\$0	
Walls - Plaster/Drywall	3rd Floor	1,021	SF	6	\$2,818	
sroom #326 (Regular Classroom)						
Casework	3rd Floor	48	LF	6	\$1,212	
Ceiling - Lay-in	3rd Floor	895	SF	6	\$2,688	
Doors - Side-lite	3rd Floor	9	SF	6	\$150	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile	3rd Floor	895	SF	6	\$1,958	
Lighting - Lay-in	3rd Floor	11	EA	7	\$0	
Marker Board	3rd Floor	28	LF	7	\$0	
Walls - Plaster/Drywall	3rd Floor	1,021	SF	6	\$2,818	



Category: Classrooms

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
lassroo	om #328 (Music Room)						
	Casework	3rd Floor	13	LF	6	\$328	
	Ceiling - Exposed	3rd Floor	1,056	SF	6	\$1,570	
	Doors - Side-lite	3rd Floor	36	SF	6	\$602	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	\$903	
	Floor - Tile/Sheet	3rd Floor	1,056	SF	6	\$1,057	
	Lighting - Lay-in	3rd Floor	31	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Sound Panels	3rd Floor	22	EA	6	\$89	
	Storage/ Closet	3rd Floor	185	SF	6	\$1,341	RM 328A
	Walls - Plaster/Drywall	3rd Floor	2,399	SF	6	\$6,621	
	Work Sink	3rd Floor	2	EA	6	\$758	
assr	ooms Subtotal:					\$495,891	

\$495,891

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Ceiling - Lay-in	1st FIr- Kitchen Office	97	SF	6	\$291	
	Doors - Side-lite	1st FIr- Kitchen Office	12	SF	6	\$201	
	Doors - Steel Doors incl hw	1st FIr- Kitchen Office	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	1st FIr- Kitchen Office	97	SF	6	\$51	
	Lighting - Lay-in	1st FIr- Kitchen Office	2	EA	7	\$0	
	Power Distribution	1st FIr- Kitchen Office	4	EA	7	\$0	
	Walls - Concrete Block	1st FIr- Kitchen Office	390	SF	6	\$1,143	
	Ceiling - Lay-in	Nurse's Office RM 112	1,580	SF	6	\$4,745	
	Doors - Side-lite	Nurse's Office RM 112	9	SF	6	\$150	
	Doors - Wood Doors inclu hw	Nurse's Office RM 112	5	EA	6	\$1,505	
	Floor - Carpet	Nurse's Office RM 112	687	SF	6	\$1,464	
	Floor - Tile/Sheet	Nurse's Office RM 112	888	SF	6	\$889	
	Lighting - Lay-in	Nurse's Office RM 112	30	EA	7	\$0	
	Power Distribution	Nurse's Office RM 112	28	EA	7	\$0	
	Storage/ Closet	Nurse's Office RM 112	300	SF	6	\$2,175	Including 3 exam rooms
	Walls - Concrete Block	Nurse's Office RM 112	1,587	SF	6	\$4,652	
	Walls - Plaster/Drywall	Nurse's Office RM 112	1,587	SF	6	\$4,380	
	Work SInk	Nurse's Office RM 112	3	EA	6	\$1,524	
	Ceiling - Lay-in	Rm 100- Main Office	1,408	SF	6	\$4,228	



up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Suites/Offices						
Doors - Side-lite	Rm 100- Main Office	17	SF	6	\$284	
Doors - Wood Doors inclu hw	Rm 100- Main Office	2	EA	6	\$602	
Floor - Carpet	Rm 100- Main Office	1,206	SF	6	\$2,570	
Floor - Terrazzo	Rm 100- Main Office	202	SF	7	\$0	
Lighting - Lay-in	Rm 100- Main Office	14	EA	7	\$0	
Power Distribution	Rm 100- Main Office	18	EA	7	\$0	
Storage/ Closet	Rm 100- Main Office	80	SF	6	\$580	
Storage/ Closet	Rm 100- Main Office	120	SF	6	\$870	Vault- Rm 100D-1
Walls - Concrete Block	Rm 100- Main Office	1,195	SF	6	\$3,503	
Walls - Plaster/Drywall	Rm 100- Main Office	1,195	SF	6	\$3,298	
Ceiling - Lay-in	Rm 100A- Asst Principal	235	SF	6	\$706	
Doors - Side-lite	Rm 100A- Asst Principal	9	SF	6	\$150	
Doors - Wood Doors inclu hw	Rm 100A- Asst Principal	1	EA	6	\$301	
Floor - Carpet	Rm 100A- Asst Principal	235	SF	6	\$501	
Lighting - Lay-in	Rm 100A- Asst Principal	6	EA	7	\$0	
Power Distribution	Rm 100A- Asst Principal	12	EA	7	\$0	
Walls - Concrete Block	Rm 100A- Asst Principal	282	SF	6	\$827	
Walls - Plaster/Drywall	Rm 100A- Asst Principal	282	SF	6	\$778	
Ceiling - Lay-in	Rm 100C- Principal	345	SF	6	\$1,036	
Doors - Side-lite	Rm 100C- Principal	9	SF	6	\$150	
Doors - Wood Doors inclu hw	Rm 100C- Principal	1	EA	6	\$301	
Floor - Carpet	Rm 100C- Principal	345	SF	6	\$735	
Lighting - Lay-in	Rm 100C- Principal	4	EA	7	\$0	
Power Distribution	Rm 100C- Principal	14	EA	7	\$0	
Walls - Concrete Block	Rm 100C- Principal	175	SF	6	\$513	
Walls - Plaster/Drywall	Rm 100C- Principal	524	SF	6	\$1,446	
Ceiling - Lay-in	Rm 100C(2)- Conference Room	345	SF	6	\$1,036	
Doors - Side-lite	Rm 100C(2)- Conference Room	9	SF	6	\$150	
Doors - Wood Doors inclu hw	Rm 100C(2)- Conference Room	1	EA	6	\$301	
Floor - Carpet	Rm 100C(2)- Conference Room	345	SF	6	\$735	
Lighting - Lay-in	Rm 100C(2)- Conference Room	10	EA	7	\$0	
Lighting - Pendent/Surface	Rm 100C(2)- Conference Room	5	EA	7	\$0	
Power Distribution	Rm 100C(2)- Conference Room	14	EA	7	\$0	
Walls - Concrete Block	Rm 100C(2)- Conference Room	349	SF	6	\$1,023	
Walls - Plaster/Drywall	Rm 100C(2)- Conference Room	349	SF	6	\$963	
Ceiling - Lay-in	Rm 100D- Copy/Work Room	162	SF	6	\$486	
Doors - Side-lite	Rm 100D- Copy/Work Room	9	SF	6	\$150	



oup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
ministrative Suites/Offices							
Doors - Wood Doors in	nclu hw	Rm 100D- Copy/Work Room	1	EA	6	\$301	
Floor - Tile		Rm 100D- Copy/Work Room	162	SF	6	\$354	
Lighting - Lay-in		Rm 100D- Copy/Work Room	1	EA	7	\$0	
Power Distribution		Rm 100D- Copy/Work Room	12	EA	7	\$0	
Walls - Concrete Block	< compared by the second s	Rm 100D- Copy/Work Room	357	SF	6	\$1,047	
Walls - Plaster/Drywal		Rm 100D- Copy/Work Room	119	SF	6	\$328	
Ceiling - Lay-in		Rm 100E-Pantry (in Main office)	75	SF	6	\$225	
Floor - Tile		Rm 100E-Pantry (in Main office)	75	SF	6	\$164	
Lighting - Lay-in		Rm 100E-Pantry (in Main office)	1	EA	7	\$0	
Power Distribution		Rm 100E-Pantry (in Main office)	6	EA	7	\$0	
Walls - Concrete Block	ζ.	Rm 100E-Pantry (in Main office)	257	SF	6	\$753	
Work SInk		Rm 100E-Pantry (in Main office)	1	EA	6	\$508	
Ceiling - Lay-in		Rm 105A- Gym Office	145	SF	6	\$435	
Doors - Wood Doors in	nclu hw	Rm 105A- Gym Office	1	EA	6	\$301	
Floor - Tile		Rm 105A- Gym Office	145	SF	6	\$317	
Lighting - Lay-in		Rm 105A- Gym Office	2	EA	7	\$0	
Power Distribution		Rm 105A- Gym Office	8	EA	7	\$0	
Walls - Concrete Block	< colored and set of the set of t	Rm 105A- Gym Office	392	SF	6	\$1,149	
Ceiling - Lay-in		RM 107A-7 Engineer Office	148	SF	6	\$444	
Doors - Store Front		RM 107A-7 Engineer Office	1	EA	6	\$1,208	
Floor - Tile		RM 107A-7 Engineer Office	148	SF	6	\$324	
Lighting - Lay-in		RM 107A-7 Engineer Office	2	EA	7	\$0	
Power Distribution		RM 107A-7 Engineer Office	8	EA	7	\$0	
Walls - Concrete Block	< compared by the second s	RM 107A-7 Engineer Office	220	SF	6	\$645	
Ceiling - Lay-in		RM 108 Student Services	570	SF	6	\$1,712	
Doors - Side-lite		RM 108 Student Services	45	SF	6	\$752	
Doors - Wood Doors in	nclu hw	RM 108 Student Services	5	EA	6	\$1,505	
Floor - Carpet		RM 108 Student Services	570	SF	6	\$1,214	
Lighting - Lay-in		RM 108 Student Services	8	EA	7	\$0	
Power Distribution		RM 108 Student Services	28	EA	7	\$0	
Walls - Concrete Block	< colored and set of the set of t	RM 108 Student Services	1,200	SF	6	\$3,518	
Ceiling - Lay-in		Rm 201A- Science Office	276	SF	6	\$829	
Doors - Wood Doors in	nclu hw	Rm 201A- Science Office	2	EA	6	\$602	
Floor - Tile		Rm 201A- Science Office	276	SF	6	\$604	
Lighting - Lay-in		Rm 201A- Science Office	2	EA	7	\$0	
Power Distribution		Rm 201A- Science Office	14	EA	7	\$0	
Walls - Concrete Blocl	(Rm 201A- Science Office	648	SF	6	\$1,900	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Lay-in	RM 300A - library office	148	SF	6	\$444	
	Doors - Side-lite	RM 300A - library office	32	SF	6	\$535	
	Doors - Wood Doors inclu hw	RM 300A - library office	1	EA	6	\$301	
	Floor - Carpet	RM 300A - library office	148	SF	6	\$315	
	Lighting - Lay-in	RM 300A - library office	2	EA	7	\$0	
	Power Distribution	RM 300A - library office	8	EA	7	\$0	
	Walls - Concrete Block	RM 300A - library office	458	SF	6	\$1,343	
	Ceiling - Lay-in	RM 305 teachers lounge	736	SF	6	\$2,210	
	Doors - Wood Doors inclu hw	RM 305 teachers lounge	1	EA	6	\$301	
	Floor - Tile	RM 305 teachers lounge	736	SF	6	\$1,610	
	Lighting - Lay-in	RM 305 teachers lounge	16	EA	7	\$0	
	Power Distribution	RM 305 teachers lounge	18	EA	7	\$0	
	Walls - Concrete Block	RM 305 teachers lounge	1,012	SF	6	\$2,967	
Gymna	sia						
	Bleacher Seating	1st floor - Room 105	110	EA	6	\$3,184	
	Ceiling - Exposed	1st floor - Room 105	5,568	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st floor - Room 105	288	SF	6	\$1,590	near entrance doors
	Doors - Wood Doors inclu hw	1st floor - Room 105	6	EA	6	\$1,806	
	Floor - Tile/Sheet	1st floor - Room 105	406	SF	6	\$406	
	Floor - Wood	1st floor - Room 105	5,454	SF	6	\$38,450	
	Lighting - Lay-in	1st floor - Room 105	9	EA	7	\$0	cans- near entrance doors
	Lighting - Metal Halide/Sodium Vapor	1st floor - Room 105	20	EA	7	\$0	
	Lighting - Pendent/Surface	1st floor - Room 105	15	EA	7	\$0	LED - above stage
	Scoreboards	1st floor - Room 105	1	EA	6	\$2,244	
	Sound System	1st floor - Room 105	1	EA	6	\$41,654	
	Stage	1st floor - Room 105	927	SF	6	\$5,355	
	Stage Curtain	1st floor - Room 105	8	EA	6	\$0	
	Stage Lift	1st floor - Room 105	1	EA	6	\$6,510	
	Stage Lighting System	1st floor - Room 105	1	EA	6	\$12,369	
	Stage-Stairs - Tile	1st floor - Room 105	8	LF	6	\$74	concrete
	Storage/ Closet	1st floor - Room 105	482	SF	6	\$3,495	
	Walls - Concrete Block	1st floor - Room 105	7,917	SF	6	\$23,209	
Kitchen	1						
	Ceiling - Lay-in	1st Floor	1,009	SF	6	\$3,030	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	\$903	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,009	SF	6	\$534	



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
litchen							
	Lighting - Lay-in	1st Floor	11	EA	7	\$0	
	Storage/ Closet	1st Floor	139	SF	6	\$1,008	
	Walls - Concrete Block	1st Floor	1,427	SF	6	\$4,183	
.ibrary							
	Ceiling - Exposed	3rd floor 321	2,004	SF	6	\$2,980	
	Ceiling - Lay-in	3rd floor 321	1,831	SF	6	\$5,498	
	Doors - Side-lite	3rd floor 321	13	SF	6	\$217	
	Doors - Transom Window	3rd floor 321	48	SF	6	\$813	
	Doors - Wood Doors inclu hw	3rd floor 321	2	EA	6	\$602	
	Floor - Carpet	3rd floor 321	3,825	SF	6	\$8,150	
	Lighting - Lay-in	3rd floor 321	42	EA	7	\$0	
	Lighting - Pendent/Surface	3rd floor 321	21	EA	7	\$0	
	Storage/ Closet	3rd floor 321	150	SF	6	\$1,088	
	Walls - Concrete Block	3rd floor 321	2,300	SF	6	\$6,742	
	Walls - Plaster/Drywall	3rd floor 321	788	SF	6	\$2,175	
unch 8	& Multipurpose Room						
	Ceiling - Exposed	Cafeteria/Tray Rm	1,311	SF	7	\$0	
	Ceiling - Lay-in	Cafeteria/Tray Rm	3,445	SF	6	\$10,345	
	Ceiling - Plaster/Drywall	Cafeteria/Tray Rm	632	SF	6	\$2,187	
	Doors - Steel Doors incl hw	Cafeteria/Tray Rm	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	Cafeteria/Tray Rm	4	EA	6	\$1,204	
	Floor - Tile	Cafeteria/Tray Rm	5,388	SF	6	\$11,788	
	Lighting - Lay-in	Cafeteria/Tray Rm	84	EA	7	\$0	
	Lighting - Metal Halide/ High Pressure Sodium	Cafeteria/Tray Rm	14	EA	7	\$0	
	Serving Line	Cafeteria/Tray Rm	32	LF	6	\$1,905	
	Walls - Concrete Block	Cafeteria/Tray Rm	3,514	SF	6	\$10,301	
	Walls - Plaster/Drywall	Cafeteria/Tray Rm	3,165	SF	6	\$8,735	
	Walls - Structural Glazed Tile	Cafeteria/Tray Rm	700	SF	6	\$2,202	
IDF_ID	DF						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Finishes	2nd Floor	286	SF	6	\$2,041	
	Ventilation and Cooling	2nd Floor	1	EA	6	\$1,855	
lechan	nical/ Service Rooms						
	Janitor's Closet	1st Floor	95	SF	6	\$681	
	Mechanical/ Service Rooms	1st Floor	994	SF	6	\$7,121	Yard Storage



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Storage Room	1st Floor	376	SF	6	\$2,694	RM 107A-5, RM 107A-6
	Janitor's Closet	2nd Floor	157	SF	6	\$1,125	
	Mechanical/ Service Rooms	2nd Floor	6,022	SF	6	\$43,143	RM 211
	Boiler Room	3rd Floor	1,508	SF	6	\$10,804	
	Janitor's Closet	3rd Floor	104	SF	6	\$745	
	Mechanical/ Service Rooms	3rd Floor	1,686	SF	6	\$12,079	RM 307A, 311
	Storage Room	3rd Floor	378	SF	6	\$2,708	RM 312
Restroc	om						
	Accessories	1st floor east- Across from Main Office	343	SF	6	\$3,164	
	Accessories	1st floor east -Across from Main Office	343	SF	6	\$3,164	
	Ceiling - Plaster/Drywall	1st floor east- Across from Main Office	343	SF	6	\$1,187	
	Ceiling - Plaster/Drywall	1st floor east -Across from Main Office	343	SF	6	\$1,187	
	Floor Drain	1st floor east- Across from Main Office	3	EA	6	\$3,177	
	Floor Drain	1st floor east -Across from Main Office	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	1st floor east- Across from Main Office	343	SF	6	\$726	
	Floor - Tile Ceramic/ Porcelain	1st floor east -Across from Main Office	343	SF	6	\$726	
	Hand Dryer	1st floor east- Across from Main Office	1	EA	6	\$230	
	Hand Dryer	1st floor east -Across from Main Office	1	EA	6	\$230	
	Lavatory	1st floor east- Across from Main Office	5	EA	6	\$1,598	
	Lavatory	1st floor east -Across from Main Office	5	EA	6	\$1,598	
	Lighting - Lay-in	1st floor east- Across from Main Office	11	EA	7	\$0	cove lights & 1 can
	Lighting - Lay-in	1st floor east -Across from Main Office	11	EA	7	\$0	cove lights & 1 can
	Partitions	1st floor east- Across from Main Office	6	EA	6	\$1,782	
	Partitions	1st floor east -Across from Main Office	3	EA	7	\$0	
	Urinals	1st floor east -Across from Main Office	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	1st floor east- Across from Main Office	712	SF	6	\$2,240	
	Walls - Structural Glazed Tile	1st floor east -Across from Main Office	712	SF	6	\$2,240	
	Water Closet	1st floor east- Across from Main Office	6	EA	6	\$2,016	
	Water Closet	1st floor east -Across from Main Office	3	EA	6	\$1,008	
	Accessories	1st floor east- Women Across from Main Office	73	SF	6	\$673	
	Ceiling - Lay-in	1st floor east- Women Across from Main Office	73	SF	6	\$219	
	Doors - Wood Doors inclu hw	1st floor east- Women Across from Main Office	1	EA	6	\$301	
	Floor Drain	1st floor east- Women Across from Main Office	1	EA	6	\$1,059	



ıp	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
roo	m						
	Floor - Tile Ceramic/ Porcelain	1st floor east- Women Across from Main Office	73	SF	6	\$154	
	Lavatory	1st floor east- Women Across from Main Office	1	EA	6	\$320	
	Lighting - Lay-in	1st floor east- Women Across from Main Office	1	EA	7	\$0	
	Walls - Concrete Block	1st floor east- Women Across from Main Office	272	SF	6	\$797	
	Water Closet	1st floor east- Women Across from Main Office	1	EA	6	\$336	
	Accessories	1st floor- In Main Office Suite	66	SF	6	\$609	
	Ceiling - Lay-in	1st floor- In Main Office Suite	66	SF	6	\$198	
	Doors - Steel Doors incl hw	1st floor- In Main Office Suite	1	EA	6	\$301	
	Floor Drain	1st floor- In Main Office Suite	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor- In Main Office Suite	66	SF	6	\$140	
	Lavatory	1st floor- In Main Office Suite	1	EA	6	\$320	
	Lighting - Lay-in	1st floor- In Main Office Suite	1	EA	7	\$0	
	Walls - Concrete Block	1st floor- In Main Office Suite	260	SF	6	\$762	
	Water Closet	1st floor- In Main Office Suite	1	EA	6	\$336	
	Accessories	1st floor- In Nurse's Office	80	SF	6	\$738	
	Ceiling - Lay-in	1st floor- In Nurse's Office	80	SF	6	\$240	
	Doors - Wood Doors inclu hw	1st floor- In Nurse's Office	1	EA	6	\$301	
	Floor Drain	1st floor- In Nurse's Office	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor- In Nurse's Office	80	SF	6	\$169	
	Lavatory	1st floor- In Nurse's Office	1	EA	6	\$320	
	Lighting - Lay-in	1st floor- In Nurse's Office	1	EA	7	\$0	
	Showers	1st floor- In Nurse's Office	1	EA	6	\$311	
	Walls - Concrete Block	1st floor- In Nurse's Office	260	SF	6	\$762	
	Water Closet	1st floor- In Nurse's Office	1	EA	6	\$336	
	Accessories	1st floor- Men's Next to engineers office	65	SF	6	\$600	
	Ceiling - Lay-in	1st floor- Men's Next to engineers office	65	SF	6	\$195	
	Doors - Steel Doors incl hw	1st floor- Men's Next to engineers office	1	EA	6	\$301	
	Floor Drain	1st floor- Men's Next to engineers office	1	EA	6	\$1,059	
	Floor - Tile	1st floor- Men's Next to engineers office	65	SF	6	\$142	
	Lavatory	1st floor- Men's Next to engineers office	1	EA	6	\$320	
	Lighting - Lay-in	1st floor- Men's Next to engineers office	1	EA	7	\$0	
	Walls - Concrete Block	1st floor- Men's Next to engineers office	152	SF	6	\$446	
	Water Closet	1st floor- Men's Next to engineers office	1	EA	6	\$336	
	Accessories	1st floor west- By 128	298	SF	6	\$2,749	



roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroo	om de la companya de						
	Accessories	1st floor west- By 128	298	SF	6	\$2,749	
	Ceiling - Plaster/Drywall	1st floor west- By 128	298	SF	6	\$1,031	
	Ceiling - Plaster/Drywall	1st floor west- By 128	298	SF	6	\$1,031	
	Floor Drain	1st floor west- By 128	3	EA	6	\$3,177	
	Floor Drain	1st floor west- By 128	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	1st floor west- By 128	298	SF	6	\$631	
	Floor - Tile Ceramic/ Porcelain	1st floor west- By 128	298	SF	6	\$631	
	Hand Dryer	1st floor west- By 128	1	EA	6	\$230	
	Hand Dryer	1st floor west- By 128	1	EA	6	\$230	
	Lavatory	1st floor west- By 128	4	EA	6	\$1,278	
	Lavatory	1st floor west- By 128	4	EA	6	\$1,278	
	Lighting - Lay-in	1st floor west- By 128	7	EA	7	\$0	
	Lighting - Lay-in	1st floor west- By 128	9	EA	7	\$0	cove lights
	Partitions	1st floor west- By 128	3	EA	7	\$0	
	Partitions	1st floor west- By 128	4	EA	7	\$0	
	Urinals	1st floor west- By 128	2	EA	6	\$672	
	Walls - Structural Glazed Tile	1st floor west- By 128	662	SF	6	\$2,083	
	Walls - Structural Glazed Tile	1st floor west- By 128	662	SF	6	\$2,083	
	Water Closet	1st floor west- By 128	5	EA	6	\$1,680	
	Water Closet	1st floor west- By 128	3	EA	6	\$1,008	
	Accessories	1st floor west- Men by 128	66	SF	6	\$609	
	Ceiling - Lay-in	1st floor west- Men by 128	66	SF	6	\$198	
	Doors - Wood Doors inclu hw	1st floor west- Men by 128	1	EA	6	\$301	
	Floor Drain	1st floor west- Men by 128	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor west- Men by 128	66	SF	6	\$140	
	Lavatory	1st floor west- Men by 128	1	EA	6	\$320	
	Lighting - Lay-in	1st floor west- Men by 128	1	EA	7	\$0	
	Walls - Concrete Block	1st floor west- Men by 128	260	SF	6	\$762	
	Water Closet	1st floor west- Men by 128	1	EA	6	\$336	
	Accessories	1st floor- Women's Next to engineers office	65	SF	6	\$600	
	Ceiling - Lay-in	1st floor- Women's Next to engineers office	65	SF	6	\$195	
	Doors - Steel Doors incl hw	1st floor- Women's Next to engineers office	1	EA	6	\$301	
	Floor Drain	1st floor- Women's Next to engineers office	1	EA	6	\$1,059	
	Floor - Tile	1st floor- Women's Next to engineers office	65	SF	6	\$142	



oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroo	om de la companya de						
	Lavatory	1st floor- Women's Next to engineers office	1	EA	6	\$320	
	Lighting - Lay-in	1st floor- Women's Next to engineers office	1	EA	7	\$0	
	Walls - Concrete Block	1st floor- Women's Next to engineers office	152	SF	6	\$446	
	Water Closet	1st floor- Women's Next to engineers office	1	EA	6	\$336	
	Accessories	2nd floor east- Across from 201	343	SF	6	\$3,164	
	Accessories	2nd floor east -Across from 201	343	SF	6	\$3,164	
	Ceiling - Plaster/Drywall	2nd floor east- Across from 201	343	SF	6	\$1,187	
	Ceiling - Plaster/Drywall	2nd floor east -Across from 201	343	SF	6	\$1,187	
	Floor Drain	2nd floor east- Across from 201	3	EA	6	\$3,177	
	Floor Drain	2nd floor east -Across from 201	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	2nd floor east- Across from 201	343	SF	6	\$726	
	Floor - Tile Ceramic/ Porcelain	2nd floor east -Across from 201	343	SF	6	\$726	
	Hand Dryer	2nd floor east- Across from 201	1	EA	6	\$230	
	Hand Dryer	2nd floor east -Across from 201	1	EA	6	\$230	
	Lavatory	2nd floor east- Across from 201	5	EA	6	\$1,598	
	Lavatory	2nd floor east -Across from 201	5	EA	6	\$1,598	
	Lighting - Lay-in	2nd floor east- Across from 201	11	EA	7	\$0	cove lights & 1 can
	Lighting - Lay-in	2nd floor east -Across from 201	11	EA	7	\$0	cove lights & 1 can
	Partitions	2nd floor east- Across from 201	6	EA	7	\$0	
	Partitions	2nd floor east -Across from 201	3	EA	7	\$0	
	Urinals	2nd floor east -Across from 201	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	2nd floor east- Across from 201	712	SF	6	\$2,240	
	Walls - Structural Glazed Tile	2nd floor east -Across from 201	712	SF	6	\$2,240	
	Water Closet	2nd floor east- Across from 201	6	EA	6	\$2,016	
	Water Closet	2nd floor east -Across from 201	3	EA	6	\$1,008	
	Accessories	2nd floor east- Women Across from 201	73	SF	6	\$673	
	Ceiling - Lay-in	2nd floor east- Women Across from 201	73	SF	6	\$219	
	Doors - Wood Doors inclu hw	2nd floor east- Women Across from 201	1	EA	7	\$0	
	Floor Drain	2nd floor east- Women Across from 201	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor east- Women Across from 201	73	SF	6	\$154	
	Lavatory	2nd floor east- Women Across from 201	1	EA	6	\$320	
	Lighting - Lay-in	2nd floor east- Women Across from 201	1	EA	7	\$0	
	Walls - Concrete Block	2nd floor east- Women Across from 201	272	SF	6	\$797	
	Water Closet	2nd floor east- Women Across from 201	1	EA	6	\$336	
	Accessories	2nd floor west- By 228	298	SF	6	\$2,749	



up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
troo	om						
	Accessories	2nd floor west- By 228	298	SF	6	\$2,749	
	Ceiling - Plaster/Drywall	2nd floor west- By 228	298	SF	6	\$1,031	
	Ceiling - Plaster/Drywall	2nd floor west- By 228	298	SF	6	\$1,031	
	Floor Drain	2nd floor west- By 228	3	EA	6	\$3,177	
	Floor Drain	2nd floor west- By 228	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	2nd floor west- By 228	298	SF	6	\$631	
	Floor - Tile Ceramic/ Porcelain	2nd floor west- By 228	298	SF	6	\$631	
	Hand Dryer	2nd floor west- By 228	1	EA	6	\$230	
	Hand Dryer	2nd floor west- By 228	1	EA	6	\$230	
	Lavatory	2nd floor west- By 228	4	EA	6	\$1,278	
	Lavatory	2nd floor west- By 228	4	EA	6	\$1,278	
	Lighting - Lay-in	2nd floor west- By 228	9	EA	7	\$0	cove lights
	Lighting - Lay-in	2nd floor west- By 228	7	EA	7	\$0	
	Partitions	2nd floor west- By 228	4	EA	7	\$0	
	Partitions	2nd floor west- By 228	3	EA	7	\$0	
	Urinals	2nd floor west- By 228	2	EA	6	\$672	
	Walls - Structural Glazed Tile	2nd floor west- By 228	662	SF	6	\$2,083	
	Walls - Structural Glazed Tile	2nd floor west- By 228	662	SF	6	\$2,083	
	Water Closet	2nd floor west- By 228	3	EA	6	\$1,008	
	Water Closet	2nd floor west- By 228	5	EA	6	\$1,680	
	Accessories	2nd floor west- Men by 228	66	SF	6	\$609	
	Ceiling - Lay-in	2nd floor west- Men by 228	66	SF	6	\$198	
	Doors - Wood Doors inclu hw	2nd floor west- Men by 228	1	EA	6	\$301	
	Floor Drain	2nd floor west- Men by 228	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor west- Men by 228	66	SF	6	\$140	
	Lavatory	2nd floor west- Men by 228	1	EA	6	\$320	
	Lighting - Lay-in	2nd floor west- Men by 228	1	EA	7	\$0	
	Walls - Concrete Block	2nd floor west- Men by 228	260	SF	6	\$762	
	Water Closet	2nd floor west- Men by 228	1	EA	6	\$336	
	Accessories	3rd floor east -Across from Library	343	SF	6	\$3,164	
	Ceiling - Plaster/Drywall	3rd floor east -Across from Library	343	SF	6	\$1,187	
	Floor Drain	3rd floor east -Across from Library	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	3rd floor east -Across from Library	343	SF	6	\$726	
	Hand Dryer	3rd floor east -Across from Library	1	EA	6	\$230	
	Lavatory	3rd floor east -Across from Library	5	EA	6	\$1,598	
	Lighting - Lay-in	3rd floor east -Across from Library	11	EA	7	\$0	
	Partitions	3rd floor east -Across from Library	3	EA	7	\$0	



up Ite	em - Type	Location	Quantity	Unit	Rank	Cost	Comment
troom							
Uı	inals	3rd floor east -Across from Library	3	EA	6	\$1,008	
W	alls - Structural Glazed Tile	3rd floor east -Across from Library	712	SF	6	\$2,240	
W	ater Closet	3rd floor east -Across from Library	3	EA	6	\$1,008	
Ad	ccessories	3rd floor east- Women Across from Library	73	SF	6	\$673	
Ce	eiling - Lay-in	3rd floor east- Women Across from Library	73	SF	6	\$219	
Do	oors - Wood Doors inclu hw	3rd floor east- Women Across from Library	1	EA	6	\$301	
Fl	por Drain	3rd floor east- Women Across from Library	1	EA	6	\$1,059	
Fl	por - Tile Ceramic/ Porcelain	3rd floor east- Women Across from Library	73	SF	6	\$154	
La	ivatory	3rd floor east- Women Across from Library	1	EA	6	\$320	
Lig	ghting - Lay-in	3rd floor east- Women Across from Library	1	EA	7	\$0	
W	alls - Concrete Block	3rd floor east- Women Across from Library	272	SF	6	\$797	
W	ater Closet	3rd floor east- Women Across from Library	1	EA	6	\$336	
Ad	ccessories	3rd floor west- By 328	298	SF	6	\$2,749	
Ac	ccessories	3rd floor west- By 328	298	SF	6	\$2,749	
Ce	eiling - Plaster/Drywall	3rd floor west- By 328	298	SF	6	\$1,031	
Ce	eiling - Plaster/Drywall	3rd floor west- By 328	298	SF	6	\$1,031	
FI	oor Drain	3rd floor west- By 328	3	EA	6	\$3,177	
FI	oor Drain	3rd floor west- By 328	3	EA	6	\$3,177	
FI	oor - Tile Ceramic/ Porcelain	3rd floor west- By 328	298	SF	6	\$631	
FI	oor - Tile Ceramic/ Porcelain	3rd floor west- By 328	298	SF	6	\$631	
Ha	and Dryer	3rd floor west- By 328	1	EA	6	\$230	
Ha	and Dryer	3rd floor west- By 328	1	EA	6	\$230	
La	watory	3rd floor west- By 328	4	EA	6	\$1,278	
La	watory	3rd floor west- By 328	4	EA	6	\$1,278	
Lig	ghting - Lay-in	3rd floor west- By 328	7	EA	7	\$0	
Lig	ghting - Lay-in	3rd floor west- By 328	9	EA	7	\$0	cove lights
Pa	artitions	3rd floor west- By 328	3	EA	7	\$0	
Pa	artitions	3rd floor west- By 328	4	EA	7	\$0	
U	inals	3rd floor west- By 328	2	EA	6	\$672	
W	alls - Structural Glazed Tile	3rd floor west- By 328	662	SF	6	\$2,083	
W	alls - Structural Glazed Tile	3rd floor west- By 328	662	SF	6	\$2,083	



Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Water Closet	3rd floor west- By 328	5	EA	6	\$1,680	
	Water Closet	3rd floor west- By 328	3	EA	6	\$1,008	
	Accessories	3rd floor west- Men by 328	66	SF	6	\$609	
	Ceiling - Lay-in	3rd floor west- Men by 328	66	SF	6	\$198	
	Doors - Wood Doors inclu hw	3rd floor west- Men by 328	1	EA	7	\$0	
	Floor Drain	3rd floor west- Men by 328	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	3rd floor west- Men by 328	66	SF	6	\$140	
	Lavatory	3rd floor west- Men by 328	1	EA	6	\$320	
	Lighting - Lay-in	3rd floor west- Men by 328	1	EA	7	\$0	
	Walls - Concrete Block	3rd floor west- Men by 328	260	SF	7	\$0	
	Water Closet	3rd floor west- Men by 328	1	EA	6	\$336	
	Accessories	Third floor east- Across from Library	343	SF	6	\$3,164	
	Ceiling - Plaster/Drywall	Third floor east- Across from Library	343	SF	6	\$1,187	
	Floor Drain	Third floor east- Across from Library	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	Third floor east- Across from Library	343	SF	6	\$726	
	Hand Dryer	Third floor east- Across from Library	1	EA	6	\$230	
	Lavatory	Third floor east- Across from Library	5	EA	6	\$1,598	
	Lighting - Lay-in	Third floor east- Across from Library	11	EA	7	\$0	
	Partitions	Third floor east- Across from Library	6	EA	6	\$1,782	
	Walls - Structural Glazed Tile	Third floor east- Across from Library	712	SF	6	\$2,240	
	Water Closet	Third floor east- Across from Library	6	EA	6	\$2,016	

Rooms (Other Than Classrooms) Subtotal:

\$597,233

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
Corrido	pr						
	Ceiling - Lay-in	1st Floor	6,880	SF	6	\$20,661	
	Ceiling - Plaster/Drywall	1st Floor	1,067	SF	6	\$6,607	
	Doors - Side-lite	1st Floor	108	EA	6	\$1,805	
	Doors - Steel Doors incl hw	1st Floor	12	EA	6	\$3,612	
	Doors - Store Front	1st Floor	9	EA	6	\$10,874	
	Doors - Transom Window	1st Floor	66	EA	6	\$1,117	
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	6	\$754	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	6	\$551	
	Floor - Terrazzo	1st Floor	7,227	SF	7	\$0	



Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$389	In service hall behind Cafeteria
	Lighting - Lay-in	1st Floor	94	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	\$0	decorative pendants suspended from 2nd floor, hanging down in lobby area
	Lighting - Wall Mounted	1st Floor	10	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	365	EA	6	\$33,885	
	Walls - Concrete Block	1st Floor	14,300	SF	6	\$41,920	
	Walls - Masonry	1st Floor	165	SF	6	\$519	In Main vestibule
	Ceiling - Exposed	2nd Floor	631	SF	7	\$0	In Mechanical Hall
	Ceiling - Lay-in	2nd Floor	6,063	SF	6	\$18,207	
	Ceiling - Plaster/Drywall	2nd Floor	1,042	SF	6	\$6,452	
	Doors - Steel Doors incl hw	2nd Floor	12	EA	6	\$3,612	
	Drinking Fountains - Double Water Cooler	2nd Floor	2	EA	6	\$754	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	6	\$551	
	Floor - Terrazzo	2nd Floor	7,105	SF	6	\$59,640	
	Floor - Tile/Sheet	2nd Floor	631	SF	6	\$343	In Mechanical Hall
	Lighting - Lay-in	2nd Floor	83	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	7	EA	7	\$0	In Mechanical Hall
	Lighting - Wall Mounted	2nd Floor	10	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	542	EA	6	\$50,317	
	Walls - Concrete Block	2nd Floor	11,820	SF	6	\$34,650	
	Ceiling - Exposed	3rd Floor	563	SF	7	\$0	In Mechanical Hall
	Ceiling - Lay-in	3rd Floor	5,633	SF	6	\$16,916	
	Doors - Steel Doors incl hw	3rd Floor	12	EA	6	\$3,612	
	Drinking Fountains - Double Water Cooler	3rd Floor	2	EA	6	\$754	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	6	\$551	
	Floor - Terrazzo	3rd Floor	5,633	SF	6	\$47,284	
	Floor - Tile/Sheet	3rd Floor	563	SF	6	\$306	In Mechanical Hall
	Lighting - Lay-in	3rd Floor	83	EA	7	\$0	
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	\$0	
	Lighting - Wall Mounted	3rd Floor	10	EA	7	\$0	
	Student Lockers - One Tier	3rd Floor	460	EA	6	\$42,704	
	Walls - Concrete Block	3rd Floor	12,260	SF	6	\$35,940	
Safety							
	Camera Viewing Station	1st Floor	4	EA	6	\$2,730	Viewed at all 3 security desk & the MDF
	Metal Dedector	1st Floor	1	EA	6	\$881	
	Security Cameras	1st Floor / Entire Building	62	EA	6	\$12,030	



Category: Building Interior

ıp Iter	m - Туре	Location	Quantity	Unit	Rank	Cost	Comments
ty							
Sec	curity Cameras	1st Floor / Entire Building	29	EA	6	\$5,627	
Sec	curity Cameras	1st Floor / Entire Building	1	EA	5	\$688	not working
S							
Cei	iling - Lay-in	Stairwell A	616	SF	5	\$4,061	
Cei	iling - Plaster/Drywall	Stairwell A	384	SF	6	\$2,811	
Flo	por - Terrazzo	Stairwell A	412	SF	7	\$0	
Har	ndrails	Stairwell A	104	LF	6	\$901	
Lig	hting - Lay-in	Stairwell A	6	EA	7	\$0	
Lig	hting - Wall Mounted	Stairwell A	4	EA	7	\$0	
Sta	airs - Terrazzo	Stairwell A	52	LF	7	\$0	
Wa	alls - Concrete Block	Stairwell A	2,681	SF	6	\$7,859	
Cei	iling - Lay-in	Stairwell B	616	SF	6	\$1,850	
	iling - Plaster/Drywall	Stairwell B	384	SF	6	\$2,811	
	por - Terrazzo	Stairwell B	412	SF	7	\$0	
Har	Indrails	Stairwell B	104	LF	6	\$901	
Ligl	hting - Lay-in	Stairwell B	6	EA	7	\$0	
Lig	hting - Wall Mounted	Stairwell B	4	EA	7	\$0	
Sta	airs - Terrazzo	Stairwell B	52	LF	7	\$0	
Wa	alls - Concrete Block	Stairwell B	2,681	SF	6	\$7,859	
Cei	iling - Lay-in	Stairwell C	616	SF	6	\$1,850	
Cei	iling - Plaster/Drywall	Stairwell C	384	SF	6	\$2,811	
Flo	por - Terrazzo	Stairwell C	412	SF	7	\$0	
Har	Indrails	Stairwell C	104	LF	6	\$901	
Ligl	ihting - Lay-in	Stairwell C	6	EA	7	\$0	
	hting - Wall Mounted	Stairwell C	4	EA	7	\$0	
-	airs - Terrazzo	Stairwell C	52	LF	7	\$0	
Wa	alls - Concrete Block	Stairwell C	2,681	SF	6	\$7,859	
Cei	illing - Exposed	Stairwell D	453	SF	6	\$674	
	oor - Tile	Stairwell D	262	SF	6	\$142	
Har	Indrails	Stairwell D	104	LF	6	\$901	
Ligi	hting - Pendent/Surface	Stairwell D	4	EA	7	\$0	
-	airs - Concrete	Stairwell D	52	LF	6	\$431	
Wa	alls - Concrete Block	Stairwell D	2,650	SF	6	\$7,768	
cal Con	nveyance						
	evator - Hydraulic Elevator	1st Floor	1	EA	6	\$19,238	



Groun	ory: Building Interior Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
		Location	Quantity	Onit	Kalik		Commenta
Bullair	ng Interior Subtotal:					\$538,876	
Total E	Building Cost				\$	3,259,123	
SITE							
Catego	ory: Site						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dra	ainage		-				
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	\$9,845	
	Civil/ Drainage - Site Drain	Entire Site / Main Entrance	10	EA	6	\$3,103	
Fencing							
-	Fencing - New Standard Ornamental	Entire Site	1,485	LF	7	\$0	
Landsca	ape						
	Benches	Entire Site	4	EA	7	\$0	
	Landscape - Grass	Entire Site	21,035	SF	6	\$17,446	
	Landscape - Grass	Entire Site	18,112	SF	5	\$27,454	Sand pit - Sand fills storm drains and migrates throughout landscape and building
	Landscape - Hardscape- Concrete	Entire Site	21,556	SF	6	\$111,279	
	Parkway trees	Entire Site	22	EA	6	\$14,521	
	Planting Beds/ Area	Entire Site	13,692	SF	6	\$22,516	
	Retaining Wall - Concrete	Entire Site	1,008	SF	7	\$0	
Parking	Lot						
	Concrete Curbs	Parking Lot- North	981	LF	6	\$12,597	
	Interior Plantings	Parking Lot- North	80	LF	6	\$3,403	
	Lighting - Pole Mounted	Parking Lot- North	12	EA	7	\$0	
	Surface - Asphalt	Parking Lot- North	11,832	SF	6	\$28,594	
	Surface - Concrete	Parking Lot- North	4,079	SF	6	\$9,858	
	Trash Compactor	Parking Lot- North	1	EA	6	\$0	
	Trash Enclosure - Masonry	Parking Lot- North	912	SF	6	\$35,982	
	Vehicular Screening	Parking Lot- North	280	LF	6	\$22,046	
Sidewall	ks						
	Sidewalks - Internal Walks	Entire Site	688	LF	6	\$8,264	
	Sidewalks - Perimeter Sidewalks	Entire Site	14,843	SF	6	\$29,503	

\$3,615,535

SITE

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Signage							
Flag Pole - Flag Pole	Main entrance	3	EA	7	\$0		
Monument - Building Mounted Cut Letter Sign	Main entrance	1	EA	7	\$0		
Site Subtotal:					\$356,412		
Total Site Cost					\$356,412		

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main	- I	-					ļ	1						
Art Room	Art Room	3rd Floor	323	308	1,268	1	10	20	120	18	40	Ν	Y	Ν
Computer Lab	Computer Lab	2nd Floor	213	220	1,245	1	25	50	160	24	40	Ν	Y	Ν
Computer Lab	Computer Lab	3rd Floor	313	318	1,245	1	25	50	160	24	40	Ν	Y	Ν
Music Room	Music Room	3rd Floor	328	301	1,056	1	10	20	360	0	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	1st Floor	116	115	1,506	1	9	22	122	32	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	118	113	729	1	9	22	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	119	118	838	1	8	32	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	1st Floor	120	111	838	1	8	32	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	1st Floor	121	116	838	1	8	32	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	1st Floor	122	109	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	123	114	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	124	107	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	125	112	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	126	105	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	127	110	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	128	103	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	1st Floor	129	108	838	1	10	34	126	9	40	Y	Y	Y
Regular Classroom	Regular Classroom	1st Floor	130	101	838	1	8	32	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	219	838	1	100	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	212	217	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	215	218	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	216	213	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	217	216	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	218	211	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	219	214	838	1	4	18	126	9	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	220	209	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	221	212	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	222	207	838	1	10	34	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	223	210	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	224	205	838	1	10	34	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	225	208	838	1	10	34	126	9	40	Y	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	226	203	838	1	8	18	126	9	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom	2nd Floor	228	201	838	1	10	34	126	9	40	Y	Ν	Ν
Regular Classroom	Regular Classroom	3rd Floor	315	316	895	1	10	20	120	18	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	316	313	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	317	314	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	318	311	895	1	10	20	120	18	40	Ν	Y	Ν

HERNANDEZ



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main				+										
Regular Classroom	Regular Classroom	3rd Floor	319	312	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	320	309	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	321	310	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	322	307	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	324	305	895	1	10	20	120	18	40	Ν	Y	Ν
Regular Classroom	Regular Classroom	3rd Floor	326	303	895	1	10	20	120	18	40	Ν	Y	Ν
Science Classroom	Science Classroom	3rd Floor	310	310	1,378	1	15	30	160	24	40	N	Y	Ν
Science Lab Level 3	Science Lab Level 3	2nd Floor	200	221	1,609	1	15	30	200	18	40	Ν	Y	Ν
Science Lab Level 3	Science Lab Level 3	2nd Floor	201	223	1,609	1	15	30	200	18	40	Ν	Y	Ν
Science Lab Level 3	Science Lab Level 3	2nd Floor	214	215	1,378	1	15	30	160	24	40	N	Y	Ν
Science Lab Level 3	Science Lab Level 3	3rd Floor	314	315	1,378	1	15	30	160	24	40	Ν	Y	Ν