

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1958	1	13,080
Addition 1	1960	1	3,437
Addition 2	1998	1	11,635
Campus Total			28,152

Category : Exterior Building : Main

						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Entrance Control - Audio	#1 - Main - E	1	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	#1 - Main - E	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 - Main - E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 - Main - E	26	LF	6	10+ years	Inset pavers in field
	Exterior Doors - Exterior Steel Door	#10 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8 - N	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#8 - N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8.5 - N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 - NE	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#9 - NE	87	LF	6	6-10 years	
	Ramps - Concrete	#9 - NE	21	LF	6	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	508	LF	5	6-10 years	
	Foundation - Concrete	Entire Building	30	LF	5	6-10 years	
	Superstructure - Concrete	Entire Building	13,080	SF	6	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
		Ç				•	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	6-10 years	
Roof Sys	stem						
	Chimney - Brick Chimney- Stainless Steel	Main Roof	14	LF	6	2-5 years	
	Liner					•	
	Chimney - Brick Chimney- Stainless Steel	Main Roof	15	LF	5	2-5 years	
	Liner						
	Coping - Metal	Main Roof	178	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	56	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Main Roof	11,141	SF	4	0-1 year	Ponding and bubbles throughout
	Roof Structure - Concrete	Main Roof	11,141	SF	7	10+ years	
	Coping - Metal	NE roof	177	LF	6	6-10 years	
	Downspouts - Interior Downspouts	NE roof	17	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	NE roof	1,939	SF	4	0-1 year	Ponding and bubbles throughout
	Roof Structure - Concrete	NE roof	1,939	SF	7	10+ years	3
			,			, , , , , ,	
Walls							
	Canopy - Metal	Entire Building	234	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	8,072	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	5	SF	5	6-10 years	
Windows							
	Clerestory - Glass Double-Pane	Entire Building	180	SF	7	6-10 years	
	Curtain wall - Louver	Entire Building	20	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,976	SF	6	6-10 years	
	Lintels - Steel	Entire Building	331	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,976	SF	5	2-5 years	
Catago	w Electrical		D	ر د دادان د	. Main		
Catego	ry : Electrical		В	uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	1st Floor	5	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	1st Floor	3	EA	6	6-10 years	
	Stairs Emergency Battery Packs - Lunchrooms	1st Floor	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	1st Floor	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	1st Floor	-	SF	6		
	Stairs	191 11001	1,567	SF	O	6-10 years	
	Emergency A/C Power - Lunchrooms	1st Floor	1,483	SF	6	6-10 years	
	Security System - CCTV	Entire Building	16,157	SF	6	6-10 years	Serves the main and addition 1
	Security System - Intrusion Detection	Entire Building	16,157	SF	6	6-10 years	Serves the main and addition 1
	Scounty System - Intrusion Detection	Little building	10,137	Si	U	o- io yeais	Corves the main and addition i



Catego	ry : Electrical		В	uilding	: Main		-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Main Se	rvice						
	PA System	Entire Building	16,517	SF	6	6-10 years	
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	-		-			•	
1 110 / 1101	Fire Alarm Strobe Lights	Entire Building	13,080	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	litioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	2	EA	6	6-10 years	
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Less than 5 tons	Roof	1	EA	5	6-10 years	Condenser coils need to be cleaned. Rust in the external fresh air Ductwork.
Boiler Sy	ystems						
·	Boiler Auxiliary- Steam Boiler - Less than 50 HP	Entire Building	2	EA	5	6-10 years	Boiler feed pipes have sections of poor/no insulation for B2.
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	•
	Chemical Feeder	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	
	Condensate Pump	Entire Building	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	5	2-5 years	Pumps in good shape. Tank shows ageing
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - Less than	Entire Building	2	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		1710 E 351d 611(EE1, 611)cago, 1E 60017
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	50 HP Piping - Condensate Pipe- Steel	Entire Building	200	LF	6	6 10 years	Inculation at bailer is demaged
	Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Entire Building Entire Building	200	LF LF	5	6-10 years 6-10 years	Insulation at boiler is damaged.
	Steam Traps	Entire Building	26	EA	6	6-10 years	
	Oloum Hapo	g			· ·	o .o you.o	
Gas Boo							
	Gas Booster	Boiler Room	1	EA	6	6-10 years	
Heating	Devices						
	Cabinet Heaters - With Steam Coil	1st Floor	8	EA	6	6-10 years	
	Fin Tube - Steam	Entire Building	100	LF	6	6-10 years	
		9				o .o you.o	
_Tempera	ature Control						
	DDC System	Entire Building	13,080	SF	6	6-10 years	
	Thermostats - DDC	Entire Building	20	EA	6	6-10 years	
_Unit Ven	tilation						
_OTHE VOI	Unit Ventilators- Floor Mounted- Steam	Entire Building	16	EA	6	6-10 years	
	Heating w/ DX Cooling Coil & w/ Self	g	. •		· ·	0 .0 ,00.0	
	Contained Compressors						
\							
_Ventilatio	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	4	EA	6	6-10 years	
	CFM	Rooi	7	LA	O	0-10 years	
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	
	500 CFM					-	
	Roof Mounted Duct Work	Roof	60	LF	5	2-5 years	Duct work for fresh air for RTU is
	Type II Exhaust Hood- Warming Kitchen	Roof	1	EA	6	6-10 years	rusting.
	Type if Exhaust Hood- Warming Nitohen	11001	ı	LA	U	0-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		D.11. D.				0.10	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA EA	6	6-10 years	
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	ΕA	6	6-10 years	
_Piping							
	Domestic Piping-Cold Water Horizontal	Entire Building	13,080	SF	6	6-10 years	
	Lines						
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	13,080	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Lines	Entire Building	13,080	SF	6	6-10 years	



Catego	ry : Plumbing	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sanitary Piping	Entire Building	13,080	SF	6	10+ years	
	Storm Piping	Entire Building	13,080	SF	6	10+ years	
	Vent Piping	Entire Building	13,080	SF	6	10+ years	
<u>.</u> .	_		_				

Category : Room **Building: Main**

Culogo	ry : itooiii			ananig	· Waiii	5	
0	Harry Trans	Laattan	0	HOM	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	AC Unit	1st flr main office suite and Principal office	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr main office suite and Principal office	818	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st flr main office suite and Principal office	4	EA	6	6-10 years	
	Floor - Tile/Sheet	1st flr main office suite and Principal office	818	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st flr main office suite and Principal office	9	EA	7	6-10 years	
	Power Distribution	1st flr main office suite and Principal office	20	EA	7	6-10 years	
	Storage/ Closet	1st flr main office suite and Principal office	67	SF	7	6-10 years	
	Walls - Concrete Block	1st flr main office suite and Principal office	1,792	SF	6	6-10 years	
	AC Unit	Teacher's Lounge beside boys restroom	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Teacher's Lounge beside boys restroom	307	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Teacher's Lounge beside boys restroom	2	EA	6	6-10 years	
	Floor - Tile	Teacher's Lounge beside boys restroom	307	SF	7	6-10 years	
	Lighting - Pendent/Surface	Teacher's Lounge beside boys restroom	4	EA	7	6-10 years	
	Power Distribution	Teacher's Lounge beside boys restroom	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Teacher's Lounge beside boys restroom	700	SF	7	6-10 years	
	Work Sink	Teacher's Lounge beside boys restroom	1	EA	7	6-10 years	
Kitchen							
	Ceiling - Lay-in	1st Floor	519	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	

Campus Name: Earhart Page : 5 of 24 Assessment Date: 09/12/2019



Catego	ry : Room		В	uilding	: Main		17 10 E 9310 3 TREET, Chicago, IL 60617
carege	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Tile	1st Floor	519	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Serving Line	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	37	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	804	SF	7	6-10 years	
Lunch &	Multipurpose Room						
	AC Unit	Room 101	1	EA	7	6-10 years	
	Ceiling - Lay-in	Room 101	1,483	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Room 101	3	EA	6	6-10 years	
	Floor - Tile	Room 101	1,483	SF	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	Room 101	1,403	EA	7	6-10 years	
	Storage/ Closet	Room 101	240	SF	7	6-10 years	
	Walls - Concrete Block	Room 101	4,020	SF	7	6-10 years	
	Walls - Collete Block	Noom 101	4,020	Oi	,	0-10 years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	37	SF	5	6-10 years	
	Storage Room	1st Floor	37	SF	5	6-10 years	
	Boiler Room	Basement	810	SF	5	6-10 years	
	Crawl Space - Unfinished	Basement	5,800	SF	5	6-10 years	
_Restroor	n						
	Accessories	1st floor inside Kindergarten Room #102	21	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside Kindergarten Room #102	21	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st floor inside Kindergarten Room #102	1	EA	6	6-10 years	
	Floor - Tile/Sheet	1st floor inside Kindergarten Room #102	21	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st floor inside Kindergarten Room #102	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor inside Kindergarten Room #102	160	SF	7	6-10 years	
	Walls - Concrete Block	1st floor inside Kindergarten Room #102	3	SF	5	2-5 years	chipped paint
	Water Closet	1st floor inside Kindergarten Room #102	1	EA	7	6-10 years	
	Accessories	1st floor inside principal's office	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside principal's office	42	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st floor inside principal's office	1	ĒΑ	6	6-10 years	
	Floor - Tile/Sheet	1st floor inside principal's office	42	SF	7	6-10 years	
	Lavatory	1st floor inside principal's office	1	ĒΑ	6	6-10 years	
						-	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st floor inside principal's office	1	EA	7	6-10 years	
	Partitions	1st floor inside principal's office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor inside principal's office	224	SF	7	6-10 years	
	Water Closet	1st floor inside principal's office	1	EA	7	6-10 years	
	Accessories	Boy's Room, 1st Floor	265	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boy's Room, 1st Floor	265	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Boy's Room, 1st Floor	4	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boy's Room , 1st Floor	265	SF	6	6-10 years	
	Floor Drain	Boy's Room, 1st Floor	1	EA	7	6-10 years	
	Lavatory	Boy's Room, 1st Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	Boy's Room, 1st Floor	2	EA	7	6-10 years	
	Partitions	Boy's Room, 1st Floor	2	EA	7	6-10 years	
	Urinals	Boy's Room, 1st Floor	5	EA	7	6-10 years	
	Walls - Masonry	Boy's Room, 1st Floor	174	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Boy's Room, 1st Floor	520	SF	6	6-10 years	
	Water Closet	Boy's Room , 1st Floor	2	EA	7	6-10 years	
	Accessories	Girl's Room, 1st Floor	265	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girl's Room , 1st Floor	262	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Girl's Room , 1st Floor	3	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Girl's Room , 1st Floor	4	ĒΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Girl's Room , 1st Floor	265	SF	7	6-10 years	
	Floor Drain	Girl's Room, 1st Floor	1	ĒΑ	7	6-10 years	
	Lavatory	Girl's Room , 1st Floor	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Girl's Room , 1st Floor	2	ĒΑ	7	6-10 years	
	Partitions	Girl's Room , 1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	Girl's Room , 1st Floor	3	SF	7	6-10 years	
	Walls - Concrete Block	Girl's Room , 1st Floor	174	SF	7	6-10 years	
	Walls - Structural Glazed Tile	Girl's Room , 1st Floor	520	SF	7	6-10 years	
	Water Closet	Girl's Room , 1st Floor	7	EA	7	6-10 years	
	Accessories	In the Kitchen Area	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Kitchen Area	49	SF	6	6-10 years	
	Doors - Steel Doors incl hw	In the Kitchen Area	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	In the Kitchen Area	49	SF	6	6-10 years	
	Lavatory	In the Kitchen Area	1	EA	7	6-10 years	
	Lighting - Lay-in	In the Kitchen Area	1	EA	7	6-10 years	
	Walls - Concrete Block	In the Kitchen Area	78	SF	6	6-10 years	
	Walls - Plaster/Drywall	In the Kitchen Area	26	SF	6	6-10 years	
	Water Closet	In the Kitchen Area	1	EA	7	6-10 years	
	Accessories	In the Teacher's Lounge Area	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Teacher's Lounge Area	44	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	In the Teacher's Lounge Area	1	EA	6	10+ years	
	Floor - Tile	In the Teacher's Lounge Area	1 44	SF	7	6-10 years	
		In the Teacher's Lounge Area	1	SF EA	6	6-10 years 6-10 years	
	Lighting - Pendent/Surface	•	1	EA	7	-	
	Lighting - Pendent/Surface	In the Teacher's Lounge Area	1	EA	1	6-10 years	



	ry : Room			uilding	. IVICIII		
	_				_	Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	In the Teacher's Lounge Area	1	EA	7	6-10 years	
	Partitions	In the Teacher's Lounge Area	1	EA	7	6-10 years	
	Walls - Concrete Block	In the Teacher's Lounge Area	79	SF	7	6-10 years	
	Water Closet	In the Teacher's Lounge Area	1	EA	7	6-10 years	
atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #102 (Kindergarten)	4 . =					
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	72	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,216	SF	6	6-10 years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor		EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,216	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,020	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroc	m #103 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	798	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	2	SF	6	2-5 years	chipped paint
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	800	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Masonry	1st Floor	1,142	SF	7	6-10 years	
Classroo	m #104 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	380	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	380	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	716	SF	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
			•	_, .	•	o .o jouro	
	m #105 (Computer Lab)						



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	800	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,142	SF	7	6-10 years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
_Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	829	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1	SF	6	2-5 years	chipped paint
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years	or the contract of the contrac
	Floor - Tile/Sheet	1st Floor	830	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	880	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	20	SF	6	2-5 years	chipped paint
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	830	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	900	SF	7	6-10 years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	830	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	900	SF	7	6-10 years	
Catego	ry : Interior		В	uilding	: Main		
Group		Location	Quantity	UOM	Rank	Recommend	Comments
O. 54p		20000011	- Quantity		- Carin		



						Replacement
_Corridor						
	Ceiling - Splined	1st Floor	1,567	SF	6	6-10 years
	Doors - Wood Doors include hw	1st Floor	4	EΑ	7	6-10 years
	Drinking Fountains - Double Fountain	1st Floor	1	EΑ	7	6-10 years
	Floor - Tile/Sheet	1st Floor	1,576	SF	7	6-10 years
	Lighting - Pendent/Surface	1st Floor	17	EΑ	7	6-10 years
	Walls - Concrete Block	1st Floor	3,014	SF	7	6-10 years
Safety						
•	Camera Viewing Station	1st floor & Exterior of the building	3	EA	7	6-10 years
	Security Cameras	1st floor & Exterior of the building	3	EA	7	6-10 years
	Security Cameras	1st floor & Exterior of the building	8	EA	7	6-10 years



Category : Exterior		В	uilding	: Addition			
0	Name Time	l a satism	0	LIOM	Danie	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	Exterior Doors - Exterior Steel Door	#3 - S	2	EA		6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - S #3 - S	2	EA	6		
	Exterior Stairs - Concrete	#3 - S #3 - S	1 60	LF	6	6-10 years	
		#3 - S #3 - S		LF LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail		15 7	LF	6 6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - S	1	LF	6	6-10 years	
Foundation	on						
	Foundation - Concrete	Entire Building	122	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	5	6-10 years	
	Foundation - Concrete	Entire Building	10	LF	5	6-10 years	
	Superstructure - Concrete	Entire Building	3,437	SF	7	10+ years	
Lighting							
gg	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
Roof Sys							
	Coping - Metal	Main Roof	142	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Main Roof	14	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Main Roof	3,437	SF	4	0-1 year	Ponding and bubbles throughout
	Roof Structure - Concrete	Main Roof	3,437	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	28	SF	6	6-10 years	
	Cheek-Wall - Concrete	Entire Building	40	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,988	SF	6	10+ years	
\A <i>!</i> '		-				•	
Windows	Curtain wall - Louver	Entire Building	6	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	624	SF	6	2-5 years	
	Lintels - Steel	Entire Building	96	SF LF	5		
	Windows - Sash Aluminum Double-pane	Entire Building	624	SF	5 5	10+ years	
	windows - Sash Aluminum Double-parie	Entire building	024	SF	5	2-5 years	
Categor	ry : Electrical		В	uilding	: Additio		
0	Hom. Time	Laastian	Ouartitus	LION	Dowl	Recommend	Community
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
⊏mergen	Cy System	1et Floor		ΓΛ		6.10 years	
	Exit Signs - Corridors and Stairs	1st Floor	3	EΑ	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	
	Sialis						



ALL A	SCHOOIS						1710 E 93rd STREET, Chicago, IL 60617
Catego	ry : Electrical		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
or or ap	Emergency A/C Power - Corridors and Stairs	Entire Building	432	SF	6	6-10 years	
Main Se	rvice						
	PA System	Entire Building	3,437	SF	6	6-10 years	
	·	Č				•	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uildina	: Additi	on 1	
Juligo			_	anding	. / taaiti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	-				- 101111		
<u> </u>	Fire Alarm Strobe Lights	Entire Building	3,437	SF	6	6-10 years	
Catogo	ry : Mechanical		D	uildina	: Additi	on 1	
Calego	i y . Micchailleai			unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
J	Cabinet Heaters - With Hot Water Coil Unit Heater - Steam	1st Floor Entire Building	1 1	EA EA	6 6	6-10 years 6-10 years	
Tempera	ature Control						
	DDC System	Entire Building	3,427	SF	6	6-10 years	
	Thermostats - DDC	Entire Building	3	EA	6	6-10 years	
Unit Ven	tilation						
Onit ven	Unit Ventilators- Floor Mounted- Steam	1st Floor	3	EA	6	6-10 years	
	Heating Coils Only	151 F1001	3	EA	0	6-10 years	
Ventilation	on.						
venillalli	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6 10 2000	
	CFM	Entire Building	ı	EA	0	6-10 years	
Cotoco	ru - Classroom		ь	uildina	. A dd:4:	on 1	
Calego	ry : Classroom		D	unung	: Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	om #109 (Regular Classroom)						
VICISTIVE	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
			•		Ü	5 .5 ,00.0	

Campus Name: Earhart Page : 12 of 24 Assessment Date: 09/12/2019



Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	800	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,142	SF	7	6-10 years	
Classroc	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	830	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	900	SF	7	6-10 years	
Classroc	om #112 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	800	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	800	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,142	SF	7	6-10 years	
atego	ry : Interior		В	Building : Addition 1			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							

Calego	ıy. IIIL e rioi		DI	ununng	. Auditi	JII I		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor	432	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	6-10 years		
	Floor - Tile/Sheet	1st Floor	432	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	939	SF	7	6-10 years		



Category : Exterior	Building:	Addition 2
---------------------	-----------	------------

Salego	ry . Exterior		Building . Addition 2						
_			A			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance									
	Exterior Doors - Exterior Steel Door	#4 - NE	1	EA	6	6-10 years			
	Exterior Doors - Exterior Steel Door	#5 - E	1	EA	6	6-10 years			
	Entrance Control - Audio	#6 - SE	1	EA	7	2-5 years			
	Exterior Doors - Exterior Steel Door	#6 - SE	2	EA	6	6-10 years			
	Power Door Operator and Controls	#6 - SE	1	EA	4	1-2 years	Beyond service life		
i aula 4i na au									
ighting	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	6-10 years			
	Extends Eighting Train Mountou	Litaro Bananig		_, .	Ü	0 10 90010			
Roof Sys									
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years			
	Chimney - Metal Flue	Main Roof	42	LF	5	6-10 years			
	Coping - Stone	Main Roof	385	LF	6	6-10 years			
	Downspouts - Interior Downspouts	Main Roof	96	LF	6	10+ years			
	Parapet - Parapet > 30"	Main Roof	385	LF	6	6-10 years			
	Roof - Modified Bitumen	Main Roof	8,504	SF	4	0-1 year	bubbles, soft spots, wrinkles		
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Main Roof	8,504	SF	7	10+ years			
	Concrete Topping		•			,			
	Access Ladder - Metal	Upper roof	1	EA	7	10+ years			
	Coping - Stone	Upper roof	229	LF	6	6-10 years			
	Downspouts - Interior Downspouts	Upper roof	50	LF	6	6-10 years			
	Parapet - 16" - 30" Height	Upper roof	229	LF	6	10+ years			
	Roof - Modified Bitumen	Upper roof	3,131	SF	6	6-10 years			
	Roof Structure - Steel / Metal Deck/	Upper roof	3,131	SF	7	10+ years			
	Concrete Topping	Оррен тоог	0,101	O.	,	101 years			
Malla									
Valls	Canopy - Metal	Entire Building	24	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	9,917	SF	6	•			
	EXIGNOLVIANS - DITCK	Entire building	9,917	SF	Ū	10+ years			
Vindows	3								
	Clerestory - Glass Double-Pane	Entire Building	228	SF	6	10+ years			
	Clerestory - Glass Double-Pane	Entire Building	12	SF	5	2-5 years			
	Curtain wall - Louver	Entire Building	42	SF	6	6-10 years			
	Guard - Guards perforated	Entire Building	736	SF	6	6-10 years			
	Lintels - Steel	Entire Building	115	LF	6	10+ years			
	Windows - Sash Aluminum Double-pane	Entire Building	736	SF	5	2-5 years			
	Timasiis Gaoil / Ilaniiniani Boabie pano	Zita Dananig	700	0.	J	2 0 yours			



Category : Electrical				Building : Addition 2				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Emerger	ncy System							
	Exit Signs - Corridors and Stairs	1st Floor	6	EA	6	6-10 years		
	Exit Signs - Gym	1st Floor	4	EA	6	6-10 years		
	Emergency Battery Packs - Corridors and Stairs	1st Floor	4	EA	6	6-10 years		
	Emergency Battery Packs - Gym	1st Floor	6	EA	6	6-10 years		
	Emergency Battery Packs - Students Toilets	1st Floor	2	EA	6	6-10 years		
	Emergency A/C Power - Corridors and Stairs	1st Floor	1,423	SF	6	6-10 years		
	Emergency A/C Power - Gym	1st Floor	3,089	SF	6	6-10 years		
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years		
	Security System - CCTV	Entire Building	11,635	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	11,635	SF	6	6-10 years		
_Main Se								
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Serves Main and Additions	
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves Main and Additions	
Power D	vistribution							
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	6-10 years		
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	6-10 years		
	Lighting and Power Panels - Above 100 A	Electrical Room	2	EA	6	6-10 years		
	Lighting and Power Panels - Above 100 A	Electrical Room	3	EA	6	6-10 years		
	Lighting and Power Panels - Above 100 A	Electrical Room	1	EA	6	6-10 years		
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	6	6-10 years		
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	6	6-10 years		
	Transformers - 120/240 - 120/208	Electrical Room	1	EA	6	6-10 years		
Catego	ry : Fire Protection		В	uilding	: Additi			
					_	Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar								
	Fire Alarm Panel	Engineer's Office, Entire Building, Boiler Room	1	EA	6	6-10 years		
	Fire Alarm Strobe Lights	Engineer's Office, Entire Building, Boiler Room	11,635	SF	6	6-10 years		
	Fire Alarm_System	Engineer's Office, Entire Building, Boiler Room	11,635	SF	6	6-10 years		
	Fire Pump Controller	Engineer's Office, Entire Building,	1	EA	6	6-10 years		

Boiler Room



Category : Fire Protection			В	uilding			
			.			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Boiler Room	1	EA	6	6-10 years	
	Jockey Pump	Boiler Room	1	EA	6	6-10 years	
Sprinkle	r System						
•	Sprinkler Heads	Entire Building	11,635	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	11,635	SF	7	6-10 years	
	Wet Sprinkler System	Entire Building	11,635	SF	7	6-10 years	
Catego	ory : Mechanical		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	ditioning					•	
	Condensing Unit- Roof Mounted - 31-50 tons	Entire Building	1	EA	4	1-2 years	1 of the 2 compressors does not work.
Air Hand	lling Systems						
	Air Handling Unit- Package Multi Zone- Indoor- Hot Water and DX Cooling Coils - 6000-10000 cfm	Boiler Room & 1st floor	1	EA	6	6-10 years	
	Air Intake	Boiler Room & 1st floor	1	EA	6	6-10 years	
	Auxiliaries - 6000-10000 cfm	Boiler Room & 1st floor	1	EA	5	6-10 years	Rusting/ poor insulation in Hot water supply Lines and near drain
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	6	EA	6	6-10 years	Supply Enloc and rical drain
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	1	EA	4	0-1 year	Fan does not work. No cooling currently for the MDF room
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating & DX Cooling w/ Remote Mounted Compressor - 5 - 10 tons	Plenum	2	EA	5	6-10 years	Units are over 20 years old
Boiler S	ystems						
·	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Entire Building	2	EA	6	6-10 years	
	Chemical Pot Feeder	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	
	Glycol Feed System	Entire Building	1	EΑ	6	6-10 years	
	Hot Water Pump	Entire Building	2	EA	6	6-10 years	
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 500 - 1000 MBH	Entire Building	2	EA	6	6-10 years	



Catego	Category : Mechanical			uilding	: Additi	on 2	
	· _				_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Unit Heater - Hot Water	Boiler Room	1	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	16	LF	6	6-10 years	
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	6-10 years	
_Tempera	ature Control						
·	DDC System	Entire Building	11,635	SF	5	6-10 years	Software upgrade required.
	Thermostats - DDC	Entire Building	11	EA	6	6-10 years	
_Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	6	6-10 years	
	Roof Mounted Duct Work	Roof	30	LF	5	2-5 years	Economizer duct work for the 2 RTUs (12 ft + 8 ft)

Category: Plumbing

Building: Addition 2

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	,	Location	Qualitity	OOM	Italik	Replacement	Comments
_Hot Wate							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Cold Water Horizontal	Entire Building	11,635	SF	6	6-10 years	
	Lines	3	,	_		, , , , , , ,	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	11,635	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Lines	Entire Building	11,635	SF	6	6-10 years	
	Sanitary Piping	Entire Building	11,635	SF	6	6-10 years	
	Storm Piping	Entire Building	11,635	SF	6	6-10 years	
	Vent Piping	Entire Building	11,635	SF	6	6-10 years	
	. •	· ·				·	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	



Category : Room			В	uildina	: Additi	on 2	17 10 E 3314 OTREET, Officago, 12 00017
ge	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	1st flr #111	208	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st flr #111	12	SF	5	2-5 years	stained due to water leakage
	Doors - Wood Doors inclu hw	1st flr #111	1	EA	6	6-10 years	3
	Floor - Tile/Sheet	1st flr #111	220	SF	7	6-10 years	
	Lighting - Lay-in	1st flr #111	2	EA	7	6-10 years	
	Power Distribution	1st flr #111	6	EΑ	6	6-10 years	
	Walls - Concrete Block	1st flr #111	627	SF	7	6-10 years	
	Ceiling - Lay-in	Multipurpose Room Office	79	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Multipurpose Room Office	10	SF	5	2-5 years	stained due to water leakage
	Doors - Steel Doors incl hw	Multipurpose Room Office	1	EA	6	6-10 years	
	Floor - Tile	Multipurpose Room Office	89	SF	6	6-10 years	
	Lighting - Lay-in	Multipurpose Room Office	1	EA	7	6-10 years	
	Power Distribution	Multipurpose Room Office	2	EΑ	7	6-10 years	
	Walls - Concrete Block	Multipurpose Room Office	174	SF	7	6-10 years	
	Ceiling - Lay-in	Office, Room 122	91	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Office, Room 122	6	SF	5	2-5 years	stained due to water leakage
	Doors - Steel Doors incl hw	Office, Room 122	1	EΑ	6	6-10 years	
	Floor - Tile	Office, Room 122	97	SF	6	6-10 years	
	Lighting - Lay-in	Office, Room 122	1	EA	7	6-10 years	
	Power Distribution	Office, Room 122	4	EA	7	6-10 years	
	Walls - Concrete Block	Office, Room 122	167	SF	7	6-10 years	
Gymnas	ia						
,	Ceiling - Exposed	1st Floor	3,089	SF	6	6-10 years	
	Floor - Sport Flooring	1st Floor	3,089	SF	7	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	173	SF	7	6-10 years	
	Walls - Masonry	1st Floor	4,628	SF	7	6-10 years	
MDF ID	F						
<u></u>	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Finishes	1st Floor	345	SF	5	6-10 years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	587	SF	5	6-10 years	
	Janitor's Closet	1st Floor	42	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	480	SF	7	6-10 years	
	Storage Room	1st Floor	83	SF	5	6-10 years	
Restroor	_						
_rzesi100I	Accessories	1st Floor	256	SF	7	6-10 years	
	70069901169	13(1100)	230	J۲	,	u- iu yeais	

Campus Name: Earhart Page : 18 of 24 Assessment Date: 09/12/2019



Catego	ry : Room	<u> </u>	Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	256	SF	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	256	SF	6	6-10 years		
	Floor Drain	1st Floor	2	EΑ	7	6-10 years		
	Lavatory	1st Floor	2	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years		
	Partitions	1st Floor	3	EA	7	6-10 years		
	Urinals	1st Floor	3	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	662	SF	7	6-10 years		
	Water Closet	1st Floor	3	EA	7	6-10 years		
	Accessories	1st Floor	256	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	256	SF	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	256	SF	6	6-10 years		
	Floor Drain	1st Floor	2	EA	7	6-10 years		
	Lavatory	1st Floor	2	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	3	EΑ	7	6-10 years		
	Partitions	1st Floor	6	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	662	SF	7	6-10 years		
	Water Closet	1st Floor	6	EA	7	6-10 years		
	Accessories	1st Floor	76	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	76	SF	7	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	76	SF	7	6-10 years		
	Floor Drain	1st Floor	1	EΑ	7	6-10 years		
	Lavatory	1st Floor	1	EΑ	7	6-10 years		
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	180	SF	7	6-10 years		
	Walls - Concrete Block	1st Floor	4	SF	5	2-5 years	chipped paint	
	Water Closet	1st Floor	1	EA	7	6-10 years		

Category : Classroom **Building: Addition 2**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	om #114 (Regular Classroom)						
	Casework	1st Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	975	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	975	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,216	SF	7	6-10 years	

Classroom #116 (Regular Classroom)



Lighting - Lay-in Walls - Concrete Block

Amelia Earhart Options for Knowledge ES 1710 E 93rd STREET, Chicago, IL 60617

	oci ioois						1710 E 93rd STREET, Chicago, IL 606
Category : Classroom			В	uilding	: Additi		
				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	971	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	4	SF	5	2-5 years	stained sue to water leakage
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	975	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,216	SF	7	6-10 years	
Classroc	om #118 (Regular Classroom)						
	Casework	1st Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	975	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	975	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	5	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,216	SF	7	6-10 years	
Classroc	nm #120 (Regular Classroom)						
	Casework	1st Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	975	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	975	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	5	6-10 years	
	Student Lockers - Two Tiers	1st Floor	36	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,216	SF	7	6-10 years	
atego	ry : Interior		В	uilding	: Additi	on 2	
	Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		=					
	Ceiling - Lay-in	1st Floor	1,423	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	6-10 years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,423	SF	7	6-10 years	
	Limination I accion	4 - 4	4.4	L V	7	C 10	

Campus Name: Earhart Page : 20 of 24 Assessment Date: 09/12/2019

11 EA

2,934 SF

7

6-10 years

6-10 years

1st Floor

1st Floor



Category : Interior			Вι				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Safety	Security Cameras Security Cameras	Interior exterior	1 3	EA EA	7	6-10 years 6-10 years	

Campus Name: Earhart Page : 21 of 24 Assessment Date: 09/12/2019



Category : Site		Building : Site						
	Recomme							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Civil/Drai								
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	6-10 years		
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	6-10 years		
_Fencing								
r choing	Fencing - Chain Link	Entire Site	789	LF	6	6-10 years		
	Fencing - Chain Link	Entire Site	30	LF	4	1-2 years		
	Fencing - Chain Link	Entire Site	120	LF	4	1-2 years		
	Fencing - New Standard Ornamental	Entire Site	782	LF	6	6-10 years		
	G					•		
Landsca								
	Landscape - Grass	Entire Site	27,663	SF	6	6-10 years		
	Parkway trees	Entire Site	29	EA	6	10+ years		
	Planting Beds/ Area	Entire Site	2,775	SF	6	6-10 years		
	Play Area - Asphalt/ Hardscape	Entire Site	23,789	SF	4	1-2 years		
Parking I	ot							
	Surface - Asphalt	Parking Lot- North	9,729	SF	4	1-2 years		
	Surface - Concrete	Parking Lot- North	1,900	SF	5	1-2 years		
	Trash Enclosure - Masonry	Parking Lot- North	216	SF	5	6-10 years		
<u> Playgrou</u>	nd						_	
	Equipment - School Age 5-12	North	1	EA	5	1-2 years		
	Surface - Poured Surface	North	2,354	SF	7	6-10 years		
Sidewalk	e							
_ CIGEWalk	Sidewalks - Internal Walks	Entire Site	178	LF	7	6-10 years		
	Sidewalks - Internal Walks	Entire Site	20	LF	5	6-10 years		
	Sidewalks - Perimeter Sidewalks	Entire Site	5,325	SF	6	6-10 years		
0:								
_Signage	Flor Pole Flor Pole	Courth coot	4	ΕΛ		0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	Flag Pole - Flag Pole	Southeast	1	EΑ	6	6-10 years		
	Marquee - Free Standing Back Lighted	Southeast Southeast	1	EA EA	6 6	10+ years		
	Monument - Building Mounted Cut Letter Sign	Southeast	1	EA	Ö	10+ years		

Campus Name: Earhart Page : 22 of 24 Assessment Date: 09/12/2019

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.







Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Earhart Page: 23 of 24 Assessment Date: 09/12/2019





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-		
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board		
Building : Main											
Computer Lab	Regular Classroom	1st Floor	105	105	800	135	63	N	N		
Kindergarten	Kindergarten	1st Floor	102	102	1,216	432	208	N	N		
Library	Regular Classroom	1st Floor	103	103	800	135	63	N	N		
Office	Regular Classroom	1st Floor	104	104	380	81	39	N	N		
Regular Classroom	Regular Classroom	1st Floor	106	106	830	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	107	108	830	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	108	110	830	216	104	N	N		
Building : Addition 1											
Regular Classroom	Regular Classroom	1st Floor	109	107	800	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	110	112	830	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	112	109	800	216	104	N	N		
Building : Addition 2											
Regular Classroom	Regular Classroom	1st Floor	114	114	975	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	116	116	975	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	118	118	975	216	104	N	N		
Regular Classroom	Regular Classroom	1st Floor	120	120	975	216	104	N	N		