

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1956	3	20,650
Leased-Branch	1956	2	22,322
Campus Total			42,972

Catego	Category : Exterior			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	Entrance 2 - SW	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Main entrance 1 - East	1	EΑ	7	10+ years	
	Exterior Doors - Store Front	Main entrance 1 - East	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main entrance 1 - East	18	EA	6	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	350	LF	7	10+ years	
	Foundation - Concrete	Entire Building	5	LF	5	0-1 year	Foundation wall concrete has fault exposing reinforcement
	Superstructure - Steel	Entire Building	19,861	SF	7	10+ years	exposing reinforcement
Lighting							
	Exterior Lighting - Wall Mounted	East Façade	6	EA	6	10+ years	Ceiling mounted
	Exterior Lighting - Wall Mounted	East Façade	2	EA	4	0-1 year	Ceiling mounted, Damaged
Roof Sys	tem						
,	Chimney - Brick Chimney- Concrete/ Mortar Liner	Entire Building	9	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Entire Building	31	LF	6	10+ years	
	Coping - Metal	Entire Building	105	LF	6	10+ years	
	Coping - Metal	Entire Building	345	LF	6	10+ years	

Page: 1 of 30





$\overline{}$	ry - Exterior		В	uildina	. Main	4	946 S Paulina STREET, Chicago, IL 60609
Catego	ry : Exterior		D	uilding	. Iviain	Decemmend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Downspouts - Interior Downspouts	Entire Building	180	LF	6	Replacement 10+ years	Comments
	Roof - Modified Bitumen	Entire Building	13	SF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	7,100	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Entire Building	7,100	SF	7	10+ years	
	Concrete Topping	Little ballating	7,113	Oi	,	10+ years	
Walls							
vvalis	Exterior Walls - Brick	Entire Building	4,655	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	5	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	1,737	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	45	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	10	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	207	SF	5	10+ years	
_Windows							
'	Curtain wall - Glazed Double Pane	Entire Building	150	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	2,433	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	288	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	742	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	745	SF	6	10+ years	
	Lintels - Steel	Entire Building	10	LF	6	10+ years	
	Lintels - Steel	Entire Building	550	LF	6	10+ years	
	Lintels - Steel	Entire Building	166	LF	6	10+ years	
	Windows - Louver	Entire Building	50	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	48	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,592	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	100	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	32	SF	3	0-1 year	The caulking at this window needs to be replaced, and the new cover for the space between the windows needs to be procured
Catego	ry : Electrical		R	uilding	· Main		
Jaiogo	. , . =		_	ag		Recommend	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
·	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves main building
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,203	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,200	SF	6	10+ years	Building has an EM panel
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	- '
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years	
	Room						
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	2	0-1 year	No battery
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	No battery
	Exit Signs - Multipurpose Room	Entire Building	2	EA	2	0-1 year	No battery
	Security System - CCTV	Entire Building	20,650	SF	6	6-10 years	-
	Security System - Intrusion Detection	Entire Building	20,650	SF	6	6-10 years	
Main Sei	vice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	7	10+ years	Serves main building
	120/208/3PH	E 41 B 11 P		- 4	•	4.0	D "I " A TO
	Independent Electrical Service for	Entire Building	1	EA	6	10+ years	Building has an ATS
	emergency power	Fadas Buildia	20.0=2	0-	^	0.40	Opening and the St. P.
	PA System	Entire Building	20,650	SF	6	6-10 years	Serves main building
Power D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	
	amp						
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building
	Fire Alarm Strobe Lights	Entire Building	20,650	SF	6	10+ years	•
	Fire Alarm_System	Entire Building	20,650	SF	5	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
_		Laastian				Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2 serves cafeteria
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1 serves gym
	Air Intake	Mechanical Room	2	EA	5	10+ years	
	All Illiane	Mechanical Room	2		5	10+ years	

# **Peace & Education Coalition HS**

Catego	ry : Mechanical		E	uilding	: Main	·	546 61 ddillid 611(EE1, 6116dg6, 1E 6666
30						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Scotch Marine- Hot Water	Boiler Room	1	EA	6	6-10 years	
	Boiler - 1000 - 2000 MBH						
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	Manual
	Non Condensing- Scotch Marine- Hot Water	Boiler Room	1	EA	6	6-10 years	Serves main building
	Boiler - 1000 - 2000 MBH	5 " 5			•	40	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
_Heating_	Devices						
	Fin Tube - Hot Water	Entire Building	620	LF	5	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	5	6-10 years	
_Mechani	ical Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	10+ years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	10+ years	
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
Tempera	ature Control						
	Electric Controls	Entire Building	1	SF	5	6-10 years	Not upgraded, local programmable
		g	•	٠.	ŭ	0 .0 ,00.0	controllers for air handlers
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve air handlers
	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Serves boiler controls
		Ŭ				•	
Unit Ven							
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	8	EA	4	2-5 years	Deteriorated, old, not reliable, with
	Heating Coils Only						integral thermostats
_Ventilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	5	6-10 years	Serve restrooms
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	10+ years	
	CFM						
	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	4	2-5 years	Deteriorated, noisy, serve restrooms
	500 CFM						
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	· · · · · · · · · · · · · · · · · · ·	Location	Quantity	CON	IVAIIN	Replacement	Comments
_Hot Wate	er Gas Heater  - Less than 150000 BTU/HR	Deiler Deem	4	Ε^		0.40	Company maning brothelings
	Gas Healer - Less than 150000 BTO/HR	Boiler Room	1	EA	6	6-10 years	Serves main building
_Piping							
<del>pg</del>	Domestic Piping-Cold Water Horizontal	Entire Building	20,650	SF	6	10+ years	
	Lines	3	.,		-	,	
	Domestic Piping-Cold Water Risers	Entire Building	20,650	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to	Entire Building	20,650	SF	6	10+ years	
	Fixtures						
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	20,650	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	20,650	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	20,650	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	20,650	SF	6	10+ years	
	Fixtures	ŭ				•	
	Sanitary Piping	Entire Building	20,650	SF	6	10+ years	
	Storm Piping	Entire Building	20,650	SF	6	10+ years	
	Vent Piping	Entire Building	20,650	SF	6	10+ years	
_Pumps							
	Pumps - Ejector-Simplex	Boiler Room	1	EA	5	6-10 years	

Category : Room Building : Main

Group	Itom Tuno	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	1-B	218	SF	6	10+ years	
	Doors - Steel Doors incl hw	1-B	1	EA	6	10+ years	
	Floor - Tile	1-B	218	SF	6	10+ years	
	Lighting - Pendent/Surface	1-B	2	EA	7	10+ years	
	Power Distribution	1-B	8	EA	6	10+ years	
	Walls - Plaster/Drywall	1-B	392	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1-C	110	SF	6	10+ years	
	Doors - Steel Doors incl hw	1-C	1	EΑ	6	10+ years	
	Floor - Tile	1-C	110	SF	6	10+ years	
	Lighting - Pendent/Surface	1-C	1	EΑ	7	10+ years	
	Power Distribution	1-C	4	EA	6	10+ years	
	Walls - Plaster/Drywall	1-C	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1.5 Floor - Office 2-I	230	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - Office 2-I	1	EA	6	10+ years	
	Floor - Tile	1.5 Floor - Office 2-I	230	SF	6	10+ years	
	Lighting - Pendent/Surface	1.5 Floor - Office 2-I	2	EA	7	10+ years	
	Power Distribution	1.5 Floor - Office 2-I	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 Floor - Office 2-I	451	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		340 01 adima 011/LE1, Officago, IE 00003
J				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor - Counselor's Office 2D	204	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Counselor's Office 2D	2	EA	6	10+ years	
	Floor - Tile	1st Floor - Counselor's Office 2D	204	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor - Counselor's Office 2D	2	EA	7	10+ years	
	Power Distribution	1st Floor - Counselor's Office 2D	8	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Counselor's Office 2D	224	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Counselor's Office 2D	224	SF	6	10+ years	
	AC Unit	2-B 1st floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2-B 1st floor	204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2-B 1st floor	1	EA	6	10+ years	
	Floor - Tile	2-B 1st floor	204	SF	6	10+ years	
	Lighting - Pendent/Surface	2-B 1st floor	4	EA	7	10+ years	
	Power Distribution	2-B 1st floor	8	EA	6	10+ years	
	Walls - Masonry	2-B 1st floor	224	SF	6	10+ years	
	Walls - Plaster/Drywall	2-B 1st floor	124	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Teacher's Lounge	228	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	Basement - Teacher's Lounge	228	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - Teacher's Lounge	2	EA	7	10+ years	
	Power Distribution	Basement - Teacher's Lounge	8	EA	6	10+ years	
	Storage/ Closet	Basement - Teacher's Lounge	170	SF	7	10+ years	
	Walls - Concrete Block	Basement - Teacher's Lounge	340	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Teacher's Lounge	380	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	361	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	361	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office	5	EA	7	10+ years	
	Power Distribution	Main Office	4	EA	6	10+ years	
	Storage/ Closet	Main Office	60	SF	7	10+ years	
	Walls - Masonry	Main Office	174	SF	6	10+ years	
	Walls - Plaster/Drywall	Main Office	240	SF	6	10+ years	
_Gvmnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	3,050	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years	
	Floor - Wood	1st Floor	3,050	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Stage	1st Floor	774	SF	6	10+ years	
	Stage Curtain	1st Floor	7	EA	7	10+ years	
	Stage-Stairs - Asphalt	1st Floor	16	LF	6	10+ years	
	Walls - Masonry	1st Floor	990	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,970	SF	6	10+ years	
	a / lacton bij man	. 3. 1 1001	_,570	0.	Ū	10. 300.0	



Catego	Category : Room		В	uilding	: Main		540 01 adima 011(EE1, Officago, 1E 00000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen							
	Ceiling - Plaster/Drywall	Basement	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	6	10+ years	
	Floor - Tile	Basement	400	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	4	ĒΑ	7	10+ years	
	Serving Line	Basement	20	LF	7	10+ years	
	Walls - Plaster/Drywall	Basement	300	SF	6	10+ years	
	,					, , , , , ,	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement	3,652	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	4	EA	6	10+ years	
	Floor - Tile	Basement	3,652	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	22	EA	7	10+ years	
	Serving Line	Basement	20	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement	5,360	SF	6	10+ years	
	·					•	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Finishes	1st Floor	520	SF	5	6-10 years	
Maahani	cal/ Service Rooms						
_iviechani	Janitor's Closet	1st Floor	36	SF	7	10	
	Mechanical/ Service Rooms	1st Floor	70	SF SF	7 7	10+ years	
			325	SF		10+ years	
	Boiler Room	Basement		SF SF	7 7	10+ years	
	Janitor's Closet  Mechanical/ Service Rooms	Basement	42 700	SF SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	700	SF	1	10+ years	
Restroor	m						
	Accessories	1.5 Floor - Boys	225	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 Floor - Boys	225	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - Boys	1	EA	6	10+ years	
	Floor - Terrazzo	1.5 Floor - Boys	225	SF	6	10+ years	
	Floor Drain	1.5 Floor - Boys	1	EA	7	10+ years	
	Lavatory	1.5 Floor - Boys	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1.5 Floor - Boys	2	EA	7	10+ years	
	Partitions	1.5 Floor - Boys	4	ĒΑ	7	10+ years	
	Urinals	1.5 Floor - Boys	5	EA	7	10+ years	
	Walls - Concrete Block	1.5 Floor - Boys	480	SF	6	10+ years	
	Water Closet	1.5 Floor - Boys	3	EA	7	10+ years	
	Accessories	1.5 Floor - Girls	241	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 Floor - Girls	241	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - Girls	1	EA	6	10+ years	
	Floor - Terrazzo	1.5 Floor - Girls	241	SF	6	10+ years	
				<del>-</del> -	-	,	



Catego	ry : Room		В	uilding	: Main		. 5 :
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1.5 Floor - Girls	1	EA	7	10+ years	
	Lavatory	1.5 Floor - Girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1.5 Floor - Girls	2	EA	7	10+ years	
	Partitions	1.5 Floor - Girls	6	EA	7	10+ years	
	Walls - Concrete Block	1.5 Floor - Girls	510	SF	6	10+ years	
	Water Closet	1.5 Floor - Girls	6	EA	6	10+ years	
	Accessories	1st Floor - Principal toilet	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal toilet	64	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal toilet	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor - Principal toilet	64	SF	6	10+ years	
	Floor Drain	1st Floor - Principal toilet	1	EΑ	7	10+ years	
	Lavatory	1st Floor - Principal toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal toilet	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal toilet	256	SF	6	10+ years	
	Water Closet	1st Floor - Principal toilet	1	EA	6	10+ years	
	Accessories	At Main Entry - Men	195	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	At Main Entry - Men	195	SF	6	10+ years	
	Doors - Wood Doors inclu hw	At Main Entry - Men	195	EA	6	•	
	Floor - Terrazzo		195	SF		10+ years	
	Floor Drain	At Main Entry - Men At Main Entry - Men		Sr EA	6 7	10+ years	
			1			10+ years	
	Lavatory	At Main Entry - Men	3	EΑ	6	10+ years	
	Lighting - Pendent/Surface	At Main Entry - Men	2	EA	7	10+ years	
	Partitions	At Main Entry - Men	2	EA	7	10+ years	
	Urinals	At Main Entry - Men	4	EA	6	10+ years	
	Walls - Concrete Block	At Main Entry - Men	400	SF	6	10+ years	
	Water Closet	At Main Entry - Men	2	EA	6	10+ years	
	Accessories	At Main Entry - Women	224	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	At Main Entry - Women	224	SF	6	10+ years	
	Doors - Wood Doors inclu hw	At Main Entry - Women	1	EA	6	10+ years	
	Floor - Terrazzo	At Main Entry - Women	224	SF	6	10+ years	
	Floor Drain	At Main Entry - Women	1	EA	7	10+ years	
	Lavatory	At Main Entry - Women	3	EA	6	10+ years	
	Lighting - Pendent/Surface	At Main Entry - Women	2	EA	7	10+ years	
	Partitions	At Main Entry - Women	4	EA	7	10+ years	
	Walls - Concrete Block	At Main Entry - Women	458	SF	6	10+ years	
	Water Closet	At Main Entry - Women	4	EA	6	10+ years	
	Accessories	Basement	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	10+ years	
	Floor - Tile	Basement	42	SF	6	10+ years	
	Floor Drain	Basement	1	ĒΑ	7	10+ years	
	Lavatory	Basement	· 1	EΑ	7	10+ years	
	Lighting - Wall Mounted	Basement	1	EA	7	10+ years	
	Walls - Concrete Block	Basement	192	SF	6	10+ years	
	viano Sonorcio Biook	Dasomont	192	O.	U	ioi youis	



Catego	ory : Room		В	uilding	: Main		946 S Paulina STREET, Chicago, IL 60608
Guioge	. <b>,</b>		_	<u>.</u>	····	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Basement	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	7	10+ years	
	Floor - Tile	Basement	42	SF	7	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Wall Mounted	Basement	1	EA	7	6-10 years	
	Walls - Concrete Block	Basement	192	SF	7	10+ years	
	Water Closet	Basement	1	EA	7	10+ years	
Catego	ory : Classroom		В	uilding	: Main		
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #1 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	768	SF	7	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	768	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	10+ years	
	Walls - Concrete Block	2nd Floor	659	SF	6	10+ years	
	Walls - Masonry	2nd Floor	659	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	45	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #2 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	645	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	536	SF	6	10+ years	
	Walls - Masonry	2nd Floor	53	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	256	SF	6	10+ years	
01	((000 (Marris B)						
Classro	om #303 (Music Room)	Ond Flare			7	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	645	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	536	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	120	SF	6	10+ years	
Classroc	om #304 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	620	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	620	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	384	SF	6	10+ years	
	Walls - Masonry	2nd Floor	384	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	42	SF	6	10+ years	
Classroc	om #305 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	620	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	620	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7		
	Marker Board	2nd Floor	26	LF	7	10+ years 6-10 years	
	Walls - Concrete Block	2nd Floor	384	SF	6	•	
				SF SF	_	10+ years	
	Walls - Masonry Walls - Structural Glazed Tile	2nd Floor	384	SF SF	6	10+ years	
	wans - Structural Glazed Tile	2nd Floor	42	SF	6	10+ years	
Classroc	om #306 (Regular Classroom)	0.15				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	645	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Walls - Masonry	2nd Floor	72	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	48	SF	6	10+ years	



Categoi	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #7 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	645	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	645	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	600	SF	6	10+ years	
	Walls - Masonry	2nd Floor	200	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	48	SF	6	10+ years	
	Trans Structural Glazou File	2.10 1 1001		O.	Ŭ	ioi youro	
Classroo	m #8 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	752	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	752	SF	7	10+ years	
	Gas Line	2nd Floor	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	9	EΑ	7	10+ years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	50	SF	7	10+ years	
	Walls - Masonry	2nd Floor	432	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	432	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	52	SF	6	10+ years	
	Walls - Structural Glazed Tile	2110 1 1001	52	OI	U	10+ years	
Categoi	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1.5 Floor	78	SF	6	10+ years	
	Doors - Steel Doors incl hw	1.5 Floor	1	EA	6	10+ years	
	Floor - Terrazzo	1.5 Floor	78	SF	7	10+ years	
	Lighting - Pendent/Surface	1.5 Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 Floor	256	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	774	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
		2nd Floor	774	SF	5	10+ years	
	Floor - Tile/Sheet	2110 F1001	117	0.			
	Floor - Tile/Sheet Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	





	mana Indon		-	!   .   !	- N/!		946 S Paulina STREET, Chicago, IL 60609
Catego	ry : Interior		В	uilding	: wain	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	81	SF	6	10+ years	
	Walls - Masonry	2nd Floor	54	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	216	SF	6	10+ years	
Safety							
·	Camera Viewing Station	Entire building	1	EA	7	6-10 years	
	Metal Dedector	Entire building	1	EA	7	10+ years	
	Security Cameras	Entire building	10	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Main Entrance	150	SF	6	10+ years	
	Floor - Terrazzo	Main Entrance	40	SF	6	10+ years	
	Floor - Tile	Main Entrance	375	SF	6	10+ years	
	Handrails	Main Entrance	280	LF	5	10+ years	
	Lighting - Pendent/Surface	Main Entrance	10	EA	7	10+ years	
	Stairs - Terrazzo	Main Entrance	120	LF	6	10+ years	
	Walls - Plaster/Drywall	Main Entrance	1,296	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	96	SF	6	10+ years	
	Floor - Concrete	South	120	SF	7	10+ years	
	Handrails	South	144	LF	5	10+ years	
	Lighting - Pendent/Surface	South	6	EA	7	10+ years	
	Stairs - Concrete	South	72	LF	6	10+ years	
	Walls - Masonry	South	1,296	SF	6	10+ years	





Category : Exterior Building : Leased-Branch

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	Entrance 1 - West	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 1 - West	24	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 1 - West	12	LF	7	10+ years	
	Entrance Control - Audio and Video	Entrance 2 - SE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 2 - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2 - SE	40	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 2 - SE	20	LF	6	10+ years	
	Entrance Control - Audio	Entrance 3 - East	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3 - East	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 3 - East	35	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 3 - East	5	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 3 - East	20	LF	6	10+ years	
	Entrance Control - Audio and Video	Entrance 4 - NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 4 - NE	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Entrance 4 - NE	40	LF	5	10+ years	
	Power Door Operator and Controls	Entrance 4 - NE	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 4 - NE	25	LF	6	10+ years	
	Ramps - Concrete	Entrance 4 - NE	25	LF	5	0-1 year	Rusting rail posts are causing
	rampo conoroto	Entrance i ive	20		Ü	o i youi	concrete to break
	Stair Handrail - Steel_Stair Handrail	Entrance 4 - NE	10	LF	4	0-1 year	Rusting posts are causing concrete to
	otali Hariarali otooi_otali Hariarali	Entrance i ive	10		•	o i youi	break
	Entrance Control - Audio	Entrance 5 - NW	2	EA	7	10+ years	broak
	Exterior Doors - Exterior Steel Door	Entrance 5 - NW	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Entrance 5 - NW	32	LF	7	10+ years	
	Power Door Operator and Controls	Entrance 5 - NW	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 5 - NW	46	LF	6	10+ years	
	Ramps - Concrete	Entrance 5 - NW	21	LF	6	10+ years	
	Ramps - Concrete	Entrance 5 - NW	2	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 5 - NW	9	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 5 - NW	3	LF	6	10+ years	
	Otali Haridian - Oteel_Otali Haridian	Littlatice 3 - IVVV	3	LI	U	10+ years	
Foundati	on						
_Foundan	Foundation - Concrete	Entire Building	744	LF	7	10+ years	
	Foundation - Concrete	Entire Building  Entire Building	6	LF LF	, 5		Large wheat tree growing at the
	Foundation - Concrete	Entire building	O	LF	3	1-2 years	foundation that should be removed
	Superstructure - Steel	Entire Building	33,484	SF	7	10+ years	ioundation that should be removed
	Superstructure - Steel	Entire building	33,404	SI	,	10+ years	
الماملية ا							
_Lighting_	Errinia D. C. D. (M. C.)	E (				40	_
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EΑ	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	

Page : 13 of 30





Category : Exterior			Building : Leased-Branch				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Exterior Lighting - Wall Mounted	Entire Building	2	EΑ	5	1-2 years	
oof Sys	stem						
,	Access Ladder - Metal	Roof 1	1	EA	5	2-5 years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	40	LF	7	10+ years	
	Liner	. 100.			•	.o. you.o	
	Chimney - Metal Flue	Roof 1	70	LF	7	10+ years	
	Coping - Stone	Roof 1	775	LF	6	10+ years	
	Coping - Stone	Roof 1	20	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	293	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	222	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	10	LF	5	10+ years	Needs Tuckpointing
	Parapet - Parapet < 16" Height	Roof 1	545	LF	7	10+ years	riocae raenpenning
	Parapet - Parapet > 30"	Roof 1	2	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1	20	LF	4	0-1 year	Displaced masonry, poor previous
	rarapet rarapet > 00	10011	20		7	o i yeai	repairs
	Roof - Asphalt Gravel Ballast	Roof 1	13,742	SF	7	10+ years	repairs
	Roof - Asphalt Gravel Ballast	Roof 1	3,000	SF	5	10+ years	Much of the flashing sealant is
	11001 - Aspiralit Graver Ballast	11001 1	3,000	Oi	3	10+ years	deteriorated, Large area missing
							gravel
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	graver
	Roof Structure - Steel / Metal Deck/	Roof 1	16,742	SF	7	10+ years	
	Concrete Topping	ROOI I	10,742	SF	,	10+ years	
	Concrete Topping						
/alls							
vano	Exterior Walls - Brick	Entire Building	12,330	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	26	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	3	0-1 year	Wall is damaged and continues to
	Exterior Walls - Drick	Little Building	400	OI.	3	0-1 year	deteriorate.
	Exterior Walls - Stone-Cast	Entire Building	140	SF	5	10+ years	deteriorate.
	Exterior Walls - Stone-Cast	Entire Building	20	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,900	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,335	SF	5	•	
		Entire Building	2,835	SF	5 5	10+ years	
	Exterior Walls - Stucco	Entire Building	2,030	SF	5	10+ years	
Vindows	s						
	Guard - Guards perforated	Entire Building	1,578	SF	6	10+ years	
	Lintels - Steel	Entire Building	795	LF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	3,310	SF	6	6-10 years	
	pane	· · · =	3,0.0		-	y <b>,</b>	
	Windows - Decorative	Entire Building	12	SF	6	6-10 years	
	Windows - Louver	Entire Building	24	SF	6	6-10 years	
	Windows - Louver	Entire Building	28	SF	5	6-10 years	
	**************************************	Zitti o Dalianiy	20	O.	3	o io youis	





Catago				!  al!			946 S Paulina STREET, Chicago, IL 60609
Catego	ry : Exterior		В	uilding	: Lease	d-Branch	
<b>0</b>	Hans Toma	Lasation	0	LIOM	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Electrical		R	uildina	· l ease	d-Branch	
Outego	y . Electrical			unung	. Louse	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ncy System		,				
Linoigo	Emergency A/C Power - Corridors and Stairs	Entire Building	7,550	SF	6	10+ years	Building has EM panel
	Emergency A/C Power - Multipurpose Room	Entire Building	4,500	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	28	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	23	EA	6	6-10 years	
	Security System - CCTV	Entire Building	33,484	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	33,484	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	Serves leased building
	PA System	Entire Building	33,484	SF	6	6-10 years	Serves leased building
Dower D	intribution						
Power D	istribution Lighting and Power Panels - 100 A	Entire Duilding	1	EA	6	10	
	Lighting and Power Panels - 100 A  Lighting and Power Panels - 100 A	Entire Building	1		6 6	10+ years 10+ years	
	Lighting and Power Panels - 100 A  Lighting and Power Panels - Above 100 A	Entire Building	4	EA EA	6	•	
		Entire Building Entire Building	5		6	10+ years	
	Lighting and Power Panels - Above 100 A		_	EΑ	_	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	6	10+ years	
	·		_		_		
Catego	ry : Fire Protection		В	ullaing	: Lease	d-Branch	
Crour	Itam Tuna	Laggian	Ouert!tr	LION	Donle	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		F & B 7 P				40	
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	33,484	SF	6	10+ years	
	Fire Alarm_System	Entire Building	33,484	SF	6	10+ years	
Sprinkle	System						
,	Sprinkler Heads	Entire Building	33,484	SF	7	10+ years	
	Sprinkler Piping	Entire Building	33,484	SF	6	10+ years	
	-1		33, 101	٥.	•	,	

Page : 15 of 30



### **Peace & Education Coalition HS**

4946 S Paulina STREET, Chicago, IL 60609

**Building: Leased-Branch Category: Fire Protection** Recommend Location Group Item - Type Quantity UOM Replacement Comments Rank Wet Sprinkler System **Entire Building** 33,484 SF 10+ years 6

Category : Mechanical Building : Leased-Branch

Category : Mechanical			Building : Leased-Branch						
	_					Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Air Cond	•								
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Carrier CU7, serves south portion of building		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Carrier Gemini CU2 PB, serves north, first floor, shared with Precious Blood tenant		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	10+ years	Carrier CU6serves center portion of building		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Goodman CU4 PBserves center, first floor		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	10+ years	Carrier CU 8 HS, serves south end of building		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Goodman CU 1 PB, serves north, first floor, shared with Precious Blood tenant		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Goodman CU 10, serves south end		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Goodman CU 5 HS, serves center portion of building		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Carrier CU3 PB, serves north, first floor		
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	5	6-10 years	Carrier CU 9, serves south end		
_Air Hand	lling Systems								
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	2	EA	6	10+ years	Serves north end, first floor, with gas heating, not an air handler, domestic style furnace with DX coil, Good FactTool option for description not available, shared with Precious Blood tenant		
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	6	EA	6	10+ years	Serve center and south end, domestic style furnace with gas heating, with DX coil		
	Fan Coil Unit- Floor Mounted - Electric	Entire Building	2	EA	6	10+ years	Serve north end, first floor, with gas heating, domestic style furnace with DX coil. shared with pressure blood tenant		

Page: 16 of 30



# **Peace & Education Coalition HS**

Category : Mechanical		В	uilding	: Lease	d-Branch		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Heating	Devices						
	Cabinet Heaters - With Electric Coil	1st Floor	4	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	6	10+ years	
Temper	rature Control						
	Electric Thermostat	Electrical Room	10	EA	6	10+ years	Serve fan coil units
Ventilati	ion						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	4	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	4	EA	5	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	Vertical, along wall
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	ĒΑ	6	10+ years	
Catego	ory : Plumbing		В	uilding	: Lease	d-Branch	
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	Serves south end of building
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	Serves south end of building
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	5	6-10 years	Serve north end of building
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Cold Water Risers	Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	33,484	SF	6	10+ years	
		Entire Building	33,484	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire building	,				
		Entire Building	33,484	SF	6	10+ years	
	Fixtures	<u> </u>		SF SF SF	6 6	10+ years 10+ years	







Category : Room			Building : Leased-Branch					
						Recommend		
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminist	rative Suites/Offices							
	Ceiling - Plaster/Drywall	1st Floor - 102B	104	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - 102B	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor - 102B	104	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - 102B	2	ĒΑ	7	10+ years		
	Power Distribution	1st Floor - 102B	6	EA	6	10+ years		
	Storage/ Closet	1st Floor - 102B	12	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - 102B	360	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor - 102B	72	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - ADMIN 102	295	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - ADMIN 102	1	EΑ	7	10+ years		
	Floor - Tile	1st Floor - ADMIN 102	295	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - ADMIN 102	6	ĒΑ	7	6-10 years		
	Power Distribution	1st Floor - ADMIN 102	8	EA	6	10+ years		
	Storage/ Closet	1st Floor - ADMIN 102	12	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - ADMIN 102	612	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - Conference Room	130	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Conference Room	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor - Conference Room	130	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - Conference Room	2	ĒΑ	7	10+ years		
	Power Distribution	1st Floor - Conference Room	8	ΕA	6	10+ years		
	Walls - Concrete Block	1st Floor - Conference Room	24	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Conference Room	352	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - DIRECTOR 102A	176	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - DIRECTOR 102A	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor - DIRECTOR 102A	176	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - DIRECTOR 102A	2	ĒΑ	7	10+ years		
	Power Distribution	1st Floor - DIRECTOR 102A	6	EA	6	10+ years		
	Walls - Plaster/Drywall	1st Floor - DIRECTOR 102A	468	SF	6	10+ years		
	Ceiling - Exposed	1st Floor - Engineer's Office	296	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Engineer's Office	2	EA	7	10+ years		
	Floor - Tile	1st Floor - Engineer's Office	296	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - Engineer's Office	3	EA	7	10+ years		
	Power Distribution	1st Floor - Engineer's Office	8	EA	6	10+ years		
	Walls - Concrete Block	1st Floor - Engineer's Office	272	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor - Engineer's Office	272	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor - Engineer's Office	54	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - Library Resource 116	240	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Library Resource 116	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Library Resource 116	240	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor - Library Resource 116	2	ĒΑ	7	10+ years		
	Power Distribution	1st Floor - Library Resource 116	8	EA	6	10+ years		
	Walls - Concrete Block	1st Floor - Library Resource 116	120	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor - Library Resource 116	480	SF	6	10+ years		





Category : Room			Building : Leased-Branch						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	1st Floor - Library Resource 116	82	SF	6	10+ years			
	Ceiling - Exposed	1st Floor - Reception 100	98	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - Reception 100	1	EA	7	10+ years			
	Floor - Tile	1st Floor - Reception 100	98	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor - Reception 100	1	EA	6	10+ years			
	Power Distribution	1st Floor - Reception 100	2	EA	6	10+ years			
	Walls - Concrete Block	1st Floor - Reception 100	162	SF	6	10+ years			
	Ceiling - Plaster/Drywall	210 office	98	SF	6	10+ years			
	Doors - Wood Doors inclu hw	210 office	1	EA	7	10+ years			
	Floor - Carpet	210 office	98	SF	6	6-10 years			
	Lighting - Pendent/Surface	210 office	1	EA	7	10+ years			
	Power Distribution	210 office	8	EΑ	6	10+ years			
	Walls - Concrete Block	210 office	144	SF	6	10+ years			
	Walls - Plaster/Drywall	210 office	144	SF	6	10+ years			
	Ceiling - Plaster/Drywall	210 office 2nd Floor - 212	850	SF	6	•			
	Doors - Wood Doors inclu hw	2nd Floor - 212 2nd Floor - 212		EA		10+ years			
			1		7	10+ years			
	Floor - Carpet	2nd Floor - 212	850	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor - 212	6	EA	7	10+ years			
	Power Distribution	2nd Floor - 212	16	EA	6	10+ years			
	Walls - Concrete Block	2nd Floor - 212	580	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor - 212	580	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor - 212	110	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor - Computer Technical Room 208	150	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - Computer Technical Room 208	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor - Computer Technical Room 208	150	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor - Computer Technical Room 208	1	EA	7	10+ years			
	Power Distribution	2nd Floor - Computer Technical Room 208	4	EA	6	10+ years			
	Walls - Concrete Block	2nd Floor - Computer Technical Room 208	192	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor - Computer Technical Room 208	192	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor - Computer Technical Room 208	42	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Office 124	117	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Office 124	1	EA	6	10+ years			
	Floor - Tile	Office 124	117	SF	6	10+ years			
	Lighting - Pendent/Surface	Office 124	2	ĒΑ	7	10+ years			
	Walls - Concrete Block	Office 124	110	SF	6	10+ years			
	Walls - Plaster/Drywall	Office 124	98	SF	6	10+ years			



Kitchen  Ceiling Doors Floor Lightir Walls Ceiling Doors Floor Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor Lightir Marke Servin Walls  MDF_IDF Doors	rg - Plaster/Drywall s - Steel Doors incl hw r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet s - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	190 1 190 4 416 164 1 164	SF EA SF EA SF EA	6 6 6 7 6	10+ years 10+ years 10+ years 10+ years	Comments
Kitchen Ceiling Doors Floor Lightir Walls Ceiling Doors Floor Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor Lightir Marke Servin Walls  MDF_IDF Doors	ng - Plaster/Drywall s - Steel Doors incl hw r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall s - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	190 1 190 4 416 164 1 164	SF EA SF EA SF SF	6 6 6 7 6	10+ years 10+ years 10+ years 10+ years	Comments
Ceiling Doors Floor - Lightir Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	rs - Steel Doors incl hw r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 2nt Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 190 4 416 164 1	EA SF EA SF SF	6 6 7 6	10+ years 10+ years 10+ years	
Ceiling Doors Floor - Lightir Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	rs - Steel Doors incl hw r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 2nt Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 190 4 416 164 1	EA SF EA SF SF	6 6 7 6	10+ years 10+ years 10+ years	
Doors Floor - Lightir Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	rs - Steel Doors incl hw r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 2nt Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 190 4 416 164 1	EA SF EA SF SF	6 6 7 6	10+ years 10+ years 10+ years	
Floor - Lightir Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	r - Tile ting - Pendent/Surface s - Concrete Block ng - Plaster/Drywall s - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	190 4 416 164 1 164	SF EA SF SF	6 7 6	10+ years 10+ years	
Lightir Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	ring - Pendent/Surface s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ring - Pendent/Surface age/ Closet	1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	4 416 164 1 164	EA SF SF	7 6	10+ years	
Walls Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	s - Concrete Block ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ting - Pendent/Surface age/ Closet	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	416 164 1 164	SF SF	6		
Ceiling Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	ng - Plaster/Drywall rs - Wood Doors inclu hw r - Tile ring - Pendent/Surface age/ Closet	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	164 1 164	SF		10	
Doors Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	rs - Wood Doors inclu hw r - Tile ring - Pendent/Surface age/ Closet	2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 164			10+ years	
Floor - Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	r - Tile ting  - Pendent/Surface age/ Closet	2nd Floor 2nd Floor 2nd Floor		ΓΛ	7	10+ years	
Lightir Storag Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	ring - Pendent/Surface age/ Closet	2nd Floor 2nd Floor		EA	6	10+ years	
Storacy Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	age/ Closet	2nd Floor		SF	6	10+ years	
Storace Walls  Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	age/ Closet		2	EA	7	10+ years	
Walls  Lunch & Multipur Ceiling Doors Floor Lightir Marke Servin Walls  MDF_IDF Doors	s - Plaster/Drywall		40	SF	7	10+ years	
Lunch & Multipur Ceiling Doors Floor - Lightir Marke Servin Walls  MDF_IDF Doors	•	2nd Floor	384	SF	6	10+ years	
Ceiling Doors Floor Floor Lightir Marke Servin Walls  MDF_IDF Doors						,	
Doors Floor - Lightir Marke Servin Walls MDF_IDF Doors	urpose Room						
Floor - Lightir Marke Servin Walls <u>MDF_IDF</u> Doors	ng - Plaster/Drywall	1st Floor	1,373	SF	6	10+ years	
Lightir Marke Servin Walls <u>MDF_IDF</u> Doors	rs - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
Marke Servin Walls MDF_IDF Doors	r - Tile	1st Floor	1,373	SF	6	10+ years	
Marke Servin Walls MDF_IDF Doors	ing - Pendent/Surface	1st Floor	28	EA	7	10+ years	
Servin Walls MDF_IDF Doors	xet Board	1st Floor	16	LF	7	6-10 years	
Walls  MDF_IDF  Doors	ing Line	1st Floor	14	LF	6	10+ years	
Doors	s - Plaster/Drywall	1st Floor	1,184	SF	6	10+ years	
Doors							
	s - Steel Doors incl hw	1st Floor - MDF Room 125	1	EA	7	10+ years	
Finish		1st Floor - MDF Room 125	25	SF	7	6-10 years	
	rs - Wood Doors inclu hw	IDF 119A	1	EA	7	10+ years	
Finish		IDF 119A	32	SF	7	6-10 years	
1 1111011		151 11671	02	O.	•	o ro youro	
Mechanical/ Ser	ervice Rooms						
Janito	or's Closet	1st Floor	82	SF	7	10+ years	
Mecha	nanical/ Service Rooms	1st Floor	110	SF	7	10+ years	
Mecha	nanical/ Service Rooms	1st Floor	100	SF	7	10+ years	
	nanical/ Service Rooms	1st Floor	130	SF	7	10+ years	
	nanical/ Service Rooms	1st Floor	30	SF	7	10+ years	
	age Room	1st Floor	60	SF	7	10+ years	
	age Room	1st Floor	80	SF	7	10+ years	
		1st Floor	104	SF	7	10+ years	
		2nd Floor	15	SF	7	10+ years	
	age Room	2nd Floor	150	SF	7	10+ years	
	age Room nanical/ Service Rooms		150	SF		•	
Otorag	age Room	2nd Floor			7	10+ years	





Catego	ry : Room		В	uilding	: Lease	d-Branch	, ,
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor - Men 101	187	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men 101	187	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men 101	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men 101	187	SF	6	10+ years	
	Floor Drain	1st Floor - Men 101	1	EA	7	10+ years	
	Lavatory	1st Floor - Men 101	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men 101	3	EA	7	10+ years	
	Partitions	1st Floor - Men 101	4	EA	7	10+ years	
	Urinals	1st Floor - Men 101	3	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Men 101	208	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men 101	208	SF	6	10+ years	
	Water Closet	1st Floor - Men 101	2	EA	6	10+ years	
	Accessories	1st Floor - Men 119	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men 119	380	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men 119	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men 119	380	SF	6	10+ years	
	Floor Drain	1st Floor - Men 119	1	EA	7	10+ years	
	Lavatory	1st Floor - Men 119	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men 119	6	EA	7	10+ years	
	Partitions	1st Floor - Men 119	10	EA	7	10+ years	
	Urinals	1st Floor - Men 119	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Men 119	342	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men 119	342	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Men 119	62	SF	6	10+ years	
	Water Closet	1st Floor - Men 119	6	ĒΑ	7	10+ years	
	Accessories	1st Floor - Restroom 110A	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom 110A	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom 110A	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor - Restroom 110A	36	SF	6	10+ years	
	Floor Drain	1st Floor - Restroom 110A	1	EA	7	10+ years	
	Lavatory	1st Floor - Restroom 110A	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom 110A	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Restroom 110A	192	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Restroom 110A	24	SF	6	10+ years	
	Accessories	1st Floor - Restroom 131	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Restroom 131	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Restroom 131	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Restroom 131	36	SF	6	10+ years	
	Floor Drain	1st Floor - Restroom 131	1	EA	7	10+ years	
	Lavatory	1st Floor - Restroom 131	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Restroom 131	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Restroom 131	81	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Restroom 131	81	SF	7	10+ years	
	Water Closet	1st Floor - Restroom 131	1	EA	6	10+ years	
	vvalet Cluset	191 LIOOL - VASILOOHI 191	1	ĽA	O	10+ years	





Catego	ry : Room		В	uilding	: Lease	d-Branch	
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Accessories	1st Floor - Women 105	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Women 105	380	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Women 105	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women 105	380	SF	6	10+ years	
	Floor Drain	1st Floor - Women 105	1	EΑ	7	10+ years	
	Lavatory	1st Floor - Women 105	5	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Women 105	8	EΑ	7	10+ years	
	Partitions	1st Floor - Women 105	16	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Women 105	226	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Women 105	304	SF	6	10+ years	
	Water Closet	1st Floor - Women 105	9	EΑ	6	10+ years	
	Accessories	2nd Floor - Bathroom 207	33	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Bathroom 207	33	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Bathroom 207	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Bathroom 207	33	SF	6	10+ years	
	Lavatory	2nd Floor - Bathroom 207	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Bathroom 207	1	EΑ	6	10+ years	
	Partitions	2nd Floor - Bathroom 207	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Bathroom 207	89	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Bathroom 207	187	SF	6	10+ years	
	Water Closet	2nd Floor - Bathroom 207	1	EA	6	10+ years	
	Accessories	2nd Floor - Men 203	205	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Men 203	205	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Men 203	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men 203	305	SF	6	10+ years	
	Floor Drain	2nd Floor - Men 203	1	EA	7	10+ years	
	Lavatory	2nd Floor - Men 203	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Men 203	2	EA	7	10+ years	
	Partitions	2nd Floor - Men 203	3	EA	7	10+ years	
	Urinals	2nd Floor - Men 203	3	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Men 203	378	SF	6	10+ years	
	Water Closet	2nd Floor - Men 203	2	EA	6	10+ years	
Catego	ry : Classroom		В	uilding	: Lease	d-Branch	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #103 (Regular Classroom)						
	Casework	1st Floor	15	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	815	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor Tile	1 of Floor	015	C.L	7	10	

Storage/ Closet

Lighting - Pendent/Surface Marker Board

Floor - Tile

1st Floor

1st Floor

1st Floor

1st Floor

SF

EΑ

LF

SF

815

10

30

7

7

7

7

10+ years

10+ years

6-10 years

10+ years





Catego	ory : Classroom		В	uilding	: Lease	d-Branch	340 OT adima OTTELLT, Officago, iL 00003
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Walls - Concrete Block	1st Floor	104	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	772	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	100	SF	7	10+ years	
Classroo	om #104 (Regular Classroom)						
	Casework	1st Floor	15	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	506	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	506	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	ĒΑ	7	10+ years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	64	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	594	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	100	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #115 (Regular Classroom)						
	Ceiling - Exposed	1st Floor	850	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	102	SF	6	10+ years	
Classroo	om #117 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	98	SF	6	10+ years	
Classroo	om #120 (Science Classroom)						
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	48	LF	7	6-10 years	





Catego	ry : Classroom		В	uilding	: Lease	d-Branch	1940 S Faulilia STREET, Chicago, IL 60609
<b>J</b>				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	42	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	336	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	336	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #122 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	540	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	540	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	10+ years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	736	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	42	SF	7	10+ years	
Classroo	om #123 (Computer Lab)						
	Ceiling - Plaster/Drywall	1st Floor	774	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	774	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	400	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	650	SF	6	10+ years 10+ years	
	Walls - Structural Glazed Tile	1st Floor	500	SF	6	10+ years	
Classro	om #200 (Computer Lab)						
Classice	Ceiling - Exposed	2nd Floor	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	130	EA	7	10+ years	
	Floor - Carpet	2nd Floor	130	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	•	
		2nd Floor		SF	=	6-10 years	
	Walls - Concrete Block		24		6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	225	SF	6	10+ years	
Classroo	om #205 (Weight)						
	Ceiling - Plaster/Drywall	2nd Floor	729	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor	729	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	550	SF	6	10+ years	
	•					·	

Page : 24 of 30





	ry : Classroom		Building : Leased-Branch						
Group Item - Type Location				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	2nd Floor	550	SF	6	10+ years			
Classroo	m #215 (Music Room)								
	Ceiling - Plaster/Drywall	2nd Floor	535	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	400	SF	6	6-10 years			
	Floor - Tile	2nd Floor	135	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	368	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	368	SF	6	10+ years			
Catego	ry : Interior		В	uildina	: Lease	d-Branch			
	,					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Exposed	1st Floor	2,856	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	8	EA	6	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years			
	Floor - Terrazzo	1st Floor	2,856	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	26	EA	7	10+ years			
	Student Lockers - One Tier	1st Floor	104	EA	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	848	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	848	SF	6	10+ years			
	Ceiling - Exposed	2nd Floor	890	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	3	ĒΑ	6	10+ years			
	Floor - Terrazzo	2nd Floor	890	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	464	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	464	SF	6	10+ years			
Safety									
-	Camera Viewing Station	Entire Building	1	EA	7	6-10 years			
	Security Cameras	Entire Building	16	EA	7	6-10 years			
Stairs									
	Ceiling - Plaster/Drywall	South East	266	SF	7	10+ years			
	Floor - Terrazzo	South East	225	SF	6	10+ years			
	Handrails	South East	52	LF	7	10+ years			
	Lighting - Pendent/Surface	South East	5	EA	7	10+ years			
	Stairs - Terrazzo	South East	26	LF	6	10+ years			
	Walls - Concrete Block	South East	62	SF	7	10+ years			
	Walls - Plaster/Drywall	South East	576	SF	7	10+ years			
			3.0		-	- ,			



## **Peace & Education Coalition HS**

4946 S Paulina STREET, Chicago, IL 60609

Category : Interior

Building : Leased-Branch
Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments

Walls - Structural Glazed Tile South East 576 SF 7 10+ years



Category: Site

Recommend Location Replacement Group Item - Type Quantity **UOM** Rank Comments Athletic SF South 7 Surface - Asphalt 4,000 10+ years Civil/Drainage Civil/ Drainage - Catch Basin 5 Second Chance EΑ 6 10+ years Civil/ Drainage - Site Manhole 3 Second Chance EΑ 6 10+ years \_Fencing Fencing - Chain Link Second Chance 1,210 LF 7 10+ years LF Second Chance Fencing - Chain Link 20 5 1-2 years LF 5 Fencing - Chain Link Second Chance 0-1 year Sinkhole has occurred pulling down the footing for one of the chain-link posts Second Chance 5 LF Sinkhole has occurred pulling down Fencing - Chain Link 4 0-1 year the footing for one of the chain-link posts Fencing - Old Standard Ornamental Second Chance 400 LF 6 10+ years LF Fencing - Chain Link Sinclair 142 6 10+ years Fencing - Chain Link 1-2 years Sinclair LF 5 30 8 LF 5 Fencing - Chain Link Sinclair 1-2 years RECenter post or replace LF 5 Fencing - Chain Link Sinclair 1-2 years RECenter post or replace

**Building: Site** 

<u>Landscape</u>
------------------

11							
	Benches	Second Chance	65	EA	4	1-2 years	Damaged
	Landscape - Grass	Second Chance	39,587	SF	6	10+ years	
	Landscape - Grass	Second Chance	20,000	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Second Chance	415	SF	5	6-10 years	
	Landscape - Hardscape- Concrete	Second Chance	725	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Second Chance	355	SF	6	10+ years	
	Parkway trees	Second Chance	17	EA	6	10+ years	
	Parkway trees	Second Chance	1	EA	5	1-2 years	Tree is not a Parkway tree, it is located near the athletic field, basketball court. It is Rotting
	Parkway trees	Second Chance	1	EA	5	1-2 years	Tree is not a Parkway tree, it is located near the athletic field, basketball court. It is Rotting
	Planting Beds/ Area	Second Chance	580	SF	7	10+ years	•
	Planting Beds/ Area	Second Chance	20,290	SF	7	10+ years	
	Play Area - Asphalt/ Hardscape	Second Chance	9,817	SF	6	10+ years	
	Walking Path - Crushed Stone	Second Chance	450	SF	7	10+ years	
	Landscape - Grass	Sinclair	1,775	SF	4	1-2 years	
	Landscape - Hardscape- Asphalt	Sinclair	40	SF	6	10+ years	





Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Landscape - Hardscape- Concrete	Sinclair	780	SF	6	2-5 years	
	Landscape - Hardscape- Pavers	Sinclair	200	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Sinclair	200	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Sinclair	128	SF	5	10+ years	
	Parkway trees	Sinclair	1	EA	5	0-1 year	No trees on the parkway
	Parkway trees	Sinclair	3	EA	5	0-1 year	There are no Parkway trees
	Planting Beds/ Area	Sinclair	1,075	SF	5	10+ years	•
Parking I	ot						
ŭ	Concrete Curbs	Second Chance - NW corner of site	30	LF	7	10+ years	
	Interior Plantings	Second Chance - NW corner of site	18	LF	6	10+ years	
	Surface - Asphalt	Second Chance - NW corner of site	8,000	SF	6	6-10 years	
	Surface - Asphalt	Second Chance - NW corner of site	19,815	SF	5	6-10 years	
	Surface - Asphalt	Second Chance - NW corner of site	800	SF	5	1-2 years	Many potholes and buckling of
	·					•	surface
	Surface - Asphalt	Second Chance - NW corner of site	800	SF	5	1-2 years	Many potholes and buckling of surface
	Surface - Asphalt	Second Chance - NW corner of site	10	SF	4	0-1 year	Repair sink hole
	Surface - Asphalt	Second Chance - NW corner of site	10	SF	4	0-1 year	Repair sink hole
	Surface - Concrete	Second Chance - NW corner of site	1,300	SF	4	1-2 years	rtopan sintriolo
Sidewalk	S.S.						
	Sidewalks - Internal Walks	Second chance	50	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Second chance	2,000	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Second chance	10,895	SF	6	10+ years	
	Sidewalks - Internal Walks	Sinclair	74	LF	7	10+ years	
	Sidewalks - Internal Walks	Sinclair	26	LF	5	1-2 years	Cracked tile and concrete below
	Sidewalks - Internal Walks	Sinclair	26	LF	5	1-2 years	Cracked tile and concrete below
	Sidewalks - Perimeter Sidewalks	Sinclair	840	SF	7	10+ years	
Signage							
<del>-0-0-</del>	Monument - Building Mounted Cut Letter Sign	Second Chance	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Second Chance	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Sinclair	1	EA	6	10+ years	

Page: 28 of 30

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Page: 29 of 30



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	<u> </u>	·							•
Computer Lab	Regular Classroom	2nd Floor	1	301	768	168	45	N	N
Music Room	Regular Classroom	2nd Floor	303	303	645	183	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	2	302	645	183	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	304	304	620	128	35	N	N
Regular Classroom	Regular Classroom	2nd Floor	305	305	620	128	35	N	N
Regular Classroom	Regular Classroom	2nd Floor	306	306	645	128	35	N	N
Regular Classroom	Regular Classroom	2nd Floor	7	307	645	128	35	N	N
Science Lab Level 1	Regular Classroom	2nd Floor	8	308	752	78	28	N	N

Building : Leased-Branch									
Computer Lab	Computer Lab	1st Floor	123	123	774	72	24	Y	N
Computer Lab	Computer Lab	2nd Floor	200	200	130	48	24	N	N
Music Room	Regular Classroom	2nd Floor	215	209	535	96	48	N	N
Regular Classroom	Exclusively Used by Outside Organization	1st Floor	103	Daycare	815	12	30		
Regular Classroom	Exclusively Used by Outside Organization	1st Floor	104	Daycare	506	12	21		
Regular Classroom	Regular Classroom	1st Floor	115	115	850	96	48	Y	N
Regular Classroom	Regular Classroom	1st Floor	117	117	850	96	48	Y	N
Regular Classroom	Regular Classroom	1st Floor	122	122	540	72	36	N	N
Science Classroom	Regular Classroom	1st Floor	120	120	450	72	36	Y	N
Weight	Art Room	2nd Floor	205	205	729	184	144	Y	N

Page : 30 of 30