

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2019	2	117,000
Campus Total			117,000

Category : Exterior Building : Main

				_		Recommend	
Group Iten	m - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
Ent	trance Control - Audio and Video	1	1	EA	7	6-10 years	
Exte	terior Doors - Side lite	1	2	EA	7	10+ years	
Exte	terior Doors - Store Front	1	2	EA	7	10+ years	
Exte	terior Doors - Transom Lite	1	4	EA	7	10+ years	
Exte	terior Doors - Store Front	10	2	EA	7	10+ years	
Exte	terior Doors - Exterior Steel Door	11	2	EA	7	10+ years	
Exte	terior Doors - Side lite	11	2	EA	7	10+ years	
Exte	terior Doors - Transom Lite	11	3	EA	7	10+ years	
Exte	terior Doors - Exterior Steel Door	12	3	EA	6	10+ years	
Exte	terior Doors - Transom Lite	12	2	EA	7	10+ years	
Exte	terior Stairs - Concrete	12	40	LF	7	10+ years	
Exte	terior Doors - Exterior Steel Door	13	2	EA	6	10+ years	
Exte	terior Stairs - Concrete	13	6	LF	7	10+ years	
Exte	terior Stairs - Steel or Aluminum	13	36	LF	5	2-5 years	
Stai	air Handrail - Steel_Stair Handrail	13	26	LF	6	10+ years	
Exte	terior Doors - Overhead Rolling/ Garage	13.5	1	EA	7	10+ years	
Doo	or					•	
Exte	terior Doors - Exterior Steel Door	14	2	EA	6	10+ years	
Rar	mps - Concrete	14	65	LF	7	10+ years	
Exte	terior Doors - Exterior Steel Door	15	2	EA	6	10+ years	
Exte	terior Stairs - Concrete	15	6	LF	7	10+ years	
Exte	terior Stairs - Steel or Aluminum	15	36	LF	4	0-1 year	Loose treads
Stai	air Handrail - Steel_Stair Handrail	15	26	LF	6	10+ years	
	trance Control - Audio and Video	16	1	EA	7	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	16	2	EA	6	10+ years	
	Exterior Doors - Side lite	16	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	16	4	EA	7	10+ years	
	Exterior Stairs - Concrete	16	102	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	16	9	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	16.5	2	EA	4	0-1 year	Entrance has been boarded up.
	Exterior Stairs - Concrete	16.5	6	LF	7	10+ years	·
	Exterior Doors - Exterior Steel Door	17	2	EA	7	10+ years	
	Exterior Doors - Side lite	17	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	17	3	EA	7	10+ years	
	Entrance Control - Audio and Video	2	1	EA	7	6-10 years	
	Exterior Doors - Store Front	2	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	2	3	EA	7	10+ years	
	Exterior Stairs - Concrete	2	18	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	2	130	LF	7	10+ years	
	Ramps - Concrete	2	65	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	2	16	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	3	2	EA	6	10+ years	
	Exterior Doors - Side lite	3	2	EA	6	10+ years	
	Exterior Stairs - Concrete	3	48	LF	7	10+ years	
	Exterior Doors - Store Front	4	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	4	1	EA	7	10+ years	
	Exterior Stairs - Concrete	4	23	LF	7	10+ years	
	Exterior Doors - Store Front	4.5	1	EA	7	10+ years	
	Exterior Doors - Exterior Wood Door	5	2	EA	6	6-10 years	
	Exterior Doors - Side lite	5	2	EA	7	10+ years	
	Ramps - Concrete	5	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	6	2	EA	5	1-2 years	Rusted.
	Exterior Stairs - Concrete	6	6	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior Steel Door	7	1	EA	6	10+ years	
	Exterior Stairs - Concrete	7	3	LF	7	10+ years	
	Entrance Control - Audio and Video	8	1	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	8	2	EA	7	10+ years	
	Exterior Doors - Side lite	8	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	8	- 1	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	9	2	EA	6	10+ years	
_Foundati	ion						
	Foundation - Concrete	Entire Building	2,036	LF	6	10+ years	Some seepage at weight room
	Superstructure - Concrete	Entire Building	117,000	SF	7	10+ years	21 000page at 1101g.11 10011
Lighting							
_ 	Exterior Lighting - Lighting	Entire Building	16	EA	6	6-10 years	Soffit
	Exterior Lighting - Wall Mounted	Entire Building	15	EΑ	7	6-10 years	
			.0	_, ,	•	,	



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Roof Sys	ctom						
_KUUL Sy:	Coping - Metal	1	680	LF	7	10+ years	
	Downspouts - Interior Downspouts	1	110	LF	6	10+ years	
	Parapet - Parapet < 16" Height	1	680	LF	7	10+ years	
	Roof - Modified Bitumen	1	23,690	SF	7	10+ years	No access to roof
	Roof Structure - Concrete	1	23,690	SF	7	10+ years	140 access to 1001
	Coping - Metal	10	23,030	LF	7	10+ years	
	Downspouts - Interior Downspouts	10	40	LF	6	10+ years	
	Parapet - Parapet < 16" Height	10	60	LF	7	10+ years	
	Roof - Modified Bitumen	10	403	SF	7	10+ years	No access
	Roof Structure - Concrete	10	403	SF	7		No access
		-				10+ years	
	Coping - Metal	2 2	405	LF LF	7	10+ years	
	Downspouts - Interior Downspouts		78		6	10+ years	
	Roof - Modified Bitumen	2	15,182	SF	7	10+ years	
	Roof Structure - Concrete	2	15,182	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	3	4	LF	6	10+ years	
	Liner	_			_		
	Chimney - Metal Flue	3	18	LF	7	10+ years	
	Coping - Metal	3	595	LF	7	10+ years	
	Downspouts - Exterior Downspouts	3	12	LF	6	10+ years	
	Downspouts - Interior Downspouts	3	120	LF	6	10+ years	
	Parapet - Parapet < 16" Height	3	595	LF	7	10+ years	
	Roof - Modified Bitumen	3	17,050	SF	6	10+ years	
	Roof Structure - Concrete	3	17,050	SF	7	10+ years	
	Coping - Metal	4	295	LF	6	10+ years	
	Downspouts - Interior Downspouts	4	48	LF	6	10+ years	
	Parapet - Parapet < 16" Height	4	295	LF	7	10+ years	
	Roof - Modified Bitumen	4	8,520	SF	5	2-5 years	
	Roof Structure - Concrete	4	8,520	SF	7	10+ years	
	Access Ladder - Metal	5	. 2	EA	7	10+ years	
	Coping - Metal	5	539	LF	7	10+ years	
	Downspouts - Interior Downspouts	5	187	LF	6	10+ years	
	Parapet - Parapet < 16" Height	5	539	LF	7	10+ years	
	Roof - Modified Bitumen	5	13,050	SF	7	10+ years	
	Roof Hatch - Metal	5	1	EA	7	10+ years	
	Roof Structure - Concrete	5	13,050	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	6	9	LF	6	10+ years	
	Liner		3		J	ioi youio	
	Coping - Metal	6	270	LF	7	10+ years	
	Downspouts - Exterior Downspouts	6	110	LF	6	10+ years	
	Downspouts - Interior Downspouts	6	25	LF	6	10+ years	
	Parapet - Parapet < 16" Height	6	270	LF	7	10+ years	
	Roof - Modified Bitumen	6	2,900	SF	7 7		
	NOOI - MOUINEU DILUMEN	U	2,900	SF	1	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Concrete	6	2,900	SF	7	10+ years	
	Coping - Metal	7	30	LF	7	10+ years	
	Downspouts - Exterior Downspouts	7	66	LF	6	10+ years	
	Parapet - Parapet < 16" Height	7	30	LF	7	10+ years	
	Roof - Modified Bitumen	7	630	SF	7	10+ years	
	Roof Structure - Concrete	7	630	SF	7	10+ years	
	Coping - Metal	8	50	LF	7	10+ years	
	Downspouts - Interior Downspouts	8	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	8	50	LF	7	10+ years	
	Roof - Modified Bitumen	8	1,355	SF	7	10+ years	
	Roof Structure - Concrete	8	1,355	SF	7	10+ years	
	Coping - Metal	9	60	LF	7	10+ years	
	Downspouts - Exterior Downspouts	9	11	LF	6	10+ years	
	Parapet - Parapet < 16" Height	9	60	LF	7	10+ years	
	Roof - Modified Bitumen	9	552	SF	7	10+ years	
	Roof Structure - Concrete	9	552	SF	7	10+ years	
	Noor Gradiane Gondreie	•	002	O.	,	101 years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	1,040	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	43,889	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	5,000	SF	5	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	50	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	646	SF	5	10+ years	
Windows							
	Clerestory - Glass Single-Pane	Entire Building	90	SF	4	1-2 years	Frames corroding, single pane, sealant deteriorated.
	Lintels - Steel	Entire Building	130	LF	6	10+ years	
	Storefront Windows	Entire Building	798	SF	7	10+ years	
	Windows - Casement Steel	Entire Building	17,510	SF	4	1-2 years	Un-insulated steel, leaks, won't close properly.
	Windows - Casement Steel	Entire Building	42	SF	4	0-1 year	Boarded up. Gym
	Windows - Decorative	Entire Building	251	SF	6	6-10 years	
	Windows - Louver	Entire Building	12	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
54.090	., . =			9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	40	EA	7	10+ years	
	Exit Signs - Gym	Entire Building	8	EA	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	4	EA	7	10+ years	



Calego	ry : Electrical			uildina	· Main		
	., , =		В	uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oloup	Exit Signs - Multipurpose Room	Entire Building	2	EA	7	10+ years	Comments
	Emergency A/C Power - Corridors and	Entire Building	9,168	SF	7	10+ years	
	Stairs	g	3,.33	О.	•	,	
	Emergency A/C Power - Gym	Entire Building	18,133	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	4,034	SF	7	10+ years	
	Emergency A/C Power - Multipurpose	Entire Building	2,953	SF	7	10+ years	
	Room	•				•	
	Emergency A/C Power - Students Toilets	Entire Building	1,625	SF	7	10+ years	
	Security System - CCTV	Entire Building	117,000	SF	7	10+ years	
	Security System - Intrusion Detection	Entire Building	117,000	SF	7	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	48	EA	7	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	8	EΑ	7	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	5	EA	7	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	12	EA	7	6-10 years	
Main Ser	vice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	117,000	SF	7	10+ years	
Power Di	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	6	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	
	amp						
Categor	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarr	m						
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	117,000	SF	7	10+ years	
	Fire Alarm_System	Entire Building	117,000	SF	7	10+ years	
Categor	ry : Mechanical		В	uilding	: Main		
_		Landan				Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condi		Poof	04	E^	7	10.1.400.00	Dual for 4 ton units
	Condensing Unit- Roof Mounted - Less	Roof	21	EA	7	10+ years	Dual fan 4 ton units



Catego	ry : Mechanical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	than 5 tons	Location	Qualitity	OCIVI	Italik	Replacement	Comments
	Condensing Unit- Roof Mounted - Less	Roof	5	EA	7	10+ years	
	than 5 tons					•	
Air Hand	ling Systems						
	VAV Box	Band Room 125 - VAV Boxes	6	EA	7	10+ years	Concealed above ceiling with unever- floor unsafe to use a ladder. Served from RTU-2. Installed in 2019.
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	26	EA	7	10+ years	
	Make Up Air Unit- Roof Mounted- Gas	Roof	2	EA	7	10+ years	
	Heating and DX Cooling with Self Contained Compressor - Less than 6000 cfm					•	
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Less	Roof	3	EA	7	10+ years	
	than 5 tons Make Up Air Unit- Roof Mounted- Gas	Roof	2	EA	7	10+ years	
	Heating - Less than 6000 cfm				_		
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	7	10+ years	
	Gas Heating and DX Cooling Coil - 11 - 20						
	tons	Doof	4	_^	0	0.40	There is no second to this well force
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons	Roof	1	EA	6	6-10 years	There is no access to this unit from the roof. Unit was existing prior to renovation.
Boiler Sy	estems						
•	Boiler Auxiliary- Condensing Hot Water - More than 4000 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - Greater 4000 MBH	Boiler Room	2	EA	7	10+ years	
	Water Fill System	Boiler Room	1	EA	7	10+ years	
leating I	Devices						
-	Unit Heater - Electric	1st Floor	1	EA	7	10+ years	
	Unit Heater - Hot Water	1st Floor	4	EA	7	10+ years	
	Fin Tube - Hot Water	Entire Building	3,000	LF	6	6-10 years	The valves have been replaced and the pipes
	Cabinet Heaters - With Hot Water Coil	Entire Building	25	EA	6	10+ years	
/lechani	cal Plumbing						
	Hot Water Pump - 21 - 50 HP	Boiler Room	2	EA	7	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	1,000	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	500	LF	7	10+ years	



Temperature Control	Catego	ry : Mechanical		R	uilding	· Main		00 W Berteau AVENUE, Chicago, IL 60634
Temperature Control	Calego	ry . Mechanica			unung	. Walli	Recommend	
Thermostats - DDC Entire Building 117,000 SF 7 10+ years Interest in a DDC system Entire Building 117,000 SF 7 10+ years Interest in a DDC system yet, the installation of heating systems, cooling and electric is still an ong process. Ventitation	Group	Item - Tyne	Location	Quantity	UOM	Rank		Comments
DDC System	Oroup	Rom Typo	20041011	quantity	COIN	rturiit	rtopiacomont	Commonto
DDC System	Tempera	ature Control						
Thermostats - DDC			Entire Building	117,000	SF	7	10+ years	
Ventilation		Thermostats - DDC	Entire Buildina	40	EA	7	10+ vears	
Exhaust Fans- Indoor - 1501 - 8000 CFM Entire Building 2			ŭ				,	
Exhaust Fans- Roof Mounted - 500 - 1500 CPM Exhaust Fans- Roof Mounted - Greater than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Roof Mounted Duct Work 8000 FM Roof Mounted Duct Work 9000 FM 8000 FM 8000 FM 8000 FM 8000 FM 9000 FM 9	Ventilation	on						
CFM Exhaust Fans- Roof Mounted - Greater than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Exhaust Fans- Roof Mounted - Less than 8000 CFM Roof Mounted Duct Work 91 Exhaust Hood- Kitchen 92 Entire Building 100					EA	7	10+ years	
B000 CFM Exhaust Fans- Roof Mounted - Less than Entire Building 4 EA 7 10+ years S00 CFM Roof Mounted Duct Work Entire Building 10 LF 7 10+ years Located on Roof 2.		CFM	· ·	2			10+ years	
Solid CFM Roof Mounted Duct Work Entire Building 100 LF 7 10+ years Located on Roof 2.		8000 CFM	· ·	·			-	
Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen Entire Building Type II Exhaust Hood- Water Horizontal Entire Building Type II Exhaust Horizontal Type II Exhaust Recomment Type II Exhaust Recomment Type II Exhaust Recomment Type II Exhaust Recomment Type II II Horizontal Entire Building Type II		500 CFM	S .				,	
Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 7 10+ years Category : Plumbing Building : Main								Located on Roof 2.
Category : Plumbing Forum Item - Type Location Quantity UOM Rank Replacement Comments				•				
Recommend Replacement Comments		Type II Exnaust Hood- Warming Kitchen	Entire Building	1	EA	/	10+ years	
Item - Type	Catego	ry : Plumbing		В	uilding	: Main		
Hot Water Gas Heater - 300001 - 600000 BTU/HR Boiler Room 3 EA 7 10+ years Piping Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Pumps		_						
Piping Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 117,000 SF 7 10+ years 117,000 SF 7 10+ year	•		Location	Quantity	UOM	Rank	Replacement	Comments
Domestic Piping-Cold Water Horizontal Entire Building 117,000 SF 7 10+ years Lines Domestic Piping-Cold Water Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Cold Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years	Hot Wate							
Domestic Piping-Cold Water Horizontal Entire Building 117,000 SF 7 10+ years Domestic Piping-Cold Water Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Cold Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Pumps		Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	3	EA	7	10+ years	
Domestic Piping-Cold Water Horizontal Entire Building 117,000 SF 7 10+ years Domestic Piping-Cold Water Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Cold Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Pumps								
Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Entire Building Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers Domestic Piping-Hot Water from Risers Domestic Piping-Hot Water from Risers Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Entire Building Domestic Piping-Hot Water Risers Domestic Piping-Hot Water Return Lines Entire Building Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Lines Entire Building Domestic Piping-Hot Water Return Lines	_Piping							
Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Lines Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years		Lines	3				,	
Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers to Entire Building Entire Building Entire Building Domestic Piping Entire Building Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping Entire Building Domestic Piping Entire Building Domestic Piping Entire Building Domestic Piping Domestic Piping-Hot Water Return Risers Entire Building Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Entire Building Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Entire Building Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Lines Entire Building Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Pipin			S S				•	
Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Entire Building Domestic Piping-Hot Water from Risers to Entire Building Entir		Fixtures	· ·				,	
Domestic Piping-Hot Water Return Risers Entire Building 117,000 SF 7 10+ years Domestic Piping-Hot Water from Risers to Entire Building 117,000 SF 7 10+ years Fixtures Sanitary Piping Entire Building 117,000 SF 7 10+ years Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Pumps			S S	,			,	
Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping Storm Piping Vent Piping Entire Building Fixtures Storm Piping Fixtures Storm Piping Fixtures Storm Piping Fixtures Fixtures Fixtures Storm Piping Fixtures Fixtures Storm Piping Fixtures Fixtures Storm Piping Fixtures Fixtures Fixtures Storm Piping Fixtures Fixtures Fixtures Storm Piping Fixtures Fixtur			3	,			,	
Fixtures Sanitary Piping Entire Building Storm Piping Fixtures F			S .					
Storm Piping Entire Building 117,000 SF 7 10+ years Vent Piping Entire Building 117,000 SF 7 10+ years Pumps		Fixtures	· ·				-	
Vent Piping Entire Building 117,000 SF 7 10+ years Pumps			· ·				,	
_Pumps				,				
		vent riping	Entire Building	117,000	SI	,	10+ years	
	Pumps							
		Pumps - Sump-Duplex	Boiler Room	1	EA	7	10+ years	



Building: Main Category : Plumbing

Recommend Group Location UOM Rank Item - Type Quantity Replacement Comments Pumps - Sump-Simplex 10+ years Elevator pit pump. Boiler Room EΑ 7

Category: Room Building: Main

	ory : Room	Building : Main Recommend							
up	Item - Type	Location	Quantity	UOM	Rank		Comments		
		LUGATION	Qualitity	UUIVI	Kdlik	Replacement	Comments		
IIS	strative Suites/Offices								
	Ceiling - Lay-in	128A - Practice Room	66	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128A - Practice Room	1	EA	7	10+ years			
	Floor - Concrete	128A - Practice Room	66	SF	7	10+ years			
	Lighting - Lay-in	128A - Practice Room	2	EA	7	6-10 years			
	Power Distribution	128A - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	128A - Practice Room	256	SF	6	10+ years			
	Ceiling - Lay-in	128B - Practice Room	85	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128B - Practice Room	1	EA	7	10+ years			
	Floor - Concrete	128B - Practice Room	85	SF	7	10+ years			
	Lighting - Lay-in	128B - Practice Room	2	EA	7	6-10 years			
	Power Distribution	128B - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	128B - Practice Room	304	SF	6	10+ years			
	Ceiling - Lay-in	128C - Practice Room	52	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128C - Practice Room	1	EA	7	10+ years			
	Floor - Concrete	128C - Practice Room	52	SF	7	10+ years			
	Lighting - Lay-in	128C - Practice Room	1	EA	7	6-10 years			
	Power Distribution	128C - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	128C - Practice Room	240	SF	6	10+ years			
	Ceiling - Lay-in	128D - Practice Room	82	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128D - Practice Room	1	EA	7	10+ years			
	Floor - Concrete	128D - Practice Room	82	SF	7	10+ years			
	Lighting - Lay-in	128D - Practice Room	1	EA	7	6-10 years			
	Power Distribution	128D - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	128D - Practice Room	312	SF	6	10+ years			
	Ceiling - Lay-in	128E - Practice Room	69	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128E - Practice Room	1	EA	7	10+ years			
	Floor - Concrete	128E - Practice Room	69	SF	7	10+ years			
	Lighting - Lay-in	128E - Practice Room	1	EA	7	6-10 years			
	Power Distribution	128E - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	128E - Practice Room	192	SF	6	10+ years			
	Ceiling - Splined	1st FI - Band Practice Rms 125A-	565	SF	6	10+ years			
		125E				•			
	Doors - Wood Doors inclu hw	1st FI - Band Practice Rms 125A-	5	EA	6	10+ years			
		125E				•			
	Floor - Tile	1st FI - Band Practice Rms 125A-	565	SF	6	10+ years			
		125E				,			
	Lighting - Pendent/Surface	1st FI - Band Practice Rms 125A-	5	EA	6	10+ years			
		125E				,			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	1st FI - Band Practice Rms 125A- 125E	12	EA	6	10+ years	
	Walls - Concrete Block	1st FI - Band Practice Rms 125A- 125E	950	SF	7	10+ years	
	Ceiling - Exposed	1st FI - Engineer Office in Boiler Rm LL10-P	148	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st FI - Engineer Office in Boiler Rm LL10-P	1	EA	7	10+ years	
	Floor - Wood	1st FI - Engineer Office in Boiler Rm LL10-P	148	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Engineer Office in Boiler Rm LL10-P	4	EA	7	6-10 years	
	Power Distribution	1st FI - Engineer Office in Boiler Rm LL10-P	4	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Engineer Office in Boiler Rm LL10-P	372	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Engineer Office in Boiler Rm LL10-P	124	SF	7	10+ years	
	Ceiling - Splined	1st FI - LL14-P Conference Room	372	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI - LL14-P Conference Room	1	EA	7	10+ years	
	Floor - Carpet	1st FI - LL14-P Conference Room	372	SF	6	6-10 years	
	Lighting - Wall Mounted	1st FI - LL14-P Conference Room	6	EA	7	6-10 years	
	Power Distribution	1st FI - LL14-P Conference Room	4	EA	7	10+ years	
	Walls - Masonry	1st FI - LL14-P Conference Room	585	SF	7	10+ years	
	Walls - Metal Panel	1st FI - LL14-P Conference Room	579	SF	7	10+ years	
	Ceiling - Splined	1st FI - Main Office Suite 121	534	SF	6	10+ years	
	Ceiling - Splined	1st FI - Main Office Suite 121	200	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st FI - Main Office Suite 121	4	ĒΑ	6	10+ years	go.
	Floor - Tile	1st FI - Main Office Suite 121	734	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Main Office Suite 121	16	ĒΑ	6	6-10 years	
	Power Distribution	1st FI - Main Office Suite 121	12	EΑ	7	10+ years	
	Walls - Concrete Block	1st FI - Main Office Suite 121	980	SF	6	10+ years	
	Walls - Plaster/Drywall	1st FI - Main Office Suite 121	420	SF	6	10+ years	wood paneling
	Ceiling - Plaster/Drywall	1st FI - Office 101P / 13G - Upper Gym	353	SF	7	10+ years	nood panomig
	Doors - Steel Doors incl hw	1st FI - Office 101P / 13G - Upper Gym	1	EA	6	10+ years	
	Floor - Tile	1st FI - Office 101P / 13G - Upper Gym	353	SF	6	10+ years	
	Lighting - Pendent/Surface	1st FI - Office 101P / 13G - Upper Gym	4	EA	7	10+ years	
	Power Distribution	1st FI - Office 101P / 13G - Upper Gym	6	EA	6	10+ years	
	Walls - Concrete Block	1st FI - Office 101P / 13G - Upper	750	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Gym					
	Ceiling - Lay-in	1st FI - Office 108 near black box	166	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Office 108 near black box	2	SF	4	0-1 year	Missing tile
	Doors - Store Front	1st FI - Office 108 near black box	1	EA	7	10+ years	
	Floor - Tile	1st FI - Office 108 near black box	168	SF	6	10+ years	
	Lighting - Lay-in	1st FI - Office 108 near black box	6	EA	7	6-10 years	
	Power Distribution	1st FI - Office 108 near black box	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Office 108 near black box	676	SF	7	10+ years	
	Work SInk	1st FI - Office 108 near black box	1	EA	7	10+ years	
	Ceiling - Lay-in	1st FI - Office Kitchen 128	74	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Office Kitchen 128	1	EA	7	10+ years	
	Floor - Tile	1st FI - Office Kitchen 128	74	SF	7	10+ years	
	Lighting - Lay-in	1st FI - Office Kitchen 128	1	EA	7	10+ years	
	Power Distribution	1st FI - Office Kitchen 128	5	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Office Kitchen 128	305	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Office Suite 112P - Principal	548	SF	7	10+ years	
	Ceiling - Splined	1st FI - Office Suite 112P - Principal	60	SF	4	1-2 years	Water damaged, missing tiles
	Doors - Wood Doors inclu hw	1st FI - Office Suite 112P - Principal	3	EA	7	10+ years	
	Floor - Carpet	1st FI - Office Suite 112P - Principal	608	SF	7	6-10 years	
	Lighting - Lay-in	1st FI - Office Suite 112P - Principal	9	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Office Suite 112P - Principal	1	EA	5	6-10 years	
	Power Distribution	1st FI - Office Suite 112P - Principal	10	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Office Suite 112P - Principal	1,040	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st FI - office 111P in men's locker rm 109	175	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - office 111P in men's locker rm 109	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI - office 111P in men's locker rm 109	175	SF	6	10+ years	
	Lighting - Pendent/Surface	1st FI - office 111P in men's locker rm 109	2	EA	7	10+ years	
	Power Distribution	1st FI - office 111P in men's locker rm 109	3	EA	7	10+ years	
	Walls - Concrete Block	1st FI - office 111P in men's locker rm 109	400	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FI - office 111P in men's locker rm 109	110	SF	7	10+ years	
	Ceiling - Splined	203-PA	130	SF	7	10+ years	
	Doors - Steel Doors incl hw	203-PA	1	ĒΑ	7	10+ years	
	Floor - Carpet	203-PA	130	SF	7	6-10 years	
	Lighting - Pendent/Surface	203-PA	4	ĒΑ	7	10+ years	
	Power Distribution	203-PA	6	EA	7	10+ years	
	Walls - Concrete Block	203-PA	335	SF	7	10+ years	
	Ceiling - Lay-in	203-PB	185	SF	7	10+ years	
	•					·	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	203-PB	1	EA	7	10+ years	
	Floor - Carpet	203-PB	185	SF	7	6-10 years	
	Lighting - Pendent/Surface	203-PB	4	EA	7	10+ years	
	Power Distribution	203-PB	6	EA	7	10+ years	
	Walls - Concrete Block	203-PB	365	SF	7	10+ years	
	Ceiling - Splined	203-PC	86	SF	7	10+ years	
	Doors - Wood Doors inclu hw	203-PC	1	EA	7	10+ years	
	Floor - Carpet	203-PC	86	SF	7	6-10 years	
	Lighting - Pendent/Surface	203-PC	2	EA	7	10+ years	
	Power Distribution	203-PC	4	EA	7	10+ years	
	Walls - Concrete Block	203-PC	175	SF	7	10+ years	
	Ceiling - Splined	203-PD	68	SF	7	10+ years	
	Doors - Steel Doors incl hw	203-PD	1	EA	7	10+ years	
	Floor - Carpet	203-PD	68	SF	7	6-10 years	
	Lighting - Pendent/Surface	203-PD	2	EA	7	10+ years	
	Power Distribution	203-PD	4	EA	7	10+ years	
	Walls - Concrete Block	203-PD	114	SF	7	10+ years	
	Ceiling - Lay-in	203-PE	148	SF	7	10+ years	
	Doors - Steel Doors incl hw	203-PE	2	EA	7	10+ years	
	Floor - Carpet	203-PE	148	SF	7	6-10 years	
	Lighting - Lay-in	203-PE	3	EA	6	10+ years	
	Power Distribution	203-PE	8	EA	7	10+ years	
	Storage/ Closet	203-PE	68	SF	7	10+ years	
	Walls - Concrete Block	203-PE	312	SF	7	10+ years	
	Walls - Masonry	203-PE	10	SF	7	10+ years	
	Ceiling - Splined	206-P	562	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206-P	1	EA	7	10+ years	
	Floor - Wood	206-P	562	SF	7	10+ years	
	Lighting - Pendent/Surface	206-P	9	EA	7	10+ years	
	Power Distribution	206-P	20	EA	7	10+ years	
	Storage/ Closet	206-P	3	SF	7	10+ years	
	Walls - Concrete Block	206-P	222	SF	7	10+ years	
	Walls - Masonry	206-P	10	SF	7	10+ years	
	Walls - Plaster/Drywall	206-P	235	SF	7	10+ years	
	Ceiling - Lay-in	206-PA	83	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206-PA	1	EA	7	10+ years	
	Floor - Wood	206-PA	83	SF	7	10+ years	
	Lighting - Lay-in	206-PA	2	EA	7	10+ years	
	Power Distribution	206-PA	8	EA	7	10+ years	
	Walls - Plaster/Drywall	206-PA	154	SF	7	10+ years	
	Ceiling - Lay-in	206-PB	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206-PB	1	ĒΑ	7	10+ years	
	Floor - Wood	206-PB	81	SF	7	10+ years	
	Lighting - Lay-in	206-PB	2	ĒΑ	7	10+ years	
	3 · 3 ——, ···		_		-	,	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	206-PB	8	EA	7	10+ years	
	Walls - Plaster/Drywall	206-PB	154	SF	7	10+ years	
	Ceiling - Lay-in	212-P - Teacher's Lounge	511	SF	7	10+ years	
	Doors - Wood Doors inclu hw	212-P - Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile	212-P - Teacher's Lounge	511	SF	7	10+ years	
	Lighting - Lay-in	212-P - Teacher's Lounge	21	EA	7	10+ years	
	Power Distribution	212-P - Teacher's Lounge	12	EA	7	10+ years	
	Walls - Concrete Block	212-P - Teacher's Lounge	120	SF	7	10+ years	
	Walls - Plaster/Drywall	212-P - Teacher's Lounge	665	SF	7	10+ years	
	Work SInk	212-P - Teacher's Lounge	1	EA	7	10+ years	
	AC Unit	217-P - Teacher's Workroom	1	EA	7	6-10 years	
	Ceiling - Splined	217-P - Teacher's Workroom	738	SF	7	10+ years	
	Doors - Wood Doors inclu hw	217-P - Teacher's Workroom	1	EA	7	10+ years	
	Floor - Tile	217-P - Teacher's Workroom	738	SF	7	10+ years	
	Lighting - Pendent/Surface	217-P - Teacher's Workroom	15	EA	7	10+ years	
	Power Distribution	217-P - Teacher's Workroom	10	EΑ	7	10+ years	
	Storage/ Closet	217-P - Teacher's Workroom	19	SF	7	10+ years	
	Walls - Concrete Block	217-P - Teacher's Workroom	575	SF	7	10+ years	
	Walls - Masonry	217-P - Teacher's Workroom	10	SF	7	10+ years	
	Walls - Plaster/Drywall	217-P - Teacher's Workroom	50	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Exercise Rm 004	1,028	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement - Exercise Rm 004	6	EA	6	10+ years	
	Floor - Concrete	Basement - Exercise Rm 004	1,028	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Exercise Rm 004	18	EA	6	6-10 years	
	Power Distribution	Basement - Exercise Rm 004	6	EA	7	10+ years	
	Storage/ Closet	Basement - Exercise Rm 004	77	SF	5	10+ years	
	Walls - Concrete Block	Basement - Exercise Rm 004	1,760	SF	6	10+ years	
	Work SInk	Basement - Exercise Rm 004	1	EA	7	10+ years	
	Ceiling - Exposed	Basement - Office 014 at Boys Lockers	189	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Office 014 at Boys Lockers	1	EA	6	10+ years	
	Floor - Tile/Sheet	Basement - Office 014 at Boys Lockers	189	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement - Office 014 at Boys Lockers	2	EA	7	6-10 years	
	Power Distribution	Basement - Office 014 at Boys Lockers	4	EA	7	10+ years	
	Walls - Concrete Block	Basement - Office 014 at Boys Lockers	470	SF	7	10+ years	
	Ceiling - Lay-in	Mezzanine office 151	372	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mezzanine office 151	1	EΑ	7	10+ years	
	Floor - Tile	Mezzanine office 151	372	SF	7	10+ years	
	Lighting - Lay-in	Mezzanine office 151	4	ĒΑ	7	10+ years	
	5 5					,	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Mezzanine office 151	20	EA	7	10+ years	
	Walls - Concrete Block	Mezzanine office 151	250	SF	7	10+ years	
	Walls - Masonry	Mezzanine office 151	125	SF	7	10+ years	
	Ceiling - Lay-in	Mezzanine office 152	448	SF	7	10+ years	
	Ceiling - Lay-in	Mezzanine office 152	12	SF	4	0-1 year	Missing ceiling tiles.
	Doors - Steel Doors incl hw	Mezzanine office 152	2	EΑ	7	10+ years	-
	Floor - Concrete	Mezzanine office 152	460	SF	5	10+ years	
	Lighting - Lay-in	Mezzanine office 152	4	EA	7	10+ years	
	Power Distribution	Mezzanine office 152	8	EA	7	10+ years	
	Walls - Concrete Block	Mezzanine office 152	25	SF	7	10+ years	
	Walls - Masonry	Mezzanine office 152	512	SF	7	10+ years	
Auditoriu	m & Theater						
	AC Unit	1st Fl - Black Box Theater 105	2	EA	7	10+ years	
	Ceiling - Exposed	1st FI - Black Box Theater 105	1,872	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Black Box Theater 105	3	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st FI - Black Box Theater 105	1,872	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Black Box Theater 105	36	EA	7	10+ years	
	Sound System	1st FI - Black Box Theater 105	1	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Black Box Theater 105	1,410	SF	7	10+ years	
	Walls - Coliciete block	15t F1 - Black Box Theater 105	1,410	SF	,	10+ years	
Gymnasi	a						
	Bleacher Seating	1st FI - Lower Gym 20	250	EΑ	6	10+ years	
	Ceiling - Exposed	1st FI - Lower Gym 20	9,093	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Lower Gym 20	6	EA	6	10+ years	
	Floor - Wood	1st FI - Lower Gym 20	9,093	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Lower Gym 20	36	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st FI - Lower Gym 20	3,250	SF	7	10+ years	
	Bleacher Seating	1st FI - Upper Gym 100	150	EA	6	10+ years	
	Ceiling - Exposed	1st FI - Upper Gym 100	9,040	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st FI - Upper Gym 100	4	EA	6	10+ years	
	Floor - Wood	1st FI - Upper Gym 100	9,040	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Upper Gym 100	36	EA	7	10+ years	
	Scoreboards	1st FI - Upper Gym 100		EA			
			2 1	EA	7 7	10+ years	
	Sound System	1st FI - Upper Gym 100		SF		10+ years	
	Storage/ Closet	1st FI - Upper Gym 100	522		7	10+ years	
	Walls - Concrete Block	1st FI - Upper Gym 100	13,250	SF	7	10+ years	
	Ceiling - Lay-in	Mezzanine wrestling room 154	2,782	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mezzanine wrestling room 154	2	EA	7	10+ years	
	Floor - Concrete	Mezzanine wrestling room 154	2,782	SF	7	10+ years	
	Lighting - Lay-in	Mezzanine wrestling room 154	21	EA	7	10+ years	
	Storage/ Closet	Mezzanine wrestling room 154	6	SF	7	10+ years	
	Walls - Concrete Block	Mezzanine wrestling room 154	2,475	SF	7	10+ years	
	Walls - Masonry	Mezzanine wrestling room 154	275	SF	7	10+ years	



	/:Room			uilding	. IVIAIII		
						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
'	Walls - Plaster/Drywall	Mezzanine wrestling room 154	230	SF	7	10+ years	
10. 1							
Kitchen		=					
	Ceiling - Lay-in	1st FI - Black Box Kitchen 106	119	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Black Box Kitchen 106		EA	7	10+ years	
	Floor - Tile	1st FI - Black Box Kitchen 106	119	SF	6	10+ years	
	Lighting - Lay-in	1st FI - Black Box Kitchen 106	3	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Black Box Kitchen 106	388	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Kitchen 129-K	917	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Kitchen 129-K	5	EA	7	10+ years	
	Floor - Tile Quarry	1st FI - Kitchen 129-K	917	SF	7	10+ years	
	Lighting - Lay-in	1st FI - Kitchen 129-K	31	EA	7	10+ years	
	Serving Line	1st FI - Kitchen 129-K	24	LF	7	10+ years	
	Storage/ Closet	1st FI - Kitchen 129-K	116	SF	7	10+ years	
1	Walls - Vinyl Coated Gypsum Panel	1st FI - Kitchen 129-K	1,470	SF	7	10+ years	
_Locker/Sho	ower Room						
	Accessories	1st FI - Men's Locker 109	50	SF	7	10+ years	
	Benches, ped mounted	1st FI - Men's Locker 109	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st FI - Men's Locker 109	1,420	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Men's Locker 109	2	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st FI - Men's Locker 109	1,370	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI - Men's Locker 109	50	SF	7	10+ years	
	Floor Drain	1st FI - Men's Locker 109	11	ĒΑ	7	10+ years	
	Hand Dryer	1st FI - Men's Locker 109	1	EΑ	7	6-10 years	
	Lavatory	1st FI - Men's Locker 109	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Men's Locker 109	11	EΑ	7	10+ years	
	Showers	1st FI - Men's Locker 109	10	EΑ	7	10+ years	
	Storage/ Closet	1st FI - Men's Locker 109	74	SF	7	10+ years	
	Student Lockers - One Tier	1st FI - Men's Locker 109	40	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Men's Locker 109	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Men's Locker 109	250	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Men's Locker 109	650	SF	7	10+ years	
	Water Closet	1st FI - Men's Locker 109	1	EA	7	10+ years	
	Accessories	1st FI - Women's Locker 109	50	SF	7	10+ years	
	Benches, ped mounted	1st FI - Women's Locker 113	28	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st FI - Women's Locker 113	1,305	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Women's Locker 113	1,303	EA	7	10+ years 10+ years	
	Floor - Concrete Epoxy/ Painted	1st FI - Women's Locker 113	1,265	SF	7	10+ years	
	Floor - Tile/Sheet	1st FI - Women's Locker 113	1,265 50	SF	7		
	Floor - Tile/Sheet Floor Drain		11	Sr EA	7	10+ years	
		1st FI - Women's Locker 113			7	10+ years	
	Hand Dryer	1st FI - Women's Locker 113	1	EA EA	7 7	10+ years	
	Lavatory	1st FI - Women's Locker 113	1	EA EA	7 7	10+ years	
l	Lighting - Pendent/Surface	1st FI - Women's Locker 113	15	ĽΑ	1	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Showers	1st FI - Women's Locker 113	10	EA	7	10+ years	
	Student Lockers - One Tier	1st FI - Women's Locker 113	40	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Women's Locker 113	1,020	SF	7	10+ years	
	Walls - Tile	1st FI - Women's Locker 113	650	SF	7	10+ years	
	Water Closet	1st FI - Women's Locker 113	1	EA	7	10+ years	
	Accessories	S06-L in Basement	790	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	S06-L in Basement	790	SF	6	10+ years	
	Doors - Wood Doors inclu hw	S06-L in Basement	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	S06-L in Basement	790	SF	5	10+ years	
	Floor - Terrazzo	S06-L in Basement	25	SF	6	10+ years	
	Floor Drain	S06-L in Basement	6	EA	7	10+ years	
	Lavatory	S06-L in Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	S06-L in Basement	12	EA	6	6-10 years	
	Showers	S06-L in Basement	8	EΑ	5	10+ years	
	Storage/ Closet	S06-L in Basement	110	SF	5	10+ years	
	Student Lockers - Two Tier	S06-L in Basement	20	ĒΑ	6	10+ years	
	Walls - Concrete Block	S06-L in Basement	1,100	SF	6	10+ years	
	Water Closet	S06-L in Basement	1	ĒΑ	6	10+ years	
	Accessories	S07-L in Basement	891	SF	4	1-2 years	
	Benches, ped mounted	S07-L in Basement	32	LF	6	10+ years	
	Ceiling - Exposed	S07-L in Basement	891	SF	6	10+ years	
	Doors - Wood Doors inclu hw	S07-L in Basement	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	S07-L in Basement	891	SF	5	10+ years	
	Floor Drain	S07-L in Basement	4	EA	7	10+ years	
	Lavatory	S07-L in Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	S07-L in Basement	12	EA	6	6-10 years	
	Storage/ Closet	S07-L in Basement	20	SF	5	10+ years	
	Student Lockers - Two Tier	S07-L in Basement	40	EA	6	10+ years	
	Walls - Concrete Block	S07-L in Basement	1,320	SF	6	10+ years	
	Water Closet	S07-L in Basement	1,320	EA	6	10+ years	
	Water Closet	307-L III basement	'	LA	O	10+ years	
Lunch 9	Multipurpose Room						
LUIICII &	Ceiling - Splined	1st FI - Cafeteria/ Auditorium 127-M	4,034	SF	7	10+ years	
	Doors - Store Front	1st FI - Cafeteria/ Auditorium 127-M	4,034	EA	7		
	Doors - Wood Doors inclu hw		2	EA	6	10+ years	
		1st FI - Cafeteria/ Auditorium 127-M	4,034	SF	4	10+ years	Old brooking throughout
	Floor - Tile	1st FI - Cafeteria/ Auditorium 127-M	4,034 24	SF EA	4 7	0-1 year	Old, breaking throughout.
	Lighting - Pendent/Surface	1st FI - Cafeteria/ Auditorium 127-M				10+ years	
	Serving Line	1st FI - Cafeteria/ Auditorium 127-M	14	LF	7	10+ years	
	Sound System	1st FI - Cafeteria/ Auditorium 127-M	1 207	EA	7	10+ years	
	Stage	1st FI - Cafeteria/ Auditorium 127-M	1,297	SF	6	10+ years	
	Stage Curtain	1st FI - Cafeteria/ Auditorium 127-M	1	EΑ	7	10+ years	
	Stage Lift	1st FI - Cafeteria/ Auditorium 127-M	1	EΑ	7	10+ years	
	Stage Lighting System	1st FI - Cafeteria/ Auditorium 127-M	1	EA	5	10+ years	
	Stage-Stairs - Wood	1st FI - Cafeteria/ Auditorium 127-M	25	LF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st FI - Cafeteria/ Auditorium 127-M	116	SF	7	10+ years	
	Storage/ Closet	1st FI - Cafeteria/ Auditorium 127-M	336	SF	7	10+ years	
	Walls - Concrete Block	1st FI - Cafeteria/ Auditorium 127-M	2,176	SF	6	10+ years	
	Walls - Masonry	1st FI - Cafeteria/ Auditorium 127-M	850	SF	7	10+ years	Brick
	AC Unit	1st Fl - Faculty Lounge 125-M Northeast	1	EA	7	6-10 years	
	Ceiling - Splined	1st Fl - Faculty Lounge 125-M Northeast	427	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Faculty Lounge 125-M Northeast	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Fl - Faculty Lounge 125-M Northeast	1	EA	6	10+ years	
	Floor - Tile	1st FI - Faculty Lounge 125-M Northeast	427	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Fl - Faculty Lounge 125-M Northeast	5	EA	7	10+ years	
	Market Board	1st FI - Faculty Lounge 125-M Northeast	18	LF	7	6-10 years	
	Walls - Concrete Block	1st FI - Faculty Lounge 125-M Northeast	610	SF	7	10+ years	
	AC Unit	1st FI - Multipurpose Rm 110/ rm 26	1	EA	7	10+ years	Mini split?
	Ceiling - Splined	1st FI - Multipurpose Rm 110/ rm 26	1,261	SF	7	10+ years	·
	Doors - Wood Doors inclu hw	1st FI - Multipurpose Rm 110/ rm 26	2	EA	7	10+ years	
	Floor - Tile	1st FI - Multipurpose Rm 110/ rm 26	1,261	SF	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Multipurpose Rm 110/ rm 26	21	EA	7	10+ years	
	Storage/ Closet	1st FI - Multipurpose Rm 110/ rm 26	58	SF	7	10+ years	
	Walls - Concrete Block	1st FI - Multipurpose Rm 110/ rm 26	1,040	SF	7	10+ years	
	Ceiling - Splined	1st Multi purpose 120-M North	1,692	SF	6	10+ years	
	Doors - Store Front	1st Multi purpose 120-M North	1	EA	7	10+ years	
	Floor - Wood	1st Multi purpose 120-M North	1,692	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Multi purpose 120-M North	40	EA	7	10+ years	
	Storage/ Closet	1st Multi purpose 120-M North	116	SF	7	10+ years	
	Walls - Concrete Block	1st Multi purpose 120-M North	940	SF	6	10+ years	
	Walls - Masonry	1st Multi purpose 120-M North	2,200	SF	7	10+ years	
	Ceiling - Splined	201 Media Center	1,838	SF	7	10+ years	
	Doors - Wood Doors inclu hw	201 Media Center	2	EA	7	10+ years	
	Floor - Tile	201 Media Center	1,838	SF	7	10+ years	
	Lighting - Pendent/Surface	201 Media Center	47	ĒΑ	7	10+ years	
	Storage/ Closet	201 Media Center	165	SF	7	10+ years	
	Walls - Concrete Block	201 Media Center	1,456	SF	7	10+ years	
	Walls - Masonry	201 Media Center	150	SF	7	10+ years	
	Walls - Plaster/Drywall	201 Media Center	175	SF	7	10+ years	
אחר וח	· -					-	

_MDF_IDF



Catego	ory : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st FI - IDF 132	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - IDF 132	1	EA	4	0-1 year	Door is damaged and missing hardware.
	Finishes	1st FI - IDF 132	287	SF	7	10+ years	
	Other Cooling Unit	1st FI - IDF 132	1	EA	7	6-10 years	
	Doors - Steel Doors incl hw	1st FI - IT / IDF 24	1	EA	7	10+ years	
	Finishes	1st FI - IT / IDF 24	95	SF	7	10+ years	
	Other Cooling Unit	1st FI - IT / IDF 24	1	ĒΑ	7	10+ years	Ductless split system.
	Doors - Steel Doors incl hw	205-P	1	EA	7	10+ years	
	Finishes	205-P	238	SF	7	10+ years	
	Other Cooling Unit	205-P	1	ĒΑ	7	6-10 years	
_Mechan	ical/ Service Rooms						
	Boiler Room	1st Floor	2,110	SF	7	10+ years	
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	306	SF	7	10+ years	Switchgear rm 133
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	3
	Boiler Room	Basement	190	SF	7	10+ years	
	Storage Room	Basement	1,156	SF	5	10+ years	
	Storage Room	Basement	1,272	SF	5	10+ years	
	Storage Room	Basement	120	SF	5	10+ years	
	Storage Room	Basement	185	SF	5	10+ years	
Prep Ro	om						
•	Ceiling - Lay-in	1st FI - Bio Prep LL01	327	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Bio Prep LL01	2	EA	7	10+ years	
	Floor - Tile	1st FI - Bio Prep LL01	327	SF	7	10+ years	
	Lighting - Lay-in	1st FI - Bio Prep LL01	8	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Bio Prep LL01	524	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st FI - Bio Prep LL01	340	SF	7	10+ years	
	Work Sink	1st FI - Bio Prep LL01	1	EA	7	10+ years	Installation in progress
	Ceiling - Lay-in	1st FI - Physics Prep LL05	349	SF	7	10+ years	. 0
	Doors - Wood Doors inclu hw	1st FI - Physics Prep LL05	2	EA	7	10+ years	
	Floor - Tile	1st FI - Physics Prep LL05	349	SF	7	10+ years	
	Lighting - Lay-in	1st FI - Physics Prep LL05	8	ĒΑ	7	10+ years	
	Walls - Concrete Block	1st FI - Physics Prep LL05	745	SF	7	10+ years	
Restroo	m						
	Accessories	1st FI - Boys NE cafeteria	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI - Boys NE cafeteria	180	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Boys NE cafeteria	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI - Boys NE cafeteria	180	SF	7	10+ years	
	Floor Drain	1st FI - Boys NE cafeteria	1	ĒΑ	7	10+ years	
		•				,	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st FI - Boys NE cafeteria	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Boys NE cafeteria	3	EA	7	6-10 years	
	Partitions	1st FI - Boys NE cafeteria	2	EA	7	10+ years	
	Urinals	1st FI - Boys NE cafeteria	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Boys NE cafeteria	696	SF	7	10+ years	
	Water Closet	1st FI - Boys NE cafeteria	2	EA	7	10+ years	
	Accessories	1st FI - Boys SE LL04	148	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Boys SE LL04	148	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Boys SE LL04	1	EA	6	10+ years	
	Floor - Tile	1st FI - Boys SE LL04	148	SF	6	10+ years	
	Floor Drain	1st FI - Boys SE LL04	1	EΑ	7	10+ years	
	Hand Dryer	1st FI - Boys SE LL04	1	EA	7	10+ years	
	Lavatory	1st FI - Boys SE LL04	2	EΑ	7	10+ years	
	Lighting - Lay-in	1st FI - Boys SE LL04	2	EΑ	7	10+ years	
	Partitions	1st FI - Boys SE LL04	2	EA	7	10+ years	
	Urinals	1st FI - Boys SE LL04	3	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Boys SE LL04	420	SF	7	10+ years	
	Water Closet	1st FI - Boys SE LL04	2	EA	7	10+ years	
	Accessories	1st FI - Boys SW	99	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Boys SW	99	SF	7	10+ years	Installation in progress
	Doors - Steel Doors incl hw	1st FI - Boys SW	1	EA	6	10+ years	1 3
	Floor - Tile	1st FI - Boys SW	99	SF	6	10+ years	
	Floor Drain	1st FI - Boys SW	1	ĒA	7	10+ years	
	Lavatory	1st FI - Boys SW	1	EΑ	7	10+ years	
	Lighting - Lay-in	1st FI - Boys SW	2	EA	7	10+ years	
	Partitions	1st FI - Boys SW	1	ΕA	5	6-10 years	
	Urinals	1st FI - Boys SW	2	ΕA	7	10+ years	Installation in progress
	Walls - Tile Ceramic/ Porcelain	1st FI - Boys SW	390	SF	6	10+ years	
	Water Closet	1st FI - Boys SW	1	ĒΑ	7	10+ years	
	Accessories	1st FI - Girls NE Cafeteria	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI - Girls NE Cafeteria	180	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Girls NE Cafeteria	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI - Girls NE Cafeteria	180	SF	7	10+ years	
	Floor Drain	1st FI - Girls NE Cafeteria	1	EA	7	10+ years	
	Lavatory	1st FI - Girls NE Cafeteria	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Girls NE Cafeteria	3	EΑ	7	6-10 years	
	Partitions	1st FI - Girls NE Cafeteria	3	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Girls NE Cafeteria	696	SF	7	10+ years	
	Water Closet	1st FI - Girls NE Cafeteria	3	EA	7	10+ years	
	Accessories	1st FI - Girls SE	169	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Girls SE	169	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Girls SE	109	EA	6	10+ years	
	Floor - Tile	1st FI - Girls SE	169	SF	4	0-1 year	Separating and dirty throughout.
	Floor Drain	1st FI - Girls SE	109	EA	7	10+ years	Soparating and anty unoughout.
	1 IOO DIGIII	13t 1 Onlo OL	'	- /\	'	TOT years	

Campus Name: Rickover HS Page : 18 of 33 Assessment Date: 09/25/2020





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	1st FI - Girls SE	1	EA	7	6-10 years	
	Lavatory	1st FI - Girls SE	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI - Girls SE	2	EA	7	10+ years	
	Partitions	1st FI - Girls SE	6	EA	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Girls SE	510	SF	7	10+ years	
	Water Closet	1st FI - Girls SE	6	EA	7	10+ years	
	Accessories	1st FI - Girls SW	159	SF	5	6-10 years	
	Ceiling - Lay-in	1st FI - Girls SW	159	SF	4	1-2 years	Missing tiles
	Doors - Steel Doors incl hw	1st FI - Girls SW	1	EA	6	10+ years	· ·
	Floor - Tile Ceramic/ Porcelain	1st FI - Girls SW	159	SF	6	10+ years	
	Floor Drain	1st FI - Girls SW	1	EA	7	10+ years	
	Lavatory	1st FI - Girls SW	530	EA	7	10+ years	
	Lighting - Lay-in	1st FI - Girls SW	2	EA	7	10+ years	
	Partitions	1st FI - Girls SW	3	EA	5	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st FI - Girls SW	420	SF	6	10+ years	
	Water Closet	1st FI - Girls SW	3	EA	7	10+ years	
	Accessories	1st FI - Unisex Office Suite 28 -	28	SF	7	10+ years	
	710000001100	Principals Office	20	O.	•	101 youro	
	Ceiling - Splined	1st FI - Unisex Office Suite 28 -	28	SF	6	10+ years	
	Centrig - Opinied	Principals Office	20	Oi	U	10+ years	
	Doors - Wood Doors inclu hw	1st FI - Unisex Office Suite 28 -	1	EA	7	10+ years	
	Doors - Wood Doors Inclu IIW	Principals Office	ı	LA	,	10+ years	
	Floor - Tile	1st FI - Unisex Office Suite 28 -	28	SF	6	10 L VOORO	
	FIOOI - THE	Principals Office	20	SF	O	10+ years	
	Loveton		4	EA	7	10	
	Lavatory	1st FI - Unisex Office Suite 28 -	1	EA	7	10+ years	
	Linkting Developt/Ourfee	Principals Office	4	- ^	7	40	
	Lighting - Pendent/Surface	1st FI - Unisex Office Suite 28 -	1	EA	7	10+ years	
	W II TI O : / B	Principals Office	222	0.5	_	4.0	
	Walls - Tile Ceramic/ Porcelain	1st FI - Unisex Office Suite 28 -	220	SF	7	10+ years	
		Principals Office			_		
	Water Closet	1st FI - Unisex Office Suite 28 -	1	EA	7	10+ years	
		Principals Office			_		
	Accessories	1st FI - Unisex SW with shower	60	SF	7	10+ years	
	Benches	1st FI - Unisex SW with shower	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st FI - Unisex SW with shower	167	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Unisex SW with shower	1	EA	7	10+ years	
	Floor - Tile	1st FI - Unisex SW with shower	167	SF	7	10+ years	
	Floor Drain	1st FI - Unisex SW with shower	2	EA	7	10+ years	
	Hand Dryer	1st FI - Unisex SW with shower	1	EA	7	6-10 years	
	Lavatory	1st FI - Unisex SW with shower	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st FI - Unisex SW with shower	3	EA	7	10+ years	
	Showers	1st FI - Unisex SW with shower	1	EA	7	10+ years	Showerhead to be installed
	Student Lockers - One Tier	1st FI - Unisex SW with shower	4	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Unisex SW with shower	200	SF	7	10+ years	
						•	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st FI - Unisex SW with shower	290	SF	7	10+ years	
	Water Closet	1st FI - Unisex SW with shower	1	EA	7	10+ years	
	Accessories	1st FI - Unisex Staff Kitchen	64	SF	7	10+ years	
	Ceiling - Lay-in	1st FI - Unisex Staff Kitchen	64	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI - Unisex Staff Kitchen	64	SF	7	10+ years	
	Floor Drain	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Hand Dryer	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Lavatory	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Walls - Concrete Block	1st FI - Unisex Staff Kitchen	340	SF	7	10+ years	
	Walls - Tile	1st FI - Unisex Staff Kitchen	95	SF	7	10+ years	
	Water Closet	1st FI - Unisex Staff Kitchen	1	EA	7	10+ years	
	Accessories	1st FI - Unisex Staff in boiler rm	35	SF	7	10+ years	
	Ceiling - Exposed	1st FI - Unisex Staff in boiler rm	35	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st FI - Unisex Staff in boiler rm	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st FI - Unisex Staff in boiler rm	35	SF	7	10+ years	
	Lavatory	1st FI - Unisex Staff in boiler rm	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FI - Unisex Staff in boiler rm	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st FI - Unisex Staff in boiler rm	280	SF	7	10+ years	
	Water Closet	1st FI - Unisex Staff in boiler rm	1	EA	7	10+ years	
	Accessories	2nd Floor	350	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	350	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	350	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	7	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	720	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	350	SF	7	6-10 years	
	Ceiling - Splined	2nd Floor	350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	350	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	8	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	720	SF	7	10+ years	
	Water Closet	2nd Floor	8	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Inside Teacher's Lounge	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside Teacher's Lounge	47	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside Teacher's Lounge	47	SF	7	10+ years	
	Floor Drain	Inside Teacher's Lounge	1	EA	7	10+ years	
	Hand Dryer	Inside Teacher's Lounge	1	EA	7	10+ years	
	Lavatory	Inside Teacher's Lounge	1	EA	7	10+ years	
	Lighting - Lay-in	Inside Teacher's Lounge	1	EA	7	10+ years	
	Walls - Concrete Block	Inside Teacher's Lounge	100	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside Teacher's Lounge	60	SF	7	10+ years	
	Water Closet	Inside Teacher's Lounge	1	EA	7	10+ years	
	Accessories	Outside teacher's lounge	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Outside teacher's lounge	35	SF	7	10+ years	
	Doors - Steel Doors incl hw	Outside teacher's lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Outside teacher's lounge	35	SF	7	10+ years	
	Floor Drain	Outside teacher's lounge	1	EA	7	10+ years	
	Hand Dryer	Outside teacher's lounge	1	EA	7	6-10 years	
	Lavatory	Outside teacher's lounge	1	EA	7	10+ years	
	Lighting - Lay-in	Outside teacher's lounge	1	EA	7	10+ years	
	Walls - Concrete Block	Outside teacher's lounge	50	SF	7	10+ years	
	Walls - Plaster/Drywall	Outside teacher's lounge	30	SF	7	10+ years	
	Water Closet	Outside teacher's lounge	1	EA	7	10+ years	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	735	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	735	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	735	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	884	SF	7	10+ years	
	Walls Collecte Block	1001		_		•	
laceroo		1011 1001	33.			•	
Classroo	m #117 (Regular Classroom)		1		7	10+ vears	
Classroo	m #117 (Regular Classroom) AC Units	1st Floor 1st Floor	1 740	EA SF	7 7	10+ years 10+ vears	
Classroo	m #117 (Regular Classroom)	1st Floor	1	EA	7 7 7	10+ years	
Classroc	m #117 (Regular Classroom) AC Units Ceiling - Splined	1st Floor 1st Floor	1	EA SF	7 7 7 7	•	
Classroc	m #117 (Regular Classroom) AC Units Ceiling - Splined Doors - Wood Doors inclu hw	1st Floor 1st Floor 1st Floor	1 740 1	EA SF EA	7 7 7 7 7	10+ years 10+ years	
Classroc	m #117 (Regular Classroom) AC Units Ceiling - Splined Doors - Wood Doors inclu hw Floor - Tile	1st Floor 1st Floor 1st Floor 1st Floor	1 740 1 740	EA SF EA SF	7 7 7 7 7	10+ years 10+ years 10+ years	
Classroc	m #117 (Regular Classroom) AC Units Ceiling - Splined Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 740 1 740 15	EA SF EA SF EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	11440 (D I. Ol)						
lassroc	om #119 (Regular Classroom)	=					
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	745	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,043	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6	SF	7	10+ years	Soffit for piping enclosure.
lassroc	om #125 (Band Room)						
	Casework	1st Floor	140	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2,109	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2,103	EA	6	10+ years	
	Floor - Terrazzo	1st Floor	2,109	SF	7	10+ years	
	Instrument Storage Casework	1st Floor		LF	6	•	
			24			10+ years	
	Lighting - Lay-in	1st Floor	32	EA	7	10+ years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Risers	1st Floor	160	LF	7	10+ years	
	Sound Panels	1st Floor	12	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,100	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,240	SF	6	10+ years	
lassroc	om #206 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,046	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,046	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	22	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	940	SF	7	10+ years	
	Walls - Masonry	2nd Floor	30	SF	7	10+ years	
	Walls - Masority Walls - Plaster/Drywall	2nd Floor 2nd Floor	120	SF	7	10+ years 10+ years	
		2nd Floor 2nd Floor	120	SF EA	7	•	
	Wireless System	ZIIU FI001	1	⊏A	1	6-10 years	
lassroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	761	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	5	SF	5	0-1 year	Missing and broken tiles.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	-



Catego	ategory : Classroom		В	Building : Main					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	2nd Floor	766	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	3	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years			
	Walls - Masonry	2nd Floor	15	SF	7	10+ years			
Classroo	m #208 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	716	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water stain.		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	2nd Floor	724	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	3	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	812	SF	7	10+ years			
	Walls - Masonry	2nd Floor 2nd Floor	15	SF	7	10+ years			
	Walls - Masority Walls - Plaster/Drywall	2nd Floor	60	SF	7	10+ years			
	walls - Flaster/Drywall	2110 F1001	00	SF	,	10+ years			
Classroo	m #209 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	15	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	747	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	747	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years			
	Walls - Masonry	2nd Floor	15	SF	7	10+ years			
_Classroo	m #210 (Regular Classroom)								
	Casework	2nd Floor	18	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	724	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	724	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years			
	Marker Board	2nd Floor	20	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	3	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years			
	Walls - Masonry	2nd Floor 2nd Floor	15	SF	7	10+ years			
	vvalis - iviasoriry	2110 1 1001	15	J۲	ı	10+ years			
_Classroo	m #211 (Regular Classroom)								

Campus Name: Rickover HS Page : 23 of 33 Assessment Date: 09/25/2020



Catego	ry : Classroom		В	Building : Main			<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EΑ	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	10+ years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
				SF SF		-	
	Walls - Masonry	2nd Floor	15	5F	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	6-10 years	
	Ceiling - Splined	2nd Floor	748	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	•	
			_			6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
	Walls - Masonry	2nd Floor	15	SF	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
				SF SF		•	
	Walls - Masonry	2nd Floor	15	SF	7	10+ years	
Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	748	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	



Catego	ory : Classroom		В	uilding	: Main		OU W Beneda AVENOE, Omcago, 12 00004
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	2nd Floor	15	SF	7	10+ years	
_Classroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	722	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
		2nd Floor 2nd Floor	15	SF	7	10+ years	
	Walls - Masonry	2110 F1001	15	SF	,	10+ years	
_Classroo	om #217 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	724	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	724	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
	Walls - Masonry	2nd Floor	15	SF	7	10+ years	
Classro	om #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor	724	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	724	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	753	SF	7	10+ years	
01	(1000 (D I. Ol)						
_Classroo	om #220 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	791	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	791	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	



Catego	ory : Classroom		Building : Main				00 W Berteau AVENOE, Onleage, ie 00004
o allo g c	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	738	SF	7	10+ years	
	Walls - Masonry	2nd Floor	100	SF	7	10+ years	
Classro	om #LL01 (Science Lab Level 1)						
Classion	AC Units	1st Floor	4	EA	7	40	
			1	LF	7	10+ years	
	Casework	1st Floor	51		7	10+ years	
	Ceiling - Lay-in	1st Floor	847	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	847	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Science Lab Elements	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,325	SF	7	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	
_Classro	om #LL03 (Science Lab Level 1)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	986	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	986	SF	7	10+ years	
	Gas Line	1st Floor	4	ĒA	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	140	SF	7	10+ years	
	Science Lab Fume Hood	1st Floor	1	ĒΑ	7	10+ years	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,104	SF	7	10+ years	
	Work Sink	1st Floor	5	EA	7	10+ years	
Classra	om #LL05 (Science)						
	,	1st Floor		EA	7	10	
	AC Units		1		7	10+ years	
	Ceiling - Splined	1st Floor	826	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	826	SF	7	10+ years	
	Gas Line	1st Floor	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	140	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,250	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	



Catego	ategory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	III I 00 (D						
Classroc	m #LL06 (Regular Classroom)	4-4-51			7	40	
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Splined	1st Floor	1,164	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	la stallation in any and
	Floor - Concrete	1st Floor	1,164	SF	7	10+ years	Installation in progress
	Lighting - Pendent/Surface	1st Floor	20	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	344	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,120	SF	6	10+ years	
Classroo	m #LL07 (Science)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,065	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Eye Wash Station	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,065	SF	7	10+ years	
	Gas Line	1st Floor	1	ĒΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	35	ΕA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Science Lab Elements	1st Floor	120	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,045	SF	7	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
Classroo	m #LL09 (Art Room)						
Classiuc	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,412	SF	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1,412	SF EA	7	10+ years 10+ years	
	Floor - Tile	1st Floor	1,412	SF	7	•	
	Kiln	1st Floor	1,412 55	EA	7	10+ years 10+ years	
	Lighting - Lay-in	1st Floor	30	EA	7	10+ years 10+ years	
	Marker Board	1st Floor	36	LF	7	10+ years	
	Storage/ Closet	1st Floor	62	SF	7	•	
	Walls - Concrete Block	1st Floor	1,047	SF	7	10+ years	
						10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #LL11 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	759	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	759	SF	7	10+ years	



Catego	ry : Classroom		Building : Main				00 W Berteau AVENUE, Chicago, IL 60634
Oalcgoi	ry . Olassi oolii			unung	. IVICIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	Comments
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	965	SF	7	10+ years	
	Walls - Collete block	131 1001	903	OI.	,	10+ years	
Clasaraa	om #LL12 (Regular Classroom)						
JIdSSIUU	AC Units	1st Floor	1	EA	7	6 10 voore	
			1		7	6-10 years	
	Ceiling - Splined	1st Floor	737	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	737	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	970	SF	7	10+ years	
Classroo	om #LL13 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	779	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	779	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
		1st Floor	22	LF	7		
	Marker Board			SF		6-10 years	
	Walls - Concrete Block	1st Floor	965	SF	7	10+ years	
Classroo	om #LL15 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	779	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	779	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	965	SF	7	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
Catego	ry : Interior		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor_					TWIN	. topicoomont	
	Ceiling - Lay-in	1st Floor	2,206	SF	7	10+ years	
	Ceiling - Splined	1st Floor	870	SF	6	10+ years	
	Ceiling - Splined	1st Floor	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	-
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,096	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	75	ĒΑ	7	6-10 years	



Catego	ry : Interior		В	uilding	: Main	<u> </u>	00 W Berteau AVENOE, Officago, IE 00004
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Terrazzo	1st Floor	24	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	260	EA	5	6-10 years	
	Walls - Concrete Block	1st Floor	5,000	SF	7	10+ years	
	Walls - Masonry	1st Floor	4,100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,200	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	4,270	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,270	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	55	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	238	EA	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	13	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	5,980	SF	7	10+ years	
	Walls - Masonry	2nd Floor	2,335	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,025	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,802	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	, 1	EA	6	10+ years	
	Doors - Wood Doors include hw	Basement	1	EA	6	10+ years	
	Drinking Fountains - Double Fountain	Basement	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,802	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	35	EA	7	6-10 years	
	Student Lockers - One Tier	Basement	20	EA	6	10+ years	
	Walls - Concrete Block	Basement	1,800	SF	7	10+ years	
	Walls - Masonry	Basement	1,000	SF	7	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	50	EA	7	6-10 years	
	cooming cannot be	g				,	
Stairs							
	Ceiling - Lay-in	Center- near Main Office	180	SF	7	10+ years	
	Floor - Terrazzo	Center- near Main Office	180	SF	7	10+ years	
	Handrails	Center- near Main Office	28	LF	7	10+ years	
	Lighting - Lay-in	Center- near Main Office	3	EA	7	6-10 years	
	Stairs - Terrazzo	Center- near Main Office	156	LF	7	10+ years	
	Walls - Masonry	Center- near Main Office	480	SF	7	10+ years	
	Ceiling - Lay-in	East - near Art rm LL09	122	SF	7	10+ years	
	Floor - Tile	East - near Art rm LL09	122	SF	7	10+ years	
	Handrails	East - near Art rm LL09	65	LF	7	10+ years	
	Lighting - Lay-in	East - near Art rm LL09	2	EA	7	6-10 years	
	Stairs - Terrazzo	East - near Art rm LL09	95	LF	6	10+ years	
	Walls - Masonry	East - near Art rm LL09	810	SF	7	10+ years	
	Ceiling - Lay-in	Gym Balcony N & S	210	SF	6	10+ years	
	Floor - Concrete	Gym Balcony N & S	210	SF	7	10+ years	
	Handrails	Gym Balcony N & S	24	LF	7	10+ years	



Catego	ry : Interior		В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Gym Balcony N & S	2	EΑ	6	6-10 years	
	Stairs - Concrete	Gym Balcony N & S	54	LF	6	10+ years	
	Walls - Concrete Block	Gym Balcony N & S	960	SF	5	1-2 years	Cracking.
	Ceiling - Lay-in	North East - near kitchen	120	SF	7	10+ years	-
	Floor - Terrazzo	North East - near kitchen	120	SF	7	10+ years	
	Handrails	North East - near kitchen	36	LF	7	10+ years	
	Lighting - Lay-in	North East - near kitchen	4	EA	7	6-10 years	
	Stairs - Terrazzo	North East - near kitchen	18	LF	7	10+ years	
	Walls - Masonry	North East - near kitchen	486	SF	7	10+ years	
	Ceiling - Lay-in	Northwest - nxt to Blackbox	184	SF	6	10+ years	
	Ceiling - Lay-in	Northwest - nxt to Blackbox	8	SF	4	0-1 year	Water damage
	Floor - Tile	Northwest - nxt to Blackbox	192	SF	7	10+ years	
	Handrails	Northwest - nxt to Blackbox	52	LF	7	10+ years	
	Lighting - Lay-in	Northwest - nxt to Blackbox	4	EA	6	6-10 years	
	Stairs - Terrazzo	Northwest - nxt to Blackbox	130	LF	4	0-1 year	Damaged throughout.
	Walls - Masonry	Northwest - nxt to Blackbox	1,008	SF	7	10+ years	
	Ceiling - Lay-in	West - at Gym	205	SF	6	10+ years	
	Floor - Terrazzo	West - at Gym	205	SF	6	10+ years	
	Handrails	West - at Gym	29	LF	7	10+ years	
	Lighting - Lay-in	West - at Gym	2	EA	6	6-10 years	
	Stairs - Terrazzo	West - at Gym	105	LF	6	10+ years	
	Walls - Masonry	West - at Gym	1,050	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	4	0-1 year	Missing.

Campus Name: Rickover HS Page : 30 of 33 Assessment Date: 09/25/2020



Category : Site **Building: Site**

	y . Site		_	unung			
			_			Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Synthetic	West	30,553	SF	7	10+ years	
	Metal Bleachers	West	360	LF	7	10+ years	
	Surface - Natural	West	98,035	SF	6	10+ years	
	Surface - Synthetic	West	3,500	SF	6	10+ years	
ivil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EA	7	10+ years	
		Entire Site	6	EA	7		
	Civil/ Drainage - Site Manhole	Entire Site	б	EA	,	10+ years	
encing							
	Fencing - Chain Link	Entire Site	1,612	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	151	LF	7	10+ years	
andscar	oe .						
	Benches	Entire Site	10	EA	7	10+ years	
	Landscape - Grass	Entire Site	61,985	SF	7	10+ years	
	Landscape - Grass	Entire Site	7,656	SF	5	1-2 years	Damaged, worn grass, poor soil
	Landscape - Hardscape- Asphalt	Entire Site	2,332	SF	4	1-2 years	Cracking throughout.
	Landscape - Hardscape- Concrete	Entire Site	4,021	SF	4	1-2 years	Extensive cracking throughout
	Parkway trees	Entire Site	61	EA	7	10+ years	Extensive cracking unoughout
	Planting Beds/ Area	Entire Site		SF	6	10+ years	
			7,324				
	Trash Receptacles	Entire Site	5	EA	7	6-10 years	
arking L							
	Concrete Curbs	North Courtyard	1,338	LF	6	10+ years	
	Surface - Asphalt	North Courtyard	3,934	SF	7	10+ years	
	Surface - Asphalt	North Courtyard	13,852	SF	6	10+ years	
	Surface - Asphalt	North Courtyard	9,876	SF	4	1-2 years	Cracking and potholes throughout
ervice G	Parage						
	Service Garage - Free-Standing	North Courtyard	1	SF	6	10+ years	
Sidewalk	e						
iiu c waik	Sidewalks - Internal Walks	Entire Site	333	LF	7	10+ years	
				LF LF			
	Sidewalks - Internal Walks	Entire Site	218	LF LF	6	10+ years	Cidovello post to building decir
	Sidewalks - Internal Walks	Entire Site	611	LF	4	1-2 years	Sidewalks next to building drain toward building
				~-	_		_
	Sidewalks - Perimeter Sidewalks	Entire Site	9,050	SF	7	10+ years	

Campus Name: Rickover HS Page : 31 of 33 Assessment Date: 09/25/2020



Hyman G Rickover Naval Academy High School

5700 W Berteau AVENUE, Chicago, IL 60634

Catego	Category : Site			uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Signage							
	Flag Pole - Flag Pole Monument - Sign	South South	1 1	EA EA	7 7	10+ years 10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Rickover HS Page: 32 of 33 Assessment Date: 09/25/2020

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classiconi Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	interface Osage	Noom Education	Humber	Number	(01)	Alca	Alca	Стор	Doard
Art Room	Art Room	1st Floor	LL09	110	1,412	343	82		
Band Room	Band Room	1st Floor	125	125	2,109	310	130		
Computer Lab	Computer Lab	2nd Floor	206	206	1,046	396	99		
Regular Classroom	Regular Classroom	1st Floor	115	23	735	186	69		
Regular Classroom	Regular Classroom	1st Floor	117	25	740	186	69		
Regular Classroom	Regular Classroom	1st Floor	119	27	745	189	69		
Regular Classroom	Regular Classroom	1st Floor	LL06	Classroom	1,164	266	83		
Regular Classroom	Regular Classroom	1st Floor	LL11	112	759	175	62		
Regular Classroom	Regular Classroom	1st Floor	LL12	113	737	175	62		
Regular Classroom	Regular Classroom	1st Floor	LL13	114	779	265	82		
Regular Classroom	Regular Classroom	1st Floor	LL15	116	779	265	82		
Regular Classroom	Regular Classroom	2nd Floor	207	208	766	252	21		N
Regular Classroom	Regular Classroom	2nd Floor	208	207	724	252	21		
Regular Classroom	Regular Classroom	2nd Floor	209	210	747	252	21		
Regular Classroom	Regular Classroom	2nd Floor	210	209	724	252	21		
Regular Classroom	Regular Classroom	2nd Floor	211	212	750	252	21		
Regular Classroom	Regular Classroom	2nd Floor	213	214	748	252	21		
Regular Classroom	Regular Classroom	2nd Floor	214	213	725	252	21		
Regular Classroom	Regular Classroom	2nd Floor	215	216	748	252	21		
Regular Classroom	Regular Classroom	2nd Floor	216	215	722	252	21		
Regular Classroom	Regular Classroom	2nd Floor	217	217	724	252	21		
Regular Classroom	Regular Classroom	2nd Floor	218	218	724	252	21		
Regular Classroom	Regular Classroom	2nd Floor	220	219	791	252	21		
Science	Science	1st Floor	LL05	104 - Science	826	175	62		
Science	Science	1st Floor	LL07	106 - Physics	1,065	245	82		
Science Lab Level 1	Science Lab Level 1	1st Floor	LL01	100- Bio Lab	847	204	69		
Science Lab Level 1	Science Lab Level 1	1st Floor	LL03	102 - Chem Lab	986	417	138		