

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report) . Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|---------------------|------------------|------------------|-----------------------|--------------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1972 | 3 | 45,270 | \$1,419,073 |
| Branch | 1989 | 2 | 20,400 | \$1,009,889 |
| SITE | | | | \$428,356 |
| Campus Total | | | 65,670 | \$2,857,318 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|-----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 7 | \$0 |
| | Exterior Doors - Exterior FRP Door | 2 | EA | 7 | \$0 |
| | Exterior Doors - Exterior Steel Door | 15 | EA | 6 | \$7,208 |
| | Exterior Doors - Transom Lite | 2 | EA | 6 | \$627 |
| | Ramps - Concrete | 10 | LF | 6 | \$1,502 |
| Foundation | | | | | |
| | Foundation - Concrete | 730 | LF | 7 | \$0 |
| | Superstructure - Metal Deck/ Concrete Topping | 45,270 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 11 | EA | 5 | \$23,980 |
| | Exterior Lighting - Wall Mounted | 15 | EA | 5 | \$6,411 |
| Roof System | | | | | |
| | Coping - Metal | 906 | LF | 6 | \$29,099 |
| | Downspouts - Interior Downspouts | 325 | LF | 6 | \$10,801 |
| | Roof - Asphalt Gravel Ballast | 3,374 | SF | 4 | \$98,199 |
| | Roof - Asphalt Gravel Ballast | 5,872 | SF | 5 | \$138,634 |
| | Roof - Modified Bitumen | 12,008 | SF | 4 | \$329,177 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|-----------|
| Roof System | | | | | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 21,254 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Precast Panel Wall | 976 | SF | 5 | \$10,928 |
| | Exterior Walls - Precast Panel Wall | 24,918 | SF | 6 | \$167,474 |
| Windows | | | | | |
| | Guard - Guards perforated | 90 | SF | 5 | \$1,380 |
| | Guard - Guards perforated | 882 | SF | 6 | \$11,263 |
| | Lintels - Steel | 714 | LF | 7 | \$0 |
| | Windows - Louver | 450 | SF | 6 | \$3,359 |
| | Windows - Sash Aluminum Double-pane | 3,312 | SF | 6 | \$24,723 |

Building Exterior Subtotal: \$864,763

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------|--|----------|------|------|----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 7 | \$0 |
| | Emergency A/C Power - Corridors and Stairs | 7,086 | SF | 6 | \$2,128 |
| | Emergency A/C Power - Gym | 3,640 | SF | 6 | \$1,353 |
| | Emergency A/C Power - Lunchrooms | 2,350 | SF | 6 | \$874 |
| | Emergency A/C Power - Students Toilets | 1,528 | SF | 6 | \$568 |
| | Emergency Battery Packs - Corridors and Stairs | 7 | EA | 6 | \$1,418 |
| | Exit Signs - Corridors and Stairs | 6 | EA | 6 | \$898 |
| | Exit Signs - Gym | 2 | EA | 6 | \$315 |
| | Exit Signs - Lunchroom | 10 | EA | 6 | \$1,497 |
| | Security System - CCTV | 45,270 | SF | 6 | \$13,595 |
| | Security System - Intrusion Detection | 45,270 | SF | 6 | \$11,652 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 2001 to 3000 A 120/240/3PH | 1 | EA | 6 | \$10,867 |
| | PA System | 45,270 | SF | 6 | \$14,889 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 |
| | Lighting and Power Panels - Above 100 A | 2 | EA | 4 | \$13,156 |

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------|---|----------|------|------|---------|
| Power Distribution | | | | | |
| | Lighting and Power Panels - Above 100 A | 11 | EA | 6 | \$5,467 |

Electrical System Subtotal:

\$79,276

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 4 | \$49,477 |
| | Fire Alarm_System | 45,270 | SF | 6 | \$22,010 |

Safty System Subtotal:

\$71,487

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|--|----------|------|------|----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 1 | EA | 7 | \$0 |
| Air Handling Systems | | | | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Electric Coils - 46 - 60 tons | 1 | EA | 5 | \$32,316 |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric Coil - 21 - 30 tons | 1 | EA | 5 | \$20,600 |
| Heating Devices | | | | | |
| | Wall Heater - Electric | 5 | EA | 4 | \$5,413 |
| | Wall Heater - Electric | 4 | EA | 5 | \$2,146 |
| | Wall Heater - Electric | 20 | EA | 6 | \$2,778 |
| Temperature Control | | | | | |
| | Electric Controls | 45,270 | SF | 6 | \$0 |
| | Electric Thermostat | 3 | EA | 6 | \$0 |
| | Electric Thermostat | 7 | EA | 7 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 5 | EA | 5 | \$49,404 |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 21 | EA | 6 | \$26,202 |

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|--|----------|------|------|------------------|
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 5 | EA | 7 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 4 | EA | 6 | \$2,370 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 4 | EA | 6 | \$2,370 |
| | Type II Exhaust Hood- Warming Kitchen | 1 | EA | 3 | \$9,916 |
| Mechanical System Subtotal: | | | | | \$153,514 |

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------------|--|----------|------|------|------------------|
| Hot Water | | | | | |
| | Electric Heater - Greater than 50 KW | 1 | EA | 7 | \$0 |
| | Electric Heater - Less than 20 KW | 1 | EA | 6 | \$682 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 45,270 | SF | 6 | \$9,063 |
| | Domestic Piping-Cold Water Horizontal Lines | 45,270 | SF | 6 | \$11,005 |
| | Domestic Piping-Cold Water Risers | 45,270 | SF | 6 | \$8,416 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 45,270 | SF | 6 | \$7,121 |
| | Domestic Piping-Hot Water Horizontal Lines | 45,270 | SF | 6 | \$8,416 |
| | Domestic Piping-Hot Water Return Lines | 45,270 | SF | 6 | \$6,474 |
| | Domestic Piping-Hot Water Return Risers | 45,270 | SF | 6 | \$6,474 |
| | Sanitary Piping | 45,270 | SF | 6 | \$41,431 |
| | Storm Piping | 45,270 | SF | 6 | \$39,489 |
| | Vent Piping | 45,270 | SF | 6 | \$30,426 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | 1 | EA | 4 | \$25,441 |
| Plumbing System Subtotal: | | | | | \$194,437 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------|-------------|----------|------|------|------|
|-------|-------------|----------|------|------|------|

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------------|-----------------------------|----------|------|------|----------|
| Art Room (1 room) | | | | | |
| | Casework | 12 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 713 | SF | 7 | \$0 |
| | Chalk Board | 16 | LF | 4 | \$1,469 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 713 | SF | 7 | \$0 |
| | Lighting - Lay-in | 10 | EA | 7 | \$0 |
| | Marker Board | 16 | LF | 7 | \$0 |
| | Walls - Concrete Block | 693 | SF | 7 | \$0 |
| | Walls - Metal Panel | 279 | SF | 7 | \$0 |
| Computer Lab (1 room) | | | | | |
| | Casework | 12 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 713 | SF | 7 | \$0 |
| | Chalk Board | 8 | LF | 4 | \$734 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 713 | SF | 7 | \$0 |
| | Lighting - Lay-in | 12 | EA | 7 | \$0 |
| | Walls - Concrete Block | 765 | SF | 7 | \$0 |
| Kindergarten (3 rooms) | | | | | |
| | Casework | 90 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 4,275 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 9 | EA | 7 | \$0 |
| | Floor - Tile | 4,275 | SF | 7 | \$0 |
| | Lighting - Lay-in | 56 | EA | 7 | \$0 |
| | Marker Board | 20 | LF | 7 | \$0 |
| | Storage/ Closet | 169 | SF | 7 | \$0 |
| | Walls - Concrete Block | 3,969 | SF | 7 | \$0 |
| | Walls - Metal Panel | 468 | SF | 7 | \$0 |
| | Work Sink | 3 | EA | 7 | \$0 |
| Regular Classroom (14 rooms) | | | | | |
| | Casework | 192 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 11,159 | SF | 7 | \$0 |
| | Chalk Board | 192 | LF | 4 | \$17,627 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 22 | EA | 7 | \$0 |
| | Floor - Tile | 11,159 | SF | 7 | \$0 |
| | Lighting - Lay-in | 166 | EA | 7 | \$0 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------------|-----------------------------|----------|------|------|-----------------|
| Regular Classroom (14 rooms) | | | | | |
| | Marker Board | 214 | LF | 7 | \$0 |
| | Storage/ Closet | 668 | SF | 7 | \$0 |
| | Walls - Concrete Block | 9,214 | SF | 7 | \$0 |
| | Walls - Metal Panel | 4,185 | SF | 7 | \$0 |
| Science Classroom (1 room) | | | | | |
| | Casework | 24 | LF | 6 | \$606 |
| | Ceiling - Lay-in | 1,580 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 3 | EA | 7 | \$0 |
| | Floor - Tile | 1,580 | SF | 7 | \$0 |
| | Lighting - Lay-in | 20 | EA | 7 | \$0 |
| | Marker Board | 32 | LF | 7 | \$0 |
| | Storage/ Closet | 121 | SF | 7 | \$0 |
| | Student Lockers - One Tier | 14 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,154 | SF | 7 | \$0 |
| | Walls - Metal Panel | 558 | SF | 7 | \$0 |
| Special Education (1 room) | | | | | |
| | Ceiling - Lay-in | 240 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 240 | SF | 7 | \$0 |
| | Lighting - Lay-in | 4 | EA | 7 | \$0 |
| | Walls - Concrete Block | 512 | SF | 7 | \$0 |
| Classrooms Subtotal: | | | | | \$20,436 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | Ceiling - Lay-in | 120 | SF | 5 | \$714 |
| | Ceiling - Lay-in | 520 | SF | 6 | \$1,562 |
| | Ceiling - Lay-in | 2,661 | SF | 7 | \$0 |
| | Doors - Side-lite | 27 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 2 | EA | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 21 | EA | 7 | \$0 |
| | Floor - Carpet | 450 | SF | 6 | \$959 |
| | Floor - Tile | 2,666 | SF | 7 | \$0 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|----------|
| Administrative Suites/Offices | | | | | |
| | Floor - Tile Quarry | 64 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 121 | SF | 7 | \$0 |
| | Lighting - Lay-in | 44 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Lighting - Pendent/Surface | 10 | EA | 7 | \$0 |
| | Power Distribution | 52 | EA | 7 | \$0 |
| | Storage/ Closet | 134 | SF | 7 | \$0 |
| | Walls - Concrete Block | 7,068 | SF | 7 | \$0 |
| | Work Slnk | 2 | EA | 7 | \$0 |
| Gymnasia | | | | | |
| | Ceiling - Exposed | 4,940 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Wood Doors inclu hw | 7 | EA | 7 | \$0 |
| | Floor - Tile | 3,640 | SF | 7 | \$0 |
| | Lighting - Lay-in | 10 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 48 | EA | 7 | \$0 |
| | Stage | 1,000 | SF | 7 | \$0 |
| | Stage Curtain | 2 | EA | 7 | \$0 |
| | Stage Lighting System | 1 | EA | 6 | \$12,369 |
| | Stage-Stairs | 98 | | 7 | \$0 |
| | Storage/ Closet | 420 | SF | 7 | \$0 |
| | Walls - Concrete Block | 10,258 | SF | 7 | \$0 |
| Kitchen | | | | | |
| | Ceiling - Lay-in | 624 | SF | 6 | \$1,874 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile Quarry | 624 | SF | 7 | \$0 |
| | Lighting - Lay-in | 12 | EA | 7 | \$0 |
| | Storage/ Closet | 96 | SF | 7 | \$0 |
| | Walls - Concrete Block | 1,188 | SF | 7 | \$0 |
| Library | | | | | |
| | Casework | 104 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 1,116 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Tile | 1,116 | SF | 7 | \$0 |
| | Lighting - Lay-in | 15 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,202 | SF | 7 | \$0 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|---------------------------------|----------|------|------|---------|
| Library | | | | | |
| Lunch & Multipurpose Room | | | | | |
| | Ceiling - Lay-in | 2,350 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile | 2,350 | SF | 7 | \$0 |
| | Lighting - Lay-in | 32 | EA | 7 | \$0 |
| | Serving Line | 16 | LF | 7 | \$0 |
| | Walls - Concrete Block | 2,328 | SF | 7 | \$0 |
| MDF_IDF | | | | | |
| | AC Unit | 1 | EA | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Finishes | 242 | SF | 7 | \$0 |
| Mechanical/ Service Rooms | | | | | |
| | Storage Room | 2,002 | SF | 7 | \$0 |
| Restroom | | | | | |
| | Accessories | 1,916 | SF | 7 | \$0 |
| | Ceiling - Lay-in | 338 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 1,578 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 28 | EA | 7 | \$0 |
| | Floor - Concrete | 50 | SF | 7 | \$0 |
| | Floor - Tile | 89 | SF | 7 | \$0 |
| | Floor - Tile Ceramic/ Porcelain | 1,777 | SF | 7 | \$0 |
| | Floor Drain | 6 | EA | 7 | \$0 |
| | Hand Dryer | 12 | EA | 7 | \$0 |
| | Lavatory | 21 | EA | 7 | \$0 |
| | Lighting - Lay-in | 26 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 4 | EA | 4 | \$2,163 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Partitions | 18 | EA | 7 | \$0 |
| | Urinals | 7 | EA | 7 | \$0 |
| | Walls - Concrete Block | 6,040 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 160 | SF | 6 | \$442 |
| | Walls - Plaster/Drywall | 160 | SF | 7 | \$0 |
| | Water Closet | 27 | EA | 7 | \$0 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--|-------------|----------|------|------|-----------------|
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$20,807 |

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 4,392 | SF | 6 | \$13,189 |
| | Ceiling - Lay-in | 2,304 | SF | 7 | \$0 |
| | Doors - Wood Doors include hw | 8 | EA | 7 | \$0 |
| | Drinking Fountains - Double Fountain | 2 | EA | 7 | \$0 |
| | Drinking Fountains - Single Fountain | 3 | EA | 7 | \$0 |
| | Floor - Tile Quarry | 432 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 6,264 | SF | 7 | \$0 |
| | Lighting - Lay-in | 50 | EA | 7 | \$0 |
| | Walls - Concrete Block | 11,224 | SF | 7 | \$0 |
| Safety | | | | | |
| | Camera Viewing Station | 1 | EA | 7 | \$0 |
| | Security Cameras | 6 | EA | 6 | \$1,164 |
| Stairs | | | | | |
| | Ceiling - Lay-in | 1,128 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 480 | SF | 7 | \$0 |
| | Floor - Terrazzo | 144 | SF | 7 | \$0 |
| | Floor - Tile | 246 | SF | 7 | \$0 |
| | Handrails | 192 | LF | 7 | \$0 |
| | Lighting - Lay-in | 8 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 4 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 480 | LF | 7 | \$0 |
| | Walls - Concrete Block | 3,584 | SF | 7 | \$0 |

| | | | | | |
|------------------------------------|--|--|--|--|-----------------|
| Building Interior Subtotal: | | | | | \$14,353 |
|------------------------------------|--|--|--|--|-----------------|

| | | | | | |
|----------------------------|--|--|--|--|--------------------|
| Total Building Cost | | | | | \$1,419,073 |
|----------------------------|--|--|--|--|--------------------|

Building: Branch

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|---|----------|------|------|------------------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 2 | EA | 7 | \$0 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 6 | \$481 |
| | Exterior Doors - Side lite | 10 | EA | 7 | \$0 |
| | Exterior Doors - Store Front | 9 | EA | 7 | \$0 |
| | Exterior Doors - Transom Lite | 7 | EA | 7 | \$0 |
| | Exterior Stairs - Concrete | 80 | LF | 5 | \$8,766 |
| | Exterior Stairs - Concrete | 180 | LF | 6 | \$14,718 |
| | Ramp Handrail - Steel_Ramp Handrail | 60 | LF | 6 | \$520 |
| | Ramps - Concrete | 30 | LF | 6 | \$4,507 |
| | Stair Handrail - Steel_Stair Handrail | 95 | LF | 6 | \$823 |
| Foundation | | | | | |
| | Foundation - Concrete | 460 | LF | 7 | \$0 |
| | Superstructure - Metal Deck/ Concrete Topping | 20,400 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 6 | EA | 6 | \$1,732 |
| Roof System | | | | | |
| | Coping - Metal | 460 | LF | 6 | \$14,774 |
| | Downspouts - Interior Downspouts | 100 | LF | 6 | \$3,323 |
| | Parapet - Parapet < 16" Height | 460 | LF | 6 | \$9,801 |
| | Roof - EPDM/ Synthetic Rubber | 3,060 | SF | 4 | \$78,983 |
| | Roof - EPDM/ Synthetic Rubber | 7,140 | SF | 5 | \$138,144 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 10,200 | SF | 7 | \$0 |
| Walls | | | | | |
| | Canopy - Metal | 320 | SF | 6 | \$6,873 |
| | Exterior Walls - Prefabricated Metal Panel Wall | 92 | SF | 5 | \$793 |
| | Exterior Walls - Prefabricated Metal Panel Wall | 8,188 | SF | 6 | \$46,484 |
| Windows | | | | | |
| | Lintels - Steel | 580 | LF | 7 | \$0 |
| | Windows - Casement Aluminum | 720 | SF | 5 | \$25,853 |
| | Windows - Decorative | 2,500 | SF | 5 | \$306,378 |
| Building Exterior Subtotal: | | | | | \$662,955 |

Building: Branch

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------|-------------|----------|------|------|------|
|-------|-------------|----------|------|------|------|

Building: Branch

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|--|----------|------|------|------------------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 20,400 | SF | 6 | \$6,126 |
| | Emergency A/C Power - Multipurpose Room | 1,711 | SF | 6 | \$636 |
| | Emergency A/C Power - Students Toilets | 684 | SF | 6 | \$254 |
| | Exit Signs - Corridors and Stairs | 6 | EA | 6 | \$898 |
| | Exit Signs - Multipurpose Room | 2 | EA | 6 | \$299 |
| | Security System - CCTV | 20,400 | SF | 4 | \$72,930 |
| | Security System - Intrusion Detection | 20,400 | SF | 6 | \$5,251 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 2000 A 120/208/3PH | 1 | EA | 6 | \$8,232 |
| | PA System | 20,400 | SF | 6 | \$6,710 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 6 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 1 | EA | 7 | \$0 |
| Electrical System Subtotal: | | | | | \$101,745 |

Building: Branch

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------|-------------------|----------|------|------|-----------------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm_System | 20,600 | SF | 6 | \$10,016 |
| Safty System Subtotal: | | | | | \$16,421 |

Building: Branch

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------|--|----------|------|------|----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 3 | EA | 3 | \$33,400 |
| Heating Devices | | | | | |
| | Unit Heater - Electric | 3 | EA | 7 | \$0 |
| | Wall Heater - Electric | 6 | EA | 6 | \$833 |

Building: Branch

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|--|----------|------|------|------------------|
| Heating Devices | | | | | |
| Temperature Control | | | | | |
| | Electric Controls | 20,400 | SF | 7 | \$0 |
| | Electric Thermostat | 24 | EA | 7 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 1 | EA | 4 | \$22,939 |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 5 | EA | 5 | \$49,404 |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | 16 | EA | 6 | \$19,963 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - Greater than 8000 CFM | 4 | EA | 6 | \$2,370 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | \$592 |
| Mechanical System Subtotal: | | | | | \$130,094 |

Building: Branch

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|----------|
| Hot Water | | | | | |
| | Electric Heater - 20 - 50 KW | 1 | EA | 4 | \$11,353 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 20,400 | SF | 6 | \$4,084 |
| | Domestic Piping-Cold Water Horizontal Lines | 20,400 | SF | 6 | \$4,959 |
| | Domestic Piping-Cold Water Risers | 20,400 | SF | 6 | \$3,792 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 20,400 | SF | 6 | \$3,209 |
| | Domestic Piping-Hot Water Horizontal Lines | 20,400 | SF | 6 | \$3,792 |
| | Domestic Piping-Hot Water Return Lines | 20,400 | SF | 6 | \$2,917 |
| | Domestic Piping-Hot Water Return Risers | 20,400 | SF | 6 | \$2,917 |
| | Sanitary Piping | 20,400 | SF | 6 | \$18,670 |
| | Storm Piping | 20,400 | SF | 6 | \$17,795 |
| | Vent Piping | 20,400 | SF | 6 | \$13,711 |

Building: Branch

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------------|-------------|----------|------|------|-----------------|
| Plumbing System Subtotal: | | | | | \$87,201 |

Building: Branch

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|-----------------------------|----------|------|------|---------|
| | Casework | 20 | LF | 7 | \$0 |
| | Ceiling - Splined | 1,131 | SF | 7 | \$0 |
| | Chalk Board | 12 | LF | 4 | \$1,102 |
| | Doors - Side-lite | 8 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Carpet | 1,131 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 970 | SF | 7 | \$0 |
| Pre School (2 rooms) | | | | | |
| | Casework | 100 | LF | 7 | \$0 |
| | Ceiling - Splined | 2,262 | SF | 7 | \$0 |
| | Doors - Side-lite | 16 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile | 2,262 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 23 | EA | 7 | \$0 |
| | Marker Board | 32 | LF | 7 | \$0 |
| | Storage/ Closet | 8 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,940 | SF | 7 | \$0 |
| | Work Sink | 2 | EA | 7 | \$0 |
| Regular Classroom (7 rooms) | | | | | |
| | Casework | 140 | LF | 7 | \$0 |
| | Ceiling - Splined | 5,887 | SF | 7 | \$0 |
| | Chalk Board | 32 | LF | 4 | \$2,938 |
| | Doors - Side-lite | 56 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 7 | EA | 7 | \$0 |
| | Floor - Tile | 5,887 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 62 | EA | 7 | \$0 |
| | Marker Board | 96 | LF | 7 | \$0 |
| | Student Lockers - One Tier | 105 | EA | 7 | \$0 |

Building: Branch

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|-----------------------------|----------|------|------|---------|
| Regular Classroom (7 rooms) | | | | | |
| | Walls - Plaster/Drywall | 6,090 | SF | 7 | \$0 |
| Special Education (2 rooms) | | | | | |
| | Casework | 62 | LF | 7 | \$0 |
| | Ceiling - Splined | 1,160 | SF | 7 | \$0 |
| | Chalk Board | 16 | LF | 4 | \$1,469 |
| | Doors - Side-lite | 16 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile | 1,160 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 10 | EA | 7 | \$0 |
| | Marker Board | 16 | LF | 7 | \$0 |
| | Storage/ Closet | 16 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,560 | SF | 7 | \$0 |
| | Work Sink | 2 | EA | 7 | \$0 |

Classrooms Subtotal:

\$5,508

Building: Branch

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | Ceiling - Splined | 231 | SF | 6 | \$188 |
| | Ceiling - Splined | 1,341 | SF | 7 | \$0 |
| | Doors - Side-lite | 88 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 2 | EA | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 3 | EA | 7 | \$0 |
| | Floor - Carpet | 600 | SF | 6 | \$1,278 |
| | Floor - Tile | 972 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 17 | EA | 7 | \$0 |
| | Power Distribution | 30 | EA | 7 | \$0 |
| | Storage/ Closet | 40 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 760 | SF | 6 | \$2,098 |
| | Walls - Plaster/Drywall | 2,140 | SF | 7 | \$0 |

Kitchen

| | | | | | |
|--|-----------------------------|-----|----|---|-----|
| | Ceiling - Plaster/Drywall | 520 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile | 520 | SF | 7 | \$0 |

Building: Branch

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|---------------------------------|----------|------|------|---------|
| Kitchen | | | | | |
| | Lighting - Pendent/Surface | 6 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,320 | SF | 7 | \$0 |
| Lunch & Multipurpose Room | | | | | |
| | Ceiling - Splined | 1,711 | SF | 7 | \$0 |
| | Chalk Board | 16 | LF | 4 | \$1,469 |
| | Doors - Side-lite | 12 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 4 | EA | 7 | \$0 |
| | Floor - Tile | 1,711 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 18 | EA | 7 | \$0 |
| | Serving Line | 20 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,460 | SF | 7 | \$0 |
| MDF_IDF | | | | | |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Finishes | 200 | SF | 7 | \$0 |
| Mechanical/ Service Rooms | | | | | |
| | Janitor's Closet | 30 | SF | 6 | \$215 |
| | Janitor's Closet | 81 | SF | 7 | \$0 |
| | Mechanical/ Service Rooms | 174 | SF | 7 | \$0 |
| | Storage Room | 100 | SF | 6 | \$716 |
| | Storage Room | 220 | SF | 7 | \$0 |
| Restroom | | | | | |
| | Accessories | 844 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 844 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 6 | EA | 7 | \$0 |
| | Floor - Tile Ceramic/ Porcelain | 844 | SF | 7 | \$0 |
| | Floor Drain | 4 | EA | 7 | \$0 |
| | Lavatory | 13 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 22 | EA | 7 | \$0 |
| | Partitions | 14 | EA | 7 | \$0 |
| | Urinals | 6 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 992 | SF | 7 | \$0 |
| | Walls - Tile Ceramic/ Porcelain | 2,112 | SF | 7 | \$0 |
| | Water Closet | 20 | EA | 7 | \$0 |

Building: Branch

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--|-------------|----------|------|------|----------------|
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$5,964 |

Building: Branch

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|--------------------------------------|----------|------|------|------------|
| Corridor | | | | | |
| | Ceiling - Splined | 2,432 | SF | 7 | \$0 |
| | Drinking Fountains - Single Fountain | 9 | EA | 7 | \$0 |
| | Floor - Tile/Sheet | 2,432 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 29 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 3,768 | SF | 7 | \$0 |
| Safety | | | | | |
| | Camera Viewing Station | 1 | EA | 7 | \$0 |
| | Security Cameras | 4 | EA | 7 | \$0 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 224 | SF | 7 | \$0 |
| | Ceiling - Splined | 320 | SF | 7 | \$0 |
| | Floor - Rubber Floor | 32 | SF | 7 | \$0 |
| | Floor - Tile | 416 | SF | 7 | \$0 |
| | Handrails | 120 | LF | 7 | \$0 |
| | Lighting - Pendent/Surface | 4 | EA | 7 | \$0 |
| | Stairs - Rubber | 184 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,600 | SF | 7 | \$0 |
| Building Interior Subtotal: | | | | | \$0 |

Total Building Cost

\$1,009,889

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|--------------------------------|----------|------|------|---------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 9 | EA | 6 | \$9,845 |
| | Civil/ Drainage - Site Manhole | 4 | EA | 6 | \$5,971 |

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|---|----------|------|------|--------------------|
| Fencing | | | | | |
| | Fencing - Chain Link | 1,456 | LF | 5 | \$88,801 |
| Landscape | | | | | |
| | Landscape - Grass | 4,768 | SF | 6 | \$3,955 |
| | Landscape - Hardscape- Concrete | 663 | SF | 5 | \$7,272 |
| | Landscape - Hardscape- Concrete | 2,651 | SF | 6 | \$13,685 |
| | Parkway trees | 4 | EA | 4 | \$10,496 |
| | Parkway trees | 9 | EA | 7 | \$0 |
| | Planting Beds/ Area | 2,154 | SF | 6 | \$3,542 |
| | Play Area - Asphalt/ Hardscape | 7,760 | SF | 5 | \$35,399 |
| Parking Lot | | | | | |
| | Concrete Curbs | 189 | LF | 6 | \$2,427 |
| | Surface - Asphalt | 6,375 | SF | 5 | \$29,081 |
| | Surface - Asphalt | 1,380 | SF | 6 | \$3,335 |
| | Trash Compactor | 1 | EA | 6 | \$0 |
| | Trash Enclosure - Chain Links | 450 | SF | 6 | \$7,896 |
| Playground | | | | | |
| | Equipment - Pre K 3-5 | 1 | EA | 5 | \$44,233 |
| | Equipment - School Age 5-12 | 1 | EA | 5 | \$66,350 |
| | Surface - Poured Surface | 1,200 | SF | 4 | \$28,623 |
| | Surface - Square Rubber Mats | 2,268 | SF | 5 | \$22,897 |
| Sidewalks | | | | | |
| | Sidewalks - Perimeter Sidewalks | 3,730 | SF | 5 | \$30,777 |
| | Sidewalks - Perimeter Sidewalks | 6,929 | SF | 6 | \$13,773 |
| Signage | | | | | |
| | Flag Pole - Flag Pole | 2 | EA | 7 | \$0 |
| | Marquee - Free Standing Back Lighted | 1 | EA | 6 | \$0 |
| | Monument - Building Mounted Cut Letter Sign | 1 | EA | 6 | \$0 |
| Site Subtotal: | | | | | \$428,356 |
| Total Site Cost | | | | | \$428,356 |
| Campus Total ^{2 3} | | | | | \$2,857,318 |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
 - **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
 - **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
 - **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
 - **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.
-

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart-Board |
|-------------------|-------------------|---------------|-------------|------------------------|-----------|---------------|--------------|----------------|--------------------|----------------------|-------------|-------------|-------------|-------------|
| Main | | | | | | | | | | | | | | |
| Art Room | Regular Classroom | | 306 | 306 | 713 | 0 | 0 | 8 | 93 | 39 | 53 | Y | Y | N |
| Computer Lab | Computer Lab | | 202 | 202 | 713 | 0 | 35 | 70 | 93 | 39 | | Y | Y | Y |
| Kindergarten | Kindergarten | | 102 | 102 | 1,333 | 0 | 3 | 8 | 124 | 52 | 40 | Y | Y | N |
| Kindergarten | Kindergarten | | 103 | 103 | 1,510 | 0 | 3 | 8 | 186 | 78 | 40 | Y | Y | N |
| Kindergarten | Kindergarten | | 104 | 104 | 1,432 | 0 | 3 | 8 | 124 | 52 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 201 | 201 | 800 | 0 | 0 | 10 | 93 | 39 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | | 203 | 203 | 775 | 0 | 0 | 8 | 93 | 39 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 205 | 205 | 713 | 0 | 0 | 8 | 93 | 39 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 207 | 207 | 713 | 0 | 0 | 8 | 93 | 39 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 208 | 208 | 713 | 0 | 0 | 8 | 93 | 39 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 210 | 210 | 800 | 0 | 0 | 10 | 93 | 39 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 211 | 211 | 1,172 | 0 | 0 | 10 | 124 | 52 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 301 | 301 | 800 | 0 | 0 | 10 | 93 | 39 | 53 | Y | N | N |
| Regular Classroom | Regular Classroom | | 302 | 302 | 713 | 0 | 3 | 24 | 93 | 39 | 53 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 303 | 303 | 800 | 0 | 0 | 8 | 93 | 39 | 53 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 304 | 304 | 713 | 0 | 0 | 8 | 93 | 39 | 53 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 305 | 305 | 713 | 0 | 0 | 8 | 93 | 39 | 53 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 307 | 307 | 867 | 0 | 3 | 28 | 93 | 39 | 53 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 309 | 309 | 867 | 0 | 0 | 8 | 62 | 26 | 53 | Y | Y | N |
| Science Classroom | Regular Classroom | | 308/310 | 308/310 | 1,580 | 0 | 3 | 20 | 93 | 39 | 53 | Y | Y | N |
| Special Education | | 2nd Floor | 202A | | 240 | 0 | 0 | 32 | | | | N | N | Y |

| | | | | | | | | | | | | | | |
|-------------------|-------------------|--|-----|-----|-------|---|---|----|-----|----|----|---|---|---|
| Branch | | | | | | | | | | | | | | |
| Pre School | Pre School | | 402 | 402 | 1,131 | 0 | 0 | 10 | 351 | 40 | 40 | Y | Y | N |
| Pre School | Pre School | | 403 | 403 | 1,131 | 0 | 0 | 10 | 351 | 40 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 501 | 501 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 502 | 502 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 503 | 503 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 504 | 504 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 505 | 505 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 513 | 513 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | | 514 | 514 | 841 | 0 | 0 | 10 | 203 | 58 | 40 | Y | Y | N |
| Special Education | Special Education | | 404 | 404 | 580 | 0 | 3 | 10 | 140 | 40 | 40 | Y | Y | N |
| Special Education | Special Education | | 405 | 405 | 580 | 0 | 3 | 10 | 140 | 40 | 40 | Y | Y | N |
| | | | 509 | 509 | 1,131 | 0 | 0 | 12 | 273 | 78 | | Y | Y | N |