

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1907 | 3 | 53,654 | \$2,543,646 |
| Addition 1 | 1913 | 3 | 11,488 | \$662,786 |
| Addition 2 | 1913 | 3 | 11,488 | \$341,055 |
| Addition 3 | 2000 | 4 | 56,323 | \$1,716,771 |
| Addition 4 | 2000 | 2 | 17,483 | \$612,634 |
| SITE | | | | \$239,279 |
| Campus Total | | | 150,436 | \$6,116,172 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--|----------|------|------|----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 6 | \$961 |
| | Exterior Doors - Side lite | 1 | EA | 7 | \$0 |
| | Exterior Doors - Store Front | 5 | EA | 6 | \$2,730 |
| | Exterior Doors - Transom Lite | 3 | EA | 6 | \$940 |
| | Exterior Doors - Transom Lite | 2 | EA | 7 | \$0 |
| | Exterior Stairs - Concrete | 66 | LF | 6 | \$5,397 |
| Fire Escape | | | | | |
| | Fire Escape | 60 | LF | 6 | \$37,906 |
| Foundation | | | | | |
| | Foundation - Concrete | 500 | LF | 7 | \$0 |
| | Foundation - Masonry | 200 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 53,654 | SF | 7 | \$0 |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---|----------|------|------|-----------|
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 7 | EA | 6 | \$2,021 |
| Roof System | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 30 | LF | 5 | \$85,547 |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 29 | LF | 6 | \$27,686 |
| | Coping - Clay Tile | 460 | LF | 6 | \$14,774 |
| | Coping - Stone | 160 | LF | 6 | \$5,139 |
| | Coping - Terra Cotta | 153 | LF | 6 | \$4,914 |
| | Downspouts - Exterior Downspouts | 30 | LF | 5 | \$2,423 |
| | Downspouts - Exterior Downspouts | 208 | LF | 6 | \$6,913 |
| | Downspouts - Interior Downspouts | 63 | LF | 6 | \$2,094 |
| | Parapet - 16" - 30" Height | 360 | LF | 6 | \$14,384 |
| | Parapet - Parapet < 16" Height | 260 | LF | 6 | \$5,540 |
| | Parapet - Parapet > 30" | 153 | LF | 6 | \$9,780 |
| | Roof - Asphalt Gravel Ballast | 2,700 | SF | 5 | \$63,745 |
| | Roof - Modified Bitumen | 13,385 | SF | 6 | \$125,945 |
| | Roof Structure - Concrete | 2,700 | SF | 7 | \$0 |
| | Roof Structure - Steel with Clay Tile Arch | 13,385 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Brick | 1,115 | SF | 5 | \$26,548 |
| | Exterior Walls - Brick | 20,534 | SF | 6 | \$138,009 |
| | Exterior Walls - Stone-Cut | 1,340 | SF | 6 | \$9,006 |
| | Exterior Walls - Terra Cotta | 90 | SF | 5 | \$1,305 |
| | Exterior Walls - Terra Cotta | 700 | SF | 6 | \$4,705 |
| Windows | | | | | |
| | Guard - Guards perforated | 172 | SF | 7 | \$0 |
| | Guard - Guards wire guard | 72 | SF | 6 | \$919 |
| | Windows - Casement Aluminum Double-pane | 5,113 | SF | 6 | \$38,166 |
| Building Exter | ior Subtotal: | | | | \$637,495 |
| - | | | | | . , |

Building: Main

| Category: Electrical | System | | | | | | |
|----------------------|---------------------------|----------|------|------|-------|--|--|
| Group | Item - Type | Quantity | Unit | Rank | Cost | | |
| Emergency System | | | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 | | |



Category: Electrical System

| Group Item - Type Emergency System Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym | Quantity 4,200 10,200 21 | Unit SF SF | Rank 6 | Cos \$2,222 |
|--|-----------------------------------|------------------|-----------|-----------------------|
| Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs | 10,200 | | 6 | \$2,222 |
| Emergency Battery Packs - Corridors and Stairs | | SF | | |
| | 04 | <u> </u> | 6 | \$3,063 |
| Emergency Battery Packs - Gym | ∠1 | EA | 6 | \$4,253 |
| | 5 | EA | 6 | \$1,01 |
| Exit Signs - Auditoium | 6 | EA | 6 | \$89 |
| Exit Signs - Corridors and Stairs | 6 | EA | 2 | \$3,27 |
| Exit Signs - Corridors and Stairs | 14 | EA | 6 | \$2,09 |
| Exit Signs - Gym | 8 | EA | 6 | \$1,25 |
| Main Service | | | | |
| Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,92 |
| Main Electrical Service - 1600 A 120/208/3PH | 1 | EA | 6 | \$5,64 |
| PA System | 53,654 | SF | 6 | \$17,64 |
| Power Distribution | | | | |
| Lighting and Power Panels - 100 A | 6 | EA | 6 | \$1,79 |
| Lighting and Power Panels - Above 100 A | 12 | EA | 6 | \$5,96 |
| Main Distribution Panels - Greater than 600 amp | 2 | EA | 6 | \$1,46 |
| Main Distribution Panels - Less than 400 amp | 2 | EA | 6 | \$1,000 |
| Electrical System Subtotal: | | | | \$54,920 |
| Building: Main | | | | |
| Category: Safty System | | | | |
| Group Item - Type | Quantity | Unit | Rank | Cos |
| Fire Alarm | | | | |
| Fire Alarm Panel | 1 | EA | 6 | \$6,400 |
| Fire Alarm Strobe Lights | 53,654 | SF | 6 | \$19,18 ⁻ |
| Fire Alarm_System | 53,654 | SF | 6 | \$26,08 |
| Safty System Subtotal: | | | | \$51,674 |
| Building: Main | | | | |
| Category: Mechanical System | | | | |
| | | | | |
| | Quantity | Unit | Rank | 0.0 |
| Group Item - Type Air Handling Systems | Quantity | Unit | Rank | Cos |



Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---|----------|------|------|-----------|
| Air Handling System | ns | | | | |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm | 1 | EA | 5 | \$95,595 |
| | Air Intake | 2 | EA | 5 | \$14,941 |
| | Auxiliaries - Greater than 35000 cfm | 2 | EA | 5 | \$37,765 |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 100 | LF | 5 | \$96,198 |
| | Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts | 200 | LF | 6 | \$98,147 |
| | Zone Dampers | 27 | EA | 5 | \$51,666 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | 2 | EA | 5 | \$24,345 |
| | Chemical Feeder | 1 | EA | 5 | \$3,075 |
| | Combustion Dampers | 2 | EA | 5 | \$5,104 |
| | Feed Water Pumps and Tank | 1 | EA | 6 | \$2,545 |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | 2 | EA | 5 | \$24,345 |
| | Piping - Condensate Pipe- Steel | 400 | LF | 6 | \$755 |
| | Piping - Steam Pipe- Steel | 400 | LF | 6 | \$755 |
| | Steam Traps | 60 | EA | 6 | \$15,849 |
| Heating Devices | | | | | |
| | Unit Heater - Steam | 1 | EA | 5 | \$909 |
| | Wall Heater - Electric | 4 | EA | 5 | \$2,146 |
| Temperature Contro |) | | | | |
| | Pneumatic System | 53,654 | SF | 4 | \$279,280 |
| | Thermostats - Pneumatic | 12 | EA | 4 | \$8,847 |
| | Thermostats - Pneumatic | 3 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 1 | EA | 6 | \$296 |
| Mechanical Svs | tem Subtotal: | | | | \$842,949 |
| Mechanical Sys | tem Subtotal: | | | | |

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|-------------------------------------|----------|------|------|-------|
| Hot Water | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | 1 | EA | 6 | \$310 |



Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|--|----------|------|------|-----------|
| Hot Water | | | | | |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 53,654 | SF | 6 | \$10,742 |
| | Domestic Piping-Cold Water Horizontal Lines | 53,654 | SF | 6 | \$13,043 |
| | Domestic Piping-Cold Water Risers | 53,654 | SF | 6 | \$9,974 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 53,654 | SF | 6 | \$8,440 |
| | Domestic Piping-Hot Water Horizontal Lines | 53,654 | SF | 6 | \$9,974 |
| | Domestic Piping-Hot Water Return Lines | 53,654 | SF | 6 | \$7,673 |
| | Domestic Piping-Hot Water Return Risers | 53,654 | SF | 6 | \$7,673 |
| | Sanitary Piping | 53,654 | SF | 6 | \$49,104 |
| | Storm Piping | 53,654 | SF | 6 | \$46,802 |
| | Vent Piping | 53,654 | SF | 7 | \$0 |
| Pumps | | | | | |
| | Pumps - Ejector-Simplex | 1 | EA | 6 | \$745 |
| | Pumps - Sump-Simplex | 1 | EA | 2 | \$11,443 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |
| Plumbing Sys | tem Subtotal: | | | | \$176,668 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|----------|------|------|---------|
| Computer Lab (1 r | room) | | | | |
| | AC Units | 2 | EA | 6 | \$991 |
| | Ceiling - Plaster/Drywall | 880 | SF | 6 | \$3,045 |
| | Chalk Board | 27 | LF | 4 | \$2,479 |
| | Doors - Transom Window | 12 | SF | 6 | \$203 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Wood | 880 | SF | 6 | \$6,204 |
| | Lighting - Pendent/Surface | 14 | EA | 5 | \$2,556 |
| | Marker Board | 24 | LF | 7 | \$0 |
| | Storage/ Closet | 135 | SF | 6 | \$979 |
| | Walls - Plaster/Drywall | 1,386 | SF | 6 | \$3,825 |
| Kindergarten (3 ro | poms) | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Ceiling - Plaster/Drywall | 2,700 | SF | 6 | \$9,344 |



Category: Classrooms

| | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|---------------------------------|----------|------|------|----------|
| Kindergarten (3 roc | oms) | | | | |
| | Chalk Board | 24 | LF | 4 | \$2,203 |
| | Chalk Board | 5 | LF | 6 | \$112 |
| | Doors - Transom Window | 24 | SF | 6 | \$406 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Tile/Sheet | 920 | SF | 6 | \$921 |
| | Floor - Wood | 1,780 | SF | 6 | \$12,549 |
| | Lighting - Pendent/Surface | 28 | EA | 5 | \$5,112 |
| | Lighting - Pendent/Surface | 14 | EA | 7 | \$0 |
| | Marker Board | 46 | LF | 7 | \$0 |
| | Storage/ Closet | 270 | SF | 6 | \$1,958 |
| | Walls - Plaster/Drywall | 25 | SF | 5 | \$128 |
| | Walls - Plaster/Drywall | 4,158 | SF | 6 | \$11,476 |
| Regular Classroom | n (11 rooms) | | | | |
| | AC Units | 2 | EA | 6 | \$991 |
| | Casework | 85 | LF | 6 | \$2,147 |
| | Ceiling - Lay-in | 491 | SF | 6 | \$1,474 |
| | Ceiling - Plaster/Drywall | 8,169 | SF | 6 | \$28,270 |
| | Chalk Board | 109 | LF | 4 | \$10,007 |
| | Doors - Side-lite | 54 | SF | 6 | \$903 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Transom Window | 52 | SF | 6 | \$880 |
| | Doors - Wood Doors inclu hw | 14 | EA | 6 | \$4,214 |
| | Floor - Tile/Sheet | 1,596 | SF | 6 | \$1,598 |
| | Floor - Wood | 7,064 | SF | 6 | \$49,800 |
| | Lighting - Lay-in | 4 | EA | 6 | \$476 |
| | Lighting - Pendent/Surface | 14 | EA | 5 | \$2,556 |
| | Lighting - Pendent/Surface | 14 | EA | 6 | \$1,735 |
| | Lighting - Pendent/Surface | 106 | EA | 7 | \$0 |
| | Marker Board | 189 | LF | 7 | \$0 |
| | Storage/ Closet | 135 | SF | 6 | \$979 |
| | Walls - Masonry | 1,468 | SF | 6 | \$4,618 |
| | Walls - Plaster/Drywall | 13,014 | SF | 6 | \$35,917 |
| Special Education (| (1 room) | | | | |
| | Ceiling - Plaster/Drywall | 152 | SF | 6 | \$526 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Concrete Epoxy/ Painted | 152 | SF | 6 | \$80 |



Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|----------------------------|----------|------|------|-----------|
| Special Educat | ion (1 room) | | | | |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Walls - Concrete Block | 84 | SF | 6 | \$246 |
| | Walls - Plaster/Drywall | 450 | SF | 6 | \$1,242 |
| Classrooms | Subtotal: | | | | \$216,601 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|----------|
| Administrative Su | ites/Offices | | | | |
| | Ceiling - Lay-in | 384 | SF | 6 | \$1,153 |
| | Ceiling - Plaster/Drywall | 512 | SF | 6 | \$1,772 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Concrete | 240 | SF | 6 | \$127 |
| | Floor - Tile | 216 | SF | 6 | \$473 |
| | Floor - Tile/Sheet | 440 | SF | 6 | \$440 |
| | Lighting - Lay-in | 2 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 4 | EA | 6 | \$496 |
| | Lighting - Pendent/Surface | 5 | EA | 7 | \$0 |
| | Power Distribution | 28 | EA | 6 | \$59,497 |
| | Storage/ Closet | 89 | SF | 6 | \$645 |
| | Walls - Concrete Block | 495 | SF | 6 | \$1,451 |
| | Walls - Plaster/Drywall | 1,824 | SF | 6 | \$5,034 |
| | Work SInk | 1 | EA | 6 | \$508 |
| Auditorium & The | ater | | | | |
| | Balcony Seating | 80 | EA | 6 | \$13,913 |
| | Ceiling - Plaster/Drywall | 1,000 | SF | 6 | \$8,337 |
| | Doors - Steel Doors incl hw | 4 | EA | 6 | \$1,204 |
| | Floor - Carpet | 900 | SF | 6 | \$1,918 |
| | Floor - Wood | 2,659 | SF | 6 | \$18,746 |
| | Lighting - Pendent/Surface | 16 | EA | 7 | \$0 |
| | Main Floor Seating | 274 | EA | 6 | \$47,653 |
| | Sound System | 1 | EA | 6 | \$10,721 |
| | Stage | 458 | SF | 6 | \$2,646 |
| | Stage Curtain | 12 | EA | 6 | \$0 |
| | Stage Lighting System | 1 | EA | 6 | \$8,077 |
| | | | | - | 4 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--------------------------------------|----------|------|------|------------|
| Auditorium & The | ater | | | | |
| | Stage-Stairs - Wood | 14 | LF | 6 | \$164 |
| | Walls - Plaster/Drywall | 7,630 | SF | 6 | \$36,333 |
| Gymnasia | | | | | |
| | Ceiling - Plaster/Drywall | 3,850 | SF | 6 | \$21,251 |
| | Doors - Steel Doors incl hw | 4 | EA | 6 | \$1,204 |
| | Doors - Transom Window | 36 | SF | 6 | \$610 |
| | Floor - Tile/Sheet | 3,850 | SF | 6 | \$3,854 |
| | Lighting - Metal Halide/Sodium Vapor | 16 | EA | 7 | \$0 |
| | Walls | 1,000 | | 6 | \$0 |
| | Walls - Plaster/Drywall | 4,110 | SF | 6 | \$11,343 |
| MDF_IDF | | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Finishes | 25 | SF | 6 | \$178 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Servi | ice Rooms | | | | |
| | Boiler Room | 1,600 | SF | 6 | \$11,463 |
| | Coal Room | 580 | SF | 6 | \$4,155 |
| | Janitor's Closet | 98 | SF | 6 | \$702 |
| | Mechanical/ Service Rooms | 2,065 | SF | 5 | \$33,309 |
| | Mechanical/ Service Rooms | 38 | SF | 6 | \$272 |
| | Storage Room | 38 | SF | 6 | \$272 |
| Restroom | | | | | |
| | Accessories | 1,500 | SF | 6 | \$13,835 |
| | Ceiling - Lay-in | 570 | SF | 6 | \$1,712 |
| | Ceiling - Plaster/Drywall | 930 | SF | 6 | \$3,218 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Floor - Concrete | 722 | SF | 6 | \$382 |
| | Floor - Terrazzo | 570 | SF | 6 | \$1,247 |
| | Floor - Tile | 208 | SF | 6 | \$455 |
| | Floor Drain | 9 | EA | 6 | \$9,532 |
| | Hand Dryer | 4 | EA | 6 | \$920 |
| | Lavatory | 15 | EA | 6 | \$4,794 |
| | Lighting - Lay-in | 7 | EA | 6 | \$833 |
| | Lighting - Lay-in | - 11 | EA | 7 | \$0 \$0 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--------------------------------|----------|------|------|-----------|
| Restroom | | | | | |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Lighting - Pendent/Surface | 4 | EA | 7 | \$0 |
| | Partitions | 19 | EA | 6 | \$5,642 |
| | Urinals | 15 | EA | 6 | \$5,040 |
| | Walls - Concrete Block | 1,827 | SF | 6 | \$5,356 |
| | Walls - Plaster/Drywall | 576 | SF | 6 | \$1,590 |
| | Walls - Structural Glazed Tile | 1,973 | SF | 6 | \$6,207 |
| | Water Closet | 20 | EA | 6 | \$6,720 |
| Rooms (Othe | r Than Classrooms) Subtotal: | | | | \$382,888 |

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|---------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 14,255 | SF | 6 | \$88,266 |
| | Floor - Concrete Epoxy/ Painted | 14,255 | SF | 6 | \$6,931 |
| | Lighting - Pendent/Surface | 24 | EA | 6 | \$2,973 |
| | Walls - Masonry | 7,306 | SF | 6 | \$22,985 |
| | Walls - Plaster/Drywall | 6,842 | SF | 6 | \$30,331 |
| Safety | | | | | |
| | Security Cameras | 2 | EA | 6 | \$388 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 736 | SF | 6 | \$5,389 |
| | Floor - Tile | 144 | SF | 6 | \$78 |
| | Floor - Tile/Sheet | 160 | SF | 6 | \$87 |
| | Handrails | 168 | LF | 6 | \$1,456 |
| | Lighting - Pendent/Surface | 6 | EA | 6 | \$743 |
| | Lighting - Pendent/Surface | 4 | EA | 7 | \$0 |
| | Stairs - Asphalt | 24 | LF | 6 | \$223 |
| | Stairs - Rubber | 68 | LF | 6 | \$731 |
| | Walls - Plaster/Drywall | 7,200 | SF | 6 | \$19,871 |

Building Interior Subtotal:

\$180,452



Total Building Cost

\$2,543,646

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 2 | EA | 6 | \$961 |
| | Exterior Stairs - Concrete | 6 | LF | 6 | \$491 |
| Foundation | | | | | |
| | Foundation - Concrete | 112 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 11,488 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 3 | EA | 6 | \$866 |
| Roof System | | | | | |
| | Coping - Clay Tile | 35 | LF | 6 | \$1,124 |
| | Coping - Stone | 112 | LF | 6 | \$3,597 |
| | Downspouts - Interior Downspouts | 63 | LF | 7 | \$0 |
| | Parapet - 16" - 30" Height | 147 | LF | 6 | \$5,873 |
| | Roof - Modified Bitumen | 2,800 | SF | 6 | \$26,346 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 2,800 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cornice - Cast Stone | 250 | LF | 6 | \$8,669 |
| | Exterior Walls - Brick | 10,552 | SF | 6 | \$70,920 |
| | Exterior Walls - Stone-Cast | 795 | SF | 6 | \$5,343 |
| Windows | | | | | |
| | Guard - Guards wire guard | 433 | SF | 6 | \$5,529 |
| | Windows - Sash Aluminum Double-pane | 1,462 | SF | 6 | \$10,913 |

Building: Addition 1

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 11,488 | SF | 6 | \$3,450 |
| | Emergency Battery Packs - Corridors and Stairs | 3 | EA | 6 | \$608 |
| | Exit Signs - Corridors and Stairs | 3 | EA | 6 | \$449 |



Building: Addition 1

| Category: Ele | ctrical System | | | | |
|--------------------|--|----------|------|------|----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | PA System | 11,488 | SF | 6 | \$3,778 |
| Power Distribution | n | | | | |
| | Lighting and Power Panels - 100 A | 3 | EA | 6 | \$897 |
| Electrical Sys | tem Subtotal: | | | | \$12,103 |
| Building: Add | ition 1 | | | | |

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--------------------------|----------|------|------|---------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 11,488 | SF | 6 | \$4,107 |
| | Fire Alarm_System | 11,488 | SF | 6 | \$5,585 |

Safty System Subtotal:

Building: Addition 1

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|-----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | 3 | EA | 4 | \$32,520 |
| Air Handling Systems | | | | | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 100 | LF | 5 | \$96,198 |
| Temperature Control | | | | | |
| | Pneumatic System | 11,488 | SF | 4 | \$59,797 |
| | Thermostats - Pneumatic | 4 | EA | 4 | \$2,949 |
| | Thermostats - Pneumatic | 2 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |
| Mechanical Syster | n Subtotal: | | | | \$192,648 |

Building: Addition 1

Category: Plumbing System



Henry D Lloyd Elementary School

2103 N Lamon Ave Chicago, IL 60639

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 11,488 | SF | 6 | \$2,300 |
| | Domestic Piping-Cold Water Horizontal Lines | 11,488 | SF | 6 | \$2,793 |
| | Domestic Piping-Cold Water Risers | 11,488 | SF | 6 | \$2,136 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 11,488 | SF | 6 | \$1,807 |
| | Domestic Piping-Hot Water Horizontal Lines | 11,488 | SF | 6 | \$2,136 |
| | Domestic Piping-Hot Water Return Lines | 11,488 | SF | 6 | \$1,643 |
| | Domestic Piping-Hot Water Return Risers | 11,488 | SF | 6 | \$1,643 |
| | Sanitary Piping | 11,488 | SF | 6 | \$10,514 |
| | Storm Piping | 11,488 | SF | 6 | \$10,021 |
| | Vent Piping | 11,488 | SF | 6 | \$7,721 |
| Plumbing Sy | stem Subtotal: | | | | \$42,712 |

Plumbing System Subtotal:

Building: Addition 1

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|---------|
| Art Room (1 roor | n) | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 45 | LF | 6 | \$1,136 |
| | Ceiling - Plaster/Drywall | 1,181 | SF | 6 | \$4,087 |
| | Chalk Board | 31 | LF | 4 | \$2,846 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 1,181 | SF | 6 | \$1,182 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Marker Board | 6 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,302 | SF | 6 | \$3,593 |
| | Work Sink | 4 | EA | 6 | \$1,516 |
| Kindergarten (1 r | room) | | | | |
| | Casework | 4 | LF | 6 | \$101 |
| | Ceiling - Plaster/Drywall | 702 | SF | 6 | \$2,429 |
| | Floor - Concrete | 702 | SF | 6 | \$371 |
| | Lighting - Pendent/Surface | 4 | EA | 6 | \$496 |
| | Marker Board | 6 | LF | 6 | \$129 |
| | Walls - Plaster/Drywall | 1,064 | SF | 6 | \$2,937 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Regular Classroo | om (9 rooms) | | | | |
| | AC Units | 3 | EA | 6 | \$1,487 |
| | Casework | 98 | LF | 6 | \$2,475 |
| | | | | | |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|----------|
| Regular Classroon | n (9 rooms) | | | | |
| | Ceiling - Lay-in | 1,141 | SF | 6 | \$3,426 |
| | Ceiling - Plaster/Drywall | 7,480 | SF | 6 | \$25,885 |
| | Chalk Board | 93 | LF | 4 | \$8,538 |
| | Chalk Board | 2 | LF | 6 | \$45 |
| | Doors - Side-lite | 4 | SF | 6 | \$67 |
| | Doors - Transom Window | 32 | SF | 6 | \$542 |
| | Doors - Wood Doors inclu hw | 9 | EA | 6 | \$2,709 |
| | Floor - Tile/Sheet | 942 | SF | 5 | \$4,230 |
| | Floor - Tile/Sheet | 1,141 | SF | 6 | \$1,142 |
| | Floor - Wood | 6,538 | SF | 6 | \$46,092 |
| | Lighting - Lay-in | 14 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 28 | EA | 5 | \$5,112 |
| | Lighting - Pendent/Surface | 85 | EA | 7 | \$0 |
| | Marker Board | 150 | LF | 7 | \$0 |
| | Storage/ Closet | 270 | SF | 6 | \$1,958 |
| | Walls - Plaster/Drywall | 12,900 | SF | 6 | \$35,603 |
| | Work Sink | 3 | EA | 6 | \$1,137 |

Classrooms Subtotal:

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|---------------------------------|----------|------|------|---------|
| Mechanical/ Servi | ice Rooms | | | | |
| | Mechanical/ Service Rooms | 70 | SF | 6 | \$502 |
| Restroom | | | | | |
| | Accessories | 455 | SF | 6 | \$4,197 |
| | Ceiling - Lay-in | 39 | SF | 6 | \$117 |
| | Ceiling - Plaster/Drywall | 416 | SF | 6 | \$1,440 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Concrete Epoxy/ Painted | 416 | SF | 6 | \$220 |
| | Floor - Tile/Sheet | 39 | SF | 6 | \$39 |
| | Floor Drain | 3 | EA | 6 | \$3,177 |
| | Hand Dryer | 2 | EA | 6 | \$460 |
| | Lavatory | 5 | EA | 6 | \$1,598 |
| | Lighting - Pendent/Surface | 5 | EA | 6 | \$619 |

\$162,446



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--------------------------------|----------|------|------|----------|
| Restroom | | | | | |
| | Partitions | 3 | EA | 6 | \$891 |
| | Urinals | 13 | EA | 6 | \$4,368 |
| | Walls - Plaster/Drywall | 212 | SF | 6 | \$585 |
| | Walls - Structural Glazed Tile | 987 | SF | 5 | \$50,147 |
| | Water Closet | 4 | EA | 6 | \$1,344 |
| Rooms (Othe | r Than Classrooms) Subtotal: | | | | \$70,306 |

Rooms (Other Than Classrooms) Subtotal:

Building: Addition 1

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 2,418 | SF | 6 | \$14,972 |
| | Floor - Concrete Epoxy/ Painted | 978 | SF | 6 | \$476 |
| | Floor - Tile/Sheet | 1,440 | SF | 6 | \$782 |
| | Lighting - Pendent/Surface | 10 | EA | 6 | \$1,239 |
| | Walls - Concrete Block | 978 | SF | 6 | \$2,867 |
| | Walls - Masonry | 1,128 | SF | 6 | \$3,549 |
| | Walls - Plaster/Drywall | 1,842 | SF | 6 | \$8,166 |
| Safety | | | | | |
| | Security Cameras | 1 | EA | 6 | \$194 |
| Building Interi | or Subtotal: | | | | \$32,244 |

Total Building Cost

\$662,786

Building: Addition 2

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--|----------|------|------|-------|
| Foundation | | | | | |
| | Foundation - Concrete | 150 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 11,488 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 2 | EA | 6 | \$577 |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|--|----------|------|------|-----------|
| Roof System | | | | | |
| | Coping - Clay Tile | 35 | LF | 6 | \$1,124 |
| | Coping - Metal | 8 | LF | 7 | \$0 |
| | Coping - Terra Cotta | 105 | LF | 6 | \$3,372 |
| | Downspouts - Interior Downspouts | 63 | LF | 7 | \$0 |
| | Parapet - Parapet > 30" | 10 | LF | 5 | \$3,797 |
| | Parapet - Parapet > 30" | 193 | LF | 6 | \$12,337 |
| | Roof - Modified Bitumen | 2,800 | SF | 6 | \$26,346 |
| | Roof Structure - Steel with Clay Tile Arch | 2,800 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cornice - Cast Stone | 180 | LF | 6 | \$6,242 |
| | Exterior Walls - Brick | 5,276 | SF | 6 | \$35,460 |
| | Exterior Walls - Stone-Cast | 554 | SF | 6 | \$3,723 |
| Windows | | | | | |
| | Guard - Guards wire guard | 217 | SF | 6 | \$2,771 |
| | Windows - Sash Aluminum Double-pane | 730 | SF | 6 | \$5,449 |
| Building Exter | ior Subtotal: | | | | \$101,199 |

Building Exterior Subtotal:

Building: Addition 2

Category: Electrical System

| | • | | | | |
|--------------------|--|----------|------|------|----------|
| Group | Item - Type | Quantity | Unit | Rank | Cos |
| Emergency System | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 11,488 | SF | 6 | \$3,450 |
| | Exit Signs - Corridors and Stairs | 3 | EA | 2 | \$1,636 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | PA System | 11,488 | SF | 6 | \$3,778 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 3 | EA | 6 | \$897 |
| Electrical System | Subtotal | | | | \$12,683 |

Building: Addition 2

Category: Safty System



Henry D Lloyd Elementary School

2103 N Lamon Ave Chicago, IL 60639

\$16,921

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 11,488 | SF | 6 | \$4,107 |
| | Fire Alarm_System | 11,488 | SF | 5 | \$12,814 |

Safty System Subtotal:

Building: Addition 2

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--|----------|------|------|----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | 2 | EA | 6 | \$6,667 |
| Temperature Contr | rol | | | | |
| | Pneumatic System | 11,488 | SF | 4 | \$59,797 |
| | Thermostats - Pneumatic | 4 | EA | 4 | \$2,949 |
| | Thermostats - Pneumatic | 2 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |
| Mechanical Sv | stem Subtotal: | | | | \$70,599 |

Building: Addition 2

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------|--|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 11,488 | SF | 6 | \$2,300 |
| | Domestic Piping-Cold Water Horizontal Lines | 11,488 | SF | 6 | \$2,793 |
| | Domestic Piping-Cold Water Risers | 11,488 | SF | 6 | \$2,136 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 11,488 | SF | 5 | \$0 |
| | Domestic Piping-Hot Water Horizontal Lines | 11,488 | SF | 6 | \$2,136 |
| | Domestic Piping-Hot Water Return Lines | 11,488 | SF | 6 | \$1,643 |
| | Domestic Piping-Hot Water Return Risers | 11,488 | SF | 6 | \$1,643 |
| | Sanitary Piping | 11,488 | SF | 6 | \$10,514 |
| | Storm Piping | 11,488 | SF | 6 | \$10,021 |
| | Vent Piping | 11,488 | SF | 6 | \$7,721 |

Plumbing System Subtotal:

Building: Addition 2



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Co |
|-------------------|-----------------------------|----------|------|------|----------|
| (indergarten (2 r | rooms) | | | | |
| | AC Units | 2 | EA | 6 | \$99 |
| | Casework | 8 | LF | 6 | \$20 |
| | Ceiling - Plaster/Drywall | 1,870 | SF | 6 | \$6,47 |
| | Chalk Board | 6 | LF | 4 | \$55 |
| | Chalk Board | 6 | LF | 6 | \$13 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$6 |
| | Floor | 935 | | 6 | 5 |
| | Floor - Tile | 935 | SF | 6 | \$2,04 |
| | Lighting - Pendent/Surface | 28 | EA | 5 | \$5,1 |
| | Marker Board | 10 | LF | 6 | \$2 |
| | Marker Board | 10 | LF | 7 | 5 |
| | Storage/ Closet | 135 | SF | 6 | \$9 |
| | Walls - Plaster/Drywall | 2,588 | SF | 6 | \$7,14 |
| | Work Sink | 1 | EA | 6 | \$3 |
| egular Classroo | om (3 rooms) | | | | |
| | Casework | 36 | LF | 6 | \$9 |
| | Ceiling - Lay-in | 1,200 | SF | 6 | \$3,6 |
| | Ceiling - Plaster/Drywall | 1,870 | SF | 6 | \$6,4 |
| | Chalk Board | 12 | LF | 4 | \$1,1 |
| | Doors - Side-lite | 16 | SF | 6 | \$2 |
| | Doors - Wood Doors inclu hw | 3 | EA | 6 | \$9 |
| | Floor - Plaster/Drywall | 935 | SF | 6 | |
| | Floor - Tile | 1,200 | SF | 5 | \$5,3 |
| | Floor - Tile | 935 | SF | 6 | \$2,0 |
| | Lighting - Lay-in | 14 | EA | 6 | \$1,6 |
| | Lighting - Pendent/Surface | 14 | EA | 5 | \$2,5 |
| | Lighting - Pendent/Surface | 14 | EA | 6 | \$1,7 |
| | Marker Board | 12 | LF | 6 | \$2 |
| | Marker Board | 20 | LF | 7 | |
| | Storage/ Closet | 270 | SF | 6 | \$1,9 |
| | Walls - Plaster/Drywall | 4,060 | SF | 6 | \$11,2 |
| Classrooms S | Subtotal: | | | | \$64,88 |
| | | | | | ψ0-7,000 |

Building: Addition 2

. . .

| Category: Rooms | (Other Than Classrooms) | | | | |
|-----------------|-------------------------|----------|------|------|------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| | | | | | |

_



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Accessories | 56 | SF | 6 | \$517 |
| | Ceiling - Plaster/Drywall | 56 | SF | 6 | \$194 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Terrazzo | 56 | SF | 6 | \$123 |
| | Lavatory | 1 | EA | 6 | \$320 |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Partitions | 1 | EA | 6 | \$297 |
| | Walls - Plaster/Drywall | 362 | SF | 6 | \$999 |
| | Water Closet | 1 | EA | 5 | \$1,344 |
| Rooms (Other | r Than Classrooms) Subtotal: | | | | \$4,217 |

Building: Addition 2

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|--------------------------------------|----------|------|------|-----------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 2,418 | SF | 6 | \$14,972 |
| | Floor | 480 | SF | 6 | \$0 |
| | Floor - Concrete Epoxy/ Painted | 978 | SF | 6 | \$476 |
| | Floor - Tile/Sheet | 960 | SF | 6 | \$522 |
| | Lighting - Metal Halide/Sodium Vapor | 2 | EA | 6 | \$267 |
| | Lighting - Pendent/Surface | 8 | EA | 6 | \$991 |
| | Walls - Masonry | 1,500 | SF | 6 | \$4,719 |
| | Walls - Plaster/Drywall | 1,692 | SF | 6 | \$7,501 |
| Safety | | | | | |
| | Security Cameras | 1 | EA | 6 | \$194 |
| Building Inte | rior Subtotal: | | | | \$29,641 |
| Total Buildin | g Cost | | | | \$341,055 |
| Building: Add | dition 3 | | | | |
| Category: Bu | uilding Exterior | | | | |
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| | | | | | |



Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|-----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 6 | \$702 |
| | Exterior Doors - Exterior Steel Door | 4 | EA | 6 | \$1,922 |
| | Exterior Doors - Side lite | 2 | EA | 6 | \$627 |
| | Exterior Doors - Side lite | 2 | EA | 7 | \$C |
| | Exterior Doors - Store Front | 11 | EA | 6 | \$6,007 |
| | Exterior Doors - Transom Lite | 3 | EA | 7 | \$0 |
| Foundation | | | | | |
| | Foundation - Concrete | 578 | LF | 7 | \$C |
| | Superstructure - Metal Deck/ Concrete Topping | 56,323 | SF | 7 | \$C |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 9 | EA | 6 | \$2,599 |
| Roof System | | | | | |
| | Chimney - Metal Flue | 24 | LF | 7 | \$C |
| | Coping - Stone | 884 | LF | 7 | \$C |
| | Downspouts - Interior Downspouts | 768 | LF | 7 | \$C |
| | Parapet - Parapet > 30" | 884 | LF | 7 | \$0 |
| | Roof - Modified Bitumen | 30 | SF | 5 | \$857 |
| | Roof - Modified Bitumen | 5,200 | SF | 6 | \$48,929 |
| | Roof - Modified Bitumen | 11,295 | SF | 7 | \$0 |
| | Roof Structure - Concrete | 16,525 | SF | 7 | \$C |
| Walls | | | | | |
| | Cornice - Cast Stone | 630 | LF | 6 | \$21,847 |
| | Exterior Walls - Brick | 280 | SF | 5 | \$6,667 |
| | Exterior Walls - Brick | 33,235 | SF | 6 | \$223,372 |
| | Exterior Walls - Precast Panel Wall | 2,280 | SF | 6 | \$15,324 |
| Windows | | | | | |
| | Guard - Guards perforated | 900 | SF | 6 | \$11,493 |
| | Windows - Casement Aluminum Double-pane | 180 | SF | 7 | \$C |
| | Windows - Sash Aluminum Double-pane | 4,890 | SF | 6 | \$36,502 |
| | r Subtotal: | | | | \$376,846 |

Building: Addition 3

Category: Electrical System



Henry D Lloyd Elementary School

2103 N Lamon Ave Chicago, IL 60639

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 11,200 | SF | 6 | \$3,363 |
| | Emergency Battery Packs - Corridors and Stairs | 16 | EA | 6 | \$3,240 |
| | Exit Signs - Corridors and Stairs | 16 | EA | 6 | \$2,396 |
| | Security System - CCTV | 56,323 | SF | 6 | \$16,914 |
| | Security System - Intrusion Detection | 56,323 | SF | 6 | \$14,498 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | Main Electrical Service - 1600 A 277/480/3PH | 1 | EA | 6 | \$5,977 |
| | PA System | 56,323 | SF | 6 | \$18,525 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - Above 100 A | 14 | EA | 6 | \$6,958 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 6 | \$528 |
| | Main Distribution Panels - Greater than 600 amp | 1 | EA | 6 | \$730 |
| | Main Distribution Panels - Less than 400 amp | 1 | EA | 6 | \$503 |
| | Transformers - 277/480 - 120/208 | 3 | EA | 6 | \$3,795 |

Electrical System Subtotal:

Building: Addition 3

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 56,323 | SF | 6 | \$20,135 |
| | Fire Alarm_System | 56,323 | SF | 6 | \$27,384 |
| | Fire Pump Controller | 1 | EA | 6 | \$1,823 |
| Pump Room Assen | mbly | | | | |
| | Fire Pump - 25-50 hp | 1 | EA | 6 | \$1,558 |
| | Jockey Pump | 1 | EA | 6 | \$758 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 56,323 | SF | 7 | \$0 |
| | Sprinkler Piping | 56,323 | SF | 6 | \$10,470 |
| | Wet Sprinkler System | 56,323 | SF | 6 | \$14,498 |
| Safty System S | Subtotal: | | | | \$83,032 |

\$80,755



Building: Addition 3

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cos |
|----------------------|--|----------|------|------|-----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 3 | EA | 5 | \$22,13 |
| Air Handling Systems | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 15001-20000 cfm | 1 | EA | 5 | \$64,83 |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 15001- 20000 cfm | 1 | EA | 6 | \$3,35 |
| | Air Intake | 1 | EA | 5 | \$7,47 |
| | Air Intake | 1 | EA | 6 | \$5,76 |
| | Auxiliaries - 15001-20000 cfm | 1 | EA | 5 | \$ |
| | Fan Coil Unit- Celing Mounted - Dual Temperature Coil | 30 | EA | 6 | \$55,98 |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | 1 | EA | 5 | \$9,73 |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | 1 | EA | 5 | \$16,25 |
| | Zone Dampers | 13 | EA | 5 | \$24,87 |
| | Zone Dampers | 17 | EA | 6 | \$14,16 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP | 3 | EA | 6 | \$9,26 |
| | Chemical Pot Feeder | 1 | EA | 5 | \$1,68 |
| | Condensing- Hot Water Boiler - 1001 - 2000 MBH | 3 | EA | 6 | \$2,99 |
| | Glycol Feed System | 1 | EA | 6 | \$53 |
| | Piping - Dual Temperature Pipes- Galvanized | 1,200 | LF | 6 | \$2,26 |
| | Water Fill System | 1 | EA | 6 | \$1,16 |
| Heating Devices | | | | | |
| | Unit Heater - Electric | 2 | EA | 6 | \$55 |
| | Unit Heater - Hot Water | 2 | EA | 6 | \$55 |
| Mechanical Plumbing | | | | | |
| | Chilled Water Pump - Less than 10 | 2 | EA | 6 | \$2,22 |
| | Hot Water Pump - 10 - 20 HP | 3 | EA | 6 | \$3,72 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | 2 | EA | 6 | \$1,18 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,18 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 3 | EA | 6 | \$88 |
| Mechanical System | Cultural | | | | \$252,799 |

Building: Addition 3



Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|--|----------|------|------|-----------|
| Hot Water | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | 2 | EA | 6 | \$620 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 56,323 | SF | 6 | \$11,276 |
| | Domestic Piping-Cold Water Horizontal Lines | 56,323 | SF | 6 | \$13,692 |
| | Domestic Piping-Cold Water Risers | 56,323 | SF | 6 | \$10,470 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 56,323 | SF | 6 | \$8,860 |
| | Domestic Piping-Hot Water Horizontal Lines | 56,323 | SF | 6 | \$10,470 |
| | Domestic Piping-Hot Water Return Lines | 56,323 | SF | 6 | \$8,054 |
| | Domestic Piping-Hot Water Return Risers | 56,323 | SF | 6 | \$8,054 |
| | Sanitary Piping | 56,323 | SF | 6 | \$51,547 |
| | Storm Piping | 56,323 | SF | 6 | \$49,131 |
| | Vent Piping | 56,323 | SF | 6 | \$37,855 |
| Pumps | | | | | |
| | Pumps - Ejector-Duplex | 1 | EA | 6 | \$1,387 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |
| Plumbing Syst | tem Subtotal: | | | | \$212,161 |

Building: Addition 3

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|-----------------------------|----------|------|------|----------|
| Office (1 room) | | | | | |
| | Casework | 6 | LF | 6 | \$152 |
| | Ceiling - Lay-in | 897 | SF | 6 | \$2,694 |
| | Doors - Transom Window | 4 | SF | 6 | \$68 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 897 | SF | 6 | \$1,963 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Marker Board | 8 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 958 | SF | 6 | \$2,644 |
| Pre School (6 rooms) | | | | | |
| | Casework | 366 | LF | 6 | \$9,243 |
| | Ceiling - Lay-in | 7,287 | SF | 6 | \$21,883 |
| | Chalk Board | 60 | LF | 4 | \$5,508 |
| | Doors - Side-lite | 24 | SF | 6 | \$401 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |



Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|----------|
| Pre School (6 roo | oms) | | | | |
| | Floor - Tile/Sheet | 7,287 | SF | 6 | \$7,294 |
| | Lighting - Lay-in | 102 | EA | 7 | \$0 |
| | Marker Board | 72 | LF | 7 | \$0 |
| | Storage/ Closet | 216 | SF | 6 | \$1,566 |
| | Walls - Concrete Block | 5,510 | SF | 6 | \$16,153 |
| | Walls - Plaster/Drywall | 2,058 | SF | 6 | \$5,680 |
| | Work Sink | 12 | EA | 6 | \$4,548 |
| Regular Classroo | om (17 rooms) | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 947 | LF | 6 | \$23,915 |
| | Ceiling | 915 | | 6 | \$0 |
| | Ceiling - Lay-in | 13,719 | SF | 6 | \$41,198 |
| | Chalk Board | 124 | LF | 4 | \$11,384 |
| | Chalk Board | 12 | LF | 6 | \$268 |
| | Doors - Side-lite | 124 | SF | 6 | \$2,073 |
| | Doors - Transom Window | 4 | SF | 6 | \$68 |
| | Doors - Wood Doors inclu hw | 19 | EA | 6 | \$5,719 |
| | Floor - Tile | 8,255 | SF | 6 | \$18,061 |
| | Floor - Tile/Sheet | 6,379 | SF | 6 | \$6,385 |
| | Lighting - Lay-in | 162 | EA | 6 | \$19,274 |
| | Lighting - Lay-in | 24 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 12 | EA | 6 | \$1,487 |
| | Marker Board | 24 | LF | 6 | \$514 |
| | Marker Board | 180 | LF | 7 | \$0 |
| | Walls - Concrete Block | 10,702 | SF | 6 | \$31,373 |
| | Walls - Plaster/Drywall | 7,566 | SF | 6 | \$20,881 |
| | Work Sink | 15 | EA | 6 | \$5,685 |

Classrooms Subtotal:

Building: Addition 3

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|------------------|----------|------|------|---------|
| Administrative Suite | s/Offices | | | | |
| | Ceiling - Lay-in | 25 | SF | 5 | \$199 |
| | Ceiling - Lay-in | 1,617 | SF | 6 | \$4,856 |

\$270,684



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|-----------|
| Administrative Su | ites/Offices | | | | |
| | Doors - Side-lite | 4 | SF | 6 | \$67 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Floor - Carpet | 745 | SF | 6 | \$1,587 |
| | Floor - Tile | 872 | SF | 6 | \$1,908 |
| | Lighting - Lay-in | 18 | EA | 6 | \$2,142 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Power Distribution | 50 | EA | 6 | \$106,244 |
| | Storage/ Closet | 164 | SF | 6 | \$1,189 |
| | Walls - Concrete Block | 2,823 | SF | 6 | \$8,276 |
| | Walls - Plaster/Drywall | 546 | SF | 6 | \$1,507 |
| | Walls - Tile | 508 | SF | 6 | \$1,111 |
| | Work SInk | 1 | EA | 6 | \$508 |
| Library | | | | | |
| | Ceiling - Lay-in | 2,406 | SF | 6 | \$7,225 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Carpet | 2,406 | SF | 6 | \$5,126 |
| | Lighting - Lay-in | 34 | EA | 6 | \$4,045 |
| | Walls - Concrete Block | 2,406 | SF | 6 | \$7,053 |
| MDF_IDF | | | | | |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Finishes | 25 | SF | 6 | \$178 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Servi | ce Rooms | | | | |
| | Janitor's Closet | 76 | SF | 6 | \$544 |
| | Mechanical/ Service Rooms | 136 | SF | 6 | \$974 |
| | Storage Room | 147 | SF | 6 | \$1,053 |
| | Vaults | 155 | SF | 6 | \$1,110 |
| Restroom | | | | | |
| | Accessories | 1,840 | SF | 6 | \$16,971 |
| | Ceiling - Lay-in | 2 | SF | 5 | \$12 |
| | Ceiling - Lay-in | 82 | SF | 6 | \$247 |
| | Ceiling - Plaster/Drywall | 1,606 | SF | 6 | \$5,558 |
| | Doors - Steel Doors incl hw | 6 | EA | 6 | \$1,806 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Terrazzo | 1,801 | SF | 6 | \$3,940 |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|---------------------------------|----------|------|------|----------|
| Restroom | | | | | |
| | Floor - Tile | 39 | SF | 6 | \$85 |
| | Floor Drain | 22 | EA | 6 | \$23,301 |
| | Lavatory | 30 | EA | 6 | \$9,588 |
| | Lighting - Lay-in | 6 | EA | 6 | \$714 |
| | Lighting - Lay-in | 34 | EA | 7 | \$0 |
| | Partitions | 22 | EA | 6 | \$6,532 |
| | Urinals | 10 | EA | 6 | \$3,360 |
| | Walls - Tile | 192 | SF | 6 | \$420 |
| | Walls - Tile Ceramic/ Porcelain | 5,108 | SF | 6 | \$11,541 |
| | Water Closet | 32 | EA | 6 | \$10,751 |

Rooms (Other Than Classrooms) Subtotal:

Building: Addition 3

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 8,878 | SF | 6 | \$26,661 |
| | Doors - Side-lite | 42 | EA | 6 | \$702 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Transom Window | 12 | EA | 6 | \$203 |
| | Doors - Wood Doors include hw | 2 | EA | 6 | \$602 |
| | Drinking Fountains - Single Fountain | 6 | EA | 6 | \$1,654 |
| | Floor - Terrazzo | 8,878 | SF | 6 | \$74,523 |
| | Lighting - Lay-in | 30 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 23 | LF | 6 | \$213 |
| | Walls - Concrete Block | 18 | SF | 5 | \$254 |
| | Walls - Concrete Block | 11,262 | SF | 6 | \$33,015 |
| Safety | | | | | |
| | Security Cameras | 3 | EA | 6 | \$582 |
| Stairs | | | | | |
| | Ceiling - Lay-in | 780 | SF | 6 | \$2,342 |
| | Floor - Terrazzo | 680 | SF | 6 | \$5,708 |
| | Handrails | 448 | LF | 6 | \$3,882 |
| | Lighting - Lay-in | 15 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 224 | LF | 6 | \$2,079 |

\$258,102



Building: Addition 3

| Total Building Co | st | | | | \$1,716,771 |
|---------------------|---|----------|------|------|-------------|
| Building Interior S | Subtotal: | | | | \$182,391 |
| | Elevator - Elevator- Roped Holeless Hydraulic | 1 | EA | 6 | \$19,238 |
| Vertical Conveyance | | | | | |
| | Walls - Concrete Block | 3,456 | SF | 6 | \$10,131 |
| Stairs | | | | | |
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Category: Building | g Interior | | | | |

Building: Addition 4

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|-----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 6 | \$702 |
| | Exterior Doors - Exterior Steel Door | 5 | EA | 6 | \$2,403 |
| | Exterior Doors - Store Front | 8 | EA | 6 | \$4,369 |
| Foundation | | | | | |
| | Foundation - Concrete | 475 | LF | 7 | \$0 |
| | Superstructure - Metal Deck/ Concrete Topping | 17,483 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 3 | EA | 6 | \$866 |
| Roof System | | | | | |
| | Coping - Stone | 47 | LF | 6 | \$1,510 |
| | Coping - Stone | 500 | LF | 7 | \$0 |
| | Downspouts - Interior Downspouts | 30 | LF | 6 | \$997 |
| | Downspouts - Interior Downspouts | 270 | LF | 7 | \$0 |
| | Parapet - 16" - 30" Height | 500 | LF | 7 | \$0 |
| | Parapet - Parapet > 30" | 47 | LF | 7 | \$0 |
| | Roof - Modified Bitumen | 12,160 | SF | 6 | \$114,418 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 12,160 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Brick | 13,635 | SF | 6 | \$91,641 |
| | Exterior Walls - Precast Panel Wall | 1,500 | SF | 6 | \$10,082 |



Building: Addition 4

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------|-------------------------------------|----------|------|------|----------|
| Windows | | | | | |
| | Guard - Guards perforated | 900 | SF | 7 | \$0 |
| | Windows - Sash Aluminum Double-pane | 2,445 | SF | 6 | \$18,251 |

Building Exterior Subtotal:

Building: Addition 4

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|-------|------|----------|
| Emergency System | | Quantity | 0.110 | | 0001 |
| Linergeney eyeteni | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 3,140 | SF | 6 | \$943 |
| | Emergency A/C Power - Lunchrooms | 1,850 | SF | 6 | \$688 |
| | | | _ | | |
| | Emergency Battery Packs - Corridors and Stairs | 3 | EA | 6 | \$608 |
| | Exit Signs - Corridors and Stairs | 2 | EA | 2 | \$1,091 |
| | Exit Signs - Corridors and Stairs | 3 | EA | 6 | \$449 |
| | Security System - CCTV | 11,488 | SF | 6 | \$3,450 |
| | Security System - Intrusion Detection | 11,488 | SF | 6 | \$2,957 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | Main Electrical Service - 1200 A 120/208/3PH | 1 | EA | 6 | \$5,078 |
| | PA System | 17,483 | SF | 6 | \$5,750 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 6 | \$299 |
| | Lighting and Power Panels - Above 100 A | 7 | EA | 6 | \$3,479 |
| | Main Distribution Panels - 400 - 600 amp | 2 | EA | 6 | \$1,055 |
| | Transformers - 277/480 - 120/208 | 1 | EA | 6 | \$1,265 |
| Electrical System | Subtotal: | | | | \$30,441 |

Electrical System Subtotal:

Building: Addition 4

Category: Safty System

| | • | | | | |
|------------|--------------------------|----------|------|------|---------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 17,483 | SF | 6 | \$6,250 |
| | Fire Alarm_System | 17,483 | SF | 6 | \$8,500 |
| | | | | | |



| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------|----------------------|----------|------|------|----------|
| Sprinkler System | 1 | | | | |
| | Sprinkler Heads | 17,483 | SF | 7 | \$0 |
| | Sprinkler Piping | 17,483 | SF | 6 | \$3,250 |
| | Wet Sprinkler System | 17,483 | SF | 6 | \$4,500 |
| Safty System Subtotal: | | | | | \$22,501 |

Building: Addition 4

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|--|----------|------|------|----------|
| Air Handling Systems | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 15001- 20000 cfm | 1 | EA | 5 | \$64,830 |
| | Air Intake | 1 | EA | 6 | \$5,765 |
| | Zone Dampers | 10 | EA | 6 | \$8,330 |
| Heating Devices | | | | | |
| | Unit Heater - Electric | 2 | EA | 6 | \$556 |
| | Unit Heater - Hot Water | 1 | EA | 6 | \$279 |
| Temperature Control | | | | | |
| | Thermostats - DDC | 12 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | \$592 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 6 | \$1,248 |
| | Type II Exhaust Hood- Warming Kitchen | 1 | EA | 6 | \$920 |
| Mechanical Syster | n Subtotal: | | | | \$84,889 |

Building: Addition 4

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------|--|----------|------|------|---------|
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 17,483 | SF | 6 | \$3,500 |
| | Domestic Piping-Cold Water Horizontal Lines | 17,483 | SF | 6 | \$4,250 |
| | Domestic Piping-Cold Water Risers | 17,483 | SF | 6 | \$3,250 |



Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Hot Water from Risers to Fixtures | 17,483 | SF | 6 | \$2,750 |
| | Domestic Piping-Hot Water Horizontal Lines | 17,483 | SF | 6 | \$3,250 |
| | Domestic Piping-Hot Water Return Lines | 17,483 | SF | 6 | \$2,500 |
| | Domestic Piping-Hot Water Return Risers | 17,483 | SF | 6 | \$2,500 |
| | Sanitary Piping | 17,483 | SF | 6 | \$16,000 |
| | Storm Piping | 17,483 | SF | 6 | \$15,250 |
| | Vent Piping | 17,483 | SF | 6 | \$11,750 |
| Plumbing Sy | stem Subtotal: | | | | \$65,002 |

Plumbing System Subtotal:

Building: Addition 4

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|---------------------------------|----------|------|------|----------|
| Administrative Su | ites/Offices | | | | |
| | Ceiling - Lay-in | 493 | SF | 6 | \$1,480 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Concrete | 493 | SF | 6 | \$261 |
| | Lighting - Lay-in | 10 | EA | 6 | \$1,190 |
| | Power Distribution | 6 | EA | 6 | \$12,749 |
| | Walls | 1,137 | | 6 | \$0 |
| Gymnasia | | | | | |
| | Ceiling - Exposed | 4,913 | SF | 6 | \$7,307 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 4,913 | SF | 6 | \$4,918 |
| | Lighting - Pendent/Surface | 10 | EA | 6 | \$1,239 |
| | Storage/ Closet | 144 | SF | 6 | \$1,044 |
| | Walls - Tile | 8,941 | SF | 6 | \$19,562 |
| Kitchen | | | | | |
| | Ceiling - Lay-in | 981 | SF | 6 | \$2,946 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Floor - Concrete Epoxy/ Painted | 981 | SF | 6 | \$519 |
| | Lighting - Lay-in | 26 | EA | 6 | \$3,093 |
| | Serving Line | 48 | LF | 6 | \$2,857 |
| | Walls - Concrete Block | 2,316 | SF | 6 | \$6,789 |
| | | | | | |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|----------|------|------|----------|
| Mechanical/ Servic | ce Rooms | | | | |
| | Janitor's Closet | 38 | SF | 6 | \$272 |
| | Mechanical/ Service Rooms | 3,367 | SF | 6 | \$24,122 |
| | Storage Room | 90 | SF | 6 | \$645 |
| Restroom | | | | | |
| | Accessories | 640 | SF | 6 | \$5,903 |
| | Ceiling - Plaster/Drywall | 640 | SF | 6 | \$2,215 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Terrazzo | 576 | SF | 6 | \$1,260 |
| | Floor - Tile | 64 | SF | 6 | \$140 |
| | Floor Drain | 3 | EA | 6 | \$3,177 |
| | Lavatory | 9 | EA | 6 | \$2,876 |
| | Lighting - Lay-in | 10 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 7 | \$0 |
| | Partitions | 8 | EA | 6 | \$2,375 |
| | Urinals | 4 | EA | 6 | \$1,344 |
| | Walls - Plaster/Drywall | 256 | SF | 6 | \$707 |
| | Walls - Tile | 1,080 | SF | 6 | \$2,363 |
| | Water Closet | 9 | EA | 6 | \$3,024 |

Rooms (Other Than Classrooms) Subtotal:

Building: Addition 4

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 1,550 | SF | 6 | \$4,655 |
| | Doors - Steel Doors incl hw | 8 | EA | 6 | \$2,408 |
| | Doors - Wood Doors include hw | 4 | EA | 6 | \$1,204 |
| | Drinking Fountains - Single Fountain | 1 | EA | 6 | \$276 |
| | Floor - Terrazzo | 1,550 | SF | 6 | \$13,011 |
| | Lighting - Lay-in | 57 | EA | 6 | \$6,782 |
| | Walls - Concrete Block | 3,405 | SF | 6 | \$9,982 |
| | Walls - Plaster/Drywall | 850 | SF | 6 | \$3,768 |
| Safety | | | | | |
| | Security Cameras | 2 | EA | 6 | \$388 |

\$119,087



Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|----------------------------|----------|------|------|----------|
| Stairs | | | | | |
| | Ceiling - Exposed | 220 | SF | 6 | \$327 |
| | Floor - Concrete | 220 | SF | 6 | \$116 |
| | Handrails | 80 | LF | 6 | \$693 |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Stairs | 39 | LF | 6 | \$0 |
| | Walls - Concrete Block | 595 | SF | 6 | \$1,744 |
| Building Inte | erior Subtotal: | | | | \$45,478 |

Total Building Cost

SITE

Category: Site

| Cost | Rank | Unit | Quantity | Item - Type | Group |
|----------|------|------|----------|-----------------------------------|----------------|
| | | | | | Athletic |
| \$10,813 | 6 | EA | 3 | Lighting | |
| \$0 | 7 | SF | 12,540 | Surface - Synthetic | |
| | | | | | Civil/Drainage |
| \$0 | 7 | EA | 17 | Civil/ Drainage - Catch Basin | |
| | | | | | Fencing |
| \$37,780 | 6 | LF | 1,030 | Fencing - Iron and Concrete Post | |
| \$37,878 | 5 | LF | 266 | Fencing - New Standard Ornamental | |
| \$17,674 | 6 | LF | 554 | Fencing - New Standard Ornamental | |
| | | | | | Landscape |
| \$3,440 | 6 | EA | 8 | Benches | |
| \$249 | 6 | SF | 300 | Landscape - Grass | |
| \$0 | 7 | SF | 28,228 | Landscape - Grass | |
| \$0 | 7 | EA | 38 | Parkway trees | |
| \$33,604 | 6 | SF | 13,905 | Play Area - Asphalt/ Hardscape | |
| \$0 | 7 | EA | 3 | Trash Receptacles | |
| | | | | | Parking Lot |
| \$0 | 7 | LF | 895 | Concrete Curbs | |
| \$5,956 | 6 | LF | 140 | Interior Plantings | |
| \$50,751 | 6 | SF | 21,000 | Surface - Asphalt | |
| | 6 | LF | 140 | Interior Plantings | Parking Lot |

\$612,634



SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---|----------|------|------|-----------|
| Parking Lot | | | | | |
| | Vehicular Screening | 280 | LF | 7 | \$0 |
| Playground | | | | | |
| | Equipment - School Age 5-12 | 1 | EA | 7 | \$0 |
| | Surface - Poured Surface | 1,980 | SF | 7 | \$0 |
| | Surface - Square Rubber Mats | 12,540 | SF | 7 | \$0 |
| Service Garage | | | | | |
| | Service Garage - Free-Standing | 188 | SF | 6 | \$1,726 |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 25 | LF | 5 | \$1,444 |
| | Sidewalks - Internal Walks | 300 | LF | 6 | \$3,604 |
| | Sidewalks - Perimeter Sidewalks | 1,100 | SF | 5 | \$10,508 |
| | Sidewalks - Perimeter Sidewalks | 12,000 | SF | 6 | \$23,852 |
| Signage | | | | | |
| | Flag Pole - Flag Pole | 1 | EA | 7 | \$0 |
| | Marquee - Free Standing Back Lighted | 1 | EA | 7 | \$0 |
| | Monument - Building Mounted Cut Letter Sign | 1 | EA | 7 | \$0 |
| Site Subtotal: | | | | | \$239,279 |
| Total Site Cost | | | | | \$239,279 |

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

\$6,116,172



- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|--|--|---|--|---|--|--|---|--|---|--|---|--|---|--|
| Main | | - F | - | | | ļ | 1 | II | | I | - | 11 | | |
| Computer Lab | Regular Classroom | 1st Floor | 103 | 103 | 880 | 2 | 36 | 115 | 55 | 51 | 40 | Y | Ν | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 104 | 104 | 892 | 2 | 3 | 32 | 124 | 77 | 40 | Y | Ν | N |
| Kindergarten | Regular Classroom | 1st Floor | 108 | 108 | 888 | 2 | 3 | 32 | 82 | 77 | 40 | Y | Ν | Ν |
| Kindergarten | Regular Classroom | 3rd Floor | 308 | 308 | 920 | 2 | 3 | 32 | 82 | 77 | 40 | Y | Ν | Ν |
| Regular Classroom | Store Room | Basement | 004A | store room | 491 | 1 | 8 | 24 | 34 | 32 | 40 | Y | Ν | Ν |
| Regular Classroom | Lunch Room | Basement | 012 | B-8 | 1,105 | 1 | 10 | 40 | 62 | 58 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 861 | 1 | 2 | 39 | 55 | 51 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 870 | 2 | 3 | 38 | 55 | 51 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 892 | 2 | 3 | 32 | 124 | 77 | 40 | Y | Ν | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 868 | 2 | 3 | 38 | 55 | 51 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 888 | 2 | 3 | 32 | 82 | 77 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 380 | 2 | 4 | 38 | 55 | 51 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 904 | 2 | 3 | 32 | 124 | 77 | 40 | Y | Ν | Ν |
| Descular Olesses | Regular Classroom | 3rd Floor | 306 | 306 | 524 | 1 | 2 | 34 | 55 | 51 | 40 | Y | Y | Ν |
| Regular Classroom | rtogalar Olaboroolli | | | | | | - | 00 | | = 4 | 40 | Y | Ν | Ν |
| Regular Classroom Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 877 | 2 | 3 | 38 | 55 | 51 | 40 | Y | IN | IN |
| , , , , , , , , , , , , , , , , , , , | 0 | 3rd Floor Basement | 307 004B | 307 004B | 877 152 | 2 0 | 3 1 | 38 6 | 55 42 | 51 18 | 40 40 | Y Y | Y | N |
| Regular Classroom Special Education Addition 1 | Regular Classroom Store Room | | | | | | | | | | | - | | |
| Regular Classroom Special Education Addition 1 Art Room | Regular Classroom Store Room Art Room | Basement | 004B 010 | 004B B-10 | 152 | 0 | 1 | 6 | 42 | 18 84 | 40 | Y | Y | N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten | Regular Classroom Store Room | Basement Basement Basement | 004B | 004B | 152 1,181 702 | 0 | 1 | 6 20 | 42 89 | 18 | 40 | Y | Y | N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room | Basement | 004B 010 011 | 004B B-10 boys play room | 152 | 0 1 0 | 1 1 0 | 6 20 6 | 42 89 27 | 18 84 25 | 40 40 40 | Y Y N | Y N N | N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement Basement | 004B 010 011 007 | 004B B-10 boys play room B2 | 152 1,181 702 1,141 | 0 1 0 1 2 | 1 1 0 3 | 6 20 6 20 | 42 89 27 100 | 18 84 25 87 | 40 40 40 40 | Y Y N Y | Y N N N | N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room | Basement Basement Basement 1st Floor | 004B 010 011 007 109 | 004B B-10 boys play room B2 109 | 152 1,181 702 1,141 937 | 0 1 0 1 | 1 1 0 3 6 | 6 20 6 20 40 | 42 89 27 100 68 | 18 84 25 87 64 | 40 40 40 40 40 40 | Y Y N Y Y | Y N N N | N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom Regular Classroom | Basement Basement Basement 1st Floor 1st Floor | 004B 010 011 007 109 110 | 004B B-10 boys play room B2 109 110 | 152 1,181 702 1,141 937 935 | 0 1 0 1 2 2 | 1 1 0 3 6 4 | 6 20 6 20 40 40 | 42 89 27 100 68 110 | 18 84 25 87 64 103 | 40 40 40 40 40 40 40 | Y N Y Y Y | Y N N N N | N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Basement Basement Basement 1st Floor 1st Floor 2nd Floor | 004B 010 011 007 109 110 201 | 004B B-10 boys play room B2 109 110 201 | 152 1,181 702 1,141 937 935 930 | 0 1 0 1 2 2 2 2 | 1 1 0 3 6 4 4 4 | 6 20 6 20 40 40 41 | 42 89 27 100 68 110 110 | 18 84 25 87 64 103 103 | 40 40 40 40 40 40 40 40 | Y N Y Y Y Y | Y N N N N N | N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor | 004B 010 011 007 109 110 201 202 | 004B B-10 boys play room B2 109 110 201 202 | 152 1,181 702 1,141 937 935 930 935 | 0 1 0 1 2 2 2 3 | 1 1 0 3 6 4 4 4 4 | 6 20 6 20 40 40 41 38 | 42 89 27 100 68 110 110 110 | 18 84 25 87 64 103 103 103 | 40 40 40 40 40 40 40 40 40 | Y N Y Y Y Y Y | Y N N N N N N | N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor | 004B 010 011 007 109 110 201 202 209 | 004B B-10 boys play room B2 109 110 201 202 209 | 152 1,181 702 1,141 937 935 930 935 937 | 0 1 0 1 2 2 2 3 2 3 2 | 1 0 3 6 4 4 4 6 | 6 20 6 20 40 40 41 38 40 | 42 89 27 100 68 110 110 110 68 | 18 84 25 87 64 103 103 103 64 | 40 40 40 40 40 40 40 40 40 40 40 | Y N Y Y Y Y Y Y Y | Y N N N N N N N | N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor | 004B 010 011 007 109 110 201 202 209 210 | 004B B-10 boys play room B2 109 110 201 202 209 210 | 152 1,181 702 1,141 937 935 930 935 937 935 | 0 1 0 1 2 2 2 2 3 2 2 2 2 | 1 0 3 6 4 4 4 4 6 4 | 6 20 6 20 40 40 41 38 40 40 | 42 89 27 100 68 110 110 110 68 110 | 18 84 25 87 64 103 103 103 64 103 | 40 40 40 40 40 40 40 40 40 40 40 40 | Y N Y Y Y Y Y Y Y Y | Y N N N N N N N N | N N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor | 004B 010 011 007 109 110 201 202 209 210 309 | 004B B-10 boys play room B2 109 110 201 202 209 210 309 | 152 1,181 702 1,141 937 935 930 935 937 935 937 935 929 | 0 1 0 1 2 2 2 3 2 2 2 2 2 2 2 2 | 1 0 3 6 4 4 4 4 6 4 6 | 6 20 6 20 40 40 41 38 40 40 22 | 42 89 27 100 68 110 110 110 68 110 68 110 68 | 18 84 25 87 64 103 103 103 64 103 64 | 40 40 40 40 40 40 40 40 40 40 40 40 | Y N Y Y Y Y Y Y Y Y | Y N N N N N N N N N | N N N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor | 004B 010 011 007 109 110 201 202 209 210 309 | 004B B-10 boys play room B2 109 110 201 202 209 210 309 | 152 1,181 702 1,141 937 935 930 935 937 935 937 935 929 | 0 1 0 1 2 2 2 3 2 2 2 2 2 2 2 2 | 1 0 3 6 4 4 4 4 6 4 6 | 6 20 6 20 40 40 41 38 40 40 22 | 42 89 27 100 68 110 110 110 68 110 68 110 68 | 18 84 25 87 64 103 103 103 64 103 64 | 40 40 40 40 40 40 40 40 40 40 40 40 | Y N Y Y Y Y Y Y Y Y | Y N N N N N N N N N | N N N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom Library | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor | 004B 010 011 007 109 110 201 202 209 210 309 310 | 004B B-10 boys play room B2 109 110 201 202 209 210 309 310 | 152 1,181 702 1,141 937 935 930 935 937 935 937 935 929 942 | 0 1 0 1 2 2 2 3 2 2 2 2 2 2 2 2 | 1 1 0 3 6 4 4 4 6 4 6 4 6 4 | 6 20 6 20 40 40 41 38 40 40 22 16 | 42 89 27 100 68 110 110 68 110 68 110 68 110 | 18 84 25 87 64 103 103 64 103 64 103 64 103 64 103 64 103 64 103 | 40 40 40 40 40 40 40 40 40 40 40 40 40 4 | Y N Y Y Y Y Y Y Y Y | Y N N N N N N N N N N | N N N N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom Library | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 1st Floor | 004B 010 011 007 109 110 201 202 209 210 309 310 101 | 004B B-10 boys play room B2 109 110 201 202 209 210 309 310 | 152 1,181 702 1,141 937 935 930 935 937 935 929 942 942 935 | 0 1 0 1 2 2 2 3 2 2 2 2 2 2 2 2 3 3 3 3 | 1 1 0 3 6 4 4 4 6 4 6 4 4 4 4 4 | 6 20 6 20 40 40 41 38 40 40 22 16 38 | 42 89 27 100 68 110 110 68 110 68 110 68 110 110 | 18 84 25 87 64 103 103 64 103 64 103 64 103 | 40 40 40 40 40 40 40 40 40 40 40 40 40 4 | Y N Y Y Y Y Y Y Y Y Y | Y N N N N N N N N N N N N N N N N N N N | N N N N N N N N N N N N |
| Regular Classroom Special Education Addition 1 Art Room Kindergarten Regular Classroom Regular Classroom | Regular Classroom Store Room Art Room Play Room Lunch Room Regular Classroom Kegular Classroom Kegular Classroom Kibrary | Basement Basement Basement Basement 1st Floor 1st Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 1st Floor | 004B 010 011 007 109 110 201 202 209 210 309 310 310 | 004B B-10 boys play room B2 109 110 201 202 209 210 309 310 310 | 152 1,181 702 1,141 937 935 930 935 937 935 929 942 942 935 935 935 | 0 1 0 1 2 2 2 3 2 2 2 2 2 3 3 3 3 | 1 0 3 6 4 4 4 4 6 4 6 4 6 4 4 4 4 | 6 20 6 20 40 40 41 38 40 40 22 16 38 38 38 | 42 89 27 100 68 110 110 68 110 68 110 68 110 110 110 110 | 18 84 25 87 64 103 103 64 103 64 103 64 103 64 103 64 103 64 103 103 | 40 40 40 40 40 40 40 40 40 40 40 40 40 4 | Y N Y Y Y Y Y Y Y Y Y Y | Y N N N N N N N N N N N N N N N N N N N | N N N N N N N N N N N N N N |



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Addition 3 | + | | + | | | | | • • • | | | -! | | | |
| Office | Regular Classroom | 3rd Floor | 316 | 3-06 | 897 | 1 | 8 | 20 | 112 | 110 | 40 | Ν | Ν | Ν |
| Pre School | Pre School | 1st Floor | 119 | 1-09 | 1,193 | 1 | 9 | 22 | 151 | 135 | 40 | Y | Ν | Ν |
| Pre School | Pre School | 1st Floor | 120 | 1-12 | 1,238 | 1 | 9 | 22 | 145 | 135 | 132 | Y | N | Ν |
| Pre School | Pre School | 1st Floor | 121 | 1-15 | 1,210 | 1 | 9 | 22 | 151 | 135 | 40 | Y | Ν | Ν |
| Pre School | Pre School | 1st Floor | 122 | 1-21 | 1,208 | 1 | 9 | 22 | 151 | 135 | 40 | Y | N | Ν |
| Pre School | Pre School | 1st Floor | 123 | 1-24 | 1,238 | 1 | 9 | 22 | 145 | 135 | 132 | Y | N | Ν |
| Pre School | Pre School | 1st Floor | 124 | 1-27 | 1,200 | 1 | 9 | 22 | 151 | 135 | 40 | Y | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 2-08 | 889 | 1 | 8 | 20 | 112 | 101 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 2-09 | 893 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 3-10 | 892 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 3-11 | 910 | 1 | 8 | 20 | 100 | 87 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 221 | 2-13 | 376 | 1 | 8 | 12 | 55 | 50 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | 2-14 | 915 | 1 | 8 | 20 | 100 | 87 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 223 | 2-15 | 896 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 224 | 2-16 | 893 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 317 | 3-07 | 897 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 318 | 3-08 | 908 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | 3-09 | 895 | 1 | 8 | 20 | 112 | 101 | 40 | Y | N | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 3-13 | 915 | 1 | 8 | 20 | 100 | 87 | 40 | Y | N | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 3-14 | 893 | 1 | 8 | 20 | 112 | 101 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | 3-15 | 895 | 1 | 8 | 20 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 325 | 3-16 | 894 | 1 | 8 | 20 | 112 | 101 | 40 | Y | N | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 326 | 3-18 | 979 | 0 | 6 | 18 | 112 | 101 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 327 | 3-19 | 694 | 0 | 1 | 12 | 84 | 79 | 40 | Y | Ν | Ν |