Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

24311

Oracle Unit:

Address: 1420 N. Hudson Avenue Region: 02 Mail Room: 33 Asbestos Surveyor: Garner, Mark X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: puppiesfrommark@aol. com A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Rooms 214-218, 219, X NO YES 221, 119 & Storage, 116-9"x9" Tan w/ Brown and 01 4500 SF 115. 1st & 2nd Fl Cor. Miscellaneous No None 0 Green Streaks Floor Tile 2nd FI Men's and Women's Toilets - 1961 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

George Manierre Elementary School

School:

Oracle Unit: 24311

4580

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	9"x9" Tan w/ Brown and Green Streaks Floor Tile Mastic	4500	SF	Rooms 214-218, 219, 221, 119 & Storage, 116- 115, 1st & 2nd FI Cor, 2nd FI Men's and Women's Toilets - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Tan w/ Beige Streaks Floor Tile	3100	SF	Rooms 201, 202, 203, 204, 205, 102, 104, 101, 103, 1st FI Teachers Restroom - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 Caring Ala Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Tan w/ Beige Streaks Floor Tile Mastic	3100	SF	Rooms 201, 202, 203, 204, 205, 102, 104, 101, 103, 1st FI Teachers Restroom - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

07 12"x12" Royal Blue w/ Light Blue Speckles Floor Tile 2200 SF 1st & 2nd Fl Corridor, Main Office & Storage - 1946 Miscellaneous No None 0 YES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1,7,7	07		2200	SF			Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Royal Blue w/ Lt Blue Speckles Floor Tile Mastic	2200	SF	1st & 2nd Fl Corridor, Main Office & Storage - 1946		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	1'x1' Cream Ceiling Tile	14975	SF	1st & 2nd Fl Corridors, 214, 215, 217, 216, 218, 219, 221, 118, 116, 119, 117, 115, 114, Lchrm '61		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 24311

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cat	egory
9M	1'x1' Cream Ceiling Tile (Mastic Glue Pucks)	14975	SF	1st and 2nd Floor Corridor, 214, 215, 216, 217, 218, 219, 221, 114, 115, 116, 117, 118, 119, Lunchroom - 1961 Addition		Surface	No	None	0		YES X NO	ı

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	Hard Coat Plaster	20000	SF	Throughout 1951		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
	N. 01											
2017 - Spring	g: No Change				_							
Comments:					4							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:	-											
2018 - Fall: N	lo Change				+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Hard Coat Plaster	20000	SF	Throughout 1946		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No Ma	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 1 /	"x9" Brown w/ Beige treak Floor Tile	1850	SF	1st & 2nd Fl Corridor, 115 Entrance - 1961, Room 203 - 1951 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Brown w/ Beige Streak Floor Tile Mastic	1850	SF	1st & 2nd Fl Corridor, 115 Entrance - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Peach w/ White, Blue, & Brown Streaks Floor Tile	6270	SF	214, 215, 217, 219, 221, 218, 216, 119, 116, 2nd FI Teach. Rest Rm & Toilet - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Peach w/ White, BI, & Brn Streaks Floor Tile Mastic	6270	SF	214, 215, 217, 219, 221, 218, 216, 119, 116, 2nd FI Teach. Rest Rm & Toilet - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

16	12"x12" Off White w/ Brown & White Streaks Floor Tile	1150	SF	116, 119, 1st FI Corridor By 117 & 119 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comment												
2017 - Spi	ring: No Change											
Comment												
2017 - Fal	I: No Change											
Comment	s:											
2018 - Sp	ring : No Change											
Comment	s:											
2018 - Fal	I: No Change											
Comment	s:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

11/11/0	Material Becompiler	Quantity	Units	Waterial Location	Туре	Category	1 Habit	Type	Quantity	Units	Gridings in 710000	omoni Galogory
17	12"x12" Off White w/ Brn & White Strks Floor Tile Mastic	1150	SF	116, 119, 1st Fl Corridor By 117 & 119 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	a. No Change											

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2018 - Fall: No Change Comments: Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Coffee w/ Brown & White Specks Floor Tile	310	SF	Rooms 117(Abated 2010), Lunch Room Office - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Coffee w/ Brown & White Specks Floor Tile Mastic	310	SF	Rooms 117(Abated 2010), Lunch Room Office - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Tan w/ White Specks Floor Tile	806	SF	Rm 116 - 1961 Storage 117		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Tan w/ White Specks Floor Tile Mastic	806	SF	Rm 116 - 1961 Storage 117		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige w/ Gray Specks Floor Tile	140	SF	1st Floor Women's Toilet - 1961 Room 101, 201 - 1951 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige w/ Gray Specks Floor Tile Mastic	80	SF	1st Floor Women's Toilet -1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Tan w/ White & Brown Speckles Floor Tile	2500	SF	Lunchroom- 1961 Lunchroom Office		Miscellaneous	No	None	0		YES X NO
004C Fall N	- Oh										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Tan w/ White & Brown Speckles Floor Tile Mastic	2500	SF	Lunchroom -1961 Lunchroom Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Gray w/ Black & Beige Streaks Floor Tile	2750	SF	104, 102, 103, 101, 204, 203, 202, 202 Closet, 201, 1st FI Teachers Restroom - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 5 11 N O	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Gray w/ Black & Beige Streaks Floor Tile Mastic	2750	SF	104, 102, 103, 101, 204, 203, 202, 202 Closet, 201, 1st FI Teachers Restroom - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
28	12"x12" Royal Blue w/ Light Blue Floor Tile	1300	SF	1st Fl Corridor - 1951		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	Ü											
2017 - Spring	: No Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change				1							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Royal Blue w/ Light Blue Floor Tile Mastic	1300	SF	1st Fl Corridor - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
39	12" x 12" Light Blue Floor Tile	800	SF	2nd Floor Corridor - 1946		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
•	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Light Blue Floor Tile Mastic	800	SF	2nd Floor Corridor - 1946		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	12" x 12" Light Blue Floor Tile	800	SF	2nd Floor Corridor - 1951		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
	2017 - Spring: No Change											
Comments	:											
	No Change											
Comments	•											

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Light Blue Floor Tile Mastic	800	SF	2nd Floor Corridor - 1951		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12x12 Cream with Brown Specks Floor Tile	1000	SF	Room 118		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12x12 Cream with Brown Specks Floor Tile Mastic	1000	SF	Room 118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
45	Steel Blue Carpet Mastic	1800	SF	Room 114 (Library) and Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												
2017 - Sprir Comments:	ng: No Change				-							
2045 5 11					-							

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
46	Hard Coat Plaster	25000	SF	Throughout 1961 Addition		Surface	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Black Spray-On Under Sink Coating	20	SF	115,116,119 - 1st Floor 215 - 2nd Floor		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Yellow Mastic (Multi- Colored Red, Blue, Green Carpet)	3000	SF	114 Library, 117, 1961 Bldg Addition		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
49	White Duct Insulation	600	SF	Attic Crawlspace Above Corridor and Room 214		TSI	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	: No Change											
Comments:												

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	1'x1' Sculpted White Ceiling Tile	10000	SF	Throughout Corridors, Classrooms, and Offices - 1946 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50M	1'x1' White Sculpted Ceiling Tile (Mastic Glue Pucks)	10000	SF	Throughout Corridors, Classrooms, and Office - 1946 Building		Miscellaneous	Yes	None	0		YES	X NO
0046 Fall N	- Oh	•	•	•	7	•	•	-	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	1'x1' White Sculpted Ceiling Tile	5000	SF	Throughout Corridors, Classrooms, and Offices - 1951 Bldg. Addition		Miscellaneous	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51M	1'x1' White Sculpted Ceiling Tile (Mastic Glue Pucks)	5000	SF	Throughout Corridors, Classrooms, and Offices - 1951 Building Addition		Miscellaneous	Yes	None	0		YES X NO
				•			•			•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12x12 White w/ Black & Blue Streaks VFT 1961 BLDG	900	SF	Room 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12x12 White W/black & Blue streaks Mastic 1961 BLDG	900	SF	Room 214		Miscellaneous	No	None	0		YES X NO
		•			ī	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12x12 White W/ Black & Blue VFT 1951 BLDG	400	SF	room 133		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12x12 White W/ Black & Blue Mastic 1951 BLDG	400	SF	Room 133		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Geo	orge Manierre Elementary School
Date: 1/9/2	2019
	
the Asbestos M	you in accordance with Illinois and Federal Asbestos Regulations, that a copy of lanagement Plan is available at each school during school hours by appointment. view the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspec	advised that CPS conducts asbestos inspections of all Schools every three years. tion was completed in 2016. eillances are conducted every six months.
CHECK ONE	
A copy o	f this notice was sent home in each child's backpack.
X A copy o	f this notice was printed in the school's newsletter and sent home with each child
A copy o	f this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY OF	THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 24311 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.