Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Edgar Allan Poe Elementary Classical School 29261 5460 School: **Oracle Unit: Building ID:** Address: 10538 S Langley Avenue Region: 06 Mail Room: Asbestos Surveyor: Agate, Joseph X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/7/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type Room 202. Teachers 9"x9" Beige w/Brown YES X NO Lounge, Tank Room 04 Streaks Floor Tile(Not 1600 SF Miscellaneous No None 0 Storage, Principal's Office Observed) (under the carpet) 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
05	12"x12" Green Floor Tile (NOT OBSERVED)			Teacher's Lounge		Miscellaneous	None	0		YES	X NO
2016 - Fall: I	Vo Change				1						
Comments:	10 Chango										
2017 - Sprin Comments:	g: No Change				<u>-</u>						
Comments.					1						
2017 - Fall: I	No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	-										
2018 - Sprin	g : No Change										
Comments:		•	•								

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	12"x12" Gray w/White Specks Floor Tile	1100	SF	3rd Floor Corridor, Rooms 201		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05B	12"x12" Beige Speckled Floor Tile	4300	SF	Rooms 102, 103, 204, 205, 305, Library, MDF RM, and Teacher's Lounge		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	o Chongo]						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2047 5 11 N O	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
0040 5 11 N 01	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	12"x12" Light Grey w/Brown & White Specks Floor Tile	14	SF	3rd Floor Under Water Fountain		Miscellaneous	No	None	0		YES X NO

•	•	
		·
		·
	•	
	•	
	•	
		·
	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05D	12"x12" Cream w/Caramel Specks Floor Tile	3130	SF	Gym Office, and Rooms 001. 201 (under existing flooring), 301		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05E	12"x12" Light Beige w/Dark Brown Streaks Floor Tile under carpet (NOT OBSERVED)	124	SF	Room 302		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

05F	12"x12" Light Gray w/White Blotches Floor Tile	940	SF	Room 101and 3rd Floor Janitor's Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	J]							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
06	Cream Colored Linoleum	1500	SF	Gym 3rd Floor		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage Quantity Change in Assessment Category

Material Location

Room 101and 3rd Floor

HA No

2016 - Fall: No Change

Comments:

Material Description

12"x12" Light Gray w/White

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	9"x9" Beige w/Brown Streaks Floor Tile Mastic (Not Observed)	1600	SF	Room 202, Tan Room Storage, Principal's Office (under the carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	•	•	•]	•	•	•	•	•		
Comments	S:				1							
2017 - Spr	ing: No Change				-							
Comments	S:											
2017 - Fall	: No Change				-							
Comments	S:											
2018 - Spr	ing : No Change				-							
Comments	S:				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Green Floor Tile Mastic (NOT OBSERVED)			Teachers Lounge		Miscellaneous			0		YES X NO

2018 - Fall: No Change

Comments:

Page 6

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
08A	12"x12" Gray w/White Specks Floor Tile Mastic	1100	SF	3rd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	12"x12" Beige Speckled Floor Tile Mastic	4300	SF	Rooms 102, 103, 203, 204, 205, 305, Library, and Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	12"x12" Light Grey w/Brown & White Specks Floor Tile Mastic	14	SF	3rd Floor Under Water Fountain		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	•	1	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08D	12"x12" Cream w/Caramel Specks Floor Tile Mastic	3130	SF	Gym Office, and Rooms 001. 201 (under existing flooring), and 301		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08E	12"x12" Light Beige w/Dark Brown Streaks Floor Tile (NOT OBSERVED)	124	SF	Room 302		Miscellaneous	No	None	0		YES X NO
	•	•	•	-	·	•	•	•	•	·	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08F	12"x12" Light Gray w/White Blotches Floor Tile Mastic	940	SF	Room 101		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	Cream Colored Linoleum Mastic	1500	SF	Gym 3rd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Spri	ing: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	S:											
2018 - Spri	ring : No Change											
Comments	S:			·								
2018 - Fall	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Drywall (NOT OBSERVED)	16500	SF	1, 2, 3rd Floors		Miscellaneous			0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Insulation in Fire Rated Doors	3	EA	Playrooms & Tank Rooms		TSI	No	None	0		YES X NO
2016 - Fall: No Change											

2040 5 11 11 01
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Boiler Door Insulation (Abated 2006)			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	Transite (Abated 2006)			Incinerator		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
	j : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Marlite (NOT OBSERVED)	185	SF	1st Floor Center Restrooms		Miscellaneous		None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Lab Tops- REMOVED			Room 305							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
	g: No Change				_							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:					_							
	g : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Drywall Compound (NOT OBSERVED)			1st, 2nd, 3rd Floors		Miscellaneous			0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 13

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	Carpet Mastic Brown	1350	SF	Main Office, Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring Comments:	g: No Change											

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

Comments.

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Brown Vinyl Baseboard	220	LF	Throughout Basement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
19	Brown Baseboard Mastic	220	LF	Throughout Basement		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					_							
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2018 - Sprin	g : No Change				1							
Comments:												
2018 - Fall:	No Change				1							
Comments:	<u> </u>				1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Interior Window Caulking	5000	LF	1st, 2nd, 3rd Floors and Basement		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	Carpet Mastic Brown	124	SF	Room 302		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	; No Change				-							
Comments:	_											
2018 - Fall: N	lo Change				-							
Comments:]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12 x 12 White/Grey Specs Floor Tile	640	SF	3rd Floor Girls Restroom, 2nd Floor Boys Restroom, and 1st Floor Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22M	12 x 12 White/Grey Specs Floor Tile Mastic	640	SF	3rd Floor Girls Restroom, 2nd Floor Boys Restroom, and 1st Floor Main Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Brown Speckled Terrazzo	400	SF	Kindergarden Restroom, North, South and East Entrances		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

24	1 x 1 Ceiling Tile	520	SF	Principal's Office		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:					 -							
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Yes

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Basement Boys

Restroom

308

HA No

25

Material Description

Aqua Green Ceramic Tile

Material

Quantity

Material

Units

SF

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Aqua Green Ceramic Tile Adhesive	308	SF	Basement Boys Restroom		Miscellaneous	No	None	0		YES X NO

			<u> </u>
2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
		·	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12 x 12 Gold with Brown Speckles Floor Tile	324	SF	Basement and Womens Restrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27M	12 x 12 Gold with Brown Speckles Floor Tile Mastic	324	SF	Basement Womens Restrooms		Miscellaneous	No	None	0		YES X NO
204C Fall N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Ÿ
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28	Grey Ceramic Tile Grout	308	SF	Basement Girls Restroom		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Grey Ceramic Tile Adhesive	308	SF	Basement Girls Restroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12x12 cream floor tile VFT	4800	SF	1st, 2nd, and 3rd floor elevator lobby, stage lobby, 1st, 2nd, and 3rd floor toilets, Room 204 storage, Room 103 storage, Room 201, 203, 303, Basement Men's and Unisex Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change	
2017 - Fall: No Change	016 - Fall: No Change
	Comments:
Commental	017 - Fall: No Change
Comments.	Comments:
2017 - Spring: No Change	017 - Spring: No Change
Comments:	Comments:
2018 - Spring : No Change	018 - Spring : No Change
Comments:	Comments:
2018 - Fall: No Change	018 - Fall: No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12x12 Cream Floor Tile VFT(Mastic)	4000	SF	1st, 2nd, and 3rd floor elevator lobby, stage lobby, 1st, 2nd, and 3rd floor toilets, Room 204 storage, Room 103 storage, Room 201, 203, 303, Basement Men's and Unisex Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	Gray Linoleum	200	SF	Room 001 (Music Room)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments	3:											
2017 - Fall	I: No Change											
Comments	S:]							
2017 - Spr	ing: No Change				-							
Comments	·				1							
2018 - Spr	ring : No Change				-							
Comments	<u> </u>				1							
2018 - Fall	I: No Change				1							
Comments]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Gray Linoleum (Mastic)	200	SF	Room 001 (Music Room)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
34	Spray on Fire-Proofing	1000	SF	Attic on Beams supporting fan unit		Surface	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Wood pattern linoleum Flooring laminate	1500	SF	Gym		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

36	Wood Pattern Linoleum Flooring Mastic	1500	SF	Gym		Miscellaneous	No	None	0	YES	X NO
2016 Fall N	o Changa				1						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	<u> </u>										
1011101											
<u> </u>					<u>.</u> II						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Tank Insulation - ABATED			Tank Room		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
В	Aircell Pipe Insulation	350	LF	Kindergarten & Basement Hallway Near Music Room, Storage Room 004		Miscellaneous	Yes	Loc	12		YES	X NO
2016 - Fall	I: No Change]							
Comments	<u> </u>											
2017 - Spr	ring: No Change											
Comments												
2017 - Fall	I: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:]							
2018 - Fall	I: No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation (NOT OBSERVED)			not observed		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Throughout Basement and 1st Floor South Stairs, Pipe chase in Room 305 and 205, Main office storage rooms, and Music Room		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall	I: No Change]									

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Plaster	40000	SF	Throughout School		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	ar Allan Poe Elementary Classical School
Date: 1/7/20	<u>19</u>
the Asbestos Ma	rou in accordance with Illinois and Federal Asbestos Regulations, that a copy of inagement Plan is available at each school during school hours by appointment. ew the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspection	dvised that CPS conducts asbestos inspections of all Schools every three years. on was completed in 2016. lances are conducted every six months.
CHECK ONE	
A copy of t	this notice was sent home in each child's backpack.
A copy of t	this notice was printed in the school's newsletter and sent home with each child
A copy of t	this notice was printed in the school's calendar and sent home with each child
Other.	
	THIS NOTICE MUST BE PLACED IN THE S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.