

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: YCCS-Sullivan House Alternative HS
Address: 8164 S. Chicago Ave

Oracle Unit: 66623
Region:

Building ID: 1121K
Mail Room: 47

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: ABALLARD1
Survey Date: 12/21/2018
Email Address: _____

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other | *Letter Mailed*

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 | Drywall | 12000 | SF | Walls throughout the building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2 | Joint Compound associated with Drywall | 12000 | SF | Walls throughout the building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3 | 12"x12" Gray Floor Tile | 600 | SF | Office and NE Classroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4 | 12"x12" Light Blue Floor Tile | 600 | SF | Office and NE Classroom Hallway | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5 | 12"x12" Tan Floor Tile | 1000 | SF | Office and NE Classroom, Rm 19 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | Mastic associated with tan/light blue/gray VFT | 600 | SF | Office and NE Classroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | Carpet Glue | 800 | SF | Northeast Computer Lab | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8 | 12"x12" Black Floor Tile | 500 | SF | Replacement Floor Tiles, Class 7 Faculty Room , Room 6 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9 | Mastic associated with 12"x12" Black VFT | 75 | SF | Replacement Floor Tiles | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | 2x4 White Ceiling Tile | 5000 | SF | Addition | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | Brown Carpet Adhesive | 2500 | SF | Addition | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12 | Drywall/ Joint Compound | 2000 | SF | Addition | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13 | Grey Carpet Adhesive | 2000 | SF | Room 10, Hallway Old Rec. Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTA | 12"x12" White Floor Tile and Mastic | 3000 | SF | Throughout most of building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTB | 12"x 12" Blue Green Floor Tile and Mastic | 1900 | SF | Cafeteria, Computer Room, and Art Room 6 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTC | 12"x12" Tan Floor Tile and Mastic | 700 | SF | Room 14 & 15 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTD | 12"x12" Rose Floor Tile and Mastic | 300 | SF | Computer Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTE | 12"x12" Blue Floor Tile and Mastic | 175 | SF | Women's and Men's Toilet Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MCA | 2'x4' Lay-in Ceiling Ceiling Tiles | 4000 | SF | Throughout most of building | | Miscellaneous | Yes | Dist | 10 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MCB | 2'x2' Lay-In Ceiling Tile | 1500 | SF | Nursery Rooms | | Miscellaneous | Yes | Dist | 10 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MIA | Mastic on Vinyl Baseboards | 1400 | LF | Throughout the Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: YCCS-Sullivan House Alternative HS
Date: 12/21/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. Letter Mailed
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.