

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2024 Fall Six Month Survey

**School:** William P Gray Elementary School  
**Address:** 3730 N Laramie Avenue

**Oracle Unit:** 23401  
**Region:** 01

**Building ID:** 3620  
**Mail Room:** 29

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Mclver, Justin  
**Survey Date:** 11/27/2024  
**Email Address:** jtmclver@cps.k12.il.us

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Water Tank Insulation			Boiler Room - 1911 Building		TSI		None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Abated
Comments: Abated
2023 Fall Six Month Survey: No Change
Comments: No Change
2024 Spring Six Month Survey: No Change
Comments: No Change
2024 Fall Six Month Survey: No Change
Comments: No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	MJP E/F/V on Aircell Pipe Insulation	10	EA	Room 211, Platform/Stage/Dressing Rooms, North Warm Air Chamber - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Friable Brick and Mortar			Basement Area - 1911 Building							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Friable Masonry and Mortar			Basement East, Ceiling - 1911 Building							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	MJP on Mag Block Pipe Insulation	10	EA	Engine and Tank Room - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Mag Block Pipe Insulation	50	LF	Engine and Tank Room - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Aircell Pipe Insulation	90	LF	Rooms 109 and 211, Stage/Platform and Dressing Room, North Warm Air Chamber - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Cardboard Pipe Insulation	300	LF	Boiler Room, Engine and Tank Room, Room 105 Toilet - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	MJP on Cardboard Pipe Insulation	38	EA	Boiler Room, Engine and Tank Room, Room 105 Toilet - 1911 Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	MJP on Fiberglass Pipe Insulation	200	LF	Engine & Tank Rooms, Boiler Room, 1st, 2nd & 3rd Floor Boys & Girls Toilet Pipe Chases - 1911 Building		TSI	Yes	None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Hard Coat Plaster	70000	SF	Throughout - 1911 Building		Surface	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	2'x4' White Ceiling Tile	30000	SF	Throughout - 1911 Building		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	1'x1' Peg Hole Ceiling Tile (Above 2'x4' Ceiling Tile)	400	SF	Room 211 - 1911 Building		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Canvas Wall Cover			Room 204 Closet and Room 105 - 1911 Building							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2'x4' Smooth Ceiling	1500	SF	Kitchen - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	2'x4' White w/ Grooves Ceiling Tile	15000	SF	Throughout - 1999 Building		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Drywall	500	SF	MDF Room - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Drywall Joint Compound	150	SF	MDF Room - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Spray on Fireproofing	15000	SF	Throughout - 1999 Building		Surface	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Drywall Tape	150	LF	MDF Room - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Violet-Streaked VFT	250	SF	Principal's Office - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12"x12" Violet-Streaked VFT Mastic	250	SF	Principal's Office - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Black Table Tops	160	SF	Room 305 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Fire Curtain	1600	SF	Assembly Hall Stage - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Terrazzo	12000	SF	1st, 2nd and 3rd Floor Corridors, all Vestibules and Stairwells - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Carpet Mastic	3500	SF	Rooms 602A-E and 2nd Floor Library - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Asphalt-like Flooring	6000	SF	Corridors - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	2' x 2' Ceiling Tile w/holes	3200	SF	3rd Floor Corridor, Rooms 307, 305, 303, and Top Floor Stairs Only		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Light Beige w/tan & Gray Specks VFT	3500	SF	Rooms: 110 & Storage, 111 & Storage, 112 & Storage, 113 & Mechanical Closet, Hallway and Vestibules - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12" x 12" Light Beige w/tan & Gray Specks VFT Mastic	3500	SF	Rooms: 110 & Storage, 111 & Storage, 112 & Storage, 113 & Mechanical Closet, Hallway and Vestibules - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Vinyl Baseboard Mastic	1000	LF	Rooms: 110 & Storage, 111 & Storage, 112 & Storage, 113 & Mechanical Closet, Hallway and Vestibules - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	2' x 2' Ceiling Tile	3500	SF	Throughout- Mobile Unit		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Drywall	4000	SF	Throughout - Mobile Unit		Miscellaneous		None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Blue Rubber Flooring Mastic	120	SF	Boys Toilet - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Red Rubber Flooring Mastic	120	SF	Girls Toilet - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Textured Ceiling Panels	80	SF	Mechanical Room 113 - Mobile Unit		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	12"x12" White w/ Brown Streaks VFT (Painted Over)	2500	SF	Assembly Hall/Gym - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	12"x12" Peach w/ White Specks VFT	800	SF	Room 103 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	9"x9" Green w/ White Streaks VFT	800	SF	Rooms 211 and 311 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB	12"x12" Peach w/ White Specks VFT Mastic	800	SF	Room 103 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Light Green Linoleum (Painted Over)	800	SF	Assembly Hall/Gym - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CC	12"x12" Beige w/Tan Streaks VFT	16000	SF	Throughout - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	12"x12 White w/ Brown Streaks VFT Mastic (Painted Over)	2500	SF	Assembly Hall/Gym - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	12"x12" Beige w/ Tan Streaks VFT Mastic	16000	SF	Throughout - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	9"x9" Green w/ White Streaks VFT Mastic	800	SF	Rooms 211 and 311 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	12"x12" Light Green w/ Dark Green Streaks VFT	2000	SF	Throughout - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Light Green Linoleum Mastic (Painted Over)	800	SF	Assembly Hall/Gym - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	12"x12" Light Green w/ Dark Green Streaks VFT Mastic	2000	SF	Throughout - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	12"x12" White w/ Brown Speckles VFT	2340	SF	Room 204, 204 Closet (MDF Room) and Room 206 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GG	24"x24" Dark Green W/ Specks VFT	500	SF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	12"x12" White w/ Brown Speckles VFT Mastic	2340	SF	Room 204, 204 Closet (MDF Room) and Room 206 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HH	24"x24" Dark Green W/ Specks VFT Mastic	500	SF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	12"x12" Dark Brown Speckles VFT	400	SF	Room 109 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
II	24"x24" Beige w/ Specks VFT	300	SF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	12"x12" Dark Brown Speckles VFT Mastic	400	SF	Room 109 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
JJ	24"x24" Beige w/ Specks VFT Mastic	300	SF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	12"x12" Beige w/ Dark Brown Speckles VFT	265	SF	Engineers Office - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
KK	Tan Linoleum	5000	SF	Gym - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	12"x12" Beige w/ Dark Brown Speckles VFT Mastic	265	SF	Engineers Office - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LL	Tan Linoleum Mastic	5000	SF	Gym - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	9"x9" Green w/ White Speckles VFT	20	SF	007 Toilet - 1911 Building - NOT OBSERVED		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MM	Beige Vinyl Baseboard	400	LF	Throughout Corridors - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	9"x9" Green w/ White Speckles VFT Mastic	290	SF	007 Toilet - 1911 Building - NOT OBSERVED		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NN	Beige Vinyl Baseboard Mastic	400	LF	Throughout Corridors - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
O	12"x12" Light Brown w/ White Speckles VFT	1040	SF	Room 101 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
OO	Rust Vinyl Baseboard	2500	LF	Throughout Classrooms - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	12"x12" Light Brown w/ White Speckles VFT Mastic	1040	SF	Room 101 - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PP	Rust Vinyl Baseboard Mastic	2500	LF	Throughout Classrooms - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	12"x12" Coffee w/ White Speckles VFT	600	SF	Main Office/Public Area, Clerk's Space - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
QQ	Green Vinyl Baseboard	240	LF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	12"x12" Coffee w/ Speckles VFT Mastic	600	SF	Main Office/Public Area, Clerk's Space - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
RR	Green Vinyl Baseboard Mastic	240	LF	Rooms 402 and 503 - 1999 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	12"x12" Brown w/ White Speckles VFT	80	SF	Main Office/Public Space Closets, Engineering Storage Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T	12"x12" Brown w/ White Speckles VFT Mastic	80	SF	Main Office/Public Space Closets, Engineering Storage Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	12"x12" Brown w/ White Streaks VFT	100	SF	Engine/Tank Storage Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	12"x12" Brown w/ White Streaks VFT Mastic	100	SF	Engine/Tank Storage Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	12"x12" Dark Brown VFT	10	SF	Engineer's Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
X	12"x12" Dark Brown VFT Mastic	10	SF	Engineer's Room - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Y	12"x12" Off White VFT	70	SF	1st floor- Speech Room by Girls Restroom - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
YY	12"x12" Off-White VFT Mastic	70	SF	1st floor- Speech Room by Girls Restroom - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Z	12"x12" Beige w/brown speckles VFT	100	SF	1st floor- Speech Room by Girls Restroom - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ZZ	12"x12" Beige w/brown speckles VFT Mastic	100	SF	1st floor- Speech Room by Girls Restroom - 1911 Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:No Change
2024 Spring Six Month Survey: No Change
Comments:No Change
2024 Fall Six Month Survey: No Change
Comments:No Change

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*



---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William P Gray Elementary School

Date: 11/27/2024

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***