

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Patrick Henry Elementary School
Address: 4250 N St Louis Avenue

Oracle Unit: 23731
Region: 01

Building ID: 3940
Mail Room: 31

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Schmidt, William
Survey Date: 11/19/2024
Email Address: wschmidt@cps.k12.il.us

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other | posted to cps websit

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01 | Plaster | | | Throughout - 1904 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02 | 12"x12" Brown w/ White Streaks VFT | 1200 | SF | Princ. Office, Rooms 204, 301 - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03 | 9"x9" Brown VFT | 400 | SF | Principals Office (under the carpet) - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04 | Green Linoleum | | | Room 304 - 1904 Bldg. REMOVED | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05 | 12"x12" Brown w/ White Streaks VFT Mastic | 1200 | SF | Princ. Office, Rooms 204, 301 - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06 | 9"x9" Brown VFT Mastic | 400 | SF | Principals Office (under carpet) - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07 | Green Linoleum Mastic | | | Room 304 - 1904 Bldg. REMOVED | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08 | Drywall System | 2000 | SF | Various Locations - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09 | 12"x12" Brown w/ White Streaks VFT | 1500 | SF | Room 301 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | 9"x9" Black VFT | 200 | SF | Aud. Balcony, Room B2-1907 Bldg | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11 | 12"x12" Brown w/ White Streaks VFT Mastic | 1500 | SF | Room 301 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12 | 9"x9" Black VFT Mastic | 200 | SF | Aud. Balcony, Room B2 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13 | 12"x12" Ceiling Tile w/ Grooves | | | Throughout - 1904 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14 | 12"x12" Grey w/ Tan Spots VFT | 2300 | SF | Room 308, Basement Kitchen - 1907 Bldg. | | Miscellaneous | No | Loc | 25 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 | 12"x12" Grey w/ Tan Spots VFT Mastic | 2300 | SF | Room 308, Basement Kitchen - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | Dark Green Linoleum - REMOVED | | | Room 304 - 1904 Bldg. - REMOVED | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | Dark Green Linoleum Mastic - REMOVED | | | Room 304 - 1904 Bldg. - REMOVED | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | Multi-Color Linoleum | | | Room 304 (counter tops) - 1904 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 | Multi-Color Linoleum Mastic | | | Room 304 (counter tops) - 1904 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | 9"x9" Tan VFT | 600 | SF | Principals Office (under carpet), Vault - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | 9"x9" Tan VFT Mastic | 600 | SF | Principals Office (under carpet), Vault - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | 12"x12" Tan w/ Grey Speckles VFT | 800 | SF | Room 108 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | 12"x12" Tan w/ Grey Speckles VFT Mastic | 800 | SF | Room 108 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | 9"x9" Brown w/ White Streaks VFT | 1100 | SF | Room 001, B1, 107 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | 9"x9" Brown w/ White Streaks VFT Mastic | 1100 | SF | Room 001, B1, 107 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | 12"x12" Off White w/ Grey Streaks VFT | 400 | SF | Basement Kitchen, Kitchen Store Rm - 1907 Bldg. | | Miscellaneous | No | Loc | 10 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27 | 12"x12" Off White w/ Grey Streaks VFT Mastic | 400 | SF | Basement Kitchen, Kitchen Store Rm - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28 | Hard Coat Plaster | | | 1907 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29 | 9"x9" Brown w/ Orange Specks VFT | 40 | SF | Engineers Toilet - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | 9"x9" Brown w/ Orange Specks VFT Mastic | 40 | SF | Engineers Toilet - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | 9"x9" Brown w/ Orange Specks VFT | 300 | SF | Basement Helps Room - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32 | 9"x9" Brown w/ Orange Specks VFT mastic | 300 | SF | Basement Helps Room - 1904 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | 12"x12" Gray VFT | 8000 | SF | Throughout 1996 Annex | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36 | 12"x12" Gray VFT Mastic | 8000 | SF | Throughout 1996 Annex | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37 | 2'x4' White w/ Grooves Ceiling Tile | | | Throughout 1996 Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 | Gray Vinyl Baseboard | | | Throughout 1996 Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 | Gray Vinyl Baseboard Mastic | | | Throughout 1996 Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 | Drywall | | | Throughout 1996 Annex | | Surface | No | Loc | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 | Drywall Compound | | | Throughout 1996 Annex | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | 12"X 12" Blue Floor Tile | 1000 | SF | Room B1 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | 12"X 12" Blue Floor Tile Mastic | 1000 | SF | Room B1 - 1907 Bldg. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | Carpet Mastic | 2000 | SF | Room 208, Auditorium (1907 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | Carpet Mastic | 350 | SF | 304A (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | Terrazzo | 600 | SF | 1st Floor Stair Landings (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | Terrazzo | 150 | SF | Auditorium Vestibule (1907 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | 12"X12" Gray Streaked VFT | 700 | SF | Room 202 and 203 Teachers Washroom (1907 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52A | 12"X12" Gray Streaked VFT Mastic | 700 | SF | Room 202 and 203 Teachers Washroom (1907 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | 12"X12" White w/Gray Specks VFT | 700 | SF | Room 107 (1907 Bldg) | | Miscellaneous | No | Loc | 16 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53A | 12"X12" White w/Gray Specks VFT Mastic | 700 | SF | Room 107 - 1907 Bldg. | | Miscellaneous | No | Loc | 16 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | Fire Door | 3 | EA | Sprinkler Rm, Engine Rm, Pump Rm (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | 12"X12" Gray Streaked VFT | 1000 | SF | Rooms 203, 204A Women (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57A | 12"X12" Gray Streaked VFT Mastic | 1000 | SF | Rooms 203, 204A Women (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | 12" X 12" Black with white specks VFT | 900 | SF | Main Office (1904 Bldg) | | Miscellaneous | No | Loc | 25 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59 | 12" X 12" Black with white specks VFT Mastic | 900 | SF | Main Office (1904 Bldg) | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60 | 12" x 12" Beige with tan streaks VFT | 3000 | SF | Rooms 304, 305, 306, 307, 308, 303; Men's Toilet by Rm 304A | | Miscellaneous | No | Loc | 3 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60A | 12" x 12" Beige with tan streaks VFT Mastic | 3000 | SF | Rooms 304, 305, 306, 307, 308, 303; Men's Toilet by Rm 304A | | Miscellaneous | No | Loc | 3 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61 | 12" x 12" Off-white VFT | 200 | SF | Room 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61A | 12" x 12" Off-white VFT Mastic | 200 | SF | Room 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62 | 12" x 12" White w/ Gray Specks VFT | 700 | SF | Room 107 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62A | 12" x 12" White w/ Gray Specks VFT Mastic | 700 | SF | Room 107 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | Red Fire Stop | 6 | LF | Throughout Various Locations | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | 12 x 12 Beige w/ streaks VFT | 40 | SF | 1st floor vault | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | MJP on Fiberglass Pipe Insulation | | | Engineers Toilet, Supply Room, Hall D - 1907 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Cardboard Pipe Insulation | 300 | LF | Lunchroom 2, Engine Room, Tank Room, Boiler Room, Halls C & D, Basement Boys Toilet - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | MJP on Cardboard Pipe Insulation | 100 | FITTING | Lunchroom 2, Engine Room, Tank Room, Boiler Room, Halls C & D, Basement Boys Toilet - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Aircell Pipe Insulation | 300 | LF | Basement Girls Toilet Store Room, Lunchroom 1 & 2, Engine, Tank, & Boiler Rooms, Hall C, Base. Boy Tol Vest. - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F | MJP on Aircell Pipe Insulation | 77 | FITTING | Basement Girls Toilet Store Room, Lunchroom 1 & 2, Engine, Tank, & Boiler Rooms, Hall C, Base. Boy Tol Vest. - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G | Aircell Duct Covering | 300 | SF | Basement Hall B & C - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H | Pre-Formed Pipe Insulation (mag block) | 180 | LF | Lunchroom 1&2, Tank Room, Engine Room, Boiler Room, Hall C, both Cold decks - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I | MJP on Pre-Formed Pipe Insulation | 50 | FITTING | Lunchroom 1&2, Tank Room, Engine Room, Boiler Room, Hall C - 1904 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J | MJP on Fiberglass Pipe Insulation | | | Basement Boys & Girls Toilets, Engine, Tank, Boiler Rooms, Lunchroom 1, Helps Store, Halls C & D - 1904 Bldg. | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K | Cardboard Pipe Insulation | 286 | LF | Engineers Toilet, Kitchen, Fan Room - 1907 Bldg. | | TSI | Yes | Loc | 1 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L | MJP on Cardboard Pipe Insulation | 100 | FITTING | Engineers Toilet, Kitchen, Fan Room - 1907 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M | Aircell Pipe Insulation | 30 | LF | Hall D - 1907 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O | Aircell Duct Covering | 400 | SF | Hall A - 1907 Building | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P | Pre-Formed Pipe Insulation | 100 | LF | Engineers Store Room, Hall D, Kitchen, Fan Room - 1907 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q | MJP on Pre-Formed Pipe Insulation | 3 | FITTING | Engineers Store Room, Hall D, Kitchen, Fan Room - 1907 Bldg. | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Richard J. Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Patrick Henry Elementary School
Date: 8/1/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. posted to cps website
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.