

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2024 Fall Six Month Survey

**School:** Turner-Drew Elementary Language Academy  
**Address:** 9300 S Princeton Avenue

**Oracle Unit:** 29041  
**Region:** 06

**Building ID:** 3110  
**Mail Room:** 48

☒ **CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** McHugh, Timothy  
**Survey Date:** 10/21/2024  
**Email Address:** \_\_\_\_\_

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack*    ☐ *Notice printed in school's newsletter*    ☐ *Notice printed in school's calendar*    ☒ *Other* | *cps website*

| HA No | Material Description             | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | 9x9 Tan w/Red & Green Floor Tile | 4375              | SF             | South 1st Floor Corridor, 1st Floor Office, 2nd Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 29041

Page 1

| HA No | Material Description                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04A   | 9x9 Tan w/Red & Green Floor Tile Mastic | 4375              | SF             | South 1st Floor Corridor, 1st Floor Office, 2nd Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | 12x12 Caramel Brown w/White Streaks Floor Tile | 2314              | SF             | Kitchen (patch) and Rooms 102 & 104 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | 12x12 Tan w/Red & Green Streaks Floor Tile | 15430             | SF             | 101, 105, 107, 108, 110, 112, 114, 2nd Floor Classrooms, 2nd Floor Teachers' Lounge, Men's & Women's Restrooms, Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06A   | 12x12 Tan w/Red & Green Streaks Floor Tile Mastic | 15430             | SF             | 101, 105, 107, 108, 110, 112, 114, 2nd Floor Classrooms, 2nd Floor Teachers' Lounge, Men's & Women's Restrooms, Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | 12x12 Dark Tan w/Maroon Streaks Floor Tile | 4140              | SF             | Gym and Kitchen   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07A   | 12x12 Dark Tan w/Maroon Streaks Floor Tile Mastic | 4140              | SF             | Gym & Kitchen     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 12x12 Beige Floor Tile | 1028              | SF             | 1st Floor Corridor & Engineer's Office, and a Patch in the Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|  |
|--|
| 2022 Fall Six Month Survey: Damaged      |
| Comments:tile popping in engineer office |
|  |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|  |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|  |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|  |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|  |

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09    | 9x9 Black Floor Tile | 70                | SF             | Gym & Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:tile popping                   |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09A   | 9x9 Black Floor Tile Mastic | 70                | SF             | Gym & Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:tile coming free               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | Transite Ceiling     | 700               | SF             | Kitchen           |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged                             |
| Comments:ceiling removed in spots to install kitchen duct work. |
|   |
| 2023 Spring Six Month Survey: No Change                         |
| Comments:   |
|   |
| 2023 Fall Six Month Survey: No Change                           |
| Comments:   |
|   |
| 2024 Spring Six Month Survey: No Change                         |
| Comments:   |
|   |
| 2024 Fall Six Month Survey: No Change                           |
| Comments:   |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | 12x12 Caramel Brown w/White Streaks Floor Tile Mastic | 2314              | SF             | Rooms 102 & 104   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | 12x12 Beige Floor Tile Mastic | 1028              | SF             | 1st Floor Corridor & Engineers Office, and a Patch in the Kitchen |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:tile coming loose              |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Blown-in Insulation  | 17500             | SF             | Attic             |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Transite Table Tops  | 10                | SF             | Room 204          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Drywall              | 300               | SF             | Teachers' Lounge Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | Drywall Compound     | 300               | SF             | Teachers' Lounge Closet |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 12x12 White with Gray Specks Floor Tile | 65                | SF             | Teachers' Lounge Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17A   | 12x12 White with Gray Specks Floor Tile Mastic | 65                | SF             | Teachers' Lounge Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | Terrazzo Floor- Pink and Green | 3400              | SF             | North, South and East Stairways, Building Lobby |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | Adobe Mosaic Ceramic Tile Grout | 1970              | SF             | 1st & 2nd Floor Boys' and Girls' Restrooms, North and South Vestibules |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description               | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | Adobe Mosaic Ceramic Tile Adhesive | 1970              | SF             | 1st & 2nd Floor Boys' and Girls' Restrooms, North and South Vestibules |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | Blue Carpet Adhesive | 410               | SF             | Principal's Office and Main Office (Secretary Area) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | 12x12 Off-White w/Tan Streaks Floor Tile | 140               | SF             | Main Office (Waiting Area) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22M   | 12x12 Off-White w/Tan Streaks Floor Tile Mastic | 140               | SF             | Main Office (Waiting Area) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | Brown Carpet Mastic  | 900               | SF             | Main Office and Principal's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description               | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 12x12 Light Beige Vinyl Floor Tile | 120               | SF             | 1st & 2nd Floor Corridors by Elevator |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24A   | 12x12 Light Beige Vinyl Floor Tile Mastic | 120               | SF             | 1st & 2nd Floor Corridors by Elevator |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | Gray Carpet Tile Mastic | 600               | SF             | Library (Room 208) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-1  | Black Baseboard      |                   |                | Main Office       |               | Miscellaneous     |         |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-2  | Tan Baseboard        | 15                | LF             | Room 101          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-3  | Cream Baseboard      | 50                | LF             | Teacher's Lounge Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-1 | Black Baseboard Mastic |                   |                | Main Office       |               | Miscellaneous     |         |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-2 | Tan Baseboard Mastic | 15                | LF             | Room 101          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-3 | Cream Baseboard Mastic | 50                | LF             | Teachers' Lounge Closet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CT-2  | 12x12 Fissured Pin Dot Ceiling Tile | 5500              | SF             | 1st & 2nd Floor Corridors |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CT-3  | 12x12 Deep Fissured Ceiling Tile | 3500              | SF             | Gym               |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | Cardboard Pipe Insulation | 10                | LF             | Fire Alarm Room (Boiler Room Area), Bathroom Pipe Chases |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | Aircell Pipe Insulation (under Fan Unit) | 10                | LF             | 2nd Floor Fan Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FD-1  | Insulation in Fire Doors | 2                 | LF             | Boiler Room Doors-Interior and Exterior |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | MJP on Cardboard Insulation | 3                 | LF             | Fire Alarm Room (Boiler Room Area), Bathroom Pipe Chases |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | MJP on Aircell Pipe Insulation ABATED |                   |                | 2nd Floor Fan Room under Fan Unit |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | Boiler Gaskets/Caulk ABATED |                   |                | Boiler Room       |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Incinerator Insulation Fire Brick | 4                 | SF             | Boiler Room NOT OBSERVED |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW   | Newly Installed Suspect ACM |                   |                | Installed After Implementation of Management Plan and After Renovations |               | Miscellaneous     |         | Unknown     |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P-1   | Plaster Ceiling and Upper Walls | 45000             | SF             | Throughout Building, including- Classrooms, Boiler Room & Offices |               | Surface           | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:peeling paint on all ceilings  |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| TSI-1 | MJP on Fiberglass Pipe Insulation NOT OBSERVED | 60                | LF             | Crawlspace        |               | TSI               | Yes     | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:rips in insulation             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| VB-1  | Vibration Dampeners  |                   |                | Fan Rooms off of 2nd Floor Gym |               | Miscellaneous     |         |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| WC-1  | Window Caulk         | 5500              | LF             | Throughout Building |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| WG-1  | Window Glazing       | 15000             | LF             | Throughout Building |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

A handwritten signature in black ink, appearing to read 'Richard J. Schleyer', written in a cursive style.

---

Richard J. Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Turner-Drew Elementary Language Academy

Date: 10/21/2024

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.  
Asbestos surveillances are conducted every six months.

**CHECK ONE**

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☒ Other. cps website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***