

Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School: Walt Disney Magnet Elementary School
Address: 4140 Marine Drive

Oracle Unit: 29401
Region: 01

Building ID: 8000
Mail Room: 32

Asbestos Surveyor: Budimir, Aleksandar
Survey Date: 10/30/2024
Email Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other |

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Dk Brn w/ Beige, Tan, & Black Specks VFT	7300	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments: no change
2023 Fall Six Month Survey: No Change
Comments: no change
2023 Spring Six Month Survey: No Change
Comments: no change
2024 Spring Six Month Survey: No Change
Comments: no change
2024 Fall Six Month Survey: No Change
Comments: No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Dk Brn w/Beige, Tn, & Blk Spcks VFT Mastic	1600	SF	2nd floor lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Vinyl Baseboard			Throughout							<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2022 Fall Six Month Survey: Abated
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Vinyl Baseboard Mastic			Throughout							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Black w/ White Specks VFT	600	SF	Third Floor Science Shared Facility Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Black w/ White Specks VFT Mastic	600	SF	Third Floor Science Shared Facility Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Beige w/ Brown Specks VFT (NOT OBSERVED)	100	SF	1st Floor Communication Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Beige w/ Brown Specks VFT Mastic (NOT OBSERVED)	100	SF	2nd Floor Communication Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Light Brown w/ White & Dark Specks VFT	2800	SF	Rooms 120, 110, & 100, Elevator		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Light Brn w/ White & Dk Specks VFT Mastic	2800	SF	Rooms 120, 110, & 100, Elevator		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" X 12" Dark Blue VFT	4400	SF	First & Third Floor Dining Areas		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" X 12" Dark Blue VFT Mastic	4400	SF	First & Third Floor Dining Areas		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" X 12" Black w/ Dark Blue VFT	4400	SF	First & Third Floor Dining Areas		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" X 12" Black w/ Dark Blue VFT Mastic	4400	SF	First & Third Floor Dining Areas		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Beige w/ White Spots VFT	2000	SF	Second Floor Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" Beige w/ White Spots VFT Mastic	2000	SF	Second Floor Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Dark Brown w/ Brown Spots VFT	2000	SF	Second Floor Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Dark Brown w/ Brown Spots VFT Mastic	2000	SF	Second Floor Dining Area		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Terrazzo	3000	SF	Stairwells		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Carpet Mastic	60000	SF	Throughout (See hatchings)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	lab counter tops	250	SF	3rd fl science lab (326)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Light Blue w/ White & blue streaks VFT	1600	SF	3rd fl break room (SW of dining room)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12"x12" Light Blue w/ White & blue streaks VFT mastic	1600	SF	3rd fl break room (SW of dining room)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"X12" Green Streaked VFT	80	SF	1st fl teachers' lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" Green Streaked VFT mastic	80	SF	1st fl Teachers' lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" White w/ gray specks VFT	600	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" White w/ gray specks VFT Mastic	600	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Green Carpet	4200	SF	Rooms 100-123		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	Green Carpet Mastic	4200	SF	Rooms 100-123		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Ceiling Tile Panels	900	SF	Near school dock		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Drywall	600	SF	Basement west exit near washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Blue Carpet	8200	SF	Library, 220, 300, 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	Blue Carpet Mastic	8200	SF	Library, 220, 300, 120		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2x4 Ceiling Tiles	20000	SF	Throughout		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Orange Carpet	1800	SF	Room 110		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	Orange Carpet Mastic	1800	SF	Room 110		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Purple Carpet	1800	SF	Room 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	Purple Carpet Mastic	1800	SF	Room 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Red Carpet	1800	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	Red Carpet Mastic	1800	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Brown Carpet	1800	SF	Studio 2		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45A	Brown Carpet Mastic	1800	SF	Studio 2		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12x12 Brown w/ Light Brown Specks VFT	1800	SF	2nd floor lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46A	12x12 Brown w/ Light Brown Specks VFT Mastic	1800	SF	2nd floor lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change
2024 Spring Six Month Survey: No Change
Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12x12 Brown w/ Specks VFT	700	SF	Resource room, 1st floor safe, 2nd floor safe		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47A	12x12 Brown w/ Specks VFT Mastic	700	SF	Resource room, 1st floor safe, 2nd floor safe		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12x12 Light Blue w/ Blue Specks VFT	3400	SF	2nd floor lunch room, 3rd floor lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48A	12x12 Light Blue w/ Blue Specks VFT Mastic	3400	SF	2nd floor lunch room, 3rd floor lunch room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12x12 Dark Gray w/ Specks VFT	5100	SF	Science lab, art room		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change
2024 Spring Six Month Survey: No Change
Comments:no change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49A	12x12 Dark Gray w/ Specks VFT Mastic	5100	SF	Science lab, art room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Tank insulation	200	SF	Pethouse		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Fiberglass Pipe Insulation	300	LF	Kitchen, Engine, Kitchen Storage, Pump Room, Penthouse, NW Building Fan Rooms, Pipe chases and above suspended ceilings, and CAC building		TSI	Yes	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2022 Fall Six Month Survey: Abated Comments:Booster pump fibergass insulation and asbestos insulation around valves abated in 10/2022
2023 Fall Six Month Survey: No Change Comments:no change
2023 Spring Six Month Survey: Abated Comments:Pump room -insulation on piping for booster pumps abated
2024 Spring Six Month Survey: No Change Comments:no change
2024 Fall Six Month Survey: No Change Comments:No change

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Vibration Joint Material	5	SF	Penthouse		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Duct Insulation	500	SF	Penthouse, Kitchen (Abated)		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2022 Fall Six Month Survey: No Change
Comments:no change
2023 Fall Six Month Survey: No Change
Comments:no change
2023 Spring Six Month Survey: No Change
Comments:no change
2024 Spring Six Month Survey: No Change
Comments:no change
2024 Fall Six Month Survey: No Change
Comments:No change

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Richard J.Schleyer

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Walt Disney Magnet Elementary School
Date: 11/1/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.