## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Hyde Park Academy High School 46171 1390 School: **Oracle Unit: Building ID:** Address: 6220 S. Stony Island Region: 05 Mail Room: Asbestos Surveyor: Mullaney, Luke X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/21/2024 Email Address: Itmullaney@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other School/Admin Decisi Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES 01 SF X NO Plaster 140000 1911 Building No None 0 Surface 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
02	Hard Plaster	140000	SF	1937 Building		Surface	No	None	0		YES X NO	
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Civ Month Curvey No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
03	Hard Plaster	140000	SF	1970 Building		Surface	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	12x12 Textured Ceiling Tile NOT OBSERVED			1937 Building- Room 142		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	,	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•				1							
2023 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•											
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12x12 Ceiling Tile	10000	SF	1937 Building		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
06	2x2 Ceiling Tile	32100	SF	1911 Building		Miscellaneous	Yes	None	0		YES X NO	
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
07	2x4 Pinhole Ceiling Tile	34500	SF	1911 Building		Miscellaneous	Yes	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIANO	Material Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Туре	Quantity	Units	Onange in Asse.	SSITICITE GATEGOTY
08	2x4 Perforated Ceiling Tile NOT OBSERVED			1911 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	-											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	-											
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Tectum Ceiling Panels	13000	SF	1911 Buildings		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

Page 5

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9x9 Light Brown Floor Tile	3500	SF	MDF Room, 210, 346		Miscellaneous	No	Dist	500		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12x12 Tan Floor Tile	25000	SF	117, 119, 121, 123, 125, 126, 128, 130, MDF Room Principal's Office, 202, 208, 210, 226, 228, 229, 230, Girls' Phys Ed Dept., 310, 326, 327, 328, 329, 330, 335, 337, 339 & 403		Miscellaneous	No	Dist	100		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	12x12 Metal Ceiling Tile	3750	SF	1911 Natatorium (Ceiling is Inaccessible)		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												
Comments	S:				_							
2023 Fall \$	Six Month Survey: No Ch	nange			-							
Comments	S:	Ĭ										
2023 Sprir	ng Six Month Survey: No	Change										
Comments	S:	-										
2024 Sprir	ng Six Month Survey: No	Change										
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Transite Table Tops	1000	SF	Science Labs		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	Transite Panel Material NOT OBSERVED			Science Labs 312, 316		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	<b>V</b>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Acoustical Ceiling Tile NOT OBSERVED			1911 Building							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	12x12 Textured Ceiling Tile NOT OBSERVED			1937 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change			-							
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Spray-On Fireproofing	45000	SF	1911 Building- Above 1st, 2nd & 3rd Floor Ceiling Tile & Columns		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
18	9x9 Light Brown Floor Tile Mastic	3500	SF	210 (MDF Room), 346		Miscellaneous	No	Dist	500		YES X NO	
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9x9 Tan Floor Tile Mastic NOT OBSERVED			1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9x9 Medium Brown Floor Tile Mastic NOT OBSERVED			SEE COMMENTS FOR ROOM LOCATIONS		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 Tan Floor Tile Mastic	25000	SF	117, 119, 121, 123, 125, 126, 128, 130, MDF Room Principal's Office, 202, 208, 210, 226, 228, 229, 230, Girls' Phys Ed Dept., 310, 326, 327, 328, 329, 330, 335, 337, 339 & 403		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
22	12x12 Tan Floor Tile Mastic NOT OBSERVED			1937 Building- Patched Areas of 1st & 2nd Floor Hallways		Miscellaneous					YES	X NO
		•	•	•			-			•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
23	12x12 Light Brown Floor Tile Mastic	1700	SF	1970 Building- Weight Room		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
24	2'x2' Ceiling Tile	14000	SF	1937 Building		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
25	2'x2' Ceiling Tile	1200	SF	1970 Building- Rear of Room 143 & 2nd Floor Southwest Corridor		Miscellaneous	Yes	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Quantity Quantity	Units	Change in Asses	sment Category
26	9x9 Tan Floor Tile NOT OBSERVED			1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	•			1							
	Month Survey: No Ch	ange			-							
Comments:												

Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
, ,
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9x9 Medium Brown Floor Tile NOT OBSERVED			See Comments for Room Locations		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	12x12 Tan Floor Tile NOT OBSERVED			1937 Building- Patched Areas of 1st & 2nd Floor Hallways		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, ,
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x12 Light Brown Floor Tile NOT OBSERVED			1970 Building- Weight Room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	9x9 Medium Brown Floor Tile NOT OBSERVED			Room 246, Southeastern Hall on 2nd Floor		Miscellaneous					YES	X NO
	Month Survey: No Ch	nange										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring S	Six Month Survey: No	Change			-							
Comments:	·											
2024 Spring S	Six Month Survey: No	Change										
Comments:	,											
2024 Fall Six	Month Survey: No Ch	nange			-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9x9 Tan Floor Tile NOT OBSERVED			Room 210 & 311		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
32	12x12 Beige Floor Tile NOT OBSERVED			Small Hallways leading to Library on 2nd & 3rd Floors.		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange		`								

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12x12 Brown Floor Tile	4000	SF	1st Floor Locker Rooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	12x12 Light Brown Floor Tile NOT OBSERVED			1911 Building		Miscellaneous					YES	X NO
2022 Fall Siz	x Month Survey: No Ch	nange										
Comments:	•											
2023 Fall Siz	x Month Survey: No Ch	nange										
Comments:					_							
2023 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Spring	Six Month Survey: No	Change										
Comments:	·			<u> </u>	_							
2024 Fall Si	x Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12x12 Dark Tan Floor Tile NOT OBSERVED			1911 Building- Patched Areas		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asse	ssment Category
36	12x12 Light Green Floor Tile NOT OBSERVED			Room 133		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:					]							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
2023 Spring	Six Month Survey: No	Change			-							
Comments:	•				7							

2024 Spring Six Month Survey: No Change Comments:

\_\_\_\_\_

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12x12 Off-White Floor Tile	1825	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	12x12 White Floor Tile	2500	SF	Rooms 135 & 137		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No Ch	nange			1							
Comments:	-	_			]							
2023 Fall S	ix Month Survey: No Ch	nange			=							
Comments:												
2023 Spring	g Six Month Survey: No	Change			=							
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12x12 Tan Speckled Floor Tile ABATED			Patched Areas of 1st Floor North Hallway		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	9x9 Brown Floor Tile ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor Hallways		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange	<u> </u>	·	, ]							
Comments					1							
2023 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Sprin	g Six Month Survey: No	o Change			-							
Comments	:											
2024 Sprin	g Six Month Survey: No	o Change			-							
Comments	:											
2024 Fall S	Six Month Survey: No C	hange			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9x9 Dark Brown Floor Tile ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor Hallways		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	12x12 Light Brown Floor Tile ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES	X NO
		•	•	•	1	•	-	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	9x9 Medium Brown Floor Tile	1800	SF	Team, Visitor, Boys' & Girls' Locker Rooms, Stairs		Miscellaneous	No	Dist	120		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
44	9x9 Tan Floor Tile NOT OBSERVED			1937 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
	( Month Survey: No Ch	ange										
2023 Spring Comments:	Six Month Survey: No	Change										
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	9x9 Brown Floor Tile NOT OBSERVED			See Comments for Room Locations		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
46	9x9 Brown Floor Tile ABATED			Patched Areas of 1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES	X NO
0000 F-II Ci-	Marath Ormani Na Ob		•	•	- -	•	•	•	•	•	•	
2022 Fall Six	Month Survey: No Ch	iange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	-				1							
2023 Spring	Six Month Survey: No	Change										
Comments:		-										
		•		•								

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2024 Spring Six Month Survey: No Change Comments:

Material Description

2024 Fall Six Month Survey: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9x9 Medium Brown Floor Tile Mastic ABATED			Room 246, Southeastern Hall on 2nd Floor		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
48	9x9 Tan Floor Tile Mastic	1300	SF	Rooms 210 & 311		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S	Six Month Survey: No	Change										
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Comments:	Month Survey: No Ch	ange		·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12x12 Beige Floor Tile Mastic NOT OBSERVED			Small Hallways leading to Library on 2nd & 3rd Floors		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
50	12x12 Brown Floor Tile Mastic NOT OBSERVED			1st Floor Locker Rooms		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:					-							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12x12 Light Brown Floor Tile Mastic ABATED			Auditorium		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
52	12x12 Dark Tan Floor Tile Mastic NOT OBSERVED			1911 Building- Patched Areas		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange			<u> </u>  - 							
2023 Spring Comments:	Six Month Survey: No	Change										
2024 Spring Comments:	Six Month Survey: No	Change										
2024 Fall Six Comments:	Month Survey: No Ch	ange										
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12x12 Light Green Floor Tile Mastic NOT OBSERVED			Room 133		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12x12 Off-White Floor Tile Mastic	1825	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12x12 White Floor Tile Mastic	2500	SF	Rooms 135 & 137		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
56	12x12 Tan Speckled Floor Tile Mastic ABATED			Patched Areas of 1st Floor North Hallway		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:		<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:				_								
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	9x9 Brown Floor Tile Mastic ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor Hallways		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

					_					_	,	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
58	9x9 Dark Brown Floor Tile Mastic ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor Hallways		Miscellaneous					YES	X NO
2022 Fall Siv	Month Survey: No Ch	ange			7							
	Month Survey. No Cr	arige			4							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change			1							
Comments:	,											
2024 Spring	Six Month Survey: No	Change			1							
Comments:		<u> </u>										
2024 Fall Six	Month Survey: No Ch	ange			-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12x12 Light Brown Floor Tile Mastic ABATED			1937 Building- Patched Areas of 1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
60	9x9 Medium Brown Floor Tile Mastic	1800	SF	Team, Visitor, Boys' & Girls' Locker Rooms		Miscellaneous	No	Dist	120		YES	X NO
2022 Fall Six	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	9x9 Tan Floor Tile Mastic NOT OBSERVED			1937 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
62	9x9 Brown Floor Tile Mastic NOT OBSERVED			See Comments for Room Locations		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	9x9 Light Brown Floor Tile Mastic ABATED			Patched Areas of 1st, 2nd & 3rd Floor South Hallways		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
64	12x12 Textured Ceiling Tile	25000	SF	1911 Building		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange										
Comments:					4							
2023 Fall S	ix Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												

2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12x12 Textured Ceiling Tile Mastic	25000	SF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
66	Ceiling Tile System	15000	SF	1911 Building		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12x12 Ceiling Tile Mastic	1300	SF	1937 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	2'x4' Ceiling Tile	800	SF	1937 Building- Rooms 231, 341 (ROTC), Hall to Dock		Miscellaneous	Yes	Loc	150		YES X NO
		•	•	•	1		•	•			

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Drop-In Ceiling Tile NOTY OBSERVED			1937 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
70	2'x4' Ceiling Tile NOT OBSERVED			1970 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No C	hange										
Comments:		•										
2023 Fall Six	Month Survey: No C	hange										
Comments:												
2023 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Black Trim Vinyl Baseboard	18000	LF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	Black Trim Vinyl Baseboard Mastic	18000	LF	1911 Building		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
0004 F II 0' M
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Black Trim Vinyl Baseboard	275	LF	1937 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Black Trim Vinyl Baseboard Mastic	275	LF	1937 Building		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 5 11 21 14 14 2
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Black Trim Vinyl Baseboard	300	LF	1970 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Black Trim Vinyl Baseboard Mastic	300	LF	1970 Building		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Transite Windowsill	3000	SF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
78	Transite Windowsill	550	SF	1937 Building		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Grey Carpet Mastic	950	SF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
80	Green Carpet Mastic	1900	SF	1911 Building		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Brown Carpet Mastic	1200	SF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
82	Dark Orange Carpet Mastic	15000	SF	1911 Building		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
0004 0 : 0: M (I 0 N 0)
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	Orange Carpet Mastic	21000	SF	1911 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12x12 Light Gray w/White Floor Tile	3600	SF	Auditorium, Room 142		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12x12 Light Gray w/White Floor Tile Mastic	3000	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
86	Gray Mix Terrazzo	5000	SF	Entrance & Stairwells		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										
2023 Spring S Comments:	Six Month Survey: No	Change										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2024 Spring S Comments:	Six Month Survey: No	Change										
2024 Fall Six Comments:	Month Survey: No Cha	ange										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	12x12 White w/Gray & Black Floor Tile ABATED			Room 114 and Patches in Room 210		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

		Quantity	Units		Type	Category	Туре	Quantity	Units		
88	12x12 White w/Gray & Black Floor Tile ABATED			Room 114 and Patches in Room 210		Miscellaneous				YES	X NO
0000 F II O	M (1.0 N.0)				7						
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:		_			1						
					1						
2023 Fall Six	Month Survey: No Ch	ange			1						
Comments:	•										
2024 Spring	Six Month Survey: No	Change			1						
Comments:	•										
2024 Fall Six	Month Survey: No Ch	ange									
Comments:	,				1						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12x12 White w/Blue & Red Floor Tile ABATED			Room 117		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
		Quantity	Offits		туре	Category		туре	Quartity	Office		
90	12x12 White w/Blue & Red Floor Tile Mastic ABATED			Room 117		Miscellaneous					YES	X NO
		•						-	-			
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
2023 Spring	Six Month Survey: No	Change			+							
Comments:	Ž	<u> </u>										
2024 Spring	Six Month Survey: No	Change			-							
Comments:	•											
2024 Fall Six	Month Survey: No Ch	ange			+							
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	Black Chalkboards	13000	SF	Classrooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
92	Black Chalkboard Adhesive	13000	SF	Classrooms		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	x Month Survey: No Ch	ange										
2023 Fall Six Comments:	x Month Survey: No Ch	ange										
	Six Month Survey: No	Change										
Comments:	Six Month Survey: No	Changa										
Comments:	Six Month Survey. No	Change										
2024 Fall Six	x Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	2'x2' Carpet Square Mastic NOT OBSERVED			Library		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12x12 Gray Floor Tile	8000	SF	Rooms 142, 341, 344, 345, and Stage 107A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12x12 Gray Floor Tile Mastic	8000	SF	Rooms 142, 341, 344, 345, and Stage 107A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	2'x2' Lay in Ceiling Tile	100000	SF	1st floor Throughout, 2nd floor Corridors, East Corridor Classrooms, 3rd Floor Throughout & 4th Floor Throughout		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12x12 Gray & Tan Marbled Floor Tile	30000	SF	1st, 2nd & 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	12x12 White, Green & Blue Floor Tile	40000	SF	Cafeteria, Band, Orchestra, and Rooms 134, 136, 137, 138, 140, 200, 210, 232, 234, 236, 238, 240, 300, 301, 303, 305, 309, 311, 332, 334, 336, 338, 340 & 342		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	12x12 White w/Gray Markings Floor Tile	6000	SF	Band Offices, Rooms 102, 114, 114 E/F/G, & 131		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12x12 Floor Tile Mastic	76000	SF	Areas as defined in HAS 97, 98 & 99		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12"x12" White & Blue Floor Tile	300	SF	Room 405		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101A	12"x12" White & Blue Floor Tile Mastic	300	SF	Room 405		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
102	12"x12" Green Floor Tile	300	SF	Room 405		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												
2023 Spring	g Six Month Survey: No	Change		·								
Comments:												

2024 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	12"x12" Green Floor Tile Mastic	300	SF	Room 405		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" Blue Floor Tile	300	SF	Room 405		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Ossiss O's Mostle Ossas No Obsessor
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103A	12"x12" Blue Floor Tile Mastic	300	SF	Room 405		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	Mag Block Insulation ABATED			Boiler		TSI		None			YES	X NO
2022 Fall Six	« Month Survey: No Cł	nange										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring	Six Month Survey: No	Change			=							
Comments:												
2024 Spring	Six Month Survey: No	Change			=							
Comments:												
2024 Fall Six Month Survey: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Mag Block Insulation ABATED			Garage		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

		Quantity	Units		Type	Category	Type	Quantity	Units		
С	Mag Block Insulation ABATED			Suspended in Pump Room		TSI				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange			7						
Comments:	,	<u> </u>			1						
2023 Fall Six	Month Survey: No Cha	ange			_						
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:				<u> </u>	_						
2024 Spring Six Month Survey: No Change					+						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Insulation ABATED			Pump Room		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Е	Mag Block Insulation ABATED			boiler room		TSI					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S	Six Month Survey: No	Change										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Comments:	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Preform Pipe Insulation ABATED			Boiler Room & Tunnel		TSI		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
G	Preform Fittings ABATED			Basement & Tunnels		TSI		None			YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7							
Comments:	•	•										
2023 Spring S	Six Month Survey: No	Change			+							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Cardboard Pipe Insulation ABATED			Compressor Room/Pump Room, Absorption Room & Tunnels		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1000	1'x1' Grooved White Ceiling Tile Glue	34500	SF	Rooms 301, 303, 305, 307, 309, 311		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1001	New 2'x2' White Ceiling Tile	35000	SF	Throughout 1st & 3rd Floor		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1002	New 2'x4' White Ceiling Tile	35000	SF	Throughout 1st & 3rd Floors		Miscellaneous	Yes	None	0		YES X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1003	Black Sink Undercoating	15	SF	Art Rooms 401, 402 & 406		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Cardboard Fittings	40	LF	Tunnels & Compressor Room		TSI	Yes	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2004 O. San O'. Marth O. and No. Ohanna
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Fiberglass Fittings	1800	LF	1911 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
K	Aircell Duct Insulation	30	SF	Tunnels		TSI	Yes	None	0		YES X NO		
2022 Fall Six Month Survey: No Change													

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Aircell Pipe Insulation	2240	LF	Pump Room Tunnels and Unexcavated Crawlspace		TSI	Yes	Dist	50		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 64

M Aircell Fitting 140 LF 1911 Pump Room, Tunnels & Unexcavated Crawlspace TSI Yes Dist 50 YES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	М	Aircell Fitting	140	LF	Tunnels & Unexcavated		TSI	Yes	Dist	50		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Fiberglass Fittings	400	LF	1937 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			YES	X NO
2022 Fall Si	x Month Survey: No C	hange										
Comments:	,											
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Si	x Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Si	x Month Survey: No C	hange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Fiberglass Fittings NOT OBSERVED			1970 Building		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
Р	2'x2' White Ceiling Tile	69000	SF	Throughout 1911 Building		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall S	ix Month Survey: No C	hange			]							
Comments:												
2023 Fall S	ix Month Survey: No C	hange										
Comments:												
2023 Spring	g Six Month Survey: No	Change										
Comments:												
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Gray & White Linoleum Flooring	2000	SF	Rooms 245 & 343		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categoria	jory
Q-1	Linoleum Flooring Mastic	950	SF	Rooms 245 & 343		Miscellaneous	No	None	0		YES X NO	
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	12x12 Brown Vinyl Floor Tile	2300	SF	Rooms 333 & 341		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		1			1		1	1	1	1		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
R-1	12x12 Brown Vinyl Floor Tile Mastic	2300	SF	Rooms 333 & 341		Miscellaneous	No	None	0		YES	X NO
2022 Fall Siv	Month Survey: No Ch	ange			1	•						
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2022 Spring	Six Month Survey: No	Chango										
	Six Month Survey. No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
	Monar Survey: No Si	arigo										
Comments:					4							
2024 Spring	Six Month Survey: No	Change										
Comments:	•				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	12x12 Blue Vinyl Floor Tile	3250	SF	East Stairwell, Front of Auditorium & All of Auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S-1	12x12 Blue Vinyl Floor Tile Mastic	3250	SF	East Stairwell, Front of Auditorium & All of Auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	12x12 Orange w/Green Vinyl Floor Tile	450	SF	Back Stage of Auditorium w/Hallway		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T-1	12x12 Orange w/Green Vinyl Floor Tile Mastic	450	SF	Back Stage of Auditorium w/Hallway		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hyde Park Academy High School
Date: 10/30/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. School/Admin Decision
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

Oracle Unit: 46171

SCHOOL'S ASBESTOS MANAGEMENT PLAN.