

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Jensen Elementary Scholastic Academy  
**Address:** 3030 W. Harrison

**Oracle Unit:** 29341  
**Region:** 03

**Building ID:** 6920  
**Mail Room:** 36

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Palmer, Julian  
**Survey Date:** 12/16/2025  
**Email Address:** jpalmer30@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other | CPS .edu

| HA No | Material Description     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4     | 9" x 9" Black Floor Tile | 33000             | SF             | Throughout Building |               | Miscellaneous     | No      | Loc         | 10              | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5     | Fire Door Insulation | 650               | SF             | Throughout Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6     | 9" x 9" Black Floor Tile Mastic | 33000             | SF             | Throughout Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description       | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7     | 1' x 1' White Ceiling Tile |                   |                | Throughout Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8     | Drywall              |                   |                | Main Office       |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9     | Carpet Mastic        |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | Hard Plaster         |                   |                | Throughout Building |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | 2' x 2' Ceiling Tile |                   |                | 1st Floor Corridor |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | 12" x 12" Green Floor Tile |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | 12" x 12" Green Floor Tile Mastic |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | 12" x 12" White Floor Tile |                   |                | Hallway Womens Engineer's Office |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | 12" x 12" White Floor Tile Mastic |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | Purple Baseboard     |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | Purple Baseboard Mastic |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | Green Baseboard      |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | Green Baseboard Mastic |                   |                | Lunchroom         |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | Brown Linoleum       |                   |                | MATERIAL REMOVED  |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | Brown Linoleum Mastic |                   |                | MATERIAL REMOVED  |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | Interior Brick       |                   |                | Throughout Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | Interior Brick Mortar |                   |                | Throughout Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | Interior Window Caulk |                   |                | Throughout Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | Vibration Damper     | 30                | LF             | 4th Floor Mechanical Room and Boiler Room |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | Exterior Window Caulk - Non-AHERA |                   |                | Exterior of Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | Roofing Material - Non-AHERA |                   |                | Exterior Roof     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 12" x 12" Black Floor Tile w/ White Flecks | 170               | SF             | 403 Closet        |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 12" x 12" Black Floor Tile w/ White Flecks Mastic | 170               | SF             | 403 Closet        |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 12" x 12" White Floor Tile w/ Brown Flecks |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 12" x 12" White Floor Tile w/ Brown Flecks Mastic |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | Elevator Brake Shoes |                   |                | Basement          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 1' x 1' Ceiling Tile Mastic | 5000              | SF             | Throughout Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | Drywall Joint Compound | 24                | SF             | Main Office       |               | Surface           | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 9" x 9" Black w/ White Streaks Floor Tile |                   |                | Rooms 103 and 105 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | 9" x 9" Red w/ White Streaks Floor Tile Mastic |                   |                | Rooms 103 and 105 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | Brown Carpet Adhesive | 1000              | SF             | Room 102          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | Red Carpet Adhesive  |                   |                | South Hallway (Exhibit Area) |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | 12" x 12" Beige w/ White Streaks Floor Tile |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | 12" x 12" Beige w/ White Streaks Floor Tile Mastic |                   |                | Room 102          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | 12" x 12" Red w/ White Streaks Floor Tile | 1000              | SF             | 1995 Building - Far West Hallway |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 12" x 12" Red w/ White Streaks Floor Tile Mastic | 1000              | SF             | 1995 Building - Far West Hallway |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | 12" x 12" Cherry Red w/ Dark Red Streaks Floor Tile | 30                | SF             | Far West Hallway  |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | 12" x 12" Cherry Red w/ Dark Red Streaks Floor Tile Mastic | 30                | SF             | Far West Hallway  |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | Green Carpet Mastic  | 3000              | SF             | 1995 Building - Teachers' Lounge, Rooms 140 & 160b |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | 12" x 12" Green w/ White Specks Floor Tile |                   |                | Room 105          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | 12" x 12" Green w/ White Specks Floor Tile Mastic |                   |                | Room 105          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description             | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | 6" x 6" Ceramic Floor Tile Grout | 30                | SF             | South and Southwest Entrance |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | 12" x 12" Ceramic Floor Tile Grout | 700               | SF             | Kitchen           |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | Insulation in Vault Door | 30                | SF             | Main Office (No Entry) |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | Chalkboard and Posterboard Adhesive | 1000              | LF             | Rooms 101-108, 201-208, 301-308, 401-408 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | Lavender Carpet Adhesive |                   |                | ABATED            |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description         | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | 12" x 12" Red Mix Floor Tile | 70                | SF             | 1995 Building - Foyer by Teachers' Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54    | 12" x 12" Red Mix Floor Tile Mastic | 70                | SF             | 1995 Building - Foyer by Teachers' Lounge |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55    | 12" x 12" Red w/ White Specks Floor Tile | 1070              | SF             | 1995 Building - Throughout Hallways |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56    | 12" x 12" Red w/ White Specks Floor Tile Mastic | 1070              | SF             | 1995 Building - Throughout Hallways |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57    | 4" Black Vinyl Baseboard | 700               | LF             | 1995 Building - Computer Lab and Throughout Hallways, Old Building 1st Floor Hall, Main Office, Lunchroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58    | 4" Black Vinyl Baseboard Adhesive | 700               | SF             | 1995 Building - Computer Lab and Throughout Hallways, Old Building 1st Floor Hall, Main Office, Lunchroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59    | Drywall              | 5000              | SF             | Throughout 1995 Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60    | Drywall Compound     | 5000              | SF             | Throughout 1995 Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | 2' x 2' Lay-in Ceiling Panels | 8000              | SF             | Throughout 1995 Building |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | Green Carpet Adhesive | 3000              | SF             | 1995 Building - Teachers' Lounge, Rooms 140 & 160b |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | 4" Green Vinyl Baseboard | 600               | LF             | 1995 Building - Teachers' Lounge, Library, Rooms 120 and 160b |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64    | 4" Green Vinyl Baseboard Adhesive | 600               | LF             | 1995 Building - Teachers' Lounge, Library, Room 120, Room 160b |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65    | 12" x 12" Green w/ White Specks Floor Tile | 1155              | SF             | 1995 Building - Computer Lab, Library Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66    | 12" x 12" Green w/ White Specks Floor Tile Mastic | 1155              | SF             | 1995 Building - Computer Lab, Library Office |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67    | Chalk Board/Poster Board Adhesive | 600               | LF             | Throughout Rooms  |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68    | 12" x 12" Beige/Yellow Specks Floor Tile | 1000              | SF             | Room 101          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69    | 12" x 12" Beige/Yellow Specks Floor Tile Mastic | 1000              | SF             | Room 101          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70    | 12" x 12" Floor Till White w/ Blue Streaks | 900               | SF             | Room 120          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71    | 12" x 12" Floor Tile White w/ Blue Streaks Mastic | 900               | SF             | Room 120          |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72    | Brown Ceramic Flooring, Grout | 2800              | SF             | 1st floor All Gender Bathroom, Teachers Lounge Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73    | Ceramic Flooring Brown, Adhesive |                   |                | 1st floor All Gender Bathroom, Teachers Lounge Bathroom |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74    | Gray Ceramic Flooring, Grout | 2000              | SF             | 2nd, 3rd, 4th Floors 1st Floor Boys Bathrooms, Girls Bathrooms |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75    | Gray Ceramic Flooring, Adhesive | 2000              | SF             | 2nd, 3rd, 4th Floors 1st Floor Boys Bathrooms, Girls Bathrooms |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76    | 12" x 12" White w/ Green and Brown Specks Floor Tile | 8414              | SF             | 1st Floor Corridor, Lunchroom, Janitor Mens and Womens Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77    | 12" x 12" White w/ Green and Brown Specks Floor Tile Mastic | 8414              | SF             | 1st Floor Corridor, Lunchroom, Janitor Mens and Womens Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78    | 12" x 12" Blue Floor Tile | 500               | SF             | Administrative Office, Gym |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description             | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79    | 12" x 12" Blue Floor Tile Mastic | 500               | SF             | Administrative Office, Gym |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80    | Asphalt Floor        | 30000             | SF             | Throughout Building |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description           | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81    | 12" x 24" Floor Tile and Grout | 2000              | SF             | 4th, 3rd & 2nd Floor Restrooms |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82    | 12" x 12" White w/ Gray Streaks Floor Tile | 3001              | SF             | 106, Patches in Hallways |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83    | 12" x 12" White w/ Gray Streaks Floor Tile Mastic | 3001              | SF             | 106, Patches in Hallways |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 84    | 12" x 12" Blue w/ Dark Blue Streaks Floor Tile | 400               | SF             | Rooms 103, 105    |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                                  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 85    | 12" x 12" Blue w/ Dark Blue Streaks Floor Tile Mastic | 400               | SF             | Rooms 103, 105    |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 86    | 12" x 12" White w/ Blue Vinyl Floor Tile | 400               | SF             | Rooms 103, 105    |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                     | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 87    | 12" x 12" Gray w/ White Vinyl Floor Tile | 450               | SF             | Rooms 103, 1st Floor Hall, 105 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description  | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 88    | 12" x 12" Gray w/ White and White w/ Blue Vinyl Floor Tile Mastic | 400               | SF             | Rooms 103, 1st Floor Hall, 105 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                    | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 89    | 2" x 2" Blue Ceramic Floor Tile & Grout | 200               | SF             | Room 103 Bathroom, 105 Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 90    | 6" x 6" White Ceramic Wall Tile & Grout | 200               | SF             | Room 103 Bathroom, 105 Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 91    | 8" x 8" White Ceramic Wall Tile & Grout | 300               | SF             | 1st Floor Boys Bathroom, 1st Floor Girls Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 92    | 2" x 2" Aqua Blue Ceramic Floor Tile & Grout | 300               | SF             | 1st Floor Boys Bathroom, 1st Floor Girls Bathroom |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 93    | 12" x 12" Black Floor Tile | 2000              | SF             | Room 107, 108     |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 94    | 12" x 12" Black Floor Tile Mastic | 1000              | SF             | Room 107,108      |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 95    | 12" x 12" Brown & Gray Vinyl Floor Tile | 700               | SF             | 1995 Building - Principals Office (100) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 96    | 12" x 12" Brown & Gray Vinyl Floor Tile Mastic | 700               | SF             | 1995 Building - Principals Office (100) |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 97    | 2' x 4' Ceiling Tile | 500               | SF             | 1995 Building - 130A Servery |               | Miscellaneous     | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 98    | 12" x 12" White & Gray Mottled Floor Tile | 800               | SF             | 1995 Building - 130A Servery |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 99    | 12" x 12" White & Gray Mottled Floor Tile Mastic | 800               | SF             | 1995 Building - 130A Servery |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 100   | 12" x 12" Dark Gray Mottled Floor Tile | 850               | SF             | 1995 Building - Room 160 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 101   | 12" x 12" Dark Gray Mottled Floor Tile Mastic | 50                | SF             | 1995 Building - Room 160 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102   | 12" x 12" Light Gray Mottled Floor Tile | 850               | SF             | 1995 Building - Room 160 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 103   | 12" x 12" Light Gray Mottled Floor Tile Mastic | 850               | SF             | 1995 Building - Room 160 |               | Miscellaneous     | No      | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description       | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104   | Fiberglass Pipe Insulation | 4000              | LF             | Throughout Boiler Room |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105   | Boiler Gaskets       |                   |                | On Boiler in Boiler Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                       |
|---------------------------------------|
| 2025 Fall Six Month Survey: No Change |
| Comments:                             |
|                                       |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 106   | Duct Insulation      | 1300              | LF             | Throughout Boiler Room |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description           | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Elbows on Fiberglass Pipe Runs | 200               | LF             | Throughout Building |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description      | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Paperwrap Pipe Insulation | 12                | LF             | 4th Floor Storage Room and Mechanical Room |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

| HA No | Material Description                | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Elbows on Paperwrap Pipe Insulation | 2                 | LF             | 4th Floor Storage Room and Mechanical Room |               | TSI               | Yes     | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jensen Elementary Scholastic Academy  
Date: 12/16/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. CPS .edu
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.