

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2025 Fall Six Month Survey

**School:** Ashburn Community Elementary School  
**Address:** 8300 S. St. Louis

**Oracle Unit:** 32081  
**Region:** 05

**Building ID:** 7100  
**Mail Room:** 44

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Moriarty, Brendan  
**Survey Date:** 12/17/2025  
**Email Address:** bmoriarty@cps.edu

A copy of the 2025/2026 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack    
 Notice printed in school's newsletter    
 Notice printed in school's calendar    
 Other | posted to the cps we

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	MJP E/F/V on Corrugated Pipe Insulation	100	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	Corrugated Pipe Cover	500	LF	Mechanical Areas and Plumbing Chases Throughout Building		TSI	Yes	Dist	8		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	MJP E/F/V on Paper Wrapped Pipe Insulation	100	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Paper Wrapped Pipe Insulation	5	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	MJP E/F/V on Paper Wrapped Pipe Insulation	2	LF	Basement		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Paper Wrapped Pipe Insulation	10	LF	Basement		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Corrugated Pipe Insulation	100	LF	All Floors in Buidling		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Corrugated Pipe Insulation	525	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	1'x1' Acoustical Ceiling Tile	7000	SF	Basement, 1st and 2nd Floor		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Dark Red w/Cream Specks Floor Tile	24200	SF	1st and 2nd Floors Rooms: 101,102, 103, 104, 105, 107, 201, 202, 203, 204, 205, 206, 207, 208, 209 & 211		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	MJP E/F/V on Corrugated Pipe Insulation	100	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Corrugated Pipe Insulation	600	LF	All Floors in Building		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	1'x1' Acoustical Ceiling Tile Mastic	28400	SF	Basement, 1st and 2nd Floor Hallways		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Black w/Cream Speckled Floor Tile	420	SF	1st Floor Maintenance		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	1'x1' Acoustical Ceiling Tile	100	SF	Throughout Building and Basement		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Dark Brown Floor Tile	8058	SF	Under 12x12 Floor Tile in Basement, 113, 114, 116, 117, Janitor's Closet, 210, 212, 213, 215, 216, and 217		Miscellaneous	No	Loc	1		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	1'x1' Acoustical Ceiling Tile Mastic	8058	SF	Throughout Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Breeching/Exhaust Packing	320	SF	Boiler Room		TSI	Yes	Loc	2		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	Corrugated Pipe Insulation	65	LF	Boiler Room		TSI	Yes	None	12		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22B	MJP E/F/V on Corrugated Pipe Insulation	65	LF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Vibration Dampening Cloth	5	SF	Basement Storage		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Vinyl Baseboard and Mastic	376	LF	Ground Floor		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
 Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Pink Floor Tile	2000	SF	Lunchroom/Gym		Miscellaneous	No	Loc	20		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Pink Floor Tile Mastic	2000	SF	Lunchroom/Gym		Miscellaneous	No	Loc	20		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"X12" White Floor Tile	1000	SF	Lunchroom/Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" White Floor Tile Mastic	1000	SF	Lunchroom/Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Carpet Mastic	3000	SF	Rooms 108, 110, 112, 218, 219, and Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Green and Beige Terrazzo	10000	SF	Hallways and Stairwells		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Blue Floor Tile	1600	SF	Rooms 106, 109 & 219		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Blue Floor Tile Mastic	1600	SF	Rooms 106, 109 & 219		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Gray w/Specks Vinyl Floor Tile	3500	SF	Rooms 114, 214, 215, 216, 217 and 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33B	12"x12" Gray w/Specks Vinyl Floor Tile Mastic	3500	SF	Rooms 114, 214, 215, 216, 217 and 210		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Carpet Mastic	1500	SF	Room 111, 212, Faculty Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" White Floor Tile	800	SF	Room 202		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35M	Mastic associated w/12" x12" White Floor Tile	800	SF	Room 202		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"X12" Light Grey & Grey Floor Tile	800	SF	Room 212		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36M	Mastic associated w/12" x12" Light Grey & Grey Floor Tile	800	SF	Room 212		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Transite Siding	100	SF	Ground Floor		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Drywall System	600	SF	Multipurpose Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Fire Door	1	EA	Electrical Room & Gym Storage		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12"x12" White w/Tan & Light Brown Specks Vinyl Floor Tile	2100	SF	Rooms 202, 210, and 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102A	12"x12" White w/Tan & Light Brown Specks Vinyl Floor Tile Mastic	2100	SF	Rooms 202, 210 & 213		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12"x12" White w/Tan Specks Vinyl Floor Tile	700	SF	Room 113		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103A	12"x12" White w/Tan Specks Vinyl Floor Tile Mastic	700	SF	Room 113		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12"x12" Light & Gray w/Gray & White Specks Vinyl Floor Tile	2900	SF	Rooms 214, 215, 216 & 217		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104A	12"x12" Light & Gray w/Gray & White Specks Vinyl Floor Tile Mastic	2900	SF	Rooms 214 215, 216 & 217		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12"x12" Grey Speckled Floor Tile	600	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105A	Mastic associated with 12" x12" Grey Speckled Floor Tile	600	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	2'x2' Ceiling Tile	300	SF	1st Floor Girls' Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2025 Fall Six Month Survey: No Change
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

*Richard J. Schleyer*

---

Richard J.Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ashburn Community Elementary School

Date: 8/1/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2025. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. posted to the cps website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**