

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.

For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.

Total Campus Need also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Chimney		Brick Chimney - Concrete/ Mortar Liner	Roof	6	80	LF	\$40,040	
Chimney		Brick Chimney - Concrete/ Mortar Liner	Roof	5	5	LF	\$8,938	
Chimney		Metal Flue	Above pre-K	4	7	LF	\$3,804	Rickety, rusted
Cornice		Cornice - Metal Projecting	Entire Building	5	607	LF	\$179,600	
Doors		Exterior Steel Door	1st Floor	6	20	EA	\$6,607	
Doors		Side Lite	1st Floor	6	2	EA	\$453	
Doors		Transom Lite	1st Floor	6	17	EA	\$4,813	
Entrance		Concrete Exterior Stairs	1st Floor	6	129	LF	\$13,835	
Entrance		Concrete Exterior Stairs	Northeast corner	7	59	LF	\$0	
Entrance		Stair Handrails	Northeast entrance	7	39	LF	\$0	
Entrance		Stair Handrails	1st Floor	6	30	LF	\$0	
Foundation		Masonry Foundation	Entire Building	7	29,016	SF	\$0	

Building: Main
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lighting		Exterior Lights - Parapet or Roof Mounted	Entire Building	4	11	EA	\$40,898	Mount covers missing, conduits disconnected, fixture housings deteriorating
Lighting		Exterior Lights - Wall Mounted	Entire Building	6	11	EA	\$2,360	
Lintels		Lintels - Steel	Entire Building	7	936	LF	\$0	
Parapet		Coping - Metal	Lower Roof	6	326	LF	\$0	
Parapet		Coping - Stone	Roof	5	1,071	LF	\$93,393	
Parapet		Coping - Stone	Above pre-K	4	1	LF	\$264	Missing coping piece replaced with brick, brick and mortar spalling
Parapet		Parapet < 16" Height	Entire Building	5	128	LF	\$30,806	
Parapet		Parapet > 30" Height	Roof	5	601	LF	\$241,070	
Parapet		Parapet 16" to 30" Height	Roof	5	343	LF	\$110,066	
Roof System		Exterior Downspouts	Lower Roof	5	12	LF	\$223	
Roof System		Interior Downspouts	Roof	6	560	LF	\$0	
Roof System		Metal Roof	Lower Roof	5	1,558	SF	\$27,849	Rusted
Roof System		Modified Bitumen Roof	Roof	5	27,458	SF	\$323,936	
Roof System		Roof Structure: Steel with Clay Tile Arch	Roof	6	29,016	SF	\$547,706	
Superstructure		Steel with Clay Tile Arch	Entire Building	7	59,563	SF	\$0	
Walls		Brick	Entire Building	6	33,738	SF	\$222,893	
Walls		Prefabricated Metal Panel Wall	Lower Roof	5	768	SF	\$21,965	
Walls		Stone - Cast	Entire Building	6	7,125	SF	\$101,888	
Windows		Skylite - Glass Single-Pane	Boiler Room	5	26	SF	\$1,570	
Windows		Window - Guards perforated	1st Floor	6	3,921	SF	\$0	
Windows		Windows - Sash Aluminum Double-pane	Entire Building	6	7,853	SF	\$67,379	
EXTERIOR Sub Total							\$2,092,355	

Building: Main
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Emergency System		Automatic Transfer switch	Mechanical Room	2	2	EA	\$17,732	There is no Source to switch to should the switches function
Emergency System		Emergency A/C power - Auditorium and aisle lighting	Gym/Auditorium	3	59,563	SF	\$413,099	Aisle Lights work under normal power - No EM source to function
Emergency System		Emergency A/C power - Corridors and Stairs	Corridors and Stairs	3	59,563	SF	\$183,126	Aisle Lights work under normal power - No EM source to function

Building: Main
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Emergency System		Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	6	24	EA	\$2,574	Batteries
Emergency System		Emergency Battery Packs - Lunchroom and Gym	Gym/Auditorium	6	9	EA	\$965	Batteries
Emergency System		Exit Signs - Auditorium	Gym/Auditorium	2	4	EA	\$3,718	Batteries need replacing and UPS is not working
Emergency System		Exit Signs - Corridors and Stairs	Corridors and Stairs	2	24	EA	\$22,308	Batteries need replacing and UPS is not working
Emergency System		Public Announcement System	Entire Building	6	59,563	SF	\$35,774	
Emergency System		Security System - Intrusion detection	Entire Building	6	59,563	SF	\$55,364	
Emergency System		UPS 30 to 60 KW	Mechanical Room	2	1	EA	\$81,510	UPS is disconnected and has not been replaced with the proper emergency system (emergency generator for system I or battery packs for system II)
Main Service		Main Electrical service - Live Front - 1000 A and below 120/208/3PH	Field House	4	1	EA	\$96,096	
Power Distribution		Lighting and power panels	Field House	6	1	EA	\$715	
Power Distribution		Lighting and power panels	Entire Building	6	8	EA	\$5,720	Labeling Issues
Power Distribution		Lighting and power panels	Main Entry and Mechanical Rooms	4	8	EA	\$43,472	
Power Distribution		Main distribution panels 400-600 amp	Mechanical Room	7	2	EA	\$0	
Power Distribution		Main distribution panels above 600 amp	Mechanical Room	7	1	EA	\$0	
Power Distribution		Main distribution panels less than 400 amp	Field House	4	2	EA	\$13,156	
ELECTRICAL Sub Total							\$975,329	

Building: Main
Category: FIRE PROTECTION

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Fire Alarm		Fire Alarm Strobe Lights	Entire Building	6	59,563	SF	\$21,294	
Fire Alarm		Fire Alarm System	North Courtyard	6	59,563	SF	\$72,399	
FIRE PROTECTION Sub Total							\$93,693	

Building: Main
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Air Conditioning		Window A/C Unit	Entire Building	6	2	EA	\$429	
Air Handling Systems		Air Handling Unit Package - Single Zone - Steam less than 4,000 cfm	Field House	4	1	EA	\$35,750	Natural gas unit

Building: Main
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Air Handling Systems		Air Intake - Built Up Air Handling Unit	Roof	3	1	EA	\$26,169	Dampers are inoperative System Starved - Housing doors have to be opened to relieve excessive pressure.
Air Handling Systems		Air intake for all Air Handling Units except built up AHU	East Façade	7	1	EA	\$0	
Air Handling Systems		Multi Zone Built Up Air Handling Unit - Steam 25,001 to 35,000 cfm	Mechanical Room	6	2	EA	\$25,740	
Air Handling Systems		Multi Zone Built Up Air Handling Unit Auxiliaries - Steam 25,001 to 35,000 cfm	Mechanical Room	6	2	EA	\$7,150	
Air Handling Systems		Return Fans - Indoor 10,001 to 20,000 CFM	Attic	6	2	EA	\$4,862	
Air Handling Systems		Single Zone Built Up Air Handling Unit - Steam 4,000 to 8,000 cfm	Mechanical Room	6	1	EA	\$5,005	
Boiler Systems		Boiler Assembly - Steam - Flexible Tube Boiler 50-75 HP	Basement Boiler Room	6	1	EA	\$18,733	Operations have problems with excessive scale buildupVent piping inside and on the roof is in poor condition.
Boiler Systems		Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 101-150 HP	Boiler Room	6	2	EA	\$29,458	
Boiler Systems		Boiler Auxiliary - Steam Boiler 101-150 HP	Boiler Room	5	2	EA	\$22,880	
Boiler Systems		Boiler Auxiliary - Steam Boiler 50-75 HP	Under Floor	6	1	EA	\$1,859	
Boiler Systems		Chemical Feed System (Steam Boilers)	Boiler Room	7	2	EA	\$0	
Boiler Systems		Combustion Dampers	Boiler Room	6	2	EA	\$572	
Boiler Systems		Feed Water Pumps and Tank - Steam Boilers	Boiler Room	6	1	EA	\$8,437	Tank not insulated.
Boiler Systems		Gas Boosters	Mechanical Room	7	1	EA	\$0	
Heating Devices		Radiators - Steam	Kindergarden	6	3	EA	\$420	
Heating Devices		Unit Heater - Electric	Yard Storage and Entire Building	6	12	EA	\$17,160	
Heating Devices		Unit Heater - Gas	Boiler Room	6	1	EA	\$2,145	
Heating Devices		Wall Heater - Electric	Entire Building	7	3	EA	\$0	
Mechanical Plumbing		Condensate Assembly - Pumps and Tank	Mechanical Room	6	1	EA	\$715	
Mechanical Plumbing		Piping - Condensate - Steel or Galvanized	Entire Building	5	225	LF	\$7,320	
Mechanical Plumbing		Piping - Steam - Steel or Galvanized	Entire Building	5	225	LF	\$11,133	
Temperature Control		Hybrid Pneumatic/Direct Digital Control (DDC) System	Entire Building	3	59,563	SF	\$596,226	DDC Functions Inoperative HYBRID SYSTEM No Control of AHU's and Boilers - Stop/Start/Scheduling Inoperative
Temperature Control		Pneumatic System	Entire Building	4	59,563	SF	\$425,875	

Building: Main
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Temperature Control		Thermostats - Pneumatic	Entire Building	4	26	EA	\$17,103	
Temperature Control		Zone Dampers	Plenum	4	26	EA	\$21,936	Dampers do not work, Fans turned off and on manually to control space temps
Ventilation		Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm	Roof	6	3	EA	\$1,287	
MECHANICAL Sub Total							\$1,288,364	

Building: Main
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Hot Water		Hot Water Heater - Gas 150,000 -300,000 BTU/HR	Boiler Room	4	1	EA	\$22,880	
Hot Water		Hot Water Heater - Gas less than 150,000 BTU/HR	Field House	4	1	EA	\$14,872	
Piping		Domestic Piping - Cold Water from Risers to Fixtures	Entire Building	6	59,563	SF	\$6,814	
Piping		Domestic Piping - Cold Water Risers	Entire Building	6	59,563	SF	\$9,369	
Piping		Domestic Piping - Hot Water from Riser to fixtures	Entire Building	5	59,563	SF	\$68,140	
Piping		Domestic Piping - Hot Water Return Risers	Entire Building	5	59,563	SF	\$12,776	
Piping		Domestic Piping - Hot Water Risers	Entire Building	5	59,563	SF	\$15,332	
Piping		Domestic Piping Cold Water Horizontal lines	Entire Building	6	59,563	SF	\$13,628	
Piping		Domestic Piping Cold Water Horizontal lines	Field House	4	1,812	SF	\$4,327	
Piping		Domestic Piping Hot Water Horizontal lines	Field House	4	1,812	SF	\$3,576	
Piping		Domestic Piping Hot Water Horizontal lines	Entire Building	5	59,563	SF	\$31,515	
Piping		Domestic Piping Hot Water Return Lines	Entire Building	5	59,563	SF	\$32,367	
Piping		Sanitary Piping	Entire Building	5	59,563	SF	\$36,625	
Piping		Sanitary Piping	Field House	5	1,812	SF	\$1,114	
Piping		Storm Piping	Entire Building	5	59,563	SF	\$28,108	
Piping		Vent Piping	Field House	5	1,812	SF	\$648	
Piping		Vent Piping	Entire Building	5	59,563	SF	\$21,294	
Pumps		Domestic Booster Pump simplex	Mechanical Room	6	1	EA	\$1,716	
PLUMBING Sub Total							\$325,100	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	1st floor NW corner	6	557	SF	\$1,195	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	3rd floor Rm306A at north end of corridor	6	360	SF	\$772	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	1st floor SW corner teachers lounge	6	333	SF	\$714	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	2nd floor Rm206A at north end of corridor	6	211	SF	\$453	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	3rd floor at top of south stair well	6	302	SF	\$855	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	3rd floor Rm312 at top of north stair well	6	302	SF	\$855	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	3rd floor Rm306A at north end of corridor	6	360	SF	\$515	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	1st floor SW corner teachers lounge	6	333	SF	\$476	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	2nd floor Rm206A at north end of corridor	6	211	SF	\$302	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	1st floor NW corner	6	557	SF	\$797	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	3rd floor Rm312 at top of north stair well	6	302	SF	\$2,280	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	3rd floor at top of south stair well	6	302	SF	\$2,280	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	2nd floor Rm206A at north end of corridor	6	2	SF	\$1	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	1st floor NW corner	6	7	SF	\$5	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	3rd floor Rm306A at north end of corridor	6	3	SF	\$2	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	3rd floor at top of south stair well	6	4	SF	\$3	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	1st floor SW corner teachers lounge	6	6	SF	\$4	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	3rd floor Rm312 at top of north stair well	6	4	SF	\$3	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	3rd floor Rm312 at top of north stair well	6	722	SF	\$1,704	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	3rd floor at top of south stair well	6	722	SF	\$1,704	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	3rd floor Rm306A at north end of corridor	6	884	SF	\$2,086	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	1st floor SW corner teachers lounge	6	936	SF	\$2,208	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	1st floor NW corner	6	1,182	SF	\$2,789	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	2nd floor Rm206A at north end of corridor	6	646	SF	\$1,524	
Corridor		Stair Handrails	Inside boiler room	6	15	LF	\$0	
Corridor		Stairs - Wood	Inside boiler room	6	6	LF	\$112	
Doors		Interior Steel Doors incl hw	1st Floor	6	6	EA	\$1,699	
Doors		Interior Steel Doors incl hw	2nd Floor	6	1	EA	\$283	
Doors		Interior Wood Doors incl hw	2nd Floor	6	24	EA	\$6,795	
Doors		Interior Wood Doors incl hw	1st Floor	6	64	EA	\$18,121	
Doors		Side-lite	1st Floor	6	10	SF	\$186	
Doors		Side-lite	2nd Floor	6	10	SF	\$186	
Doors		Transom Window	2nd Floor	6	100	SF	\$1,859	
Doors		Transom Window	1st Floor	6	330	SF	\$6,135	
Drinking Fountains	Corridors	Single Fountain	3rd Floor	6	2	EA	\$772	
Drinking Fountains	Corridors	Single Fountain	1st Floor	6	2	EA	\$772	
Drinking Fountains	Corridors	Single Fountain	2nd Floor	6	2	EA	\$772	
Gymnasium / Auditorium	Gymnasium.Auditorium	Ceiling - Plaster/Drywall	1st Floor	6	6,600	SF	\$56,439	
Gymnasium / Auditorium	Gymnasium.Auditorium	Flooring - Wood	1st Floor	6	6,600	SF	\$49,833	
Gymnasium / Auditorium	Gymnasium.Auditorium	Lighting - Metal Halide/Sodium Vapor	1st Floor	6	28	EA	\$5,005	
Gymnasium / Auditorium	Gymnasium.Auditorium	Lighting - Pendant/Surface	1st Floor	6	15	EA	\$1,823	
Gymnasium / Auditorium	Gymnasium.Auditorium	Scoreboards	1st Floor	6	1	EA	\$2,076	
Gymnasium / Auditorium	Gymnasium.Auditorium	Sound System	1st Floor	6	1	EA	\$5,005	
Gymnasium / Auditorium	Gymnasium.Auditorium	Stage Curtain	1st Floor	6	2	EA	\$18,876	
Gymnasium / Auditorium	Gymnasium.Auditorium	Stage Platform	1st Floor	6	648	SF	\$2,752	
Gymnasium / Auditorium	Gymnasium.Auditorium	Walls - Plaster/Drywall	1st Floor	6	6,686	SF	\$57,366	
MDF/IDF		Finishes	2nd floor north end of corridor inside rm 206A IDF room	6	124	SF	\$422	
MDF/IDF		Ventilation and Cooling	2nd floor north end of corridor inside rm 206A IDF room	6	124	EA	\$173,774	
Mechanical/Service Rooms		Boiler Room	1st Floor	6	1,790	SF	\$8,447	
Mechanical/Service Rooms		Janitor's Closet	Entire Building	6	3	SF	\$14	
Mechanical/Service Rooms		Mechanical/Service Rooms	1st floor inside auditorium booth & dress room	6	228	SF	\$1,076	
Mechanical/Service Rooms		Mechanical/Service Rooms	1st floor between boiler & auditorium	6	3,326	SF	\$15,695	
Mechanical/Service Rooms		Storage Room	1st floor next to vestibule of auditorium	6	553	SF	\$2,610	
Mechanical/Service Rooms		Storage Room	1st floor inside kindergarten	6	95	SF	\$448	
Mechanical/Service Rooms		Storage Room	1st floor next to boiler room	6	468	SF	\$2,208	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Mechanical/Service Rooms		Storage Room	1st floor inside teachers lounge at SW corner	6	108	SF	\$510	
Staff Restroom	Staff Restroom	Accessories	1st floor next to girls restroom	6	38	SF	\$293	
Staff Restroom	Staff Restroom	Accessories	2nd floor men's next to boys restroom	6	44	SF	\$340	
Staff Restroom	Staff Restroom	Accessories	1st floor inside boiler room	6	15	SF	\$116	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd floor boys	6	266	SF	\$2,054	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd floor girls	6	266	SF	\$2,054	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd floor girls	6	266	SF	\$2,054	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd floor boys	6	266	SF	\$2,054	
Staff Restroom	Staff Restroom	Accessories	1st floor inside office at NW corner	6	67	SF	\$517	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st floor girls	6	203	SF	\$1,568	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st floor boys	6	266	SF	\$2,054	
Staff Restroom	Staff Restroom	Accessories	3rd floor women's next to boys restroom	6	44	SF	\$340	
Staff Restroom	Early Childhood Student Restroom	Accessories	1st floor inside kindergarten	6	44	SF	\$340	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	2nd floor men's next to boys restroom	6	44	SF	\$125	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Plaster/Drywall	1st floor inside kindergarten	6	44	SF	\$125	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	1st floor inside office at NW corner	6	67	SF	\$190	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st floor girls	6	203	SF	\$575	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd floor boys	6	266	SF	\$753	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	1st floor next to girls restroom	6	38	SF	\$108	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd floor girls	6	266	SF	\$753	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd floor girls	6	266	SF	\$753	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd floor boys	6	266	SF	\$753	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	1st floor inside boiler room	6	15	SF	\$42	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st floor boys	6	266	SF	\$753	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	3rd floor women's next to boys restroom	6	44	SF	\$125	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd floor boys	6	1	EA	\$300	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st floor boys	6	1	EA	\$300	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd floor girls	6	1	EA	\$300	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd floor girls	6	1	EA	\$300	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st floor girls	6	1	EA	\$300	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd floor boys	6	1	EA	\$300	
Staff Restroom	Staff Restroom	Flooring - Concrete	1st floor next to girls restroom	6	38	SF	\$179	
Staff Restroom	Staff Restroom	Flooring - Concrete	1st floor inside boiler room	6	15	SF	\$71	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd floor boys	6	266	SF	\$677	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	3rd floor women's next to boys restroom	6	44	SF	\$112	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	2nd floor men's next to boys restroom	6	44	SF	\$112	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd floor boys	6	266	SF	\$677	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd floor girls	6	266	SF	\$677	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st floor girls	6	203	SF	\$517	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st floor boys	6	266	SF	\$677	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd floor girls	6	266	SF	\$677	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	1st floor inside office at NW corner	6	67	SF	\$96	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	1st floor inside kindergarten	6	44	SF	\$63	
Staff Restroom	Staff Restroom	Lavatory	3rd floor women's next to boys restroom	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lavatory	2nd floor men's next to boys restroom	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lavatory	1st floor inside boiler room	6	1	EA	\$372	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd floor boys	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd floor girls	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd floor girls	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd floor boys	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st floor girls	6	3	EA	\$1,115	
Staff Restroom	Staff Restroom	Lavatory	1st floor inside office at NW corner	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st floor boys	6	3	EA	\$1,115	
Staff Restroom	Early Childhood Student Restroom	Lavatory	1st floor inside kindergarten	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lavatory	1st floor next to girls restroom	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	2nd floor men's next to boys restroom	4	2	SF	\$9	T-12
Staff Restroom	Early Childhood Student Restroom	Lighting - Pendant/ Surface	1st floor inside kindergarten	4	1	SF	\$4	T-12
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st floor boys	6	4	SF	\$3	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st floor girls	4	4	SF	\$17	T-12
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd floor boys	6	4	SF	\$3	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd floor girls	6	4	SF	\$3	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd floor girls	6	4	SF	\$3	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd floor boys	6	4	SF	\$3	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	1st floor next to girls restroom	4	1	SF	\$4	T-12
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	3rd floor women's next to boys restroom	4	2	SF	\$9	T-12
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd floor boys	6	3	EA	\$538	
Staff Restroom	Children's Standard Student Restroom	Partitions	1st floor girls	6	5	EA	\$897	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd floor boys	6	3	EA	\$538	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Partitions	1st floor boys	6	3	EA	\$538	
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd floor girls	6	7	EA	\$1,255	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd floor girls	6	7	EA	\$1,255	
Staff Restroom	Children's Standard Student Restroom	Urinals	1st floor boys	6	5	EA	\$1,859	
Staff Restroom	Children's Standard Student Restroom	Urinals	2nd floor boys	6	5	EA	\$1,859	
Staff Restroom	Children's Standard Student Restroom	Urinals	3rd floor boys	6	5	EA	\$1,859	
Staff Restroom	Staff Restroom	Wall - Concrete Block	1st floor inside boiler room	6	222	SF	\$635	
Staff Restroom	Early Childhood Student Restroom	Wall - Plaster/Drywall	1st floor inside kindergarten	6	349	SF	\$823	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	3rd floor girls	6	425	SF	\$1,003	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	1st floor inside office at NW corner	6	307	SF	\$724	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	1st floor boys	6	425	SF	\$1,003	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	1st floor girls	6	388	SF	\$915	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	2nd floor girls	6	425	SF	\$1,003	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	3rd floor boys	6	425	SF	\$1,003	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	1st floor next to girls restroom	6	165	SF	\$389	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	2nd floor men's next to boys restroom	6	322	SF	\$760	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	3rd floor women's next to boys restroom	6	322	SF	\$760	
Staff Restroom	Children's Standard Student Restroom	Wall - Plaster/Drywall	2nd floor boys	6	425	SF	\$1,003	
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	3rd floor women's next to boys restroom	6	46	SF	\$329	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st floor boys	6	425	SF	\$3,039	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st floor girls	6	388	SF	\$2,774	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd floor boys	6	425	SF	\$3,039	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd floor girls	6	425	SF	\$3,039	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd floor girls	6	425	SF	\$3,039	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd floor boys	6	425	SF	\$3,039	
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	2nd floor men's next to boys restroom	6	46	SF	\$329	
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	1st floor next to girls restroom	6	165	SF	\$1,180	
Staff Restroom	Staff Restroom	Water Closet	1st floor inside office at NW corner	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st floor boys	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd floor girls	6	7	EA	\$2,603	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st floor girls	6	5	EA	\$1,859	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd floor boys	6	3	EA	\$1,115	
Staff Restroom	Staff Restroom	Water Closet	2nd floor men's next to boys restroom	6	1	EA	\$372	
Staff Restroom	Early Childhood Student Restroom	Water Closet	1st floor inside kindergarten	6	2	EA	\$744	
Staff Restroom	Staff Restroom	Water Closet	1st floor next to girls restroom	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Water Closet	1st floor inside boiler room	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd floor boys	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd floor girls	6	7	EA	\$2,603	
Staff Restroom	Staff Restroom	Water Closet	3rd floor women's next to boys restroom	6	1	EA	\$372	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
INTERIOR Sub Total							\$554,349	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		6	10	LF	\$358	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		6	9	LF	\$322	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	9	LF	\$322	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	9	LF	\$322	
Casework	Classroom	Casework		6	9	LF	\$322	
Casework	Classroom	Casework		6	9	LF	\$322	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	15	LF	\$536	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	12	LF	\$429	
Casework	Classroom	Casework		6	15	LF	\$536	
Casework	Classroom	Casework		6	38	LF	\$1,359	
Casework	Classroom	Casework		6	12	LF	\$429	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	34	LF	\$1,216	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	10	LF	\$358	
Casework	Classroom	Casework		6	24	LF	\$858	
Casework	Classroom	Casework		6	20	LF	\$715	
Casework	Classroom	Casework		6	12	LF	\$429	
Casework	Classroom	Casework		6	24	LF	\$858	
Casework	Classroom	Casework		6	9	LF	\$322	
Ceiling	Classroom	Lay-In/Drop		6	415	SF	\$890	
Ceiling	Classroom	Lay-In/Drop		6	866	SF	\$1,858	
Ceiling	Classroom	Lay-In/Drop		6	927	SF	\$1,988	
Ceiling	Classroom	Lay-In/Drop		6	881	SF	\$1,890	
Ceiling	Classroom	Lay-In/Drop		6	888	SF	\$1,905	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	909	SF	\$1,950	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Ceiling	Classroom	Lay-In/Drop		6	888	SF	\$1,905	
Ceiling	Classroom	Lay-In/Drop		6	888	SF	\$1,905	
Ceiling	Classroom	Lay-In/Drop		6	602	SF	\$1,291	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	554	SF	\$1,188	
Ceiling	Classroom	Lay-In/Drop		6	934	SF	\$2,003	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	908	SF	\$1,948	
Ceiling	Classroom	Lay-In/Drop		6	909	SF	\$1,950	
Ceiling	Classroom	Lay-In/Drop		6	903	SF	\$1,937	
Ceiling	Classroom	Lay-In/Drop		6	888	SF	\$1,905	
Ceiling	Classroom	Lay-In/Drop		6	879	SF	\$1,885	
Ceiling	Classroom	Lay-In/Drop		6	415	SF	\$890	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Ceiling	Classroom	Lay-In/Drop		6	910	SF	\$1,952	
Ceiling	Classroom	Lay-In/Drop		6	910	SF	\$1,952	
Ceiling	Classroom	Lay-In/Drop		6	888	SF	\$1,905	
Ceiling	Classroom	Lay-In/Drop		6	938	SF	\$2,012	
Chalk Board	Classroom	Chalk Board		4	35	LF	\$4,254	
Chalk Board	Classroom	Chalk Board		4	10	LF	\$1,216	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	26	LF	\$3,160	
Chalk Board	Classroom	Chalk Board		4	26	LF	\$3,160	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	28	LF	\$3,403	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	37	LF	\$4,497	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	30	LF	\$3,647	
Chalk Board	Classroom	Chalk Board		4	31	LF	\$3,768	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	26	LF	\$3,160	
Chalk Board	Classroom	Chalk Board		4	8	LF	\$972	
Chalk Board	Classroom	Chalk Board		4	30	LF	\$3,647	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	22	LF	\$2,674	
Chalk Board	Classroom	Chalk Board		4	26	LF	\$3,160	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Corridors	Corridors	Asphalt	2nd Floor	6	2,349	SF	\$3,359	
Corridors	Corridors	Asphalt	1st Floor	6	4,745	SF	\$6,785	
Corridors	Corridors	Asphalt	Entire building stair wells	6	2,130	SF	\$3,046	
Corridors	Corridors	Asphalt	3rd Floor	6	2,349	SF	\$3,359	
Corridors	Corridors	Drop/Lay-In	2nd Floor	6	2,554	SF	\$5,478	
Corridors	Corridors	Drop/Lay-In	1st Floor	6	4,157	SF	\$8,917	
Corridors	Corridors	Drop/Lay-In	3rd Floor	6	2,554	SF	\$5,478	
Corridors	Corridors	Lay-In	1st Floor	6	4,157	EA	\$2,972	
Corridors	Corridors	Lay-In	2nd Floor	6	2,554	EA	\$1,826	
Corridors	Corridors	Lay-In	3rd Floor	6	2,554	EA	\$1,826	
Corridors	Corridors	Pendant/Surface	1st Floor	6	900	EA	\$644	
Corridors	Corridors	Pendant/Surface	Entire building stair wells	6	2,130	EA	\$1,523	
Corridors	Corridors	Plaster/Drywall	2nd Floor	6	4,707	SF	\$11,106	
Corridors	Corridors	Plaster/Drywall	Entire building stair wells	6	3,444	SF	\$8,126	
Corridors	Corridors	Plaster/Drywall	1st Floor	6	10,807	SF	\$25,499	
Corridors	Corridors	Plaster/Drywall	3rd Floor	6	4,707	SF	\$11,106	
Corridors	Corridors	Stair Handrails	Entire building stair wells	6	206	LF	\$0	
Corridors	Corridors	Structural Glazed Tile	1st Floor	6	612	SF	\$4,376	
Corridors	Corridors	Terrazzo	2nd Floor	6	205	SF	\$1,161	
Corridors	Corridors	Terrazzo	3rd Floor	6	205	SF	\$1,161	
Corridors	Corridors	Tile/Sheet Flooring	1st Floor	6	633	SF	\$905	
Corridors Ceiling	Corridors	Plaster/Drywall	1st Floor	6	900	SF	\$2,548	
Corridors Ceiling	Corridors	Plaster/Drywall	Entire building stair wells	6	2,130	SF	\$6,031	
Stairs	Corridors	Asphalt	Entire building stair wells	6	96	SF	\$686	
Floor	Classroom	Carpet		6	415	SF	\$593	
Floor	Classroom	Tile/Sheet		6	910	SF	\$1,301	
Floor	Classroom	Tile/Sheet		6	423	SF	\$605	
Floor	Classroom	Tile/Sheet		6	888	SF	\$1,270	
Floor	Classroom	Wood		6	866	SF	\$6,539	
Floor	Classroom	Wood		6	938	SF	\$7,082	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Floor	Classroom	Wood		6	602	SF	\$4,545	
Floor	Classroom	Wood		6	888	SF	\$6,705	
Floor	Classroom	Wood		6	888	SF	\$6,705	
Floor	Classroom	Wood		6	909	SF	\$6,863	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	415	SF	\$3,133	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	927	SF	\$6,999	
Floor	Classroom	Wood		6	908	SF	\$6,856	
Floor	Classroom	Wood		6	554	SF	\$4,183	
Floor	Classroom	Wood		6	888	SF	\$6,705	
Floor	Classroom	Wood		6	934	SF	\$7,052	
Floor	Classroom	Wood		6	877	SF	\$6,622	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	879	SF	\$6,637	
Floor	Classroom	Wood		6	888	SF	\$6,705	
Floor	Classroom	Wood		6	903	SF	\$6,818	
Floor	Classroom	Wood		6	909	SF	\$6,863	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Floor	Classroom	Wood		6	881	SF	\$6,652	
Floor	Classroom	Wood		6	938	SF	\$7,082	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	30	EA	\$2,145	
Lighting	Classroom	Lay-In		6	18	EA	\$1,287	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	21	EA	\$1,502	
Lighting	Classroom	Lay-In		6	6	EA	\$429	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lighting	Classroom	Lay-In		6	8	EA	\$572	
Lighting	Classroom	Lay-In		6	3	EA	\$215	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	21	EA	\$1,502	
Lighting	Classroom	Lay-In		6	21	EA	\$1,502	
Lighting	Classroom	Lay-In		6	21	EA	\$1,502	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Lighting	Classroom	Lay-In		6	10	EA	\$715	
Lighting	Classroom	Lay-In		6	14	EA	\$1,001	
Marker Board	Classroom	Marker Board		6	16	LF	\$458	
Marker Board	Classroom	Marker Board		6	12	LF	\$343	
Marker Board	Classroom	Marker Board		6	8	LF	\$229	
Marker Board	Classroom	Marker Board		6	20	LF	\$572	
Marker Board	Classroom	Marker Board				LF	\$0	
Wall	Classroom	Masonry		6	258	SF	\$3,320	
Wall	Classroom	Plaster/Drywall		6	1,017	SF	\$2,400	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,127	SF	\$2,659	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,249	SF	\$2,947	
Wall	Classroom	Plaster/Drywall		6	850	SF	\$2,006	
Wall	Classroom	Plaster/Drywall		6	1,127	SF	\$2,659	
Wall	Classroom	Plaster/Drywall		6	1,034	SF	\$2,440	
Wall	Classroom	Plaster/Drywall		6	1,150	SF	\$2,713	
Wall	Classroom	Plaster/Drywall		6	1,300	SF	\$3,067	
Wall	Classroom	Plaster/Drywall		6	1,022	SF	\$2,411	
Wall	Classroom	Plaster/Drywall		6	1,070	SF	\$2,525	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,070	SF	\$2,525	
Wall	Classroom	Plaster/Drywall		6	1,150	SF	\$2,713	
Wall	Classroom	Plaster/Drywall		6	1,150	SF	\$2,713	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,003	SF	\$2,367	
Wall	Classroom	Plaster/Drywall		6	1,687	SF	\$3,980	
Wall	Classroom	Plaster/Drywall		6	1,409	SF	\$3,325	
Wall	Classroom	Plaster/Drywall		6	887	SF	\$2,093	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
Wall	Classroom	Plaster/Drywall		6	1,249	SF	\$2,947	
Wall	Classroom	Plaster/Drywall		6	1,070	SF	\$2,525	
Wall	Classroom	Plaster/Drywall		6	1,512	SF	\$3,568	
Wall	Classroom	Plaster/Drywall		6	850	SF	\$2,006	
Wall	Classroom	Plaster/Drywall		6	1,232	SF	\$2,907	
ROOM Sub Total							\$533,273	
Building Main Sub Total							\$5,862,463	

Building: Addition
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Chimney		Metal Flue	Roof	7	20	LF	\$0	
Doors		Exterior Steel Door	1st Floor	6	19	EA	\$6,276	
Doors		Transom Lite	1st Floor	6	4	EA	\$1,133	
Entrance		Concrete Exterior Stairs	1st Floor	6	360	LF	\$38,610	
Entrance		Entrance Controls - Audio and Video	1st Floor	7	2	EA	\$0	
Entrance		Stair Handrails	1st Floor	6	24	LF	\$0	
Foundation		Concrete Foundation	Entire Building	7	835	LF	\$0	
Lighting		Exterior Lights - Wall Mounted	Entire Building	6	22	EA	\$4,719	
Lintels		Lintels - Steel	Entire Building	7	782	LF	\$0	
Parapet		Coping - Stone	Roof	6	1,039	LF	\$0	
Parapet		Parapet > 30" Height	Roof	6	147	LF	\$38,153	
Parapet		Parapet 16" to 30" Height	Roof	7	889	LF	\$0	
Roof System		Interior Downspouts	Roof	6	546	LF	\$0	
Roof System		Modified Bitumen Roof	Roof	6	28,536	SF	\$201,992	
Roof System		Roof Structure: Steel/Metal Deck/Concrete Topping	Roof	7	28,536	SF	\$0	
Superstructure		Metal Deck/Concrete Topping	Entire Building	7	71,850	SF	\$0	
Walls		Brick	Entire Building	7	31,159	SF	\$0	
Walls		Stone - Cast	Entire Building	6	11,016	SF	\$157,529	

Building: Addition
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Windows		Window - Guards perforated	1st Floor	6	1,465	SF	\$0	
Windows		Windows - Sash Aluminum Double-pane	Entire Building	6	5,660	SF	\$48,563	
EXTERIOR Sub Total							\$496,975	

Building: Addition
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Emergency System		Automatic Transfer switch	Mechanical Room	2	1	EA	\$8,866	There is no source to switch to should the power fail.
Emergency System		Emergency A/C power - Corridors and Stairs	Entire Building	7	71,850	SF	\$0	
Emergency System		Emergency A/C power - Gym and Lunch rooms	Gym/Multi Purpose Room	7	6,280	SF	\$0	
Emergency System		Emergency A/C power - Students Toilets	Student Toilets	7	1,260	SF	\$0	
Emergency System		Emergency Battery Packs - Corridors and Stairs	Corridors and Stairs	6	20	EA	\$2,145	Batteries
Emergency System		Emergency Battery Packs - Lunchroom and Gym	Gym/Multi Purpose Room	6	8	EA	\$858	Batteries
Emergency System		Emergency Battery Packs - Toilets	Student Toilets	6	3	EA	\$322	Batteries
Emergency System		Exit Signs - Corridors and Stairs	Corridors and Stairs	2	20	EA	\$18,590	Batteries need replacing and UPS is not working
Emergency System		Exit Signs - Lunchroom - Gym - multipurpose rooms	Gym/Multi Purpose Room	2	8	EA	\$7,436	Batteries need replacing and UPS is not working
Emergency System		Independent Electrical Service for emergency power	Mechanical Room	6	1	EA	\$1,430	
Emergency System		Public Announcement System	Entire Building	7	71,850	SF	\$0	
Emergency System		Security System - Intrusion detection	Mechanical Room	6	71,850	SF	\$66,785	RM
Main Service		Main Electrical service 2000 A 277/480/3PH	Mechanical Room	6	1	EA	\$15,194	
Power Distribution		Lighting and power panels	Mechanical Room	4	1	EA	\$5,434	Fuses
Power Distribution		Lighting and power panels	Entire Building	6	13	EA	\$9,295	
Power Distribution		Main distribution panels 400-600 amp	Mechanical Room	6	2	EA	\$2,860	
Power Distribution		Main distribution panels above 600 amp	Mechanical Room	6	5	EA	\$10,725	
Power Distribution		Main distribution panels less than 400 amp	Mechanical Room	6	2	EA	\$2,431	
Power Distribution		Transformers 277/480-120/208	Mechanical Room	7	3	EA	\$0	
Power Distribution		Transformers 277/480-120/208	Boiler Room	6	1	EA	\$1,144	Hot and Excessive hum
ELECTRICAL Sub Total							\$153,514	

Building: Addition
Category: FIRE PROTECTION

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Fire Alarm		Fire Alarm Strobe Lights	Entire Building	6	71,850	SF	\$25,686	

Building: Addition
Category: FIRE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Fire Alarm		Fire Pump Controller	Mechanical Room	6	1	EA	\$2,145	
Pump Room Assembly		Fire Pump 25-50hp	Mechanical Room	6	1	EA	\$3,718	
Pump Room Assembly		Jockey Pump	Mechanical Room	6	1	EA	\$744	
Sprinkler System		Sprinkler Heads	Entire Building	7	71,850	SF	\$0	
Sprinkler System		Wet Sprinkler System	Entire Building	7	71,850	SF	\$0	
FIRE PROTECTION Sub Total							\$32,293	

Building: Addition
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Air Conditioning		Chillers - Air Cooled - Rotary/Screw type - Roof Mounted 100 to 200 tons	Roof	5	2	EA	\$278,850	Substantial Hail Damage to Condenser Coil Fins. Piping Insulation needs repair and sealing. Pipe Hangers were not galvanized or painted and are rusting.
Air Conditioning		Condensing Unit - Roof Mounted less than 5 tons	Roof - Unit is for the MDF Room	7	1	EA	\$0	
Air Handling Systems		Air Handling Unit Package - Single Zone - Hot Water 4,000 to 8,000 cfm	Mechanical Room	6	1	EA	\$5,005	
Air Handling Systems		Air Handling Unit Package - Single Zone - Hot Water 12,001 to 20,000 cfm	Mechanical Room	6	2	EA	\$15,158	Routine Maintenance
Air Handling Systems		Air Handling Unit Package - Single Zone - Hot Water above 30,000 cfm	Mechanical Room	6	1	EA	\$21,450	
Air Handling Systems		Air intake for all Air Handling Units except built up AHU	Exterior Facades	6	4	EA	\$5,720	
Air Handling Systems		Fan Coil Unit - Hot Water-Heating	Entire Building	6	6	EA	\$8,065	Routine Maintenance
Air Handling Systems		Fan Power Box With Hot Water Coil	Entire Building	5	27	EA	\$52,124	Routine Maintenance
Air Handling Systems		Make Up Air Unit - Indoor Mounted - Hot Water less than 6000 cfm	Mechanical Room	6	1	EA	\$2,002	Routine Maintenance
Air Handling Systems		Return Fans - Indoor 10,001 to 20,000 CFM	Mechanical Room	6	2	EA	\$4,862	Routine Maintenance
Air Handling Systems		Return Fans - Indoor 5,000 to 10,000 CFM	Mechanical Room	6	1	EA	\$1,716	Routine Maintenance
Air Handling Systems		Return Fans - Indoor greater than 20,000 CFM	Mechanical Room	6	1	EA	\$3,289	Routine Maintenance
Air Handling Systems		Variable Air Volume (VAV) Box With Hot Water Coil	Entire Building	6	16	EA	\$5,262	Routine Maintenance
Boiler Systems		Boiler Assembly - Non-Condensing Flexible Tube Hot Water Boiler 3,001MBH-4,000 MBH	Boiler Room	5	3	EA	\$195,195	Evidence of Burner Blow Back
Boiler Systems		Boiler Auxiliary Non-Condensing Hot Water Boiler 3,001MBH-4,000 MBH	Boiler Room	7	3	EA	\$0	
Boiler Systems		Chemical Pot Feeder - Hot Water	Boiler Room	7	2	EA	\$0	

Building: Addition
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Boiler Systems		Combustion Dampers	Boiler Room	4	1	EA	\$5,577	One Damper for 3 Boilers Does not open fully
Boiler Systems		Combustion Dampers	Boiler Room	6	1	EA	\$286	
Boiler Systems		Gas Boosters	Boiler Room	7	1	EA	\$0	
Boiler Systems		Glycol Feed System	Boiler Room	6	2	EA	\$2,174	
Heating Devices		Radiators - Hot Water	Entire Building	7	18	EA	\$0	
Heating Devices		Unit Heater - Electric	Mechanical Room	6	10	EA	\$14,300	Routine Maintenance
Mechanical Plumbing		Piping - Hydronic Supply and Return - Steel or Galvanized	Roof	6	700	LF	\$6,206	Roof Insulation and pipe hangers need repair and or painting
Mechanical Plumbing		Pumps - Chilled Water 10 to 20 HP	Boiler Room	6	2	EA	\$5,148	Routine Maintenance
Mechanical Plumbing		Pumps - Chilled Water 10 to 20 HP	Boiler Room	6	3	EA	\$7,722	Routine Maintenance
Mechanical Plumbing		Pumps - Hot Water 11 to 20 HP	Boiler Room	6	2	EA	\$5,148	Routine Maintenance
Temperature Control		Direct Digital Control (DDC) System	Entire Building	6	71,850	SF	\$71,922	
Temperature Control		Thermostats - Direct Digital Control (DDC)	Entire Building	6	56	EA	\$8,008	
Ventilation		Exhaust Fan - Indoor	Mechanical Room	6	5	EA	\$2,503	Routine Maintenance
Ventilation		Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm	Roof	5	1	EA	\$1,502	Ponding / Standing water on iron duct is rusting.
Ventilation		Exhaust Fans - Roof Mounted 500 to 1,500 cfm	Roof	6	2	EA	\$458	Routine Maintenance
Ventilation		Exhaust Fans - Roof Mounted 500 to 1,500 cfm	Roof	6	1	EA	\$229	Routine Maintenance
Ventilation		Exhaust Fans - Roof mounted less than 500 CFM	Roof	6	1	EA	\$157	Routine Maintenance
Ventilation		Type I Exhaust Hood - Kitchen or Culinary Arts	Kitchen	7	1	EA	\$0	
Ventilation		Type II Exhaust Hood - Warming Kitchen	Kitchen	7	1	EA	\$0	

MECHANICAL Sub Total \$730,036

Building: Addition
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Hot Water		Hot Water Heater - Gas more than 300,000 BTU/HR	Boiler Room	6	2	EA	\$13,442	
Hot Water		Storage Tank less than 500 gallons	Boiler Room	6	1	EA	\$1,859	
Piping		Domestic Piping - Cold Water from Risers to Fixtures	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping - Cold Water Risers	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping - Hot Water from Riser to fixtures	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping - Hot Water Return Risers	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping - Hot Water Risers	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping Cold Water Horizontal lines	Entire Building	7	71,850	SF	\$0	

Building: Addition
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Piping		Domestic Piping Hot Water Horizontal lines	Entire Building	7	71,850	SF	\$0	
Piping		Domestic Piping Hot Water Return Lines	Entire Building	7	71,850	SF	\$0	
Piping		Sanitary Piping	Entire Building	7	71,850	SF	\$0	
Piping		Storm Piping	Entire Building	7	71,850	SF	\$0	
Piping		Vent Piping	Entire Building	7	71,850	SF	\$0	
Pumps		Domestic Booster Pump duplex	Mechanical Room	6	1	EA	\$3,146	
Pumps		Sump Pump	Elevator Sump	6	1	EA	\$1,359	

PLUMBING Sub Total **\$19,806**

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Exposed	Third floor, west end, engineers office	7	1,092	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Second floor, east end, room 237	7	174	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Second floor, library, workroom/office	7	200	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	second floor, room 227, teacher resource room	7	448	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	First floor, main office	6	763	SF	\$1,637	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	First floor, east, main office, faculty center	7	274	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	First floor, east, main office, principal office	7	413	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	First floor, kitchen office	6	73	SF	\$157	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Third floor, room 338	5	211	SF	\$1,195	large amount of stained tiles
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	First floor, west end, adjacent to multipurpose	6	287	SF	\$616	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	First floor, main office	6	634	SF	\$907	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	First floor, east, main office, faculty center	6	274	SF	\$392	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	First floor, east, main office, principal office	6	413	SF	\$591	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	First floor, kitchen office	6	73	SF	\$344	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	Third floor, west end, engineers office	6	1,092	SF	\$5,153	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Flooring - Terrazzo	First floor, main office	7	129	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	second floor, room 227, teacher resource room	7	448	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	First floor, west end, adjacent to multipurpose	7	287	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Third floor,room 338	6	211	SF	\$302	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Second floor, east end, room 237	6	174	SF	\$249	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Second floor, library, workroom/office	7	200	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	First floor, east, main office, principal office	6	4	SF	\$3	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	First floor, west end, adjacent to multipurpose	6	4	SF	\$3	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	First floor, east, main office, faculty center	6	3	SF	\$2	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	First floor, main office	6	13	SF	\$9	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	second floor, room 227, teacher resource room	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Second floor, library, workroom/office	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Second floor, east end, room 237	7	1	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	First floor, kitchen office	6	1	SF	\$1	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Third floor,room 338	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Third floor, west end, engineers office	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	First floor, east, main office, principal office	6	340	SF	\$972	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Second floor, library, workroom/office	7	100	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Third floor,room 338	6	599	SF	\$1,713	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	First floor, west end, adjacent to multipurpose	6	708	SF	\$2,025	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	First floor, east, main office, faculty center	6	287	SF	\$821	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	First floor, main office	6	1,105	SF	\$3,160	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	second floor, room 227, teacher resource room	6	630	SF	\$1,802	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	First floor, kitchen office	6	320	SF	\$915	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Third floor, west end, engineers office	6	1,618	SF	\$4,627	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Second floor, east end, room 237	6	418	SF	\$1,195	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	second floor, room 227, teacher resource room	6	310	SF	\$731	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	First floor, east, main office, faculty center	6	547	SF	\$1,291	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	First floor, main office	6	770	SF	\$1,817	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	Third floor, west end, engineers office	6	1,228	SF	\$2,897	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	Second floor, library, workroom/office	6	580	SF	\$1,369	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	First floor, east, main office, principal office	6	662	SF	\$1,562	
Doors		Interior Steel Doors incl hw	3rd Floor	7	10	EA	\$0	
Doors		Interior Steel Doors incl hw	1st Floor	7	9	EA	\$0	
Doors		Interior Steel Doors incl hw	2nd Floor	7	7	EA	\$0	
Doors		Interior Wood Doors incl hw	3rd Floor	7	25	EA	\$0	
Doors		Interior Wood Doors incl hw	2nd Floor	7	27	EA	\$0	
Doors		Interior Wood Doors incl hw	1st Floor	7	58	EA	\$0	
Doors		Side-lite	1st Floor	7	65	SF	\$0	
Doors		Side-lite	2nd Floor	7	117	SF	\$0	
Doors		Side-lite	3rd Floor	7	117	SF	\$0	
Drinking Fountains	Corridors	Double Fountain	1st Floor	7	1	EA	\$0	
Kitchen	Cooking Kitchen	Ceiling - Lay-In	1st Floor	6	817	SF	\$2,337	
Kitchen	Cooking Kitchen	Flooring - Concrete	1st Floor	6	817	SF	\$3,855	
Kitchen	Cooking Kitchen	Lighting - Lay-In	1st Floor	6	10	SF	\$7	
Kitchen	Cooking Kitchen	Wall - Concrete Block	1st Floor	6	1,442	SF	\$4,124	
Library		Casework	2nd Floor	6	76	LF	\$2,331	
Library	Library	Flooring Carpet	2nd Floor	6	2,463	SF	\$3,522	
Library	Library	Lighting - Lay-In	2nd Floor	6	28	SF	\$20	
Lunchroom	Multipurpose Room	Ceiling - Exposed	First floor, west end, multipurpose room and servery	7	5,240	SF	\$0	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lunchroom	Multipurpose Room	Ceiling - Lay-In	First floor, west end, multipurpose room and servery	6	1,040	SF	\$2,231	
Lunchroom	Multipurpose Room	Flooring - Tile/Sheet	First floor, west end, multipurpose room and servery	6	6,280	SF	\$8,980	
Lunchroom	Multipurpose Room	Lighting - Lay-In	First floor, west end, multipurpose room and servery	6	15	SF	\$11	
Lunchroom	Multipurpose Room	Lighting - Pendant/Surface	First floor, west end, multipurpose room and servery	6	12	SF	\$9	
Lunchroom	Multipurpose Room	Serving Line	First floor, west end, multipurpose room and servery	7	28	LF	\$0	
Lunchroom	Multipurpose Room	Wall - Concrete Block	First floor, west end, multipurpose room and servery	6	10,046	SF	\$28,732	
MDF/IDF		Finishes	second floor, west end, room 222	6	140	SF	\$476	
MDF/IDF		Ventilation and Cooling	second floor, west end, room 222	7	140	EA	\$0	
Mechanical/Service Rooms		Boiler Room	Third floor, west end, boiler room	7	1,889	SF	\$0	
Mechanical/Service Rooms		Janitor's Closet	2nd Floor	6	1	SF	\$5	
Mechanical/Service Rooms		Janitor's Closet	3rd Floor	6	1	SF	\$5	
Mechanical/Service Rooms		Janitor's Closet	1st Floor	6	2	SF	\$9	
Mechanical/Service Rooms		Mechanical/Service Rooms	First floor, west end, dish wash	6	159	SF	\$750	
Mechanical/Service Rooms		Mechanical/Service Rooms	First floor, east end, room 130	7	273	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Third floor, west end, electrical room 330	7	83	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Second floor, west end, fan room	6	3,951	SF	\$18,645	
Mechanical/Service Rooms		Mechanical/Service Rooms	Second floor, west end, room 230	6	81	SF	\$382	
Mechanical/Service Rooms		Mechanical/Service Rooms	Second floor, east end, inside of elevator machine room	7	54	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Second floor, east end, elevator machine room	7	153	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	First floor, east end, room 131	6	275	SF	\$1,298	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Mechanical/Service Rooms		Storage Room	First floor, gym storage	6	345	SF	\$1,628	
Mechanical/Service Rooms		Storage Room	224	7	211	SF	\$0	
Mechanical/Service Rooms		Storage Room	Third floor, west end, storage room	6	1,221	SF	\$5,762	
Mechanical/Service Rooms		Storage Room	Third floor, west end, room 327	6	153	SF	\$722	
Mechanical/Service Rooms		Storage Room	Second floor, room 329	7	210	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, room 126	7	41	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, room 122	7	41	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, room 121, storage	7	41	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, room 128, storage	7	41	SF	\$0	
Mechanical/Service Rooms		Storage Room	Second floor, room328	7	162	SF	\$0	
Mechanical/Service Rooms		Storage Room	East end, storage room 332	6	70	SF	\$330	
Mechanical/Service Rooms		Storage Room	Second floor, library	7	21	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, west end, room 127	7	234	SF	\$0	
Mechanical/Service Rooms		Storage Room	First floor, kitchen food storage	6	138	SF	\$651	
Mechanical/Service Rooms		Storage Room	First floor, east end, room 129A	6	54	SF	\$255	
Mechanical/Service Rooms		Storage Room	First floor, east end, room 132	6	65	SF	\$307	
Mechanical/Service Rooms		Storage Room	Third floor, east end, room 337	7	337	SF	\$0	
Mechanical/Service Rooms		Storage Room	Third floor, east end, room 232	6	66	SF	\$311	
Mechanical/Service Rooms		Storage Room	First floor, room 123	6	41	SF	\$193	
Mechanical/Service Rooms		Storage Room	First floor, east end,room 129B	7	59	SF	\$0	
Mechanical/Service Rooms		Vaults	First floor, main office	7	167	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Accessories	first floor, class 126	7	38	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	First floor, main office	6	51	SF	\$394	
Staff Restroom	Early Childhood Student Restroom	Accessories	first floor, class 122	7	38	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	First floor, east end	7	45	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	First floor, kitchen	6	42	SF	\$324	
Staff Restroom	Early Childhood Student Restroom	Accessories	first floor, class 128	7	38	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	First floor, east end, girls	6	210	SF	\$1,622	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Accessories	First floor, east end, boys	6	210	SF	\$1,622	
Staff Restroom	Children's Standard Student Restroom	Accessories	Second floor, east end, boys	6	210	SF	\$1,622	
Staff Restroom	Children's Standard Student Restroom	Accessories	Third floor, east end, girls	6	210	SF	\$1,622	
Staff Restroom	Children's Standard Student Restroom	Accessories	Third floor, east end, boys	6	210	SF	\$1,622	
Staff Restroom	Staff Restroom	Accessories	Third floor, east end	7	45	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Accessories	first floor, class 121	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Accessories	first floor, class 123	7	38	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	Second floor, east end, girls	6	210	SF	\$1,622	
Staff Restroom	Staff Restroom	Accessories	Second floor, east end	7	45	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	First floor, kitchen	6	42	SF	\$90	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	first floor, class 121	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	first floor, class 128	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	first floor, class 122	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	first floor, class 126	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	first floor, class 123	7	38	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	First floor, east end, girls	6	210	SF	\$595	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	First floor, main office	6	51	SF	\$144	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	First floor, east end	6	45	SF	\$127	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	Third floor, east end, boys	6	210	SF	\$595	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	Third floor, east end, girls	6	210	SF	\$595	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	Second floor, east end	6	45	SF	\$127	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	Second floor, east end, boys	6	210	SF	\$595	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	Second floor, east end, girls	6	210	SF	\$595	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	Third floor, east end	6	45	SF	\$127	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	First floor, east end, boys	6	210	SF	\$595	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Floor Drain	First floor, east end, girls	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	first floor, class 122	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	first floor, class 126	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	first floor, class 123	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	First floor, kitchen	6	1	EA	\$300	
Staff Restroom	Staff Restroom	Floor Drain	First floor, main office	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	first floor, class 128	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	First floor, east end	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	first floor, class 121	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Third floor, east end	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Third floor, east end, boys	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Third floor, east end, girls	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	First floor, east end, boys	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Second floor, east end, girls	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Second floor, east end, boys	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Second floor, east end	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Flooring - Concrete	First floor, kitchen	6	42	SF	\$198	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	Second floor, east end, boys	7	210	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	Second floor, east end, girls	7	210	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	Third floor, east end, girls	7	210	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	First floor, east end, boys	7	210	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Terrazzo	Second floor, east end	7	45	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	Third floor, east end, boys	7	210	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Terrazzo	First floor, east end, girls	7	210	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Terrazzo	First floor, east end	7	45	SF	\$0	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Flooring - Terrazzo	Third floor, east end	7	45	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	first floor, class 122	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	first floor, class 123	7	38	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	First floor, main office	7	51	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	first floor, class 121	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	first floor, class 128	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile/Sheet	first floor, class 126	7	38	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Lavatory	first floor, class 126	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Lavatory	first floor, class 123	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Second floor, east end, boys	6	3	EA	\$1,115	
Staff Restroom	Staff Restroom	Lavatory	Third floor, east end	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Second floor, east end, girls	6	3	EA	\$1,115	
Staff Restroom	Early Childhood Student Restroom	Lavatory	first floor, class 128	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Lavatory	first floor, class 121	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	First floor, kitchen	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lavatory	First floor, main office	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Lavatory	First floor, east end	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Lavatory	First floor, east end, girls	6	3	EA	\$1,115	
Staff Restroom	Early Childhood Student Restroom	Lavatory	first floor, class 122	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	First floor, east end, boys	6	3	EA	\$1,115	
Staff Restroom	Staff Restroom	Lavatory	Second floor, east end	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Third floor, east end, girls	6	3	EA	\$1,115	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Third floor, east end, boys	6	3	EA	\$1,115	
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	first floor, class 121	6	1	SF	\$1	
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	first floor, class 122	6	1	SF	\$1	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	first floor, class 123	6	1	SF	\$1	
Staff Restroom	Staff Restroom	Lighting - Lay-In	First floor, kitchen	6	1	SF	\$1	
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	first floor, class 128	6	1	SF	\$1	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	Second floor, east end, boys	7	5	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	First floor, east end	6	1	SF	\$1	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	First floor, east end, girls	7	5	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	Third floor, east end, girls	6	5	SF	\$4	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	First floor, east end, boys	7	5	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Second floor, east end	6	1	SF	\$1	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	Second floor, east end, girls	7	5	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	First floor, main office	6	1	SF	\$1	
Staff Restroom	Children's Standard Student Restroom	Lighting - Lay-In	Third floor, east end, boys	6	5	SF	\$4	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Third floor, east end	6	1	SF	\$1	
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	first floor, class 126	6	1	SF	\$1	
Staff Restroom	Children's Standard Student Restroom	Partitions	Third floor, east end, girls	6	4	EA	\$717	
Staff Restroom	Children's Standard Student Restroom	Partitions	Third floor, east end, boys	6	2	EA	\$359	
Staff Restroom	Children's Standard Student Restroom	Partitions	Second floor, east end, boys	6	2	EA	\$359	
Staff Restroom	Children's Standard Student Restroom	Partitions	Second floor, east end, girls	6	4	EA	\$717	
Staff Restroom	Children's Standard Student Restroom	Partitions	First floor, east end, boys	6	2	EA	\$359	
Staff Restroom	Children's Standard Student Restroom	Partitions	First floor, east end, girls	6	4	EA	\$717	
Staff Restroom	Children's Standard Student Restroom	Urinals	Second floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Children's Standard Student Restroom	Urinals	Third floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Children's Standard Student Restroom	Urinals	First floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Staff Restroom	Wall - Concrete Block	First floor, east end	7	210	SF	\$0	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	First floor, east end, girls	7	592	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	First floor, east end, boys	7	592	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	first floor, class 122	7	196	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	first floor, class 126	7	196	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	first floor, class 123	7	196	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	Second floor, east end, girls	7	592	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	Second floor, east end, boys	7	592	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	First floor, main office	6	284	SF	\$812	
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	Third floor, east end, girls	7	592	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	Second floor, east end	7	210	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Concrete Block	Third floor, east end, boys	7	592	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	First floor, kitchen	6	208	SF	\$595	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	first floor, class 121	7	196	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	first floor, class 128	7	196	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	Third floor, east end	7	210	SF	\$0	
Staff Restroom	Staff Restroom	Water Closet	First floor, east end	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Water Closet	first floor, class 123	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Water Closet	first floor, class 126	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Third floor, east end, girls	6	4	EA	\$1,487	
Staff Restroom	Early Childhood Student Restroom	Water Closet	first floor, class 122	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Third floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Early Childhood Student Restroom	Water Closet	first floor, class 128	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Third floor, east end	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	First floor, kitchen	6	1	EA	\$372	
Staff Restroom	Children's Standard Student Restroom	Water Closet	First floor, east end, girls	6	4	EA	\$1,487	

Building: Addition
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Early Childhood Student Restroom	Water Closet	first floor, class 121	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	First floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Second floor, east end, girls	6	4	EA	\$1,487	
Staff Restroom	Staff Restroom	Water Closet	Second floor, east end	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Second floor, east end, boys	6	2	EA	\$744	
Staff Restroom	Staff Restroom	Water Closet	First floor, main office	7	1	EA	\$0	
Vertical Conveyance		Elevator - Roped Holeless Hydraulic	East end of building, all three floors	6	1	EA	\$17,160	
Vocational Shop	Classroom	Work Sink		6	2	EA	\$772	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	2	EA	\$772	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		7	1	EA	\$0	
Vocational Shop	Classroom	Work Sink		6	1	EA	\$386	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	1	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	1	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	1	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	2	EA	\$0	
Vocational Shop	Classroom	Work Sink		7	1	EA	\$0	
INTERIOR Sub Total							\$185,008	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		6	51	LF	\$1,823	
Casework	Classroom	Casework		6	51	LF	\$1,823	
Casework	Classroom	Casework		6	51	LF	\$1,823	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		6	51	LF	\$1,823	
Casework	Classroom	Casework		6	56	LF	\$2,002	
Casework	Classroom	Casework		6	56	LF	\$2,002	
Casework	Classroom	Casework		6	51	LF	\$1,823	
Casework	Classroom	Casework		6	66	LF	\$2,360	
Casework	Classroom	Casework		6	48	LF	\$1,716	
Casework	Classroom	Casework		7	24	LF	\$0	
Casework	Classroom	Casework		6	51	LF	\$1,823	
Casework	Classroom	Casework		7	24	LF	\$0	
Casework	Classroom	Casework		7	24	LF	\$0	
Casework	Classroom	Casework		7	6	LF	\$0	
Casework	Classroom	Casework		7	24	LF	\$0	
Casework	Classroom	Casework		7	24	LF	\$0	
Casework	Classroom	Casework		6	66	LF	\$2,360	
Casework	Classroom	Casework		6	66	LF	\$2,360	
Casework	Classroom	Casework		6	66	LF	\$2,360	
Casework	Classroom	Casework		6	66	LF	\$2,360	
Ceiling	Classroom	Lay-In/Drop		7	1,053	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		6	900	SF	\$1,931	water damage in corner
Ceiling	Classroom	Lay-In/Drop		6	900	SF	\$1,931	
Ceiling	Classroom	Lay-In/Drop		6	1,098	SF	\$2,355	
Ceiling	Classroom	Lay-In/Drop		6	852	SF	\$1,828	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	1,098	SF	\$2,355	
Ceiling	Classroom	Lay-In/Drop		6	1,044	SF	\$2,239	
Ceiling	Classroom	Lay-In/Drop		7	848	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		6	1,098	SF	\$2,355	
Ceiling	Classroom	Lay-In/Drop		7	900	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,073	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		6	900	SF	\$1,931	water damage in corner near window
Ceiling	Classroom	Lay-In/Drop		7	1,073	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	900	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		6	852	SF	\$1,828	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	852	SF	\$1,828	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	852	SF	\$1,828	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	1,019	SF	\$2,186	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	852	SF	\$1,828	Sagging tiles
Ceiling	Classroom	Lay-In/Drop		6	900	SF	\$1,931	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	23	LF	\$2,796	
Chalk Board	Classroom	Chalk Board		4	23	LF	\$2,796	
Chalk Board	Classroom	Chalk Board		4	23	LF	\$2,796	
Chalk Board	Classroom	Chalk Board		4	23	LF	\$2,796	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	23	LF	\$2,796	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	24	LF	\$2,917	
CLASSROOM	Classroom	Laptop Charging Station		7	1	EA	\$0	
CLASSROOM	Classroom	Laptop Charging Station		7	1	EA	\$0	
Corridors	Corridors	Ceiling	2nd Floor	6	4,714	SF	\$13,347	
Corridors	Corridors	Concrete Block	Stairs, entire building	7	9,959	SF	\$0	
Corridors	Corridors	Concrete Block	1st Floor	7	6,434	SF	\$0	
Corridors	Corridors	Concrete Block	3rd Floor	7	6,207	SF	\$0	
Corridors	Corridors	Concrete Block	2nd Floor	7	6,207	SF	\$0	
Corridors	Corridors	Drinking Fountains	3rd Floor	7	1	EA	\$0	
Corridors	Corridors	Drinking Fountains	2nd Floor	7	1	EA	\$0	
Corridors	Corridors	Drop/Lay-In	Stairs, entire building	6	953	SF	\$2,044	
Corridors	Corridors	Drop/Lay-In	1st Floor	6	4,068	SF	\$8,726	
Corridors	Corridors	Drop/Lay-In	3rd Floor	6	4,714	SF	\$10,112	
Corridors	Corridors	Lay-In	3rd Floor	6	4,171	EA	\$2,982	
Corridors	Corridors	Lay-In	1st Floor	6	4,395	EA	\$3,142	
Corridors	Corridors	Lay-In	2nd Floor	6	4,171	EA	\$2,982	
Corridors	Corridors	Lay-In	Stairs, entire building	6	1,457	EA	\$1,042	
Corridors	Corridors	Pendant/Surface	Stairs, entire building	6	1,457	EA	\$1,042	
Corridors	Corridors	Plaster/Drywall	Stairs, entire building	6	95	SF	\$224	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Corridors	Corridors	Stair Handrails	Stairs, entire building	7	370	LF	\$0	
Corridors	Corridors	Structural Glazed Tile	1st Floor	6	1,304	SF	\$9,324	
Corridors	Corridors	Terrazzo	Stairs, entire building	7	1,457	SF	\$0	
Corridors	Corridors	Terrazzo	3rd Floor	7	4,714	SF	\$0	
Corridors	Corridors	Terrazzo	2nd Floor	7	4,714	SF	\$0	
Corridors	Corridors	Terrazzo	1st Floor	7	4,935	SF	\$0	
Corridors Ceiling	Corridors	Plaster/Drywall	1st Floor	6	867	SF	\$2,455	
Corridors Ceiling	Corridors	Plaster/Drywall	Stairs, entire building	6	428	SF	\$1,212	
Stairs	Corridors	Terrazzo	Stairs, entire building	7	149	SF	\$0	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		6	1,053	SF	\$1,506	
Floor	Classroom	Tile/Sheet		6	1,044	SF	\$1,493	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		6	848	SF	\$1,213	
Floor	Classroom	Tile/Sheet		7	852	SF	\$0	
Floor	Classroom	Tile/Sheet		7	852	SF	\$0	
Floor	Classroom	Tile/Sheet		7	852	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,019	SF	\$0	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		7	852	SF	\$0	
Floor	Classroom	Tile/Sheet		6	1,073	SF	\$1,534	
Floor	Classroom	Tile/Sheet		6	1,098	SF	\$1,570	
Floor	Classroom	Tile/Sheet		6	1,073	SF	\$1,534	
Floor	Classroom	Tile/Sheet		6	1,098	SF	\$1,570	
Floor	Classroom	Tile/Sheet		6	1,098	SF	\$1,570	
Floor	Classroom	Tile/Sheet		6	900	SF	\$1,287	
Floor	Classroom	Tile/Sheet		7	852	SF	\$0	
LIBRARY_CEILING	Library	Drop/Lay-In	2nd Floor	7	2,463	SF	\$0	
LIBRARY_WALL	Library	Concrete Block	2nd Floor	6	1,978	SF	\$5,657	
LIBRARY_WALL	Library	Plaster/Drywall	2nd Floor	6	326		\$769	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lighting	Classroom	Lay-In		6	17	EA	\$1,216	
Lighting	Classroom	Lay-In		6	17	EA	\$1,216	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lay-In		6	17	EA	\$1,216	
Lighting	Classroom	Lay-In		6	17	EA	\$1,216	
Lighting	Classroom	Lay-In		6	17	EA	\$1,216	
Lighting	Classroom	Lay-In		6	12	EA	\$858	
Lighting	Classroom	Lighting		7	12	EA	\$0	
Marker Board	Multipurpose Room	Marker Board	First floor, west end, multipurpose room and servery	7	12	LF	\$0	
Marker Board	Classroom	Marker Board		6	16	LF	\$458	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Wall	Classroom	Concrete Block		7	673	SF	\$0	
Wall	Classroom	Concrete Block		7	673	SF	\$0	
Wall	Classroom	Concrete Block		7	901	SF	\$0	
Wall	Classroom	Concrete Block		7	707	SF	\$0	
Wall	Classroom	Concrete Block		6	841	SF	\$2,405	
Wall	Classroom	Concrete Block		6	1,125	SF	\$3,218	
Wall	Classroom	Concrete Block		6	767	SF	\$2,194	
Wall	Classroom	Concrete Block		6	841	SF	\$2,405	
Wall	Classroom	Concrete Block		6	841	SF	\$2,405	
Wall	Classroom	Concrete Block		6	767	SF	\$2,194	
Wall	Classroom	Concrete Block		6	767	SF	\$2,194	
Wall	Classroom	Concrete Block		6	662	SF	\$1,893	
Wall	Classroom	Concrete Block		6	841	SF	\$2,405	
Wall	Classroom	Concrete Block		7	673	SF	\$0	
Wall	Classroom	Concrete Block		6	876	SF	\$2,505	
Wall	Classroom	Concrete Block		6	616	SF	\$1,762	
Wall	Classroom	Concrete Block		6	876	SF	\$2,505	
Wall	Classroom	Concrete Block		6	876	SF	\$2,505	

Building: Addition
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Wall	Classroom	Concrete Block		7	1,177	SF	\$0	
Wall	Classroom	Concrete Block		6	616	SF	\$1,762	
Wall	Classroom	Plaster/Drywall		6	252	SF	\$595	
Wall	Classroom	Plaster/Drywall		6	252	SF	\$595	
Wall	Classroom	Plaster/Drywall		6	252	SF	\$595	
Wall	Classroom	Plaster/Drywall		6	504	SF	\$1,189	
Wall	Classroom	Plaster/Drywall		6	504	SF	\$1,189	
Wall	Classroom	Plaster/Drywall		6	504	SF	\$1,189	
Wall	Classroom	Plaster/Drywall		6	504	SF	\$1,189	
Wall	Classroom	Plaster/Drywall		6	579	SF	\$1,366	
Wall	Classroom	Plaster/Drywall		6	504	SF	\$1,189	
Wall	Classroom	Plaster/Drywall		6	252	SF	\$595	
Wall	Classroom	Plaster/Drywall		6	251	SF	\$592	
Wall	Classroom	Plaster/Drywall		6	502	SF	\$1,184	
Wall	Classroom	Plaster/Drywall		6	502	SF	\$1,184	
Wall	Classroom	Plaster/Drywall		6	251	SF	\$592	
Wall	Classroom	Plaster/Drywall		6	502	SF	\$1,184	
Wall	Classroom	Plaster/Drywall		6	502	SF	\$1,184	
Wall	Classroom	Plaster/Drywall		6	251	SF	\$592	
Wall	Classroom	Plaster/Drywall		6	251	SF	\$592	
ROOM Sub Total							\$255,344	

Building Addition Sub Total \$1,872,976

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Athletic		Football/Soccer - Synthetic including exc and retention	Courtyard	6	16,174	SF	\$40,475	
Athletic		Running Track Asphalt	Central Courtyard	5	13,613	SF	\$44,968	
Civil/Drainage		Catch Basin	Entire Site	7	11	EA	\$0	
Civil/Drainage		Site Manhole	Entire Site	7	10	EA	\$0	
Fencing		Ornamental Iron	North perimeter	5	789	LF	\$49,147	
Fencing		Ornamental Iron	Entire Site	6	653	LF	\$12,326	
Field House		Masonry Fieldhouse	Courtyard	5	1,812	SF		
Landscape		Asphalt Play Area/Hardscape	Courtyard	6	6,239	SF	\$5,353	
Landscape		Benches	Northeast courtyard	6	6	EA	\$1,416	

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Landscape		Benches	Entire Site	6	13	EA	\$3,067	
Landscape		Grass	Entire Site	6	34,607	SF	\$13,857	
Landscape		Hardscape - Concrete	Entire Site	6	15,489	SF	\$29,237	
Landscape		Hardscape - Concrete	Outside pre-K	5	1,879	SF	\$11,715	
Landscape		Hardscape - Pavers	Courtyard	6	314	SF	\$889	
Landscape		Parkway trees	Entire Site	6	32	EA	\$9,152	
Landscape		Planting Beds/ Areas	Entire Site	6	6,425	SF	\$0	
Landscape		Trash Receptacles	Entire Site	6	8	EA	\$1,661	
Parking Lot		Asphalt	Site - East	6	15,489	SF	\$13,290	
Parking Lot		Concrete	Compactor alley	6	1,861	SF	\$0	
Parking Lot		Concrete Curbs	Site - East	6	388	LF	\$2,341	
Parking Lot		Lights, Pole Mounted	Entire Site	6	21	EA	\$24,024	
Parking Lot		Trash Compactor	Compactor alley	6	1	EA	\$3,575	
Playground		Playground - Swingset	Courtyard	6	1	EA	\$0	
Playground		Playground Equipment - School Age 5-12	Courtyard	6	1	EA	\$0	
Playground		Playground Surfacing - Poured Surface	Playground	5	6,239	SF	\$54,423	
Sidewalks		Internal Walks	Entire Site	6	694	LF	\$6,550	
Sidewalks		Perimeter Sidewalks	North, south and east side	6	13,342	SF	\$25,184	
Signage		Flag Pole	Main Entrance	7	1	EA	\$0	
Signage		Monument Sign	Main Entrance	7	1	EA	\$0	
SITE Sub Total							\$352,651	
SITE Sub Total							\$352,651	

Total Campus Need ^{2 3} \$8,088,090

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Building: Main														
101	888	0	2	12	40	224	120	0	Y	Y	Y	Classroom		
102	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
103	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
104	934	0	2	12	40	168	90	0	Y	N	Y	Classroom		
105	910	0	2	12	40	168	90	1	Y	N	Y	Classroom		
200	415	0	10	20	40	84	45	0	Y	N	Y	Classroom		
201	888	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
202	903	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
203	909	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
204	908	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
205	866	0	2	12	40	76	40	0	Y	N	Y	Classroom		
206B	554	2	6	30	40	82	44	0	Y	N	Y	Classroom		
207	927	0	2	15	40	134	70	0	Y	N	Y	Classroom		
208	881	0	2	16	40	114	59	0	Y	Y	Y	Classroom		
209	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
210	879	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
300	415	0	2	6	40	84	45	0	Y	Y	Y	Classroom		
301	888	0	2	12	40	224	120	0	Y	Y	Y	Classroom		
302	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
303	909	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
304	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
305	888	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
306B	602	0	2	12	40	168	90	0	Y	N	Y	Classroom		
307	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
308	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
309	938	0	2	12	40	168	90	0	Y	Y	Y	Classroom		
310	888	0	2	12	40	224	120	0	Y	Y	Y	Classroom		
Kindergarten	1300	0	2	20	40	420	225		Y	N	Y	Classroom		
Other	557			18					N	N	Y	Administrative Suites/Offices		1st floor NW corner
Other	6600								N	N	N	Gymnasia	Gymnasium.Auditorium	1st Floor
Other	302			6					N	N	Y	Administrative Suites/Offices		3rd floor at top of south stair well
Other	302			6					N	N	Y	Administrative Suites/Offices		3rd floor Rm312 at top of north stair well
Other	360			6					N	N	Y	Administrative Suites/Offices		3rd floor Rm306A at north end of corridor
Other	44								N	N	N	Restroom	Staff Restroom	3rd floor women's next to boys restroom

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Other	44								N	N	N	Restroom	Staff Restroom	2nd floor men's next to boys restroom
Other	333			6					N	N	Y	Administrative Suites/Offices		1st floor SW corner teachers lounge
Other	38								N	N	N	Restroom	Staff Restroom	1st floor next to girls restroom
Other	67								N	N	N	Restroom	Staff Restroom	1st floor inside office at NW corner
Other	266								N	N	N	Restroom	Children's Standard Student Restroom	2nd floor boys
Other	44								N	N	N	Restroom	Early Childhood Student Restroom	1st floor inside kindergarten
Other	211			6					N	N	Y	Administrative Suites/Offices		2nd floor Rm206A at north end of corridor
Other	203								N	N	N	Restroom	Children's Standard Student Restroom	1st floor girls
Other	266								N	N	N	Restroom	Children's Standard Student Restroom	1st floor boys
Other	15								N	N	N	Restroom	Staff Restroom	1st floor inside boiler room
Other	266								N	N	N	Restroom	Children's Standard Student Restroom	2nd floor girls
Other	266								N	N	N	Restroom	Children's Standard Student Restroom	3rd floor girls
Other	266								N	N	N	Restroom	Children's Standard Student Restroom	3rd floor boys
Other	710								N	N	N	Corridors		Entire building stair wells
Other	5057								N	N	N	Corridors		1st Floor
Other	2554								N	N	N	Corridors		2nd Floor
Other	2554								N	N	N	Corridors		3rd Floor

Building: Addition

121	1073	1	1	12	40	164	56		Y	N	N	Classroom		
122	1073	1	1	12	40	164	56		Y	N	N	Classroom		
123	1098	1	1	12	40	164	56		Y	N	N	Classroom		
126	1098	1	1	12	40	164	56		Y	N	N	Classroom		
129	1098	1	1	12	40	164	56		Y	N	N	Classroom		
223	852	1	9	18	40	89	45	0	Y	N	Y	Classroom		
224	852	1	9	16	40	89	45	0	Y	N	Y	Classroom		
225	852	1	9	18	40	113	57	0	Y	N	Y	Classroom		
228	852	1	9	18	40	89	45	0	Y	N	Y	Classroom		
229	1019	2	40	92	40	89	45	0	Y	N	Y	Classroom		
231	852	1	9	18	40	89	45	0	Y	N	Y	Classroom		
320	900	1	8	22	40	155	28		Y	N	N	Classroom		
321	900	1	8	22	40	98	42		Y	N	N	Classroom		
322	900	1	8	24	40	155	28		Y	N	Y	Classroom		
323	900	1	8	22	40	155	28		Y	Y	N	Classroom		
324	900	1	8	22	40	98	42		Y	Y	N	Classroom		

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
325	900	1	8	22	40	155	28		Y	Y	N	Classroom		
328	1053	1	8	24	40	98	42		Y	Y	N	Classroom		
329	1044	1	13	36	40	98	42		Y	N	Y	Classroom		
331	848	1	8	22	40	98	42		Y	N	N	Classroom		
Other	38								N	N	N	Restroom	Early Childhood Student Restroom	first floor, class 123
Other	4714								N	N	N	Corridors		3rd Floor
Other	6280								N	N	N	Lunch & Multipurpose Room	Multipurpose Room	First floor, west end, multipurpose room and servery
Other	817								N	N	N	Kitchen	Cooking Kitchen	1st Floor
Other	73			2					N	N	N	Administrative Suites/Offices		First floor, kitchen office
Other	287			6					N	N	N	Administrative Suites/Offices		First floor, west end, adjacent to multipurpose
Other	42								N	N	N	Restroom	Staff Restroom	First floor, kitchen
Other	4935								N	N	N	Corridors		1st Floor
Other	4714								N	N	N	Corridors		2nd Floor
Other	38								N	N	N	Restroom	Early Childhood Student Restroom	first floor, class 121
Other	38								N	N	N	Restroom	Early Childhood Student Restroom	first floor, class 128
Other	51								N	N	N	Restroom	Staff Restroom	First floor, main office
Other	38								N	N	N	Restroom	Early Childhood Student Restroom	first floor, class 126
Other	200			6					N	N	N	Administrative Suites/Offices		Second floor, library, workroom/office
Other	211			0					N	N	N	Administrative Suites/Offices		Third floor, room 338
Other	38								N	N	N	Restroom	Early Childhood Student Restroom	first floor, class 122
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	Second floor, east end, girls
Other	1457								N	N	N	Corridors		Stairs, entire building
Other	1092			8					N	N	N	Administrative Suites/Offices		Third floor, west end, engineers office
Other	45								N	N	N	Restroom	Staff Restroom	Third floor, east end
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	Third floor, east end, boys
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	Third floor, east end, girls
Other	174			2					N	N	N	Administrative Suites/Offices		Second floor, east end, room 237
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	First floor, east end, boys
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	Second floor, east end, boys
Other	413			12					N	N	N	Administrative Suites/Offices		First floor, east, main office, principal office
Other	2463								N	N	N	Library		2nd Floor
Other	448			14					N	N	N	Administrative Suites/Offices		second floor, room 227, teacher resource room
Other	210								N	N	N	Restroom	Children's Standard Student Restroom	First floor, east end, girls
Other	45								N	N	N	Restroom	Staff Restroom	First floor, east end

Room Summary														
Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Other	763			22					N	N	N	Administrative Suites/Offices		First floor, main office
Other	274			8					N	N	Y	Administrative Suites/Offices		First floor, east, main office, faculty center
Other	45								N	N	N	Restroom	Staff Restroom	Second floor, east end