

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Building A	1973	3	245,084	\$18,059,113
Linked Addition-Athletic Building B	1973	2	170,493	\$11,456,642
SITE				\$2,110,609
Campus Total			415,577	\$31,626,365

Building: Building A

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Intrance								
Entrance Control - Audio and Video	10	1	EA	6	\$702			
Entrance Control - Audio and Video	6	1	EA	7	\$0			
Exterior Doors - Exterior Steel Door	10	1	EA	6	\$481			
Exterior Doors - Exterior Steel Door	6	4	EA	5	\$5,365			
Exterior Doors - Exterior Steel Door	7	3	EA	5	\$4,024			
Exterior Doors - Exterior Steel Door	7	1	EA	4	\$3,823	exposed core		
Exterior Doors - Exterior Steel Door	7.1	2	EA	6	\$961			
Exterior Doors - Exterior Steel Door	8	1	EA	5	\$1,341			
Exterior Doors - Exterior Steel Door	9	1	EA	6	\$481			
Exterior Doors - Overhead Rolling/ Garage Door	Loading Dock	3	EA	6	\$4,300			
Exterior Doors - Transom Lite	10	1	EA	6	\$313			
Exterior Stairs - Concrete	10	18	LF	6	\$1,472			
Power Door Operator and Controls	6	1	EA	7	\$0			
Stair Handrail - Steel_Stair Handrail	10	5	LF	6	\$43			
Foundation								
Foundation - Concrete	Entire Building	1,078	LF	7	\$0			
Foundation - Concrete	Entire Building / South East	80	LF	7	\$0	cracked		
Superstructure - Metal Deck/ Concrete Topping	Entire Building	245,084	SF	7	\$0			



Building: Building A

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lighting	l						
	Exterior Lighting - Parapet or Roof Mounted		15	EA	7	\$0	
	Exterior Lighting - Wall Mounted		11	EA	6	\$3,176	
Roof Sy	stem						
	Coping - Metal	A	1,918	LF	6	\$61,602	
	Coping - Metal	В	104	LF	6	\$3,340	
	Coping - Metal	C	104	LF	6	\$3,340	
	Coping - Metal	D	104	LF	6	\$3,340	
	Coping - Metal	E	104	LF	6	\$3,340	
	Coping - Metal	F	56	LF	6	\$1,799	
	Downspouts - Interior Downspouts	A	720	LF	5	\$159,341	
	Parapet - Parapet < 16" Height	A	1,918	LF	6	\$40,867	
	Parapet - Parapet < 16" Height	В	104	LF	6	\$2,216	
	Parapet - Parapet < 16" Height	C	104	LF	6	\$2,216	
	Parapet - Parapet < 16" Height	D	104	LF	6	\$2,216	
	Parapet - Parapet < 16" Height	E	104	LF	6	\$2,216	
	Parapet - Parapet < 16" Height	F	56	LF	6	\$1,193	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	A	80,728	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	В	676	SF	7	\$0 \$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	C	676	SF	7	\$0 \$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	D	676	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	E	676	SF	7	\$0 \$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	F	196	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	A	80,728	SF	4	\$2,262,644	blistering, bubbling, leaking throughout
	Roof - Asphalt Gravel Ballast	В	676	SF	4	\$18,947	
	Roof - Asphalt Gravel Ballast	C	676	SF	4	\$18,947	
	Roof - Asphalt Gravel Ballast	D	676	SF	4	\$18,947	blistering, bubbling, leaking throughout
	Roof - Asphalt Gravel Ballast	E	676	SF	4	\$18,947	blistering, bubbling, leaking throughout
	Roof - Asphalt Gravel Ballast	F	196	SF	4	\$5,493	blistering, bubbling, leaking throughout
Welle							
Walls	Exterior Walls - Brick	Entire Building	1,200	SF	5	\$28,571	araffiti
	Exterior Walls - Brick	Entire Building	36,546	SF	5 6	\$28,571 \$245,626	granu
	Exterior Walls - Brick	Entire Building / South Façade		SF			spalled cracking deteriorating morter
	Exterior Walls - Precast Panel Wall	Entire Building / South Façade	23 2,000	SF	4 5	\$3,787 \$16,559	spalled, cracking, deteriorating mortar
	Exterior Walls - Precast Panel Wall	Entire Building / South East Entire Building / Roof	2,000	SF	5 6	\$10,559	
			3,040	ЪГ	U	Φ 17,∠38	
Window							
	Guard - Guards perforated	Entire Building	1,431	SF	6	\$18,274	



Building: Building A

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments	
Windows							
Guard - Guards perforated	Entire Building / North West	1,026	SF	5	\$15,728		
Lintels - Steel	Entire Building	1,785	LF	6	\$51,817		
Storefront Windows	Entire Building / South West	120	SF	6	\$1,345		
Windows - Decorative	Entire Building	14,721	SF	5	\$1,804,073	fixed, non operable	
Windows - Louver	Entire Building	36	SF	5	\$3,083		
Building Exterior Subtotal:	ilding Exterior Subtotal: \$4,863,555						

Building Exterior Subtotal:

Building: Building A

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Basement / Electrical Room	2	EA	7	\$0	
	Emergency A/C Power - Corridors and Stairs	Entire Building	54,566	SF	6	\$16,386	
	Emergency A/C Power - Lunchrooms	Entire Building	17,100	SF	6	\$6,358	
	Emergency A/C Power - Students Toilets	Entire Building	4,683	SF	6	\$1,741	
	Emergency Generator- Indoor- Natural Gas - 151 - 200 KW	Basement / Mechanical Room	1	EA	5	\$24,187	Serves main and addition
	Exit Signs - Corridors and Stairs	Entire Building	40	EA	6	\$5,990	
	Exit Signs - Lunchroom	Entire Building	12	EA	6	\$1,797	
	Security System - Intrusion Detection	Entire Building	245,084	SF	6	\$63,085	
Main Se	ervice						
	Independent Electrical Service for emergency power	Basement / Electrical Room	2	EA	6	\$5,841	Serves main and addition
	Main Electrical Service - 1200 A 277/480/3PH	Entire Building / Penthouse	1	EA	6	\$5,346	
	Main Electrical Service - 800 A and 277/480/3PH	Entire Building / Penthouse	7	EA	6	\$27,278	
	Main Electrical Service - 800 A and Less than 277/480/3PH	Entire Building / Electrical Room	1	EA	6	\$3,398	
	Main Electrical Service - Greater than 3000 A 120/208/3PH	Entire Building / Electrical Room	1	EA	6	\$16,381	
	PA System	Entire Building	245,084	SF	4	\$1,068,934	40 year old system
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / Electrical Room	7	EA	6	\$2,094	
	Lighting and Power Panels - 100 A	Entire Building	48	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	\$0	
	Transformers - 277/480 - 120/208	Entire Building	4	EA	7	\$0	
Electr	ical System Subtotal:				9	51,248,817	



Building: Building A

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building / Electrical Room	1	EA	6	\$6,406	Serves main and addition
	Fire Alarm Strobe Lights	Entire Building	245,084	SF	6	\$87,618	
	Fire Alarm_System	Entire Building / Mechanical Room	245,084	SF	6	\$119,160	
	Fire Pump Controller	Entire Building	1	EA	6	\$1,823	
Pump Re	oom Assembly						
	Fire Pump - 51-75hp	Mechanical Room / Basement	1	EA	5	\$11,446	Serves main and addition
	Jockey Pump	Mechanical Room / Basement	1	EA	5	\$2,958	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	245,084	SF	5	\$0	
	Sprinkler Piping	Entire Building	245,084	SF	5	\$171,730	
	Wet Sprinkler System	Entire Building	245,084	SF	5	\$87,618	
Safty S	System Subtotal:					\$488,758	

Safty System Subtotal:

Building: Building A

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	5	\$12,315	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	2	\$14,893	Out of service. Appears abandoned in place.
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	\$7,379	
Air Han	dling Systems						
	Air Handling Unit- Package Multi Zone- Indoor- Electric and DX Cooling Coil - 10001-15000 cfm	Mechanical Room / Basement	1	EA	5	\$52,178	
	Air Handling Unit- Package Single Zone- Indoor- Electric Coil - Less than 4000 cfm	Mechanical Room	1	EA	5	\$20,373	
	Air Intake	Mechanical Room / Areaway	1	EA	3	\$17,616	
	Auxiliaries - Less than 4000 cfm	Mechanical Room	1	EA	5	\$0	
	Auxiliaries	Mechanical Room / Basement	1	EA	5	\$0	
	Fan Coil Unit- Floor Mounted - Electric	Loading Dock	2	EA	4	\$22,078	
	Fan Coil Unit- Floor Mounted - Electric	Mechanical Room	1	EA	4	\$11,039	
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Roof	4	EA	2	\$269,207	
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Roof	1	EA	4	\$67,302	



Building: Building A

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Har	ndling Systems						
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 21 - 30 tons	Roof	7	EA	4	\$913,944	20 years old. Of 17 RTUs in A Building, only 7 can meet DAT.sp. All units have at least one out of four compressors out, and some have all four compressors out. Condensing coils are damaged and unit housing is beginning to deteriorate.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof	10	EA	4	\$1,672,334	20 years old. Of 17 RTUs in A Building, only 7 can meet DAT.sp. All units have at least one out of four compressors out, and some have all four compressors out. Condensing coils are damaged and unit housing is beginning to deteriorate.
Heating	g Devices						
	Cabinet Heaters - With Electric Coil	Entire Building	5	EA	5	\$7,929	
	Duct Heater - Electric	Basement	5		6	\$2,136	
	Fin Tube - Electric	Entire Building	2,722	LF	5	\$138,922	
	Unit Heater - Electric	Entire Building / 1st Floor	5	EA	5	\$5,038	
	Unit Heater - Electric	Entire Building / Mechanical Room	3	EA	6	\$833	
Tempe	rature Control						
	DDC System	Entire Building	245,084	SF	5	\$403,041	Serves main and addition
	Pneumatic System	Entire Building / Basement	6,000	SF	6	\$3,175	
	Thermostats - DDC	Entire Building	131	EA	6	\$0	
	Thermostats - Pneumatic	Entire Building / Basement	5	EA	6	\$0	
Ventila	tion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / 1st Floor	1	EA	4	\$6,392	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / 1st Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Basement	1	EA	6	\$592	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	1	EA	4	\$1,278	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	4	EA	3	\$25,568	Heavily corroded and inoperable centrifugal fans paired with MAUs
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	9	EA	5	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	4	EA	4	\$16,978	> 15 years of age and vibrating
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	3	\$1,942	Damaged/inoperable, not cost effective to repair
	Lab Exhaust Hood	Entire Building	5	EA	5	\$14,751	
	Type I Exhaust Hood- Culinary Arts	Entire Building / 3rd Floor	4	EA	5	\$15,798	
	Type I Exhaust Hood- Kitchen	Entire Building	10	EA	7	\$0	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	6	EA	7	\$0	



\$3,725,625

Building: Building A

Category: Mechanical System Group Item - Type Location Quantity Unit Rank **Cost Comments** Ventilation

Mechanical System Subtotal:

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ot Wa	ter						
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	6	\$620	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room / Penthouse	2	EA	5	\$4,498	
ping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	245,084	SF	4	\$175,235	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	245,084	SF	4	\$353,975	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Cold Water Risers	Entire Building	245,084	SF	4	\$196,263	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	245,084	SF	4	\$133,179	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	245,084	SF	4	\$315,423	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Return Lines	Entire Building	245,084	SF	4	\$210,282	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Return Risers	Entire Building	245,084	SF	4	\$119,160	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Sanitary Piping	Entire Building	245,084	SF	6	\$224,301	
	Storm Piping	Entire Building	245,084	SF	6	\$213,787	
	Vent Piping	Entire Building	245,084	SF	6	\$164,721	
ol Sy	/stems						
	Pool Drain Piping	Mechanical Room	50	LF	7	\$0	
	Pool Filtration System including Pump	Mechanical Room	2	EA	7	\$0	Sand Filter - recent Upgrade
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	6	\$310	
	Pool Supply and Return Piping	Mechanical Room	75	LF	7	\$0	
imps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	3	EA	4	\$76,322	
	Pumps - Ejector-Simplex	Mechanical Room / Loading Dock Ramp	2	EA	5	\$11,253	
	Pumps - Ejector-Simplex	Mechanical Room	2	EA	5	\$11,253	
	Pumps - Sump-Duplex	Mechanical Room	1	EA	5	\$7,535	



Building: Building A

Category: Plumbing System			
Group Item - Type	Location	Quantity Unit Rank C	Cost Comments
Pumps			
Pumps - Sump-Simplex	Mechanical Room	2 EA 5 \$11,	,253
Plumbing System Subtotal:		\$2,229,3	369

Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #143 Web Design (Computer Lab)						
	Ceiling - Lay-in		1,871	SF	7	\$0	
	Doors - Side-lite		36	SF	7	\$0	
	Doors - Transom Window		25	SF	7	\$0	
	Doors - Wood Doors inclu hw		4	EA	6	\$1,204	
	Floor - Tile/Sheet		1,871	SF	7	\$0	
	Lighting - Pendent/Surface		70	EA	7	\$0	
	Marker Board		20	LF	6	\$428	
	Storage/ Closet		181	SF	7	\$0	Rm 143B
	Walls - Concrete Block		180	SF	7	\$0	
	Walls - Metal Panel		1,562	SF	7	\$0	
	Wireless System		1	EA	7	\$0	
Classro	om #144 Elect Lab (Regular Classroom)						
	Ceiling - Lay-in		1,044	SF	6	\$3,135	
	Doors - Side-lite		36	SF	7	\$0	
	Doors - Transom Window		40	SF	7	\$0	
	Doors - Wood Doors inclu hw		5	EA	6	\$1,505	
	Floor - Tile/Sheet		1,044	SF	7	\$0	
	Lighting - Pendent/Surface		40	EA	6	\$4,956	
	Marker Board		10	LF	6	\$214	
	Storage/ Closet		181	SF	7	\$0	Room 144A
	Walls - Concrete Block		120	SF	7	\$0	
	Walls - Metal Panel		856	SF	6	\$6,390	
	Walls - Plaster/Drywall		348	SF	6	\$960	
Classro	om #145 (Computer Lab)						
	Ceiling - Lay-in		1,002	SF	6	\$3,009	
	Doors - Transom Window		10	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Concrete		1,002	SF	5	\$1,719	Seams are coming apart

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #145 (Computer Lab)						
	Lighting - Pendent/Surface		38	EA	6	\$4,708	
	Marker Board		16	LF	6	\$343	
	Storage/ Closet		90	SF	7	\$0	
	Walls - Concrete Block		60	SF	7	\$0	
	Walls - Metal Panel		904	SF	6	\$6,748	
	Walls - Plaster/Drywall		298	SF	7	\$0	
	Wireless System		1	EA	7	\$0	
Classro	oom #146 (Regular Classroom)						
	Ceiling - Lay-in		632	SF	6	\$1,898	
	Doors - Side-lite		17	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		632	SF	7	\$0	
	Lighting - Pendent/Surface		23	EA	6	\$2,850	
	Marker Board		18	LF	7	\$0	
	Walls - Concrete Block		50	SF	7	\$0	
	Walls - Metal Panel		990	SF	6	\$7,390	
Classro	oom #147 (Regular Classroom)						
	Ceiling - Lay-in		793	SF	6	\$2,381	
	Chalk Board		5	LF	4	\$459	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		793	SF	6	\$794	
	Lighting - Pendent/Surface		28	EA	6	\$3,469	
	Marker Board		10	LF	7	\$0	
	Walls - Concrete Block		454	SF	6	\$1,331	
	Walls - Metal Panel		493	SF	6	\$3,680	
	Walls - Plaster/Drywall		250	SF	6	\$690	
Classro	oom #148 DigitalDsgn (Computer Lab)						
	Ceiling - Lay-in		2,234	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	door does not have door knob/latch
	Floor - Tile/Sheet		2,234	SF	7	\$0	
	Lighting - Pendent/Surface		87	EA	7	\$0	
	Marker Board		16	LF	7	\$0	
	Storage/ Closet		538	SF	7	\$0	Rms 148A and 148B (no access to 148B which was blocked by equipment/boxes in 148A)
	Walls - Concrete Block		740	SF	7	\$0	

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssro	oom #148 DigitalDsgn (Computer Lab)						
	Walls - Metal Panel		1,253	SF	7	\$0	
	Wireless System		1	EA	7	\$0	
issro	oom #150 Photography (Laboratory/Shop)						
	Ceiling - Lay-in		734	SF	6	\$2,204	
	Doors - Side-lite		36	SF	7	\$0	
	Doors - Transom Window		15	SF	7	\$0	
	Doors - Wood Doors inclu hw		6	EA	6	\$1,806	
	Floor - Tile/Sheet		734	SF	7	\$0	
	Lighting - Pendent/Surface		30	EA	6	\$3,717	
	Marker Board		5	LF	6	\$107	
	Storage/ Closet		231	SF	7	\$0	3 rooms, 150A, 150B & 150C
	Walls - Concrete Block		290	SF	7	\$0	
	Walls - Metal Panel		900	SF	7	\$0	
	Work Sink		2	EA	5	\$3,016	
issro	oom #151 Dark Rm (Laboratory/Shop)						
	Ceiling - Lay-in		440	SF	6	\$1,321	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Terrazzo		440	SF	7	\$0	
	Lighting - Pendent/Surface		8	EA	7	\$0	
	Storage/ Closet		21	SF	7	\$0	
	Walls - Concrete Block		438	SF	7	\$0	
	Walls - Metal Panel		514	SF	7	\$0	
	Work Sink		2	EA	7	\$0	
ssro	oom #152 Comp/Elec (Laboratory/Shop)						
	Ceiling - Lay-in		1,451	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	7	\$0	
	Floor - Tile/Sheet		1,451	SF	7	\$0	
	Lighting - Lay-in		22	EA	7	\$0	
	Marker Board		16	LF	6	\$343	
	Walls - Concrete Block		120	SF	7	\$0	
	Walls - Metal Panel		1,092	SF	7	\$0	
	Walls - Plaster/Drywall		598	SF	7	\$0	
ssro	oom #159 (Special Program)						
	Casework		9	LF	7	\$0	
	Ceiling - Lay-in		1,627	SF	7	\$0	

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	bom #159 (Special Program)	Location	Quantity	0.111	Nulli	0031	
0100010	Doors - Side-lite		12	SF	7	\$0	
	Doors - Transom Window		15	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		1,627	SF	7	\$0	
	Lighting - Lay-in		30	EA	7	\$0	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		760	SF	7	\$0	
	Walls - Plaster/Drywall		693	SF	7	\$0	
Classro	oom #160 (Special Program)						
	Ceiling - Lay-in		1,434	SF	7	\$0	
	Doors - Side-lite		12	SF	7	\$0	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile/Sheet		1,434	SF	7	\$0	
	Lighting - Lay-in		24	EA	7	\$0	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		200	SF	7	\$0	
	Walls - Plaster/Drywall		1,292	SF	6	\$3,566	
Classro	oom #161 (Special Program)						
	Ceiling - Lay-in		1,453	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		1,453	SF	6	\$1,454	
	Lighting - Pendent/Surface		59	EA	6	\$7,310	
	Marker Board		5	LF	6	\$107	
	Walls - Concrete Block		250	SF	7	\$0	
	Walls - Metal Panel		859	SF	7	\$0	
	Walls - Plaster/Drywall		478	SF	7	\$0	
	Work Sink		1	EA	4	\$8,619	Sink gone, pipe capped
Classro	oom #162 (Computer Lab)						
	Casework		12	LF	7	\$0	
	Ceiling - Lay-in		1,234	SF	6	\$3,706	
	Doors - Side-lite		17	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		1,234	SF	7	\$0	
	Lighting - Pendent/Surface		48	EA	6	\$5,947	
	Marker Board		10	LF	6	\$214	

-	ory: Classrooms		•			•	•
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	om #162 (Computer Lab)					.	
	Walls - Concrete Block		870	SF	6	\$2,550	
	Walls - Metal Panel		474	SF	6	\$3,538	
	Work Sink		3	EA	6	\$1,137	
assro	om #163 Woodworking (Laboratory/Shop)						
	Ceiling - Plaster/Drywall		2,491	SF	7	\$0	
	Doors - Steel Doors incl hw		4	EA	6	\$1,204	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Concrete		2,491	SF	7	\$0	
	Lighting - Pendent/Surface		88	EA	6	\$10,903	
	Storage/ Closet		423	SF	7	\$0	2 storage rooms
	Walls - Concrete Block		2,100	SF	6	\$6,156	Teacher stated that many outlets in this room do not work
	Work Sink		3	EA	5	\$4,523	
assro	om #164 Metal (Store Room)						
	Ceiling - Plaster/Drywall		2,531	SF	7	\$0	
	Doors - Steel Doors incl hw		6	EA	6	\$1,806	
	Doors - Wood Doors inclu hw		3	EA	6	\$903	
	Floor - Concrete		2,531	SF	7	\$0	
	Lighting - Pendent/Surface		75	EA	6	\$9,292	
	Storage/ Closet		286	SF	7	\$0	Room 164A
	Walls - Concrete Block		2,384	SF	7	\$0	
	Work Sink		3	EA	5	\$4,523	
assro	om #165 TV Studio (Computer Lab)						
	Ceiling - Lay-in		422	SF	7	\$0	
	Ceiling - Splined		1,163	SF	7	\$0	
	Doors - Wood Doors inclu hw		5	EA	7	\$0	
	Floor - Tile/Sheet		1,585	SF	7	\$0	
	Lighting - Lay-in		9	EA	7	\$0	
	Lighting - Pendent/Surface		15	EA	6	\$1,858	
	Marker Board		8	LF	7	\$0	
	Storage/ Closet		54	SF	7	\$0	No Access
	Walls - Concrete Block		1,614	SF	7	\$0	
	Walls - Plaster/Drywall		346	SF	7	\$0	
assro	om #166 Automotive (Laboratory/Shop)						
	Casework		19	LF	7	\$0	

Building: Building A

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	pom #166 Automotive (Laboratory/Shop)						
	Ceiling - Plaster/Drywall		3,960	SF	7	\$0	
	Doors - Steel Doors incl hw		2	EA	6	\$602	
	Doors - Wood Doors inclu hw		3	EA	5	\$3,522	
	Floor - Concrete Epoxy/ Painted		3,960	SF	6	\$2,095	
	Lighting - Metal Halide/Sodium Vapor		35	EA	7	\$0	
	Lighting - Pendent/Surface		3	EA	7	\$0	
	Storage/ Closet		977	SF	6	\$7,083	3 rooms & 2 mezzanines
	Student Lockers - One Tier		3	EA	6	\$279	
	Student Lockers - Two Tiers		98	EA	6	\$4,549	
	Walls - Concrete Block		1,150	SF	6	\$3,865	Walls are poured concrete not concrete block
	Walls - Concrete Block		2,452	SF	7	\$0	
	Work Sink		2	EA	6	\$758	
Classro	oom #167 (Health)						
	Ceiling - Lay-in		954	SF	7	\$0	
	Chalk Board		15	LF	4	\$1,377	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		954	SF	7	\$0	
	Lighting - Pendent/Surface		35	EA	6	\$4,336	
	Walls - Concrete Block		510	SF	5	\$5,236	10 If settlement crack in masonry
	Walls - Metal Panel		560	SF	6	\$4,180	
Classro	oom #168 (Health)						
	Ceiling - Lay-in		974	SF	6	\$2,925	
	Chalk Board		15	LF	4	\$1,377	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		974	SF	6	\$975	
	Lighting - Pendent/Surface		20	EA	6	\$2,478	
	Walls - Concrete Block		190	SF	7	\$0	
	Walls - Metal Panel		727	SF	6	\$5,427	
	Walls - Plaster/Drywall		200	SF	6	\$552	
Classro	oom #232 (Regular Classroom)						
	Ceiling - Lay-in		750	SF	5	\$4,462	
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		6	SF	6	\$102	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		750	SF	6	\$1,641	
	Lighting - Lay-in		14	EA	6	\$1,666	

Category: Classrooms						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #232 (Regular Classroom)						
Marker Board		12	LF	6	\$257	
Walls - Concrete Block		172	SF	6	\$504	
Walls - Metal Panel		720	SF	6	\$5,375	
Classroom #233 (Regular Classroom)						
Ceiling - Lay-in		1,140	SF	6	\$3,423	
Doors - Side-lite		10	SF	6	\$167	
Doors - Transom Window		6	SF	6	\$102	
Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
Floor - Tile		1,140	SF	6	\$2,494	
Lighting - Lay-in		18	EA	6	\$2,142	
Marker Board		16	LF	6	\$343	
Walls - Concrete Block		188	SF	6	\$551	
Walls - Metal Panel		1,120	SF	6	\$8,360	
Classroom #235E (Computer Lab)						
Ceiling - Lay-in		870	SF	6	\$2,613	
Doors - Side-lite		20	SF	6	\$334	
Doors - Transom Window		12	SF	6	\$203	
Doors - Wood Doors inclu hw		2	EA	6	\$602	
Floor - Tile		870	SF	5	\$3,906	
Lighting - Lay-in		17	EA	5	\$2,757	
Marker Board		13	LF	6	\$278	
Storage/ Closet		81	SF	6	\$587	
Walls - Metal Panel		1,060	SF	6	\$7,912	
Wireless System		1	EA	6	\$372	
Classroom #241 (Regular Classroom)						
Ceiling - Lay-in		1,384	SF	6	\$4,156	
Doors - Wood Doors inclu hw		2	EA	6	\$602	
Floor - Carpet		1,384	SF	5	\$7,105	
Lighting - Lay-in		26	EA	5	\$4,217	
Walls - Concrete Block		250	SF	6	\$733	
Walls - Metal Panel		1,250	SF	5	\$38,235	
Classroom #243 (Regular Classroom)						
Ceiling - Lay-in		738	SF	6	\$2,216	
Doors - Side-lite		11	SF	6	\$184	
Doors - Transom Window		9	SF	6	\$152	

	ory: Classrooms						
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #243 (Regular Classroom)						
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		14	EA	6	\$1,666	
	Marker Board		16	LF	6	\$343	
	Walls - Concrete Block		334	SF	4	\$11,974	Cracks in edge by window.
	Walls - Metal Panel		495	SF	5	\$15,141	
Classro	oom #244 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	5	\$4,390	
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		16	LF	6	\$343	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		799	SF	5	\$24,440	
Classro	oom #245 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		14	EA	6	\$1,666	
	Marker Board		15	LF	6	\$321	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		695	SF	6	\$5,188	
Classro	oom #248 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	4	\$6,343	Warped floor, water damage, stained
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		120	SF	5	\$1,232	cracks throughout window edge, peeling material
	Walls - Metal Panel		570	SF	5	\$17,435	

i It	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
	n #248 (Regular Classroom)		•				
oor	n #249 (Regular Classroom)						
	eiling - Lay-in		738	SF	4	\$7,503	water damage
	oors - Side-lite		11	SF	6	\$184	-
С	oors - Transom Window		9	SF	6	\$152	
С	oors - Wood Doors inclu hw		1	EA	5	\$1,174	
F	loor - Tile		738	SF	6	\$1,615	
L	ighting - Lay-in		15	EA	6	\$1,785	
Ν	larker Board		15	LF	6	\$321	
V	/alls - Concrete Block		120	SF	6	\$352	
V	/alls - Metal Panel		579	SF	6	\$4,322	
oor	n #250 (Regular Classroom)						
	eiling - Lay-in		400	SF	5	\$2,380	
	halk Board		20	LF	4	\$1,836	obsolete material.
С	oors - Side-lite		11	SF	7	\$0	
С	oors - Transom Window		9	SF	6	\$152	
С	oors - Wood Doors inclu hw		2	EA	6	\$602	
F	loor - Tile		400	SF	5	\$1,796	
L	ighting - Lay-in		8	EA	5	\$1,298	
	larker Board		20	LF	6	\$428	
V	/alls - Metal Panel		510	SF	5	\$15,600	
oor	n #252 (Regular Classroom)						
С	eiling - Lay-in		400	SF	6	\$1,201	
	oors - Side-lite		11	SF	6	\$184	
С	oors - Transom Window		9	SF	6	\$152	
С	oors - Wood Doors inclu hw		1	EA	6	\$301	
F	loor - Tile		400	SF	6	\$875	
L	ighting - Lay-in		8	EA	6	\$952	
	larker Board		7	LF	6	\$150	
V	/alls - Metal Panel		559	SF	5	\$17,099	
oor	n #253 (Regular Classroom)						
С	eiling - Lay-in		738	SF	6	\$2,216	
С	oors - Side-lite		11	SF	6	\$184	
С	oors - Transom Window		9	SF	6	\$152	
С	oors - Wood Doors inclu hw		1	EA	6	\$301	
F	loor - Tile		738	SF	6	\$1,615	

Catego	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroo	om #253 (Regular Classroom)						
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		13	LF	7	\$0	
	Walls - Concrete Block		120	SF	6	\$352	
	Walls - Metal Panel		559	SF	6	\$4,173	
Classroo	om #254 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Chalk Board		4	LF	4	\$367	obsolete material.
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		16	LF	6	\$343	
	Walls - Concrete Block		120	SF	5	\$1,232	
	Walls - Metal Panel		799	SF	6	\$5,964	
Classroo	om #255 (Regular Classroom)						
	Ceiling - Lay-in		600	SF	6	\$1,802	
	Chalk Board		5	LF	4	\$459	Obsolete Material.
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		600	SF	5	\$2,694	
	Lighting - Lay-in		12	EA	6	\$1,428	
	Marker Board		17	LF	7	\$0	
	Walls - Metal Panel		610	SF	6	\$4,553	
Classroo	om #257 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	4	\$7,503	water damage.
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		120	SF	6	\$352	
						A 4 4 - A	
	Walls - Metal Panel		600	SF	6	\$4,479	
			600	SF	6	\$4,479	

Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #258 (Regular Classroom)						
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		738	SF	6	\$739	
	Lighting - Pendent/Surface		15	EA	6	\$1,858	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		180	SF	6	\$528	
	Walls - Metal Panel		600	SF	6	\$4,479	
Classro	om #259 (Regular Classroom)						
	Ceiling - Lay-in		600	SF	4	\$6,100	Water Damage.
	Doors - Side-lite		160	SF	7	\$0	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		600	SF	6	\$1,313	
	Lighting - Lay-in		12	EA	6	\$1,428	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		130	SF	5	\$1,335	
	Walls - Metal Panel		465	SF	5	\$14,223	
Classro	om #260 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	5	\$4,390	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		180	SF	6	\$528	
	Walls - Metal Panel		840	SF	6	\$6,270	
Classro	om #261 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,170	SF	6	\$3,514	
	Chalk Board	2nd Floor	5	LF	4	\$459	partially covered; obsolete material.
	Doors - Side-lite	2nd Floor	60	SF	7	\$0	
	Doors - Transom Window	2nd Floor	9	SF	5	\$381	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,170	SF	6	\$2,560	
	Lighting - Lay-in	2nd Floor	1	EA	5	\$162	
	Marker Board	2nd Floor	13	LF	6	\$278	

	Hom Tuno		Ourseller	In	Derels	0 1	Commente
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	om #261 (Computer Lab)	0.15	450	05		.	
	Walls - Concrete Block	2nd Floor	456	SF	4		cracks throughout wall.
	Walls - Metal Panel	2nd Floor	390	SF	5	\$11,929	
	Wireless System	2nd Floor	1	EA	6	\$372	
assro	om #262 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	5	\$4,390	
	Chalk Board		10	LF	4	\$918	partially covered; obsolete material.
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		14	EA	5	\$2,271	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		180	SF	6	\$528	
	Walls - Metal Panel		840	SF	6	\$6,270	
assro	om #263 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	5	\$4,390	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		180	SF	6	\$528	
	Walls - Metal Panel		840	SF	6	\$6,270	
assro	om #264 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	7	\$0	
	Chalk Board		5	LF	4	\$459	Obsolete Material.
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		12	LF	7	\$0	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		840	SF	6	\$6,270	

Building: Building A

		1	• •		D 1	•	0
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	bom #265 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		15	EA	5	\$2,433	
	Marker Board		30	LF	7	\$0	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		840	SF	6	\$6,270	
Classro	oom #266 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		14	EA	5	\$2,271	
	Marker Board		18	LF	7	\$0	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		840	SF	5	\$25,694	
Classro	oom #267 (Regular Classroom)						
	Ceiling - Lay-in		730	SF	7	\$0	
	Doors - Side-lite		11	SF	5	\$770	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		13	EA	5	\$2,108	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		840	SF	5	\$25,694	
Classro	oom #268 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		15	EA	6	\$1,785	

4959 S Archer Ave Chicago, IL 60632

-	ory: Classrooms	Leastion	Quantitu	l lm it	Dank	Cast	Commente
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	om #268 (Regular Classroom)		10		7	^	
	Marker Board		12	LF	7	\$0	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		795	SF	6	\$5,934	
Classro	om #269 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	5	\$4,390	
	Doors - Side-lite		9	SF	5	\$630	
	Doors - Transom Window		11	SF	5	\$466	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		14	EA	6	\$1,666	
	Marker Board		14	LF	6	\$300	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		765	SF	5	\$23,400	Vandalism on walls.
Classro	om #270 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,500	SF	5	\$8,923	
	Doors - Side-lite	2nd Floor	10	SF	7	\$0	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Carpet	2nd Floor	1,500	SF	7	\$0	
	Lighting - Lay-in	2nd Floor	27	EA	6	\$3,212	
	Walls - Concrete Block	2nd Floor	488	SF	7	\$0	
	Walls - Metal Panel	2nd Floor	580	SF	7	\$0	
	Wireless System	2nd Floor	1	EA	7	\$0	
lassro	om #271 (Regular Classroom)						
140010	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	5	\$770	
	Doors - Transom Window		9	SF	5	\$381	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		14	EA	5	\$2,271	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		120	SF	6	\$352	
	Walls - Metal Panel		980	SF	5	\$29,976	
lacero	om #272 (Regular Classroom)		500		-	,	
192210	UIII #212 (Negular Glassi UUIII)					\$0	

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #272 (Regular Classroom)						
	Doors - Side-lite		251	SF	6	\$4,196	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Tile		600	SF	5	\$2,694	
	Lighting - Lay-in		12	EA	5	\$1,946	
	Marker Board		15	LF	7	\$0	
	Walls - Metal Panel		610	SF	5	\$18,658	
lassro	oom #274 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	5	\$770	
	Doors - Transom Window		9	SF	5	\$381	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		15	EA	5	\$2,433	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		495	SF	6	\$3,695	
lassro	oom #275 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	6	\$1,615	
	Lighting - Lay-in		14	EA	6	\$1,666	
	Marker Board		12	LF	7	\$0	
	Walls - Concrete Block		314	SF	5	\$3,224	
	Walls - Metal Panel		485	SF	5	\$14,835	
lassro	oom #277 (Regular Classroom)						
	Ceiling - Lay-in		687	SF	6	\$2,063	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Tile/Sheet		687	SF	6	\$688	
	Lighting - Metal Halide/Sodium Vapor		12	EA	5	\$2,722	
	Marker Board		7	LF	6	\$150	
	Walls - Metal Panel		650	SF	5	\$19,882	

Building: Building A

4959 S Archer Ave Chicago, IL 60632

-	ory: Classrooms	Leastien	Questitu	l lmit	Denk	C	Commente
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
assro	om #284 (Regular Classroom)					* 450	
	Marker Board		7	LF	6	\$150	
	Walls - Concrete Block		190	SF	5	\$1,951	
	Walls - Metal Panel		663	SF	6	\$4,949	
assro	om #285 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		15	EA	6	\$1,785	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		150	SF	5	\$1,540	
	Walls - Metal Panel		795	SF	5		delaminating walls.
assro	om #286 (Regular Classroom)						
	Ceiling - Lay-in		687	SF	5	\$4,087	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Tile/Sheet		687	SF	5	\$3,085	
	Lighting - Lay-in		15	EA	5	\$2,433	
	Marker Board		5	LF	6	\$107	
	Walls - Metal Panel		883	SF	5	\$27,009	
assro	om #287 (Regular Classroom)						
	Ceiling - Lay-in		687	SF	5	\$4,087	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Tile		687	SF	5	\$3,085	
	Lighting - Lay-in		15	EA	5	\$2,433	
	Marker Board		5	LF	7	\$0	
	Walls - Metal Panel		758	SF	5	\$23,185	
assro	om #288 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	4	\$7,503	water damage.
	Chalk Board		5	LF	4	\$459	obsolete material.
	Doors - Side-lite		14	SF	6	\$234	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	

-	jory: Classrooms		-		_ ·	-	
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #288 (Regular Classroom)						
	Marker Board		5	LF	6	\$107	
	Walls - Concrete Block		280	SF	5	\$2,875	
	Walls - Metal Panel		705	SF	6	\$5,263	
lassro	oom #289 (Regular Classroom)						
	Ceiling - Lay-in		696	SF	5	\$4,140	
	Chalk Board		12	LF	4	\$1,102	obsolete material.
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		696	SF	5	\$3,125	
	Lighting - Lay-in		14	EA	5	\$2,271	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		180	SF	5	\$1,848	
	Walls - Metal Panel		775	SF	6	\$5,785	
lassro	oom #290 (Regular Classroom)						
	Ceiling - Lay-in		738	SF	6	\$2,216	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		738	SF	5	\$3,314	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		314	SF	5	\$3,224	
	Walls - Metal Panel		485	SF	5	\$14,835	
lassro	oom #332 (Computer Lab)						
	Ceiling - Lay-in		1,326	SF	5	\$7,888	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
	Floor - Tile		1,326	SF	6	\$2,901	
	Lighting - Lay-in		22	EA	5	\$3,568	
	Walls - Concrete Block		222	SF	6	\$651	
	Walls - Metal Panel		895	SF	6	\$6,681	
	Wireless System		1	EA	6	\$372	

Building: Building A

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #334/335 (Regular Classroom)		•				
	Casework		24	LF	6	\$606	
	Ceiling - Lay-in		2,716	SF	6	\$8,156	
	Doors - Side-lite		33	SF	7	\$0	
	Doors - Transom Window		36	SF	7	\$0	
	Doors - Wood Doors inclu hw		3	EA	7	\$0	
	Floor - Tile		2,716	SF	6	\$5,942	
	Lighting - Lay-in		51	EA	6	\$6,068	
	Storage/ Closet		432	SF	7	\$0	
	Walls - Concrete Block		300	SF	7	\$0	
	Walls - Metal Panel		1,035	SF	6	\$7,726	
lassro	oom #335A (Regular Classroom)						
	Ceiling - Lay-in		686	SF	6	\$2,060	
	Chalk Board		8	LF	4	\$734	obsolete material
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		13	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		686	SF	6	\$1,501	
	Lighting - Lay-in		16	EA	6	\$1,904	
	Marker Board		5	LF	6	\$107	
	Storage/ Closet		150	SF	7	\$0	
	Walls - Concrete Block		150	SF	6	\$440	
	Walls - Metal Panel		850	SF	6	\$6,345	
	Work Sink		1	EA	6	\$379	
lassro	oom #336 (Computer Lab)						
	Ceiling - Lay-in		1,020	SF	6	\$3,063	
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		6	SF	6	\$102	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Floor - Tile		1,020	SF	6	\$2,232	
	Lighting - Lay-in		21	EA	6	\$2,498	
	Marker Board		25	LF	6	\$536	
	Walls - Concrete Block		270	SF	6	\$792	
	Walls - Metal Panel		950	SF	6	\$7,091	
	Wireless System		1	EA	7	\$0	
lassro	oom #336A (Other Instructional Use)						
	Ceiling - Lay-in		1,521	SF	7	\$0	

_	Item - Type	Location Quantity	Unit	Rank	Cost	Comments
	om #336A (Other Instructional Use)	Quanty			0001	
	Doors - Steel Doors incl hw	2	EA	6	\$602	
	Floor - Tile	1,521	SF	6	\$3,328	
	Lighting - Lay-in	30	EA	7	\$0	
	Marker Board	8	LF	6	\$171	
	Walls - Concrete Block	250	SF	6	\$733	
	Walls - Metal Panel	1,175	SF	6	\$8,771	
Classrc	om #337 (Computer Lab)					
	Ceiling - Lay-in	960	SF	6	\$2,883	
	Doors - Side-lite	20	SF	6	\$334	
	Doors - Transom Window	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2	EA	6	\$602	
	Floor - Tile	960	SF	6	\$2,100	
	Lighting - Lay-in	18	EA	6	\$2,142	
	Marker Board	15	LF	6	\$321	
	Walls - Metal Panel	1,206	SF	6	\$9,002	
	Wireless System	1	EA	7	\$0	
Classrc	om #338 (Computer Lab)					
	Ceiling - Lay-in	986	SF	6	\$2,961	
	Doors - Side-lite	11	SF	6	\$184	
	Doors - Transom Window	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2	EA	5	\$2,348	
	Floor - Tile	986	SF	6	\$2,157	
	Lighting - Lay-in	18	EA	6	\$2,142	
	Marker Board	30	LF	6	\$643	
	Walls - Metal Panel	1,210	SF	6	\$9,032	
	Wireless System	1	EA	6	\$372	
Classro	om #339 (Computer Lab)					
	Ceiling - Lay-in	686		6	\$2,060	
	Doors - Side-lite	22	SF	6	\$368	
	Doors - Transom Window	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2	EA	6	\$602	
	Floor - Tile	686	SF	6	\$1,501	
	Lighting - Lay-in	18	EA	6	\$2,142	
	Marker Board	12	LF	6	\$257	
	Walls - Metal Panel	1,210	SF	6	\$9,032	
	Wireless System	1	EA	6	\$372	

Building: Building A

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #339 (Computer Lab)						
Classr	oom #340 (Science Lab Level 2)						
010001	Casework		140	LF	6	\$3,536	
	Ceiling - Lay-in		1,250	SF	6	\$3,754	
	Doors - Side-lite		20	SF	6	\$334	
	Doors - Transom Window		12	SF	6	\$203	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		1,250	SF	6	\$2,735	
	Fume Hood		1	EA	6	\$816	
	Gas Line		21	EA	6	\$10,692	
	Lighting - Lay-in		21	EA	7	\$0	
	Marker Board		18	LF	6	\$386	
	Science Lab Shower		1	EA	6	\$379	
	Walls - Plaster/Drywall		1,405	SF	6	\$3,878	
	Work Sink		9	EA	6	\$3,411	
Classro	oom #341 (Computer Lab)						
	Ceiling - Lay-in		850	SF	6	\$2,553	
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		850	SF	6	\$1,860	
	Lighting - Lay-in		17	EA	6	\$2,023	
	Marker Board		17	LF	6	\$364	
	Walls - Concrete Block		360	SF	6	\$1,055	
Classro	oom #343 (Computer Lab)						
	Ceiling - Lay-in		1,496	SF	7	\$0	
	Doors - Side-lite		12	SF	6	\$201	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		1,496	SF	6	\$3,273	
	Lighting - Lay-in		27	EA	7	\$0	
	Marker Board		7	LF	6	\$150	
	Walls - Concrete Block		380	SF	6	\$1,114	
	Walls - Metal Panel		1,130	SF	6	\$8,435	
Classro	oom #346 (Science Lab Level 2)						
	Casework		22	LF	6	\$556	

Building: Building A

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #346 (Science Lab Level 2)						
	Ceiling - Lay-in		1,110	SF	6	\$3,333	
	Chalk Board		10	LF	4	\$918	obsolete material.
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		1,110	SF	6	\$2,429	
	Fume Hood		1	EA	6	\$816	
	Gas Line		16	EA	6	\$8,146	
	Lighting - Lay-in		38	EA	6	\$4,521	
	Marker Board		5	LF	6	\$107	
	Walls - Concrete Block		202	SF	5	\$2,074	cracks throughout wall.
	Walls - Metal Panel		820	SF	6	\$6,121	
	Work Sink		8	EA	6	\$3,032	
Classro	oom #347 (Regular Classroom)						
	Ceiling - Lay-in		600	SF	6	\$1,802	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		600	SF	7	\$0	
	Lighting - Lay-in		13	EA	5	\$2,108	
	Marker Board		10	LF	6	\$214	
	Walls - Concrete Block		120	SF	4	\$4,302	cracks throughout.
	Walls - Metal Panel		680	SF	6	\$5,076	
Classro	oom #349 (Science Lab Level 2)						
	Casework		18	LF	6	\$455	
	Ceiling - Lay-in		1,234	SF	6	\$3,706	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		1,234	SF	6	\$2,700	
	Fume Hood		1	EA	6	\$816	
	Gas Line		6	EA	6	\$3,055	
	Lighting - Lay-in		34	EA	5	\$5,514	
	Marker Board		10	LF	6	\$214	
	Walls - Concrete Block		130	SF	5	\$1,335	
	Walls - Metal Panel		825	SF	5	\$25,235	

0	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	m #349 (Science Lab Level 2)	Loouton	Quantity	onit	Nam	0031	Commente
	Work Sink		8	EA	6	\$3,032	
			Ũ		0	<i>40,00</i>	
	m #350 (Science Lab Level 2)						
	Casework		18	LF	5	\$3,763	
	Ceiling - Lay-in		888	SF	6	\$2,667	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
I	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		888	SF	7	\$0	
	Fume Hood		1	EA	6	\$816	
	Gas Line		16	EA	6	\$8,146	
1	Lighting - Lay-in		31	EA	5	\$5,028	
1	Marker Board		12	LF	6	\$257	
!	Storage/ Closet		98	SF	6	\$711	
١	Walls - Concrete Block		120	SF	4	\$4,302	cracks throughout.
1	Walls - Metal Panel		815	SF	5	\$24,929	
١	Work Sink		8	EA	6	\$3,032	
roo	m #351 (Regular Classroom)						
1	Ceiling - Lay-in		625	SF	6	\$1,877	
1	Chalk Board		5	LF	4	\$459	Obsolete Material.
ł	Doors - Transom Window		9	SF	6	\$152	
Į	Doors - Wood Doors inclu hw		2	EA	5	\$2,348	
Į	Floor - Tile		625	SF	5	\$2,806	
ł	Lighting - Lay-in		12	EA	6	\$1,428	
I	Marker Board		10	LF	6	\$214	
1	Storage/ Closet		196	SF	6	\$1,421	
١	Walls - Concrete Block		130	SF	6	\$381	
١	Walls - Metal Panel		630	SF	5	\$19,270	
roo	m #353 (Science Lab Level 2)						
	Casework		12	LF	6	\$303	
1	Ceiling - Lay-in		950	SF	6	\$2,853	
ł	Doors - Side-lite		20	SF	6	\$334	
1	Doors - Transom Window		8	SF	6	\$135	
1	Doors - Wood Doors inclu hw		2	EA	6	\$602	
1	Eye Wash Station		1	EA	6	\$336	
r	Floor - Tile		950	SF	6	\$2,079	

Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #353 (Science Lab Level 2)						
	Fume Hood		1	EA	6	\$816	
	Gas Line		10	EA	6	\$5,091	
	Lighting - Lay-in		35	EA	6	\$4,164	
	Marker Board		10	LF	6	\$214	
	Walls - Concrete Block		250	SF	6	\$733	
	Walls - Metal Panel		876	SF	6	\$6,539	
	Work Sink		2	EA	6	\$758	
Classro	oom #354 (Science Lab Level 2)						
	Casework		21	LF	5	\$4,391	
	Ceiling - Lay-in		888	SF	6	\$2,667	
	Doors - Side-lite		10	SF	6	\$167	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	
	Eye Wash Station		1	EA	6	\$336	
	Floor - Tile		888	SF	7	\$0	
	Fume Hood		1	EA	6	\$816	
	Gas Line		16	EA	6	\$8,146	
	Lighting - Lay-in		37	EA	6	\$4,402	
	Marker Board		15	LF	6	\$321	
	Storage/ Closet		299	SF	6	\$2,168	
	Walls - Concrete Block		120	SF	5	\$1,232	
	Walls - Metal Panel		810	SF	6	\$6,046	
	Work Sink		8	EA	6	\$3,032	
Classro	oom #355 (Science Lab Level 3)						
	Casework		50	LF	5	\$10,454	
	Ceiling - Lay-in		1,850	SF	6	\$5,556	
	Chalk Board		5	LF	4	\$459	obsolete material.
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		1,850	SF	6	\$4,048	
	Gas Line		4	EA	6	\$2,036	
	Lighting - Lay-in		24	EA	6	\$2,855	
	Marker Board		7	LF	6	\$150	
	Storage/ Closet		81	SF	6	\$587	
	Walls - Concrete Block		309	SF	4	\$11,078	cracks throughout wall
	Walls - Metal Panel		890	SF	6	\$6,643	-
					-	, .,	

p Ite	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	#355 (Science Lab Level 3)						
	ork Sink		2	EA	6	\$758	
	#360 (Science Lab Level 2)						
	asework		23	LF	6	\$581	
	eiling - Lay-in		23 900	SF	6	\$2,703	
	nalk Board		5	LF	4	\$2,703 \$459	Obsolete Material.
	pors - Side-lite		11	SF	6	\$439 \$184	
	pors - Transom Window		12	SF	6	\$203	
	pors - Wood Doors inclu hw		12	EA	5	\$203 \$1,174	
	ve Wash Station		1	EA	5	\$844	
	oor - Tile		900	SF	7	\$044 \$0	
	ume Hood		900	EA	6	\$0 \$816	
	as Line		20	EA	6	\$10,182	
	ghting - Lay-in		28	EA	5	\$4,541	
-	arker Board		10	LF	5	\$507	
	alls - Concrete Block		156	SF	6	\$457	
	alls - Metal Panel		650	SF	6	\$4,852	
	ork Sink		9	EA	6	\$3,411	
			0	LA	0	ψ0,411	
	#361 (Science Lab Level 2)						
	asework		50	LF	6	\$1,263	
	eiling - Lay-in		900	SF	6	\$2,703	
	pors - Wood Doors inclu hw		1	EA	6	\$301	
	ve Wash Station		1	EA	6	\$336	
	oor - Tile		900	SF	6	\$1,969	
	ume Hood		1	EA	6	\$816	
	as Line		12	EA	6	\$6,109	
-	ghting - Lay-in		30	EA	6	\$3,569	
	arker Board		10	LF	6	\$214	
	alls - Concrete Block		156	SF	4		cracks throught.
	alls - Metal Panel		725	SF	5	\$22,176	
W	ork Sink		12	EA	6	\$4,548	
sroom	#362 (Regular Classroom)						
Ce	eiling - Lay-in		500	SF	6	\$1,502	
Do	oors - Side-lite		11	SF	6	\$184	
Do	oors - Transom Window		9	SF	6	\$152	
Do	oors - Wood Doors inclu hw		2	EA	5	\$2,348	
Flo	oor - Tile		500	SF	6	\$1,094	

Building: Building A

-	Home Time	Laster	0	11	Devil	• • • • •	Commonto
	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #362 (Regular Classroom)					Ac	
	Lighting - Lay-in		28	EA	6	\$3,331	
	Marker Board		13	LF	6	\$278	
	Walls - Concrete Block		156	SF	5	\$1,602	
	Walls - Metal Panel		555	SF	6	\$4,143	
	Walls - Plaster/Drywall		300	SF	7	\$0	
Classro	oom #363 (Science Lab Level 2)						
	Casework		43	LF	6	\$1,086	
	Ceiling - Lay-in		900	SF	6	\$2,703	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Eye Wash Station		1	EA	7	\$0	
	Floor - Tile		900	SF	6	\$1,969	
	Fume Hood		1	EA	6	\$816	
	Gas Line		24	EA	6	\$12,219	
	Lighting - Lay-in		28	EA	6	\$3,331	
	Marker Board		10	LF	7	\$0	
	Walls - Concrete Block		156	SF	5	\$1,602	
	Walls - Metal Panel		750	SF	6	\$5,598	
	Work Sink		1	EA	6	\$379	
Classro	oom #364 (Regular Classroom)						
	Casework		4	LF	6	\$101	
	Ceiling - Lay-in		750	SF	6	\$2,252	
	Doors - Side-lite		9	SF	6	\$150	
	Doors - Transom Window		14	SF	6	\$237	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		750	SF	7	\$0	
	Lighting - Lay-in		14	EA	6	\$1,666	
	Marker Board		22	LF	6	\$471	
	Walls - Concrete Block		130	SF	6	\$381	
	Walls - Metal Panel		805	SF	6	\$6,009	
Classro	oom #365 (Regular Classroom)						
5140010	Ceiling - Lay-in		725	SF	6	\$2,177	
	Chalk Board		10	LF	4		obsolete material.
	Doors - Side-lite		9	SF	4 6	\$910 \$150	
	Doors - Transom Window		9 11	SF	6	\$130 \$186	
			11	0	0	φ100	

Categ	Category: Classrooms								
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Classro	om #365 (Regular Classroom)								
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile		725	SF	7	\$0			
	Lighting - Lay-in		14	EA	6	\$1,666			
	Marker Board		15	LF	6	\$321			
	Walls - Concrete Block		130	SF	5	\$1,335			
	Walls - Metal Panel		785	SF	6	\$5,860			
Classro	om #366 (Regular Classroom)								
	Casework		5	LF	6	\$126			
	Ceiling - Lay-in		750	SF	4	\$7,625	water damage stains		
	Doors - Side-lite		11	SF	6	\$184			
	Doors - Transom Window		9	SF	6	\$152			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile		750	SF	7	\$0			
	Lighting - Lay-in		15	EA	6	\$1,785			
	Marker Board		23	LF	6	\$493			
	Walls - Concrete Block		130	SF	6	\$381			
	Walls - Metal Panel		805	SF	6	\$6,009			
Classro	om #367 (Regular Classroom)								
	Casework		5	LF	6	\$126			
	Ceiling - Lay-in		750	SF	4	\$7,625	water damage		
	Chalk Board		10	LF	4	\$918			
	Doors - Side-lite		14	SF	6	\$234			
	Doors - Transom Window		9	SF	6	\$152			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile/Sheet		750	SF	7	\$0			
	Lighting - Pendent/Surface		15	EA	6	\$1,858			
	Marker Board		10	LF	6	\$214			
	Walls - Concrete Block		130	SF	6	\$381			
	Walls - Metal Panel		805	SF	6	\$6,009			
Classro	om #368 (Regular Classroom)								
	Casework		5	LF	6	\$126			
	Ceiling - Lay-in		750	SF	6	\$2,252			
	Chalk Board		10	LF	4	\$918	obsolete material.		
	Doors - Side-lite		14	SF	6	\$234			
	Doors - Transom Window		9	SF	6	\$152			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			

Catego	Category: Classrooms								
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments		
Classro	om #368 (Regular Classroom)								
	Floor - Tile/Sheet		750	SF	6	\$751			
	Lighting - Pendent/Surface		15	EA	6	\$1,858			
	Marker Board		10	LF	6	\$214			
	Walls - Concrete Block		130	SF	6	\$381			
	Walls - Metal Panel		805	SF	6	\$6,009			
Classro	om #369 (Computer Lab)								
	Ceiling - Lay-in		960	SF	7	\$0			
	Doors - Side-lite		14	SF	6	\$234			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile/Sheet		960	SF	7	\$0			
	Lighting - Lay-in		25	EA	6	\$2,974			
	Marker Board		6	LF	7	\$0			
	Walls - Concrete Block		800	SF	6	\$2,345			
	Walls - Metal Panel		240	SF	7	\$0			
	Wireless System		1	EA	7	\$0			
Classro	om #370 (Special Education)								
	Ceiling - Plaster/Drywall		350	SF	6	\$1,211			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile/Sheet		350	SF	7	\$0			
	Lighting - Pendent/Surface		8	EA	6	\$991			
	Marker Board		12	LF	6	\$257			
	Walls - Concrete Block		458	SF	5	\$4,702			
	Walls - Metal Panel		250	SF	6	\$1,866			
Classro	om #371 (Regular Classroom)								
	Ceiling - Lay-in		960	SF	6	\$2,883			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile/Sheet		960	SF	7	\$0			
	Lighting - Pendent/Surface		16	EA	6	\$1,982			
	Marker Board		12	LF	6	\$257			
	Walls - Concrete Block		180	SF	6	\$528			
	Walls - Metal Panel		795	SF	6	\$5,934			
Classro	om #373 (Regular Classroom)								
	Ceiling - Lay-in		400	SF	6	\$1,201			
	Doors - Wood Doors inclu hw		1	EA	6	\$301			
	Floor - Tile/Sheet		400	SF	7	\$0			

ear	ory: Classrooms						
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #373 (Regular Classroom)	Location	quantity	0	- Carine	0000	
	Lighting - Pendent/Surface		9	EA	6	\$1,115	
	Marker Board		10	LF	6	\$214	
	Walls - Metal Panel		695	SF	6	\$5,188	
sro	om #374 (Regular Classroom)						
	Ceiling - Lay-in		696	SF	6	\$2,090	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		696	SF	7	\$0	
	Lighting - Pendent/Surface		15	EA	6	\$1,858	
	Walls - Concrete Block		360	SF	6	\$1,055	
	Walls - Metal Panel		550	SF	6	\$4,106	
sro	om #375 (Regular Classroom)						
	Ceiling - Lay-in		722	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		722	SF	6	\$723	
	Lighting - Lay-in		13	EA	6	\$1,547	
	Marker Board		15	LF	7	\$0	
	Walls - Metal Panel		1,050	SF	6	\$7,838	
	Wireless System		1	EA	6	\$372	
sro	om #377 (Regular Classroom)						
	Ceiling - Lay-in		696	SF	6	\$2,090	
	Doors - Side-lite		14	SF	6	\$234	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		696	SF	7	\$0	
	Lighting - Lay-in		13	EA	6	\$1,547	
	Marker Board		8	LF	6	\$171	
	Walls - Concrete Block		96	SF	6	\$281	
	Walls - Metal Panel		799	SF	6	\$5,964	
sro	om #378 (Regular Classroom)						
	Ceiling - Lay-in		725	SF	6	\$2,177	
	Doors - Side-lite		14	SF	6	\$234	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		725	SF	7	\$0	

Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #378 (Regular Classroom)						
	Lighting - Lay-in		13	EA	6	\$1,547	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		170	SF	6	\$498	
	Walls - Metal Panel		769	SF	6	\$5,740	
Classro	oom #379 (Regular Classroom)						
	Ceiling - Lay-in		580	SF	6	\$1,742	
	Doors - Side-lite		14	SF	6	\$234	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		580	SF	6	\$581	
	Lighting - Lay-in		8	EA	6	\$952	
	Marker Board		6	LF	6	\$129	
	Walls - Metal Panel		705	SF	6	\$5,263	
Classro	om #380 (Computer Lab)						
	Ceiling - Lay-in		900	SF	5	\$5,354	water damage
	Doors - Side-lite		14	SF	6	\$234	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile/Sheet		900	SF	7	\$0	
	Lighting - Lay-in		14	EA	7	\$0	
	Marker Board		10	LF	6	\$214	
	Walls - Concrete Block		156	SF	6	\$457	
	Walls - Metal Panel		555	SF	6	\$4,143	
	Walls - Plaster/Drywall		300	SF	6	\$828	
	Wireless System		1	EA	6	\$372	
Classro	om #381 (Laboratory/Shop)						
	Ceiling - Lay-in		2,000	SF	7	\$0	
	Doors - Side-lite		20	SF	7	\$0	
	Doors - Steel Doors incl hw		1	EA	7	\$0	
	Doors - Transom Window		18	SF	6	\$305	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Tile		954	SF	7	\$0	
	Floor - Tile Quarry		1,046	SF	6	\$2,214	
	Lighting - Lay-in		39	EA	6	\$4,640	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		208	SF	6	\$610	
Building: Building A

Categ	ory: Classrooms						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #381 (Laboratory/Shop)						
	Walls - Plaster/Drywall		610	SF	6	\$1,684	
	Walls - Tile		470	SF	7	\$0	
	Work Sink		7	EA	6	\$2,653	
Classro	om #381B (Laboratory/Shop)						
	Ceiling - Lay-in	3rd Floor	279	SF	6	\$838	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	279	SF	6	\$610	
	Lighting - Lay-in	3rd Floor	6	EA	7	\$0	
	Walls - Metal Panel	3rd Floor	575	SF	6	\$4,292	
Classro	om #383 (Science Lab Level 3)						
	Casework		11	LF	6	\$278	
	Ceiling - Lay-in		986	SF	5	\$5,866	
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Transom Window		13	SF	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Tile		986	SF	6	\$2,157	
	Gas Line		2	EA	6	\$1,018	
	Lighting - Lay-in		35	EA	6	\$4,164	
	Marker Board		12	LF	6	\$257	
	Walls - Concrete Block		374	SF	5	\$3,840	
	Walls - Metal Panel		500	SF	5	\$15,294	
	Work Sink		3	EA	6	\$1,137	

Classrooms Subtotal:

\$2,094,199

Building: Building A

	•				
Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Administrative Suites/Offices					
Ceiling - Lay-in	126 - Guidance Office	114	SF	7	\$0
Doors - Side-lite	126 - Guidance Office	12	SF	7	\$0
Doors - Transom Window	126 - Guidance Office	5	SF	7	\$O
Doors - Wood Doors inclu hw	126 - Guidance Office	1	EA	6	\$301
Floor - Tile/Sheet	126 - Guidance Office	114	SF	6	\$114
Lighting - Pendent/Surface	126 - Guidance Office	4	EA	7	\$0
Power Distribution	126 - Guidance Office	4	EA	7	\$0



Building: Building A

	126 - Guidance Office	120	SF	7	\$0	
	126 - Guidance Office	265	SF	6	\$1,978	
	127 - Guidance Office	114	SF	6	\$342	
	127 - Guidance Office	30	SF	7	\$0	
W	127 - Guidance Office	20	SF	7	\$0	
lu hw	127 - Guidance Office	1	EA	6	\$301	
	127 - Guidance Office	114	SF	6	\$114	
ace	127 - Guidance Office	4	EA	7	\$0	
	127 - Guidance Office	4	EA	7	\$0	
	127 - Guidance Office	360	SF	7	\$0	
	128 - Guidance Office	114	SF	7	\$0	
lu hw	128 - Guidance Office	1	EA	6	\$301	
	128 - Guidance Office	114	SF	6	\$114	
ace	128 - Guidance Office	4	EA	7	\$0	
	128 - Guidance Office	4	EA	6	\$8,500	
	128 - Guidance Office	410	SF	6	\$3,060	
	129 - Special Ed Office	114	SF	6	\$342	
lu hw	129 - Special Ed Office	1	EA	6	\$301	
	129 - Special Ed Office	114	SF	6	\$114	
ace	129 - Special Ed Office	4	EA	7	\$0	
	129 - Special Ed Office	4	EA	6	\$8,500	
	129 - Special Ed Office	410	SF	6	\$1,290	
	130 - Guidance Office	114	SF	7	\$0	
	130 - Guidance Office	30	SF	7	\$0	
W	130 - Guidance Office	20	SF	7	\$0	
lu hw	130 - Guidance Office	1	EA	6	\$301	
	130 - Guidance Office	114	SF	6	\$114	
ace	130 - Guidance Office	4	EA	6	\$496	
	130 - Guidance Office	4	EA	7	\$0	
	130 - Guidance Office	360	SF	6	\$2,687	
	131 - Guidance Office	114	SF	6	\$342	
	131 - Guidance Office	30	SF	7	\$0	
W	131 - Guidance Office	20	SF	7	\$0	
lu hw	131 - Guidance Office	1	EA	6	\$301	
	131 - Guidance Office	114	SF	7	\$0	
ace	131 - Guidance Office	4	EA	6	\$496	
	131 - Guidance Office	4	EA	6	\$8,500	
	ace	lu hw 128 - Guidance Office 128 - Guidance Office 128 - Guidance Office 128 - Guidance Office 128 - Guidance Office 129 - Special Ed Office 130 - Guidance Office 131 - Guidance Office	Iu hw 128 - Guidance Office 1 ace 128 - Guidance Office 14 ace 128 - Guidance Office 4 128 - Guidance Office 4 128 - Guidance Office 4 128 - Guidance Office 4 128 - Guidance Office 4 129 - Special Ed Office 114 129 - Special Ed Office 114 Iu hw 129 - Special Ed Office 114 129 - Special Ed Office 114 ace 129 - Special Ed Office 4 129 - Special Ed Office 4 ace 129 - Special Ed Office 4 129 - Special Ed Office 4 uace 130 - Guidance Office 114 130 - Guidance Office 114 uace 130 - Guidance Office 114 130 - Guidance Office 114 ace 130 - Guidance Office 114 130 - Guidance Office 114 ace 130 - Guidance Office 114 131 - Guidance Office 114 uace 130 - Guidance Office 114 131 - Guidance Office 114 uace 13	lu hw 128 - Guidance Office 1 KA 128 - Guidance Office 114 SF ace 128 - Guidance Office 4 EA 128 - Guidance Office 4 EA 128 - Guidance Office 114 SF 129 - Special Ed Office 1 K 129 - Special Ed Office 4 EA 129 - Special Ed Office 4 EA 129 - Special Ed Office 1 K 129 - Special Ed Office 1 K 130 - Guidance Office 1 K 131 - Guidance Office 1 K 132 - Guidance Office 1 K 133 - Guidance Office 1 K 131 - Guidance Office 1 K 132 - Guidance Office 1 K 133 - Guidance Office 1 K 131 - Guidance Office 1 K 1	Iu hw 128 - Guidance Office 1 EA 6 128 - Guidance Office 114 SF 6 ace 128 - Guidance Office 4 EA 7 128 - Guidance Office 4 EA 7 128 - Guidance Office 4 EA 6 128 - Guidance Office 4 EA 6 129 - Special Ed Office 114 SF 6 1u hw 129 - Special Ed Office 1 EA 6 129 - Special Ed Office 1 SF 6 ace 129 - Special Ed Office 1 EA 6 129 - Special Ed Office 4 EA 7 ace 129 - Special Ed Office 4 EA 6 130 - Guidance Office 114 SF 7 w 130 - Guidance Office 114 SF 7 w 130 - Guidance Office 1 EA 6 130 - Guidance Office 1 SF 6	Iu hw 128 - Guidance Office 1 EA 6 \$301 128 - Guidance Office 114 SF 6 \$114 ace 128 - Guidance Office 4 EA 7 \$0 128 - Guidance Office 4 EA 6 \$85,000 128 - Guidance Office 410 SF 6 \$30,600 129 - Special Ed Office 114 SF 6 \$31,200 lu hw 129 - Special Ed Office 114 SF 6 \$3114 ace 129 - Special Ed Office 114 SF 6 \$3114 ace 129 - Special Ed Office 144 SF 6 \$3114 ace 129 - Special Ed Office 4 EA 7 \$0 130 - Guidance Office 114 SF 6 \$129.00 130 - Guidance Office 114 SF 7 \$0 130 - Guidance Office 14 SF 6 \$114 ace 130 - Guidance Office 14<



Building: Building A

iroup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	strative Suites/Offices						
	Walls - Metal Panel	131 - Guidance Office	360	SF	6	\$2,687	
	Ceiling - Lay-in	142B IT Office	817	SF	7	\$0	
	Doors - Wood Doors inclu hw	142B IT Office	2	EA	6	\$602	
	Floor - Tile/Sheet	142B IT Office	817	SF	6	\$818	
	Lighting - Pendent/Surface	142B IT Office	31	EA	6	\$3,841	
	Power Distribution	142B IT Office	14	EA	7	\$0	
	Walls - Metal Panel	142B IT Office	776	SF	6	\$5,793	
	Walls - Plaster/Drywall	142B IT Office	333	SF	7	\$0	
	Work Sink	142B IT Office	3	EA	6	\$1,524	Sink not accessible. Blocked by storage materials Cannot reach to check functionality.
	Ceiling - Lay-in	148B Workroom (previously a darkroom)	195	SF	6	\$586	
	Doors - Wood Doors inclu hw	148B Workroom (previously a darkroom)	1	EA	5	\$1,174	Door was removed and is leaning against a wall in this room
	Floor - Terrazzo	148B Workroom (previously a darkroom)	195	SF	6	\$427	
	Lighting - Pendent/Surface	148B Workroom (previously a darkroom)	4	EA	5	\$730	Lighting did not work
	Power Distribution	148B Workroom (previously a darkroom)	6	EA	7	\$0	
	Walls - Metal Panel	148B Workroom (previously a darkroom)	574	SF	6	\$4,285	
	Work SInk	148B Workroom (previously a darkroom)	1	EA	6	\$508	
	Ceiling - Lay-in	154 Office	195	SF	6	\$586	
	Doors - Side-lite	154 Office	17	SF	7	\$0	
	Doors - Wood Doors inclu hw	154 Office	1	EA	7	\$0	
	Floor - Tile/Sheet	154 Office	195	SF	7	\$0	
	Lighting - Pendent/Surface	154 Office	4	EA	6	\$496	
	Power Distribution	154 Office	4	EA	7	\$0	
	Walls - Concrete Block	154 Office	30	SF	7	\$0	
	Walls - Metal Panel	154 Office	526	SF	6	\$3,926	
	Ceiling - Lay-in	157 - ID Office	168	SF	6	\$505	
	Doors - Wood Doors inclu hw	157 - ID Office	1	EA	6	\$301	
	Floor - Tile/Sheet	157 - ID Office	168	SF	6	\$168	
	Lighting - Pendent/Surface	157 - ID Office	3	EA	7	\$0	
	Power Distribution	157 - ID Office	6	EA	7	\$0	
	Walls - Metal Panel	157 - ID Office	325	SF	6	\$2,426	
	Walls - Plaster/Drywall	157 - ID Office	180	SF	6	\$497	
	Ceiling - Lay-in	159A Office/Storage	218	SF	7	\$0	
	Doors - Side-lite	159A Office/Storage	108	SF	7	\$0	
	Doors - Wood Doors inclu hw	159A Office/Storage	1	EA	7	\$0	
	Floor - Tile/Sheet	159A Office/Storage	218	SF	7	\$0	
	Lighting - Lay-in	159A Office/Storage	2	EA	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Power Distribution	159A Office/Storage	8	EA	7	\$0	Qty is an estimate; Room was filled with stored equipment/boxes.
	Walls - Concrete Block	159A Office/Storage	107	SF	7	\$0	
	Walls - Plaster/Drywall	159A Office/Storage	375	SF	7	\$0	
	Ceiling - Lay-in	165A Work Room	178	SF	7	\$0	
	Doors - Side-lite	165A Work Room	12	SF	7	\$0	
	Doors - Wood Doors inclu hw	165A Work Room	1	EA	6	\$301	
	Floor - Tile/Sheet	165A Work Room	178	SF	7	\$0	
	Lighting - Lay-in	165A Work Room	3	EA	7	\$0	
	Power Distribution	165A Work Room	4	EA	7	\$0	
	Walls - Concrete Block	165A Work Room	431	SF	7	\$0	
	Walls - Plaster/Drywall	165A Work Room	132	SF	7	\$0	
	Ceiling - Lay-in	165B Control Room	188	SF	7	\$0	
	Doors - Wood Doors inclu hw	165B Control Room	1	EA	6	\$301	
	Lighting - Lay-in	165B Control Room	3	EA	7	\$0	
	Power Distribution	165B Control Room	4	EA	7	\$0	
	Walls - Concrete Block	165B Control Room	195	SF	7	\$0	
	Walls - Plaster/Drywall	165B Control Room	368	SF	7	\$0	
	Ceiling - Lay-in	167A - Office	190	SF	7	\$0	
	Doors - Wood Doors inclu hw	167A - Office	1	EA	7	\$0	
	Floor - Carpet	167A - Office	190	SF	5	\$975	carpet is very worn
	Lighting - Pendent/Surface	167A - Office	5	EA	6	\$619	
	Power Distribution	167A - Office	4	EA	7	\$0	
	Walls - Concrete Block	167A - Office	390	SF	6	\$1,143	
	Walls - Metal Panel	167A - Office	188	SF	6	\$1,403	
	Ceiling - Lay-in	168A Office/Storage	207	SF	7	\$0	Lockers in this room are used to store books
	Doors - Wood Doors inclu hw	168A Office/Storage	1	EA	7	\$0	
	Floor - Carpet	168A Office/Storage	207	SF	4	\$1,903	Carpet is very worn and stained
	Lighting - Pendent/Surface	168A Office/Storage	5	EA	6	\$619	
	Power Distribution	168A Office/Storage	4	EA	7	\$0	
	Walls - Concrete Block	168A Office/Storage	303	SF	7	\$0	
	Walls - Metal Panel	168A Office/Storage	103	SF	7	\$0	
	Walls - Plaster/Drywall	168A Office/Storage	200	SF	6	\$552	
	Ceiling - Lay-in	169 - Dean's Office open area	920	SF	7	\$0	Ceiling covers rooms 169C, 169D, and 169E which have partial height walls
	Doors - Side-lite	169 - Dean's Office open area	12	SF	7	\$0	
	Doors - Transom Window	169 - Dean's Office open area	15	SF	7	\$0	
	Doors - Wood Doors inclu hw	169 - Dean's Office open area	1	EA	7	\$0	



Building: Building A

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
Floor - Tile/Sheet	169 - Dean's Office open area	594	SF	6	\$595	
Lighting - Pendent/Surface	169 - Dean's Office open area	18	EA	6	\$2,230	Lighting covers rooms 169C, 169D, and 169 which have partial height walls
Power Distribution	169 - Dean's Office open area	10	EA	7	\$0	
Walls - Concrete Block	169 - Dean's Office open area	190	SF	7	\$0	
Walls - Metal Panel	169 - Dean's Office open area	220	SF	6	\$1,642	
Walls - Plaster/Drywall	169 - Dean's Office open area	304	SF	6	\$839	
Ceiling - Plaster/Drywall	169A Camera Viewing Rm	145	SF	7	\$0	
Doors - Transom Window	169A Camera Viewing Rm	10	SF	7	\$0	
Doors - Wood Doors inclu hw	169A Camera Viewing Rm	2	EA	7	\$0	
Floor - Tile/Sheet	169A Camera Viewing Rm	145	SF	7	\$0	
Lighting - Pendent/Surface	169A Camera Viewing Rm	2	EA	6	\$248	
Power Distribution	169A Camera Viewing Rm	4	EA	6	\$8,500	
Walls - Concrete Block	169A Camera Viewing Rm	97	SF	6	\$284	
Walls - Metal Panel	169A Camera Viewing Rm	337	SF	6	\$2,516	
Ceiling - Lay-in	169B Police Office	146	SF	6	\$438	
Doors - Wood Doors inclu hw	169B Police Office	1	EA	6	\$301	
Floor - Tile/Sheet	169B Police Office	146	SF	6	\$146	
Lighting - Pendent/Surface	169B Police Office	3	EA	7	\$0	
Power Distribution	169B Police Office	2	EA	6	\$4,250	
Walls - Concrete Block	169B Police Office	128	SF	7	\$0	
Walls - Metal Panel	169B Police Office	428	SF	6	\$3,195	
Doors - Wood Doors inclu hw	169C Copy/File Rm.	2	EA	7	\$0	
Floor - Tile/Sheet	169C Copy/File Rm.	200	SF	7	\$0	
Power Distribution	169C Copy/File Rm.	4	EA	7	\$0	
Walls - Concrete Block	169C Copy/File Rm.	30	SF	7	\$0	
Walls - Metal Panel	169C Copy/File Rm.	298	SF	6	\$2,224	
Walls - Plaster/Drywall	169C Copy/File Rm.	238	SF	6	\$657	
Doors - Wood Doors inclu hw	169D Office	1	EA	7	\$0	
Floor - Tile/Sheet	169D Office	191	SF	7	\$0	
Power Distribution	169D Office	4	EA	7	\$0	
Walls - Concrete Block	169D Office	50	SF	7	\$0	
Walls - Metal Panel	169D Office	150	SF	6	\$1,120	
Walls - Plaster/Drywall	169D Office	232	SF	7	\$0	
Doors - Wood Doors inclu hw	169E Conference Rm	1	EA	7	\$0	
Floor - Tile/Sheet	169E Conference Rm	155	SF	7	\$0	
Power Distribution	169E Conference Rm	4	EA	7	\$0	
Walls - Concrete Block	169E Conference Rm	164	SF	6	\$481	



Building: Building A

	ive Suites/Offices						
Wal							
	Ills - Plaster/Drywall	169E Conference Rm	203	SF	7	\$0	
Ceili	ling - Lay-in	170 Nurse's Office	316	SF	6	\$949	
Doo	ors - Wood Doors inclu hw	170 Nurse's Office	1	EA	7	\$0	
Floc	or - Tile/Sheet	170 Nurse's Office	316	SF	7	\$0	
Ligh	hting - Pendent/Surface	170 Nurse's Office	5	EA	6	\$619	
Pow	ver Distribution	170 Nurse's Office	4	EA	7	\$0	
Wal	Ils - Concrete Block	170 Nurse's Office	338	SF	7	\$0	
Wal	ills - Metal Panel	170 Nurse's Office	298	SF	6	\$2,224	
Wal	Ils - Plaster/Drywall	170 Nurse's Office	145	SF	6	\$400	
Ceili	ling - Lay-in	170A	95	SF	7	\$0	
Doo	ors - Side-lite	170A	12	SF	7	\$0	
Doo	ors - Transom Window	170A	5	SF	7	\$0	
Doo	ors - Wood Doors inclu hw	170A	2	EA	6	\$602	
Floc	or - Tile/Sheet	170A	95	SF	7	\$0	
Ligh	hting - Pendent/Surface	170A	2	EA	7	\$0	
Pow	ver Distribution	170A	4	EA	7	\$0	
Wal	Ills - Concrete Block	170A	77	SF	7	\$0	
Wal	ills - Metal Panel	170A	256	SF	6	\$1,911	
Ceili	ling - Lay-in	170B	146	SF	7	\$0	
Doo	ors - Side-lite	170B	50	SF	7	\$0	
Doo	ors - Wood Doors inclu hw	170B	1	EA	7	\$0	
Floc	or - Tile/Sheet	170B	146	SF	7	\$0	
Ligh	hting - Pendent/Surface	170B	3	EA	7	\$0	
Pow	ver Distribution	170B	8	EA	7	\$0	
Wal	ills - Metal Panel	170B	424	SF	6	\$3,165	
Ceili	ling - Lay-in	170C Office	198	SF	6	\$595	
Doo	ors - Wood Doors inclu hw	170C Office	1	EA	7	\$0	
Floc	or - Carpet	170C Office	198	SF	5	\$1,016	
Ligh	hting - Pendent/Surface	170C Office	4	EA	7	\$0	
Pow	ver Distribution	170C Office	16	EA	7	\$0	
Wal	Ils - Concrete Block	170C Office	50	SF	7	\$0	
Wal	ills - Metal Panel	170C Office	475	SF	6	\$3,546	
Ceili	ling - Lay-in	170D Exam Room	147	SF	6	\$441	
Doo	ors - Wood Doors inclu hw	170D Exam Room	1	EA	6	\$301	
Floc	or - Tile/Sheet	170D Exam Room	147	SF	7	\$0	
Ligh	hting - Pendent/Surface	170D Exam Room	3	EA	7	\$0	
Pow	ver Distribution	170D Exam Room	4	EA	7	\$0	



Building: Building A

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Iministrative Suites/Offices						
Walls - Concrete Block	170D Exam Room	222	SF	7	\$0	
Walls - Metal Panel	170D Exam Room	277	SF	6	\$2,068	
Ceiling - Lay-in	171 Main Office	1,521	SF	7	\$0	
Doors - Side-lite	171 Main Office	100	SF	7	\$0	
Doors - Steel Doors incl hw	171 Main Office	1	EA	7	\$0	
Doors - Transom Window	171 Main Office	5	SF	7	\$0	
Doors - Wood Doors inclu hw	171 Main Office	4	EA	7	\$0	
Floor - Carpet	171 Main Office	1,206	SF	4	\$11,089	carpet stained, old and needs replacement
Floor - Tile/Sheet	171 Main Office	315	SF	7	\$0	
Lighting - Pendent/Surface	171 Main Office	30	EA	6	\$3,717	
Power Distribution	171 Main Office	28	EA	7	\$0	
Storage/ Closet	171 Main Office	903	SF	7	\$0	
Walls - Concrete Block	171 Main Office	450	SF	7	\$0	
Walls - Metal Panel	171 Main Office	726	SF	6	\$5,419	
Walls - Plaster/Drywall	171 Main Office	50	SF	7	\$0	
Ceiling - Lay-in	171A Mail Room	219	SF	7	\$0	
Doors - Side-lite	171A Mail Room	24	SF	7	\$0	
Doors - Transom Window	171A Mail Room	20	SF	7	\$0	
Doors - Wood Doors inclu hw	171A Mail Room	1	EA	7	\$0	
Floor - Tile/Sheet	171A Mail Room	219	SF	7	\$0	
Lighting - Pendent/Surface	171A Mail Room	4	EA	7	\$0	
Walls - Concrete Block	171A Mail Room	100	SF	7	\$0	
Walls - Metal Panel	171A Mail Room	223	SF	7	\$0	
Walls - Plaster/Drywall	171A Mail Room	124	SF	6	\$342	
Ceiling - Lay-in	171B Work Room	355	SF	7	\$0	
Doors - Side-lite	171B Work Room	25	SF	7	\$0	
Doors - Transom Window	171B Work Room	10	SF	7	\$0	
Doors - Wood Doors inclu hw	171B Work Room	1	EA	7	\$0	
Floor - Carpet	171B Work Room	355	SF	5	\$1,822	
Lighting - Pendent/Surface	171B Work Room	8	EA	7	\$0	
Power Distribution	171B Work Room	6	EA	7	\$0	
Walls - Concrete Block	171B Work Room	50	SF	6	\$147	
Walls - Metal Panel	171B Work Room	450	SF	7	\$0	
Walls - Plaster/Drywall	171B Work Room	124	SF	6	\$342	
Work SInk	171B Work Room	1	EA	6	\$508	
Ceiling - Lay-in	176 Office	178	SF	6	\$535	
Doors - Side-lite	176 Office	5	SF	7	\$0	



Building: Building A

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
Doors - Side-lite	176 Office	12	SF	7	\$0	
Doors - Wood Doors inclu hw	176 Office	1	EA	7	\$0	
Floor - Carpet	176 Office	178	SF	6	\$379	
Lighting - Pendent/Surface	176 Office	4	EA	6	\$496	
Power Distribution	176 Office	8	EA	7	\$0	
Walls - Concrete Block	176 Office	278	SF	7	\$0	
Walls - Metal Panel	176 Office	124	SF	7	\$0	
Ceiling - Lay-in	177 Office	145	SF	6	\$435	
Doors - Side-lite	177 Office	35	SF	7	\$0	
Doors - Transom Window	177 Office	25	SF	7	\$0	
Doors - Wood Doors inclu hw	177 Office	1	EA	7	\$0	
Floor - Carpet	177 Office	145	SF	6	\$309	
Lighting - Pendent/Surface	177 Office	3	EA	7	\$0	
Power Distribution	177 Office	6	EA	7	\$0	
Walls - Concrete Block	177 Office	40	SF	7	\$0	
Walls - Metal Panel	177 Office	313	SF	6	\$2,336	
Ceiling - Lay-in	178 Principal Reception Area	390	SF	7	\$0	
Doors - Side-lite	178 Principal Reception Area	15	SF	7	\$0	
Doors - Wood Doors inclu hw	178 Principal Reception Area	1	EA	7	\$0	
Floor - Carpet	178 Principal Reception Area	390	SF	6	\$831	
Lighting - Pendent/Surface	178 Principal Reception Area	8	EA	6	\$991	
Power Distribution	178 Principal Reception Area	4	EA	7	\$0	
Walls - Concrete Block	178 Principal Reception Area	80	SF	7	\$0	
Walls - Metal Panel	178 Principal Reception Area	588	SF	6	\$4,389	
Walls - Plaster/Drywall	178 Principal Reception Area	90	SF	7	\$0	
Ceiling - Lay-in	180 Principal's Office	277	SF	7	\$0	
Doors - Side-lite	180 Principal's Office	24	SF	7	\$0	
Doors - Transom Window	180 Principal's Office	10	SF	7	\$0	
Doors - Wood Doors inclu hw	180 Principal's Office	2	EA	7	\$0	
Floor - Tile/Sheet	180 Principal's Office	277	SF	7	\$0	
Lighting - Pendent/Surface	180 Principal's Office	6	EA	7	\$0	
Power Distribution	180 Principal's Office	8	EA	7	\$0	
Walls - Concrete Block	180 Principal's Office	70	SF	7	\$0	
Walls - Metal Panel	180 Principal's Office	404	SF	7	\$0	
Ceiling - Lay-in	182 Conference Room	257	SF	7	\$0	
Doors - Side-lite	182 Conference Room	12	SF	7	\$0	
Doors - Transom Window	182 Conference Room	5	SF	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Doors - Wood Doors inclu hw	182 Conference Room	2	EA	7	\$0	
	Floor - Tile/Sheet	182 Conference Room	257	SF	7	\$0	
	Lighting - Pendent/Surface	182 Conference Room	5	EA	7	\$0	
	Power Distribution	182 Conference Room	8	EA	7	\$0	
	Walls - Concrete Block	182 Conference Room	128	SF	7	\$0	
	Walls - Metal Panel	182 Conference Room	413	SF	7	\$0	
	Ceiling - Lay-in	183 Office	140	SF	6	\$420	
	Doors - Side-lite	183 Office	12	SF	7	\$0	
	Doors - Transom Window	183 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	183 Office	2	EA	7	\$0	
	Floor - Carpet	183 Office	140	SF	7	\$0	
	Lighting - Pendent/Surface	183 Office	5	EA	7	\$0	
	Power Distribution	183 Office	4	EA	7	\$0	
	Walls - Concrete Block	183 Office	80	SF	7	\$0	
	Walls - Metal Panel	183 Office	352	SF	6	\$2,628	
	Ceiling - Lay-in	184 Office	331	SF	6	\$994	
	Doors - Side-lite	184 Office	12	SF	7	\$0	
	Doors - Transom Window	184 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	184 Office	2	EA	7	\$0	
	Floor - Carpet	184 Office	331	SF	7	\$0	
	Lighting - Pendent/Surface	184 Office	10	EA	6	\$1,239	
	Power Distribution	184 Office	6	EA	6	\$12,749	
	Walls - Concrete Block	184 Office	360	SF	6	\$1,055	crack in concrete block
	Walls - Metal Panel	184 Office	343	SF	6	\$2,560	
	Ceiling - Lay-in	185 Office	192	SF	7	\$0	
	Doors - Side-lite	185 Office	12	SF	7	\$0	
	Doors - Transom Window	185 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	185 Office	2	EA	7	\$0	
	Floor - Carpet	185 Office	192	SF	6	\$409	
	Lighting - Pendent/Surface	185 Office	7	EA	6	\$867	
	Power Distribution	185 Office	6	EA	7	\$0	
	Walls - Concrete Block	185 Office	79	SF	7	\$0	
	Walls - Metal Panel	185 Office	452	SF	6	\$3,374	
	Ceiling - Lay-in	186 Office	146	SF	6	\$438	
	Doors - Side-lite	186 Office	12	SF	7	\$0	
	Doors - Transom Window	186 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	186 Office	1	EA	5	\$1,174	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Floor - Tile/Sheet	186 Office	146	SF	7	\$0	
	Lighting - Pendent/Surface	186 Office	3	EA	6	\$372	
	Power Distribution	186 Office	2	EA	6	\$4,250	
	Walls - Concrete Block	186 Office	60	SF	7	\$0	
	Walls - Metal Panel	186 Office	308	SF	6	\$2,299	
	Ceiling - Lay-in	187 Attendance Office	665	SF	6	\$1,997	
	Doors - Side-lite	187 Attendance Office	24	SF	7	\$0	
	Doors - Transom Window	187 Attendance Office	60	SF	7	\$0	
	Doors - Wood Doors inclu hw	187 Attendance Office	3	EA	6	\$903	
	Floor - Tile/Sheet	187 Attendance Office	665	SF	7	\$0	
	Lighting - Pendent/Surface	187 Attendance Office	12	EA	6	\$1,487	
	Power Distribution	187 Attendance Office	6	EA	6	\$12,749	
	Storage/ Closet	187 Attendance Office	54	SF	7	\$0	
	Walls - Concrete Block	187 Attendance Office	304	SF	7	\$0	
	Walls - Metal Panel	187 Attendance Office	719	SF	6	\$5,367	
	Ceiling - Lay-in	190 Office	97	SF	6	\$291	
	Doors - Side-lite	190 Office	12	SF	7	\$0	
	Doors - Transom Window	190 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	190 Office	1	EA	6	\$301	
	Floor - Tile/Sheet	190 Office	97	SF	7	\$0	
	Lighting - Pendent/Surface	190 Office	2	EA	7	\$0	
	Power Distribution	190 Office	4	EA	7	\$0	
	Walls - Concrete Block	190 Office	40	SF	7	\$0	
	Walls - Metal Panel	190 Office	258	SF	6	\$1,926	
	Ceiling - Lay-in	191 Office	144	SF	6	\$432	
	Doors - Side-lite	191 Office	12	SF	7	\$0	
	Doors - Transom Window	191 Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	191 Office	1	EA	6	\$301	
	Floor - Tile/Sheet	191 Office	144	SF	7	\$0	
	Lighting - Pendent/Surface	191 Office	3	EA	7	\$0	
	Power Distribution	191 Office	4	EA	7	\$0	
	Walls - Concrete Block	191 Office	160	SF	7	\$0	
	Walls - Metal Panel	191 Office	208	SF	6	\$1,553	
	Ceiling - Lay-in	192 - Meeting Room	1,104	SF	6	\$3,315	
	Doors - Side-lite	192 - Meeting Room	24	SF	7	\$0	
	Doors - Transom Window	192 - Meeting Room	30	SF	7	\$0	
	Doors - Wood Doors inclu hw	192 - Meeting Room	3	EA	6	\$903	



Building: Building A

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lmini	strative Suites/Offices						
	Floor - Carpet	192 - Meeting Room	1,104	SF	6	\$2,352	
	Lighting - Pendent/Surface	192 - Meeting Room	21	EA	6	\$2,602	
	Power Distribution	192 - Meeting Room	6	EA	6	\$12,749	
	Storage/ Closet	192 - Meeting Room	53	SF	7	\$0	
	Walls - Concrete Block	192 - Meeting Room	160	SF	7	\$0	
	Walls - Metal Panel	192 - Meeting Room	636	SF	6	\$4,747	
	Ceiling - Lay-in	193 - Local School Council Office	122	SF	6	\$366	
	Doors - Side-lite	193 - Local School Council Office	12	SF	7	\$0	
	Doors - Transom Window	193 - Local School Council Office	5	SF	7	\$0	
	Doors - Wood Doors inclu hw	193 - Local School Council Office	1	EA	7	\$0	
	Floor - Carpet	193 - Local School Council Office	122	SF	6	\$260	
	Lighting - Pendent/Surface	193 - Local School Council Office	2	EA	7	\$0	
	Power Distribution	193 - Local School Council Office	6	EA	7	\$0	
	Walls - Concrete Block	193 - Local School Council Office	40	SF	7	\$0	
	Walls - Metal Panel	193 - Local School Council Office	308	SF	6	\$2,299	
	Ceiling - Lay-in	195 Special Ed Office	120	SF	7	\$0	
	Doors - Side-lite	195 Special Ed Office	37	SF	7	\$0	
	Doors - Transom Window	195 Special Ed Office	15	SF	7	\$0	
	Doors - Wood Doors inclu hw	195 Special Ed Office	2	EA	6	\$602	
	Floor - Tile/Sheet	195 Special Ed Office	120	SF	6	\$120	
	Lighting - Pendent/Surface	195 Special Ed Office	2	EA	7	\$0	
	Power Distribution	195 Special Ed Office	2	EA	6	\$4,250	
	Walls - Concrete Block	195 Special Ed Office	30	SF	7	\$0	
	Walls - Metal Panel	195 Special Ed Office	318	SF	6	\$2,374	
	Work SInk	195 Special Ed Office	1	EA	6	\$508	
	Ceiling - Lay-in	196 Conference Room	296	SF	6	\$889	
	Doors - Wood Doors inclu hw	196 Conference Room	1	EA	6	\$301	
	Floor - Tile/Sheet	196 Conference Room	296	SF	7	\$0	
	Lighting - Pendent/Surface	196 Conference Room	6	EA	6	\$743	
	Power Distribution	196 Conference Room	6	EA	7	\$0	
	Walls - Concrete Block	196 Conference Room	60	SF	7	\$0	
	Walls - Metal Panel	196 Conference Room	353	SF	6	\$2,635	
	Ceiling - Lay-in	197 - Yearbook Office	190	SF	6	\$571	
	Doors - Side-lite	197 - Yearbook Office	75	SF	7	\$0	
	Doors - Transom Window	197 - Yearbook Office	45	SF	7	\$0	
	Doors - Wood Doors inclu hw	197 - Yearbook Office	2	EA	7	\$0	
	Floor - Tile/Sheet	197 - Yearbook Office	190	SF	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Lighting - Pendent/Surface	197 - Yearbook Office	2	EA	7	\$0	
	Power Distribution	197 - Yearbook Office	10	EA	7	\$0	
	Walls - Masonry	197 - Yearbook Office	40	SF	7	\$0	
	Walls - Metal Panel	197 - Yearbook Office	78	SF	6	\$582	
	Walls - Plaster/Drywall	197 - Yearbook Office	253	SF	6	\$698	
	Ceiling - Plaster/Drywall	1st FIr Book Selling/Transaction Counter	348	SF	7	\$0	
	Doors - Side-lite	1st FIr Book Selling/Transaction Counter	114	SF	7	\$0	Counter window
	Doors - Wood Doors inclu hw	1st FIr Book Selling/Transaction Counter	1	EA	6	\$301	
	Floor - Tile/Sheet	1st FIr Book Selling/Transaction Counter	348	SF	7	\$0	
	Lighting - Pendent/Surface	1st FIr Book Selling/Transaction Counter	6	EA	7	\$0	
	Power Distribution	1st FIr Book Selling/Transaction Counter	8	EA	7	\$0	
	Walls - Concrete Block	1st FIr Book Selling/Transaction Counter	170	SF	7	\$0	
	Walls - Masonry	1st FIr Book Selling/Transaction Counter	90	SF	7	\$0	
	Walls - Metal Panel	1st FIr Book Selling/Transaction Counter	895	SF	7	\$0	
	Ceiling - Lay-in	1st flr Faculty Workroom (156 on plan)	725	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st flr Faculty Workroom (156 on plan)	1	EA	6	\$301	
	Floor - Tile/Sheet	1st flr Faculty Workroom (156 on plan)	725	SF	7	\$0	
	Lighting - Pendent/Surface	1st flr Faculty Workroom (156 on plan)	12	EA	7	\$0	
	Power Distribution	1st flr Faculty Workroom (156 on plan)	8	EA	7	\$0	
	Walls - Concrete Block	1st flr Faculty Workroom (156 on plan)	418	SF	7	\$0	
	Walls - Metal Panel	1st flr Faculty Workroom (156 on plan)	355	SF	6	\$2,650	
	Ceiling - Lay-in	1st Flr NW Parent Resource Center (north of 157 ID Office)	185	SF	6	\$556	
	Doors - Steel Doors incl hw	1st Flr NW Parent Resource Center (north of 157 ID Office)	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Flr NW Parent Resource Center (north of 157 ID Office)	185	SF	7	\$0	
	Lighting - Pendent/Surface	1st Flr NW Parent Resource Center (north of 157 ID Office)	2	EA	7	\$0	
	Power Distribution	1st Flr NW Parent Resource Center (north of 157 ID Office)	6	EA	7	\$0	
	Walls - Masonry	1st Flr NW Parent Resource Center (north of 157 ID Office)	80	SF	7	\$0	
	Walls - Metal Panel	1st Flr NW Parent Resource Center (north of 157 ID Office)	365	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st flr Senior Office (east side of elevator 'A')	120	SF	7	\$0	Room is currently being used for storage
	Doors - Wood Doors inclu hw	1st flr Senior Office (east side of elevator 'A')	1	EA	6	\$301	



Building: Building A

b Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
Floor - Tile/Sheet	1st flr Senior Office (east side of elevator 'A')	120	SF	7	\$0	
Lighting - Pendent/Surface	1st flr Senior Office (east side of elevator 'A')	1	EA	6	\$124	could not locate light switch
Power Distribution	1st flr Senior Office (east side of elevator 'A')	4	EA	6	\$8,500	
Walls - Concrete Block	1st flr Senior Office (east side of elevator 'A')	232	SF	7	\$0	
Walls - Metal Panel	1st flr Senior Office (east side of elevator 'A')	40	SF	7	\$0	
Walls - Plaster/Drywall	1st flr Senior Office (east side of elevator 'A')	138	SF	7	\$0	
Ceiling - Lay-in	226 - Guidance Office	115	SF	6	\$345	
Doors - Transom Window	226 - Guidance Office	9	SF	7	\$0	
Doors - Wood Doors inclu hw	226 - Guidance Office	1	EA	6	\$301	
Floor - Tile	226 - Guidance Office	115	SF	6	\$252	
Lighting - Lay-in	226 - Guidance Office	4	EA	6	\$476	
Power Distribution	226 - Guidance Office	2	EA	7	\$0	
Walls - Metal Panel	226 - Guidance Office	350	SF	6	\$2,613	
Ceiling - Lay-in	227 - Guidance Office	115	SF	6	\$345	
Doors - Transom Window	227 - Guidance Office	9	SF	7	\$0	
Doors - Wood Doors inclu hw	227 - Guidance Office	1	EA	6	\$301	
Floor - Tile	227 - Guidance Office	115	SF	5	\$516	
Lighting - Lay-in	227 - Guidance Office	4	EA	6	\$476	
Power Distribution	227 - Guidance Office	2	EA	6	\$4,250	
Walls - Metal Panel	227 - Guidance Office	350	SF	6	\$2,613	
Ceiling - Lay-in	228 - Guidance Office	115	SF	7	\$0	
Doors - Wood Doors inclu hw	228 - Guidance Office	1	EA	7	\$0	
Floor - Tile	228 - Guidance Office	115	SF	6	\$252	
Lighting - Lay-in	228 - Guidance Office	4	EA	7	\$0	
Power Distribution	228 - Guidance Office	2	EA	7	\$0	
Walls - Metal Panel	228 - Guidance Office	350	SF	6	\$2,613	
Ceiling - Lay-in	229 - Guidance Office	115	SF	6	\$345	
Doors - Transom Window	229 - Guidance Office	9	SF	7	\$0	
Doors - Wood Doors inclu hw	229 - Guidance Office	1	EA	6	\$301	
Floor - Tile	229 - Guidance Office	115	SF	5	\$516	
Lighting - Lay-in	229 - Guidance Office	4	EA	6	\$476	
Power Distribution	229 - Guidance Office	2	EA	7	\$0	
Walls - Metal Panel	229 - Guidance Office	350	SF	6	\$2,613	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Lay-in	230 - IMBYB Office	115	SF	6	\$345	
	Doors - Transom Window	230 - IMBYB Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	230 - IMBYB Office	1	EA	6	\$301	
	Floor - Tile	230 - IMBYB Office	115	SF	6	\$252	
	Lighting - Lay-in	230 - IMBYB Office	4	EA	7	\$0	
	Power Distribution	230 - IMBYB Office	2	EA	7	\$0	
	Walls - Metal Panel	230 - IMBYB Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	231 - Guidance Office	115	SF	6	\$345	
	Doors - Transom Window	231 - Guidance Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	231 - Guidance Office	1	EA	6	\$301	
	Floor - Tile	231 - Guidance Office	115	SF	5	\$516	
	Lighting - Lay-in	231 - Guidance Office	3	EA	6	\$357	
	Power Distribution	231 - Guidance Office	2	EA	7	\$0	
	Walls - Metal Panel	231 - Guidance Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	235B Library work room	150	SF	6	\$450	
	Doors - Side-lite	235B Library work room	11	SF	6	\$184	
	Doors - Transom Window	235B Library work room	13	SF	6	\$220	
	Doors - Wood Doors inclu hw	235B Library work room	1	EA	6	\$301	
	Floor - Carpet	235B Library work room	150	SF	6	\$320	
	Lighting - Lay-in	235B Library work room	3	EA	7	\$0	
	Power Distribution	235B Library work room	6	EA	7	\$0	
	Walls - Metal Panel	235B Library work room	750	SF	6	\$5,598	
	Ceiling - Lay-in	235C Media Viewing	550	SF	7	\$0	
	Doors - Transom Window	235C Media Viewing	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	235C Media Viewing	1	EA	6	\$301	
	Floor - Carpet	235C Media Viewing	550	SF	6	\$1,172	
	Lighting - Lay-in	235C Media Viewing	11	EA	7	\$0	
	Power Distribution	235C Media Viewing	18	EA	7	\$0	
	Walls - Concrete Block	235C Media Viewing	250	SF	7	\$0	
	Walls - Metal Panel	235C Media Viewing	720	SF	7	\$0	
	Ceiling - Lay-in	235D Computer Room in Library	625	SF	6	\$1,877	
	Doors - Wood Doors inclu hw	235D Computer Room in Library	1	EA	6	\$301	
	Floor - Tile	235D Computer Room in Library	625	SF	6	\$1,367	
	Lighting - Lay-in	235D Computer Room in Library	13	EA	6	\$1,547	
	Power Distribution	235D Computer Room in Library	64	EA	7	\$0	
	Walls - Concrete Block	235D Computer Room in Library	300	SF	7	\$0	
	Walls - Metal Panel	235D Computer Room in Library	720	SF	6	\$5,375	



Building: Building A

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
Ceiling - Plaster/Drywall	236A-Library	2,596	SF	6	\$8,984	
Doors - Transom Window	236A-Library	15	SF	6	\$254	
Doors - Wood Doors inclu hw	236A-Library	2	EA	6	\$602	
Floor - Carpet	236A-Library	2,596	SF	5	\$13,327	
Lighting - Pendent/Surface	236A-Library	20	EA	5	\$3,651	
Power Distribution	236A-Library	8	EA	6	\$16,999	
Walls - Concrete Block	236A-Library	930	SF	6	\$2,726	
Walls - Metal Panel	236A-Library	1,300	SF	6	\$9,704	
Work SInk	236A-Library	1	EA	6	\$508	
Ceiling - Lay-in	236B Resource Area	225	SF	6	\$676	
Doors - Transom Window	236B Resource Area	18	SF	6	\$305	
Doors - Wood Doors inclu hw	236B Resource Area	2	EA	6	\$602	
Floor - Carpet	236B Resource Area	225	SF	6	\$479	
Lighting - Lay-in	236B Resource Area	4	EA	7	\$0	
Power Distribution	236B Resource Area	12	EA	7	\$0	
Walls - Metal Panel	236B Resource Area	847	SF	7	\$0	
Ceiling - Lay-in	236C	126	SF	6	\$378	
Doors - Transom Window	236C	6	SF	6	\$102	
Doors - Wood Doors inclu hw	236C	2	EA	6	\$602	
Floor - Carpet	236C	126	SF	6	\$268	
Lighting - Pendent/Surface	236C	3	EA	5	\$548	
Power Distribution	236C	6	EA	6	\$12,749	
Walls - Metal Panel	236C	400	SF	5	\$12,235	
Ceiling - Lay-in	236E	26	SF	5	\$155	
Doors - Side-lite	236E	10	SF	6	\$167	
Doors - Transom Window	236E	6	SF	6	\$102	
Doors - Wood Doors inclu hw	236E	1	EA	6	\$301	
Floor - Carpet	236E	266	SF	6	\$567	
Lighting - Lay-in	236E	6	EA	6	\$714	
Power Distribution	236E	8	EA	6	\$16,999	
Walls - Metal Panel	236E	579	SF	6	\$4,322	
Ceiling - Lay-in	236F	171	SF	6	\$514	
Doors - Side-lite	236F	10	SF	6	\$167	
Doors - Wood Doors inclu hw	236F	1	EA	6	\$301	
Floor - Tile	236F	171	SF	5	\$768	
Lighting - Lay-in	236F	4	EA	6	\$476	
Power Distribution	236F	12	EA	6	\$25,499	



Building: Building A

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
Walls - Metal Panel	236F	515	SF	6	\$3,844	
Ceiling - Lay-in	238 Office	180	SF	6	\$541	
Doors - Side-lite	238 Office	10	SF	6	\$167	
Doors - Transom Window	238 Office	6	SF	6	\$102	
Doors - Wood Doors inclu hw	238 Office	1	EA	6	\$301	
Floor - Tile	238 Office	180	SF	6	\$394	
Lighting - Lay-in	238 Office	4	EA	7	\$0	
Power Distribution	238 Office	8	EA	7	\$0	
Walls - Metal Panel	238 Office	380	SF	6	\$2,837	
Ceiling - Lay-in	239 open office	3,318	SF	6	\$9,964	
Doors - Side-lite	239 open office	15	SF	6	\$251	
Doors - Transom Window	239 open office	18	SF	6	\$305	
Doors - Wood Doors inclu hw	239 open office	2	EA	6	\$602	
Floor - Tile	239 open office	3,318	SF	6	\$7,259	
Lighting - Lay-in	239 open office	67	EA	6	\$7,971	
Power Distribution	239 open office	30	EA	7	\$0	
Storage/ Closet	239 open office	42	SF	7	\$0	
Walls - Metal Panel	239 open office	2,450	SF	6	\$18,288	
Ceiling - Plaster/Drywall	239A	280	SF	6	\$969	
Doors - Transom Window	239A	6	SF	6	\$102	
Doors - Wood Doors inclu hw	239A	1	EA	6	\$301	
Floor - Concrete	239A	280	SF	5	\$480	Cracks throughtout.
Lighting - Pendent/Surface	239A	4	EA	6	\$496	-
Power Distribution	239A	4	EA	6	\$8,500	
Walls - Metal Panel	239A	650	SF	6	\$4,852	
Ceiling - Lay-in	239B SE Corner	90	SF	5	\$535	
Doors - Side-lite	239B SE Corner	11	SF	6	\$184	
Doors - Wood Doors inclu hw	239B SE Corner	1	EA	6	\$301	
Floor - Tile	239B SE Corner	90	SF	5	\$404	
Lighting - Lay-in	239B SE Corner	4	EA	6	\$476	
Power Distribution	239B SE Corner	4	EA	6	\$8,500	
Walls - Concrete Block	239B SE Corner	90	SF	6	\$264	
Walls - Metal Panel	239B SE Corner	205	SF	6	\$1,530	
Ceiling - Lay-in	240 Open Office	646	SF	7	\$0	
Doors - Transom Window	240 Open Office	9	SF	6	\$152	
Doors - Wood Doors inclu hw	240 Open Office	1	EA	7	\$0	
Floor - Tile	240 Open Office	646	SF	6	\$1,413	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Lighting - Lay-in	240 Open Office	14	EA	6	\$1,666	
	Power Distribution	240 Open Office	14	EA	7	\$0	
	Storage/ Closet	240 Open Office	64	SF	6	\$464	
	Walls - Concrete Block	240 Open Office	340	SF	7	\$0	
	Walls - Metal Panel	240 Open Office	630	SF	6	\$4,703	
	Work Slnk	240 Open Office	1	EA	6	\$508	
	Ceiling - Lay-in	240B Office	81	SF	6	\$243	
	Doors - Wood Doors inclu hw	240B Office	1	EA	6	\$301	
	Floor - Tile	240B Office	81	SF	5	\$364	
	Lighting - Lay-in	240B Office	4	EA	6	\$476	
	Power Distribution	240B Office	2	EA	6	\$4,250	
	Walls - Metal Panel	240B Office	180	SF	6	\$1,344	
	Ceiling - Lay-in	241A	231	SF	7	\$0	
	Doors - Transom Window	241A	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	241A	1	EA	6	\$301	
	Floor - Carpet	241A	231	SF	4	\$2,124	stained, worn out
	Lighting - Lay-in	241A	4	EA	6	\$476	
	Power Distribution	241A	4	EA	6	\$8,500	
	Walls - Concrete Block	241A	441	SF	5	\$4,528	
	Ceiling - Lay-in	242C	81	SF	6	\$243	
	Doors - Wood Doors inclu hw	242C	1	EA	6	\$301	
	Floor - Tile	242C	81	SF	6	\$177	
	Lighting - Lay-in	242C	4	EA	6	\$476	
	Power Distribution	242C	4	EA	6	\$8,500	
	Walls - Concrete Block	242C	70	SF	6	\$205	
	Walls - Metal Panel	242C	185	SF	6	\$1,381	
	Ceiling - Lay-in	246/247 Media Center Office	10	SF	4	\$141	water damage.
	Ceiling - Lay-in	246/247 Media Center Office	671	SF	6	\$2,015	
	Doors - Side-lite	246/247 Media Center Office	10	SF	6	\$167	
	Doors - Transom Window	246/247 Media Center Office	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	246/247 Media Center Office	2	EA	4	\$6,826	chipped wood, damage finish.
	Floor - Tile	246/247 Media Center Office	681	SF	6	\$1,490	
	Lighting - Lay-in	246/247 Media Center Office	14	EA	6	\$1,666	
	Power Distribution	246/247 Media Center Office	8	EA	6	\$16,999	
	Walls - Metal Panel	246/247 Media Center Office	716	SF	6	\$5,345	
	Ceiling - Lay-in	256 Office	120	SF	6	\$360	
	Doors - Transom Window	256 Office	9	SF	6	\$152	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Doors - Wood Doors inclu hw	256 Office	1	EA	6	\$301	
	Floor - Tile	256 Office	120	SF	6	\$263	
	Lighting - Lay-in	256 Office	4	EA	5	\$649	
	Power Distribution	256 Office	10	EA	6	\$21,249	
	Walls - Metal Panel	256 Office	281	SF	6	\$2,098	
	Ceiling - Lay-in	261A - Yearbook Office	270	SF	6	\$811	
	Doors - Side-lite	261A - Yearbook Office	60	SF	7	\$0	
	Doors - Transom Window	261A - Yearbook Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	261A - Yearbook Office	1	EA	6	\$301	
	Floor - Tile	261A - Yearbook Office	270	SF	6	\$591	
	Lighting - Lay-in	261A - Yearbook Office	6	EA	6	\$714	
	Power Distribution	261A - Yearbook Office	3	EA	6	\$6,375	
	Walls - Concrete Block	261A - Yearbook Office	42	SF	6	\$123	
	Walls - Metal Panel	261A - Yearbook Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	276 - Coordinator Office	190	SF	6	\$571	
	Doors - Side-lite	276 - Coordinator Office	11	SF	6	\$184	
	Doors - Transom Window	276 - Coordinator Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	276 - Coordinator Office	1	EA	5	\$1,174	
	Floor - Tile	276 - Coordinator Office	190	SF	6	\$416	
	Lighting - Lay-in	276 - Coordinator Office	4	EA	6	\$476	
	Power Distribution	276 - Coordinator Office	6	EA	6	\$12,749	
	Walls - Metal Panel	276 - Coordinator Office	445	SF	6	\$3,322	
	Ceiling - Lay-in	281 - IB Coordinator Office	190	SF	6	\$571	
	Doors - Side-lite	281 - IB Coordinator Office	11	SF	6	\$184	
	Doors - Transom Window	281 - IB Coordinator Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	281 - IB Coordinator Office	1	EA	5	\$1,174	
	Floor - Tile	281 - IB Coordinator Office	190	SF	5	\$853	
	Lighting - Lay-in	281 - IB Coordinator Office	4	EA	6	\$476	
	Power Distribution	281 - IB Coordinator Office	6	EA	6	\$12,749	
	Walls - Metal Panel	281 - IB Coordinator Office	445	SF	6	\$3,322	
	Ceiling - Lay-in	326 - Guidance Office	115	SF	6	\$345	
	Doors - Transom Window	326 - Guidance Office	1	SF	7	\$0	
	Doors - Wood Doors inclu hw	326 - Guidance Office	1	EA	6	\$301	
	Floor - Tile	326 - Guidance Office	115	SF	6	\$252	
	Lighting - Lay-in	326 - Guidance Office	4	EA	7	\$0	
	Power Distribution	326 - Guidance Office	2	EA	7	\$0	
	Walls - Metal Panel	326 - Guidance Office	350	SF	6	\$2,613	



Building: Building A

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
.dmini	strative Suites/Offices						
	Ceiling - Lay-in	327 Office	115	SF	6	\$345	
	Doors - Transom Window	327 Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	327 Office	1	EA	6	\$301	
	Floor - Tile	327 Office	115	SF	6	\$252	
	Lighting - Lay-in	327 Office	9	EA	6	\$1,071	
	Power Distribution	327 Office	2	EA	7	\$0	
	Walls - Metal Panel	327 Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	328 - Guidance Office	115	SF	6	\$345	
	Doors - Transom Window	328 - Guidance Office	1	SF	7	\$0	
	Doors - Wood Doors inclu hw	328 - Guidance Office	1	EA	6	\$301	
	Floor - Tile	328 - Guidance Office	115	SF	6	\$252	
	Lighting - Lay-in	328 - Guidance Office	4	EA	7	\$0	
	Power Distribution	328 - Guidance Office	2	EA	7	\$0	
	Walls - Masonry	328 - Guidance Office	350	SF	6	\$1,101	
	Ceiling - Lay-in	329 Speech/Language/Hearing Office	115	SF	6	\$345	
	Doors - Transom Window	329 Speech/Language/Hearing Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	329 Speech/Language/Hearing Office	1	EA	6	\$301	
	Floor - Tile	329 Speech/Language/Hearing Office	115	SF	6	\$252	
	Lighting - Lay-in	329 Speech/Language/Hearing Office	4	EA	6	\$476	
	Power Distribution	329 Speech/Language/Hearing Office	2	EA	7	\$0	
	Walls - Metal Panel	329 Speech/Language/Hearing Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	330 - Guidance Office	115	SF	6	\$345	
	Doors - Transom Window	330 - Guidance Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	330 - Guidance Office	1	EA	6	\$301	
	Floor - Terrazzo	330 - Guidance Office	115	SF	6	\$252	
	Lighting - Lay-in	330 - Guidance Office	4	EA	7	\$0	
	Power Distribution	330 - Guidance Office	2	EA	7	\$0	
	Walls - Metal Panel	330 - Guidance Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	331 Office	115	SF	6	\$345	
	Doors - Transom Window	331 Office	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	331 Office	1	EA	6	\$301	
	Floor - Tile	331 Office	115	SF	6	\$252	
	Lighting - Lay-in	331 Office	4	EA	6	\$476	
	Power Distribution	331 Office	2	EA	7	\$0	
	Walls - Metal Panel	331 Office	350	SF	6	\$2,613	
	Ceiling - Lay-in	333 Special Ed Department Office	1,040	SF	6	\$3,123	
	Doors - Side-lite	333 Special Ed Department Office	10	SF	6	\$167	



Building: Building A

D D FI	ative Suites/Offices loors - Transom Window loors - Wood Doors inclu hw loor - Tile	333 Special Ed Department Office	6				
D	oors - Wood Doors inclu hw		6				
FI			0	SF	6	\$102	
	loor - Tile	333 Special Ed Department Office	1	EA	6	\$301	
Li		333 Special Ed Department Office	1,040	SF	6	\$2,275	
	ighting - Lay-in	333 Special Ed Department Office	17	EA	6	\$2,023	
P	ower Distribution	333 Special Ed Department Office	26	EA	7	\$0	
W	/alls - Concrete Block	333 Special Ed Department Office	157	SF	5	\$1,612	
W	/alls - Metal Panel	333 Special Ed Department Office	980	SF	6	\$7,315	
С	ceiling - Plaster/Drywall	334A	136	SF	7	\$0	
D	oors - Transom Window	334A	9	SF	6	\$152	
D	oors - Wood Doors inclu hw	334A	1	EA	7	\$0	
FI	loor - Tile	334A	136	SF	6	\$298	
Li	ighting - Pendent/Surface	334A	2	EA	7	\$0	
P	ower Distribution	334A	8	EA	7	\$0	
W	/alls - Concrete Block	334A	235	SF	7	\$0	
W	Valls - Metal Panel	334A	235	SF	6	\$1,754	
С	ceiling - Lay-in	334B Office	136	SF	7	\$0	
D	oors - Transom Window	334B Office	9	SF	6	\$152	
D	oors - Wood Doors inclu hw	334B Office	1	EA	6	\$301	
FI	loor - Tile	334B Office	136	SF	6	\$298	
Li	ighting - Lay-in	334B Office	2	EA	6	\$238	
P	ower Distribution	334B Office	4	EA	7	\$0	
W	/alls - Concrete Block	334B Office	129	SF	7	\$0	
W	/alls - Metal Panel	334B Office	350	SF	6	\$2,613	
С	ceiling - Lay-in	334B	136	SF	7	\$0	
D	oors - Wood Doors inclu hw	334B	1	EA	7	\$0	
D	oors - Wood Doors inclu hw	334B	9	EA	7	\$0	
FI	loor - Tile	334B	136	SF	6	\$298	
Li	ighting - Lay-in	334B	2	EA	7	\$0	
P	ower Distribution	334B	6	EA	7	\$0	
W	/alls - Concrete Block	334B	135	SF	7	\$0	
W	/alls - Metal Panel	334B	335	SF	7	\$0	
С	ceiling - Lay-in	341A	198	SF	6	\$595	
D	oors - Transom Window	341A	9	SF	7	\$0	
D	oors - Wood Doors inclu hw	341A	1	EA	6	\$301	
FI	loor - Tile	341A	198	SF	5	\$889	
Li	ighting - Lay-in	341A	5	EA	6	\$595	
P	ower Distribution	341A	8	EA	6	\$16,999	



Building: Building A

o Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
Walls - Metal Panel	341A	438	SF	6	\$3,269	
Ceiling - Lay-in	341B Office	118	SF	6	\$354	
Ceiling - Plaster/Drywall	341B Office	100	SF	5	\$917	
Doors - Side-lite	341B Office	40	SF	6	\$669	
Doors - Transom Window	341B Office	9	SF	6	\$152	
Doors - Wood Doors inclu hw	341B Office	1	EA	5	\$1,174	
Floor - Tile	341B Office	218	SF	6	\$477	
Lighting - Lay-in	341B Office	4	EA	6	\$476	
Lighting - Pendent/Surface	341B Office	1	EA	6	\$124	
Power Distribution	341B Office	4	EA	7	\$0	
Walls - Metal Panel	341B Office	540	SF	6	\$4,031	
Walls - Plaster/Drywall	341B Office	50	SF	6	\$138	
Ceiling - Lay-in	342 Open Office	1,383	SF	6	\$4,153	
Doors - Side-lite	342 Open Office	30	SF	6	\$502	
Doors - Transom Window	342 Open Office	18	SF	6	\$305	
Doors - Wood Doors inclu hw	342 Open Office	2	EA	6	\$602	
Floor - Tile	342 Open Office	1,383	SF	6	\$3,026	
Lighting - Lay-in	342 Open Office	24	EA	6	\$2,855	
Power Distribution	342 Open Office	46	EA	7	\$0	
Walls - Concrete Block	342 Open Office	450	SF	7	\$0	
Walls - Metal Panel	342 Open Office	1,400	SF	6	\$10,450	
Work Sink	342 Open Office	1	EA	5	\$1,508	
Ceiling - Lay-in	342B Office	84	SF	5	\$500	
Doors - Side-lite	342B Office	11	SF	6	\$184	
Doors - Transom Window	342B Office	9	SF	6	\$152	
Doors - Wood Doors inclu hw	342B Office	1	EA	6	\$301	
Floor - Tile	342B Office	84	SF	6	\$184	
Lighting - Lay-in	342B Office	2	EA	5	\$324	
Power Distribution	342B Office	2	EA	6	\$4,250	
Walls - Metal Panel	342B Office	240	SF	5	\$7,341	
Ceiling - Lay-in	344 / 345 Open Office	2,123	SF	6	\$6,375	
Doors - Transom Window	344 / 345 Open Office	18	SF	7	\$0	
Doors - Wood Doors inclu hw	344 / 345 Open Office	2	EA	6	\$602	
Floor - Tile	344 / 345 Open Office	2,123	SF	6	\$4,645	
Lighting - Lay-in	344 / 345 Open Office	41	EA	6	\$4,878	
Power Distribution	344 / 345 Open Office	24	EA	7	\$0	
Walls - Concrete Block	344 / 345 Open Office	720	SF	7	\$0	



Building: Building A

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	trative Suites/Offices						
	Walls - Metal Panel	344 / 345 Open Office	1,350	SF	6	\$10,077	
	Work Sink	344 / 345 Open Office	1	EA	6	\$508	
	Ceiling - Lay-in	344A Office	81	SF	6	\$243	
	Doors - Side-lite	344A Office	51	SF	6	\$853	
	Doors - Transom Window	344A Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	344A Office	5	EA	6	\$1,505	
	Floor - Tile	344A Office	81	SF	6	\$177	
	Lighting - Lay-in	344A Office	4	EA	5	\$649	
	Walls - Metal Panel	344A Office	180	SF	6	\$1,344	
	Ceiling - Lay-in	345A	95	SF	6	\$285	
	Doors - Wood Doors inclu hw	345A	1	EA	6	\$301	
	Floor - Tile	345A	95	SF	6	\$208	
	Lighting - Lay-in	345A	4	EA	5	\$649	
	Power Distribution	345A	2	EA	6	\$4,250	
	Walls - Metal Panel	345A	200	SF	6	\$1,493	
	Ceiling - Lay-in	353B- Science Lab Office	108	SF	6	\$324	
	Doors - Side-lite	353B- Science Lab Office	10	SF	6	\$167	
	Doors - Transom Window	353B- Science Lab Office	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	353B- Science Lab Office	1	EA	6	\$301	
	Floor - Tile	353B- Science Lab Office	108	SF	6	\$236	
	Lighting - Lay-in	353B- Science Lab Office	2	EA	6	\$238	
	Power Distribution	353B- Science Lab Office	4	EA	7	\$0	
	Walls - Metal Panel	353B- Science Lab Office	397	SF	6	\$2,963	
	Ceiling - Lay-in	359 Office	700	SF	6	\$2,102	
	Doors - Transom Window	359 Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	359 Office	2	EA	5	\$2,348	
	Floor - Tile	359 Office	700	SF	5	\$3,143	
	Lighting - Lay-in	359 Office	28	EA	5	\$4,541	
	Power Distribution	359 Office	8	EA	6	\$16,999	
	Walls - Concrete Block	359 Office	376	SF	4	\$13,480	cracks throughout.
	Walls - Metal Panel	359 Office	580	SF	6	\$4,329	
	Ceiling - Lay-in	382	162	SF	7	\$0	
	Doors - Side-lite	382	22	SF	7	\$0	
	Doors - Transom Window	382	26	SF	7	\$0	
	Doors - Wood Doors inclu hw	382	2	EA	6	\$602	
	Floor - Tile	382	162	SF	6	\$354	
	Lighting - Lay-in	382	4	EA	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Power Distribution	382	8	EA	7	\$0	
	Walls - Metal Panel	382	230	SF	7	\$0	
	Walls - Plaster/Drywall	382	200	SF	7	\$0	
	Ceiling - Exposed	B14A Engineer's Shop	352	SF	6	\$523	
	Doors - Wood Doors inclu hw	B14A Engineer's Shop	4	EA	6	\$1,204	
	Floor - Concrete	B14A Engineer's Shop	352	SF	6	\$186	
	Lighting - Pendent/Surface	B14A Engineer's Shop	7	EA	6	\$867	
	Power Distribution	B14A Engineer's Shop	10	EA	7	\$0	
	Walls - Concrete Block	B14A Engineer's Shop	189	SF	7	\$0	conc foundation wall
	Walls - Concrete Block	B14A Engineer's Shop	566	SF	6	\$1,659	
	Walls - Plaster/Drywall	B14A Engineer's Shop	61	SF	7	\$0	
	Ceiling - Plaster/Drywall	B15 Engineer's Office	144	SF	6	\$498	
	Doors - Wood Doors inclu hw	B15 Engineer's Office	2	EA	6	\$602	
	Floor - Tile	B15 Engineer's Office	144	SF	6	\$315	
	Lighting - Lay-in	B15 Engineer's Office	4	EA	7	\$0	
	Power Distribution	B15 Engineer's Office	44	EA	7	\$0	
	Walls - Concrete Block	B15 Engineer's Office	458	SF	7	\$0	
	Ceiling - Plaster/Drywall	B16 Engineer's Office	134	SF	7	\$0	
	Doors - Wood Doors inclu hw	B16 Engineer's Office	1	EA	7	\$0	
	Floor - Tile	B16 Engineer's Office	134	SF	5	\$602	
	Lighting - Lay-in	B16 Engineer's Office	4	EA	7	\$0	
	Power Distribution	B16 Engineer's Office	8	EA	7	\$0	
	Walls - Concrete Block	B16 Engineer's Office	359	SF	7	\$0	
	Ceiling - Lay-in	B3 Kitchen Office	135	SF	5	\$803	
	Doors - Transom Window	B3 Kitchen Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	B3 Kitchen Office	1	EA	7	\$0	
	Floor - Terrazzo	B3 Kitchen Office	135	SF	6	\$295	
	Lighting - Pendent/Surface	B3 Kitchen Office	2	EA	6	\$248	
	Power Distribution	B3 Kitchen Office	4	EA	6	\$8,500	
	Walls - Structural Glazed Tile	B3 Kitchen Office	300	SF	7	\$0	
	Ceiling - Plaster/Drywall	B9B Engineer's Office	158	SF	6	\$547	
	Doors - Wood Doors inclu hw	B9B Engineer's Office	2	EA	7	\$0	
	Floor - Carpet	B9B Engineer's Office	158	SF	5	\$811	
	Lighting - Pendent/Surface	B9B Engineer's Office	2	EA	6	\$248	
	Power Distribution	B9B Engineer's Office	8	EA	6	\$16,999	
	Storage/ Closet	B9B Engineer's Office	10	SF	6	\$73	
	Walls - Plaster/Drywall	B9B Engineer's Office	423	SF	6	\$1,167	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Plaster/Drywall	B9C Engineer's Office	177	SF	7	\$0	
	Doors - Wood Doors inclu hw	B9C Engineer's Office	1	EA	7	\$0	
	Floor - Carpet	B9C Engineer's Office	177	SF	6	\$377	
	Lighting - Pendent/Surface	B9C Engineer's Office	2	EA	7	\$0	
	Power Distribution	B9C Engineer's Office	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	B9C Engineer's Office	465	SF	7	\$0	
Kitchen	1						
	Ceiling - Lay-in	115 Canteen	185	SF	7	\$0	
	Doors - Wood Doors inclu hw	115 Canteen	2	EA	7	\$0	
	Floor - Terrazzo	115 Canteen	185	SF	7	\$0	
	Lighting - Pendent/Surface	115 Canteen	3	EA	7	\$0	
	Walls - Structural Glazed Tile	115 Canteen	275	SF	7	\$0	
	Ceiling - Lay-in	116 Serving Area	1,222	SF	6	\$3,670	
	Doors - Transom Window	116 Serving Area	90	SF	7	\$0	
	Doors - Wood Doors inclu hw	116 Serving Area	4	EA	5	\$4,696	
	Doors - Wood Doors inclu hw	116 Serving Area	4	EA	6	\$1,204	
	Floor - Terrazzo	116 Serving Area	1,222	SF	7	\$0	
	Lighting - Pendent/Surface	116 Serving Area	22	EA	6	\$2,726	
	Serving Line	116 Serving Area	68	LF	7	\$0	
	Walls - Masonry	116 Serving Area	410	SF	7	\$0	
	Walls - Metal Panel	116 Serving Area	637	SF	6	\$4,755	
	Walls - Structural Glazed Tile	116 Serving Area	1,040	SF	7	\$0	
	Ceiling - Lay-in	1st flr Faculty Serving Area (158 on plan)	360	SF	6	\$1,081	All materials/quantities for this room are estimates since Engineers masterkey did not work on the locks to this space.
	Doors - Wood Doors inclu hw	1st flr Faculty Serving Area (158 on plan)	3	EA	6	\$903	
	Floor - Tile/Sheet	1st flr Faculty Serving Area (158 on plan)	360	SF	7	\$0	
	Lighting - Pendent/Surface	1st flr Faculty Serving Area (158 on plan)	9	EA	6	\$1,115	
	Serving Line	1st flr Faculty Serving Area (158 on plan)	20	LF	7	\$0	
	Walls - Masonry	1st flr Faculty Serving Area (158 on plan)	100	SF	7	\$0	
	Walls - Metal Panel	1st flr Faculty Serving Area (158 on plan)	260	SF	6	\$1,941	
	Ceiling - Lay-in	216/215 Kitchen	1,354	SF	7	\$0	
	Doors - Wood Doors inclu hw	216/215 Kitchen	10	EA	5	\$11,741	
	Floor - Terrazzo	216/215 Kitchen	920	SF	6	\$2,013	
	Floor - Tile	216/215 Kitchen	434	SF	6	\$950	
	Lighting - Lay-in	216/215 Kitchen	28	EA	6	\$3,331	
	Serving Line	216/215 Kitchen	84	LF	6	\$4,999	



Building: Building A

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Kitcher		Louion	suantity	Unit	Nank	COSL	
Ritchel	Valls - Metal Panel	216/215 Kitchen	500	SF	6	\$3,732	
	Walls - Plaster/Drywall	216/215 Kitchen	1,420	SF	7	\$3,732 \$0	
	Ceiling - Lay-in	316/315 Serving Lines	1,420	SF	6	\$4,066	
	Doors - Wood Doors inclu hw	316/315 Serving Lines	1,004	EA	5	\$11,741	
	Floor - Terrazzo	316/315 Serving Lines	920	SF	7	\$0	
	Floor - Tile	316/315 Serving Lines	434	SF	6	\$950	
	Lighting - Lay-in	316/315 Serving Lines	28	EA	6	\$3,331	
	Serving Line	316/315 Serving Lines	84	LF	7	¢0,001 \$0	
	Walls - Masonry	316/315 Serving Lines	340	SF	7	\$0	
	Walls - Metal Panel	316/315 Serving Lines	500	SF	6	\$3,732	
	Walls - Structural Glazed Tile	316/315 Serving Lines	1,420	SF	7	\$0 \$0	
	Ceiling - Lay-in	Basement	3,047	SF	5	\$18,126	replace dirty/damaged ceiling tiles and replace (or paint) existing ceiling grid
	Doors - Wood Doors inclu hw	Basement	3	EA	6	\$903	painty existing centry grid
	Floor - Terrazzo	Basement	3.047	SF	5	\$114,682	floor surface is damaged and cracked
	Lighting - Pendent/Surface	Basement	59	EA	6	\$7,310	
	Storage/ Closet	Basement	825	SF	6	\$5,981	
	Walls - Structural Glazed Tile	Basement	1,688	SF	7	\$0	
Library			·				
	Casework	2nd Floor	138	LF	6	\$3,485	
	Ceiling - Lay-in	2nd Floor	12,300	SF	5	\$73,170	
	Doors - Side-lite	2nd Floor	20	SF	6	\$334	
	Doors - Transom Window	2nd Floor	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	2nd Floor	6	EA	6	\$1,806	
	Floor - Carpet	2nd Floor	12,300	SF	6	\$26,208	
	Lighting - Lay-in	2nd Floor	162	EA	5	\$26,275	
	Storage/ Closet	2nd Floor	329	SF	6	\$2,385	Room 235A
	Walls - Concrete Block	2nd Floor	414	SF	6	\$1,214	
	Walls - Metal Panel	2nd Floor	3,750	SF	6	\$27,992	
Lunch	& Multipurpose Room						
	Ceiling - Lay-in	101/102 Faculty Lunchroom (157 & 157A on plan)	1,443	SF	7	\$0	
	Doors - Wood Doors inclu hw	101/102 Faculty Lunchroom (157 & 157A on plan)	2	EA	6	\$602	
	Floor - Tile/Sheet	101/102 Faculty Lunchroom (157 & 157A on plan)	1,443	SF	7	\$0	
	Lighting - Pendent/Surface	101/102 Faculty Lunchroom (157 & 157A on plan)	24	EA	6	\$2,973	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch a	& Multipurpose Room						
	Walls - Concrete Block	101/102 Faculty Lunchroom (157 & 157A on plan)	820	SF	7	\$0	
	Walls - Metal Panel	101/102 Faculty Lunchroom (157 & 157A on plan)	1,030	SF	6	\$7,689	
	Ceiling - Lay-in	118 West Lunchroom	1,675	SF	5	\$9,964	
	Floor - Tile/Sheet	118 West Lunchroom	1,675	SF	7	\$0	
	Lighting - Pendent/Surface	118 West Lunchroom	28	EA	6	\$3,469	
	Walls - Masonry	118 West Lunchroom	445	SF	7	\$0	
	Walls - Metal Panel	118 West Lunchroom	783	SF	5	\$23,950	
	Ceiling - Lay-in	119 East Lunchroom	1,770	SF	6	\$5,315	
	Floor - Tile/Sheet	119 East Lunchroom	1,770	SF	7	\$0	
	Lighting - Pendent/Surface	119 East Lunchroom	29	EA	6	\$3,593	
	Walls - Masonry	119 East Lunchroom	485	SF	7	\$0	
	Walls - Metal Panel	119 East Lunchroom	953	SF	5	\$29,150	
	Ceiling - Lay-in	218 2nd Floor West	2,128	SF	6	\$6,390	
	Floor - Tile	218 2nd Floor West	2,128	SF	4	\$18,289	Tile is damaged, worn & mismatched tile
	Lighting - Lay-in	218 2nd Floor West	33	EA	6	\$3,926	
	Serving Line	218 2nd Floor West	8	LF	7	\$0	
	Walls - Masonry	218 2nd Floor West	421	SF	7	\$0	
	Walls - Metal Panel	218 2nd Floor West	1,250	SF	6	\$9,331	
	Ceiling - Lay-in	219 2nd Floor East	2,128	SF	6	\$6,390	
	Floor - Tile	219 2nd Floor East	2,128	SF	4	\$18,289	worn, damaged and mismatched tile.
	Lighting - Lay-in	219 2nd Floor East	33	EA	6	\$3,926	
	Storage/ Closet	219 2nd Floor East	8	SF	7	\$0	
	Walls - Masonry	219 2nd Floor East	421	SF	7	\$0	
	Walls - Metal Panel	219 2nd Floor East	1,250	SF	6	\$9,331	
	Ceiling - Lay-in	241 - Lecture Center	1,120	SF	6	\$3,363	
	Doors - Wood Doors inclu hw	241 - Lecture Center	1	EA	6	\$301	
	Floor - Carpet	241 - Lecture Center	1,120	SF	6	\$2,386	
	Lighting - Lay-in	241 - Lecture Center	24	EA	6	\$2,855	
	Stage	241 - Lecture Center	196	SF	6	\$1,132	
	Walls - Metal Panel	241 - Lecture Center	1,026	SF	6	\$7,659	
	Ceiling - Lay-in	318 3rd Floor West	2,128	SF	6	\$6,390	
	Floor - Tile	318 3rd Floor West	2,128	SF	4	\$18,289	damaged, worn, mismatched tiles
	Lighting - Lay-in	318 3rd Floor West	33	EA	6	\$3,926	
	Serving Line	318 3rd Floor West	8	LF	7	\$0	
	Walls - Masonry	318 3rd Floor West	421	SF	7	\$0	
	Walls - Metal Panel	318 3rd Floor West	1,250	SF	6	\$9,331	
	Walls - Metal Panel	318 3rd Floor West	1,250	SF	6	\$9,331	



Building: Building A

•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_unch 8	& Multipurpose Room						
	Ceiling - Lay-in	319 3rd Floor East	2,128	SF	6	\$6,390	
	Floor - Tile	319 3rd Floor East	2,128	SF	4	\$18,289	damaged, worn and mismatched tile
	Lighting - Lay-in	319 3rd Floor East	33	EA	6	\$3,926	
	Serving Line	319 3rd Floor East	8	LF	7	\$0	
	Walls - Masonry	319 3rd Floor East	421	SF	7	\$0	
	Walls - Metal Panel	319 3rd Floor East	1,250	SF	6	\$9,331	
MDF_ID	F						
	Doors - Wood Doors inclu hw	237	1	EA	6	\$301	
	Finishes	237	194	SF	6	\$1,384	
	Ventilation and Cooling	237	1	EA	7	\$0	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	96	SF	6	\$688	108 in South corridor, 111 & 114 in North corridor
	Mechanical/ Service Rooms	1st Floor	118	SF	7	\$0	110 Electric & 113 Electric in North corridor
	Mechanical/ Service Rooms	1st Floor	75	SF	6	\$537	107 Electric in rm 166
	Mechanical/ Service Rooms	1st Floor	37	SF	7	\$0	Electric in rm 164
	Storage Room	1st Floor	143	SF	7	\$0	142A
	Storage Room	1st Floor	966	SF	7	\$0	142 Book Storage
	Storage Room	1st Floor	86	SF	7	\$0	122A & 123A in North corridor
	Janitor's Closet	2nd Floor Support Rooms	25	SF	6	\$179	room 214
	Janitor's Closet	2nd Floor Support Rooms	25	SF	6	\$179	room 208
	Janitor's Closet	2nd Floor Support Rooms	25	SF	6	\$179	room 211
	Janitor's Closet	2nd Floor Support Rooms	25	SF	6	\$179	room 204
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	6	\$143	room 203 elect. room
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	6	\$143	room 213 elect. room
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	6	\$143	room 210 elect. room
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	6	\$143	room 207 elect. room
	Storage Room	2nd Floor Support Rooms	200	SF	6	\$1,433	room 242B Storage
	Storage Room	2nd Floor Support Rooms	49	SF	6	\$351	room 235F
	Janitor's Closet	3rd Floor	25	SF	7	\$0	rm. 314
	Janitor's Closet	3rd Floor	25	SF	5	\$403	room 311
	Janitor's Closet	3rd Floor	25	SF	6	\$179	room 304
	Janitor's Closet	3rd Floor	25	SF	6	\$179	room 308
	Mechanical/ Service Rooms	3rd Floor	65	SF	7	\$0	Laundry Room @ Rm 381
	Mechanical/ Service Rooms	3rd Floor	20	SF	7	\$0	303 elect. closet
	Mechanical/ Service Rooms	3rd Floor	20	SF	7	\$0	307 elect. closet
	Mechanical/ Service Rooms	3rd Floor	20	SF	7	\$0	313 elect. closet



Building: Building A

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
chan	nical/ Service Rooms						
	Mechanical/ Service Rooms	3rd Floor	20	SF	7	\$0	310 elect. closet
	Storage Room	3rd Floor	200	SF	6	\$1,433	Rm 372 Math Department Storage.
	Storage Room	3rd Floor	200	SF	6	\$1,433	
	Storage Room	3rd Floor	126	SF	5	\$2,032	Storage Rm. 348
	Storage Room	3rd Floor	196	SF	6	\$1,404	348A Storage
	Storage Room	3rd Floor	204	SF	6	\$1,462	Storage 350A
	Storage Room	3rd Floor	170	SF	6	\$1,218	Library Storage 342A
	Storage Room	3rd Floor	126	SF	6	\$903	Storage 352A
	Storage Room	3rd Floor	89	SF	6	\$638	386A
	Loading Docks	Basement Loading Dock	504	SF	6	\$3,611	
	Janitor's Closet	Basement Service Rooms	21	SF	6	\$150	B10A
	Mechanical/ Service Rooms	Basement Service Rooms	40	SF	6	\$287	B8 elevator equipment room
	Mechanical/ Service Rooms	Basement Service Rooms	308	SF	6	\$2,207	B14 Electrical Rm.
	Mechanical/ Service Rooms	Basement Service Rooms	2,408	SF	6	\$17,252	B12 Mech. Room
	Mechanical/ Service Rooms	Basement Service Rooms	537	SF	6	\$3,847	B13A Elect. Room
	Mechanical/ Service Rooms	Basement Service Rooms	164	SF	7	\$0	B14B Electrical Room
	Storage Room	Basement Service Rooms	369	SF	6	\$2,644	B19 Building Storage Room
	Storage Room	Basement Service Rooms	368	SF	6	\$2,636	B20 Receiving Storage Room
	Storage Room	Basement Service Rooms	152	SF	6	\$1,089	B12A Mech Storage
	Storage Room	Basement Service Rooms	278	SF	6	\$1,992	B9 Storage
	Storage Room	Basement Service Rooms	609	SF	5	\$9,823	В9А
p Ro	bom						
	Casework	340A	30	LF	6	\$758	
	Ceiling - Lay-in	340A	175	SF	6	\$526	
	Doors - Wood Doors inclu hw	340A	1	EA	6	\$301	
	Floor - Tile	340A	175	SF	6	\$383	
	Lighting - Lay-in	340A	3	EA	7	\$0	
	Walls - Metal Panel	340A	380	SF	6	\$2,837	
	Walls - Plaster/Drywall	340A	219	SF	7	\$0	
	Work Sink	340A	1	EA	6	\$379	
	Ceiling - Lay-in	346A/B	406	SF	6	\$1,219	
	Doors - Side-lite	346A/B	22	SF	6	\$368	
	Doors - Transom Window	346A/B	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	346A/B	2	EA	6	\$602	
	Floor - Tile	346A/B	406	SF	6	\$888	
	Lighting - Lay-in	346A/B	8	EA	7	\$0	
	Walls - Concrete Block	346A/B	78	SF	4	\$2,796	cracks throughtout.



Building: Building A

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ep Ro	oom						
	Walls - Metal Panel	346A/B	290	SF	6	\$2,165	
	Ceiling - Lay-in	349A/349B	288	SF	6	\$865	
	Doors - Wood Doors inclu hw	349A/349B	1	EA	6	\$301	
	Floor - Tile	349A/349B	288	SF	5	\$1,293	
	Lighting - Lay-in	349A/349B	11	EA	6	\$1,309	
	Walls - Metal Panel	349A/349B	675	SF	6	\$5,039	
	Work Sink	349A/349B	2	EA	6	\$758	
	Casework	350B	12	LF	6	\$303	
	Ceiling - Lay-in	350B	204	SF	6	\$613	
	Doors - Side-lite	350B	11	SF	6	\$184	
	Doors - Wood Doors inclu hw	350B	1	EA	6	\$301	
	Floor - Tile	350B	204	SF	6	\$446	
	Lighting - Lay-in	350B	7	EA	7	\$0	
	Walls - Metal Panel	350B	477	SF	7	\$0	
	Work Sink	350B	1	EA	6	\$379	
	Ceiling - Lay-in	353A	212	SF	6	\$637	
	Doors - Side-lite	353A	10	SF	6	\$167	
	Doors - Transom Window	353A	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	353A	1	EA	6	\$301	
	Floor - Tile	353A	212	SF	6	\$464	
	Lighting - Lay-in	353A	7	EA	6	\$833	
	Walls - Metal Panel	353A	530	SF	6	\$3,956	
	Work Sink	353A	1	EA	6	\$379	
	Ceiling - Lay-in	354B	299	SF	6	\$898	
	Doors - Wood Doors inclu hw	354B	1	EA	6	\$301	
	Floor - Tile/Sheet	354B	299	SF	5	\$1,343	
	Lighting - Pendent/Surface	354B	11	EA	6	\$1,363	
	Walls - Metal Panel	354B	675	SF	5	\$20,647	
	Work Sink	354B	2	EA	6	\$758	
	Ceiling - Lay-in	363A	135	SF	6	\$405	
	Doors - Transom Window	363A	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	363A	1	EA	6	\$301	
	Floor - Tile	363A	135	SF	6	\$295	
	Lighting - Lay-in	363A	4	EA	6	\$476	
	Walls - Concrete Block	363A	42	SF	6	\$123	
	Walls - Metal Panel	363A	369	SF	6	\$2,754	
	Work Sink	363A	1	EA	6	\$379	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om de la companya de						
	Accessories	109 NW Girls	377	SF	5	\$7,461	Soap dispenser, toilet paper dispenser,
	Ceiling - Plaster/Drywall	109 NW Girls	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	109 NW Girls	2	EA	7	\$0	
	Floor Drain	109 NW Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	109 NW Girls	377	SF	6	\$798	
	Hand Dryer	109 NW Girls	1	EA	7	\$0	
	Lavatory	109 NW Girls	3	EA	7	\$0	
	Lighting - Lay-in	109 NW Girls	11	EA	7	\$0	
	Partitions	109 NW Girls	7	EA	5	\$5,256	Vandalized throughout.
	Walls - Structural Glazed Tile	109 NW Girls	694	SF	6	\$2,183	
	Water Closet	109 NW Girls	7	EA	6	\$2,352	
	Accessories	112 NE Boys	377	SF	5	\$7,461	Missing and vandalized accessories
	Ceiling - Plaster/Drywall	112 NE Boys	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	112 NE Boys	2	EA	6	\$602	
	Floor Drain	112 NE Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	112 NE Boys	377	SF	7	\$0	
	Hand Dryer	112 NE Boys	1	EA	5	\$590	
	Lavatory	112 NE Boys	4	EA	6	\$1,278	
	Lighting - Lay-in	112 NE Boys	11	EA	7	\$0	
	Partitions	112 NE Boys	3	EA	4	\$5,959	Urinal partitions missing; Toilet partitions are vandalized beyond repair.
	Urinals	112 NE Boys	5	EA	7	\$0	
	Walls - Structural Glazed Tile	112 NE Boys	694	SF	6	\$2,183	
	Water Closet	112 NE Boys	3	EA	6	\$1,008	
	Accessories	159D	80	SF	7	\$0	
	Ceiling - Plaster/Drywall	159D	80	SF	7	\$0	
	Doors - Wood Doors inclu hw	159D	1	EA	7	\$0	
	Floor Drain	159D	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	159D	80	SF	7	\$0	
	Hand Dryer	159D	1	EA	5	\$590	Won't turn on.
	Lavatory	159D	80	EA	7	\$0	
	Lighting - Lay-in	159D	1	EA	7	\$0	
	Walls - Plaster/Drywall	159D	340	SF	6	\$938	
	Water Closet	159D	1	EA	7	\$0	
	Accessories	170E Small Unisex in Nurse's Office	17	SF	7	\$0	
	Ceiling - Plaster/Drywall	170E Small Unisex in Nurse's Office	17	SF	7	\$0	
	Doors - Wood Doors inclu hw	170E Small Unisex in Nurse's Office	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	170E Small Unisex in Nurse's Office	17	SF	6	\$36	tile baseboard missing a section



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroor	m						
	Lavatory	170E Small Unisex in Nurse's Office	1	EA	7	\$0	
	Lighting - Wall Mounted	170E Small Unisex in Nurse's Office	1	EA	6	\$124	missing lens
	Walls - Metal Panel	170E Small Unisex in Nurse's Office	147	SF	6	\$1,097	
	Water Closet	170E Small Unisex in Nurse's Office	1	EA	7	\$0	
	Accessories	170F Unisex in Nurse's Office	43	SF	7	\$0	
	Ceiling - Plaster/Drywall	170F Unisex in Nurse's Office	43	SF	7	\$0	
	Doors - Steel Doors incl hw	170F Unisex in Nurse's Office	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	170F Unisex in Nurse's Office	43	SF	7	\$0	
	Lavatory	170F Unisex in Nurse's Office	1	EA	7	\$0	
	Lighting - Wall Mounted	170F Unisex in Nurse's Office	1	EA	6	\$124	light missing lens
	Walls - Plaster/Drywall	170F Unisex in Nurse's Office	250	SF	6	\$690	
	Water Closet	170F Unisex in Nurse's Office	1	EA	7	\$0	
	Accessories	172A Unisex in Main Office	23	SF	7	\$0	
	Ceiling - Plaster/Drywall	172A Unisex in Main Office	23	SF	7	\$0	
	Doors - Wood Doors inclu hw	172A Unisex in Main Office	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	172A Unisex in Main Office	23	SF	7	\$0	
	Lavatory	172A Unisex in Main Office	1	EA	7	\$0	
	Lighting - Wall Mounted	172A Unisex in Main Office	1	EA	7	\$0	Incandescent
	Walls - Concrete Block	172A Unisex in Main Office	20	SF	7	\$0	
	Walls - Metal Panel	172A Unisex in Main Office	150	SF	7	\$0	plastic panel covered
	Water Closet	172A Unisex in Main Office	1	EA	7	\$0	
	Accessories	182A Unisex in Principal's Office	24	SF	7	\$0	
	Ceiling - Plaster/Drywall	182A Unisex in Principal's Office	24	SF	7	\$0	
	Doors - Wood Doors inclu hw	182A Unisex in Principal's Office	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	182A Unisex in Principal's Office	24	SF	7	\$0	
	Lavatory	182A Unisex in Principal's Office	1	EA	6	\$320	
	Lighting - Wall Mounted	182A Unisex in Principal's Office	1	EA	7	\$0	
	Walls - Concrete Block	182A Unisex in Principal's Office	48	SF	7	\$0	
	Walls - Metal Panel	182A Unisex in Principal's Office	128	SF	6	\$955	
	Water Closet	182A Unisex in Principal's Office	1	EA	7	\$0	
	Accessories	1st Floor SE Girls	377	SF	6	\$3,477	Soap dispenser, mirror, toilet paper dispenser.
	Ceiling - Plaster/Drywall	1st Floor SE Girls	377	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor SE Girls	2	EA	7	\$0	
	Floor Drain	1st Floor SE Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor SE Girls	2	SF	7	\$0	
	Hand Dryer	1st Floor SE Girls	1	EA	5	\$590	
	Lavatory	1st Floor SE Girls	4	EA	5	\$6,359	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Lighting - Lay-in	1st Floor SE Girls	9	EA	7	\$0	
	Partitions	1st Floor SE Girls	6	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor SE Girls	694	SF	7	\$0	
	Water Closet	1st Floor SE Girls	6	EA	6	\$2,016	
	Accessories	1st Flr NW Mens (in 102 Faculty Lunchroom)	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Flr NW Mens (in 102 Faculty Lunchroom)	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	1st Flr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Floor Drain	1st Flr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Flr NW Mens (in 102 Faculty Lunchroom)	90	SF	7	\$0	
	Hand Dryer	1st FIr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Lavatory	1st FIr NW Mens (in 102 Faculty Lunchroom)	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st FIr NW Mens (in 102 Faculty Lunchroom)	2	EA	7	\$0	
	Lighting - Wall Mounted	1st Flr NW Mens (in 102 Faculty Lunchroom)	1	EA	6	\$124	
	Partitions	1st FIr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Urinals	1st FIr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Flr NW Mens (in 102 Faculty Lunchroom)	512	SF	7	\$0	
	Water Closet	1st Flr NW Mens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Accessories	1st Flr NW Womens (in 102 Faculty Lunchroom)	93	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Flr NW Womens (in 102 Faculty Lunchroom)	93	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Flr NW Womens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Floor Drain	1st Flr NW Womens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st FIr NW Womens (in 102 Faculty Lunchroom)	93	SF	7	\$0	
	Hand Dryer	1st Flr NW Womens (in 102 Faculty Lunchroom)	1	EA	7	\$0	



Building: Building A

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroo	m						
	Lavatory	1st Flr NW Womens (in 102 Faculty Lunchroom)	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Flr NW Womens (in 102 Faculty Lunchroom)	1	EA	7	\$0	
	Lighting - Wall Mounted	1st Flr NW Womens (in 102 Faculty Lunchroom)	1	EA	6	\$124	
	Partitions	1st Flr NW Womens (in 102 Faculty Lunchroom)	2	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Flr NW Womens (in 102 Faculty Lunchroom)	508	SF	7	\$0	
	Water Closet	1st Flr NW Womens (in 102 Faculty Lunchroom)	2	EA	7	\$0	
	Accessories	1st Flr SW Boys	377	SF	5	\$7,461	vandalized & missing
	Ceiling - Plaster/Drywall	1st Flr SW Boys	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	1st Flr SW Boys	2	EA	5	\$2,348	
	Floor Drain	1st Flr SW Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Flr SW Boys	377	SF	6	\$798	
	Hand Dryer	1st Flr SW Boys	1	EA	6	\$230	
	Lavatory	1st Flr SW Boys	4	EA	5	\$6,359	
	Lighting - Lay-in	1st Flr SW Boys	11	EA	6	\$1,309	
	Partitions	1st Flr SW Boys	8	EA	5	\$6,007	
	Urinals	1st Flr SW Boys	5	EA	6	\$1,680	
	Walls - Structural Glazed Tile	1st Flr SW Boys	694	SF	7	\$0	
	Water Closet	1st Flr SW Boys	4	EA	6	\$1,344	
	Accessories	202 Unisex	82	SF	6	\$756	Toilet paper, soap dispenser, mirror.
	Ceiling - Plaster/Drywall	202 Unisex	82	SF	7	\$0	
	Doors - Wood Doors inclu hw	202 Unisex	1	EA	7	\$0	
	Floor Drain	202 Unisex	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	202 Unisex	82	SF	7	\$0	
	Hand Dryer	202 Unisex	1	EA	7	\$0	
	Lavatory	202 Unisex	1	EA	7	\$0	
	Lighting - Lay-in	202 Unisex	1	EA	7	\$0	
	Walls - Structural Glazed Tile	202 Unisex	228	SF	7	\$0	
	Walls - Tile Ceramic/ Porcelain	202 Unisex	114	SF	7	\$0	
	Water Closet	202 Unisex	1	EA	7	\$0	
	Accessories	205 - 2nd Flr SE Girls	377	SF	6	\$3,477	Soap dispenser and toilet paper available.
	Ceiling - Plaster/Drywall	205 - 2nd Flr SE Girls	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	205 - 2nd Flr SE Girls	2	EA	6	\$602	
	Floor Drain	205 - 2nd FIr SE Girls	1	EA	6	\$1,059	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor - Tile Ceramic/ Porcelain	205 - 2nd FIr SE Girls	377	SF	7	\$0	
	Hand Dryer	205 - 2nd FIr SE Girls	1	EA	7	\$0	
	Lavatory	205 - 2nd FIr SE Girls	4	EA	7	\$0	
	Lighting - Lay-in	205 - 2nd FIr SE Girls	11	EA	7	\$0	
	Partitions	205 - 2nd FIr SE Girls	8	EA	6	\$2,375	
	Walls - Structural Glazed Tile	205 - 2nd FIr SE Girls	694	SF	7	\$0	
	Water Closet	205 - 2nd FIr SE Girls	8	EA	7	\$0	
	Accessories	206	83	SF	7	\$0	Mirror, soap dispenser, toilet paper, paper towel dispenser.
	Ceiling - Plaster/Drywall	206	83	SF	7	\$0	
	Doors - Transom Window	206	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	206	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	206	83	SF	7	\$0	
	Lavatory	206	1	EA	6	\$320	
	Lighting - Lay-in	206	1	EA	6	\$119	
	Partitions	206	2	EA	7	\$0	
	Walls - Structural Glazed Tile	206	267	SF	7	\$0	
	Water Closet	206	2	EA	7	\$0	
	Accessories	2nd Flr NE Boys	377	SF	5	\$7,461	Most of the accessories in this room have been vandalized.
	Ceiling - Plaster/Drywall	2nd FIr NE Boys	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	2nd Flr NE Boys	2	EA	5	\$2,348	
	Floor Drain	2nd FIr NE Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Flr NE Boys	377	SF	7	\$0	
	Hand Dryer	2nd FIr NE Boys	1	EA	5	\$590	
	Lavatory	2nd Flr NE Boys	4	EA	6	\$1,278	
	Lighting - Lay-in	2nd Flr NE Boys	11	EA	6	\$1,309	
	Partitions	2nd Flr NE Boys	7	EA	5	\$5,256	
	Urinals	2nd Flr NE Boys	5	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd Flr NE Boys	694	SF	6	\$2,183	
	Water Closet	2nd Flr NE Boys	3	EA	7	\$0	
	Accessories	2nd FIr NW Girls	377	SF	6	\$3,477	Rusted soap dispenser, toilet paper available.
	Ceiling - Plaster/Drywall	2nd Flr NW Girls	377	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Flr NW Girls	2	EA	6	\$602	
	Floor Drain	2nd Flr NW Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Flr NW Girls	377	SF	7	\$0	
	Hand Dryer	2nd Flr NW Girls	1	EA	6	\$230	
	Lavatory	2nd Flr NW Girls	4	EA	6	\$1,278	



Building: Building A

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroo	om						
	Lighting - Lay-in	2nd FIr NW Girls	11	EA	7	\$0	
	Partitions	2nd FIr NW Girls	7	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd FIr NW Girls	694	SF	7	\$0	
	Water Closet	2nd FIr NW Girls	7	EA	7	\$0	
	Accessories	2nd FIr SW Boys	377	SF	5	\$7,461	damaged and vandalized soap dispenser, toilet paper available.
	Ceiling - Plaster/Drywall	2nd FIr SW Boys	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	2nd FIr SW Boys	2	EA	5	\$2,348	
	Floor Drain	2nd FIr SW Boys	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	2nd FIr SW Boys	377	SF	7	\$0	
	Hand Dryer	2nd FIr SW Boys	1	EA	6	\$230	
	Lavatory	2nd FIr SW Boys	4	EA	5	\$6,359	
	Lighting - Lay-in	2nd FIr SW Boys	11	EA	6	\$1,309	
	Partitions	2nd FIr SW Boys	5	EA	4	\$9,932	3 missing urinal screens, vandalized beyond
	Urinals	2nd FIr SW Boys	5	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd FIr SW Boys	694	SF	7	\$0	
	Water Closet	2nd FIr SW Boys	4	EA	7	\$0	
	Accessories	301 Male staff	82	SF	7	\$0	soap dispenser, paper towel dispenser, toilet paper dispenser.
	Ceiling - Plaster/Drywall	301 Male staff	82	SF	7	\$0	
	Doors - Wood Doors inclu hw	301 Male staff	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	301 Male staff	82	SF	7	\$0	
	Lavatory	301 Male staff	1	EA	6	\$320	
	Lighting - Lay-in	301 Male staff	1	EA	7	\$0	
	Partitions	301 Male staff	1	EA	7	\$0	
	Urinals	301 Male staff	1	EA	7	\$0	
	Walls - Plaster/Drywall	301 Male staff	283	SF	7	\$0	
	Water Closet	301 Male staff	1	EA	7	\$0	
	Accessories	301 SW Boys	377	SF	6	\$3,477	Soap dispenser and toilet paper dispenser broken.
	Ceiling - Plaster/Drywall	301 SW Boys	377	SF	6	\$1,305	
	Doors - Transom Window	301 SW Boys	9	SF	7	\$0	
	Doors - Wood Doors inclu hw	301 SW Boys	2	EA	5	\$2,348	
	Floor Drain	301 SW Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	301 SW Boys	377	SF	7	\$0	
	Hand Dryer	301 SW Boys	1	EA	7	\$0	
	Lavatory	301 SW Boys	4	EA	6	\$1,278	
	Lighting - Lay-in	301 SW Boys	11	EA	7	\$0	
	Partitions	301 SW Boys	4	EA	5		Vandalism throughout partitions.



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
	Urinals	301 SW Boys	5	EA	7	\$0	
	Walls - Structural Glazed Tile	301 SW Boys	694	SF	7	\$0	
	Water Closet	301 SW Boys	4	EA	6	\$1,344	
	Accessories	306 SE Girls	377	SF	6	\$3,477	Soap dispenser, toilet paper.
	Ceiling - Plaster/Drywall	306 SE Girls	377	SF	7	\$0	
	Doors - Transom Window	306 SE Girls	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	306 SE Girls	2	EA	6	\$602	
	Floor Drain	306 SE Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	306 SE Girls	377	SF	7	\$0	
	Hand Dryer	306 SE Girls	1	EA	5	\$590	
	Lavatory	306 SE Girls	4	EA	6	\$1,278	
	Lighting - Lay-in	306 SE Girls	11	EA	6	\$1,309	
	Partitions	306 SE Girls	8	EA	6	\$2,375	
	Walls - Structural Glazed Tile	306 SE Girls	694	SF	7	\$0	
	Water Closet	306 SE Girls	8	EA	7	\$0	
	Accessories	306 Women's Staff Toilet	83	SF	7	\$0	
	Ceiling - Plaster/Drywall	306 Women's Staff Toilet	83	SF	7	\$0	
	Doors - Wood Doors inclu hw	306 Women's Staff Toilet	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	306 Women's Staff Toilet	83	SF	7	\$0	
	Hand Dryer	306 Women's Staff Toilet	1	EA	7	\$0	
	Lavatory	306 Women's Staff Toilet	1	EA	6	\$320	
	Lighting - Lay-in	306 Women's Staff Toilet	1	EA	7	\$0	
	Partitions	306 Women's Staff Toilet	2	EA	7	\$0	
	Walls - Structural Glazed Tile	306 Women's Staff Toilet	283	SF	7	\$0	
	Water Closet	306 Women's Staff Toilet	2	EA	7	\$0	
	Accessories	309 NW Girls	377	SF	6	\$3,477	soap dispenser and toilet paper dispenser was broken.
	Ceiling - Plaster/Drywall	309 NW Girls	377	SF	7	\$0	
	Doors - Wood Doors inclu hw	309 NW Girls	2	EA	7	\$0	
	Floor Drain	309 NW Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	309 NW Girls	377	SF	6	\$798	
	Hand Dryer	309 NW Girls	1	EA	6	\$230	
	Lavatory	309 NW Girls	4	EA	6	\$1,278	
	Lighting - Lay-in	309 NW Girls	11	EA	7	\$0	
	Partitions	309 NW Girls	7	EA	7	\$0	
	Walls - Structural Glazed Tile	309 NW Girls	694	SF	7	\$0	
	Water Closet	309 NW Girls	7	EA	7	\$0	
	Accessories	3rd NE Boys	377	SF	6	\$3,477	Toilet paper and soap dispenser.


Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om de la companya de						
	Ceiling - Plaster/Drywall	3rd NE Boys	377	SF	6	\$1,305	
	Doors - Wood Doors inclu hw	3rd NE Boys	2	EA	5	\$2,348	
	Floor Drain	3rd NE Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd NE Boys	377	SF	7	\$0	
	Hand Dryer	3rd NE Boys	1	EA	7	\$0	
	Lavatory	3rd NE Boys	4	EA	6	\$1,278	
	Lighting - Lay-in	3rd NE Boys	11	EA	7	\$0	
	Partitions	3rd NE Boys	7	EA	5	\$5,256	urinal screens missing; graffiti on WC partitions
	Urinals	3rd NE Boys	5	EA	7	\$0	
	Walls - Structural Glazed Tile	3rd NE Boys	694	SF	7	\$0	
	Water Closet	3rd NE Boys	3	EA	7	\$0	
	Accessories	B15A Engineer's Toilet/Locker Room	105	SF	7	\$0	Soap dispenser, paper towel dispenser, mirror.
	Ceiling - Plaster/Drywall	B15A Engineer's Toilet/Locker Room	105	SF	7	\$0	
	Doors - Wood Doors inclu hw	B15A Engineer's Toilet/Locker Room	1	EA	7	\$0	
	Floor Drain	B15A Engineer's Toilet/Locker Room	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	B15A Engineer's Toilet/Locker Room	105	SF	7	\$0	
	Lavatory	B15A Engineer's Toilet/Locker Room	1	EA	7	\$0	
	Lighting - Lay-in	B15A Engineer's Toilet/Locker Room	2	EA	7	\$0	
	Lighting - Pendent/Surface	B15A Engineer's Toilet/Locker Room	1	EA	6	\$124	
	Lighting - Wall Mounted	B15A Engineer's Toilet/Locker Room	1	EA	7	\$0	
	Partitions	B15A Engineer's Toilet/Locker Room	3	EA	7	\$0	
	Showers	B15A Engineer's Toilet/Locker Room	1	EA	6	\$311	
	Urinals	B15A Engineer's Toilet/Locker Room	1	EA	7	\$0	
	Walls - Structural Glazed Tile	B15A Engineer's Toilet/Locker Room	459	SF	7	\$0	
	Water Closet	B15A Engineer's Toilet/Locker Room	1	EA	7	\$0	
	Accessories	B16A Engineer's Toilet/Shower Room	68	SF	7	\$0	mirror, soap dispenser, and paper towel dispenser.
	Ceiling - Plaster/Drywall	B16A Engineer's Toilet/Shower Room	68	SF	6	\$235	
	Doors - Wood Doors inclu hw	B16A Engineer's Toilet/Shower Room	1	EA	7	\$0	
	Floor Drain	B16A Engineer's Toilet/Shower Room	2	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	B16A Engineer's Toilet/Shower Room	68	SF	7	\$0	
	Lavatory	B16A Engineer's Toilet/Shower Room	1	EA	6	\$320	
	Lighting - Lay-in	B16A Engineer's Toilet/Shower Room	1	EA	7	\$0	
	Lighting - Wall Mounted	B16A Engineer's Toilet/Shower Room	1	EA	6	\$124	
	Partitions	B16A Engineer's Toilet/Shower Room	2	EA	7	\$0	
	Showers	B16A Engineer's Toilet/Shower Room	1	EA	6	\$311	
	Walls - Structural Glazed Tile	B16A Engineer's Toilet/Shower Room	276	SF	7	\$0	
	Water Closet	B16A Engineer's Toilet/Shower Room	1	EA	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Accessories	B17 Mens Toilet/Locker Room	535	SF	6	\$4,935	Mirror, drying paper towel, soap/soap dispenser, toilet paper.
	Ceiling - Plaster/Drywall	B17 Mens Toilet/Locker Room	535	SF	6	\$1,851	
	Doors - Wood Doors inclu hw	B17 Mens Toilet/Locker Room	2	EA	6	\$602	
	Floor Drain	B17 Mens Toilet/Locker Room	3	EA	6	\$3,177	
	Floor - Tile	B17 Mens Toilet/Locker Room	335	SF	5	\$1,504	
	Floor - Tile Ceramic/ Porcelain	B17 Mens Toilet/Locker Room	200	SF	7	\$0	
	Hand Dryer	B17 Mens Toilet/Locker Room	1	EA	7	\$0	
	Lavatory	B17 Mens Toilet/Locker Room	2	EA	5	\$3,179	
	Lighting - Lay-in	B17 Mens Toilet/Locker Room	6	EA	7	\$0	
	Lighting - Wall Mounted	B17 Mens Toilet/Locker Room	1	EA	6	\$124	
	Partitions	B17 Mens Toilet/Locker Room	4	EA	6	\$1,188	
	Showers	B17 Mens Toilet/Locker Room	1	EA	6	\$311	
	Student Lockers - One Tier	B17 Mens Toilet/Locker Room	39	EA	6	\$3,621	
	Urinals	B17 Mens Toilet/Locker Room	2	EA	7	\$0	
	Walls - Structural Glazed Tile	B17 Mens Toilet/Locker Room	1,524	SF	7	\$0	
	Water Closet	B17 Mens Toilet/Locker Room	2	EA	6	\$672	
	Accessories	B18 Womens Toilet/Locker Room	145	SF	7	\$0	Toilet paper dispenser, soap dispenser, mirror.
	Ceiling - Plaster/Drywall	B18 Womens Toilet/Locker Room	145	SF	7	\$0	
	Doors - Wood Doors inclu hw	B18 Womens Toilet/Locker Room	2	EA	6	\$602	
	Floor - Tile	B18 Womens Toilet/Locker Room	119	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	B18 Womens Toilet/Locker Room	26	SF	7	\$0	
	Lavatory	B18 Womens Toilet/Locker Room	1	EA	5	\$1,590	
	Lighting - Lay-in	B18 Womens Toilet/Locker Room	2	EA	7	\$0	
	Lighting - Wall Mounted	B18 Womens Toilet/Locker Room	1	EA	6	\$124	
	Student Lockers - One Tier	B18 Womens Toilet/Locker Room	5	EA	6	\$464	
	Walls - Structural Glazed Tile	B18 Womens Toilet/Locker Room	628	SF	7	\$0	
	Water Closet	B18 Womens Toilet/Locker Room	1	EA	7	\$0	
	Accessories	B6 - Men's staff toilet and locker room	143	SF	6	\$1,319	Soap dispenser.
	Ceiling - Plaster/Drywall	B6 - Men's staff toilet and locker room	143	SF	7	\$0	
	Doors - Wood Doors inclu hw	B6 - Men's staff toilet and locker room	1	EA	6	\$301	
	Floor Drain	B6 - Men's staff toilet and locker room	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	B6 - Men's staff toilet and locker room	5	SF	4	\$192	missing tiles at floor drain.
	Floor - Tile Ceramic/ Porcelain	B6 - Men's staff toilet and locker room	138	SF	6	\$292	
	Hand Dryer	B6 - Men's staff toilet and locker room	1	EA	7	\$0	
	Lavatory	B6 - Men's staff toilet and locker room	2	EA	6	\$639	
	Lighting - Lay-in	B6 - Men's staff toilet and locker room	3	EA	7	\$0	
	Lighting - Wall Mounted	B6 - Men's staff toilet and locker room	1	EA	6	\$124	



\$1,970,238

4959 S Archer Ave Chicago, IL 60632

Building: Building A

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Partitions	B6 - Men's staff toilet and locker room	1	EA	5	\$751	
	Urinals	B6 - Men's staff toilet and locker room	1	EA	7	\$0	
	Walls - Structural Glazed Tile	B6 - Men's staff toilet and locker room	474	SF	7	\$0	
	Water Closet	B6 - Men's staff toilet and locker room	1	EA	6	\$336	
	Accessories	B7 Women's Staff Toilet/Locker Room	271	SF	6	\$2,500	Soap dispenser, paper towel dispenser, toilet paper.
	Ceiling - Plaster/Drywall	B7 Women's Staff Toilet/Locker Room	271	SF	5	\$2,484	
	Doors - Wood Doors inclu hw	B7 Women's Staff Toilet/Locker Room	1	EA	5	\$1,174	Missing hardware.
	Floor Drain	B7 Women's Staff Toilet/Locker Room	1	EA	6	\$1,059	
	Floor - Tile	B7 Women's Staff Toilet/Locker Room	125	SF	6	\$273	
	Floor - Tile Ceramic/ Porcelain	B7 Women's Staff Toilet/Locker Room	146	SF	7	\$0	
	Hand Dryer	B7 Women's Staff Toilet/Locker Room	1	EA	7	\$0	
	Lavatory	B7 Women's Staff Toilet/Locker Room	2	EA	5	\$3,179	
	Lighting - Lay-in	B7 Women's Staff Toilet/Locker Room	5	EA	6	\$595	
	Lighting - Wall Mounted	B7 Women's Staff Toilet/Locker Room	1	EA	6	\$124	
	Partitions	B7 Women's Staff Toilet/Locker Room	2	EA	6	\$594	
	Walls - Structural Glazed Tile	B7 Women's Staff Toilet/Locker Room	699	SF	7	\$0	
	Water Closet	B7 Women's Staff Toilet/Locker Room	2	EA	7	\$0	

Rooms (Other Than Classrooms) Subtotal:

Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corridor	•						
	Ceiling - Lay-in	1st East	980	SF	6	\$2,943	
	Ceiling - Splined	1st East	3,784	SF	4	\$45,021	water damage stains.
	Doors - Steel Doors incl hw	1st East	8	EA	7	\$0	
	Doors - Transom Window	1st East	48	EA	6	\$813	
	Floor - Tile/Sheet	1st East	980	SF	6	\$533	
	Lighting - Lay-in	1st East	58	EA	6	\$6,901	
	Lighting - Wall Mounted	1st East	3	EA	6	\$372	
	Walls - Concrete Block	1st East	60	SF	7	\$0	
	Walls - Masonry	1st East	2,850	SF	7	\$0	
	Walls - Metal Panel	1st East	1,170	SF	6	\$8,734	
	Doors - Wood Doors include hw	1st flr misc mech/sevice doors	15	EA	7	\$0	
	Ceiling - Splined	1st middle south	1,173	SF	5	\$8,353	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Tile/Sheet	1st middle south	1,173	SF	6	\$637	
	Lighting - Lay-in	1st middle south	30	EA	5	\$4,866	
	Walls - Concrete Block	1st middle south	180	SF	6	\$528	
	Walls - Metal Panel	1st middle south	1,710	SF	6	\$12,764	
	Walls - Plaster/Drywall	1st middle south	650	SF	6	\$2,881	
	Ceiling - Lay-in	1st North	5,651	SF	5	\$37,253	water damage
	Ceiling - Splined	1st North	4,090	SF	5	\$29,127	
	Doors - Transom Window	1st North	36	EA	6	\$610	
	Doors - Wood Doors include hw	1st North	12	EA	6	\$3,612	
	Drinking Fountains - Single Water Cooler	1st North	4	EA	7	\$0	located in corridor
	Floor - Tile/Sheet	1st North	9,445	SF	6	\$5,132	
	Lighting - Lay-in	1st North	75	EA	5	\$12,164	
	Lighting - Pendent/Surface	1st North	114	EA	6	\$14,124	
	Lighting - Wall Mounted	1st North	1	EA	6	\$124	
	Student Lockers - One Tier	1st North	500	EA	6	\$46,418	
	Walls - Masonry	1st North	3,610	SF	6	\$11,357	
	Walls - Metal Panel	1st North	1,191	SF	5	\$36,430	
	Ceiling - Splined	1st South	2,615	SF	5	\$18,622	
	Doors - Store Front	1st South	2	EA	6	\$2,416	
	Drinking Fountains - Single Water Cooler	1st South	4	EA	6	\$1,267	
	Floor - Tile/Sheet	1st South	2,615	SF	6	\$1,421	
	Lighting - Pendent/Surface	1st South	36	EA	5	\$6,573	
	Walls - Concrete Block	1st South	60	SF	6	\$176	
	Walls - Masonry	1st South	1,600	SF	6	\$5,034	
	Walls - Tile Ceramic/ Porcelain	1st South	1,420	SF	5	\$22,743	
	Ceiling - Lay-in	1st West	2,794	SF	5	\$18,419	
	Ceiling - Splined	1st West	595	SF	5	\$4,237	
	Doors - Steel Doors incl hw	1st West	8	EA	6	\$2,408	
	Drinking Fountains - Single Water Cooler	1st West	2	EA	6	\$633	
	Floor - Tile/Sheet	1st West	3,389	SF	6	\$1,842	
	Lighting - Lay-in	1st West	26	EA	6	\$3,093	
	Lighting - Lay-in	1st West	14	EA	6	\$1,666	
	Student Lockers - One Tier	1st West	83	EA	6	\$7,705	
	Walls - Concrete Block	1st West	140	SF	6	\$410	
	Walls - Masonry	1st West	1,636	SF	7	\$0	
	Walls - Metal Panel	1st West	1,340	SF	6	\$10,003	
	Ceiling - Lay-in	2nd East	2,226	SF	6	\$6,685	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Doors - Wood Doors include hw	2nd East	16	EA	6	\$4,816	
	Floor - Tile/Sheet	2nd East	2,226	SF	6	\$1,210	
	Lighting - Lay-in	2nd East	43	EA	6	\$5,116	
	Walls - Masonry	2nd East	40	SF	7	\$0	
	Walls - Metal Panel	2nd East	3,302	SF	6	\$24,648	
	Ceiling - Lay-in	2nd North	7,318	SF	6	\$21,976	
	Floor - Tile/Sheet	2nd North	7,318	SF	6	\$3,977	
	Lighting - Lay-in	2nd North	138	EA	6	\$16,419	
	Student Lockers - One Tier	2nd North	650	EA	6	\$60,343	
	Walls - Masonry	2nd North	1,910	SF	7	\$0	
	Walls - Metal Panel	2nd North	2,422	SF	6	\$18,079	
	Ceiling - Lay-in	2nd South	3,330	SF	6	\$10,000	
	Floor - Tile/Sheet	2nd South	3,330	SF	6	\$1,810	
	Lighting - Lay-in	2nd South	46	EA	6	\$5,473	
	Walls - Masonry	2nd South	729	SF	7	\$0	
	Walls - Metal Panel	2nd South	2,965	SF	5	\$90,693	
	Ceiling - Lay-in	2nd West	2,476	SF	6	\$7,435	
	Doors - Transom Window	2nd West	72	EA	7	\$0	
	Doors - Wood Doors include hw	2nd West	16	EA	6	\$4,816	
	Drinking Fountains - Single Water Cooler	2nd West	4	EA	6	\$1,267	
	Floor - Tile/Sheet	2nd West	2,476	SF	6	\$1,345	
	Lighting - Lay-in	2nd West	41	EA	5	\$6,650	
	Walls - Concrete Block	2nd West	250	SF	7	\$0	
	Walls - Masonry	2nd West	60	SF	7	\$0	
	Walls - Metal Panel	2nd West	3,740	SF	6	\$27,918	
	Ceiling - Lay-in	3rd East	2,392	SF	6	\$7,183	
	Doors - Wood Doors include hw	3rd East	16	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	3rd East	4	EA	7	\$0	
	Floor - Tile/Sheet	3rd East	2,392	SF	6	\$1,300	
	Lighting - Lay-in	3rd East	42	EA	6	\$4,997	
	Walls - Masonry	3rd East	240	SF	7	\$0	
	Walls - Metal Panel	3rd East	3,530	SF	6	\$26,350	
	Ceiling - Lay-in	3rd Middle South	1,440	SF	6	\$4,324	
	Floor - Tile/Sheet	3rd Middle South	1,440	SF	6	\$782	
	Lighting - Lay-in	3rd Middle South	32	EA	5	\$5,190	
	Walls - Metal Panel	3rd Middle South	3,230	SF	5	\$98,798	
	Ceiling - Lay-in	3rd North	4,541	SF	6	\$13,637	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Tile/Sheet	3rd North	4,541	SF	6	\$2,468	
	Lighting - Lay-in	3rd North	138	EA	6	\$16,419	
	Student Lockers - One Tier	3rd North	720	EA	6	\$66,842	
	Walls - Masonry	3rd North	1,115	SF	7	\$0	
	Walls - Metal Panel	3rd North	1,190	SF	6	\$8,883	
	Ceiling - Lay-in	3rd South	3,501	SF	6	\$10,514	
	Floor - Tile/Sheet	3rd South	3,501	SF	6	\$1,902	
	Lighting - Lay-in	3rd South	52	EA	6	\$6,187	
	Walls - Masonry	3rd South	750	SF	7	\$0	
	Walls - Metal Panel	3rd South	3,095	SF	6	\$23,103	
	Ceiling - Lay-in	3rd West	2,314	SF	6	\$6,949	
	Floor - Tile/Sheet	3rd West	2,314	SF	6	\$1,257	
	Lighting - Lay-in	3rd West	40	EA	6	\$4,759	
	Student Lockers - One Tier	3rd West	15	EA	6	\$1,393	
	Walls - Masonry	3rd West	240	SF	7	\$0	
	Walls - Metal Panel	3rd West	4,120	SF	6	\$30,754	
	Ceiling - Plaster/Drywall	Basement - N/S Main	1,681	SF	6	\$10,409	
	Floor - Tile/Sheet	Basement - N/S Main	1,681	SF	5	\$7,548	
	Lighting - Pendent/Surface	Basement - N/S Main	17	EA	6	\$2,106	
	Walls - Concrete Block	Basement - N/S Main	1,440	SF	5	\$14,785	concrete foundation wall
	Walls - Concrete Block	Basement - N/S Main	1,247	SF	6	\$4,191	
	Ceiling - Splined	Basement - NW	294	SF	5	\$2,094	stained and mismatched tiles.
	Doors - Wood Doors include hw	Basement - NW	2	EA	6	\$602	
	Floor - Tile/Sheet	Basement - NW	294	SF	6	\$160	
	Lighting - Pendent/Surface	Basement - NW	4	EA	6	\$496	
	Walls - Concrete Block	Basement - NW	648	SF	6	\$1,900	
	Ceiling - Plaster/Drywall	Basement - West	211	SF	7	\$0	
	Floor - Tile/Sheet	Basement - West	211	SF	6	\$115	vct
	Lighting - Pendent/Surface	Basement - West	2	EA	7	\$0	
	Walls - Concrete Block	Basement - West	517	SF	7	\$0	
	Ceiling - Splined	North Link to Annex	2,309	SF	4	\$27,472	
	Doors - Steel Doors incl hw	North Link to Annex	1	EA	6	\$301	
	Floor - Tile/Sheet	North Link to Annex	607	SF	4	\$6,996	
	Floor - Tile/Sheet	North Link to Annex	2,202	SF	6	\$1,197	
	Lighting - Lay-in	North Link to Annex	48	EA	7	\$0	
	Lighting - Wall Mounted	North Link to Annex	2	EA	7	\$0	
	Walls - Masonry	North Link to Annex	896	SF	7	\$0	



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Splined	South Link to Annex	2,309	SF	4	\$27,472	
	Doors - Steel Doors incl hw	South Link to Annex	1	EA	6	\$301	
	Floor - Tile/Sheet	South Link to Annex	607	SF	4	\$6,996	
	Floor - Tile/Sheet	South Link to Annex	2,202	SF	6	\$1,197	
	Lighting - Lay-in	South Link to Annex	48	EA	7	\$0	
	Lighting - Wall Mounted	South Link to Annex	2	EA	7	\$0	
	Walls - Masonry	South Link to Annex	896	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule - North Link to Annex	250	SF	7	\$0	
	Doors - Transom Window	Vestibule - North Link to Annex	60	EA	7	\$0	
	Doors - Wood Doors include hw	Vestibule - North Link to Annex	8	EA	6	\$2,408	
	Floor - Tile/Sheet	Vestibule - North Link to Annex	510	SF	5	\$2,290	
	Floor - Tile/Sheet	Vestibule - North Link to Annex	46	SF	4	\$681	
	Lighting - Pendent/Surface	Vestibule - North Link to Annex	4	EA	6	\$496	
	Lighting - Wall Mounted	Vestibule - North Link to Annex	2	EA	6	\$248	
	Walls - Masonry	Vestibule - North Link to Annex	810	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule at door #8 - in room 164	66	SF	7	\$0	
	Floor - Concrete	Vestibule at door #8 - in room 164	25	SF	7	\$0	
	Lighting - Pendent/Surface	Vestibule at door #8 - in room 164	1	EA	6	\$124	
	Stairs - Concrete Stairs	Vestibule at door #8 - in room 164	54	LF	7	\$0	
	Walls - Concrete Block	Vestibule at door #8 - in room 164	366	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule/Stair to Classroom 166	85	SF	7	\$0	
	Doors - Side-lite	Vestibule/Stair to Classroom 166	1	EA	7	\$0	
	Floor - Concrete	Vestibule/Stair to Classroom 166	42	SF	7	\$0	
	Lighting - Lay-in	Vestibule/Stair to Classroom 166	2	EA	7	\$0	
	Stairs - Concrete Stairs	Vestibule/Stair to Classroom 166	52	LF	7	\$0	
	Walls - Concrete Block	Vestibule/Stair to Classroom 166	125	SF	7	\$0	
	Walls - Concrete Block	Vestibule/Stair to Classroom 166	468	SF	7	\$0	
Stairs							
	Ceiling - Lay-in	East - Basement/1st	169	SF	7	\$0	
	Floor - Concrete	East - Basement/1st	72	SF	6	\$38	
	Floor - Tile	East - Basement/1st	20	SF	6	\$11	
	Handrails	East - Basement/1st	58	LF	6	\$503	
	Lighting - Lay-in	East - Basement/1st	4	EA	7	\$0	
	Stairs - Concrete	East - Basement/1st	92	LF	6	\$763	
	Walls - Concrete Block	East - Basement/1st	1,168	SF	6	\$3,424	
	Ceiling - Plaster/Drywall	NE Stair	409	SF	7	\$0	
	Ceiling - Splined	NE Stair	1,073	SF	5		water stains.
	- 1						



Building: Building A

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Floor - Terrazzo	NE Stair	975	SF	6	\$8,184	
	Handrails	NE Stair	72	LF	6	\$624	
	Lighting - Lay-in	NE Stair	21	EA	6	\$2,498	
	Stairs - Terrazzo	NE Stair	260	LF	7	\$0	
	Walls - Masonry	NE Stair	2,876	SF	7	\$0	
	Walls - Plaster/Drywall	NE Stair	125	SF	6	\$345	
	Ceiling - Plaster/Drywall	NW Stair	409	SF	6	\$2,995	
	Ceiling - Splined	NW Stair	1,073	SF	5	\$7,641	water damage.
	Floor - Terrazzo	NW Stair	975	SF	7	\$0	
	Handrails	NW Stair	72	LF	5	\$828	
	Lighting - Lay-in	NW Stair	21	EA	6	\$2,498	
	Stairs - Terrazzo	NW Stair	260	LF	7	\$0	
	Walls - Masonry	NW Stair	2,999	SF	7	\$0	
	Handrails	Room 166 mezzanine stairs	11	LF	6	\$95	Wood railing
	Handrails	Room 166 mezzanine stairs	14	LF	7	\$0	
	Stairs - Concrete	Room 166 mezzanine stairs	48	LF	7	\$0	
	Stairs - Wood	Room 166 mezzanine stairs	51	LF	6	\$599	
	Ceiling - Plaster/Drywall	SW Stair	409	SF	6	\$2,995	
	Ceiling - Splined	SW Stair	1,073	SF	6	\$3,099	
	Floor - Terrazzo	SW Stair	975	SF	6	\$8,184	
	Handrails	SW Stair	72	LF	5	\$828	
	Lighting - Lay-in	SW Stair	21	EA	6	\$2,498	
	Stairs - Terrazzo	SW Stair	260	LF	7	\$0	
	Walls - Masonry	SW Stair	2,999	SF	7	\$0	
	Ceiling - Exposed	West - Basement/1st	137	SF	6	\$204	
	Floor - Concrete	West - Basement/1st	77	SF	6	\$41	
	Handrails	West - Basement/1st	58	LF	7	\$0	
	Lighting - Pendent/Surface	West - Basement/1st	2	EA	6	\$248	
	Lighting - Wall Mounted	West - Basement/1st	2	EA	6	\$248	
	Stairs - Concrete	West - Basement/1st	85	LF	6	\$705	
	Walls - Concrete Block	West - Basement/1st	253	SF	7	\$0	concrete foundation wall
	Walls - Concrete Block	West - Basement/1st	467	SF	7	\$0	
	Walls - Masonry	West - Basement/1st	141	SF	7	\$0	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator		1	EA	6	\$19,238	
	Elevator - Hydraulic Elevator		2	EA	5	\$173,968	



\$18,059,113

Building: Building A

Category: Building Interior			
Group Item - Type	Location	Quantity Unit Rank Cost Comments	
Building Interior Subtotal:		\$1,438,551	

Total Building Cost

Building: Linked Addition-Athletic Building B

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rance	e						
	Exterior Doors - Exterior FRP Door	1 - Main	16	EA	6	\$10,102	
	Exterior Doors - Exterior FRP Door	13	2	EA	5	\$3,672	
	Exterior Doors - Exterior FRP Door	14	2	EA	5	\$3,672	
	Exterior Doors - Exterior FRP Door	2	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	3	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	4	2	EA	5	\$3,672	
	Exterior Doors - Exterior Steel Door	11/12	8	EA	6	\$3,844	
	Exterior Doors - Side lite	1 - Main	20	EA	6	\$6,266	
	Exterior Doors - Store Front	5	8	EA	5	\$14,690	
	Exterior Doors - Transom Lite	1 - Main	24	EA	6	\$7,520	
	Exterior Doors - Transom Lite	11/12	8	EA	6	\$2,507	
	Exterior Doors - Transom Lite	3	2	EA	6	\$627	
	Exterior Doors - Transom Lite	4	2	EA	6	\$627	
	Exterior Stairs - Concrete	11/12	24	LF	6	\$1,962	
	Ramps - Concrete	11/12	10	LF	6	\$1,502	
Indat	tion						
	Foundation - Concrete	Entire Building	1,640	LF	7	\$0	
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	170,493	SF	7	\$0	
hting	3						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	15	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building	26	EA	6	\$7,507	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	\$0	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	\$855	
of Sys	stem						
	Coping - Metal	G	509	LF	6	\$16,348	
	Coping - Metal	Н	1,345	LF	6	\$43,198	
	Coping - Metal	I	428	LF	6	\$13,746	



Building: Linked Addition-Athletic Building B

Roof System J Go III - Metal J Go III - GO IIII - GO IIIIIIIIII	Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Downspouts -Interior Downspouts H 45 F 6 9997 Downspouts -Interior Downspouts I 140 LF 5 \$100.05 Downspouts -Interior Downspouts I 140 LF 5 \$100.05 Downspouts -Interior Downspouts I 140 LF 5 \$30.983 Parapet -Farapet <16" Height	Roof Sy	vstem						
Downspouts H 465 LF 5 \$100,095 Downspouts -Interior Downspouts G 500 LF 6 \$30,083 Parapet -Parapet (F) Height G 500 LF 6 \$30,083 Parapet -Parapet (F) Height H 1,345 LF 6 \$30,702 losse, bubbled Parapet - Parapet (F) Height I 0 LF 6 \$31,702 losse, bubbled Parapet - Parapet (F) Height I 0 LF 6 \$31,702 losse, bubbled Parapet - Parapet (F) Height I 0 LF 6 \$31,702 losse, bubbled Parapet (F) Height J 0 LF 6 \$31,702 losse, bubbled Rod Structure - Steel / Metal Deck Concrete Topping G 10,303 SF 7 \$00 Rod Structure - Steel / Metal Deck Concrete Topping J 22,40 SF 4 \$15,697,66 leaking, bubbling, bilistering throughout Rod - Asphat Grave Balast I 12 2,20 SF 4 \$15,697,66 leaking, bubbling,		Coping - Metal	J	60	LF	6	\$1,927	
Downspout I 10 UP 5 \$20,833 Parapet - 16' Height G 50 U 6 \$10,445 Parapet - Parapet - 16' Height H 1,345 LF 6 \$23,058 Parapet - Parapet - 16' Height I 448 LF 6 \$31,129 Parapet - Parapet - 16' Height J G LF 6 \$31,23 Parapet - Parapet - 16' Height J G LF 6 \$31,278 Parapet - Parapet - 16' Height J G 1330 SF 7 S0 Roof Structure - Steol / Metal Deck/ Concrete Topping I 22,408 SF 7 S0 Roof Structure - Steol / Metal Deck/ Concrete Topping I 23,408 SF 4 \$55,907 teaking, bubbling, bitstering throughout Roof - Asphalt Grave Balast H 1,330 SF 4 \$55,907 teaking, bubbling, bitstering throughout Roof - Asphalt Grave Balast I 22,408 SF 5 \$22,204 parapet - P		Downspouts - Interior Downspouts	G	30	LF	6	\$997	
Parapet - Parapet - 10 ⁴ Height G 509 LF 6 \$12,85 Parapet - Parapet - 10 ⁴ Height H / North 5 LF 6 \$33,70 loose, bubbled Parapet - Parapet - 10 ⁴ Height I 428 LF 6 \$31,72 Parapet - Parapet - 10 ⁴ Height I 428 LF 6 \$31,72 Parapet - Parapet - 10 ⁴ Height I 428 LF 7 \$0 Parapet - Parapet - 10 ⁴ Height I 428 LF 7 \$0 Parapet - Parapet - 10 ⁴ Height I 428 LF 7 \$0 Roof Structure - Steel / Metal Deck/ Concrete Topping G 10,330 SF 7 \$0 Roof - Asphat Gravel Ballest G 10,330 SF 4 \$2895.50 leaking, bubbling, bilstering throughout Roof - Asphat Gravel Ballest H 58.89 SF 7 \$00 Roof - Asphat Gravel Ballest H 234.08 \$565.07 leaking, bubbling, bilstering throughout Window Deckrivel Walls Ballest L \$56.07 \$56.07		Downspouts - Interior Downspouts	Н	455	LF	5	\$100,695	
Parapet - Parapet - 16" (Height H 1.345 LF 6 \$28,663 Parapet - Parapet - 16" (Height I 428 LF 6 \$3,702 loces. bubbled Parapet - Parapet - 16" (Height J 00 LF 6 \$3,173 Roof Structure - Steel / Metal Deck/ Concrete Topping G 10.30 SF 7 \$30 Roof Structure - Steel / Metal Deck/ Concrete Topping J 228 SF 7 \$30 Roof Structure - Steel / Metal Deck/ Concrete Topping J 228 SF 7 \$30 Roof Structure - Steel / Metal Deck/ Concrete Topping J 228 SF 7 \$30 Roof Structure - Steel / Metal Deck/ Concrete Topping J 228 SF 7 \$30 Roof Asphat Gravel Ballast H 5.94 \$1.954,763 teaking, bubbling, blistering throughout Roof Asphat Gravel Ballast I 2.3408 SF 4 \$5.956,707 teaking, bubbling, blistering throughout Roof Asphat Gravel Ballast I 2.3408 SF 6 \$7.4122 teaking, bubbbling, blistering throughout Wa		Downspouts - Interior Downspouts	I	140	LF	5	\$30,983	
Parapet - Parapet < 16' Height		Parapet - Parapet < 16" Height	G	509	LF	6	\$10,845	
Parapet - Parapet < 16' Haight		Parapet - Parapet < 16" Height	Н	1,345	LF	6	\$28,658	
Parapet - Parapet < 16' Height		Parapet - Parapet < 16" Height	H / North	5	LF	4	\$3,702	loose, bubbled
Rof Structure - Steel / Metal Deck/ Concrete Topping G 10.30 SF 7 S0 Rof Structure - Steel / Metal Deck/ Concrete Topping I 23.408 SF 7 S0 Rof Structure - Steel / Metal Deck/ Concrete Topping J 22.5 F 7 S0 Rof Structure - Steel / Metal Deck/ Concrete Topping J 22.5 F 7 S0 Rof - Asphati Gravel Ballast G 10.30 SF 4 \$15.97,676 leaking, bubbling, bilstering throughout Rof - Asphati Gravel Ballast I 23.408 SF 4 \$66.079 leaking, bubbling, bilstering throughout Rof - Asphati Gravel Ballast I 23.408 SF 4 \$65.079 leaking, bubbling, bilstering throughout Rof - Asphati Gravel Ballast I 23.408 SF 5 \$52.310 graffiti Rof - Asphati Gravel Succo Entire Building / North East 2.40 SF 6 \$71.22 graffiti Exterior Walls - Brick Entire Building / North East 2.40 SF 6 \$10.22 graffiti Exterior Walls - Brick Entire Building / North Ea		Parapet - Parapet < 16" Height	1	428	LF	6	\$9,119	
Rod Structure - Steel / Metal Deck/ Concrete ToppingH56,899SF7\$0Rod Structure - Steel / Metal Deck/ Concrete ToppingI2,26SF7\$0Rod Structure - Steel / Metal Deck/ Concrete ToppingG10,330SF4\$289,529leaking, bubbling, bilstering throughoutRod - Asphalt Gravel BallastH56,899SF4\$15,594,765leaking, bubbling, bilstering throughoutRod - Asphalt Gravel BallastH56,899SF4\$56,007leaking, bubbling, bilstering throughoutRod - Asphalt Gravel BallastJ225SF4\$66,079leaking, bubbling, bilstering throughoutRod - Asphalt Gravel BallastJ225SF6\$71,212Rod - Asphalt Gravel BallastJ225SF6\$24,300WallsGravel Valla - BrickEntire Building / North East2,240SF6\$24,300Exterior Walls - BrickEntire Building / North East2,240SF6\$24,000Exterior Walls - BrickEntire Building / North East2,240SF6\$24,000Gravel - Gravel Swite guardEntire Building / North East15SF6\$32,064Lintels - SteelStructure - Steel / Building / North East15SF6\$1,022Skylite - Glass Double-PaneEntire Building566LF6\$1,614Skylite - Glass Double-PaneEntire Building3,990SF6\$44,733Skylite - Glass Doubl		Parapet - Parapet < 16" Height	J	60	LF	6	\$1,278	
Roof Structure - Steel / Metal Deck/ Concrete ToppingI23,408SF7\$0Roof Structure - Steel / Metal Deck/ Concrete ToppingJ225SF7\$0Roof - Asphalt Gravel BallastG10.303SF4\$1,594,765leaking, bubbling, blistering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$566,079leaking, bubbling, blistering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$566,079leaking, bubbling, blistering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$566,079leaking, bubbling, blistering throughoutWaltsCanopy - Concrete/ StuccoEntire Building / North East2,240SF6\$74,122Exterior Walts - BrickEntire Building / North East2,240SF6\$22,070rarked, spallingWindowsGEntire Building / North East1,50SF4\$2,470rarked, spallingWindowsGEntire Building1,000SF5\$23,201structureUirtals - SteelEntire Building80SF6\$10,02structureSkylite - Glass Double-PaneEntire Building1,000SF5\$143,646Skylite - Glass Double-PaneEntire Building1,000SF5\$143,646Skylite - Glass Double-PaneEntire Building1,050SF4\$343,048Skylite - Glass Double-PaneEntire Building1,050SF<		Roof Structure - Steel / Metal Deck/ Concrete Topping	G	10,330	SF	7	\$0	
Roof Structure - Steel / Metal Deck/ Concrete ToppingJ225SF7S0Roof - Asphalt Gravel BallastG10,330SF4\$289,529leaking, bubbling, bilstering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$656,079leaking, bubbling, bilstering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$656,079leaking, bubbling, bilstering throughoutWaterCanopy - Concrete/StuccoEntire Building / North East2,240SF6\$74,122Exterior Walls - BrickEntire Building / North East2,240SF6\$322,064Exterior Walls - BrickEntire Building / North East2,25554\$2,470Exterior Walls - BrickEntire Building / North East5\$2,3,810graffitiExterior Walls - BrickEntire Building / North East15SF6\$322,064WindowsEntire Building / North East15SF6\$1,022Gardar - Guards wire guardEntire Building / North East15SF6\$1,022Lintels - SteelEntire Building / Main Roof1,200SF5\$14,34,66Storefront WindowsEntire Building / Main Roof1,200SF5\$14,34,66Storefront Windows - DecorativeEntire Building1,050SF6\$44,733Windows - DecorativeEntire Building1,050SF5\$52,8149Windows - DecorativeEntire Building1,050 </td <td></td> <td>Roof Structure - Steel / Metal Deck/ Concrete Topping</td> <td>Н</td> <td>56,899</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td>		Roof Structure - Steel / Metal Deck/ Concrete Topping	Н	56,899	SF	7	\$0	
Roof - Asphalt Gravel BallastG10,330SF4\$289,529leaking, bubbling, blistering throughoutRoof - Asphalt Gravel BallastH56,999SF4\$1,594,765leaking, bubbling, blistering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$666,079leaking, bubbling, blistering throughoutWalls22SF6\$74,122stering throughoutstering throughoutCanopy - Concrete/ StuccoEntire Building / North East2,240SF6\$232,064Exterior Walls - BrickEntire Building / North East2,240SF4\$529,279cracked, spallingWallsExterior Walls - BrickEntire Building / North East2,240SF4\$52,004Exterior Walls - BrickEntire Building / North East1SF4\$22,470cracked, spallingWindowsEntire Building / North East1SF4\$22,470cracked, spallingWindowsEntire Building / North East1,200SF6\$1,021steringSkylite - Glass Double-PaneEntire Building80SF6\$1,43,646Skylite - Glass Double-PaneEntire Building1,200SF5\$143,646Storefront WindowsEntire Building1,000SF5\$143,646Windows - DecorativeEntire Building1,000SF5\$23,810Windows - DecorativeEntire Building1,000SF5\$24,804Buildi		Roof Structure - Steel / Metal Deck/ Concrete Topping	I	23,408	SF	7	\$0	
Roof - Asphalt Gravel BallastH56,899SF4\$1,594,765leaking, bubbling, bitsering throughoutRoof - Asphalt Gravel BallastI23,408SF4\$6560,79leaking, bubbling, bitseringRoof - Asphalt Gravel BallastJ225SF4\$6,500leaking, bubbling, bitsering throughoutWallsCanopy - Concrete/StuccoEntire Building / North East2,240SF6\$74,122Exterior Walls - BrickEntire Building1,000SF5\$23,810grafftiExterior Walls - BrickEntire Building / North East15SF6\$322,064Exterior Walls - BrickEntire Building / North East15SF6\$322,064WindowsEntire Building / North East15SF6\$16,102Uintels - SteleEntire Building / North East15SF6\$16,204Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building1,650SF4\$330,48leakingWindows - DecorativeEntire Building1,050SF4\$343,048leakingBuilding: Linked Addition-Athletic Building BEntire Building1,050SF4\$352,819Building: Linked Addition-Athletic Building BEntire Building1,050SF4\$343,048leakingBuilding: Linked Addition-Athletic Building BEntire Building1,050SF5\$343,048l		Roof Structure - Steel / Metal Deck/ Concrete Topping	J	225	SF	7	\$0	
Roof - Asphalt Gravel BallastI23,408SF4\$656,079leaking, bubbling, blisteringRoof - Asphalt Gravel BallastJ225SF4\$66,306leaking, bubbling, blistering throughoutWallsCanopy - Concrete/StuccoEntire Building / North East2,240SF6\$74,112Exterior Walls - BrickEntire Building47,919SF6\$322,064Exterior Walls - BrickEntire Building / North East15SF4\$2,470cracked, spallingWindowsExterior Walls - BrickEntire Building / North East15SF6\$322,064WindowsEntire Building / North East15SF6\$32,610cracked, spallingWindowsEntire Building80SF6\$10,02cracked, spallingSkylite - Glass Double-PaneEntire Building568LF6\$143,646Storefront WindowsEntire Building3,990SF5\$143,646Storefront Windows - DecorativeEntire Building1,050SF5\$52,819Building Exterior Subtotal:Exterior Subtotal:Storefront WindowsSF5\$52,819		Roof - Asphalt Gravel Ballast	G	10,330	SF	4	\$289,529	leaking, bubbling, blistering throughout
Roof - Asphalt Gravel BallastJ225SF4\$6,300leaking, bubbling, blistering throughoutWallsCanopy - Concrete/ StuccoEntire Building (North East2,240SF6\$74,122Exterior Walls - BrickEntire Building1,000SF5\$322,004Exterior Walls - BrickEntire Building (North East1,5SF4\$2,470Exterior Walls - BrickEntire Building (North East1,5SF6\$322,004WindowsGuard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building60SF6\$1,022Skylite - Glass Double-PaneEntire Building68SF4\$185,621Skylite - Glass Double-PaneEntire Building1,200SF5\$143,646Storefront VindowsEntire Building1,050SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048Building: Exterior Subtotal:Exterior Subtotal:Exterior Subtotal:		Roof - Asphalt Gravel Ballast	Н	56,899	SF	4	\$1,594,765	leaking, bubbling, blistering throughout
Wails Canopy - Concrete/ Stucco Entire Building / North East 2,240 SF 6 \$74,122 Exterior Walls - Brick Entire Building 1,000 SF 5 \$23,810 graffiti Exterior Walls - Brick Entire Building 47,919 SF 6 \$322,064 Exterior Walls - Brick Entire Building / North East 15 SF 4 \$2,470 cracked, spalling Windows Entire Building / North East 15 SF 6 \$322,064 cracked, spalling Windows Entire Building / North East 15 SF 6 \$31,022 cracked, spalling Skylite - Glass Double-Pane Entire Building 56 LF 6 \$16,140 Skylite - Glass Double-Pane Entire Building / Main Roof 1,200 SF 5 \$143,646 Storefront Windows Entire Building 1,050 SF 4 \$195,621 leaking Windows - Decorative Entire Building 1,050 SF 4 \$143,646 \$44,733 Windows - Decorative Entire Building 1,050 SF 4 <t< td=""><td></td><td>Roof - Asphalt Gravel Ballast</td><td>I</td><td>23,408</td><td>SF</td><td>4</td><td>\$656,079</td><td>leaking, bubbling, blistering</td></t<>		Roof - Asphalt Gravel Ballast	I	23,408	SF	4	\$656,079	leaking, bubbling, blistering
Canopy - Concrete/ StuccoEntire Building / North East2,240SF6\$74,122Exterior Walls - BrickEntire Building1,000SF5\$23,810graffitiExterior Walls - BrickEntire Building47,919SF6\$322,064Exterior Walls - BrickEntire Building / North East15SF4\$2,470cracked, spallingWindowsGuard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building556LF6\$16,140Skylite - Glass Double-PaneEntire Building688SF4\$185,621leakingStorefront WindowsEntire Building1,200SF5\$143,646Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal: \$4,089,223		Roof - Asphalt Gravel Ballast	J	225	SF	4	\$6,306	leaking, bubbling, blistering throughout
Exterior Walls - BrickEntire Building1,00SF5\$23,810graffitiExterior Walls - BrickEntire Building47,919SF6\$322,064Exterior Walls - BrickEntire Building / North East15SF4\$2,470cracked, spallingWindowsGuard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building56LF6\$16,140Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building / Main Roof1,200SF5\$143,646Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building1,050SF4\$343,048leakingBuilding Exterior Subtotal:Entire Building Hain Roof1,050SF5\$52,819Storefor Subtotal:store Subtotal:Storefor Subtotal: <td< td=""><td>Walls</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Walls							
Exterior Walls - BrickEntire Building47,919SF6\$322,064Exterior Walls - BrickEntire Building / North East15SF4\$2,470cracked, spallingWindowsGuard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building556LF6\$16,140Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048Building Exterior Subtotal:Entire Building B3SF5\$52,819Building: Linked Addition-Athletic Building BEntire Building BSSSSCategory: Electrical SystemSSSSS		Canopy - Concrete/ Stucco	Entire Building / North East	2,240	SF	6	\$74,122	
Exterior Walls - BrickEntire Building / North East15SF4\$2,470cracked, spallingWindowsGuard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building566LF6\$16,140Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Skylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building431SF5\$52,819Set StateBuilding: Linked Addition-Athletic Building BEntire Building BEntire Building BEntire Building BEntire Building BEntire Building BCategory: Electrical SystemSFSFSFSFSFSF		Exterior Walls - Brick	Entire Building	1,000	SF	5	\$23,810	graffiti
Windows Guard - Guards wire guard Entire Building 80 SF 6 \$1,022 Lintels - Steel Entire Building 556 LF 6 \$16,140 Skylite - Glass Double-Pane Entire Building 688 SF 4 \$185,621 leaking Skylite - Glass Double-Pane Entire Building / Main Roof 1,200 SF 5 \$143,646 Storefront Windows Entire Building 3,990 SF 6 \$44,733 Windows - Decorative Entire Building 1,050 SF 4 \$343,048 leaking Windows - Decorative Entire Building 431 SF 5 \$52,819 \$52,819 Building Exterior Subtotal: \$4,089,223		Exterior Walls - Brick	Entire Building	47,919	SF	6	\$322,064	
Guard - Guards wire guardEntire Building80SF6\$1,022Lintels - SteelEntire Building556LF6\$16,140Skylite - Glass Double-PaneEntire Building688SF4\$185,621leakingSkylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048Windows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:\$4,089,223		Exterior Walls - Brick	Entire Building / North East	15	SF	4	\$2,470	cracked, spalling
Lintels - SteelEntire Building556LF6\$16,140Skylite - Glass Double-PaneEntire Building688SF4\$185,621leakingSkylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:\$4,089,223	Window	/S						
Skylite - Glass Double-PaneEntire Building688SF4\$185,621leakingSkylite - Glass Double-PaneEntire Building / Main Roof1,200SF5\$143,646Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048Windows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:studing BCategory: Electrical System		Guard - Guards wire guard	Entire Building	80	SF	6	\$1,022	
Skylite - Glass Double-Pane Entire Building / Main Roof 1,200 SF 5 \$143,646 Storefront Windows Entire Building 3,990 SF 6 \$44,733 Windows - Decorative Entire Building 1,050 SF 4 \$343,048 leaking Windows - Decorative Entire Building 1,050 SF 4 \$343,048 leaking Windows - Decorative Entire Building 431 SF 5 \$52,819 Building Exterior Subtotal: Building: Linked Addition-Athletic Building B Entire Building Linked System State		Lintels - Steel	Entire Building	556	LF	6	\$16,140	
Storefront WindowsEntire Building3,990SF6\$44,733Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:Stategory: Electrical System		Skylite - Glass Double-Pane	Entire Building	688	SF	4	\$185,621	leaking
Windows - Decorative Windows - DecorativeEntire Building1,050SF4\$343,048leakingWindows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:Subtotal:Subtotal:Subtotal:Category: Electrical System		Skylite - Glass Double-Pane	Entire Building / Main Roof	1,200	SF	5	\$143,646	
Windows - DecorativeEntire Building431SF5\$52,819Building Exterior Subtotal:\$4,089,223Building: Linked Addition-Athletic Building B Category: Electrical System </td <td></td> <td>Storefront Windows</td> <td>Entire Building</td> <td>3,990</td> <td>SF</td> <td>6</td> <td>\$44,733</td> <td></td>		Storefront Windows	Entire Building	3,990	SF	6	\$44,733	
Building Exterior Subtotal: \$4,089,223 Building: Linked Addition-Athletic Building B Category: Electrical System		Windows - Decorative	Entire Building	1,050	SF	4	\$343,048	leaking
Building: Linked Addition-Athletic Building B Category: Electrical System		Windows - Decorative	Entire Building	431	SF	5	\$52,819	
Category: Electrical System	Buildi	ng Exterior Subtotal:				\$	4,089,223	
Category: Electrical System								
	Buildi	ng: Linked Addition-Athletic Building B						
Group Item - Type Location Quantity Unit Rank Cost Comments	Categ	ory: Electrical System						
	Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments



Building: Linked Addition-Athletic Building B

Category: Electrical System

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
erge	ency System						
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	8,200	SF	6	\$4,339	
	Emergency A/C Power - Corridors and Stairs	Entire Building	29,956	SF	6	\$8,996	
	Emergency A/C Power - Gym	Entire Building	22,551	SF	6	\$8,384	
	Emergency A/C Power - Students Toilets	Entire Building	946	SF	6	\$352	
	Exit Signs - Auditoium	Entire Building	16	EA	6	\$2,396	
	Exit Signs - Corridors and Stairs	Entire Building	30	EA	6	\$4,492	
	Exit Signs - Gym	Entire Building	15	EA	6	\$2,361	
	Exit Signs - Pool	Entire Building	4	EA	6	\$620	
	Security System - Intrusion Detection	Electrical Room	137,930	SF	6	\$35,503	Independent System
n S	ervice						
	Independent Electrical Service for emergency power	Electrical Room / Basement	2	EA	7	\$0	
	Main Electrical Service - 1200 A 277/480/3PH	Entire Building / Penthouse	4	EA	6	\$21,386	
	Main Electrical Service - Greater than 3000 A 277/480/3PH	Entire Building / Electrical Room	1	EA	6	\$17,930	
	PA System	Entire Building	137,930	SF	5	\$94,675	
ver	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	30	EA	7	\$0	
	Transformers - 277/480 - 120/208	Entire Building	8	EA	6	\$10,120	
	ical System Subtotal:					\$211,554	

Category: Safty System

Category: Safty System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	137,930	SF	6	\$49,310	
Sprinkler System						
Sprinkler Heads	Entire Building	137,930	SF	5	\$0	
Sprinkler Piping	Entire Building	137,930	SF	5	\$96,648	
Wet Sprinkler System	Entire Building	137,930	SF	5	\$49,310	Served by main
Safty System Subtotal:					\$195,268	
Building: Linked Addition-Athletic Building B						
Category: Mechanical System						
Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments



Building: Linked Addition-Athletic Building B

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	nditioning	Location	Quantity	Onit	Nank	0031	Comments
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	6	\$4,120	
				_ /(Ũ	ψ1,120	
Air Har	idling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Mechanical Room	1	EA	3	\$9,149	Electric heat not functional
	Fan Coil Unit- Floor Mounted - Electric	Mechanical Room	1	EA	2	\$11,039	
	Fan Coil Unit- Floor Mounted - Electric	Mechanical Room	1	EA	4	\$11,039	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 21 - 30 tons	Roof	2	EA	4	\$292,255	25 years old. Needs new compressor(s). Condensing coils are damaged and unit housing is beginning to deteriorate.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 31 - 45 tons	Roof	3	EA	4	\$548,392	25 years old. Needs new compressor(s). Condensing coils are damaged and unit housing is beginning to deteriorate.
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons	Roof	3	EA	4	\$942,210	25 years old. Needs new compressor(s). Condensing coils are damaged and unit housing is beginning to deteriorate.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating & DX Cooling w/ Remote Mounted Compressor - 31 - 45 tons	Roof	1	EA	7	\$0	Installed 4 years ago. Serves pool.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons	Roof	1	EA	4	\$87,148	20 years old. Needs new compressor(s). Condensing coils are damaged and unit housing is beginning to deteriorate.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons	Roof	4	EA	4	\$501,827	20 years old. Needs new compressor(s). Condensing coils are damaged and unit housing is beginning to deteriorate.
Heating	g Devices						
	Duct Heater - Electric	Entire Building	12		6	\$5,127	
	Fin Tube - Electric	Entire Building	60	LF	7	\$0	
	Fin Tube - Electric	Entire Building	390	LF	5	\$19,904	
	Unit Heater - Electric	Mechanical Room	2	EA	6	\$556	
	Unit Heater - Gas	Mechanical Room / Basement	1	EA	7	\$0	
Tempe	rature Control						
	Electric Thermostat	Entire Building	1	EA	7	\$0	
	Hybrid Pneumatic/DDC System	Entire Building	170,493	SF	5	\$587,570	
	Thermostats - Pneumatic	Entire Building	20	EA	6	\$0	
Ventila	tion						
• critila	Exhaust Fans- Indoor - 1501 - 8000 CFM	Roof / 1st Floor	1	EA	4	\$6,392	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof / Penthouse	1	EA	3		Not operational or repairable
	Exhaust Fans- Roof Mounted - 1500 CFM	Roof	2	EA	7	4,240 \$0	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	4	EA	4		> 15 years of age and vibrating
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	9	EA	4		 > 15 years of age and vibrating > 15 years of age and vibrating
			5		-	ψ00,201	2 To youro of ago and violating



Building: Linked Addition-Athletic Building B

Category: Mechanical System

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
tilation						
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	\$592	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	\$0	
Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	1	EA	3	\$11,390	Not operational or repairable
Lab Exhaust Hood	Roof / 3rd Floor	1	EA	5	\$2,950	

Building: Linked Addition-Athletic Building B

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	iter						
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room / 2nd Floor	1	EA	6	\$310	
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room / Basement	1	EA	7	\$0	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	3	EA	4	\$39,811	Asbestos insulation
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	170,493	SF	4	\$121,902	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	170,493	SF	4	\$246,243	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Cold Water Risers	Entire Building	170,493	SF	4	\$136,531	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	170,493	SF	4	\$92,646	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	170,493	SF	4	\$219,424	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Return Lines	Entire Building	170,493	SF	4	\$146,283	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Domestic Piping-Hot Water Return Risers	Entire Building	170,493	SF	4	\$82,894	Over 1,000 clamps installed on domestic water lines throughout. Full replacement required.
	Sanitary Piping	Entire Building	170,493	SF	6	\$156,035	
	Storm Piping	Entire Building	170,493	SF	6	\$148,721	
	Vent Piping	Entire Building	170,493	SF	6	\$114,588	
Pool Sy	ystems						
	Pool Drain Piping	Mechanical Room	50	LF	7	\$0	
	Pool Filtration System including Pump	Mechanical Room	2	EA	7	\$0	
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	6	\$310	
	Pool Supply and Return Piping	Mechanical Room	300	LF	7	\$0	



Building: Linked Addition-Athletic Building B

Category: Plumbing System

	Location	Quantity	Unit	Rank	Cost	Comments
Pumps						
Pumps - Ejector-Simplex	Mechanical Room	1	EA	4	\$11,443	
Pumps - Sump-Simplex	Mechanical Room	1	EA	5	\$5,627	

Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #508 Quin Hall (Dance Room)						
	Ceiling - Exposed	1st Floor	2,520	SF	7	\$0	
	Ceiling - Splined	1st Floor	90	SF	6	\$73	
	Doors - Transom Window	1st Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	5	\$2,348	not operable between 525 and 508 as material is stored against these doors
	Floor - Tile	1st Floor	90	SF	6	\$197	
	Floor - Wood	1st Floor	2,520	SF	6	\$17,766	
	Lighting - Lay-in	1st Floor	2	EA	7	\$0	recessed type
	Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	13	EA	5	\$2,373	
	Lighting - Wall Mounted	1st Floor	1	EA	7	\$0	
	Storage/ Closet	1st Floor	300	SF	7	\$0	
	Wall Mirrors	1st Floor	14	EA	7	\$0	
	Walls - Concrete Block	1st Floor	4,350	SF	6	\$12,752	
	Walls - Concrete Block	1st Floor	940	SF	7	\$0	with wood tambour type (slat) walls.
Classro	oom #510 (Band Room)						
	Ceiling - Plaster/Drywall	1st Floor	40	SF	7	\$0	
	Ceiling - Splined	1st Floor	2,020	SF	7	\$0	
	Doors - Side-lite	1st Floor	290	SF	6	\$4,848	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	4	\$3,413	missing door
	Floor - Tile	1st Floor	2,060	SF	5	\$9,250	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	15	EA	7	\$0	metal halide, not sure if hps or sv
	Lighting - Metal Halide/Sodium Vapor	1st Floor	14	EA	6	\$1,872	metal halide, not sure if hps or sv
	Risers	1st Floor	138	LF	6	\$3,106	



Building: Linked Addition-Athletic Building B

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #510 (Band Room)						
	Sound Panels	1st Floor	158	EA	7	\$0	
	Storage/ Closet	1st Floor	160	SF	6	\$1,160	
	Student Lockers - One Tier	1st Floor	26	EA	6	\$2,414	
	Student Lockers - Three Tiers	1st Floor	2	EA	6	\$62	Five Tier
	Student Lockers - Two Tiers	1st Floor	62	EA	6	\$2,878	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	7	\$0	
	Work Sink	1st Floor	1	EA	5	\$1,508	
lassro	oom #514 (Band Room)						
	Ceiling - Plaster/Drywall	1st Floor	40	SF	7	\$0	
	Ceiling - Splined	1st Floor	2,020	SF	7	\$0	
	Doors - Side-lite	1st Floor	290	SF	6	\$4,848	
	Doors - Transom Window	1st Floor	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Floor - Tile	1st Floor	2,060	SF	6	\$4,507	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	4	EA	6	\$535	metal halide, not sure if hps or sv
	Lighting - Metal Halide/Sodium Vapor	1st Floor	27	EA	7	\$0	metal halide, not sure if hps or sv
	Risers	1st Floor	138	LF	6	\$3,106	
	Sound Panels	1st Floor	158	EA	7	\$0	
	Storage/ Closet	1st Floor	380	SF	7	\$0	
	Student Lockers - One Tier	1st Floor	11	EA	6	\$1,021	
	Student Lockers - Three Tiers	1st Floor	9	EA	6	\$279	
	Student Lockers - Three Tiers	1st Floor	42	EA	6	\$1,300	Five tier
	Student Lockers - Two Tiers	1st Floor	22	EA	6	\$1,021	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	7	\$0	
lassro	oom #525 (Laboratory/Shop)						
	Casework	1st Floor	112	LF	6	\$2,828	shop tables w/lockers below.
	Ceiling - Plaster/Drywall	1st Floor	40	SF	4	\$871	damaged - hole in ceiling
	Ceiling - Plaster/Drywall	1st Floor	1,930	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Doors - Transom Window	1st Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	\$1,505	
	Floor - Concrete	1st Floor	1,970	SF	5	\$3,381	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	12	EA	5	\$2,191	



Building: Linked Addition-Athletic Building B

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	om #525 (Laboratory/Shop)						
	Storage/ Closet	1st Floor	370	SF	6	\$2,683	
	Student Lockers - Two Tiers	1st Floor	48	EA	5	\$4,499	
	Walls - Concrete Block	1st Floor	3,300	SF	6	\$9,674	
	Work Sink	1st Floor	1	EA	6	\$379	
assroo	om #544 (Weight)						
	Ceiling - Plaster/Drywall		2,876	SF	7	\$0	
	Chalk Board		10	LF	4	\$918	
	Doors - Steel Doors incl hw		3	EA	7	\$0	
	Doors - Wood Doors inclu hw		1	EA	7	\$0	
	Floor - Weight/ Fitness Room Floor Matting		2,876	SF	6	\$15,052	
	Lighting - Lay-in		63	EA	6	\$7,495	egg-crate lenses damaged
	Walls - Concrete Block		2,894	SF	7	\$0	
assroo	om #612 (Music Room)						
	Ceiling - Splined	2nd Floor	80	SF	5	\$773	
	Ceiling - Splined	2nd Floor	740	SF	6	\$603	
	Doors - Transom Window	2nd Floor	10	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	820	SF	5	\$3,682	
	Lighting - Lay-in	2nd Floor	27	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	6	\$343	
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	\$2,870	
assroo	om #613 (Music Room)						
	Ceiling - Splined	2nd Floor	683	SF	6	\$557	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	683	SF	6	\$1,494	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Lighting - Lay-in	2nd Floor	2	EA	6	\$238	
	Marker Board	2nd Floor	22	LF	6	\$471	
	Sound System	2nd Floor	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	890	SF	6	\$2,456	
assroo	om #616 (Music Room)						
	Ceiling - Splined	2nd Floor	1,640	SF	7	\$0	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	\$903	



Building: Linked Addition-Athletic Building B

-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	om #616 (Music Room)					0001	
	Floor - Wood	2nd Floor	1,640	SF	6	\$11,562	
	Lighting - Lay-in	2nd Floor	29	EA	7	\$0	
	Lighting - Lay-in	2nd Floor	5	EA	6	\$595	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Sound Panels	2nd Floor	83	EA	7	\$0	
	Sound System	2nd Floor	1	EA	7	\$0	
	Storage/ Closet	2nd Floor	125	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	950	SF	7	\$0	
lassro	om #619 (Art Room)						
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	7	\$0	note: teacher stated windows leak at top
	Ceiling - Splined	2nd Floor	775	SF	6	\$632	
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,125	SF	6	\$2,461	
	Lighting - Lay-in	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	224	SF	6	\$657	
	Walls - Masonry	2nd Floor	270	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	620	SF	6	\$1,711	
	Work Sink	2nd Floor	1	EA	6	\$379	
	Work Sink	2nd Floor	1	EA	5	\$1,508	non-operable
assro	om #621 (Art Room)						
	Ceiling - Plaster/Drywall	2nd Floor	228	SF	7	\$0	note: teacher stated windows leak at top
	Ceiling - Splined	2nd Floor	600	SF	6	\$489	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Tile	2nd Floor	828	SF	6	\$1,812	
	Lighting - Lay-in	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Walls - Concrete Block	2nd Floor	308	SF	6	\$903	
	Walls - Masonry	2nd Floor	230	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	380	SF	6	\$1,049	
	Work Sink	2nd Floor	2	EA	6	\$758	
assro	om #627 (Art Room)						
	Casework	2nd Floor	40	LF	5	\$8,363	work table with drawers below
	Ceiling - Splined	2nd Floor	180	SF	6	\$190	skylights in ceiling
	Ceiling - Splined	2nd Floor	20	SF	4	\$281	skylight in ceiling leaking - water damage



Building: Linked Addition-Athletic Building B

			_			-	
•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #627 (Art Room)						
	Ceiling - Splined	2nd Floor	28	SF	4		stained/water damage @ 1 skylight perimeter
	Ceiling - Splined	2nd Floor	1,900	SF	6	\$1,549	
	Doors - Transom Window	2nd Floor	40	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	5	EA	6	\$1,505	
	Floor - Tile	2nd Floor	2,128	SF	6	\$4,656	
	Kiln	2nd Floor	1	EA	7	\$0	
	Lighting - Lay-in	2nd Floor	54	EA	7	\$0	
	Lighting - Lay-in	2nd Floor	6	EA	5	\$973	
	Marker Board	2nd Floor	12	LF	6	\$257	
	Storage/ Closet	2nd Floor	154	SF	7	\$0	
	Walls - Concrete Block	2nd Floor	2,300	SF	5	\$23,615	large vertical crack in wall @ NW corner
	Work Sink	2nd Floor	3	EA	6	\$1,137	
Classro	oom #629 (Art Room)						
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	7	\$0	note: teacher stated windows leak at top
	Ceiling - Splined	2nd Floor	750	SF	6	\$611	
	Ceiling - Splined	2nd Floor	25	SF	4	\$351	stained/water damage
	Doors - Transom Window	2nd Floor	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,125	SF	6	\$2,461	
	Lighting - Lay-in	2nd Floor	16	EA	7	\$0	
	Lighting - Lay-in	2nd Floor	2	EA	6	\$238	
	Marker Board	2nd Floor	12	LF	6	\$257	
	Walls - Concrete Block	2nd Floor	660	SF	6	\$1,935	
	Walls - Masonry	2nd Floor	265	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	190	SF	7	\$0	
	Work Sink	2nd Floor	2	EA	6	\$758	
Classro	oom #639 (Regular Classroom)						
	Ceiling - Splined		780	SF	4	\$8,142	stained, water damage
	Chalk Board		10	LF	4	\$918	
	Doors - Wood Doors inclu hw		1	EA	5	\$1,174	no hardware
	Floor - Tile/Sheet		780	SF	6	\$781	
	Lighting - Lay-in		10	EA	7	\$0	
	Lighting - Lay-in		4	EA	6	\$476	
	Marker Board		8	LF	7	\$0	
	Walls - Concrete Block		879	SF	6	\$2,577	
	Walls - Plaster/Drywall		105	SF	6	\$290	
				-	-	,	



Building: Linked Addition-Athletic Building B

Category: Classrooms

roup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
lassroom #643 (Healt	h)						
Ceiling - Splin	ed		773	SF	4	\$8,069	staining, water damage, missing tiles
Chalk Board			12	LF	4	\$1,102	
Doors - Wood	Doors inclu hw		2	EA	6	\$602	
Floor - Tile/She	eet		773	SF	6	\$774	
Lighting - Lay-	in		20	EA	6	\$2,380	
Walls - Concre	ete Block		879	SF	6	\$2,577	minor cracking and needs paint
Walls - Plaster	/Drywall		105	SF	6	\$290	needs paint
lassrooms Subt	otal:					6260,354	

Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Ceiling - Splined	1st Floor Boys Gym Office North	8	SF	4	\$112	damaged/missing tiles
	Ceiling - Splined	1st Floor Boys Gym Office North	112	SF	6	\$91	
	Doors - Side-lite	1st Floor Boys Gym Office North	100	SF	6	\$1,672	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym Office North	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym Office North	2	EA	5	\$2,348	doors do not lock
	Floor - Tile	1st Floor Boys Gym Office North	114	SF	6	\$249	
	Floor - Tile	1st Floor Boys Gym Office North	6	SF	4	\$78	damaged/missing tiles
	Lighting - Lay-in	1st Floor Boys Gym Office North	2	EA	7	\$0	
	Power Distribution	1st Floor Boys Gym Office North	4	EA	6	\$8,500	
	Walls - Concrete Block	1st Floor Boys Gym Office North	250	SF	6	\$733	
	Ceiling - Splined	1st Floor Boys Gym Office South	115	SF	6	\$94	
	Ceiling - Splined	1st Floor Boys Gym Office South	5	SF	4	\$70	damaged/missing tiles
	Doors - Side-lite	1st Floor Boys Gym Office South	100	SF	6	\$1,672	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym Office South	3	EA	6	\$903	
	Floor - Carpet	1st Floor Boys Gym Office South	120	SF	5	\$616	
	Lighting - Lay-in	1st Floor Boys Gym Office South	2	EA	7	\$0	
	Power Distribution	1st Floor Boys Gym Office South	4	EA	6	\$8,500	
	Walls - Concrete Block	1st Floor Boys Gym Office South	250	SF	6	\$733	
	Ceiling - Splined	1st Floor Girls Gym North Office	4	SF	4	\$56	damaged/missing tiles
	Ceiling - Splined	1st Floor Girls Gym North Office	88	SF	6	\$72	
	Doors - Wood Doors inclu hw	1st Floor Girls Gym North Office	1	EA	6	\$301	
	Floor - Tile	1st Floor Girls Gym North Office	92	SF	6	\$201	
	Lighting - Lay-in	1st Floor Girls Gym North Office	1	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	Lighting - Lay-in	1st Floor Girls Gym North Office	1	EA	6	\$119	
	Power Distribution	1st Floor Girls Gym North Office	4	EA	6	\$8,500	
	Walls - Concrete Block	1st Floor Girls Gym North Office	350	SF	6	\$1,026	
	Ceiling - Splined	1st Floor Girls Gym South Office	10	SF	4	\$113	damaged/missing tiles
	Ceiling - Splined	1st Floor Girls Gym South Office	82	SF	6	\$67	
	Doors - Wood Doors inclu hw	1st Floor Girls Gym South Office	1	EA	6	\$301	
	Floor - Tile	1st Floor Girls Gym South Office	92	SF	6	\$201	
	Lighting - Lay-in	1st Floor Girls Gym South Office	2	EA	7	\$0	
	Power Distribution	1st Floor Girls Gym South Office	4	EA	6	\$8,500	
	Walls - Concrete Block	1st Floor Girls Gym South Office	350	SF	6	\$1,026	
	Ceiling - Splined	503E Production Manager Office	70	SF	6	\$57	
	Doors - Side-lite	503E Production Manager Office	56	SF	6	\$936	
	Doors - Wood Doors inclu hw	503E Production Manager Office	1	EA	6	\$301	
	Floor - Wood	503E Production Manager Office	70	SF	6	\$493	
	Lighting - Metal Halide/Sodium Vapor	503E Production Manager Office	1	EA	6	\$134	
	Power Distribution	503E Production Manager Office	4	EA	7	\$0	
	Walls - Concrete Block	503E Production Manager Office	166	SF	7	\$0	
	Ceiling - Plaster/Drywall	506 Theatre Office	210	SF	7	\$0	
	Doors - Wood Doors inclu hw	506 Theatre Office	2	EA	6	\$602	
	Floor - Tile	506 Theatre Office	210	SF	6	\$459	
	Lighting - Lay-in	506 Theatre Office	4	EA	6	\$476	
	Power Distribution	506 Theatre Office	14	EA	6	\$29,748	
	Storage/ Closet	506 Theatre Office	445	SF	7	\$0	formerly be box office 505, but ticket windows have display cabinets now and used as storage
	Walls - Plaster/Drywall	506 Theatre Office	400	SF	6	\$1,104	
	Ceiling - Plaster/Drywall	507 Theatre Office	210	SF	7	\$0	note: storage room is included in 506
	Doors - Wood Doors inclu hw	507 Theatre Office	2	EA	6	\$602	
	Floor - Tile	507 Theatre Office	210	SF	6	\$459	
	Lighting - Pendent/Surface	507 Theatre Office	3	EA	6	\$372	
	Power Distribution	507 Theatre Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	507 Theatre Office	400	SF	6	\$1,104	
	Work SInk	507 Theatre Office	1	EA	6	\$508	
	Ceiling - Splined	508B Tickets (Box Office)	30	SF	6	\$24	
	Ceiling - Splined	508B Tickets (Box Office)	6	SF	4	\$68	missing tiles
	Doors - Wood Doors inclu hw	508B Tickets (Box Office)	1	EA	7	\$0	
	Floor - Tile	508B Tickets (Box Office)	36	SF	6	\$79	
	Lighting - Lay-in	508B Tickets (Box Office)	1	EA	7	\$0	
	Power Distribution	508B Tickets (Box Office)	2	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	istrative Suites/Offices						
	Walls - Masonry	508B Tickets (Box Office)	220	SF	7	\$0	
	Ceiling - Splined	510A - Practice Room	76	SF	4	\$793	damaged + patchwork
	Doors - Side-lite	510A - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	510A - Practice Room	1	EA	5	\$1,174	
	Floor - Tile	510A - Practice Room	76	SF	6	\$166	
	Lighting - Lay-in	510A - Practice Room	2	EA	7	\$0	
	Power Distribution	510A - Practice Room	4	EA	7	\$0	
	Walls - Concrete Block	510A - Practice Room	200	SF	7	\$0	
	Ceiling - Splined	510B - Practice Room	54	SF	5	\$385	
	Doors - Side-lite	510B - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	510B - Practice Room	1	EA	6	\$301	
	Floor - Tile	510B - Practice Room	54	SF	6	\$118	
	Lighting - Lay-in	510B - Practice Room	1	EA	7	\$0	
	Lighting - Lay-in	510B - Practice Room	1	EA	6	\$119	
	Power Distribution	510B - Practice Room	4	EA	7	\$0	
	Walls - Concrete Block	510B - Practice Room	163	SF	7	\$0	
	Ceiling - Splined	510C - Practice Room	70	SF	5	\$498	
	Ceiling - Splined	510C - Practice Room	6	SF	4	\$84	damaged/missing tiles
	Doors - Side-lite	510C - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	510C - Practice Room	1	EA	6	\$301	
	Floor - Tile	510C - Practice Room	76	SF	5	\$341	
	Lighting - Lay-in	510C - Practice Room	1	EA	7	\$0	
	Lighting - Lay-in	510C - Practice Room	1	EA	5	\$162	
	Power Distribution	510C - Practice Room	4	EA	5	\$15,407	
	Walls - Concrete Block	510C - Practice Room	200	SF	7	\$0	
	Ceiling - Splined	510D - Practice Room	76	SF	4	\$793	stained/damaged tiles
	Doors - Side-lite	510D - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	510D - Practice Room	1	EA	6	\$301	
	Floor - Tile	510D - Practice Room	76	SF	6	\$166	
	Lighting - Lay-in	510D - Practice Room	2	EA	7	\$0	
	Power Distribution	510D - Practice Room	4	EA	7	\$0	
	Walls - Concrete Block	510D - Practice Room	200	SF	7	\$0	
	Ceiling - Splined	514A - Practice Room	54	SF	4	\$564	over 50% damaged
	Doors - Side-lite	514A - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	514A - Practice Room	1	EA	6	\$301	
	Floor - Tile	514A - Practice Room	54	SF	6	\$118	
	Lighting - Lay-in	514A - Practice Room	2	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
istrative Suites/Offices						
Power Distribution	514A - Practice Room	4	EA	7	\$0	
Walls - Concrete Block	514A - Practice Room	163	SF	7	\$0	
Ceiling - Splined	514B - Practice Room	44	SF	6	\$36	
Ceiling - Splined	514B - Practice Room	10	SF	4	\$113	damaged/missing tile
Doors - Side-lite	514B - Practice Room	25	SF	6	\$418	
Doors - Wood Doors inclu hw	514B - Practice Room	1	EA	5	\$1,174	
Floor - Tile	514B - Practice Room	54	SF	6	\$118	
Lighting - Lay-in	514B - Practice Room	1	EA	7	\$0	
Power Distribution	514B - Practice Room	2	EA	6	\$4,250	
Walls - Concrete Block	514B - Practice Room	163	SF	7	\$0	
Ceiling - Splined	514C - Practice Room	86	SF	4	\$898	over 50% damaged
Doors - Side-lite	514C - Practice Room	75	SF	6	\$1,254	
Doors - Wood Doors inclu hw	514C - Practice Room	1	EA	6	\$301	
Floor - Tile	514C - Practice Room	86	SF	7	\$0	
Lighting - Lay-in	514C - Practice Room	2	EA	7	\$0	
Power Distribution	514C - Practice Room	2	EA	6	\$4,250	
Walls - Concrete Block	514C - Practice Room	200	SF	7	\$0	
Ceiling - Splined	518 1st Floor Music Office	10	SF	4	\$141	damaged/missing tiles
Ceiling - Splined	518 1st Floor Music Office	410	SF	6	\$334	
Doors - Side-lite	518 1st Floor Music Office	225	SF	6	\$3,761	
Doors - Transom Window	518 1st Floor Music Office	6	SF	6	\$102	
Doors - Wood Doors inclu hw	518 1st Floor Music Office	4	EA	6	\$1,204	
Floor - Tile	518 1st Floor Music Office	370	SF	6	\$810	
Floor - Tile	518 1st Floor Music Office	50	SF	5	\$246	
Lighting - Lay-in	518 1st Floor Music Office	10	EA	6	\$1,190	
Power Distribution	518 1st Floor Music Office	16	EA	6	\$33,998	
Storage/ Closet	518 1st Floor Music Office	280	SF	6	\$2,030	517 File Storage
Walls - Concrete Block	518 1st Floor Music Office	480	SF	7	\$0	
Ceiling - Splined	520 Green Room	358	SF	7	\$0	
Doors - Transom Window	520 Green Room	10	SF	6	\$169	
Doors - Wood Doors inclu hw	520 Green Room	1	EA	6	\$301	
Floor - Carpet	520 Green Room	358	SF	5	\$1,838	
Lighting - Lay-in	520 Green Room	5	EA	7	\$0	
Lighting - Lay-in	520 Green Room	1	EA	6	\$119	
Power Distribution	520 Green Room	6	EA	7	\$0	
Walls - Concrete Block	520 Green Room	720	SF	7	\$0	
Work SInk	520 Green Room	1	EA	7	\$0	



Building: Linked Addition-Athletic Building B

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninist	rative Suites/Offices						
(Ceiling - Splined	522 1st Floor Dressing Room (make up room)	284	SF	7	\$0	
I	Doors - Transom Window	522 1st Floor Dressing Room (make up room)	20	SF	7	\$0	
I	Doors - Wood Doors inclu hw	522 1st Floor Dressing Room (make up room)	2	EA	7	\$0	
ļ	Floor - Tile	522 1st Floor Dressing Room (make up room)	284	SF	6	\$621	
ļ	Lighting - Pendent/Surface	522 1st Floor Dressing Room (make up room)	3	EA	6	\$372	Incandescent domes
ļ	Lighting - Wall Mounted	522 1st Floor Dressing Room (make up room)	82	EA	6	\$10,159	make-up lighting - incandescent
,	Power Distribution	522 1st Floor Dressing Room (make up room)	16	EA	7	\$0	
`	Walls - Concrete Block	522 1st Floor Dressing Room (make up room)	612	SF	6	\$1,794	
`	Work Slnk	522 1st Floor Dressing Room (make up room)	1	EA	6	\$508	
I	Ceiling - Splined	525 Shop Office	150	SF	6	\$122	
(Ceiling - Splined	525 Shop Office	20	SF	4	\$227	damaged/missing tile
ſ	Doors - Steel Doors incl hw	525 Shop Office	1	EA	6	\$301	overhead door
ſ	Doors - Transom Window	525 Shop Office	6	SF	4	\$459	plywood infill panel
ſ	Doors - Wood Doors inclu hw	525 Shop Office	1	EA	6	\$301	
ſ	Floor - Tile	525 Shop Office	170	SF	6	\$372	
ſ	Lighting - Lay-in	525 Shop Office	3	EA	6	\$357	
ſ	Power Distribution	525 Shop Office	6	EA	7	\$0	
Ţ	Walls - Concrete Block	525 Shop Office	300	SF	6	\$879	
,	Ceiling - Plaster/Drywall	542C Pool Office	135	SF	7	\$0	
ſ	Doors - Steel Doors incl hw	542C Pool Office	1	EA	7	\$0	
ſ	Doors - Wood Doors inclu hw	542C Pool Office	1	EA	7	\$0	
ſ	Floor - Tile Ceramic/ Porcelain	542C Pool Office	135	SF	6	\$286	
ſ	Lighting - Lay-in	542C Pool Office	4	EA	7	\$0	
ſ	Power Distribution	542C Pool Office	6	EA	7	\$0	
,	Walls - Concrete Block	542C Pool Office	430	SF	7	\$0	
1	Ceiling - Splined	601 Control Room (in Auditorium)	180	SF	5	\$1,282	
1	Ceiling - Splined	601 Control Room (in Auditorium)	10	SF	4	\$141	damaged/missing tiles
	Doors - Side-lite	601 Control Room (in Auditorium)	80	SF	7	\$0	-
1	Doors - Wood Doors inclu hw	601 Control Room (in Auditorium)	1	EA	6	\$301	
1	Floor - Carpet	601 Control Room (in Auditorium)	190	SF	5	\$975	carpet on a built-up wood platform
	Lighting - Pendent/Surface	601 Control Room (in Auditorium)	4	EA	6		incandescent lamps



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Power Distribution	601 Control Room (in Auditorium)	8	EA	6	\$16,999	
	Walls - Concrete Block	601 Control Room (in Auditorium)	410	SF	6	\$1,202	
	Ceiling - Splined	602 Spots in Auditorium	70	SF	6	\$57	
	Doors - Side-lite	602 Spots in Auditorium	40	SF	7	\$0	
	Doors - Wood Doors inclu hw	602 Spots in Auditorium	1	EA	6	\$301	
	Floor - Carpet	602 Spots in Auditorium	70	SF	6	\$149	
	Lighting - Pendent/Surface	602 Spots in Auditorium	2	EA	7	\$0	incandescent lamp
	Power Distribution	602 Spots in Auditorium	2	EA	7	\$0	
	Walls - Concrete Block	602 Spots in Auditorium	208	SF	6	\$610	
	Ceiling - Splined	603 Spots in Auditorium	10	SF	4	\$113	damaged/missing tiles
	Ceiling - Splined	603 Spots in Auditorium	60	SF	6	\$49	
	Doors - Side-lite	603 Spots in Auditorium	40	SF	7	\$0	
	Doors - Wood Doors inclu hw	603 Spots in Auditorium	1	EA	6	\$301	
	Floor - Carpet	603 Spots in Auditorium	70	SF	6	\$149	
	Lighting - Pendent/Surface	603 Spots in Auditorium	2	EA	7	\$0	incandescent lamps
	Power Distribution	603 Spots in Auditorium	2	EA	7	\$0	
	Walls - Concrete Block	603 Spots in Auditorium	208	SF	6	\$610	
	Ceiling - Splined	616 Music Office	290	SF	7	\$0	
	Doors - Side-lite	616 Music Office	84	SF	6	\$1,404	
	Doors - Transom Window	616 Music Office	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	616 Music Office	1	EA	6	\$301	
	Floor - Tile	616 Music Office	290	SF	6	\$634	
	Lighting - Lay-in	616 Music Office	6	EA	7	\$0	
	Power Distribution	616 Music Office	6	EA	7	\$0	
	Walls - Concrete Block	616 Music Office	350	SF	7	\$0	
	Walls - Masonry	616 Music Office	190	SF	7	\$0	
	Ceiling - Splined	616B - Practice Room	120	SF	7	\$0	
	Doors - Side-lite	616B - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	616B - Practice Room	1	EA	6	\$301	
	Floor - Carpet	616B - Practice Room	120	SF	5	\$616	
	Lighting - Lay-in	616B - Practice Room	1	EA	7	\$0	
	Power Distribution	616B - Practice Room	2	EA	7	\$0	
	Walls - Concrete Block	616B - Practice Room	20	SF	5	\$282	vertical crack in cmu corner
	Walls - Concrete Block	616B - Practice Room	256	SF	7	\$0	
	Ceiling - Splined	616C - Practice Room	75	SF	7	\$0	
	Doors - Side-lite	616C - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	616C - Practice Room	1	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	strative Suites/Offices						
	Floor - Carpet	616C - Practice Room	75	SF	5	\$385	
	Lighting - Lay-in	616C - Practice Room	2	EA	7	\$0	
	Power Distribution	616C - Practice Room	2	EA	7	\$0	
	Walls - Concrete Block	616C - Practice Room	208	SF	7	\$0	
	Ceiling - Splined	616D - Practice Room	90	SF	6	\$73	
	Doors - Side-lite	616D - Practice Room	25	SF	6	\$418	
	Doors - Wood Doors inclu hw	616D - Practice Room	1	EA	6	\$301	
	Floor - Carpet	616D - Practice Room	90	SF	5	\$462	
	Lighting - Lay-in	616D - Practice Room	2	EA	7	\$0	
	Power Distribution	616D - Practice Room	2	EA	7	\$0	
	Walls - Concrete Block	616D - Practice Room	190	SF	6	\$557	
	Ceiling - Splined	620 Art Office	705	SF	6	\$575	
	Doors - Side-lite	620 Art Office	52	SF	6	\$869	
	Doors - Wood Doors inclu hw	620 Art Office	1	EA	7	\$0	
	Floor - Tile	620 Art Office	705	SF	6	\$1,542	
	Lighting - Lay-in	620 Art Office	19	EA	7	\$0	
	Power Distribution	620 Art Office	8	EA	6	\$16,999	
	Walls - Concrete Block	620 Art Office	1,010	SF	5	\$10,370	crack in cmu wall at south wall column
	Work SInk	620 Art Office	1	EA	5	\$1,508	
	Ceiling - Plaster/Drywall	620A Art Office	88	SF	7	\$0	
	Doors - Transom Window	620A Art Office	10	SF	7	\$0	
	Doors - Wood Doors inclu hw	620A Art Office	1	EA	7	\$0	
	Floor - Tile	620A Art Office	88	SF	6	\$193	
	Lighting - Pendent/Surface	620A Art Office	1	EA	7	\$0	
	Walls - Concrete Block	620A Art Office	344	SF	7	\$0	
	Ceiling - Plaster/Drywall	630 Office	287	SF	7	\$0	No access to room - same as 638
	Doors - Wood Doors inclu hw	630 Office	2	EA	7	\$0	
	Floor - Tile/Sheet	630 Office	287	SF	6	\$287	
	Lighting - Pendent/Surface	630 Office	3	EA	7	\$0	
	Power Distribution	630 Office	2	EA	7	\$0	
	Walls - Concrete Block	630 Office	540	SF	6	\$1,583	
	Walls - Plaster/Drywall	630 Office	123	SF	7	\$0	
	Ceiling - Splined	631 Office	570	SF	6	\$465	No access to room - same as 639
	Doors - Wood Doors inclu hw	631 Office	1	EA	7	\$0	
	Floor - Tile/Sheet	631 Office	570	SF	6	\$571	
	Lighting - Lay-in	631 Office	8	EA	7	\$0	
	Power Distribution	631 Office	12	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Walls - Concrete Block	631 Office	1,017	SF	6	\$2,981	
	Walls - Plaster/Drywall	631 Office	204	SF	7	\$0	
	AC Unit	638 - Copy Room	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	638 - Copy Room	287	SF	7	\$0	
	Doors - Wood Doors inclu hw	638 - Copy Room	2	EA	7	\$0	
	Floor - Tile/Sheet	638 - Copy Room	287	SF	6	\$287	
	Lighting - Pendent/Surface	638 - Copy Room	3	EA	7	\$0	
	Power Distribution	638 - Copy Room	2	EA	7	\$0	
	Walls - Concrete Block	638 - Copy Room	540	SF	6	\$1,583	some cracking in all 4 corners
	Walls - Plaster/Drywall	638 - Copy Room	123	SF	7	\$0	
	Ceiling - Splined	639 Office	570	SF	5	\$4,059	
	Doors - Wood Doors inclu hw	639 Office	1	EA	7	\$0	
	Floor - Tile/Sheet	639 Office	570	SF	5	\$2,559	floor cracking, and worn
	Lighting - Lay-in	639 Office	8	EA	7	\$0	
	Power Distribution	639 Office	12	EA	7	\$0	
	Walls - Concrete Block	639 Office	1,017	SF	6	\$2,981	cracking in all 4 corners
	Walls - Plaster/Drywall	639 Office	204	SF	7	\$0	
Audito	rium & Theater						
	Ceiling - Exposed	1st Floor	3,000	SF	7	\$0	stage area
	Ceiling - Plaster/Drywall	1st Floor	8,000	SF	7	\$0	main auditorium
	Ceiling - Splined	1st Floor	500	SF	6	\$408	center stair exits to south vestibules
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	doors @ 2nd floor exits
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	doors @ central exit stairs
	Floor - Carpet	1st Floor	8,200	SF	5	\$42,096	main auditorium + lower south entrance
	Lighting - Lay-in	1st Floor	9	EA	6	\$1,071	recessed can par lamps @ central stair exits
	Lighting - Lay-in	1st Floor	3	EA	5	\$487	recessed can par lamps @ central stair exits. not lit
	Lighting - Pendent/Surface	1st Floor	66	EA	5	\$12,049	main auditorium lighting. building engineer stated ballasts are outdated.
	Lighting - Pendent/Surface	1st Floor	10	EA	5	\$1,826	
	Lighting - Pendent/Surface	1st Floor	20	EA	4	\$10,813	main auditorium lighting. not lit - building enginee stated lighting which is not lit may be non- functional
	Lighting - Wall Mounted	1st Floor	4	EA	4	\$1,573	not lit - building engineer stated lighting which is not lit may be non-functional
	Lighting - Wall Mounted	1st Floor	10	EA	6	\$1,239	
	Main Floor Seating	1st Floor	965	EA	7	\$0	
	Sound System	1st Floor	1	EA	7	\$0	



Building: Linked Addition-Athletic Building B

р	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
oriu	ım & Theater						
	Stage	1st Floor	3,300	SF	6	\$19,065	wood floor
	Stage Curtain	1st Floor	5	EA	6	\$0	
	Stage Lift	1st Floor	1	EA	5	\$18,165	stage lift is actually an elevator which also services other floors. It's access to stage is through corridor. Building engineer stated there is a work order in place to have it repaired.
	Stage Lighting System	1st Floor	1	EA	5	\$98,708	building engineer can no longer obtain lamps for stage lighting.
	Stage-Stairs - Wood	1st Floor	30	LF	5	\$1,601	carpet
	Stairs	1st Floor	100		7	\$0	2 concrete stairs from backstage to below stage storage (1 each side)
	Stairs	1st Floor	110		5	\$0	carpet treads - 1 exit stair at center auditorium (east)
	Stairs	1st Floor	42		6	\$0	steel spiral stair from backstage to stage balcony
	Stairs - Tile	1st Floor	110	LF	6	\$1,021	rubber treads - 1 exit stair at center auditorium (west)
	Stairs - Tile	1st Floor	40	LF	5	\$718	carpeted - 2 exit stairs at lower auditorium
	Storage/ Closet	1st Floor	640	SF	6	\$4,640	area below stage
	Walls - Concrete Block	1st Floor	4,100	SF	6	\$12,019	stage
	Walls - Masonry	1st Floor	8,000	SF	7	\$0	main auditorium, lower stairs + central stairs
asi	a						
	Bleacher Seating	1st Floor Boys Gym	300	EA	4	\$70,854	bleachers were closed, however park district teacher estimated about 20% damaged beyond repair (not useable)
	Bleacher Seating	1st Floor Boys Gym	1,130	EA	6	\$32,706	bleacher seating was not viewed in an open position
	Ceiling - Exposed	1st Floor Boys Gym	12,230	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor Boys Gym	24	SF	7	\$0	
	Doors - Transom Window	1st Floor Boys Gym	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym	4	EA	6	\$1,204	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym	2	EA	7	\$0	
	Floor - Wood	1st Floor Boys Gym	12,254	SF	7	\$0	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor Boys Gym	44	EA	7	\$0	metal halide - hps or sv?
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor Boys Gym	4	EA	5	\$907	metal halide - hps or sv?
	Lighting - Pendent/Surface	1st Floor Boys Gym	6	EA	7	\$0	
	Scoreboards	1st Floor Boys Gym	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor Boys Gym	7,200	SF	6	\$21,107	
	Walls - Concrete Block	1st Floor Boys Gym	4,600	SF	6	\$15,458	behind bleachers. cannot see condition to rank, because bleachers were closed.



Building: Linked Addition-Athletic Building B

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sia						
Walls - Metal Panel	1st Floor Boys Gym	900	SF	6	\$8,147	unknown type panel wall system above moveable panel wall
Walls - Metal Panel	1st Floor Boys Gym	100	SF	4	\$12,131	unknown type panel wall system above moveable panel wall - damaged w/large holes in panels
Walls - Metal Panel	1st Floor Boys Gym	1,100	SF	7	\$0	wood panel wall above bleachers
Ceiling - Exposed	1st Floor Girls Gym North 533A	4,560	SF	7	\$0	
Ceiling - Plaster/Drywall	1st Floor Girls Gym North 533A	12	SF	4	\$272	damaged/broken ceiling @ doors
Doors - Steel Doors incl hw	1st Floor Girls Gym North 533A	2	EA	6	\$602	
Doors - Transom Window	1st Floor Girls Gym North 533A	20	SF	6	\$339	
Doors - Transom Window	1st Floor Girls Gym North 533A	6	SF	7	\$0	
Doors - Wood Doors inclu hw	1st Floor Girls Gym North 533A	1	EA	7	\$0	
Doors - Wood Doors inclu hw	1st Floor Girls Gym North 533A	2	EA	5	\$2,348	west storage room
Floor - Wood	1st Floor Girls Gym North 533A	4,572	SF	7	\$0	
Lighting - Metal Halide/Sodium Vapor	1st Floor Girls Gym North 533A	2	EA	5	\$454	
Lighting - Metal Halide/Sodium Vapor	1st Floor Girls Gym North 533A	13	EA	7	\$0	
Lighting - Pendent/Surface	1st Floor Girls Gym North 533A	2	EA	7	\$0	
Scoreboards	1st Floor Girls Gym North 533A	1	EA	6	\$2,244	
Storage/ Closet	1st Floor Girls Gym North 533A	130	SF	7	\$0	
Storage/ Closet	1st Floor Girls Gym North 533A	200	SF	6	\$1,450	padlocked. not accessible.
Walls - Concrete Block	1st Floor Girls Gym North 533A	4,200	SF	6	\$12,312	
Walls - Metal Panel	1st Floor Girls Gym North 533A	1,070	SF	6	\$9,686	unknown type panel wall system above moveable panel wall
Walls - Metal Panel	1st Floor Girls Gym North 533A	160	SF	4	\$19,409	unknown type panel wall system above moveable panel wall - damaged w/large holes in panels
Walls - Metal Panel	1st Floor Girls Gym North 533A	3,000	SF	4	\$299,185	moveable panel wall system - non-operable, wall being held in place by 2 x wood studs screwed into gym floor at base. panels are in very poor condition and have been repaired several times. doors are in poor condition between gyms. wall has not operated for over 6 years according to gym teachers.
Ceiling - Exposed	1st Floor Girls Gym South 533B	4,560	SF	7	\$0	
Ceiling - Plaster/Drywall	1st Floor Girls Gym South 533B	12	SF	7	\$0	
Doors - Steel Doors incl hw	1st Floor Girls Gym South 533B	5	EA	6	\$1,505	
Doors - Transom Window	1st Floor Girls Gym South 533B	26	SF	6	\$440	
Doors - Wood Doors inclu hw	1st Floor Girls Gym South 533B	2	EA	5	\$2,348	
Floor - Wood	1st Floor Girls Gym South 533B	4,572	SF	7	\$0	
Lighting - Metal Halide/Sodium Vapor	1st Floor Girls Gym South 533B	15	EA	7	\$0	
Lighting - Pendent/Surface	1st Floor Girls Gym South 533B	1	EA	7	\$0	
Scoreboards	1st Floor Girls Gym South 533B	1	EA	6	\$2,244	



Building: Linked Addition-Athletic Building B

ltem - Type	Location	Quantity	Unit	Rank	Cost	Comments
asia						
Storage/ Closet	1st Floor Girls Gym South 533B	200	SF	6	\$1,450	
Storage/ Closet	1st Floor Girls Gym South 533B	130	SF	7	\$0	
Walls - Concrete Block	1st Floor Girls Gym South 533B	4,170	SF	6	\$12,224	
Walls - Metal Panel	1st Floor Girls Gym South 533B	722	SF	6	\$6,535	unknown type panel wall system above moveable panel wall
Walls - Metal Panel	1st Floor Girls Gym South 533B	512	SF	4	\$55,395	unknown type panel wall system above moveable panel wall - damaged w/large holes in panels
Walls - Metal Panel	1st Floor Girls Gym South 533B	1,350	SF	4	\$134,633	moveable panel wall system - non-operable, wall is being held in place by 2 x wood studs screwed into gym floor at base. panels are in very poor condition and have been repaired several times. doors are in poor condition between gyms. wall has not operated for over 6 years according to gym teachers.
Ceiling - Plaster/Drywall	540 Wrestling Gym	2,679	SF	7	\$0	
Doors - Wood Doors inclu hw	540 Wrestling Gym	2	EA	7	\$0	
Floor - Weight/ Fitness Room Floor Matting	540 Wrestling Gym	2,475	SF	7	\$0	
Floor - Weight/ Fitness Room Floor Matting	540 Wrestling Gym	204	SF	4	\$6,120	Floor is split and has large gaps of missing material
Lighting - Lay-in	540 Wrestling Gym	50	EA	6	\$5,949	egg-crate lenses damaged
Walls - Concrete Block	540 Wrestling Gym	2,800	SF	7	\$0	
r/Shower Room						
Accessories	2nd Floor Team Large	243	SF	5	\$2,123	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
Ceiling - Plaster/ Drywall	2nd Floor Team Large	20	SF	4	\$435	Damaged/collapsed
Ceiling - Plaster/ Drywall	2nd Floor Team Large	753	SF	6	\$2,606	
Doors - Wood Doors inclu hw	2nd Floor Team Large	2	EA	6	\$602	
Floor Drain	2nd Floor Team Large	3	EA	6	\$3,177	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
Floor - Concrete	2nd Floor Team Large	530	SF	6	\$280	
Floor - Tile Ceramic/ Porcelain	2nd Floor Team Large	243	SF	6	\$514	
Lavatory	2nd Floor Team Large	2	EA	5	\$7,526	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
Lighting - Pendent/Surface	2nd Floor Team Large	8	EA	6	\$991	
Partitions	2nd Floor Team Large	1	EA	6	\$297	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/	/Shower Room						
	Showers	2nd Floor Team Large	4	EA	5	\$10,858	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
	Storage/ Closet	2nd Floor Team Large	108	SF	6	\$783	
	Student Lockers - One Tier	2nd Floor Team Large	71	EA	5	\$9,951	
	Urinals	2nd Floor Team Large	1	EA	5	\$3,894	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
	Walls - Concrete Block	2nd Floor Team Large	691	SF	6	\$2,026	
	Walls - Structural Glazed Tile	2nd Floor Team Large	598	SF	6	\$1,881	
	Water Closet	2nd Floor Team Large	1	EA	5	\$3,894	No access to toilet/shower area which is gated/padlocked off from lockers; appeared abandoned
	Ceiling - Plaster/ Drywall	2nd Floor Team Small	248	SF	6	\$858	
	Doors - Steel Doors incl hw	2nd Floor Team Small	1	EA	6	\$301	
	Floor - Concrete	2nd Floor Team Small	248	SF	6	\$131	
	Lighting - Pendent/Surface	2nd Floor Team Small	4	EA	6	\$496	covers missing
	Student Lockers - Two Tier	2nd Floor Team Small	64	EA	5	\$5,999	bent, broken
	Walls - Concrete Block	2nd Floor Team Small	476	SF	6	\$1,395	
	Accessories	2nd Floor	400	SF	6	\$1,567	
	Accessories	2nd Floor	400	SF	6	\$1,567	
	Benches, ped mounted	2nd Floor	80	LF	6	\$8,710	
	Benches, ped mounted	2nd Floor	80	LF	6	\$8,710	
	Ceiling - Plaster/ Drywall	2nd Floor	3,781	SF	6	\$13,085	
	Ceiling - Plaster/ Drywall	2nd Floor	3,781	SF	6	\$13,085	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor Drain	2nd Floor	21	EA	7	\$0	
	Floor Drain	2nd Floor	3	EA	5	\$6,282	covers missing
	Floor Drain	2nd Floor	24	EA	7	\$0	
	Floor - Concrete Epoxy/ Painted	2nd Floor	2,398	SF	6	\$1,269	
	Floor - Epoxy/ Painted	2nd Floor	2,398	SF	6	\$1,269	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	1,098	SF	6	\$2,324	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	1,383	SF	6	\$2,927	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	285	SF	4	\$9,145	displaced, broken
	Hand Dryer	2nd Floor	12	EA	7	\$0	
	Hand Dryer	2nd Floor	12	EA	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker	/Shower Room						
	Lavatory	2nd Floor	3	EA	6	\$959	
	Lavatory	2nd Floor	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	2nd Floor	51	EA	6	\$6,319	
	Lighting - Pendent/Surface	2nd Floor	51	EA	6	\$6,319	
	Partitions	2nd Floor	4	EA	7	\$0	
	Partitions	2nd Floor	5	EA	6	\$1,485	
	Showers	2nd Floor	26	EA	5	\$70,577	
	Showers	2nd Floor	26	EA	5	\$70,577	
	Storage/ Closet	2nd Floor	54	SF	6	\$392	
	Storage/ Closet	2nd Floor	54	SF	6	\$392	
	Student Lockers - One Tier	2nd Floor	8	EA	6	\$743	
	Student Lockers - One Tier	2nd Floor	28	EA	6	\$2,599	
	Student Lockers - Two Tier	2nd Floor	750	EA	6	\$34,813	
	Student Lockers - Two Tier	2nd Floor	734	EA	6	\$34,071	
	Urinals	2nd Floor	2	EA	7	\$0	
	Walls - Concrete Block	2nd Floor	1,305	SF	6	\$3,826	
	Walls - Concrete Block	2nd Floor	1,305	SF	6	\$3,826	
	Walls - Structural Glazed Tile	2nd Floor	1,902	SF	6	\$5,984	
	Walls - Structural Glazed Tile	2nd Floor	1,902	SF	6	\$5,984	
	Water Closet	2nd Floor	4	EA	6	\$1,344	
	Water Closet	2nd Floor	5	EA	6	\$1,680	
	Accessories	538A Accessible Locker Room	251	SF	7	\$0	
	Benches, ped mounted	538A Accessible Locker Room	4	LF	7	\$0	
	Ceiling - Plaster/ Drywall	538A Accessible Locker Room	251	SF	7	\$0	
	Doors - Wood Doors inclu hw	538A Accessible Locker Room	2	EA	6	\$602	
	Floor Drain	538A Accessible Locker Room	2	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	538A Accessible Locker Room	251	SF	7	\$0	
	Hand Dryer	538A Accessible Locker Room	1	EA	7	\$0	
	Lavatory	538A Accessible Locker Room	1	EA	7	\$0	
	Lighting - Lay-in	538A Accessible Locker Room	4	EA	7	\$0	
	Lighting - Pendent/Surface	538A Accessible Locker Room	2	EA	7	\$0	
	Showers	538A Accessible Locker Room	1	EA	7	\$0	
	Student Lockers - One Tier	538A Accessible Locker Room	4	EA	7	\$0	
	Walls - Structural Glazed Tile	538A Accessible Locker Room	930	SF	7	\$0	
	Water Closet	538A Accessible Locker Room	1	EA	7	\$0	
	Accessories	539B Accessible Locker Room	251	SF	7	\$0	
	Benches, ped mounted	539B Accessible Locker Room	4	LF	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker/	Shower Room						
	Ceiling - Plaster/ Drywall	539B Accessible Locker Room	251	SF	7	\$0	
	Doors - Wood Doors inclu hw	539B Accessible Locker Room	2	EA	6	\$602	
	Floor Drain	539B Accessible Locker Room	2	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	539B Accessible Locker Room	251	SF	7	\$0	
	Hand Dryer	539B Accessible Locker Room	1	EA	7	\$0	
	Lavatory	539B Accessible Locker Room	1	EA	7	\$0	
	Lighting - Lay-in	539B Accessible Locker Room	4	EA	7	\$0	
	Lighting - Pendent/Surface	539B Accessible Locker Room	2	EA	7	\$0	
	Showers	539B Accessible Locker Room	1	EA	7	\$0	
	Student Lockers - One Tier	539B Accessible Locker Room	4	EA	7	\$0	
	Walls - Structural Glazed Tile	539B Accessible Locker Room	30	SF	6	\$145	
	Walls - Structural Glazed Tile	539B Accessible Locker Room	900	SF	7	\$0	
	Water Closet	539B Accessible Locker Room	1	EA	7	\$0	
Mechar	ical/ Service Rooms						
	Janitor's Closet	1st Floor	180	SF	6	\$1,290	off corridor south of Girls Gym
	Mechanical/ Service Rooms	1st Floor	300	SF	6	\$2,149	526B, 526C, 530A, 531A,Mechanical
	Mechanical/ Service Rooms	1st Floor	244	SF	7	\$0	544A - Electrical Switch Room in Weight Room
	Storage Room	1st Floor	358	SF	7	\$0	524 Prop Storage
	Storage Room	1st Floor	200	SF	7	\$0	504A off corridor north of Girls Gym
	Storage Room	1st Floor	160	SF	6	\$1,146	540A - Wrestling Gym Storage (No Access - Padlocked)
	Storage Room	1st Floor	232	SF	7	\$0	546 - Equipment Storage in Weight Room
	Storage Room	1st Floor	125	SF	7	\$0	544B - Athletic Equipment Storage in Weight Room
	Interior Stairs	2nd Floor	52	LF	6	\$469	access stair to roof - concrete
	Janitor's Closet	2nd Floor	30	SF	6	\$215	in 609 Men's Restroom NW
	Janitor's Closet	2nd Floor	28	SF	5	\$452	in 625 Men's Restroom NE
	Mechanical/ Service Rooms	2nd Floor	300	SF	7	\$0	623A + 623B
	Mechanical/ Service Rooms	2nd Floor	110	SF	6	\$788	access stair to roof
	Mechanical/ Service Rooms	2nd Floor	200	SF	7	\$0	605 Electrical (access via back stage balcony 604 or spiral stair from stage)
	Mechanical/ Service Rooms	2nd Floor	90	SF	7	\$0	Elevator Machine Room
	Mechanical/ Service Rooms	2nd Floor	200	SF	7	\$0	625B in Men's Restroom 625 NE
	Mechanical/ Service Rooms	2nd Floor	150	SF	6	\$1,075	645 - Storage / Laundry Room
	Storage Room	2nd Floor	56	SF	7	\$0	623D
	Storage Room	2nd Floor	134	SF	7	\$0	618A
	Storage Room	2nd Floor	406	SF	6	\$2,909	611, 611A, + 611B
	Storage Room	2nd Floor	154	SF	7	\$0	627B Art Storage



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Storage Room	2nd Floor	620	SF	7	\$0	604 + 606 Stage Balconies
	Mechanical/ Service Rooms	3rd Floor	625	SF	6	\$4,478	Mechanical room accessible from roof only
	Mechanical/ Service Rooms	Basement	4,450	SF	6	\$31,881	Pool Equipment and area around pool basin
Pool &	Natatorium						
	Accessories	1st Floor	7,592	SF	7	\$0	
	Bleachers Seating/Plank Seating	1st Floor	136	EA	7	\$0	
	Ceiling - Lay-In	1st Floor	7,592	SF	7	\$0	
	Ceiling - Plaster/ Drywall	1st Floor	390	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	\$0	
	Floor - Concrete Epoxy/ Painted	1st Floor	882	SF	7	\$0	
	Lighting - Lay-in	1st Floor	4	EA	7	\$0	
	Lighting - Lay-in	1st Floor	2	EA	6	\$238	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	19	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	4	EA	7	\$0	
	Pool Basin	1st Floor	3,451	SF	7	\$0	
	Pool Deck	1st Floor	2,873	SF	7	\$0	
	Pool Deck Drains	1st Floor	24	EA	7	\$0	Estimate. Linear drainage system along circumference of pool.
	Storage/ Closet	1st Floor	92	SF	7	\$0	
	Walls - Masonry	1st Floor	8,605	SF	7	\$0	
Restroo	om						
	Accessories	1st Floor NE Boys	355	SF	6	\$3,274	
	Ceiling - Plaster/Drywall	1st Floor NE Boys	355	SF	6	\$1,229	
	Doors - Transom Window	1st Floor NE Boys	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	1st Floor NE Boys	2	EA	6	\$602	
	Floor Drain	1st Floor NE Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor NE Boys	335	SF	6	\$709	
	Floor - Tile Ceramic/ Porcelain	1st Floor NE Boys	20	SF	4	\$769	damaged/broken tile
	Hand Dryer	1st Floor NE Boys	1	EA	5	\$590	
	Hand Dryer	1st Floor NE Boys	1	EA	6	\$230	
	Lavatory	1st Floor NE Boys	2	EA	6	\$639	
	Lavatory	1st Floor NE Boys	1	EA	5	\$1,590	
	Lighting - Lay-in	1st Floor NE Boys	2	EA	6	\$238	
	Lighting - Lay-in	1st Floor NE Boys	2	EA	7	\$0	
	Partitions	1st Floor NE Boys	3	EA	7	\$0	
	Urinals	1st Floor NE Boys	4	EA	6	\$1,344	
	Walls - Structural Glazed Tile	1st Floor NE Boys	875	SF	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Water Closet	1st Floor NE Boys	3	EA	6	\$1,008	
	Accessories	1st Floor NW Girls (by link)	385	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor NW Girls (by link)	385	SF	7	\$0	
	Doors - Transom Window	1st Floor NW Girls (by link)	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	1st Floor NW Girls (by link)	2	EA	6	\$602	
	Floor Drain	1st Floor NW Girls (by link)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor NW Girls (by link)	385	SF	6	\$815	
	Hand Dryer	1st Floor NW Girls (by link)	1	EA	7	\$0	
	Lavatory	1st Floor NW Girls (by link)	4	EA	6	\$1,278	
	Lighting - Lay-in	1st Floor NW Girls (by link)	4	EA	7	\$0	
	Lighting - Lay-in	1st Floor NW Girls (by link)	1	EA	6	\$119	
	Partitions	1st Floor NW Girls (by link)	7	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor NW Girls (by link)	950	SF	7	\$0	
	Water Closet	1st Floor NW Girls (by link)	7	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor Pool Boys	70	SF	7	\$0	
	Doors - Side-lite	1st Floor Pool Boys	1	SF	6	\$17	does not fit correctly in doorjamb
	Floor Drain	1st Floor Pool Boys	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor Pool Boys	68	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor Pool Boys	2	SF	4	\$77	missing tiles
	Lighting - Lay-in	1st Floor Pool Boys	1	EA	7	\$0	
	Partitions	1st Floor Pool Boys	1	EA	6	\$297	
	Urinals	1st Floor Pool Boys	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor Pool Boys	9	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor Pool Boys	360	SF	7	\$0	
	Water Closet	1st Floor Pool Boys	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor Pool Girls	70	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor Pool Girls	1	EA	7	\$0	
	Floor Drain	1st Floor Pool Girls	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor Pool Girls	70	SF	7	\$0	
	Lighting - Lay-in	1st Floor Pool Girls	1	EA	7	\$0	
	Partitions	1st Floor Pool Girls	2	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor Pool Girls	9	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor Pool Girls	360	SF	7	\$0	
	Water Closet	1st Floor Pool Girls	2	EA	7	\$0	
	Accessories	1st Floor SE Girls	208	SF	6	\$1,918	
	Ceiling - Plaster/Drywall	1st Floor SE Girls	208	SF	6	\$720	
	Doors - Wood Doors inclu hw	1st Floor SE Girls	1	EA	6	\$301	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Floor Drain	1st Floor SE Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor SE Girls	188	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	1st Floor SE Girls	20	SF	4	\$769	damaged/missing
	Hand Dryer	1st Floor SE Girls	1	EA	6	\$230	
	Lavatory	1st Floor SE Girls	3	EA	7	\$0	
	Lighting - Lay-in	1st Floor SE Girls	3	EA	7	\$0	
	Partitions	1st Floor SE Girls	3	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor SE Girls	750	SF	6	\$2,360	
	Water Closet	1st Floor SE Girls	3	EA	7	\$0	
	Accessories	1st Floor SW Boys (used as Storage)	175	SF	5	\$3,463	
	Ceiling - Plaster/Drywall	1st Floor SW Boys (used as Storage)	175	SF	6	\$606	
	Doors - Wood Doors inclu hw	1st Floor SW Boys (used as Storage)	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor SW Boys (used as Storage)	175	SF	6	\$370	
	Lavatory	1st Floor SW Boys (used as Storage)	2	EA	6	\$639	
	Lighting - Lay-in	1st Floor SW Boys (used as Storage)	3	EA	7	\$0	
	Partitions	1st Floor SW Boys (used as Storage)	2	EA	6	\$594	
	Urinals	1st Floor SW Boys (used as Storage)	2	EA	5	\$2,688	not visible
	Walls - Structural Glazed Tile	1st Floor SW Boys (used as Storage)	648	SF	7	\$0	
	Water Closet	1st Floor SW Boys (used as Storage)	2	EA	6	\$672	
	Accessories	2nd Floor NE Men	190	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor NE Men	190	SF	7	\$0	
	Doors - Transom Window	2nd Floor NE Men	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	2nd Floor NE Men	2	EA	6	\$602	
	Floor Drain	2nd Floor NE Men	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor NE Men	10	SF	4	\$385	damaged/missing tile
	Floor - Tile Ceramic/ Porcelain	2nd Floor NE Men	180	SF	6	\$381	
	Hand Dryer	2nd Floor NE Men	1	EA	7	\$0	
	Lavatory	2nd Floor NE Men	2	EA	6	\$639	
	Lighting - Lay-in	2nd Floor NE Men	3	EA	7	\$0	
	Partitions	2nd Floor NE Men	2	EA	7	\$0	
	Urinals	2nd Floor NE Men	3	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd Floor NE Men	640	SF	7	\$0	
	Walls - Structural Glazed Tile	2nd Floor NE Men	2	SF	4	\$245	damaged/broken tile
	Water Closet	2nd Floor NE Men	2	EA	7	\$0	-
	Accessories	2nd Floor NE Women	230	SF	7	\$0	
	Ceiling - Plaster/Drywall	2nd Floor NE Women	230	SF	7	\$0	
	Doors - Transom Window	2nd Floor NE Women	10	SF	6	\$169	



Building: Linked Addition-Athletic Building B

RestroomPoors Vlood Doors inclu hw2nd Floor NE Women1EA6\$3.01Floor Orain2nd Floor NE Women20SF6\$4.87Lovatory2nd Floor NE Women20EA6\$6.83Lighting - Lay-in2nd Floor NE Women2EA7\$0.01Lighting - Lay-in2nd Floor NE Women2EA7\$0.01Pattions2nd Floor NE Women4EA6\$1.19Pattions2nd Floor NE Women4EA7\$0.01Walls - Structural Glazed Tile2nd Floor NE Women4EA7\$0.01Water Closet2nd Floor NE Women4EA7\$0.01Accessories2nd Floor NE Women4EA7\$0.01Doors - Transom Window2nd Floor NE Women4EA7\$0.01Doors - Transom Window2nd Floor NW Mens (609)100SF6\$1.752Doors - Transom Window2nd Floor NW Mens (609)100SF6\$1.69Floor Train2nd Floor NW Mens (609)10SF6\$4.02Floor Train2nd Floor NW Mens (609)10SF6\$4.02Hand Dryer2nd Floor NW Mens (609)10 <th></th>	
Floor Drain2nd Floor NE Women1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NE Women230SF6\$487Lavatory2nd Floor NE Women2EA6\$639Lighting - Lay-in2nd Floor NE Women2EA7\$00Lighting - Lay-in2nd Floor NE Women4EA7\$00Partitions2nd Floor NE Women4EA7\$00Walls - Structural Glazed Tile2nd Floor NE Women4EA7\$00Water Closet2nd Floor NE Women4EA7\$00Accessories2nd Floor NE Women4EA7\$00Oros - Transom Window2nd Floor NW Mens (609)190SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)10SF6\$169Floor Tile Ceramic/ Porcelain2nd Floor NW Mens (609)10SF6\$169Floor Tile Ceramic/ Porcelain2nd Floor NW Mens (609)10SF6\$402Hand Dryer2nd Floor NW Mens (609)10SF6\$402Hand Dryer2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)10SF6\$402Hand Dryer2nd Floor NW Mens (609)10SF6\$402Lighting - Lay-in2nd Floor NW Mens (609)10SF6\$402Lighting - Lay-in2nd Floor NW Mens (609)10 <th></th>	
Floor - Tile Ceramic/ Porcelain2nd Floor NE Women230SF64487Lavatory2nd Floor NE Women2EA6\$639Lighting - Lay-in2nd Floor NE Women2EA7\$0Lighting - Lay-in2nd Floor NE Women1EA7\$0Partitions2nd Floor NE Women4EA7\$0Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NE Women4EA7\$0Accessories2nd Floor NE Women4EA7\$0Doors - Transom Window2nd Floor NW Mens (609)190SF6\$119Doors - Wood Doors inclu hw2nd Floor NW Mens (609)10SF6\$109Floor Drain2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$109Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$309Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$309 <td></td>	
Lavatory2nd Floor NE Women2EA6\$639Lighting - Lay-in2nd Floor NE Women2EA7\$0Lighting - Lay-in2nd Floor NE Women1EA6\$119Partitions2nd Floor NE Women4EA7\$0Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women926SF6\$1,752Ceiling - Plaster/Drywall2nd Floor NW Mens (609)10SF6\$109Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Transom Window2nd Floor NW Mens (609)10SF6\$109Doors - Transom Window2nd Floor NW Mens (609)10SF6\$109Doors - Transom Window2nd Floor NW Mens (609)1EA6\$109Floor Drain2nd Floor NW Mens (609)1EA6\$109Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)2EA7\$00Lavatory2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)2EA6\$230 <tr< td=""><td></td></tr<>	
Lighting - Lay-in2nd Floor NE Women2EA7S0Lighting - Lay-in2nd Floor NE Women1EA6\$119Partitions2nd Floor NE Women4EA7\$0Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NE Women4EA7\$0Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF6\$1,752Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)10SF6\$1,059Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor Jile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$230Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lighting - Lay-in2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)1EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119Lighting - Lay-in2nd Floor NW Mens (
Lighting - Lay-in2nd Floor NE WomenIEA6\$119Partitions2nd Floor NE Women4EA7\$0Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NE Women4EA7\$0Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF6\$17,52Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Transom Window2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$230Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$230Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$19Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119Lighting - Lay-in2nd Floor NW Mens	
Partitions2nd Floor NE Women4EA7\$0Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NW Mens (609)190SF6\$1,752Ceiling - Plaster/Drywall2nd Floor NW Mens (609)10SF6\$169Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Walls - Structural Glazed Tile2nd Floor NE Women926SF7\$0Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NW Mens (609)190SF6\$1,752Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF7\$0Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Water Closet2nd Floor NE Women4EA7\$0Accessories2nd Floor NW Mens (609)190SF6\$1,752Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF7\$0Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Accessories2nd Floor NW Mens (609)190SF6\$1,752Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF7\$0Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)1EA6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Ceiling - Plaster/Drywall2nd Floor NW Mens (609)190SF7\$0Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Doors - Transom Window2nd Floor NW Mens (609)10SF6\$169Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Doors - Wood Doors inclu hw2nd Floor NW Mens (609)1EA7\$0Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Floor Drain2nd Floor NW Mens (609)1EA6\$1,059Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Floor - Tile Ceramic/ Porcelain2nd Floor NW Mens (609)190SF6\$402Hand Dryer2nd Floor NW Mens (609)1EA6\$230Lavatory2nd Floor NW Mens (609)3EA6\$959Lighting - Lay-in2nd Floor NW Mens (609)2EA7\$0Lighting - Lay-in2nd Floor NW Mens (609)1EA6\$119	
Hand Dryer 2nd Floor NW Mens (609) 1 EA 6 \$230 Lavatory 2nd Floor NW Mens (609) 3 EA 6 \$959 Lighting - Lay-in 2nd Floor NW Mens (609) 2 EA 7 \$0 Lighting - Lay-in 2nd Floor NW Mens (609) 1 EA 6 \$119	
Lavatory 2nd Floor NW Mens (609) 3 EA 6 \$959 Lighting - Lay-in 2nd Floor NW Mens (609) 2 EA 7 \$0 Lighting - Lay-in 2nd Floor NW Mens (609) 1 EA 6 \$119	
Lighting - Lay-in 2nd Floor NW Mens (609) 2 EA 7 \$0 Lighting - Lay-in 2nd Floor NW Mens (609) 1 EA 6 \$119	
Lighting - Lay-in2nd Floor NW Mens (609)1 EA6\$119	
Partitions 2nd Floor NW Mens (609) 1 FA 6 \$297	
Urinals 2nd Floor NW Mens (609) 3 EA 6 \$1,008	
Walls - Structural Glazed Tile2nd Floor NW Mens (609)750SF7\$0	
Water Closet2nd Floor NW Mens (609)1EA7\$0	
Accessories 2nd Floor NW Womens (610) 190 SF 7 \$0	
Ceiling - Plaster/Drywall 2nd Floor NW Womens (610) 190 SF 7 \$0	
Doors - Transom Window2nd Floor NW Womens (610)10SF7\$0	
Doors - Wood Doors inclu hw2nd Floor NW Womens (610)1EA7\$0	
Floor Drain 2nd Floor NW Womens (610) 1 EA 6 \$1,059	
Floor - Tile Ceramic/ Porcelain2nd Floor NW Womens (610)190SF6\$402	
Hand Dryer2nd Floor NW Womens (610)1EA7\$0	
Lavatory 2nd Floor NW Womens (610) 2 EA 6 \$639	
Lavatory 2nd Floor NW Womens (610) 1 EA 5 \$1,590 non-operable	
Lighting - Lay-in 2nd Floor NW Womens (610) 2 EA 7 \$0	
Partitions 2nd Floor NW Womens (610) 2 EA 7 \$0	
Walls - Structural Glazed Tile2nd Floor NW Womens (610)700SF7\$0	
Water Closet2nd Floor NW Womens (610)2EA7\$0	
Accessories 521 1st Floor Womens Dressing Room 136 SF 6 \$1,254	


Building: Linked Addition-Athletic Building B

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Ceiling - Plaster/Drywall	521 1st Floor Womens Dressing Room	110	SF	7	\$0	
	Ceiling - Splined	521 1st Floor Womens Dressing Room	230	SF	7	\$0	
	Ceiling - Splined	521 1st Floor Womens Dressing Room	10	SF	4	\$141	damaged/missing tiles
	Doors - Transom Window	521 1st Floor Womens Dressing Room	10	SF	7	\$0	
	Doors - Wood Doors inclu hw	521 1st Floor Womens Dressing Room	1	EA	7	\$0	
	Floor Drain	521 1st Floor Womens Dressing Room	1	EA	6	\$1,059	
	Floor - Tile	521 1st Floor Womens Dressing Room	214	SF	6	\$468	
	Floor - Tile Ceramic/ Porcelain	521 1st Floor Womens Dressing Room	116	SF	7	\$0	
	Lavatory	521 1st Floor Womens Dressing Room	1	EA	6	\$320	
	Lighting - Lay-in	521 1st Floor Womens Dressing Room	5	EA	7	\$0	
	Partitions	521 1st Floor Womens Dressing Room	1	EA	7	\$0	
	Showers	521 1st Floor Womens Dressing Room	2	EA	6	\$623	
	Student Lockers - One Tier	521 1st Floor Womens Dressing Room	6	EA	7	\$0	
	Walls - Concrete Block	521 1st Floor Womens Dressing Room	640	SF	7	\$0	
	Walls - Structural Glazed Tile	521 1st Floor Womens Dressing Room	520	SF	7	\$0	
	Water Closet	521 1st Floor Womens Dressing Room	1	EA	7	\$0	
	Accessories	523 1st Floor Mens Dressing Room	136	SF	6	\$1,254	
	Ceiling - Plaster/Drywall	523 1st Floor Mens Dressing Room	110	SF	7	\$0	
	Ceiling - Splined	523 1st Floor Mens Dressing Room	220	SF	6	\$179	
	Ceiling - Splined	523 1st Floor Mens Dressing Room	20	SF	4	\$281	damaged/missing tiles
	Doors - Transom Window	523 1st Floor Mens Dressing Room	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	523 1st Floor Mens Dressing Room	1	EA	6	\$301	
	Floor Drain	523 1st Floor Mens Dressing Room	1	EA	6	\$1,059	
	Floor - Tile	523 1st Floor Mens Dressing Room	214	SF	6	\$468	
	Floor - Tile Ceramic/ Porcelain	523 1st Floor Mens Dressing Room	116	SF	7	\$0	
	Lavatory	523 1st Floor Mens Dressing Room	1	EA	6	\$320	
	Lighting - Lay-in	523 1st Floor Mens Dressing Room	5	EA	7	\$0	
	Partitions	523 1st Floor Mens Dressing Room	1	EA	7	\$0	
	Showers	523 1st Floor Mens Dressing Room	2	EA	6	\$623	
	Student Lockers - One Tier	523 1st Floor Mens Dressing Room	6	EA	7	\$0	
	Walls - Concrete Block	523 1st Floor Mens Dressing Room	640	SF	7	\$0	
	Walls - Structural Glazed Tile	523 1st Floor Mens Dressing Room	520	SF	7	\$0	
	Water Closet	523 1st Floor Mens Dressing Room	1	EA	7	\$0	
—	o (Other Then Classroome) Subtetel				^	4 700 040	

Rooms (Other Than Classrooms) Subtotal:

\$1,738,216

Building: Linked Addition-Athletic Building B



Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Plaster/Drywall	1st Floor	120	SF	6	\$743	
	Ceiling - Splined	1st Floor	1,175	SF	5	\$11,358	
	Ceiling - Splined	1st Floor	5,818	SF	6	\$19,801	
	Ceiling - Splined	1st Floor	7,382	SF	4	\$87,828	
	Doors - Side-lite	1st Floor	82	EA	6	\$1,371	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	Janitor's Closet by south of girls gym
	Doors - Store Front	1st Floor	20	EA	6	\$24,164	
	Doors - Transom Window	1st Floor	80	EA	6	\$1,354	4 mechanical rooms + 1 storage room
	Doors - Transom Window	1st Floor	200	EA	6	\$3,386	
	Doors - Wood Doors include hw	1st Floor	7	EA	6	\$2,107	4 mechanical rooms + 1 storage room
	Doors - Wood Doors include hw	1st Floor	2	EA	7	\$0	524 Prop Storage Room
	Doors - Wood Doors include hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors include hw	1st Floor	1	EA	5	\$1,174	
	Doors - Wood Doors include hw	1st Floor	1	EA	6	\$301	
	Drinking Fountains - Single Fountain	1st Floor	7	EA	7	\$0	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	6	\$276	
	Floor - Concrete Epoxy/ Painted	1st Floor	3,585	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	5,618	SF	6	\$3,615	
	Floor - Tile/Sheet	1st Floor	6,964	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	12	SF	4	\$178	
	Lighting - Lay-in	1st Floor	1	EA	6	\$0	
	Lighting - Lay-in	1st Floor	263	EA	7	\$0	
	Lighting - Lay-in	1st Floor	1	EA	4	\$0	
	Lighting - Wall Mounted	1st Floor	6	EA	7	\$0	
	Stairs - Concrete Stairs	1st Floor	110	LF	7	\$0	
	Walls - Concrete Block	1st Floor	770	SF	7	\$0	
	Walls - Masonry	1st Floor	16,030	SF	7	\$0	
	Ceiling - Splined	2nd Floor	4,900	SF	4	\$58,298	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Doors - Store Front	2nd Floor	2	EA	6	\$2,416	
	Doors - Transom Window	2nd Floor	26	EA	7	\$0	
	Doors - Transom Window	2nd Floor	44	EA	6	\$745	
	Doors - Wood Doors include hw	2nd Floor	11	EA	7	\$0	
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	\$1,204	
	Doors - Wood Doors include hw	2nd Floor	1	EA	6	\$301	
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	\$602	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	2,654	SF	6	\$1,442	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	pr						
	Floor - Tile/Sheet	2nd Floor	1,235	SF	5	\$6,075	
	Lighting - Lay-in	2nd Floor	9	EA	6	\$1,071	
	Lighting - Lay-in	2nd Floor	66	EA	7	\$0	
	Walls - Concrete Block	2nd Floor	344	SF	5	\$4,152	
	Walls - Concrete Block	2nd Floor	1,122	SF	6	\$3,770	
	Walls - Concrete Block	2nd Floor	820	SF	7	\$0	
	Walls - Masonry	2nd Floor	6,814	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	531	SF	6	\$2,794	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	\$201	
	Walls - Plaster/Drywall	2nd Floor	620	SF	7	\$0	
	Ceiling - Splined	510 Corridor @ Practice Rooms	122	SF	6	\$352	
	Doors - Wood Doors include hw	510 Corridor @ Practice Rooms	2	EA	6	\$602	
	Floor - Tile/Sheet	510 Corridor @ Practice Rooms	122	SF	6	\$66	
	Lighting - Lay-in	510 Corridor @ Practice Rooms	3	EA	7	\$0	
	Lighting - Pendent/Surface	510 Corridor @ Practice Rooms	1	EA	6	\$124	
	Walls - Concrete Block	510 Corridor @ Practice Rooms	60	SF	7	\$0	
	Ceiling - Splined	510 North Vestibule	45	SF	5	\$320	
	Doors - Transom Window	510 North Vestibule	16	EA	6	\$271	
	Doors - Wood Doors include hw	510 North Vestibule	2	EA	5	\$2,348	
	Floor - Tile/Sheet	510 North Vestibule	45	SF	6	\$24	
	Lighting - Lay-in	510 North Vestibule	1	EA	7	\$0	
	Walls - Masonry	510 North Vestibule	110	SF	7	\$0	
	Ceiling - Splined	510 South Corridor	1	SF	4	\$17	
	Ceiling - Splined	510 South Corridor	23	SF	6	\$66	
	Doors - Transom Window	510 South Corridor	8	EA	6	\$135	
	Doors - Wood Doors include hw	510 South Corridor	1	EA	5	\$1,174	
	Floor - Tile/Sheet	510 South Corridor	24	SF	6	\$13	
	Lighting - Lay-in	510 South Corridor	1	EA	5	\$162	
	Walls - Masonry	510 South Corridor	88	SF	7	\$0	
	Ceiling - Splined	514 Corridor @ Practice Rooms	12	SF	4	\$206	
	Ceiling - Splined	514 Corridor @ Practice Rooms	110	SF	6	\$318	
	Doors - Wood Doors include hw	514 Corridor @ Practice Rooms	2	EA	6	\$602	
	Floor - Tile/Sheet	514 Corridor @ Practice Rooms	122	SF	6	\$66	
	Lighting - Lay-in	514 Corridor @ Practice Rooms	3	EA	7	\$0	
	Lighting - Pendent/Surface	514 Corridor @ Practice Rooms	1	EA	6	\$124	
	Walls - Concrete Block	514 Corridor @ Practice Rooms	60	SF	7	\$0	
	Ceiling - Splined	514 North Vestibule	5	SF	4	\$69	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	n						
	Ceiling - Splined	514 North Vestibule	36	SF	6	\$104	
	Doors - Wood Doors include hw	514 North Vestibule	1	EA	5	\$1,174	
	Floor - Tile/Sheet	514 North Vestibule	40	SF	5	\$180	
	Lighting - Lay-in	514 North Vestibule	1	EA	7	\$0	
	Walls - Plaster/Drywall	514 North Vestibule	132	SF	5	\$974	
	Ceiling - Splined	514 South Vestibule	45	SF	5	\$320	
	Doors - Transom Window	514 South Vestibule	16	EA	6	\$271	
	Doors - Wood Doors include hw	514 South Vestibule	2	EA	5	\$2,348	
	Floor - Tile/Sheet	514 South Vestibule	45	SF	6	\$24	
	Lighting - Lay-in	514 South Vestibule	1	EA	7	\$0	
	Walls - Masonry	514 South Vestibule	110	SF	7	\$0	
	Ceiling - Splined	616 at Practice Rooms	124	SF	7	\$0	
	Doors - Transom Window	616 at Practice Rooms	6	EA	6	\$102	
	Doors - Wood Doors include hw	616 at Practice Rooms	2	EA	6	\$602	
	Floor - Carpet	616 at Practice Rooms	124	SF	5	\$637	
	Lighting - Lay-in	616 at Practice Rooms	2	EA	7	\$0	
	Stairs - Concrete Stairs	616 at Practice Rooms	13	LF	5	\$1,288	
	Walls - Concrete Block	616 at Practice Rooms	130	SF	7	\$0	
	Ceiling - Splined	616 South Vestibule	2	SF	4	\$34	
	Ceiling - Splined	616 South Vestibule	73	SF	7	\$0	
	Doors - Transom Window	616 South Vestibule	6	EA	6	\$102	
	Doors - Wood Doors include hw	616 South Vestibule	1	EA	7	\$0	
	Doors - Wood Doors include hw	616 South Vestibule	2	EA	6	\$602	
	Floor - Tile/Sheet	616 South Vestibule	75	SF	6	\$41	
	Lighting - Lay-in	616 South Vestibule	1	EA	7	\$0	
	Walls - Concrete Block	616 South Vestibule	164	SF	7	\$0	
	Ceiling - Splined	617 to Choral Hall 618	44	SF	7	\$0	
	Doors - Store Front	617 to Choral Hall 618	2	EA	6	\$2,416	
	Doors - Wood Doors include hw	617 to Choral Hall 618	1	EA	6	\$301	
	Floor - Tile/Sheet	617 to Choral Hall 618	44	SF	6	\$24	
	Lighting - Lay-in	617 to Choral Hall 618	1	EA	7	\$0	
	Walls - Concrete Block	617 to Choral Hall 618	160	SF	7	\$0	
	Ceiling - Plaster/Drywall	Exit Vestibule Under East Pool Stair	45	SF	6	\$279	
	Floor - Concrete	Exit Vestibule Under East Pool Stair	45	SF	6	\$24	
	Lighting - Lay-in	Exit Vestibule Under East Pool Stair	1	EA	7	\$0	
	Walls - Concrete Block	Exit Vestibule Under East Pool Stair	138	SF	7	\$0	
	Ceiling - Plaster/Drywall	Exit Vestibule Under West Pool Stair	45	SF	6	\$279	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Floor - Concrete	Exit Vestibule Under West Pool Stair	45	SF	6	\$24	
	Lighting - Lay-in	Exit Vestibule Under West Pool Stair	1	EA	7	\$0	
	Walls - Concrete Block	Exit Vestibule Under West Pool Stair	138	SF	7	\$0	
	Doors - Steel Doors incl hw	Mechanical/Storage Doors	2	EA	7	\$0	
	Doors - Steel Doors incl hw	Mechanical/Storage Doors	1	EA	7	\$0	
	Doors - Steel Doors incl hw	Mechanical/Storage Doors	2	EA	7	\$0	
	Doors - Wood Doors include hw	Mechanical/Storage Doors	1	EA	6	\$301	
	Doors - Wood Doors include hw	Mechanical/Storage Doors	2	EA	6	\$602	
	Doors - Side-lite	Stair Doors	24	EA	6	\$401	
	Doors - Side-lite	Stair Doors	24	EA	6	\$401	
	Doors - Steel Doors incl hw	Stair Doors	1	EA	7	\$0	
	Doors - Steel Doors incl hw	Stair Doors	1	EA	7	\$0	
	Doors - Transom Window	Stair Doors	30	EA	6	\$508	
	Doors - Transom Window	Stair Doors	30	EA	6	\$508	
	Doors - Wood Doors include hw	Stair Doors	1	EA	6	\$301	
	Doors - Wood Doors include hw	Stair Doors	1	EA	6	\$301	
	Doors - Wood Doors include hw	Stair Doors	3	EA	6	\$903	
	Doors - Wood Doors include hw	Stair Doors	3	EA	6	\$903	
	Ceiling - Splined	Unisex Locker Room Corridor	105	SF	4	\$1,249	
	Doors - Wood Doors include hw	Unisex Locker Room Corridor	1	EA	5	\$1,174	
	Doors - Wood Doors include hw	Unisex Locker Room Corridor	1	EA	6	\$301	
	Floor - Tile/Sheet	Unisex Locker Room Corridor	105	SF	5	\$471	
	Lighting - Lay-in	Unisex Locker Room Corridor	1	EA	7	\$0	
	Lighting - Lay-in	Unisex Locker Room Corridor	1	EA	6	\$119	
	Walls - Concrete Block	Unisex Locker Room Corridor	433	SF	6	\$1,269	
	Ceiling - Splined	Vestibule - Auditorium SE	50	SF	6	\$144	
	Doors - Side-lite	Vestibule - Auditorium SE	20	EA	6	\$334	
	Doors - Store Front	Vestibule - Auditorium SE	1	EA	6	\$1,208	
	Doors - Store Front	Vestibule - Auditorium SE	1	EA	4	\$5,324	main exit door
	Doors - Wood Doors include hw	Vestibule - Auditorium SE	2	EA	6	\$602	
	Floor - Carpet	Vestibule - Auditorium SE	50	SF	5	\$257	
	Lighting - Lay-in	Vestibule - Auditorium SE	2	EA	6	\$238	
	Walls - Masonry	Vestibule - Auditorium SE	100	SF	7	\$0	
	Ceiling - Splined	Vestibule - Auditorium Stage NE	30	SF	6	\$87	
	Doors - Transom Window	Vestibule - Auditorium Stage NE	20	EA	6	\$339	
	Doors - Wood Doors include hw	Vestibule - Auditorium Stage NE	4	EA	5	\$4,696	
	Floor - Tile/Sheet	Vestibule - Auditorium Stage NE	30	SF	6	\$16	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or and a second s						
	Lighting - Lay-in	Vestibule - Auditorium Stage NE	1	EA	6	\$119	
	Walls - Concrete Block	Vestibule - Auditorium Stage NE	100	SF	6	\$293	
	Ceiling - Splined	Vestibule - Auditorium Stage NW	30	SF	6	\$87	
	Doors - Transom Window	Vestibule - Auditorium Stage NW	20	EA	6	\$339	
	Doors - Wood Doors include hw	Vestibule - Auditorium Stage NW	4	EA	5	\$4,696	
	Floor - Tile/Sheet	Vestibule - Auditorium Stage NW	30	SF	6	\$16	
	Lighting - Lay-in	Vestibule - Auditorium Stage NW	1	EA	6	\$119	
	Walls - Concrete Block	Vestibule - Auditorium Stage NW	100	SF	6	\$293	
	Ceiling - Splined	Vestibule - Auditorium SW	50	SF	6	\$144	
	Doors - Side-lite	Vestibule - Auditorium SW	20	EA	6	\$334	
	Doors - Store Front	Vestibule - Auditorium SW	2	EA	6	\$2,416	
	Doors - Wood Doors include hw	Vestibule - Auditorium SW	2	EA	6	\$602	
	Floor - Carpet	Vestibule - Auditorium SW	50	SF	5	\$257	
	Lighting - Lay-in	Vestibule - Auditorium SW	2	EA	6	\$238	
	Walls - Masonry	Vestibule - Auditorium SW	100	SF	7	\$0	
e / 1							
Stairs							
	Ceiling - Plaster/Drywall	East Locker Stairs	34	SF	5	\$500	
	Ceiling - Splined	East Locker Stairs	170	SF	4	\$2,023	
	Floor - Concrete Epoxy/ Painted	East Locker Stairs	35	SF	7	\$0	
	Floor - Terrazzo	East Locker Stairs	36	SF	7	\$0	
	Floor - Tile/Sheet	East Locker Stairs	135	SF	6	\$73	
	Handrails	East Locker Stairs	70	LF	6	\$607	
	Lighting - Lay-in	East Locker Stairs	2	EA	7	\$0	
	Lighting - Pendent/Surface	East Locker Stairs	1	EA	6	\$124	
	Stairs - Terrazzo	East Locker Stairs	128	LF	7	\$0	
	Walls - Masonry	East Locker Stairs	1,334	SF	7	\$0	
	Ceiling - Lay-in	East Pool Stairs	242	SF	7	\$0	
	Floor - Concrete	East Pool Stairs	70	SF	6	\$37	
	Floor - Tile/Sheet	East Pool Stairs	22	SF	7	\$0	
	Handrails	East Pool Stairs	72	LF	7	\$0	
	Lighting - Wall Mounted	East Pool Stairs	2	EA	7	\$0	
	Stairs - Concrete	East Pool Stairs	116	LF	6	\$962	
	Stairs - Tile	East Pool Stairs	17	LF	7	\$0	
	Walls - Masonry	East Pool Stairs	1,135	SF	7	\$0	
	Ceiling - Plaster/Drywall	Northeast Fire Stair	170	SF	6	\$1,245	
	Ceiling - Splined	Northeast Fire Stair	270	SF	6	\$780	
	Ceiling - Splined	Northeast Fire Stair	16	SF	4	\$274	



Building: Linked Addition-Athletic Building B

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs			,				
	Floor - Terrazzo	Northeast Fire Stair	24	SF	7	\$0	
	Floor - Tile/Sheet	Northeast Fire Stair	342	SF	6	\$186	
	Handrails	Northeast Fire Stair	68	LF	6	\$589	
	Lighting - Lay-in	Northeast Fire Stair	6	EA	7	\$0	
	Stairs - Terrazzo	Northeast Fire Stair	102	LF	7	\$0	
	Walls - Masonry	Northeast Fire Stair	1,621	SF	7	\$0	
	Ceiling - Splined	Northeast Stair - Central Stairs	187	SF	6	\$540	
	Floor - Terrazzo	Northeast Stair - Central Stairs	40	SF	7	\$0	
	Handrails	Northeast Stair - Central Stairs	28	LF	6	\$243	
	Handrails	Northeast Stair - Central Stairs	69	LF	7	\$0	
	Lighting - Lay-in	Northeast Stair - Central Stairs	4	EA	7	\$0	
	Stairs - Terrazzo	Northeast Stair - Central Stairs	160	LF	7	\$0	
	Walls - Masonry	Northeast Stair - Central Stairs	994	SF	7	\$0	
	Ceiling - Splined	Northwest Fire Stair	286	SF	6	\$826	
	Floor - Terrazzo	Northwest Fire Stair	24	SF	7	\$0	
	Floor - Tile/Sheet	Northwest Fire Stair	342	SF	6	\$186	
	Handrails	Northwest Fire Stair	68	LF	6	\$589	
	Lighting - Lay-in	Northwest Fire Stair	6	EA	7	\$0	
	Stairs - Terrazzo	Northwest Fire Stair	102	LF	7	\$0	
	Walls - Masonry	Northwest Fire Stair	1,621	SF	7	\$0	
	Walls - Plaster/Drywall	Northwest Fire Stair	104	SF	7	\$0	
	Ceiling - Splined	Northwest Stair - Central Stairs	187	SF	6	\$540	
	Floor - Terrazzo	Northwest Stair - Central Stairs	40	SF	7	\$0	
	Handrails	Northwest Stair - Central Stairs	38	LF	6	\$329	
	Handrails	Northwest Stair - Central Stairs	69	LF	7	\$0	
	Lighting - Lay-in	Northwest Stair - Central Stairs	3	EA	6	\$357	
	Lighting - Lay-in	Northwest Stair - Central Stairs	1	EA	5	\$162	
	Stairs - Terrazzo	Northwest Stair - Central Stairs	160	LF	7	\$0	
	Walls - Masonry	Northwest Stair - Central Stairs	994	SF	7	\$0	
	Ceiling - Splined	Southeast Core Stairs	187	SF	6	\$540	
	Floor - Terrazzo	Southeast Core Stairs	20	SF	7	\$0	
	Floor - Terrazzo	Southeast Core Stairs	20	SF	6	\$198	
	Handrails	Southeast Core Stairs	38	LF	6	\$329	
	Handrails	Southeast Core Stairs	69	LF	7	\$0	
	Lighting - Lay-in	Southeast Core Stairs	3	EA	7	\$0	
	Stairs - Terrazzo	Southeast Core Stairs	160	LF	7	\$0	
	Walls - Masonry	Southeast Core Stairs	994	SF	7	\$0	



Building: Linked Addition-Athletic Building B

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Splined	Southwest Stairs - Core Stairs	187	SF	6	\$540	
	Floor - Terrazzo	Southwest Stairs - Core Stairs	40	SF	7	\$0	
	Handrails	Southwest Stairs - Core Stairs	69	LF	7	\$0	
	Handrails	Southwest Stairs - Core Stairs	38	LF	6	\$329	
	Lighting - Lay-in	Southwest Stairs - Core Stairs	3	EA	7	\$0	
	Stairs - Terrazzo	Southwest Stairs - Core Stairs	160	LF	7	\$0	
	Walls - Masonry	Southwest Stairs - Core Stairs	994	SF	7	\$0	
	Handrails	Stair #15 in 525	30	LF	7	\$0	
	Stairs	Stair #15 in 525	40	LF	7	\$0	Steel spiral stair
	Handrails	Stair #16 in 503 backstage	30	LF	7	\$0	
	Stairs	Stair #16 in 503 backstage	40	LF	7	\$0	steel spiral stair
	Ceiling - Plaster/Drywall	West Locker Stairs	6	SF	5	\$88	
	Ceiling - Splined	West Locker Stairs	193	SF	6	\$557	
	Ceiling - Splined	West Locker Stairs	6	SF	4	\$103	
	Floor - Concrete Epoxy/ Painted	West Locker Stairs	35	SF	7	\$0	
	Floor - Terrazzo	West Locker Stairs	36	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	West Locker Stairs	5	SF	6	\$50	
	Floor - Tile Ceramic/ Porcelain	West Locker Stairs	146	SF	7	\$0	
	Floor - Tile/Sheet	West Locker Stairs	50	SF	6	\$27	
	Handrails	West Locker Stairs	70	LF	6	\$607	
	Lighting - Lay-in	West Locker Stairs	2	EA	7	\$0	
	Lighting - Pendent/Surface	West Locker Stairs	1	EA	6	\$124	
	Stairs - Terrazzo	West Locker Stairs	128	LF	7	\$0	
	Walls - Masonry	West Locker Stairs	1,334	SF	7	\$0	
	Ceiling - Lay-in	West Pool Stairs	242	SF	7	\$0	
	Floor - Concrete	West Pool Stairs	70	SF	6	\$37	
	Floor - Tile/Sheet	West Pool Stairs	22	SF	7	\$0	
	Handrails	West Pool Stairs	69	LF	7	\$0	
	Handrails	West Pool Stairs	3	LF	6	\$26	
	Lighting - Wall Mounted	West Pool Stairs	2	EA	7	\$0	
	Stairs - Concrete	West Pool Stairs	116	LF	6	\$962	
	Stairs - Tile	West Pool Stairs	17	LF	7	\$0	
	Walls - Masonry	West Pool Stairs	1,135	SF	7	\$0	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator		1	EA	6	\$19,238	



\$2,811

\$505

9 EA

1 EA

6 5 4959 S Archer Ave Chicago, IL 60632

Building: Linked Addition-Athletic Building B

real Building Cost Fe regory: Site up Item - Type etic Surface - Asphalt Surface - Asphalt Surface - Natural Surface - Natural //Drainage Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain Civil/ Drainage - Site Manhole cting Fencing - Chain Link Fencing - Chain Link Fencing - Chain Link Fencing - Stendard Ornamental dscape Benches Benches Irrigation Landscape - Grass	Location	Quantity	Unit	Rank	Cost	Comments
uilding Interior Subtotal:					\$329,586	
otal Building Cost				\$1 ⁻	1,456,642	
ITE						
	Location	Quantity	Unit	Rank	Cost	Comments
hletic						
Surface - Asphalt	East	29,484	SF	5	\$134,497	
Surface - Asphalt	Northeast	7,300	SF	5	\$33,300	hoops are missing from backboards
Surface - Natural	Northeast	63,852	SF	5	\$96,787	
Surface - Natural	Northeast	57,150	SF	5	\$86,628	
vil/Drainage						
Civil/ Drainage - Catch Basin	Entire Site	21	EA	7	\$0	
Civil/ Drainage - Site Drain	Entire Site / Site South	5	EA	6	\$1,551	
Civil/ Drainage - Site Manhole	Entire Site	18	EA	7	\$0	
encing						
Fencing - Chain Link	Entire Site	1,794	LF	6	\$33,684	grassfields
Fencing - Chain Link	Entire Site	3,639	LF	4	\$334,082	bent, corroded, missing chain link
Fencing - Guard Rail	Entire Site	209	LF	7	\$0	
Fencing - New Standard Ornamental	Entire Site	1,389	LF	5	\$197,793	corroded
andscape						
Benches	Entire Site	4	EA	4	\$11,304	baseball field- wood is rotting
Benches	Entire Site	24	EA	6	\$10,321	
Irrigation	Entire Site / North East	63,852	SF	7	\$0	
Landscape - Grass	Entire Site	205,413	SF	7	\$0	
Landscape - Hardscape- Concrete	Entire Site	41,968	SF	6	\$216,651	
Landscape - Hardscape- Concrete	Entire Site	3,215	SF	4	\$68,456	cracked, broken, spalled
Parkway trees	Entire Site	1	EA	4	\$2,624	on Pulaski- stump
Parkway trees	Entire Site	29	EA	7	\$0	
Planting Beds/ Area	Entire Site	4,896	SF	7	\$0	
Retaining Wall - Concrete	Entire Site / Site South	100	SF	4		cracked, broken
Retaining Wall - Concrete	Entire Site / Site South	1,015	SF	6	\$23,789	

Trash Receptacles

Trash Receptacles

Entire Site

Entire Site / North West



-

\$31,626,365

4959 S Archer Ave Chicago, IL 60632

SITE

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Parking	Lot						
	Concrete Curbs	Entire Site	2,777	LF	6	\$35,661	
	Interior Plantings	Entire Site	8	LF	7	\$0	
	Surface - Asphalt	Entire Site	143,641	SF	5	\$655,247	faded striping
	Surface - Concrete	Entire Site / Loading Dock	300	SF	4	\$6,388	spalled, broken
	Surface - Concrete	Entire Site / Site South	16,942	SF	6	\$40,944	
Service	Garage						
	Service Garage - Free-Standing	Southeast	1,500	SF	4	\$41,806	per engineer: water infiltration at roof and/or drain
Sidewal	ks						
	Sidewalks - Perimeter Sidewalks	Entire Site	400	SF	4	\$6,435	cracked
	Sidewalks - Perimeter Sidewalks	Entire Site	550	SF	5	\$5,254	
	Sidewalks - Perimeter Sidewalks	Entire Site	24,452	SF	6	\$48,603	
ignage							
	Flag Pole - Flag Pole	Entire Site / Main Entrance	1	EA	6	\$1,657	alon Archer Ave.
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site / Site West	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	Entire Site / South West	2	EA	6	\$0	
Site S	ubtotal:				\$2	2,110,609	
Total S	Site Cost				\$	2,110,609	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report;

by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

Campus Total ^{2 3}

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.



- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Building A							ļ					ļ	I	1
Computer Lab	Laboratory/Shop		143 Web Desigr	143	2,052	1	39	52	0	0	40	Ν	Y	Ν
Computer Lab	Other Instructional Use		145	146	1,092	0	2	42	0	0	40	Ν	Y	Ν
Computer Lab	Computer Lab		148 DigitalDsgn	148	2,772	1	46	120	0	0	40	N	Y	Ν
Computer Lab	Other Instructional Use		162	162	1,234	1	33	106	104	0	40	Ν	N	Ν
Computer Lab	Other Instructional Use		165 TV Studio	165	1,641	2	38	86	0	0	40	Ν	Y	Ν
Computer Lab	Computer Lab		235E	235E	951	0	30	92	0	0	40	Ν	Y	Ν
Computer Lab		2nd Floor	261	261	1,170	0	33	74	264	0	40	Ν	Y	Ν
Computer Lab	Other Instructional Use	2nd Floor	270	270	1,500	0	31	70	312	0		Ν	Y	Ν
Computer Lab	Computer Lab		332	332	1,326	0	30	68	168	0	40	Ν	Ν	Ν
Computer Lab	Computer Lab		336	336	1,020	1	30	78	0	0	40	Ν	Ν	Ν
Computer Lab	Computer Lab		337	337	960	1	25	50	0	0	40	N	N	Ν
Computer Lab	Computer Lab		338	338	986	0	43	92	0	0	40	Ν	N	Ν
Computer Lab	Computer Lab		339	339	686	0	39	50	0	0	40	N	N	Ν
Computer Lab	Computer Lab		341	341	850	0	15	42	0	0	40	N	Y	Y
Computer Lab	Computer Lab		343	343	1,496	0	12	40	0	0	40	N	Y	Ν
Computer Lab	Regular Classroom		369	369	960	1	25	60	240	0	40	N	N	Ν
Computer Lab	Regular Classroom		380	380	900	1	6	24	144	0	40	N	N	Ν
Health	Other Instructional Use		167	167	954	1	4	14	130	0	40	N	N	Ν
Health	Other Instructional Use		168	168	974	1	4	14	130	0	40	N	Y	Ν
Laboratory/Shop	Laboratory/Shop		150 Photograph	150	965	0	3	18	0	0	40	N	Y	Ν
Laboratory/Shop	Laboratory/Shop		151 Dark Rm	151	461	0	0	16	0	0	40	N	N	Ν
Laboratory/Shop	Other Instructional Use		152 Comp/Elec	152/153	1,451	2	50	104	0	0	40	N	Y	Ν
Laboratory/Shop	Laboratory/Shop		63 Woodworkin	163	2,914	0	0	62	117	0	40	Ν	Y	Ν
Laboratory/Shop	Laboratory/Shop		166 Automotive	166	4,937	1	2	68	195	0	40	N	Y	Ν
Laboratory/Shop	Regular Classroom		381	381	2,000	1	2	25	165	0	40	N	Ν	Ν
Laboratory/Shop	Other Instructional Use	3rd Floor	381B	NA	279	1	1	2	72	0	40	Ν	Ν	Ν
Other Instructional Use	Computer Lab		336A	336A	1,521	1	26	56	0	0	40	Ν	Y	Ν
Regular Classroom	Laboratory/Shop		144 Elect Lab	144 (partial)	1,225	1	4	24	0	0	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		146	147	632	1	4	14	0	0	40	N	Y	Ν
Regular Classroom	Regular Classroom		147	145	793	1	2	16	0	0	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		232	232	750	1	3	8	168	0	40	N	Ν	N
Regular Classroom	Regular Classroom		233	233	1,140	1	3	12	147	0	40	N	Ν	N
Regular Classroom	Regular Classroom		241	241	1,384	0	1	10	0	0	40	N	Ν	N
Regular Classroom	Regular Classroom		243	243	738	0	3	12	216	0	40	N	Ν	N
Regular Classroom	Regular Classroom		244	244	738	0	4	16	120	0	40	N	Ν	N
Regular Classroom	Regular Classroom		245	245	738	0	4	14	120	0	40	N	Ν	N
Regular Classroom	Regular Classroom		248	248	738	0	4	14	120	0	40	N	N	N



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Building A					1	1	1			ļ	-	ļ		
Regular Classroom	Regular Classroom		249	249	738	0	4	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		250	250	400	1	4	20	0	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		252	252	400	0	2	8	0	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		253	253	738	0	4	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		254	254	738	0	4	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		255	255	600	0	2	16	0	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		257	257	738	0	4	16	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		258	258	738	0	4	16	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		259	259	600	0	3	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		260	260	738	0	11	12	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		262	262	738	0	3	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		263	263	738	1	4	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		264	264	738	1	4	14	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		265	265	738	1	4	14	120	0	0	Ν	N	Ν
Regular Classroom	Regular Classroom		266	266	738	0	4	16	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		267	267	738	0	3	14	120	0	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		268	268	738	0	3	12	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		269	269	738	1	3	16	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		271	271	738	1	4	18	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		272	272	600	1	2	16	300	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		274	274	738	0	4	10	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		275	275	738	0	2	8	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		277	277	687	1	4	16	320	0	40	N	N	Ν
Regular Classroom	Regular Classroom		279	279	738	10	4	10	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		280	280	738	0	6	10	120	0	40	N	N	Ν
Regular Classroom	Regular Classroom		282	282	687	1	4	6	0	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		284	284	738	0	3	12	120	0	40	N	N	Ν
Regular Classroom	Regular Classroom		285	285	738	1	3	10	120	0	40	N	N	Ν
Regular Classroom	Regular Classroom		286	286	687	0	3	8	87	0	40	N	Y	Ν
Regular Classroom			287	287	687	0	3	8	87	0	40	Ν	Y	Ν
Regular Classroom	Regular Classroom		288	288	738	1	3	8	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		289	289	696	1	2	6	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		290	290	738	0	2	8	216	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		334/335	334	3,148	1	0	12	0	0	40	Ν	Y	Ν
Regular Classroom	Other Instructional Use		335A	335A	836	0	6	24	0	0	40	Ν	Y	Ν
Regular Classroom	Science Lab Level 2		347	357	600	0	3	18	210	0	40	Ν	N	Ν
Regular Classroom	Science Lab Level 2		351	351	821	0	6	14	120	0	40	Ν	Ν	Ν



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Building A	ļ										1			1
Regular Classroom			362	362	500	0	5	20	96	0		Ν	Ν	Ν
Regular Classroom	Regular Classroom		364	364	750	1	4	56	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		365	365	725	1	4	16	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		366	366	750	0	6	40	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		367	367	750	1	6	40	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		368	368	750	1	6	30	120	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		371	371	960	1	2	8	103	0	40	Ν	N	Ν
Regular Classroom	Store Room		373	373	400	1	2	46	0	0	40	Ν	N	Ν
Regular Classroom	Regular Classroom		374	374	696	1	4	14	120	0	40	Ν	Ν	Ν
Regular Classroom	Computer Lab		375	375	722	2	26	60	0	0	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		377	377	696	1	2	8	120	0	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		378	378	725	1	2	12	120	0	40	Ν	Ν	Ν
Regular Classroom	Regular Classroom		379	379	580	1	2	18	0	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		340	340	1,250	1	40	70	0	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		346	346	1,516	0	13	40	168	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		349	349	1,234	0	2	32	120	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		350	350	986	0	2	26	120	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		353	353	950	1	2	30	120	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		354	354	1,187	0	3	37	126	0	40	Ν	N	Ν
Science Lab Level 2	Regular Classroom		360	360	900	0	4	32	144	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		361	361	900	0	3	34	144	0	40	Ν	N	Ν
Science Lab Level 2	Science Lab Level 2		363	363	900	1	4	32	144	0	40	Ν	Y	Ν
Science Lab Level 3	Science Lab Level 3		355	355	1,931	1	6	16	120	0	40	Ν	N	Ν
Science Lab Level 3	Regular Classroom		383	383	986	1	26	66	240	0	40	Ν	Y	Ν
Special Education	Special Education		370	370	350	1	3	12	72	0	40	Ν	N	Ν
Special Program	Special Program		159	159	1,627	1	6	26	166	0	40	N	Y	Ν
Special Program	Other Instructional Use		160	160	1,434	2	11	28	156	0	40	Ν	N	Ν
Special Program	Other Instructional Use		161	161	1,453	0	4	16	156	0	40	Ν	Y	Ν
Store Room	Laboratory/Shop		164 Metal	164	2,817	0	1	42	104	0	40	Ν	Ν	Ν
Linked Addition-	Athletic Building B													
Art Room	Art Room	2nd Floor	619	619	1,125	1	19	50	400	0		Ν	Y	Ν
Art Room	Art Room	2nd Floor	621	621	828	1	7	18	276	0		N	N	N
Art Room	Art Room	2nd Floor	627	627	2,282	0	22	70	252	0		N	N	N
Art Room	Art Room	2nd Floor	629	629	1,125	1	1	24	400	0		N	Y	N
Band Room	Band Room	1st Floor	510	510	2,220	0	0	6	0	0		N	N	N
Band Room	Band Room	1st Floor	514	514	2,440	0	0	8	0	0		N	N	N



Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Linked Addition-A	thletic Building B												•	
Dance Room	Dance Room	1st Floor	508 Quin Hall	508	2,910				0	0		N	Ν	Ν
Health			643		773	3	2	8	0	0	40	Ν	Ν	N
Laboratory/Shop	Laboratory/Shop	1st Floor	525	525	2,340	0	0	12	0	0		Ν	Ν	N
Music Room	Music Room	2nd Floor	612	612	820	1	2	16	100	0		Ν	Y	N
Music Room	Music Room	2nd Floor	613	613	683	1	21	78	150	0		Ν	Y	N
Music Room	Music Room	2nd Floor	616	616	1,765	1	2	48	25	0		Ν	Ν	N
Regular Classroom			639		780	3	2	8	0	0	40	Ν	Ν	Ν
Weight			544		2,876	0	1	10	0	0	40	Ν	Ν	Ν