

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1911	3	61,724
Addition 2	1999	3	70,296
Addition-Gymnasium	1992	1	5,637
Addition-Lunchroom/Kitchen	1999	1	9,359
Campus Total			147,016

- ·· ··

....

Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	N/A	2	EA	7	10+ years	
Entrance	2						
	Exterior Doors - Exterior FRP Door	Entrance 16-South	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 16-South	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 16-South	12	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 6-West / Assembly Hall Vestibule	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 6-West / Assembly Hall Vestibule	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 6-West / Assembly Hall Vestibule	140	LF	5	2-5 years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 6-West / Assembly Hall Vestibule	120	LF	6	10+ years	
	Ramps - Concrete	Entrance 6-West / Assembly Hall Vestibule	60	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 6-West / Assembly Hall Vestibule	30	LF	4	1-2 years	Rust/Corrosion/Corroded - Detached/broken from itself
	Exterior Doors - Exterior FRP Door	Entrance 7-NW	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 7-NW	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 7-NW	37	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main	2110	W Greenieal AVENUE, Chicago, IL 60045
outogo				unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	Entrance 7-NW	3	LF	5	0-1 year	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 7-NW	20	LF	6	10+ years	
	Ramps - Concrete	Entrance 7-NW	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 7-NW	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Entrance 8-North	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 8-North	4	EA	6	10+ years	
_Foundat	on						
	Foundation - Masonry	Entire Building	500	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	61,724	SF	7	10+ years	
Lighting							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	11	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
_Roof Svs	stem						
	Coping - Metal	Roof 3	110	LF	7	10+ years	
	Coping - Stone	Roof 3	425	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	330	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	110	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 3	70	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	465	LF	7	10+ years	
	Roof - Metal	Roof 3	750	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 3	13,145	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 3	200	SF	7	10+ years	
	Concrete Topping		200	01	,	ior youro	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	13,695	SF	7	10+ years	
	Access Ladder - Metal	Roof 4	2	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	52	LF	6	6-10 years	Quantity Adjusted
	Liner		02		Ũ	o ro youro	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4	28	LF	5	2-5 years	
	Coping - Stone	Roof 4	265	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	250	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	265	LF	6	10+ years	
	Roof - Metal	Roof 4	300	SF	4	0-1 year	Rust/Corrosion - Open Joints
	Roof - Modified Bitumen	Roof 4	15,370	SF	4 7	10+ years	Ruse contosion - Open Joints
	Roof Hatch - Metal	Roof 4	2	EA	3	1-2 years	The north hatch is Aged/Worned/Bent
			2	EA	3	I-2 years	- Does not Latch Properly. The south hatch is Aged/Worned/Bent - Does not Latch Properly.
	Roof Structure - Steel with Clay Tile Arch	Roof 4	15,670	SF	7	10+ years	····



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls							
	Canopy - Concrete/ Stucco	Entire Building	1,000	SF	6	10+ years	Metal
	Cheek-Wall - Concrete	Entire Building	240	SF	5	10+ years	
	Cheek-Wall - Stone	Entire Building	200	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	580	LF	4	0-1 year	Deteriorating- Peeling Paint/Rust/Corrosion with open Seams/Joints
	Exterior Walls - Brick	Entire Building	30,371	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	3,385	SF	4	1-2 years	Cracks/Deteriorated Mortar Joints- Open Masonry Joints inside and outside at Parapet walls
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	756	SF	7	10+ years	None Found - Previous Assessment shows the RTU's side panel
	Exterior Walls - Stone-Cast	Entire Building	2,994	SF	6	10+ years	
Windows	3						
	Curtain wall - Insulated Panel	Entire Building	765	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	1,820	SF	6	10+ years	
	Lintels - Steel	Entire Building	805	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	191	SF	6	10+ years	
	Windows - Sash Lexan	Entire Building	6,615	SF	6	10+ years	
	Lintels - Steel	North Facade - Courtyard	3	LF	4	0-1 year	Lintel not Present/Missing. At Minimum, weight of Brick/Structural integrity at risk!

Category : Electrical			В	uilding				
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System							
Ū.	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Deteriorated, old	
	Security System - CCTV	Entire Building	61,724	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	61,724	SF	6	6-10 years		
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,393	SF	6	6-10 years		
	Emergency A/C Power - Multipurpose Room	Entire Building	6,067	SF	6	6-10 years		
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	4	2-5 years	Old, deteriorated	
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	2	0-1 year	No battery pack, no AC generator	
	Exit Signs - Multipurpose Room	Entire Building	8	EA	2	0-1 year	No batteries, no AC generator	

Main Service



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves main and gym building
	Independent Electrical Service for emergency power	Electrical Room	1	EA	4	2-5 years	Using old ATS
	PA System	Entire Building	61,724	SF	6	6-10 years	Connected to other buildings on campus
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	1-2 years	Deteriorated with missing circuit
	Lighting and Power Panels - Above 100 A	Entire Building	1			2	breakers Serviced, functional
			•	EA EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1		7	10+ years	Serviced, functional
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar			-				
	Fire Alarm Strobe Lights	Entire Building	61,724	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	61,724	SF	5	6-10 years	Updated panel in 1999
Catego	ry : Mechanical		В	uilding	: Main		
outogo			_	anang	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves old gym area
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted roof air intakes
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	5	10+ years	Painted
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	5	10+ years	Painted duct work
	Zone Dampers	Mechanical Room	20	EA	5	6-10 years	Some are manually operated
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	6	10+ years	Serves north side of building
	Steam Coils - 15001 - 25000 cfm			L /\	0	ioi youio	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted roof air intakes. Metal is good
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	10+ years	-
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	Painted duct work
	Zone Dampers	Mechanical Room	24	EA	5	10+ years	Some are manually operated
oiler Sy	vstems						
-	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	Recently lubricated
	Condensate Pump	Boiler Room	3	EA	5	6-10 years	Serve 3 air handlers
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	There are a few pipe clamps
	Steam Traps	Boiler Room	16	EA	5	6-10 years	
leating	Devices						
	Radiators - Steam	1st Floor	2	EA	4	2-5 years	Deteriorated, not painted
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	•
	Wall Heater - Electric	Entire Building	6	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Recently serviced
empera	ture Control						
	Electric Thermostat	Entire Building	1	EA	4	0-1 year	Damaged, serves gas unit heater in boiler room
	Pneumatic System	Entire Building	61,724	SF	5	6-10 years	Serves main building. Has some leaks
	Thermostats - Pneumatic	Entire Building	45	EA	5	6-10 years	Not calibrated
entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	3	EA	5	6-10 years	
atego	ry : Plumbing		В	uilding	: Main		
broup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
lot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	4	2-5 years	Serves main building, functional,



Catego	ry : Plumbing		В	uilding	: Main		
Ŭ	<i>,</i> , , , , , , , , , , , , , , , , , ,			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							scheduled for replacement
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	6	6-10 years	Serves main building, east side
					·		g,
Piping							
-10	Domestic Piping-Hot Water Return Lines	Entire Building	61,724	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot Water Return Risers	Entire Building	61,724	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	61,724	SF	6	6-10 years	
	Fixtures	5	,			,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	61,724	SF	6	6-10 years	There are a few pipe clamps
	(Horizontal Lines)	C C				•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	61,724	SF	6	6-10 years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	61,724	SF	6	6-10 years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	61,724	SF	6	6-10 years	
	Storm Piping	Entire Building	61,724	SF	6	6-10 years	
	Vent Piping	Entire Building	61,724	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	6-10 years	Functional, repacked/resealed pump
	Pumps - Sump-Simplex	Mechanical Room	1	EA	5	6-10 years	
Catego	ry : Room		В	uilding	: Main		
	· · · · · · · · · · · · · · · · · · ·		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	102 A Office	98	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 A Office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	102 A Office	98	SF	7	10+ years	
	Lighting - Pendent/Surface	102 A Office	1	ĒA	7	6-10 years	
	Power Distribution	102 A Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	102 A Office	186	SF	7	10+ years	
	Ceiling - Lay-in	106 Office	470	SF	7	10+ years	
	Doors - Side-lite	106 Office	470	SF	7		
				OF		10+ years	
						10, 100000	
	Doors - Wood Doors inclu hw	106 Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw Floor - Tile			EA SF		10+ years	Observed clean floor. Rank change to update current observation.
	Doors - Wood Doors inclu hw	106 Office	1	EA	7	•	•
	Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	106 Office 106 Office	1 470 8	EA SF	7 7 7	10+ years 6-10 years	
	Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution	106 Office 106 Office 106 Office 106 Office	1 470 8 12	EA SF EA EA	7 7 7 7	10+ years 6-10 years 10+ years	
	Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution Walls - Plaster/Drywall	106 Office 106 Office 106 Office 106 Office 106 Office	1 470 8 12 700	EA SF EA EA SF	7 7 7 7 7	10+ years 6-10 years 10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Power Distribution	106 Office 106 Office 106 Office 106 Office	1 470 8 12	EA SF EA EA	7 7 7 7	10+ years 6-10 years 10+ years	Observed clean floor. Rank changed to update current observation. Observed clean ceiling. Rank



Catego	ry : Room		В	uilding	: Main			
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
							observation.	
	Doors - Transom Window	211 ADJ Room	10	SF	6	10+ years		
	Doors - Wood Doors inclu hw	211 ADJ Room	1	EA	6	10+ years		
	Floor - Tile	211 ADJ Room	415	SF	7	10+ years	Observed clean floor. Rank change	
							to update current observation.	
	Lighting - Lay-in	211 ADJ Room	6	EA	6	6-10 years		
	Power Distribution	211 ADJ Room	8	EA	7	10+ years		
	Walls - Plaster/Drywall	211 ADJ Room	930	SF	7	10+ years	Observed painted walls. Rank	
							changed to update current	
							observation.	
	AC Unit	99 Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	99 Office	490	SF	7	10+ years	Observed clean ceiling. Rank	
							changed to update current	
							observation.	
	Doors - Transom Window	99 Office	80	SF	6	10+ years		
	Doors - Wood Doors inclu hw	99 Office	1	EA	6	10+ years		
	Floor - Tile	99 Office	490	SF	7	10+ years	Observed clean floor. Rank change	
							to update current observation.	
	Lighting - Lay-in	99 Office	9	EA	6	6-10 years		
	Power Distribution	99 Office	12	EA	7	10+ years		
	Storage/ Closet	99 Office	20	SF	7	10+ years		
	Walls - Plaster/Drywall	99 Office	730	SF	7	10+ years	Observed painted walls. Rank	
							changed to update current	
							observation.	
	AC Unit	99-1 Conference	1	EA	7	6-10 years		
	Ceiling - Lay-in	99-1 Conference	187	SF	7	10+ years	Observed clean ceiling. Rank	
							changed to update current	
							observation.	
	Doors - Transom Window	99-1 Conference	70	SF	6	10+ years		
	Doors - Wood Doors inclu hw	99-1 Conference	1	EA	6	10+ years		
	Floor - Tile	99-1 Conference	187	SF	6	10+ years		
	Lighting - Lay-in	99-1 Conference	3	EA	6	6-10 years		
	Power Distribution	99-1 Conference	8	EA	7	10+ years		
	Walls - Plaster/Drywall	99-1 Conference	355	SF	7	10+ years	Observed painted walls. Rank	
	-					-	changed to update current	
							observation.	
	AC Unit	Assistant Engineer's Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Assistant Engineer's Office	167	SF	7	10+ years	Observed painted ceiling. Rank	
							changed to update current	
							observation.	
	Doors - Wood Doors inclu hw	Assistant Engineer's Office	1	EA	6	10+ years		
	Floor - Tile	Assistant Engineer's Office	167	SF	6	10+ years		
	Lighting - Pendent/Surface	Assistant Engineer's Office	3	EA	7	6-10 years		
	Lighting - Pendent/Sunace	Assistant Engineer's Office	•			0.0,00.0		



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Assistant Engineer's Office	317	SF	7	10+ years	
	Ceiling - Exposed	Custodian Office	190	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Custodian Office	1	EA	7	10+ years	NA Door removed
	Floor - Concrete	Custodian Office	190	SF	7	10+ years	
	Lighting - Pendent/Surface	Custodian Office	2	EA	6	6-10 years	
	Power Distribution	Custodian Office	6	EA	7	10+ years	
	Walls - Masonry	Custodian Office	361	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	179	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation.
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	179	SF	7	10+ years	Observed clean floor. Rank changed to update current observation
	Lighting - Pendent/Surface	Engineer's Office	1	EA	6	6-10 years	
	Power Distribution	Engineer's Office	4	EA	7	10+ years	
	Storage/ Closet	Engineer's Office	30	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	650	SF	7	10+ years	
	Work SInk	Engineer's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	P.E Office	127	SF	7	10+ years	
	Doors - Wood Doors inclu hw	P.E Office	1	EA	6	10+ years	
	Floor - Tile	P.E Office	127	SF	6	10+ years	
	Lighting - Pendent/Surface	P.E Office	3	EA	7	6-10 years	
	Power Distribution	P.E Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	P.E Office	241	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Gymnasi							
	Ceiling - Lay-in	1st Floor	2,890	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,033	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	7	10+ years	
	Floor - Wood	1st Floor	6,067	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Main Floor Seating	1st Floor	425	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	420	SF	6	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Masonry	1st Floor	3,164	SF	6	10+ years	Ptd
/lechani	cal/ Service Rooms						
		det Eleen	4 050	0	7	10	
	Air Intake Plenums	1st Floor	1,250	SF	7 7	10+ years	



	bry : Room		R	uilding	: Main	2110	J W Greenlear AVENUE, Chicago, IL 60645		
Gulogo	.,		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Boiler Room	1st Floor	1,511	SF	7	10+ years			
	Coal Room	1st Floor	276	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	2,150	SF	7	10+ years			
	Storage Room	1st Floor	70	SF	7	10+ years	Caged Storage Area		
	Storage Room	1st Floor	205	SF	7	10+ years			
	Janitor's Closet	2nd Floor	20	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	Per Bldg Engineer & plans- A Mech/		
				0.	·	lot youro	Service Room does not exist on Floor 2		
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	-		
	Mechanical/ Service Rooms	3rd Floor	50	SF	7	10+ years	Door removed at location per plan,		
				01	,	Tor youro	mech space not accessible		
Restroo	m								
	Accessories	1st Floor Boy's Room	467	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Boy's Room	467	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor Boy's Room	5	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Boy's Room	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Boy's Room	467	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.		
	Floor Drain	1st Floor Boy's Room	1	EA	7	10+ years	•		
	Hand Dryer	1st Floor Boy's Room	2	EA	7	10+ years			
	Lavatory	1st Floor Boy's Room	2	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor Boy's Room	4	EA	6	6-10 years			
	Partitions	1st Floor Boy's Room	2	EA	7	10+ years			
	Urinals	1st Floor Boy's Room	5	EA	7	10+ years			
	Walls - Masonry	1st Floor Boy's Room	530	SF	7	10+ years	No visible mortar cracks observed. Rank changed to update current observation.		
	Walls - Masonry	1st Floor Boy's Room	2	SF	6	1-2 years			
	Walls - Plaster/Drywall	1st Floor Boy's Room	512	SF	7	10+ years	Observed painted walls. Rank		
	Walls Thatal by Wall		012	01	,	Tor years	changed to update current observation.		
	Walls - Plaster/Drywall	1st Floor Boy's Room	20	SF	6	2-5 years	Damaged wall		
	Water Closet	1st Floor Boy's Room	2	EA	7	10+ years	Observed flush valves functioning		
						- ,	and properly working. Rank changed to update current observation.		
	Accessories	1st Floor Girl's Room	468	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Girl's Room	428	SF	7	10+ years	Observed painted ceiling. Rank changed to update current observation		
	Ceiling - Plaster/Drywall	1st Floor Girl's Room	40	SF	6	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor Girl's Room	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's Room	468	SF	6	10+ years			
			400	5	0	ioi youio			



	bry : Room		В	uilding	: Main	2110	W Greenieal AVENUE, Chicago, il 60045
Juigo	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor Girl's Room	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girl's Room	2	EA	7	10+ years	
	Lavatory	1st Floor Girl's Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girl's Room	4	EA	7	6-10 years	Observed fixtures functioning and
							properly working. Rank changed to update current observation.
	Partitions	1st Floor Girl's Room	7	EA	7	10+ years	
	Walls - Masonry	1st Floor Girl's Room	532	SF	7	10+ years	No visible mortar cracks observed.
						-)	Rank changed to update current observation.
	Walls - Plaster/Drywall	1st Floor Girl's Room	512	SF	7	10+ years	Observed painted walls. Rank
	,					,	changed to update current observation.
	Walls - Plaster/Drywall	1st Floor Girl's Room	20	SF	6	2-5 years	
	Water Closet	1st Floor Girl's Room	7	EA	7	10+ years	
	Accessories	2nd Floor	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	5	1-2 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	50	SF	7	10+ years	
	Lavatory	2nd Floor	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	285	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor Boy's Room	467	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boy's Room	467	SF	7	10+ years	Observed painted ceiling. Rank
				0.	•	lot youro	changed to update current observation.
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boy's Room	467	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boy's Room	3	SF	5	1-2 years	Metal Sill/ threshold loose
	Floor Drain	2nd Floor Boy's Room	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Boy's Room	2	EA	7	10+ years	
	Lavatory	2nd Floor Boy's Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boy's Room	4	EA	7	6-10 years	
	Partitions	2nd Floor Boy's Room	2	EA	7	10+ years	
	Urinals	2nd Floor Boy's Room	5	EA	7	10+ years	
	Walls - Masonry	2nd Floor Boy's Room	532	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Boy's Room	532	SF	7	10+ years	
	Water Closet	2nd Floor Boy's Room	2	EA	7	10+ years	Observed flush valves functioning
	Water Closet		2	LA	,	TO+ years	and properly working. Rank changed
							to update current observation.
	Accessories	2nd Floor Girl's Room	468	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's Room	468	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girl's Room	468	SF	7	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor Drain 2nd Floor Girl's Room EΑ 10+ vears 7 1 2 ΕA 7 Hand Drver 2nd Floor Girl's Room 10+ years Lavatorv 2nd Floor Girl's Room 2 FΑ 7 10+ years Lighting - Pendent/Surface ΕA 7 2nd Floor Girl's Room 4 6-10 years Observed fixtures functioning and properly working. Rank changed to update current observation. Partitions 2nd Floor Girl's Room 7 ΕA 7 10+ years SF Walls - Masonry 2nd Floor Girl's Room 532 7 10+ years SF Walls - Plaster/Drvwall 2nd Floor Girl's Room 532 7 10+ years Water Closet 2nd Floor Girl's Room 7 EΑ 7 10+ vears Accessories 3rd Floor 50 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor 50 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 6 3rd Floor 1 10+ years 7 SF Floor - Tile Ceramic/ Porcelain 3rd Floor 50 10+ years ΕA 7 Lavatorv 3rd Floor 1 10+ years Lighting - Pendent/Surface 7 3rd Floor 1 FΑ 6-10 years 7 Partitions 3rd Floor 1 EΑ 10+ vears Walls - Plaster/Drywall 3rd Floor 285 SF 6 10+ years Water Closet 3rd Floor EΑ 7 6-10 years 1 Accessories 3rd Floor Boy's Room 467 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor Boy's Room 467 SF 7 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 3rd Floor Boy's Room 467 10+ years 7 Floor Drain 3rd Floor Boy's Room 1 EA 10+ years 2 7 Hand Dryer 3rd Floor Boy's Room FΑ 10+ years 3rd Floor Boy's Room 2 EΑ 6 Lavatorv 10+ years Lighting - Pendent/Surface 3rd Floor Boy's Room 4 FΑ 6 6-10 years 2 7 Partitions 3rd Floor Boy's Room EΑ 10+ years 3rd Floor Boy's Room 5 ΕA 7 Urinals 10+ years SF Walls - Masonry 3rd Floor Boy's Room 532 6 10+ years Walls - Plaster/Drywall 3rd Floor Boy's Room 532 SF 6 10+ years Water Closet 3rd Floor Boy's Room 2 EΑ 7 10+ vears Accessories 3rd Floor Girl's Room 468 SF 7 6-10 years SF 7 Ceiling - Plaster/Drywall 3rd Floor Girl's Room 468 10+ years Floor - Tile Ceramic/ Porcelain 468 SF 7 3rd Floor Girl's Room 10+ years Floor Drain 7 3rd Floor Girl's Room 1 EΑ 10+ years ΕA 7 Hand Dryer 3rd Floor Girl's Room 2 6-10 years Lavatory 3rd Floor Girl's Room 2 EΑ 6 6-10 years Lighting - Pendent/Surface 7 3rd Floor Girl's Room 4 EA 6-10 years Partitions 3rd Floor Girl's Room 7 EΑ 7 6-10 years SF Walls - Masonrv 3rd Floor Girl's Room 532 7 10+ vears SF Walls - Plaster/Drywall 3rd Floor Girl's Room 532 7 10+ years FΑ 7 Water Closet 3rd Floor Girl's Room 7 10+ vears Accessories 99 Staff Unisex Toilet 37 SF 7 6-10 years SF Ceiling - Plaster/Drywall 99 Staff Unisex Toilet 37 6 10+ years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Doors - Wood Doors inclu hw 99 Staff Unisex Toilet EΑ 6 10+ vears 1 Floor - Tile 37 SF 6 99 Staff Unisex Toilet 10+ years Lavatorv 99 Staff Unisex Toilet 1 FΑ 7 10+ years Lighting - Pendent/Surface 1 ΕA 99 Staff Unisex Toilet 6 6-10 years SF 7 Walls - Plaster/Drywall 99 Staff Unisex Toilet 230 10+ years Observed painted walls. Rank changed to update current observation. SF Walls - Plaster/Drywall 99 Staff Unisex Toilet 40 5 1-2 years Damaged wall Water Closet 99 Staff Unisex Toilet 1 EΑ 6 10+ years SF Accessories First Floor - NA Does not exist 50 7 6-10 vears NA SF Ceiling - Plaster/Drvwall First Floor - NA Does not exist 50 6 10+ vears NA Doors - Wood Doors inclu hw First Floor - NA Does not exist 1 ΕA 6 10+ years NA Floor - Tile Ceramic/ Porcelain First Floor - NA Does not exist 50 SF 6 10+ years NA ΕA 6 Lavatory First Floor - NA Does not exist 1 10+ years NA Lighting - Pendent/Surface First Floor - NA Does not exist ΕA 6 1 6-10 years NA Walls - Plaster/Drywall First Floor - NA Does not exist 285 SF 7 10+ years NA ΕA 7 Water Closet First Floor - NA Does not exist 1 10+ vears NA First zscFloor Men's Staff in Boys SF Accessories 45 7 6-10 years Restroom SF Ceiling - Plaster/Drywall First zscFloor Men's Staff in Boys 45 7 10+ years Restroom Doors - Wood Doors inclu hw First zscFloor Men's Staff in Boys 1 EA 7 10+ years Restroom Floor - Tile Ceramic/ Porcelain First zscFloor Men's Staff in Boys SF 7 45 10+ years Restroom Lavatorv First zscFloor Men's Staff in Bovs 1 FΑ 7 10+ years Restroom Lighting - Pendent/Surface First zscFloor Men's Staff in Boys ΕA 1 7 10+ years Restroom Partitions First zscFloor Men's Staff in Boys ΕA 7 1 10+ years Restroom First zscFloor Men's Staff in Boys Walls - Plaster/Drvwall 187 SF 7 10+ vears Restroom Water Closet First zscFloor Men's Staff in Bovs FΑ 7 1 10+ years Restroom SF 7 Accessories In Boiler Room Area 6-10 years 16 Ceiling - Plaster/Drywall SF In Boiler Room Area 16 6 10+ years Doors - Wood Doors inclu hw In Boiler Room Area 1 ΕA 6 10+ years SF Floor - Concrete In Boiler Room Area 16 5 10+ years ΕA Lighting - Wall Mounted In Boiler Room Area 1 6 6-10 years Walls - Concrete Block In Boiler Room Area 145 SF 6 10+ years Water Closet FΑ 6 In Boiler Room Area 10+ vears 1 Accessories Unisex Toilet in room 105 46 SF 7 6-10 years SF Ceiling - Plaster/Drywall Unisex Toilet in room 105 46 6 10+ years



Building : Main Category : Room Recommend UOM Group Location Quantity Item - Type Rank Replacement Comments 10+ years Doors - Wood Doors inclu hw Unisex Toilet in room 105 ΕA 6 1 Floor - Terrazzo Unisex Toilet in room 105 46 SF 6 10+ years Not tile-terrazzo 10+ years Lavatory Unisex Toilet in room 105 1 ΕA 7 Lighting - Wall Mounted 6-10 years Unisex Toilet in room 105 1 ΕA 7 Walls - Plaster/Drywall SF Observed painted walls. Rank 7 Unisex Toilet in room 105 260 10+ years changed to update current observation. Walls - Plaster/Drywall Unisex Toilet in room 105 SF 20 6 2-5 years Water Closet Unisex Toilet in room 105 2 ΕA 7 10+ years

Category : Classroom

Building : Main

	No. 10	1	0			Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	915	SF	7	10+ years	Observed clean ceiling. Rank changed to update current observation.
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	915	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	Observed fixtures functioning and properly working. Rank changed t update current observation.
	Marker Board	1st Floor	8	LF	7	6-10 years	•
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	815	SF	7	10+ years	
	Chalk Board	1st Floor	50	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	815	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	815	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	815	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	
assroo	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	815	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	815	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	ĒA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	
assroo	m #104 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	6-10 years	Hardware to be fixed
	Floor - Wood	2nd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,240	SF	6	10+ years	
assroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	915	SF	7	10+ years	Observed clean ceiling. Rank changed to update current observation



2110 W	Greenleaf	AVENUE,	Chicago,	IL	60645

Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	915	SF	7	10+ years	Observed clean floor. Rank changed to update current observation
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	•
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	10+ years	
Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	415	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	50	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	415	SF	7	10+ years	Observed clean floor. Rank changed
				•	•	,jeure	to update current observation.
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	930	SF	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	815	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	וט טעטמוב כעוופווו טאצריאמוטוו.
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
Closero	om #202 (Regular Classroom)						
_0/255100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF			
					7	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	5	2-5 years	
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		W Greenleal AVENDE, Chicago, il 60645
ealege			_	anang	i inairi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	2nd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
Classro	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30		7		
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	815	SF	7	10+ years 10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7		
			10	EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor		SF		10+ years	Observed clean flear Deals changed
	Floor - Tile	2nd Floor	815	55	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	•
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,321	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classro	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LA	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
Closeror	om #205 (Regular Classroom)						
_01033100	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	30		7	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	30 815	SF	7	10+ years	
	Chalk Board	2nd Floor 2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	50 10	SF	4 7		
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	10	EA	7	10+ years	
	Floor - Wood Doors Inclu hw	2nd Floor 2nd Floor	815	SF	7	10+ years	
		2nd Floor 2nd Floor	12	EA	7	10+ years	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	12	LF	7	6-10 years	
			16	LF	1	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,145	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	75	SF	6	6-10 years	
Classroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	Observed clean ceiling. Rank
				_		-)	changed to update current observation.
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	815	SF	7	10+ years	Observed clean floor Rank changed to update current observation.
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	Observed painted walls. Rank changed to update current observation.
Classroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	Observed clean ceiling. Rank changed to update current observation.
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	815	SF	7	10+ years	Observed clean floor. Rank change to update current observation.
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	Observed clean ceiling. Rank changed to update current



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observation.
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
lassroc	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	815	SF	7	10+ years	Observed clean ceiling. Rank
	g,				-	,	changed to update current observation.
	Chalk Board	2nd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,220	SF	7	10+ years	
assroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	533	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	533	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	920	SF	7	10+ years	
assroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	417	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	



Catego	ry : Classroom		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	996	SF	7	10+ years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	815	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
	Walls - Flastel/Drywall	310 1001	1,220	SF	I	TO+ years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	

_Classroom #304 (Regular Classroom)



Catego	ory : Classroom		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	815	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	815	SF	6	6-10 years	
	Chalk Board	3rd Floor	50	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Wood	3rd Floor	815	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	16	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	40	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years			
lassroo	om #308 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	30	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	815	SF	7	10+ years			
	Chalk Board	3rd Floor	50	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	8	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	6	•			
	Floor - Wood	3rd Floor		SF	7	10+ years			
			815			10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years			
	Marker Board	3rd Floor	16	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	40	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	6	10+ years			
Classroo	om #309 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	30	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	815	SF	6	6-10 years			
	Chalk Board	3rd Floor	50	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years			
	Floor - Wood	3rd Floor	815	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years			
	Marker Board	3rd Floor	16	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	40	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years			
Classroo	om #310 (Regular Classroom)								
	Casework	3rd Floor	20	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	533	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	7	10+ years			
	Floor - Wood Doors Inclu flw	3rd Floor	533	SF					
					7	10+ years			
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years			
	Marker Board	3rd Floor	8	LF	7	6-10 years			
	Storage/ Closet Walls - Plaster/Drywall	3rd Floor	40	SF SF	7	10+ years			
		3rd Floor	920	UE .	7	10+ years			



George Armstrong International Studies ES

			2110 W Greenleaf AVENUE, Chicago, IL 60645 Building : Main					
Jatego	ry : Classroom							
~~~~~	Hom Type	Location	Quentitu	UOM	Rank	Recommend	Commente	
Broup	Item - Type	Location	Quantity	UOIVI	Rank	Replacement	Comments	
Jassroc	m #311 (Regular Classroom)			= .	-			
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	415	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	415	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	930	SF	7	10+ years		
atego	ry : Interior		В	uilding	• Main			
laioge			_	anang		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor	3,071	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years		
	Doors - Wood Doors include hw	1st Floor	12	EA	6	10+ years		
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor	3,071	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	Observed fixtures functioning and	
							properly working. Rank changed t	
							update current observation	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	Missing Lens	
	Lighting - Pendent/Surface	1st Floor	35	EA	7	6-10 years	Observed fixtures functioning and	
							properly working. Rank changed t	
							update current observation.	
	Walls - Plaster/Drywall	1st Floor	4,481	SF	7	10+ years	Observed painted walls. Rank	
							changed to update current	
							observation.	
	Ceiling - Lay-in	2nd Floor	3,071	SF	6	10+ years	lt's clean	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	Due to COVID, fountain closed of	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EA	5	1-2 years		
	Floor - Concrete Epoxy/ Painted	2nd Floor	3,071	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	29	EA	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	4,481	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	3,071	SF	5	6-10 years		
	Drinking Fountains - Single Fountain	3rd Floor	3,071	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	3rd Floor	3,071	SF	7	10+ years		
				UL UL				
	Lighting - Lay-in Walls - Plaster/Drywall	3rd Floor 3rd Floor	29 4,481	EA SF	6 7	6-10 years 10+ years		

<u>Safety</u>



ALL A						2110	W Greenleaf AVENUE, Chicago, IL 6064
Catego	ry : Interior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Camera Viewing Station	Entire Building	1	EA	7	10+ years	
	Security Cameras	Entire Building	10	EA	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	Stairwell # 1 (south)	321	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Stairwell # 1 (south)	590	SF	7	10+ years	
	Handrails	Stairwell # 1 (south)	180	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell # 1 (south)	6	EA	6	10+ years	
	Lighting - Wall Mounted	Stairwell # 1 (south)	2	EA	6	6-10 years	
	Stairs - Concrete	Stairwell # 1 (south)	60	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell # 1 (south)	2,052	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stairwell # 2 (north)	321	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Stairwell # 2 (north)	590	SF	7	10+ years	
	Handrails	Stairwell # 2 (north)	180	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell # 2 (north)	6	EA	6	6-10 years	
	Lighting - Wall Mounted	Stairwell # 2 (north)	2	EA	6	6-10 years	
	Stairs - Concrete	Stairwell # 2 (north)	60	LF	7	10+ years	
	Walls - Plaster/Drywall	Stairwell # 2 (north)	2,052	SF	7	10+ years	



Catego	Category : Exterior		В	uilding	: Additi		
				•		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	lipment						
	Cell Equipment - Antenna	Roof	6	EA	7	10+ years	
Entrance	9						
	Exterior Doors - Side lite	Entrance 3-West	4	EA	7	10+ years	
	Exterior Doors - Store Front	Entrance 3-West	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 3-West	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3A-West / Outside Electrical Room	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 3A-West / Outside Electrical Room	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 3B-West / Outside Pump Room	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 3B-West / Outside Pump Room	1	EA	7	10+ years	
	Exterior Doors - Store Front	Entrance 4-NW	2	EA	6	10+ years	
	Entrance Control - Audio and Video	Entrance 5-North	1	EA	7	10+ years	
	Exterior Doors - Store Front	Entrance 5-North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 5-North	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 2-South	2	EA	6	10+ years	
	Entrance Control - Audio and Video	Main Entrance 1-South	1	EA	7	10+ years	
	Exterior Doors - Store Front	Main Entrance 1-South	6	EA	7	10+ years	
	Exterior Doors - Transom Lite	Main Entrance 1-South	6	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Roof Access	4	EA	7	10+ years	
	Exterior Stairs - Steel or Aluminum	Roof Access	12	LF	7	10+ years	
_Foundat	ion						
	Foundation - Concrete	Entire Building	628	LF	7	10+ years	
	Superstructure - Steel	Entire Building	70,296	SF	7	10+ years	
Lighting		-				-	
	Exterior Lighting - Wall Mounted	Entire Building	27	EA	7	10+ years	
	Extende Lighting - Wait Mounted		21	LA	,	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 1	25	LF	7	10+ years	
	Coping - Metal	Roof 1	50	LF	7	10+ years	
	Coping - Stone	Roof 1	410	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 1	195	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	300	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	50	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 1	5,830	SF	5	2-5 years	



Catego	ry : Exterior	Building : Addition 2							
3	-			Ŭ		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof 1	5,830	SF	7	10+ years			
	Concrete Topping								
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years			
	Coping - Stone	Roof 2	675	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof 2	545	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Roof 2	45	LF	7	10+ years			
	Parapet - Parapet > 30"	Roof 2	630	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 2	15,035	SF	5	2-5 years			
	Roof Hatch - Metal	Roof 2	1	EA	7	10+ years	West - Near Cell Antennas		
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2	15,035	SF	7	10+ years			
Valls									
	Exterior Walls - Brick	Entire Building	33,896	SF	7	10+ years			
	Exterior Walls - Concrete Block	Entire Building	1,168	SF	7	10+ years			
	Exterior Walls - Stone-Cast	Entire Building	6,834	SF	7	10+ years			
/indows	3								
	Guard - Guards perforated	Entire Building	2,294	SF	7	10+ years			
	Lintels - Steel	Entire Building	906	LF	7	10+ years			
	Windows - Louver	Entire Building	750	SF	7	10+ years			
	Windows - Sash Aluminum Double-pane	Entire Building	6,590	SF	6	10+ years			
atego	ry : Electrical		В	uilding	: Additi	on 2			
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
merger	ncy System								
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Functional, 1999 installation		
	Security System - CCTV	Entire Building	70,296	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	70,296	SF	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	19,592	SF	6	10+ years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years			
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	29	EA	2	0-1 year	No batteries, no AC generator		
lain Se	vice								
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	Serves 1999 addition 2 and lunchroom building		
	Independent Electrical Service for	Electrical Boom	1		7	10	ATS and 2 maters, convex addition		

emergency power

Independent Electrical Service for

ΕA

1

7

10+ years

Electrical Room

ATS and 2 meters, serves addition 2



Catego	ry : Electrical	Building : Addition 2							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement			
	PA System	Entire Building	70,296	SF	6	6-10 years	Serves addition 2 and other buildings		
Power Di	stribution								
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Functional panel rated 7		
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	7	10+ years	1999 installation		
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years			
	Transformers - 277/480 - 120/208	Entire Building	4	EA	7	10+ years			
Catago	nu Fire Drotostion		В	سناطنهم		on 2			
Catego	ry : Fire Protection		В	unaing	: Additi	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar									
	Fire Alarm Panel	Mechanical Room	2	EA	6	6-10 years	Serve all 4 buildings		
	Fire Alarm Strobe Lights	Mechanical Room	70,296	SF	6	10+ years	5		
	Fire Alarm_System	Mechanical Room	70,296	SF	5	6-10 years	Connected to other buildings		
	Fire Pump Controller	Mechanical Room	1	ĒA	6	6-10 years			
				_/ .	Ū	0.0900.0			
Pump Ro	oom Assembly								
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	Serves addition 2, gym building, kitchen building		
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	Kitchen building		
Sprinkler	System								
	Sprinkler Heads	Entire Building	70,296	SF	7	10+ years			
	Sprinkler Piping	Entire Building	70,296	SF	7	10+ years			
	Wet Sprinkler System	Entire Building	70,296	SF	6	10+ years	1999 installation		
		Entitle Building	70,290	36	0	10+ years			
Catego	ry : Mechanical		В	uilding	: Additi	on 2			
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Cond	0								
	Chemical Pot Feeder	Roof	1	EA	6	6-10 years	<b>_</b>		
	Chiller-Air Cooled- Recipricating-Roof Mounted - 101 - 200 tons	Roof	1	EA	2	0-1 year	Does not work according to the building engineer.		
	Glycol Feed	Roof	1	EA	5	6-10 years	Functional, tested		
	Pipes - Chilled Water Pipe- Copper	Roof	100	LF	6	6-10 years	i unclional, lesteu		
	Pipes - Chilled Water Pipe- Copper Pipes - Chilled Water Pipe- Steel			LF		,			
		Roof	400		6	6-10 years	Draviaualy not accessed		
	Pressure Fill System	Roof	1	EA	6	6-10 years	Previously not assessed		
Air Hand	ling Systems								
	Fan Power Box - Fan Power Box with Hot	Entire Building	16	EA	5	6-10 years	Difficult to access, above ceilings,		



Catego	ry : Mechanical		В	Building : Addition 2					
U	•			Ŭ		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	17	EA	5	6-10 years	Difficult to access, above ceilings, functional		
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	25	EA	5	6-10 years	Difficult to access, above ceilings, functional		
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Entire Building	1	EA	6	10+ years	ER1, Serves AHU 1		
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Entire Building	1	EA	6	10+ years	ER2, Serves AHU 2		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	6	10+ years	AHU 1, serves first and second floors 1999 installation		
	Air Intake	Mechanical Room	2	EA	6	10+ years			
	VAV Box	Mechanical Room	2	EA	5	6-10 years	Difficult to access, above ceilings		
	VAV Box	Mechanical Room	6	EA	5	6-10 years	Difficult to access, above ceilings		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU 2, serve third floor, 1999 installation		
	Air Intake	Mechanical Room	1	EA	6	10+ years			
	VAV Box	Mechanical Room	7	EA	5	6-10 years	Difficult to access, 1999 installation		
Boiler Sy	/stems								
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	4	EA	6	6-10 years	1999 installation		
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years			
	Combustion Dampers	Boiler Room	4	EA	6	10+ years			
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	4	EA	6	6-10 years	Serves addition 2 and 1999 lunchroom/kitchen addition, 1999 installation		
	Water Fill System	Boiler Room	1	EA	5	6-10 years	Functional		
Gas Boo	oster								
	Gas Booster	Mechanical Room	1	EA	6	10+ years	First floor, exterior door, only one found. Confirmed by engineer		
Heating									
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	In pump room and electric room, exterior door entrance		
	Unit Heater - Hot Water	Entire Building	6	EA	6	6-10 years			
	Cabinet Heaters - With Hot Water Coil	Entire Building	8	EA	5	6-10 years	With minor scratches and corrosion		
Mechani	cal Plumbing								
	Hot Water Pump - 10 - 20 HP	Boiler Room	2	EA	6	6-10 years	Serve HW boilers		
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	6-10 years	Serve air handlers, ceiling mounted		



Catego	ry : Mechanical		В	uilding	: Additie	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hydronic Supply and Return - Copper	Entire Building	1,300	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	2	EA	5	6-10 years	1999 installation
empera	ature Control						
	DDC System	Entire Building	70,296	SF	5	6-10 years	Landry's & Gyr, software not update
							recently
	Electric Thermostat	Entire Building	8	EA	6	6-10 years	Serve unit heaters
	Thermostats - DDC	Entire Building	73	EA	6	6-10 years	Serve fan power boxes and VAV
		5				,	boxes
/entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	EF1, in-line type
		Entro Danang		<b>L</b> /(	Ū	o ro youro	
atego	ry : Plumbing		В	uilding	: Additie		
	Hanna Tama	l tion	Owentites		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	Serves addition 2 and kitchen addition
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	70,296	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	70,296	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	70,296	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	70,296	SF	7	10+ years	1999 installation
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	-	70,296	SF	7	10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	70,296 70,296	SF SF	7 7	10+ years 10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	70,296	SF	7	10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	-				-	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	70,296 70,296	SF SF	7	10+ years 10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Entire Building Entire Building Entire Building	70,296 70,296 70,296	SF SF SF	7	10+ years 10+ years 10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	70,296 70,296	SF SF	7 7	10+ years 10+ years	1999 Installation
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Entire Building Entire Building Entire Building	70,296 70,296 70,296	SF SF SF	7 7 7	10+ years 10+ years 10+ years	1999 Installation
Pumps	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building Entire Building Entire Building Entire Building	70,296 70,296 70,296 70,296	SF SF SF SF	7 7 7 7	10+ years 10+ years 10+ years 10+ years	1999 Installation
umps	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building Entire Building Entire Building Entire Building	70,296 70,296 70,296 70,296	SF SF SF SF	7 7 7 7	10+ years 10+ years 10+ years 10+ years	Serves addition 2



Catego	ry : Plumbing		Building : Addition 2					
_				-		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
atego	ry : Room		В	uildina	: Additi	on 2		
	,		_			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminist	rative Suites/Offices							
	Doors - Wood Doors inclu hw	1st Floor - Faculty Room	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Faculty Room	476	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - Faculty Room	6	EA	7	6-10 years		
	Power Distribution	1st Floor - Faculty Room	8	EA	7	10+ years		
	Walls - Concrete Block	1st Floor - Faculty Room	739	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Faculty Room	336	SF	7	10+ years		
	Work Sink	1st Floor - Faculty Room	1	EA	7	10+ years		
	Ceiling - Lay-in	2nd Floor - Music Room Next to	163	SF	7	10+ years		
		Staff Restroom	100	01	'	TO+ years		
	Ceiling - Lay-in	2nd Floor - Music Room Next to	4	SF	4	0-1 year	Quantity changeddamaged tiles	
	5	Staff Restroom				,	, , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	2nd Floor - Music Room Next to	1	EA	7	10+ years		
		Staff Restroom						
	Floor - Tile	2nd Floor - Music Room Next to	175	SF	7	10+ years		
		Staff Restroom						
	Lighting - Lay-in	2nd Floor - Music Room Next to	3	EA	7	6-10 years		
		Staff Restroom				•		
	Power Distribution	2nd Floor - Music Room Next to	4	EA	7	10+ years		
		Staff Restroom				,		
	Walls - Concrete Block	2nd Floor - Music Room Next to	653	SF	7	10+ years		
		Staff Restroom		•	-	, ,		
	Ceiling - Lay-in	3rd floor - Next to Staff Restroom	167	SF	7	10+ years		
	Ceiling - Lay-in	3rd floor - Next to Staff Restroom	8	SF	4	0-1 year		
	Doors - Wood Doors inclu hw	3rd floor - Next to Staff Restroom	1	EA	7	10+ years		
	Floor - Tile	3rd floor - Next to Staff Restroom	175	SF	7	10+ years		
	Lighting - Lay-in	3rd floor - Next to Staff Restroom	3	EA	7	6-10 years		
	Power Distribution	3rd floor - Next to Staff Restroom	4	EA	7	10+ years		
	Walls - Concrete Block	3rd floor - Next to Staff Restroom	653	SF	7	10+ years		
			175	SF		,		
	Ceiling - Lay-in	In room 221			7	10+ years		
	Doors - Wood Doors inclu hw	In room 221	1	EA	7	10+ years		
	Floor - Tile	In room 221	175	SF	7	10+ years		
	Lighting - Lay-in	In room 221	2	EA	7	6-10 years		
	Power Distribution	In room 221	6	EA	7	10+ years		
	Walls - Concrete Block	In room 221	368	SF	7	10+ years		
	Walls - Plaster/Drywall	In room 221	176	SF	7	10+ years		
	Ceiling - Lay-in	In room 321	167	SF	7	10+ years		
	Ceiling - Lay-in	In room 321	8	SF	4	0-1 year		
	Doors - Wood Doors inclu hw	In room 321	1	EA	7	10+ years		
	Floor - Tile	In room 321	175	SF	7	10+ years		



Category : Room **Building : Addition 2** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Lay-in In room 321 3 ΕA 6-10 vears 7 Power Distribution 4 ΕA 7 In room 321 10+ vears Walls - Concrete Block In room 321 368 SF 7 10+ years SF 7 Walls - Plaster/Drywall In room 321 176 10+ years SF Ceiling - Lay-in Library office 141 7 10+ years SF Library office Ceiling - Lay-in 8 3 0-1 year missing Doors - Transom Window Library office SF 7 15 10+ years Doors - Wood Doors inclu hw Library office 1 ΕA 7 10+ years Floor - Tile Library office 149 SF 6 10+ years Library office Lighting - Lay-in 3 ΕA 7 6-10 years Power Distribution Library office 8 ΕA 7 10+ vears Storage/ Closet Library office 68 SF 7 10+ years Walls - Concrete Block Library office 170 SF 7 10+ years Library office SF 7 Walls - Plaster/Drywall 309 10+ years Work SInk Library office ΕA 7 1 10+ years Main Office 838 SF 7 Ceiling - Lay-in 10+ years Main Office SF Ceiling - Lay-in 8 4 0-1 vear SF Doors - Side-lite Main Office 64 7 10+ years ΕA Doors - Wood Doors inclu hw Main Office 2 7 10+ vears Floor - Carpet Main Office 615 SF 7 6-10 years Floor - Terrazzo Main Office 240 SF 7 10+ years Main Office 7 Lighting - Lay-in 13 EΑ 6-10 years Main Office 7 **Power Distribution** 16 EΑ 10+ years SF Storage/ Closet Main Office 23 7 10+ years Walls - Concrete Block Main Office 1.809 SF 7 10+ years SF Walls - Plaster/Drvwall Main Office 514 7 10+ vears SF Ceiling - Lay-in Next to room 222A 64 7 10+ years Doors - Wood Doors inclu hw Next to room 222A ΕA 7 1 10+ years SF 7 Floor - Tile Next to room 222A 64 10+ years Lighting - Lay-in Next to room 222A 1 ΕA 5 1-2 years 7 Power Distribution Next to room 222A 2 FΑ 10+ vears Walls - Concrete Block Next to room 222A 160 SF 7 10+ vears SF 7 Walls - Plaster/Drywall 160 Next to room 222A 10+ years Ceiling - Lay-in Principals office 307 SF 7 10+ years SF Ceiling - Lay-in Principals office 2 4 0-1 year Quantity Doors - Wood Doors inclu hw ΕA 7 Principals office 2 10+ years 311 SF Floor - Carpet Principals office 7 6-10 years Lighting - Lay-in Principals office 7 5 EA 6-10 years Power Distribution Principals office 16 EΑ 7 10+ years SF Walls - Concrete Block Principals office 501 7 10+ vears SF Walls - Plaster/Drywall Principals office 645 7 10+ years Library 7 Casework Room 222 191 LF 10+ years



Category : Room				Building : Addition 2					
J				J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Ceiling - Lay-in	Room 222	1,562	SF	7	10+ years			
	Ceiling - Lay-in	Room 222	8	SF	4	0-1 year			
	Doors - Side-lite	Room 222	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 222	1	EA	7	10+ years			
	Floor - Carpet	Room 222	1,570	SF	7	6-10 years			
	Lighting - Lay-in	Room 222	18	EA	7	6-10 years			
	Walls - Concrete Block	Room 222	1,277	SF	7	10+ years			
	Walls - Plaster/Drywall	Room 222	562	SF	7	10+ years			
IDF IDF	-								
_	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Finishes	2nd Floor	148	SF	7	10+ years			
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split		
lechanio	cal/ Service Rooms								
	Janitor's Closet	1st Floor	28	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	170	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	305	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	65	SF	7	10+ years	Elevator Machine Room		
	Mechanical/ Service Rooms	1st Floor	22	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	64	SF	7	10+ years			
	Vaults	1st Floor	221	SF	7	10+ years	Vault		
	Janitor's Closet	2nd Floor	28	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	12	SF	7	10+ years	Electrical Closet		
	Mechanical/ Service Rooms	2nd Floor	22	SF	7	10+ years	Electrical Closet		
	Mechanical/ Service Rooms	2nd Floor	64	SF	7	10+ years	None per engineer		
	Janitor's Closet	3rd Floor	28	SF	7	10+ years	None per engineer		
	Mechanical/ Service Rooms	3rd Floor	12	SF	7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	22	SF	7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	64	SF	7	10+ years			
	Mechanical/ Service Rooms	4th Floor	4,630	SF	7	10+ years			
estroon	1								
	Accessories	1st Floor	241	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	241	SF	7	10+ years			
	Floor - Terrazzo	1st Floor	241	SF	7	10+ years			
	Floor Drain	1st Floor	2	ĒA	7	10+ years			
	Hand Dryer	1st Floor	2	EA	7	6-10 years			
	Lavatory	1st Floor	-3	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years			
	Partitions	1st Floor	3	EA	7	10+ years			
	Urinals	1st Floor	3	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	995	SF	7	10+ years			



Catego	ry : Room		B	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	293	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	293	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	293	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,155	SF	7	10+ years	
	Water Closet	1st Floor	6	EA	7	10+ years	
	Accessories	2nd Floor	241	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	241	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	241	SF	7	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	7	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	10+ years	
	Urinals	2nd Floor	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	995	SF	7	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	2nd Floor	42	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	42	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	213	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	293	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	293	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	293	SF	7	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	7	EA	7	6-10 years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,155	SF	7	10+ years	
	Water Closet	2nd Floor	6	EA	7	10+ years	
	Accessories	3rd Floor	241	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	241	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	241	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Additi	on 2	
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Partitions	3rd Floor	3	EA	7	10+ years	
	Urinals	3rd Floor	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	995	SF	7	10+ years	
	Water Closet	3rd Floor	3	EA	7	10+ years	
	Accessories	3rd Floor	42	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	42	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor	213	SF	7	10+ years	
	Water Closet	3rd Floor	1	EA	7	10+ years	
	Accessories	3rd Floor	293	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	293	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	293	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Partitions	3rd Floor	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,155	SF	7	10+ years	
	Water Closet	3rd Floor	6	EA	7	10+ years	
	Accessories	In Room 110	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 110	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 110	1	EA	7	10+ years	
	Floor - Terrazzo	In Room 110	36	SF	7	10+ years	
	Floor Drain	In Room 110	1	EA	7	10+ years	
	Lavatory	In Room 110	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 110	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 110	200	SF	7	10+ years	
	Water Closet	In Room 110	1	EA	7	10+ years	
	Accessories	In Room 111	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 111	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 111	1	EA	7	10+ years	
	Floor - Terrazzo	In Room 111	36	SF	7	10+ years	
	Floor Drain	In Room 111	1	EA	7	10+ years	
	Lavatory	In Room 111	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 111	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 111	200	SF	7	10+ years	



Catego	ry : Room		В	uildina	: Additi	on 2	
J	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	In Room 111	1	EA	7	10+ years	
	Accessories	In Room 112	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 112	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 112	1	EA	7	10+ years	
	Floor - Terrazzo	In Room 112	36	SF	7	10+ years	
	Floor Drain	In Room 112	1	EA	7	10+ years	
	Lavatory	In Room 112	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 112	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 112	200	SF	7	10+ years	
	Water Closet	In Room 112	1	EA	7	10+ years	
	Accessories	In Room 113	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 113	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 113	1	ĒA	7	10+ years	
	Floor - Terrazzo	In Room 113	36	SF	7	10+ years	
	Floor Drain	In Room 113	1	EA	7	10+ years	
	Lavatory	In Room 113	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 113	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 113	200	SF	7	10+ years	
	Water Closet	In Room 113	200	EA	7	10+ years	
	Accessories	In Room 114	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 114	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 114		EA	7	10+ years	
	Floor - Terrazzo	In Room 114	36	SF	7	10+ years	
	Floor Drain	In Room 114		EA	7	10+ years	
	Lavatory	In Room 114	1	EA	7	10+ years	
		In Room 114	1	EA			
	Lighting - Lay-in Walls - Structural Glazed Tile	In Room 114	200	SF	7 7	6-10 years 10+ years	
	Walls - Structural Glazed The Water Closet			EA			
		In Room 114	1	SF	7	10+ years	
	Accessories	In Room 115	36		7	6-10 years	
	Ceiling - Lay-in	In Room 115	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 115	1	EA	7	10+ years	
	Floor - Terrazzo	In Room 115	36	SF	7	10+ years	
	Floor Drain	In Room 115	1	EA	7	10+ years	
	Lavatory	In Room 115	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 115	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 115	200	SF	7	10+ years	
	Water Closet	In Room 115	1	EA	7	10+ years	
	Accessories	In Room 116	36	SF	7	6-10 years	
	Ceiling - Lay-in	In Room 116	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 116	1	EA	7	10+ years	
	Floor - Terrazzo	In Room 116	36	SF	7	10+ years	
	Floor Drain	In Room 116	1	EA	7	10+ years	
	Lavatory	In Room 116	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 116	1	EA	7	6-10 years	



Catego	ry : Room	Building : Addition 2							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	In Room 116	200	SF	7	10+ years			
	Water Closet	In Room 116	1	EA	7	10+ years			
	Accessories	Main Office	42	SF	7	6-10 years			
	Ceiling - Lay-in	Main Office	42	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years			
	Floor - Terrazzo	Main Office	42	SF	7	10+ years			
	Floor Drain	Main Office	1	EA	7	10+ years			
	Lavatory	Main Office	1	EA	7	10+ years			
	Lighting - Lay-in	Main Office	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	Main Office	233	SF	7	10+ years			
	Water Closet	Main Office	1	EA	7	10+ years			

#### **Category : Classroom**

**Building : Addition 2** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #110 (Pre School)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,220	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,220	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	46	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,060	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	306	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Peeling paint
	Work Sink	1st Floor	1	EA	7	10+ years	
0							
	om #111 (Pre School)		50			40	
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,172	SF	1	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,172	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	692	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	692	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	



Category : Classroom			В	Building : Addition 2			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Quantity		Nalik	Replacement	Comments
Jassioc	m #112 (Kindergarten)	1st Floor	50	LF	7	10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	
	Casework					10+ years	
	Ceiling - Lay-in	1st Floor	1,220	SF LF	7	10+ years	
	Chalk Board	1st Floor	12	LF SF	4	2-5 years	
	Doors - Side-lite	1st Floor	8		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,220	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	754	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	612	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroc	m #113 (Pre School)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,172	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	-	EA	7	10+ years	
	Floor - Tile	1st Floor	1,172	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	.,	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	692	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	692	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
IdSSI00	m #114 (Kindergarten)	1st Floor		LF	7	10, years	
	Casework		50	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,220		7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,220	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	754	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	Walls - Concrete Block Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor 1st Floor	754 612 2	SF SF EA	7 7 7	10+ years 10+ years 10+ years	

Classroom #115 (Kindergarten)



Catego	ry : Classroom		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	1st Floor	50	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	4	SF	4	0-1 year	Quantity changed	
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,172	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	50	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	692	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	692	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroo	m #116 (Kindergarten)							
	Casework	1st Floor	50	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,196	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	No	
	Chalk Board	1st Floor	50	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years		
	Floor - Tile	1st Floor	1,220	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	50	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,060	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	306	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroo	m #119 (Kindergarten)							
	Casework	1st Floor	54	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	888	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	None	
	Doors - Side-lite	1st Floor	16	SF	7	10+ years	None	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	900	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	10	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	728	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	728	SF	7	10+ years		
Classroo	m #213 (Special Program)							



Catego	ry : Classroom		Building : Addition 2				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	23	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	450	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	450	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor		SF	7		
			364	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	238	55	/	10+ years	
assroo	m #214 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	924	SF		-	
					7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	237	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroc	m #215 (Regular Classroom)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	925	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	925	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	525 1	EA	7	6-10 years	
				LF	7	,	
	Marker Board	2nd Floor	10	SF		6-10 years	
	Storage/ Closet	2nd Floor	5		7	10+ years	
	Walls - Concrete Block	2nd Floor	699	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	414	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	60	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	m #216 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	



Catego	ry : Classroom		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	,		
				SF		10+ years		
	Walls - Concrete Block	2nd Floor	699		7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	474	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
assroo	om #217 (Regular Classroom)							
	Casework	2nd Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
		2nd Floor		SF				
	Floor - Tile		900		7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	699	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	474	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
lassroo	om #218 (Regular Classroom)							
	Casework	2nd Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years		
				LF				
	Chalk Board	2nd Floor	12		4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	470	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	470	SF	5	1-2 years		
			-	SF				
	Walls - Plaster/Drywall	2nd Floor	699		7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
lassroc	om #219 (Language Lab)							
	Casework	2nd Floor	22	LF	7	10+ years		



atego	ry : Classroom		В	Building : Addition 2				
Ŭ	•			Recommend				
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Ceiling - Lay-in	2nd Floor	450	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	450	SF	6	10+ years	Clean	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	364	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	364	SF	7	10+ years		
				0.	•	ier jeale		
lassroo	om #220 (Regular Classroom)							
	Casework	2nd Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years		
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	410	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	640	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
loooroo	om #221 (Art Room)							
1855100	Casework	2nd Floor	58	LF	7	10+ years		
		2nd Floor	1,024	SF				
	Ceiling - Lay-in Ceiling - Lay-in	2nd Floor	1,024	SF	7 4	10+ years 0-1 year	Quantity changed	
	Chalk Board	2nd Floor	° 12	LF	4	2-5 years	Quantity changed	
	Doors - Side-lite	2nd Floor		SF	4			
	Doors - Wood Doors inclu hw	2nd Floor	8 1	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,034	SF	7	10+ years		
						10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	637	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	577	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	60	SF	6	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		
lassroo	m #222A (Regular Classroom)							
	Casework	2nd Floor	49	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	653	SF	7	10+ years		



Catego	ry : Classroom		В	Building : Addition 2				
Ŭ						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	653	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	374	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,004	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	Ptd	
Classroo	om #223 (Computer Lab)							
_01233100	Casework	2nd Floor	130	LF	7	10+ years		
	Casework Ceiling - Lay-in	2nd Floor	1,221	SF				
				LF	7	10+ years		
	Chalk Board	2nd Floor	12		4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,221	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	132	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	703	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	703	SF	7	10+ years		
Classroo	om #225 (Store Room)							
	Casework	2nd Floor	20	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	425	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	425	SF	6	10+ years	Clean	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	602	SF	7	10+ years		
Classro	om #313 (Special Program)							
	Casework	3rd Floor	20	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	394	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	594 4	SF	4	0-1 year		
	Doors - Side-lite	3rd Floor	4 8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	7	10+ years		
	Floor - Tile	3rd Floor	398	SF	7	-		
		3rd Floor 3rd Floor				10+ years		
	Lighting - Lay-in		6	EA	7	6-10 years		
	Marker Board	3rd Floor	22	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	331	SF	7	10+ years		



|--|

Catego	ry : Classroom		В	Building : Addition 2					
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_	Walls - Plaster/Drywall	3rd Floor	223	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years			
Classroo	om #314/316 (Regular Classroom)								
	Casework	3rd Floor	30	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	902	SF	7	10+ years			
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	918	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	730	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	320	SF	7	10+ years			
Classroo	om #315 (Regular Classroom)								
	Casework	3rd Floor	16	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	30	SF	4	0-1 year			
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	-	EA	7	10+ years			
	Floor - Tile	3rd Floor	925	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	ĒA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	5	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	699	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	494	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	10+ years			
Classroo	om #317 (Regular Classroom)								
	Casework	3rd Floor	26	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	876	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year			
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	880	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	5	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	699	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	477	SF	7	10+ years			
	Work Sink	3rd Floor	477	EA	7				
	WORK SILIK	310 F1001	1	EA	1	10+ years			



Catego	ry : Classroom		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	m #318 (Regular Classroom)							
Jassioo		3rd Floor	40	LF	7	10, , , , , , , , , , , , , , , , , , ,		
	Casework	3rd Floor	40 876	SF	7 7	10+ years		
	Ceiling - Lay-in	3rd Floor		SF		10+ years		
	Ceiling - Lay-in		24	SF LF	4	0-1 year		
	Chalk Board	3rd Floor	12		4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	899	SF	7	10+ years		
	Floor - Tile	3rd Floor	1	SF	4	0-1 year		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	410	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	699	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	m #319 (Special Program)							
	Casework	3rd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	377	SF	7	10+ years		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	377	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	330	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	320	SF	7			
		3rd Floor		SF	6	10+ years		
	Walls - Plaster/Drywall	310 FI001	10	35	0	10+ years		
Classroo	m #320 (Regular Classroom)							
	Casework	3rd Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	410	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	699	SF	7	10+ years		



Catego	ry : Classroom		Building : Addition 2						
-			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Work Sink	3rd Floor	1	EA	7	10+ years			
`lassror	m #321 (Regular Classroom)								
1022100	Casework	3rd Floor	45	LF	7	10, , , , , , , , , , , , , , , , , , ,			
				SF		10+ years			
	Ceiling - Lay-in	3rd Floor	1,018		7	10+ years	Other democrad tiles were realess		
	Ceiling - Lay-in	3rd Floor	1	SF	5	0-1 year	Other damaged tiles were replace		
	Chalk Board	3rd Floor	10	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,034	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	5	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	637	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	637	SF	7	10+ years			
	Work Sink	3rd Floor	2	EA	7	10+ years			
laceror	m #322 (Regular Classroom)								
7/233100	Casework	3rd Floor	40	LF	7	10 L VOORS			
		3rd Floor		SF		10+ years			
	Ceiling - Lay-in		892		7	10+ years			
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	900	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	5	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	410	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	640	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	10+ years			
Classroc	m #323 (Regular Classroom)								
	Casework	3rd Floor	16	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	461	SF	7	10+ years			
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	465	SF	7	10+ years			
		3rd Floor	403	EA	7	•			
	Lighting - Lay-in Marker Baard		-			6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	5	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	366	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	264	SF	7	10+ years			



Catego	ategory : Classroom		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #324 (Regular Classroom)							
	Casework	3rd Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	898	SF	7	10+ years		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	-	ĒA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	ĒA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	410	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	640	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
						io: youro		
Classroo	om #325 (Regular Classroom)							
	Casework	3rd Floor	28	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	905	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	925	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	ĒA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	699	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	454	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	40	SF	6	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	om #326 (Regular Classroom) Casework	3rd Floor	40	LF	7	10+ years		
				SF	7			
	Ceiling - Lay-in	3rd Floor	898	LF		10+ years		
	Chalk Board	3rd Floor	12		4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	5	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	474	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	679	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	20	SF	6	10+ years		



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	m #327 (Special Program)						
	Casework	3rd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	446	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	450	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	364	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	243	SF	7	10+ years	
	Wallo T lastell Drywall		210	01	•	Tor youro	
Classroo	m #328 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	5	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	699	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor		SF			
			474	EA	7 7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor			7.070	05	-	10	
	Ceiling - Lay-in	1st Floor	7,073	SF	7	10+ years	N. 1
	Ceiling - Lay-in	1st Floor	24	SF	4	0-1 year	Nodamage
	Ceiling - Plaster/Drywall	1st Floor	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	11	EA	7	10+ years	
	Doors - Store Front	1st Floor	10	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	7,097	SF	7	10+ years	
		1st Floor	143	EA	7	6-10 years	
	Lighting - Lay-in	13(1100)	1+5		-	0.0,00.0	
	Lighting - Lay-in Stairs - Terrazzo	1st Floor	36	LF	7	10+ years	



Catego	ry : Interior		В	Building : Addition 2				
eulege	.,		_	anang	, , ca aiti	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	broken damaged	
	Doors - Steel Doors incl hw	2nd Floor	10	EA	7	10+ years	5	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	Do not use	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years		
	Floor - Terrazzo	2nd Floor	5,647	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	120	EA	7	6-10 years		
	Walls - Structural Glazed Tile	2nd Floor	7,636	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	5,627	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year		
	Doors - Steel Doors incl hw	3rd Floor	10	EA	7	10+ years		
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years		
	Floor - Terrazzo	3rd Floor	5,647	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	120	EA	7	6-10 years		
	Walls - Structural Glazed Tile	3rd Floor	7,636	SF	7	10+ years		
Safety								
	Camera Viewing Station	Entire Building	0	EA	7	6-10 years		
	Security Cameras	Entire Building	2	EA	7	6-10 years		
	Security Cameras	Entire Building	2	EA	7	6-10 years		
	Security Cameras	Entire Building	4	EA	7	6-10 years		
Stairs								
	Ceiling - Exposed	Stairwell #1	72	SF	7	10+ years		
	Ceiling - Lay-in	Stairwell #1	478	SF	7	10+ years		
	Ceiling - Lay-in	Stairwell #1	2	SF	4	0-1 year		
	Floor - Terrazzo	Stairwell #1	373	SF	7	10+ years		
	Handrails	Stairwell #1	130	LF	7	10+ years		
	Lighting - Lay-in	Stairwell #1	10	EA	7	6-10 years		
	Lighting - Wall Mounted	Stairwell #1	2	EA	7	6-10 years		
	Stairs - Terrazzo	Stairwell #1	54	LF	7	10+ years		
	Walls - Concrete Block	Stairwell #1	1,874	SF	7	10+ years		
	Ceiling - Exposed	Stairwell #2	356	SF	7	10+ years		
	Ceiling - Lay-in	Stairwell #2	329	SF	7	10+ years		
	Ceiling - Lay-in	Stairwell #2	12	SF	4	0-1 year		
	Floor - Terrazzo	Stairwell #2	455	SF	7	10+ years		
	Handrails	Stairwell #2	162	LF	7	10+ years		
	Lighting - Lay-in	Stairwell #2	6	EA	7	6-10 years		
	Lighting - Pendent/Surface	Stairwell #2	1	EA	7	6-10 years		
	Lighting - Wall Mounted	Stairwell #2	4	EA	7	6-10 years		
	Stairs - Terrazzo	Stairwell #2	77	LF	7	10+ years		
	Walls - Concrete Block	Stairwell #2	4,070	SF	7	10+ years		
	Walls - Plaster/Drywall	Stairwell #2	45	SF	7	10+ years		
	Ceiling - Lay-in	Stairwell #3	480	SF	7	10+ years		
	Floor - Terrazzo	Stairwell #3	373	SF	7	10+ years		



Catego	ry : Interior		В	uilding	: Additie	on 2				
		Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Handrails	Stairwell #3	130	LF	7	10+ years				
	Lighting - Lay-in	Stairwell #3	8	EA	7	6-10 years				
	Lighting - Wall Mounted	Stairwell #3	2	EA	7	6-10 years				
	Stairs - Terrazzo	Stairwell #3	54	LF	7	10+ years				
	Walls - Concrete Block	Stairwell #3	1,874	SF	7	10+ years				
/ertical (	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years				



Catego	ry : Exterior		В	Building : Addition-Gymnasium					
_			<b>-</b>			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Intrance				= .		4.0			
	Exterior Doors - Exterior Steel Door	Entrance 13-East / Kitchen	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Entrance 14-SE	2	EA	7	10+ years			
	Exterior Doors - Side lite	Entrance 14-SE	2	EA	7	10+ years			
	Exterior Doors - Transom Lite	Entrance 14-SE	2	EA	7	10+ years			
	Exterior Stairs - Concrete	Entrance 14-SE	30	LF	7	10+ years			
	Stair Handrail - Steel_Stair Handrail	Entrance 14-SE	25	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	Entrance 15-South	2	EA	5	2-5 years			
	Exterior Doors - Side lite	Entrance 15-South	2	EA	4	1-2 years	Rust/Corroded - Deterioration of Frame and bottom "Rail/Sash" of Sidelight		
	Exterior Doors - Transom Lite	Entrance 15-South	2	EA	6	10+ years	-		
	Exterior Doors - Exterior Steel Door	Entrance 15A-South / Inner court	2	EA	7	10+ years			
	Exterior Doors - Side lite	Entrance 15A-South / Inner court	2	EA	7	10+ years			
	Exterior Doors - Transom Lite	Entrance 15A-South / Inner court	2	EA	7	10+ years			
						-			
oundati	Foundation - Concrete	Entire Building	244	LF	7	10+ years			
	Superstructure - Steel	Entire Building	5,637	SF	7	10+ years			
	Superstructure - Steel	Entire Building	5,057	36	'	TUT years			
ighting									
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	10+ years			
oof Sys	stem								
,	Coping - Stone	Roof 6	260	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof 6	135	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof 6	88	LF	6	10+ years			
	Parapet - Parapet < 16" Height	Roof 6	260	LF	7	10+ years			
	Roof - Metal	Roof 6	1,920	SF	7	10+ years			
	Roof - Modified Bitumen	Roof 6	3,717	SF	5	2-5 years			
	Roof Structure - Steel / Metal Deck/	Roof 6	5,637	SF	7	10+ years			
	Concrete Topping					-			
Valls									
	Exterior Walls - Brick	Entire Building	6,336	SF	7	10+ years			
	Exterior Walls - Stone-Cast	Entire Building	244	SF	7	10+ years			
Vindows	3								
	Curtain wall - Glazed Double Pane	Entire Building	413	SF	6	10+ years			
	Lintels - Steel	Entire Building	98	LF	7	10+ years			



Catego	Category : Exterior			Building : Addition-Gymnasium				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Windows - Decorative	Entire Building	12	SF	5	10+ years	None Found cracked/broken - Film on window is ripped/torned	

Catego	ry : Electrical	Building : Addition-Gymnasium							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Emerger	ncy System								
	Security System - CCTV	Entire Building	5,637	SF	6	6-10 years	Previously not assessed		
	Security System - Intrusion Detection	Entire Building	5,637	SF	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	758	SF	6	10+ years			
	Emergency A/C Power - Gym	Entire Building	1,646	SF	6	10+ years			
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No batteries, no AC generator		
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	No batteries, no AC generator		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years			
Main Se	rvice								
	PA System	Entire Building	5,637	SF	6	6-10 years	Connected to other buildings		
Catego	ry : Fire Protection		Building : Addition-Gymnasium						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar									
	Fire Alarm Strobe Lights	Entire Building	5,637	SF	6	6-10 years	1992 installation		
	Fire Alarm_System	Entire Building	5,637	SF	5	6-10 years	Connected to addition 2, 1992 installation. 1999 fire alarm panel in addition 2		
Sprinkle	r System								
	Sprinkler Heads	Entire Building	5.637	SF	7	10+ years			
	Sprinkler Piping	Entire Building	5,637	SF	7	10+ years			
	Wet Sprinkler System	Entire Building	5,637	SF	7	10+ years	1992 installation, connected to addition 2		
Catego	ry : Mechanical		В	uilding	: Additi	on-Gymnasiun	ı		
_					_	Recommend	-		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Hanc	Iling Systems								
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained	Roof	1	EA	4	2-5 years	Recently serviced, serves gym, deteriorated		

Compressor - 21 - 30 tons



Catego	ry : Mechanical		В	uilding	: Additi	on-Gymnasiun	1
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tompora	ture Control						
rempera	DDC System	Entire Building	5,637	SF	6	6-10 years	Software not upgraded recently
	Thermostats - DDC	Entire Building	5,007	EA	6	6-10 years	1992 installation
	memostats - DDO	Entre Building	I	LA	0	0-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on-Gymnasiun	1
_						Recommend	<b>.</b> .
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Storm Piping	Entire Building	5,637	SF	6	10+ years	1992 installation
	Vent Piping	Entire Building	5,637	SF	6	10+ years	Previously not assessed
Catego	ry : Room		В	uildina	: Additi	on-Gymnasiun	ı
	,		_			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	103A, Gym Teacher's Office	185	SF	7	10+ years	
	Ceiling - Lay-in	103A, Gym Teacher's Office	4	SF	6	1-2 years	Loose tile
	Doors - Steel Doors incl hw	103A, Gym Teacher's Office	1	EA	7	10+ years	
	Floor - Tile	103A, Gym Teacher's Office	189	SF	7	10+ years	
	Lighting - Lay-in	103A, Gym Teacher's Office	2	EA	7	6-10 years	
	Power Distribution	103A, Gym Teacher's Office	6	EA	7	10+ years	
	Walls - Concrete Block	103A, Gym Teacher's Office	451	SF	7	10+ years	
	Ceiling - Lay-in	Faculty Lounge	273	SF	7	10+ years	
	Floor - Tile	Faculty Lounge	273	SF	6	10+ years	
	Lighting - Lay-in	Faculty Lounge	2	EA	7	6-10 years	
	Power Distribution	Faculty Lounge	6	EA	7	10+ years	
	Walls - Concrete Block	Faculty Lounge	614	SF	7	10+ years	
	Ceiling - Lay-in	Parent's Room	252	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Parent's Room	1	EA	7	10+ years	
	Floor - Tile	Parent's Room	252	SF	7	10+ years	Observed clean floor. Rank changed to update current observation.
	Lighting - Lay-in	Parent's Room	2	EA	7	6-10 years	to apuate current observation.
	Power Distribution	Parent's Room	- 8	EA	7	10+ years	
	Walls - Plaster/Drywall	Parent's Room	655	SF	7	10+ years	
), m===:	-						
Symnasi	Ceiling - Exposed	1st Floor	1,646	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1,040	EA	7	10+ years	
	Floor - Sport Flooring	1st Floor	1,646	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1,040	EA	7	6-10 years	
	Sound System		10		7	-	
	Sound System	1st Floor	- I	EA		10+ years	
	Walls - Concrete Block	1st Floor	5,244	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Additi	on-Gymnasium	1
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	nem - Type	Location	Quantity		ιτατικ	Replacement	Comments
Restroor	n						
	Accessories	Gender Neutral Across from Parent's Room	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gender Neutral Across from Parent's Room	47	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gender Neutral Across from Parent's Room	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Gender Neutral Across from Parent's Room	47	SF	7	10+ years	
	Floor Drain	Gender Neutral Across from Parent's Room	1	EA	7	10+ years	
	Lavatory	Gender Neutral Across from Parent's Room	1	EA	7	10+ years	
	Lighting - Lay-in	Gender Neutral Across from Parent's Room	1	EA	7	6-10 years	
	Walls - Concrete Block	Gender Neutral Across from Parent's Room	122	SF	7	10+ years	
	Water Closet	Gender Neutral Across from Parent's Room	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Gender Neutral across Parents Rom	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gender Neutral across Parents Rom	1	EA	7	10+ years	
	Floor - Tile	Gender Neutral across Parents Rom	37	SF	7	10+ years	Item type changed
	Floor Drain	Gender Neutral across Parents Rom	1	EA	7	10+ years	
	Lavatory	Gender Neutral across Parents Rom	1	EA	7	10+ years	
	Lighting - Lay-in	Gender Neutral across Parents Rom	1	EA	7	6-10 years	
	Walls - Concrete Block	Gender Neutral across Parents Rom	112	SF	7	10+ years	
	Water Closet	Gender Neutral across Parents Rom	1	EA	7	10+ years	

#### **Category : Interior**

### **Building : Addition-Gymnasium**

<b>Group</b> Corridor	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Comuoi	Ceiling - Lay-in	1st Floor	758	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	758	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,365	SF	7	10+ years	
Safety							
	Security Cameras	Entire Building	1	EA	7	6-10 years	Only 1 not 2 cameras



Category : Exterior			Building : Addition-Lunchroom/Kitchen						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance									
	Exterior Doors - Exterior Steel Door	Entrance 8A-NE / Outside Yard	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Storage Exit 10-NE / Lunchroom	1	EA	5	2-5 years			
	Ramp Handrail - Steel_Ramp Handrail	Exit 10-NE / Lunchroom	115		5	2-5 years 2-5 years	Secured by other/adjacent post.		
					-	-	Railing is failing		
	Ramps - Concrete	Exit 10-NE / Lunchroom	55	LF	5	2-5 years			
	Exterior Doors - Exterior Steel Door	Exit 11-East / Lunchroom	1	EA	6	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	Exit 11-East / Lunchroom	140	LF	6	10+ years			
	Ramps - Concrete	Exit 11-East / Lunchroom	55	LF	5	2-5 years			
	Exterior Doors - Exterior Steel Door	Exit 12-East	1	EA	5	2-5 years			
	Exterior Stairs - Concrete	Exit 12-East	25	LF	7	6-10 years			
	Stair Handrail - Steel Stair Handrail	Exit 12-East	12	LF	7	10+ years			
	Exterior Doors - Exterior Steel Door	Exit 9-SW / Lunchroom	2	EA	5	2-5 years			
	Ramp Handrail - Steel_Ramp Handrail	Exit 9-SW / Lunchroom	40	LF	6	10+ years			
	Ramps - Concrete	Exit 9-SW / Lunchroom	10	LF	5	2-5 years			
	Exterior Doors - Exterior Steel Door	Roof Access Door	10	EA	6	2-5 years			
	Exterior Stairs - Steel or Aluminum	Roof Access Door	3	LF	7	6-10 years			
		Noti Access Dool	5		'	0-10 years			
oundati									
	Foundation - Concrete	Entire Building	338	LF	7	10+ years			
	Superstructure - Steel	Entire Building	9,359	SF	7	10+ years			
ighting									
igning_	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	10+ years			
Roof Sys	tom								
<u>001 Sys</u>	Access Ladder - Metal	Roof 5	1	EA	7	10+ years			
	Chimney - Metal Flue	Roof 5	30	LF	7	10+ years			
	Coping - Stone	Roof 5	380	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof 5	150	LF	6	10+ years			
	Parapet - 16" - 30" Height	Roof 5	380	LF	7	10+ years			
	Roof - Modified Bitumen	Roof 5	9,359	SF	5	2-5 years			
	Roof Hatch - Metal	Roof 5	9,359	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/		-	SF	7				
	Concrete Topping	Roof 5	9,359	35	1	10+ years			
Valls				~-					
	Cheek-Wall - Concrete	Entire Building	570	SF	5	10+ years			
	Exterior Walls - Brick	Entire Building	8,630	SF	7	10+ years			
	Exterior Walls - Brick Exterior Walls - Stone-Cast	Entire Building Entire Building	550 2,704	SF SF	7 6	10+ years 10+ years			

### Cotogory - Exterior



Catego	ry : Exterior		Building : Addition-Lunchroom/Kitchen						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Windows									
	Clerestory - Glass Double-Pane	Entire Building	336	SF	7	10+ years			
	Lintels - Steel	Entire Building	64	LF	7	10+ years			
	Windows - Louver	Entire Building	80	SF	7	10+ years			
Catego	ry : Electrical		В	uilding	: Additi	on-Lunchroom	/Kitchen		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto		
-		Location	Quantity		Ralik	Replacement	Comments		
Emerger	ncy System								
	Emergency A/C Power - Corridors and Stairs	Entire Building	1,341	SF	6	6-10 years			
	Emergency A/C Power - Lunchrooms	Entire Building	5,733	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	9,359	SF	6	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years			
	Emergency Battery Packs - Lunchrooms	Entire Building	5	EA	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	0-1 year	No batteries, no AC generator		
	Exit Signs - Lunchroom	Entire Building	6	EA	2	0-1 year	No batteries, no AC generator		
Main Se	rvice								
	PA System	Entire Building	9,359	SF	6	6-10 years	Connected to other buildings on campus		
Power D	istribution								
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	Found 3		
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Serviced, cleaned, found 2		
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years			
Catego	ry : Fire Protection		В	uilding	: Additi	on-Lunchroom	/Kitchen		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar	m								
	Fire Alarm Strobe Lights	Entire Building	9,359	SF	6	6-10 years			
	Fire Alarm_System	Entire Building	9,359	SF	5	6-10 years	Connected to addition 2		
Sprinklei	r System								
	Sprinkler Heads	Entire Building	9,359	SF	7	6-10 years			
	Sprinkler Piping	Entire Building	9,359	SF	7	10+ years			
	Wet Sprinkler System	Entire Building	9,359	SF	7	10+ years	1999 installation, connected to		
			5,005	01	,		building 2		



Catego	ry : Mechanical		В	uilding	: Additie	on-Lunchroom	/Kitchen
			Ū		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litionina						
	Pipes - Chilled Water Pipe- Steel	Entire Building	100	LF	6	6-10 years	Located above ceiling, connected to addition 2
Air Hand	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Kitchen / Lunch room	4	EA	5	6-10 years	Functional, serves lunchroom area
	Fan Power Box - Fan Power Box with Hot Water Coil	Kitchen / Lunch room	5	EA	5	6-10 years	Functional, serves kitchen area
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Serves air handler, ER3
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	4	2-5 years	MUA1, requires frequent maintenance, old, serves kitchen, 1999 installation
Heating	Devices						
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	6	10+ years	Ceiling mounted
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
Mechan	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	150	LF	7	10+ years	1999 installation
	Hydronic Supply and Return - Steel	Entire Building	100	LF	7	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	Serves AHU 3, ceiling mounted
Tempera	ature Control						
	DDC System	Entire Building	9,359	SF	6	10+ years	
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Serves 3 HW unit heaters and 1 make-up unit
	Thermostats - DDC	Entire Building	9	EA	7	6-10 years	Serve 9 fan power boxes
Ventilati							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	6	6-10 years	KE1, exhaust fan, serves kitchen
	CFM	Linito Dallallig				•	
		Entire Building Entire Building	10	LF	5	6-10 years 10+ years	Not painted, at make-up unit



Catego	ory : Mechanical	В	uildina	Building : Addition-Lunchroom/Kitchen						
outogo				unung	. / taanti	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	Served dishwasher			
0-1										
Catego	ory : Plumbing		В	ullaing		on-Lunchroom	Kitchen			
Crown	Item - Type	Location	Quantitu	UOM	Donk	Recommend	Commente			
Group		Location	Quantity	UUIVI	Rank	Replacement	Comments			
Hot Wate										
	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room Mechanical Room	1 1	EA EA	6 5	6-10 years 6-10 years	Serves kitchen			
Piping										
	Domestic Piping-Hot Water Return Lines	Entire Building	9,359	SF	7	10+ years				
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	9,359	SF	7	10+ years				
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	9,359	SF	7	10+ years	1999 installation			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	9,359	SF	7	10+ years				
	Sanitary Piping	Entire Building	9,359	SF	7	10+ years				
	Storm Piping	Entire Building	9,359	SF	7	10+ years				
	Vent Piping	Entire Building	9,359	SF	6	10+ years				
Catego	ory : Room		В	uilding	: Additi	on-Lunchroom	/Kitchen			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Administ	trative Suites/Offices									
	Ceiling - Lay-in	Kitchen Manager	66	SF	7	10+ years				
	Doors - Side-lite	Kitchen Manager	12	SF	7	10+ years				
	Doors - Steel Doors incl hw	Kitchen Manager	1	ĒA	7	10+ years				
	Floor - Concrete	Kitchen Manager	66	SF	7	10+ years				
	Lighting - Lay-in	Kitchen Manager	1	ĒA	7	6-10 years				
	Power Distribution	Kitchen Manager	6	EA	7	10+ years				
	Walls - Concrete Block	Kitchen Manager	243	SF	7	10+ years				
Kitchen										
	Ceiling - Lay-in	1st Floor	407	SF	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor	407	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years				
	Walls - Concrete Block	1st Floor	649	SF	7	10+ years				
	Ceiling - Lay-in	Dishwash	166	SF	7	10+ years				
	Ceiling - Lay-in	Dishwash	12	SF	5	0-1 year	Quantity changed 2 tiles			
	Doors - Steel Doors incl hw	Dishwash	12	EA	7	10+ years	Quantity changed 2 lies			
	Floor - Concrete Epoxy/ Painted	Dishwash	178	SF	7	10+ years				



Catego	ry : Room		Building : Addition-Lunchroom/Kitchen							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Lighting - Lay-in	Dishwash	2	EA	7	6-10 years				
	Walls - Concrete Block	Dishwash	338	SF	7	10+ years				
	Ceiling - Lay-in	Servery Line	893	SF	7	10+ years				
	Doors - Steel Doors incl hw	Servery Line	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Servery Line	893	SF	7	10+ years				
	Lighting - Lay-in	Servery Line	13	EA	7	6-10 years				
	Serving Line	Servery Line	60	LF	7	10+ years				
	Walls - Concrete Block	Servery Line	1,696	SF	7	10+ years				
ocker/S	Shower Room									
	Accessories	In Kitchen Area	75	SF	7	6-10 years				
	Ceiling - Lay-in	In Kitchen Area	75	SF	7	10+ years				
	Doors - Steel Doors incl hw	In Kitchen Area	1	EA	7	10+ years				
	Floor - Concrete	In Kitchen Area	75	SF	7	10+ years				
	Lavatory	In Kitchen Area	1	EA	7	10+ years				
	Lighting - Lay-in	In Kitchen Area	1	EA	7	6-10 years				
	Student Lockers - One Tier	In Kitchen Area	9	EA	7	10+ years				
	Walls - Concrete Block	In Kitchen Area	345	SF	7	10+ years				
	Water Closet	In Kitchen Area	1	EA	7	10+ years				
unch &	Multipurpose Room									
	Ceiling - Exposed	1st Floor	5,733	SF	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor	5,733	SF	7	10+ years				
	Lighting - Chandelier, Incandescent	1st Floor	3	EA	7	6-10 years				
	Walls - Concrete Block	1st Floor	8,902	SF	7	10+ years				
Catego	ry : Interior		В	uilding	: Additi	on-Lunchroom	/Kitchen			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Corridor										
	Ceiling - Lay-in	1st Floor	1,329	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	12	SF	5	1-2 years				
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor	1,341	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	11	EA	7	10+ years				
	Walls - Concrete Block	1st Floor	1,829	SF	7	10+ years				
Safety										
	Security Cameras	1st Floor	1	EA	7	6-10 years				



Category : Site			В	uilding			
_			<b>-</b>			Recommend	<b>.</b> .
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic				~-			
	Surface - Synthetic	West	10,000	SF	7	10+ years	Basketball court and running track Quantity changed to accommodate the soccer field and running track/basketball court materials separately.
	Surface - Synthetic	West	8,000	SF	7	10+ years	Soccer Field. Quantity changed to accommodate the soccer field and running track/basketball court materials separately.
Civil/Dra	0						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
Fencing							
	Fencing - Guard Rail	Entire Site	110	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,441	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	5	2-5 years	small portions are bent and entirely needs new paint.
Landsca	ре						
Landsca	Benches	Entire Site	15	EA	7	10+ years	
Landsca	Benches Landscape - Grass	Entire Site Entire Site	10,827	SF	7 6	6-10 years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt		10,827 14,890	SF SF			
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete	Entire Site	10,827	SF SF SF	6 7 7	6-10 years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt	Entire Site Entire Site	10,827 14,890	SF SF	6 7	6-10 years 10+ years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees	Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36	SF SF SF	6 7 7	6-10 years 10+ years 10+ years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete	Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500	SF SF SF SF	6 7 7 6	6-10 years 10+ years 10+ years 10+ years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees	Entire Site Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36	SF SF SF EA	6 7 7 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area	Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363	SF SF SF EA SF	6 7 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete	Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113	SF SF SF EA SF SF	6 7 6 6 7	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry	Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600	SF SF SF EA SF SF SF	6 7 6 6 7 5	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years 10+ years	
_andsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete	Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60	SF SF SF SF SF SF SF SF	6 7 6 6 7 5 7	6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years	
	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1	SF SF SF SF SF SF SF SF SF EA	6 7 6 6 7 5 7 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years 10+ years 10+ years 10+ years	
Landsca	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1	SF SF SF SF SF SF SF SF SF EA	6 7 6 6 7 5 7 6	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years 10+ years 10+ years 10+ years	
	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1 200	SF SF SF SF SF SF SF SF SF SF SF	6 7 6 6 6 7 5 7 6 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years	
	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1 200	SF SF SF SF SF SF SF SF LF LF	6 7 6 6 7 5 7 6 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1 200 635 635 60 4	SF SF SF SF SF SF SF SF LF	6 7 6 6 6 7 5 7 6 7 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
	Benches Landscape - Grass Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Retaining Wall - Concrete Retaining Wall - Masonry Trash Receptacles Walking Path - Hardscape- Pavers	Entire Site Entire Site NW NW	10,827 14,890 13,441 500 36 5,363 8,113 600 60 1 200 635 635 60	SF SF SF SF SF SF SF SF SF SF SF SF SF S	6 7 6 6 7 5 7 6 7 7 7	6-10 years 10+ years 10+ years 10+ years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	



						2110	W Greenleal AVENUE, Chicago, iE 00045
Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Trash Enclosure - Masonry	NW	2,860	SF	7	10+ years	
	Vehicular Screening	NW	375	LF	6	10+ years	
	Surface - Asphalt	South - Main Entrance 1	2,050	SF	7	10+ years	
_Playgrou	Ind						
,,,	Equipment - Pre K 3-5	Entire Site	1	EA	6	10+ years	
	Surface - Poured Surface	Entire Site	2,150	SF	7	10+ years	
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	1,122	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,729	SF	7	10+ years	
_Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years	Needs A flag - Missing
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



#### Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Usage	Room Edeation	Number	Number		Alea	Alea	0.00	Doard
Regular Classroom	Kindergarten	1st Floor	105	105	915	132	66	N	Y
Regular Classroom	Library	1st Floor	100	100	915	132	66	N	Ý
Regular Classroom	Office	3rd Floor	311	Adj. Room	415	66	33	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	815	132	66	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	815	132	66	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	104	104	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	200	NA	415	66	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	815	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	815	132	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	533	88	44	N	Y
Regular Classroom	Regular Classroom	3rd Floor	300	NA	417	66	33	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	815	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	533	88	44	N	Y
×	÷ ž				•		•		
Building : Addition 2									
Art Room	Art Room	2nd Floor	221	2-14	1,034	154	77	N	N
Computer Lab	Regular Classroom	2nd Floor	223	2-06	1,221	176	88	N	Y
Kindergarten	Kindergarten	1st Floor	112	1-28	1,220	232	116	N	N
Kindergarten	Kindergarten	1st Floor	114	1-31	1,220	232	116	N	Ν
Kindergarten	Kindergarten	1st Floor	116	1-34	1,220	232	116	N	Ν
Kindergarten	Pre School	1st Floor	115	1-12	1,172	176	88	N	N
Kindergarten	Regular Classroom	1st Floor	119	1-05/1-06	900	66	33	N	N



### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Language Lab	Regular Classroom	2nd Floor	219	2-15	450	66	33	N	N
Pre School	Pre School	1st Floor	110	1-25	1,220	232	116	N	N
Pre School	Pre School	1st Floor	111	1-18	1,172	176	88	N	N
Pre School	Pre School	1st Floor	113	1-15	1,172	176	88	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	2-19	900	132	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	2-17	925	132	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	2-20	900	132	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	2-16	900	66	33	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	2-21	900	132	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	2-22/2-23	900	132	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	222A	-	653	132	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	314/316	3-18/3-19	918	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	315	3-16	925	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	317	3-15	880	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	318	3-20	900	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	3-21	900	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	321	3-13	1,034	154	77	N	Y
Regular Classroom	Regular Classroom	3rd Floor	322	3-22/3-23	900	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	323	3-07	465	44	22	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	324	3-24	900	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	325	3-06	925	132	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	3-25	900	132	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	328	3-26	900	132	66	N	N
Special Program	Regular Classroom	2nd Floor	213	2-18	450	66	33	N	N
Special Program	Regular Classroom	3rd Floor	313	3-17	398	66	33	N	N
Special Program	Regular Classroom	3rd Floor	319	3-14	377	66	33	N	N
Special Program	Regular Classroom	3rd Floor	327	3-05	450	66	33	N	N
Store Room	Regular Classroom	2nd Floor	225	2-05	425	66	33	N	Ν