

## Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1957	2	42,735
Addition 1	1996	1	3,264
Addition 2	2001	2	17,980
Campus Total			63,979

Catego	ry : Exterior	В	uilding	: Main			
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	Boiler Room 11	1	EA	5	1-2 years	Rusting.
	Exterior Doors - Transom Lite	Boiler Room 11	1	EA	5	1-2 years	Rusting.
	Ramps - Concrete	Boiler Room 11	9	LF	6	6-10 years	
	Exterior Doors - Store Front	Entrance 1	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 1	26	LF	7	10+ years	
	Entrance Control - Audio and Video	Entrance 2	1	EA	7	6-10 years	
	Exterior Doors - Store Front	Entrance 2	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 2	3	EA	6	6-10 years	
	Exterior Stairs - Stone	Entrance 2	20	LF	6	10+ years	
	Exterior Doors - Store Front	Entrance 3	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 3	6	LF	5	2-5 years	Minor chipping around handrails.
	Ramps - Concrete	Entrance 3	12	LF	5	2-5 years	Minor chipping at beginning of ramp.
	Stair Handrail - Steel_Stair Handrail	Entrance 3	35	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Kitchen	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Kitchen	3	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Yard Storage 10	2	EA	6	6-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	600	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	42,735	SF	7	10+ years	



Categor	y : Exterior		В	uilding	: Main		1414 E 61SI PLACE, Chicago, IL 60637
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
	Exterior Lighting - Lighting	Entire Building	1	EA	7	10+ years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	6-10 years	
Roof Sys	tem						
	Access Ladder - Metal	1	1	EA	7	6-10 years	
	Chimney - Brick Chimney- Stainless Steel	1	36	LF	5	2-5 years	
	Liner						
	Coping - Stone	1	778	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	1	20	LF	6	6-10 years	
	Downspouts - Interior Downspouts	1	110	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	1	778	LF	6	6-10 years	
	Roof - Modified Bitumen	1	21,225	SF	5	2-5 years	Minor ponding and bubbling.
	Roof Hatch - Metal	1	3	EA	5	2-5 years	
	Roof Structure - Concrete	1	21,225	SF	7	10+ years	
	Coping - Stone	2	34	LF	6	6-10 years	
	Downspouts - Interior Downspouts	2	13	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	2	34	LF	7	10+ years	
	Roof - Modified Bitumen	2	285	SF	5	2-5 years	Minor ponding stains and bubbling.
	Roof Structure - Concrete	2	285	SF	7	10+ years	
						- <b>,</b>	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	152	SF	5	6-10 years	
	Cheek-Wall - Stone	Entire Building	56	SF	7	6-10 years	
	Exterior Walls - Brick	Entire Building	13,840	SF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	12	SF	5	2-5 years	
	Exterior Walls - Stone-Cast	Entire Building	340	SF	5	2-5 years	
	Exterior Walls - Stone-Cast	Entire Building	20	SF	5	6-10 years	
Windows							
	Guard - Guards perforated	Entire Building	1,826	SF	6	6-10 years	
	Lintels - Steel	Entire Building	689	LF	6	2-5 years	
	Windows - Casement Aluminum Double-	Entire Building	1,150	SF	6	10+ years	
	pane	5	,			2	
	Windows - Decorative	Entire Building	2,372	SF	6	6-10 years	
	Windows - Insulated Panel	Entire Building	223	SF	6	10+ years	
	Windows - Louver	Entire Building	79	SF	6	6-10 years	
Categor	y : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	cy System	Location	Quantity		Nullin	Replacement	Commonto



<u> </u>	schools						1414 E 61st PLACE, Chicago, IL 6063
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Automatic Transfer Switch	Boiler Room	1	EA	4	2-5 years	Older unit.
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	4	0-1 year	Older signs. Lighting dimmed.
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	4	0-1 year	Older signs. Lighting dimmed.
	Exit Signs - Gym	Entire Building	1	EA	4	0-1 year	Older signs. Lighting dimmed.
	Exit Signs - Gym	Entire Building	4	EA	4	0-1 year	Older signs. Lighting dimmed.
	Emergency Generator- Outdoor- Natural Gas - Below 60 KW	Entire Building	1	EA	4	2-5 years	Signs of rust.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	4	EA	2	0-1 year	Broken.
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,261	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,033	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,017	SF	6	6-10 years	
	Security System - CCTV	Entire Building	65,199	SF	3	1-2 years	Per building engineer cameras are
	Security System - COTV	Little Building	00,199		5	1-2 years	under repair - old rapid eye system
	Security System - Intrusion Detection	Entire Building	65,199	SF	6	6-10 years	
/lain Sei	vice						
	Main Electrical Service - 2000 A 120/240/3PH	Boiler Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	6-10 years	
	PA System	Entire Building	65,199	SF	6	6-10 years	Per building engineer, works throughout.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	6	10+ years	Labeling is worn.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						

Fire Alarm Panel

Entire Building

1 EA 6

2-5 years



Catego	ry : Fire Protection		В	uilding	: Main		
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	42,735	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	65,199	SF	5	2-5 years	
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
ump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Boiler Room	1	EA	4	0-1 year	Pump has evidence of leaking.
	Jockey Pump	Boiler Room	1	EA	5	0-1 year	Pump has evidence of leaking.
ategoi	ry : Mechanical		В	uilding	: Main		
ategoi	y . meenamear				· main	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Hand	ling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	2nd Floor	1	EA	5	2-5 years	
	Air Intake	2nd Floor	1	EA	5	6-10 years	
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	2nd Floor	1	EA	5	2-5 years	
oiler Sy	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	2-5 years	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	2-5 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	3	0-1 year	Actuator motor is missing. Damper are set in open position. Engineer reports that a bid is out to replace t motor.
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	4	0-1 year	Boiler 2 is operational
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	4	2-5 years	Boiler 2 is not operational.
	Piping - Condensate Pipe- Steel	Boiler Room	756	LF	5	2-5 years	Per building engineer there are clamps.
	Piping - Steam Pipe- Steel	Boiler Room	756	LF	5	2-5 years	Per building engineer there are clamps.
	Steam Traps	Boiler Room	27	EA	5	2-5 years	oumpo.
eatina I	Devices						
	Radiators - Steam	Entire Building	8	EA	5	2-5 years	Paint required.
	Radiators - Steam	Entire Building	1	EA	4	0-1 year	2nd floor restroom unit is damaged



	ry : Mechanical		B	uilding	· Main		1414 E 61st PLACE, Chicago, IL 6063
Jalego	ry . Mechanical			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							and leaks into 1st floor.
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	2-5 years	
	Cabinet Heaters - With Steam Coil	Entire Building	1	EA	5	1-2 years	Damaged and rusted.
	Wall Heater - Electric	Entire Building	6	EA	5	2-5 years	
<i></i>	cal Plumbing						
	Condensate-Steel or Galvanized	Entire Building	756	LF	5	2-5 years	
	Condensate-Steel or Galvanized	Entire Building	756	LF	5	2-5 years	
empera	ture Control						
	Electric Controls	Entire Building	42,735	SF	5	2-5 years	Old system.
	Electric Thermostat	Entire Building	27	EA	5	2-5 years	
Jnit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	27	EA	6	6-10 years	
/entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	2-5 years	All of these fans are running with n damage/rust.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	2-5 years	
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
•••••	Here True	Leastlen	Quantita		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
					-	<b>,</b>	
Piping		Frether Duilleli	10 707	05		10	
	Domestic Piping-Hot Water Return Lines	Entire Building	42,735	SF	7	10+ years	New pipes
	Domestic Piping-Hot Water Return Risers	Entire Building	42,735	SF	7	10+ years	New pipes
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,735	SF	7	10+ years	New piping
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,735	SF	7	10+ years	New pipes
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,735	SF	7	10+ years	New pipes
	Domestic Piping-Hot/Cold Water Supply	Entire Building	42,735	SF	7	10+ years	New pipes



1414 E 61st PLACE, Chicago, IL 60637 **Category : Plumbing Building : Main** Recommend Group Quantity UOM Location Item - Type Rank **Replacement** Comments (from Risers to Fixtures) Sanitary Piping Entire Building 42,735 SF 6 6-10 years Storm Piping Entire Building 42,735 SF 6-10 years 6 Vent Piping Entire Building 42,735 SF 6 6-10 years Pumps Pumps - Domestic Booster Pump-Duplex Boiler Room 1 ΕA 6 6-10 years Category : Room **Building : Main** 

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	121 A	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121 A	1	EA	6	10+ years	
	Floor - Tile	121 A	160	SF	6	6-10 years	
	Lighting - Pendent/Surface	121 A	2	EA	7	6-10 years	
	Walls - Concrete Block	121 A	215	SF	7	10+ years	
	Walls - Plaster/Drywall	121 A	220	SF	6	10+ years	
	Ceiling - Lay-in	121 B	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	121 B	1	EA	6	10+ years	
	Floor - Tile	121 B	160	SF	6	6-10 years	
	Lighting - Lay-in	121 B	2	EA	7	6-10 years	
	Walls - Concrete Block	121 B	109	SF	7	10+ years	
	Walls - Plaster/Drywall	121 B	326	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	150	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	500	SF	7	10+ years	
	AC Unit	Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	110	SF	6	10+ years	
	Doors - Steel Doors incl hw	Engineer's Office	2	EA	6	10+ years	
	Floor - Tile	Engineer's Office	110	SF	6	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Engineer's Office	463	SF	7	6-10 years	
	Work SInk	Engineer's Office	1	EA	7	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	466	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Main Office	1	EA	6	6-10 years	
	Floor - Tile	Main Office	466	SF	6	6-10 years	
	Lighting - Pendent/Surface	Main Office	6	ĒA	7	6-10 years	
					7	•	
			1		7		
		•	175		6	-	
	Lighting - Pendent/Surface Walls - Concrete Block AC Unit Ceiling - Plaster/Drywall	Main Office Main Office Principal's Office Principal's Office	6 624 1 175	EA SF EA SF	7 7 7 6	6-10 years 6-10 years 6-10 years 10+ years	



Catego	ry : Room		B	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Steel Doors incl hw	Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Principal's Office	175	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	3	EA	7	6-10 years	
	Walls - Concrete Block	Principal's Office	445	SF	7	10+ years	
	Ceiling - Lay-in	Room 121	184	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 121	1	EA	6	10+ years	
	Floor - Tile	Room 121	184	SF	6	6-10 years	
	Lighting - Lay-in	Room 121	2	EA	7	6-10 years	
	Storage/ Closet	Room 121	450	SF	7	6-10 years	
	Walls - Concrete Block	Room 121	117	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 121	350	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 203 - Office	164	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 203 - Office	1	ĒA	6	10+ years	
	Floor - Epoxy/ Painted	Room 203 - Office	164	SF	7	6-10 years	
	Lighting - Pendent/Surface	Room 203 - Office	4	EA	7	6-10 years	
	Walls - Concrete Block	Room 203 - Office	353	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 203 - Office	118	SF	7	10+ years	
	AC Unit	Room 207 - teacher's lounge	1	EA	7	6-10 years	Noisy unit
	Ceiling - Plaster/Drywall	Room 207 - teacher's lounge	262	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 207 - teacher's lounge	1	EA	6	10+ years	
	Floor - Tile	Room 207 - teacher's lounge	262	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 207 - teacher's lounge	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Room 207 - teacher's lounge	1	EA	5	0-1 year	Fixture not lit
	Walls - Concrete Block	Room 207 - teacher's lounge	626	SF	7	10+ years	
	AC Unit	room 118	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	room 118	354	SF	6	10+ years	
	Doors - Steel Doors incl hw	room 118	1	EA	6	6-10 years	
	Floor - Tile	room 118	354	SF	6	6-10 years	
	Lighting - Pendent/Surface	room 118	10	EA	7	6-10 years	
	Walls - Concrete Block	room 118	600	SF	7	10+ years	
			000	0	'	IUT years	
Symnas	ia						
	Ceiling - Splined	Room 109	2,392	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Room 109	6	EA	6	6-10 years	
	Floor - Tile	Room 109	2,392	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 109	12	EA	7	6-10 years	
	Sound System	Room 109	1	EA	7	6-10 years	
	Stage	Room 109	400	SF	6	6-10 years	
	Stage Curtain	Room 109	6	EA	7	6-10 years	
	Stage-Stairs - Asphalt	Room 109	30	LF	6	6-10 years	
	Walls - Concrete Block	Room 109	2,654	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 109	1,264	SF	7	10+ years	

Kitchen



r : Room Item - Type Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet Walls - Concrete Block	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 600 1 3 600	UOM SF EA	Rank 6	Recommend Replacement 6-10 years	Comments
Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	600 1 3	SF		Replacement	Comments
Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	600 1 3	SF			
Doors - Steel Doors incl hw Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor	1 3			6-10 years	
Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor 1st Floor 1st Floor	3		6	6-10 years	
Floor - Tile Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor 1st Floor		EA	6	6-10 years	
Lighting - Pendent/Surface Serving Line Storage/ Closet	1st Floor		SF	6	6-10 years	
Serving Line Storage/ Closet		9	EA	7	6-10 years	
Storage/ Closet	1st Floor	17	LF	6	6-10 years	
Walls - Concrete Block	1st Floor	160	SF	7	6-10 years	
	1st Floor	100	SF	7	6-10 years	
Walls - Structural Glazed Tile	1st Floor	590	SF	7		
Walls - Structural Glazed The	TSI FIOOI	590	35	1	6-10 years	
ower Room						
Accessories	Helper office inside boiler room	81	SF	5	6-10 years	
Ceiling - Plaster/Drywall	Helper office inside boiler room	81	SF	6		
Doors - Steel Doors incl hw	Helper office inside boiler room	1	EA	6		
Floor - Concrete		81				
Lighting - Pendent/Surface		1		7	•	
		285		7		
	· · · F · · · · · · · · · · · · · · · ·				,	
Doors - Steel Doors incl hw					10+ years	
Finishes	2nd Floor	150		7	10+ years	
Window AC Unit	2nd Floor	1	EA	7	6-10 years	
al/ Service Rooms						
	1st Floor	3.000	SF	7	10+ vears	
					•	
						121S
					-	1210
						2 SF of tile chipped.
		20				2 Si ol lie chipped.
Storage Room	2110 F1001	30	35	1	0-10 years	
Accessories	120 B	30		5	6-10 years	
Ceiling - Plaster/Drywall		30	SF	6	10+ years	
Doors - Wood Doors inclu hw	120 B	1	EA	6	10+ years	
Floor - Tile	120 B	1	SF	6	6-10 years	
Lavatory	120 B	1	EA	7	6-10 years	
		1	EA	7		
Walls - Concrete Block	120 B	200	SF	7		
		1				
	Accessories Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Concrete Lighting - Pendent/Surface Walls - Concrete Block Doors - Steel Doors incl hw Finishes Window AC Unit al/ Service Rooms Boiler Room Janitor's Closet Storage Room Storage Room Storage Room Storage Room Storage Room Janitor's Closet Storage Room Storage Room Storage Room Janitor's Closet Storage Room Janitor's Clo	AccessoriesHelper office inside boiler roomCeiling - Plaster/DrywallHelper office inside boiler roomDoors - Steel Doors incl hwHelper office inside boiler roomFloor - ConcreteHelper office inside boiler roomLighting - Pendent/SurfaceHelper office inside boiler roomWalls - Concrete BlockHelper office inside boiler roomDoors - Steel Doors incl hw2nd FloorFinishes2nd FloorWindow AC Unit2nd FloorAl/ Service Rooms1st FloorBoiler Room1st FloorStorage Room2nd FloorStorage Room1st FloorStorage Room2nd FloorStorage Room2nd FloorStorage Room1st FloorLantor's Closet2nd FloorStorage Room2nd FloorStorage Room2nd FloorLatter Storage Room2nd FloorStorage Room2nd FloorLatter Storage Room2nd FloorLatter Storage Room2nd FloorLatter Storage Room<	AccessoriesHelper office inside boiler room81Ceiling - Plaster/DrywallHelper office inside boiler room81Doors - Steel Doors incl hwHelper office inside boiler room1Lighting - Pendent/SurfaceHelper office inside boiler room1Walls - Concrete BlockHelper office inside boiler room1Doors - Steel Doors incl hw2nd Floor1Finishes2nd Floor1Doors - Steel Doors incl hw2nd Floor1Finishes2nd Floor1Mindow AC Unit2nd Floor1al/ Service Rooms13,000Janitor's Closet1st Floor3000Janitor's Closet1st Floor120Storage Room1st Floor250Storage Room1st Floor200Storage Room1st Floor3000Storage Room1st Floor200Storage Room1st Floor300Storage Room1st Floor300Storage Room1st Floor300Storage Room1st Floor30Ceiling - Plaster/Drywall120 B30Ceiling - Plaster/Drywall120 B1Lavatory120 B1Lavatory120 B1Lavatory120 B1Lighting - Pendent/Surface120 B1Lighting - Pendent/Surface120 B1Lighting - Concrete Block120 B1Value Closet120 B1Lighting - Concrete Block120 B	AccessoriesHelper office inside boiler room81SFCeiling - Plaster/DrywallHelper office inside boiler room81SFDoors - Steel Doors incl hwHelper office inside boiler room1EAFloor - ConcreteHelper office inside boiler room1EALighting - Pendent/SurfaceHelper office inside boiler room1EAWalls - Concrete BlockHelper office inside boiler room285SFDoors - Steel Doors incl hw2nd Floor1EAFinishes2nd Floor1EAWindow AC Unit2nd Floor1EAJ/ Service Rooms1st Floor3,000SFBoiler Room1st Floor50SFStorage Room1st Floor120SFStorage Room1st Floor220SFJanitor's Closet2nd Floor120SFStorage Room1st Floor300SFStorage Room1st Floor30SFAccessories2nd Floor32SFJanitor's Closet2nd Floor30SFStorage Room1st Floor30SFStorage Room1st Floor30SFJanitor's Closet2nd Floor30SFJanitor's Closet2nd Floor30SFJanitor's Closet2nd Floor30SFJanitor's Closet2nd Floor30SFJanitor's Closet2nd Floor30SFLighting - Plaster/Drywall120 B </td <td>AccessoriesHelper office inside boiler room81SF5Ceiling - Plaster/DrywallHelper office inside boiler room81SF6Doors - Steel Doors incl hwHelper office inside boiler room1EA6Floor - ConcreteHelper office inside boiler room1EA7Lighting - Pendent/SurfaceHelper office inside boiler room1EA7Walls - Concrete BlockHelper office inside boiler room285SF7Doors - Steel Doors incl hw2nd Floor1EA6Finishes2nd Floor150SF7Window AC Unit2nd Floor1EA7Al/ Service Rooms50SF7Boiler Room1st Floor3,000SF7Janitor's Closet1st Floor50SF7Storage Room1st Floor120SF7Storage Room1st Floor22SF5Janitor's Closet2nd Floor30SF7Storage Room1st Floor30SF7Storage Room1st Floor30SF5Storage Room1st Floor30SF5Ceiling - Plaster/Drywall120 B30SF5Ceiling - Plaster/Drywall120 B1SF6Doors - Wood Doors inclu hw120 B1SF6Lavatory120 B1SF6Lavatory120 B1SF<td< td=""><td>AccessoriesHelper office inside boiler room81SF56-10 yearsCeiling - Plaster/DrywallHelper office inside boiler room81SF610+ yearsDoors - Steel Doors incl hwHelper office inside boiler room1EA610+ yearsFloor - ConcreteHelper office inside boiler room1EA76-10 yearsLighting - Pendent/SurfaceHelper office inside boiler room1EA76-10 yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsPoors - Steel Doors incl hw2nd Floor1EA610+ yearsFinishes2nd Floor1EA76-10 yearsWindow AC Unit2nd Floor1EA76-10 yearsal/ Service Rooms3,000SF710+ yearsBoiler Room1st Floor3,000SF710+ yearsStorage Room1st Floor120SF710+ yearsStorage Room1st Floor20SF710+ yearsStorage Room1st Floor30SF56-10 yearsJanitor's Closet2nd Floor32SF56-10 yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF5</td></td<></td>	AccessoriesHelper office inside boiler room81SF5Ceiling - Plaster/DrywallHelper office inside boiler room81SF6Doors - Steel Doors incl hwHelper office inside boiler room1EA6Floor - ConcreteHelper office inside boiler room1EA7Lighting - Pendent/SurfaceHelper office inside boiler room1EA7Walls - Concrete BlockHelper office inside boiler room285SF7Doors - Steel Doors incl hw2nd Floor1EA6Finishes2nd Floor150SF7Window AC Unit2nd Floor1EA7Al/ Service Rooms50SF7Boiler Room1st Floor3,000SF7Janitor's Closet1st Floor50SF7Storage Room1st Floor120SF7Storage Room1st Floor22SF5Janitor's Closet2nd Floor30SF7Storage Room1st Floor30SF7Storage Room1st Floor30SF5Storage Room1st Floor30SF5Ceiling - Plaster/Drywall120 B30SF5Ceiling - Plaster/Drywall120 B1SF6Doors - Wood Doors inclu hw120 B1SF6Lavatory120 B1SF6Lavatory120 B1SF <td< td=""><td>AccessoriesHelper office inside boiler room81SF56-10 yearsCeiling - Plaster/DrywallHelper office inside boiler room81SF610+ yearsDoors - Steel Doors incl hwHelper office inside boiler room1EA610+ yearsFloor - ConcreteHelper office inside boiler room1EA76-10 yearsLighting - Pendent/SurfaceHelper office inside boiler room1EA76-10 yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsPoors - Steel Doors incl hw2nd Floor1EA610+ yearsFinishes2nd Floor1EA76-10 yearsWindow AC Unit2nd Floor1EA76-10 yearsal/ Service Rooms3,000SF710+ yearsBoiler Room1st Floor3,000SF710+ yearsStorage Room1st Floor120SF710+ yearsStorage Room1st Floor20SF710+ yearsStorage Room1st Floor30SF56-10 yearsJanitor's Closet2nd Floor32SF56-10 yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF5</td></td<>	AccessoriesHelper office inside boiler room81SF56-10 yearsCeiling - Plaster/DrywallHelper office inside boiler room81SF610+ yearsDoors - Steel Doors incl hwHelper office inside boiler room1EA610+ yearsFloor - ConcreteHelper office inside boiler room1EA76-10 yearsLighting - Pendent/SurfaceHelper office inside boiler room1EA76-10 yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsDoors - Steel Doors incl hw2nd Floor1EA610+ yearsPoors - Steel Doors incl hw2nd Floor1EA610+ yearsFinishes2nd Floor1EA76-10 yearsWindow AC Unit2nd Floor1EA76-10 yearsal/ Service Rooms3,000SF710+ yearsBoiler Room1st Floor3,000SF710+ yearsStorage Room1st Floor120SF710+ yearsStorage Room1st Floor20SF710+ yearsStorage Room1st Floor30SF56-10 yearsJanitor's Closet2nd Floor32SF56-10 yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF710+ yearsStorage Room1st Floor30SF5



Category : Room Buildin					Building : Main					
e alege	<b>, , , , , , , , , ,</b>		_			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	121	34	SF	6	10+ years				
	Doors - Wood Doors inclu hw	121	1	EA	6	10+ years				
	Floor - Tile	121	34	SF	6	6-10 years				
	Lavatory	121	1	EA	7	6-10 years				
	Lighting - Lay-in	121	1	EA	7	6-10 years				
	Walls - Concrete Block	121	189	SF	7	10+ years				
	Water Closet	121	1	EA	7	6-10 years				
	Accessories	1st Floor	256	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	256	SF	6	10+ years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor	256	SF	6	6-10 years				
	Floor Drain	1st Floor	1	EA	7	6-10 years				
	Hand Dryer	1st Floor	1	EA	7	6-10 years				
	Lavatory	1st Floor	1	EA	7	6-10 years				
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years				
	Partitions	1st Floor	6	EA	7	6-10 years				
	Walls - Concrete Block	1st Floor	278	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor	278	SF	7	10+ years				
	Water Closet	1st Floor	6	EA	7	6-10 years				
	Accessories	1st Floor	226	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	226	SF	6	10+ years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor	226	SF	6	6-10 years				
	Floor Drain	1st Floor	1	EA	7	6-10 years				
	Hand Dryer	1st Floor	1	EA	7	6-10 years				
	Lavatory	1st Floor	1	EA	7	6-10 years				
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years				
	Partitions	1st Floor	2	EA	7	6-10 years				
	Urinals	1st Floor	4	EA	7	6-10 years				
	Walls - Concrete Block	1st Floor	266	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor	264	SF	6	10+ years				
	Walls - Structural Glazed Tile	1st Floor	2	SF	5	1-2 years	Cracks.			
	Water Closet	1st Floor	2	EA	7	6-10 years				
	Accessories	207- Staff Restroom	57	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	207- Staff Restroom	57	SF	6	10+ years				
	Doors - Steel Doors incl hw	207- Staff Restroom	1	EA	6	10+ years				
	Floor - Tile	207- Staff Restroom	57	SF	6	6-10 years				
	Lavatory	207- Staff Restroom	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	207- Staff Restroom	1	EA	7	6-10 years				
	Partitions	207- Staff Restroom	2	EA	7	6-10 years				
	Walls - Concrete Block	207- Staff Restroom	251	SF	7	10+ years				
	Water Closet	207- Staff Restroom	2	EA	7	6-10 years				



	1414 E 61st PLACE, Chicago, IL 60637								
Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	2nd Floor	255	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	255	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	255	SF	6	6-10 years			
	Floor Drain	2nd Floor	1	EA	7	6-10 years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years			
	Partitions	2nd Floor	7	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	144	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	433	SF	7	10+ years			
	Water Closet	2nd Floor	7	EA	7	6-10 years			
	Accessories	2nd Floor	250	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	250	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	6-10 years			
	Floor Drain	2nd Floor	1	EA	7	6-10 years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years			
	Partitions	2nd Floor	1	EA	7	6-10 years			
	Urinals	2nd Floor	5	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	143	SF	7	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	429	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	7	6-10 years			
	Accessories	Engineer's Office Toilet	15	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Engineer's Office Toilet	15	SF	6	10+ years			
	Doors - Steel Doors incl hw	Engineer's Office Toilet	1	EA	6	10+ years			
	Floor - Tile	Engineer's Office Toilet	15	SF	6	6-10 years			
	Lighting - Lay-in	Engineer's Office Toilet	1	EA	7	6-10 years			
	Walls - Concrete Block	Engineer's Office Toilet	111	SF	6	10+ years			
	Water Closet	Engineer's Office Toilet	1	EA	7	6-10 years			
	Accessories	Helper office restroom	15	SF	7	6-10 years			
	Ceiling - Lay-in	Helper office restroom	15	SF	6	10+ years			
	Doors - Steel Doors incl hw	Helper office restroom	1	EA	6	10+ years			
	Floor - Tile	Helper office restroom	15	SF	6	6-10 years			
	Lighting - Lay-in	Helper office restroom	1	EA	7	6-10 years			
	Walls - Concrete Block	Helper office restroom	220	SF	7	10+ years			
	Water Closet	Helper office restroom	1	EA	7	6-10 years			
	Accessories	Main Office Toilet	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Main Office Toilet	30	SF	6	10+ years			
	Doors - Steel Doors incl hw	Main Office Toilet	1	EA	6	10+ years			
	Floor - Tile	Main Office Toilet	30	SF	6	6-10 years			
	Lavatory	Main Office Toilet	1	EA	7	6-10 years			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Main Office Toilet	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Main Office Toilet	1	EA	7	6-10 years	
	Walls - Concrete Block	Main Office Toilet	154	SF	7	10+ years	
	Water Closet	Main Office Toilet	1	EA	7	6-10 years	
	Accessories	Men's Toilet 2nd floor	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Toilet 2nd floor	60	SF	6	10+ years	
	Doors - Steel Doors incl hw	Men's Toilet 2nd floor	1	EA	6	10+ years	
	Floor - Tile	Men's Toilet 2nd floor	60	SF	6	6-10 years	
	Lavatory	Men's Toilet 2nd floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Men's Toilet 2nd floor	2	EA	7	6-10 years	
	Partitions	Men's Toilet 2nd floor	1	EA	7	6-10 years	
	Walls - Concrete Block	Men's Toilet 2nd floor	286	SF	7	10+ years	
	Walls - Concrete Block	Men's Toilet 2nd floor	3	SF	6	10+ years	Paint not covering wall from where urinal was removed.
	Water Closet	Men's Toilet 2nd floor	1	EA	7	6-10 years	

5.	ry : Classroom			uilding		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroo	m #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	736	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	736	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	954	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	762	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	762	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	962	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	

\_Classroom #104 (Regular Classroom)



Catego	ategory : Classroom			uilding	1414 E 61st PLACE, Chicago, IL 60637		
Jaleyo	19.01035100111		D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00p	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	29	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	733	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	733	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	937	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	732	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	728	SF	6	6-10 years	
	Floor - Tile	1st Floor	4	SF	4	0-1 year	Missing.
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	-
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	954	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	887	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3	SF	5	0-1 year	Cracking/paint peeling.
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	733	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	



Group Classroon Classroon	y : Classroom Item - Type Marker Board Walls - Concrete Block m #114 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block m #116 (Regular Classroom) AC Units	Location 1st Floor 1st Floor	B Quantity 20 937 1 8 765 1 765 20 20 911	UOM LF SF EA LF SF EA SF EA LF SF	Rank 6 7 7 6 6 6 6 6 7 7 7	Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Comments
Classroon	Marker Board Walls - Concrete Block n #114 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor	20 937 1 8 765 1 765 20 20	LF SF EA LF EA SF EA LF	6 7 6 6 6 6 7 7	Replacement6-10 years10+ years6-10 years6-10 years10+ years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years6-10 years	Comments
Classroon	Marker Board Walls - Concrete Block n #114 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor	20 937 1 8 765 1 765 20 20	LF SF EA LF EA SF EA LF	6 7 6 6 6 6 7 7	6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	Comments
Classroon	Walls - Concrete Block n #114 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	937 1 8 765 1 765 20 20	SF EA LF SF EA SF EA LF	7 7 6 6 6 6 7 7	10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	
Classroon	n #114 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 8 765 1 765 20 20	EA LF SF EA SF EA LF	7 6 6 6 7 7	6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	
Classroon	AC Units Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block m #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	8 765 1 765 20 20	LF SF EA EA LF	6 6 6 7 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years	
Classroon	Casework Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	8 765 1 765 20 20	LF SF EA EA LF	6 6 6 7 7	6-10 years 10+ years 6-10 years 6-10 years 6-10 years	
Classroon	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block m #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	765 1 765 20 20	SF EA SF EA LF	6 6 7 7	10+ years 6-10 years 6-10 years 6-10 years	
Classroon	Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor 1st Floor	1 765 20 20	EA SF EA LF	6 6 7 7	6-10 years 6-10 years 6-10 years	
Classroon	Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor 1st Floor	765 20 20	SF EA LF	6 7 7	6-10 years 6-10 years 6-10 years	
Classroon	Lighting - Pendent/Surface Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor 1st Floor	20 20	EA LF	7 7	6-10 years 6-10 years	
Classroon	Marker Board Walls - Concrete Block n #116 (Regular Classroom)	1st Floor	20	EA LF	7	6-10 years	
Classroon	Marker Board Walls - Concrete Block n #116 (Regular Classroom)				7		
Classroon	Walls - Concrete Block n #116 (Regular Classroom)					6-10 years	
					7	10+ years	
		1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	767	SF	6	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	767	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20		7	6-10 years	
	Walls - Concrete Block	1st Floor	968	SF	7		
	Work Sink		900	EA	7	10+ years	
	WORK SINK	1st Floor	I	EA	1	6-10 years	
	n #120 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	48	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,060	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,060	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,210	SF	7	10+ years	
Classroon	n #201 (Music Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	48	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	500	SF	4	1-2 years	Paint peeling in several areas of
	<b>č</b>		500		-+	1-2 years	ceiling.
	Chalk Board	2nd Floor	6	LF	4	2-5 years	-



Catogo	tegory : Classroom			Building : Main			1414 E 61st PLACE, Chicago, IL 6063
Catego	y . Glassiooni		В	unung	. wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Doors - Steel Doors incl hw	2nd Floor	Quantity 1	EA	6	6-10 years	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,100	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor		EA	7	6-10 years	
	Marker Board	2nd Floor	30 30		7	•	
	Walls - Concrete Block	2nd Floor 2nd Floor	30 1,045	SF	7	6-10 years 10+ years	
			1,045	эг	'	TO+ years	
Classroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	762	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	762	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	977	SF	7	10+ years	
lassroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	17	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	750	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	955	SF	7	10+ years	
1855100	m #205 (Regular Classroom) AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	8		6		
		2nd Floor 2nd Floor		SF	-	6-10 years	
	Ceiling - Plaster/Drywall		737	SF	6 5	10+ years	Water demoge
	Ceiling - Plaster/Drywall	2nd Floor	10	LF	-	0-1 year	Water damage.
	Chalk Board	2nd Floor	20		4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	747	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	953	SF	7	10+ years	
lassroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA LF	7	6-10 years	
		2nd Floor	8		6	6-10 years	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	2nd Floor	722	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Paint peeling & water damage.
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	732	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	941	SF	7	10+ years	
						,	
lassroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	734	SF	5	0-1 year	Cracking and water damage
							throughout.
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	734	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	943	SF	7	10+ years	
laceroo	m #210 (Regular Classroom)						
1922100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	370	SF	7		
	Doors - Steel Doors incl hw	2nd Floor 2nd Floor		EA	6 6	10+ years	
	Floor - Tile	2nd Floor	1 370	SF	6	10+ years 6-10 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	10 6	EA LF	7 7	6-10 years	
	Marker Board Walls - Concrete Block	2nd Floor 2nd Floor	692	SF		6-10 years	
	Work Sink	2nd Floor 2nd Floor	092	EA	7 7	10+ years	
	WORK SINK	2110 F1001	I	EA	1	10+ years	
lassroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	732	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	936	SF	7	10+ years	
lassroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 vears	
						-	
Classroo	m #214 (Regular Classroom)	2nd Floor 2nd Floor 2nd Floor 2nd Floor		EA LF SF	7 6 6	6-10 years 6-10 years 10+ years	



Categol							
	ategory : Classroom			uilding	: Main		
<b>C</b>	Items Trune	Leastion	Quentitu		Dauk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	733	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	943	SF	7	10+ years	
Classroo	m #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	801	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	801	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	992	SF	7	10+ years	
Classroo	m #218 (Regular Classroom)						
0.000.000	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	749	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	749	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	955	SF	7	10+ years	
		2110 F1001	900	ЗГ	I	TO+ years	
Classroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	465	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	465	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	765	SF	7	10+ years	
Classroo	m #220 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
					6	6-10 years	



Cotorio				ي بالمانين	Main		1414 E 61st PLACE, Chicago, IL 6063
Catego	ry : Classroom		В	uilding	: Main	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
broup	Ceiling - Plaster/Drywall	2nd Floor	Quantity 748	SF	6	Replacement 10+ years	Comments
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	748	SF		•	
	Lighting - Pendent/Surface		-		6	6-10 years	
		2nd Floor 2nd Floor	20	EA	7	6-10 years	
	Marker Board		20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	955	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	m #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	748	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	954	SF	7	10+ years	
	Walls - Concrete Diock	21011001	554	01	,	TOF years	
lassroo	m #222 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	748	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	954	SF	7	10+ years	
atego	ry : Interior		В	uilding			
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Ceiling - Plaster/Drywall	1st Floor	1,514	SF	6	10+ years	
	Ceiling - Splined	1st Floor	560	SF			
	Doors - Store Front	1st Floor	560 9	EA	6	6-10 years	
			9		6	6-10 years	
	Drinking Fountains - Double Fountain	1st Floor		EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	2,074	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	106	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,885	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,885	SF	7	10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor West 1st Floor West	90 930	SF SF	6 6	6-10 years	



Group	y : Interior Item - Type			uilding	····		
		Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Terrazzo	1st Floor West	90	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor West	930	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor West	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor West	12	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor West	64	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor West	180	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor West	378	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor West	378	SF	7	10+ years	
				SF			
	Ceiling - Plaster/Drywall	2nd Floor	2,153		6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,153	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	.17	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	157	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,958	SF	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	1,958	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor West	784	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor West	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor West	784	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor West	12	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor West	70	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor West	713	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor West	713	SF	7	6-10 years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	36	EA	5	0-1 year	7 security cameras don't work and
				<u>L</u> /(	Ū	0 i your	need repair or replacement per security staff and principal
Noiro							
stairs	Ceiling - Plaster/Drywall	East Stairs	260	SF	6	10+ years	
	Floor - Terrazzo	East Stairs	125	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	East Stairs	66	SF	6	6-10 years	
	Handrails	East Stairs	60	LF	7	6-10 years	
	Lighting - Pendent/Surface	East Stairs	1	EA	7	6-10 years	
	Stairs - Terrazzo	East Stairs	110	LF	7	6-10 years	
	Walls - Plaster/Drywall	East Stairs	459	SF	7	10+ years	
	Walls - Structural Glazed Tile	East Stairs	459	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West Stairs	260	SF	6	10+ years	
	Floor - Terrazzo	West Stairs	125	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	West Stairs	66	SF	6	6-10 years	
	Handrails	West Stairs West Stairs	60	SF LF	6 7	6-10 years	
	Lighting - Pendent/Surface		60 1	EA	7	•	
	Stairs - Terrazzo	West Stairs West Stairs	110	LF	7	6-10 years 10+ years	



Catego	ry : Interior		B	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall Walls - Structural Glazed Tile	West Stairs West Stairs	459 459	SF SF	7 7	10+ years 10+ years	



Category : Exterior			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	7	1	EA	5	1-2 years	Minor rusting.
	Exterior Stairs - Concrete	7	10	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	8	1	EA	6	6-10 years	
	Ramps - Concrete	8	10	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	8	24	LF	6	6-10 years	
Foundatio	on						
	Foundation - Concrete	Entire Building	115	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	3,264	SF	7	10+ years	
		Linito Dallallig	0,201	0.	•	let youro	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
Roof Sys	stem						
-	Coping - Stone	Entire Building	125	LF	6	10+ years	
	Downspouts - Interior Downspouts	Entire Building	52	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Entire Building	125	LF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	3,264	SF	5	1-2 years	Roof is bubbling, ponding, and
			0,201	5.	Ũ	jouro	cracking throughout.
	Roof Structure - Concrete	Entire Building	3,264	SF	7	10+ years	ordoning inroughout.
Walls	Exterior Walls - Brick	Entire Building	1,104	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	265	SF	5	2-5 years	Missing mortar.
	Exterior wails - Drick	Entire Building	205	36	5	2-5 years	Missing mortal.
Windows	3						
	Guard - Guards perforated	Entire Building	126	SF	6	6-10 years	
	Lintels - Steel	Entire Building	36	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	126	SF	6	10+ years	
Categor	ry : Electrical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	ncy System						
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years	
		Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entitle Dullullig					
	Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs		-	EA	-		
	Emergency Battery Packs - Lunchrooms Exit Signs - Corridors and Stairs Exit Signs - Lunchroom	Entire Building Entire Building Entire Building	2		7 7	6-10 years 6-10 years	



Catego	ry : Electrical		В	uilding	: Additi	on 1	
_						Recommend	_
Group	Item - Type Stairs	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Lunchrooms	Entire Building	2,093	SF	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi	on 1	
Ŭ				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	3,264	SF	6	6-10 years	
Sprinkler	r System						
орппкіе	Sprinkler Heads	Entire Building	3,264	SF	7	10+ years	
	Sprinkler Piping	Entire Building	3,264	SF	7	10+ years	Repaired, no issues per building
		-				-	engineer.
	Wet Sprinkler System	Entire Building	3,264	SF	7	10+ years	Repaired, no issues per building engineer.
Catego	ry : Mechanical		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc							
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	6	6-10 years	
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	2-5 years	Rust.
	Gas Heating and DX Cooling Coil - 11 - 20 tons						
Heating	Devices						
libuting	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	2-5 years	Signs of rust observed.
	Fin Tube - Steam	Entire Building	48	LF	6	6-10 years	Painting required.
Mechani	cal Plumbing						
Mechani	Condensate-Steel or Galvanized	Entire Building	100	LF	6	6-10 years	
	Condensate-Steel or Galvanized	Entire Building	100	LF	6	6-10 years	
Tempera	ature Control						
•	Electric Controls	Entire Building	3,264	SF	6	6-10 years	
	Electric Thermostat	Entire Building	2	EA	4	0-1 year	Do not work, broken.
Ventilatio	วท						



**Building : Addition 1 Category : Mechanical** Recommend Group Item - Type Location UOM **Replacement** Comments Quantity Rank Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 2-5 years ΕA 1 5 CFM Exhaust Fans- Roof Mounted - Less than ΕA 6-10 years Entire Building 2 6

### Category : Plumbing

500 CFM

Recommend
Replacement Comments
6-10 years
6-10 years
6.10 vecro
6-10 years
6-10 years
6-10 years
6-10 years
6-10 years
6-10 years
on 1
Recommend
Replacement Comments
10+ years
10+ years
6-10 years
6-10 years
10+ years
10+ years
,
•
10+ years 10+ years 6-10 years 6-10 years



Catego	ry : Room		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	1st Floor	155	SF	7	6-10 years	
Restroo	m						
	Accessories	Lunchroom Staff restroom inside locker room	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Lunchroom Staff restroom inside locker room	60	SF	6	10+ years	
	Doors - Steel Doors incl hw	Lunchroom Staff restroom inside locker room	1	EA	6	10+ years	
	Floor - Tile	Lunchroom Staff restroom inside locker room	60	SF	6	6-10 years	
	Floor Drain	Lunchroom Staff restroom inside locker room	1	EA	7	6-10 years	
	Lavatory	Lunchroom Staff restroom inside locker room	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Lunchroom Staff restroom inside locker room	2	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Lunchroom Staff restroom inside locker room	227	SF	7	10+ years	
	Water Closet	Lunchroom Staff restroom inside locker room	1	EA	7	6-10 years	

## Category · Interior

Category : Interior			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	185	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	181	SF	5	6-10 years	
	Floor - Tile/Sheet	1st Floor	4	SF	4	0-1 year	Missing.
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Walls - Masonry	1st Floor	502	SF	7	10+ years	



**Category : Exterior** 

**Building : Addition 2** 

Recommend Location Replacement Item - Type Quantity UOM **Comments** Group Rank Entrance Exterior Doors - Store Front 3 FΑ 7 4 10+ years 4 3 ΕA 7 Exterior Doors - Transom Lite 10+ years Exterior Doors - Store Front 5 2 EΑ 7 10+ years Exterior Doors - Transom Lite 5 2 ΕA 7 10+ years Exterior Doors - Store Front 6 2 EΑ 7 10+ years Exterior Doors - Transom Lite 2 6 EΑ 7 10+ years Foundation Foundation - Concrete Entire Building 328 LF 7 10+ years SF Superstructure - Metal Deck/ Concrete Entire Building 17,980 7 10+ years Topping Liahtina Exterior Lighting - Wall Mounted Entire Building 8 ΕA 6 6-10 years Roof System Access Ladder - Metal Entire Building 1 ΕA 7 10+ years 393 LF Coping - Stone Entire Building 6 10+ vears LF **Downspouts - Interior Downspouts** Entire Building 104 6 6-10 years Parapet - Parapet < 16" Height Entire Building 393 LF 7 6-10 years Roof - Modified Bitumen Entire Building 8,996 SF 5 2-5 years Minor cracking, bubbling, and ponding. Roof Hatch - Metal 7 Entire Building ΕA 10+ years 1 SF Roof Structure - Steel / Metal Deck/ Entire Building 8.990 7 10+ years Concrete Topping LF Coping - Metal West Entrances 20 6 2-5 years LF Downspouts - Interior Downspouts West Entrances 12 7 6-10 vears Roof - Modified Bitumen SF 5 West Entrances 70 2-5 years Cracking. Roof Structure - Concrete 70 SF 7 2-5 years West Entrances Walls SF Canopy - Concrete/ Stucco Entire Building 120 6 10+ years SF Exterior Walls - Brick Entire Building 7 10+ years 9.567 Exterior Walls - Stone-Cast Entire Building 874 SF 7 10+ years Windows Guard - Guards perforated Entire Building 683 SF 6 6-10 years Lintels - Steel Entire Building 192 LF 6 6-10 years SF Windows - Decorative Entire Building 80 6 6-10 years SF Windows - Sash Aluminum Double-pane Entire Building 1,365 6 6-10 years



ALLA S							1414 E 61st PLACE, Chicago, IL 6063
Catego	ry : Exterior		В	uilding	: Additi	on 2	
-				Ū		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Electrical		Building : Addition 2				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	cy System						
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	5	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,711	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	6-10 years	Can not locate transformers on firs floor. Engineer could not either.
Catego	ry : Fire Protection		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	19,200	SF	6	6-10 years	
Sprinkler	System						
	Sprinkler Heads	Entire Building	19,200	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	19,200	SF	7	6-10 years	
	Wet Sprinkler System	Entire Building	19,200	SF	7	6-10 years	
Catego	ry : Mechanical		В	uilding	on 2		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	2nd Floor	1	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM	2nd Floor	1	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils -	Entire Building	1	EA	6	6-10 years	



-			ب مالماني	. A al al !+ !	1414 E 61st PLACE, Chicago, IL 60637		
Catego	ry : Mechanical		В	uilaing	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	12001-20000 cfm						
	Air Intake	Entire Building	1	EA	6	6-10 years	
	VAV Box	Entire Building	2	EA	6	6-10 years	
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	10	EA	6	6-10 years	Located in ceiling, could not access.
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - Less than 5 tons	Roof	1	EA	5	2-5 years	Signs of deterioration.
Boiler Sy	vstems						
-	Piping - Condensate Pipe- Steel	Entire Building	100	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	100	LF	6	6-10 years	
	Steam Traps	Entire Building	6	EA	6	6-10 years	
	Chemical Pot Feeder	Mechanical Room	1	EA	6	6-10 years	
Heat Exc							
	Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	1	EA	6	6-10 years	
Heating	Devices						
•	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	5	EA	6	6-10 years	
	Radiator Panels - Hot Water	Entire Building	3	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Mechanical Room	186	LF	6	6-10 years	
Tempera	ture Control						
	DDC System	Entire Building	19,200	SF	5	6-10 years	
	Thermostats - DDC	Entire Building	15	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	



Recommend Replacement				
Replacement				
	Comments			
6-10 years				
6-10 years				
,				
e re jeure				
6-10 years				
-				
6-10 years				
6-10 years				
6-10 years				
Building : Addition 2				
	Comments			
6-10 vears				
6-10 years				
6-10 years				
10+ years				
0.40				
6-10 years				
10+ years				
10+ years				
6-10 years				
6-10 years				
6-10 years				
6-10 years				
	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years ion 2 Recommend Replacement 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years			



Catego	ry : Room		В	uilding	: Additi	on 2	Building : Addition 2							
	·			3		Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments							
•	Water Closet	124	1	EA	7	6-10 years								
	Accessories	126	41	SF	7	6-10 years								
	Ceiling - Lay-in	126	41	SF	6	10+ years								
	Doors - Wood Doors inclu hw	126	1	ĒA	6	10+ years								
	Floor - Tile	126	41	SF	6	6-10 years								
	Floor Drain	126	1	EA	7	6-10 years								
	Lavatory	126	1	EA	7	6-10 years								
	Lighting - Lay-in	126	1	EA	7	6-10 years								
	Walls - Concrete Block	126	235	SF	7	10+ years								
	Water Closet	126	1	EA	7	6-10 years								
	Accessories	1st Floor Girls	45	SF	7	6-10 years								
	Ceiling - Plaster/Drywall	1st Floor Girls	45	SF	6	10+ years								
	Doors - Steel Doors incl hw	1st Floor Girls	1	EA	7	10+ years								
	Floor - Terrazzo	1st Floor Girls	45	SF	6	6-10 years								
	Floor Drain	1st Floor Girls	1	EA	7	6-10 years								
	Lavatory	1st Floor Girls	1	EA	7	6-10 years								
	Lighting - Lay-in	1st Floor Girls	1	EA	7	6-10 years								
	Walls - Structural Glazed Tile	1st Floor Girls	220	SF	7	10+ years								
	Water Closet	1st Floor Girls	1	EA	7	6-10 years								
	Accessories	1st Floor Staff	105	SF	7	6-10 years								
	Ceiling - Plaster/Drywall	1st Floor Staff	105	SF	6									
	Doors - Steel Doors incl hw	1st Floor Staff	105	EA	6	10+ years								
	Floor - Terrazzo	1st Floor Staff	105	SF	6	10+ years 6-10 years								
	Floor Drain	1st Floor Staff	105	EA	7	6-10 years								
		1st Floor Staff	1	EA	7	6-10 years								
	Lavatory	1st Floor Staff	2	EA	7	•								
	Lighting - Lay-in Walls - Structural Glazed Tile	1st Floor Staff	389	SF	7	6-10 years								
	Water Closet	1st Floor Staff		EA	7	10+ years 6-10 years								
	Accessories	1st floor Boys	47	SF	7	6-10 years								
				SF										
	Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st floor Boys	47 1		6 7	10+ years								
		1st floor Boys 1st floor Boys	47	EA SF		10+ years								
	Floor - Terrazzo Floor Drain		47	EA	6 7	6-10 years								
		1st floor Boys	1	EA	7	6-10 years								
	Lavatory	1st floor Boys	1	EA	7	6-10 years								
	Lighting - Lay-in	1st floor Boys	1	EA	7	6-10 years								
	Urinals	1st floor Boys		SF		6-10 years								
	Walls - Structural Glazed Tile	1st floor Boys	274		7	10+ years								
	Water Closet	1st floor Boys	1	EA	7	6-10 years								
	Accessories	2nd Floor Boys	242	SF	7	6-10 years								
	Ceiling - Plaster/Drywall	2nd Floor Boys	242	SF	6	10+ years								
	Floor - Terrazzo	2nd Floor Boys	242	SF	7	10+ years								
	Floor Drain	2nd Floor Boys	2	EA	7	6-10 years								
	Hand Dryer	2nd Floor Boys	1	EA	7	6-10 years								
	Lavatory	2nd Floor Boys	3	EA	7	6-10 years								



Catego	ry : Room		R	uilding	: Additi	on 2	
Calego				unung	. Auulti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Lighting - Lay-in	2nd Floor Boys	5	EA	7	6-10 years	Comments
	Partitions	2nd Floor Boys	2	EA	7	6-10 years	
	Urinals	2nd Floor Boys	3	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor Boys	570	SF	7	10+ years	
	Water Closet	2nd Floor Boys	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Faculty Toilet	_ 54	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor Faculty Toilet	1	ĒA	6	10+ years	
	Floor - Terrazzo	2nd Floor Faculty Toilet	54	SF	6	6-10 years	
	Floor Drain	2nd Floor Faculty Toilet	1	EA	7	6-10 years	
	Lavatory	2nd Floor Faculty Toilet	1	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor Faculty Toilet	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor Faculty Toilet	284	SF	7	10+ years	
	Water Closet	2nd Floor Faculty Toilet	1	EA	7	6-10 years	
	Accessories	2nd floor girls	242	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls	242	SF	6	10+ years	
	Floor - Terrazzo	2nd floor girls	242	SF	6	6-10 years	
	Floor Drain	2nd floor girls	1	EA	7	6-10 years	
	Hand Dryer	2nd floor girls	1	EA	7	6-10 years	
	Lavatory	2nd floor girls	3	EA	7	6-10 years	
	Lighting - Lay-in	2nd floor girls	5	EA	7	6-10 years	
	Partitions	2nd floor girls	5	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd floor girls	586	SF	7	10+ years	
	Water Closet	2nd floor girls	5	EA	7	6-10 years	

# **Category : Classroom**

# **Building : Addition 2**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #124 (Regular Classroom)						
	Casework	1st Floor	34	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	999	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	999	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	41	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	826	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	275	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	m #125 (Regular Classroom)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	854	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	



	schools						1414 E 61st PLACE, Chicago, IL 6063
Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	854	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	260	SF	7	10+ years	
Classroc	om #126 (Regular Classroom)						
	Casework	1st Floor	64	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,024	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,024	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	ĒA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	173	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	854	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	285	SF	7	10+ years	
	Work Sink	1st Floor	203	EA	7	6-10 years	
	Work Onik	13(1100)	2	LA	,	0-10 years	
lassroc	om #127 (Regular Classroom)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	850	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	4	SF	4	1-2 years	Missing tile & water damage.
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	854	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	786	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	263	SF	6	10+ years	Paint chipping and peeling.
lassroc	om #224 (Regular Classroom)						
	Casework	2nd Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	854	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	854	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24		7		
				SF		6-10 years	
	Walls - Concrete Block	2nd Floor	780	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	260	55	7	10+ years	



							1414 E 61st PLACE, Chicago, IL 6063
Categor	y : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #225 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	526	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	1-2 years	Water damage.
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	530	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	770	SF	7	10+ years	
Classroo	m #226 (Regular Classroom)						
	Casework	2nd Floor	26	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	528	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	1-2 years	Water damage.
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	ge
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	530	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	770	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	10	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	430	SF	6	10+ years	Paint cracking and peeling.
		211011001	450	0	0	TOT years	r and clacking and peeiing.
Classroo	m #228 (Science Lab Level 1)						
	Casework	2nd Floor	51	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,027	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,027	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	775	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	258	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
ategor	y : Interior		В	Building : Addition 2			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Ceiling - Plaster/Drywall	1st Floor Corridor	1,897	SF	6	10+ years	



Catego	ry : Interior		B	uilding			
				. 3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Steel Doors incl hw	1st Floor Corridor	6	EA	6	6-10 years	
	Doors - Store Front	1st Floor Corridor	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor Corridor	1	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor Corridor	1,897	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor Corridor	14	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor Corridor	38	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor Corridor	22	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor Corridor	1,342	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor Corridor	1,629	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor Corridor	32	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor Corridor	6	EA	6	6-10 years	
	Drinking Fountains - Double Fountain	2nd Floor Corridor	1	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor Corridor	1,661	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor Corridor	51	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor Corridor	13	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor Corridor	36	LF	6	6-10 years	
	Student Lockers - One Tier	2nd Floor Corridor	14	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor Corridor	107	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor Corridor	2,670	SF	7	6-10 years	
Stairs							
	Ceiling - Lay-in	North	520	SF	6	10+ years	
	Floor - Terrazzo	North	426	SF	6	6-10 years	
	Handrails	North	60	LF	7	6-10 years	
	Lighting - Lay-in	North	5	EA	7	6-10 years	
	Lighting - Wall Mounted	North	1	EA	7	6-10 years	
	Stairs - Terrazzo	North	156	LF	7	6-10 years	
	Walls - Concrete Block	North	1,822	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	908	SF	6	10+ years	
	Floor - Terrazzo	South	727	SF	6	6-10 years	
	Handrails	South	60	LF	7	6-10 years	
	Lighting - Lay-in	South	20	EA	7	6-10 years	
	Lighting - Wall Mounted	South	1	EA	7	6-10 years	
	Stairs - Terrazzo	South	156	LF	7	6-10 years	
	Walls - Concrete Block	South	2,360	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Hydraulic Elevator	Addition 2	1	EA	7	10+ years	



Catego	Category : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	5	2-5 years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	5	2-5 years	
Fencing							
	Fencing - New Standard Ornamental	Entire Site	1,640	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	0-1 year	Broke/bent.
	5					,	
Landsca	ре						
	Benches	Entire Site	5	EA	5	2-5 years	
	Landscape - Grass	Entire Site	1,260	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	10,750	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	25	SF	4	1-2 years	Cracking.
	Parkway trees	Entire Site	12	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	8,126	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	1,280	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	7	10+ years	
Parking	Lot						
- 0	Concrete Curbs	Entire Site	246	LF	6	2-5 years	
	Lighting - Pole Mounted	Entire Site	2	EA	6	2-5 years	
	Surface - Asphalt	Entire Site	15,482	SF	4	0-1 year	Cracking and potholes throughout.
	Surface - Concrete	Entire Site	1,748	SF	5	2-5 years	
	Trash Compactor	Entire Site	1	EA	5	2-5 years	
	Trash Enclosure - Masonry	Entire Site	1,980	SF	7	10+ years	
Playgrou	ind						
	Equipment - School Age 5-12	Southeast	1	EA	6	10+ years	
	Surface - Square Rubber Mats	Southeast	2,250	SF	4	0-1 year	Separating.
			_,	•	-	- · · · ·	
Sidewall							
	Sidewalks - Perimeter Sidewalks	Entire Site	7,279	SF	4	0-1 year	Uneven and cracking.
Signago							
Signage	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	7	10+ years	
	Sign		Ζ.		'	iot years	



1414 E 61st PLACE, Chicago, IL 60637

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



# **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	2nd Floor	220	220	748	119	94	N	Y
Music Room	Library	2nd Floor	201	201	1,100	119	94	N	Y
Pre School	Pre School	1st Floor	120	120	1,103	183	168	N	Y
Regular Classroom	Regular Classroom	1st Floor	101	101	736	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	762	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	104	104	733	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	106	106	732	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	110	110	730	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	733	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	114	114	765	119	94	N	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	767	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	762	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	750	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	747	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	732	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	734	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	370	56	42	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	732	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	733	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	801	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	749	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	219	207	465	77	56	N	Y
Regular Classroom	Regular Classroom	2nd Floor	221	209	748	119	94	N	Y
Regular Classroom	Regular Classroom	2nd Floor	222	222	748	119	94	N	Y
Building : Addition 2									
Regular Classroom	Regular Classroom	1st Floor	124	1-11	1,040	160	80	N	Y
Regular Classroom	Regular Classroom	1st Floor	125	1-15	854	100	50	N	Ý
Regular Classroom	Regular Classroom	1st Floor	126	1-17	1,197	160	80	N	Ý
Regular Classroom	Regular Classroom	1st Floor	127	1-18	854	100	50	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	224	2-11	854	100	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	2-12	530	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	2-13	530	84	42	N	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	228	2-16	1,081	195	97	N	Y