



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1971	2	25,927
Campus Total			25,927

Catego	ry : Exterior		В	uilding	: Main		
		1	0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 - Main - E	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#1 - Main - E	2	EA	6	6-10 years	Replace door sweep
	Exterior Doors - Transom Lite	#1 - Main - E	1	EΑ	<u>/</u>	6-10 years	
	Exterior Doors - Exterior Steel Door	#1.5 - N	1	EA	_	10+ years	
	Entrance Control - Audio and Video	#2 - NW	1	EA	/	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 - NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - SW	1	EA	5	1-2 years	Bottom of door and frame are rusting
_Foundati	on						
	Foundation - Concrete	Entire Building	543	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	10	SF	5	0-1 year	Room 101. A car drove through the wall in this room sometime ago. The column was affected and repaired. At this time a crack in the drywall at the location of that column. From the exterior, recently pointed brick, nothing is notable.
	Superstructure - Steel	Entire Building	25,917	SF	7	10+ years	
_Liahtina							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	



Catego	ory : Exterior		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	6-10 years	
Roof Sy	stem						
	Access Ladder - Metal	Lower Roofs	1	EA	7	10+ years	
	Coping - Metal	Lower Roofs	151	LF	7	10+ years	
	Downspouts - Interior Downspouts	Lower Roofs	18	LF	7	10+ years	
	Roof - Modified Bitumen	Lower Roofs	2,826	SF	7	10+ years	
	Roof Hatch - Metal	Lower Roofs	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Lower Roofs	2,826	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	455	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	80	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	11,538	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	11,538	SF	6	10+ years	
	Concrete Topping					•	
Valls							
	Exterior Walls - Brick	Entire Building	12,608	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	45	SF	5	2-5 years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	497	SF	7	10+ years	
Vindow	S						
	Curtain wall - Louver	Entire Building	360	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	32	SF	7	10+ years	
	Lintels - Stone	Entire Building	442	LF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	2,280	SF	7	10+ years	

Category : Electrical **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Emerger	ncy System						
· ·	Automatic Transfer Switch	1st Floor	1	EA	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,144	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,758	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	896	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	7	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EΑ	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	4	0-1 year	Older signs with faded lighting.



Catego	ry : Electrical		В	uilding	: Main		
Juliogo	. y . =100111041		_	anan g		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о а.р	Exit Signs - Lunchroom	Entire Building	2	EA	4	0-1 year	Older signs with faded lighting.
	Security System - CCTV	Entire Building	25,927	SF	6	6-10 years	Grade eighte man radea lightling.
	Security System - Intrusion Detection	Entire Building	25,927	SF	5	6-10 years	
	Cooding Cyclom Intradion Detection	Entire Banaing	20,021	O.	Ü	o ro youro	
Main Se	rvice						
Maii OC	Main Electrical Service - 2000 A	1st Floor	1	EA	6	6-10 years	
	120/208/3PH	13(1100)	ı	LA	U	0-10 years	
	Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	
	emergency power	Liectrical Room	ı	LA	U	10+ years	
	PA System	Entire Building	25,927	SF	6	2-5 years	
	1 A dystem	Little ballaring	25,521	Oi	O	2-5 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
Catego	ry : Fire Protection		R	uilding	· Main		
Guiogo	.,		_	aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	'm					•	
	Fire Alarm Panel	Entire Building	1	EA	3	0-1 year	Outdated
	Fire Alarm_System	Entire Building	25,927	SF	4	2-5 years	Outdated.
		3	-,-			, , , , ,	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Item - Type Iling Systems	Location	Quantity	UOM	Rank		Comments
•		Location Roof	Quantity 1	UOM EA	Rank 5		
	lling Systems					Replacement	
	lling Systems Roof Top Unit-Single Zone-Roof Mounted-					Replacement	Ductwork not insulated, causing larg
Air Hand	Hing Systems Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons					Replacement	Ductwork not insulated, causing larg
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Roof	1	EA	5	Replacement 10+ years	Ductwork not insulated, causing larg
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained					Replacement	Ductwork not insulated, causing larg
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained Cooling	Roof 1st Floor	1	EA EA	5	Replacement 10+ years 6-10 years	Ductwork not insulated, causing larg water leakage into lunchroom
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained Cooling Fin Tube - Electric	Roof 1st Floor 2nd Floor	1 1 10	EA LF	5 6 5	Replacement 10+ years 6-10 years 2-5 years	Ductwork not insulated, causing larg
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained Cooling	Roof 1st Floor	1	EA EA	5	Replacement 10+ years 6-10 years	Ductwork not insulated, causing larg water leakage into lunchroom
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained Cooling Fin Tube - Electric Wall Heater - Electric	Roof 1st Floor 2nd Floor	1 1 10	EA LF	5 6 5	Replacement 10+ years 6-10 years 2-5 years	Ductwork not insulated, causing larg water leakage into lunchroom
Air Hand	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons Devices PTAC - Electric Heating and Self Contained Cooling Fin Tube - Electric	Roof 1st Floor 2nd Floor	1 1 10	EA LF	5 6 5	Replacement 10+ years 6-10 years 2-5 years	Ductwork not insulated, causing larg water leakage into lunchroom

Campus Name: Cullen Page : 3 of 16 Assessment Date: 07/15/2021



Catego	egory : Mechanical			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Thermostats - DDC	Entire Building	1	EA	4	0-1 year	RTU continues to cool past set points.
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	20	EA	5	2-5 years	
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	1	EA	4	1-2 years	Leaking TXV valve
	Unit Ventilators - Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	2	EA	4	1-2 years	Drain pan overflowing
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	3	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Electric Heater - Less than 20 KW	1st Floor	2	EA	6	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	25,927	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	25,927	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	25,927	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	25,927	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	25,927	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	25,927	SF	6	6-10 years	
	Sanitary Piping	Entire Building	25,927	SF	6	6-10 years	
	Storm Piping	Entire Building	25,927	SF	6	6-10 years	
	Vent Piping	Entire Building	25,927	SF	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		



					Replacement	
Administrative Suites/Offices						
Ceiling - Lay-in	1st Floor Assistant Principal's Office	117	SF	7	6-10 years	
Doors - Steel Doors incl hw	1st Floor Assistant Principal's Office	1	ĒΑ	7	6-10 years	
Floor - Carpet	1st Floor Assistant Principal's Office	117	SF	6	6-10 years	
Lighting - Lay-in	1st Floor Assistant Principal's Office	2	ĒΑ	7	6-10 years	
Power Distribution	1st Floor Assistant Principal's Office	6	ΕA	6	6-10 years	
Walls - Metal Panel	1st Floor Assistant Principal's Office	181	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor Engineer's Office	390	SF	6	6-10 years	
Doors - Steel Doors incl hw	1st Floor Engineer's Office	1	ĒΑ	7	6-10 years	
Floor - Tile	1st Floor Engineer's Office	390	SF	6	6-10 years	
Lighting - Lay-in	1st Floor Engineer's Office	4	ĒΑ	7	6-10 years	
Power Distribution	1st Floor Engineer's Office	8	ĒΑ	6	6-10 years	
Walls - Plaster/Drywall	1st Floor Engineer's Office	624	SF	6	6-10 years	
Ceiling - Lay-in	1st Floor Main Office	462	SF	7	6-10 years	
Doors - Steel Doors incl hw	1st Floor Main Office	2	EΑ	7	6-10 years	
Floor - Carpet	1st Floor Main Office	347	SF	6	6-10 years	
Floor - Tile	1st Floor Main Office	116	SF	6	6-10 years	
Lighting - Lay-in	1st Floor Main Office	6	EΑ	7	6-10 years	
Power Distribution	1st Floor Main Office	10	ΕA	6	6-10 years	
Storage/ Closet	1st Floor Main Office	35	SF	7	6-10 years	
Walls - Metal Panel	1st Floor Main Office	716	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor Principal's Office	177	SF	7	6-10 years	
Doors - Steel Doors incl hw	1st Floor Principal's Office	1	EA	7	6-10 years	
Floor - Carpet	1st Floor Principal's Office	177	SF	6	6-10 years	
Lighting - Lay-in	1st Floor Principal's Office	2	EA	7	6-10 years	
Power Distribution	1st Floor Principal's Office	8	EA	6	6-10 years	
Walls - Metal Panel	1st Floor Principal's Office	240	SF	7	6-10 years	
Ceiling - Lay-in	2nd Floor Room 210, Office	390	SF	6	6-10 years	
Doors - Steel Doors incl hw	2nd Floor Room 210, Office	1	EA	6	6-10 years	
Floor - Carpet	2nd Floor Room 210, Office	390	SF	4	0-1 year	Ripped and torn throughout.
Lighting - Lay-in	2nd Floor Room 210. Office	4	EA	7	6-10 years	rapped and terri anoughout.
Power Distribution	2nd Floor Room 210, Office	8	EA	6	6-10 years	
Walls - Plaster/Drywall	2nd Floor Room 210, Office	604	SF	6	6-10 years	
Ceiling - Lay-in	2nd Floor Teachers Lounge next to	289	SF	7	6-10 years	
Ocining Lay III	girl's restroom	200	OI	,	o to yours	
Doors - Steel Doors incl hw	2nd Floor Teachers Lounge next to	1	EA	7	6-10 years	
Booto Ctool Booto morriw	girl's restroom			•	o io youio	
Floor - Epoxy/ Painted	2nd Floor Teachers Lounge next to	289	SF	7	6-10 years	
поот Ерохул ганнеа	girl's restroom	200	OI	,	o to yours	
Lighting - Pendent/Surface	2nd Floor Teachers Lounge next to	3	EA	7	6-10 years	
Lighting T chachirounace	girl's restroom	0	L/\	,	o to yours	
Power Distribution	2nd Floor Teachers Lounge next to	6	EA	6	6-10 years	
1 OWEI DISTINGUIOTI	girl's restroom	O	LA	U	0-10 years	
Walls - Metal Panel	2nd Floor Teachers Lounge next to	709	SF	7	6-10 years	
vvalio - ivictal i alici	girl's restroom	103	O1	,	u- iu yeais	
Ceiling - Lay-in	Counselor Office In Library	115	SF	7	10+ years	
Coming Lay in	Codinocior Cinioc III Library	113	Oi.	,	101 years	



XII R	SCHOOIS						650 S Eberhart AVENUE, Chicago, IL 60628
						Replacement	
	Doors - Wood Doors inclu hw	Counselor Office In Library	1	EA	6	10+ years	
	Floor - Tile	Counselor Office In Library	115	SF	6	10+ years	
	Lighting - Lay-in	Counselor Office In Library	2	EΑ	7	10+ years	
	Power Distribution	Counselor Office In Library	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Counselor Office In Library	380	SF	6	10+ years	
	,	,		_	_	, , , , , ,	
Kitchen							
MICHELL	Calling Lavin	4 of Elean	257	- CE		0.40	
	Ceiling - Lay-in	1st Floor	357	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	357	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	5	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	138	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	414	SF	6	6-10 years	
Library							
	Ceiling - Lay-in	2nd Floor	975	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	975	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EΑ	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,511	SF	7	6-10 years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,658	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	100	SF	4	1-2 years	Missing tiles reported water damage.
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	2,758	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	20	EΑ	6	6-10 years	
	Serving Line	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	361	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	4,413	SF	6	6-10 years	
			,,,,,		-	- · · · · · · · · · · · · · · · · · · ·	
MDF ID	F						
_	Doors - Steel Doors incl hw	1st Floor next to girl's restroom	1	EA	6	6-10 years	
	Finishes	1st Floor next to girl's restroom	95	SF	7	10+ years	
	Window AC Unit	1st Floor next to girl's restroom	1	ĒΑ	4	0-1 year	Does not work, cover removed.
	Timacii 710 Ciii	Tot I foot floor to gill a footiooni	·	_, 、		o i youi	Dood Hot Work, dover romeved.
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	180	SF	7	10+ years	
	Storage Room	1st Floor	138	SF	7	10+ years	
	Vaults	1st Floor	97	SF	7	10+ years	
	Janitor's Closet	2nd Floor	48	SF	, 5	2-5 years	
	Janitul 5 Cluset	ZHU FIOOI	40	SF	ວ	2-5 years	
Restroor	n						
	Accessories	1st Floor Boys	217	SF	7	6-10 years	
	70063301163	13t 1 loor boys	217	Ji	,	0-10 years	



					Replacement	
Ceiling - Plaster/Drywall	1st Floor Boys	217	SF	7	6-10 years	
Doors - Steel Doors incl hw	1st Floor Boys	4	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st Floor Boys	217	SF	6	10+ years	
Floor Drain	1st Floor Boys	1	EA	7	10+ years	
Hand Dryer	1st Floor Boys	1	EA	7	2-5 years	
Lavatory	1st Floor Boys	2	EA	6	6-10 years	
Lighting - Lay-in	1st Floor Boys	3	EA	7	6-10 years	
Partitions	1st Floor Boys	2	EA	7	10+ years	
Urinals	1st Floor Boys	4	EA	7	6-10 years	
Walls - Metal Panel	1st Floor Boys	420	SF	7	6-10 years	
Walls - Tile Ceramic/ Porcelain	1st Floor Boys	140	SF	7	10+ years	
Water Closet	1st Floor Boys	2	EA	7	6-10 years	
Accessories	1st Floor Girls	217	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor Girls	217	SF	7	2-5 years	
Doors - Steel Doors incl hw	1st Floor Girls	4	EA	7	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st Floor Girls	217	SF	7	10+ years	
Floor Drain	1st Floor Girls	1	EΑ	7	10+ years	
Hand Dryer	1st Floor Girls	1	EA	7	2-5 years	
Lavatory	1st Floor Girls	2	EA	6	6-10 years	
Lighting - Lay-in	1st Floor Girls	3	EA	7	6-10 years	
Partitions	1st Floor Girls	7	EA	7	10+ years	
Walls - Metal Panel	1st Floor Girls	420	SF	7	6-10 years	
Walls - Tile Ceramic/ Porcelain	1st Floor Girls	140	SF	7	10+ years	
Water Closet	1st Floor Girls	7	EA	6	6-10 years	
Accessories	1st Floor In Main Office	48	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor In Main Office	48	SF	6	6-10 years	
Doors - Steel Doors incl hw	1st Floor In Main Office	1	EA	6	6-10 years	
Floor - Tile	1st Floor In Main Office	48	SF	6	6-10 years	
Lavatory	1st Floor In Main Office	1	ĒΑ	6	6-10 years	
Lighting - Pendent/Surface	1st Floor In Main Office	1	ĒΑ	7	6-10 years	
Walls - Metal Panel	1st Floor In Main Office	48	SF	6	10+ years	
Water Closet	1st Floor In Main Office	1	ĒΑ	6	6-10 years	
Accessories	1st Floor Unisex	31	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor Unisex	31	SF	7	6-10 years	
Doors - Steel Doors incl hw	1st Floor Unisex	1	EΑ	7	6-10 years	
Floor - Wood	1st Floor Unisex	31	SF	7	6-10 years	
Hand Dryer	1st Floor Unisex	1	EA	7	2-5 years	
Lavatory	1st Floor Unisex	1	EΑ	6	6-10 years	
Lighting - Pendent/Surface	1st Floor Unisex	1	EΑ	7	6-10 years	
Walls - Plaster/Drywall	1st Floor Unisex	198	SF	7	10+ years	
Water Closet	1st Floor Unisex	1	EA	6	6-10 years	
Accessories	1st Floor inside Kindergarten #101	28	SF	7	6-10 years	
Ceiling - Lay-in	1st Floor inside Kindergarten #101	28	SF	7	2-5 years	
Doors - Steel Doors incl hw	1st Floor inside Kindergarten #101	1	EA	6	6-10 years	
Floor - Tile	1st Floor inside Kindergarten #101	28	SF	7	2-5 years	
Lavatory	1st Floor inside Kindergarten #101	1	EA	7	6-10 years	
Lighting - Pendent/Surface	1st Floor inside Kindergarten #101	1	EA	7	6-10 years	
	10t 1 1001 molas Milasigatori // 101	•	_, 、	•	3 . 3 , 5 0 1 5	



					Replacement
Walls - Metal Panel	1st Floor inside Kindergarten #101	190	SF	7	10+ years
Water Closet	1st Floor inside Kindergarten #101	1	EA	7	6-10 years
Accessories	2nd Floor Boys	217	SF	7	6-10 years
Ceiling - Plaster/Drywall	2nd Floor Boys	217	SF	6	6-10 years
Doors - Steel Doors incl hw	2nd Floor Boys	4	EA	6	6-10 years
Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	217	SF	6	10+ years
Floor Drain	2nd Floor Boys	1	EA	7	10+ years
Hand Dryer	2nd Floor Boys	1	EΑ	7	2-5 years
Lavatory	2nd Floor Boys	2	EΑ	6	6-10 years
Lighting - Lay-in	2nd Floor Boys	3	EΑ	6	6-10 years
Partitions	2nd Floor Boys	2	EΑ	7	2-5 years
Urinals	2nd Floor Boys	4	EΑ	6	6-10 years
Walls - Metal Panel	2nd Floor Boys	420	SF	6	6-10 years
Walls - Tile Ceramic/ Porcelain	2nd Floor Boys	140	SF	6	10+ years
Water Closet	2nd Floor Boys	2	EΑ	6	6-10 years
Accessories	2nd Floor Girls	217	SF	7	6-10 years
Ceiling - Plaster/Drywall	2nd Floor Girls	217	SF	7	6-10 years
Doors - Steel Doors incl hw	2nd Floor Girls	4	EΑ	7	6-10 years
Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	217	SF	7	10+ years
Floor Drain	2nd Floor Girls	1	EΑ	7	10+ years
Hand Dryer	2nd Floor Girls	1	EΑ	7	2-5 years
Lavatory	2nd Floor Girls	2	EΑ	6	6-10 years
Lighting - Lay-in	2nd Floor Girls	3	EΑ	6	6-10 years
Partitions	2nd Floor Girls	7	EA	7	10+ years
Walls - Metal Panel	2nd Floor Girls	420	SF	7	6-10 years
Walls - Tile Ceramic/ Porcelain	2nd Floor Girls	140	SF	7	10+ years
Water Closet	2nd Floor Girls	7	ĒΑ	6	6-10 years
Accessories	2nd Floor Unisex East	20	SF	7	6-10 years
Ceiling - Lay-in	2nd Floor Unisex East	20	SF	7	6-10 years
Doors - Steel Doors incl hw	2nd Floor Unisex East	1	ĒΑ	7	6-10 years
Floor - Wood	2nd Floor Unisex East	20	SF	7	6-10 years
Hand Dryer	2nd Floor Unisex East	1	ĒΑ	7	2-5 years
Lavatory	2nd Floor Unisex East	1	ΕA	6	6-10 years
Lighting - Pendent/Surface	2nd Floor Unisex East	1	EΑ	7	6-10 years
Walls - Plaster/Drywall	2nd Floor Unisex East	162	SF	6	10+ years
Water Closet	2nd Floor Unisex East	1	EA	6	6-10 years
Accessories	2nd Floor Unisex West	20	SF	7	6-10 years
Ceiling - Lay-in	2nd Floor Unisex West	20	SF	6	6-10 years
Doors - Steel Doors incl hw	2nd Floor Unisex West	1	EA	6	6-10 years
Floor - Wood	2nd Floor Unisex West	20	SF	7	6-10 years
Hand Dryer	2nd Floor Unisex West	1	EA	7	2-5 years
Lavatory	2nd Floor Unisex West	1	EA	6	6-10 years
Lighting - Pendent/Surface	2nd Floor Unisex West	1	EA	7	10+ years
Walls - Plaster/Drywall	2nd Floor Unisex West	162	SF	7	10+ years
Water Closet	2nd Floor Unisex West	102	EA	6	6-10 years
vvater 01036t	ZIIG I IOOI OHISEA WEST	1	$L\Lambda$	U	0-10 years



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #101 (Kindergarten)						
	Casework	1st Floor	35	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,080	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	6-10 years	
	Floor - Carpet	1st Floor	1,080	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	1,674	SF	7	6-10 years	
Classroc	om #102 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	745	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	745	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	6-10 years	
	Walls - Metal Panel	1st Floor	1,155	SF	7	6-10 years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	725	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Metal Panel	1st Floor	863	SF	7	6-10 years	
Classroc	om #104 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	745	SF	7	6-10 years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	745	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	5	6-10 years	
	Walls - Metal Panel	1st Floor	837	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	279	SF	7	6-10 years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #105 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	725	SF	7	6-10 years	
					-	, ,	



Catego	ry : Classroom		В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years		
	Floor - Tile	1st Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	6	6-10 years		
	Walls - Metal Panel	1st Floor	863	SF	6	6-10 years		
Classroo	m #106 (Office)							
	Casework	1st Floor	6	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	745	SF	7	6-10 years		
	Chalk Board	1st Floor	303	LF	4	2-5 years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years		
	Floor - Tile	1st Floor	745	SF	7	6-10 years		
		1st Floor		EA				
	Lighting - Lay-in		12		7	6-10 years		
	Marker Board	1st Floor	8	LF	6	6-10 years		
	Storage/ Closet	1st Floor	12	SF	7	6-10 years		
	Walls - Metal Panel	1st Floor	837	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	279	SF	7	6-10 years		
Classroo	m #107 (Regular Classroom)							
	Casework	1st Floor	8	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	725	SF	7	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years		
	Floor - Tile	1st Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	18	LF	6	6-10 years		
	Walls - Metal Panel	1st Floor	647	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	216	SF	7	6-10 years		
Classroo	m #201 (Science)							
	Casework	2nd Floor	8	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years		
	Chalk Board	2nd Floor	22	LF	4	2-5 years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6			
			=		_	6-10 years		
	Floor - Tile	2nd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years		
	Marker Board	2nd Floor	18	LF	6	6-10 years		
	Walls - Metal Panel	2nd Floor	867	SF	6	6-10 years		
Classroo	m #202 (Regular Classroom)							
	Casework	2nd Floor	6	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	900	SF	7	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	6-10 years		
	Floor - Tile	2nd Floor	900	SF	7	6-10 years		

Campus Name: Cullen Page : 10 of 16 Assessment Date: 07/15/2021



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,395	SF	7	6-10 years	
Classroo	m #203 (Other Instructional Use)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	On folding partition
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	On folding partition
						•	
	Floor - Tile	2nd Floor	721	SF	7	6-10 years	A 40
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Missing tile
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	867	SF	7	6-10 years	
Classroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	745	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	•	
	•			SF SF		6-10 years	
	Walls - Metal Panel	2nd Floor	1,155	5F	7	6-10 years	
Classroo	m #205 (Regular Classroom)						
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	858	SF	7	6-10 years	
Classroo	m #206 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	145	EA	7	6-10 years	
				SF			
	Floor - Tile	2nd Floor	745		6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,145	SF	7	6-10 years	



Category : Classroom			В	Building : Main			50 & Ebernant AVENOE, Officago, IE 00020
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #207 (Science)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	858	SF	7	6-10 years	
Classroo	om #208 (Other Instructional Use)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor	745	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor					
			1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	745	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	5	6-10 years	
	Walls - Metal Panel	2nd Floor	1,145	SF	7	6-10 years	
_Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
				SF		•	
	Walls - Metal Panel	2nd Floor	647	SF SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	216	SF	7	6-10 years	
Catego	ry : Interior		В	Building : Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Corridor		Location	Qualitity	UOIVI	IVALIA	Replacement	Comments
	Ceiling - Lay-in	1st Floor	1,642	SF	7	6-10 years	
	Doors - Wood Doors include hw	1st Floor	4	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	2-5 years	
	Floor - Tile/Sheet	1st Floor	1,642	SF	7	2-5 years	
	Lighting - Lay-in	1st Floor	1,042	EA	7	6-10 years	
	Walls - Metal Panel	1st Floor	3,033	SF			
				SF SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,348		6	6-10 years	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EA	7	2-5 years	
	Floor - Tile/Sheet	2nd Floor	1,348	SF	7	2-5 years	



Catego	ry : Interior		Building : Main						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Lighting - Lay-in	2nd Floor	10	EΑ	7	6-10 years			
	Walls - Metal Panel	2nd Floor	2,844	SF	7	6-10 years			
Safety									
,	Camera Viewing Station	Entire Building	4	EA	7	2-5 years			
	Metal Dedector	Entire Building	1	EA	7	6-10 years			
	Security Cameras	Entire Building	5	EA	7	2-5 years			
	Security Cameras	Entire Building	6	EA	7	1-2 years			
Stairs									
	Ceiling - Lay-in	East	136	SF	7	6-10 years			
	Floor - Tile	East	60	SF	5	2-5 years			
	Handrails	East	64	LF	7	2-5 years			
	Lighting - Lay-in	East	1	EA	7	6-10 years			
	Stairs - Concrete	East	30	LF	7	6-10 years			
	Walls - Metal Panel	East	1,160	SF	7	6-10 years			
	Ceiling - Lay-in	West	136	SF	6	6-10 years			
	Floor - Tile	West	60	SF	5	2-5 years			
	Handrails	West	64	LF	7	2-5 years			
	Lighting - Lay-in	West	1	EA	6	6-10 years			
	Stairs - Concrete	West	30	LF	6	6-10 years			
	Walls - Metal Panel	West	1,160	SF	6	6-10 years			



Sign

Catego	ry : Site		В						
						Recommend	nd		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Civil/Dra	inage								
	Civil/ Drainage - Catch Basin	North	2	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	North	1	EA	6	10+ years			
	-					-			
Fencina									
J	Fencing - New Standard Ornamental	Entire Site	738	LF	6	6-10 years			
	Fencing - New Standard Ornamental	Entire Site	10	LF	4	0-1 year	Gate is misaligned		
_Landsca	no.								
_Lanusud	Landscape - Grass	Entire Site	1,444	SF	6	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	1,296	SF	6	6-10 years			
	Landscape - Hardscape- Pavers	Entire Site	1,135	SF	6	6-10 years			
	Parkway trees	Entire Site	14	ĒΑ	6	10+ years			
	Planting Beds/ Area	Entire Site	175	SF	6	6-10 years			
	Play Area - Hardscape- Asphalt	Entire Site	9,628	SF	7	10+ years			
	Play Area - Synthetic Turf	Entire Site	4,000	SF	7	10+ years			
	Trash Receptacles	Entire Site	2	EA	7	6-10 years			
	Trash Receptacles	Entire Site	2	EA	6	2-5 years			
_Playgrou	und								
- , ,	Equipment - Combo 3-12	West	1	EA	5	2-5 years			
	Surface - Square Rubber Mats	West	2,285	SF	4	0-1 year	Broken tiles, worn out.		
_Sidewall	(e								
_Cidewall	Sidewalks - Internal Walks	Entire Site	8	LF	6	6-10 years			
	Sidewalks - Perimeter Sidewalks	Entire Site	3,527	SF	6	6-10 years			
	Sidewalks - Perimeter Sidewalks	Entire Site	400	SF	4	0-1 year	Distressed areas of concrete		
							sidewalk on south side of the building		
_Signage									
_ Olynage	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years			
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years			
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	2-5 years			
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	5	0-1 year	Sign is rusting.		

Page : 14 of 16 Campus Name: Cullen Assessment Date: 07/15/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Cullen Page: 15 of 16 Assessment Date: 07/15/2021





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	mionaca coago	Room Location	Italiboi	Hamboi	(01)	Allou	Alou	Otop	Board
Computer Lab	Regular Classroom	1st Floor	104	NA	745	94	33	N	Υ
Kindergarten	Kindergarten	1st Floor	101	NA	1,080	151	54	N	N
Office	Regular Classroom	1st Floor	106	106	745	94	33	N	N
Other Instructional Use	Regular Classroom	2nd Floor	203	203	725	94	33	N	N
Other Instructional Use	Regular Classroom	2nd Floor	208	208	745	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	745	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	725	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	725	94	33	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	725	94	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	900	94	33	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	745	94	33	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	725	94	33	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	206	206	745	94	33	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	725	94	33	N	N
Science	Regular Classroom	2nd Floor	201	201	725	94	33	N	Υ
Science	Regular Classroom	2nd Floor	207	207	725	94	33	N	Υ