

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main-Building A	1973	3	245,084
Linked Addition-Athletic Building B	1973	2	170,493
Campus Total			415,577

Catego	ry : Exterior	В	Building : Main-Building A				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	10	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	10	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	10	1	EA	7	10+ years	
	Exterior Stairs - Concrete	10	18	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	10	5	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	10.1 - Garage	1	EA	6	10+ years	
	Door						
	Exterior Doors - Overhead Rolling/ Garage	10.2 - Loading Dock	2	EA	6	10+ years	
	Door						
	Entrance Control - Audio and Video	6 - SW	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	6 - SW	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6.1 - SW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	6.1 - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7 - SE	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7.1 - SE	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	8	1	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	8.1- Automotive	3	EA	6	10+ years	
	Door					-	
	Exterior Doors - Exterior Steel Door	9	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Roof doors	4	EA	7	10+ years	
	Exterior Stairs - Steel or Aluminum	Roof doors	12	LF	6	10+ years	

Foundation



Catego	ry : Exterior		Building : Main-Building A					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Foundation - Concrete	Entire Building	1,078	LF	7	10+ years		
	Foundation - Concrete	Entire Building	80	LF	7	10+ years		
	Superstructure - Metal Deck/ Concrete	Entire Building	245,084	SF	7	10+ years		
	Topping							
Lighting								
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	15	EA	7	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	7	10+ years		
Roof Svs	stem							
,	Access Ladder - Metal	Α	1	EA	7	10+ years		
	Coping - Metal	A	1,918	LF	7	10+ years		
	Downspouts - Interior Downspouts	A	720	LF	6	10+ years		
	Parapet - Parapet > 30"	A	1,918	LF	7	10+ years		
	Roof - Modified Bitumen	A	80,728	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	A	80,728	SF	7	10+ years		
	Concrete Topping					-		
	Coping - Metal	В	104	LF	7	10+ years		
	Downspouts - Interior Downspouts	В	2	LF	6	10+ years		
	Parapet - Parapet < 16" Height	В	104	LF	7	10+ years		
	Roof - Modified Bitumen	В	676	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	В	676	SF	7	10+ years		
	Concrete Topping					-		
	Coping - Metal	C - NW	104	LF	7	10+ years		
	Downspouts - Interior Downspouts	C - NW	2	LF	6	10+ years		
	Parapet - Parapet < 16" Height	C - NW	104	LF	7	10+ years		
	Roof - Modified Bitumen	C - NW	676	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	C - NW	676	SF	7	10+ years		
	Concrete Topping					-		
	Coping - Metal	D	104	LF	7	10+ years		
	Downspouts - Interior Downspouts	D	2	LF	6	10+ years		
	Parapet - Parapet < 16" Height	D	104	LF	7	10+ years		
	Roof - Modified Bitumen	D	676	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	D	676	SF	7	10+ years		
	Concrete Topping			-		- ,		
	Coping - Metal	E	104	LF	7	6-10 years		
	Downspouts - Interior Downspouts	Ē	2	LF	6	6-10 years		
	Parapet - Parapet < 16" Height	Ē	104	LF	7	10+ years		
	Roof - Modified Bitumen	Ē	676	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	Ē	676	SF	7	10+ years		
	Concrete Topping		510	2.	-			
	Coping - Metal	F - Link Roof	56	LF	7	10+ years		
	Downspouts - Interior Downspouts	F - Link Roof	6	LF	6	10+ years		
	Parapet - Parapet < 16" Height	F - Link Roof	56	LF	7	10+ years		



Catego	ry : Exterior		В	Building : Main-Building A				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Roof - Modified Bitumen	F - Link Roof	196	SF	6	10+ years		
	Roof Structure - Steel / Metal Deck/	F - Link Roof	196	SF	7	10+ years		
	Concrete Topping							
Nalls								
	Exterior Walls - Brick	Entire Building	37,769	SF	6	6-10 years		
	Exterior Walls - Precast Panel Wall	Entire Building	2,000	SF	6	10+ years		
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	3,040	SF	6	10+ years		
Nindows	3							
	Guard - Guards perforated	Entire Building	1,431	SF	6	10+ years		
	Lintels - Steel	Entire Building	1,785	LF	6	10+ years		
	Storefront Windows	Entire Building	120	SF	6	10+ years		
	Windows - Casement Aluminum	Entire Building	14,721	SF	6	10+ years		
	Windows - Louver	Entire Building	36	SF	6	10+ years		
Catego	ry : Electrical		В	uilding	: Main-E	Building A		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Emerger	ncy System							
	Emergency Generator- Indoor- Natural Gas - 151 - 200 KW	Basement	1	EA	5	2-5 years	Serves both buildings	
	Automatic Transfer Switch	Basement	3	EA	7	10+ years		
	Security System - CCTV	Entire Building	245,084	SF	6	6-10 years		
	Security System - Intrusion Detection	Entire Building	245,084	SF	6	6-10 years		
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	7	10+ years		
	Exit Signs - Corridors and Stairs	Entire Building	35	EA	6	6-10 years	The faulty units have been replaced	
	Exit Signs - Lunchroom	Entire Building	12	EA	6	6-10 years	Faulty units have been replaced.	
	Emergency A/C Power - Corridors and Stairs	Entire Building	54,566	SF	6	6-10 years		
	Emergency A/C Power - Lunchrooms	Entire Building	17,100	SF	6	6-10 years		
	Emergency A/C Power - Students Toilets	Entire Building	4,683	SF	6	6-10 years		
Main Se	rvice							
	Independent Electrical Service for emergency power	Basement	2	EA	6	6-10 years		
	Main Electrical Service - 1200 A 277/480/3PH	Entire Building	2	EA	6	2-5 years	Units installed in 1972	
	Main Electrical Service - 800 A and 277/480/3PH	Entire Building	1	EA	6	2-5 years	Units installed in 1972	
	Main Electrical Service - 800 A and 277/480/3PH	Entire Building	7	EA	6	2-5 years	Units installed in 1972	



Catego	ry : Electrical		R	uilding	· Main-F	Building A	1959 S AICHEI AVENUE, Chicago, IE 6063
Jacyo				anung	. mani-L	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sibup	Main Electrical Service - Greater than 3000	Entire Building	Quantity	EA	6	2-5 years	Units installed in 1972
	A 120/208/3PH	Entire Banang	I	LA	0	2-5 years	Office installed in 1972
	PA System	Entire Building	245,084	SF	6	6-10 years	
	r A System	Little Building	240,004	0	0	0-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	18	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	30	EA	6	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	24	EA	7	10+ vears	
	Main Distribution Panels - Greater than 600	Entire Building	4	EA	6	6-10 years	
	amp	3			÷	• • • , • • •	
	Transformers - 277/480 - 120/208	Entire Building	4	EA	7	6-10 years	
Catego	ry : Fire Protection		в	uildina	· Main-F	Building A	
outego				unung	. Main E	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	245,084	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	245,084	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	5	2-5 years	
Pump Re	pom Assembly						
	Fire Pump - 51-75hp	Mechanical Room	1	EA	6	6-10 years	
	Jockey Pump	Mechanical Room	1	EA	6	6-10 years	
	Sockey Fump		1	LA	0	0-10 years	
Sprinkler	System						
	Sprinkler Heads	Entire Building	245,084	SF	4	2-5 years	
	Sprinkler Piping	Entire Building	245,084	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	245,084	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	Building A		
Ŭ	- -			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	21	EA	7	10+ years	
	than 5 tons		21	L/\	,	ior yours	



Catego	ry : Mechanical		B	uildina	: Main-E	Building A	1959 S Archer AVENUE, Chicago, IL 60632
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric Air Handling Unit- Package Single Zone- Indoor- Electric Coil - Less than 4000 cfm	Entire Building Mechanical Room	21 1	EA EA	6 5	6-10 years 2-5 years	Serve computer labs on 3rd floor.
	Air Handling Unit- Package Multi Zone- Indoor- Electric and DX Cooling Coil - 10001-15000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves entire basement.
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 31 - 45 tons	Roof	17	EA	7	10+ years	
	Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm	Roof	1	EA	7	10+ years	
	VAV Box	VAV Boxes	4	EA	7	10+ years	Serve AC-16. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	7	EA	7	10+ years	Serves AC-13. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	9	EA	7	10+ years	Serves AC-8. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	10	EA	7	10+ years	Serves AC-1. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	6	EA	7	10+ years	Serves AC-11. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	9	EA	7	10+ years	Serves AC-9. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	8	EA	7	10+ years	Serve AC-14. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	6	EA	7	10+ years	Serve AC-2. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	9	EA	7	10+ years	Serve AC-15. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	9	EA	7	10+ years	Serves AC-6. 2018 Installation. Retrofit kits, above ceilings.
	VAV Box	VAV Boxes	8	EA	7	10+ years	Serve AC-12. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	10	EA	7	10+ years	Serve AC-4. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	8	EA	7	10+ years	Serve AC-7. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	7	EA	7	10+ years	Serve AC-10. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	7	EA	7	10+ years	Serve AC-17. 2018 Installation. Retrofit kits, above ceiling.
	VAV Box	VAV Boxes	7	EA	7	10+ years	Serve AC-3. 2018 Installation. Retrofit kits, above ceiling.



Catego	ry : Mechanical		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type		Quantity 7	UOM EA	Rank	Replacement	Comments
	VAV Box	VAV Boxes	7	EA	7	10+ years	Serve AC-5. 2018 Installation. Retrofit kits, above ceiling.
leating	Devices						
	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	2	EA	5	2-5 years	
	Unit Heater - Electric	Entire Building	4	EA	5	2-5 years	
	Unit Heater - Electric	Entire Building	1	EA	4	0-1 year	Corroded, non functional
	Unit Heater - Electric	Entire Building	1	EA	4	0-1 year	Corroded, non functional
	Fin Tube - Steam	Entire Building	2,722	LF	5	6-10 years	
	Duct Heater - Electric	Entire Building	56		7	10+ years	
	Cabinet Heaters - With Electric Coil	Entire Building	5	EA	5	6-10 years	
Tempera	ture Control						
	DDC System	Entire Building	245,084	SF	7	10+ years	
	Electric Thermostat	Entire Building	2	EA	7	10+ years	
	Pneumatic System	Entire Building	6,000	SF	6	2-5 years	
	Thermostats - DDC	Entire Building	131	EA	7	10+ years	
	Thermostats - Pneumatic	Entire Building	5	EA	6	2-5 years	
Ventilatio)n						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	7	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	16	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	4	EA	6	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	4	EA	6	6-10 years	The unit has been repaired
	Type I Exhaust Hood- Kitchen	Entire Building	10	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	6	EA	7	10+ years	



Catego	ry : Plumbing		В	uilding	: Main-E	Building A	
Group	Itom Tuno	Logation	Quantity	UOM	Donk	Recommend Replacement	Commente
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
HOL WATE	Gas Heater - 300001 - 600000 BTU/HR	Penthouse	2	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Penthouse	3	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Domestic Piping-Hot Water Return Risers	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	245,084	SF	4	0-1 year	Pipes are 50 years old, corroded and clamped
	Sanitary Piping	Entire Building	245,084	SF	6	2-5 years	·
	Storm Piping	Entire Building	245,084	SF	6	2-5 years	
	Vent Piping	Entire Building	245,084	SF	6	2-5 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	3	EA	4	0-1 year	Only 2 pumps are working, one is down and cannot be repaired. As put the engineer, if another pump fails, the water will be partially available of the first floor and not at all to the second and third floors
	Pumps - Ejector-Simplex	Mechanical Room	2	EA	6	6-10 years	
	Pumps - Ejector-Simplex	Mechanical Room	2	EA	3	0-1 year	Corroded.
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	2	EA	5	2-5 years	
Catego	ry : Room		В	uilding	: Main-E	Building A	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Administ	rative Suites/Offices	Location	Quantity		Nalik	Replacement	Comments
	Ceiling - Lay-in	126 - Guidance Office	114	SF	6	10+ years	
	Doors - Side-lite	126 - Guidance Office	12	SF	7	10+ years	
	Doors - Transom Window	126 - Guidance Office	5	SF	7	10+ years	
	Doors - Wood Doors inclu hw	126 - Guidance Office	1	EA	6	10+ years	
				SF	•		



Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	126 - Guidance Office	4	EA	6	6-10 years	
	Power Distribution	126 - Guidance Office	4	EA	7	10+ years	
	Walls - Concrete Block	126 - Guidance Office	120	SF	7	10+ years	
	Walls - Metal Panel	126 - Guidance Office	265	SF	6	10+ years	
	Ceiling - Lay-in	127 - Guidance Office	114	SF	7	10+ years	
	Doors - Side-lite	127 - Guidance Office	30	SF	7	10+ years	
	Doors - Transom Window	127 - Guidance Office	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	127 - Guidance Office	1	EA	7	10+ years	
	Floor - Tile	127 - Guidance Office	114	SF	7	10+ years	
	Lighting - Pendent/Surface	127 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	127 - Guidance Office	4	EA	7	10+ years	
	Walls - Metal Panel	127 - Guidance Office	360	SF	7	10+ years	
	Ceiling - Lay-in	128 - Guidance Office	114	SF	6	10+ years	
	Doors - Wood Doors inclu hw	128 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	128 - Guidance Office	114	SF	6	10+ years	
	Lighting - Pendent/Surface	128 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	128 - Guidance Office	4	EA	6	10+ years	
	Walls - Metal Panel	128 - Guidance Office	410	SF	6	10+ years	
	Ceiling - Lay-in	129 - Special Ed Office	114	SF	7	10+ years	
	Doors - Wood Doors inclu hw	129 - Special Ed Office	1	ĒA	7	10+ years	
	Floor - Tile	129 - Special Ed Office	114	SF	7	10+ years	Changed to match current observations
	Lighting - Pendent/Surface	129 - Special Ed Office	4	EA	7	6-10 years	observations
	Power Distribution	129 - Special Ed Office	4	EA	7	10+ years	
	Walls - Metal Panel	129 - Special Ed Office	410	SF	7	10+ years	Changed to match current
			-			-	observations and
	Ceiling - Lay-in	130 - Guidance Office	114	SF	6	10+ years	
	Doors - Side-lite	130 - Guidance Office	30	SF	7	10+ years	
	Doors - Transom Window	130 - Guidance Office	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	130 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	130 - Guidance Office	114	SF	6	10+ years	
	Lighting - Pendent/Surface	130 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	130 - Guidance Office	4	EA	7	10+ years	
	Walls - Metal Panel	130 - Guidance Office	360	SF	6	10+ years	
	Ceiling - Lay-in	131 - Guidance Office	114	SF	6	10+ years	
	Doors - Side-lite	131 - Guidance Office	30	SF	7	10+ years	
	Doors - Transom Window	131 - Guidance Office	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	131 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	131 - Guidance Office	114	SF	7	10+ years	
	Lighting - Pendent/Surface	131 - Guidance Office	4	EA	6	6-10 years	
	Power Distribution	131 - Guidance Office	4	EA	6	10+ years	
	Walls - Metal Panel	131 - Guidance Office	360	SF	6	10+ years	
	Ceiling - Lay-in	142B IT Office	817	SF	7	10+ years	
	Doors - Wood Doors inclu hw	142B IT Office	1	EA	6	10+ years	Quantity changed to match current



Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations
	Floor - Tile	142B IT Office	817	SF	7	10+ years	
	Lighting - Pendent/Surface	142B IT Office	31	EA	6	6-10 years	
	Power Distribution	142B IT Office	14	EA	7	10+ years	
	Walls - Metal Panel	142B IT Office	776	SF	6	10+ years	
	Walls - Plaster/Drywall	142B IT Office	333	SF	7	10+ years	
	Work SInk	142B IT Office	3	EA	7	6-10 years	
	Ceiling - Lay-in	148B Workroom (previously a	195	SF	6	10+ years	
		darkroom)					
	Doors - Wood Doors inclu hw	148B Workroom (previously a	1	EA	7	10+ years	
		darkroom)					
	Floor - Terrazzo	148B Workroom (previously a	195	SF	6	10+ years	
		darkroom)				-	
	Lighting - Pendent/Surface	148B Workroom (previously a	4	EA	6	6-10 years	
	0 0	darkroom)					
	Power Distribution	148B Workroom (previously a	6	EA	7	10+ years	
		darkroom)				,	
	Walls - Metal Panel	148B Workroom (previously a	574	SF	6	10+ years	
		darkroom)	••••	•	•	, ,	
	Work SInk	148B Workroom (previously a	1	EA	7	6-10 years	
		darkroom)			-	- · · , · · · ·	
	Ceiling - Plaster/Drywall	150B	142	SF	7	10+ years	
	Doors - Transom Window	150B	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	150B	1	ĒA	7	10+ years	
	Floor - Concrete	150B	142	SF	7	10+ years	
	Lighting - Pendent/Surface	150B	2	EA	7	6-10 years	
	Power Distribution	150B	2	EA	7	10+ years	
	Walls - Concrete Block	150B	140	SF	7	10+ years	
	Walls - Metal Panel	150B	320	SF	7	10+ years	
	Ceiling - Lay-in	154 Office	195	SF	6	10+ years	
	Doors - Side-lite	154 Office	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	154 Office	1	EA	7	10+ years	
	Floor - Tile	154 Office	195	SF	7	10+ years	
	Lighting - Pendent/Surface	154 Office	4	EA	6	6-10 years	
	Power Distribution	154 Office	4	EA	7	10+ years	
	Walls - Concrete Block	154 Office	30	SF	7	10+ years	
	Walls - Metal Panel	154 Office	526	SF	6	10+ years	
	Ceiling - Lay-in	156 Space Studio	725	SF	7		
	Floor - Tile	156 Space Studio	725	SF	6	10+ years 10+ years	
	Lighting - Pendent/Surface	156 Space Studio	12	EA	7	6-10 years	
	Power Distribution	156 Space Studio	8	EA	7	10+ years	
		156 Space Studio		SF	7	•	
	Walls - Concrete Block		418	SF		10+ years	
	Walls - Metal Panel	156 Space Studio	355		6	10+ years	
	Ceiling - Lay-in	157 ID Office	185	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main-E	Building A	Achel Avenue, officago, ie 00032
	-			5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	157 ID Office	1	EA	6	10+ years	Changed to match current observations
	Floor - Tile	157 ID Office	185	SF	7	10+ years	
	Lighting - Pendent/Surface	157 ID Office	3	EA	6	6-10 years	
	Power Distribution	157 ID Office	6	EA	7	10+ years	
	Walls - Metal Panel	157 ID Office	365	SF	7	10+ years	
	Ceiling - Lay-in	158 Office	168	SF	6	10+ years	
	Doors - Wood Doors inclu hw	158 Office	1	EA	6	10+ years	
	Floor - Tile	158 Office	168	SF	6	10+ years	
	Lighting - Pendent/Surface	158 Office	2	EA	6	6-10 years	
	Power Distribution	158 Office	6	EA	7	10+ years	
	Walls - Metal Panel	158 Office	325	SF	6	10+ years	
	Walls - Plaster/Drywall	158 Office	180	SF	6	10+ years	
	Ceiling - Lay-in	159A Office/Storage	218	SF	7	10+ years	
	Doors - Side-lite	159A Office/Storage	108	SF	7	10+ years	Glass along the wall
	Doors - Wood Doors inclu hw	159A Office/Storage	1	EA	7	10+ years	5
	Floor - Tile	159A Office/Storage	218	SF	7	10+ years	
	Lighting - Lay-in	159A Office/Storage	2	EA	7	6-10 years	
	Power Distribution	159A Office/Storage	8	EA	7	10+ years	
	Walls - Concrete Block	159A Office/Storage	107	SF	7	10+ years	
	Walls - Plaster/Drywall	159A Office/Storage	375	SF	7	10+ years	
	Ceiling - Lay-in	165A Work Room	178	SF	6	10+ years	
	Doors - Side-lite	165A Work Room	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	165A Work Room	1	EA	6	10+ years	
	Floor - Tile	165A Work Room	178	SF	6	10+ years	
	Lighting - Lay-in	165A Work Room	3	EA	7	6-10 years	
	Power Distribution	165A Work Room	4	EA	7	10+ years	
	Walls - Concrete Block	165A Work Room	431	SF	7	10+ years	
	Walls - Plaster/Drywall	165A Work Room	132	SF	7	10+ years	
	Ceiling - Lay-in	165B Control Room	188	SF	7	10+ years	
	Doors - Steel Doors incl hw	165B Control Room	1	EA	7	10+ years	
	Floor - Tile	165B Control Room	188	SF	6	10+ years	
	Lighting - Lay-in	165B Control Room	3	EA	7	6-10 years	
	Power Distribution	165B Control Room	4	EA	7	10+ years	
	Walls - Concrete Block	165B Control Room	195	SF	7	10+ years	
	Walls - Plaster/Drywall	165B Control Room	368	SF	7	10+ years	
	Ceiling - Lay-in	167A - Office	166	SF	7	10+ years	
	Ceiling - Lay-in	167A - Office	24	SF	4	0-1 year	Water damage/missing tiles
	Doors - Steel Doors incl hw	167A - Office	1	EA	7	10+ years	
	Floor - Carpet	167A - Office	190	SF	4	0-1 year	Damaged carpet
	Lighting - Lay-in	167A - Office	5	EA	6	6-10 years	
	Power Distribution	167A - Office	4	EA	7	10+ years	
	Walls - Concrete Block	167A - Office	385	SF	6	10+ years	
	Walls - Concrete Block	167A - Office	5	SF	5	0-1 year	Cracked CMU tiles



	Building : Main-Building A						
					Recommend		
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Walls - Metal Panel	167A - Office	188	SF	6	10+ years		
Ceiling - Lay-in	168A Office/Storage	204	SF	6	10+ years		
Ceiling - Lay-in	168A Office/Storage	3	SF	4	0-1 year	Missing.	
Doors - Wood Doors inclu hw	168A Office/Storage	1	EA	7	10+ years		
Floor - Tile	168A Office/Storage	207	SF	6	10+ years		
Lighting - Lay-in	168A Office/Storage	5	EA	7	6-10 years		
Power Distribution	168A Office/Storage	4	EA	7	10+ years		
Walls - Concrete Block	168A Office/Storage	303	SF	7	10+ years		
Walls - Metal Panel	168A Office/Storage	103	SF	7	10+ years		
Walls - Plaster/Drywall	168A Office/Storage	200	SF	6	10+ years		
Ceiling - Lay-in	169 - Dean's Office open area	594	SF	7	10+ years		
Doors - Side-lite	169 - Dean's Office open area	12	SF	7	10+ years		
Doors - Transom Window	169 - Dean's Office open area	15	SF	7	10+ years		
Doors - Wood Doors inclu hw	169 - Dean's Office open area	1	EA	7	10+ years		
Floor - Tile	169 - Dean's Office open area	594	SF	6	10+ years		
Lighting - Lay-in	169 - Dean's Office open area	18	EA	7	6-10 years		
Power Distribution	169 - Dean's Office open area	10	EA	7	10+ years		
Walls - Concrete Block	169 - Dean's Office open area	190	SF	7	10+ years		
Walls - Metal Panel	169 - Dean's Office open area	220	SF	6	10+ years		
Walls - Plaster/Drywall	169 - Dean's Office open area	304	SF	6	10+ years		
Ceiling - Lay-in	169A Camera Viewing Rm	145	SF	6	10+ years		
Doors - Wood Doors inclu hw	169A Camera Viewing Rm	2	EA	7	10+ years		
Floor - Tile	169A Camera Viewing Rm	145	SF	6	10+ years		
Lighting - Lay-in	169A Camera Viewing Rm	2	EA	6	6-10 years		
Power Distribution	169A Camera Viewing Rm	4	EA	6	10+ years		
Walls - Concrete Block	169A Camera Viewing Rm	97	SF	6	10+ years		
Walls - Metal Panel	169A Camera Viewing Rm	337	SF	6	10+ years		
Ceiling - Lay-in	169B Police Office	146	SF	6	10+ years		
Doors - Steel Doors incl hw	169B Police Office	1	EA	6	10+ years		
Floor - Tile	169B Police Office	146	SF	6	10+ years		
Lighting - Pendent/Surface	169B Police Office	3	EA	7	6-10 years		
Power Distribution	169B Police Office	2	EA	6	10+ years		
Walls - Concrete Block	169B Police Office	128	SF	7	10+ years		
Walls - Metal Panel	169B Police Office	428	SF	6	10+ years		
Ceiling - Plaster/Drywall	169C Copy/File Rm.	200	SF	6	10+ years		
Doors - Wood Doors inclu hw	169C Copy/File Rm.	2	EA	7	10+ years		
Floor - Tile	169C Copy/File Rm.	200	SF	6	10+ years		
Lighting - Pendent/Surface	169C Copy/File Rm.	4	EA	5	0-1 year	Does not work.	
Power Distribution	169C Copy/File Rm.	4	EA	7	10+ years	/	
Walls - Concrete Block	169C Copy/File Rm.	24	SF	7	10+ years		
Walls - Concrete Block	169C Copy/File Rm.	6	SF	5	0-1 year	Cracked CMU tiles	
Walls - Metal Panel	169C Copy/File Rm.	298	SF	6	10+ years		
Walls - Plaster/Drywall	169C Copy/File Rm.	238	SF	6	10+ years		
Ceiling - Lay-in	169D Office	191	SF	6	10+ years		



Building : Main-Building A Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw 169D Office ΕA 10+ vears 7 1 169D Office 191 SF Floor - Tile 6 10+ vears Lighting - Lay-in 169D Office 2 FΑ 7 6-10 years Power Distribution 7 169D Office 4 EΑ 10+ years SF Walls - Concrete Block 169D Office 50 7 10+ years SF Walls - Metal Panel 169D Office 150 6 10+ years Walls - Plaster/Drywall 169D Office 232 SF 7 10+ years SF Ceiling - Lay-in 169E Conference Rm 155 6 10+ years Doors - Wood Doors inclu hw 169E Conference Rm 1 EΑ 7 10+ vears SF Floor - Tile 169E Conference Rm 155 6 10+ vears Lighting - Lay-in 169E Conference Rm 2 ΕA 7 6-10 years Power Distribution 169E Conference Rm 4 EΑ 7 10+ years Walls - Concrete Block SF 6 10+ years 169E Conference Rm 164 7 SF Walls - Plaster/Drywall 169E Conference Rm 203 10+ years Ceiling - Lay-in SF 170 Nurse's Office 316 6 10+ years Doors - Wood Doors inclu hw FΑ 7 170 Nurse's Office 1 10+ years Floor - Tile SF 170 Nurse's Office 316 6 10+ vears Lighting - Lay-in 170 Nurse's Office 5 EΑ 5 0-1 year Does not work. 4 7 Power Distribution 170 Nurse's Office EΑ 10+ vears Walls - Concrete Block 170 Nurse's Office 338 SF 7 10+ years Walls - Metal Panel 170 Nurse's Office 298 SF 6 10+ years SF 6 10+ years Walls - Plaster/Drywall 170 Nurse's Office 145 SF 6 Ceiling - Lay-in 170A 95 10+ years Doors - Side-lite SF 7 170A 12 10+ years Doors - Transom Window 170A 5 SF 7 10+ years 2 Doors - Wood Doors inclu hw 170A ΕA 6 10+ vears 95 SF Floor - Tile 170A 4 0-1 year Dirty and minor holes developing. Lighting - Lay-in 170A 2 ΕA 7 6-10 years **Power Distribution** 170A 4 EΑ 7 10+ years Walls - Concrete Block 170A 77 SF 7 10+ years SF Walls - Metal Panel 170A 256 6 10+ vears SF Ceiling - Lav-in 170B 146 6 10+ vears Doors - Side-lite SF 7 10+ years 170B 50 Doors - Steel Doors incl hw 170B FΑ 7 10+ years 1 SF Floor - Tile 170B 146 6 10+ years ΕA 7 Lighting - Lay-in 170B 3 6-10 years **Power Distribution** 170B 8 EΑ 7 10+ years Walls - Metal Panel SF 170B 424 6 10+ years SF Ceiling - Lay-in 170C Office 198 6 10+ years Doors - Steel Doors incl hw 7 170C Office 1 EΑ 10+ vears Floor - Carpet 170C Office 198 SF 6 6-10 years Lighting - Lay-in 170C Office FΑ 7 6-10 years 4 Power Distribution 170C Office 16 EΑ 7 10+ years Walls - Concrete Block SF 170C Office 50 7 10+ years



Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Metal Panel	170C Office	475	SF	6	10+ years	
	Ceiling - Lay-in	170D Exam Room	147	SF	6	10+ years	
	Doors - Steel Doors incl hw	170D Exam Room	1	EA	6	10+ years	
	Floor - Tile	170D Exam Room	147	SF	6	10+ years	
	Lighting - Lay-in	170D Exam Room	3	EA	6	6-10 years	
	Power Distribution	170D Exam Room	4	EA	7	10+ years	
	Walls - Concrete Block	170D Exam Room	222	SF	7	10+ years	
	Walls - Metal Panel	170D Exam Room	277	SF	6	10+ years	
	Ceiling - Lay-in	171 Main Office	2,424	SF	6	10+ years	
	Doors - Side-lite	171 Main Office	100	SF	7	10+ years	
	Doors - Steel Doors incl hw	171 Main Office	1	EA	7	10+ years	
	Doors - Steel Doors incl hw	171 Main Office	4	EA	7	10+ years	
	Doors - Transom Window	171 Main Office	5	SF	7	10+ years	
	Floor - Carpet	171 Main Office	2,109	SF	7	6-10 years	Repaired.
	Floor - Tile	171 Main Office	315	SF	6	10+ years	·
	Lighting - Lay-in	171 Main Office	30	EA	6	6-10 years	
	Power Distribution	171 Main Office	28	EA	7	10+ years	
	Storage/ Closet	171 Main Office	903	SF	5	10+ years	
	Walls - Concrete Block	171 Main Office	450	SF	7	10+ years	
	Walls - Metal Panel	171 Main Office	726	SF	6	10+ years	
	Walls - Plaster/Drywall	171 Main Office	50	SF	7	10+ years	
	Ceiling - Lay-in	171A Conference Room	219	SF	6	10+ years	
	Doors - Side-lite	171A Conference Room	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	171A Conference Room	1	EA	7	10+ years	
	Doors - Transom Window	171A Conference Room	20	SF	7	10+ years	
	Floor - Carpet	171A Conference Room	219	SF	6	6-10 years	
	Lighting - Pendent/Surface	171A Conference Room	4	ĒA	7	6-10 years	
	Walls - Concrete Block	171A Conference Room	100	SF	7	10+ years	
	Walls - Metal Panel	171A Conference Room	223	SF	7	10+ years	
	Walls - Plaster/Drywall	171A Conference Room	124	SF	6	10+ years	
	Work Sink	171A Conference Room	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	174 Storage	355	SF	6	10+ years	
	Doors - Side-lite	174 Storage	25	SF	7	10+ years	
	Doors - Transom Window	174 Storage	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	174 Storage	1	EA	7	10+ years	
	Floor - Concrete	174 Storage	355	SF	5	10+ years	Minor cracking.
	Lighting - Pendent/Surface	174 Storage	8	EA	7	6-10 years	Winter erdeking.
	Power Distribution	174 Storage	6	EA	7	10+ years	
	Walls - Concrete Block	174 Storage	50	SF	6	10+ years	
	Walls - Metal Panel	174 Storage	450	SF	7	10+ years	
	Walls - Plaster/Drywall	174 Storage	124	SF	6	10+ years	
	Ceiling - Lay-in	176 Office	178	SF	6	10+ years	
	Doors - Side-lite	176 Office	170	SF	7	10+ years	
	Doors - Steel Doors incl hw	176 Office	1	EA	7	10+ years	
			1	LA	1	IUT years	



Building : Main-Building A Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Carpet 176 Office 178 SF 6 6-10 years 176 Office ΕA 6 6-10 vears Lighting - Lay-in 4 **Power Distribution** 176 Office 8 FΑ 7 10+ years Walls - Concrete Block 278 SF 7 176 Office 10+ years SF 7 Walls - Metal Panel 176 Office 124 10+ years SF Ceiling - Lay-in 177 Office 145 6 10+ years Doors - Side-lite 177 Office SF 7 10+ years 35 Doors - Steel Doors incl hw 177 Office 1 EΑ 7 10+ years Doors - Transom Window 177 Office 25 SF 7 10+ years SF Floor - Carpet 177 Office 145 6 6-10 years Lighting - Lay-in 177 Office 3 ΕA 6 6-10 years Power Distribution 177 Office 6 EΑ 7 10+ years Walls - Concrete Block 177 Office 40 SF 7 10+ years SF Walls - Metal Panel 177 Office 313 6 10+ years Ceiling - Lay-in SF 6 178 Principal Reception Area 374 10+ years Ceiling - Lay-in SF 4 178 Principal Reception Area 16 0-1 year Water damage Doors - Side-lite SF 7 178 Principal Reception Area 15 10+ vears Doors - Steel Doors incl hw 178 Principal Reception Area 1 EΑ 7 10+ years 178 Principal Reception Area SF Floor - Carpet 390 6 6-10 vears 178 Principal Reception Area Lighting - Lay-in 8 EΑ 7 6-10 years Power Distribution 178 Principal Reception Area 4 ΕA 7 10+ years SF 7 Walls - Concrete Block 178 Principal Reception Area 80 10+ years SF Walls - Metal Panel 178 Principal Reception Area 588 6 10+ years SF 7 Walls - Plaster/Drywall 178 Principal Reception Area 90 10+ years Ceiling - Lay-in 180 Principal's Office SF 6 277 10+ years Doors - Side-lite SF 180 Principal's Office 24 7 10+ vears Doors - Steel Doors incl hw 180 Principal's Office 2 EA 7 10+ years Doors - Transom Window 180 Principal's Office 10 SF 7 10+ years Doors - Wood Doors inclu hw 180 Principal's Office 1 EΑ 7 10+ years Floor - Tile 180 Principal's Office 277 SF 6 10+ years Lighting - Lay-in 180 Principal's Office 6 ΕA 6 6-10 years Power Distribution 180 Principal's Office 8 EΑ 7 10+ vears SF 7 10+ years Walls - Concrete Block 180 Principal's Office 70 Walls - Metal Panel 180 Principal's Office 404 SF 7 10+ years SF Ceiling - Lay-in 182 Conference Room 257 6 10+ years SF 7 Doors - Side-lite 182 Conference Room 12 10+ years Doors - Steel Doors incl hw 182 Conference Room 2 EΑ 7 10+ years Doors - Transom Window 5 SF 7 182 Conference Room 10+ years SF Floor - Tile 182 Conference Room 257 6 10+ years ΕA 7 Lighting - Lav-in 182 Conference Room 5 6-10 years Power Distribution 182 Conference Room 8 ΕA 7 10+ years SF 7 Walls - Concrete Block 182 Conference Room 128 10+ vears Walls - Metal Panel 182 Conference Room 413 SF 7 10+ years SF Ceiling - Lay-in 183 Office 140 6 10+ years



Catego	ry : Room	Building : Main-Building A						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Side-lite	183 Office	12	SF	7	10+ years		
	Doors - Steel Doors incl hw	183 Office	1	EA	7	10+ years		
	Doors - Transom Window	183 Office	5	SF	7	10+ years		
	Doors - Wood Doors inclu hw	183 Office	1	EA	7	10+ years		
	Floor - Carpet	183 Office	140	SF	6	6-10 years		
	Lighting - Lay-in	183 Office	5	EA	6	6-10 years		
	Power Distribution	183 Office	4	EA	7	10+ years		
	Walls - Concrete Block	183 Office	80	SF	7	10+ years		
	Walls - Metal Panel	183 Office	352	SF	6	10+ years		
	Ceiling - Lay-in	184 Office	331	SF	6	10+ years		
	Doors - Side-lite	184 Office	12	SF	7	10+ years		
	Doors - Steel Doors incl hw	184 Office	1	EA	7	10+ years		
	Doors - Transom Window	184 Office	5	SF	7	10+ years		
	Doors - Wood Doors inclu hw	184 Office	1	EA	7	10+ years		
	Floor - Carpet	184 Office	331	SF	6	6-10 years		
	Lighting - Lay-in	184 Office	10	EA	7	6-10 years		
	Power Distribution	184 Office	6	EA	7	10+ years		
	Walls - Concrete Block	184 Office	360	SF	6	10+ years		
	Walls - Metal Panel	184 Office	343	SF	6	10+ years		
	Ceiling - Lay-in	185 Assistant Principals Office	192	SF	6	10+ years		
	Doors - Side-lite	185 Assistant Principals Office	12	SF	7	10+ years		
	Doors - Steel Doors incl hw	185 Assistant Principals Office	1	EA	7	10+ years		
	Doors - Transom Window	185 Assistant Principals Office	5	SF	7	10+ years		
	Doors - Wood Doors inclu hw	185 Assistant Principals Office	1	EA	7	10+ years		
	Floor - Carpet	185 Assistant Principals Office	192	SF	6	6-10 years		
	Lighting - Lay-in	185 Assistant Principals Office	7	EA	7	6-10 years		
	Power Distribution	185 Assistant Principals Office	6	EA	7	10+ years		
	Walls - Concrete Block	185 Assistant Principals Office	79	SF	7	10+ years		
	Walls - Metal Panel	185 Assistant Principals Office	452	SF	6	10+ years		
	Ceiling - Lay-in	186 Mail Room	146	SF	6	10+ years		
	Doors - Side-lite	186 Mail Room	12	SF	7	10+ years		
	Doors - Transom Window	186 Mail Room	5	SF	7	10+ years		
	Doors - Wood Doors inclu hw	186 Mail Room	1	EA	6	10+ years		
	Floor - Tile	186 Mail Room	146	SF	6	10+ years		
	Lighting - Lay-in	186 Mail Room	3	ĒA	7	6-10 years		
	Power Distribution	186 Mail Room	2	EA	7	10+ years		
	Walls - Concrete Block	186 Mail Room	60	SF	7	10+ years		
	Walls - Metal Panel	186 Mail Room	308	SF	6	10+ years		
	Ceiling - Lay-in	187 Attendance Office	665	SF	6	10+ years		
	Doors - Side-lite	187 Attendance Office	24	SF	7	10+ years		
	Doors - Steel Doors incl hw	187 Attendance Office	1	EA	7	10+ years		
	Doors - Transom Window	187 Attendance Office	60	SF	7	10+ years		
	Doors - Wood Doors inclu hw	187 Attendance Office	2	EA	6	10+ years		
	Floor - Tile	187 Attendance Office	665	SF	6	10+ years		
			000	0.	Ũ	youro		



Category : Room			Building : Main-Building A						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	187 Attendance Office	12	EA	7	6-10 years			
	Power Distribution	187 Attendance Office	6	EA	7	10+ years			
	Storage/ Closet	187 Attendance Office	54	SF	7	10+ years			
	Walls - Concrete Block	187 Attendance Office	304	SF	7	10+ years			
	Walls - Metal Panel	187 Attendance Office	719	SF	6	10+ years			
	Ceiling - Lay-in	190 Office	97	SF	6	10+ years			
	Doors - Side-lite	190 Office	12	SF	7	10+ years			
	Doors - Transom Window	190 Office	5	SF	7	10+ years			
	Doors - Wood Doors inclu hw	190 Office	1	EA	6	10+ years			
	Floor - Tile	190 Office	97	SF	6	10+ years			
	Lighting - Lay-in	190 Office	2	EA	6	6-10 years			
	Power Distribution	190 Office	4	EA	7	10+ years			
	Walls - Concrete Block	190 Office	40	SF	7	10+ years			
	Walls - Metal Panel	190 Office	258	SF	6	10+ years			
	Ceiling - Lay-in	191 Office	144	SF	6	10+ years			
	Doors - Side-lite	191 Office	12	SF	7	10+ years			
	Doors - Steel Doors incl hw	191 Office	1	EA	6	10+ years			
	Doors - Transom Window	191 Office	5	SF	7	10+ years			
	Floor - Tile	191 Office	144	SF	6	10+ years			
	Lighting - Lay-in	191 Office	3	EA	6	6-10 years			
	Power Distribution	191 Office	4	EA	7	10+ years			
	Walls - Concrete Block	191 Office	160	SF	7	10+ years			
	Walls - Metal Panel	191 Office	208	SF	6	10+ years			
	Ceiling - Lay-in	192 - Meeting Room	1,104	SF	6	10+ years			
	Doors - Side-lite	192 - Meeting Room	24	SF	7	10+ years			
	Doors - Transom Window	192 - Meeting Room	30	SF	7	10+ years			
	Doors - Wood Doors inclu hw	192 - Meeting Room	3	EA	6	10+ years			
	Floor - Tile	192 - Meeting Room	1,104	SF	6	10+ years			
	Lighting - Lay-in	192 - Meeting Room	21	EA	7	6-10 years			
	Power Distribution	192 - Meeting Room	21	EA	7	•			
	Storage/ Closet	192 - Meeting Room	53	SF	5	10+ years 10+ years			
	Walls - Concrete Block	192 - Meeting Room	160	SF	7	10+ years			
	Walls - Metal Panel	192 - Meeting Room	636	SF	6				
		192 - Meeting Room 193 - Local School Council Office	122	SF	6	10+ years			
	Ceiling - Lay-in Doors - Side-lite	193 - Local School Council Office		SF	6 7	10+ years			
			12			10+ years			
	Doors - Transom Window	193 - Local School Council Office	5	SF	7	10+ years			
	Doors - Wood Doors inclu hw	193 - Local School Council Office	1	EA	7	10+ years			
	Floor - Carpet	193 - Local School Council Office	122	SF	6	6-10 years	Stained, needs to be cleaned.		
	Lighting - Lay-in	193 - Local School Council Office	2	EA	6	6-10 years			
	Power Distribution	193 - Local School Council Office	6	EA	7	10+ years			
	Walls - Concrete Block	193 - Local School Council Office	40	SF	7	10+ years			
	Walls - Metal Panel	193 - Local School Council Office	308	SF	6	10+ years			
	Ceiling - Lay-in	195 Special Ed Office	120	SF	6	10+ years			
	Doors - Side-lite	195 Special Ed Office	37	SF	7	10+ years			



Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	195 Special Ed Office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	195 Special Ed Office	1	EA	6	10+ years	Quantity changed to match current observations
	Floor - Tile	195 Special Ed Office	120	SF	6	10+ years	
	Lighting - Pendent/Surface	195 Special Ed Office	2	EA	7	6-10 years	
	Power Distribution	195 Special Ed Office	2	EA	6	10+ years	
	Walls - Concrete Block	195 Special Ed Office	30	SF	7	10+ years	
	Walls - Metal Panel	195 Special Ed Office	318	SF	6	10+ years	
	Work SInk	195 Special Ed Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	196 Conference Room	288	SF	6	10+ years	
	Ceiling - Lay-in	196 Conference Room	8	SF	4	0-1 year	Falling
	Doors - Wood Doors inclu hw	196 Conference Room	1	ĒA	6	10+ years	
	Floor - Tile	196 Conference Room	296	SF	6	10+ years	
	Lighting - Pendent/Surface	196 Conference Room	6	EA	7	6-10 years	
	Power Distribution	196 Conference Room	6	EA	7	10+ years	
	Walls - Concrete Block	196 Conference Room	60	SF	7	10+ years	
	Walls - Metal Panel	196 Conference Room	353	SF	6	10+ years	
	Ceiling - Lay-in	197 - Yearbook Office	190	SF	6	10+ years	
	Doors - Side-lite	197 - Yearbook Office	75	SF	7	10+ years	
	Doors - Transom Window	197 - Yearbook Office	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	197 - Yearbook Office	2	EA	7	10+ years	
	Floor - Tile	197 - Yearbook Office	190	SF	6	10+ years	
	Lighting - Pendent/Surface	197 - Yearbook Office	2	EA	6	6-10 years	
	Power Distribution	197 - Yearbook Office	10	EA	7	10+ years	
	Walls - Masonry	197 - Yearbook Office	40	SF	7	10+ years	
	Walls - Metal Panel	197 - Yearbook Office	78	SF	6	10+ years	
	Walls - Plaster/Drywall	197 - Yearbook Office	253	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor School Store	264	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor School Store	204	EA	7	10+ years	
	Floor - Tile	1st Floor School Store	264	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor School Store	6	EA	7	6-10 years	
	Power Distribution	1st Floor School Store	8	EA	7	10+ years	
	Walls - Masonry	1st Floor School Store	100	SF	7	10+ years	
	Walls - Metal Panel	1st Floor School Store	460	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st flr Senior Office (east side of	120	SF	7	10+ years	
		elevator 'A')				10+ years	
	Doors - Wood Doors inclu hw	1st flr Senior Office (east side of elevator 'A')	1	EA	6	10+ years	
	Floor - Tile	1st flr Senior Office (east side of elevator 'A')	120	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr Senior Office (east side of elevator 'A')	1	EA	7	6-10 years	
	Power Distribution	1st flr Senior Office (east side of elevator 'A')	4	EA	6	10+ years	



Catego	ory : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st flr Senior Office (east side of	232	SF	7	10+ years	
		elevator 'A')					
	Walls - Metal Panel	1st flr Senior Office (east side of	40	SF	7	10+ years	
		elevator 'A')					
	Walls - Plaster/Drywall	1st flr Senior Office (east side of	138	SF	7	10+ years	
		elevator 'A')					
	Ceiling - Lay-in	226 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	226 - Guidance Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	226 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	226 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	226 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	226 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	226 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	227 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	227 - Guidance Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	227 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	227 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	227 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	227 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	227 - Guidance Office	350	SF	7	10+ years	
	Ceiling - Lay-in	228 - Guidance Office	115	SF	6	10+ years	
	Doors - Wood Doors inclu hw	228 - Guidance Office	1	EA	7	10+ years	
	Floor - Tile	228 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	228 - Guidance Office	4	EA	6	6-10 years	
	Power Distribution	228 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	228 - Guidance Office	350	SF	7	10+ years	
	Ceiling - Lay-in	229 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	229 - Guidance Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	229 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	229 - Guidance Office	115	SF	7	10+ years	
	Lighting - Lay-in	229 - Guidance Office	4	EA	6	6-10 years	
	Power Distribution	229 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	229 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	230 - IMBYB Office	115	SF	6	10+ years	
	Doors - Transom Window	230 - IMBYB Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	230 - IMBYB Office	1	EA	6	10+ years	
	Floor - Tile	230 - IMBYB Office	115	SF	6	10+ years	
	Lighting - Lay-in	230 - IMBYB Office	4	ĒA	6	6-10 years	
	Power Distribution	230 - IMBYB Office	2	EA	7	10+ years	
	Walls - Metal Panel	230 - IMBYB Office	350	SF	6	10+ years	
	Ceiling - Lay-in	231 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	231 - Guidance Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	231 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	231 - Guidance Office	115	SF	7	10+ years	
	-				-	,	



Catego	ry : Room		В	uilding	: Main-	Building A	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	231 - Guidance Office	3	EA	6	6-10 years	
	Power Distribution	231 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	231 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	235B Library work room	142	SF	6	10+ years	
	Ceiling - Lay-in	235B Library work room	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	235B Library work room	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	235B Library work room	1	EA	6	10+ years	
	Doors - Transom Window	235B Library work room	13	SF	6	10+ years	
	Floor - Tile	235B Library work room	150	SF	7	10+ years	
	Lighting - Lay-in	235B Library work room	3	EA	7	6-10 years	
	Power Distribution	235B Library work room	6	EA	7	10+ years	
	Walls - Metal Panel	235B Library work room	750	SF	6	10+ years	
	Ceiling - Lay-in	235C Media Viewing	550	SF	6	10+ years	
	Doors - Steel Doors incl hw	235C Media Viewing	1	EA	6	10+ years	
	Doors - Transom Window	235C Media Viewing	9	SF	6	10+ years	
	Floor - Tile	235C Media Viewing	550	SF	7	10+ years	
	Lighting - Lay-in	235C Media Viewing	11	EA	6	6-10 years	
	Power Distribution	235C Media Viewing	18	EA	7	10+ years	
	Walls - Concrete Block	235C Media Viewing	250	SF	6	10+ years	
	Walls - Metal Panel	235C Media Viewing	720	SF	6	10+ years	
	Ceiling - Lay-in	235D Computer Room in Library	625	SF	6	10+ years	
	Doors - Steel Doors incl hw	235D Computer Room in Library	1	EA	6	10+ years	
	Floor - Tile	235D Computer Room in Library	625	SF	7	10+ years	
	Lighting - Lay-in	235D Computer Room in Library	13	EA	6	6-10 years	
	Power Distribution	235D Computer Room in Library	64	EA	7	10+ years	
	Walls - Concrete Block	235D Computer Room in Library	300	SF	7	10+ years	
	Walls - Metal Panel	235D Computer Room in Library	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	236A-Library	2,596	SF	6	10+ years	
	Doors - Steel Doors incl hw	236A-Library	2	EA SF	7	10+ years	
	Doors - Transom Window	236A-Library	15	EA	6 6	10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	236A-Library 236A-Library	2,596	SF	7	10+ years 10+ years	
	Lighting - Pendent/Surface	236A-Library	2,590	EA	6	6-10 years	
	Power Distribution	236A-Library	20	EA	6	10+ years	
	Walls - Concrete Block	236A-Library	930	SF	6	10+ years	
	Walls - Metal Panel	236A-Library	1,300	SF	6	10+ years	
	Work Sink	236A-Library	1,300	EA	7	10+ years	
	Ceiling - Lay-in	236B Resource Area	225	SF	6	10+ years	
	Doors - Steel Doors incl hw	236B Resource Area	225	EA	6	10+ years	
	Doors - Transom Window	236B Resource Area	18	SF	6	10+ years	
	Floor - Tile	236B Resource Area	225	SF	7	10+ years	
	Lighting - Lay-in	236B Resource Area	4	EA	6	6-10 years	
	Power Distribution	236B Resource Area	12	EA	7	10+ years	
						•	
	Walls - Metal Panel	236B Resource Area	847	SF	6	10+ years	



Building : Main-Building A Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Lav-in 236C 126 SF 6 10+ vears Doors - Steel Doors incl hw 236C 2 ΕA 6 10+ years Doors - Transom Window 236C 6 SF 6 10+ years Floor - Tile 236C SF 7 126 10+ years Lighting - Lay-in 7 236C 3 EΑ 6-10 years 6 Power Distribution 236C EΑ 6 10+ years Walls - Metal Panel 236C 400 SF 7 10+ years SF Ceiling - Lay-in 236E 266 6 10+ years Doors - Side-lite 236E 10 SF 6 10+ years Doors - Steel Doors incl hw 236E EΑ 6 10+ years 1 Doors - Transom Window 236E 6 SF 6 10+ vears Floor - Tile 236E 266 SF 7 10+ years Lighting - Lay-in 236E 6 ΕA 7 6-10 years ΕA Power Distribution 236E 8 6 10+ years 236E SF Walls - Metal Panel 579 6 10+ years 236F SF 6 Ceiling - Lay-in 171 10+ years SF Doors - Side-lite 236F 10 6 10+ years Doors - Steel Doors incl hw 236F 1 EΑ 6 10+ years SF Floor - Tile 236F 171 7 10+ vears Lighting - Lay-in 236F 4 EΑ 7 6-10 years Power Distribution 236F 12 ΕA 6 10+ years 236F SF Walls - Metal Panel 515 6 10+ years SF 6 Ceiling - Lay-in 238 Office 172 10+ years SF Ceiling - Lay-in 238 Office 8 4 0-1 year Water damage Doors - Side-lite 238 Office 10 SF 6 10+ years Doors - Steel Doors incl hw 238 Office 1 ΕA 7 10+ vears 6 SF Doors - Transom Window 238 Office 6 10+ years Floor - Tile 238 Office 180 SF 6 10+ years 238 Office 7 Lighting - Lay-in 4 EΑ 6-10 years **Power Distribution** 238 Office 8 ΕA 7 10+ years Walls - Metal Panel 238 Office 380 SF 6 10+ vears SF Ceiling - Lav-in 239 open office 3.318 6 10+ vears Doors - Side-lite SF 7 239 open office 15 10+ years Doors - Transom Window 239 open office 18 SF 6 10+ years 2 7 Doors - Wood Doors inclu hw 239 open office EΑ 10+ years Floor - Tile SF 239 open office 3,318 6 10+ years Lighting - Lay-in 239 open office 67 EΑ 6 6-10 years Power Distribution 239 open office 7 30 EΑ 10+ years Storage/ Closet 239 open office 42 SF 5 10+ years SF Walls - Metal Panel 239 open office 2.450 6 10+ vears Ceiling - Plaster/Drywall SF 239A 280 6 10+ years Doors - Transom Window 239A SF 6 6 10+ vears Doors - Wood Doors inclu hw 239A 1 EΑ 7 10+ years SF Floor - Concrete 239A 280 5 10+ years



Catego	ry : Room		В	uilding	: Main-E	Building A	· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	239A	4	EA	7	6-10 years	
	Power Distribution	239A	4	EA	6	10+ years	
	Walls - Metal Panel	239A	650	SF	6	10+ years	
	Ceiling - Lay-in	239B SE Corner	90	SF	6	10+ years	
	Doors - Side-lite	239B SE Corner	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	239B SE Corner	1	EA	7	10+ years	
	Floor - Tile	239B SE Corner	90	SF	6	10+ years	
	Lighting - Lay-in	239B SE Corner	4	EA	6	6-10 years	
	Power Distribution	239B SE Corner	4	EA	7	10+ years	
	Walls - Concrete Block	239B SE Corner	90	SF	6	10+ years	
	Walls - Metal Panel	239B SE Corner	205	SF	6	10+ years	
	Ceiling - Lay-in	240 Open Office	710	SF	6	10+ years	
	Doors - Steel Doors incl hw	240 Open Office	1	EA	7	10+ years	
	Doors - Transom Window	240 Open Office	9	SF	6	10+ years	
	Floor - Tile	240 Open Office	710	SF	6	10+ years	
	Lighting - Lay-in	240 Open Office	14	EA	6	6-10 years	
	Power Distribution	240 Open Office	14	EA	7	10+ years	
	Storage/ Closet	240 Open Office	64	SF	5	10+ years	
	Walls - Concrete Block	240 Open Office	340	SF	7	10+ years	
	Walls - Metal Panel	240 Open Office	630	SF	6	10+ years	
	Work Sink	240 Open Office	1	EA	7	10+ years	
	Ceiling - Lay-in	240B Office	81	SF	6	10+ years	
	Doors - Steel Doors incl hw	240B Office	1	EA	6	10+ years	
	Floor - Tile	240B Office	81	SF	6	10+ years	
	Lighting - Lay-in	240B Office	4	EA	6	6-10 years	
	Power Distribution		4	EA	-	•	
		240B Office		SF	6	10+ years	
	Walls - Metal Panel	240B Office	180	SF	6 6	10+ years	
	Ceiling - Lay-in	241A	231	SF	-	10+ years	
	Doors - Transom Window	241A	6		6	10+ years	
	Doors - Wood Doors inclu hw	241A	1	EA	6	10+ years	
	Floor - Carpet	241A	231	SF	4	0-1 year	Carpet was removed
	Lighting - Lay-in	241A	4	EA	7	6-10 years	
	Power Distribution	241A	4	EA	6	10+ years	
	Walls - Concrete Block	241A	438	SF	6	10+ years	
	Walls - Concrete Block	241A	3	SF	5	0-1 year	Cracks.
	Ceiling - Lay-in	242C	81	SF	6	10+ years	
	Doors - Steel Doors incl hw	242C	1	EA	7	10+ years	
	Floor - Tile	242C	81	SF	6	10+ years	
	Lighting - Lay-in	242C	4	EA	7	6-10 years	
	Power Distribution	242C	4	EA	7	10+ years	
	Walls - Concrete Block	242C	70	SF	6	10+ years	
	Walls - Metal Panel	242C	185	SF	6	10+ years	
	Ceiling - Lay-in	246/247 Media Center Office	681	SF	6	10+ years	
	Doors - Side-lite	246/247 Media Center Office	10	SF	6	10+ years	



Catego	ory : Room		Building : Main-Building A				
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	246/247 Media Center Office	2	EA	6	10+ years	
	Doors - Transom Window	246/247 Media Center Office	12	SF	6	10+ years	
	Floor - Tile	246/247 Media Center Office	681	SF	7	10+ years	
	Lighting - Lay-in	246/247 Media Center Office	14	EA	6	6-10 years	
	Power Distribution	246/247 Media Center Office	8	EA	7	10+ years	
	Walls - Metal Panel	246/247 Media Center Office	716	SF	6	10+ years	
	Ceiling - Lay-in	256 Office	120	SF	6	10+ years	
	Doors - Steel Doors incl hw	256 Office	1	EA	7	10+ years	
	Doors - Transom Window	256 Office	9	SF	7	10+ years	
	Floor - Tile	256 Office	120	SF	6	10+ years	
	Lighting - Lay-in	256 Office	4	EA	6	6-10 years	
	Power Distribution	256 Office	10	EA	6	10+ years	
	Walls - Metal Panel	256 Office	281	SF	6	10+ years	
	Ceiling - Lay-in	261A - Yearbook Office	270	SF	6	10+ years	
	Doors - Side-lite	261A - Yearbook Office	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	261A - Yearbook Office	1	EA	6	10+ years	
	Doors - Transom Window	261A - Yearbook Office	9	SF	6	10+ years	
	Floor - Tile	261A - Yearbook Office	270	SF	6	10+ years	
	Lighting - Lay-in	261A - Yearbook Office	6	EA	6	6-10 years	
	Power Distribution	261A - Yearbook Office	3	EA	6	10+ years	
	Walls - Concrete Block	261A - Yearbook Office	42	SF	6	10+ years	
	Walls - Metal Panel	261A - Yearbook Office	350	SF	6	10+ years	
	Ceiling - Lay-in	276 - Coordinator Office	190	SF	6	10+ years	
	Doors - Side-lite	276 - Coordinator Office	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	276 - Coordinator Office	1	EA	7	10+ years	
	Doors - Transom Window Floor - Tile	276 - Coordinator Office 276 - Coordinator Office	9 190	SF SF	6 6	10+ years	
		276 - Coordinator Office	190		6	10+ years 6-10 years	
	Lighting - Lay-in Power Distribution	276 - Coordinator Office	4	EA EA	6		
	Walls - Metal Panel	276 - Coordinator Office	6 445	SF	6	10+ years	
	Ceiling - Lay-in	281 - IB Coordinator Office	445 190	SF	6	10+ years	
	Doors - Side-lite	281 - IB Coordinator Office	190	SF	6	10+ years	
	Doors - Steel Doors incl hw	281 - IB Coordinator Office	1	EA	7	10+ years	
	Doors - Transom Window	281 - IB Coordinator Office	9	SF	6	10+ years	
	Floor - Tile	281 - IB Coordinator Office	9 190	SF	6	10+ years 10+ years	
	Lighting - Lay-in	281 - IB Coordinator Office	4	EA	6	6-10 years	
	Power Distribution	281 - IB Coordinator Office	4	EA	6	10+ years	
	Walls - Metal Panel	281 - IB Coordinator Office	445	SF	6	10+ years	
	Ceiling - Lay-in	326 - Guidance Office	445 115	SF	6	10+ years	
	Doors - Transom Window	326 - Guidance Office	1	SF	7	10+ years	
	Doors - Wood Doors inclu hw	326 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	326 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	326 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	326 - Guidance Office	2	EA	7	10+ years	
		320 - Guidance Onice	2	EA	I	IUT years	



Catego	ry : Room		R	uilding	: Main-F	Building A	1959 S AICHEI AVEINDE, CHICAGO, IL 60052
Jacogo				anang	. man-L	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Walls - Metal Panel	326 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	327 Office	115	SF	7	10+ years	
	Doors - Transom Window	327 Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	327 Office	1	EA	7	10+ years	
	Floor - Tile	327 Office	115	SF	7	10+ years	
	Lighting - Lay-in	327 Office	9	EA	7	6-10 years	
	Power Distribution	327 Office	2	EA	7	10+ years	
	Walls - Metal Panel	327 Office	350	SF	7	10+ years	
	Ceiling - Lay-in	328 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	328 - Guidance Office	9	SF	7	10+ years	Quantity changed to match current
	Doors - mansom window	326 - Guidance Onice	9		'	-	observations
	Doors - Wood Doors inclu hw	328 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	328 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	328 - Guidance Office	4	EA	7	6-10 years	
	Power Distribution	328 - Guidance Office	2	EA	7	10+ vears	
	Walls - Masonry	328 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	329 Speech/Language/Hearing	115	SF	7	10+ years	
		Office	-				
	Doors - Transom Window	329 Speech/Language/Hearing Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	329 Speech/Language/Hearing Office	1	EA	7	10+ years	
	Floor - Tile	329 Speech/Language/Hearing	115	SF	7	10+ years	
	Lighting - Lay-in	Office 329 Speech/Language/Hearing	4	EA	6	6-10 years	
		Office					
	Power Distribution	329 Speech/Language/Hearing Office	2	EA	7	10+ years	
	Walls - Metal Panel	329 Speech/Language/Hearing Office	350	SF	7	10+ years	
	Ceiling - Lay-in	330 - Guidance Office	115	SF	6	10+ years	
	Doors - Transom Window	330 - Guidance Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	330 - Guidance Office	1	EA	6	10+ years	
	Floor - Tile	330 - Guidance Office	115	SF	6	10+ years	
	Lighting - Lay-in	330 - Guidance Office	4	EA	6	6-10 years	
	Power Distribution	330 - Guidance Office	2	EA	7	10+ years	
	Walls - Metal Panel	330 - Guidance Office	350	SF	6	10+ years	
	Ceiling - Lay-in	331 Office	115	SF	7	10+ years	
	Doors - Transom Window	331 Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	331 Office	9	EA	7	10+ years	
				SF			
	Floor - Tile	331 Office	115		7	10+ years	
	Lighting - Lay-in	331 Office	4	EA	6	6-10 years	
	Power Distribution	331 Office	2	EA	7	10+ years	
	Walls - Metal Panel	331 Office	350	SF	7	10+ years	



Group

Category : Room **Building : Main-Building A** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Lav-in 333 Special Ed Department Office 1.040 SF 6 10+ vears Doors - Side-lite 333 Special Ed Department Office SF 6 10 10+ years Doors - Transom Window 333 Special Ed Department Office 6 SF 6 10+ years 333 Special Ed Department Office 6 Doors - Wood Doors inclu hw 1 EΑ 10+ years 1,040 SF Floor - Tile 333 Special Ed Department Office 6 10+ years 333 Special Ed Department Office Lighting - Lay-in 17 EA 6 6-10 years **Power Distribution** 333 Special Ed Department Office 26 ΕA 7 10+ years 333 Special Ed Department Office SF Walls - Concrete Block 157 7 10+ years SF Walls - Metal Panel 333 Special Ed Department Office 980 6 10+ years Ceiling - Plaster/Drywall SF 334A 136 7 10+ vears Doors - Transom Window SF 334A 9 7 10+ vears Doors - Wood Doors inclu hw 334A 1 EΑ 7 10+ years Floor - Tile 334A 120 SF 7 10+ years SF Floor - Tile 334A 16 4 0-1 year Rusty and damaged. Lighting - Pendent/Surface 2 ΕA 7 334A 6-10 years Power Distribution 334A 8 ΕA 7 10+ years SF 7 Walls - Concrete Block 334A 235 10+ years SF Walls - Metal Panel 334A 235 7 10+ years Ceiling - Lay-in SF 334B 136 7 10+ vears Doors - Wood Doors inclu hw 334B 1 EΑ 7 10+ years Doors - Wood Doors inclu hw 334B 9 ΕA 7 10+ years SF 7 10+ years Floor - Tile 334B 136 ΕA 7 Lighting - Lay-in 334B 2 6-10 years 7 Power Distribution 334B 6 FΑ 10+ years Walls - Concrete Block 334B SF 7 135 10+ years SF Walls - Metal Panel 334B 335 7 10+ vears 341A/B Office SF Ceiling - Lay-in 118 7 10+ years Ceiling - Plaster/Drywall 341A/B Office 100 SF 7 10+ years Doors - Side-lite SF 341A/B Office 40 7 10+ years Doors - Transom Window 341A/B Office 9 SF 7 10+ years Doors - Wood Doors inclu hw 341A/B Office 1 ΕA 7 10+ vears Floor - Tile 341A/B Office 218 SF 7 10+ vears 7 341A/B Office FΑ 6-10 years Lighting - Lay-in 4 Lighting - Pendent/Surface 341A/B Office 1 FΑ 7 6-10 years Power Distribution 7 341A/B Office 4 EΑ 10+ years SF 7 Walls - Metal Panel 341A/B Office 540 10+ years SF Walls - Plaster/Drywall 341A/B Office 50 7 10+ years Ceiling - Plaster/Drywall SF 341C office/storage inside 118 6 10+ years classroom 341 Doors - Wood Doors inclu hw 341C office/storage inside 1 EΑ 7 10+ years classroom 341 SF Floor - Concrete 341C office/storage inside 7 Changed to match current 118 10+ years classroom 341 observations Lighting - Pendent/Surface 341C office/storage inside 2 EA 6 6-10 years Changed to match current



Catego	ory : Room		Building : Main-Building A							
	-			Ū		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		classroom 341					observations			
	Power Distribution	341C office/storage inside	8	EA	7	10+ years				
		classroom 341	-			- ,				
	Walls - Concrete Block	341C office/storage inside	200	SF	5	0-1 year	Cracking			
		classroom 341	200	•	°,	e i jea.	e a com a g			
	Walls - Metal Panel	341C office/storage inside	238	SF	7	10+ years				
		classroom 341	200	0.		io: jouro				
	Work SInk	341C office/storage inside	1	EA	5	6-10 years				
		classroom 341	•	L/ (U	o ro youro				
	Ceiling - Lay-in	342 Open Office	1,367	SF	6	10+ years				
	Ceiling - Lay-in	342 Open Office	1,307	SF	4	0-1 year	Water damage.			
	Doors - Side-lite	342 Open Office	30	SF	7	10+ years	Water damage.			
	Doors - Transom Window	342 Open Office	18	SF	7	10+ years				
	Doors - Wood Doors inclu hw	342 Open Office	2	EA	7	10+ years				
	Floor - Tile	342 Open Office	1,383	SF	6	10+ years				
	Lighting - Lay-in	342 Open Office	24	EA	6	6-10 years				
	Power Distribution		24 46	EA	7					
	Walls - Concrete Block	342 Open Office	46 450	SF	7	10+ years				
		342 Open Office				10+ years				
	Walls - Metal Panel	342 Open Office	1,400	SF	7	10+ years				
	Work SInk	342 Open Office	1	EA	7	10+ years				
	Ceiling - Plaster/Drywall	342A Coordinator Office Inside open	180	SF	6	10+ years				
		office 342(used as storage)	10	05	-	10				
	Doors - Transom Window	342A Coordinator Office Inside open	16	SF	7	10+ years				
		office 342(used as storage)	0	Ξ.	-	10				
	Doors - Wood Doors inclu hw	342A Coordinator Office Inside open	2	EA	7	10+ years	Changed to match current			
		office 342(used as storage)	400	05	-	10	observations			
	Floor - Concrete	342A Coordinator Office Inside open	180	SF	7	10+ years	Changed to match current			
		office 342(used as storage)				0.40	observations			
	Lighting - Lay-in	342A Coordinator Office Inside open	4	EA	6	6-10 years				
		office 342(used as storage)			_	4.0				
	Power Distribution	342A Coordinator Office Inside open	6	EA	7	10+ years				
		office 342(used as storage)		~-						
	Walls - Metal Panel	342A Coordinator Office Inside open	580	SF	6	10+ years	Changed to match current			
	.	office 342(used as storage)			_		observations			
	Ceiling - Lay-in	342B Office	84	SF	7	10+ years				
	Doors - Side-lite	342B Office	11	SF	7	10+ years				
	Doors - Transom Window	342B Office	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	342B Office	1	EA	7	10+ years				
	Floor - Tile	342B Office	84	SF	7	10+ years				
	Lighting - Lay-in	342B Office	2	EA	7	6-10 years				
	Power Distribution	342B Office	2	EA	7	10+ years				
	Walls - Metal Panel	342B Office	240	SF	7	10+ years				
	Ceiling - Lay-in	344 / 345 Open Office	2,123	SF	7	10+ years				
	Doors - Transom Window	344 / 345 Open Office	18	SF	7	10+ years				



Catego	ry : Room		В	uilding	: Main-F	Building A	1959 S Archer AVENUE, Chicago, IL 60632
Jacogo	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	344 / 345 Open Office	2	EA	7	10+ years	
	Floor - Tile	344 / 345 Open Office	2,123	SF	7	10+ years	
	Lighting - Lay-in	344 / 345 Open Office	41	EA	7	6-10 years	
	Power Distribution	344 / 345 Open Office	24	EA	7	6-10 years	
	Walls - Concrete Block	344 / 345 Open Office	720	SF	7	10+ years	
	Walls - Metal Panel	344 / 345 Open Office	1,350	SF	7	10+ years	
	Work SInk	344 / 345 Open Office	1	EA	7	10+ years	
	Ceiling - Lay-in	344A Office	81	SF	7	10+ years	
	Doors - Side-lite	344A Office	51	SF	7	10+ years	
	Doors - Transom Window	344A Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	344A Office	1	EA	7	10+ years	Quantity changed to match current observations
	Floor - Tile	344A Office	81	SF	7	10+ years	
	Lighting - Lay-in	344A Office	4	EA	7	6-10 years	
	Walls - Metal Panel	344A Office	180	SF	7	10+ years	
	Ceiling - Lay-in	345A	95	SF	6	10+ years	
	Doors - Wood Doors inclu hw	345A	1	EA	6	10+ years	
	Floor - Tile	345A	95	SF	6	10+ years	
	Lighting - Lay-in	345A	4	EA	6	6-10 years	
	Power Distribution	345A	2	EA	7	10+ years	
	Walls - Metal Panel	345A	200	SF	6	10+ years	
	Ceiling - Lay-in	350A science office	150	SF	7	10+ years	
	Doors - Side-lite	350A science office	14	SF	7	10+ years	
	Doors - Transom Window	350A science office	15	SF	7	10+ years	
	Floor - Tile	350A science office	150	SF	7	10+ years	
	Lighting - Pendent/Surface	350A science office	2	EA	7	6-10 years	
	Power Distribution	350A science office	3	EA	7	10+ years	
	Walls - Plaster/Drywall	350A science office	360	SF	7	10+ years	
	Ceiling - Lay-in	353B- Science Lab Office	108	SF	6	10+ years	
	Doors - Side-lite	353B- Science Lab Office	10	SF	6	10+ years	
	Doors - Transom Window	353B- Science Lab Office	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	353B- Science Lab Office	1	EA	6	10+ years	
	Floor - Tile	353B- Science Lab Office	108	SF	6	10+ years	
	Lighting - Lay-in	353B- Science Lab Office	2	EA	6	6-10 years	
	Power Distribution	353B- Science Lab Office	4	EA	7	10+ years	
	Walls - Metal Panel	353B- Science Lab Office	397	SF	7	10+ years	
	Ceiling - Lay-in	359 Office	700	SF	6	10+ years	
	Doors - Side-lite	359 Office	66	SF	7	10+ years	
	Doors - Transom Window	359 Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	359 Office	2	EA	6	10+ years	
	Floor - Terrazzo	359 Office	700	SF	6	10+ years	Changed to match current observations
	Lighting - Lay-in	359 Office	28	EA	6	6-10 years	
	Power Distribution	359 Office	8	EA	6	10+ years	



Marie Sklodowska Curie Metropolitan High School 4959 S Archer AVENUE, Chicago, IL 60632 Building · Main-Building A

Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	359 Office	376	SF	7	10+ years	
	Walls - Metal Panel	359 Office	580	SF	6	10+ years	
	Work SInk	359 Office	2	EA	5	6-10 years	
	Ceiling - Lay-in	382	162	SF	7	10+ years	
	Doors - Side-lite	382	22	SF	7	10+ years	
	Doors - Transom Window	382	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	382	2	EA	7	10+ years	
	Floor - Tile	382	162	SF	7	10+ years	
	Lighting - Lay-in	382	4	EA	7	6-10 years	
	Power Distribution	382	8	EA	7	10+ years	
	Walls - Metal Panel	382	230	SF	7	10+ years	
	Walls - Plaster/Drywall	382	200	SF	7	10+ years	
	Ceiling - Exposed	B14A Engineer's Shop	352	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B14A Engineer's Shop	4	EA	6	10+ years	
	Floor - Concrete	B14A Engineer's Shop	352	SF	5	10+ years	
	Lighting - Pendent/Surface	B14A Engineer's Shop	552	EA	6		
					7	6-10 years	
	Power Distribution	B14A Engineer's Shop	10	EA		10+ years	
	Walls - Concrete Block	B14A Engineer's Shop	755	SF	6	10+ years	
	Walls - Plaster/Drywall	B14A Engineer's Shop	61	SF	6	10+ years	
	Ceiling - Plaster/Drywall	B15 Engineer's Office	144	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B15 Engineer's Office	1	EA	6	10+ years	Quantity changed to match current observations
	Floor - Tile	B15 Engineer's Office	144	SF	6	10+ years	
	Lighting - Lay-in	B15 Engineer's Office	4	EA	7	6-10 years	
	Power Distribution	B15 Engineer's Office	44	EA	7	10+ years	
	Walls - Concrete Block	B15 Engineer's Office	458	SF	7	10+ years	
	Ceiling - Plaster/Drywall	B16 Engineer's Office	134	SF	7	10+ years	
	Doors - Wood Doors inclu hw	B16 Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	B16 Engineer's Office	134	SF	6	10+ years	Changed to match current observations
	Lighting - Lay-in	B16 Engineer's Office	4	EA	7	6-10 years	
	Power Distribution	B16 Engineer's Office	8	EA	7	10+ years	
	Walls - Concrete Block	B16 Engineer's Office	359	SF	7	10+ years	
	Ceiling - Lay-in	B3 Kitchen Office	135	SF	6	10+ years	
	Doors - Transom Window	B3 Kitchen Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	B3 Kitchen Office		EA	7	10+ years	
	Floor - Terrazzo	B3 Kitchen Office	135	SF	6	10+ years	
	Lighting - Pendent/Surface	B3 Kitchen Office	2	EA	6		
	Power Distribution	B3 Kitchen Office	2	EA	6	6-10 years 10+ years	
		B3 Kitchen Office	4 300	SF	6 7		
	Walls - Structural Glazed Tile					10+ years	
	Ceiling - Lay-in	Science office 348	180	SF	7	10+ years	
	Doors - Transom Window	Science office 348	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Science office 348	1	EA	7	10+ years	
	Floor - Tile	Science office 348	180	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main-E	Building A	Soo o Alonei Avenoe, omougo, ie oooe
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Science office 348	2	EA	7	6-10 years	
	Power Distribution	Science office 348	3	EA	7	10+ years	
	Walls - Metal Panel	Science office 348	360	SF	7	10+ years	Changed to match current observations
	Work SInk	Science office 348	1	EA	7	10+ years	
	Ceiling - Lay-in	Science office 361A	450	SF	6	10+ years	
	Doors - Side-lite	Science office 361A	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Science office 361A	2	ĒA	6	10+ years	
	Floor - Tile	Science office 361A	450	SF	6	10+ years	
	Lighting - Lay-in	Science office 361A	12	EA	6	6-10 years	
	Power Distribution	Science office 361A	4	EA	7	10+ years	
	Walls - Concrete Block	Science office 361A	950	SF	6	10+ years	
	Walls - Metal Panel	Science office 361A	360	SF	6	10+ years	
	Work SInk	Science office 361A	2	EA	5	6-10 years	
Kitchen							
	Ceiling - Lay-in	115 Canteen	185	SF	6	10+ years	
	Doors - Wood Doors inclu hw	115 Canteen	2	EA	7	10+ years	
	Floor - Terrazzo	115 Canteen	185	SF	6	10+ years	
	Lighting - Pendent/Surface	115 Canteen	3	EA	7	6-10 years	
	Walls - Structural Glazed Tile	115 Canteen	275	SF	7	10+ years	
	Ceiling - Lay-in	116 Serving Area	1,222	SF	6	10+ years	
	Doors - Transom Window	116 Serving Area	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	116 Serving Area	4	EA	6	10+ years	
	Doors - Wood Doors inclu hw	116 Serving Area	4	EA	6	10+ years	
	Floor - Terrazzo	116 Serving Area	1,222	SF	6	10+ years	
	Lighting - Pendent/Surface	116 Serving Area	22	EA	7	6-10 years	
	Serving Line	116 Serving Area	68	LF	7	10+ years	
	Walls - Masonry	116 Serving Area	410	SF	7	10+ years	
	Walls - Metal Panel	116 Serving Area	637	SF	6	10+ years	
	Walls - Structural Glazed Tile	116 Serving Area	1,040	SF	7	10+ years	
	Ceiling - Lay-in	1st flr Faculty Serving Area (158 on plan)	360	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr Faculty Serving Area (158 on plan)	3	EA	6	10+ years	
	Floor - Tile	1st flr Faculty Serving Area (158 on plan)	356	SF	7	10+ years	
	Floor - Tile	1st flr Faculty Serving Area (158 on plan)	4	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	1st flr Faculty Serving Area (158 on plan)	9	EA	6	6-10 years	
	Walls - Masonry	1st flr Faculty Serving Area (158 on plan)	100	SF	7	10+ years	
	Walls - Metal Panel	1st flr Faculty Serving Area (158 on	260	SF	6	10+ years	



Category : Room				Building : Main-Building A					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		plan)							
	Ceiling - Lay-in	216/215 Kitchen	1,354	SF	6	10+ years			
	Doors - Steel Doors incl hw	216/215 Kitchen	9	EA	7	10+ years			
	Doors - Wood Doors inclu hw	216/215 Kitchen	1	EA	7	10+ years			
	Floor - Terrazzo	216/215 Kitchen	920	SF	6	10+ years			
	Floor - Tile	216/215 Kitchen	434	SF	6	10+ years			
	Lighting - Lay-in	216/215 Kitchen	28	EA	6	6-10 years			
	Serving Line	216/215 Kitchen	84	LF	6	6-10 years			
	Walls - Metal Panel	216/215 Kitchen	500	SF	6	10+ years			
	Walls - Structural Glazed Tile	216/215 Kitchen	1,420	SF	7	10+ years			
	Ceiling - Lay-in	316/315 Serving Lines	1,354	SF	7	10+ years			
	Doors - Wood Doors inclu hw	316/315 Serving Lines	10	EA	7	10+ years			
	Floor - Terrazzo	316/315 Serving Lines	920	SF	7	10+ years			
	Floor - Tile	316/315 Serving Lines	430	SF	6	10+ years			
	Floor - Tile	316/315 Serving Lines	4	SF	4	0-1 year	Missing		
	Lighting - Lay-in	316/315 Serving Lines	28	EA	7	6-10 years	Missing		
	Serving Line	316/315 Serving Lines	84	LF	7				
			-	SF		10+ years			
	Walls - Masonry	316/315 Serving Lines	340		7	10+ years			
	Walls - Metal Panel	316/315 Serving Lines	500	SF	7	10+ years			
	Walls - Structural Glazed Tile	316/315 Serving Lines	1,420	SF	7	10+ years			
	Ceiling - Lay-in	Basement	3,047	SF	6	6-10 years	Changed to match current observations		
	Doors - Wood Doors inclu hw	Basement	3	EA	6	10+ years			
	Floor - Terrazzo	Basement	3,037	SF	6	10+ years	Changed to match current observations		
	Floor - Terrazzo	Basement	10	SF	4	0-1 year	Large cracks/changed to match current observations		
	Lighting - Pendent/Surface	Basement	59	EA	6	6-10 years			
	Storage/ Closet	Basement	825	SF	7	10+ years			
	Walls - Structural Glazed Tile	Basement	1,688	SF	7	10+ years			
brary									
,	Casework	2nd Floor	138	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	12,300	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	20	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	6	EA	6	10+ years			
	Floor - Tile	2nd Floor	12,300	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	162	EA	6	6-10 years			
	Storage/ Closet	2nd Floor	329	SF	5	10+ years			
	Walls - Concrete Block	2nd Floor	414	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	3,750	SF	6	10+ years			



Catego	ry : Room		В	uilding	: Main-E	Building A	
Ŭ	•			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	101/102 Faculty Lunchroom (157 &	1,443	SF	7	10+ years	
		157A on plan)				-	
	Doors - Wood Doors inclu hw	101/102 Faculty Lunchroom (157 &	2	EA	6	10+ years	
		157A on plan)					
	Floor - Tile	101/102 Faculty Lunchroom (157 &	1,443	SF	5	10+ years	
		157A on plan)				-	
	Lighting - Pendent/Surface	101/102 Faculty Lunchroom (157 &	24	EA	6	6-10 years	
	0	157A on plan)					
	Walls - Concrete Block	101/102 Faculty Lunchroom (157 &	820	SF	7	10+ years	
		157A on plan)				,	
	Walls - Metal Panel	101/102 Faculty Lunchroom (157 &	1,030	SF	6	10+ years	
		157A on plan)	,			- ,	
	Ceiling - Lay-in	118 West Lunchroom	1,675	SF	6	10+ years	
	Floor - Tile	118 West Lunchroom	1,675	SF	7	10+ years	
	Lighting - Pendent/Surface	118 West Lunchroom	28	EA	6	6-10 years	
	Walls - Masonry	118 West Lunchroom	445	SF	7	10+ years	
	Walls - Metal Panel	118 West Lunchroom	783	SF	6	10+ years	
	Ceiling - Lay-in	119 East Lunchroom	1,770	SF	7	10+ years	
	Floor - Tile	119 East Lunchroom	1,766	SF	7	10+ years	
	Floor - Tile	119 East Lunchroom	4	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	119 East Lunchroom	29	ĒA	7	6-10 years	•
	Walls - Masonry	119 East Lunchroom	485	SF	7	10+ years	
	Walls - Metal Panel	119 East Lunchroom	953	SF	7	10+ years	
	Ceiling - Lay-in	218 2nd Floor West	2,128	SF	6	10+ years	
	Floor - Tile	218 2nd Floor West	2,128	SF	6	10+ years	
	Lighting - Lay-in	218 2nd Floor West	33	EA	6	6-10 years	
	Serving Line	218 2nd Floor West	8	LF	7	10+ years	
	Student Lockers - One Tier	218 2nd Floor West	48	EA	7	10+ years	
	Walls - Masonry	218 2nd Floor West	421	SF	7	10+ years	
	Walls - Metal Panel	218 2nd Floor West	1,250	SF	6	10+ years	
	Ceiling - Lay-in	219 2nd Floor East	2,128	SF	6	10+ years	
	Floor - Tile	219 2nd Floor East	2,128	SF	6	10+ years	
	Lighting - Lay-in	219 2nd Floor East	33	EA	6	6-10 years	
	Storage/ Closet	219 2nd Floor East	8	SF	7	10+ years	
	Student Lockers - One Tier	219 2nd Floor East	48	EA	7	10+ years	
	Walls - Masonry	219 2nd Floor East	421	SF	7	10+ years	
	Walls - Metal Panel	219 2nd Floor East	1,250	SF	6	10+ years	
	Ceiling - Lay-in	318 3rd Floor West	2,128	SF	6	10+ years	
	Floor - Tile	318 3rd Floor West	2,128	SF	7	10+ years	
	Lighting - Lay-in	318 3rd Floor West	33	EA	7	6-10 years	
	Serving Line	318 3rd Floor West	8	LF	7	10+ years	
	Walls - Masonry	318 3rd Floor West	421	SF	7	10+ years	
	Walls - Metal Panel	318 3rd Floor West	1,250	SF	7	10+ years	
	Ceiling - Lay-in	319 3rd Floor East	2,128	SF	7	10+ years	
			2,120	01	'	ior years	



Category : Room			В	Building : Main-Building A					
entege	.,		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	319 3rd Floor East	2,128	SF	7	10+ years			
	Lighting - Lay-in	319 3rd Floor East	33	EA	7	6-10 years			
	Serving Line	319 3rd Floor East	8	LF	7	10+ years			
	Walls - Masonry	319 3rd Floor East	421	SF	7	10+ years			
	Walls - Metal Panel	319 3rd Floor East	1,250	SF	7	10+ years			
			,			,			
MDF_ID		007	4	۲.	0	10			
	Doors - Wood Doors inclu hw	237	1	EA	6	10+ years			
	Finishes	237	194	SF	5	10+ years			
	Other Cooling Unit	237	1	EA	7	6-10 years	Split system, Carrier.		
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	96	SF	5	10+ years	Water damage to ceiling.		
	Janitor's Closet	1st Floor	96	SF	5	10+ years			
	Mechanical/ Service Rooms	1st Floor	37	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	118	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	75	SF	7	10+ years			
	Storage Room	1st Floor	86	SF	7	10+ years			
	Storage Room	1st Floor	86	SF	7	10+ years			
	Storage Room	1st Floor	966	SF	7	10+ years			
	Storage Room	1st Floor	143	SF	7	10+ years			
	Janitor's Closet	2nd Floor Support Rooms	25	SF	5	10+ years			
	Janitor's Closet	2nd Floor Support Rooms	25	SF	5	10+ years			
	Janitor's Closet	2nd Floor Support Rooms	25	SF	5	10+ years			
	Janitor's Closet	2nd Floor Support Rooms	25	SF	5	10+ years			
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	5	10+ years			
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	5	10+ years			
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	5	10+ years			
	Mechanical/ Service Rooms	2nd Floor Support Rooms	20	SF	5	10+ years			
	Storage Room	2nd Floor Support Rooms	200	SF	5	10+ years			
	Storage Room	2nd Floor Support Rooms	49	SF	5	10+ years			
	Janitor's Closet	3rd Floor	25	SF	5	10+ years	Missing door handle. Hole in ceiling		
	Janitor's Closet	3rd Floor	25	SF	5	10+ years	3 1 1 1		
	Janitor's Closet	3rd Floor	25	SF	5	10+ years	Hole in ceiling.		
	Janitor's Closet	3rd Floor	25	SF	5	10+ years	Hole in ceiling.		
	Mechanical/ Service Rooms	3rd Floor	20	SF	5	10+ years			
	Mechanical/ Service Rooms	3rd Floor	65	SF	5	10+ years			
	Mechanical/ Service Rooms	3rd Floor	20	SF	5	10+ years			
	Mechanical/ Service Rooms	3rd Floor	20	SF	5	10+ years			
	Mechanical/ Service Rooms	3rd Floor	20	SF	5	10+ years			
	Storage Room	3rd Floor	204	SF	7	10+ years			
	Storage Room	3rd Floor	196	SF	5	10+ years			
	Storage Room	3rd Floor	126	SF	5	10+ years			
			120	SF	0	i u i youis			



Catego	ry : Room		В	uilding	: Main-E	Building A	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage Room	3rd Floor	89	SF	5	10+ years	
	Loading Docks	Basement Loading Dock	504	SF	5	10+ years	
	Janitor's Closet	Basement Service Rooms	21	SF	7	10+ years	B10A
	Mechanical/ Service Rooms	Basement Service Rooms	164	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement Service Rooms	537	SF	7	10+ years	B13A
	Mechanical/ Service Rooms	Basement Service Rooms	2,408	SF	7	10+ years	B12
	Mechanical/ Service Rooms	Basement Service Rooms	308	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement Service Rooms	40	SF	7	10+ years	B8
	Storage Room	Basement Service Rooms	368	SF	7	10+ years	
	Storage Room	Basement Service Rooms	278	SF	7	10+ years	
	Storage Room	Basement Service Rooms	369	SF	7	10+ years	
	Storage Room	Basement Service Rooms	152	SF	7	10+ years	
	Storage Room	Basement Service Rooms	609	SF	5	10+ years	
			000	01	Ũ	for yourd	
Prep Ro							
	Ceiling - Lay-in	151 Dark Room	461	SF	6	10+ years	
	Doors - Steel Doors incl hw	151 Dark Room	1	EA	4	0-1 year	Rotary Darkroom door is broken.
	Floor - Terrazzo	151 Dark Room	461	SF	7	6-10 years	
	Lighting - Pendent/Surface	151 Dark Room	8	EA	7	10+ years	
	Walls - Concrete Block	151 Dark Room	438	SF	7	10+ years	
	Walls - Metal Panel	151 Dark Room	514	SF	7	10+ years	
	Work Sink	151 Dark Room	2	EA	7	10+ years	
	Casework	340A	30	LF	6	10+ years	
	Ceiling - Lay-in	340A	175	SF	6	10+ years	
	Doors - Wood Doors inclu hw	340A	1	ĒΑ	6	10+ years	
	Floor - Tile	340A	175	SF	6	10+ years	
	Lighting - Lay-in	340A	3	ĒA	6	6-10 years	
	Walls - Metal Panel	340A	380	SF	6	10+ years	
	Walls - Plaster/Drywall	340A	219	SF	7	10+ years	
	Work Sink	340A	1	EA	7	10+ years	
	Ceiling - Lay-in	346A/B	406	SF	7	10+ years	
	Doors - Side-lite	346A/B	22	SF	7	10+ years	
	Doors - Transom Window	346A/B	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	346A/B	2	EA	7	10+ years	
	Floor - Tile	346A/B	406	SF	6	10+ years	
		346A/B 346A/B	406	EA	7		
	Lighting - Lay-in Walls - Concrete Block	346A/B 346A/B	o 78	SF	7	6-10 years	
				SF		10+ years	
	Walls - Metal Panel	346A/B	290		7	10+ years	
	Ceiling - Lay-in	349A/349B	272	SF	6	10+ years	Min alian
	Ceiling - Lay-in	349A/349B	16	SF	4	0-1 year	Missing
	Doors - Side-lite	349A/349B	28	SF	7	10+ years	
	Doors - Transom Window	349A/349B	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	349A/349B	2	EA	6	10+ years	
	Floor - Tile	349A/349B	288	SF	6	10+ years	



Building : Main-Building A Category : Room Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Lighting - Lay-in 349A/349B EΑ 10+ vears 11 6 Walls - Metal Panel 349A/349B 675 SF 6 10+ years Work Sink 349A/349B 2 FΑ 5 6-10 years 12 LF 6 Casework 350B 10+ years SF Ceiling - Lay-in 350B 204 6 10+ years SF Doors - Side-lite 350B 14 6 10+ years Doors - Transom Window 350B SF 7 18 10+ years SF Doors - Transom Window 350B 15 7 10+ years Doors - Wood Doors inclu hw 350B 1 EΑ 6 10+ years SF Floor - Tile 350B 204 6 10+ vears Lighting - Lav-in 350B 7 ΕA 6 6-10 years Walls - Metal Panel 350B 477 SF 7 10+ years Work Sink 350B ΕA 5 6-10 years 1 SF 6 Ceiling - Lay-in 353A 212 10+ years Doors - Side-lite SF 353A 10 6 10+ years Doors - Transom Window SF 6 353A 12 10+ years ΕA Doors - Wood Doors inclu hw 353A 1 6 10+ years Floor - Tile 353A 212 SF 6 10+ years Lighting - Lay-in 353A 7 ΕA 6 6-10 years Walls - Metal Panel 353A 530 SF 6 10+ years Work Sink 353A ΕA 5 6-10 years 1 SF 6 Ceiling - Lay-in 354B 299 10+ years SF 7 Doors - Side-lite 354B 14 10+ years SF 7 Doors - Transom Window 354B 15 10+ years Doors - Wood Doors inclu hw 354B 2 ΕA 6 10+ years Floor - Tile SF 354B 299 6 10+ vears 7 Lighting - Pendent/Surface 354B EΑ 6-10 years 11 Walls - Metal Panel 354B 675 SF 7 10+ years Work Sink ΕA 354B 2 7 10+ years Ceiling - Lay-in 363A 135 SF 7 10+ years Doors - Side-lite SF 363A 14 7 10+ vears Doors - Transom Window SF 363A 15 7 10+ vears 7 Doors - Wood Doors inclu hw 363A FΑ 1 10+ years Floor - Tile 363A 135 SF 7 10+ years Lighting - Lay-in 363A 4 EΑ 6 6-10 years Walls - Concrete Block SF 7 363A 42 10+ years SF Walls - Metal Panel 363A 369 7 10+ years Work Sink 363A 1 EΑ 7 10+ years Ceiling - Lay-in 382 Laundry Inside Culinary 104 SF 7 10+ years Ceiling - Lav-in SF 382 Laundry Inside Culinary 16 4 0-1 vear Water damage Doors - Steel Doors incl hw 382 Laundry Inside Culinary 1 ΕA 7 10+ years Floor - Tile 120 SF 7 382 Laundry Inside Culinary 10+ vears Lighting - Lay-in 382 Laundry Inside Culinary 2 EΑ 7 6-10 years Walls - Plaster/Drywall SF 382 Laundry Inside Culinary 440 7 10+ years



Category : Room			Building : Main-Building A					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Restrool								
	Accessories	109 NW Girls	377	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	109 NW Girls	377	SF	6	10+ years		
	Doors - Wood Doors inclu hw	109 NW Girls	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	109 NW Girls	377	SF	6	10+ years		
	Floor Drain	109 NW Girls	1	EA	7	10+ years		
	Hand Dryer	109 NW Girls	1	EA	7	6-10 years		
	Lavatory	109 NW Girls	3	EA	6	10+ years		
	Lighting - Lay-in	109 NW Girls	11	EA	7	6-10 years		
	Partitions	109 NW Girls	7	EA	5	10+ years		
	Walls - Structural Glazed Tile	109 NW Girls	694	SF	6	10+ years		
	Water Closet	109 NW Girls	7	EA	6	10+ years		
	Accessories	112 NE Boys	377	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	112 NE Boys	377	SF	6	10+ years		
	Doors - Wood Doors inclu hw	112 NE Boys	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	112 NE Boys	377	SF	6	10+ years		
	Floor Drain	112 NE Boys	1	EA	7	10+ years		
	Hand Dryer	112 NE Boys	1	EA	7	6-10 years		
	Lavatory	112 NE Boys	4	EA	6	10+ years		
	Lighting - Lay-in	112 NE Boys	11	EA	7	6-10 years		
	Partitions	112 NE Boys	3	EA	5	10+ years		
	Urinals	112 NE Boys	5	EA	6	10+ years		
	Walls - Structural Glazed Tile	112 NE Boys	694	SF	6	10+ years		
	Water Closet	112 NE Boys	3	EA	6	10+ years		
	Accessories	159D	80	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	159D	80	SF	7	10+ years		
	Doors - Wood Doors inclu hw	159D	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	159D	80	SF	7	10+ years		
	Floor Drain	159D	1	EA	7	10+ years		
	Hand Dryer	159D	1	EA	7	6-10 years	It's in a working condition	
	Lavatory	159D	1	EA	7	10+ years		
	Lighting - Lay-in	159D	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	159D	340	SF	6	10+ years		
	Water Closet	159D	1	EA	7	10+ years		
	Accessories	170E Small Unisex in Nurse's Office	17	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	170E Small Unisex in Nurse's Office	17	SF	6	10+ years		
	Doors - Wood Doors inclu hw	170E Small Unisex in Nurse's Office	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	170E Small Unisex in Nurse's Office	15	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	170E Small Unisex in Nurse's Office	2	SF	4	0-1 year	Missing tiles	
	Lavatory	170E Small Unisex in Nurse's Office	1	EA	6	10+ years		
	Lighting - Wall Mounted	170E Small Unisex in Nurse's Office	1	EA	5	6-10 years		
	Walls - Metal Panel	170E Small Unisex in Nurse's Office	147	SF	6	10+ years		
	Water Closet	170E Small Unisex in Nurse's Office	1	EA	7	10+ years		



Category : Room **Building : Main-Building A** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Accessories 170F Unisex in Nurse's Office 43 SF 6-10 years 7 43 SF Ceiling - Plaster/Drvwall 170F Unisex in Nurse's Office 6 10+ vears Doors - Steel Doors incl hw 170F Unisex in Nurse's Office 1 FΑ 6 10+ years SF 6 Floor - Tile Ceramic/ Porcelain 170F Unisex in Nurse's Office 43 10+ years 6 Lavatory 170F Unisex in Nurse's Office 1 EΑ 10+ years 5 Lighting - Wall Mounted 170F Unisex in Nurse's Office 1 EΑ 6-10 years Walls - Plaster/Drywall 170F Unisex in Nurse's Office 250 SF 6 10+ years 10+ years Water Closet 170F Unisex in Nurse's Office 1 EΑ 6 Accessories 172A Unisex in Main Office 23 SF 7 6-10 years SF Ceiling - Plaster/Drvwall 23 6 10+ vears 172A Unisex in Main Office Doors - Wood Doors inclu hw 172A Unisex in Main Office 1 ΕA 7 10+ vears Floor - Tile Ceramic/ Porcelain 172A Unisex in Main Office 23 SF 6 10+ years 1 ΕA 6 10+ years Lavatory 172A Unisex in Main Office 7 Lighting - Wall Mounted 172A Unisex in Main Office 1 EΑ 6-10 years Walls - Concrete Block SF 7 172A Unisex in Main Office 20 10+ years Walls - Metal Panel SF 7 172A Unisex in Main Office 150 10+ years ΕA Water Closet 172A Unisex in Main Office 1 6 10+ vears 182A Unisex in Principal's Office SF 7 Accessories 24 6-10 years Ceiling - Plaster/Drvwall SF 182A Unisex in Principal's Office 24 6 10+ vears Doors - Wood Doors inclu hw 182A Unisex in Principal's Office 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain 182A Unisex in Principal's Office 23 SF 6 10+ years Floor - Tile Ceramic/ Porcelain SF 182A Unisex in Principal's Office 1 4 0-1 year Missing tiles 6 Lavatorv 182A Unisex in Principal's Office 1 EA 10+ years 7 Lighting - Wall Mounted 182A Unisex in Principal's Office 1 FΑ 6-10 years Walls - Concrete Block 182A Unisex in Principal's Office 48 SF 7 10+ years SF Walls - Metal Panel 182A Unisex in Principal's Office 128 7 10+ vears Water Closet 182A Unisex in Principal's Office EA 6 10+ years 1 1st Floor SE Girls 377 SF 7 6-10 years Accessories Ceiling - Plaster/Drywall SF 1st Floor SE Girls 377 6 10+ years Doors - Wood Doors inclu hw 1st Floor SE Girls 2 ΕA 6 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor SE Girls 377 6 10+ vears Floor Drain 1st Floor SE Girls 1 ΕA 7 10+ vears Hand Dryer 1st Floor SE Girls FΑ 5 6-10 years 1 4 FΑ 5 10+ vears Lavatorv 1st Floor SE Girls 9 6 Lighting - Lay-in 1st Floor SE Girls ΕA 6-10 years 6 ΕA 7 Partitions 1st Floor SE Girls 10+ years SF Walls - Structural Glazed Tile 1st Floor SE Girls 694 7 10+ years Water Closet ΕA 1st Floor SE Girls 6 6 10+ years SF Accessories 1st FIr NW Mens (in 102 Faculty 90 7 6-10 years Lunchroom) Ceiling - Plaster/Drywall 1st FIr NW Mens (in 102 Faculty 90 SF 6 10+ years Lunchroom) Doors - Wood Doors inclu hw 1st Flr NW Mens (in 102 Faculty EA 7 10+ years 1 Lunchroom)



Group

Marie Sklodowska Curie Metropolitan High School 4959 S Archer AVENUE, Chicago, IL 60632

Building : Main-Building A Category : Room Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Tile Ceramic/ Porcelain 1st FIr NW Mens (in 102 Faculty 90 SF 7 10+ vears Lunchroom) Floor Drain 1st FIr NW Mens (in 102 Faculty 1 ΕA 7 10+ years Lunchroom) Hand Dryer 1st Flr NW Mens (in 102 Faculty 1 ΕA 7 6-10 years Lunchroom) 1st Flr NW Mens (in 102 Faculty ΕA 1 6 10+ years Lavatory Lunchroom) Lighting - Pendent/Surface 1st FIr NW Mens (in 102 Faculty 2 ΕA 7 6-10 years Lunchroom) Lighting - Wall Mounted 1st Flr NW Mens (in 102 Faculty 1 ΕA 7 6-10 vears Lunchroom) Partitions 1st Flr NW Mens (in 102 Faculty 1 ΕA 7 10+ years Lunchroom) Urinals 1st Flr NW Mens (in 102 Faculty 1 ΕA 7 10+ years Lunchroom) Walls - Structural Glazed Tile 1st FIr NW Mens (in 102 Faculty 512 SF 7 10+ years Lunchroom) Water Closet 1st FIr NW Mens (in 102 Faculty ΕA 7 1 10+ years Lunchroom) Accessories 1st Flr NW Womens (in 102 Faculty 93 SF 7 6-10 years Lunchroom) Ceiling - Plaster/Drywall 1st FIr NW Womens (in 102 Faculty 93 SF 6 10+ years Lunchroom) Doors - Wood Doors inclu hw 1st Flr NW Womens (in 102 Faculty ΕA 1 7 10+ years Lunchroom) Floor - Tile Ceramic/ Porcelain 1st Flr NW Womens (in 102 Faculty 93 SF 7 10+ years Lunchroom) Floor Drain 1st Flr NW Womens (in 102 Faculty 1 ΕA 7 10+ years Lunchroom) Hand Dryer 1st Flr NW Womens (in 102 Faculty FΑ 7 1 6-10 years Lunchroom) 1st Flr NW Womens (in 102 Faculty 2 FΑ Lavatory 6 10+ years Lunchroom) Lighting - Pendent/Surface 1st FIr NW Womens (in 102 Faculty 1 ΕA 7 6-10 years Lunchroom) Lighting - Wall Mounted 1st Flr NW Womens (in 102 Faculty 1 ΕA 6 6-10 years Lunchroom) Partitions 1st Flr NW Womens (in 102 Faculty 2 ΕA 7 10+ years Lunchroom) Walls - Structural Glazed Tile 1st FIr NW Womens (in 102 Faculty 508 SF 7 10+ years Lunchroom) Water Closet 1st Flr NW Womens (in 102 Faculty 2 ΕA 7 10+ years

Lunchroom)



Catego	ry : Room		Building : Main-Building A						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	1st FIr SW Boys	377	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st FIr SW Boys	377	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st FIr SW Boys	2	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st FIr SW Boys	377	SF	7	10+ years			
	Floor Drain	1st FIr SW Boys	1	EA	7	10+ years			
	Hand Dryer	1st FIr SW Boys	1	EA	7	10+ years			
	Lavatory	1st FIr SW Boys	4	EA	7	10+ years			
	Lighting - Lay-in	1st FIr SW Boys	9	EA	6	6-10 years			
	Partitions	1st FIr SW Boys	4	EA	7	10+ years			
	Urinals	1st Flr SW Boys	5	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st FIr SW Boys	694	SF	7	10+ years			
	Water Closet	1st FIr SW Boys	4	EA	7	10+ years			
	Accessories	202 Unisex	82	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	202 Unisex	82	SF	6	10+ years			
	Doors - Wood Doors inclu hw	202 Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	202 Unisex	82	SF	7	10+ years			
	Floor Drain	202 Unisex	1	EA	7	10+ years			
	Hand Dryer	202 Unisex	1	EA	7	6-10 years			
	Lavatory	202 Unisex	1	EA	7	10+ years			
	Lighting - Lay-in	202 Unisex	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	202 Unisex	228	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	202 Unisex	114	SF	7	10+ years			
	Water Closet	202 Unisex	1	EA	7	10+ years			
	Accessories	205 - 2nd Flr SE Girls	377	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	205 - 2nd Flr SE Girls	377	SF	6	10+ years			
	Doors - Wood Doors inclu hw	205 - 2nd Flr SE Girls	2	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	205 - 2nd Flr SE Girls	377	SF	6	10+ years			
	Floor Drain	205 - 2nd Flr SE Girls	1	EA	7	10+ years			
	Hand Dryer	205 - 2nd Flr SE Girls	1	EA	7	6-10 years			
	Lavatory	205 - 2nd Flr SE Girls	4	EA	6	10+ years			
	Lighting - Lay-in	205 - 2nd Flr SE Girls	11	EA	7	6-10 years			
	Partitions	205 - 2nd Flr SE Girls	8	EA	5	10+ years			
	Walls - Structural Glazed Tile	205 - 2nd Flr SE Girls	694	SF	7	10+ years			
	Water Closet	205 - 2nd Flr SE Girls	8	EA	6	10+ years			
	Accessories	206	83	SF	7	10+ years			
	Ceiling - Plaster/Drywall	206	83	SF	6	10+ years			
	Doors - Transom Window	206	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	206	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	206	83	SF	6	10+ years			
	Lavatory	206	1	EA	6	10+ years			
	Lighting - Lay-in	206	1	EA	6	6-10 years			
	Partitions	206	2	EA	7	10+ years			
	Walls - Structural Glazed Tile	206	267	SF	6	10+ years			
	Water Closet	206	2	EA	6	10+ years			
						2			



Catego	ry : Room		В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	2nd FIr NE Boys	377	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd FIr NE Boys	377	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr NE Boys	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr NE Boys	377	SF	6	10+ years	
	Floor Drain	2nd Flr NE Boys	1	EA	7	10+ years	
	Hand Dryer	2nd FIr NE Boys	1	EA	7	6-10 years	
	Lavatory	2nd Flr NE Boys	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Flr NE Boys	11	EA	7	6-10 years	
	Partitions	2nd Flr NE Boys	3	EA	5	10+ years	
	Urinals	2nd Flr NE Boys	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Flr NE Boys	694	SF	6	10+ years	
	Water Closet	2nd Fir NE Boys	3	EA	6	10+ years	
	Accessories	2nd Flr NW Girls	377	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr NW Girls	377	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr NW Girls	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr NW Girls	377	SF	6	10+ years	
	Floor Drain	2nd Flr NW Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Fir NW Girls	1	EA	7	6-10 years	
	-		4	EA		•	
	Lavatory	2nd Flr NW Girls		EA	6	10+ years	
	Lighting - Lay-in	2nd Flr NW Girls	11		7	6-10 years	
	Partitions	2nd Flr NW Girls	7	EA	5	10+ years	
	Walls - Structural Glazed Tile	2nd Flr NW Girls	694	SF	7	10+ years	
	Water Closet	2nd Flr NW Girls	7	EA	6	10+ years	
	Accessories	2nd Flr SW Boys	377	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr SW Boys	377	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr SW Boys	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr SW Boys	377	SF	6	10+ years	
	Floor Drain	2nd Flr SW Boys	1	EA	7	10+ years	
	Hand Dryer	2nd Flr SW Boys	1	EA	7	6-10 years	
	Lavatory	2nd FIr SW Boys	4	EA	6	10+ years	
	Lighting - Lay-in	2nd FIr SW Boys	11	EA	7	6-10 years	
	Partitions	2nd FIr SW Boys	4	EA	5	10+ years	
	Urinals	2nd FIr SW Boys	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd FIr SW Boys	694	SF	7	10+ years	
	Water Closet	2nd FIr SW Boys	4	EA	6	10+ years	
	Accessories	301 SW Boys	377	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	301 SW Boys	377	SF	6	10+ years	
	Doors - Transom Window	301 SW Boys	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	301 SW Boys	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	301 SW Boys	377	SF	7	10+ years	
	Floor Drain	301 SW Boys	1	EA	7	10+ years	
	Hand Dryer	301 SW Boys	1	EA	7	6-10 years	
	Lavatory	301 SW Boys	4	EA	6	10+ years	
	Lighting - Lay-in	301 SW Boys	11	EA	7	6-10 years	
	5 5 <u> </u>				-		



Building : Main-Building A Category : Room Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Partitions 301 SW Bovs 4 ΕA 5 6-10 years 301 SW Boys 5 ΕA 7 Urinals 10+ vears Walls - Structural Glazed Tile 301 SW Boys 694 SF 7 10+ years Water Closet ΕA 301 SW Boys 4 6 10+ years SF 7 Accessories 302 Male staff 82 6-10 years SF 7 Ceiling - Plaster/Drywall 302 Male staff 82 10+ years Doors - Wood Doors inclu hw ΕA 7 302 Male staff 1 10+ years SF Floor - Tile Ceramic/ Porcelain 302 Male staff 82 7 10+ years Lavatorv 302 Male staff 1 EΑ 6 10+ years Lighting - Lay-in 302 Male staff 1 FΑ 7 6-10 years Partitions 302 Male staff 1 ΕA 7 10+ vears Urinals 302 Male staff 1 EΑ 7 10+ years Walls - Plaster/Drywall 302 Male staff 283 SF 7 10+ years 7 Water Closet 302 Male staff 1 EA 10+ years SF 7 Accessories 305 SE Girls 377 6-10 years Ceiling - Plaster/Drywall SF 305 SE Girls 377 6 10+ years Doors - Transom Window SF 305 SE Girls 9 6 10+ years Doors - Wood Doors inclu hw 305 SE Girls 2 EΑ 6 10+ years SF Floor - Tile Ceramic/ Porcelain 305 SE Girls 377 7 10+ vears Floor Drain 305 SE Girls 1 EΑ 7 10+ years Hand Drver 305 SE Girls 1 ΕA 7 6-10 years Lavatory 305 SE Girls 4 EΑ 6 10+ years 7 Lighting - Lay-in 305 SE Girls 11 EΑ 6-10 years 7 Partitions 305 SE Girls 8 FΑ 10+ years Walls - Structural Glazed Tile SF 7 305 SE Girls 694 10+ years Water Closet 305 SE Girls 8 ΕA 7 10+ vears SF Accessories 306 Women's Staff Toilet 83 7 6-10 years Ceiling - Plaster/Drywall 306 Women's Staff Toilet 83 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 306 Women's Staff Toilet 1 7 10+ years Floor - Tile Ceramic/ Porcelain 306 Women's Staff Toilet 83 SF 7 10+ years Hand Drver 1 FΑ 7 6-10 years 306 Women's Staff Toilet Lavatorv 306 Women's Staff Toilet 1 EΑ 6 10+ vears 7 Lighting - Lay-in 306 Women's Staff Toilet 1 FΑ 6-10 years Partitions 2 FΑ 7 10+ years 306 Women's Staff Toilet Walls - Structural Glazed Tile SF 7 306 Women's Staff Toilet 283 10+ years ΕA 7 Water Closet 306 Women's Staff Toilet 2 10+ years SF Accessories 309 NW Girls 377 7 6-10 years Ceiling - Plaster/Drywall 309 NW Girls SF 7 377 10+ years Doors - Wood Doors inclu hw 309 NW Girls 2 EΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain 309 NW Girls 377 6 10+ vears Floor Drain 309 NW Girls 1 ΕA 7 10+ years FΑ 7 Hand Drver 309 NW Girls 1 6-10 years Lavatory 309 NW Girls 4 EA 6 10+ years Lighting - Lay-in 309 NW Girls 11 EΑ 6 6-10 years



Building : Main-Building A Category : Room Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Partitions 309 NW Girls ΕA 10+ vears 7 7 309 NW Girls 694 SF 7 Walls - Structural Glazed Tile 10+ years Water Closet 309 NW Girls 7 EΑ 7 10+ years 377 SF 7 Accessories 3rd NE Boys 6-10 years SF Ceiling - Plaster/Drywall 3rd NE Boys 377 6 10+ years ΕA 6 Doors - Wood Doors inclu hw 3rd NE Boys 2 10+ years Floor - Tile Ceramic/ Porcelain 3rd NE Boys 377 SF 7 10+ years Floor Drain 3rd NE Boys 1 ΕA 7 10+ years Hand Dryer 3rd NE Boys 1 ΕA 7 6-10 years 3rd NE Boys 4 FΑ 6 10+ vears Lavatory Lighting - Lay-in 3rd NE Bovs 11 ΕA 6 6-10 vears Partitions 3rd NE Boys 3 ΕA 7 6-10 years Changed to match current observations 7 Urinals 3rd NE Boys 5 EΑ 10+ years Walls - Structural Glazed Tile SF 7 10+ years 3rd NE Boys 694 Water Closet 3 ΕA 7 3rd NE Boys 10+ years SF Accessories B15A Engineer's Toilet/Locker 105 7 6-10 years Room SF Ceiling - Plaster/Drywall B15A Engineer's Toilet/Locker 105 6 10+ years Room Doors - Wood Doors inclu hw B15A Engineer's Toilet/Locker 1 ΕA 6 10+ years Room SF Floor - Tile Ceramic/ Porcelain B15A Engineer's Toilet/Locker 105 6 10+ years Room Floor Drain B15A Engineer's Toilet/Locker 2 ΕA 7 10+ years Room B15A Engineer's Toilet/Locker EΑ 6 Lavatory 1 10+ years Room 6-10 years Lighting - Lay-in B15A Engineer's Toilet/Locker 2 ΕA 6 Room FΑ Lighting - Pendent/Surface B15A Engineer's Toilet/Locker 2 6 Quantity changed to match current 6-10 years observations Room FΑ 6 Lighting - Wall Mounted B15A Engineer's Toilet/Locker 1 10+ years Room Partitions B15A Engineer's Toilet/Locker 1 ΕA 7 10+ years Room Showers B15A Engineer's Toilet/Locker 1 EΑ 7 10+ years Room Urinals B15A Engineer's Toilet/Locker 1 EΑ 6 10+ years Room Walls - Structural Glazed Tile B15A Engineer's Toilet/Locker 459 SF 6 10+ years Room Water Closet B15A Engineer's Toilet/Locker 1 ΕA 6 10+ years Room



Building : Main-Building A Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Accessories B16A Engineer's Toilet/Shower 68 SF 5 6-10 years Room Ceiling - Plaster/Drywall B16A Engineer's Toilet/Shower 68 SF 6 10+ years Room Doors - Wood Doors inclu hw B16A Engineer's Toilet/Shower 1 EΑ 6 10+ years Room B16A Engineer's Toilet/Shower SF Floor - Tile Ceramic/ Porcelain 68 6 10+ years Room Floor Drain B16A Engineer's Toilet/Shower 2 ΕA 7 10+ years Room B16A Engineer's Toilet/Shower 1 ΕA 6 Lavatorv 10+ years Room ΕA 6 Lighting - Lay-in B16A Engineer's Toilet/Shower 1 6-10 years Room Lighting - Wall Mounted B16A Engineer's Toilet/Shower 1 EΑ 6 6-10 years Room Partitions B16A Engineer's Toilet/Shower 1 ΕA 7 10+ years Room Showers B16A Engineer's Toilet/Shower EΑ 7 1 10+ years Room Walls - Structural Glazed Tile B16A Engineer's Toilet/Shower 276 SF 7 10+ years Room Water Closet B16A Engineer's Toilet/Shower 1 EΑ 7 10+ years Room SF 5 Accessories B17 Mens Toilet/Locker Room 535 6-10 years Ceiling - Plaster/Drywall SF B17 Mens Toilet/Locker Room 535 6 10+ vears Doors - Wood Doors inclu hw 6 B17 Mens Toilet/Locker Room 2 EΑ 10+ years Floor - Tile 335 SF 5 B17 Mens Toilet/Locker Room 10+ years SF Floor - Tile Ceramic/ Porcelain B17 Mens Toilet/Locker Room 200 6 10+ years Floor Drain B17 Mens Toilet/Locker Room 3 ΕA 7 10+ years Hand Dryer 1 ΕA 7 6-10 years B17 Mens Toilet/Locker Room Lavatorv 2 ΕA 5 6-10 vears B17 Mens Toilet/Locker Room Lighting - Lay-in 6 FΑ 6 6-10 years B17 Mens Toilet/Locker Room Lighting - Wall Mounted 1 FΑ 6 6-10 years B17 Mens Toilet/Locker Room 2 7 Partitions B17 Mens Toilet/Locker Room EΑ 10+ years ΕA 7 Showers B17 Mens Toilet/Locker Room 1 10+ years Student Lockers - One Tier B17 Mens Toilet/Locker Room 39 ΕA 6 10+ years 7 Urinals B17 Mens Toilet/Locker Room 2 EΑ 10+ years SF Walls - Structural Glazed Tile B17 Mens Toilet/Locker Room 1.524 6 10+ years ΕA Water Closet B17 Mens Toilet/Locker Room 2 6 10+ vears Accessories B18 Womens Toilet/Locker Room 145 SF 5 6-10 years SF 6 Ceiling - Plaster/Drywall B18 Womens Toilet/Locker Room 145 10+ vears Doors - Wood Doors inclu hw B18 Womens Toilet/Locker Room 2 EΑ 6 10+ years Floor - Tile B18 Womens Toilet/Locker Room 119 SF 6 10+ years



Catego	ry : Room		В	uildina	: Main-F	Building A	4959 S Archer AVENUE, Chicago, IL 60632
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	B18 Womens Toilet/Locker Room	26	SF	6	10+ years	
	Lavatory	B18 Womens Toilet/Locker Room	1	EA	6	6-10 years	
	Lighting - Lay-in	B18 Womens Toilet/Locker Room	3	EA	6	6-10 years	
	Lighting - Wall Mounted	B18 Womens Toilet/Locker Room	1	EA	6	6-10 years	
	Student Lockers - One Tier	B18 Womens Toilet/Locker Room	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	B18 Womens Toilet/Locker Room	628	SF	7	10+ years	
	Water Closet	B18 Womens Toilet/Locker Room	1	EA	7	10+ years	
	Accessories	B6 - Men's staff toilet and locker room	143	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	B6 - Men's staff toilet and locker	143	SF	7	10+ years	
	Centrig - Flaster/Drywan	room	140	01	'	TOF years	
	Doors - Wood Doors inclu hw	B6 - Men's staff toilet and locker	1	EA	6	10+ years	
		room		_ / (Ũ	io i youro	
	Floor - Tile Ceramic/ Porcelain	B6 - Men's staff toilet and locker	137	SF	6	10+ years	
		room					
	Floor - Tile Ceramic/ Porcelain	B6 - Men's staff toilet and locker	6	SF	4	0-1 year	Missing
	Floor Drain	room B6 - Men's staff toilet and locker	1	EA	7	10, 10000	
		room	1	EA	'	10+ years	
	Hand Dryer	B6 - Men's staff toilet and locker	1	EA	7	6-10 years	
		room					
	Lavatory	B6 - Men's staff toilet and locker	2	EA	6	10+ years	
		room					
	Lighting - Lay-in	B6 - Men's staff toilet and locker	3	EA	7	6-10 years	
		room			-		
	Lighting - Wall Mounted	B6 - Men's staff toilet and locker	1	EA	6	6-10 years	
	Partitions	room B6 - Men's staff toilet and locker	1	EA	5	10	
	Farmons	room	1	EA	5	10+ years	
	Student Lockers - One Tier	B6 - Men's staff toilet and locker	9	EA	7	10+ years	
		room	Ũ	_ / (•	io i youro	
	Urinals	B6 - Men's staff toilet and locker	1	EA	7	10+ years	
		room					
	Walls - Structural Glazed Tile	B6 - Men's staff toilet and locker	474	SF	7	10+ years	
		room			-		
	Water Closet	B6 - Men's staff toilet and locker	1	EA	6	10+ years	
	Accessories	room B7 Women's Staff Toilet/Locker	271	SF	7	6 10 10000	
	Accessories	Room	271	эг	'	6-10 years	
	Ceiling - Plaster/Drywall	B7 Women's Staff Toilet/Locker	271	SF	6	10+ years	Changed to match current
		Room		•	Ũ	let yeare	observations
	Doors - Wood Doors inclu hw	B7 Women's Staff Toilet/Locker	1	EA	6	10+ years	Changed to match current
		Room				, -	observations
	Floor - Tile	B7 Women's Staff Toilet/Locker	125	SF	6	10+ years	



Catego	ery : Room		В	uilding	: Main-I	Building A	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Room					
	Floor - Tile Ceramic/ Porcelain	B7 Women's Staff Toilet/Locker Room	146	SF	6	10+ years	
	Floor Drain	B7 Women's Staff Toilet/Locker Room	1	EA	7	10+ years	
	Hand Dryer	B7 Women's Staff Toilet/Locker Room	1	EA	7	6-10 years	
	Lavatory	B7 Women's Staff Toilet/Locker Room	2	EA	6	6-10 years	Changed to match current observations
	Lighting - Lay-in	B7 Women's Staff Toilet/Locker Room	5	EA	6	6-10 years	
	Lighting - Wall Mounted	B7 Women's Staff Toilet/Locker Room	1	EA	6	6-10 years	
	Partitions	B7 Women's Staff Toilet/Locker Room	2	EA	7	10+ years	
	Student Lockers - One Tier	B7 Women's Staff Toilet/Locker Room	32	EA	7	10+ years	
	Walls - Structural Glazed Tile	B7 Women's Staff Toilet/Locker Room	699	SF	7	10+ years	
	Water Closet	B7 Women's Staff Toilet/Locker Room	2	EA	6	10+ years	

Category : Classroom

Catego	Category : Classroom			Building : Main-Building A				
_						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Classroo	om #143 Web Design (Computer Lab)							
	Ceiling - Lay-in	1st Floor	2,052	SF	6	10+ years		
	Doors - Side-lite	1st Floor	36	SF	7	10+ years		
	Doors - Transom Window	1st Floor	25	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years		
	Floor - Tile	1st Floor	2,052	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	70	EA	6	6-10 years		
	Marker Board	1st Floor	20	LF	6	6-10 years		
	Storage/ Closet	1st Floor	181	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	180	SF	7	10+ years		
	Walls - Metal Panel	1st Floor	1,562	SF	7	10+ years		
	Wireless System	1st Floor	1	EA	7	6-10 years		
Classroo	om #144 Elect Lab (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	1,225	SF	6	10+ years		
	Doors - Side-lite	1st Floor	36	SF	7	10+ years		
	Doors - Transom Window	1st Floor	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years		
	Floor - Tile	1st Floor	1,225	SF	6	10+ years		



Catego	ry : Classroom		Building : Main-Building A						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	1st Floor	40	EA	6	6-10 years			
	Marker Board	1st Floor	10	LF	6	6-10 years			
	Storage/ Closet	1st Floor	181	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	120	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	856	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	348	SF	6	10+ years			
Classroo	m #145 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	1,002	SF	6	10+ years			
	Doors - Transom Window	1st Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Carpet	1st Floor	1,002	SF	5	6-10 years			
	Lighting - Pendent/Surface	1st Floor	38	EA	6	6-10 years			
	Marker Board	1st Floor	16	LF	6	6-10 years			
	Storage/ Closet	1st Floor	90	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	60	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	904	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	298	SF	7	10+ years			
	Wireless System	1st Floor	290	EA	7	6-10 years			
	Whereas Cystem			L/(,	o roycars			
Classroo	m #146 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	632	SF	6	10+ years			
	Doors - Side-lite	1st Floor	17	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	632	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	23	EA	6	6-10 years			
	Marker Board	1st Floor	18	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	50	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	990	SF	6	10+ years			
Classroo	m #147 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	793	SF	6	10+ years			
	Chalk Board	1st Floor	5	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	793	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	28	EA	6	6-10 years			
	Marker Board	1st Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	454	SF	6	10+ years			
	Walls - Metal Panel	1st Floor	493	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	250	SF	6	10+ years			
Claseroo	m #148 DigitalDsgn (Computer Lab)								
21033100	Ceiling - Lay-in	1st Floor	2,234	SF	7	10+ years			



Catego	ry : Classroom		В	Building : Main-Building A					
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Side-lite	1st Floor	20	SF	7	10+ years			
	Doors - Transom Window	1st Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years			
	Floor - Tile	1st Floor	2,234	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	87	EA	6	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Storage/ Closet	1st Floor	538	SF	7	10+ vears			
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	1,253	SF	7	10+ years			
	Wireless System	1st Floor	· 1	EA	7	6-10 years			
Classroc	om #150 Photography (Laboratory/Shop)								
	Ceiling - Lay-in	1st Floor	734	SF	6	10+ years			
	Doors - Side-lite	1st Floor	36	SF	7	10+ years			
	Doors - Transom Window	1st Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years			
	Floor - Tile	1st Floor	734	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	30	EA	6	6-10 years			
	Marker Board	1st Floor	5	LF	6	6-10 years			
	Storage/ Closet	1st Floor	231	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	290	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	900	SF	7	10+ years			
	Work Sink	1st Floor	2	EA	5	6-10 years			
Classroc	om #152 Comp/Elec (Computer Lab)								
	Ceiling - Lay-in	1st Floor	1,451	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	7	10+ years			
	Floor - Tile	1st Floor	1,451	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	22	EA	7	6-10 years			
	Marker Board	1st Floor	 16	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	120	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	1,092	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	598	SF	6	10+ years			
	Wireless System	1st Floor	1	EA	7	6-10 years			
Classroo	om #159 (Pre School)								
	Casework	1st Floor	9	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,627	SF	7	10+ years			
	Doors - Side-lite	1st Floor	12	SF	7	10+ years			
	Doors - Transom Window	1st Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	.0	EA	6	10+ years			
	Floor - Tile	1st Floor	1,627	SF	7	10+ years			



Catego	ry : Classroom		В	uilding	: Main-I	Building A	
U	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	693	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #160 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	1,434	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,434	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	6	6-10 years	
	Marker Board	1st Floor	13	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	200	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,292	SF	6	10+ years	
Classroo	om #161 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	1,453	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,452	SF	6	10+ years	
	Floor - Tile	1st Floor	1	SF	4	0-1 year	Missing tile
	Lighting - Lay-in	1st Floor	59	EA	6	6-10 years	
	Marker Board	1st Floor	5	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	250	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	859	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	478	SF	6	10+ years	
Classroo	om #162 (Computer Lab)						
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,234	SF	6	10+ years	
	Doors - Side-lite	1st Floor	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,234	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	48	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	870	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	474	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	

Ceiling - Exposed	1st Floor	2,914	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Concrete	1st Floor	2,914	SF	5	0-1 year	Cracking and deterioration.



Catego	ry : Classroom		В	Building : Main-Building A					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	1st Floor	88	EA	6	6-10 years			
	Storage/ Closet	1st Floor	423	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	2,100	SF	6	10+ years			
	Work Sink	1st Floor	3	EA	7	10+ years			
Classroo	om #164 Metal (Faculty Lounge)								
	Ceiling - Exposed	1st Floor	2,817	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years			
	Floor - Concrete	1st Floor	2,817	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	75	EA	6	6-10 years			
	Storage/ Closet	1st Floor	286	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	2,384	SF	7	10+ years			
	Work Sink	1st Floor	2,004	EA	7	10+ years			
Classroo	om #165 TV Studio (Computer Lab)								
	Ceiling - Lay-in	1st Floor	422	SF	6	10+ years			
	Ceiling - Splined	1st Floor	1,219	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years			
	Floor - Tile	1st Floor	1.641	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor		EA	6	•			
	Marker Board	1st Floor	15 8		7	6-10 years 6-10 years			
	Storage/ Closet	1st Floor	o 54	SF	7	10+ years			
		1st Floor		SF					
	Walls - Concrete Block		1,614		7 7	10+ years			
	Walls - Plaster/Drywall	1st Floor	346	SF	/	10+ years			
Classroo	om #166 Automotive (Autoshop)								
	Casework	1st Floor	19	LF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	3,960	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	1st Floor	3,960	SF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	1st Floor	35	EA	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years			
	Storage/ Closet	1st Floor	977	SF	5	10+ years			
	Student Lockers - One Tier	1st Floor	3	EA	6	10+ years			
	Student Lockers - Two Tiers	1st Floor	98	EA	6	10+ years			
	Walls - Concrete Block	1st Floor	3,602	SF	6	10+ years			
	Work Sink	1st Floor	2	EA	5	6-10 years			
lassroc	om #167 (Health)								
	Ceiling - Lay-in	1st Floor	954	SF	6	10+ years			



atego	ry : Classroom		В	Building : Main-Building A					
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	954	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	35	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor	510	SF	6	10+ years			
	Walls - Metal Panel	1st Floor	560	SF	6	10+ years			
lassroo	om #168 (Health)								
	Ceiling - Lay-in	1st Floor	974	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	6	10+ years			
	Floor - Tile	1st Floor	974	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	20	EA	6	6-10 years			
	Marker Board	1st Floor	12	LA	7	6-10 years			
	Walls - Concrete Block	1st Floor	190	SF	7	10+ years			
	Walls - Concrete Block Walls - Metal Panel	1st Floor	727	SF	6	10+ years			
				SF		•			
	Walls - Plaster/Drywall	1st Floor	200	55	6	10+ years			
assroo	m #232 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	750	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	750	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years			
	Marker Board	2nd Floor	12	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	172	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	720	SF	6	10+ years			
lassroo	m #233 (Music Room)								
	Ceiling - Lay-in	2nd Floor	1,140	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	1,140	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	1,140	EA	6	6-10 years			
	Marker Board	2nd Floor	16		6	6-10 years			
	Walls - Concrete Block	2nd Floor	188	SF					
					6	10+ years			
	Walls - Metal Panel	2nd Floor	1,120	SF	6	10+ years			
assroo	m #235E (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	951	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	20	SF	6	10+ years			
		2nd Floor		SF					



Catego	ry : Classroom		В	Building : Main-Building A					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Tile	2nd Floor	951	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	17	EA	6	6-10 years			
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	81	SF	5	10+ years			
	Walls - Metal Panel	2nd Floor	1,060	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
lassroc	om #241 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	1,384	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Carpet	2nd Floor	1,384	SF	4	0-1 year	Worn throughout.		
	Lighting - Lay-in	2nd Floor	26	EA	6	6-10 years	Worn throughout.		
	Walls - Concrete Block	2nd Floor	250	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	1,250	SF	6	10+ years	Changed to match current		
	Walls - Melai Fallei		1,230	SF	0	10+ years	observations		
lassroo	om #243 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Doors - Transom Window	2nd Floor	. 9	SF	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	334	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	495	SF	6	10+ years			
			495	36	0	10+ years			
lassroc	om #244 (Regular Classroom)			~-					
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	799	SF	6	10+ years			
lassroc	om #245 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	e e e e e e e e e e e e e e e e e e e		



Catego	ry : Classroom	B	Building : Main-Building A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Tile	2nd Floor	738	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	15	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years		
	Walls - Metal Panel	2nd Floor	695	SF	6	10+ years		
Classroc	m #248 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage.	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	Water damage.	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Tile	2nd Floor	738	SF	6	10+ years		
		2nd Floor		EA				
	Lighting - Lay-in		15		6	6-10 years		
	Marker Board	2nd Floor	13	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years		
	Walls - Metal Panel	2nd Floor	570	SF	6	10+ years		
Classroc	m #249 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Tile	2nd Floor	738	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	15	ĒA	6	6-10 years		
	Marker Board	2nd Floor	15	LF	6	6-10 years		
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years		
	Walls - Metal Panel	2nd Floor	579	SF	6	10+ years		
Classroo	m #250 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	400	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Tile	2nd Floor	400	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	400	EA	6	6-10 years		
	Marker Board	2nd Floor 2nd Floor	° 20		6	6-10 years		
	Walls - Metal Panel	2nd Floor 2nd Floor	20 510	SF	6 6	10+ years		
Closerer	m #252 (Regular Classroom)							
JISSIOC	Ceiling - Lay-in	2nd Floor	400	SF	6	10+ years		



Catego	ry : Classroom		В	Building : Main-Building A					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	400	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	8	EA	6	6-10 years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Walls - Metal Panel	2nd Floor	559	SF	6	10+ years			
Classroo	m #253 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	13	LA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years			
	Walls - Concrete Block Walls - Metal Panel	2nd Floor	559	SF	6				
		210 1001	009	эг	0	10+ years			
Classroc	m #254 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	799	SF	6	10+ years			
Classroc	m #255 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	600	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	600	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years			
	Marker Board	2nd Floor	17	LF	7	6-10 years			
	Walls - Metal Panel	2nd Floor	610	SF	6	10+ years			
			010	01	0	for years			
Classroc	m #257 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			



Catego	ry : Classroom		В	Building : Main-Building A					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	600	SF	6	10+ years			
lassroo	om #258 (Regular Classroom)								
21000100	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	Water damage		
	Floor - Tile	2nd Floor	738	SF	6	-			
					-	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	12	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	600	SF	6	10+ years			
lassroc	om #259 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	600	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	171	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	600	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	6	6-10 years			
	Lighting - Lay-in	2nd Floor	3	EA	5	0-1 year	Does not work.		
	Marker Board	2nd Floor	12	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	130	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	465	SF	6	10+ years			
Classroo	om #260 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor 2nd Floor	12	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years			
Jacoroo	om #261 (Computer Lab)								
1000		2nd Floor	1,170	SF	6	101, 100,000			
	Ceiling - Lay-in				6	10+ years			
	Doors - Side-lite Doors - Steel Doors incl hw	2nd Floor	60	SF EA	7	10+ years			
		2nd Floor	1	FA	6	10+ years			



Category : Classroom			В	Building : Main-Building A					
				Recommend					
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	1,170	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years			
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	456	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	390	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
lassroo	m #262 (Regular Classroom)								
1000100	Ceiling - Lay-in	2nd Floor	722	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor	10	SF	6	10+ years	Water damage		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6				
	Floor - Tile	2nd Floor	738	SF	6	10+ years 10+ years			
	Lighting - Lay-in	2nd Floor 2nd Floor	738 14	EA	6	6-10 years			
					-				
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years			
lassroo	m #263 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years			
	Marker Board	2nd Floor	12	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years			
Classroo	m #264 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	738	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years			
		21011001	100	SF	6	10+ years			



Catego	ry : Classroom		В	uilding	: Main-E	Building A	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years	
Classroc	om #266 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years	
Classroc	om #267 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	840	SF	6	10+ years	
Classroo	om #268 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	



Category : Classroom			В	uilding	: Main-E	Building A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	om #269 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	765	SF	6	10+ years	
Classroo	om #270 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,492	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Carpet	2nd Floor	1,500	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	27	ĒA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	488	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	580	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #271 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	120	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	980	SF	6	10+ years	
Classroo	om #272 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	600	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	251	SF	7	10+ years	
			9	SF	7	10+ years	
		2nd Floor					
	Doors - Transom Window	2nd Floor 2nd Floor					
	Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile	2nd Floor 2nd Floor	2 600	EA SF	7 6	10+ years 10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main-E	Building A Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #274 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	Changed to match current observations
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Replaced with wood panel
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	Changed to match current observations
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	They are in a good shape, some bulbs need to be replaced
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	Changed to match current observations
	Walls - Metal Panel	2nd Floor	495	SF	6	10+ years	
Classroo	m #275 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	738	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	314	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	485	SF	7	10+ years	
lassroo	m #277 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	687	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	22	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	687	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	650	SF	6	10+ years	
lassroo	m #279 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	107	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	738	SF	7	10+ years	



Catego	ry : Classroom		B	uilding	: Main-E	Building A		
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	20	LF	7	6-10 years	Quantity changed to match current observations	
	Walls - Concrete Block	2nd Floor	120	SF	7	10+ years		
	Walls - Metal Panel	2nd Floor	603	SF	7	10+ years		
lassroc	om #280 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	738	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	171	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	738	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	17	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	180	SF	7	10+ years		
	Walls - Metal Panel	2nd Floor	600	SF	7	10+ years		
lassroc	om #282 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	687	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	9 2	EA	7	10+ years		
	Floor - Tile	2nd Floor	687	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	14	LF	7	6-10 years		
	Walls - Metal Panel	2nd Floor	650	SF	7	10+ years		
lassroc	om #284 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	738	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	5	EA	7	10+ years		
	Floor - Tile	2nd Floor	738	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	7	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	, 190	SF	7	10+ years		
	Walls - Concrete Block Walls - Metal Panel	2nd Floor 2nd Floor	663	SF	6	10+ years		
			003	36	0	TO+ years		
lassroc	om #285 (Regular Classroom)			05		10		
	Ceiling - Lay-in	2nd Floor	738	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		



Catego	ry : Classroom		В	uilding	: Main-E	Building A	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	738	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	13	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	150	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	795	SF	6	10+ years	
loooroo	om #286 (Regular Classroom)						
1005100		2nd Floor	687	SF	6	10	
	Ceiling - Lay-in				6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	687	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	Quantity changed to match current observations
	Walls - Metal Panel	2nd Floor	883	SF	6	10+ years	observations
lassroo	om #288 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	738	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	280	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	705	SF	6	10+ years	
			705	5	0	TO+ years	
lassroc	om #289 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	696	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	696	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	180	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	775	SF	6	10+ years	
lassroc	om #290 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	738	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Side-lite		11	36	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main-E	Building A			
-				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Doors - Transom Window	2nd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	738	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	14	ĒA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years	Quantity changed to match current		
					-		observations		
	Walls - Concrete Block	2nd Floor	314	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	485	SF	6	10+ years			
						-			
lassroo	om #332 (Science Classroom)								
	Ceiling - Lay-in	3rd Floor	1,314	SF	6	6-10 years			
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Missing/water damage.		
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,326	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years			
	Walls - Concrete Block	3rd Floor	222	SF	6	10+ years			
	Walls - Metal Panel	3rd Floor	895	SF	6	10+ years			
	Wireless System	3rd Floor	1	EA	7	6-10 years			
	Work Sink	3rd Floor	5	EA	7	10+ years			
						-			
lassroo	om #334/335 (Regular Classroom)								
	Casework	3rd Floor	24	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	2,716	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	33	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	36	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years			
	Floor - Tile	3rd Floor	2,716	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	51	EA	7	6-10 years			
	Storage/ Closet	3rd Floor	432	SF	5	10+ years			
	Walls - Concrete Block	3rd Floor	300	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	935	SF	6	10+ years			
					-				
lassroo	om #335A (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	686	SF	6	10+ years			
	Chalk Board	3rd Floor	8	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	686	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years			
	Marker Board	3rd Floor	5	LF	6	6-10 years			
	Source Bound		Ũ	<u> </u>	0	5 10 ,0010			



Catego	ry : Classroom		В	Building : Main-Building A					
0	Kenne Turne	Legetier	O		Devi	Recommend	Commente		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storage/ Closet	3rd Floor	150	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	150	SF	6	10+ years			
	Walls - Metal Panel	3rd Floor	850	SF	6	10+ years			
	Work Sink	3rd Floor	1	EA	5	6-10 years			
Classroo	m #336 (Computer Lab)								
	Ceiling - Lay-in	3rd Floor	1,020	SF	6	6-10 years			
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years			
	Floor - Tile	3rd Floor	1,020	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years			
	Marker Board	3rd Floor	25	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	270	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	950	SF	6	10+ years			
	Wireless System	3rd Floor	1	EA	7	6-10 years			
	Wileless System	314 1 1001	I	LA	'	0-10 years			
lassroc	m #336A (Computer Lab)								
	Ceiling - Lay-in	3rd Floor	1,473	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	48	SF	4	0-1 year	Water damage and missing.		
	Doors - Side-lite	3rd Floor	49	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	3	EA	7	10+ years			
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years			
	Floor - Tile	3rd Floor	1,521	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	30	EA	7	6-10 years			
	Marker Board	3rd Floor	8	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	250	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	1,175	SF	6	10+ years			
lassroo	m #337 (Computer Lab)								
	Ceiling - Lay-in	3rd Floor	960	SF	6	6-10 years			
	Doors - Side-lite	3rd Floor	20	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	960	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years			
	Marker Board	3rd Floor	15	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	100	SF	6	10+ years			
	Walls - Officiele Block Walls - Metal Panel	3rd Floor	1,106	SF	6	10+ years			
		3rd Floor	1,100	EA	7	,			
	Wireless System	3rd F100r	1	EA	/	6-10 years			
lassroo	m #338 (Computer Lab)								
	Ceiling - Lay-in	3rd Floor	986	SF	6	6-10 years			



Catego	ry : Classroom		В	Building : Main-Building A						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years				
	Floor - Tile	3rd Floor	986	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years				
	Marker Board	3rd Floor	30	LF	6	6-10 years				
	Walls - Metal Panel	3rd Floor	1,210	SF	6	10+ years				
	Wireless System	3rd Floor	1	EA	7	6-10 years				
Classroc	om #339 (Computer Lab)									
	Ceiling - Lay-in	3rd Floor	678	SF	6	6-10 years				
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage.			
	Doors - Side-lite	3rd Floor	22	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years				
	Floor - Tile	3rd Floor	686	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years				
	Marker Board	3rd Floor	10	LF	6	6-10 years				
	Walls - Metal Panel	3rd Floor	1,210	SF	6	10+ years				
	Wireless System	3rd Floor	1,210	EA	7	6-10 years				
lassroc	om #340 (Science Lab Level 2)									
7000100	Casework	3rd Floor	140	LF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	1,250	SF	6	6-10 years				
	Doors - Side-lite	3rd Floor	20	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7					
	Eye Wash Station	3rd Floor	2	EA	7	10+ years				
	Floor - Tile			SF	6	10+ years				
		3rd Floor	1,250			10+ years				
	Gas Line	3rd Floor	21 21	EA EA	7 7	10+ years				
	Lighting - Lay-in Markar Baard	3rd Floor				6-10 years				
	Marker Board	3rd Floor	18	LF	6	6-10 years				
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years				
	Science Lab Shower	3rd Floor	1	EA	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	1,405	SF	6	10+ years				
	Work Sink	3rd Floor	10	EA	7	10+ years				
Classroc	om #341 (Computer Lab)									
	Ceiling - Lay-in	3rd Floor	850	SF	6	10+ years				
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years				
	Floor - Tile	3rd Floor	850	SF	6	10+ years				



Category : Classroom			В	Building : Main-Building A					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Marker Board	3rd Floor	17	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	360	SF	6	10+ years			
	Walls - Metal Panel	3rd Floor	820	SF	7	10+ years			
Classroo	m #343 (Computer Lab)								
	Ceiling - Lay-in	3rd Floor	1,480	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Water damage		
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years			
	Floor - Tile	3rd Floor	1,496	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	27	EA	6	6-10 years			
	Marker Board	3rd Floor	7	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	380	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	1,130	SF	6	10+ years			
0	"242 (2 ·					·			
Classroo	m #346 (Science Lab Level 2)	Ord Elsen	00		0	10			
	Casework	3rd Floor	22	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	1,110	SF	6	10+ years			
	Chalk Board	3rd Floor	10	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,110	SF	6	10+ years			
	Gas Line	3rd Floor	16	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	38	EA	7	6-10 years			
	Marker Board	3rd Floor	5	LF	6	6-10 years			
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	202	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	820	SF	6	10+ years			
	Work Sink	3rd Floor	8	EA	7	10+ years			
Classroo	m #347 (Science Lab Level 2)								
	Casework	3rd Floor	20	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	600	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	600	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	120	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	680	SF	7	10+ years			



Catego	Category : Classroom		Building : Main-Building A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Work Sink	3rd Floor	2	EA	7	10+ years		
Classroo	om #349 (Science Lab Level 1)							
	Casework	3rd Floor	18	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	1,234	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,234	SF	6	10+ years		
	Gas Line	3rd Floor	6	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	34	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	6	6-10 years		
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years		
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	130	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	825	SF	6	10+ years		
	Work Sink	3rd Floor	8	EA	7	10+ years		
_Classroo	om #350 (Science Lab Level 1)							
	Casework	3rd Floor	18	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	888	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	883	SF	6	10+ years		
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Chipping	
	Gas Line	3rd Floor	16	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	31	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years		
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	120	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	815	SF	6	10+ years		
	Work Sink	3rd Floor	8	EA	7	10+ years		
Classro	om #351 (Regular Classroom)							
0	Ceiling - Lay-in	3rd Floor	625	SF	6	10+ years		
	Chalk Board	3rd Floor	5	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	9 2	EA	7	10+ years		
	Floor - Tile	3rd Floor	625	SF	6	10+ years		
			025	01	0	ior years		



Building : Main-Building A Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Lay-in 3rd Floor 12 ΕA 6-10 years 7 Marker Board 3rd Floor LF 6 6-10 years 10 Walls - Concrete Block 3rd Floor 130 SF 7 10+ years 630 SF Walls - Metal Panel 3rd Floor 6 10+ years Classroom #353 (Science Lab Level 1) Casework 3rd Floor 12 LF 6 10+ years SF Ceiling - Lay-in 3rd Floor 950 6 10+ years SF 7 Doors - Side-lite 3rd Floor 20 10+ years SF Doors - Transom Window 3rd Floor 8 7 10+ years Doors - Wood Doors inclu hw 2 ΕA 7 3rd Floor 10+ years Eve Wash Station 3rd Floor 1 EΑ 7 10+ years Floor - Tile 3rd Floor 950 SF 6 10+ years Gas Line 3rd Floor 10 ΕA 7 10+ years 3rd Floor 35 ΕA 7 Lighting - Lay-in 6-10 years Marker Board 3rd Floor 10 LF 6 6-10 years ΕA Science Lab Fume Hood 3rd Floor 1 6 6-10 years 7 Science Lab Shower 3rd Floor 1 EΑ 6-10 years 250 SF 7 Walls - Concrete Block 3rd Floor 10+ years Walls - Metal Panel 3rd Floor 876 SF 6 10+ years Work Sink 3rd Floor 8 ΕA 7 10+ years Classroom #354 (Science Lab Level 1) Casework 3rd Floor LF 10+ years 21 6 Ceiling - Lay-in 3rd Floor 888 SF 6 10+ years SF Doors - Side-lite 3rd Floor 7 10 10+ years SF Doors - Transom Window 3rd Floor 9 7 10+ years ΕA 7 Doors - Wood Doors inclu hw 3rd Floor 1 10+ years Eve Wash Station 3rd Floor 1 FΑ 7 10+ years Floor - Tile SF 3rd Floor 888 6 10+ years Gas Line ΕA 7 3rd Floor 16 10+ years 37 7 Lighting - Lay-in 3rd Floor EΑ 6-10 years Marker Board 15 LF 6-10 years 3rd Floor 6 Science Lab Fume Hood 3rd Floor 1 EΑ 7 10+ years Science Lab Shower 3rd Floor 1 ΕA 7 6-10 years SF Storage/ Closet 3rd Floor 299 7 10+ years Walls - Concrete Block 3rd Floor 120 SF 7 10+ vears Walls - Metal Panel 3rd Floor 810 SF 6 10+ years Work Sink ΕA 7 3rd Floor 8 10+ years Classroom #355 (Science Lab Level 3) Casework 3rd Floor 50 LF 6 10+ years SF Ceiling - Lay-in 3rd Floor 1.850 6 10+ years



Catego	Category : Classroom			Building : Main-Building A					
U				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years			
	Floor - Tile	3rd Floor	1,850	SF	6	10+ years			
	Gas Line	3rd Floor	4	ĒA	7	10+ years			
	Lighting - Lay-in	3rd Floor	24	EA	7	6-10 years			
	Marker Board	3rd Floor	24	LF	6	6-10 years	Quantity changed to match current		
	Marker Board		27	L 1	0	o io years	observations		
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	003017410113		
	Walls - Concrete Block	3rd Floor	309	SF	6	10+ years			
				SF	-	-			
	Walls - Metal Panel	3rd Floor	890		6	10+ years			
	Work Sink	3rd Floor	5	EA	7	10+ years	Quantity changed to match current		
							observations		
Classica									
	om #360 (Science Lab Level 1) Casework	3rd Floor	23	LF	6	10+ years			
						•			
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years			
	Chalk Board	3rd Floor	5	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	900	SF	6	10+ years			
	Gas Line	3rd Floor	20	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	28	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	6	6-10 years			
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years			
	Science Lab Shower	3rd Floor	1	EA	4	0-1 year	No water drain		
	Walls - Concrete Block	3rd Floor	156	SF	6	10+ years			
	Walls - Metal Panel	3rd Floor	650	SF	6	10+ years			
	Work Sink	3rd Floor	9	EA	7	10+ years			
	Work Sink	514 1 1001	5	LA	'	10+ years			
Classroo	om #361 (Science Lab Level 2)								
	Casework	3rd Floor	50	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	900	SF	6	10+ years			
	Gas Line	3rd Floor	12	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	30	EA	7	6-10 years			
	Marker Board	3rd Floor	30 10		7	6-10 years			
				EA		•			
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years			



Category : Classroom			В	Building : Main-Building A						
						Recommend				
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor	156	SF	7	10+ years				
	Walls - Metal Panel	3rd Floor	725	SF	6	10+ years				
	Work Sink	3rd Floor	12	EA	7	10+ years				
lassroo	om #362 (Regular Classroom)									
	Ceiling - Lay-in	3rd Floor	500	SF	6	10+ years				
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years				
	Floor - Tile	3rd Floor	500	SF	6	10+ years				
	Lighting - Lay-in	3rd Floor	28	EA	6	10+ years				
	Marker Board	3rd Floor	13	LF	6	10+ years				
	Walls - Concrete Block	3rd Floor	156	SF	7	10+ years				
	Walls - Metal Panel	3rd Floor	555	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years				
	Work Sink	3rd Floor	1	EA	5	6-10 years				
					Ũ	e re jeare				
lassroo	om #363 (Science Lab Level 2)									
	Casework	3rd Floor	43	LF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years				
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years				
	Eye Wash Station	3rd Floor	1	EA	7	10+ years				
	Floor - Tile	3rd Floor	900	SF	6	10+ years				
	Gas Line	3rd Floor	24	EA	7	10+ years				
	Lighting - Lay-in	3rd Floor	28	EA	7	6-10 years				
	Marker Board	3rd Floor	10	LF	7	6-10 years				
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years				
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor	156	SF	7	10+ years				
	Walls - Metal Panel	3rd Floor	750	SF	6	10+ years				
	Work Sink	3rd Floor	5	EA	7	10+ years	Quantity changed to match current			
			0	L /\	,	Tor youro	observations			
lassro	om #364 (Regular Classroom)									
	Casework	3rd Floor	4	LF	6	10+ years				
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years				
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years				
	Doors - Steel Doors incl hw	3rd Floor	9	EA	7	10+ years				
	Doors - Transom Window	3rd Floor	14	SF	7					
						10+ years				
	Floor - Tile	3rd Floor	750	SF	6	10+ years				



Category : Classroom		Building : Main-Building A						
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years		
	Marker Board	3rd Floor	22	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	130	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	805	SF	6	10+ years		
Classroo	om #365 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years		
	Chalk Board	3rd Floor	10	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	11	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years		
	Floor - Tile	3rd Floor	725	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	15	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	130	SF	6	10+ years		
	Walls - Metal Panel	3rd Floor	785	SF	6	10+ years		
Classroo	om #366 (Regular Classroom)							
	Casework	3rd Floor	5	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Floor - Tile	3rd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years		
	Marker Board	3rd Floor	23	LF	6	•		
	Walls - Concrete Block	3rd Floor	130	SF	7	6-10 years 10+ years		
	Walls - Metal Panel	3rd Floor	805	SF	6	10+ years		
Classroo	om #367 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years		
	Chalk Board	3rd Floor	10	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	14	SF	4 7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	14	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	•		
	Floor - Tile		-	SF	6	10+ years		
		3rd Floor 3rd Floor	750			10+ years		
	Lighting - Lay-in Markar Baard		15	EA LF	7	6-10 years		
	Marker Board	3rd Floor	10	LF SF	7	6-10 years		
	Walls - Concrete Block Walls - Metal Panel	3rd Floor 3rd Floor	130 805	SF SF	7 6	10+ years 10+ years		
Olasari						-		
Jassroo	om #368 (Regular Classroom) Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years		



Category : Classroom			B	Building : Main-Building A					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	3rd Floor	10	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	750	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years			
	Marker Board	3rd Floor	10	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	130	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	805	SF	6	10+ years			
Classroc	om #369 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	960	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ËA	7	10+ years			
	Floor - Tile	3rd Floor	960	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	25	EA	7	6-10 years			
	Marker Board	3rd Floor	6	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	800	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	240	SF	6	10+ years			
	Wireless System	3rd Floor	1	EA	7	10+ years			
Classroo	om #370 (Special Education)								
	Ceiling - Plaster/Drywall	3rd Floor	350	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	350	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years			
	Marker Board	3rd Floor	12	LF	6	6-10 years			
	Walls - Concrete Block	3rd Floor	458	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	250	SF	6	10+ years			
lassroc	om #371 (Regular Classroom)								
	Ceiling - Lay-in	3rd Floor	960	SF	6	10+ years			
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years			
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years			
	Floor - Tile	3rd Floor	960	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	16	EA	6	6-10 years			
	Marker Board	3rd Floor	12	LA	6	6-10 years			
	Walls - Concrete Block	3rd Floor	180	SF	7	10+ years			
	Walls - Metal Panel	3rd Floor	795	SF	6	-			
	vvalis - Ivielai Faliel	310 F1001	795	эг	O	10+ years			



Category : Classroom			Building : Main-Building A					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
. .								
Classroo	om #373 (Regular Classroom)	- · -						
	Ceiling - Lay-in	3rd Floor	400	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	15	SF	7	10+ years		
	Floor - Tile	3rd Floor	400	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	6	6-10 years		
	Marker Board	3rd Floor	10	LF	6	6-10 years		
	Walls - Metal Panel	3rd Floor	695	SF	6	10+ years		
Classroc	om #374 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	680	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Water damage	
	Doors - Side-lite	3rd Floor	15	SF	7	10+ years	3	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Floor - Tile	3rd Floor	696	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	15	ĒA	7	6-10 years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	360	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	550	SF	6	10+ years		
Classroo	om #375 (Regular Classroom)							
01255100	Ceiling - Lay-in	3rd Floor	722	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	22	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	•		
	Floor - Tile	3rd Floor	722	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor 3rd Floor	13	EA	6 7	10+ years 6-10 years		
	Marker Board	3rd Floor	13		7			
		3rd Floor	1,050	SF		6-10 years		
	Walls - Metal Panel Wireless System	3rd Floor 3rd Floor	1,050	EA	6 7	10+ years		
	Wheless System	310 FI001	I	EA	/	10+ years		
Classroo	om #377 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	696	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Floor - Tile	3rd Floor	696	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	96	SF	7	10+ years		



Category : Classroom			В	Building : Main-Building A				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
. .								
Classroo	om #378 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	725	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Floor - Tile	3rd Floor	725	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years		
	Marker Board	3rd Floor	12	LF	6	6-10 years		
	Walls - Concrete Block	3rd Floor	170	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	769	SF	6	10+ years		
lassro	om #379 (Regular Classroom)							
1000100	Ceiling - Lay-in	3rd Floor	580	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	14	EA	7	10+ years		
			9	SF	7	•		
	Doors - Transom Window	3rd Floor	•	SF	-	10+ years		
	Floor - Tile	3rd Floor	580		6	10+ years		
	Lighting - Lay-in	3rd Floor	8	EA	6	6-10 years		
	Marker Board	3rd Floor	6	LF	6	6-10 years		
	Walls - Metal Panel	3rd Floor	705	SF	6	10+ years		
lassroo	om #380 (Computer Lab)							
	Ceiling - Lay-in	3rd Floor	876	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Water damage	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	ĒA	7	10+ years		
	Doors - Transom Window	3rd Floor	. 9	SF	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	156	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	555	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	300	SF	6			
		3rd Floor	300	EA	6 7	10+ years		
	Wireless System	310 FI001	I	EA	1	10+ years		
lassroo	om #381 (Culinary)							
	Ceiling - Lay-in	3rd Floor	1,996	SF	7	10+ years		
		3rd Floor	4	SF	4	0-1 year	Missing.	
	Ceiling - Lay-in				7		-	
	Ceiling - Lay-in Culinary Exhaust Hood - Type I	3rd Floor	1	EA	7	10+ years		
	Culinary Exhaust Hood - Type I	3rd Floor	1 13	EA EA	7			
						10+ years 10+ years 10+ years		



Category : Classroom			Building : Main-Building A					
Ū	-			-		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Tile	3rd Floor	954	SF	6	10+ years		
	Floor - Tile Quarry	3rd Floor	1,046	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	39	EA	7	6-10 years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	7	SF	7	10+ years		
	Storage/ Closet	3rd Floor	7	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	208	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	610	SF	7	10+ years		
	Walls - Tile	3rd Floor	470	SF	7	10+ years		
	Work Sink	3rd Floor	4	EA	7	10+ years		
	Work Sink	3rd Floor	1	EA	5	0-1 year	Sensor not working.	
	Work Sink	3rd Floor	2	EA	4	0-1 year	Piping issues.	
<u>Classroo</u>	m #381B (Store Room)							
	Ceiling - Lay-in	3rd Floor	271	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	278	SF	7	10+ years		
	Floor - Tile	3rd Floor	1	SF	4	0-1 year	Chipped	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years		
	Storage/ Closet	3rd Floor	8	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	575	SF	7	10+ years		
Classroo	m #383 (Science Lab Level 3)							
	Casework	3rd Floor	11	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	986	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	11	SF	7	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years		
	Doors - Transom Window	3rd Floor	13	SF	7	10+ years		
	Floor - Tile	3rd Floor	986	SF	6	10+ years		
	Gas Line	3rd Floor	2	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	35	EA	6	6-10 years		
	Marker Board	3rd Floor	12	LF	6	10+ years		
	Walls - Concrete Block	3rd Floor	374	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	500	SF	6	10+ years		
	Work Sink	3rd Floor	2	EA	7	10+ years		
Catego	ry : Interior		В	uilding	: Main-E	Building A		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	nom - Type	Location	Quantity		Nank	Replacement	ooninienta	



Group

Category : Interior

Marie Sklodowska Curie Metropolitan High School 4959 S Archer AVENUE, Chicago, IL 60632

Building : Main-Building A

Recommend Location Item - Type Quantity UOM Rank **Replacement** Comments Ceiling - Lay-in 1st East 980 SF 6 10+ vears Ceiling - Splined SF 6 1st East 3.784 10+ years Doors - Steel Doors incl hw 1st East 8 EΑ 7 10+ years 48 SF Doors - Transom Window 1st East 6 10+ years 7 **Drinking Fountains** - Single Fountain 1st East 2 EΑ 10+ years SF 5 Floor - Tile/Sheet 1st East 4.764 10+ years Lighting - Lay-in 1st East ΕA 6 6-10 years 58 Lighting - Wall Mounted 1st East 3 ΕA 6 6-10 years Walls - Concrete Block 1st East 60 SF 7 10+ years SF Walls - Masonrv 7 10+ vears 1st East 2.850 SF Walls - Metal Panel 1st East 1.170 6 10+ vears Ceiling - Lay-in 1st North 5.633 SF 6 10+ years Ceiling - Lay-in SF 4 0-1 year 1st North 18 Missing. SF 6 Ceiling - Splined 1st North 4,090 10+ years Doors - Transom Window SF 6 1st North 36 10+ years 12 FΑ 6 Doors - Wood Doors include hw 1st North 10+ years 7 Drinking Fountains - Single Water Cooler 1st North 4 ΕA 10+ years Floor - Tile/Sheet 1st North 9.741 SF 7 10+ years Lighting - Lav-in 1st North 75 ΕA 6 6-10 years Lighting - Pendent/Surface 1st North 114 ΕA 6 6-10 years Lighting - Wall Mounted 1st North ΕA 6 6-10 years 1 Student Lockers - One Tier 1st North 500 ΕA 6 10+ years SF 6 Walls - Masonry 1st North 3.610 10+ years SF Walls - Metal Panel 1st North 1.191 6 10+ years Ceiling - Lay-in 2.615 SF 6 1st South 10+ years Doors - Store Front 1st South 2 ΕA 6 10+ vears Drinking Fountains - Single Water Cooler 7 1st South 4 ΕA 10+ years Floor - Tile/Sheet 1st South 2.615 SF 7 10+ years Lighting - Lay-in ΕA 1st South 36 6 6-10 years Walls - Concrete Block 1st South 60 SF 6 10+ years SF Walls - Masonry 1st South 1.600 6 10+ vears SF Walls - Structural Glazed Tile 1st South 1.420 6 10+ vears SF Ceiling - Lay-in 1st West 2.794 6 10+ years Ceiling - Splined 1st West 595 SF 6 10+ years Doors - Steel Doors incl hw 1st West 8 EΑ 6 10+ years Drinking Fountains - Single Water Cooler ΕA 7 1st West 2 10+ years SF Floor - Tile/Sheet 1st West 3,389 7 10+ years 6-10 years Lighting - Lay-in 1st West 40 EΑ 6 Student Lockers - One Tier 1st West 83 EΑ 6 10+ years SF Walls - Concrete Block 1st West 140 6 10+ vears SF Walls - Masonry 1st West 1.636 7 10+ years SF Walls - Metal Panel 1st West 1.340 6 10+ years Ceiling - Lay-in 1st middle south 1,173 SF 6 10+ years Changed to match current observations



Category : Interior **Building : Main-Building A** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile/Sheet 1st middle south 1.161 SF 10+ vears 7 Floor - Tile/Sheet SF 0-1 vear 1st middle south 12 4 Chipped Lighting - Lay-in 1st middle south 30 EΑ 6 6-10 years Walls - Concrete Block 1st middle south SF 6 180 10+ years Walls - Metal Panel 1st middle south 1,710 SF 6 10+ years SF 1st middle south Walls - Plaster/Drywall 650 6 10+ years Ceiling - Lay-in 2nd East 2,226 SF 6 10+ years Doors - Wood Doors include hw 2nd East 16 EΑ 6 10+ years Drinking Fountains - Single Fountain 2nd East 2 EΑ 7 10+ years SF Floor - Tile/Sheet 2nd East 2.226 7 10+ vears Lighting - Lav-in 2nd East 43 ΕA 6 6-10 years Student Lockers - One Tier 2nd East 650 EΑ 7 10+ years Walls - Masonry SF 7 2nd East 40 10+ years SF Walls - Metal Panel 2nd East 3,302 6 10+ years Ceiling - Lay-in SF 6 2nd North 7,318 10+ years Floor - Tile/Sheet SF 5 2nd North 7,318 10+ years ΕA 6 Lighting - Lav-in 2nd North 138 6-10 years 7 Student Lockers - One Tier 2nd North 96 EΑ 10+ years SF Walls - Masonry 2nd North 1.910 7 10+ vears SF Walls - Metal Panel 2nd North 2,422 6 10+ years Ceiling - Lay-in 2nd South 3.330 SF 6 10+ years Floor - Tile/Sheet SF 7 2nd South 3,330 10+ years Lighting - Lay-in 2nd South 46 EΑ 6 6-10 years Walls - Masonry 729 SF 7 2nd South 10+ years Walls - Metal Panel 2.965 SF 6 2nd South 10+ years SF Ceiling - Lav-in 2nd West 2.476 6 10+ vears Doors - Transom Window SF 7 2nd West 72 10+ years Doors - Wood Doors include hw 2nd West 16 ΕA 6 10+ years 7 Drinking Fountains - Single Fountain 2nd West 2 EΑ 10+ years Floor - Tile/Sheet 2nd West 2,476 SF 7 10+ years Lighting - Lay-in 2nd West ΕA 6 6-10 years 41 Walls - Concrete Block 2nd West 250 SF 7 10+ vears SF 7 10+ years Walls - Masonry 2nd West 60 Walls - Metal Panel 2nd West 3.740 SF 6 10+ years SF Ceiling - Lay-in 3rd East 2,392 6 10+ years Doors - Store Front ΕA 7 3rd East 16 10+ years Changed to match current observations Drinking Fountains - Single Water Cooler 10+ years 3rd East EA 7 4 Floor - Tile/Sheet 3rd East 2.392 SF 5 10+ years 7 Lighting - Lav-in 3rd East 42 ΕA 6-10 years Student Lockers - One Tier 3rd East 10 ΕA 7 10+ years SF 7 Walls - Masonrv 3rd East 240 10+ vears Walls - Metal Panel 3rd East 3,530 SF 6 10+ years SF Ceiling - Lay-in 3rd Middle South 1,440 6 10+ years



Building : Main-Building A Category : Interior Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Floor - Tile/Sheet 3rd Middle South 1.440 SF 5 10+ vears 32 ΕA 6 6-10 vears Lighting - Lay-in 3rd Middle South Walls - Concrete Block 3rd Middle South 200 SF 6 10+ years Walls - Metal Panel SF 6 3rd Middle South 3.030 10+ years SF 6 Ceiling - Lay-in 3rd North 4,541 10+ years SF Floor - Tile/Sheet 5 3rd North 4,531 10+ years Floor - Tile/Sheet 3rd North SF 4 0-1 year 10 Chipping Lighting - Lay-in 3rd North 136 ΕA 7 6-10 years Lighting - Lay-in 3rd North 2 ΕA 6 6-10 years Student Lockers - One Tier 720 ΕA 7 10+ years 3rd North Walls - Masonrv 3rd North 1.115 SF 7 10+ vears Walls - Metal Panel 3rd North 1.190 SF 6 10+ years Ceiling - Lay-in 3,501 SF 6 10+ years 3rd South 5 SF Floor - Tile/Sheet 3rd South 3,501 6-10 years Lighting - Lay-in ΕA 6 6-10 years 3rd South 52 Walls - Masonry 750 SF 7 3rd South 10+ years 3.095 SF Walls - Metal Panel 3rd South 6 10+ years Ceiling - Lav-in SF 3rd West 2,314 6 10+ years ΕA Doors - Store Front 3rd West 16 6 10+ vears Drinking Fountains - Double Fountain 3rd West 3 EΑ 7 10+ years Drinking Fountains - Double Fountain 3rd West 4 ΕA 5 6-10 years Changed to match current observations Floor - Tile/Sheet SF 7 3rd West 2,304 10+ years SF Floor - Tile/Sheet 3rd West 10 4 0-1 year Chipping/cracking Lighting - Lay-in 3rd West ΕA 6 6-10 years 40 Student Lockers - One Tier 3rd West 15 ΕA 7 10+ vears SF Walls - Masonry 3rd West 240 7 10+ years Walls - Metal Panel 3rd West 4,120 SF 6 10+ years Basement - N/S Main SF 6 Ceiling - Plaster/Drywall 1,681 10+ years Drinking Fountains - Single Fountain Basement - N/S Main ΕA 5 6-10 years 1 Floor - Tile/Sheet Basement - N/S Main 1.481 SF 5 6-10 years Basement - N/S Main SF Floor - Tile/Sheet 200 4 0-1 vear Missing/broken/Quantity changed to match current observations Lighting - Pendent/Surface Basement - N/S Main FΑ 6 6-10 years 17 Walls - Concrete Block SF Basement - N/S Main 2,687 6 10+ years Changed to match current observations / peeling paint throughout Basement - West SF Ceiling - Plaster/Drywall 211 6 10+ years SF Ceiling - Splined Basement - West 294 6 10+ years Floor - Tile/Sheet SF 5 Basement - West 420 6-10 vears SF Floor - Tile/Sheet Basement - West 85 4 0-1 year Missing/cracking FΑ 7 6-10 vears Lighting - Pendent/Surface Basement - West 14 Walls - Concrete Block Basement - West 1,165 SF 6 10+ years Ceiling - Lay-in SF North Link to Annex 2,809 6 10+ years



Catego	ry : Interior		Building : Main-Building A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Steel Doors incl hw	North Link to Annex	1	EA	6	10+ years		
	Drinking Fountains - Single Fountain	North Link to Annex	2	EA	7	10+ years		
	Floor - Tile/Sheet	North Link to Annex	2,809	SF	5	10+ years		
	Lighting - Lay-in	North Link to Annex	48	EA	7	6-10 years		
	Lighting - Wall Mounted	North Link to Annex	2	EA	7	6-10 years		
	Walls - Masonry	North Link to Annex	896	SF	7	10+ years		
	Ceiling - Lay-in	South Link to Annex	2,809	SF	6	10+ years		
	Doors - Steel Doors incl hw	South Link to Annex	1	EA	6	10+ years		
	Drinking Fountains - Single Fountain	South Link to Annex	2	EA	7	10+ years		
	Floor - Tile/Sheet	South Link to Annex	2,809	SF	5	10+ years		
	Lighting - Lay-in	South Link to Annex	48	EA	7	6-10 years		
	Lighting - Wall Mounted	South Link to Annex	2	EA	7	6-10 years		
	Walls - Masonry	South Link to Annex	896	SF	7	10+ years		
Safety								
	Metal Dedector	Entire building	3	EA	7	6-10 years		
	Security Cameras	Entire building	45	EA	7	6-10 years		
stairs								
	Ceiling - Plaster/Drywall	East - Basement/1st	169	SF	7	10+ years		
	Floor - Concrete	East - Basement/1st	72	SF	5	10+ years		
	Floor - Tile	East - Basement/1st	20	SF	6	10+ years		
	Handrails	East - Basement/1st	58	LF	5	10+ years		
	Lighting - Lay-in	East - Basement/1st	4	EA	7	6-10 years		
	Stairs - Concrete	East - Basement/1st	92	LF	6	10+ years		
	Walls - Concrete Block	East - Basement/1st	1,168	SF	6	10+ years		
	Ceiling - Lay-in	NE Stair	1,069	SF	7	10+ years		
	Ceiling - Lay-in	NE Stair	4	SF	4	0-1 year	Water damage	
	Ceiling - Plaster/Drywall	NE Stair	409	SF	7	10+ years	C C	
	Floor - Terrazzo	NE Stair	975	SF	6	10+ years		
	Handrails	NE Stair	72	LF	7	10+ years		
	Lighting - Lay-in	NE Stair	21	EA	6	6-10 years		
	Stairs - Terrazzo	NE Stair	260	LF	6	10+ years		
	Walls - Masonry	NE Stair	2,876	SF	7	10+ years		
	Walls - Plaster/Drywall	NE Stair	125	SF	6	10+ years		
	Ceiling - Lay-in	NW Stair	1,073	SF	7	10+ years		
	Ceiling - Plaster/Drywall	NW Stair	409	SF	6	10+ years		
	Floor - Terrazzo	NW Stair	975	SF	7	10+ years		
	Handrails	NW Stair	72	LF	7	10+ years		
	Lighting - Lay-in	NW Stair	21	EA	6	6-10 years		
	Stairs - Terrazzo	NW Stair	260	LF	6	10+ years		
	Walls - Masonry	NW Stair	2,999	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Room 166 mezzanine stairs	90	SF	6	10+ years		
	Floor - Concrete	Room 166 mezzanine stairs	70	SF	5	10+ years		



Catego	ry : Interior		В	Building : Main-Building A						
-				Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Handrails	Room 166 mezzanine stairs	14	LF	7	10+ years				
	Handrails	Room 166 mezzanine stairs	11	LF	7	10+ years				
	Lighting - Pendent/Surface	Room 166 mezzanine stairs	2	EA	7	6-10 years				
	Stairs - Concrete	Room 166 mezzanine stairs	48	LF	7	10+ years				
	Stairs - Concrete	Room 166 mezzanine stairs	51	LF	6	10+ years				
	Walls - Concrete Block	Room 166 mezzanine stairs	520	SF	6	10+ years				
	Ceiling - Lay-in	SE	1,069	SF	7	10+ years				
	Ceiling - Lay-in	SE	4	SF	4	0-1 year	Water damage			
	Ceiling - Plaster/Drywall	SE	409	SF	6	10+ years				
	Floor - Terrazzo	SE	975	SF	7	10+ years				
	Handrails	SE	72	LF	7	10+ years				
	Lighting - Lay-in	SE	21	EA	7	6-10 years				
	Stairs - Terrazzo	SE	260	LF	6	10+ years				
	Walls - Masonry	SE	2,999	SF	7	10+ years				
	Ceiling - Lay-in	SW Stair	1,073	SF	7	10+ years				
	Ceiling - Plaster/Drywall	SW Stair	409	SF	6	10+ years				
	Floor - Terrazzo	SW Stair	975	SF	6	10+ years				
	Handrails	SW Stair	72	LF	7	10+ years				
	Lighting - Lay-in	SW Stair	21	EA	6	6-10 years				
	Stairs - Terrazzo	SW Stair	260	LF	6	10+ years				
	Walls - Masonry	SW Stair	2,999	SF	7	10+ years				
	Ceiling - Exposed	West - Basement/1st	137	SF	6	10+ years				
	Floor - Concrete	West - Basement/1st	77	SF	5	10+ years				
	Handrails	West - Basement/1st	58	LF	7	10+ years				
	Lighting - Pendent/Surface	West - Basement/1st	2	EA	6	6-10 years				
	Lighting - Wall Mounted	West - Basement/1st	2	EA	6	6-10 years				
	Stairs - Concrete	West - Basement/1st	85	LF	6	10+ years				
	Walls - Concrete Block	West - Basement/1st	729	SF	7	10+ years				
	Walls - Masonry	West - Basement/1st	141	SF	7	10+ years				
Vertical	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	Pieces of flooring missing. Quantity updated to match current observation.			
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	Flooring cracking/chipping.			



Category : Exterior			В	Building : Linked Addition-Athletic Building B						
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Entrance										
	Entrance Control - Audio and Video	1 - Main north	1	EA	6	10+ years				
	Exterior Doors - Exterior FRP Door	1 - Main north	4	EA	6	10+ years				
	Exterior Doors - Side lite	1 - Main north	12	EA	6	10+ years				
	Exterior Doors - Transom Lite	1 - Main north	9	EA	6	10+ years				
	Power Door Operator and Controls	1 - Main north	1	EA	7	6-10 years				
	Exterior Doors - Exterior FRP Door	11/12	8	EA	6	10+ years				
	Exterior Doors - Transom Lite	11/12	8	EA	6	10+ years				
	Exterior Stairs - Concrete	11/12	24	LF	6	10+ years				
	Ramps - Concrete	11/12	10	LF	6	10+ years				
	Exterior Doors - Exterior FRP Door	13	2	EA	6	10+ years				
	Exterior Doors - Exterior FRP Door	14	2	EA	6	10+ years				
	Exterior Doors - Exterior FRP Door	2	2	EA	6	10+ years	Graffiti all over doors.			
	Exterior Doors - Exterior FRP Door	3	2	EA	6	10+ years				
	Exterior Doors - Transom Lite	3	2	EA	6	10+ years				
	Exterior Doors - Exterior FRP Door	4	2	EA	6	10+ years				
	Exterior Doors - Transom Lite	4	2	EA	6	10+ years				
	Exterior Doors - Side lite	5	4	EA	6	10+ years				
	Exterior Doors - Store Front	5	8	EA	6	10+ years				
	Exterior Doors - Exterior FRP Door	Courtyard doors	8	EA	7	10+ years				
	Exterior Doors - Side lite	Courtyard doors	8	EA	7	10+ years				
	Exterior Doors - Transom Lite	Courtyard doors	8	EA	7	10+ years				
	Exterior Stairs - Concrete	Courtyard doors	40	LF	7	10+ years				
	Exterior Doors - Exterior Steel Door	Roof	1	EA	6	10+ years				
	Exterior Stairs - Steel or Aluminum	Roof	3	LF	6	10+ years				
Foundat	on									
	Foundation - Concrete	Entire Building	1,640	LF	7	10+ years				
	Superstructure - Metal Deck/ Concrete	Entire Building	170,493	SF	7	10+ years				
	Topping	Entro Bananig	110,100	0.	•	lot youro				
Lighting										
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	15	EA	7	10+ years	Led			
	Exterior Lighting - Wall Mounted	Entire Building	29	EA	7	10+ years	Led			
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years				
Roof Sys	stem									
<u></u>	Coping - Metal	G	509	LF	7	10+ years				
	Downspouts - Interior Downspouts	G	30	LF	6	10+ years				
	Parapet - 16" - 30" Height	G	509	LF	7	10+ years				
	Roof - Modified Bitumen	G	10,330	SF	6	10+ years				
	Roof Structure - Steel / Metal Deck/	G	10,330	SF	7	10+ years				
		5	10,330	0	1	io+ years				

Category : Exterior



Building : Linked Addition-Athletic Building B Category : Exterior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Concrete Topping Coping - Metal Н LF 7 10+ vears 1.345 Downspouts - Interior Downspouts Н 455 LF 6 10+ years Parapet - Parapet < 16" Height 1,350 LF 7 н 10+ years SF Roof - Modified Bitumen н 56,899 6 10+ years SF Roof Structure - Steel / Metal Deck/ н 56,899 7 10+ years Concrete Topping LF Coping - Metal 428 7 10+ years Downspouts - Interior Downspouts 140 LF 6 2-5 years Parapet - Parapet < 16" Height LF 428 7 10+ years Roof - Modified Bitumen SF 23.408 6 10+ vears Roof Structure - Steel / Metal Deck/ Е 23.408 SF 7 10+ years Concrete Topping Access Ladder - Metal J 1 EΑ 7 10+ years LF 7 Coping - Metal J 60 10+ years LF Downspouts - Interior Downspouts J 10 6 10+ years Parapet - Parapet < 16" Height LF 7 J 60 10+ years SF Roof - Modified Bitumen J 225 6 10+ years ΕA Roof Hatch - Metal J 1 7 10+ vears 225 Roof Structure - Steel / Metal Deck/ .1 SF 7 10+ years Concrete Topping Walls Canopy - Concrete/ Stucco Entire Building 2.240 SF 6 10+ vears Exterior Walls - Brick Entire Building 48.934 SF 6 10+ years Windows LF 6 Lintels - Steel Entire Building 556 10+ years Storefront Windows Entire Building 3.990 SF 6 10+ years SF Windows - Decorative Entire Building 431 6 10+ years **Category : Electrical** Building : Linked Addition-Athletic Building B Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Emergency System Security System - CCTV Electrical Room 170,483 SF 6 6-10 years Security System - Intrusion Detection SF Electrical Room 170,493 6 6-10 years Exit Signs - Auditoium 16 ΕA 5 2-5 years Entire Building Exit Signs - Corridors and Stairs Entire Building 30 ΕA 5 2-5 years Exit Signs - Gvm Entire Building 15 ΕA 6 2-5 vears Exit Signs - Pool Entire Building 4 FΑ 5 2-5 years SF Emergency A/C Power - Auditoium and Entire Building 6 6-10 years 8,200 Aisle Lighting



)	bry : Electrical		R	Building : Linked Addition-Athletic Building B						
Juicgo		Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Emergency A/C Power - Corridors and Stairs	Entire Building	29,956	SF	6	6-10 years				
	Emergency A/C Power - Gym	Entire Building	22,551	SF	6	6-10 years				
Main Se	rvice									
	PA System	Entire Building	170,493	SF	5	6-10 years	Connected to the main building			
	Main Electrical Service - 1200 A 277/480/3PH	Entire Building	4	EA	6	2-5 years	50 years old.			
	Main Electrical Service - Greater than 3000 A 277/480/3PH	Entire Building	1	EA	6	2-5 years	50 years old.			
Power D	Distribution									
	Lighting and Power Panels - 100 A	Entire Building	10	EA	7	10+ years				
	Lighting and Power Panels - 100 A	Entire Building	20	EA	6	2-5 years				
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years				
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	2-5 years				
	Transformers - 277/480 - 120/208	Entire Building	8	EA	6	6-10 years				
Catego	ry : Fire Protection		В	uilding	: Linkec		etic Building B			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
Fire Alar										
	Fire Alarm Strobe Lights	Entire Building	170,493	SF	6	6-10 years				
	Fire Alarm_System	Entire Building	170,493	SF	6	6-10 years				
Catego	ry : Mechanical		В	uilding	: Linked	Addition-Athl	etic Building B			
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Air Conc	0	Deef				40				
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	6	10+ years	Serves the pool unit.			
Air Hand	lling Systems									
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating & DX Cooling w/ Remote Mounted Compressor - 31 - 45 tons	Roof	1	EA	7	10+ years				
		Roof	1	EA	7	10+ years				
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons		·			,				



Catego	ry : Mechanical	В	Building : Linked Addition-Athletic Building B						
					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons	Roof	7	EA	7	10+ years			
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons	Roof	4	EA	7	10+ years			
Heating	Devices								
	Duct Heater - Electric	Entire Building	12		6	6-10 years			
	Fin Tube - Electric	Entire Building	60	LF	7	10+ years			
	Fin Tube - Steam	Entire Building	390	LF	6	6-10 years			
	Unit Heater - Electric	Mechanical Room	2	EA	7	6-10 years			
	Unit Heater - Gas	Mechanical Room	1	EA	6	10+ years			
Tempera	ature Control								
	DDC System	Entire Building	170,493	SF	7	10+ years			
	Electric Thermostat	Entire Building	1	EA	7	6-10 years			
	Thermostats - DDC	Entire Building	18	EA	7	10+ years			
Ventilatio	on								
	Exhaust Fans- Indoor - Less than 500 CFM	Roof	1	EA	4	0-1 year	Corroded		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	7	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	9	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years			
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	1	EA	7	10+ years			

Category : Plumbing

Building : Linked Addition-Athletic Building B

Group Hot Wate	Item - Type	Location	Quantity	ι	JOM	Rank	Recommend Replacement	Comments
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room		1	EA	6	6-10 years	
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room		1	EA	7	10+ years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	:	3	EA	7	10+ years	



Catego	ry : Plumbing		В	uilding	: Linked		etic Building B
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years, leaky and rusted
	Domestic Piping-Hot Water Return Risers	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years, leaky and rusted
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years leaky and rusted
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years leaky and rusted
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years leaky and rusted
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	170,493	SF	4	0-1 year	The pipes are older than 50 years leaky and rusted
	Sanitary Piping	Entire Building	170,493	SF	6	2-5 years	loaky and rubiou
	Storm Piping	Entire Building	170,493	SF	6	2-5 years	
	Vent Piping	Entire Building	170,493	SF	6	2-5 years	
Pool Sys							
	Pool Drain Piping	Mechanical Room	50	LF	7	6-10 years	
	Pool Filtration System including Pump	Mechanical Room	2	EA	6	6-10 years	
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	6	10+ years	
	Pool Supply and Return Piping	Mechanical Room	300	LF	7	10+ years	
oumps							
	Pumps - Ejector-Duplex	Mechanical Room	1	EA	4	0-1 year	Corroded and aged
	Pumps - Sump-Simplex	Mechanical Room	1	EA	5	6-10 years	
Catego	ry : Room		В	uilding	: Linked		etic Building B
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Splined	1st Floor Boys Gym Office North	112	SF	6	6-10 years	
	Ceiling - Splined	1st Floor Boys Gym Office North	8	SF	4	0-1 year	Damaged
	Doors - Side-lite	1st Floor Boys Gym Office North	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys Gym Office North	3	EA	6	10+ years	
	Floor - Tile	1st Floor Boys Gym Office North	120	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Boys Gym Office North	2	EA	6	6-10 years	
	Power Distribution	1st Floor Boys Gym Office North	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Boys Gym Office North	250	SF	6	10+ years	
		1st Floor Boys Gym Office South	110	SF	6	6-10 years	
	Ceiling - Splined		110	-	0	0 TO yours	
	Ceiling - Splined	1st Floor Boys Gym Office South	10	SF	4	0-1 year	Water damage
			-	-		•	Water damage



Catego	ry : Room		В	uildina	: Linked		etic Building B
30.030			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Carpet	1st Floor Boys Gym Office South	120	SF	6	6-10 years	Dirty, needs to be cleaned.
	Lighting - Lay-in	1st Floor Boys Gym Office South	2	EA	7	6-10 years	
	Power Distribution	1st Floor Boys Gym Office South	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Boys Gym Office South	250	SF	6	10+ years	
	Ceiling - Splined	1st Floor Girls Gym North Office	88	SF	6	10+ years	
	Ceiling - Splined	1st Floor Girls Gym North Office	4	SF	4	0-1 year	Damaged.
	Doors - Wood Doors inclu hw	1st Floor Girls Gym North Office	1	EA	6	10+ years	ů.
	Floor - Tile	1st Floor Girls Gym North Office	92	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Girls Gym North Office	2	EA	6	6-10 years	
	Power Distribution	1st Floor Girls Gym North Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls Gym North Office	350	SF	6	10+ years	
	Ceiling - Splined	1st Floor Girls Gym South Office	82	SF	6	10+ years	
	Ceiling - Splined	1st Floor Girls Gym South Office	10	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	1st Floor Girls Gym South Office	1	EA	6	10+ years	-
	Floor - Tile	1st Floor Girls Gym South Office	92	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Girls Gym South Office	2	EA	6	6-10 years	
	Power Distribution	1st Floor Girls Gym South Office	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Girls Gym South Office	350	SF	6	10+ years	
	Ceiling - Splined	503E Production Manager Office	70	SF	6	10+ years	
	Doors - Side-lite	503E Production Manager Office	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	503E Production Manager Office	1	EA	6	10+ years	
	Floor - Wood	503E Production Manager Office	70	SF	6	10+ years	
	Lighting - Lay-in	503E Production Manager Office	1	EA	6	6-10 years	
	Power Distribution	503E Production Manager Office	4	EA	7	10+ years	
	Walls - Concrete Block	503E Production Manager Office	166	SF	6	10+ years	
	Ceiling - Plaster/Drywall	505 (tickets room)	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	505 (tickets room)	2	EA	6	10+ years	
	Floor - Tile	505 (tickets room)	220	SF	6	6-10 years	
	Lighting - Lay-in	505 (tickets room)	4	EA	6	6-10 years	
	Power Distribution	505 (tickets room)	4	EA	6	10+ years	
	Walls - Plaster/Drywall	505 (tickets room)	800	SF	6	10+ years	
	Ceiling - Plaster/Drywall	506 Theatre Office	210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	506 Theatre Office	1	EA	6	10+ years	The other door belongs to room 505.
	Floor - Tile	506 Theatre Office	210	SF	6	10+ years	5
	Lighting - Lay-in	506 Theatre Office	4	EA	6	6-10 years	
	Power Distribution	506 Theatre Office	4	EA	6	10+ years	Quantity changed to match current observations
	Walls - Plaster/Drywall	506 Theatre Office	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	507 Theatre Office	210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	507 Theatre Office	210	EA	6	10+ years	
	Floor - Tile	507 Theatre Office	210	SF	6	10+ years	
	Lighting - Pendent/Surface	507 Theatre Office	3	EA	7	6-10 years	
	Power Distribution	507 Theatre Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	507 Theatre Office	400	SF	6	10+ years	
			-00	01	0	ior yours	



Catego	ry : Room		В	uilding	: Linked	Addition-Athl	etic Building B
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	507 Theatre Office	1	EA	5	6-10 years	Changed to match current observations
	Ceiling - Splined	508A Tickets (Box Office) inside dance room	30	SF	6	10+ years	
	Ceiling - Splined	508A Tickets (Box Office) inside dance room	6	SF	4	0-1 year	Missing/damage
	Doors - Wood Doors inclu hw	508A Tickets (Box Office) inside dance room	1	EA	6	10+ years	
	Floor - Tile	508A Tickets (Box Office) inside dance room	36	SF	6	10+ years	
	Lighting - Lay-in	508A Tickets (Box Office) inside dance room	1	EA	6	6-10 years	
	Power Distribution	508A Tickets (Box Office) inside dance room	2	EA	6	10+ years	
	Walls - Masonry	508A Tickets (Box Office) inside dance room	220	SF	6	10+ years	
	Ceiling - Splined Doors - Side-lite	510A - Practice Room 510A - Practice Room	76 25	SF SF	4 6	0-1 year 10+ years	Chipped throughout
	Doors - Wood Doors inclu hw Floor - Tile	510A - Practice Room 510A - Practice Room 510A - Practice Room	23 1 76	EA SF	6 6	10+ years 10+ years 10+ years	Missing door handle
	Lighting - Lay-in Power Distribution	510A - Practice Room	78 2 4	EA EA	6	6-10 years	
	Walls - Concrete Block	510A - Practice Room 510A - Practice Room	200	SF SF	6 6	10+ years 10+ years	
	Ceiling - Splined Doors - Side-lite	510B - Practice Room 510B - Practice Room	54 25	SF	6 6	6-10 years 10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	510B - Practice Room 510B - Practice Room	1 54	EA SF	6 6	10+ years 6-10 years	
	Lighting - Lay-in Power Distribution	510B - Practice Room 510B - Practice Room	2 4	EA EA	7 7	6-10 years 10+ years	
	Walls - Concrete Block Ceiling - Splined	510B - Practice Room 510C - Practice Room	163 76	SF SF	7 4	10+ years 0-1 year	The tiles are chipped throughout
	Doors - Side-lite Doors - Wood Doors inclu hw	510C - Practice Room 510C - Practice Room	25 1	SF EA	6 6	10+ years 10+ years	
	Floor - Tile Lighting - Lay-in	510C - Practice Room 510C - Practice Room	76 3	SF EA	6 6	10+ years 6-10 years	
	Walls - Concrete Block Ceiling - Splined	510C - Practice Room 510D - Practice Room	200 76	SF SF	6 4	10+ years 1-2 years	Damaged tiles throughout.
	Doors - Side-lite Doors - Wood Doors inclu hw	510D - Practice Room 510D - Practice Room	25 1	SF EA	6 6	10+ years 10+ years	
	Floor - Tile Lighting - Lay-in	510D - Practice Room 510D - Practice Room	76 2	SF EA	6 6	10+ years 6-10 years	
	Walls - Concrete Block Ceiling - Splined	510D - Practice Room 514A - Practice Room	200 50	SF	6 6	10+ years 6-10 years	
	Ceiling - Splined	514A - Practice Room	4	SF	4	0-1 year	Missing/damaged.



Category : Room Building : Linked Addition-Athletic Building B Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Side-lite 514A - Practice Room 25 SF 10+ vears 6 ΕA 6 Doors - Wood Doors inclu hw 514A - Practice Room 1 10+ years Floor - Tile 514A - Practice Room 54 SF 6 10+ years 2 ΕA 6 Lighting - Lay-in 514A - Practice Room 6-10 years 7 Power Distribution 514A - Practice Room 4 EΑ 10+ years SF 7 Walls - Concrete Block 514A - Practice Room 163 10+ years Ceiling - Splined SF 6-10 years 514B - Practice Room 50 6 SF Ceiling - Splined 514B - Practice Room 4 4 0-1 year Missina Doors - Side-lite 514B - Practice Room 25 SF 6 10+ years Doors - Wood Doors inclu hw 1 ΕA 5 10+ years 514B - Practice Room Floor - Tile 514B - Practice Room 54 SF 6 10+ vears Lighting - Lay-in 514B - Practice Room 1 ΕA 6 6-10 years **Power Distribution** 2 ΕA 6 514B - Practice Room 10+ years SF 7 Walls - Concrete Block 514B - Practice Room 163 10+ years SF Ceiling - Splined 514C - Practice Room 86 4 0-1 year Broken missing tiles throughout Doors - Side-lite 75 SF 6 514C - Practice Room 10+ years ΕA Doors - Wood Doors inclu hw 514C - Practice Room 1 6 10+ vears Floor - Tile 514C - Practice Room 86 SF 6 10+ years Lighting - Lay-in 514C - Practice Room 2 ΕA 6 6-10 vears Power Distribution 514C - Practice Room 2 EΑ 6 10+ years Walls - Concrete Block 514C - Practice Room 200 SF 6 10+ years SF Ceiling - Splined 518 1st Floor Music Office 410 6 6-10 years SF Ceiling - Splined 518 1st Floor Music Office 30 4 0-1 year Missing/damage 225 SF Doors - Side-lite 518 1st Floor Music Office 6 10+ years Doors - Transom Window 6 SF 6 518 1st Floor Music Office 10+ years Doors - Wood Doors inclu hw 518 1st Floor Music Office 4 ΕA 6 10+ vears SF Floor - Tile 518 1st Floor Music Office 440 6 10+ years Lighting - Lay-in ΕA 6 6-10 years 518 1st Floor Music Office 10 **Power Distribution** 518 1st Floor Music Office 16 EΑ 6 10+ years Storage/ Closet 518 1st Floor Music Office 280 SF 7 10+ years SF Walls - Concrete Block 518 1st Floor Music Office 480 6 10+ vears SF Ceiling - Splined 520 Green Room 358 6 10+ vears SF Doors - Transom Window 520 Green Room 10 6 10+ years Doors - Wood Doors inclu hw 520 Green Room FΑ 6 1 10+ years SF Floor - Carpet 520 Green Room 358 6 6-10 years Changed to match current observations Lighting - Lay-in 520 Green Room 6 EΑ 7 6-10 years Power Distribution 520 Green Room 6 EΑ 7 10+ years SF Walls - Concrete Block 520 Green Room 720 6 10+ years ΕA 7 Work SInk 520 Green Room 1 10+ vears Ceiling - Splined 522 1st Floor Dressing Room (make 282 SF 7 10+ years up room) Ceiling - Splined 522 1st Floor Dressing Room (make 2 SF 4 0-1 year Missing. up room)



Catego	ry : Room		В	uildina	: Linked		letic Building B
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	522 1st Floor Dressing Room (make up room)	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	522 1st Floor Dressing Room (make up room)	2	EA	7	10+ years	
	Floor - Tile	522 1st Floor Dressing Room (make up room)	284	SF	6	10+ years	
	Lighting - Pendent/Surface	522 1st Floor Dressing Room (make up room)	3	EA	7	6-10 years	
	Lighting - Wall Mounted	522 1st Floor Dressing Room (make up room)	82	EA	7	6-10 years	
	Power Distribution	522 1st Floor Dressing Room (make up room)	16	EA	7	10+ years	
	Walls - Concrete Block	522 1st Floor Dressing Room (make up room)	612	SF	6	10+ years	
	Work SInk	522 1st Floor Dressing Room (make up room)	1	EA	7	10+ years	
	Ceiling - Splined	525 Shop Office	150	SF	6	10+ years	
	Ceiling - Splined	525 Shop Office	20	SF	4	0-1 year	Missing/Loose
	Doors - Steel Doors incl hw	525 Shop Office	1	ĒA	6	10+ years	
	Doors - Transom Window	525 Shop Office	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	525 Shop Office	1	EA	6	10+ years	
	Floor - Tile	525 Shop Office	170	SF	6	10+ years	
	Lighting - Lay-in	525 Shop Office	3	EA	7	6-10 years	
	Power Distribution	525 Shop Office	6	EA	7	10+ years	
	Walls - Concrete Block	525 Shop Office	300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	542C Pool Office	135	SF	6	10+ years	
	Doors - Steel Doors incl hw	542C Pool Office	135	EA	6	10+ years	
	Doors - Wood Doors inclu hw	542C Pool Office	1	EA	6	-	
				SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	542C Pool Office	135	-	6	10+ years	
	Lighting - Lay-in	542C Pool Office	4	EA	6	6-10 years	
	Power Distribution	542C Pool Office	6	EA	7	10+ years	
	Walls - Concrete Block	542C Pool Office	430	SF	6	10+ years	•••
	Ceiling - Splined	601 Control Room (in Auditorium)	190	SF	4	0-1 year	Missing throughout.
	Doors - Side-lite	601 Control Room (in Auditorium)	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	601 Control Room (in Auditorium)	1	EA	6	10+ years	
	Floor - Carpet	601 Control Room (in Auditorium)	190	SF	5	6-10 years	
	Lighting - Pendent/Surface	601 Control Room (in Auditorium)	4	EA	6	6-10 years	
	Power Distribution	601 Control Room (in Auditorium)	8	EA	6	10+ years	
	Walls - Concrete Block	601 Control Room (in Auditorium)	410	SF	6	10+ years	
	Ceiling - Splined	602 Spots in Auditorium	68	SF	6	10+ years	
	Ceiling - Splined	602 Spots in Auditorium	2	SF	4	0-1 year	Damaged.
	Doors - Side-lite	602 Spots in Auditorium	40	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	602 Spots in Auditorium	1	EA	6	10+ years	
	Floor - Carpet	602 Spots in Auditorium	70	SF	6	6-10 years	



Group

Category : Room Building : Linked Addition-Athletic Building B Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 602 Spots in Auditorium 2 ΕA 6-10 vears 6 Power Distribution 2 ΕA 7 602 Spots in Auditorium 10+ years Walls - Concrete Block 602 Spots in Auditorium 208 SF 6 10+ years 70 SF Ceiling - Splined 603 Spots in Auditorium 4 0-1 year Missing throughout. SF 7 Doors - Side-lite 603 Spots in Auditorium 40 10+ years Doors - Wood Doors inclu hw 603 Spots in Auditorium 1 EΑ 6 10+ years Floor - Carpet 603 Spots in Auditorium 70 SF 6 6-10 years Lighting - Pendent/Surface 603 Spots in Auditorium 2 EΑ 6 6-10 years Power Distribution 603 Spots in Auditorium 2 EΑ 7 10+ years SF Walls - Concrete Block 603 Spots in Auditorium 208 6 10+ vears Ceiling - Lav-in SF 611 Teacher's Office 327 7 10+ vears Doors - Wood Doors inclu hw 611 Teacher's Office 2 ΕA 7 10+ years Floor - Tile 327 SF 6 10+ years 611 Teacher's Office 7 Lighting - Lay-in ΕA 611 Teacher's Office 2 6-10 years **Power Distribution** 8 ΕA 7 611 Teacher's Office 10+ years Storage/ Closet 35 SF 5 611 Teacher's Office 10+ years Walls - Concrete Block SF 7 611 Teacher's Office 736 10+ years SF Ceiling - Splined 616 Music Office 290 6 10+ years Doors - Side-lite SF 616 Music Office 84 6 10+ vears SF Doors - Transom Window 616 Music Office 6 6 10+ years Doors - Wood Doors inclu hw 616 Music Office 1 ΕA 6 10+ years SF 7 Floor - Carpet 616 Music Office 290 6-10 years ΕA 7 Lighting - Lay-in 616 Music Office 6 6-10 years 7 Power Distribution 616 Music Office 6 FΑ 10+ years Walls - Concrete Block 350 SF 7 616 Music Office 10+ years SF Walls - Masonry 616 Music Office 190 7 10+ vears SF Ceiling - Splined 616B - Practice Room 117 7 10+ years Ceiling - Splined SF 0-1 year 616B - Practice Room 3 4 Broken tiles. Doors - Side-lite SF 616B - Practice Room 25 6 10+ years Doors - Wood Doors inclu hw 616B - Practice Room 1 ΕA 6 10+ years SF Floor - Carpet 120 5 2-5 years Stained needs to be cleaned. 616B - Practice Room Lighting - Lav-in 616B - Practice Room ΕA 7 6-10 vears 1 2 7 Power Distribution FΑ 10+ years 616B - Practice Room Walls - Concrete Block 276 SF 7 10+ years 616B - Practice Room

SF

SF

SF

EΑ

SF

ΕA

ΕA

SF

SF

SF

63

12

25

1

75

2

2

2

208

703

7

4

6

7

7

7

7

7

6

4

10+ years

0-1 year

10+ years

10+ years

6-10 years

6-10 years

10+ years

10+ vears

10+ years

0-1 year

Water damage.

Damaged.

Ceiling - Lay-in

Ceiling - Lay-in

Doors - Side-lite

Lighting - Lay-in

Power Distribution

Ceiling - Splined

Ceiling - Splined

Walls - Concrete Block

Floor - Carpet

Doors - Wood Doors inclu hw

616C/D- Practice Room

620 Art Office

620 Art Office



Catego	ry : Room	В	uilding	: Linked		etic Building B	
Ū	•			-		Recommend	<u> </u>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	620 Art Office	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	620 Art Office	1	EA	7	10+ years	
	Floor - Tile	620 Art Office	705	SF	6	10+ years	
	Lighting - Lay-in	620 Art Office	19	EA	7	6-10 years	
	Power Distribution	620 Art Office	8	EA	6	10+ years	
	Walls - Concrete Block	620 Art Office	1,010	SF	7	10+ years	
	Work SInk	620 Art Office	. 1	EA	5	10+ years	
	Ceiling - Plaster/Drywall	620A Art Office	88	SF	6	10+ years	
	Doors - Transom Window	620A Art Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	620A Art Office	1	ĒA	7	10+ years	
	Floor - Tile	620A Art Office	88	SF	6	10+ years	
	Lighting - Pendent/Surface	620A Art Office	1	ĒA	7	6-10 years	
	Walls - Concrete Block	620A Art Office	344	SF	7	10+ years	
	Ceiling - Splined	630 Office	287	SF	4	0-1 year	Dirty and separating throughout.
	Doors - Wood Doors inclu hw	630 Office	207	EA	7	10+ years	Dirty and opparating introdgrout.
	Floor - Tile	630 Office	287	SF	6	10+ years	
	Lighting - Pendent/Surface	630 Office	3	EA	6	6-10 years	
	Power Distribution	630 Office	2	EA	6	10+ years	
	Walls - Concrete Block	630 Office	540	SF	6	10+ years	
	Walls - Plaster/Drywall	630 Office	123	SF	7	10+ years	
	Ceiling - Splined	631 Office	570	SF	4	0-1 year	Dirty/separating throughout.
	Doors - Wood Doors inclu hw	631 Office	570	EA	4 7	10+ years	Dirty/separating throughout.
	Floor - Tile	631 Office	570	SF	6	10+ years	
	Lighting - Lay-in	631 Office	570	EA	7	6-10 years	
	Power Distribution	631 Office	12	EA	7	10+ years	
				SF			
	Walls - Concrete Block	631 Office 631 Office	1,017 204	SF	6 7	10+ years	
	Walls - Plaster/Drywall			SF		10+ years	
	Ceiling - Plaster/Drywall	634D	170		6	10+ years	
	Doors - Side-lite	634D	9	SF	7	10+ years	
	Doors - Steel Doors incl hw	634D	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	634D	170	SF	6	10+ years	
	Lighting - Pendent/Surface	634D	3	EA	6	6-10 years	
	Power Distribution	634D	2	EA	6	10+ years	
	Walls - Concrete Block	634D	525	SF	6	10+ years	
	Work Sink	634D	1	EA	5	6-10 years	
	AC Unit	638 - Copy Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	638 - Copy Room	287	SF	6	10+ years	
	Doors - Wood Doors inclu hw	638 - Copy Room	2	EA	6	10+ years	
	Floor - Tile	638 - Copy Room	287	SF	6	10+ years	
	Lighting - Pendent/Surface	638 - Copy Room	3	EA	6	6-10 years	
	Power Distribution	638 - Copy Room	2	EA	7	10+ years	
	Walls - Concrete Block	638 - Copy Room	440	SF	6	10+ years	
	Walls - Concrete Block	638 - Copy Room	100	SF	5	0-1 year	Cracking/loose.
	Walls - Plaster/Drywall	638 - Copy Room	123	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Linked	Addition-Athl	letic Building B
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	639 Office	562	SF	6	10+ years	
	Ceiling - Splined	639 Office	8	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	639 Office	1	EA	7	10+ years	
	Floor - Tile	639 Office	570	SF	6	10+ years	
	Lighting - Lay-in	639 Office	8	EA	7	6-10 years	
	Power Distribution	639 Office	12	EA	7	10+ years	
	Walls - Concrete Block	639 Office	1,000	SF	6	10+ years	
	Walls - Concrete Block	639 Office	· 17	SF	5	0-1 year	Loose/cracking.
	Walls - Plaster/Drywall	639 Office	204	SF	7	10+ years	3
	Ceiling - Plaster/Drywall	642D Office	175	SF	6	10+ years	
	Doors - Steel Doors incl hw	642D Office	1	EA	6	10+ years	
	Floor - Carpet	642D Office	25	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	642D Office	150	SF	6	10+ years	
	Lighting - Pendent/Surface	642D Office	3	EA	6	6-10 years	
	Power Distribution	642D Office	3 1	EA	6	•	
	Walls - Concrete Block	642D Office	550	SF	6 6	10+ years	
	Work Sink	642D Office	550	EA	7	10+ years	
	WORK SINK	842D Onice	I	EA	1	10+ years	
uditoriu	Im & Theater						
	Ceiling - Exposed	1st Floor	3,000	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8,000	SF	7	10+ years	
	Ceiling - Splined	1st Floor	496	SF	6	10+ years	
	Ceiling - Splined	1st Floor	4	SF	4	0-1 year	Loose and damaged tiles.
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	5
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Carpet	1st Floor	11,500	SF	4	0-1 year	Torn throughout.
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	. em an eugneen
	Lighting - Pendent/Surface	1st Floor	96	EA	5	6-10 years	
	Lighting - Wall Mounted	1st Floor	14	EA	6	6-10 years	
	Main Floor Seating	1st Floor	965	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	3,300	SF	5	10+ years	
	Stage Curtain	1st Floor	3,300 5	EA	5 5	6-10 years	
	Stage Lift		5 1	EA	5 5	10+ years	
		1st Floor	1				
	Stage Lighting System	1st Floor	-	EA	5	6-10 years	
	Stage-Stairs - Wood	1st Floor	30	LF	6	10+ years	
	Stairs - Tile	1st Floor	302	LF	6	10+ years	
	Stairs - Wood	1st Floor	100	LF	7	10+ years	
	Storage/ Closet	1st Floor	640	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,100	SF	6	10+ years	
	Walls - Masonry	1st Floor	8,000	SF	7	10+ years	
<u>/mnas</u>	ia						
	Bleacher Seating	1st Floor Boys Gym	1,430	EA	6	6-10 years	



Category : Room Building : Linked Addition-Athletic Building B Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Exposed 1st Floor Boys Gym 12.230 SF 10+ vears 6 Ceiling - Plaster/Drywall 1st Floor Boys Gym SF 6 24 10+ years Doors - Transom Window 1st Floor Boys Gym 32 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor Boys Gym 2 ΕA 7 10+ years Doors - Wood Doors inclu hw 1st Floor Boys Gym 4 ΕA 6 10+ years SF 1st Floor Boys Gym Floor - Wood 12,254 6 10+ years Lighting - Metal Halide/ High Pressure 1st Floor Boys Gym ΕA 6 6-10 years 48 Sodium Lighting - Pendent/Surface 1st Floor Boys Gym 6 EΑ 7 6-10 years 2 Scoreboards 1st Floor Boys Gym FΑ 7 6-10 years Quantity changed to match current observations Walls - Concrete Block 1st Floor Boys Gym 11,800 SF 6 10+ years Walls - Metal Panel 1st Floor Boys Gym SF 6 10+ years 2,100 SF 6 Ceiling - Exposed 1st Floor Girls Gym North 533A 4,560 10+ years Ceiling - Plaster/Drywall 1st Floor Girls Gym North 533A SF 7 12 10+ years Repaired. Doors - Steel Doors incl hw 1st Floor Girls Gym North 533A 2 EΑ 6 10+ years 6 SF 7 Doors - Transom Window 1st Floor Girls Gvm North 533A 10+ years SF Doors - Transom Window 1st Floor Girls Gym North 533A 20 6 10+ years 1st Floor Girls Gvm North 533A ΕA Doors - Wood Doors inclu hw 1 7 10+ vears 1st Floor Girls Gym North 533A Doors - Wood Doors inclu hw 2 EΑ 6 10+ years Floor - Wood 1st Floor Girls Gym North 533A 4.572 SF 6 10+ years 6 Lighting - Metal Halide/Sodium Vapor 1st Floor Girls Gym North 533A 15 EΑ 6-10 years 7 Lighting - Pendent/Surface 2 1st Floor Girls Gym North 533A EA 6-10 years 7 Scoreboards 1st Floor Girls Gym North 533A 1 FΑ 6-10 years Storage/ Closet 1st Floor Girls Gym North 533A SF 5 130 10+ years SF Storage/ Closet 1st Floor Girls Gvm North 533A 200 5 10+ vears Walls - Concrete Block SF 1st Floor Girls Gym North 533A 4,200 6 10+ years Walls - Metal Panel 1st Floor Girls Gym North 533A SF 7 160 10+ years Repaired. 1st Floor Girls Gym North 533A SF Walls - Metal Panel 1,070 6 10+ years Walls - Metal Panel 1st Floor Girls Gym North 533A 4,230 SF 6 10+ years SF Ceiling - Exposed 1st Floor Girls Gvm South 533B 4.560 6 10+ vears SF Ceiling - Plaster/Drvwall 1st Floor Girls Gvm South 533B 12 5 10+ vears Doors - Steel Doors incl hw 6 1st Floor Girls Gym South 533B 5 FΑ 10+ years Doors - Transom Window 1st Floor Girls Gvm South 533B 26 SF 6 10+ years 2 Doors - Wood Doors inclu hw 1st Floor Girls Gym South 533B EΑ 6 10+ years SF 6 Floor - Wood 1st Floor Girls Gym South 533B 4,572 10+ years Lighting - Metal Halide/Sodium Vapor 1st Floor Girls Gym South 533B 15 EΑ 6 6-10 years Lighting - Pendent/Surface 1st Floor Girls Gym South 533B 1 EA 6 6-10 years Scoreboards 1st Floor Girls Gym South 533B 1 EΑ 7 6-10 years SF Storage/ Closet 1st Floor Girls Gvm South 533B 200 5 10+ vears SF Storage/ Closet 1st Floor Girls Gym South 533B 130 5 10+ years 1st Floor Girls Gvm South 533B SF 6 Walls - Concrete Block 4.170 10+ vears Walls - Metal Panel 1st Floor Girls Gym South 533B 1,862 SF 6 10+ years Repaired. 1st Floor Girls Gym South 533B SF Walls - Metal Panel 722 6 10+ years



Category : Room		В	Building : Linked Addition-Athletic Building B						
_				_		Recommend	-		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	540 Wrestling Gym	2,679	SF	6	10+ years			
	Doors - Wood Doors inclu hw	540 Wrestling Gym	2	EA	7	10+ years			
	Floor - Weight/ Fitness Room Floor Matting	540 Wrestling Gym	2,679	SF	6	10+ years			
	Lighting - Lay-in	540 Wrestling Gym	50	EA	6	6-10 years			
	Storage/ Closet	540 Wrestling Gym	117	SF	5	10+ years			
	Walls - Concrete Block	540 Wrestling Gym	2,800	SF	6	10+ years			
ocker/S	Shower Room								
	Accessories	2nd Floor 642	881	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor 642	881	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor 642	2	EA	6	10+ years			
	Floor - Concrete	2nd Floor 642	530	SF	7				
				SF		10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor 642	351		6	10+ years			
	Floor Drain	2nd Floor 642	3	EA	7	10+ years			
	Lavatory	2nd Floor 642	2	EA	5	10+ years			
	Lighting - Pendent/Surface	2nd Floor 642	8	EA	6	6-10 years			
	Partitions	2nd Floor 642	1	EA	7	10+ years			
	Showers	2nd Floor 642	4	EA	5	10+ years			
	Storage/ Closet	2nd Floor 642	108	SF	7	10+ years			
	Student Lockers - One Tier	2nd Floor 642	71	EA	6	10+ years			
	Urinals	2nd Floor 642	1	EA	5	10+ years			
	Walls - Concrete Block	2nd Floor 642	691	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor 642	598	SF	6	10+ years			
	Water Closet	2nd Floor 642	1	EA	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor 636	248	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor 636	1	ĒA	6	10+ years			
	Floor - Concrete	2nd Floor 636	. 248	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor 636	4	EA	6	6-10 years			
	Student Lockers - Two Tier	2nd Floor 636	64	EA	5	10+ years			
	Walls - Concrete Block	2nd Floor 636	476	SF	6	10+ years			
	Accessories	2nd Floor Boys 634	3,781	SF	7	6-10 years			
				LF		•			
	Benches, ped mounted	2nd Floor Boys 634	80		6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor Boys 634	3,781	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor Boys 634	4	EA	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor Boys 634	2	EA	6	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor Boys 634	2,398	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys 634	1,383	SF	6	10+ years			
	Floor Drain	2nd Floor Boys 634	24	EA	7	10+ years			
	Hand Dryer	2nd Floor Boys 634	12	EA	7	6-10 years			
	Lavatory	2nd Floor Boys 634	3	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor Boys 634	51	EA	6	6-10 years			
	Partitions	2nd Floor Boys 634	2	EA	7	10+ years	Quantity changed to match current observations		
	Partitions	2nd Floor Boys 634	1	EA	4	0-1 year	Broken door		



Catego	ry : Room		Building : Linked Addition-Athletic Building B					
5	-			Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Showers	2nd Floor Boys 634	26	EA	5	10+ years		
	Storage/ Closet	2nd Floor Boys 634	54	SF	7	10+ years		
	Student Lockers - One Tier	2nd Floor Boys 634	28	EA	6	10+ years		
	Student Lockers - Two Tier	2nd Floor Boys 634	750	EA	6	10+ years		
	Urinals	2nd Floor Boys 634	2	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor Boys 634	1,305	SF	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor Boys 634	1,902	SF	6	10+ years		
	Water Closet	2nd Floor Boys 634	3	EA	6	10+ years		
	Accessories	538A Accessible Locker Room	251	SF	7	6-10 years		
	Benches, ped mounted	538A Accessible Locker Room	4	LF	6	10+ years		
	Ceiling - Plaster/Drywall	538A Accessible Locker Room	251	SF	6	10+ years		
	Doors - Wood Doors inclu hw	538A Accessible Locker Room	2	ĒA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	538A Accessible Locker Room	251	SF	6	10+ years		
	Floor Drain	538A Accessible Locker Room	2	ĒA	7	10+ years		
	Hand Dryer	538A Accessible Locker Room	1	EA	7	6-10 years		
	Lavatory	538A Accessible Locker Room	1	EA	6	10+ years		
	Lighting - Lay-in	538A Accessible Locker Room	4	EA	6	6-10 years		
	Lighting - Pendent/Surface	538A Accessible Locker Room	2	EA	6	6-10 years		
	Showers	538A Accessible Locker Room	1	EA	7	10+ years		
	Student Lockers - One Tier	538A Accessible Locker Room	4	EA	6	10+ years		
	Walls - Structural Glazed Tile	538A Accessible Locker Room	930	SF	6	10+ years		
	Water Closet	538A Accessible Locker Room	1	EA	6	10+ years		
	Accessories	539B Accessible Locker Room	251	SF	7	6-10 years		
	Benches, ped mounted	539B Accessible Locker Room	4	LF	7	10+ years		
	Ceiling - Plaster/Drywall	539B Accessible Locker Room	251	SF	7	10+ years		
	Doors - Wood Doors inclu hw	539B Accessible Locker Room	201	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	539B Accessible Locker Room	251	SF	7	10+ years		
	Floor Drain	539B Accessible Locker Room	231	EA	7	10+ years		
	Hand Dryer	539B Accessible Locker Room	1	EA	7	10+ years		
	Lavatory	539B Accessible Locker Room	1	EA	7	10+ years		
	Lighting - Lay-in	539B Accessible Locker Room	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	539B Accessible Locker Room	2	EA	7	6-10 years		
	Showers	539B Accessible Locker Room	1	EA	7	10+ years		
	Student Lockers - One Tier	539B Accessible Locker Room	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	539B Accessible Locker Room	930	SF	7	10+ years		
	Walls - Structural Glazed The Water Closet	539B Accessible Locker Room	930	EA	7	10+ years		
	Accessories	637	240	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	637		SF	5 6			
	Doors - Wood Doors inclu hw	637	240 1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	637	240	SF	7	10+ years		
		637		EA	6	10+ years		
	Lavatory		1		-	10+ years		
	Lighting - Pendent/Surface	637 637	8 1	EA EA	6	6-10 years		
	Partitions	637	1	EA	7 7	10+ years		
	Showers	037	2	EA	1	10+ years		



Catego	ry : Room	Building : Linked Addition-Athletic Building B					
2						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	637	55	EA	6	10+ years	
	Urinals	637	1	EA	6	10+ years	
	Walls - Concrete Block	637	475	SF	6	10+ years	
	Water Closet	637	1	EA	6	10+ years	
	Accessories	646 Girls Locker Room	400	SF	7	6-10 years	
	Benches, ped mounted	646 Girls Locker Room	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	646 Girls Locker Room	3,781	SF	6	10+ years	
	Doors - Steel Doors incl hw	646 Girls Locker Room	4	EA	6	10+ years	
	Doors - Wood Doors inclu hw	646 Girls Locker Room	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	646 Girls Locker Room	2,398	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	646 Girls Locker Room	1,383	SF	6	10+ years	
	Floor Drain	646 Girls Locker Room	24	EA	7	10+ years	
	Hand Dryer	646 Girls Locker Room	12	EA	7	6-10 years	
	Lavatory	646 Girls Locker Room	4	EA	6	10+ years	
	Lighting - Pendent/Surface	646 Girls Locker Room	51	EA	6	6-10 years	
	Partitions	646 Girls Locker Room	5	EA	7	10+ years	
	Showers	646 Girls Locker Room	26	EA	5	10+ years	
	Storage/ Closet	646 Girls Locker Room	54	SF	7	10+ years	
	Student Lockers - One Tier	646 Girls Locker Room	8	EA	6	10+ years	
	Student Lockers - Two Tier	646 Girls Locker Room	734	EA	6	10+ years	
	Walls - Concrete Block	646 Girls Locker Room	1,305	SF	6	10+ years	
	Walls - Structural Glazed Tile	646 Girls Locker Room	1,902	SF	6	10+ years	
	Water Closet	646 Girls Locker Room	5	EA	6	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	180	SF	7	10+ years	531A
	Janitor's Closet	1st Floor	180	SF	5	10+ years	00111
	Mechanical/ Service Rooms	1st Floor	300	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	244	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	80	SF	5	10+ years	530A
	Mechanical/ Service Rooms	1st Floor	81	SF	5	10+ years	526B
	Mechanical/ Service Rooms	1st Floor	65	SF	5	10+ years	Elevator equipment room 526C
	Storage Room	1st Floor	125	SF	7	10+ years	
	Storage Room	1st Floor	358	SF	7	10+ years	524
	Storage Room	1st Floor	160	SF	7	10+ years	
	Storage Room	1st Floor	200	SF	7	10+ years	
	Storage Room	1st Floor	232	SF	7	10+ years	
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	
	Janitor's Closet	2nd Floor	28	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	150	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	110	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	200	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	200	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	300	SF	7	10+ years	
						-	



Category : Room Building : Linked Addition-Athletic Building B Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Mechanical/ Service Rooms 2nd Floor 90 SF 10+ vears 7 2nd Floor 620 SF 7 Storage Room 10+ years Storage Room 2nd Floor 154 SF 7 10+ years Storage Room SF 7 2nd Floor 406 10+ years SF 7 Storage Room 2nd Floor 134 10+ years SF 5 Storage Room 2nd Floor 56 10+ years Holes in ceiling. Mechanical/ Service Rooms SF 5 According to the engineer, it's unsafe **Basement** 4,450 10+ years to enter without a chemical mask due to the chlorine level. SF Mechanical/ Service Rooms Penthouse 625 5 10+ years Pool & Natatorium 1st Floor 7.592 SF 7 6-10 years Accessories **Bleachers Seating/Plank Seating** 1st Floor 136 ΕA 6 10+ years 7.202 SF 6 Ceiling - Lav-in 1st Floor 10+ vears Ceiling - Plaster/Drywall 1st Floor 390 SF 6 10+ years ΕA Doors - Steel Doors incl hw 1st Floor 4 6 10+ years Floor - Concrete Epoxy/ Painted SF 7 1st Floor 7,592 10+ years ΕA 7 Lighting - Lay-in 1st Floor 6 6-10 years Lighting - Metal Halide/Sodium Vapor 19 ΕA 7 6-10 years 1st Floor Lighting - Wall Mounted 1st Floor 4 ΕA 7 6-10 years Pool Basin 1st Floor 3.451 SF 6 10+ vears SF Pool Deck 1st Floor 2.873 6 10+ years 1st Floor 24 ΕA 7 Pool Deck Drains 10+ vears Storage/ Closet 1st Floor 92 SF 7 10+ years Walls - Masonry 8,605 SF 6 1st Floor 10+ years Restroom Accessories 1st Floor NE Boys 355 SF 7 6-10 vears SF Ceiling - Plaster/Drywall 1st Floor NE Boys 355 6 10+ years Doors - Transom Window SF 6 1st Floor NE Boys 20 10+ years 2 ΕA Doors - Wood Doors inclu hw 1st Floor NE Boys 6 10+ years SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor NE Boys 355 10+ years Floor Drain 1st Floor NE Boys 1 EΑ 7 10+ years Hand Drver 1st Floor NE Boys 2 ΕA 7 6-10 years 1st Floor NE Boys 3 FΑ 6 10+ vears Lavatory Lighting - Lay-in 4 ΕA 7 1st Floor NE Boys 6-10 years Partitions 1st Floor NE Boys 3 FΑ 7 10+ years ΕA 6 Urinals 1st Floor NE Boys 4 10+ years SF 7 Walls - Structural Glazed Tile 1st Floor NE Boys 875 10+ years ΕA Water Closet 1st Floor NE Boys 3 6 10+ years 1st Floor NW Girls (by link) 385 SF 7 6-10 years Accessories

Ceiling - Plaster/Drywall

Doors - Transom Window

1st Floor NW Girls (by link)

1st Floor NW Girls (by link)

SF

SF

7

6

10+ years

10+ years

385

20



Group

Category : Room

Item - Type

Replacement Comments

Building : Linked Addition-Athletic Building B

Recommend

10+ years 10+ vears 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ vears 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years

10+ years

10+ years

6-10 years

Not in use

Doors - Wood Doors inclu hw 1st Floor NW Girls (by link) 2 ΕA 6 10+ vears Floor - Tile Ceramic/ Porcelain 1st Floor NW Girls (by link) 385 SF 6 10+ years Floor Drain 1st Floor NW Girls (by link) FΑ 7 10+ years 1 Hand Drver 2 ΕA 7 1st Floor NW Girls (by link) 6-10 years Quantity changed to match current observations Lavatory 1st Floor NW Girls (by link) 4 EΑ 6 10+ years Lighting - Lay-in 1st Floor NW Girls (by link) 5 ΕA 6 6-10 years 7 Partitions 1st Floor NW Girls (by link) ΕA 7 10+ years SF Walls - Structural Glazed Tile 1st Floor NW Girls (by link) 950 7 10+ years ΕA 7 Water Closet 1st Floor NW Girls (by link) 7 10+ years Accessories 1st Floor Pool Boys 70 SF 7 6-10 years Ceiling - Plaster/Drywall 1st Floor Pool Boys 70 SF 6 10+ years Doors - Side-lite 1st Floor Pool Boys SF 6 10+ years 1 SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor Pool Boys 60 10+ years Floor - Tile Ceramic/ Porcelain 1st Floor Pool Boys SF 10 4 0-1 year Missing. FΑ 7 Floor Drain 1st Floor Pool Boys 1 10+ years ΕA Lighting - Lay-in 1st Floor Pool Boys 1 6 6-10 years Partitions 1st Floor Pool Boys 1 ΕA 5 10+ years Urinals 1st Floor Pool Boys FΔ 6 1 10+ vears 10+ years 10+ years 10+ years 6-10 years 10+ years

Quantity

UOM

SF

ΕA

SF

6

7

4

750

175

3

Rank

Urinais	TSt Floor Pool Boys	1	EA	6	
Walls - Plaster/Drywall	1st Floor Pool Boys	9	SF	6	
Walls - Structural Glazed Tile	1st Floor Pool Boys	360	SF	6	
Water Closet	1st Floor Pool Boys	1	EA	6	
Accessories	1st Floor Pool Girls	70	SF	7	
Ceiling - Plaster/Drywall	1st Floor Pool Girls	70	SF	6	
Doors - Steel Doors incl hw	1st Floor Pool Girls	1	EA	6	
Floor - Tile Ceramic/ Porcelain	1st Floor Pool Girls	70	SF	6	
Floor Drain	1st Floor Pool Girls	1	EA	7	
Lighting - Lay-in	1st Floor Pool Girls	1	EA	6	
Partitions	1st Floor Pool Girls	2	EA	7	
Walls - Plaster/Drywall	1st Floor Pool Girls	9	SF	6	
Walls - Structural Glazed Tile	1st Floor Pool Girls	360	SF	6	
Water Closet	1st Floor Pool Girls	2	EA	6	
Accessories	1st Floor SE Girls	208	SF	7	
Ceiling - Plaster/Drywall	1st Floor SE Girls	208	SF	6	
Doors - Wood Doors inclu hw	1st Floor SE Girls	1	EA	6	
Floor - Tile Ceramic/ Porcelain	1st Floor SE Girls	208	SF	7	
Floor Drain	1st Floor SE Girls	1	EA	7	
Hand Dryer	1st Floor SE Girls	1	EA	7	
Lavatory	1st Floor SE Girls	3	EA	7	
Lighting - Lay-in	1st Floor SE Girls	3	EA	7	
Partitions	1st Floor SE Girls	3	EA	7	

1st Floor SE Girls

1st Floor SE Girls

1st Floor SW Boys (used as

Location

Water Closet

Accessories

Walls - Structural Glazed Tile



Catego	Category : Room Building : Linked Addition-Athletic Building B						
Jaleyo			D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	item Type	Storage)	Quantity	00111	Nank	Replacement	ooninients
	Ceiling - Plaster/Drywall	1st Floor SW Boys (used as	175	SF	6	10+ years	
		Storage)		•	•	, e , j e e	
	Doors - Wood Doors inclu hw	1st Floor SW Boys (used as	1	EA	6	10+ years	
		Storage)				2	
	Floor - Tile Ceramic/ Porcelain	1st Floor SW Boys (used as	175	SF	6	10+ years	
		Storage)					
	Lavatory	1st Floor SW Boys (used as	2	EA	6	10+ years	
		Storage)					
	Lighting - Lay-in	1st Floor SW Boys (used as	3	EA	6	6-10 years	
		Storage)	_		_		
	Partitions	1st Floor SW Boys (used as	2	EA	7	10+ years	
		Storage)				4.0	
	Urinals	1st Floor SW Boys (used as	2	EA	6	10+ years	
	Malla Structural Classed Tile	Storage)	C 40	05	7	10	
	Walls - Structural Glazed Tile	1st Floor SW Boys (used as	648	SF	7	10+ years	
	Water Closet	Storage) 1st Floor SW Boys (used as	2	EA	6	10	
	Water Closet	Storage)	2	EA	0	10+ years	
	Accessories	2nd Floor	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	190	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	190	SF	6	10+ years	
	Floor Drain	2nd Floor	190	EA	7		
						10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	3	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	360	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	20	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor NE Men	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor NE Men	190	SF	6	10+ years	
	Doors - Transom Window	2nd Floor NE Men	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor NE Men	20	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor NE Men	190	SF	6	10+ years	
	Floor Drain	2nd Floor NE Men	190	EA	7		
				EA	7	10+ years	
	Hand Dryer	2nd Floor NE Men	1			6-10 years	
	Lavatory	2nd Floor NE Men	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor NE Men	3	EA	6	6-10 years	
	Partitions	2nd Floor NE Men	2	EA	7	10+ years	
	Urinals	2nd Floor NE Men	3	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Linked	d Addition-Ath	letic Building B
-						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	2nd Floor NE Men	642	SF	6	10+ years	
	Water Closet	2nd Floor NE Men	2	EA	6	10+ years	
	Accessories	2nd Floor NE Women	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor NE Women	230	SF	6	10+ years	
	Doors - Transom Window	2nd Floor NE Women	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor NE Women	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor NE Women	230	SF	6	10+ years	
	Floor Drain	2nd Floor NE Women	1	EA	7	10+ years	
	Lavatory	2nd Floor NE Women	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor NE Women	3	EA	6	6-10 years	
	Partitions	2nd Floor NE Women	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor NE Women	926	SF	7	10+ years	
	Water Closet	2nd Floor NE Women	4	EA	7	10+ years	
	Accessories	2nd Floor NW Mens (609)	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor NW Mens (609)	190	SF	7	10+ years	
	Doors - Transom Window	2nd Floor NW Mens (609)	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor NW Mens (609)	1	EA	7	10+ years	
	Floor - Concrete	2nd Floor NW Mens (609)	190	SF	6	10+ years	
	Floor Drain	2nd Floor NW Mens (609)	1	EA	7	10+ years	
	Hand Dryer	2nd Floor NW Mens (609)	1	EA	7	6-10 years	
	Lavatory	2nd Floor NW Mens (609)	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor NW Mens (609)	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor NW Mens (609)	1	EA	5	0-1 year	Missing lens.
	Partitions	2nd Floor NW Mens (609)	1	EA	7	10+ years	3 3
	Urinals	2nd Floor NW Mens (609)	3	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor NW Mens (609)	750	SF	7	10+ years	
	Water Closet	2nd Floor NW Mens (609)	1	EA	7	10+ years	
	Accessories	2nd Floor NW Womens (610)	190	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor NW Womens (610)	190	SF	7	10+ years	
	Doors - Transom Window	2nd Floor NW Womens (610)	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor NW Womens (610)	1	ĒA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor NW Womens (610)	190	SF	6	10+ years	
	Floor Drain	2nd Floor NW Womens (610)	1	ĒA	7	10+ years	
	Hand Dryer	2nd Floor NW Womens (610)	1	EA	7	6-10 years	
	Lavatory	2nd Floor NW Womens (610)	3	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor NW Womens (610)	2	EA	7	6-10 years	
	Partitions	2nd Floor NW Womens (610)	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor NW Womens (610)	700	SF	7	10+ years	
	Water Closet	2nd Floor NW Womens (610)	2	ĒA	7	10+ years	
	Accessories	521 1st Floor Womens Dressing	350	SF	7	6-10 years	
		Room	200	•.	•	5.0,000	
	Ceiling - Plaster/Drywall	521 1st Floor Womens Dressing Room	136	SF	7	10+ years	
	Ceiling - Splined	521 1st Floor Womens Dressing	174	SF	6	6-10 years	



Group

Marie Sklodowska Curie Metropolitan High School 4959 S Archer AVENUE, Chicago, IL 60632

Category : Room Building : Linked Addition-Athletic Building B Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Room SF Ceiling - Splined 521 1st Floor Womens Dressing 40 Missing/broken 4 0-1 vear Room SF Doors - Transom Window 521 1st Floor Womens Dressing 10 7 10+ years Room Doors - Wood Doors inclu hw 521 1st Floor Womens Dressing ΕA 7 1 10+ years Room Floor - Tile 521 1st Floor Womens Dressing 214 SF 6 10+ years Room SF Floor - Tile Ceramic/ Porcelain 521 1st Floor Womens Dressing 136 7 10+ years Room Floor Drain 521 1st Floor Womens Dressing 1 ΕA 7 10+ years Room Lavatory 521 1st Floor Womens Dressing 1 EΑ 6 10+ years Room FΑ 7 Lighting - Lay-in 521 1st Floor Womens Dressing 5 6-10 years Room Partitions 521 1st Floor Womens Dressing 1 EΑ 7 10+ years Room Showers 521 1st Floor Womens Dressing 2 ΕA 7 10+ years Room Student Lockers - One Tier 521 1st Floor Womens Dressing 6 ΕA 7 10+ years Room SF Walls - Concrete Block 521 1st Floor Womens Dressing 640 6 10+ years Room Walls - Structural Glazed Tile 521 1st Floor Womens Dressing 520 SF 7 10+ years Room Water Closet 521 1st Floor Womens Dressing ΕA 1 7 10+ years Room Accessories 523 1st Floor Mens Dressing Room 360 SF 7 6-10 years SF Ceiling - Plaster/Drywall 523 1st Floor Mens Dressing Room 10+ vears 116 6 SF Ceiling - Splined 523 1st Floor Mens Dressing Room 224 6 6-10 vears SF Ceiling - Splined 523 1st Floor Mens Dressing Room 20 4 0-1 vear Missing/damage Doors - Transom Window 523 1st Floor Mens Dressing Room 10 SF 6 10+ years 6 Doors - Wood Doors inclu hw 523 1st Floor Mens Dressing Room 1 EΑ 10+ years 523 1st Floor Mens Dressing Room SF 6 Floor - Tile 244 10+ years SF Floor - Tile Ceramic/ Porcelain 523 1st Floor Mens Dressing Room 116 6 10+ years 523 1st Floor Mens Dressing Room ΕA 7 Floor Drain 1 10+ years Lavatory 523 1st Floor Mens Dressing Room 1 EΑ 6 10+ years Lighting - Lay-in 523 1st Floor Mens Dressing Room 5 ΕA 6 6-10 years Partitions 523 1st Floor Mens Dressing Room 1 ΕA 7 10+ years 2 FΑ 7 523 1st Floor Mens Dressing Room 10+ vears Showers Student Lockers - One Tier 523 1st Floor Mens Dressing Room 6 EΑ 7 10+ years SF Walls - Concrete Block 523 1st Floor Mens Dressing Room 640 6 10+ years



Category : Room				Building : Linked Addition-Athletic Building B					
				Recommend					
Group Ite	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
W	alls - Structural Glazed Tile	523 1st Floor Mens Dressing Room	520	SF	6	10+ years			
W	/ater Closet	523 1st Floor Mens Dressing Room	1	EA	6	10+ years			

Category : Classroom

Building : Linked Addition-Athletic Building B

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #508 Quin Hall (Dance Room)						
	Ceiling - Exposed	1st Floor	2,520	SF	6	10+ years	
	Ceiling - Splined	1st Floor	90	SF	6	10+ years	
	Doors - Transom Window	1st Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	8	EA	7	10+ years	
	Floor - Tile	1st Floor	90	SF	6	10+ years	
	Floor - Wood	1st Floor	2,520	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	40	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	300	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	940	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	5,290	SF	6	10+ years	
Classroo	m #510 (Band Room)						
	Ceiling - Splined	1st Floor	2,010	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Missing/Damage
	Doors - Side-lite	1st Floor	290	SF	6	10+ years	Glass along the corridor
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile	1st Floor	2,020	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	39	EA	6	6-10 years	
	Risers	1st Floor	138	LF	6	10+ years	
	Sound Panels	1st Floor	74	EA	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	26	EA	6	10+ years	
	Student Lockers - Three Tiers	1st Floor	2	EA	6	10+ years	
	Student Lockers - Two Tiers	1st Floor	62	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classree	m #514 (Band Baam)						
_Classf00	m #514 (Band Room)		0.000	05		10	
	Ceiling - Splined	1st Floor	2,020	SF	6	10+ years	Destau
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Broken
	Doors - Side-lite	1st Floor	290	SF	6	10+ years	Glass along the corridor
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile	1st Floor	2,030	SF	6	10+ years	



Catego	ry : Classroom		Building : Linked Addition-Athletic Building B					
				U		Recommend	U	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	31	EA	6	6-10 years		
	Risers	1st Floor	138	LF	6	10+ years		
	Sound Panels	1st Floor	158	EA	7	6-10 years		
	Storage/ Closet	1st Floor	380	SF	7	10+ years		
	Student Lockers - One Tier	1st Floor	11	EA	6	10+ years		
	Student Lockers - Three Tiers	1st Floor	51	EA	6	10+ years		
	Student Lockers - Two Tiers	1st Floor	22	EA	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,000	SF	6	10+ years		
Classroo	m #525 (Laboratory/Shop)							
	Casework	1st Floor	112	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	1,970	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	. 1	EA	6	10+ years		
	Doors - Transom Window	1st Floor	20	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years		
	Floor - Concrete	1st Floor	1,970	SF	5	10+ years		
	Lighting - Pendent/Surface	1st Floor	23	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	12	EA	5	0-1 year	Missing cover	
	Storage/ Closet	1st Floor	145	SF	5	10+ years		
	Storage/ Closet	1st Floor	370	SF	5	10+ years		
	Student Lockers - Two Tiers	1st Floor	48	EA	5	10+ years		
	Walls - Concrete Block	1st Floor	3,300	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	5	6-10 years	Quantity changed to match current observations	
Classroo	m #544 (Weight)							
	Ceiling - Plaster/Drywall	1st Floor	2,876	SF	6	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	2,876	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor	63	EA	5	0-1 year	Majority of lighting does not work.	
	Walls - Concrete Block	1st Floor	2,894	SF	7	10+ years		
Classroo	m #612 (Music Room)							
	Ceiling - Splined	2nd Floor	820	SF	6	6-10 years		
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	820	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years		



Catego	ry : Classroom	В	uilding	: Linked	d Addition-Ath	etic Building B	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #613 (Music Room)						
	Ceiling - Splined	2nd Floor	683	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	683	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Sound System	2nd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	890	SF	6	10+ years	
0							
Classroo	m #616 (Music Room)	and Floor	1.040	0	0	10	
	Ceiling - Splined	2nd Floor	1,640	SF SF	6	10+ years	
	Doors - Transom Window	2nd Floor	20		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA SF	6 6	10+ years	
	Floor - Wood	2nd Floor 2nd Floor	1,640	EA	6 7	10+ years	
	Lighting - Lay-in		26			6-10 years	
	Lighting - Lay-in	2nd Floor 2nd Floor	7	EA	6	6-10 years	Missing long
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	16	EA LF	5 7	0-1 year	Missing lens
	Sound Panels	2nd Floor 2nd Floor	83	EA	7	6-10 years	
						6-10 years	
	Sound System	2nd Floor	1	EA SF	7 7	6-10 years	
	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor	125 950	SF	7	10+ years	
	Walls - Flaster/Drywall		950	36	'	10+ years	
Classroo	m #619 (Art Room)						
	Ceiling - Lay-in	2nd Floor	775	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,125	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	224	SF	6	10+ years	
	Walls - Masonry	2nd Floor	270	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	620	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
	Work Sink	2nd Floor	1	EA	5	2-5 years	
_Classroo	m #621 (Art Room)						
	Ceiling - Lay-in	2nd Floor	600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	228	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	828	SF	6	10+ years	
			020	•	÷	,	



Category : Classroom			В	Building : Linked Addition-Athletic Building B						
-						Recommend	-			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years				
	Marker Board	2nd Floor	12	LF	7	6-10 years				
	Walls - Concrete Block	2nd Floor	308	SF	6	10+ years				
	Walls - Masonry	2nd Floor	230	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	380	SF	6	10+ years				
	Work Sink	2nd Floor	2	EA	5	6-10 years				
Classroc	om #627 (Art Room)									
	Casework	2nd Floor	40	LF	6	10+ years				
	Ceiling - Lay-in	2nd Floor	2,282	SF	7	10+ years	Newly replaced			
	Doors - Transom Window	2nd Floor	40	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	Quantity changed to match current			
		21011001	2	L/(Ū	for years	observations			
	Floor - Tile	2nd Floor	2,282	SF	6	10+ years				
	Kiln	2nd Floor	1	EA	7	10+ years				
	Lighting - Lay-in	2nd Floor	58	EA	7	6-10 years				
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years				
	Marker Board	2nd Floor	12	LF	6	6-10 years				
	Storage/ Closet	2nd Floor	154	SF	5	10+ years				
	Walls - Concrete Block	2nd Floor	2,300	SF	6	10+ years				
	Work Sink	2nd Floor	2,000	EA	5	6-10 years				
<u>.</u> .										
Classroc	om #629 (Art Room)									
	Ceiling - Lay-in	2nd Floor	775	SF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	7	10+ years				
	Doors - Transom Window	2nd Floor	20	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years				
	Floor - Tile	2nd Floor	1,125	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years				
	Marker Board	2nd Floor	12	LF	6	6-10 years				
	Walls - Concrete Block	2nd Floor	660	SF	6	10+ years				
	Walls - Masonry	2nd Floor	265	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	190	SF	6	10+ years				
	Work Sink	2nd Floor	2	EA	5	6-10 years				
Classroo	om #639 (Regular Classroom)									
	Ceiling - Lay-in	2nd Floor	750	SF	6	10+ years				
	Ceiling - Lay-in	2nd Floor	30	SF	4	0-1 year	Damaged/does not fit.			
	Chalk Board	2nd Floor	10	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	4 6	10+ years				
	Floor - Tile	2nd Floor	780	SF	6	10+ years				
		2nd Floor 2nd Floor	780 14	EA						
	Lighting - Lay-in			LF	6	6-10 years				
	Marker Board	2nd Floor	8	LF	7	6-10 years				



Catego	ry : Classroom	B	Building : Linked Addition-Athletic Building B				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	879	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	105	SF	6	10+ years	
Classroo	m #643 (Health)						
	Ceiling - Splined	2nd Floor	763	SF	6	6-10 years	
	Ceiling - Splined	2nd Floor	10	SF	4	0-1 year	Water damage.
	Chalk Board	2nd Floor	12	LF	4	2-5 years	-
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	773	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	879	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	105	SF	6	10+ years	

Category : Interior

Building : Linked Addition-Athletic Building B

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	16,179	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	120	SF	6	10+ years	
	Doors - Side-lite	1st Floor	82	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Store Front	1st Floor	20	EA	6	10+ years	
	Doors - Transom Window	1st Floor	80	SF	6	10+ years	
	Doors - Transom Window	1st Floor	200	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	7	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	7	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	3,585	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	12,594	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	265	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	6	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	110	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years	
	Walls - Masonry	1st Floor	16,030	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	4,900	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Doors - Store Front	2nd Floor	2	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	26	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	44	SF	6	10+ years	



Catego	itegory : Interior			Building : Linked Addition-Athletic Building B						
outogo				anang	. בוווונסט	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors include hw	2nd Floor	11	EA	7	10+ years				
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	10+ years				
	Doors - Wood Doors include hw	2nd Floor	1	EA	6	10+ years				
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	10+ years				
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years				
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	4	0-1 year	Missing.			
	Floor - Tile/Sheet	2nd Floor	3,889	SF	5	10+ years	5			
	Floor - Tile/Sheet	2nd Floor	1,011	SF	4	0-1 year	Cracking/chipping.			
	Lighting - Lay-in	2nd Floor	75	EA	7	6-10 years	0 11 0			
	Walls - Concrete Block	2nd Floor	2,286	SF	6	10+ years				
	Walls - Masonry	2nd Floor	6,814	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	1,271	SF	7	10+ years				
	Ceiling - Splined	510 Corridor @ Practice Rooms	122	SF	6	6-10 years				
	Doors - Wood Doors include hw	510 Corridor @ Practice Rooms	2	EA	6	10+ years				
	Floor - Tile/Sheet	510 Corridor @ Practice Rooms	122	SF	5	6-10 years				
	Lighting - Lay-in	510 Corridor @ Practice Rooms	3	EA	7	6-10 years				
	Lighting - Pendent/Surface	510 Corridor @ Practice Rooms	1	EA	6	6-10 years				
	Walls - Concrete Block	510 Corridor @ Practice Rooms	60	SF	7	10+ years				
	Ceiling - Splined	514 Corridor @ Practice Rooms	114	SF	6	6-10 years				
	Ceiling - Splined	514 Corridor @ Practice Rooms	8	SF	4	0-1 year	Broken			
	Doors - Wood Doors include hw	514 Corridor @ Practice Rooms	2	ĒA	6	10+ years				
	Floor - Tile/Sheet	514 Corridor @ Practice Rooms	122	SF	5	6-10 years				
	Lighting - Lay-in	514 Corridor @ Practice Rooms	3	EA	7	6-10 years				
	Lighting - Pendent/Surface	514 Corridor @ Practice Rooms	1	EA	6	6-10 years				
	Walls - Concrete Block	514 Corridor @ Practice Rooms	60	SF	7	10+ years				
	Ceiling - Splined	514 North Vestibule	40	SF	4	0-1 year	Damaged throughout			
	Doors - Wood Doors include hw	514 North Vestibule	1	EA	6	10+ years	Changed to match current observations			
	Floor - Tile/Sheet	514 North Vestibule	40	SF	5	6-10 years				
	Lighting - Lay-in	514 North Vestibule	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	514 North Vestibule	132	SF	5	10+ years				
	Ceiling - Splined	616 South Vestibule	70	SF	6	10+ years				
	Ceiling - Splined	616 South Vestibule	5	SF	4	0-1 vear	Broken.			
	Doors - Transom Window	616 South Vestibule	6	SF	6	10+ years				
	Doors - Wood Doors include hw	616 South Vestibule	1	EA	7	10+ years				
	Doors - Wood Doors include hw	616 South Vestibule	2	EA	6	10+ years				
	Floor - Tile/Sheet	616 South Vestibule	75	SF	4	0-1 year	Cracking and chipping throughout.			
	Lighting - Lay-in	616 South Vestibule	1	ĒA	7	6-10 years	3 1 1 3 1 3			
	Walls - Concrete Block	616 South Vestibule	164	SF	7	10+ years				
	Ceiling - Splined	616 at Practice Rooms	124	SF	7	10+ years				
	Doors - Transom Window	616 at Practice Rooms	6	SF	6	10+ years				
	Doors - Wood Doors include hw	616 at Practice Rooms	2	EA	6	10+ years				
	Floor - Carpet	616 at Practice Rooms	124	SF	7	6-10 years				
	Lighting - Lay-in	616 at Practice Rooms	2	EA	7	6-10 years				



Catego	ry : Interior		Building : Linked Addition-Athletic Building B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Stairs - Concrete Stairs	616 at Practice Rooms	13	LF	7	10+ years		
	Walls - Concrete Block	616 at Practice Rooms	130	SF	7	10+ years		
afety								
uioty	Camera Viewing Station	1st Floor	1	EA	7	6-10 years		
	Metal Dedector	1st Floor	3	EA	7	6-10 years		
	Security Cameras	1st Floor	20	EA	5	6-10 years		
airs								
	Ceiling - Splined	East Locker Stairs	157	SF	6	10+ years		
	Ceiling - Splined	East Locker Stairs	34	SF	6	10+ years		
	Ceiling - Splined	East Locker Stairs	13	SF	4	0-1 year	Broken.	
	Floor - Terrazzo	East Locker Stairs	135	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	East Locker Stairs	71	SF	7	10+ years		
	Handrails	East Locker Stairs	70	LF	5	10+ years		
	Lighting - Lay-in	East Locker Stairs	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	East Locker Stairs	1	EA	7	6-10 years		
	Stairs - Terrazzo	East Locker Stairs	128	LF	7	10+ years		
	Walls - Masonry	East Locker Stairs	1,334	SF	7	10+ years		
	Ceiling - Lay-in	East Pool Stairs	242	SF	7	10+ years		
	Floor - Concrete	East Pool Stairs	70	SF	5	10+ years		
	Floor - Rubber Floor	East Pool Stairs	22	SF	6	10+ years		
	Handrails	East Pool Stairs	72	LF	5	10+ years		
	Lighting - Wall Mounted	East Pool Stairs	2	EA	7	6-10 years		
	Stairs - Concrete	East Pool Stairs	116	LF	6	10+ years		
	Stairs - Tile	East Pool Stairs	17	LF	7	10+ years		
	Walls - Masonry	East Pool Stairs	1,135	SF	7	10+ years		
	Ceiling - Lay-in	Northeast Fire Stair	286	SF	6	10+ years	Changed to match current	
	Colling Bloster/Drawoll	Northeast Fire Stair	170	SF	e	10	observations	
	Ceiling - Plaster/Drywall Floor - Terrazzo	Northeast Fire Stair	24	SF	6 7	10+ years 10+ years		
	Floor - Tile/Sheet	Northeast Fire Stair	24 342	SF	5			
				LF	5 5	6-10 years		
	Handrails	Northeast Fire Stair	68	EA	-	10+ years		
	Lighting - Lay-in Stairs - Terrazzo	Northeast Fire Stair	6		6	6-10 years		
		Northeast Fire Stair	102	LF	7	10+ years		
	Walls - Masonry	Northeast Fire Stair	1,621	SF	7	10+ years		
	Ceiling - Splined	Northeast Stair - Central Stairs	187	SF	6	10+ years		
	Floor - Terrazzo	Northeast Stair - Central Stairs	40	SF	7	10+ years		
	Handrails	Northeast Stair - Central Stairs	69	LF	7	10+ years		
	Handrails	Northeast Stair - Central Stairs	28	LF	5	2-5 years		
	Lighting - Lay-in	Northeast Stair - Central Stairs	4	EA	7	6-10 years		
	Stairs - Terrazzo	Northeast Stair - Central Stairs	160	LF	7	10+ years		
	Walls - Masonry	Northeast Stair - Central Stairs	994	SF	7	10+ years		
	Ceiling - Lay-in	Northwest Fire Stair	286	SF	6	10+ years	Changed to match current	



Catego	ry : Interior		Building : Linked Addition-Athletic Building B					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
							observations	
	Floor - Terrazzo	Northwest Fire Stair	24	SF	7	10+ years		
	Floor - Tile/Sheet	Northwest Fire Stair	342	SF	5	6-10 years		
	Handrails	Northwest Fire Stair	68	LF	5	10+ years		
	Lighting - Lay-in	Northwest Fire Stair	6	EA	7	6-10 years		
	Stairs - Terrazzo	Northwest Fire Stair	102	LF	7	10+ years		
	Walls - Masonry	Northwest Fire Stair	1,621	SF	7	10+ years		
	Walls - Plaster/Drywall	Northwest Fire Stair	104	SF	7	10+ years		
	Ceiling - Splined	Northwest Stair - Central Stairs	187	SF	4	0-1 year	Dirty and broken.	
	Floor - Terrazzo	Northwest Stair - Central Stairs	52	SF	5	10+ years		
	Handrails	Northwest Stair - Central Stairs	69	LF	7	10+ years		
	Handrails	Northwest Stair - Central Stairs	38	LF	5	0-1 year	Rusting.	
	Lighting - Lay-in	Northwest Stair - Central Stairs	4	EA	7	6-10 years		
	Stairs - Terrazzo	Northwest Stair - Central Stairs	160	LF	7	10+ years		
	Walls - Masonry	Northwest Stair - Central Stairs	994	SF	7	10+ years		
	Ceiling - Splined	Southeast Core Stairs	187	SF	4	0-1 year	Dirty and broken throughout.	
	Floor - Terrazzo	Southeast Core Stairs	40	SF	6	10+ years		
	Handrails	Southeast Core Stairs	69	LF	7	10+ years		
	Handrails	Southeast Core Stairs	38	LF	5	10+ years		
	Lighting - Lay-in	Southeast Core Stairs	3	EA	7	6-10 years		
	Stairs - Terrazzo	Southeast Core Stairs	160	LF	7	10+ years		
	Walls - Masonry	Southeast Core Stairs	994	SF	7	10+ years		
	Ceiling - Splined	Southwest Stairs - Core Stairs	187	SF	4	0-1 year	Chipping throughout.	
	Floor - Terrazzo	Southwest Stairs - Core Stairs	40	SF	4	0-1 year	Cracking.	
	Handrails	Southwest Stairs - Core Stairs	69	LF	7	10+ years		
	Handrails	Southwest Stairs - Core Stairs	38	LF	5	2-5 years		
	Lighting - Lay-in	Southwest Stairs - Core Stairs	3	EA	7	6-10 years		
	Stairs - Terrazzo	Southwest Stairs - Core Stairs	160	LF	7	10+ years		
	Walls - Masonry	Southwest Stairs - Core Stairs	994	SF	7	10+ years		
	Ceiling - Plaster/Drywall	West Locker Stairs	6	SF	6	10+ years		
	Ceiling - Splined	West Locker Stairs	182	SF	6	10+ years		
	Ceiling - Splined	West Locker Stairs	17	SF	4	0-1 year	Chipped.	
	Floor - Terrazzo	West Locker Stairs	121	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	West Locker Stairs	151	SF	7	10+ years		
	Handrails	West Locker Stairs	70	LF	5	10+ years		
	Lighting - Lay-in	West Locker Stairs	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	West Locker Stairs	1	EA	7	6-10 years		
	Stairs - Terrazzo	West Locker Stairs	128	LF	7	10+ years		
	Walls - Masonry	West Locker Stairs	1,334	SF	7	10+ years		
	Ceiling - Lay-in	West Pool Stairs	238	SF	7	10+ years		
	Ceiling - Lay-in	West Pool Stairs	4	SF	4	0-1 year	Water damage.	
	Floor - Concrete	West Pool Stairs	70	SF	5	0-1 year	Cracking.	
	Floor - Rubber Floor	West Pool Stairs	22	SF	6	10+ years		
	Handrails	West Pool Stairs	72	LF	5	10+ years		



Building : Linked Addition-Athletic Building B Category : Interior Recommend Group Item - Type Quantity UOM Location Rank **Replacement** Comments Lighting - Wall Mounted 6-10 years West Pool Stairs 2 ΕA 7 Stairs - Concrete West Pool Stairs 116 LF 6 10+ years LF 7 10+ years Stairs - Tile West Pool Stairs 17 Walls - Masonry West Pool Stairs 1,135 SF 7 10+ years Vertical Conveyance Elevator - Hydraulic Elevator Flooring cracking. 1st Floor 1 ΕA 6 10+ years



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Athletic SF Surface - Asphalt East 4 Nets missing, courts need to be 29,484 0-1 year resealed and striped. Lighting Northeast 8 EΑ 6 6-10 years Surface - Natural Northeast 57,150 SF 6 10+ years SF Surface - Concrete Northeast 7,300 6 10+ years 63,852 SF Surface - Natural Northeast 6 10+ years Civil/Drainage Civil/ Drainage - Catch Basin Entire Site 19 ΕA 6 10+ years Civil/ Drainage - Catch Basin Entire Site 2 ΕA 4 0-1 year Sinking Civil/ Drainage - Site Drain **Entire Site** 5 ΕA 6 10+ years Civil/ Drainage - Site Manhole Entire Site 18 ΕA 6 10+ years Fencing 1,794 Fencing - Chain Link Entire Site LF 6 10+ years Fencing - Chain Link Entire Site 3.639 LF 4 0-1 year Loose chain link and falling over. LF Fencing - Guard Rail Entire Site 209 6 10+ years LF Fencing - New Standard Ornamental Entire Site 1,389 6 10+ years Landscape Benches Entire Site 4 EΑ 6 6-10 years Entire Site SF 7 Landscape - Grass 205,413 10+ years Landscape - Hardscape- Concrete Entire Site 41,968 SF 10+ years 6 SF Landscape - Hardscape- Concrete Entire Site 4 0-1 year Cracking, holes, and minor sloping. 3.215 Parkway trees **Entire Site** 3 EΑ 7 10+ vears Parkway trees Entire Site 29 EΑ 7 10+ years Planting Beds/ Area Entire Site 4.896 SF 7 10+ vears Retaining Wall - Concrete Entire Site 1.055 SF 7 10+ years Retaining Wall - Concrete Entire Site 60 SF 5 0-1 year Top portion missing/falling off. **Trash Receptacles** Entire Site 9 EΑ 6 10+ years Parking Lot Concrete Curbs LF Parking Lot- North 2.777 6 10+ years Interior Plantings Parking Lot- North 8 LF 6 6-10 years Lighting - Pole Mounted 6-10 years Parking Lot- North 1 EΑ 6 Surface - Asphalt Parking Lot- North SF 0-1 year 143,641 4 Potholes, cracks LF Concrete Curbs Parking Lot- South 6 10+ years 250 Interior Plantings Parking Lot- South 20 LF 7 10+ vears Lighting - Pole Mounted Parking Lot- South 2 EΑ 6 6-10 years Surface - Asphalt Parking Lot- South SF 38.920 4 0-1 vear Large holes, cracks, spalling Trash Compactor Parking Lot- South EA 6 10+ years 1



Marie Sklodowska Curie Metropolitan High School

4959 S Archer AVENUE, Chicago, IL 60632

Catego	ry : Site	В	uilding	: Site			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Service	Garage						
	Service Garage - Free-Standing Service Garage - Free-Standing	East Drivers ED East Service Garage	1 1	SF SF	4 7	0-1 year 10+ years	Damaged railings, siding
Sidewall	(S						
	Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site Entire Site	400 24,502 500	LF SF SF	6 6 4	10+ years 10+ years 0-1 year	Cracking.
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	5	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main-Building A			- i	i	1	ł	i	ł	i
Autoshop	Laboratory/Shop	1st Floor	166 Automotive	166	3,960	195	0	N	N
Computer Lab	Computer Lab	1st Floor	148 DigitalDsgn	148	2,234	0	0	N	Ν
Computer Lab	Computer Lab	3rd Floor	336	336	1,020	0	0	N	Y
Computer Lab	Computer Lab	3rd Floor	336A	336A	1,521	0	0	N	N
Computer Lab	Computer Lab	3rd Floor	337	337	960	0	0	N	N
Computer Lab	Computer Lab	3rd Floor	338	338	986	0	0	N	Ν
Computer Lab	Computer Lab	3rd Floor	339	339	686	0	0	N	N
Computer Lab	Computer Lab	3rd Floor	341	341	850	0	0	N	Y
Computer Lab	Computer Lab	3rd Floor	343	343	1,496	0	0	N	Y
Computer Lab	Laboratory/Shop	1st Floor	143 Web Design	143	2,052	0	0	N	N
Computer Lab	Other Instructional Use	1st Floor	152 Comp/Elec	152/153	1,451	0	0	N	N
Computer Lab	Other Instructional Use	1st Floor	162	162	1,234	104	0	N	N
Computer Lab	Other Instructional Use	1st Floor	165 TV Studio	165	1,641	0	0	N	N
Computer Lab	Other Instructional Use	2nd Floor	270	270	1,500	312	0	N	Y
Computer Lab	Regular Classroom	2nd Floor	261	261	1,170	264	0	N	N
Computer Lab	Regular Classroom	3rd Floor	380	380	900	144	0	N	Y
Culinary	Regular Classroom	3rd Floor	381	381	2,000	165	0	N	N
Faculty Lounge	Laboratory/Shop	1st Floor	164 Metal	164	2,817	104	0	N	N
Health	Other Instructional Use	1st Floor	167	167	954	130	0	N	Y
Health	Other Instructional Use	1st Floor	168	168	974	130	0	N	Y
Laboratory/Shop	Laboratory/Shop	1st Floor	150 Photograph y	150	734	0	0	N	N
Laboratory/Shop	Laboratory/Shop	1st Floor	163 Woodworki ng	163	2,914	117	0	N	N
Music Room	Regular Classroom	2nd Floor	233	233	1,140	147	0	N	Y
Pre School	Special Program	1st Floor	159	159	1,627	166	0	N	Ν
Regular Classroom	Computer Lab	2nd Floor	235E	235E	951	0	0	N	Ν
Regular Classroom	Computer Lab	3rd Floor	375	375	722	0	0	N	Ν
Regular Classroom	Laboratory/Shop	1st Floor	144 Elect Lab	144 (partial)	1,225	0	0	N	Y
Regular Classroom	Other Instructional Use	1st Floor	145	146	1,002	0	0	N	N
Regular Classroom	Other Instructional Use	1st Floor	160	160	1,434	156	0	N	N



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Other Instructional Use	1st Floor	161	161	1,453	156	0	N	N
Regular Classroom	Other Instructional Use	3rd Floor	335A	335A	686	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	146	147	632	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	147	145	793	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	232	232	750	168	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	241	241	1,384	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	243	243	738	216	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	244	244	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	245	245	738	120	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	248	248	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	249	249	738	120	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	250	250	400	0	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	252	252	400	0	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	253	253	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	254	254	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	255	255	600	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	257	257	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	258	258	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	259	259	600	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	260	260	738	120	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	262	262	738	120	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	263	263	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	264	264	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	265	265	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	266	266	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	267	267	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	268	268	738	120	0	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	269	269	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	271	271	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	272	272	600	300	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	274	274	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	275	275	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	277	277	687	320	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	279	279	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	280	280	738	120	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	282	282	687	0	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	284	284	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	285	285	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	285	285	687	87	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	288	288	738	120	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	289	289	696	120	0	N	N
Regular Classicolli			209	209	090	120	U	IN	IN



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	290	290	738	216	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	334/335	334	2,716	0	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	362	362	500	96	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	364	364	750	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	365	365	725	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	366	366	750	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	367	367	750	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	368	368	750	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	369	369	960	240	0	N	Y
Regular Classroom	Regular Classroom	3rd Floor	371	371	960	103	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	374	374	696	120	0	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	377	377	696	120	0	N	Y
Regular Classroom	Regular Classroom	3rd Floor	378	378	725	120	0	N	Y
Regular Classroom	Regular Classroom	3rd Floor	379	379	580	0	0	N	Ν
Regular Classroom	Science Lab Level 2	3rd Floor	351	351	625	120	0	N	N
Regular Classroom	Store Room	3rd Floor	373	373	400	0	0	N	Y
Science Classroom	Computer Lab	3rd Floor	332	332	1,326	168	0	N	Y
Science Lab Level 1	Regular Classroom	3rd Floor	360	360	900	144	0	N	Y
Science Lab Level 1	Science Lab Level 2	3rd Floor	349	349	1,234	120	0	N	Ν
Science Lab Level 1	Science Lab Level 2	3rd Floor	350	350	888	120	0	N	Ν
Science Lab Level 1	Science Lab Level 2	3rd Floor	353	353	950	120	0	N	Y
Science Lab Level 1	Science Lab Level 2	3rd Floor	354	354	888	126	0	N	Ν
Science Lab Level 2	Science Lab Level 2	3rd Floor	340	340	1,250	0	0	N	Y
Science Lab Level 2	Science Lab Level 2	3rd Floor	346	346	1,110	168	0	N	N
Science Lab Level 2	Science Lab Level 2	3rd Floor	347	357	600	210	0	N	Y
Science Lab Level 2	Science Lab Level 2	3rd Floor	361	361	900	144	0	N	Ν
Science Lab Level 2	Science Lab Level 2	3rd Floor	363	363	900	144	0	N	Ν
Science Lab Level 3	Regular Classroom	3rd Floor	383	383	986	240	0	N	Y
Science Lab Level 3	Science Lab Level 3	3rd Floor	355	355	1,850	120	0	N	Y
Special Education	Special Education	3rd Floor	370	370	350	72	0	N	Ν
Store Room	Other Instructional Use	3rd Floor	381B	NA	279	72	0	N	Ν

Building : Linked Add	lition-Athletic Building B								
Art Room	Art Room	2nd Floor	619	619	1,125	400	0	N	N
Art Room	Art Room	2nd Floor	621	621	828	276	0	N	Y
Art Room	Art Room	2nd Floor	627	627	2,282	252	0	N	Y
Art Room	Art Room	2nd Floor	629	629	1,125	400	0	N	Y
Band Room	Band Room	1st Floor	510	510	2,020	0	0	N	N
Band Room	Band Room	1st Floor	514	514	2,030	0	0	N	N
Dance Room	Dance Room	1st Floor	508 Quin	508	2,610	0	0	N	N
			Hall						



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Health	Health	2nd Floor	643	643	773	0	0	N	N
Laboratory/Shop	Laboratory/Shop	1st Floor	525	525	1,970	0	0	N	N
Music Room	Music Room	2nd Floor	612	612	820	100	0	N	Y
Music Room	Music Room	2nd Floor	613	613	683	150	0	N	N
Music Room	Music Room	2nd Floor	616	616	1,640	25	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	639	639	780	0	0	N	N
Weight	Weight	1st Floor	544	544	2,876	0	0	N	N