

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1980	2	67,506
Campus Total			67,506

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 S	3	EA	6	6-10 years	
	Exterior Doors - Side lite	#1 S	5	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 S	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2 SW	2	EA	6	6-10 years	Door frames need to be recaulked
	Exterior Doors - Side lite	#2 SW	2	EA	6	6-10 years	One of the sidelights needs some welding
	Exterior Doors - Transom Lite	#2 SW	1	EA	6	6-10 years	Frames need to be recaulked
	Exterior Doors - Exterior Steel Door	#3 W	1	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Overhead Rolling/ Garage	#3.5 W	1	EA	5	1-2 years	Door frame needs to be adjusted
	Exterior Doors - Exterior Steel Door	#4 NW	2	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Side lite	#4 NW	2	EA	6	6-10 years	- F
	Exterior Doors - Transom Lite	#4 NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5 N	3	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Transom Lite	#5 N	18	EA	6	6-10 years	1 5
	Exterior Doors - Exterior Steel Door	#6 E	2	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Side lite	#6 E	2	EA	6	6-10 years	1 5
	Exterior Doors - Transom Lite	#6 E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 SE	1	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Transom Lite	#7 SE	6	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8 SE	1	EA	6	6-10 years	Opening needs to be recaulked
	Exterior Doors - Transom Lite	#8 SE	1	EA	6	6-10 years	-



ALM S			_				2040 W 62nd STREET, Chicago, IL 6063
Catego	ry : Exterior		В	uilding	: Main		
2	Here True	Leastion	Quantitu	UOM	Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oundati							
	Foundation - Concrete	Entire Building	758	LF	7	10+ years	
	Superstructure - Steel	Entire Building	67,506	SF	7	10+ years	
ighting							
• •	Exterior Lighting - Lighting	Entire Building	9	EA	7	10+ years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	10+ years	
Roof Sys	tem						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Coping - Metal	Main Roof	758	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	290	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	36,329	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	36,329	SF	7	10+ years	
	Concrete Topping		00,020	01	1	for years	
Valls							
	Exterior Walls - Brick	Entire Building	21,774	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	5	SF	4	0-1 year	Brick is cracked at the base of column
	Exterior Walls - Brick	Entire Building	3	SF	3	1-2 years	Large hole in wall
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	114	SF	6	6-10 years	
Vindows							
	Curtain wall - Windows	Entire Building	4,498	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	5,787	SF	7	10+ years	
	Lintels - Steel	Entire Building	1,023	LF	7	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	1,287	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Ū.				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	icy System						
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	4	1-2 years	Lighting dimmed.
	Exit Signs - Gym	Entire Building	2	EA	4	1-2 years	Lighting dimmed.
				— •			
	Exit Signs - Lunchroom Exit Signs - Multipurpose Room	Entire Building	2	EA EA	4	1-2 years	Lighting dimmed. Lighting dimmed.



							2040 W 62nd STREET, Chicago, IL 60636
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Corridors and Stairs	Entire Building	33	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,724	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,049	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,328	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,800	SF	6	6-10 years	
	Security System - CCTV	Entire Building	67,506	SF	6	6-10 years	System upgraded 2020
	Security System - Intrusion Detection	Entire Building	67,506	SF	6	6-10 years	System upgraded 2020
	Automatic Transfer Switch	Mechanical Room	1	EA	6	6-10 years	
Main Ser	vice						
	PA System	Entire Building	67,506	SF	6	6-10 years	
	Main Electrical Service - 2000 A 277/480/3PH	Mechanical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	10+ years	Installed 2020; serves fire pump.
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	0	EA	6	6-10 years	Removed from the building with radiant panels
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	1-2 years	Missing breakers exposed live parts
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	5	2-5 years	Slightly dented
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Aları	m						
	Fire Alarm Panel	Elevator Equipment Room, Pump Room	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Elevator Equipment Room, Pump Room	67,506	SF	7	6-10 years	Installed 2020
	Fire Alarm_System	Elevator Equipment Room, Pump Room	67,506	SF	7	6-10 years	Installed 2020
	Fire Pump Controller	Elevator Equipment Room, Pump	1	EA	7	10+ years	Installed 2020



"atoma	ory : Fire Protection		D	uilding	· Main		2040 W 62nd STREET, Chicago, IL 606
Jaleyo			D		Decommond		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
noup	nem - Type	Room	Quantity		Kalik	Replacement	Comments
		Room					
ump R	oom Assembly						
	Fire Pump - 25-50 hp	Pump Room	1	EA	7	10+ years	Installed 2020
	Jockey Pump	Pump Room	1	EA	7	10+ years	Installed 2020
prinkle	r System						
•	Sprinkler Heads	Entire Building	67,506	SF	7	10+ years	Installed 2020
	Sprinkler Piping	Entire Building	67,506	SF	7	10+ years	Installed 2020
	Wet Sprinkler System	Entire Building	67,506	SF	7	10+ years	Installed 2020
						yeare	
atego	ory : Mechanical		В	uilding	: Main	Recommend	
roup	Itom Tuno	Location	Quantity	UOM	Rank	Replacement	Comments
iroup	Item - Type		wuantity		Ndiik	Replacement	Comments
ir Cond	ditioning						
	Chemical Pot Feeder	Entire Building	1	EA	7	10+ years	Installed 2020
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Entire Building	1	EA	7	10+ years	Installed 2020. Replaced multiple
	- Greater than 200 tons						condensing units.
	Glycol Feed	Entire Building	1	EA	7	10+ years	Installed 2020
ir Hand	dling Systems						
	Air Handling Unit- Package Single Zone-	Mechanical Room - AHU-1	1	EA	7	10+ years	Installed 2020.
	Indoor- Dual Temperature Coils - 20001-						
	30000 cfm						
	Air Intake	Mechanical Room - AHU-1	1	EA	7	10+ years	
	VAV Box	Mechanical Room - AHU-1	21	EA	7	10+ years	
	Air Handling Unit- Package Single Zone-	Mechanical Room - AHU-2	1	EA	7	10+ years	Installed 2020.
	Indoor- Dual Temperature Coils - 6000-				-	, , , , , , , , , , , , , , , , , , ,	
	10000 cfm						
	Air Intake	Mechanical Room - AHU-2	1	EA	7	10+ years	
	VAV Box	Mechanical Room - AHU-2	6	EA	7	10+ years	
	Air Handling Unit- Package Single Zone-	Mechanical Room - AHU-3	1	EA	7	10+ years	Installed 2020
	Indoor- Dual Temperature Coils - 10001-	Mechanical Room - And-3	I	EA	1	10+ years	Installed 2020
	15000 cfm						
	15000 cm		4	– ^	-	10	
			1	EA	7	10+ years	
	Air Intake	Mechanical Room - AHU-3		— A	-		
	Air Intake VAV Box	Mechanical Room - AHU-3	7	EA	7	10+ years	
	Air Intake VAV Box Air Handling Unit- Package Single Zone-			EA EA	7 7	10+ years 10+ years	Installed 2020
	Air Intake VAV Box Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001-	Mechanical Room - AHU-3	7				Installed 2020
	Air Intake VAV Box Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001- 30000 cfm	Mechanical Room - AHU-3 Mechanical Room - AHU-4	7		7	10+ years	Installed 2020
	Air Intake VAV Box Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001-	Mechanical Room - AHU-3	7				Installed 2020

Boiler Systems



Catego	ry : Mechanical		B	uilding	: Main		
-				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	3	EA	7	10+ years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	3	EA	7	10+ years	
Gas Boo	ster						
	Gas Booster	Boiler Room	1	EA	7	10+ years	Installed 2020
Heating	Devices						
leading	Cabinet Heaters - With Electric Coil	1st Floor	11	EA	6	6-10 years	
	Wall Heater - Electric	1st Floor	2	EA	6	6-10 years	
	Unit Heater - Hot Water	Mechanical Room	6	EA	7	10+ years	Installed 2020
	Unit Heater - Hot Water		0	LA	'	TU+ years	
Mechani	cal Plumbing						
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	7	10+ years	Installed 2020
	Dual Temperature Pump - Less than 10	Boiler Room	4	EA	7	10+ years	AHU coil circulation pumps.
	Hydronic Supply and Return - Steel	Entire Building	800	LF	7	10+ years	Installed 2020, Dual Temperature
Tempera	ature Control						
	DDC System	Entire Building	67,605	SF	6	6-10 years	New BAS in 2020
	Electric Thermostat	Entire Building	11	EA	7	10+ years	Control unit heaters, and cabinet heaters in vestibules
	Thermostats - DDC	Entire Building	51	EA	6	6-10 years	Installed 2020
Ventilatio	n						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	Installed 2020
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	4	EA	7	6-10 years	
	Exhaust Fans- Indoor - Greater than 8000	Entire Building	3	EA	6	6-10 years	
	CFM	Entire Building	0	L/\	U	o io years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	EF-2
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	7	10+ years	Three toilet exhausts and a kitcher exhaust
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	EF-3
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	7	10+ years	EF-1
	Exhaust Fans- Roof Mounted - Greater than	Entire Building	1	EA	7	10+ years	EF-4
	8000 CFM Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	6-10 years	
Catego	ry : Plumbing		R	uilding	• Main		
Group		Location	Quantity	UOM	Rank	Recommend	Comments
Group	Kom Type		Quantity		Nank	Recomment	voniments



ALM S	Schools						2040 W 62nd STREET, Chicago, IL 60
						Replacement	
ot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	7	10+ years	Installed 2020
oing							
-	Domestic Piping-Hot Water Return Lines	Entire Building	67,506	SF	6	6-10 years	Installed 2020
	Domestic Piping-Hot Water Return Risers	Entire Building	67,506	SF	6	6-10 years	Installed 2020
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	67,506	SF	6	6-10 years	Installed 2020
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	67,506	SF	6	6-10 years	Installed 2020
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,506	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	67,506	SF	6	6-10 years	Installed 2020
	Sanitary Piping	Entire Building	67,506	SF	6	6-10 years	
	Storm Piping	Entire Building	67,506	SF	6	6-10 years	
	Vent Piping	Entire Building	67,506	SF	6	6-10 years	
nps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	7	10+ years	Installed 2020
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
tego	ry : Room		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minist	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor	161	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	161	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	
	Power Distribution	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	574	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor- Principal	270	SF	6	6-10 years	
	Doors - Side-lite	1st Floor- Principal	54	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor- Principal	2	ĒA	7	6-10 years	
	Floor - Tile	1st Floor- Principal	270	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor- Principal	2	ĒA	6	6-10 years	
	Power Distribution	1st Floor- Principal	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor- Principal	628	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor- conference room / AP's	235	SF	6	6-10 years	

Doors - Steel Doors incl hw

Floor - Tile

Office

Office

Office

1st Floor- conference room / AP's

1st Floor- conference room / AP's

6

6

6-10 years

6-10 years

ΕA

SF

235

2



Catego	ry : Room		B	uilding	• Main		2040 W 6210 STREET, Chicago, IL 60636
Calego				unung	. Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ereap	Lighting - Lay-in	1st Floor- conference room / AP's Office	4	EA	6	6-10 years	
	Power Distribution	1st Floor- conference room / AP's Office	8	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor- conference room / AP's Office	505	SF	6	6-10 years	
	Ceiling - Lay-in	1st floor engineer's office at west end of building	138	SF	6	6-10 years	
	Doors - Side-lite	1st floor engineer's office at west end of building	48	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor engineer's office at west end of building	1	EA	6	6-10 years	
	Floor - Tile	1st floor engineer's office at west end of building	138	SF	6	6-10 years	
	Lighting - Lay-in	1st floor engineer's office at west end of building	2	EA	6	6-10 years	
	Power Distribution	1st floor engineer's office at west end of building	6	EA	6	6-10 years	
	Storage/ Closet	1st floor engineer's office at west end of building	68	SF	7	6-10 years	
	Walls - Concrete Block	1st floor engineer's office at west end of building	433	SF	6	6-10 years	
	Ceiling - Lay-in	1st floor gym office	235	SF	6	6-10 years	
	Doors - Side-lite	1st floor gym office	32	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor gym office	1	EA	6	6-10 years	
	Floor - Tile	1st floor gym office	235	SF	6	6-10 years	
	Lighting - Lay-in	1st floor gym office	3	ĒA	6	6-10 years	
	Power Distribution	1st floor gym office	6	EA	7	6-10 years	
	Walls - Concrete Block	1st floor gym office	631	SF	6	6-10 years	
		1st floor teacher's lounge at SW	550	SF	7	6-10 years	
	Ceiling - Lay-in Doors - Steel Doors incl hw	corner		-		-	
		1st floor teacher's lounge at SW corner	1	EA	7	6-10 years	
	Floor - Carpet	1st floor teacher's lounge at SW corner	550	SF	7	6-10 years	
	Lighting - Lay-in	1st floor teacher's lounge at SW corner	6	EA	7	6-10 years	
	Power Distribution	1st floor teacher's lounge at SW corner	8	EA	7	6-10 years	
	Storage/ Closet	1st floor teacher's lounge at SW corner	48	SF	7	6-10 years	
	Walls - Concrete Block	1st floor teacher's lounge at SW corner	929	SF	7	6-10 years	
	Work SInk	1st floor teacher's lounge at SW	1	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		corner					
	Ceiling - Lay-in	1st floor- 100 main office suite	925	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor- 100 main office suite	1	EA	6	6-10 years	
	Doors - Transom Window	1st floor- 100 main office suite	48	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st floor- 100 main office suite	1	EA	6	6-10 years	
	Floor - Tile	1st floor- 100 main office suite	925	SF	6	6-10 years	
	Lighting - Lay-in	1st floor- 100 main office suite	14	EA	6	6-10 years	
	Power Distribution	1st floor- 100 main office suite	18	EA	6	6-10 years	
	Storage/ Closet	1st floor- 100 main office suite	12	SF	7	6-10 years	
	Walls - Concrete Block	1st floor- 100 main office suite	1,873	SF	6	6-10 years	
	Work SInk	1st floor- 100 main office suite	1	EA	7	6-10 years	
	Ceiling - Lay-in	206, school counselor	224	SF	7	6-10 years	
	Doors - Steel Doors incl hw	206, school counselor	1	EA	7	6-10 years	
	Floor - Tile	206, school counselor	224	SF	7	10+ years	
	Lighting - Lay-in	206, school counselor	2	EA	7	6-10 years	
	Power Distribution	206, school counselor	6	EA	7	6-10 years	
	Walls - Concrete Block	206, school counselor	342	SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, library office	280	SF	7	2-5 years	
	Doors - Steel Doors incl hw	Second floor, library office	200	EA	7	6-10 years	
	Floor - Carpet	Second floor, library office	280	SF	7	6-10 years	
	Lighting - Lay-in	Second floor, library office	4	EA	7	6-10 years	
	Power Distribution	Second floor, library office	6	EA	7	6-10 years	
	Walls - Concrete Block	Second floor, library office	604	SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, resource room 202	489	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Second floor, resource room 202	2	EA	7	6-10 years	
	Floor - Tile	Second floor, resource room 202	489	SF	7	6-10 years	
	Lighting - Lay-in	Second floor, resource room 202	-05	EA	7	6-10 years	
	Power Distribution	Second floor, resource room 202	12	EA	7	6-10 years	
	Walls - Concrete Block	Second floor, resource room 202	864	SF	6	2-5 years	
	Ceiling - Exposed	gymnasium, PE Storage room	228	SF	6	6-10 years	
	Doors - Steel Doors incl hw	gymnasium, PE Storage room	220	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	gymnasium, PE Storage room	228	SF	5	6-10 years	
	Lighting - Pendent/Surface	gymnasium, PE Storage room	3	EA	6	6-10 years	
	Power Distribution	gymnasium, PE Storage room	6	EA	7	6-10 years	
	Walls - Concrete Block	gymnasium, PE Storage room	620	SF	6	6-10 years	
		wrecked ball space in gymnasium	250	SF	6		
	Ceiling - Exposed Doors - Steel Doors incl hw	wrecked ball space in gymnasium			6	6-10 years	
			2	EA		6-10 years	
	Floor - Tile	wrecked ball space in gymnasium	250	SF	6	6-10 years	
	Lighting - Lay-in	wrecked ball space in gymnasium	9	EA	6	6-10 years	
	Walls - Concrete Block	wrecked ball space in gymnasium	810	SF	6	6-10 years	
Symnasi	a						
	Ceiling - Lay-in	1st Floor	3,049	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	6-10 years	



NIR S							2040 W 62nd STREET, Chicago, IL 60636
Catego	ry : Room		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	3,049	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	18	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	130	SF	7	6-10 years	
	Storage/ Closet	1st Floor	325	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	5,277	SF	6	6-10 years	
Kitchen							
	Ceiling - Lay-in	1st Floor	1,441	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile Quarry	1st Floor	1,441	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Serving Line	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	2,663	SF	6	6-10 years	
Library							
-	Casework	2nd Floor	50	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	2,510	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	1-2 years	Door lock broken.
	Floor - Carpet	2nd Floor	1,730	SF	7	6-10 years	
	Floor - Tile	2nd Floor	580	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	26	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,928	SF	7	6-10 years	
Locker/S	Shower Room						
	Accessories	1st floor kitchen women's locker room	123	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor kitchen women's locker room	123	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor kitchen women's locker room	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor kitchen women's locker room	123	SF	6	6-10 years	
	Lavatory	1st floor kitchen women's locker room	1	EA	6	6-10 years	
	Lighting - Lay-in	1st floor kitchen women's locker room	2	EA	6	6-10 years	
	Partitions	1st floor kitchen women's locker room	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor kitchen women's locker	508	SF	6	6-10 years	



	ry : Room		В	uilding	: Main		
Ŭ				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		room	,				
	Water Closet	1st floor kitchen women's locker	1	EA	6	6-10 years	
		room			-	,	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor- 108	2,328	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor- 108	2,328	EA	6 6		
		1st Floor- 108		SF	-	6-10 years	
	Floor - Tile		2,328		7	2-5 years	
	Lighting - Lay-in	1st Floor- 108	24	EA	6	6-10 years	
	Serving Line	1st Floor- 108	48	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor- 108	1,992	SF	6	6-10 years	
	Ceiling - Lay-in	first floor -104	1,800	SF	6	6-10 years	
	Doors - Steel Doors incl hw	first floor -104	4	EA	6	6-10 years	
	Floor - Tile	first floor -104	1,800	SF	6	6-10 years	
	Lighting - Lay-in	first floor -104	12	EA	6	6-10 years	
	Walls - Concrete Block	first floor -104	3,414	SF	6	6-10 years	
MDF_ID							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	2-5 years	
	Finishes	2nd Floor	60	SF	7	6-10 years	
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	Ductless split system. 2019
							the set of the state of
							installation
Mechani	ical/ Service Rooms						installation
Mechani	cal/ Service Rooms	1st Floor	18	SF	5	6-10 years	installation
Mechani	Janitor's Closet	1st Floor 1st Floor	18 25	SF	5	6-10 years 6-10 years	installation
Mechani	Janitor's Closet Janitor's Closet	1st Floor	25	SF	5	6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks	1st Floor 1st Floor	25 138	SF SF	5 5	6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms	1st Floor 1st Floor 1st Floor	25 138 65	SF SF SF	5 5 5	6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor 1st Floor 1st Floor 1st Floor	25 138 65 72	SF SF SF SF	5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	25 138 65 72 48	SF SF SF SF SF	5 5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	25 138 65 72 48 225	SF SF SF SF SF	5 5 5 5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Vaults	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	25 138 65 72 48 225 125	SF SF SF SF SF SF	5 5 5 5 5 5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Vaults Janitor's Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	25 138 65 72 48 225 125 45	SF SF SF SF SF SF SF	5 5 5 5 5 5 5 5 5 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65	SF SF SF SF SF SF SF SF	5 5 5 5 5 5 5 5 5 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780	SF SF SF SF SF SF SF SF SF	5 5 5 5 5 5 5 5 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10	\$F \$	5 5 5 5 5 5 5 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10 10	\$F \$	5 5 5 5 5 5 5 7 7 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	installation
Mechan	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10	\$F \$	5 5 5 5 5 5 5 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	installation
	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10 10	\$F \$	5 5 5 5 5 5 5 7 7 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	installation
	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10 10	SFFFFFFFFFF SFFFFFFFF LF	5 5 5 5 5 5 5 7 7 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years	installation
Mechani Prep Ro	Janitor's Closet Janitor's Closet Loading Docks Mechanical/ Service Rooms Storage Room Vaults Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Storage Room	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	25 138 65 72 48 225 125 45 65 780 10 10 10	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	5 5 5 5 5 5 5 7 7 7 7 7 7 7	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	installation



Catego	ry : Room		В	uilding	: Main		
Ū						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile	In 209	81	SF	7	10+ years	
	Lighting - Lay-in	In 209	1	EA	7	10+ years	
	Walls - Concrete Block	In 209	160	SF	7	10+ years	
						-	
estroor	m						
	Accessories	1st floor inside Rm #101	34	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor inside Rm #101	34	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside Rm #101	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #101	34	SF	6	6-10 years	
	Lavatory	1st floor inside Rm #101	1	ĒA	6	6-10 years	
	Lighting - Lay-in	1st floor inside Rm #101	1	EA	6	6-10 years	
	Walls - Concrete Block	1st floor inside Rm #101	211	SF	6	6-10 years	
	Water Closet	1st floor inside Rm #101	1	EA	6	6-10 years	
	Accessories	1st floor inside Rm #109	34	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor inside Rm #109	34	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside Rm #109	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #109	.34	SF	6	6-10 years	
	Lavatory	1st floor inside Rm #109	1	EA	6	6-10 years	
	Lighting - Lay-in	1st floor inside Rm #109	1	EA	6	6-10 years	
	Walls - Concrete Block	1st floor inside Rm #109	211	SF	6	6-10 years	
	Water Closet	1st floor inside Rm #109	1	EA	6	6-10 years	
	Accessories	1st floor inside Rm #123	34	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor inside Rm #123	34	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside Rm #123	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #123	34	SF	6	6-10 years	
	Lavatory	1st floor inside Rm #123	1	EA	7	6-10 years	
	Lighting - Lay-in	1st floor inside Rm #123	1	EA	6	6-10 years	
	Walls - Concrete Block	1st floor inside Rm #123	211	SF	6	6-10 years	
	Water Closet	1st floor inside Rm #123	1	EA	7	6-10 years	
	Accessories	1st floor inside engineer's office	57	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside engineer's office	57	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside engineer's office	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside engineer's office	57	SF	7	6-10 years	
		1st floor inside engineer's office	1	EA	7	6-10 years	
	Lavatory Lighting - Lay-in	1st floor inside engineer's office	1	EA	6	6-10 years	
	Urinals	1st floor inside engineer's office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor inside engineer's office	305	SF	6	6-10 years	
	Water Closet	1st floor inside engineer's office	303 1	EA	7	•	
	Accessories		49	SF	7	6-10 years	
		1st floor inside gym office	49 49	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st floor inside gym office	-		ь 6	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside gym office	1	EA	-	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside gym office	49	SF	6	6-10 years	
	Lavatory	1st floor inside gym office	1	EA	6	6-10 years	
	Lighting - Lay-in	1st floor inside gym office	1	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		2040 W 62110 STREET, Chicago, IL 60636
<u>-</u>			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Showers	1st floor inside gym office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor inside gym office	265	SF	6	6-10 years	
	Water Closet	1st floor inside gym office	1	EA	6	6-10 years	
	Accessories	1st floor inside main office suite	77	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor inside main office suite	77	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st floor inside main office suite	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside main office suite	77	SF	6	6-10 years	
	Lavatory	1st floor inside main office suite	1	EA	6	6-10 years	
	Lighting - Lay-in	1st floor inside main office suite	1	EA	6	6-10 years	
	Walls - Concrete Block	1st floor inside main office suite	289	SF	6	6-10 years	
	Water Closet	1st floor inside main office suite	1	EA	6	6-10 years	
	Accessories	1st floor- RR inside main office suite	77	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor- RR inside main office suite	77	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st floor- RR inside main office suite	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor- RR inside main office suite	77	SF	7	6-10 years	
	Lavatory	1st floor- RR inside main office suite	1	EA	7	6-10 years	
	Lighting - Lay-in	1st floor- RR inside main office suite	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor- RR inside main office suite	289	SF	7	6-10 years	
	Water Closet	1st floor- RR inside main office suite	1	EA	7	6-10 years	
	Accessories	1 1st floor- staff RR inside main office 2	77	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor- staff RR inside main office	77	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st floor- staff RR inside main office	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor- staff RR inside main office	77	SF	7	6-10 years	
	Lavatory	1st floor- staff RR inside main office	1	EA	7	6-10 years	
	Lighting - Lay-in	1st floor- staff RR inside main office	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor- staff RR inside main office	289	SF	7	6-10 years	
	Water Closet	1st floor- staff RR inside main office	1	EA	7	6-10 years	
	Accessories	First floor Boys near 106	131	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Plaster/Drywall	First floor Boys near 106	131	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor Boys near 106	131	SF	6	6-10 years	
	Floor Drain	First floor Boys near 106	1	EA	7	6-10 years	
	Hand Dryer	First floor Boys near 106	2	EA	7	6-10 years	
	Lavatory	First floor Boys near 106	2	EA	7	6-10 years	
	Lighting - Lay-in	First floor Boys near 106	3	EA	7	6-10 years	
	Partitions	First floor Boys near 106	1	EA	7	6-10 years	
	Urinals	First floor Boys near 106	3	EA	7	6-10 years	
	Walls - Concrete Block	First floor Boys near 106	430	SF	6	6-10 years	
	Water Closet	First floor Boys near 106	1	EA	7	6-10 years	
	Accessories	First floor Boys near 136	127	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor Boys near 136	127	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor Boys near 136	127	SF	6	6-10 years	
	Hand Dryer	First floor Boys near 136	2	EA	7	6-10 years	
	Lavatory	First floor Boys near 136	2	EA	7	6-10 years	
	Lighting - Lay-in	First floor Boys near 136	3	EA	7	6-10 years	
	Partitions	First floor Boys near 136	1	EA	7	6-10 years	
	Urinals	First floor Boys near 136	2	EA	7	6-10 years	
	Walls - Concrete Block	First floor Boys near 136	418	SF	6	6-10 years	
	Water Closet	First floor Boys near 136	1	EA	7	6-10 years	
	Accessories	First floor Girls near 106	131	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor Girls near 106	131	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor Girls near 106	131	SF	6	6-10 years	
	Hand Dryer	First floor Girls near 106	2	EA	7	6-10 years	
	Lavatory	First floor Girls near 106	2	EA	7	6-10 years	
	Lighting - Lay-in	First floor Girls near 106	3	EA	6	6-10 years	
	Partitions	First floor Girls near 106	2	EA	7	6-10 years	
	Walls - Concrete Block	First floor Girls near 106	430	SF	6	6-10 years	
	Water Closet	First floor Girls near 106	2	EA	7	6-10 years	
	Accessories	First floor Girls near 136	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor Girls near 136	176	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor Girls near 136	176	SF	6	6-10 years	
	Hand Dryer	First floor Girls near 136	2	EA	7	6-10 years	
	Lavatory	First floor Girls near 136	1	EA	7	6-10 years	
	Lighting - Lay-in	First floor Girls near 136	5	EA	7	6-10 years	
	Partitions	First floor Girls near 136	3	EA	7	6-10 years	
	Walls - Concrete Block	First floor Girls near 136	516	SF	6	6-10 years	
	Water Closet	First floor Girls near 136	3	EA	7	6-10 years	
	Accessories	First floor, Women's near 136	102	SF	7	6-10 years	
	Ceiling - Lay-in	First floor, Women's near 136	102	SF	7	6-10 years	
	Doors - Steel Doors incl hw	First floor, Women's near 136	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor, Women's near 136	102	SF	7	6-10 years	
	Lavatory	First floor, Women's near 136	1	EA	7	6-10 years	
	Lighting - Lay-in	First floor, Women's near 136	2	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	First floor, Women's near 136	2	EA	7	6-10 years	
	Walls - Concrete Block	First floor, Women's near 136	430	SF	7	6-10 years	
	Water Closet	First floor, Women's near 136	2	EA	7	6-10 years	
	Accessories	First floor, men's near 136	102	SF	7	6-10 years	
	Ceiling - Lay-in	First floor, men's near 136	99	SF	7	6-10 years	
	Ceiling - Lay-in	First floor, men's near 136	3	SF	4	0-1 year	Missing.
	Doors - Steel Doors incl hw	First floor, men's near 136	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First floor, men's near 136	102	SF	6	6-10 years	
	Lavatory	First floor, men's near 136	1	EA	7	6-10 years	
	Lighting - Lay-in	First floor, men's near 136	2	EA	7	6-10 years	
	Partitions	First floor, men's near 136	1	EA	7	6-10 years	
	Urinals	First floor, men's near 136	1	EA	7	6-10 years	
	Walls - Concrete Block	First floor, men's near 136	430	SF	7	6-10 years	
	Water Closet	First floor, men's near 136	1	EA	7	6-10 years	
	Accessories	Second floor Boys near 200	127	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Second floor Boys near 200	127	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor Boys near 200	127	SF	7	6-10 years	
	Hand Dryer	Second floor Boys near 200	2	EA	7	6-10 years	
	Lavatory	Second floor Boys near 200	2	EA	7	6-10 years	
	Lighting - Lay-in	Second floor Boys near 200	3	EA	7	6-10 years	
	Partitions	Second floor Boys near 200	1	EA	7	6-10 years	
	Urinals	Second floor Boys near 200	2	EA	7	6-10 years	
	Walls - Concrete Block	Second floor Boys near 200	418	SF	6	6-10 years	
	Water Closet	Second floor Boys near 200	1	EA	7	6-10 years	
	Accessories	Second floor Boys near 221	127	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Second floor Boys near 221	127	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor Boys near 221	127	SF	7	6-10 years	
	Hand Dryer	Second floor Boys near 221	2	EA	7	6-10 years	
	Lavatory	Second floor Boys near 221	2	EA	7	6-10 years	
	Lighting - Lay-in	Second floor Boys near 221	3	EA	7	6-10 years	
	Partitions	Second floor Boys near 221	1	EA	7	6-10 years	
	Urinals	Second floor Boys near 221	3	EA	7	6-10 years	
	Walls - Concrete Block	Second floor Boys near 221	418	SF	7	6-10 years	
	Water Closet	Second floor Boys near 221	1	EA	7	6-10 years	
	Accessories	Second floor Girls near 200	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Second floor Girls near 200	176	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor Girls near 200	176	SF	7	6-10 years	
	Hand Dryer	Second floor Girls near 200	2	EA	7	6-10 years	
	Lavatory	Second floor Girls near 200	1	EA	7	6-10 years	
	Lighting - Lay-in	Second floor Girls near 200	5	EA	7	6-10 years	
	Partitions	Second floor Girls near 200	3	EA	7	6-10 years	
	Walls - Concrete Block	Second floor Girls near 200	516	SF	6	6-10 years	
	Water Closet	Second floor Girls near 200	3	EA	7	6-10 years	
			176	SF	7	,	



Catego	ry : Room		B	uilding	: Main		2040 W 62nd STREET, Chicago, IL 60636
Jaiogo				unung	· Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Second floor Girls near 221	176	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor Girls near 221	176	SF	7	6-10 years	
	Hand Dryer	Second floor Girls near 221	2	EA	7	6-10 years	
	Lavatory	Second floor Girls near 221	1	EA	7	6-10 years	
	Lighting - Lay-in	Second floor Girls near 221	5	EA	7	6-10 years	
	Partitions	Second floor Girls near 221	3	EA	7	6-10 years	
	Walls - Concrete Block	Second floor Girls near 221	516	SF	6	6-10 years	
	Water Closet	Second floor Girls near 221	3	EA	7	6-10 years	
	Accessories	Second floor, Women's near 200	102	SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, Women's near 200	102	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Second floor, Women's near 200	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor, Women's near 200	102	SF	7	6-10 years	
	Lavatory	Second floor, Women's near 200	1	EA	7	6-10 years	
	Lighting - Lay-in	Second floor, Women's near 200	2	EA	7	6-10 years	
	Partitions	Second floor, Women's near 200	2	EA	7	6-10 years	
	Walls - Concrete Block	Second floor, Women's near 200	430	SF	6	6-10 years	
	Water Closet	Second floor, Women's near 200	2	EA	7	6-10 years	
	Accessories	Second floor, inside room 221	34	SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, inside room 221	4	SF	7	10+ years	
	Ceiling - Lay-in	Second floor, inside room 221	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Second floor, inside room 221	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor, inside room 221	34	SF	7	6-10 years	
	Lavatory	Second floor, inside room 221	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Second floor, inside room 221	1	EA	7	6-10 years	
	Walls - Concrete Block	Second floor, inside room 221	216	SF	7	6-10 years	
	Water Closet	Second floor, inside room 221	1	EA	7	6-10 years	
	Accessories	Second floor, inside room 223	34	SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, inside room 223	34	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Second floor, inside room 223	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor, inside room 223	34	SF	7	6-10 years	
	Lavatory	Second floor, inside room 223	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Second floor, inside room 223	1	EA	7	6-10 years	
	Walls - Concrete Block	Second floor, inside room 223	216	SF	7	6-10 years	
	Water Closet	Second floor, inside room 223	1	EA	7	6-10 years	
	Accessories	Second floor, men's near 200	102	SF SF	7	6-10 years	
	Ceiling - Lay-in	Second floor, men's near 200	102		7	6-10 years	
	Doors - Steel Doors incl hw	Second floor, men's near 200	1	EA SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Second floor, men's near 200	102	EA	7	6-10 years	
	Lavatory	Second floor, men's near 200	1	EA	7	6-10 years	
	Lighting - Lay-in	Second floor, men's near 200			7	6-10 years	
	Partitions Urinals	Second floor, men's near 200	1 1	EA EA	7	6-10 years	
	Walls - Concrete Block	Second floor, men's near 200	430	EA SF	7 7	6-10 years	
		Second floor, men's near 200	430			6-10 years	
	Water Closet	Second floor, men's near 200	1	EA	7	6-10 years	



Category : Room			В	uilding	: Main		
-	- -			-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
			-				
atego	ry : Classroom		В	uilding	: Main	Deserves	
	Hanna Truna	Leastian	Ouentitu	UOM	Dauk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Kindergarten)						
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,298	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,298	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,325	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassror	m #103 (Regular Classroom)						
21035100	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	899	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	899	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,146	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
	m #105 (Regular Classroom)					,	
Jassioo	Casework	1st Floor	8	LF	6	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	899	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	899	SF			
		1st Floor		EA	6 6	6-10 years	
	Lighting - Lay-in Marker Board	1st Floor	12 16	LF	6	6-10 years	
						6-10 years	
	Walls - Concrete Block	1st Floor	1,146	SF	6 7	6-10 years	
	Work Sink	1st Floor	1	EA	/	6-10 years	
Classroo	m #107 (Faculty Lounge)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	899	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	899	SF	7	6-10 years	
		1st Floor	12	ĒA	7	6-10 years	
	Lighting - Lay-in	13(1100)	14				
	Lighting - Lay-in Marker Board	1st Floor	16	LF	6	6-10 years	



Catego	ory : Classroom		B	uilding	• Main		2040 W 62nd STREET, Chicago, T
ealege			_	anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #109 (Pre School)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,298	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	, 1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,298	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	 14	EA	6	6-10 years	
	Marker Board	1st Floor	5	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,283	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #111 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	ĒA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,071	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #113 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,071	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classro	om #115 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	10+ years	
	Lighting Lov in	1st Floor	12		6	6 10 years	

Work Sink

Lighting - Lay-in Marker Board

Walls - Concrete Block

ΕA

LF

SF

ΕA

12

30

1

1,071

6

7

6

7

6-10 years

6-10 years

6-10 years

6-10 years

1st Floor

1st Floor

1st Floor

1st Floor



Charles W Earle Elementary School 2040 W 62nd STREET, Chicago, IL 60636

Catego	Category : Classroom		В	uilding	: Main		2040 W 02HU STREET, Chicago, ie 00030
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #117 (Regular Classroom)						
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor		EA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒA	7	6-10 years	
	Marker Board	1st Floor	32	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	959	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
			•	273	•	o ro youro	
Classroo	om #119 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	922	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,071	SF	6	6-10 years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
						,	
Classroo	om #121 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,000	SF	7	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #123 (Store Room)			. –			
	Casework	1st Floor	14	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	922	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,071	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #125 (Office)						
	Casework	1st Floor	14	LF	6	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	922	SF	6 6	6-10 years 6-10 years	
	Centry - Lay-III		922	ЗГ	U	0-10 years	



Category : Classroom		В	uilding	: Main			
J •	-			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	922	SF	7	2-5 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	987	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,533	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,533	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,467	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroo	om #203 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	590	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	590	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	898	SF	7	6-10 years	
Classroo	om #205 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	660	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	2-5 years	
	Floor - Tile	2nd Floor	660	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	928	SF	7	6-10 years	
Classroo	om #207 (Science Classroom)						
	Ceiling - Lay-in	2nd Floor	1,013	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,013	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	264	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,164	SF	7	6-10 years	



)	Schools		_				2040 W 62nd STREET, Chicago, IL 606
Catego	ry : Classroom		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group		Location	Quantity	UCIW	Rank	Replacement	Comments
Classroo	om #209 (Computer Lab) Casework	2nd Floor	4	LF	7	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor	923	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	923	EA	7	6-10 years	
	Floor - Tile	2nd Floor	923	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	923	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,041	SF	7	6-10 years	
	Work Sink	2nd Floor	1,041	EA	7	6-10 years	
	WOR SINK	210 F1001	I	EA	1	0-10 years	
Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	896	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	896	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,062	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #213 (Regular Classroom)						
01000100	Casework	2nd Floor	16	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	896	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	896	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,062	SF	7	2-5 years	
	Work Sink	2nd Floor	1,002	EA	7	6-10 years	
Classfor	om #215 (Regular Classroom) Casework	2nd Floor	16	LF	7	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor		SF		6-10 years 6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	920 1	EA	7 7		
	Floor - Tile	2nd Floor 2nd Floor	920	EA SF	7	6-10 years 10+ years	
				EA	7	•	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	12 36	EA LF		6-10 years	
				SF	7 7	6-10 years 6-10 years	
	Walls - Concrete Block Work Sink	2nd Floor 2nd Floor	1,094	EA	7		
	VVUK SINK	2nd Floor	1	EA	1	6-10 years	
Classroo	om #217 (Science Classroom)						
	Casework	2nd Floor	12	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	920	SF	7	6-10 years	
Classroo	Casework						



							2040 W 62nd STREET, Chicago, IL 60636
Catego	ry : Classroom		В	uilding	: Main	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	920	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,094	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #219 (Regular Classroom)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	936	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	936	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,094	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classro	om #221 (Special Education)						
Ciubbiot	Casework	2nd Floor	26	LF	7	2-5 years	
	Ceiling - Lay-in	2nd Floor	876	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor		SF	7		
	Lighting - Lay-in	2nd Floor	876 12	EA	7	6-10 years 6-10 years	
				LF			
	Marker Board	2nd Floor	36		7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,047	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #223 (Special Education)						
	Casework	2nd Floor	11	LF	7	2-5 years	
	Ceiling - Lay-in	2nd Floor	812	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	812	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	958	SF	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #225 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	762	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	762	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
			36	LF	7		
	Marker Board	2nd Floor	36	LF	1	6-10 years	



Category : Classroom

Catego	/ y . 01855100111			unung	. Wall		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	961	SF	7	6-10 years	
Classro	om #227 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	820	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	2-5 years	
	Floor - Tile	2nd Floor	820	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	988	SF	7	6-10 years	
Classro	om #229 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	746	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	746	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	930	SF	7	6-10 years	
Classro	om #231 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	821	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	821	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	988	SF	7	6-10 years	
Classro	om #233 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	824	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	824	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	988	SF	7	6-10 years	
Classro	om #235 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	957	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile	2nd Floor	957	SF	7	2-5 years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,012	SF	7	6-10 years	
			7 -			,	

Building : Main



Charles W Earle Elementary School 2040 W 62nd STREET, Chicago, IL 60636

Catego	Category : Interior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,958	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	708	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	92	SF	6	6-10 years	
	Doors - Store Front	1st Floor	12	ĒA	6	6-10 years	
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	5,665	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	58	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	11,070	SF	6	10+ years	
	Walls - Masonry	1st Floor	120	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5,562	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	5,562	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	42	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	10,998	SF	7	6-10 years	
	Ceiling - Lay-in	Classroom 101 Vestibule	36	SF	6	6-10 years	
	Doors - Side-lite	Classroom 101 Vestibule	20	SF	6	6-10 years	
	Doors - Store Front	Classroom 101 Vestibule	1	EA	6	6-10 years	
	Doors - Transom Window	Classroom 101 Vestibule	6	SF	6	6-10 years	
	Floor - Tile/Sheet	Classroom 101 Vestibule	36	SF	7	6-10 years	
	Lighting - Lay-in	Classroom 101 Vestibule	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 101 Vestibule	175	SF	6	6-10 years	
	Ceiling - Lay-in	Classroom 109 Vestibule	36	SF	6	6-10 years	
	Doors - Side-lite	Classroom 109 Vestibule	20	SF	6	6-10 years	
	Doors - Store Front	Classroom 109 Vestibule	1	EA	6	6-10 years	
	Doors - Transom Window	Classroom 109 Vestibule	6	SF	6	6-10 years	
	Floor - Tile/Sheet	Classroom 109 Vestibule	36	SF	7	6-10 years	
	Lighting - Lay-in	Classroom 109 Vestibule	1	EA	6	6-10 years	
	Walls - Concrete Block	Classroom 109 Vestibule	175	SF	6	6-10 years	
Safety							
	Metal Dedector	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	7	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	#1 N Stair	210	SF	7	6-10 years	
	Floor - Tile	#1 N Stair	150	SF	7	6-10 years	
	Handrails	#1 N Stair	70	LF	5	6-10 years	
	Lighting - Lay-in	#1 N Stair	2	EA	7	6-10 years	
	Stairs - Tile	#1 N Stair	32	LF	7	2-5 years	
	Walls - Concrete Block	#1 N Stair	1,120	SF	7	6-10 years	
						2	



Category : Interior							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	#2 E Stair	206	SF	7	6-10 years	
	Floor - Tile	#2 E Stair	125	SF	7	6-10 years	
	Handrails	#2 E Stair	70	LF	5	2-5 years	
	Lighting - Lay-in	#2 E Stair	3	EA	6	6-10 years	
	Stairs - Tile	#2 E Stair	32	LF	6	6-10 years	
	Walls - Concrete Block	#2 E Stair	1,380	SF	6	6-10 years	
	Ceiling - Lay-in	#3 SE Stair	210	SF	7	6-10 years	
	Floor - Tile	#3 SE Stair	150	SF	7	6-10 years	
	Handrails	#3 SE Stair	70	LF	5	2-5 years	
	Lighting - Lay-in	#3 SE Stair	2	EA	7	6-10 years	
	Stairs - Tile	#3 SE Stair	32	LF	7	6-10 years	
	Walls - Concrete Block	#3 SE Stair	1,120	SF	7	6-10 years	
/ertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	



Category : Site			В	uilding	: Site		
Ţ	•			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	10+ years	
	Ũ						
Fencina							
0	Fencing - Chain Link	Entire Site	679	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	10	LF	4	0-1 year	Missing at parking lot.
	Fencing - Guard Rail	Entire Site	105	LF	7	10+ years	5 1 5
	Fencing - Guard Rail	Entire Site	15	LF	4	0-1 year	Guard rail has detached from post
	Fencing - New Standard Ornamental	Entire Site	677	LF	5	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	10	LF	4	0-1 year	No hole for this gate to lock.
				_ .	•	e i year	
Landsca	De						
	Benches	Entire Site	5	EA	7	10+ years	
	Landscape - Grass	Entire Site	12,879	SF	6	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,777	SF	6	6-10 years	
	Landscape - Hardscape- Pavers	Entire Site	225	SF	6	6-10 years	
	Parkway trees	Entire Site	8	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	90	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	558	SF	5	0-1 year	Foundation is cracked in several
			000	0.	Ũ	o i your	areas
Derkiner							
Parking I	Concrete Curbs	Darking Lat West	20	LF	7	10, , , , , , , , , , , , , , , , , , ,	
	Concrete Curbs	Parking Lot-West	886	LF	7	10+ years	
		Parking Lot- West		SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- West	17,596		7	6-10 years	
	Surface - Asphalt	Parking Lot- West	200	SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- West	4,800	SF	4	0-1 year	Cracking and potholes throughout.
	Trash Enclosure - Chain Links	Parking Lot- West	200	SF	7	6-10 years	
Playgrou	nd						
grou	Equipment - School Age 5-12	North Courtyard	3	EA	7	6-10 years	
	Surface - Poured Surface	North Courtyard	6.426	SF	7	6-10 years	
			0,120	0.	•	e le jeule	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	679	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	4,567	SF	6	10+ years	
						-	
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	6-10 years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	6	6-10 years	



Category : Site			Building : Site					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	w/ LED Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	6-10 years		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•	•					
Computer Lab	Regular Classroom	1st Floor	119	NA	922	144	24	N	Ν
Computer Lab	Science Classroom	2nd Floor	209	209	923	138	28	N	Y
Faculty Lounge	Regular Classroom	1st Floor	107	107	899	96	24	N	N
Kindergarten	Kindergarten	1st Floor	101	101	1,298	132	36	N	N
Office	Regular Classroom	1st Floor	125	NA	922	192	48	N	Y
Pre School	Kindergarten	1st Floor	109	109	1,298	168	24	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	899	96	24	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	899	96	24	N	N
Regular Classroom	Regular Classroom	1st Floor	111	NA	922	120	24	N	N
Regular Classroom	Regular Classroom	1st Floor	113	NA	922	144	24	N	N
Regular Classroom	Regular Classroom	1st Floor	115	NA	922	144	24	N	N
Regular Classroom	Regular Classroom	1st Floor	117	NA	922	216	48	N	N
Regular Classroom	Regular Classroom	1st Floor	121	NA	922	144	24	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,533	161	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	590	92	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	660	92	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	896	138	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	896	138	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	920	138	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	936	138	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	225	225	762	182	43	N	Y
Regular Classroom	Regular Classroom	2nd Floor	227	227	820	126	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	229	229	746	126	28	N	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	821	126	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	233	233	824	126	28	N	Y
Regular Classroom	Regular Classroom	2nd Floor	235	235	957	195	56	N	Y
Science Classroom	Regular Classroom	2nd Floor	217	217	920	207	42	N	Y
Science Classroom	Science Classroom	2nd Floor	207	207	1,013	138	28	N	Y
Special Education	Special Education	2nd Floor	221	221	876	138	28	N	Y
Special Education	Special Education	2nd Floor	223	223	812	138	28	N	N
Store Room	Special Program	1st Floor	123	NA	922	144	24	N	N