

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1919	3	82,716
Addition	2001	3	82,797
Campus Total			165,513

Category : Exterior Building : Main

July	I J I Extorior		unung				
			•			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	9						
	Entrance Control - Audio	#1-Main	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1-Main	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1-Main	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1-Main	120	LF	5	2-5 years	
	Entrance Control - Audio	#14-N	1	EA	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#14-N	2	EA	6	6-10 years	Paint required.
	Exterior Doors - Transom Lite	#14-N	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#2-SW	2	EA	6	2-5 years	Minor rust at bottom of door.
	Exterior Doors - Transom Lite	#2-SW	2	EA	7	6-10 years	
	Exterior Stairs - Concrete	#2-SW	6	LF	6	10+ years	
	Entrance Control - Audio	#3-SE	1	EA	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#3-SE	4	EA	6	2-5 years	
	Exterior Doors - Exterior Steel Door	#4-Kindergarten SW	2	EA	5	0-1 year	Rusting.
	Exterior Doors - Transom Lite	#4-Kindergarten SW	2	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#4-Kindergarten SW	15	LF	5	6-10 years	
	Exterior Stairs - Stone	#4-Kindergarten SW	6	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4-Kindergarten SW	10	LF	6	6-10 years	New item
	Stair Handrail - Steel_Stair Handrail	#4-Kindergarten SW	14	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5-SW	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5-SW	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5-SW	140	LF	5	2-5 years	Minor chipping.
	Exterior Doors - Exterior Steel Door	#5.5-Boiler Room	1	EA	6	6-10 years	5
	Entrance Control - Audio	#6-Courtyard	1	EA	5	6-10 years	



Category : Exterior			В				
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	#6-Courtyard	4	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	ComEd	2	EA	6	6-10 years	
oundati	ion						
<u> </u>	Foundation - Masonry	Entire Building	1,012	LF	6	10+ years	
	Foundation - Masonry	Entire Building	30	LF	5	0-1 year	Cracks.
	Superstructure - Heavy Timber	Entire Building	82,797	SF	7	10+ years	
ghting							
giittiig	Exterior Lighting - Parapet or Roof Mounted	Entire Building	31	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	5	2-5 years	
oof Svs	etem						
ioi oy:	Access Ladder - Metal	#1	3	EA	7	10+ years	
	Coping - Clay Tile	#1	220	LF	6	6-10 years	
	Coping - Terra Cotta	#1	707	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#1	330	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#1	160	LF	6	6-10 years	
				LF	_		
	Parapet - Parapet < 16" Height	#1	40		6	6-10 years	
	Parapet - Parapet > 30"	#1	507	LF	6	6-10 years	
	Roof - Modified Bitumen	#1	11,567	SF	6	6-10 years	
	Roof Hatch - Metal	#1	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#1	11,567	SF	7	10+ years	
	Coping - Terra Cotta	#10	45	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#10	30	LF	5	2-5 years	
	Parapet - Parapet < 16" Height	#10	45	LF	6	6-10 years	
	Roof - Metal	#10	90	SF	7	6-10 years	Rubber Membrane atop of Metal
	Roof Structure - Steel with Clay Tile Arch	#10	90	SF	7	10+ years	rance memorane arep or metar
	Access Ladder - Metal	#2	1	EA	7	10+ years	
	Coping - Terra Cotta	#2	263	LF	6	6-10 years	
	Downspouts - Interior Downspouts	#2	224	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#2	263	LF	6	6-10 years	
	Roof - Modified Bitumen	#2	7,351	SF	6	6-10 years	
	Roof - Modified Bitumen	#2	75	SF	5	2-5 years	
	Roof Hatch - Metal	#2	1	EΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#2	7,426	SF	7	10+ years	
	Access Ladder - Metal	#3	2	EA	7	10+ years	
	Coping - Terra Cotta	#3	207	LF	6	6-10 years	
				LF			No flashing on West Center.
	Coping - Terra Cotta	#3	40	LF	5	1-2 years	Cracking mortar.
	Downspouts - Interior Downspouts	#3	56	LF	7	6-10 years	Potential for Leak Repaired-Non Issue.



Catego	ry : Exterior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Downspouts - Interior Downspouts	#3	168	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#3	40	LF	6	10+ years			
	Roof - Modified Bitumen	#3	7,266	SF	6	6-10 years			
	Roof Hatch - Metal	#3	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	#3	7,266	SF	7	10+ years			
	Concrete Topping		·			•			
	Chimney - Brick Chimney- Concrete/ Mortar	#4	44	LF	5	6-10 years			
	Liner				•	- · · · · · · · ·			
	Coping - Terra Cotta	#4	143	LF	6	6-10 years			
	Downspouts - Interior Downspouts	#4	197	LF	6	6-10 years			
	Parapet - 16" - 30" Height	#4	108	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	#4	35	LF	6	6-10 years			
	Roof - Modified Bitumen	# <del>4</del> #4	2,226	SF	6	6-10 years			
			2,226	SF	7				
	Roof Structure - Steel with Clay Tile Arch	#4	· · · · · · · · · · · · · · · · · · ·			10+ years			
	Downspouts - Interior Downspouts	#9	20	LF	6	6-10 years			
	Roof - Modified Bitumen	#9	874	SF	6	6-10 years			
	Roof Structure - Steel with Clay Tile Arch	#9	874	SF	7	10+ years			
	Access Ladder - Metal	.#5	1	EA	7	10+ years			
	Coping - Terra Cotta	.#5	120	LF	6	6-10 years			
	Downspouts - Interior Downspouts	.#5	19	LF	6	6-10 years			
	Parapet - 16" - 30" Height	.#5	50	LF	6	6-10 years			
	Parapet - Parapet < 16" Height	.#5	70	LF	6	6-10 years			
	Roof - Modified Bitumen	.#5	1,922	SF	6	6-10 years			
	Roof Hatch - Metal	.#5		EA	7	10+ years	Handles falling off around hatch.		
	Roof Structure - Steel with Clay Tile Arch	.#5	1,922	SF	6	10+ years	Ü		
Valls									
Valis	Cheek-Wall - Concrete	Entire Building	40	SF	6	6-10 years			
	Cheek-Wall - Concrete	Entire Building	60	SF	4	1-2 years	Cracking.		
	Cheek-Wall - Stone	Entire Building	50	SF	6	6-10 years	<b>G</b>		
	Cheek-Wall - Stone	Entire Building	30	SF	5	6-10 years	Located at entrance #14 on North		
	Chical Ham Clark	g		٠.	· ·	o .o you.o	Elevation - Facing West.		
	Cornice - Terra Cotta	Entire Building	1,100	LF	6	6-10 years	No		
	Exterior Walls - Brick	Entire Building	50,964	SF	6	10+ years	140		
	Exterior Walls - Brick	Entire Building	100	SF	5	2-5 years			
	Exterior Walls - Brick	Entire Building	600	SF	5	2-5 years 2-5 years			
				SF	6	•			
	Exterior Walls - Stone-Cast	Entire Building	3,755	SF	6	10+ years			
Vindows	3								
	Guard - Guards perforated	Entire Building	3,572	SF	7	6-10 years			
	Lintels - Steel	Entire Building	960	LF	6	6-10 years			
	Skylite - Glass Single-Pane	Entire Building	140	SF	7	6-10 years			
	Windows - Sash Aluminum Double-pane	Entire Building	9,400	SF	6	6-10 years			
	Time to Guoti / Wallington Bodolo pario	Zita Bananig	5,400	٥.	J	J 10 yours			



Catego	y : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	cy System	Location	Quantity	00111	Italik	Replacement	Comments
-merger	Automatic Transfer Switch	Boiler Room	1	EA	4	1-2 years	Serves main building, older unit.
	Emergency A/C Power - Auditoium and	Entire Building	6,057	SF	6	6-10 years	Cerves main ballang, older and.
	Aisle Lighting	Zimio Bananig	0,001	O.	Ŭ	o io youio	
	Emergency A/C Power - Corridors and	Entire Building	15,366	SF	6	6-10 years	
	Stairs	3	-,		-	, , , , , , , , , , , , , , , , , , , ,	
	Emergency A/C Power - Gym	Entire Building	5,447	SF	6	6-10 years	
	Security System - CCTV	Entire Building	82,716	SF	5	2-5 years	
	Security System - Intrusion Detection	Entire Building	80,632	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	2,084	SF	4	2-5 years	Old not reliable
	Exit Signs - Auditoium	Entire Building	11	EA	2	0-1 year	No battery-backup
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	2	0-1 year	No battery backup
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	No battery -back up
	Emergency Battery Packs - Auditoium and	Entire Building	7	EA	4	1-2 years	Old, not reliable
	Aisle Lighting						
	Emergency Battery Packs - Corridors and	Entire Building	10	EA	4	1-2 years	Old, not reliable
	Stairs						
Main Ser							
	Main Electrical Service - 1200 A	Electrical Room	1	EA	4	1-2 years	Serves main building. Old unit.
	120/208/3PH	EL .: 15		<b>-</b> ^	•	0.40	0
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	Serves main building
	emergency power	Entire Duilding	00.746	SF	E	6.10 , , , , , , , ,	Connected to addition
	PA System	Entire Building	82,716	SF	5	6-10 years	Connected to addition
Power D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Labeling is worn off.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp	B			_	40	<b>.</b>
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	Power conditioning
Catego	y : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Fire Alar	-	Location	Quantity	OOW	Nalik	Replacement	Comments
LIIE AIdl	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	Serves main and addition buildin
	Fire Alarm Strobe Lights	Mechanical Room	82,716	SF	6	10+ years	
	ŭ		, -			,	



Catego	ry : Fire Protection	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm_System	Mechanical Room	82.716	SF	6	6-10 years	

Catogory - Machanical Building - Main

Comments
Return common air
Dampers do not open.
Inside reheat boxes
Dampers do not open.
Inside reheat boxes
There are a few pipe clamps
There are a few pipe clamps

Campus Name: Falconer Page : 5 of 51 Assessment Date: 07/14/2021



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Traps	Boiler Room	70	EA	4	1-2 years	Many steam traps have internal leaks
_Heating	Devices						
· ·	Fin Tube - Steam	1st Floor	100	LF	6	10+ years	
	Fin Tube - Steam	1st Floor	50	LF	5	6-10 years	
	Unit Heater - Electric	Entire Building	9	EA	5	6-10 years	
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	
	Radiators - Steam	Entire Building	45	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	In restrooms
_Tempera	ature Control						
•	Electric Thermostat	Entire Building	10	EA	5	6-10 years	Serves unit heater, not recallibrated
	Pneumatic System	Entire Building	82,761	SF	3	1-2 years	Serves main building, manually operated, works poorly
	Thermostats - Pneumatic	Entire Building	41	EA	4	1-2 years	More than 30 years old, may have leaks.
_Ventilation	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	6	6-10 years	

Category : Plumbing **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Serves main building. Minor rust/corrosion.
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	82,716	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	82,716	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	82,716	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	82,716	SF	6	6-10 years	There are a few pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	82,716	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	82,716	SF	6	6-10 years	
	Sanitary Piping	Entire Building	82,716	SF	6	6-10 years	
	Storm Piping	Entire Building	82,716	SF	6	6-10 years	

Campus Name: Falconer Page : 6 of 51 Assessment Date: 07/14/2021



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Vent Piping	Entire Building	82,716	SF	6	6-10 years	
_Pumps_							
-	Pumps - Sump-Simplex	Boiler Room	1	EA	6	6-10 years	Other unit is a condensate well

Building · Main Category : Room

Catego	ry : Room	Building : Main					
			0 44			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>dminis</u> t	trative Suites/Offices						
	AC Unit	105	1	EA	7	6-10 years	
	Ceiling - Lay-in	105	450	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105	1	EA	6	10+ years	
	Floor - Tile	105	450	SF	6	10+ years	
	Lighting - Lay-in	105	1	EA	7	6-10 years	
	Lighting - Lay-in	105	8	EA	7	6-10 years	
	Power Distribution	105	8	EA	6	6-10 years	
	Storage/ Closet	105	129	SF	7	10+ years	
	Storage/ Closet	105	20	SF	5	1-2 years	Water damage.
	Walls - Plaster/Drywall	105	926	SF	6	10+ years	
	Ceiling - Lay-in	112 Store Room	354	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112 Store Room	1	EA	7	10+ years	
	Floor - Wood	112 Store Room	354	SF	6	10+ years	
	Lighting - Lay-in	112 Store Room	4	EA	7	6-10 years	
	Power Distribution	112 Store Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	112 Store Room	625	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor - Copy Room inside Classroom 100	82	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st floor - Copy Room inside Classroom 100	10	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	1st floor - Copy Room inside Classroom 100	1	EA	6	6-10 years	
	Floor - Wood	1st floor - Copy Room inside Classroom 100	92	SF	6	10+ years	
	Lighting - Pendent/Surface	1st floor - Copy Room inside Classroom 100	3	EA	6	6-10 years	
	Power Distribution	1st floor - Copy Room inside Classroom 100	2	EA	6	10+ years	
	Walls - Plaster/Drywall	1st floor - Copy Room inside Classroom 100	465	SF	6	10+ years	
	Work Slnk	1st floor - Copy Room inside Classroom 100	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	204C Store Room	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	204C Store Room	1	EA	6	6-10 years	
	Floor - Wood	204C Store Room	160	SF	6	10+ years	

Page : 7 of 51 Campus Name: Falconer Assessment Date: 07/14/2021



ategory : Room			В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	204C Store Room	1	EA	6	6-10 years	
	Power Distribution	204C Store Room	4	EA	6	10+ years	
	Walls - Plaster/Drywall	204C Store Room	816	SF	6	10+ years	
	Ceiling - Plaster/Drywall	205C Ms. Rubio Office	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	205C Ms. Rubio Office	1	EA	6	10+ years	
	Floor - Wood	205C Ms. Rubio Office	160	SF	6	10+ years	
	Lighting - Pendent/Surface	205C Ms. Rubio Office	2	EA	6	6-10 years	
	Power Distribution	205C Ms. Rubio Office	8	EA	6	10+ years	
	Walls - Plaster/Drywall	205C Ms. Rubio Office	816	SF	6	10+ years	
	AC Unit	212	1	EA	7	6-10 years	
	Ceiling - Lay-in	212	354	SF	6	10+ years	
	Doors - Wood Doors inclu hw	212	1	EA	6	10+ years	
	Floor - Wood	212	354	SF	6	10+ years	
	Lighting - Lay-in	212	4	EA	6	6-10 years	
	Power Distribution	212	8	EA	6	10+ years	
	Walls - Concrete Block	212	156	SF	6	10+ years	
	Walls - Plaster/Drywall	212	494	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3.5 floor - inside Gym	69	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3.5 floor - inside Gym	2	SF	4	1-2 years	Water damage.
	Doors - Wood Doors inclu hw	3.5 floor - inside Gym	1	EA	6	10+ years	
	Floor - Wood	3.5 floor - inside Gym	71	SF	6	10+ years	
	Lighting - Pendent/Surface	3.5 floor - inside Gym	2	EA	6	6-10 years	
	Power Distribution	3.5 floor - inside Gym	4	EA	6	10+ years	
	Walls - Plaster/Drywall	3.5 floor - inside Gym	344	SF	6	10+ years	
	Walls - Plaster/Drywall	3.5 floor - inside Gym	10	SF	5	1-2 years	Water damage.
	Ceiling - Plaster/Drywall	Basement	201	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	6	10+ years	
	Floor - Concrete	Basement	201	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	3	EΑ	7	6-10 years	
	Power Distribution	Basement	12	EΑ	6	10+ years	
	Storage/ Closet	Basement	208	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	427	SF	6	10+ years	
	Ceiling - Lay-in	Main Office - 104	455	SF	6	10+ years	
	Doors - Side-lite	Main Office - 104	16	SF	6	10+ years	
	Doors - Transom Window	Main Office - 104	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office - 104	1	EA	6	10+ years	
	Floor - Tile	Main Office - 104	455	SF	6	6-10 years	
	Lighting - Lay-in	Main Office - 104	10	EA	6	6-10 years	
	Power Distribution	Main Office - 104 Main Office - 104	10	EA	6	10+ years	
	Walls - Plaster/Drywall	Main Office - 104	926	SF	6	,	Paint needed around windows.
	AC Unit			SF EA	7	10+ years	raint needed afound windows.
		Principal's Office-Room 103	1	SF		6-10 years	
	Ceiling - Lay-in	Principal's Office-Room 103	455		6	10+ years	
	Doors - Side-lite	Principal's Office-Room 103	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office-Room 103	2	EA	5	10+ years	

Campus Name: Falconer Page : 8 of 51 Assessment Date: 07/14/2021



Category : Room		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Carpet	Principal's Office-Room 103	455	SF	6	6-10 years		
	Lighting - Lay-in	Principal's Office-Room 103	5	EA	7	6-10 years		
	Power Distribution	Principal's Office-Room 103	6	EA	6	10+ years		
	Walls - Plaster/Drywall	Principal's Office-Room 103	986	SF	6	10+ years		
	Ceiling - Lay-in	Room 103A-Testing	189	SF	7	10+ years		
	Ceiling - Lay-in	Room 103A-Testing	3	SF	4	0-1 year	Tile not sitting properly on grid.	
	Doors - Wood Doors inclu hw	Room 103A-Testing	1	EA	7	10+ years	3 , 3	
	Floor - Terrazzo	Room 103A-Testing	192	SF	4	0-1 year	Cracks in terrazo	
	Lighting - Lay-in	Room 103A-Testing	2	EA	7	6-10 years		
	Power Distribution	Room 103A-Testing	6	EA	7	10+ years		
	Walls - Plaster/Drywall	Room 103A-Testing	375	SF	7	10+ years		
	Ceiling - Lay-in	Staff Lounge Room 105- Nurse	410	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Staff Lounge Room 105- Nurse	1	EA	6	10+ years		
	Floor - Terrazzo	Staff Lounge Room 105- Nurse	410	SF	4	1-2 years	Cracked terrazzo	
	Lighting - Lay-in	Staff Lounge Room 105- Nurse	2	EA	7	6-10 years	Oracked terrazzo	
	Power Distribution	Staff Lounge Room 105- Nurse	4	EA	6	10+ years		
	Walls - Plaster/Drywall	Staff Lounge Room 105- Nurse	467	SF	6	10+ years		
	Walls - Flastel/Drywall	Stall Lounge Room 103- Nuise	407	OI .	U	10+ years		
Auditoriu	m & Theater							
	Balcony Seating	1st Floor	142	EA	5	2-5 years		
	Balcony Seating	1st Floor	48	EA	4	0-1 year	Broken, cracked, chipped seats.	
	Ceiling - Plaster/Drywall	1st Floor	4,169	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	10+ years		
	Floor - Concrete	1st Floor	4,169	SF	7	10+ years		
	Floor - Tile	1st Floor	1,888	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years		
	Lighting - Wall Mounted	1st Floor	30	EA	6	6-10 years		
	Lighting - Wall Mounted	1st Floor	48	EA	6	6-10 years		
	Main Floor Seating	1st Floor	454	ĒΑ	5	2-5 years		
	Main Floor Seating	1st Floor	78	EA	4	0-1 year	Pieces missing.	
	Sound System	1st Floor	1	EA	5	2-5 years	eeeeeeg.	
	Stage	1st Floor	1,376	SF	6	10+ years		
	Stage Curtain	1st Floor	2	EA	5	6-10 years		
	Stage Lighting System	1st Floor	1	EA	7	10+ years		
	Stage-Stairs - Wood	1st Floor	6	LF	6	10+ years		
	Stairs - Wood	1st Floor	10	LF	6	•		
	Storage/ Closet	1st Floor	68	SF	7	10+ years 10+ years		
	Walls - Plaster/Drywall	1st Floor		SF SF	, 6	,		
	walls - Plastel/Drywall	ISt Floor	10,393	SF	б	10+ years		
Gymnasi	a							
•	Ceiling - Plaster/Drywall	3.5 floor - West side of Main building	5,447	SF	6	10+ years		
	Doors - Transom Window	3.5 floor - West side of Main building	40	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3.5 floor - West side of Main building	1	EA	5	0-1 year	Door cracked at bottom.	
	Doors - Wood Doors inclu hw	3.5 floor - West side of Main building	1	EA	4	1-2 years	Damaged door at sill	
	_ 55.5	3.5 hos. Troot oldo of Main building	•	_, 、	'	. = youro	_ aagoa aooi at om	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3.5 floor - West side of Main building	5,447	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3.5 floor - West side of Main building	24	EA	6	6-10 years	
	Sound System	3.5 floor - West side of Main building	1	EA	7	6-10 years	
	Storage/ Closet	3.5 floor - West side of Main building	134	SF	7	10+ years	
	Walls - Plaster/Drywall	3.5 floor - West side of Main building	6,538	SF	7	10+ years	
	Walls - Plaster/Drywall	3.5 floor - West side of Main building	25	SF	4	1-2 years	Water damage by radiator.
MDF_ID	F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	115	SF	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	5	6-10 years	
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	7	SF	5	2-5 years	Damaged walls
	Mechanical/ Service Rooms	1st Floor	140	SF	5	6-10 years	•
	Storage Room	1st Floor	209	SF	5	6-10 years	
	Storage Room	1st Floor	7	SF	5	6-10 years	
	Storage Room	1st Floor	633	SF	5	6-10 years	
	Storage Room	1st Floor	124	SF	5	6-10 years	
	Janitor's Closet	1st Floor	7	SF	7	10+ years	
	Janitor's Closet	3rd Floor	7	SF	5	10+ years	
	Janitor's Closet	3rd Floor	7	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	7	SF	7	10+ years	
	Air Intake Plenums	Basement	215	SF	7	10+ years	
	Air Tunnel	Basement	4,427	SF	7	10+ years	
	Boiler Room	Basement	2,819	SF	7	10+ years	
	Coal Room	Basement	244	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	1,872	SF	7	10+ years	
Restroor	m						
	Accessories	1.5 Floor - NE of Assembly Hall	83	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 Floor - NE of Assembly Hall	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - NE of Assembly Hall	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	1.5 Floor - NE of Assembly Hall	83	SF	6	10+ years	
	Lavatory	1.5 Floor - NE of Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1.5 Floor - NE of Assembly Hall	1	EΑ	6	6-10 years	
	Partitions	1.5 Floor - NE of Assembly Hall	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	1.5 Floor - NE of Assembly Hall	365	SF	6	10+ years	
	Water Closet	1.5 Floor - NE of Assembly Hall	1	EA	6	6-10 years	
	Accessories	1.5 Floor - SW of Assembly Hall	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 Floor - SW of Assembly Hall	80	SF SF	6	10+ years	
	Doors - Wood Doors inclu hw	1.5 Floor - SW of Assembly Hall	1	SF EA		10+ years 10+ years	
				SF	6	•	
	Floor - Terrazzo	1.5 Floor - SW of Assembly Hall	80	or.	6	10+ years	

Campus Name: Falconer Page : 10 of 51 Assessment Date: 07/14/2021



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1.5 Floor - SW of Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1.5 Floor - SW of Assembly Hall	1	EA	7	6-10 years	
	Partitions	1.5 Floor - SW of Assembly Hall	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	1.5 Floor - SW of Assembly Hall	362	SF	6	10+ years	
	Water Closet	1.5 Floor - SW of Assembly Hall	1	EA	6	6-10 years	
	Accessories	1st Floor	350	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	350	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	350	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EA	6	6-10 years	
	Partitions	1st Floor	6	EA	5	2-5 years	
	Walls - Plaster/Drywall	1st Floor	640	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	545	SF	6	10+ years	
	Water Closet	1st Floor	5	EA	6	6-10 years	
	Accessories	1st Floor	350	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	350	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	350	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
		1st Floor	2	EA	6	6-10 years	
	Lavatory Lighting - Pendent/Surface	1st Floor	6	EA	6		
			1	EA		6-10 years	
	Partitions	1st Floor	5	EA	7 6	6-10 years	
	Urinals Walls - Plaster/Drywall	1st Floor 1st Floor	327	SF	6	6-10 years	
	•		545	SF SF	_	10+ years	
	Walls - Structural Glazed Tile	1st Floor			6	10+ years	
	Water Closet	1st Floor	1	EA	6	6-10 years	
	Accessories	2.5 Floor - NE of Assembly Hall	83	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2.5 Floor - NE of Assembly Hall	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2.5 Floor - NE of Assembly Hall	1	EA	6	6-10 years	
	Floor - Terrazzo	2.5 Floor - NE of Assembly Hall	83	SF	6	10+ years	
	Lavatory	2.5 Floor - NE of Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2.5 Floor - NE of Assembly Hall	1	EA	7	6-10 years	
	Partitions	2.5 Floor - NE of Assembly Hall	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2.5 Floor - NE of Assembly Hall	365	SF	6	10+ years	
	Water Closet	2.5 Floor - NE of Assembly Hall	1	EA	6	6-10 years	
	Accessories	2.5 Floor - SE of Assembly Hall	87	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2.5 Floor - SE of Assembly Hall	87	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2.5 Floor - SE of Assembly Hall	1	EA	6	6-10 years	
	Floor - Terrazzo	2.5 Floor - SE of Assembly Hall	87	SF	6	10+ years	
	Lavatory	2.5 Floor - SE of Assembly Hall	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2.5 Floor - SE of Assembly Hall	1	EA	6	6-10 years	



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2.5 Floor - SE of Assembly Hall	1	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	2.5 Floor - SE of Assembly Hall	443	SF	6	10+ years			
	Water Closet	2.5 Floor - SE of Assembly Hall	1	EA	6	6-10 years			
	Accessories	2nd Floor	350	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	350	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EΑ	7	10+ years			
	Lavatory	2nd Floor	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years			
	Partitions	2nd Floor	1	EA	7	6-10 years			
	Urinals	2nd Floor	5	EA	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	545	SF	6	10+ years			
	Water Closet	2nd Floor	1	EΑ	6	6-10 years			
	Accessories	2nd Floor	350	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	350	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	335	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	15	SF	4	0-1 year	Cracked.		
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	6	EΑ	7	6-10 years			
	Partitions	2nd Floor	6	EΑ	5	2-5 years			
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	545	SF	6	10+ years			
	Water Closet	2nd Floor	6	EΑ	6	6-10 years			
	Accessories	3rd Floor	240	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	240	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	240	SF	6	10+ years			
	Floor Drain	3rd Floor	2	EΑ	7	10+ years			
	Lavatory	3rd Floor	3	EΑ	6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	4	EΑ	6	6-10 years			
	Partitions	3rd Floor	2	EΑ	7	6-10 years			
	Walls - Concrete Block	3rd Floor	240	SF	6	10+ years			
	Water Closet	3rd Floor	2	EΑ	6	6-10 years			
	Accessories	3rd Floor	241	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	221	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	4	0-1 year	Water damage.		
	Floor - Terrazzo	3rd Floor	240	SF	7	10+ years	•		
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Lavatory	3rd Floor	3	EA	6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	6-10 years			
	<b>5 6 1.11 1.11</b>				-	,			

Campus Name: Falconer Page : 12 of 51 Assessment Date: 07/14/2021



Catego	ry : Room		Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Partitions	3rd Floor	2	EA	7	6-10 years				
	Walls - Concrete Block	3rd Floor	770	SF	6	10+ years				
	Water Closet	3rd Floor	2	EΑ	6	6-10 years				
	Accessories	Basement	28	SF	5	2-5 years				
	Ceiling - Plaster/Drywall	Basement	28	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	10+ years				
	Floor - Concrete Epoxy/ Painted	Basement	28	SF	5	10+ years				
	Lavatory	Basement	1	EΑ	6	6-10 years				
	Lighting - Wall Mounted	Basement	1	EΑ	6	6-10 years				
	Walls - Masonry	Basement	251	SF	6	10+ years				
	Water Closet	Basement	1	EA	6	6-10 years				
	Accessories	Inside classroom 100	57	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Inside classroom 100	57	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Inside classroom 100	1	EΑ	6	10+ years				
	Floor - Terrazzo	Inside classroom 100	57	SF	6	10+ years				
	Lavatory	Inside classroom 100	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	Inside classroom 100	1	EA	6	6-10 years				
	Partitions	Inside classroom 100	1	EA	5	2-5 years				
	Walls - Plaster/Drywall	Inside classroom 100	289	SF	6	10+ years				
	Walls - Plaster/Drywall	Inside classroom 100	6	SF	5	1-2 years	Minor water damage.			
	Water Closet	Inside classroom 100	1	EA	6	6-10 years				

Category : Classroom **Building: Main** 

arege	, ,					D	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	m #100 (Kindergarten)		,				
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	53	LF	4	0-1 year	Broken doors.
	Ceiling - Lay-in	1st Floor	2,013	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	2,013	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	23	EA	6	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,814	SF	6	10+ years	
ssroc	m #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	760	SF	6	6-10 years	
	Chalk Board	1st Floor	37	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	

Campus Name: Falconer Page : 13 of 51 Assessment Date: 07/14/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	760	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	62	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,251	SF	6	10+ years	
Classroo	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	4	1-2 years	Needs repair
	Ceiling - Lay-in	1st Floor	1,022	SF	6	6-10 years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,022	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,454	SF	6	10+ years	
			1,454	EA	7	,	
	Work Sink	1st Floor	ı	EA	,	6-10 years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	760	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	760	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	62	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,250	SF	6	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	834	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	834	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	62	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
CIASSIUC	,	1ot Floor	4		7	6 10 2000	
	AC Units	1st Floor	1	EA	7	6-10 years	



	ry : Classroom		В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	1st Floor	834	SF	6	6-10 years			
	Chalk Board	1st Floor	22	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Tile	1st Floor	814	SF	6	6-10 years			
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Rust stains, little chips, and holes		
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	rtaet etame, mae empe, and more		
	Walls - Plaster/Drywall	1st Floor	1,300	SF	6	10+ years			
assro	om #109 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	6	6-10 years	Door does not open properly		
	Ceiling - Lay-in	1st Floor	708	SF	7	6-10 years	Door doos not open properly		
	Chalk Board	1st Floor	22	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	-			
						6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Wood	1st Floor	760	SF	5	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Storage/ Closet	1st Floor	48	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,240	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Minor cracking.		
assro	om #110 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	4	1-2 years	Casework in need of repair or removal		
	Ceiling - Lay-in	1st Floor	760	SF	6	6-10 years	removal		
			700			,			
	Doore - Transom Window	1ct Floor	۵	QE.	6				
	Doors - Wood Doors include	1st Floor	9	SF EA	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Doors - Wood Doors inclu hw Floor - Wood	1st Floor 1st Floor	1 760	EA SF	6 6	10+ years 10+ years			
	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in	1st Floor 1st Floor 1st Floor	1 760 14	EA SF EA	6 6 7	10+ years 10+ years 6-10 years			
	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board	1st Floor 1st Floor 1st Floor 1st Floor	1 760 14 20	EA SF EA LF	6 6 7 6	10+ years 10+ years 6-10 years 6-10 years			
	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 760 14 20 48	EA SF EA LF SF	6 6 7 6 5	10+ years 10+ years 6-10 years 6-10 years 10+ years			
	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board	1st Floor 1st Floor 1st Floor 1st Floor	1 760 14 20	EA SF EA LF	6 6 7 6	10+ years 10+ years 6-10 years 6-10 years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units	1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units Casework	1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units	1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units Casework	1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units Casework Ceiling - Lay-in	1st Floor	1 760 14 20 48 1,250	EA SF EA LF SF EA LF SF	6 6 7 6 5 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 2-5 years			
assroo	Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Storage/ Closet Walls - Plaster/Drywall  om #111 (Regular Classroom) AC Units Casework Ceiling - Lay-in Chalk Board	1st Floor	1 760 14 20 48 1,250 1 1 10 760 22	EA SF EA LF SF EA LF SF LF	6 6 7 6 5 6 7 6 6 4	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years			

Campus Name: Falconer Page : 15 of 51 Assessment Date: 07/14/2021



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	5	0-1 year	Cover falling off.
	Marker Board	1st Floor	20	LF	6	6-10 years	•
	Storage/ Closet	1st Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,240	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	744	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water damaged.
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	Transom panel removed & replaced w/ painted plywood.
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	w/ painted plywood.
				SF		•	
	Floor - Wood	2nd Floor	760		6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	14	EA	7	6-10 years	
		2nd Floor 2nd Floor	22	LF	7		
	Marker Board		22 48	SF	, 5	6-10 years	
	Storage/ Closet	2nd Floor	48	<b>5</b> F	Э	10+ years	

Campus Name: Falconer Page : 16 of 51 Assessment Date: 07/14/2021



Category : Classroom			В	uilding	Building : Main				
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	Paint cracking and peeling above Smart board.		
Classroo	om #204 (Computer Lab)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Ceiling - Lay-in	2nd Floor	806	SF	6	6-10 years			
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	806	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	68	SF	5	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,820	SF	6	10+ years			
	Wireless System	2nd Floor	1	ĒΑ	7	6-10 years			
Classroo	om #205 (Computer Lab)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	780	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years			
	Floor - Wood	2nd Floor	780	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years			
	Storage/ Closet	2nd Floor	20	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,820	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
Classroo	nm #206 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	6-10 years			
	Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	760	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	22	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	48	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years			
lassroo	om #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	760	SF	6	, , , , , , , , ,			



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	760	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	22	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	48	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	Paint chipping.		
Classroc	nm #208 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	6-10 years			
	Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood Doors inclu riw	2nd Floor 2nd Floor	760	SF	6	-			
					_	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	22	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	48	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years			
Classroc	nm #209 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	757	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Missing ceiling tile.		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	760	SF	6	10+ years			
	Floor - Wood	2nd Floor	10	SF	4	0-1 year	Floor buckling.		
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	r reer buoking.		
	Marker Board	2nd Floor	22	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	48	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,270	SF	6	10+ years			
Classroo	om #210 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	13	LF	6	6-10 years	Door at casework missing		
	Casework Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years	Door at casework imponing		
	Doors - Transom Window	2nd Floor 2nd Floor	9	SF	6	,			
						6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	760	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years			
	Marker Board	2nd Floor	22	LF	6	6-10 years			



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	754	SF	6	10+ years	
	Floor - Tile	2nd Floor	6	SF	4	0-1 year	Missing tiles.
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	
_Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,240	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Hole in wall.
_Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EΑ	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Wood	3rd Floor	760	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	14	ĒΑ	6	6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	48	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	Paint chipping and peeling.		
Classroo	om #304 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	8	LF	6	6-10 years			
	Ceiling - Lay-in	3rd Floor	858	SF	6	6-10 years			
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years			
			1		_	6-10 years			
	Doors - Wood Doors inclu hw	3rd Floor		EA SF	6				
	Floor - Wood	3rd Floor	858		6	10+ years			
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	20	SF	5	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,930	SF	6	10+ years			
Classroo	om #305 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	6	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	858	SF	6	6-10 years			
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years			
	Floor - Wood	3rd Floor	858	SF	6	10+ years			
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	68	SF	5	•			
	Walls - Plaster/Drywall	3rd Floor	1,929	SF	6	10+ years 10+ years	Paint chipping and peeling.		
N	·		,			,	11 3 1 3		
Jassro0	om #305C (Store Room)  Ceiling - Plaster/Drywall	3rd Floor	165	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	103	EA	6	10+ years			
	Floor - Wood Doors Inclu riw	3rd Floor		SF	6				
			165			10+ years			
	Lighting - Lay-in	3rd Floor	3	EA	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	591	SF	6	10+ years			
lassro	om #306 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	10	LF	6	6-10 years			
		3rd Floor	760	SF	6	6-10 years			
	Ceiling - Lay-in								



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	757	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	3	SF	4	0-1 year	Missing tiles.
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	wissing tiles.
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
		3rd Floor		EA	7		
	Lighting - Lay-in Marker Board	3rd Floor	14 22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor		SF	, 5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	48 1,244	SF SF	5 6	10+ years 10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
<u> </u>	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor 3rd Floor	757	SF			
				SF SF	6	6-10 years	Missing soiling tile
	Ceiling - Lay-in	3rd Floor	3		4	0-1 year	Missing ceiling tile.
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	



Category : Classroom		В	uilding				
_						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	28	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	10+ years	
lassroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,244	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	6	SF	6	2-5 years	
	wans - vinyi coated Gypsum i anei	310 1 1001	O	OI .	O	2-5 years	
lassroc	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	_10	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	10+ years	Touch-up paint above millwork
							header around room
lassroc	om #312 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	354	SF	6	6-10 years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	354	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	299	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	635	SF	6	10+ years	
assroo	om #400 (Music Room)						
	Ceiling - Lay-in	3rd Floor	319	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	CHAIN DUAIU	314 F1001	0	LF	4	2-0 years	



Category : Classroom			Building : Main				
				Recommend			
Location	Quantity	UOM	Rank	Replacement	Comments		
3rd Floor	2	EA	6	6-10 years			
3rd Floor	319	SF	6	10+ years			
3rd Floor	4	EA	7	6-10 years			
3rd Floor	5	LF	6	2-5 years			
3rd Floor	325	SF	5	10+ years			
3rd Floor	884	SF	6	10+ years			
	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	LocationQuantity3rd Floor23rd Floor3193rd Floor43rd Floor53rd Floor3253rd Floor884	LocationQuantityUOM3rd Floor2EA3rd Floor319SF3rd Floor4EA3rd Floor5LF3rd Floor325SF3rd Floor884SF	Location         Quantity         UOM         Rank           3rd Floor         2         EA         6           3rd Floor         319         SF         6           3rd Floor         4         EA         7           3rd Floor         5         LF         6           3rd Floor         325         SF         5	Location         Quantity         UOM         Rank         Replacement           3rd Floor         2         EA         6         6-10 years           3rd Floor         319         SF         6         10+ years           3rd Floor         4         EA         7         6-10 years           3rd Floor         5         LF         6         2-5 years           3rd Floor         325         SF         5         10+ years           3rd Floor         884         SF         6         10+ years		

Category : Interior **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
Comaoi	Ceiling - Lay-in	1st Floor	3,426	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,636	SF	6	10+ years	
	Doors - Transom Window	1st Floor	180	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	15	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	7,206	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	28	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,856	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,288	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,784	SF	6	6-10 years	
	Doors - Wood Doors include hw	2nd Floor	2	ĒΑ	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	4,080	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	40	EΑ	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	12	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,948	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,784	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	138	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	5	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	4,080	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	40	EA	7	10+ years	Total 48
	Student Lockers - Two Tiers	3rd Floor	48	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6,948	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Vestibule West of Assembly Hall	342	SF	6	10+ years	
	Doors - Wood Doors include hw	Vestibule West of Assembly Hall	3	EΑ	6	10+ years	
	Floor - Terrazzo	Vestibule West of Assembly Hall	342	SF	6	10+ years	
	Lighting - Pendent/Surface	Vestibule West of Assembly Hall	6	EA	7	10+ years	
	Stairs - Concrete Stairs	Vestibule West of Assembly Hall	6	LF	6	10+ years	
	Walls - Plaster/Drywall	Vestibule West of Assembly Hall	976	SF	6	10+ years	

Campus Name: Falconer Page : 23 of 51 Assessment Date: 07/14/2021



Catego	Category : Interior			uilding	: Main		
<b>.</b>	H T	Landin	0	11014	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
	Camera Viewing Station	1st Floor	2	EA	5	2-5 years	
	Security Cameras	1st Floor	2	EA	4	1-2 years	Older cameras.
Stairs							
Dialis	Ceiling - Plaster/Drywall	Basement	82	SF	6	10+ years	
	Floor - Concrete	Basement	45	SF	5	10+ years	
	Handrails	Basement	20	LF	5	2-5 years	
	Lighting - Pendent/Surface	Basement	2	EA	6	6-10 years	
	Stairs - Concrete	Basement	10	LF	6	10+ years	
	Walls - Masonry	Basement	611	SF	6	10+ years	
	Ceiling - Plaster/Drywall	NW Center Stair - north of court	689	SF	6	-	
	Floor - Terrazzo	NW Center Stair - north of court	565	SF	5	10+ years	
				LF		2-5 years	
	Handrails Lighting - Pendent/Surface	NW Center Stair - north of court NW Center Stair - north of court	134 4	EA	5 5	2-5 years 2-5 years	
			66	LF			
	Stairs - Concrete	NW Center Stair - north of court		SF	5	10+ years	
	Walls - Plaster/Drywall	NW Center Stair - north of court	2,976		5	10+ years	
	Ceiling - Plaster/Drywall	NW Stairs from Assembly Hall Vestibule	253	SF	6	10+ years	
	Floor - Asphalt	NW Stairs from Assembly Hall	195	SF	6	10+ years	
	1 looi - Aspilali	Vestibule	133	Oi	U	10+ years	
	Handrails	NW Stairs from Assembly Hall	33	LF	7	6-10 years	
	Tianurans	Vestibule	33	LI	′	0-10 years	
	Lighting - Pendent/Surface	NW Stairs from Assembly Hall	3	EA	6	6-10 years	
	Lighting - Fendent/Surface	Vestibule	3	LA	O	0-10 years	
	Ctaire Apphalt		17	LF	6	10	
	Stairs - Asphalt	NW Stairs from Assembly Hall Vestibule	17	LF	6	10+ years	
	Malla Diactor/Dwww.		4.040	C.E.	•	10	
	Walls - Plaster/Drywall	NW Stairs from Assembly Hall	1,012	SF	6	10+ years	
	On the second	Vestibule	400	0-	^	0.40	
	Ceiling - Lay-in	North Stairs in Main Building	482	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	North Stairs in Main Building	133	SF	6	6-10 years	AA7 1 11 P
	Floor - Asphalt	North Stairs in Main Building	293	SF	4	1-2 years	Worn, bubbling.
	Handrails	North Stairs in Main Building	121	LF	5	2-5 years	
	Lighting - Lay-in	North Stairs in Main Building	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	North Stairs in Main Building	1	EA	6	6-10 years	
	Stairs - Asphalt	North Stairs in Main Building	56	LF	6	2-5 years	
	Walls - Plaster/Drywall	North Stairs in Main Building	1,140	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	SW Center Stair - south of court	689	SF	6	6-10 years	Paint chipping and peeling.
	Floor - Asphalt	SW Center Stair - south of court	565	SF	6	6-10 years	
	Handrails	SW Center Stair - south of court	134	LF	4	2-5 years	
	Lighting - Pendent/Surface	SW Center Stair - south of court	4	EA	5	2-5 years	
	Stairs - Asphalt	SW Center Stair - south of court	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	SW Center Stair - south of court	2,976	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SW Stairs from Assembly Hall	194	SF	6	10+ years	



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Vestibule					
	Floor - Asphalt	SW Stairs from Assembly Hall	136	SF	6	10+ years	
		Vestibule					
	Handrails	SW Stairs from Assembly Hall	33	LF	7	6-10 years	
		Vestibule					
	Lighting - Pendent/Surface	SW Stairs from Assembly Hall	3	EA	6	6-10 years	
		Vestibule					
	Stairs - Asphalt	SW Stairs from Assembly Hall	17	LF	6	10+ years	
		Vestibule					
	Walls - Plaster/Drywall	SW Stairs from Assembly Hall	734	SF	6	10+ years	
		Vestibule					
	Ceiling - Lay-in	South Stairs in Main Building	482	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	South Stairs in Main Building	133	SF	6	10+ years	
	Floor - Asphalt	South Stairs in Main Building	293	SF	4	1-2 years	Bubbling.
	Handrails	South Stairs in Main Building	121	LF	5	2-5 years	
	Lighting - Lay-in	South Stairs in Main Building	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	South Stairs in Main Building	1	EA	6	6-10 years	
	Stairs - Asphalt	South Stairs in Main Building	56	LF	4	1-2 years	Bubbling.
	Walls - Plaster/Drywall	South Stairs in Main Building	1,140	SF	6	10+ years	





Category : Exterior **Building: Addition** 

	ory : Exterior	Building : Addition						
	_					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ntrance								
	Exterior Doors - Exterior Steel Door	#10-SW	2	EA	6	6-10 years	Painting required.	
	Exterior Doors - Exterior Steel Door	#11-NW	2	EA	6	6-10 years	Painting required.	
	Exterior Doors - Exterior Steel Door	#12-NW	2	EΑ	6	6-10 years		
	Entrance Control - Audio	#13-NE	1	EA	6	2-5 years		
	Exterior Doors - Store Front	#13-NE	4	EA	7	10+ years		
	Exterior Doors - Transom Lite	#13-NE	2	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	#7-Courtyard	2	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#7.5 SE	1	EA	5	2-5 years	Door dented.	
	Exterior Doors - Exterior Steel Door	#8-SW	2	EA	6	6-10 years	Painting needed.	
	Exterior Doors - Exterior Steel Door	#9 - Kitchen	1	EA	6	6-10 years		
oundat	tion							
	Foundation - Concrete	Entire Building	1,200	LF	7	10+ years		
	Superstructure - Slab on Grade	Entire Building	82,797	SF	7	2-5 years	Settlement Reflected/Starting at Sla	
	•	3	,			,	Expansion Member - Spreads as it	
							progresses to 2nd/3rd Floor. Slab	
							Settlement in Multi-Purpose Room	
ighting		F (	40			0.40		
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EΑ	7	6-10 years		
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	6-10 years		
Roof Sy								
	Coping - Stone	#6	225	LF	6	6-10 years		
	Downspouts - Interior Downspouts	#6	19	LF	6	6-10 years		
	Parapet - 16" - 30" Height	#6	35	LF	7	6-10 years		
	Parapet - 16" - 30" Height	#6	190	LF	6	6-10 years		
	Roof - Modified Bitumen	#6	2,383	SF	6	6-10 years		
	Roof Structure - Steel / Metal Deck/	#6	2,383	SF	7	10+ years		
	Concrete Topping							
	Access Ladder - Metal	#7	1	EA	7	10+ years		
	Coping - Stone	#7	531	LF	6	6-10 years		
	Coping - Stone	#7	10	LF	5	6-10 years		
	Downspouts - Interior Downspouts	#7	300	LF	6	6-10 years		
	Downopoulo interior Downopoulo		541	LF	6	6-10 years		
	Parapet - Parapet < 16" Height	#7						
		# <i>1</i> #7	15,855	SF	6	6-10 years		
	Parapet - Parapet < 16" Height				6 7	6-10 years 10+ years		
	Parapet - Parapet < 16" Height Roof - Modified Bitumen Roof Hatch - Metal	#7	15,855	SF				
	Parapet - Parapet < 16" Height Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/	#7 #7	15,855 1	SF EA	7	10+ years		
	Parapet - Parapet < 16" Height Roof - Modified Bitumen Roof Hatch - Metal	#7 #7	15,855 1	SF EA	7	10+ years		

Campus Name: Falconer Page : 26 of 51 Assessment Date: 07/14/2021



Catego	ory : Exterior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chimney - Metal Flue	#8	38	LF	6	2-5 years	
	Coping - Stone	#8	308	LF	7	6-10 years	
	Downspouts - Interior Downspouts	#8	204	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#8	318	LF	6	6-10 years	
	Roof - Modified Bitumen	#8	9,361	SF	6	6-10 years	
	Roof Hatch - Metal	#8	1	ĒΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/	#8	9,361	SF	7	10+ years	
	Concrete Topping		0,001	O.	•	.o. you.o	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	7,200	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50,948	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	50	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4,848	SF	6	6-10 years	
Window	S						
	Curtain wall - Glazed Double Pane	Entire Building	480	SF	7	6-10 years	
	Guard - Guards perforated	Entire Building	806	SF	7	6-10 years	
	Guard - Guards perforated	Entire Building	1,302	SF	7	6-10 years	
	Lintels - Steel	Entire Building	693	LF	5	6-10 years	
	Storefront Windows	Entire Building	100	SF	7	6-10 years	
	Windows - Louver	Entire Building	400	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,138	SF	7	6-10 years	
Catego	ory : Electrical		В	uilding	: Additi	on	
	•			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Serves addition
	Emergency A/C Power - Corridors and Stairs	Entire Building	18,071	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	5,024	SF	6	10+ years	
						10+ years	
		Entire Building	1.042	SF	6		
	Emergency A/C Power - Lunchrooms	Entire Building Entire Building	1,042 964	SF SF	_		
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets	Entire Building	964	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV	Entire Building Entire Building	964 82,797	SF SF	6 5	10+ years 2-5 years	
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building Entire Building	964 82,797 82,797	SF SF SF	6 5 5	10+ years 2-5 years 2-5 years	No battery back-up
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	964 82,797 82,797 19	SF SF SF EA	6 5 5 2	10+ years 2-5 years 2-5 years 0-1 year	No battery back-up
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	964 82,797 82,797 19	SF SF SF EA EA	6 5 5 2 2	10+ years 2-5 years 2-5 years 0-1 year 0-1 year	No battery back-up
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom	Entire Building	964 82,797 82,797 19 4	SF SF SF EA EA	6 5 5 2 2 2	10+ years 2-5 years 2-5 years 0-1 year 0-1 year 0-1 year	·
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs	Entire Building	964 82,797 82,797 19 4 2	SF SF SF EA EA EA	6 5 5 2 2 2 6	10+ years 2-5 years 2-5 years 0-1 year 0-1 year 0-1 year 6-10 years	No battery back-up
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Security System - CCTV Security System - Intrusion Detection Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and	Entire Building	964 82,797 82,797 19 4	SF SF SF EA EA	6 5 5 2 2 2	10+ years 2-5 years 2-5 years 0-1 year 0-1 year 0-1 year	No battery back-up



#### **Laughlin Falconer Elementary School**

Catego	ry : Electrical		Building : Addition					
Julego	. y . =			ananig	. Additi	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
J. Gup	Room	2004	quantity	<b>O</b>	rtariit	rtopiacomont		
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years		
	Emergency Battery Factor Citatorite Felicie	Zittiro Ballallig	ŭ	_, `	Ū	o io jouio		
lain Se	rvice							
IGIII OO	Main Electrical Service - 2000 A	Electrical Room	1	EA	7	10+ years	Serves addition	
	277/480/3PH	Electrical Room	'	L/ \	,	101 years	ocives addition	
	Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	Serves addition	
	emergency power	2.001.1001.1	·	_, `	Ū	ioi youlo	Corvos addition	
	PA System	Entire Building	82,797	SF	5	2-5 years	Connected to main building	
	. A System	Zimio Bananig	02,707	O.	Ŭ	2 o youro	Commedica to main ballaning	
ower D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years		
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years		
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years		
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years		
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years		
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years		
- Cotomo	wy . Fire Dretection		D	المائدة	. A alaliti			
Jalego	ry : Fire Protection		D	ullullig	: Additi	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ire Alar						•		
	Fire Alarm Strobe Lights	Mechanical Room	82,797	SF	6	10+ years		
	Fire Alarm_System	Mechanical Room	82,797	SF	6	6-10 years	Serves addition building	
	Fire Pump Controller	Mechanical Room	1	EA	6	10+ years		
Dumn D	acom Accombly							
-ump Ri	oom Assembly Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	6 10 40000	Sorves addition only	
			1	EA EA	6 6	6-10 years	Serves addition only	
	Jockey Pump	Mechanical Room	1	EA	Ö	6-10 years		
Sprinklei	System							
	Sprinkler Heads	Entire Building	82,797	SF	7	10+ years		
	Sprinkler Piping	Entire Building	82,797	SF	7	10+ years		
	Wet Sprinkler System	Entire Building	82,797	SF	6	10+ years	Serves addition only	
		9	02,.07	٥.	•	. c . y care		

Campus Name: Falconer Page : 28 of 51 Assessment Date: 07/14/2021



Category : Mechanical			В	uilding	: Additi	on	3020 W Lamon Avenue, Onicago, ie o	
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ir Cond	litioning							
	Chemical Pot Feeder	Roof	1	EA	5	2-5 years		
	Chiller-Air Cooled- Recipricating-Roof Mounted - 201 - 300 tons	Roof	1	EA	6	10+ years	Per engineer, installed in 2020	
	Glycol Feed	Roof	1	EA	6	10+ years		
	Pipes - Chilled Water Pipe- Steel	Roof	400	LF	6	10+ years		
	Pressure Fill System	Roof	1	EA	6	10+ years		
ir Hand	ling Systems							
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	54	EA	5	6-10 years	Above ceilings	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	6	10+ years		
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3 gym and kitchen, addition building	
	Air Intake	Mechanical Room	1	EA	6	10+ years		
	VAV Box	Mechanical Room	5	EA	6	6-10 years	Above ceilings	
	Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 10001-15000 cfm	Mechanical Room	1	EA	5	2-5 years	AHU2, serves addition	
	Air Intake	Mechanical Room	1	EA	6	10+ years		
	Zone Dampers	Mechanical Room	2	EA	6	10+ years	Above ceilings	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, first floor, serves addition building	
	Air Intake	Mechanical Room	1	EA	6	10+ years		
	VAV Box	Mechanical Room	10	EA	6	6-10 years	Above ceilings	
	Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - Less than 6000 cfm	Roof	1	EA	5	6-10 years	For kitchen	
Boiler Sy	vstems							
•	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Mechanical Room	3	EA	7	10+ years		
	Chemical Pot Feeder	Mechanical Room	1	EA	6	10+ years		
	Combustion Dampers	Mechanical Room	3	EA	6	10+ years		
	Glycol Feed System	Mechanical Room	1	EA	6	10+ years		
	Hot Water Pump	Mechanical Room	3	EA	7	10+ years	Boiler primary pumps inline.	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001	Mechanical Room	3	EA	7	10+ years	Serve addition building	

Campus Name: Falconer Page : 29 of 51 Assessment Date: 07/14/2021



Catego	ry : Mechanical		В	uilding	: Additi		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	- 2000 MBH				_		
	Water Fill System	Mechanical Room	1	EA	6	10+ years	
as Boo	ster						
	Gas Booster	Mechanical Room	1	EA	6	6-10 years	
eating I	Devices						
•	Unit Heater - Electric	Boiler Room	2	EA	6	6-10 years	
	Unit Heater - Hot Water	Boiler Room	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	10+ years	Ceiling mounted
1echani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	900	LF	6	10+ years	Hot water pipes
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	Chilled water pipes
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	Serve addition building
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	6-10 years	Serve main building
emnera	ture Control						
Спрста	DDC System	Entire Building	82,797	SF	6	6-10 years	Original equipment, 2001, per
	DDO Gystem	Little Building	02,797	Oi.	O	0-10 years	engineer, serves addition, upgraded software in 2015
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serve make-up unit and Lieberman unit, unit heaters
	Thermostats - DDC	Entire Building	91	EA	6	6-10 years	2001 installation
entilatio	on .						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	2-5 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Serves dishwasher
atego	ry : Plumbing		В	uildina	: Additi	on	
J	·					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
.or vvale	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	Serve addition
	Cas 1   Calci - 100000 - 300000 D10/ITK	IVICUITALIICAI INDUITI	2	LA	O	o- io yeais	Jei ve addition



Catego	ry : Plumbing	В							
_	_		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Domestic Piping-Hot Water Return Lines	Entire Building	82,716	SF	6	10+ years			
	Domestic Piping-Hot Water Return Risers	Entire Building	82,716	SF	6	10+ years			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	82,716	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	82,716	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	82,716	SF	6	10+ years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	82,716	SF	6	10+ years			
	Sanitary Piping	Entire Building	82,716	SF	6	10+ years			
	Storm Piping	Entire Building	82,716	SF	6	10+ years			
	Vent Piping	Entire Building	82,716	SF	6	10+ years			
Pumps									
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	10+ years	Serves both buildings		
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years	Under elevator		

Category: Room **Building: Addition** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	trative Suites/Offices					·	
	Ceiling - Lay-in	Conference Room inside Office Suites	121	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Conference Room inside Office Suites	43	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Conference Room inside Office Suites	1	EA	6	10+ years	
	Floor - Tile	Conference Room inside Office Suites	164	SF	6	6-10 years	
	Lighting - Lay-in	Conference Room inside Office Suites	2	EA	7	6-10 years	
	Power Distribution	Conference Room inside Office Suites	6	EA	6	10+ years	
	Walls - Concrete Block	Conference Room inside Office Suites	174	SF	6	10+ years	
	Walls - Plaster/Drywall	Conference Room inside Office Suites	454	SF	6	10+ years	
	Ceiling - Lay-in	Counselor's Office in Main Office	8	SF	7	6-10 years	
	Ceiling - Lay-in	Counselor's Office in Main Office	104	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Counselor's Office in Main Office	1	EA	6	10+ years	
	Floor - Tile	Counselor's Office in Main Office	112	SF	6	6-10 years	
	Lighting - Lay-in	Counselor's Office in Main Office	1	EA	7	6-10 years	
	Power Distribution	Counselor's Office in Main Office	8	EA	6	10+ years	

Campus Name: Falconer Page : 31 of 51 Assessment Date: 07/14/2021



Catego	ry : Room		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	Counselor's Office in Main Office	443	SF	6	10+ years		
	Ceiling - Lay-in	Faculty Service Room	324	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Faculty Service Room	1	EA	6	10+ years		
	Floor - Tile	Faculty Service Room	340	SF	6	6-10 years		
	Lighting - Lay-in	Faculty Service Room	2	EA	7	6-10 years		
	Power Distribution	Faculty Service Room	6	EA	6	10+ years		
	Walls - Concrete Block	Faculty Service Room	577	SF	6	10+ years		
	Walls - Plaster/Drywall	Faculty Service Room	177	SF	6	10+ years		
	Ceiling - Lay-in	Kitchen Office	42	SF	6	6-10 years		
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	6	10+ years		
	Floor - Tile	Kitchen Office	42	SF	6	6-10 years		
	Lighting - Lay-in	Kitchen Office	2	EA	7	6-10 years		
	Power Distribution	Kitchen Office	6	EA	6	10+ years		
	Walls - Concrete Block	Kitchen Office	250	SF	6	10+ years		
	Ceiling - Lay-in	Main Office	445	SF	6	6-10 years		
	Doors - Side-lite	Main Office	124	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years		
	Floor - Terrazzo	Main Office	145	SF	6	10+ years		
	Floor - Tile	Main Office	430	SF	6	6-10 years		
	Lighting - Lay-in	Main Office	12	ĒΑ	7	6-10 years		
	Power Distribution	Main Office	8	EA	6	10+ years		
	Walls - Concrete Block	Main Office	1,156	SF	6	10+ years		
	Walls - Plaster/Drywall	Main Office	553	SF	6	10+ years		
	Ceiling - Lay-in	Media Center - Work Room	171	SF	6	10+ years		
	Doors - Side-lite	Media Center - Work Room	12	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Media Center - Work Room	1	ĒΑ	6	10+ years		
	Floor - Carpet	Media Center - Work Room	171	SF	6	6-10 years		
	Lighting - Lay-in	Media Center - Work Room	2	ĒΑ	7	6-10 years		
	Power Distribution	Media Center - Work Room	6	EA	6	10+ years		
	Storage/ Closet	Media Center - Work Room	180	SF	7	10+ years		
	Walls - Concrete Block	Media Center - Work Room	150	SF	6	10+ years		
	Walls - Plaster/Drywall	Media Center - Work Room	450	SF	6	10+ years		
	Work Slnk	Media Center - Work Room	1	EΑ	7	6-10 years		
	Ceiling - Lay-in	Staff lounge	8	SF	7	10+ years		
	Ceiling - Lay-in	Staff lounge	442	SF	6	6-10 years	Dirty, needs to be cleaned.	
	Doors - Wood Doors inclu hw	Staff lounge	1	EA	6	10+ years	Sitty, neede to be cleaned.	
	Floor - Tile	Staff lounge	450	SF	6	6-10 years		
	Lighting - Lay-in	Staff lounge	3	EA	7	6-10 years		
	Power Distribution	Staff lounge	12	EA	6	10+ years		
	Walls - Concrete Block	Staff lounge	1,200	SF	6	10+ years		
	Work Sink	Staff lounge	1,200	EA	7	6-10 years		
	Ceiling - Lay-in	Student Services in Main Office	121	SF	6	6-10 years		
	Ceiling - Lay-in Ceiling - Plaster/Drywall	Student Services in Main Office	42	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Student Services in Main Office	1	EA	6	10+ years		
	200.0 11000 20010 III010 IIW	Stadont Corvided in Main Office	•	_/\	J	ioi youis		



Catego	ry : Room		Building : Addition					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	Student Services in Main Office	163	SF	6	6-10 years		
	Lighting - Lay-in	Student Services in Main Office	2	EA	7	6-10 years		
	Power Distribution	Student Services in Main Office	6	EA	6	6-10 years		
	Walls - Concrete Block	Student Services in Main Office	174	SF	6	10+ years		
	Walls - Plaster/Drywall	Student Services in Main Office	454	SF	6	10+ years		
	Work SInk	Student Services in Main Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	Vault Work Room in Main Office	170	SF	6	6-10 years		
	Ceiling - Lay-in	Vault Work Room in Main Office	8	SF	4	0-1 year	Ceiling tile off of grid	
	Doors - Steel Doors incl hw	Vault Work Room in Main Office	1	EA	6	10+ years		
	Floor - Tile	Vault Work Room in Main Office	178	SF	6	6-10 years		
	Lighting - Lay-in	Vault Work Room in Main Office	2	EA	7	6-10 years		
	Power Distribution	Vault Work Room in Main Office	4	EA	6	10+ years		
	Walls - Concrete Block	Vault Work Room in Main Office	646	SF	6	10+ years		
	Work SInk	Vault Work Room in Main Office	1	EA	7	6-10 years		
_Gvmnas	ia							
,	Ceiling - Exposed	1st Floor	5,024	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	10+ years		
	Floor - Tile/Sheet	1st Floor	5.024	SF	5	2-5 years		
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years		
	Storage/ Closet	1st Floor	560	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	6,628	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	3,000	SF	6	10+ years		
Kitchen								
	Ceiling - Lay-in	1st Floor	998	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor	1,000	SF	7	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor	42	SF	5	0-1 year	Cracking.	
	Lighting - Lay-in	1st Floor	10	ĒA	7	6-10 years	3	
	Storage/ Closet	1st Floor	150	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,327	SF	5	10+ years		
Library								
	Casework	2nd- Media Center	70	LF	6	10+ years		
	Ceiling - Lay-in	2nd- Media Center	2,284	SF	6	6-10 years		
	Ceiling - Lay-in	2nd- Media Center	10	SF	4	1-2 years	Water damage.	
	Doors - Side-lite	2nd- Media Center	24	SF	6	10+ years	•	
	Doors - Wood Doors inclu hw	2nd- Media Center	2	ĒΑ	6	10+ years		
	Floor - Carpet	2nd- Media Center	2,290	SF	7	6-10 years		
	Floor - Carpet	2nd- Media Center	4	SF	4	1-2 years	Ripped.	
	Lighting - Lay-in	2nd- Media Center	27	ĒΑ	7	6-10 years		
	Walls - Plaster/Drywall	2nd- Media Center	311	SF	6	10+ years		
	•					-		



Catego	ry : Room		Building : Addition  Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ookor/S	hower Poom							
_ockei/S	hower Room	Kitchen Leeker Deem	4.4	SF	7	6.10 veers		
	Accessories	Kitchen Locker Room	44	SF SF	7	6-10 years		
	Ceiling - Lay-in	Kitchen Locker Room	44		6	6-10 years		
	Doors - Wood Doors inclu hw	Kitchen Locker Room	1	EA	7	10+ years		
	Floor - Terrazzo	Kitchen Locker Room	44	SF	7	10+ years		
	Lighting - Lay-in	Kitchen Locker Room	1	EΑ	7	6-10 years		
	Student Lockers - One Tier	Kitchen Locker Room	7	EA	6	6-10 years		
	Walls - Concrete Block	Kitchen Locker Room	263	SF	6	10+ years		
unch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	1,042	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	6	10+ years		
	Floor - Tile	1st Floor	1,042	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Serving Line	1st Floor	42	LF	6	6-10 years		
	Storage/ Closet	1st Floor	65	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,539	SF	6	10+ years		
/IDF_ID	=							
טווטוי	Doors - Wood Doors inclu hw	MDF near 220	1	EA	6	10+ years		
	Finishes	MDF near 220	140	SF	5	10+ years		
	Other Cooling Unit	MDF near 220	140	EA	5	6-10 years	Ductless split system.	
	Other Cooling Offic	MDI Heal 220	'	LA	3	0-10 years	Ductiess split system.	
<u>lechani</u>	cal/ Service Rooms							
	Janitor's Closet	1st Floor	75	SF	5	6-10 years	Paint walls.	
	Mechanical/ Service Rooms	1st Floor	76	SF	7	6-10 years		
	Storage Room	1st Floor	18	SF	7	6-10 years		
	Vaults	1st Floor	291	SF	7	6-10 years		
	Janitor's Closet	2nd Floor	43	SF	7	6-10 years		
	Mechanical/ Service Rooms	2nd Floor	3,393	SF	7	6-10 years		
	Storage Room	2nd Floor	240	SF	7	6-10 years		
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	Janitor Closet was not included	
	Storage Room	3rd Floor	404	SF	7	6-10 years	during previous assessment	
						-		
estroor		442	00		7	6.40		
	Accessories	113	38	SF	7	6-10 years		
	Ceiling - Lay-in	113	38	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	113	1	EA	7	10+ years		
	Floor - Terrazzo	113	38	SF	7	10+ years		
	Floor Drain	113	1	EA	7	10+ years		
	Lavatory	113	1	EA	7	6-10 years		

Campus Name: Falconer Page : 34 of 51 Assessment Date: 07/14/2021



Category : Room		В	uilding	: Addition			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	113	1	EA	7	6-10 years	
	Walls - Concrete Block	113	198	SF	6	10+ years	
	Water Closet	113	1	EA	6	6-10 years	
	Accessories	114	38	SF	7	6-10 years	
	Ceiling - Lay-in	114	38	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	114	1	EA	6	6-10 years	
	Floor - Terrazzo	114	38	SF	6	10+ years	
	Floor Drain	114	1	EA	7	6-10 years	
	Lavatory	114	1	EA	6	6-10 years	
	Lighting - Lay-in	114	1	EA	7	6-10 years	
	Walls - Concrete Block	114	198	SF	6	10+ years	
	Water Closet	114	1	EA	6	6-10 years	
	Accessories	115	38	SF	7	6-10 years	
	Ceiling - Lay-in	115	38	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	115	1	ĒΑ	7	6-10 years	
	Floor - Terrazzo	115	38	SF	7	10+ years	
	Floor Drain	115	1	ĒΑ	7	6-10 years	
	Lavatory	115	1	EΑ	7	6-10 years	
	Lighting - Lay-in	115	1	EΑ	7	6-10 years	
	Walls - Concrete Block	115	198	SF	7	10+ years	
	Water Closet	115	1	EA	7	6-10 years	
	Accessories	116	38	SF	7	6-10 years	
	Ceiling - Lay-in	116	38	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	116	1	EA	7	10+ years	
	Floor - Terrazzo	116	38	SF	7	10+ years	
	Floor Drain	116	1	EA	7	10+ years	
	Lavatory	116	1	EA	7	6-10 years	
	Lighting - Lay-in	116	1	EA	7	6-10 years	
	Walls - Concrete Block	116	198	SF	7	•	
	Water Closet	116	190	EA	7	10+ years	
		116	38	SF	7	6-10 years	
	Accessories		38	SF SF		6-10 years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	117		SF EA	7	6-10 years	
		117	1		7	10+ years	
	Floor - Terrazzo	117	38	SF	7	10+ years	
	Floor Drain	117	1	EΑ	7	10+ years	
	Lavatory	117	1	EA	7	6-10 years	
	Lighting - Lay-in	117	1	EA	7	6-10 years	
	Walls - Concrete Block	117	198	SF	7	10+ years	
	Water Closet	117	1	EA	7	6-10 years	
	Accessories	118	38	SF	7	6-10 years	
	Ceiling - Lay-in	118	38	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	118	1	EA	7	10+ years	
	Floor - Terrazzo	118	38	SF	7	10+ years	
	Floor Drain	118	1	EA	7	10+ years	



Category : Room		Building : Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	118	1	EA	7	6-10 years	
	Lighting - Lay-in	118	1	EA	7	6-10 years	
	Walls - Concrete Block	118	198	SF	7	10+ years	
	Water Closet	118	1	EA	7	6-10 years	
	Accessories	1st Floor	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Terrazzo	1st Floor	54	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	293	SF	6	10+ years	
	Water Closet	1st Floor	1	ĒA	6	6-10 years	
	Accessories	1st Floor	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	218	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	240	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	5	2-5 years	Corrosion
	Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	0011031011
	Partitions	1st Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	6-10 years	
	Accessories	1st Floor	241	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	241	SF	7		
	•			SF		10+ years	
	Floor - Terrazzo	1st Floor	241		7	10+ years	
	Floor Drain	1st Floor	2	EA EA	7	10+ years	
	Lavatory	1st Floor	3		5	6-10 years	
	Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	6-10 years	
	Accessories	2nd Floor	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	_1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	54	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	293	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	6-10 years	
	Accessories	2nd Floor	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	240	SF	6	10+ years	
	Floor - Terrazzo	2nd Floor	240	SF	6	10+ years	
	Floor Drain	2nd Floor	2	EA	7	10+ years	
						•	



Catego	ry : Room		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	4	EA	6	6-10 years	
	Partitions	2nd Floor	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	770	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	7	6-10 years	
	Accessories	2nd Floor	241	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	241	SF	6	10+ years	
	Floor - Terrazzo	2nd Floor	241	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	4	EΑ	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	3	EΑ	6	6-10 years	
	Walls - Concrete Block	2nd Floor	770	SF	6	10+ years	
	Water Closet	2nd Floor	2	ĒΑ	6	6-10 years	
	Accessories	3rd Floor	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	250	SF	7	10+ years	
	Floor - Terrazzo	3rd Floor	250	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	5	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	4	EΑ	7	6-10 years	
	Partitions	3rd Floor	5	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	250	SF	7	10+ years	
	Water Closet	3rd Floor	5	EA	7	6-10 years	
	Accessories	3rd Floor	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	250	SF	6	10+ years	
	Floor - Terrazzo	3rd Floor	250	SF	7	10+ years	
	Floor Drain	3rd Floor	2	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	6-10 years	
	Urinals	3rd Floor	3	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	240	SF	6	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Accessories	Kitchen Staff	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen Staff	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Staff	1	EA	7	10+ years	
	Floor - Tile	Kitchen Staff	40	SF	7	6-10 years	
	Floor Drain	Kitchen Staff	1	EA	7	10+ years	
	Lavatory	Kitchen Staff	1	EA	7	6-10 years	
	Lighting - Lay-in	Kitchen Staff	1	EA	7	6-10 years	
	Walls - Concrete Block	Kitchen Staff	255	SF	7	10+ years	
	Water Closet	Kitchen Staff	255	EA	7	6-10 years	
	Accessories	Office	38	SF	7	6-10 years	
	/ 10003301163	Omog	30	OI.	,	o- To years	



Catego	ry : Room		В	uilding	: Additi	on	
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Office	38	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Office	1	EA	7	6-10 years	
	Floor - Terrazzo	Office	38	SF	7	10+ years	
	Floor Drain	Office	1	EA	7	6-10 years	
	Lavatory	Office	1	EA	7	6-10 years	
	Lighting - Lay-in	Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Office	197	SF	7	10+ years	
	Water Closet	Office	1	EA	7	6-10 years	
Catego	ry : Classroom		В	uilding	: Additi	on	
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #113 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	271	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	2-5 years	
Classroo	om #114 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1.045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	271	SF	6	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	6-10 years	
Classro	om #115 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Coming Lay III	1301 1001	1,043	01	J	o io years	



Catego	ry : Classroom		В	uilding	: Addition	on	
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	271	SF	6	10+ years	
	Work Sink	1st Floor	2	ĒΑ	5	6-10 years	
Classroc	om #116 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17.043	EA	7	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7		
	Walls - Concrete Block	1st Floor		SF	6	10+ years	
	Work Sink	1st Floor	1,010 2	EA	5	10+ years 2-5 years	
laceroo	om #117 (Kindergarten)						
iassiuc	Casework	1st Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	2-5 years	Burnt out bulbs.
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	271	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	2-5 years	
assroc	om #118 (Kindergarten)						
	Casework	1st Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,045	SF	6	6-10 years	
	Chalk Board	1st Floor	<sup>^</sup> 15	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	

Campus Name: Falconer Page : 39 of 51 Assessment Date: 07/14/2021



Catego	ry : Classroom		В	uilding	: Additi		020 N Lamon AVENUE, Chicago, IL 60041
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,045	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	15	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	271	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	2-5 years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	971	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	258	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classro	om #214 (Regular Classroom)						
Classion	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	6-10 years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	879	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	478	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	597	SF	7	10+ years	
Classro	om #215 (Regular Classroom)						
<u> </u>	Casework	2nd Floor	16	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	392	SF	6	6-10 years	
	Chalk Board	2nd Floor 2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	12	EA	6	6-10 years	
		2nd Floor	392	SF		•	
	Floor - Tile	2nd Floor 2nd Floor			6	6-10 years	
	Lighting - Lay-in		6	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	343	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	536	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
	<del></del>		0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #216 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	870	SF	6	6-10 years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	917	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	258	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #217 (Regular Classroom)						
21000100	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	6	6-10 years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	12	EA	6	10+ years	
	Floor - Tile	2nd Floor	870	SF	6	6-10 years	
					7	•	
	Lighting - Lay-in Marker Board	2nd Floor	12	EA LF	7	6-10 years	
		2nd Floor	15	SF		6-10 years	
	Storage/ Closet	2nd Floor	3		7	10+ years	
	Walls - Concrete Block	2nd Floor	917	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	258	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #218 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	870	SF	6	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	879	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	971	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	258	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	m #219 (Regular Classroom)						
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	6	6-10 years	
		2113 1 1001	370	٥.	3	o io youio	



Catego	ry : Classroom		В	uilding	: Additi		5525 IV Lamon AVENUE, Officago, 12 00041
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	597	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	478	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #220 (Regular Classroom)						
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	392	SF	6	6-10 years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	392	SF	6	6-10 years	
					-	,	
	Lighting - Lay-in	2nd Floor	6	EA	7 7	6-10 years	
	Marker Board	2nd Floor	15	LF		6-10 years	
	Walls - Concrete Block	2nd Floor	284	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	536	SF	6	10+ years	
Classroo	om #224 (Regular Classroom)						
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	539	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	539	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	6	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,097	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #313 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Chalk Board	3rd Floor	0	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	3	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	971	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	-	Paint chipping and peeling.
	Walls - Plaster/Drywall Work Sink	3rd Floor	200	EA	7	10+ years	r ann ompping and peemig.
	VVUIK SIIIK	314 F1001	1	EA	,	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #314 (Regular Classroom)						
Ciassioc	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	3	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	597	SF	6	10+ years	
					-		
	Walls - Plaster/Drywall	3rd Floor	478	SF	6 7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #315 (Regular Classroom)						
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	14	SF	6	10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	392	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	14	SF	6	10+ years	
01	1040 (Barrilan Olasana)						
Classroc	om #316 (Regular Classroom)	0.151				4.0	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	971	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #317 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Shair Board	014 1 1001	13	LI	7	2 0 years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	971	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	10+ years	
	Work Sink	3rd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #318 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	•	
		3rd Floor		EA	7	6-10 years	
	Lighting - Lay-in Marker Board	3rd Floor	12 15	LF	7	6-10 years	
				SF		6-10 years	
	Walls - Concrete Block	3rd Floor	971		6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroc	om #319 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	868	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	2	SF	4	1-2 years	Water damage.
	Chalk Board	3rd Floor	12	LF	4	2-5 years	•
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	284	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	536	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
lassroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Doors - Side-lite	3rd Floor		SF SF			
			12	_	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	



Catego	ory : Classroom		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	871	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classro	om #321 (Regular Classroom)						
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	392	SF	6	6-10 years	
	Chalk Board	3rd Floor	15	ĹF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	284	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	536	SF	6	10+ years	
Classro	om #322 (Regular Classroom)						
Classio	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	6-10 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Storage/ Closet	3rd Floor		SF	7		
	Walls - Concrete Block	3rd Floor	3 597	SF SF	6	10+ years	
				SF SF		10+ years	
	Walls - Plaster/Drywall Work Sink	3rd Floor 3rd Floor	478 1	SF EA	6 7	10+ years 6-10 years	
	WOIR SIIIR	314 F1001	1	EA	,	6-10 years	
Classro	om #323 (Regular Classroom)						
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	6	10+ years	
	Chalk Board	3rd Floor	0	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	917	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	258	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
						-	



\_Safety\_

# Laughlin Falconer Elementary School 3020 N Lamon AVENUE, Chicago, IL 60641

Category : Classroom	Ві							
			Recommend					
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroom #324 (Store Room)								
Ceiling - Lay-in	3rd Floor	539	SF	6	6-10 years			
Ceiling - Plaster/Drywall	3rd Floor	24	SF	6	10+ years			
Doors - Side-lite	3rd Floor	12	SF	6	10+ years			
Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years			
Floor - Tile	3rd Floor	539	SF	6	6-10 years			
Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years			
Marker Board	3rd Floor	6	LF	6	6-10 years			
Walls - Concrete Block	3rd Floor	1,097	SF	6	10+ years			

**Category: Interior Building: Addition** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	5,790	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	534	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	11	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	6,514	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	46	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	1	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	3	LF	6	6-10 years	
	Student Lockers - Two Tiers	1st Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	10,370	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5,341	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	410	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	5	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	5,830	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	52	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	7,854	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4,311	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	108	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	5	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	5,727	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	56	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	17	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	48	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	7,854	SF	7	10+ years	

Campus Name: Falconer Page : 46 of 51 Assessment Date: 07/14/2021



Catego	Category : Interior				: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
Stairs							
<u> Ciano</u>	Ceiling - Lay-in	North Stair of Addition 7	463	SF	6	6-10 years	
	Floor - Terrazzo	North Stair of Addition 7	190	SF	6	10+ years	
	Handrails	North Stair of Addition 7	118	LF	7	6-10 years	
	Lighting - Lay-in	North Stair of Addition 7	10	EA	7	6-10 years	
	Lighting - Wall Mounted	North Stair of Addition 7	1	EA	7	6-10 years	
	Stairs - Terrazzo	North Stair of Addition 7	52	LF	6	10+ years	
	Walls - Concrete Block	North Stair of Addition 7	2,608	SF	6	10+ years	
	Ceiling - Lay-in	South Stairs next to restrooms - Entrance 8	659	SF	6	6-10 years	
	Ceiling - Lay-in	South Stairs next to restrooms - Entrance 8	4	SF	4	1-2 years	Buckling.
	Floor - Terrazzo	South Stairs next to restrooms - Entrance 8	320	SF	6	10+ years	
	Handrails	South Stairs next to restrooms - Entrance 8	1	LF	7	2-5 years	
	Handrails	South Stairs next to restrooms - Entrance 8	135	LF	7	6-10 years	
	Lighting - Lay-in	South Stairs next to restrooms - Entrance 8	10	EA	6	6-10 years	
	Lighting - Wall Mounted	South Stairs next to restrooms - Entrance 8	4	EA	6	6-10 years	
	Stairs - Terrazzo	South Stairs next to restrooms - Entrance 8	77	LF	6	10+ years	
	Walls - Concrete Block	South Stairs next to restrooms - Entrance 8	2,746	SF	6	10+ years	
	Ceiling - Lay-in	West Stairs - Entrance 12	463	SF	6	6-10 years	
	Floor - Terrazzo	West Stairs - Entrance 12	190	SF	4	0-1 year	Crack at lowest level
	Handrails	West Stairs - Entrance 12	118	LF	7	6-10 years	
	Lighting - Lay-in	West Stairs - Entrance 12	10	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	West Stairs - Entrance 12	2	EA	7	6-10 years	
	Stairs - Terrazzo	West Stairs - Entrance 12	52	LF	6	10+ years	
	Walls - Concrete Block	West Stairs - Entrance 12	2,608	SF	6	10+ years	
Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	6	2-5 years	Upgrade finishes





Category: Site Building: Site

Jaiego	ry : Site		В	uilding	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
	•					·	
encina							
J	Fencing - Chain Link	Entire Site	25	LF	6	6-10 years	
	Fencing - Old Standard Ornamental	Entire Site	1,292	LF	6	6-10 years	Painting required.
	Ç					•	
andsca	pe						
	Landscape - Grass	Entire Site	35,248	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	23,262	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	120	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	1,800	SF	5	2-5 years	
	Landscape - Mulch	Entire Site	3,500	SF	6	6-10 years	
	Parkway trees	Entire Site	49	EΑ	6	10+ years	
	Planting Beds/ Area	Entire Site	600	SF	6	6-10 years	
	Play Area - Synthetic Turf	Entire Site	29,291	SF	6	6-10 years	
	Play Area - Synthetic Turf	Entire Site	2,427	SF	5	2-5 years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
Parking		011/	4.700			0.10	
	Concrete Curbs	SW parking lot	1,760	LF	6	6-10 years	
	Interior Plantings	SW parking lot	90	LF.	6	6-10 years	
	Lighting - Pole Mounted	SW parking lot	7	EA SF	6 4	2-5 years	Cracking and natholas
	Surface - Asphalt	SW parking lot	162,504 400	SF SF	6	0-1 year	Cracking and potholes.
	Trash Enclosure - Masonry Trash Enclosure - Masonry	SW parking lot SW parking lot	1,562	SF SF		6-10 years 10+ years	
	Vehicular Screening	SW parking lot	280	LF	6 6	2-5 years	
	verilicular Screening	Svv parking lot	200	LF	O	2-5 years	
Playgrou	und						
70	Equipment - School Age 5-12	South East	1	EA	6	2-5 years	
	Surface - Poured Surface	South East	2,427	SF	4	0-1 year	Holes throughout.
			,			•	S
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	485	LF	6	6-10 years	
	Sidewalks - Internal Walks	Entire Site	20	LF	5	2-5 years	
	Sidewalks - Internal Walks	Entire Site	120	LF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	22,000	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	18,330	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,927	SF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	600	SF	5	2-5 years	



Category : Site			В	uilding	Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site	600 600	SF SF	5 5	2-5 years 2-5 years	
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	2	EA	6	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Falconer Page: 49 of 51 Assessment Date: 07/14/2021



**Classroom Summary** 

Olassi Com Cummary			_	Floor Plan	_	Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		T		T					T
Computer Lab	Computer Lab	2nd Floor	204	204	806	132	58	N	Υ
Computer Lab	Library	2nd Floor	205	205	780	132	59	N	N
Kindergarten	Kindergarten	1st Floor	100	n/a	2,013	220	110	N	N
Kindergarten	Regular Classroom	1st Floor	102	102	1,022	220	98	N	Υ
Music Room	Regular Classroom	3rd Floor	312	312	354	88	39	N	N
Music Room	Regular Classroom	3rd Floor	400	n/a	319	72	36	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	760	176	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	760	176	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	834	176	78	Y	N
Regular Classroom	Regular Classroom	1st Floor	108	108	834	176	78	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	760	176	78	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	760	176	78	N	Υ
Regular Classroom	Regular Classroom	1st Floor	111	111	760	176	78	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	760	176	78	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	760	128	16	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	760	176	78	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	760	176	78	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	760	176	78	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	760	176	78	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	760	176	78	N	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	760	176	78	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	302	302	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	858	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	858	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	760	176	78	N	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	760	176	78	N	Y
Store Room	Other Instructional Use	3rd Floor	305C	Dining Room	165	0	0	N	N
Ctoro recom	Total mondononal ode	1 010 1 1001	1 0000	_ Dilling Room	100		<u>.                                      </u>	1 1 1	1 14
<b>Building : Addition</b>									
Kindergarten	Kindergarten	1st Floor	113	113	1,045	181	74	N	Υ
Kindergarten	Kindergarten	1st Floor	114	114	1,045	181	79	N	Υ





**Classroom Summary** 

,			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Kindergarten	1st Floor	115	115	1,045	181	74	N	Y
Kindergarten	Kindergarten	1st Floor	116	116	1,045	181	74	N	Y
Kindergarten	Kindergarten	1st Floor	117	117	1,045	181	74	N	Υ
Kindergarten	Kindergarten	1st Floor	118	118	1,045	181	74	N	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	870	136	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	870	136	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	215	392	59	29	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	216	870	136	55	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	870	136	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	870	136	55	N	Y
Regular Classroom	Regular Classroom	2nd Floor	219	219	870	136	74	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	220	220	392	59	29	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	539	88	8	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	313	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	314	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	315	315	392	59	29	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	316	316	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	317	317	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	318	318	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	319	319	870	136	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	320	320	870	159	55	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	321	321	392	59	29	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	870	136	55	N	Y
Regular Classroom	Regular Classroom	3rd Floor	323	323	870	136	55	N	Υ
Store Room	Special Education	3rd Floor	324	324	539	88	8	N	Υ