



#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1911	3	67,435
Annex	1999	3	57,255
Modular 1 (4-Classroom )	2013	1	5,300
Campus Total			129,990

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Entrance Control - Audio and Video	#1 Main - NE	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#1 Main - NE	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 Main - NE	4	EA	6	6-10 years	
	Exterior Doors - Store Front	#11 - N	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	#11 - N	4	EA	7	10+ years	
	Exterior Doors - Store Front	#3 - E	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 - E	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3 - E	12	LF	5	2-5 years	Cracked/Broken
	Exterior Doors - Store Front	#5 - SE	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - SE	4	EA	6	6-10 years	
	Entrance Control - Audio and Video	#7 - S	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#7 - S	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 - S	4	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9 - W	1	EA	5	2-5 years	
_Foundati	on						
	Foundation - Concrete	Entire Building	864	LF	6	10+ years	Mortar Deterioration
	Superstructure - Steel with Clay Tile Arch	Entire Building	67,435	SF	7	10+ years	
_Lighting_							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	20	EA	6	6-10 years	
D (0							
Roof Sys							
	Coping - Metal	Center - Lower roofs	260	LF	5	2-5 years	Rust/Corrosion
	Coping - Stone	Center - Lower roofs	369	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Center - Lower roofs	72	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Center - Lower roofs	246	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Center - Lower roofs	123	LF	6	10+ years	
	Roof - Metal	Center - Lower roofs	809	SF	6	10+ years	
	Roof - PVC Membrane	Center - Lower roofs	9,884	SF	4	1-2 years	Air Pockets. Deteriorating attachment to substrate with joints/seams failure - Leaks
	Roof Structure - Steel with Clay Tile Arch	Center - Lower roofs	10,693	SF	7	10+ years	
	Coping - Stone	East - High Roof	76	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	East - High Roof	12	LF	4	0-1 year	Gutter Rusted/Bent. Downspout missing/Not present
	Parapet - 16" - 30" Height	East - High Roof	76	LF	6	10+ years	3
	Roof - PVC Membrane	East - High Roof	711	SF	4	1-2 years	Air Pockets. Deteriorating attachment to substrate with joints/seams failure - Leaks
	Roof Structure - Steel with Clay Tile Arch	East - High Roof	711	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	3	1-2 years	Rungs spacing is awkward. Rungs embedded in wall.
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	75	LF	6	10+ years	
	Coping - Metal	Main Roof	40	LF	6	6-10 years	
	Coping - Stone	Main Roof	256	LF	6	10+ years	mortar joint deterioration, between stones and at seating bed
	Downspouts - Interior Downspouts	Main Roof	168	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	296	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	296	LF	6	10+ years	
	Roof - Metal	Main Roof	180	SF	5	1-2 years	Rust/corrosion
	Roof - PVC Membrane	Main Roof	16,468	SF	4	1-2 years	Membrane loose with air pockets under neath. Worned.
	Roof Hatch - Metal	Main Roof	2	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	16,648	SF	7	10+ years	
	Coping - Stone	West Low Roof	134	LF	5	10+ years	W/Deteriorating Mortar Joints
	Downspouts - Interior Downspouts	West Low Roof	28	LF	5	2-5 years	•
	Parapet - 16" - 30" Height	West Low Roof	134	LF	6	10+ years	
	Roof - PVC Membrane	West Low Roof	2,375	SF	4	1-2 years	Significant Damage. Air Pockets, Deteriorating attachment to substrate with Joints/Seams failure - Leaks
	Roof Structure - Steel with Clay Tile Arch	West Low Roof	2,375	SF	7	10+ years	Como Coamo Ianaro Louito

Campus Name: Gray Page : 2 of 46 Assessment Date: 11/16/2021



	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	912	LF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	100	LF	5	10+ years	
	Cornice - Metal Projecting	Entire Building	1,856	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20,086	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building Entire Building	1,400 1,219	SF	5	10+ years	
	Exterior Walls - Stone-Cast Exterior Walls - Stone-Cast	Entire Building  Entire Building	3,200	SF SF	6 6	10+ years 10+ years	
	Exterior Walls - Storie-Cast	Entire building	3,200	SF	b	10+ years	
Vindows							
	Guard - Guards perforated	Entire Building	16	SF	7	6-10 years	
	Guard - Guards perforated	Entire Building	2,386	SF	6	6-10 years	
	Lintels - Steel	Entire Building	656	LF	6	10+ years	
	Lintels - Stone	Entire Building	212	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	60	SF	7	2-5 years	
	Windows - Louver	Entire Building	112	SF SF	7	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,686	5F	6	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
	Ham. Turns	Laatian	0	HOM	Dank	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
morgo	any System						
merge	ncy System Automatic Transfer Switch	Floatrical Poom	1	ΕΛ	1	2.5 years	Old not reliable
:mergei	Automatic Transfer Switch	Electrical Room	1 67.435	EA SE	4 5	2-5 years	Old, not reliable
:merge	Automatic Transfer Switch Security System - CCTV	Entire Building	67,435	SF	5	6-10 years	Old, not reliable
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building	67,435 67,435	SF SF	5 5	6-10 years 6-10 years	•
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs	Entire Building	67,435	SF SF EA	5	6-10 years	Old, not reliable Inside exit sign
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose	Entire Building Entire Building	67,435 67,435	SF SF	5 5	6-10 years 6-10 years	·
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room	Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3	SF SF EA	5 5 6	6-10 years 6-10 years 6-10 years 6-10 years	Inside exit sign
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4	SF SF EA EA	5 5 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Inside exit sign  Recently replaced, with batteries.
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3	SF SF EA	5 5 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries
:merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and	Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4 10 9	SF SF EA EA	5 5 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Inside exit sign  Recently replaced, with batteries.
merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and Stairs	Entire Building Entire Building Entire Building  Entire Building  Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4 10 9 4 13,320	SF SF EA EA EA SF	5 5 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 10+ years	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries
:merge	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and	Entire Building Entire Building Entire Building  Entire Building  Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4 10 9 4	SF SF EA EA EA EA	5 5 6 6 6 2 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries
	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room	Entire Building Entire Building Entire Building  Entire Building  Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4 10 9 4 13,320	SF SF EA EA EA SF	5 5 6 6 6 2 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 10+ years	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries
Emerger	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room  rvice Main Electrical Service- Live Front - 1600 A	Entire Building Entire Building Entire Building  Entire Building  Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	67,435 67,435 3 4 10 9 4 13,320	SF SF EA EA EA SF	5 5 6 6 6 2 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 10+ years	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries No battery back-up  Deteriorated, no reliable, serves ma
	Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room	Entire Building	67,435 67,435 3 4 10 9 4 13,320 6,094	SF SF EA EA EA SF SF	5 5 6 6 6 2 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 0-1 year 10+ years	Inside exit sign  Recently replaced, with batteries. Recently replaced, with batteries No battery back-up

Campus Name: Gray Page : 3 of 46 Assessment Date: 11/16/2021



Cotogo				uildina	. Main	37	30 N Laramie AVENUE, Chicago, IL 60641
Catego	ry : Electrical		ь	uilding	. wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Rom Type	Location	quantity	00111	Italik	Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	Deteriorated, corroded
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Cleaned, tested, rated 7
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	4	2-5 years	Deteriorated, corroded
Catego	ry : Fire Protection		В	uilding	: Main		
Calogo	.,		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Mechanical Room	1	EA	3	2-5 years	Old, using relay logic
	Fire Alarm Strobe Lights	Mechanical Room	67,435	SF	4	2-5 years	Bells, older, deteriorated
	Fire Alarm_System	Mechanical Room	67,435	SF	4	2-5 years	Old, not reliable
Catego	ry : Mechanical		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	litioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	5	EA	6	6-10 years	Serves library and Computer room, classrooms, 5 found, mini split systems
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	5	EA	5	6-10 years	Mini split systems, previously not assessed
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 2, serves north side
	Air Intake	Mechanical Room	1	EA	5	10+ years	Not painted
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	•
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	14	EA	5	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 3, serves south side
	Air Intake	Mechanical Room	1	EA	5	6-10 years	Not painted
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	6	10+ years	

Campus Name: Gray Page : 4 of 46 Assessment Date: 11/16/2021



Catego	ry : Mechanical		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Zone Dampers	Mechanical Room	14	EA	5	6-10 years		
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, serves auditorium	
	Air Intake	Mechanical Room	1	EA	5	10+ years	Not painted	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	5	6-10 years		
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	10+ years		
Boiler Sy	ystems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	3	EA	5	6-10 years		
	Chemical Feed System	Boiler Room	1	EA	6	10+ years		
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years		
	Condensate Pump	Boiler Room	3	EA	6	6-10 years		
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years		
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	3	EA	5	6-10 years	Serves main building	
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	10+ years		
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	5	10+ years	There are a few pipe clamps	
	Steam Traps	Boiler Room	45	EA	5	6-10 years		
Heating	Devices							
	Wall Heater - Electric	Electrical Room	11	EA	5	6-10 years		
	Wall Heater - Electric	Electrical Room	10	EA	5	6-10 years	Cleaned, tested	
	Cabinet Heaters - With Steam Coil	Electrical Room	3	EA	5	6-10 years	None, radiator behind grill	
	Unit Heater - Gas	Entire Building	1	EA	6	10+ years		
	Fin Tube - Steam	Entire Building	36	LF	5	6-10 years		
	Radiators - Steam	Entire Building	1	EA	5	6-10 years	Inside of the cover	
	Radiators - Steam	Entire Building	1	EA	5	6-10 years		
Tempera	ature Control							
·	Electric Thermostat	Entire Building	6	EA	5	6-10 years	Used with 1 gas unit heater, 5 mini split systems. Electric wall heaters have integral thermostats, not counted.	
	Pneumatic System	Entire Building	67,435	SF	4	2-5 years	Mostly manually controlled	
	Thermostats - Pneumatic	Entire Building	8	EA	5	6-10 years	Not calibrated	
	Thermostats - Pneumatic	Entire Building	21	EA	4	2-5 years	Many leakingthermostats	
Ventilatio	on.							
<u>v Grillialli</u>	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	3	EA	5	6-10 years		

Campus Name: Gray Page : 5 of 46 Assessment Date: 11/16/2021



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wat	er		•			•	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves main building
_Piping_							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	67,435	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	67,435	SF	6	6-10 years	Leaks occasionally repaired. Building has a few pipeclamps
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	67,435	SF	6	6-10 years	Leaks occasionally repaired. Building has a few pipeclamps
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	67,435	SF	6	6-10 years	Building has a few pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,435	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	67,435	SF	6	6-10 years	
	Sanitary Piping	Entire Building	67,435	SF	6	6-10 years	
	Storm Piping	Entire Building	67,435	SF	6	6-10 years	
	Vent Piping	Entire Building	67,435	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	5	6-10 years	Serves main building

Category : Room **Building: Main** 

Group	Itam Tuna	Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UCIVI	Rank	Replacement	Comments
_Adminisi	rative Suites/Offices	A.E D D 014				2.12	0 " 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	AC Unit	Adjustment Room, Room 211	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	Adjustment Room, Room 211	397	SF	6	10+ years	
	Doors - Transom Window	Adjustment Room, Room 211	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Adjustment Room, Room 211	1	EA	6	10+ years	
	Floor - Tile	Adjustment Room, Room 211	397	SF	7	10+ years	No required repair observed. Rank changed to update current observation
	Lighting - Lay-in	Adjustment Room, Room 211	12	EA	6	6-10 years	
	Power Distribution	Adjustment Room, Room 211	12	EA	6	10+ years	
	Walls - Plaster/Drywall	Adjustment Room, Room 211	457	SF	7	10+ years	Newly painted walls observed. No damage observed. Rank changed to update current observation.
	AC Unit	Conference Room, Room 311	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	Conference Room, Room 311	397	SF	6	10+ years	
	Doors - Transom Window	Conference Room, Room 311	9	SF	6	10+ years	

Campus Name: Gray Page : 6 of 46 Assessment Date: 11/16/2021



Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Conference Room, Room 311	1	EA	6	10+ years	
	Floor - Tile	Conference Room, Room 311	397	SF	6	10+ years	
	Lighting - Lay-in	Conference Room, Room 311	12	EA	7	6-10 years	
	Power Distribution	Conference Room, Room 311	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Conference Room, Room 311	457	SF	6	10+ years	
	Ceiling - Lay-in	Engineer's Office	178	SF	5	10+ years	
	Ceiling - Lay-in	Engineer's Office	4	SF	5	0-1 year	Water damaged tiles
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	182	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	6	6-10 years	
	Power Distribution	Engineer's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	50	SF	6	1-2 years	
	Walls - Plaster/Drywall	Engineer's Office	159	SF	5	10+ years	
	AC Unit	Faculty Lounge 109	1	EA	7	2-5 years	
	Ceiling - Lay-in	Faculty Lounge 109	147	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Faculty Lounge 109	1	EA	6	10+ years	
	Floor - Tile	Faculty Lounge 109	147	SF	6	10+ years	
	Lighting - Lay-in	Faculty Lounge 109	1	EA	7	6-10 years	
	Power Distribution	Faculty Lounge 109	12	EA	6	10+ years	
	Walls - Plaster/Drywall	Faculty Lounge 109	169	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	2-5 years	
	Ceiling - Lay-in	Main Office	281	SF	6	10+ years	
	Doors - Side-lite	Main Office	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Floor - Tile	Main Office	281	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office	4	EA	7	6-10 years	
	Power Distribution	Main Office	8	EA	6	10+ years	
	Storage/ Closet	Main Office	26	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	323	SF	6	10+ years	
	Ceiling - Exposed	Offices at the Back of the Stage	342	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Offices at the Back of the Stage	1	EA	6	10+ years	
	Floor - Wood	Offices at the Back of the Stage	342	SF	6	10+ years	
	Lighting - Pendent/Surface	Offices at the Back of the Stage	3	EA	6	6-10 years	
	Power Distribution	Offices at the Back of the Stage	8	EA	6	10+ years	
	Walls - Masonry	Offices at the Back of the Stage	197	SF	6	10+ years	
	Walls - Plaster/Drywall	Offices at the Back of the Stage	197	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Office	94	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Principal's Office	94	SF	6	10+ years	
	Lighting - Lay-in	Principal's Office	2	EA	7	6-10 years	
	Power Distribution	Principal's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Principal's Office	108	SF	6	10+ years	
Cumnosi							

Gymnasia



Categor	ry : Room		В	uilding	: Main				
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Bleacher Seating	1st Floor	582	EΑ	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	6,094	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	8	EΑ	6	10+ years			
	Floor - Tile	1st Floor	3,036	SF	5	10+ years			
	Floor - Tile	1st Floor	11	SF	4	0-1 year	Damaged tile		
	Floor - Wood	1st Floor	3,047	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	48	EA	7	6-10 years			
	Sound System	1st Floor	1	EΑ	7	6-10 years			
	Stage	1st Floor	428	SF	6	10+ years			
	Stage Curtain	1st Floor	2	EA	7	6-10 years			
	Stage Lighting System	1st Floor	1	EA	7	6-10 years			
	Stage-Stairs - Wood	1st Floor	10	LF	6	6-10 years			
	Storage/ Closet	1st Floor	228	SF	7	10+ years			
	Walls - Masonry	1st Floor	3,504	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	3,504	SF	5	10+ years			
MDF_IDF	=								
_	Doors - Wood Doors inclu hw	In Library 204	1	EA	6	10+ years			
	Finishes	In Library 204	39	SF	7	10+ years			
	Other Cooling Unit	In Library 204	1	ĒΑ	7	10+ years	Ductless split system		
Mechanic	cal/ Service Rooms								
	Boiler Room	1st Floor	1,424	SF	7	10+ years			
	Coal Room	1st Floor	540	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	496	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	722	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	190	SF	7	10+ years			
	Storage Room	1st Floor	74	SF	7	10+ years			
	Janitor's Closet	2nd Floor	17	SF	7	10+ years	Existing Jan Closet from previous		
	carmer o crocot	2110 1 1001	• •	O.	•	io. youro	assessment		
	Janitor's Closet	3rd Floor	17	SF	7	10+ years	Quantity changed to update current observation		
Restroom	1								
	Accessories	1st Floor	49	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	49	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	49	SF	6	10+ years			
	Lavatory	1st Floor	1	ĒΑ	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years			
	Partitions	1st Floor	1	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	29	SF	6	10+ years			
					-	- ,			
	Walls - Plaster/Drywall	1st Floor	29	SF	6	10+ years			



Category : Room		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	405	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	0-1 year	Not working
	Partitions	1st Floor	2	EA	7	10+ years	3
	Urinals	1st Floor	5	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	117	SF	6	10+ years	
	Walls - Masonry	1st Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	117	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	6	10+ years	
	Accessories	1st Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	405	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	6	•	
			4	EA		10+ years	
	Lighting - Pendent/Surface	1st Floor			6	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	117	SF	6	10+ years	
	Walls - Masonry	1st Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	117	SF	6	10+ years	
	Water Closet	1st Floor	6	EA	6	10+ years	
	Accessories	2nd Floor	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	49	SF	6	10+ years	
	Lavatory	2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	29	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	29	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	10+ years	
	Accessories	2nd Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	405	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
						•	



Catego	ory : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Urinals	2nd Floor	5	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	117	SF	6	10+ years	
	Walls - Masonry	2nd Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	117	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	10+ years	
	Accessories	2nd Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	405	SF	6	10+ years	
	Floor Drain	2nd Floor	1	ĒΑ	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	6	6-10 years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	117	SF	6	10+ years	
	Walls - Masonry	2nd Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	117	SF	6	10+ years	
	Water Closet	2nd Floor	6	EA	6	10+ years	
	Accessories	3rd Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	405	SF	6	,	
	Floor Drain	3rd Floor	405	EA	7	10+ years	
				EA	6	10+ years	
	Lavatory	3rd Floor	2	EA	_	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4		6	6-10 years	
	Partitions	3rd Floor	6	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	117	SF	6	10+ years	
	Walls - Masonry	3rd Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	117	SF	6	10+ years	
	Water Closet	3rd Floor	6	EA	6	10+ years	
	Accessories	3rd Floor	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	49	SF	6	10+ years	
	Lavatory	3rd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Partitions	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	29	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	29	SF	6	10+ years	
	Water Closet	3rd Floor	1	EA	6	10+ years	
	Accessories	3rd Floor	405	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	405	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EΑ	7	10+ years	
						•	

Campus Name: Gray Page : 10 of 46 Assessment Date: 11/16/2021



Catego	ry : Room		В	uilding	: Main	31	30 N Laramie AVENUE, Chicago, IL 6064
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lavatory	3rd Floor	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	6	10+ years	
	Walls - Concrete Block	3rd Floor	117	SF	6	10+ years	
	Walls - Masonry	3rd Floor	233	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	117	SF	6	10+ years	
	Water Closet	3rd Floor	2	EA	6	10+ years	
	Accessories	In the Boiler Room area	18	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Boiler Room area	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In the Boiler Room area	1	EA	6	10+ years	
	Floor - Concrete	In the Boiler Room area	18	SF	7	10+ years	
	Lighting - Wall Mounted	In the Boiler Room area	1	EA	6	6-10 years	
	Walls - Masonry	In the Boiler Room area	11	SF	6	10+ years	
	Walls - Plaster/Drywall	In the Boiler Room area	11	SF	6	10+ years	
	Water Closet	In the Boiler Room area	1	ĒΑ	6	10+ years	
	Accessories	Rm 103	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 103	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm 103	1	ĒΑ	6	10+ years	
	Floor - Tile	Rm 103	30	SF	6	10+ years	
	Lavatory	Rm 103	1	ĒΑ	6	10+ years	
	Lighting - Lay-in	Rm 103	1	EA	7	6-10 years	
	Walls - Masonry	Rm 103	60	SF	6	10+ years	
	Water Closet	Rm 103	1	ĒΑ	6	10+ years	
	Accessories	Room 105	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 105	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 105	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 105	62	SF	6	10+ years	
	Lavatory	Room 105	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	Room 105	1	ΕA	6	6-10 years	
	Walls - Concrete Block	Room 105	74	SF	6	10+ years	
	Water Closet	Room 105	1	ĒΑ	6	10+ years	
atego	ry : Classroom		В	uilding	: Main		
_		Location		UOM	Rank	Recommend	Comments
roup	Item - Type	Location	Quantity	UUIVI	Rdilk	Replacement	Comments
lassroo	m #101 (Vacant)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	890	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	890	SF	6	10+ years	
				_ ^	^	0.40	
	Lighting - Lay-in	1st Floor	14 24	EA LF	6 7	6-10 years	



Categor	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,026	SF	6	10+ years	
Classroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	42	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,040	SF	6	10+ years	
Classroo	m #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	820	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,546	SF	6	10+ years	
Classroo	m #104 (Kindergarten)						
Classico	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	890	SF			
	Doors - Transom Window		9	SF SF	6 6	10+ years	
		1st Floor				10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1 890	EA SF	6	10+ years	
	Floor - Wood	1st Floor			6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	6	6-10 years	
	Storage/ Closet	1st Floor	47	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,688	SF	6	10+ years	
_Classroo	m #105 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	820	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Storage/ Closet	1st Floor	49	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,004	SF	6	10+ years	
Classroo	m #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	820	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	820	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	3	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,020	SF	6	10+ years	
Classroo	m #200 (Regular Classroom)						
Classiuc	AC Units	2nd Floor	1	EA	7	6-10 years	Quantity changed to update current
						•	observation
	Ceiling - Lay-in	2nd Floor	405	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Epoxy/ Painted	2nd Floor	405	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	10+ years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	466	SF	7	10+ years	
Classroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	Quantity changed to update current observation
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	observation
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years	
Classroo	m #202 (Regular Classroom)						
Classiu	AC Units	2nd Floor	2	EA	7	6-10 years	Quantity changed to update current
	AC UTIILS	ZIIU FIUUI	2	EA	,	o- io years	observation

Campus Name: Gray Page : 13 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	39	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	943	SF	6	10+ years	
Classro	om #203 (Regular Classroom)						
DIOGRAM	AC Units	2nd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	55501 Valio11
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	820	SF	6	-	
						10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Storage/ Closet	2nd Floor	49	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years	
Classroo	om #204 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	19	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	39	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,546	SF	6	10+ years	
Classro	om #205 (Regular Classroom)						
CIGOU O	Casework	2nd Floor	4	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Chalk Board	2nd Floor 2nd Floor	10	LF	4		
					-	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	64	SF	7	10+ years	Quantity changed to update current observation

Campus Name: Gray Page : 14 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<b>.</b> .	#000 (D I. Ol )						
Classroo	m #206 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	550	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	550	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,038	SF	6	10+ years	
Classroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	Quantity changed to update curren
	Cailing Lawin	2nd Floor	000	C.E.	7	40	observation
	Ceiling - Lay-in	2nd Floor	820	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	49	SF	7	10+ years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years	
Classroo	m #208 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	14	EA	7	•	
				LF		6-10 years	
	Marker Board	2nd Floor	40		6	6-10 years	
	Storage/ Closet	2nd Floor	5	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,546	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	2-5 years	Quantity changed to update current observation
	Ceiling - Lay-in	2nd Floor	820	SF	7	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	788	SF	6	10+ years	
	11001 11000	210 1 1001	700	01	J	TOT years	

Campus Name: Gray Page : 15 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	32	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	42	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,040	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	Quantity changed to update current
	710 Office	2110 1 1001	2		•	o ro youro	observation
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years	observation
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	EA			
			-		6	10+ years	
	Floor - Wood	2nd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,546	SF	6	10+ years	
Classroc	om #300 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	405	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	8	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
		3rd Floor	466	SF	6		
	Walls - Plaster/Drywall	310 F1001	400	SF	б	10+ years	
Classroc	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	. <u>-</u> 1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor		EA	7	6-10 years	
			14				
	Marker Board	3rd Floor	46	LF CF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,040	SF	6	10+ years	
Classroc	om #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	Quantity changed to update current

Campus Name: Gray Page : 16 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	34	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,546	SF	6	10+ years	
Classroc	om #303 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	42	LF	6	6-10 years	
		3rd Floor	44	SF	7		
	Storage/ Closet					10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,040	SF	6	10+ years	
lassroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update curren observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	35	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,546	SF	6	10+ years	
Classroo	om #305 (Art Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update curren observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	6	10+ years	
			· · · · · · · · · · · · · · · · · · ·	SF	_	-	
	Floor - Wood	3rd Floor	820		6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	18	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	48	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,040	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	

Campus Name: Gray Page : 17 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #306 (Regular Classroom)						
Classion	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	0.001.44.1011
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
						-	
	Walls - Plaster/Drywall	3rd Floor	1,546	SF	6	10+ years	
Classro	om #307 (Regular Classroom)						
	Casework	3rd Floor	4	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	820	SF	7	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6		
						10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	42	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,040	SF	6	10+ years	
Classro	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	820	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	38	LF	6	6-10 years	
			54	SF	7		
	Storage/ Closet	3rd Floor				10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,546	SF	6	10+ years	
Classro	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
		<del></del>	·		-	· ,	

Campus Name: Gray Page : 18 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Main		30 N Latarille AVENUE, Chicago, IL 60041
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	3rd Floor	96	SF	6	10+ years	
	Floor - Wood	3rd Floor	724	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	13	EA	7	6-10 years	
	Marker Board	3rd Floor	42	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,040	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	Quantity changed to update current observation
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	860	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,546	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	•	Location	Qualitity	OCIVI	Naiik	Replacement	Comments
_Corridor	Ceiling - Lay-in	1st Floor	2,923	SF		10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor	2,923	SF SF	6 6	10+ years 10+ years	
	Drinking Fountains - Double Fountain	151 11001	2.923		O	•	
		1et Floor	•	E ∧	7	10± vaare	
		1st Floor	2	EΑ	7 7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2 2	EA	7	10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted	1st Floor 1st Floor	2 2 5,846	EA SF	7 7	10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor	2 2 5,846 38	EA SF EA	7 7 7	10+ years 10+ years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted	1st Floor 1st Floor 1st Floor 1st Floor	2 2 5,846 38 5	EA SF EA EA	7 7 7 6	10+ years 10+ years 6-10 years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2 2 5,846 38 5 44	EA SF EA EA	7 7 7 6 6	10+ years 10+ years 6-10 years 6-10 years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2 2 5,846 38 5 44 6,723	EA SF EA EA EA SF	7 7 7 6 6 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 2nd Floor	2 2 5,846 38 5 44 6,723 2,288	EA SF EA EA SF SF	7 7 7 6 6 6 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor	2 2 5,846 38 5 44 6,723 2,288	EA SF EA EA SF SF EA	7 7 7 6 6 6 6 7	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288	EA SF EA EA SF SF EA SF	7 7 7 6 6 6 6 7 7	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288	EA SF EA EA SF SF EA SF EA	7 7 7 6 6 6 6 7 7	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288 18 2,631	EA SF EA EA SF EA SF EA SF	7 7 7 6 6 6 7 7 7 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288 18 2,631 2,288	EA SF EA SF SF EA SF SF SF	7 7 7 6 6 6 7 7 7 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288 18 2,631 2,288 2	EA SF EA EA SF EA SF EA SF EA	7 7 7 6 6 6 7 7 6 6 7	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years	
	Drinking Fountains - Single Fountain Floor - Concrete Epoxy/ Painted Lighting - Pendent/Surface Lighting - Wall Mounted Student Lockers - One Tier Walls - Plaster/Drywall Ceiling - Lay-in Drinking Fountains - Single Fountain Floor - Epoxy/ Painted Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor	2 2 5,846 38 5 44 6,723 2,288 2 2,288 18 2,631 2,288	EA SF EA SF SF EA SF SF SF	7 7 7 6 6 6 7 7 7 6	10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	

Campus Name: Gray Page : 19 of 46 Assessment Date: 11/16/2021



Catego	ry : Interior		В	uilding	: Main		30 IN Laranne AVENOE, Chicago, IL 60041
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
	Camera Viewing Station	Entire Building	2	EA	7	10+ years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North East	1,449	SF	6	10+ years	
	Floor - Epoxy/ Painted	North East	1,449	SF	7	10+ years	
	Handrails	North East	321	LF	7	10+ years	
	Lighting - Lay-in	North East	12	EΑ	7	6-10 years	
	Stairs - Asphalt	North East	105	LF	6	10+ years	
	Walls - Plaster/Drywall	North East	1,740	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South East	1,449	SF	6	10+ years	
	Floor - Epoxy/ Painted	South East	1,449	SF	7	10+ years	
	Handrails	South East	321	LF	7	10+ years	
	Lighting - Lay-in	South East	12	EA	7	6-10 years	
	Stairs - Asphalt	South East	105	LF	6	10+ years	
	Walls - Plaster/Drywall	South East	1,740	SF	6	10+ years	



Category : Exterior	Building : Annex

tegory . Exterior			ananig	. Allilex	Recommend	
up Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rance	Location	Quantity	COM	Nuin	Ropidocilicit	Comments
Exterior Doors - Exterior Steel Door	#10 - N	2	EA	6	6-10 years	
Exterior Doors - Exterior Steel Door	#10 - N #12 - NW	2	EA	7	10+ years	
Entrance Control - Audio and Video	#12 - NW #14 - NW	1	EA	6	6-10 years	
Exterior Doors - Store Front	#14 - NW	2	EA	6	6-10 years	
Power Door Operator and Controls	#14 - NW	1	EA	7	10+ years	
Exterior Doors - Store Front	#14 - NVV #16 - N	2	EA	7	10+ years	
Entrance Control - Audio and Video	#10 - N #2 - E	1	EA	6	6-10 years	
Exterior Doors - Side lite	#2 - E #2 - E	4	EA	7	10+ years	
Exterior Doors - Store Front	#2 - E #2 - E	2	EA	7		
Exterior Doors - Store Front  Exterior Doors - Transom Lite	#2 - E #2 - E	2	EA	7	10+ years	
Exterior Doors - Transom Lite Exterior Doors - Store Front	#2 - E #4 - S	2	EA	7	10+ years	
	_	1		-	10+ years	
Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door	#4 - S #6 - S	1	EA EA	7	10+ years	
		•		6	6-10 years	
Exterior Doors - Exterior Steel Door	#8 - SW	2	EA	6	6-10 years	
ındation						
Foundation - Concrete	Entire Building	789	LF	7	10+ years	
Superstructure - Steel	Entire Building	57,255	SF	7	10+ years	
Atm on						
ting Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	6-10 years	
Extends Eighting Trail Medition	Zitaro Danaing	ŭ	_, ,	Ü	o royouro	
f System						
Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
Coping - Stone	Main Roof	532	LF	5	2-5 years	
Downspouts - Interior Downspouts	Main Roof	215	LF	6	6-10 years	
Parapet - 16" - 30" Height	Main Roof	462	LF	6	10+ years	
Parapet - Parapet > 30"	Main Roof	70	LF	6	10+ years	
Roof - Modified Bitumen	Main Roof	14,701	SF	4	1-2 years	Per Site Engineer - Significant Damage
Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	14,701	SF	7	10+ years	-
Access Ladder - Metal	West Low Roof	1	EA	7	10+ years	
Chimney - Metal Flue	West Low Roof	18	LF	6	6-10 years	
	West Low Roof	328	LF	5	10+ years	W/Deteriorating Mortar Joints
	West Low Root					, Dotoriorating Mortal Collits
Coping - Stone			l F	6	n-10 vears	
Coping - Stone Downspouts - Interior Downspouts	West Low Roof	116	LF I F	6 6	6-10 years	
Coping - Stone Downspouts - Interior Downspouts Parapet - Parapet > 30"	West Low Roof West Low Roof	116 328	LF	6	10+ years	Per Site Engineer - Significant
Coping - Stone Downspouts - Interior Downspouts Parapet - Parapet > 30" Roof - Modified Bitumen	West Low Roof West Low Roof West Low Roof	116	LF SF	6 5	10+ years 1-2 years	Per Site Engineer - Significant Damage
Coping - Stone Downspouts - Interior Downspouts Parapet - Parapet > 30"	West Low Roof West Low Roof	116 328	LF	6	10+ years	_

Campus Name: Gray Page : 21 of 46 Assessment Date: 11/16/2021



Category : Exterior

#### William P Gray Elementary School 3730 N Laramie AVENUE, Chicago, IL 60641

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Concrete Topping						
<u>Walls</u>							
	Exterior Walls - Brick	Entire Building	20,846	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	10,560	SF	6	10+ years	
_Windows							
vviiiuow:	Guard - Guards perforated	Entire Building	1,525	SF	6	6-10 years	
	Lintels - Steel	Entire Building	536	LF	6	10+ years	
	Lintels - Stone	Entire Building	185	LF	6	10+ years	
	Windows - Louver	Entire Building	336	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,866	SF	6	6-10 years	
Catago	ry : Electrical	· ·	D	uildina	: Annex		
Calego	ry . Liectricai			unung	. Alliex	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
_	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Security System - CCTV	Entire Building	57,255	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	57,255	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	22	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EΑ	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	25	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	16,409	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	4,089	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,254	SF	6	10+ years	
_Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves annex, only 1 switchgear in annex building, 2 sections
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	Serves annex
	PA System	Entire Building	55,225	SF	6	6-10 years	Also connected to main and modular building
_Power_D	vistribution						
	Lighting and Power Panels - Above 100 A	Entire Building	12	EA	7	10+ years	
Campus I	Name: Gray		Page : 22 of 46				Assessment Date: 11/16/2021

**Building : Annex** 

Recommend



Calego	ry : Electrical	В	uilding	<u> </u>			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Also serves modular building
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	m Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	Serves annex
	Fire Alarm Strobe Lights	Electrical Room	57,255	SF	6	10+ years	Serves armex
	Fire Alarm_System	Electrical Room	57,255 57,255	SF	6	10+ years	Serves annex
	Fire Pump Controller	Electrical Room	57,255 1	EA	6	10+ years	Serves armex
	File Fulfip Controller	Electrical Room	1	LA	U	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Pump room	1	EA	6	10+ years	Serves main building
	Jockey Pump	Pump room	1	EA	6	10+ years	
Sprinkler	System						
	Sprinkler Heads	Entire Building	57,255	SF	7	10+ years	
	Sprinkler Piping	Entire Building	57,255	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	57,255	SF	6	10+ years	Serves annex
Catego	ry : Mechanical		В	uildina	: Annex		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	0						
	Chemical Pot Feeder	Roof	1	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	5	6-10 years	Serves annex
	Mounted - 101 - 200 tons	5 (	-		_	4.0	
	Glycol Feed	Roof	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Steel	Roof	500	LF	6	10+ years	
	Pressure Fill System	Roof	1	EA	6	10+ years	0 1105
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	5	6-10 years	Serves MDF room, evaporator behin ceiling
	ling Systems						

Campus Name: Gray Page : 23 of 46 Assessment Date: 11/16/2021



atego	ry : Mechanical		В	uilding	: Annex		
			<b></b>			Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	3rd Floor	1	EA	5	6-10 years	AHU 3, serves third floor
	Air Intake	3rd Floor	1	EA	6	10+ years	
	Induction Fan	3rd Floor	1	EA	6	10+ years	
	VAV Box	3rd Floor	2	EA	6	10+ years	Served by AHU 3
	Fan Power Box - Fan Power Box with No Coil	Above ceilings	40	EA	5	6-10 years	Located above ceilings
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001- 15000 cfm	Boiler Room	1	EA	5	6-10 years	Serves south side of annex buildi AHU 1, serves south side
	Air Intake	Boiler Room	1	EA	6	6-10 years	
	Induction Fan	Boiler Room	1	EΑ	6	10+ years	
	VAV Box	Boiler Room	5	EΑ	6	10+ years	Served by AHU 1, above ceilings
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001- 30000 cfm	Boiler Room	1	EA	5	6-10 years	Serves north side of annex buildir AHU 2
	Air Intake	Boiler Room	1	EA	6	10+ years	
	Induction Fan	Boiler Room	1	EA	5	10+ years	
	VAV Box	Boiler Room	10	ΕA	5	10+ years	Above ceilings, served by AHU 2
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Boiler Room	1	EA	5	6-10 years	Serves annex, ceiling mounted
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Boiler Room	2	EA	5	6-10 years	Serve annex, ceiling mounted
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating Coil - 11 - 20 tons	Roof	1	EA	5	6-10 years	Serves cafeteria
er Sy	estems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	1	EA	5	6-10 years	
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	5	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	1	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	5	6-10 years	Serves annex
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	6-10 years	Serves annex
	Water Fill System	Boiler Room	0	EA	5	6-10 years	

Campus Name: Gray Page : 24 of 46 Assessment Date: 11/16/2021



Serve air handlers, ceiling mounted  Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serve air handlers, ceiling mounted  Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves annex building Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serves Liebert unit in MDF room Serve fan power boxes and 1 RTU
Serve fan power boxes and 1 RTU
Serve fan coil boxed
Rusting at top surpace, previously rassessed
a336336u
In kitchen
Comments
Serves annex
Serves annex
Serves dishwasher

Campus Name: Gray Page : 25 of 46 Assessment Date: 11/16/2021



Catego	ry : Plumbing		В	, , , , , , , , , , , , , , , , , , , ,			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	57,255	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	57,255	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	57,255	SF	6	10+ years	
	Sanitary Piping	Entire Building	57,255	SF	6	10+ years	
	Storm Piping	Entire Building	57,255	SF	6	10+ years	
	Vent Piping	Entire Building	57,255	SF	6	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	1st Floor and Mechanical Room	1	EA	6	10+ years	Serves annex
	Pumps - Sump-Simplex	1st Floor and Mechanical Room	1	EA	6	10+ years	Under elevator

Catego	ry : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	1st floor 416 conference	150	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor 416 conference	1	EA	7	10+ years	
	Floor - Tile	1st floor 416 conference	150	SF	7	10+ years	
	Lighting - Lay-in	1st floor 416 conference	2	EA	7	10+ years	
	Walls - Concrete Block	1st floor 416 conference	575	SF	7	10+ years	
	Ceiling - Lay-in	408 Business Office	478	SF	6	10+ years	
	Doors - Wood Doors inclu hw	408 Business Office	1	EA	6	10+ years	
	Floor - Tile	408 Business Office	478	SF	6	10+ years	
	Lighting - Lay-in	408 Business Office	10	EA	7	6-10 years	
	Power Distribution	408 Business Office	10	EA	6	10+ years	
	Storage/ Closet	408 Business Office	18	SF	7	10+ years	
	Walls - Concrete Block	408 Business Office	275	SF	6	10+ years	
	Walls - Plaster/Drywall	408 Business Office	275	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen Manager's Office	76	SF	6	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager's Office	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	Kitchen Manager's Office	76	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager's Office	1	EA	6	6-10 years	
	Power Distribution	Kitchen Manager's Office	4	EA	6	10+ years	
	Walls - Concrete Block	Kitchen Manager's Office	87	SF	6	10+ years	
	Ceiling - Lay-in	Office 602A	260	SF	6	10+ years	
	Doors - Side-lite	Office 602A	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office 602A	1	EA	6	10+ years	
	Floor - Carpet	Office 602A	260	SF	6	6-10 years	
	Lighting - Lay-in	Office 602A	2	EA	7	6-10 years	
	Storage/ Closet	Office 602A	7	SF	7	10+ years	
	Walls - Plaster/Drywall	Office 602A	727	SF	6	10+ years	

Campus Name: Gray Page : 26 of 46 Assessment Date: 11/16/2021



Catego	ry : Room		Building : Annex						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	Room 410, Student Services Office	138	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 410, Student Services Office	1	EA	6	10+ years			
	Floor - Tile	Room 410, Student Services Office	138	SF	6	10+ years			
	Lighting - Lay-in	Room 410, Student Services Office	2	EA	7	6-10 years			
	Power Distribution	Room 410, Student Services Office	4	EA	6	10+ years			
	Walls - Concrete Block	Room 410, Student Services Office	80	SF	6	10+ years			
	Walls - Plaster/Drywall	Room 410, Student Services Office	80	SF	6	10+ years			
	Ceiling - Lay-in	Room 418, Faculty Center	444	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Room 418, Faculty Center	1	ĒΑ	6	10+ years			
	Floor - Tile	Room 418, Faculty Center	444	SF	6	10+ years			
	Lighting - Lay-in	Room 418, Faculty Center	6	ĒΑ	6	6-10 years			
	Power Distribution	Room 418, Faculty Center	8	ΕA	6	10+ years			
	Walls - Concrete Block	Room 418, Faculty Center	255	SF	6	10+ years			
	Walls - Plaster/Drywall	Room 418, Faculty Center	255	SF	6	10+ years			
	Work Sink	Room 418, Faculty Center	1	EΑ	7	10+ years			
	Ceiling - Lay-in	Work Room in Library	131	SF	6	10+ years			
	Doors - Steel Doors incl hw	Work Room in Library	1	EA	6	10+ years			
	Floor - Tile	Work Room in Library	131	SF	6	10+ years			
	Lighting - Lay-in	Work Room in Library	2	EA	7	6-10 years			
	Power Distribution	Work Room in Library	4	EA	6	10+ years			
	Storage/ Closet	Work Room in Library	97	SF	7	10+ years			
	Walls - Concrete Block	Work Room in Library	75	SF	6	10+ years			
	Walls - Plaster/Drywall	Work Room in Library	75 75	SF	6	10+ years			
	Ceiling - Lay-in	room 412, Assistant Principal's	180	SF	6	10+ years			
		Office	100			-			
	Doors - Wood Doors inclu hw	room 412, Assistant Principal's Office	1	EA	6	10+ years			
	Floor - Tile	room 412, Assistant Principal's	180	SF	6	10+ years			
	Limbting Lavin	Office	0	Ε.	7	0.40			
	Lighting - Lay-in	room 412, Assistant Principal's Office	2	EA	7	6-10 years			
	Power Distribution	room 412, Assistant Principal's Office	8	EA	6	10+ years			
	Walls - Concrete Block	room 412, Assistant Principal's Office	52	SF	6	10+ years			
	Walls - Plaster/Drywall	room 412, Assistant Principal's Office	155	SF	6	10+ years			
_Kitchen									
	Ceiling - Lay-in	1st Floor	764	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years			
	Floor - Epoxy/ Painted	1st Floor	764	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years			
	Storage/ Closet	1st Floor	104	SF	7	10+ years			
	Glorage/ Gloset	1301 1001	104	Ji	,	TOT years			

Campus Name: Gray Page : 27 of 46 Assessment Date: 11/16/2021



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	879	SF	6	10+ years	
	Ceiling - Lay-in	Servery	967	SF	6	10+ years	
	Doors - Steel Doors incl hw	Servery	4	EA	6	10+ years	
	Floor - Epoxy/ Painted	Servery	967	SF	7	10+ years	
	Lighting - Lay-in	Servery	11	EΑ	7	6-10 years	
	Serving Line	Servery	45	LF	6	10+ years	
	Walls - Concrete Block	Servery	1,112	SF	6	10+ years	
Library							
,	Casework	2nd Floor	84	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,297	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Carpet	2nd Floor	2,297	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	2,237	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,321	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor		SF	6		
	walls - Plaster/Drywall	2nd Floor	661	SF	О	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	1st Floor	4,089	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EΑ	6	10+ years	
	Floor - Sport Flooring	1st Floor	4,089	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	9	EA	6	6-10 years	
	Storage/ Closet	1st Floor	291	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,702	SF	6	10+ years	
MDF ID	F						
_	Doors - Steel Doors incl hw	2nd Floor Annex building	1	EA	7	10+ years	
	Finishes	2nd Floor Annex building	137	SF	7	10+ years	
	Other Cooling Unit	2nd Floor Annex building	2	EA	5	0-1 year	Central air conditioning currently not working
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	22	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	162	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	45	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	193	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	139	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	275	SF	7	10+ years	
	Vaults	1st Floor	170	SF	7	10+ years	Vault has been converted into a work
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	room
	Mechanical/ Service Rooms	2nd Floor	5,652	SF	7	10+ years	
	Wiconamical Cervice Nooms	ZIIU I IOOI	5,002	Oi.	,	TOT years	

Campus Name: Gray Page : 28 of 46 Assessment Date: 11/16/2021



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
<b>3roup</b>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	2nd Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	40	SF	7	10+ years	
	Janitor's Closet	3rd Floor	32	SF	7	10+ years	Quantity changed to correct current observation
estroor	n						
	Accessories	1st Floor	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	43	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Terrazzo	1st Floor	43	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EΑ	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EΑ	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	49	SF	6	10+ years	
	Water Closet	1st Floor	1	ĒΑ	6	10+ years	
	Accessories	1st Floor	209	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	209	SF	6	10+ years	
	Floor - Terrazzo	1st Floor	209	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	2	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	240	SF	6	10+ years	
	Water Closet	1st Floor	240	EA	6	10+ years	
	Accessories	1st Floor	209	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	209	SF	6	•	
	Floor - Terrazzo		209	SF	6	10+ years	
		1st Floor		SF EA		10+ years	
	Floor Drain	1st Floor	1		7	10+ years	
	Lavatory	1st Floor	3	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	5	EΑ	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	240	SF	6	10+ years	
	Water Closet	1st Floor	4	EA	6	10+ years	
	Accessories	2nd Floor	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	43	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor	43	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	49	SF	6	10+ years	
	Water Closet	2nd Floor	1	EΑ	6	10+ years	
	Accessories	2nd Floor	209	SF	7	6-10 years	



Catego	ry : Room		В	Building : Annex				
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	2nd Floor	209	SF	6	10+ years		
	Floor - Terrazzo	2nd Floor	209	SF	6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Lavatory	2nd Floor	3	EA	6	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	10+ years		
	Urinals	2nd Floor	2	EA	6	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	240	SF	6	10+ years		
	Water Closet	2nd Floor	2	EA	6	10+ years		
	Accessories	2nd Floor	209	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	209	SF	6	10+ years		
	Floor - Terrazzo	2nd Floor	209	SF	6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Lavatory	2nd Floor	3	EA	6	10+ years		
	Lighting - Lay-in	2nd Floor	5	EA	7	6-10 years		
	Partitions	2nd Floor	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	240	SF	6	10+ years		
	Water Closet	2nd Floor	4	EA	6	10+ years		
	Accessories	3rd Floor	209	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	209	SF	6	10+ years		
	Floor - Terrazzo	3rd Floor	209	SF	6	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Lavatory	3rd Floor	3	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years		
	Partitions	3rd Floor	2	EA	7	10+ years		
	Urinals	3rd Floor	2	EA	6	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	240	SF	6	10+ years		
	Water Closet	3rd Floor	2	EA	6	10+ years		
	Accessories	3rd Floor	209	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	209	SF	6	10+ years		
	Floor - Terrazzo	3rd Floor	209	SF	6	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Lavatory	3rd Floor	3	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years		
	Partitions	3rd Floor	4	EA	7	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	240	SF	6	10+ years		
	Water Closet	3rd Floor	4	EA	6	10+ years		
	Accessories	3rd Floor	43	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	43	SF	6	10+ years		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years		
	Floor - Terrazzo	3rd Floor	43	SF	6	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Lavatory	3rd Floor	1	EA	6	10+ years		
	Lighting - Lay-in	3rd Floor	1	EA	7	6-10 years		



Catego	ory : Room		Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	3rd Floor	49	SF	6	10+ years			
	Water Closet	3rd Floor	1	EΑ	6	10+ years			
	Accessories	In Kitchen Area	38	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	In Kitchen Area	38	SF	6	10+ years			
	Doors - Steel Doors incl hw	In Kitchen Area	1	EΑ	6	10+ years			
	Floor - Terrazzo	In Kitchen Area	38	SF	6	10+ years			
	Floor Drain	In Kitchen Area	1	EA	7	10+ years			
	Lavatory	In Kitchen Area	1	EΑ	6	10+ years			
	Lighting - Lay-in	In Kitchen Area	1	EΑ	7	6-10 years			
	Walls - Structural Glazed Tile	In Kitchen Area	44	SF	6	10+ years			
	Water Closet	In Kitchen Area	1	EA	6	10+ years			
Catego	Category : Classroom		В	uilding	: Annex	(			
			• 44			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classio	om #401 (Regular Classroom)	1st Floor	836	SF	6	10 L VOORO			
	Ceiling - Lay-in				6	10+ years			
	Doors - Side-lite	1st Floor	12	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor 1st Floor	836 12	SF	6	10+ years			
	Lighting - Lay-in			EA	7	6-10 years			
	Marker Board	1st Floor	22	LF	6	6-10 years			
	Storage/ Closet Walls - Concrete Block	1st Floor	63 1,580	SF	7 6	10+ years			
	Walls - Concrete Block	1st Floor	1,580	SF	ь	10+ years			
Classro	om #402 (Computer Lab)								
	Ceiling - Lay-in	1st Floor	1,021	SF	6	10+ years			
	Doors - Side-lite	1st Floor	12	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	1,021	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	24	LF	6	6-10 years			
	Storage/ Closet	1st Floor	7	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	672	SF	6	10+ years			
	Walls - Concrete Block	1st Floor	225	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	360	SF	6	10+ years			
Classro	om #403 (Regular Classroom)								
	Casework	1st Floor	37	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	675	SF	6	10+ years			
	Doors - Side-lite	1st Floor	12	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	675	SF	6	10+ years			
						ŕ			

Campus Name: Gray Page: 31 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	78	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	615	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	675	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	5	10+ years	
Classroo	om #404 (Regular Classroom)						
	Casework	1st Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	590	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	590	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	7	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	710	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	360	SF	6	10+ years	
	·			•		.0. ,00.0	
Classroo	m #405 (Regular Classroom)						
	Casework	1st Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	675	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	675	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	14	LF	6	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	655	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	650	SF	6	10+ years	
Classroo	nm #406 (Regular Classroom)						
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	590	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	590	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	7	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,180	SF	6	10+ years	
	vvalis - Colletete block	1301 1001	1,180	Ji	U	TOT years	
	om #420 (Regular Classroom)						

Campus Name: Gray Page : 32 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	Building : Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	836	SF	6	10+ years	
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	836	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	6	6-10 years	
	Storage/ Closet	1st Floor	164	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,580	SF	6	10+ years	
Classroo	om #501 (Regular Classroom)						
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	836	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	2	SF	6	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	836	SF	6	10+ years	
		2nd Floor	12	EA	6		
	Lighting - Lay-in			LF		6-10 years	
	Marker Board	2nd Floor	25	SF	6	6-10 years	
	Storage/ Closet	2nd Floor	108		7	10+ years	
	Walls - Concrete Block	2nd Floor	1,500	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	10+ years	
Classroo	om #502 (Regular Classroom)						
	Casework	2nd Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	888	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	762	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	360	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #503 (Science Classroom)						
	Casework	2nd Floor	22	LF	6	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,000	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	1,000	SF	6	10+ years	
			12	EA	6		
	Doors - Wood Doors inclu hw	2nd Floor				10+ years	
	Floor - Tile	2nd Floor	1,000	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	29	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	300	SF	7	10+ years	

Campus Name: Gray Page : 33 of 46 Assessment Date: 11/16/2021



atego	ry : Classroom		B	uilding	: Annex		
	Home Time	Location	Overetite.	UOM	Donk	Recommend	Comments
Froup	Item - Type Walls - Plaster/Drywall	2nd Floor	Quantity 1,866	SF	Rank 6	Replacement 10+ years	Comments
	Work Sink	2nd Floor	1,000	EA	6 7	10+ years 10+ years	
	WORK SILIK	2110 F1001	2	EA	,	10+ years	
Classroo	om #504 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	888	SF	7	10+ years	
	Chalk Board	2nd Floor	55	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	762	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	360	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	10+ years	
Classroo	om #508 (Regular Classroom)						
	Casework	2nd Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	888	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	762	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	360	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
	WORK SILIK	2110 11001	ı	EA	,	10+ years	
Classroo	om #601 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	836	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	836	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	26	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	116	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,580	SF	6	10+ years	
	Work Sink	3rd Floor	1	EΑ	7	10+ years	

Campus Name: Gray Page : 34 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	4,182	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Carpet	3rd Floor	4,182	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	60	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	28	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	7,014	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	360	SF	6	10+ years	
Classroo	om #603 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	7	10+ years	Observed no damaged tiles. Rank
	Coming Lay in		700	O.	,	101 youro	changed to update current observation
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	700	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	6	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	72	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,324	SF	6	10+ years	
Classroo	om #605 (Regular Classroom)						
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	580	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	580	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	27	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,116	SF	6	10+ years	
Classroo	om #607 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	836	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	836	SF	7	10+ years	No damaged flooring observed. Rank changed to update current
	Lighting Lovin	2rd Floor		Г^	^	6.10	observation
	Lighting - Lay-in	3rd Floor	11	EΑ	6	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	26	LF	6	6-10 years	

Campus Name: Gray Page : 35 of 46 Assessment Date: 11/16/2021



Catego	ry : Classroom		В	uilding	: Annex	[	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	100	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,582	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	Faucet & levers function. No damage observed. Rank changed to update current observation
Classroc	om #612 (Regular Classroom)						
	Casework	3rd Floor	45	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	11	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	7	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	878	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	360	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Annex	[	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,893	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	4,893	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Student Lockers - Two Tiers	1st Floor	187	EΑ	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,627	SF	6	10+ years	
	Coiling Lay in	2nd Floor	3 085	SE.	6	10 L VOORS	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,893	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	4,893	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Student Lockers - Two Tiers	1st Floor	187	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,627	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,985	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	3,985	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	108	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	4,583	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,985	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	3,985	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	108	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	4,583	SF	6	10+ years	

Campus Name: Gray Page : 36 of 46 Assessment Date: 11/16/2021



Catego	ry : Interior		В	Building : Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Safety							
,	Security Cameras	1st Floor	3	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	East	1,182	SF	6	10+ years	
	Floor - Terrazzo	East	1,182	SF	6	10+ years	
	Handrails	East	270	LF	7	10+ years	
	Lighting - Lay-in	East	12	EA	7	6-10 years	
	Stairs - Terrazzo	East	108	LF	6	10+ years	
	Walls - Structural Glazed Tile	East	1,419	SF	6	10+ years	
	Ceiling - Lay-in	North	1,182	SF	6	10+ years	
	Floor - Terrazzo	North	1,182	SF	6	10+ years	
	Handrails	North	270	LF	7	10+ years	
	Lighting - Lay-in	North	12	EA	7	6-10 years	
	Stairs - Terrazzo	North	108	LF	6	10+ years	
	Walls - Structural Glazed Tile	North	1,419	SF	6	10+ years	
	Ceiling - Lay-in	South	1,182	SF	6	10+ years	
	Floor - Terrazzo	South	1,182	SF	6	10+ years	
	Handrails	South	270	LF	7	10+ years	
	Lighting - Lay-in	South	4	EA	7	6-10 years	
	Stairs - Terrazzo	South	108	LF	6	10+ years	
	Walls - Structural Glazed Tile	South	1,419	SF	6	10+ years	
Vertical (	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	6	10+ years	





Category: Exterior Building: Modular 1 (4-Classroom) Recommend Item - Type Location Replacement Comments Quantity **UOM** Group Rank Entrance Entrance Control - Audio and Video FΑ #13 - F 1 6 6-10 years #13 - E 2 EΑ 6 Exterior Doors - Exterior Steel Door 6-10 years Ramps - Concrete LF #13 - E 12 6 10+ years Exterior Doors - Exterior Steel Door #15 - W 2 EΑ 6 6-10 years ΙF Ramps - Concrete #15 - W 12 10+ years Foundation Foundation - Concrete **Entire Building** 294 LF 7 10+ years Superstructure - Steel Entire Building 5,300 SF 7 10+ years \_Lighting Exterior Lighting - Wall Mounted **Entire Building** 4 EΑ 6 6-10 years Roof System Coping - Metal Main Roof LF 294 6 6-10 years Downspouts - Exterior Downspouts Main Roof 48 LF 6 6-10 years SF Roof - PVC Membrane Main Roof 5.400 6 6-10 years Roof Structure - Steel / Metal Deck/ Main Roof SF 5.400 10+ years Concrete Topping Walls Exterior Walls - Hardie Board 3.528 SF 6 **Entire Building** 6-10 years Windows Guard - Guards perforated **Entire Building** 240 SF 6 6-10 years LF Lintels - Steel **Entire Building** 6 10+ years 40 SF Windows - Sash Aluminum Double-pane **Entire Building** 240 6 6-10 years Category: Electrical Building: Modular 1 (4-Classroom) Recommend Rank Group Item - Type Location Quantity **UOM** Replacement Comments Emergency System Security System - CCTV 1st Floor SF 5 6-10 years 5.300 SF Security System - Intrusion Detection 1st Floor 5.300 5 6-10 years Exit Signs - Corridors and Stairs EΑ 5 6-10 years 1st Floor Emergency Battery Packs - Corridors and 1st Floor 3 EΑ 6 6-10 years Emergency Battery Packs - Students Toilets 1st Floor 2 EΑ 6 6-10 years

Campus Name: Gray Page: 38 of 46 Assessment Date: 11/16/2021



	ry : Electrical		В	uliaing	: Modul	ar 1 (4-Classro Recommend	oom )	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Main Se			,					
	PA System	Electrical Room	5,300	SF	5	6-10 years	Connected to main and annea	
Power D	istribution							
	Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp	1st Floor 1st Floor	2 1	EA EA	7 7	10+ years 10+ years		
Catego	ry : Fire Protection		В	uildina	: Modul	ar 1 (4-Classro	oom )	
Jaiogo	.,		_	uug		Recommend	, c ,	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m					·		
	Fire Alarm Strobe Lights	1st Floor	5,300	SF	6	10+ years	None, horns only	
	Fire Alarm_System	1st Floor	5,300	SF	6	10+ years	Horns only, basic system	
Sprinkle	r System							
	Sprinkler Heads	1st Floor	5,300	SF	7	10+ years		
	Sprinkler Piping	1st Floor	5,300	SF	6	10+ years		
	Wet Sprinkler System	1st Floor	5,300	SF	6	10+ years	Using city pressure	
Category : Mechanical		_	Building : Modular 1 (4-Classroom )					
Catego	ry : Mechanicai		В	unung	. Wodu		om ,	
_		1		_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank			
Group	Item - Type ature Control		Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	Item - Type	Location  Entire Building		_		Recommend		
Group Tempera	Item - Type ature Control Electric Thermostat		Quantity	UOM	Rank	Recommend Replacement	Comments	
Group Tempera	Item - Type ature Control Electric Thermostat		Quantity	UOM	Rank	Recommend Replacement	Comments	
<b>Group</b> Tempera	Item - Type  ature Control  Electric Thermostat  tilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	Quantity 4	<b>UOM</b>	Rank 5	Recommend Replacement 10+ years	Comments	
<b>Group</b> Tempera	Item - Type  ature Control  Electric Thermostat  tilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	Quantity 4	<b>UOM</b>	Rank 5	Recommend Replacement 10+ years	Comments	
Group Tempera Unit Ven	Item - Type  ature Control  Electric Thermostat  tilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling  on  Exhaust Fans- Roof Mounted - 500 - 1500  CFM	Entire Building  Exterior wall	Quantity 4	EA EA	<b>Rank</b> 5 6	Recommend Replacement  10+ years  6-10 years	Comments  Serve exterior univents	
Group Tempera Unit Ven	Item - Type  ature Control Electric Thermostat  tilation Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling  Exhaust Fans- Roof Mounted - 500 - 1500 CFM  ry: Plumbing	Entire Building  Exterior wall	Quantity 4	EA EA	<b>Rank</b> 5 6	Recommend Replacement  10+ years  6-10 years  6-10 years  ar 1 (4-Classro Recommend	Comments  Serve exterior univents  com )	
Group Tempera Unit Ven Ventilatio	Item - Type  ature Control  Electric Thermostat  tilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling  on  Exhaust Fans- Roof Mounted - 500 - 1500  CFM	Entire Building  Exterior wall	Quantity 4	EA EA	<b>Rank</b> 5 6	Recommend Replacement  10+ years  6-10 years  6-10 years  ar 1 (4-Classro	Comments  Serve exterior univents  com )	
Group Tempera Unit Ven Ventilatio Catego Group	Item - Type  ature Control  Electric Thermostat  Itilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling  On  Exhaust Fans- Roof Mounted - 500 - 1500  CFM  ry: Plumbing  Item - Type	Entire Building  Exterior wall  Roof	Quantity  4  4  1	EA EA uilding	6 : Modul	Recommend Replacement  10+ years  6-10 years  6-10 years  ar 1 (4-Classro Recommend	Comments  Serve exterior univents  com )	
Group Tempera Unit Ven	Item - Type  ature Control  Electric Thermostat  Itilation  Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling  On  Exhaust Fans- Roof Mounted - 500 - 1500  CFM  ry: Plumbing  Item - Type	Entire Building  Exterior wall  Roof	Quantity  4  4  1	EA EA uilding	6 : Modul	Recommend Replacement  10+ years  6-10 years  6-10 years  ar 1 (4-Classro Recommend	Comments  Serve exterior univents  oom )	

Campus Name: Gray Page : 39 of 46 Assessment Date: 11/16/2021



Category : Plumbing Building : Modular 1 (4-Classroom			oom )				
	_			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	1st Floor	5,300	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	1st Floor	5,300	SF	6	10+ years	
	(Horizontal Lines)	4 (5)	5.000	0.5	•	40	
	Sanitary Piping	1st Floor	5,300	SF SF	6	10+ years	
	Storm Piping Vent Piping	1st Floor 1st Floor	5,300 5,300	SF SF	6 6	10+ years 10+ years	
	vent riping	151 11001	5,300	SF	O	10+ years	
Catego	ry : Classroom		В	uildina	: Modul	ar 1 (4-Classro	oom )
	<b>,</b>					Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #110 (Regular Classroom)		_			-	
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	933	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
						•	
Classroo	m #111 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	933	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #112 (Regular Classroom)						
VIGSSIUU	Ceiling - Lay-in	1st Floor	812	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	933	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classes -	m #112 (Dogular Classification)						
Ciassroo	m #113 (Regular Classroom)	1st Floor	040	SF	6	10	
	Ceiling - Lay-in Doors - Wood Doors inclu hw		812 1		6	10+ years	
	DOOLS - MOOD DOOLS INCIN UM	1st Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	812	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	933	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	oom )
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	• •	Location	Quantity	CON	IVALIK	Replacement	Comments
<u>/lecnani</u>	ical/ Service Rooms						0
	Mechanical/ Service Rooms	In Classroom 113	84	SF	7	10+ years	Quantity changed to correct current observation
							observation
Restrooi							
	Accessories	1st Floor	206	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	206	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	206	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Urinals	1st Floor	2	EA	6	10+ years	
	Walls - Metal Panel	1st Floor	236	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	180	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	100	EA	6	•	
	Floor - Tile/Sheet	1st Floor	180	SF	7	10+ years	
						10+ years	
	Floor Drain	1st Floor 1st Floor	1	EΑ	7	10+ years	
	Hand Dryer		1	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	6	10+ years	
	Lighting - Lay-in	1st Floor	2	EΑ	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	207	SF	6	10+ years	
	Water Closet	1st Floor	4	EA	6	10+ years	
	Accessories	1st Floor	49	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	49	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	



Catego	ry : Room		Building : Modular 1 (4-Classroom )					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	1st Floor	1	EA	6	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
	Walls - Metal Panel	1st Floor	56	SF	6	10+ years		
	Water Closet	1st Floor	1	EA	6	10+ years		

Category: Interior Building: Modular 1 (4-Classroom)

ogory i intorior		Dunaing i Modulai i (4 Olacorochi )				
	Recommend					
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ceiling - Lay-in	1st Floor	549	SF	6	10+ years	
Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
Floor - Tile/Sheet	1st Floor	549	SF	7	10+ years	
Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
Walls - Metal Panel	1st Floor	631	SF	6	10+ years	
	Item - Type  Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	Item - TypeLocationCeiling - Lay-in1st FloorDoors - Steel Doors incl hw1st FloorDrinking Fountains - Single Fountain1st FloorFloor - Tile/Sheet1st FloorLighting - Lay-in1st Floor	Item - TypeLocationQuantityCeiling - Lay-in1st Floor549Doors - Steel Doors incl hw1st Floor4Drinking Fountains - Single Fountain1st Floor2Floor - Tile/Sheet1st Floor549Lighting - Lay-in1st Floor7	Item - TypeLocationQuantityUOMCeiling - Lay-in1st Floor549SFDoors - Steel Doors incl hw1st Floor4EADrinking Fountains - Single Fountain1st Floor2EAFloor - Tile/Sheet1st Floor549SFLighting - Lay-in1st Floor7EA	Item - TypeLocationQuantityUOMRankCeiling - Lay-in1st Floor549SF6Doors - Steel Doors incl hw1st Floor4EA6Drinking Fountains - Single Fountain1st Floor2EA7Floor - Tile/Sheet1st Floor549SF7Lighting - Lay-in1st Floor7EA7	Item - TypeLocationQuantityUOMRankRecommend ReplacementCeiling - Lay-in1st Floor549SF610+ yearsDoors - Steel Doors incl hw1st Floor4EA610+ yearsDrinking Fountains - Single Fountain1st Floor2EA710+ yearsFloor - Tile/Sheet1st Floor549SF710+ yearsLighting - Lay-in1st Floor7EA76-10 years

Campus Name: Gray Page : 42 of 46 Assessment Date: 11/16/2021



Category : Site	Building : Site

Jaiogo	iy. Oile			unung	. Oile	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
	errin = remanger = remaining		-		•	, , , , , , , , , , , , , , , , , , , ,	
encina							
Chonig	Fencing - Chain Link	South Courtyard and Entire Site	40	LF	6	6-10 years	
	Fencing - New Standard Ornamental	South Courtyard and Entire Site	2,310	LF	6	6-10 years	
	r ending - New Standard Offiamental	South Courtyard and Entire Site	2,310	LI	O	0-10 years	
andsca	pe						
	Benches	Entire Site	10	EA	6	6-10 years	
	Irrigation	Entire Site	35,358	SF	6	6-10 years	
	Landscape - Grass	Entire Site	35,358	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	12,359	SF	6	10+ years	
	Parkway trees	Entire Site	45	ĒΑ	6	10+ years	
	Planting Beds/ Area	Entire Site	2,245	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	17,865	SF	6	6-10 years	
	Trash Receptacles	Entire Site	3	ĒΑ	6	6-10 years	
	·					,	
Parking I							
	Concrete Curbs	North	394	LF	6	10+ years	
	Surface - Asphalt	North	8,303	SF	6	6-10 years	
	Trash Enclosure - Masonry	North	1,760	SF	6	10+ years	
	Concrete Curbs	West	360	LF	6	10+ years	
	Surface - Asphalt	West	12,420	SF	5	2-5 years	Cracking throughout, potholes
	Vehicular Screening	West	245	LF	6	10+ years	
Playgrou	nd						
<del>, g</del>	Equipment - Pre K 3-5	North	1	EA	6	6-10 years	
	Surface - Poured Surface	North	6,805	SF	6	6-10 years	
	Equipment - School Age 5-12	West	1	EA	6	6-10 years	
	Surface - Poured Surface	West	4,674	SF	6	6-10 years	
	2.2.2.2.2.2.2.3.3.3.3.3.3.3.3.3.3.3.3.3		.,	٠.	·	<b>,</b>	
Sidewalk							
	Sidewalks - Internal Walks	Entire Site	256	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	20,556	SF	6	10+ years	
Signage							
uanade	Flag Pole - Flag Pole	East	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	East	1	EA	6	6-10 years	
	marques 1 100 Standing Buok Lighted			L, (	J	3 10 yours	



#### **William P Gray Elementary School**


3730 N Laramie AVENUE, Chicago, IL 60641

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Gray Page : 44 of 46 Assessment Date: 11/16/2021





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	· ·	•	•						
Art Room	Special Program	3rd Floor	305	305	820	132	66	N	N
Kindergarten	Kindergarten	1st Floor	103	103	820	132	66	N	Υ
Kindergarten	Kindergarten	1st Floor	104	104	890	132	66	N	Υ
Kindergarten	Kindergarten	1st Floor	105	105	820	180	72	N	Υ
Office	Regular Classroom	3rd Floor	300	300	405	66	33	N	N
Regular Classroom	Library	2nd Floor	204	204	820	132	66	N	Υ
Regular Classroom	Library	2nd Floor	206	206	550	76	38	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	820	180	72	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	820	180	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	200	200	405	66	33		
Regular Classroom	Regular Classroom	2nd Floor	201	201	820	180	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	820	132	66	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	820	132	66	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	820	180	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	820	180	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	820	132	66	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	820	180	72	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	820	132	66	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	820	180	72	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	820	132	66	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	820	180	72	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	820	132	66	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	820	132	66	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	820	180	72	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	820	132	66	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	820	180	72	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	820	132	66	N	Υ
Vacant	Regular Classroom	1st Floor	101	101	890	150	60	N	Υ
Building : Annex									
Computer Lab	Computer Lab	1st Floor	402	1-02	1,021	336	56	N	Υ
Regular Classroom	Regular Classroom	1st Floor	401	1-01	836	87	45	N	Υ
Regular Classroom	Regular Classroom	1st Floor	403	1-03	675	76	40	N	Υ
Regular Classroom	Regular Classroom	1st Floor	404	1-04	590	192	32	N	Υ
Regular Classroom	Regular Classroom	1st Floor	405	1-04	675	57	30	N	Υ
Regular Classroom	Regular Classroom	1st Floor	406	1-05	590	177	38	N	Υ
Regular Classroom	Regular Classroom	1st Floor	420	1-22	836	87	45	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	501	2-04	836	87	45	N	Υ



**Classroom Summary** 

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	502	2-01	888	144	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	504	2-05	888	144	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	508	2-19	888	144	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	601	3-01	836	87	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	603	3-03	700	73	38	N	Y
Regular Classroom	Regular Classroom	3rd Floor	605	3-05	580	44	23	N	Y
Regular Classroom	Regular Classroom	3rd Floor	607	607	836	87	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	612	3-17	865	144	48	N	Y
Regular Classroom	Rehabilitation under progress	3rd Floor	602BCDE	3-02	4,182	708	248	N	Y
Science Classroom	Science Classroom	2nd Floor	503	2-03	1,000	73	38	N	Y

Building : Modular 1 (4-Classroom )									
Regular Classroom	Regular Classroom	1st Floor	110	NA	812	132	66	N	Υ
Regular Classroom	Regular Classroom	1st Floor	111	NA	812	132	66	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	812	132	66	N	Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	812	132	66	N	Υ

Campus Name: Gray Page : 46 of 46 Assessment Date: 11/16/2021