

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2009	3	127,162
Campus Total			127,162

Category : Exterior Building : Main

						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	12A-Roof five	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Door 1 - Southeast Main Entrance	2	EA	6	6-10 years	
	Exterior Doors - Store Front	Door 1 - Southeast Main Entrance	5	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 1 - Southeast Main Entrance	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - Southeast Main Entrance	120	LF	6	10+ years	
	Power Door Operator and Controls	Door 1 - Southeast Main Entrance	2	EA	7	6-10 years	
	Ramps - Concrete	Door 1 - Southeast Main Entrance	100	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 1 - Southeast Main Entrance	36	LF	7	10+ years	
	Exterior Doors - Store Front	Door 10 - East north	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 10 - East north	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 11 - East south	2	EA	5	0-1 year	Door not shutting on its own. Has to be pulled firmly shut.
	Exterior Doors - Transom Lite	Door 11 - East south	1	EA	7	10+ years	be palled liftling strat.
	Exterior Doors - Exterior Steel Door	Door 12 Roof 5	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 13 Roof 6	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 14 Roof 6	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 2 - West	1	EA	6	6-10 years	
	Exterior Doors - Store Front	Door 2 - West	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 2 - West	2	EA	6	10+ years	
	Power Door Operator and Controls	Door 2 - West	1	EA	7	6-10 years	
	Exterior Doors - Store Front	Door 3 - North	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 3 - North	2	EA	6	10+ years	
	Power Door Operator and Controls	Door 3 - North	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 4 - North	2	EA	6	10+ years	



tem - Type Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Overhead Rolling/ Garage Door Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door  Foundation - Concrete Superstructure - Steel	Location  Door 5 - West Door 5 - West Door 6 - West Door 7 - Northwest  Door 8 - North  Door 9 - North Door 9 - North  Entire Building	Quantity 1 2 1 1 1 1	UOM EA EA EA EA EA	Rank 6 6 4 5	Recommend Replacement 10+ years 10+ years 0-1 year 0-1 year	Comments  Corroded door and frame Rusting.  Damaged door and corroded frame. Door does not lock properly. Missing hardware.
Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Overhead Rolling/ Garage Door Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door	Door 5 - West Door 5 - West Door 6 - West Door 7 - Northwest  Door 8 - North  Door 9 - North Door 9 - North	1 2 1 1 1	EA EA EA EA	6 6 4 5	10+ years 10+ years 0-1 year 0-1 year 0-1 year	Corroded door and frame Rusting.  Damaged door and corroded frame. Door does not lock properly. Missing
Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Overhead Rolling/ Garage Door Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door  Foundation - Concrete	Door 5 - West Door 6 - West Door 7 - Northwest  Door 8 - North  Door 9 - North Door 9 - North	2 1 1 1	EA EA EA	6 4 5 4	10+ years 0-1 year 0-1 year 0-1 year	Rusting.  Damaged door and corroded frame.  Door does not lock properly. Missing
Exterior Doors - Exterior Steel Door Exterior Doors - Overhead Rolling/ Garage Door Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Foundation - Concrete	Door 6 - West Door 7 - Northwest Door 8 - North Door 9 - North Door 9 - North	1 1 1	EA EA EA	4 5 4	0-1 year 0-1 year 0-1 year	Rusting.  Damaged door and corroded frame. Door does not lock properly. Missing
Exterior Doors - Overhead Rolling/ Garage Door Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Foundation - Concrete	Door 7 - Northwest  Door 8 - North  Door 9 - North  Door 9 - North	1 1 1	EA EA	5 4	0-1 year 0-1 year	Rusting.  Damaged door and corroded frame Door does not lock properly. Missing
Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Foundation - Concrete	Door 9 - North Door 9 - North Door 9 - North	1	EA EA	4	0-1 year	Damaged door and corroded frame Door does not lock properly. Missin
Exterior Doors - Exterior Steel Door Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Foundation - Concrete	Door 9 - North Door 9 - North	1	EA		,	Door does not lock properly. Missin
Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Foundation - Concrete	Door 9 - North Door 9 - North	1	EA		,	Door does not lock properly. Missin
Exterior Doors - Exterior Steel Door  Foundation - Concrete	Door 9 - North			6	,	Door does not lock properly. Missin
Exterior Doors - Exterior Steel Door  Foundation - Concrete	Door 9 - North			6		
Exterior Doors - Exterior Steel Door  Foundation - Concrete	Door 9 - North			6		
Exterior Doors - Exterior Steel Door  Foundation - Concrete	Door 9 - North				6-10 years	
Foundation - Concrete		_		5	0-1 year	Corroding door frame
oundation - Concrete	Entire Buildina			· ·	o . you.	concerning accordance
	Entire Buildina					
Superstructure - Steel		1,447	LF	7	10+ years	
	Entire Building	127,162	SF	7	10+ years	
	E.C. D.T.E.	4.5			0.10	
exterior Lighting - Wall Mounted	Entire Building	24	ΕA	6	6-10 years	
m						
Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
Chimney - Metal Flue	Roof 1	23	LF	7	10+ years	
Coping - Metal	Roof 1	1,050	LF	6	10+ years	
Downspouts - Interior Downspouts	Roof 1		LF		-	
		30		5	•	Cracked brick, open joints,
					,	deteriorated mortar.
		40		6	10+ years	
Parapet - Parapet > 30"	Roof 1	980		6	10+ years	
Roof - PVC Membrane	Roof 1	30,404	SF	6	10+ years	Green roof.
Roof Structure - Steel / Metal Deck/	Roof 1	30,404	SF	7	10+ years	
Concrete Topping						
Coping - Metal	Roof 2	127	LF	6	10+ years	
	Roof 2	116	LF	6		
	Roof 2	127	LF	6		
			SF	-	•	No access to this roof
					•	
		.,510		•	,	
	Roof 3	1	FA	7	10+ years	
. •						
					-	Green roof.
		,			•	GIEGH 1001.
こ ロルここく できるくこくきんさんぎん	ccess Ladder - Metal chimney - Metal Flue coping - Metal cownspouts - Interior Downspouts carapet - 16" - 30" Height carapet - Parapet < 16" Height carapet - Parapet > 30" coof - PVC Membrane coof Structure - Steel / Metal Deck/ concrete Topping	xterior Lighting - Wall Mounted  Entire Building  Ccess Ladder - Metal Chimney - Metal Flue Coping - Metal Cownspouts - Interior Downspouts Coping - Metal Cownspouts - 16" - 30" Height Coping - Weight  Coping - Metal Coping - Weight Coping - Metal Coping - PVC Membrane Coping - Metal Coping - Metal Coping - Metal Coping - Roof 2 Coping - Metal Copin	Second   S	Section   Company   Comp	Sterior Lighting - Wall Mounted   Entire Building   24 EA 6   EA   6	Section Lighting - Wall Mounted   Entire Building   24 EA 6 6-10 years



3510 W 55th STREET, Chicago, IL 60632

Catego	ry : Exterior		В	uilding	: Main		3310 W 3311 01 NEE1, Officago, IE 00032
Guiogo	. y . =		_	<u>.</u>	····	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel / Metal Deck/	Roof 3	2,783	SF	7	10+ years	
	Concrete Topping		,			, , , , , ,	
	Coping - Metal	Roof 4	75	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	75	LF	6	10+ years	
	Roof - PVC Membrane	Roof 4	687	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 4	687	SF	7	10+ years	
	Concrete Topping			٠.	•	.o. you.o	
	Coping - Metal	Roof 5	156	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 5	256	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 5	156	LF	6	10+ years	
	Roof - PVC Membrane	Roof 5	5,746	SF	6	10+ years	Green roof.
	Roof Structure - Steel / Metal Deck/	Roof 5	5,746	SF	7	10+ years	C10011 1001.
	Concrete Topping	11001 3	0,140	Oi	•	101 yours	
	Coping - Metal	Roof 6	170	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 6	192	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 6	170	LF	6	10+ years	
	Roof - PVC Membrane	Roof 6	2,472	SF	6	10+ years	Green roof.
	Roof Structure - Steel / Metal Deck/	Roof 6	2,472	SF	7	10+ years	Green 1001.
	Concrete Topping	K001 0	2,472	SF	,	10+ years	
	Concrete Toppling						
\/\alla							
Walls	Canopy - Metal	South Façade	900	SF	7	10+ years	
	Exterior Walls - Brick	South Façade	50.243	SF	6	•	
	Exterior Walls - Brick	South Façade	1,000	SF	4	10+ years 0-1 year	Deteriorated or missing scalant and
	Exterior vvalis - Drick	Soulii Façade	1,000	SF	4	0-1 year	Deteriorated or missing sealant and expansion joints
	Exterior Walle Priok	Courth Founds	2,000	SF	4	0.1	
	Exterior Walls - Brick	South Façade	2,000	SF	4	0-1 year	Some open joints and deteriorated
							mortar at the very top ice
							shield/flashing at all exterior brick walls
	Cytorian Walle Duefah visated Matal Danal	Cauth Facada	F 020	C.E.	•	10	walls
	Exterior Walls - Prefabricated Metal Panel	South Façade	5,938	SF	6	10+ years	
	Wall	Cavith Facada	4 007	C.E.	•	10	
	Exterior Walls - Prefabricated Metal Panel	South Façade	1,237	SF	6	10+ years	
	Wall	Ossida Essada	0.4	0.5	4	0.4	Mississ market a smaller and a second assess
	Exterior Walls - Prefabricated Metal Panel	South Façade	24	SF	4	0-1 year	Missing metal panels around access
	Wall						hatch.
_Windows		E 0 D 3 P	0.504			40	
	Curtain wall - Glazed Double Pane	Entire Building	2,561	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,156	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	293	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,185	LF	6	10+ years	
	Windows - Louver	Entire Building	24	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,353	SF	6	10+ years	

Campus Name: Hernandez Page : 3 of 37 Assessment Date: 04/13/2022



3510 W 55th STREET, Chicago, IL 60632

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group Category: Electrical **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System FΑ Automatic Transfer Switch ATS Room, Elevator Machine Room 2 7 6-10 years FΑ 7 Automatic Transfer Switch ATS Room, Elevator Machine Room 1 6-10 years Security System - CCTV **Entire Building** 127,162 SF 6-10 years **Entire Building** SF Security System - Intrusion Detection 127,162 6 6-10 years Exit Signs - Corridors and Stairs Entire Building 37 EΑ 7 6-10 years With batteries Exit Signs - Lunchroom **Entire Building** 5 EΑ 7 6-10 years With batteries Exit Signs - Multipurpose Room Entire Building 4 EΑ 7 6-10 years With batteries Emergency Battery Packs - Corridors and 6 FΑ 7 6-10 years **Entire Building** Stairs Emergency Battery Packs - Multipurpose **Entire Building** 2 FΑ 7 6-10 years Room Emergency A/C Power - Corridors and **Entire Building** 18.966 SF 7 6-10 years New item added per current observation Stairs Emergency A/C Power - Lunchrooms **Entire Building** 5,280 SF 7 6-10 years New item added per current observation Emergency A/C Power - Multipurpose **Entire Building** 5,860 SF 7 6-10 years Room Emergency A/C Power - Students Toilets **Entire Building** 3.576 SF 7 New item added per current 6-10 years observation Emergency Generator- Indoor- Natural Gas EΑ 5 Generator Room 1-2 years Failed bank load testing. - 101 - 150 KW Main Service Electrical Room FΑ 7 Main Electrical Service - 1600 A 1 New item added per current 10+ years 120/208/3PH observation Main Electrical Service - 2001 to 3000 A Electrical Room 1 EΑ 7 10+ years 277/480/3PH PA System **Entire Building** 127,162 SF 7 6-10 years Independent Electrical Service for Pump Room 1 EΑ 7 6-10 years emergency power Power Distribution Lighting and Power Panels - 100 A Electrical Room EΑ 7 1 10+ years Lighting and Power Panels - 100 A Electrical Room 1 EΑ 6 10+ years Lighting and Power Panels - Above 100 A Electrical Room 1 EΑ 7 10+ years Lighting and Power Panels - Above 100 A **Electrical Room** 1 FΑ 7 10+ years Lighting and Power Panels - Above 100 A FΑ **Electrical Room** 8 7 10+ years Lighting and Power Panels - Above 100 A Electrical Room 1 EΑ 7 10+ years



Catono	ry : Electrical	Building : Main				3310 W 3311 GTREET, Chicago, 12 00032	
Calego	ı y . Liguti idai		D	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Lighting and Power Panels - Above 100 A	Electrical Room	13	EA	7	10+ years	Commonto
	Main Distribution Panels - 400 - 600 amp	Electrical Room	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Electrical Room	1	EA	7	10+ years	
	amp	Electrical Room	'	L/\	'	101 years	
	Main Distribution Panels - Greater than 600	Electrical Room	1	EA	7	10+ years	
	amp	Lioundi Mooni	'		•	101 youro	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Electrical Room	1	EA	6	10+ years	
	Transformers - 277/400 - 120/200	Liectrical (Conf	'	LA	U	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	127,162	SF	7	6-10 years	
	Fire Alarm_System	Electrical Room	127,162	SF	6	6-10 years	
	Fire Pump Controller	Electrical Room	1	EA	7	6-10 years	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Pump Room	1	EA	7	6-10 years	
	Jockey Pump	Pump Room	1	EA	6	6-10 years	
0 : 11	0.1						
Sprinkle							
	Sprinkler Heads	Entire Building	127,162	SF	7	10+ years	
	Sprinkler Piping	Entire Building	127,162	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	127,162	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Chemical Pot Feeder	Lower Roof	1	EA	6	6-10 years	
	Chiller-Air Cooled-Scroll Type-Roof Mounted	Lower Roof	2	EA	6	6-10 years	
	- 151 - 200 tons		_		-		
	Pipes - Chilled Water Pipe- Steel	Lower Roof	200	LF	6	6-10 years	
	Condensing Unit- Roof Mounted - Less	Roof	1	ĒΑ	6	6-10 years	
	than 5 tons		•	_, .	Ŭ	o .o jouro	
Air Hand	ling Systems						
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	Serves 3rd floor. AHU-5
	3		·		-	,	



3510 W 55th STREET, Chicago, IL 60632

Catego	ry : Mechanical		В	uilding	: Main		. 5 :
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Hot Water and Chilled Water Coils -						
	20001-30000 cfm						
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	22	EA	7	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-2
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	7	6-10 years	RF-4
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-1
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF-5
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves 1st floor. AHU-1.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	29	EA	7	6-10 years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	Not controlled with DDC system -
	Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm					·	control needs to be replaced Unit was off per current observation Serves 2nd floor. AHU-4
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	24	EΑ	7	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves 1st floor kitchen and lunch room. AHU-2.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	4	EA	7	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves Gym. AHU-3.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
_Boiler Sv	stems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	3	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	3	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	
	Piping - Dual Temperature Pipes- Steel	Boiler Room	250	LF	7	6-10 years	
	Water Fill System	Boiler Room	1	ĒΑ	7	6-10 years	
_Heating	Devices						

Campus Name: Hernandez Page : 6 of 37 Assessment Date: 04/13/2022



# Irene C. Hernandez Middle School for the Advancement of Science 3510 W 55th STREET, Chicago, IL 60632

atego	ry : Mechanical		В	uilding	: Main		
				J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EΑ	6	6-10 years	
	Unit Heater - Electric	Entire Building	4	EA	7	6-10 years	
	Unit Heater - Hot Water	Entire Building	10	EA	7	6-10 years	
	Radiator Panels - Hot Water	Entire Building	201	EA	6	6-10 years	
echani	cal Plumbing						
	Hot Water Pump - 21 - 50 HP	Boiler Room	2	EA	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Boiler Room	2	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	1,000	LF	7	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	5	EA	7	6-10 years	Served Only hot water
	Chilled Water Pump - Less than 10	Mechanical Room	5	EA	7	6-10 years	·
empera	iture Control						
	DDC System	Entire Building	127,162	SF	5	1-2 years	System not working and can't acces
							in the computer, per building
							engineer- blank screen - need some
							upgrade.
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	. 5
	Thermostats - DDC	Entire Building	80	EA	6	2-5 years	Manually open and close
entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	6-10 years	Art room- 3rd floor Location change
		Ü				,	per current observation
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	4	EA	7	6-10 years	•
	CFM	Ü				,	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	3	EA	7	6-10 years	
	CFM	9			•	- · · · · · · · · · · · · · · · · · · ·	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	7	6-10 years	
	500 CFM Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	
	-	Entire Building	·			101 years	
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ot Wate	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	7	6-10 years	Per current observation WH-1 pum
						,	seals leaking - present water runnir
							WH-2 working only
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	0-1 year	Per current observation WH-1 pum
			'		Ü	5 . j 5 cai	seals leaking - present water runnir



3510 W 55th STREET, Chicago, IL 60632

Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	127,162	SF	7	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	127,162	SF	7	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	127,162	SF	7	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	127,162	SF	7	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	127,162	SF	7	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	127,162	SF	7	6-10 years	
	Sanitary Piping	Entire Building	127,162	SF	7	6-10 years	
	Storm Piping	Entire Building	127,162	SF	7	6-10 years	
	Vent Piping	Entire Building	127,162	SF	6	6-10 years	
_Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	2-5 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	2-5 years	Per building engineer inspected in 2022. Located in Elevator pit.

Category : Room Building : Main

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Lay-in	107A-1- Kitchen Office	97	SF	7	10+ years	
	Doors - Side-lite	107A-1- Kitchen Office	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	107A-1- Kitchen Office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	107A-1- Kitchen Office	97	SF	7	10+ years	
	Lighting - Lay-in	107A-1- Kitchen Office	2	EA	7	6-10 years	
	Power Distribution	107A-1- Kitchen Office	4	EA	7	10+ years	
	Walls - Concrete Block	107A-1- Kitchen Office	390	SF	7	10+ years	
	Ceiling - Lay-in	112A	125	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112A	1	EA	7	10+ years	
	Floor - Tile	112A	125	SF	7	10+ years	
	Lighting - Lay-in	112A	1	EA	7	6-10 years	
	Power Distribution	112A	2	EA	7	10+ years	
	Walls - Concrete Block	112A	275	SF	7	10+ years	
	Ceiling - Lay-in	112B	101	SF	7	10+ years	
	Ceiling - Lay-in	112B	4	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	112B	1	EA	7	10+ years	-
	Floor - Tile	112B	105	SF	7	10+ years	
	Lighting - Lay-in	112B	2	EA	7	6-10 years	

Campus Name: Hernandez Page: 8 of 37 Assessment Date: 04/13/2022



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	112B	2	EA	7	10+ years	
	Walls - Concrete Block	112B	236	SF	7	10+ years	
	Work SInk	112B	1	EA	7	10+ years	
	Ceiling - Lay-in	112C Exam Room	105	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112C Exam Room	1	EA	7	10+ years	
	Floor - Tile	112C Exam Room	105	SF	7	10+ years	
	Lighting - Lay-in	112C Exam Room	2	EA	7	6-10 years	
	Power Distribution	112C Exam Room	2	EA	7	10+ years	
	Walls - Concrete Block	112C Exam Room	236	SF	7	10+ years	
	Work Sink	112C Exam Room	1	EA	7	10+ years	
	Ceiling - Lay-in	Nurse's Office RM 112	1,580	SF	7	10+ years	
	Doors - Side-lite	Nurse's Office RM 112	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse's Office RM 112	5	ĒΑ	7	10+ years	
	Floor - Tile	Nurse's Office RM 112	1,580	SF	7	10+ years	
	Lighting - Lay-in	Nurse's Office RM 112	30	ĒΑ	7	6-10 years	
	Power Distribution	Nurse's Office RM 112	28	EA	7	10+ years	
	Storage/ Closet	Nurse's Office RM 112	300	SF	7	10+ years	
	Walls - Concrete Block	Nurse's Office RM 112	1,587	SF	7	10+ years	
	Walls - Plaster/Drywall	Nurse's Office RM 112	1,587	SF	7	10+ years	
	Work SInk	Nurse's Office RM 112	3	ĒΑ	7	10+ years	
	Ceiling - Lay-in	RM 107A-7 Engineer Office	148	SF	7	10+ years	
	Doors - Store Front	RM 107A-7 Engineer Office	1	ĒΑ	7	10+ years	
	Floor - Tile	RM 107A-7 Engineer Office	148	SF	7	10+ years	
	Lighting - Lay-in	RM 107A-7 Engineer Office	2	ĒΑ	7	6-10 years	
	Power Distribution	RM 107A-7 Engineer Office	8	EA	7	10+ years	
	Walls - Concrete Block	RM 107A-7 Engineer Office	220	SF	7	10+ years	
	Ceiling - Lay-in	RM 108 Student Services	570	SF	7	10+ years	
	Doors - Side-lite	RM 108 Student Services	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	RM 108 Student Services	5	ĒΑ	7	10+ years	
	Floor - Carpet	RM 108 Student Services	570	SF	7	6-10 years	
	Lighting - Lay-in	RM 108 Student Services	8	ĒΑ	7	6-10 years	
	Power Distribution	RM 108 Student Services	28	EA	7	10+ years	
	Walls - Concrete Block	RM 108 Student Services	1,200	SF	7	10+ years	
	Ceiling - Lay-in	RM 300A - library office	148	SF	7	10+ years	
	Doors - Side-lite	RM 300A - library office	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	RM 300A - library office	1	ĒΑ	7	10+ years	
	Floor - Carpet	RM 300A - library office	148	SF	7	6-10 years	
	Lighting - Lay-in	RM 300A - library office	2	ĒΑ	7	6-10 years	
	Power Distribution	RM 300A - library office	8	EΑ	7	10+ years	
	Storage/ Closet	RM 300A - library office	95	SF	7	10+ years	
	Walls - Concrete Block	RM 300A - library office	458	SF	7	10+ years	
	Work SInk	RM 300A - library office	1	EA	7	10+ years	Quantity updated
	Ceiling - Lay-in	RM 305 teachers lounge	736	SF	7	10+ years	and all agrees
	Doors - Wood Doors inclu hw	RM 305 teachers lounge	1	EA	7	10+ years	
			·		-	- <b>,</b>	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	RM 305 teachers lounge	736	SF	7	10+ years	
	Lighting - Lay-in	RM 305 teachers lounge	16	EA	7	6-10 years	
	Power Distribution	RM 305 teachers lounge	18	EA	7	10+ years	
	Walls - Concrete Block	RM 305 teachers lounge	1,012	SF	7	10+ years	
	Work SInk	RM 305 teachers lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 100- Main Office	1,408	SF	7	10+ years	
	Doors - Side-lite	Rm 100- Main Office	17	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 100- Main Office	2	EΑ	7	10+ years	
	Floor - Carpet	Rm 100- Main Office	1,206	SF	7	6-10 years	
	Floor - Terrazzo	Rm 100- Main Office	202	SF	7	10+ years	
	Lighting - Lay-in	Rm 100- Main Office	14	EA	7	6-10 years	
	Power Distribution	Rm 100- Main Office	18	EA	7	10+ years	
	Storage/ Closet	Rm 100- Main Office	120	SF	7	10+ years	
	Storage/ Closet	Rm 100- Main Office	80	SF	7	10+ years	
	Walls - Concrete Block	Rm 100- Main Office	1,195	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 100- Main Office	1,195	SF	7	10+ years	
	Ceiling - Lay-in	Rm 100A- Asst Principal	235	SF	7	10+ years	
	Doors - Side-lite	Rm 100A- Asst Principal	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 100A- Asst Principal	1	EA	7	10+ years	
	Floor - Carpet	Rm 100A- Asst Principal	235	SF	7	6-10 years	
	Lighting - Lay-in	Rm 100A- Asst Principal	6	EA	7	6-10 years	
	Power Distribution	Rm 100A- Asst Principal	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 100A- Asst Principal	282	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 100A- Asst Principal	282	SF	7	10+ years	
	Ceiling - Lay-in	Rm 100C(2)- Conference Room	345	SF	7	10+ years	
	Doors - Side-lite	Rm 100C(2)- Conference Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 100C(2)- Conference Room	1	EA	7	10+ years	
	Floor - Carpet	Rm 100C(2)- Conference Room	345	SF	7	6-10 years	
	Lighting - Lay-in	Rm 100C(2)- Conference Room	10	EA	7	6-10 years	
	Lighting - Lay-III Lighting - Pendent/Surface	Rm 100C(2)- Conference Room	5	EA	7	6-10 years	
	Power Distribution	Rm 100C(2)- Conference Room	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 100C(2)- Conference Room	349	SF	7	•	
	Walls - Plaster/Drywall	Rm 100C(2)- Conference Room	349	SF	7	10+ years	
				SF SF		10+ years	
	Ceiling - Lay-in	Rm 100C- Principal	345	SF SF	7	10+ years	
	Doors - Side-lite	Rm 100C- Principal	9		7	10+ years	
	Doors - Wood Doors inclu hw	Rm 100C- Principal	1	EA	7	10+ years	
	Floor - Carpet	Rm 100C- Principal	345	SF	7	6-10 years	
	Lighting - Lay-in	Rm 100C- Principal	4	EΑ	7	6-10 years	
	Power Distribution	Rm 100C- Principal	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 100C- Principal	175	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 100C- Principal	524	SF	7	10+ years	
	Ceiling - Lay-in	Rm 100D- Copy/Work Room	162	SF	7	10+ years	
	Doors - Side-lite	Rm 100D- Copy/Work Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 100D- Copy/Work Room	1	EΑ	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Rm 100D- Copy/Work Room	162	SF	7	10+ years	
	Lighting - Lay-in	Rm 100D- Copy/Work Room	1	EA	7	6-10 years	
	Power Distribution	Rm 100D- Copy/Work Room	12	EA	7	10+ years	
	Walls - Concrete Block	Rm 100D- Copy/Work Room	357	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 100D- Copy/Work Room	119	SF	7	10+ years	
	Ceiling - Lay-in	Rm 100E-Pantry (in Main office)	75	SF	7	10+ years	
	Floor - Tile	Rm 100E-Pantry (in Main office)	75	SF	7	10+ years	
	Lighting - Lay-in	Rm 100E-Pantry (in Main office)	1	ĒΑ	7	6-10 years	
	Power Distribution	Rm 100E-Pantry (in Main office)	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 100E-Pantry (in Main office)	257	SF	7	10+ years	
	Work SInk	Rm 100E-Pantry (in Main office)	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 105A- Gym Office	145	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 105A- Gym Office	1 1	EA	7	10+ years	
	Floor - Tile	Rm 105A- Gym Office	145	SF	7	10+ years	
	Lighting - Lay-in	Rm 105A- Gym Office	2	EA	7	6-10 years	
	Power Distribution	Rm 105A- Gym Office	8	EA	7	10+ years	
	Walls - Concrete Block	Rm 105A- Gym Office	392	SF	7	10+ years	
	Walls - Coliciete block	KIII 105A- Gyill Ollice	392	SF	,	10+ years	
_Gymnas	ia						
	Bleacher Seating	1st floor - Room 105	110	EA	7	10+ years	
	Ceiling - Exposed	1st floor - Room 105	5,572	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor - Room 105	288	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor - Room 105	6	EA	7	10+ years	
	Floor - Tile	1st floor - Room 105	406	SF	7	10+ years	
	Floor - Wood	1st floor - Room 105	5,454	SF	7	10+ years	
	Lighting - Lay-in	1st floor - Room 105	<sup>′</sup> 9	EA	7	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	1st floor - Room 105	20	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor - Room 105	15	EA	7	6-10 years	
	Scoreboards	1st floor - Room 105	1	ĒΑ	7	6-10 years	
	Sound System	1st floor - Room 105	1	EA	7	6-10 years	
	Stage	1st floor - Room 105	927	SF	7	10+ years	
	Stage Curtain	1st floor - Room 105	8	EA	7	6-10 years	
	Stage Lift	1st floor - Room 105	1	EΑ	7	10+ years	
	Stage Lighting System	1st floor - Room 105	1	EΑ	7	6-10 years	
	Stage-Stairs - Tile	1st floor - Room 105	8	LF	7	10+ years	
	Storage/ Closet	1st floor - Room 105	482	SF	7	10+ years	
	Walls - Concrete Block	1st floor - Room 105	7,917	SF	7	10+ years	
			- ,		-	- ,	
_Kitchen_							
	Ceiling - Lay-in	1st Floor	1,009	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,009	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Serving Line	1st Floor	75	LF	6	10+ years	



Catego	Category : Room			uilding	: Main	3310 W 3311 GTREET, Glicago, ie 6665	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	1st Floor	139	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,427	SF	6	10+ years	
Library							
Library	Ceiling - Exposed	3rd floor 321	2,004	SF	6	10+ years	
	Ceiling - Lay-in	3rd floor 321	1,831	SF	6	10+ years	
	Doors - Side-lite	3rd floor 321	13	SF	6	10+ years	
	Doors - Transom Window	3rd floor 321	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor 321	2	EA	6	10+ years	
	Floor - Carpet	3rd floor 321	3,835	SF	6	6-10 years	
	Lighting - Lay-in	3rd floor 321	42	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd floor 321	21	EA	7	6-10 years	
	Storage/ Closet	3rd floor 321	150	SF	7	10+ years	
	Walls - Concrete Block	3rd floor 321	2,300	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor 321	788	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	Cafeteria/Tray Rm	1,311	SF	7	10+ years	
	Ceiling - Lay-in	Cafeteria/Tray Rm	3,445	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Cafeteria/Tray Rm	632	SF	7	10+ years	
	Doors - Steel Doors incl hw	Cafeteria/Tray Rm	1	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	Cafeteria/Tray Rm	4	ΕA	7	10+ years	
	Floor - Tile	Cafeteria/Tray Rm	5,388	SF	7	10+ years	
	Lighting - Lay-in	Cafeteria/Tray Rm	84	EA	7	6-10 years	
	Lighting - Metal Halide/ High Pressure	Cafeteria/Tray Rm	14	EA	7	6-10 years	
	Sodium	Carciena Tray Tim	1-7	L/\	,	o to years	
	Serving Line	Cafeteria/Tray Rm	32	LF	7	10+ years	
	Walls - Concrete Block	Cafeteria/Tray Rm	3,514	SF	7	10+ years	
	Walls - Plaster/Drywall	Cafeteria/Tray Rm		SF	7		
			3,165			10+ years	
	Walls - Structural Glazed Tile	Cafeteria/Tray Rm	700	SF	7	10+ years	
_MDF_ID							
	Doors - Steel Doors incl hw	205A inside Mechanical Room 2nd Floor	1	EA	7	10+ years	
	Finishes	205A inside Mechanical Room 2nd	286	SF	7	10+ years	Updated to match current
		Floor					observations
	Other Cooling Unit	205A inside Mechanical Room 2nd	1	EA	7	6-10 years	
		Floor					
_Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	95	SF	7	10+ years	
	Janitor's Closet	1st Floor	45	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	994	SF	7	10+ years	
	Modifical Colvide Rooms	1301 1001	33 <del>4</del>	51	,	ioi yeais	



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	90	SF	7	10+ years	
	Storage Room	1st Floor	50	SF	7	10+ years	
	Storage Room	1st Floor	85	SF	7	10+ years	
	Vaults	1st Floor	100	SF	7	10+ years	
	Janitor's Closet	2nd Floor	157	SF	7	10+ years	
	Janitor's Closet	2nd Floor	157	SF	7	10+ years	Updated to match current observations
	Mechanical/ Service Rooms	2nd Floor	6,022	SF	7	10+ years	observations
	Mechanical/ Service Rooms	2nd Floor	300	SF	7	10+ years	
	Storage Room	2nd Floor	271	SF	7	10+ years	
	Boiler Room	3rd Floor	1,508	SF	7	10+ years	
	Janitor's Closet	3rd Floor	45	SF	7	10+ years	
	Janitor's Closet			SF			
		3rd Floor	65		7	10+ years	Electrical vacua
	Mechanical/ Service Rooms	3rd Floor	270	SF	7	10+ years	Electrical room
	Mechanical/ Service Rooms	3rd Floor	1,686	SF	7	10+ years	
	Storage Room	3rd Floor	105	SF	7	10+ years	
	Storage Room	3rd Floor	125	SF	7	10+ years	
Restroor							
	Accessories	100F	66	SF	7	6-10 years	
	Ceiling - Lay-in	100F	66	SF	7	10+ years	
	Doors - Steel Doors incl hw	100F	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	100F	66	SF	7	10+ years	
	Floor Drain	100F	1	EA	7	10+ years	
	Lavatory	100F	1	EA	7	10+ years	
	Lighting - Lay-in	100F	1	EA	7	6-10 years	
	Walls - Concrete Block	100F	260	SF	7	10+ years	
	Water Closet	100F	1	EA	7	10+ years	
	Accessories	107A-3	65	SF	7	6-10 years	
	Ceiling - Lay-in	107A-3	65	SF	7	10+ years	
	Doors - Steel Doors incl hw	107A-3	1	EA	7	10+ years	
	Floor - Tile	107A-3	65	SF	7	10+ years	
	Floor Drain	107A-3	1	ĒΑ	7	10+ years	
	Lavatory	107A-3	1	EA	7	10+ years	
	Lighting - Lay-in	107A-3	1	EΑ	7	6-10 years	
	Walls - Concrete Block	107A-3	152	SF	7	10+ years	
	Water Closet	107A-3	1	EA	7	10+ years	
	Accessories	107A-4	65	SF	7	6-10 years	
	Ceiling - Lay-in	107A-4	65	SF	7	10+ years	
	Doors - Steel Doors incl hw	107A-4	1	EA	7	10+ years	
	Floor - Tile	107A-4 107A-4	65	SF	7	10+ years	
	Floor Drain	107A-4 107A-4	1	EA	7		
		107A-4 107A-4		EA EA	7	10+ years	
	Lavatory		1			10+ years	
	Lighting - Lay-in	107A-4	1	EA	7	6-10 years	



Catego	Category : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	107A-4	152	SF	7	10+ years	
	Water Closet	107A-4	1	EA	7	10+ years	
	Accessories	109A	343	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109A	343	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109A	343	SF	7	10+ years	
	Floor Drain	109A	3	EA	7	10+ years	
	Hand Dryer	109A	1	EA	5	0-1 year	Does not function properly.
	Lavatory	109A	5	EA	7	10+ years	1 1 7
	Lighting - Lay-in	109A	11	EA	7	6-10 years	
	Partitions	109A	3	EA	7	10+ years	
	Urinals	109A	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	109A	712	SF	7	10+ years	
	Water Closet	109A	3	EΑ	7	10+ years	
	Accessories	109B	73	SF	7	6-10 years	
	Ceiling - Lay-in	109B	73	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109B	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109B	73	SF	7	10+ years	
	Floor Drain	109B	1	EA	7	10+ years	
	Lavatory	109B	1	EA	7	10+ years	
	Lavatory Lighting - Lay-in	109B 109B	1	EA	7		
	Walls - Concrete Block	109B	272	SF		6-10 years	
				SF EA	6	10+ years	
	Water Closet	109B	1		6	10+ years	
	Accessories	109C	343	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109C	343	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109C	343	SF	7	10+ years	
	Floor Drain	109C	3	EA	7	10+ years	
	Hand Dryer	109C	1	EA	7	6-10 years	
	Lavatory	109C	5	EA	7	10+ years	
	Lighting - Lay-in	109C	11	EA	7	6-10 years	
	Partitions	109C	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	109C	712	SF	6	10+ years	
	Water Closet	109C	6	EA	6	10+ years	
	Accessories	112E	80	SF	7	6-10 years	
	Ceiling - Lay-in	112E	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112E	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	112E	80	SF	7	10+ years	
	Floor Drain	112E	1	EΑ	7	10+ years	
	Lavatory	112E	1	EA	7	10+ years	
	Lighting - Lay-in	112E	1	EA	7	6-10 years	
	Showers	112E	1	EA	7	10+ years	
	Walls - Concrete Block	112E	260	SF	7	10+ years	
	Water Closet	112E	1	ĒΑ	7	10+ years	
	Accessories	131A Boys	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	131A Boys	298	SF	6	10+ years	
		1011120,0	200	٥.	·	10. 30010	



Category : Room			Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile Ceramic/ Porcelain	131A Boys	298	SF	6	10+ years		
	Floor Drain	131A Boys	3	EA	7	10+ years		
	Hand Dryer	131A Boys	1	EA	7	6-10 years		
	Lavatory	131A Boys	4	EA	6	10+ years		
	Lighting - Lay-in	131A Boys	7	EA	7	6-10 years		
	Partitions	131A Boys	3	EA	7	10+ years		
	Urinals	131A Boys	2	EA	6	10+ years		
	Walls - Structural Glazed Tile	131A Boys	662	SF	7	10+ years		
	Water Closet	131A Boys	3	EA	6	10+ years		
	Accessories	131C Girls	298	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	131C Girls	298	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	131C Girls	298	SF	6	10+ years		
	Floor Drain	131C Girls	3	EA	7	10+ years		
	Hand Dryer	131C Girls	1	EA	5	0-1 year	Does not work.	
	Lavatory	131C Girls	4	EA	6	10+ years		
	Lighting - Lay-in	131C Girls	9	EA	7	6-10 years		
	Partitions	131C Girls	5	EA	7	10+ years		
	Walls - Structural Glazed Tile	131C Girls	662	SF	7	10+ years		
	Water Closet	131C Girls	5	EA	6	10+ years		
	Accessories	131D Unisex	66	SF	7	6-10 years		
	Ceiling - Lay-in	131D Unisex	66	SF	7	10+ years		
	Doors - Wood Doors inclu hw	131D Unisex	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	131D Unisex	66	SF	6	10+ years		
	Floor Drain	131D Unisex	1	EA	7	10+ years		
	Lavatory	131D Unisex	1	EA	6	10+ years		
	Lighting - Lay-in	131D Unisex	1	EA	7	6-10 years		
	Walls - Concrete Block	131D Unisex	260	SF	7	10+ years		
	Water Closet	131D Unisex	1	EA	6	10+ years		
	Accessories	209A Boys	343	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	209A Boys	343	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	209A Boys	343	SF	6	10+ years		
	Floor Drain	209A Boys	3	EA	7	10+ years		
	Hand Dryer	209A Boys	1	EA	7	6-10 years		
	Lavatory	209A Boys	5	EA	6	10+ years		
	Lighting - Lay-in	209A Boys	11	EA	7	6-10 years		
	Partitions	209A Boys	3	EA	7	10+ years		
	Urinals	209A Boys	3	EA	6	10+ years		
	Walls - Structural Glazed Tile	209A Boys	711	SF	7	10+ years		
	Walls - Structural Glazed Tile	209A Boys	1	SF	4	0-1 year	Broken tiles.	
	Water Closet	209A Boys	3	EA	6	10+ years		
	Accessories	209B Women	73	SF	7	6-10 years		
	Ceiling - Lay-in	209B Women	73	SF	7	10+ years		
	Doors - Wood Doors inclu hw	209B Women	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	209B Women	73	SF	6	10+ years		
						-		



Catego	Category : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	209B Women	1	EA	7	10+ years	
	Lavatory	209B Women	1	EA	6	10+ years	
	Lighting - Lay-in	209B Women	1	EA	7	6-10 years	
	Walls - Concrete Block	209B Women	272	SF	7	10+ years	
	Water Closet	209B Women	1	EA	6	10+ years	
	Accessories	209C Girls	343	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	209C Girls	343	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	209C Girls	343	SF	6	10+ years	
	Floor Drain	209C Girls	3	ĒΑ	7	10+ years	
	Hand Dryer	209C Girls	1	EA	7	6-10 years	
	Lavatory	209C Girls	5	EA	6	10+ years	
	Lighting - Lay-in	209C Girls	11	EA	6	6-10 years	
	Partitions	209C Girls	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	209C Girls	712	SF	6	10+ years	
	Water Closet	209C Girls	6	EA	6	10+ years	
	Accessories	231C Boys	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	231C Boys	298	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	231C Boys	298	SF	6	10+ years	
	Floor Drain	231C Boys	3	EA	7	10+ years	
	Hand Dryer	231C Boys 231C Boys	1	EA	7	6-10 years	
	Lavatory	231C Boys	4	EA	6	10+ years	
	Lighting - Lay-in	231C Boys	7	EA	7	6-10 years	
	Partitions	231C Boys	3	EA	7	-	
	Urinals	231C Boys 231C Boys	2	EA	6	10+ years	
	Walls - Structural Glazed Tile		662	SF		10+ years	
	Water Closet	231C Boys		EA	7	10+ years	
		231C Boys 231C Girls	3 298	SF	6 7	10+ years	
	Accessories Ceiling - Plaster/Drywall	231C Girls 231C Girls	296 298	SF SF	<i>7</i> 6	6-10 years	
	,			SF SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	231C Girls	298		6	10+ years	
	Floor Drain	231C Girls	3	EΑ	7	10+ years	
	Hand Dryer	231C Girls	1	EΑ	7	6-10 years	
	Lavatory	231C Girls	4	EΑ	6	10+ years	
	Lighting - Lay-in	231C Girls	9	EΑ	7	6-10 years	
	Partitions	231C Girls	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	231C Girls	662	SF	7	10+ years	
	Water Closet	231C Girls	5	EA	6	10+ years	
	Accessories	231D Men	66	SF	7	6-10 years	
	Ceiling - Lay-in	231D Men	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	231D Men	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	231D Men	66	SF	6	10+ years	
	Floor Drain	231D Men	1	EA	7	10+ years	
	Lavatory	231D Men	1	EA	6	10+ years	
	Lighting - Lay-in	231D Men	. 1	EA	7	6-10 years	
	Walls - Concrete Block	231D Men	260	SF	7	10+ years	



Catego	ry : Room	Building : Main					
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	231D Men	1	EA	6	10+ years	
	Accessories	309A	343	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	309A	343	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	309A	343	SF	7	10+ years	
	Floor Drain	309A	3	EA	7	10+ years	
	Hand Dryer	309A	1	EA	7	6-10 years	
	Lavatory	309A	5	EA	7	10+ years	
	Lighting - Lay-in	309A	11	EA	7	6-10 years	
	Partitions	309A	3	EA	7	10+ years	
	Urinals	309A	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	309A	711	SF	7	10+ years	
	Walls - Structural Glazed Tile	309A	1	SF	4	0-1 year	Hole through tile.
	Water Closet	309A	3	EA	7	10+ years	•
	Accessories	309B	73	SF	7	6-10 years	
	Ceiling - Lay-in	309B	73	SF	7	10+ years	
	Doors - Wood Doors inclu hw	309B	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	309B	73	SF	7	10+ years	
	Floor Drain	309B	1	EA	7	10+ years	
	Lavatory	309B	1	EA	7	10+ years	
	Lighting - Lay-in	309B	1	EA	7	6-10 years	
	Walls - Concrete Block	309B	272	SF	7	10+ years	
	Water Closet	309B	1	EA	7	10+ years	
	Accessories	309C	343	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	309C	343	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	309C	343	SF	7	10+ years	
	Floor Drain	309C	3	EA	7	10+ years	
	Hand Dryer	309C	1	EA	7	6-10 years	
	Lavatory	309C	5	EA	7	10+ years	
	Lighting - Lay-in	309C	11	EA	7	6-10 years	
	Partitions	309C	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	309C	712	SF	7	10+ years	
	Water Closet	309C	6	EA	7	10+ years	
	Accessories	331A	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	331A	298	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	331A 331A	298	SF	7	10+ years	
	Floor Drain	331A	3	EA	7	10+ years	
	Hand Dryer	331A 331A	1	EA	7	6-10 years	
	Lavatory	331A 331A	4	EA	7	10+ years	
	Lavatory Lighting - Lay-in	331A 331A	7	EA	7	6-10 years	
	Partitions	331A 331A	3	EA	7	10+ years	
	Urinals	331A 331A	2	EA	7	•	
	Walls - Structural Glazed Tile	331A 331A		SF	7	10+ years	
	Walls - Structural Glazed Tile Walls - Structural Glazed Tile	331A 331A	661 1	SF SF	4	10+ years	Hole through tile.
	Water Closet	331A 331A	3	Sr EA	7	0-1 year	noie unough me.
	vvaler CIUSEL	33 IA	3	EA	,	10+ years	



3510 W 55th STREET, Chicago, IL 60632

Catego	ry : Room		В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	331C	298	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	331C	298	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	331C	298	SF	7	10+ years	
	Floor Drain	331C	3	EA	7	10+ years	
	Hand Dryer	331C	1	EA	7	6-10 years	
	Lavatory	331C	4	EA	7	10+ years	
	Lighting - Lay-in	331C	9	EA	7	6-10 years	
	Partitions	331C	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	331C	662	SF	7	10+ years	
	Water Closet	331C	5	EA	7	10+ years	
	Accessories	331D	66	SF	7	6-10 years	
	Ceiling - Lay-in	331D	66	SF	7	10+ years	
	Doors - Wood Doors inclu hw	331D	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	331D	66	SF	7	10+ years	
	Floor Drain	331D	1	EA	7	10+ years	
	Lavatory	331D	1	EA	7	10+ years	
	Lighting - Lay-in	331D	1	EA	7	6-10 years	
	Walls - Concrete Block	331D	260	SF	7	10+ years	
	Water Closet	331D	1	EA	7	10+ years	

Category : Classroom Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #116 (Regular Classroom)						
	Casework	1st Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,506	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile	1st Floor	1,506	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,040	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	290	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #118 (Regular Classroom)						
	Casework	1st Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	729	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	729	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	

Campus Name: Hernandez Page : 18 of 37 Assessment Date: 04/13/2022



Catama	Classes and			به منالمانی	. Main		3310 W 3311 GTREET, Griicago, ie 00032
Category : Classroom			В	uilding	: wain		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	708	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	290	SF	6	10+ years	
Classro	om #119 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
				SF			
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classro	om #120 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
01	W404 (D						
Classro	om #121 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classro	om #122 (Regular Classroom)						
_CI022100		4 of Floor	40	1.5		40	
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	3310 W 3311 GTREET, Officago, 12 00032		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #123 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classroo	m #124 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classroo	m #125 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classroo	m #126 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
_Classroo	m #127 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	



Catego	Category : Classroom			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classroo	om #128 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7		
	Walls - Concrete Block	181 11001	1,074	SF	,	10+ years	
Classroo	om #129 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classroo	om #130 (Regular Classroom)						
	Casework	1st Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	838	SF	7	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	838	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,074	SF	7	10+ years	
Classes	om #200 (Science Lab Level 3)						
CIASSIO	,	On al Ele	22	1		40	
	Casework	2nd Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,609	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	



Catego	ategory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,609	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	768	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroo	om #201 (Science Lab Level 3)						
CIGOGIO	Casework	2nd Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,609	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	SF EA	7 7	10+ years 10+ years	
	Floor - Tile	2nd Floor 2nd Floor	1,609	SF	7		
			•			10+ years	
	Gas Line	2nd Floor	1	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	768	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	768	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroc	om #210 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	806	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	268	SF	6	10+ years	
Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	838	SF	6	•	
		2nd Floor 2nd Floor		SF EA	7	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	11	LF		6-10 years	
	Marker Board		24		7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	



Catego	ory : Classroom		В	uilding	: Main		3310 W 33th STREET, Officago, IE 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #213 (Computer Lab)						
	Casework	2nd Floor	3	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,245	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,245	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classro	om #214 (Science Lab Level 3)						
	Casework	2nd Floor	26	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,378	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,378	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	18	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	741	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	741	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classro	om #215 (Regular Classroom)						
Classio	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
			00.		-	- ,	
_Classroo	om #216 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



Recommend	Catego	ry : Classroom		В	uilding	: Main		
Floor - Tile							Recommend	
Lighting - Lay-in	Group	Item - Type	Location	Quantity		Rank	Replacement	Comments
Marker Board   2nd Floor   24		Floor - Tile	2nd Floor	838	SF	6	10+ years	
Marker Board   2nd Floor   24		Lighting - Lay-in	2nd Floor	11	EΑ	7	6-10 years	
Walls - Concrete Block   2nd Floor   537 SF 7 10+ years		Marker Board	2nd Floor	24	LF	7	6-10 years	
Classroom #217 (Regular Classroom)		Walls - Concrete Block	2nd Floor	537	SF	7	•	
Casework		Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Casework	Classroo	om #217 (Regular Classroom)						
Caling - Lay-in		,	2nd Floor	49	ΙF	6	10+ vears	
Doors - Side-lite							-	
Doors - Wood Doors inclu hw   2nd Floor   1 EA 7 10+ ýears   Floor - Tile   2nd Floor   838 SF 6 10+ years   Lighting - Lay-in   2nd Floor   211 EA 7 6-10 years   Marker Board   2nd Floor   537 SF 7 10+ years   Walls - Concrete Block   2nd Floor   537 SF 6 10+ years   Walls - Flaster/Drywall   2nd Floor   537 SF 6 10+ years   Walls - Flaster/Drywall   2nd Floor   537 SF 7 10+ years   Walls - Flaster/Drywall   2nd Floor   838 SF 7 10+ years   2nd Floor   838 SF 6 10+ years   2nd Floor   2nd Floor								
Floor - Tile					_			
Lighting - Lay-in								
Marker Board         2nd Floor         24         LF         7         6-10 years           Walls - Concrete Block         2nd Floor         537         SF         7         10+ years           Classroom #218 (Regular Classroom)         2nd Floor         49         LF         6         10+ years           Celling - Lay-in         2nd Floor         49         LF         6         10+ years           Celing - Lay-in         2nd Floor         838         SF         7         10+ years           Doors - Side-lite         2nd Floor         9         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         11         EA         7         10+ years           Lighting - Lay-in         2nd Floor         11         EA         7         6-10 years           Marker Board         2nd Floor         11         EA         7         6-10 years           Walls - Concrete Block         2nd Floor         537         SF         7         10+ years           Classroom #219 (Regular Classroom)         2nd Floor         49         LF         6         10+ years							,	
Walls - Concrete Block   2nd Floor   537   SF   7   10+ years								
Classroom #218 (Regular Classroom)   Casework						-	<u>-</u>	
Classroom #218 (Regular Classroom)  Casework 2nd Floor 49 LF 6 10+ years Ceiling - Lay-in 2nd Floor 9 SF 7 10+ years Doors - Side-litte 2nd Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Floor - Tile 2nd Floor 838 SF 6 10+ years Lighting - Lay-in 2nd Floor 11 EA 7 6-10 years Lighting - Lay-in 2nd Floor 24 LF 7 6-10 years Walts - Concrete Block 2nd Floor 537 SF 7 10+ years Walts - Concrete Block 2nd Floor 537 SF 7 10+ years Walts - Plaster/Drywall 2nd Floor 537 SF 7 10+ years  Classroom #219 (Regular Classroom)  Classroom #220 (Regular Classroom)  Classroom #220 (Regular Classroom)  Classroom #220 (Regular Classroom)  Classroom #220 (Regular Classroom)  Casework 2nd Floor 49 LF 6 10+ years Classroom #220 (Regular Classroom)  Classroom #220 (Regular Classroom)								
Casework		walis - Plaster/Drywali	2na Floor	537	SF	б	10+ years	
Ceiling - Lay-in	Classroo	om #218 (Regular Classroom)						
Doors - Side-lite   2nd Floor   9 SF 7 10+ years			2nd Floor			6	10+ years	
Doors - Wood Doors inclu hw		Ceiling - Lay-in	2nd Floor	838		7	10+ years	
Floor - Tile		Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
Floor - Tile		Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
Lighting - Lay-in		Floor - Tile	2nd Floor	838	SF	6	10+ years	
Marker Board       2nd Floor       24       LF       7       6-10 years         Walls - Concrete Block       2nd Floor       537       SF       7       10+ years         Walls - Plaster/Drywall       2nd Floor       537       SF       6       10+ years         Classroom#219 (Regular Classroom)         Casework       2nd Floor       49       LF       6       10+ years         Ceiling - Lay-in       2nd Floor       838       SF       7       10+ years         Doors - Wood Doors inclu hw       2nd Floor       9       SF       7       10+ years         Floor - Tile       2nd Floor       838       SF       6       10+ years         Lighting - Lay-in       2nd Floor       11       EA       7       6-10 years         Walls - Concrete Block       2nd Floor       24       LF       7       6-10 years         Walls - Plaster/Drywall       2nd Floor       537       SF       6       10+ years         Classroom         Classroom #220 (Regular Classroom)         Casework       2nd Floor       49       LF       6       10+ years         Celling - Lay-in       2nd Floor       838       SF		Lighting - Lay-in	2nd Floor	11	EA	7		
Walls - Concrete Block Walls - Plaster/Drywall       2nd Floor       537 SF 7 10+ years         Classroom #219 (Regular Classroom)       2nd Floor       49 LF 6 10+ years         Ceiling - Lay-in       2nd Floor       838 SF 7 10+ years         Doors - Side-lite       2nd Floor       9 SF 7 10+ years         Doors - Wood Doors inclu hw       2nd Floor       1 EA 7 10+ years         Floor - Tile       2nd Floor       838 SF 6 10+ years         Lighting - Lay-in       2nd Floor       11 EA 7 6-10 years         Marker Board       2nd Floor       24 LF 7 6-10 years         Walls - Concrete Block       2nd Floor       537 SF 7 10+ years         Walls - Plaster/Drywall       2nd Floor       537 SF 6 10+ years     Classroom #220 (Regular Classroom)  Casework Ceiling - Lay-in 2nd Floor 2nd Floor 838 SF 7 10+ years			2nd Floor	24	LF	7	•	
Walls - Plaster/Drywall         2nd Floor         537         SF         6         10+ years           Classroom #219 (Regular Classroom)           Casework         2nd Floor         49         LF         6         10+ years           Ceiling - Lay-in         2nd Floor         838         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         9         SF         7         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         7         10+ years           Floor - Tile         2nd Floor         838         SF         6         10+ years           Lighting - Lay-in         2nd Floor         11         EA         7         6-10 years           Marker Board         2nd Floor         24         LF         7         6-10 years           Walls - Concrete Block         2nd Floor         537         SF         7         10+ years           Walls - Plaster/Drywall         2nd Floor         537         SF         6         10+ years           Classroom #220 (Regular Classroom)         49         LF         6         10+ years           Ceiling - Lay-in         2nd Floor         838         SF					SF			
Casework       2nd Floor       49       LF       6       10+ years         Ceiling - Lay-in       2nd Floor       838       SF       7       10+ years         Doors - Side-lite       2nd Floor       9       SF       7       10+ years         Doors - Wood Doors inclu hw       2nd Floor       1       EA       7       10+ years         Floor - Tile       2nd Floor       838       SF       6       10+ years         Lighting - Lay-in       2nd Floor       11       EA       7       6-10 years         Marker Board       2nd Floor       24       LF       7       6-10 years         Walls - Concrete Block       2nd Floor       537       SF       7       10+ years         Walls - Plaster/Drywall       2nd Floor       537       SF       6       10+ years     Classroom #220 (Regular Classroom)  Casework  Ceiling - Lay-in  2nd Floor  Agents  Ag						6	•	
Casework       2nd Floor       49       LF       6       10+ years         Ceiling - Lay-in       2nd Floor       838       SF       7       10+ years         Doors - Side-lite       2nd Floor       9       SF       7       10+ years         Doors - Wood Doors inclu hw       2nd Floor       1       EA       7       10+ years         Floor - Tile       2nd Floor       838       SF       6       10+ years         Lighting - Lay-in       2nd Floor       11       EA       7       6-10 years         Marker Board       2nd Floor       24       LF       7       6-10 years         Walls - Concrete Block       2nd Floor       537       SF       7       10+ years         Walls - Plaster/Drywall       2nd Floor       537       SF       6       10+ years     Classroom #220 (Regular Classroom)  Casework  Ceiling - Lay-in  2nd Floor  Agents  Ag	Classroo	om #219 (Regular Classroom)						
Ceiling - Lay-in       2nd Floor       838       SF       7       10+ years         Doors - Side-lite       2nd Floor       9       SF       7       10+ years         Doors - Wood Doors inclu hw       2nd Floor       1       EA       7       10+ years         Floor - Tile       2nd Floor       838       SF       6       10+ years         Lighting - Lay-in       2nd Floor       11       EA       7       6-10 years         Marker Board       2nd Floor       24       LF       7       6-10 years         Walls - Concrete Block       2nd Floor       537       SF       7       10+ years         Walls - Plaster/Drywall       2nd Floor       537       SF       6       10+ years     Classroom #220 (Regular Classroom)  Casework  Ceiling - Lay-in  2nd Floor  838  SF  7  10+ years  10+ years		` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `	2nd Floor	49	LF	6	10+ vears	
Doors - Side-lite   2nd Floor   9								
Doors - Wood Doors inclu hw   2nd Floor   1   EA   7   10+ years							•	
Floor - Tile							,	
Lighting - Lay-in       2nd Floor       11 EA 7 6-10 years         Marker Board       2nd Floor       24 LF 7 6-10 years         Walls - Concrete Block       2nd Floor       537 SF 7 10+ years         Walls - Plaster/Drywall       2nd Floor       537 SF 6 10+ years         Classroom #220 (Regular Classroom)         Casework       2nd Floor       49 LF 6 10+ years         Ceiling - Lay-in       2nd Floor       838 SF 7 10+ years							-	
Marker Board       2nd Floor       24 LF 7 6-10 years         Walls - Concrete Block       2nd Floor       537 SF 7 10+ years         Walls - Plaster/Drywall       2nd Floor       537 SF 6 10+ years             Classroom #220 (Regular Classroom)       2nd Floor       49 LF 6 10+ years         Ceiling - Lay-in       2nd Floor       838 SF 7 10+ years								
Walls - Concrete Block Walls - Plaster/Drywall       2nd Floor       537 SF 7 10+ years         Classroom #220 (Regular Classroom)       537 SF 6 10+ years         Casework Ceiling - Lay-in       2nd Floor       49 LF 6 10+ years         838 SF 7 10+ years								
Walls - Plaster/Drywall       2nd Floor       537 SF 6 10+ years         Classroom #220 (Regular Classroom)       2nd Floor       49 LF 6 10+ years         Casework Ceiling - Lay-in       2nd Floor       838 SF 7 10+ years							•	
Casework 2nd Floor 49 LF 6 10+ years Ceiling - Lay-in 2nd Floor 838 SF 7 10+ years							,	
Casework 2nd Floor 49 LF 6 10+ years Ceiling - Lay-in 2nd Floor 838 SF 7 10+ years	Classro	om #220 (Regular Classroom)						
Ceiling - Lay-in 2nd Floor 838 SF 7 10+ years	OldoolUl	, ,	2nd Floor	40	1.5	6	10 L Voors	
Doors - Side-lite 2nd Floor 9 SF / 10+ years		Ceiling - Lay-in						
		Doors - Side-lite	ZNA FIOOF	9	<b>5</b> F	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main		3310 W 331110111EE1, Officago, IE 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Classroo	om #221 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Classro	om #222 (Regular Classroom)						
Oldssion	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Classro	om #223 (Regular Classroom)						
Classiu	Casework	2nd Floor	49	LF	6	10	
		2nd Floor 2nd Floor		SF	6 7	10+ years	
	Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor	838 9	SF SF	7	10+ years 10+ years	
			9	Sr EA	7	•	
	Doors - Wood Doors inclu hw	2nd Floor	·			10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in Marker Board	2nd Floor	11	EA	7	6-10 years	
		2nd Floor	24	LF CF	7	6-10 years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	537 537	SF SF	7 6	10+ years 10+ years	
Ola						-	
Liassroo	om #224 (Regular Classroom)	0.15				40	
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Classroo	om #225 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
Classroo	om #226 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	537	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	6	10+ years	
	vvalis - Flastei/Diywali	2110 F1001	337	SI	O	10+ years	
Classroo	om #228 (Regular Classroom)						
	Casework	2nd Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	838	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	838	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	806	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	268	SF	6	10+ years	
Classroo	om #310 (Science)						
	Ceiling - Lay-in	3rd Floor	1,378	SF	7	10+ years	
_Classroo	om #310 (Science) Ceiling - Lay-in	3rd Floor	1,378	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		3310 W 33th GTNEET, Glileago, in 00032
				3		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	Quantity updated
	Floor - Tile	3rd Floor	1,378	SF	7	10+ years	•
	Lighting - Lay-in	3rd Floor	18	EΑ	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	201	SF	7	10+ years	
	Walls - Masonry	3rd Floor	635	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	635	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	om #313 (Computer Lab)						
	Ceiling - Lay-in	3rd Floor	1,245	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,245	SF	7	10+ years	
		3rd Floor	13	EA	7	6-10 years	
	Lighting - Lay-in Lighting - Lay-in	3rd Floor	13	EA	, 5		Doog not work
	Marker Board	3rd Floor	28	LF	5 7	0-1 year	Does not work.
				SF		6-10 years	
	Walls - Concrete Block	3rd Floor	603		7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	603	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
Classroo	om #314 (Science Lab Level 3)						
	Ceiling - Lay-in	3rd Floor	1,378	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,378	SF	7	10+ years	
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	635	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	635	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
Classroo	om #315 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
	Eg. ang Euy III	014 1 1001	10	<b>∟</b> / \	,	o io youis	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	1	EA	5	0-1 year	Flashing off and on
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	m #316 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	10+ years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	6	10+ years	
Classroc	m #317 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	m #318 (Regular Classroom)						
21443100	Casework	3rd Floor	48	LF	7	10+ years	
				SF	7 7	•	
	Ceiling - Lay-in	3rd Floor	895			10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroc	m #319 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		3310 W 33th GTREET, Glildago, in 00032
<u> </u>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	-	
						10+ years	
	Lighting - Lay-in	3rd Floor	11	EA LF	7	6-10 years	
	Marker Board	3rd Floor	28		7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	om #321 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	om #322 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	,	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
						10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF CF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	511	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	511	SF	7	10+ years	
Classroo	om #323 (Art Room)						
	Casework	3rd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,268	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
						,	



Catego	ry : Classroom		В	uilding	: Main		3310 W 3311 GTREET, Officago, 12 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,268	SF	7	10+ years	
	Kiln	3rd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	17	EA	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	440	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	567	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	567	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
	Work Sink	3rd Floor	1	EA	5	0-1 year	Dripping
_Classroo	om #324 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,021	SF	7	10+ years	
Classroo	om #326 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	890	SF	7	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Chipped tiles
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	Criippod tiioo
	Marker Board	3rd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,021	SF	7	10+ years	
Classroo	om #328 (Music Room)						
	Casework	3rd Floor	13	LF	7	10+ years	
	Ceiling - Exposed	3rd Floor	1,056	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,056	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	31	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Sound Panels	3rd Floor	22	EA	7	10+ years	
	Storage/ Closet	3rd Floor	185	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,399	SF	6	10+ years	



3510 W 55th STREET, Chicago, IL 60632

Category : Classroom Building : Main

Group Item - Type Location Quantity UOM Rank Replacement Comments

Work Sink 3rd Floor 1 EA 7 10+ years Quantity updated

Category : Interior Building : Main

Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	6,880	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,067	SF	6	10+ years			
	Doors - Side-lite	1st Floor	108	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	12	EA	7	10+ years			
	Doors - Store Front	1st Floor	9	EA	7	10+ years			
	Doors - Transom Window	1st Floor	66	SF	7	10+ years			
	Drinking Fountains - Double Water Cooler	1st Floor	2	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years			
	Floor - Terrazzo	1st Floor	7,227	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	720	SF	5	10+ years			
	Lighting - Lay-in	1st Floor	94	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years			
	Lighting - Wall Mounted	1st Floor	10	EA	7	6-10 years			
	Student Lockers - One Tier	1st Floor	365	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	14,300	SF	7	10+ years			
	Walls - Masonry	1st Floor	165	SF	7	10+ years			
	Ceiling - Exposed	2nd Floor	631	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	6,063	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	1,042	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	12	EA	7	10+ years			
	Drinking Fountains - Double Water Cooler	2nd Floor	2	EA	7	10+ years			
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years			
	Floor - Terrazzo	2nd Floor	7,105	SF	6	10+ years			
	Floor - Tile/Sheet	2nd Floor	631	SF	7	10+ years	Updated to match current observations		
	Lighting - Lay-in	2nd Floor	83	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	7	EA	7	6-10 years			
	Lighting - Wall Mounted	2nd Floor	10	EA	7	6-10 years			
	Student Lockers - One Tier	2nd Floor	542	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	11,820	SF	7	10+ years			
	Ceiling - Exposed	3rd Floor	563	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	5,633	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	12	EA	7	10+ years			
	Drinking Fountains - Double Water Cooler	3rd Floor	2	EA	7	10+ years			
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years			
	Floor - Terrazzo	3rd Floor	5,633	SF	7	10+ years			
	Floor - Tile/Sheet	3rd Floor	563	SF	7	10+ years			
						•			



Catego	ory : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	83	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	6-10 years	
	Lighting - Wall Mounted	3rd Floor	10	EA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	460	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	12,259	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1	SF	5	0-1 year	Cracking around fixture
Safety							
	Camera Viewing Station	1st Floor	4	EA	7	6-10 years	
	Metal Dedector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	29	EA	7	6-10 years	
	Security Cameras	1st Floor	62	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	Stairwell A	616	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairwell A	384	SF	6	10+ years	
	Floor - Terrazzo	Stairwell A	412	SF	7	10+ years	
	Handrails	Stairwell A	104	LF	7	10+ years	
	Lighting - Lay-in	Stairwell A	6	EΑ	7	6-10 years	
	Lighting - Wall Mounted	Stairwell A	4	EΑ	7	6-10 years	
	Stairs - Terrazzo	Stairwell A	52	LF	7	10+ years	
	Walls - Concrete Block	Stairwell A	2,681	SF	7	10+ years	
	Ceiling - Lay-in	Stairwell B	616	SF	7	10+ years	
	Ceiling - Lay-iii Ceiling - Plaster/Drywall	Stairwell B	384	SF	6	10+ years	
	Floor - Terrazzo	Stairwell B	412	SF	7	,	
	Handrails	Stairwell B	104	LF	7	10+ years	
						10+ years	
	Lighting - Lay-in	Stairwell B	6	EΑ	7	6-10 years	
	Lighting - Wall Mounted	Stairwell B	4	EA	7	6-10 years	
	Stairs - Terrazzo	Stairwell B	52	LF	7	10+ years	
	Walls - Concrete Block	Stairwell B	2,681	SF	7	10+ years	
	Ceiling - Lay-in	Stairwell C	616	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Stairwell C	384	SF	6	10+ years	
	Floor - Terrazzo	Stairwell C	412	SF	7	10+ years	
	Handrails	Stairwell C	104	LF	7	10+ years	
	Lighting - Lay-in	Stairwell C	6	EA	7	6-10 years	
	Lighting - Wall Mounted	Stairwell C	4	EA	7	6-10 years	
	Stairs - Terrazzo	Stairwell C	52	LF	7	10+ years	
	Walls - Concrete Block	Stairwell C	2,681	SF	7	10+ years	
	Ceiling - Exposed	Stairwell D	453	SF	7	10+ years	
	Floor - Tile	Stairwell D	262	SF	7	10+ years	
	Handrails	Stairwell D	104	LF	7	10+ years	
	Lighting - Pendent/Surface	Stairwell D	4	ĒΑ	7	6-10 years	
	Stairs - Concrete	Stairwell D	52	LF	7	10+ years	
			<b>5</b> _		•	- ,	



3510 W 55th STREET, Chicago, IL 60632

Catego	ry : Interior		В	uilding	: Main		
0	Hans Toma	Landin	Over the	LIOM	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Stairwell D	2,650	SF	7	10+ years	
Vertical (	Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	

Campus Name: Hernandez Page : 33 of 37 Assessment Date: 04/13/2022



Category : Site Building : Site

atego	ry : Site		В	uilding	: Site		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	10	EA	6	10+ years	
encing							
	Fencing - New Standard Ornamental	Entire Site	1,470	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	15	LF	4	0-1 year	Bench fencing, damaged gate
							hardware
ndsca	20						
iiusua	Benches	Entire Site	4	EA	7	10+ years	
	Landscape - Grass	Entire Site	21,035	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	21,556	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,594	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	6	SF	4	0-1 year	Small area of missing pavers.
	Parkway trees	Entire Site	18	EA	6	10+ years	•
	Parkway trees	Entire Site	4	EA	4	0-1 year	Missing parkway trees
	Planting Beds/ Area	Entire Site	13,692	SF	6	6-10 years	
	Play Area - Synthetic Turf	Entire Site	18,112	SF	7	10+ years	Sand area is in good shape
	Retaining Wall - Concrete	Entire Site	1,008	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	10+ years	
arking I	ot						
	Concrete Curbs	Parking Lot- North	200	LF	6	10+ years	
	Surface - Concrete	Parking Lot- North	4,079	SF	7	10+ years	
	Trash Compactor	Parking Lot- North		EA	6	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- North	412	SF	7	10+ years	
	Trash Enclosure - Masonry	Parking Lot- North	500	SF	5	0-1 year	Open joints, cracks, deteriorated mortar.
	Concrete Curbs	Parking Lot- West	781	LF	6	10+ years	
	Interior Plantings	Parking Lot- West	80	LF	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- West	12	EA	7	10+ years	
	Surface - Asphalt	Parking Lot- West	11,332	SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- West	500	SF	5	0-1 year	Large cracks
	Vehicular Screening	Parking Lot- West	280	LF	6	6-10 years	
dewalk	s						
	Sidewalks - Internal Walks	Entire Site	688	LF	6	10+ years	<del></del>
		Entire Site	14,743	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks		14,740	OI.	U	IUT years	



3510 W 55th STREET, Chicago, IL 60632

Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage							
0 0	Flag Pole - Flag Pole	Main entrance	3	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Main entrance	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter	Main entrance	1	EA	7	10+ years	
	Sign						

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hernandez Page : 35 of 37 Assessment Date: 04/13/2022

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	monaca ccago	Noom Zoodiion	Tunibo.	1141111001	(0.)	700	71.00	Clop	
Art Room	Art Room	3rd Floor	323	308	1,268	120	18	N	N
Computer Lab	Computer Lab	2nd Floor	213	220	1,245	160	24	N	N
Computer Lab	Computer Lab	3rd Floor	313	318	1,245	160	24	N	N
Music Room	Music Room	3rd Floor	328	301	1,056	360	0	N	N
Regular Classroom	Regular Classroom	1st Floor	116	115	1,506	122	32	N	N
Regular Classroom	Regular Classroom	1st Floor	118	113	729	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	119	118	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	120	111	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	121	116	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	122	109	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	123	114	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	124	107	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	125	112	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	126	105	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	127	110	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	128	103	838	126	9	Y	N
Regular Classroom	Regular Classroom	1st Floor	129	108	838	126	9	Y	Y
Regular Classroom	Regular Classroom	1st Floor	130	101	838	126	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	210	219	838	126	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	212	217	838	126	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	215	218	838	126	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	213	838	126	9	Y	N
Regular Classroom	Regular Classroom	2nd Floor	217	216	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	218	211	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	219	214	838	126	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	209	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	221	212	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	222	207	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	223	210	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	224	205	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	225	208	838	126	9	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	226	203	838	126	9	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	201	838	126	9	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	315	316	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	313	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	314	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	311	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	312	895	120	18	N	N



3510 W 55th STREET, Chicago, IL 60632

**Classroom Summary** 

			Room	Floor Plan	Aros	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Room Number	Area (SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	320	309	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	321	310	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	307	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	305	895	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	303	895	120	18	N	N
Science	Science Classroom	3rd Floor	310	310	1,378	160	24	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	200	221	1,609	200	18	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	201	223	1,609	200	18	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	214	215	1,378	160	24	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	314	315	1,378	160	24	N	N