

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1965	3	71,892
Campus Total			71,892

Catego	Category : Exterior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	3						
	Exterior Doors - Exterior Steel Door	Entrance 1-SW	2	EA	6	2-5 years	
	Exterior Stairs - Concrete	Entrance 1-SW	12	LF	6	6-10 years	
	Exterior Stairs - Stone	Entrance 1-SW	6	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	Entrance 1-SW	5	LF	6	2-5 years	
	Exterior Doors - Exterior Steel Door	Entrance 3-SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 3-SE	12	LF	6	10+ years	
	Exterior Stairs - Stone	Entrance 3-SE	6	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Entrance 3-SE	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 4-NE	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 4-NE	18	LF	6	10+ years	
	Exterior Stairs - Stone	Entrance 4-NE	8	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 5-North / Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Entrance 5-North / Boiler Room	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Entrance 5-North / Boiler Room	8	LF	6	10+ years	
	Exterior Stairs - Wood	Entrance 5-North / Boiler Room	3	LF	5	1-2 years	Wood splitting
	Exterior Doors - Exterior Steel Door	Entrance 5A-North / Outside Yard Storage	2	EA	6	6-10 years	
	Exterior Stairs - Wood	Entrance 5A-North / Outside Yard Storage	6	LF	5	1-2 years	
	Ramps - Concrete	Entrance 5A-North / Outside Yard Storage	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 8-NW	2	EA	6	6-10 years	
	Exterior Stairs - Stone	Entrance 8-NW	6	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 8-NW	10	LF	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 8-NW	10	LF	6	6-10 years	



NIG S							644 W 71st STREET, Chicago, IL 6062	
Catego	ry : Exterior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ramps - Concrete	Entrance 8-NW	5	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Exit 1A-SW / Adjacent to entrance 1	1	EA	6	6-10 years		
		from inside 106 classroom						
	Exterior Stairs - Stone	Exit 1A-SW / Adjacent to entrance 1	3	LF	6	10+ years		
		from inside 106 classroom						
	Exterior Doors - Exterior Steel Door	Exit 6-North / All purpose room	1	EA	6	6-10 years		
	Exterior Stairs - Concrete	Exit 6-North / All purpose room	8	LF	6	10+ years		
	Exterior Stairs - Stone	Exit 6-North / All purpose room	3	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Exit 7-North / All purpose room	1	EA	6	6-10 years		
	Exterior Stairs - Concrete	Exit 7-North / All purpose room	10	LF	6	10+ years		
	Exterior Stairs - Stone	Exit 7-North / All purpose room	3	LF	6	10+ years		
	Entrance Control - Audio and Video	Main Entrance 2-South	1	EA	6	2-5 years		
	Exterior Doors - Exterior Steel Door	Main Entrance 2-South	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	Main Entrance 2-South	2	EA	5	2-5 years		
	Exterior Stairs - Concrete	Main Entrance 2-South	20	LF	6	6-10 years		
	Ramp Handrail - Steel_Ramp Handrail	Main Entrance 2-South	35	LF	6	6-10 years		
	Ramps - Concrete	Main Entrance 2-South	15	LF	6	6-10 years		
	Stair Handrail - Steel_Stair Handrail	Main Entrance 2-South	15	LF	6	6-10 years		
	Exterior Doors - Exterior Steel Door	Roof access door	1	EA	5	2-5 years		
oundati								
	Foundation - Concrete	Entire Building	731	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	69,892	SF	7	10+ years		
	Superstructure - Concrete	Entire Building	2,000	SF	6	10+ years		
ighting								
99	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	5	2-5 years		
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	4	1-2 years		
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	5	1-2 years		
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4	6-10 years		
						,		
Roof Sys				Ε.	_	0.40		
	Access Ladder - Metal	Roof 1	2	EA	7	6-10 years		
	Access Ladder - Metal	Roof 1	2	EA	5	6-10 years		
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	40	LF	6	10+ years		
	Coping - Metal	Roof 1	905	LF	6	6-10 years		
	Downspouts - Interior Downspouts	Roof 1	205	LF	6	6-10 years		
	Roof - Asphalt Gravel Ballast	Roof 1	20,982	SF	5	1-2 years		
	Roof - Asphalt Gravel Ballast	Roof 1	60	SF	5	0-1 year	Potential leaks	
	Roof - Asphalt Gravel Ballast	Roof 1	500	SF	4	0-1 year	Leaks	
	Roof - EPDM/ Synthetic Rubber	Roof 1	60	SF	6	1-2 years		



							644 W 71st STREET, Chicago, IL 6062
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Concrete	Roof 1	21,482	SF	7	10+ years	
	Coping - Metal	Roof 2	350	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 2	115	LF	6	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof 2	7,400	SF	5	1-2 years	Leaks, aggregate displaced
	Roof - Asphalt Gravel Ballast	Roof 2	100	SF	4	1-2 years	Leaks, aggregate displaced
	Roof Structure - Concrete	Roof 2	7,500	SF	7	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	250	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	10	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	23,406	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	160	SF	5	1-2 years	
	Exterior Walls - Brick	Entire Building	100	SF	4	0-1 year	
	Exterior Walls - Precast Panel Wall	Entire Building	4,000	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	130	SF	5	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	680	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	50	SF	5	6-10 years	
			50	01	5	0-10 years	
lindows							
	Clerestory - Glass Single-Pane	Entire Building	360	SF	5	2-5 years	
	Curtain wall - Insulated Panel	Entire Building	115	SF	6	6-10 years	
	Guard - Guards wire guard	Entire Building	575	SF	6	6-10 years	
	Lintels - Steel	Entire Building	1,498	LF	6	6-10 years	
	Windows - Casement Lexan	Entire Building	8,694	SF	6	2-5 years	
	Windows - Louver	Entire Building	40	SF	6	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System	Location	Quantity		Nalik	Replacement	Comments
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	ASCO, 1965
	Automatic Transfer Switch Emergency A/C Power - Corridors and	Electrical Room Entire Building	1 12,828	EA SF	6 6	6-10 years 10+ years	ASCO, 1965
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs	Entire Building	12,828	SF	6	10+ years	ASCO, 1965
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Entire Building Entire Building	12,828 3,914	SF SF	6 6	10+ years 10+ years	
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Entire Building Entire Building Entire Building	12,828 3,914 2,043	SF SF SF	6 6 6	10+ years 10+ years 10+ years	ASCO, 1965 Building has an EM panel
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	12,828 3,914	SF SF EA	6 6 6	10+ years 10+ years 10+ years 6-10 years	
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building	12,828 3,914 2,043	SF SF EA EA	6 6 6 6	10+ years 10+ years 10+ years	Building has an EM panel
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	12,828 3,914 2,043 10	SF SF EA	6 6 6	10+ years 10+ years 10+ years 6-10 years	Building has an EM panel No battery pack
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building	12,828 3,914 2,043 10 1	SF SF EA EA	6 6 6 6	10+ years 10+ years 10+ years 6-10 years 6-10 years	Building has an EM panel
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	12,828 3,914 2,043 10 1 33	SF SF EA EA EA	6 6 6 6 2	10+ years 10+ years 10+ years 6-10 years 6-10 years 0-1 year	Building has an EM panel No battery pack
	Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	12,828 3,914 2,043 10 1 33 6	SF SF EA EA EA EA	6 6 6 6 2 2	10+ years 10+ years 10+ years 6-10 years 0-1 year 0-1 year	Building has an EM panel No battery pack No battery packs



stalled in1965	
965	
ent repairs	
installations	
Installations	
acement (a.k.a. RUL)	
update/correct to match	
ervations	
aintenance needed, 196	
oisy, serves cafeteria	
dors	
dors	
C	



r : Mechanical			uilding			
Terre - Terre -					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Zone Dampers	Mechanical Room	5	EA	5	10+ years	
ama						
Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	5	6-10 years	
	Entire Building	1		6		
		-				
Condensate Pump		1			6-10 years	Serves heat exchanger
		1			10+ years	
	Entire Building	2	EA	5	10+ years	Serves heat exchanger
	Entire Building	200	IF	5	10+ vears	
						Serves heat exchanger
						Near heat exchanger
Steam maps	Entire Ballang	5	L/	0	o to years	Near near exchanger
angers						
Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	1	EA	6	10+ years	Served by stem boiler, for hydronic system in univents
evices						
Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Quantity changed to update/correct match current observations
PTAC - Electric Heating and Self Contained Cooling	Entire Building	6	EA	6	6-10 years	In offices
Cabinet Heaters - With Steam Coil	Entire Building	12	EA	5	6-10 years	Wall mounted
I Plumbing						
Hydronic Supply and Return - Copper	Entire Building	800	LF	6	10+ years	
Hydronic Supply and Return - Galvanized		200	LF	6		
Hot Water Pump - Less than 10	Mechanical Room	1	EA			Booster pump
Hot Water Pump - Less than 10	Mechanical Room	2	EA	5	6-10 years	Serve heat exchanger
Ire Control						
Electric Thermostat	Entire Building	12	EA	5	6-10 years	Serve cabinet heaters
Pneumatic System	Entire Building	71,892	SF	4	2-5 years	Leaks
Thermostats - Pneumatic	Entire Building	2	EA	5	6-10 years	Serve univents
Thermostats - Pneumatic	Entire Building	6	EA	5	6-10 years	Serve univents
Thermostats - Pneumatic			EA	4		More than 30 years old, leaks
Thermostats - Pneumatic	Entire Building	44	EA	4	2-5 years	Leaks, serve univents
	Pressure Boiler - 101 - 150 HP Chemical Feeder Combustion Dampers Condensate Pump Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Steam Traps angers Heat Exchanger - Steam to Hot Water Shell Type Avices Wall Heater - Electric PTAC - Electric Heating and Self Contained Cooling Cabinet Heaters - With Steam Coil LPlumbing Hydronic Supply and Return - Copper Hydronic Supply and Return - Galvanized Hot Water Pump - Less than 10 Hot Water Pump - Less than 10	Boiler Auxiliary- Scotch Marine- Steam Low Entire Building Pressure Boiler - 101 - 150 HP Entire Building Chemical Feed System Entire Building Combustion Dampers Entire Building Condensate Pump Entire Building Feed Water Pumps and Tank Entire Building Non Condensing- Fire Tube- Scotch Marine- Entire Building Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Entire Building Piping - Condensate Pipe- Steel Entire Building Entire Building Steam Traps Entire Building Entire Building Pages Entire Building Entire Building Steam Traps Entire Building Entire Building angers Entire Building Entire Building Heat Exchanger - Steam to Hot Water Shell Mechanical Room Type Mall Heater - Electric Entire Building Page Supply and Return - Copper Entire Building LPlumbing Entire Building Hydronic Supply and Return - Copper Entire Building Hydronic Supply and Return - Galvanized Entire Building Hot Water Pump - Less than 10 Mechanical Room	Boiler Auxiliary- Scotch Marine- Steam Low Entire Building 2 Pressure Boiler - 101 - 150 HP Entire Building 1 Chemical Feed System Entire Building 1 Combustion Dampers Entire Building 1 Condensate Pump Entire Building 1 Feed Water Pumps and Tank Entire Building 1 Feed Water Pumps and Tank Entire Building 2 Steam Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe - Steel Entire Building 200 Piping - Condensate Pipe - Steel Entire Building 200 Steam Traps Entire Building 200 angers Entire Building 2 Heat Exchanger - Steam to Hot Water Shell Mechanical Room 1 Type Intire Building 2 Vices Intire Building 2 Vales Entire Building 2 Vales Intire Building 2 PTAC - Electric Heating and Self Contained Entire Building 2 PTAC - Electric Heating and Self Contained Entire Building 200 Liplumbing 12 12	Boiler Auxiliary- Scotch Marine- Steam Low Entire Building 2 EA Pressure Boiler - 101 - 150 HP Entire Building 1 EA Chemical Feed System Entire Building 1 EA Combustion Dampers Entire Building 1 EA Condensate Pump Entire Building 1 EA Condensate Pumps and Tank Entire Building 1 EA Non Condensing- Fire Tube- Scotch Marine- Entire Building 2 EA Steam - Low Pressure Boiler - 101 - 150 HP Entire Building 200 LF Piping - Condensate Pipe- Steel Entire Building 200 LF Steam Traps Entire Building 2 EA angers - - - - Heat Exchanger - Steam to Hot Water Shell Mechanical Room 1 EA Vices - - - - - Wall Heater - Electric Entire Building 2 EA PTAC - Electric Heating and Self Contained Entire Building 1 EA LPumbing - - - -	Boiler Auxiliary- Scotch Marine- Steam LowEntire Building2EA5Pressure Boiler - 101 - 150 HPEntire Building1EA6Chemical FeederEntire Building1EA6Combustion DampersEntire Building1EA6Condensate PumpEntire Building1EA6Feed Water Pumps and TankEntire Building1EA6Steam- Low Pressure Boiler - 101 - 150 HPEntire Building200LF5Steam- Low Pressure Boiler - 101 - 150 HPEntire Building200LF5Steam TrapsEntire Building200LF5Steam TrapsEntire Building200LF5Steam TrapsEntire Building200LF5AngersEntire Building5EA5AngersEntire Building2EA5VicesEntire Building2EA5VicesEntire Building2EA5PTAC - ElectricEntire Building1EA6CoolingEntire Building12EA5Cabinet Heaters - With Steam CoilEntire Building200LF6Hydronic Supply and Return - CopperEntire Building200LF6Hydronic Supply and Return - GalvanizedEntire Building200LF6Hydronic Supply and Return - CopperEntire Building12EA5Free ControlEntire Build	Boiler Auxiliary- Scotch Marine- Steam LowEntire Building2EA56-10 yearsPressure Boiler - 101 - 150 HPEntire Building1EA66-10 yearsChemical FeederEntire Building1EA66-10 yearsCombustion DampersEntire Building1EA66-10 yearsCondensate PumpEntire Building1EA66-10 yearsCondensate PumpEntire Building1EA66-10 yearsFeed Water Pumps and TankEntire Building2EA510+ yearsSno Condensing- Fire Tube-Scotch Marine- Bream Low Pressure Boiler - 101 - 150 HPEntire Building200LF510+ yearsPriping - Steam Pipe- SteelEntire Building200LF510+ yearsSteam TrapsEntire Building5EA56-10 yearsSteam TrapsEntire Building2EA56-10 yearsAgersEntire Building2EA56-10 yearsYepeEntire Building2EA56-10 yearsVicesEntire Building1EA66-10 yearsVicesEntire Building12EA56-10 yearsVicesEntire Building12EA56-10 yearsPTAC - Electric Heating and Self Contained CoolingEntire Building200LF610+ yearsVidonic Supply and Return - Copper Hydronic Supply and Return - Galvanized Hydroni



A - 1							
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	52	EA	5	2-5 years	Heating only, hot water, require frequent repair
entilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Quantity changed to update/correct match current observations
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	5	6-10 years	Priority replacement (a.k.a. RUL) changed to update/correct to match current observations
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire extinguisher
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	Served dishwasher
atego	ry : Plumbing		В	uilding	: Main		
	Hanna Tama	Leastlen	0		Daula	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	1	EA	5	6-10 years	Added
Piping							
'iping	Domestic Piping-Hot Water Return Lines	Entire Building	71,892	SF	6	10+ years	
'iping	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building Entire Building	71,892 71,892	SF SF	6	10+ years 10+ years	
Piping							
Piping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to	Entire Building	71,892	SF	6	10+ years	There are a few pipe clamps
iping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	71,892 71,892	SF SF	6 6	10+ years 10+ years	There are a few pipe clamps
iping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building Entire Building Entire Building	71,892 71,892 71,892	SF SF SF	6 6 6	10+ years 10+ years 10+ years	There are a few pipe clamps 1965 installation
tiping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building Entire Building Entire Building	71,892 71,892 71,892 71,892	SF SF SF SF	6 6 6	10+ years 10+ years 10+ years 10+ years	
tiping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building Entire Building Entire Building Entire Building Entire Building	71,892 71,892 71,892 71,892 71,892 71,892	SF SF SF SF SF	6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years	
iping	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	71,892 71,892 71,892 71,892 71,892 71,892 71,892	SF SF SF SF SF SF	6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping Vent Piping	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	71,892 71,892 71,892 71,892 71,892 71,892 71,892 71,892	SF SF SF SF SF SF SF	6 6 6 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	1965 installation
Piping Pumps	Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping Storm Piping	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	71,892 71,892 71,892 71,892 71,892 71,892 71,892 71,892	SF SF SF SF SF SF SF	6 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	



Catogo	ory : Plumbing		B	uilding	· Main		044 W 7 ISt STREET, Chicago, IE 00021
Calego	iry. Fluinbing		Б	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Pumps - Ejector-Duplex	Mechanical Room	1	EA	5	6-10 years	Comments
					-		
Catego	ery : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	112 Principals Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	112 Principals Office	163	SF	6	10+ years	
	Doors - Wood Doors inclu hw	112 Principals Office	1	EA	6	10+ years	
	Floor - Tile	112 Principals Office	163	SF	6	10+ years	
	Lighting - Lay-in	112 Principals Office	4	EA	6	6-10 years	
	Power Distribution	112 Principals Office	8	EA	6	6-10 years	
	Storage/ Closet	112 Principals Office	9	SF	7	10+ years	
	Walls - Concrete Block	112 Principals Office	563	SF	6	10+ years	
	AC Unit	1st FI Conference Rm (Rm 110 on	1	EA	4	0-1 year	Not working properly-
		Floor Plan)	1	LA	-	0-1 year	
	Ceiling - Splined	1st FI Conference Rm (Rm 110 on	465	SF	6	10+ years	
		Floor Plan)					
	Doors - Wood Doors inclu hw	1st FI Conference Rm (Rm 110 on	1	EA	6	10+ years	
		Floor Plan)					
	Floor - Carpet	1st FI Conference Rm (Rm 110 on	465	SF	4	1-2 years	Torn carpet
		Floor Plan)		-		,	
	Lighting - Pendent/Surface	1st FI Conference Rm (Rm 110 on	6	EA	6	6-10 years	
		Floor Plan)	0	_/ .	U U	0 10 900.0	
	Power Distribution	1st FI Conference Rm (Rm 110 on	12	EA	7	6-10 years	
		Floor Plan)	.=	_/ .	•	0 10 900.0	
	Storage/ Closet	1st FI Conference Rm (Rm 110 on	393	SF	7	10+ years	
	Biologe/ Bioset	Floor Plan)	000	01	'	Tor years	
	Walls - Concrete Block	1st FI Conference Rm (Rm 110 on	696	SF	6	10+ years	
		Floor Plan)	030	51	0	TUT years	
	Ceiling - Lay-in	1st Floor Faculty Lounge	362	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	1st Floor Faculty Lounge	362	SF	6	10+ years	
	Lighting - Lay-in	1st Floor Faculty Lounge	4	EA	7	6-10 years	
	Power Distribution	1st Floor Faculty Lounge	6	EA	6	6-10 years	
	Storage/ Closet	1st Floor Faculty Lounge	9	SF	7	6-10 years	Nine 2 tier lockers
	Walls - Concrete Block	1st Floor Faculty Lounge	625	SF	6	10+ years	
	Ceiling - Lay-in	203, 2nd FI Faculty Lounge	362	SF	6	10+ years	
	Doors - Wood Doors inclu hw	203, 2nd FI Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile	203, 2nd FI Faculty Lounge	362	SF	6	10+ years	
	Lighting - Lay-in	203, 2nd FI Faculty Lounge	4	EA	6	6-10 years	
	Power Distribution	203, 2nd FI Faculty Lounge	6	EA	6	6-10 years	
	Walls - Concrete Block	203, 2nd FI Faculty Lounge	600	SF	6	10+ years	
	Walls - Structural Glazed Tile	203, 2nd FI Faculty Lounge	25	SF	6	10+ years	
		• •				-	



Catego	ry : Room		В	uilding	: Main		
J				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	303, 3rd FI Faculty Lounge	362	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	303, 3rd FI Faculty Lounge	1	EA	6	6-10 years	
	Floor - Tile	303, 3rd FI Faculty Lounge	362	SF	6	6-10 years	
	Lighting - Lay-in	303, 3rd FI Faculty Lounge	4	EA	6	6-10 years	
	Power Distribution	303, 3rd FI Faculty Lounge	6	EA	6	6-10 years	
	Walls - Concrete Block	303, 3rd FI Faculty Lounge	600	SF	6	10+ years	
	Walls - Structural Glazed Tile	303, 3rd FI Faculty Lounge	25	SF	6	10+ years	
	AC Unit	Engineers Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineers Office	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineers Office	1	EA	6	10+ years	
	Floor - Tile	Engineers Office	80	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineers Office	1	EA	6	6-10 years	
	Power Distribution	Engineers Office	6	EA	6	6-10 years	
	Storage/ Closet	Engineers Office	30	SF	5	10+ years	
	Walls - Concrete Block	Engineers Office	289	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Gym Office	180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gym Office	1	EA	7	10+ years	
	Floor - Tile	Gym Office	180	SF	6	10+ years	
	Lighting - Pendent/Surface	Gym Office	1	EA	7	6-10 years	
	Power Distribution	Gym Office	4	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	432	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Managers Office	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Managers Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Managers Office	105	SF	6	10+ years	
	Lighting - Lay-in	Kitchen Managers Office	2	EA	6	6-10 years	
	Power Distribution	Kitchen Managers Office	6	EA	6	6-10 years	
	Storage/ Closet	Kitchen Managers Office	25	SF	7	10+ years	
	Walls - Concrete Block	Kitchen Managers Office	291	SF	6	10+ years	
	AC Unit	Main Office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main Office	318	SF	6	10+ years	
	Doors - Store Front	Main Office	1	EA	6	10+ years	
	Floor - Tile	Main Office	318	SF	6	10+ years	
	Lighting - Lay-in	Main Office	6	EA	6	6-10 years	
	Power Distribution	Main Office	6	EA	6	6-10 years	
	Walls - Concrete Block	Main Office	601	SF	6	10+ years	
	AC Unit	Room 114	1	EA	7	6-10 years	
	Ceiling - Lay-in	Room 114	345	SF	6	10+ years	
	Ceiling - Lay-in	Room 114	2	SF	4	1-2 years	Water marks on tiles
	Doors - Wood Doors inclu hw	Room 114	1	EA	6	10+ years	
	Floor - Tile	Room 114	347	SF	6	10+ years	
	Lighting - Lay-in	Room 114	6	EA	6	6-10 years	
	Power Distribution	Room 114	8	EA	6	6-10 years	
	Storage/ Closet	Room 114	4	SF	7	10+ years	
	Walls - Concrete Block	Room 114	616	SF	6	10+ years	



	_		_				644 W 71st STREET, Chicago, IL 6062
Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Waiting Room in Principals Office	79	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Waiting Room in Principals Office	1	EA	6	10+ years	
	Floor - Tile	Waiting Room in Principals Office	79	SF	6	10+ years	
	Lighting - Lay-in	Waiting Room in Principals Office	1	EA	6	6-10 years	
	Power Distribution	Waiting Room in Principals Office	4	EA	6	6-10 years	
	Walls - Concrete Block	Waiting Room in Principals Office	286	SF	6	10+ years	
Gvmnasi	ia						
,	Ceiling - Lay-in	1st Floor	24	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	3,890	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile	1st Floor	2,914	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	9	EA	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	497	SF	6	10+ years	
	Stage Curtain	1st Floor	6	ĒA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	5	6-10 years	
	Stage-Stairs - Terrazzo	1st Floor	30	LF	7	10+ years	
	Stage-Stairs - Wood	1st Floor	30	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	2,513	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,689	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	609	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
	Floor - Tile	1st Floor	609	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	6-10 years	
	Serving Line	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	130	SF	5	10+ years	
	Walls - Structural Glazed Tile	1st Floor	778	SF	6	10+ years	
ibrary							
	AC Unit	204 Library, 2nd floor in rooms 203/204 combined	1	EA	7	6-10 years	In good condition
	AC Unit	203/204 combined 204 Library, 2nd floor in rooms 203/204 combined	1	EA	7	6-10 years	
	Casework	203/204 combined 204 Library, 2nd floor in rooms 203/204 combined	150	LF	6	10+ years	
	Ceiling - Lay-in	203/204 combined 204 Library, 2nd floor in rooms 203/204 combined	1,821	SF	6	10+ years	
	Doors - Wood Doors inclu hw	203/204 combined 204 Library, 2nd floor in rooms	3	EA	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		203/204 combined					
	Floor - Tile	204 Library, 2nd floor in rooms	1,821	SF	6	10+ years	
		203/204 combined					
	Lighting - Lay-in	204 Library, 2nd floor in rooms	27	EA	6	6-10 years	
		203/204 combined	-	05	-	40	
	Storage/ Closet	204 Library, 2nd floor in rooms 203/204 combined	5	SF	7	10+ years	
	Walls - Concrete Block	203/204 combined 204 Library, 2nd floor in rooms	1,546	SF	6	10+ years	
		203/204 combined	1,540	51	0	TOF years	
	Walls - Plaster/Drywall	204 Library, 2nd floor in rooms	150	SF	6	10+ years	
		203/204 combined		•	Ū	let yeare	
	Walls - Structural Glazed Tile	204 Library, 2nd floor in rooms	60	SF	6	10+ years	
		203/204 combined				-	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,027	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Water spots on tile
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile	1st Floor	2,043	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	32	EA	6	6-10 years	
	Storage/ Closet	1st Floor	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,562	SF	6	10+ years	
MDF ID	F						
	Doors - Steel Doors incl hw	In storage room next to room 212	1	EA	6	10+ years	
	Finishes	In storage room next to room 212	136	SF	7	6-10 years	
	Window AC Unit	In storage room next to room 212	100	EA	7	6-10 years	
						,	
Mechani	ical/ Service Rooms						
	Boiler Room	1st Floor	2,090	SF	7	10+ years	
	Crawl Space - Unfinished	1st Floor	3,580	SF	7	10+ years	
	Janitor's Closet	1st Floor	60	SF	7	6-10 years	Priority replacement (a.k.a. RUL)
						,	changed to update/correct to match current observations
	Mechanical/ Service Rooms	1st Floor	620	SF	7	10+ years	
	Storage Room	1st Floor	160	SF	7	10+ years	
	Storage Room	1st Floor	80	SF	7	10+ years	
	Vaults	1st Floor	60	SF	7	10+ years	
	Janitor's Closet	2nd Floor	55	SF	5	1-2 years	Plaster damaged
	Mechanical/ Service Rooms	2nd Floor	290	SF	7	10+ years	i lastel dallaged
		2nd Floor	290 290	SF	7		
	Mechanical/ Service Rooms					10+ years	
	Storage Room	2nd Floor	254	SF	7	10+ years	
	Janitor's Closet	3rd Floor	55	SF	7	10+ years	



Category : Room				uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage Room	3rd Floor	401	SF	7	10+ years	
						,	
estroon	n						
0011001	Accessories	1st FI Boys Room	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI Boys Room	323	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI Boys Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI Boys Room	323	SF	6	10+ years	
	Floor Drain	1st FI Boys Room	1	EA	7	10+ years	
	Hand Dryer	1st Fl Boys Room	2	EA	5	2-5 years	
	Lavatory	1st FI Boys Room	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FI Boys Room	2	EA	6	6-10 years	
	Partitions	1st FI Boys Room	3	EA	7	10+ years	
	Urinals	1st FI Boys Room	5 4	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st FI Boys Room	600	SF	6	10+ years	
	Water Closet	1st FI Boys Room	3	EA	6	6-10 years	
	Accessories	1st Fl Girls Room	313	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st FI Girls Room	313	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Girls Room	3	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st FI Girls Room	313	SF	6	10+ years	
	Floor Drain	1st FI Girls Room	1	EA	7	10+ years	
	Hand Dryer	1st Fl Girls Room	2	EA	5	2-5 years	
	Lavatory	1st FI Girls Room	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Fl Girls Room	1	EA	6	6-10 years	
	Partitions	1st FI Girls Room	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Fl Girls Room	592	SF	6	10+ years	
	Water Closet	1st FI Girls Room	7	EA	6	6-10 years	
	Accessories	1st FI Mens Room	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI Mens Room	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI Mens Room	1	EA	6	10+ years	
	Floor - Tile	1st FI Mens Room	49	SF	6	1-2 years	Stained tiles
	Lavatory	1st FI Mens Room	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st FI Mens Room	1	EA	6	6-10 years	
	Walls - Concrete Block	1st FI Mens Room	225	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI Mens Room	35	SF	6	10+ years	
	Water Closet	1st FI Mens Room	1	EA	6	6-10 years	
	Accessories	1st FI Womens Room	78	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI Womens Room	78	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI Womens Room	1	EA	6	10+ years	
	Floor - Tile	1st FI Womens Room	78	SF	6	10+ years	
	Lavatory	1st FI Womens Room	1	EA	6	6-10 years	
	Lighting - Wall Mounted	1st FI Womens Room	1	EA	6	6-10 years	
	Partitions	1st FI Womens Room	2	EA	5	6-10 years	
	Walls - Concrete Block	1st FI Womens Room	286	SF	6	10+ years	
		1st FI Womens Room	200	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		044 W / ISL STREET, Chicago, iE 00021
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st FI in Kindergarten Room #102	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI in Kindergarten Room #102	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI in Kindergarten Room #102	1	EA	6	10+ years	
	Floor - Tile	1st FI in Kindergarten Room #102	26	SF	6	10+ years	
	Lavatory	1st FI in Kindergarten Room #102	1	EA	6	6-10 years	
	Lighting - Lay-in	1st FI in Kindergarten Room #102	1	EA	6	6-10 years	
	Walls - Concrete Block	1st FI in Kindergarten Room #102	158	SF	6	10+ years	
	Water Closet	1st FI in Kindergarten Room #102	1	EA	6	6-10 years	
	Accessories	1st FI in Kindergarten Room #104	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI in Kindergarten Room #104	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI in Kindergarten Room #104	1	EA	6	10+ years	
	Floor - Tile	1st FI in Kindergarten Room #104	26	SF	6	10+ years	
	Lavatory	1st FI in Kindergarten Room #104	1	EA	6	6-10 years	
	Lighting - Lay-in	1st FI in Kindergarten Room #104	1	EA	6	6-10 years	
	Walls - Concrete Block	1st FI in Kindergarten Room #104	158	SF	6	10+ years	
	Water Closet	1st FI in Kindergarten Room #104	1	EA	6	6-10 years	
	Accessories	1st FI in Kindergarten Room #106	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st FI in Kindergarten Room #106	26	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI in Kindergarten Room #106	1	EA	6	10+ years	
	Floor - Tile	1st FI in Kindergarten Room #106	26	SF	6	10+ years	
	Lavatory	1st FI in Kindergarten Room #106	1	EA	6	6-10 years	
	Lighting - Lay-in	1st FI in Kindergarten Room #106	1	EA	6	6-10 years	
	Walls - Concrete Block	1st FI in Kindergarten Room #106	158	SF	6	10+ years	
	Water Closet	1st FI in Kindergarten Room #106	1	EA	6	6-10 years	
	Accessories	2nd FI Boys Restroom	323	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FI Boys Restroom	320	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd FI Boys Restroom	3	SF	4	1-2 years	Water damaged drywall ceiling
	Doors - Wood Doors inclu hw	2nd FI Boys Restroom	3	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FI Boys Restroom	1	EA	4	1-2 years	Louvre removed
	Floor - Tile Ceramic/ Porcelain	2nd FI Boys Restroom	323	SF	6	10+ years	
	Floor Drain	2nd FI Boys Restroom	1	EA	7	6-10 years	
	Hand Dryer	2nd FI Boys Restroom	2	EA	7	2-5 years	
	Lavatory	2nd FI Boys Restroom	3	EA	6	6-10 years	
	Lighting - Lay-in	2nd FI Boys Restroom	1	EA	6	6-10 years	
	Partitions	2nd FI Boys Restroom	3	EA	7	6-10 years	
	Urinals	2nd FI Boys Restroom	5	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd FI Boys Restroom	600	SF	6	10+ years	
	Water Closet	2nd FI Boys Restroom	3	EA	6	6-10 years	
	Accessories	2nd FI Girls restroom	313	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FI Girls restroom	313	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd FI Girls restroom	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd FI Girls restroom	313	SF	6	10+ years	
	Floor Drain	2nd FI Girls restroom	1	EA	7	10+ years	
	Hand Dryer	2nd FI Girls restroom	2	EA	5	2-5 years	



LightingLay-in2nd Fl GirlLightingPendent/Surface2nd Fl GirlPartitions2nd Fl GirlWallsStructural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeilingPlaster/Drywall2nd Fl MeDoorsWood Doors inclu hw2nd Fl Me	Qua s restroom s restroom s restroom s restroom s restroom ns staff restroom ns staff restroom ns staff restroom ns staff restroom ns staff restroom	antity 3 1 2 7 631 7 49 49 49	ilding : EA EA EA EA SF EA SF SF	Rank 6 6 7 6 6 7	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Comments
Lavatory2nd Fl GirlLighting - Lay-in2nd Fl GirlLighting - Pendent/Surface2nd Fl GirlPartitions2nd Fl GirlWalls - Structural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	s restroom s restroom s restroom s restroom s restroom ns staff restroom ns staff restroom ns staff restroom ns staff restroom	3 1 2 7 631 7 49 49	EA EA EA SF EA SF	6 6 7 6	6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Comments
LightingLay-in2nd Fl GirlLighting- Pendent/Surface2nd Fl GirlPartitions2nd Fl GirlWalls- Structural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeiling- Plaster/Drywall2nd Fl MeDoors- Wood Doors inclu hw2nd Fl Me	s restroom s restroom s restroom s restroom ns staff restroom ns staff restroom ns staff restroom	1 2 7 631 7 49 49	EA EA SF EA SF	6 6 7 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	
Lighting - Pendent/Surface2nd Fl GirlPartitions2nd Fl GirlWalls - Structural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	s restroom s restroom s restroom s staff restroom ns staff restroom ns staff restroom	2 7 631 7 49 49	EA EA SF EA SF	6 7 6 6	6-10 years 6-10 years 10+ years 6-10 years	
Partitions2nd Fl GirlWalls - Structural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	s restroom s restroom s restroom ns staff restroom ns staff restroom ns staff restroom	7 631 7 49 49	EA SF EA SF	7 6 6	6-10 years 10+ years 6-10 years	
Walls - Structural Glazed Tile2nd Fl GirlWater Closet2nd Fl GirlAccessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	s restroom s restroom ns staff restroom ns staff restroom ns staff restroom	631 7 49 49	SF EA SF	6 6	10+ years 6-10 years	
Water Closet2nd Fl GirlAccessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	s restroom ns staff restroom ns staff restroom ns staff restroom	7 49 49	EA SF	6	6-10 years	
Accessories2nd Fl MeCeiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	ns staff restroom ns staff restroom ns staff restroom	49 49	SF	-		
Ceiling - Plaster/Drywall2nd Fl MeDoors - Wood Doors inclu hw2nd Fl Me	ns staff restroom ns staff restroom	49		7	o 4 o	
Doors - Wood Doors inclu hw 2nd FI Me	ns staff restroom	-	SE	•	6-10 years	
		1		6	10+ years	
Floor - Tile 2nd Fl Me	ns staff restroom	•	EA	6	10+ years	
		49	SF	6	10+ years	
	ns staff restroom	1	EA	6	6-10 years	
	ns staff restroom	1	EA	6	6-10 years	
Lighting - Wall Mounted 2nd FI Me	ns staff restroom	1	EA	6	6-10 years	
Partitions 2nd FI Me	ns staff restroom	1	EA	7	6-10 years	
Walls - Concrete Block 2nd FI Me	ns staff restroom	224	SF	7	10+ years	
Water Closet 2nd FI Me	ns staff restroom	1	EA	6	6-10 years	
	men's Staff Restroom	78	SF	5	6-10 years	
Ceiling - Plaster/Drywall 2nd FI Wo	men's Staff Restroom	78	SF	6	10+ years	
Doors - Wood Doors inclu hw 2nd FI Wo	men's Staff Restroom	1	EA	6	10+ years	
Floor - Tile 2nd Fl Wo	men's Staff Restroom	78	SF	6	10+ years	
Lavatory 2nd FI Wo	men's Staff Restroom	1	EA	6	6-10 years	
Lighting - Lay-in 2nd FI Wo	men's Staff Restroom	1	EA	6	6-10 years	
Lighting - Wall Mounted 2nd FI Wo	men's Staff Restroom	1	EA	6	6-10 years	
Partitions 2nd FI Wo	men's Staff Restroom	2	EA	7	6-10 years	
Walls - Concrete Block 2nd FI Wo	men's Staff Restroom	262	SF	6	10+ years	
Walls - Structural Glazed Tile 2nd Fl Wo	men's Staff Restroom	23	SF	6	10+ years	
Water Closet 2nd Fl Wo	men's Staff Restroom	2	EA	6	6-10 years	
Accessories 3rd Fl Boy	s Restroom	323	SF	7	6-10 years	
Ceiling - Plaster/Drywall 3rd Fl Boy	s Restroom	323	SF	6	6-10 years	
Doors - Wood Doors inclu hw 3rd Fl Boy	s Restroom	4	EA	6	2-5 years	
Floor - Tile Ceramic/ Porcelain 3rd Fl Boy	s Restroom	323	SF	6	10+ years	
Floor Drain 3rd Fl Boy	s Restroom	1	EA	7	10+ years	
Hand Dryer 3rd Fl Boy	s Restroom	2	EA	7	2-5 years	
Lavatory 3rd Fl Boy	s Restroom	2	EA	6	6-10 years	
	s Restroom	1	EA	5	6-10 years	
	s Restroom	1	EA	6	6-10 years	
	s Restroom	3	EA	7	6-10 years	
	s Restroom	5	EA	6	6-10 years	
	s Restroom	600	SF	5	2-5 years	
	s Restroom	3	EA	6	6-10 years	
	s Restroom	313	SF	7	6-10 years	
	s Restroom	313	SF	6	10+ years	
	s Restroom	4	EA	6	10+ years	
	s Restroom	313	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	3rd FI Girls Restroom	1	EA	7	10+ years	
	Hand Dryer	3rd FI Girls Restroom	2	EA	5	2-5 years	
	Lavatory	3rd FI Girls Restroom	3	EA	6	6-10 years	
	Lighting - Lay-in	3rd FI Girls Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd FI Girls Restroom	2	EA	6	6-10 years	
	Partitions	3rd FI Girls Restroom	7	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd FI Girls Restroom	631	SF	6	10+ years	
	Water Closet	3rd FI Girls Restroom	7	EA	6	6-10 years	
	Accessories	3rd FI Mens staff restroom	49	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd FI Mens staff restroom	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd FI Mens staff restroom	1	EA	6	6-10 years	
	Floor - Tile/Sheet	3rd FI Mens staff restroom	49	SF	7	10+ years	
	Lavatory	3rd FI Mens staff restroom	1	EA	5	6-10 years	
	Lighting - Pendent/Surface	3rd FI Mens staff restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	3rd FI Mens staff restroom	1	EA	6	6-10 years	
	Partitions	3rd FI Mens staff restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd FI Mens staff restroom	224	SF	6	10+ years	
	Water Closet	3rd FI Mens staff restroom	1	EA	6	6-10 years	
	Accessories	3rd FI Women's Staff Restroom	78	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd FI Women's Staff Restroom	78	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd FI Women's Staff Restroom	1	EA	6	6-10 years	
	Floor - Tile	3rd FI Women's Staff Restroom	78	SF	6	6-10 years	
	Lavatory	3rd FI Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Lay-in	3rd FI Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	3rd FI Women's Staff Restroom	1	EA	6	6-10 years	
	Partitions	3rd FI Women's Staff Restroom	2	EA	7	6-10 years	
	Walls - Concrete Block	3rd FI Women's Staff Restroom	262	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd FI Women's Staff Restroom	24	SF	6	10+ years	
	Water Closet	3rd FI Women's Staff Restroom	2	EA	6	6-10 years	
	Accessories	In Engineers Office	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Engineers Office	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	In Engineers Office	1	EA	6	10+ years	
	Floor - Tile	In Engineers Office	32	SF	6	10+ years	
	Lavatory	In Engineers Office	1	EA	6	6-10 years	
	Lighting - Lay-in	In Engineers Office	1	EA	6	6-10 years	
	Walls - Concrete Block	In Engineers Office	184	SF	6	10+ years	
	Water Closet	In Engineers Office	1	EA	6	6-10 years	
	Accessories	In Principals Office	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Principals Office	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Principals Office	1	EA	6	10+ years	
	Floor - Tile	In Principals Office	38	SF	6	10+ years	
	Lavatory	In Principals Office	1	EA	6	6-10 years	
	Lighting - Lay-in	In Principals Office	1	EA	6	6-10 years	
	Walls - Concrete Block	In Principals Office	200	SF	6	10+ years	



<u> </u>	Schools						644 W 71st STREET, Chicago, IL 6062
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	In Principals Office	1	EA	6	6-10 years	
	Accessories	In the Main Office	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Main Office	44	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In the Main Office	1	EA	6	10+ years	
	Floor - Tile	In the Main Office	44	SF	6	10+ years	
	Lavatory	In the Main Office	1	EA	6	6-10 years	
	Lighting - Lay-in	In the Main Office	1	EA	6	6-10 years	
	Walls - Concrete Block	In the Main Office	189	SF	6	10+ years	
	Water Closet	In the Main Office	1	EA	6	10+ years	
	Accessories	Next to Kitchen	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to Kitchen	90	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Next to Kitchen	1	EA	6	10+ years	
	Floor - Tile	Next to Kitchen	90	SF	6	10+ years	
	Lavatory	Next to Kitchen	1	EA	6	6-10 years	
	Lighting - Lay-in	Next to Kitchen	2	EA	6	6-10 years	
	Partitions	Next to Kitchen	1	EA	7	6-10 years	
	Student Lockers - One Tier	Next to Kitchen	4	EA	6	6-10 years	
	Walls - Concrete Block	Next to Kitchen	285	SF	6	10+ years	
	Water Closet	Next to Kitchen	1	EA	6	6-10 years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	70	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,067	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,067	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Storage/ Closet	1st Floor	79	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	891	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	Priority replacement (a.k.a. RUL) changed to update/correct to matcl current observations
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	70	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,067	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
			°,			,	

Floor - Tile

Lighting - Lay-in

Doors - Wood Doors inclu hw

1st Floor

1st Floor

1st Floor

2

17

1,067

ΕA

SF

ΕA

6

6

6

10+ years

10+ years

6-10 years



Catego	ategory : Classroom		В	uilding	044 W / ISt OTREET, Officago, ie 0002		
U				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	79	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	891	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	Repaired.
Classroo	m #106 (Kindergarten)						
	AC Units	1st Floor	7	EA	7	6-10 years	
	Casework	1st Floor	70	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,067	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,067	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Storage/ Closet	1st Floor	79	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	891	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #108 (Office)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	740	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	10+ years	
	Storage/ Closet	1st Floor	33	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	876	SF	6	10+ years	
lassroo	m #116 (Store Room)						
	Casework	1st Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	726	SF	6	10+ years	
lassroo	m #118 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	



Category : Classroom			В	uilding	: Main		
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	781	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒA	7	6-10 years	
						,	
lassroo	m #120 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	730	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	781	SF	6	10+ years	
				01	Ũ	ior youro	
lassroo	om #122 (Office)						
	Casework	1st Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	33	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	949	SF	6	10+ years	
lassroo	m #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	Priority replacement (a.k.a. RUL) changed to update/correct to matc
							current observations
	Casework	2nd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	739	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
assroo	m #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	



Juicyu	ory : Classroom		R	uilding	• Main		
				anang	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	4	1-2 years	Holes in tiles in flooring throughout
				01			classroom
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
						-	
~ .							
Classroc	om #208 (Regular Classroom)				-	A 4 A	
Classroc	AC Units	2nd Floor	1	EA	7	6-10 years	
Classroc	AC Units Casework	2nd Floor	42	LF	6	10+ years	
Classroc	AC Units Casework Ceiling - Lay-in	2nd Floor 2nd Floor	42 738	LF SF	6 6	10+ years 6-10 years	
lassror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in	2nd Floor 2nd Floor 2nd Floor	42 738 2	LF SF SF	6 6 5	10+ years 6-10 years 1-2 years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32	LF SF SF LF	6 6 5 4	10+ years 6-10 years 1-2 years 2-5 years	Damaged
Classroc	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1	LF SF SF LF EA	6 6 5 4 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years	Damaged
Classroc	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740	LF SF LF EA SF	6 6 5 4 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 10+ years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740 12	LF SF LF EA SF EA	6 6 5 4 6 6 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 10+ years 6-10 years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740 12 8	LF SF LF EA SF EA LF	6 5 4 6 6 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 10+ years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30	LF SF EA SF EA LF SF	6 5 4 6 6 6 7	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years 10+ years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740 12 8	LF SF EA SF EA F SF	6 5 4 6 6 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years	Damaged
Classror	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30	LF SF EA SF EA LF SF	6 5 4 6 6 6 7	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years 10+ years	Damaged
	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30 816	LF SF EA SF EA F SF	6 5 4 6 6 6 7 6	10+ years 6-10 years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Damaged
	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30 816	LF SF EA SF EA SF SF SF	6 5 4 6 6 6 7 6 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Damaged
	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30 816 60	LF SF EA SF EA SF SF SF EA	6 5 4 6 6 6 7 6 6 7	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Damaged
	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Structural Glazed Tile Dom #210 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30 816 60	LF SF EA SF EA SF SF EA LF	6 5 4 6 6 6 7 6 7 6	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Damaged
	AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor 2nd Floor	42 738 2 32 1 740 12 8 30 816 60	LF SF EA SF EA SF SF SF EA	6 5 4 6 6 6 7 6 6 7	10+ years 6-10 years 1-2 years 2-5 years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Damaged



Catoro	ry : Classroom		P	uilding	• Main		644 W 71st STREET, Chicago, IL 6062
Calego	ry . Classroom		B	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Floor - Tile	2nd Floor	740	SF	6	10+ years	comments
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8		6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	816	SF		•	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6 6	10+ years 10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	740	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	740	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
lassroo	m #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water marks on tiles
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
			700	SF	4	1-2 years	Holes in fleering throughout
	Floor - Tile	2nd Floor	730	ъг	4		
							Holes in flooring throughout
	Floor - Tile Lighting - Lay-in Marker Board	2nd Floor 2nd Floor 2nd Floor	730 12 12	EA LF	4 6 6	6-10 years 6-10 years	Holes in nooning throughout



<u> </u>					. Ma'::		644 W 71st STREET, Chicago, IL 6062
Catego	Category : Classroom		В	uilding			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	666	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
lassroc	m #218 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	6-10 years	Priority replacement (a.k.a. RUL)
						,	changed to update/correct to matc
							current observations
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	Work Onik			L/	,	o to years	
lassroc	m #220 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	4	1-2 years	Holes in tiles throughout
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	5
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
lassroo	m #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	4	•	Holes in flooring throughout
						1-2 years	Holes in flooring throughout
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #222 (Store Room)						
	Casework	2nd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
Classroo	om #223 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	740	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	4	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	6	10+ years	
_Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	4	6-10 years	
	Casework	3rd Floor	37	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	6-10 years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	715	SF	6	6-10 years	
	Floor - Tile	3rd Floor	15	SF	5	1-2 years	Damage/holes
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	, and the second s
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	61	SF	6	10+ years	
Classroo	om #301 (Store Room)						
	Casework	3rd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	740	SF	õ	6-10 years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
					-	,	



Catego	ry : Classroom		В	uilding	: Main		
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	5	10+ years	
	Walls - Concrete Block	3rd Floor	786	SF	6	10+ years	
	Walls - Concrete Block	3rd Floor	24	SF	5	1-2 years	Settlement cracks
	Walls - Structural Glazed Tile	3rd Floor	70	SF	6	10+ years	
						,	
lassroc	om #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	6-10 years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	730	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
lassroc	om #304 (Science)	- · -	-				
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	50	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,104	SF	6	6-10 years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,104	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	6	6-10 years	
	Science Lab Elements	3rd Floor	1,104	SF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	931	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	87	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	Repaired.
lassror	om #306 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	728	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	2	SF	5	1-2 years	Damaged
	Chalk Board	3rd Floor	36	LF	5 4	2-5 years	Damayeu
	Doors - Wood Doors inclu hw	3rd Floor		EA	4 6	6-10 years	
			=	SF		•	
	Floor - Tile	3rd Floor	729	55	6	6-10 years	



-	SCHOOIS						644 W 71st STREET, Chicago, IL 6062
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Damaged
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
laceror	om #308 (Regular Classroom)						
7005100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	42	LF	6	6-10 years	
		3rd Floor	740	SF	6	6-10 years	
	Ceiling - Lay-in Chalk Board			LF	4		
		3rd Floor	28		-	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	10+ years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
lassroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	42	LF	5	6-10 years	
	Ceiling - Lay-in	3rd Floor	740	SF	5	6-10 years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	6-10 years	
	Floor - Tile	3rd Floor	740	SF	4	1-2 years	Holes throughout floor
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	· · · · · · · · · · · · · · · · · · ·
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
Jassio	om #311 (Store Room)	Ord Floor	F 2	1 5	^	0.40	
	Casework	3rd Floor	52	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	400	SF	7	6-10 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	400	SF	6	6-10 years	
	Lighting - Metal Halide/ High Pressure Sodium	3rd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	500	SF	7	10+ years	
lassroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
			I		,	0-10 years	



Catego	ry : Classroom		В	uilding	: Main		
J	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	740	SF	6	6-10 years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	Quantity changed to update/correct to match current observations
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	740	SF	4	2-5 years	Holes throughout entire floor
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	740	SF	5	6-10 years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	4	2-5 years	Lots of holes
	Lighting - Lay-in	3rd Floor	12	ĒA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
Classroo	om #316 (Vacant)						
	Casework	3rd Floor	22	LF	6	2-5 years	
	Ceiling - Lay-in	3rd Floor	740	SF	6	6-10 years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	4	1-2 years	Damage
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
Classroo	om #318 (Vacant)						
	Casework	3rd Floor	42	LF	6	2-5 years	
	Ceiling - Lay-in	3rd Floor	24	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	716	SF	6	6-10 years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	2-5 years	
Classroo	m #320 (Vacant)						
	Casework	3rd Floor	22	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Damage
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	730	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
			00	01	0	Tor years	
Classroo	m #321 (Vacant)					10	
	Casework	3rd Floor	37	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	726	SF	6	10+ years	
	Floor - Tile	3rd Floor	4	SF	4	0-1 year	Damaged
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	
Classroc	m #322 (Vacant)						
	AC Units	3rd Floor	1	EA	4	0-1 year	Not working
	Casework	3rd Floor	37	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	730	SF	6	6-10 years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	730	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	721	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	740	SF	6	6-10 years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	5	6-10 years	
	Lighting - Lay-in	3rd Floor	12	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	816	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	60	SF	6	10+ years	

Category : Interior

Category : Interior			В	uilding	: Main		
Crown	Itom Turo	Location	Quantity	UOM	Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Ceiling - Lay-in	1st Floor	3,948	SF	6	10	
	Drinking Fountains - Single Fountain	1st Floor	3,940	EA	5	10+ years	
	Floor - Terrazzo	1st Floor	340	SF	5	6-10 years	
	Floor - Tile/Sheet	1st Floor		SF	5	10+ years	
			3,948		-	10+ years	
	Lighting - Lay-in Walls - Concrete Block	1st Floor 1st Floor	29 1,803	EA SF	6	6-10 years	
				SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,454		6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,948	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	100	SF	1	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,848	SF	5	6-10 years	
	Lighting - Lay-in	2nd Floor	25	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,281	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,845	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,948	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	5	2-5 years	
	Drinking Fountains - Single Water Cooler	3rd Floor	3	EA	4	1-2 years	No water
	Floor - Terrazzo	3rd Floor	100	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,884	SF	5	10+ years	
	Lighting - Lay-in	3rd Floor	24	EA	6	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	114	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,281	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3,845	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3	SF	4	2-5 years	
Safety							
	Camera Viewing Station	Entire Building	2	EA	5	6-10 years	
	Security Cameras	Entire Building	12	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	5	6-10 years	
		-				-	



Group Item - Type Location Quantity UOM Rank Recommend Replacement Comments Stairs									
Stairs Ceiling - Lay-in Stairwell #1, southwest Corner 115 SF 6 10+ years Ceiling - Lay-in Stairwell #1, southwest Corner 8 SF 5 1-2 years		Recommend							
Ceiling - Lay-inStairwell #1, southwest Corner115SF610+ yearsCeiling - Lay-inStairwell #1, southwest Corner8SF51-2 years	Comments	Replacement	Rank	UOM	Quantity	Location	ltem - Type	Group	
Ceiling - Lay-inStairwell #1, southwest Corner115SF610+ yearsCeiling - Lay-inStairwell #1, southwest Corner8SF51-2 years								Stairs	
Ceiling - Lay-in Stairwell #1, southwest Corner 8 SF 5 1-2 years		10+ years	6	SF	115	Stairwell #1, southwest Corner	Ceiling - Lay-in		
						,			
Ceiling - Plaster/Drywall Stairwell #1, southwest Corner 71 SF 6 10+ years		10+ years	6	SF	71	Stairwell #1, southwest Corner	Ceiling - Plaster/Drywall		
Floor - Terrazzo Stairwell #1, southwest Corner 152 SF 6 10+ years			6	SF	152				
Handrails Stairwell #1, southwest Corner 95 LF 5 10+ years									
Lighting - Lay-in Stairwell #1, southwest Corner 2 EA 6 6-10 years			6	EA	2	Stairwell #1, southwest Corner	Lighting - Lay-in		
Lighting - Wall Mounted Stairwell #1, southwest Corner 1 EA 6 6-10 years		6-10 years	6	EA	1	Stairwell #1, southwest Corner			
Stairs - Terrazzo Stairwell #1, southwest Corner 32 LF 6 10+ years		•	6	LF	32				
Walls - Concrete Block Stairwell #1, southwest Corner 350 SF 6 10+ years			6						
Walls - Structural Glazed Tile Stairwell #1, southwest Corner 366 SF 6 10+ years			6	SF	366		Walls - Structural Glazed Tile		
Ceiling - Lay-in Stairwell #3, northeast corner 123 SF 6 10+ years		•	6	SF	123		Ceiling - Lay-in		
Ceiling - Plaster/Drywall Stairwell #3, northeast corner 71 SF 6 10+ years		•	6	SF	71	Stairwell #3, northeast corner			
Floor - Terrazzo Stairwell #3, northeast corner 152 SF 6 10+ years			6	SF	152	Stairwell #3, northeast corner			
Handrails Stairwell #3, northeast corner 95 LF 7 10+ years		10+ years	7	LF	95	Stairwell #3, northeast corner	Handrails		
Lighting - Lay-in Stairwell #3, northeast corner 2 EA 6 6-10 years		6-10 years	6	EA	2	Stairwell #3, northeast corner	Lighting - Lay-in		
Lighting - Pendent/Surface Stairwell #3, northeast corner 1 EA 6 6-10 years		6-10 years	6	EA	1	Stairwell #3, northeast corner			
Stairs - Terrazzo Stairwell #3, northeast corner 32 LF 6 10+ years		10+ years	6	LF	32	Stairwell #3, northeast corner	Stairs - Terrazzo		
Walls - Concrete Block Stairwell #3, northeast corner 350 SF 6 10+ years		10+ years	6	SF	350	Stairwell #3, northeast corner	Walls - Concrete Block		
Walls - Structural Glazed Tile Stairwell #3, northeast corner 366 SF 6 10+ years		10+ years	6		366	Stairwell #3, northeast corner	Walls - Structural Glazed Tile		
Ceiling - Lay-in Stairwell #4, northwest corner 115 SF 6 10+ years		10+ years	6	SF	115	Stairwell #4, northwest corner	Ceiling - Lay-in		
Ceiling - Lay-in Stairwell #4, northwest corner 8 SF 5 1-2 years Damaged	Damaged	1-2 years	5		8	Stairwell #4, northwest corner	Ceiling - Lay-in		
Ceiling - Plaster/Drywall Stairwell #4, northwest corner 71 SF 6 10+ years		10+ years	6	SF	71	Stairwell #4, northwest corner	Ceiling - Plaster/Drywall		
Floor - Terrazzo Stairwell #4, northwest corner 152 SF 6 10+ years		10+ years	6		152	Stairwell #4, northwest corner	Floor - Terrazzo		
Handrails Stairwell #4, northwest corner 95 LF 5 10+ years		10+ years	5		95	Stairwell #4, northwest corner	Handrails		
Lighting - Lay-in Stairwell #4, northwest corner 2 EA 6 6-10 years		6-10 years	6	EA	2	Stairwell #4, northwest corner			
Lighting - Wall Mounted Stairwell #4, northwest corner 1 EA 6 6-10 years		6-10 years	6		1	Stairwell #4, northwest corner	Lighting - Wall Mounted		
Stairs - Terrazzo Stairwell #4, northwest corner 32 LF 6 10+ years			6			,			
Walls - Concrete Block Stairwell #4, northwest corner 350 SF 6 10+ years		10+ years	6		350	Stairwell #4, northwest corner	Walls - Concrete Block		
Walls - Structural Glazed Tile Stairwell #4, northwest corner 366 SF 6 10+ years		10+ years	-			Stairwell #4, northwest corner			
Ceiling - Lay-in Stairwell#2, southeast corner 123 SF 6 10+ years		10+ years				Stairwell#2, southeast corner			
Ceiling - Plaster/Drywall Stairwell#2, southeast corner 71 SF 6 10+ years						Stairwell#2, southeast corner			
Floor - Terrazzo Stairwell#2, southeast corner 152 SF 6 10+ years		10+ years	-			Stairwell#2, southeast corner			
Handrails Stairwell#2, southeast corner 95 LF 5 10+ years		10+ years					Handrails		
Lighting - Lay-in Stairwell#2, southeast corner 2 EA 6 6-10 years		•							
Lighting - Pendent/Surface Stairwell#2, southeast corner 1 EA 6 6-10 years					-				
Stairs - Terrazzo Stairwell#2, southeast corner 32 LF 6 10+ years			-						
Walls - Concrete Block Stairwell#2, southeast corner 366 SF 6 10+ years			-			•			
Walls - Structural Glazed TileStairwell#2, southeast corner250SF610+ years		10+ years	6	SF	250	Stairwell#2, southeast corner	Walls - Structural Glazed Tile		



Catego	ry : Site		В	uilding	: Site	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
 Civil/Dra							
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Manhole	Entire Site Entire Site	5 2	EA EA	7 7	6-10 years 6-10 years	
Fencina							
	Fencing - Chain Link Fencing - Chain Link	Entire Site Entire Site	973 400	LF LF	6 5	6-10 years 6-10 years	
Landsca	De						
	Landscape - Grass Landscape - Hardscape- Asphalt	Entire Site Entire Site	8,118 1,000	SF SF	6 5	10+ years 2-5 years	Priority replacement (a.k.a. RUL) changed to update/correct to match current observations
	Parkway trees Planting Beds/ Area Play Area - Hardscape- Asphalt Trash Receptacles	Entire Site Entire Site Entire Site Entire Site	9 800 24,437 1	EA SF SF EA	6 6 6	10+ years 10+ years 2-5 years 2-5 years	
Parking	ot						
	Surface - Asphalt Surface - Asphalt	Entire Site Entire Site	1,500 14,725	SF SF	5 4	1-2 years 2-5 years	Cracks, uneven
Playgrou	nd						
	Equipment - School Age 5-12 Surface - Poured Surface	West West	2 3,800	EA SF	7 7	6-10 years 6-10 years	
Sidewalk	S						
	Sidewalks - Internal Walks Sidewalks - Perimeter Sidewalks	Entire Site Entire Site	195 7,393	LF SF	6 6	10+ years 10+ years	
_Signage							
	Flag Pole - Flag Pole Marquee - Free Standing Back Lighted	Entire Site Entire Site	1 1	EA EA	6 6	10+ years 6-10 years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Intended Osage	Koom Location	Number	Number	(51)	Alea	Alea	Stop	Duaru
Computer Lab	Regular Classroom	2nd Floor	218	218	730	150	40	N	N
Computer Lab	Regular Classroom	2nd Floor	220	220	730	150	40	N	N
Kindergarten	Kindergarten	1st Floor	102	102	1,067	225	60	N	N
Kindergarten	Kindergarten	1st Floor	102	102	1,067	225	60	N	N
Kindergarten	Kindergarten	1st Floor	104	104	1,067	225	60	N	N
Office	Regular Classroom	1st Floor	108	108	740	192	40	N	N
Office	Regular Classroom	1st Floor	122	122	730	152	40	N	N
Other Instructional Use	Regular Classroom	3rd Floor	306	306	730	150	40	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	730	150	40	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	730	150	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	730	150	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	740	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	152	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	740	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	740	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	210	740	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	740	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	730	152	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	730	192	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	740	192	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	300	300	730	150	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	730	150	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	740	192	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	740	192	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	740	192	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	312	740	192	40	N	N
Science	Science	3rd Floor	304	304	1,104	225	60	N	N
Store Room	Regular Classroom	1st Floor	116	116	730	150	40	N	N
Store Room	Regular Classroom	2nd Floor	222	222	730	150	40	N	N
Store Room	Regular Classroom	3rd Floor	301	301	740	192	40	N	N
Store Room	Regular Classroom	3rd Floor	323	323	740	192	40	N	N
Store Room	Store Room	3rd Floor	311	NA	400	72	36		
Vacant	Regular Classroom	3rd Floor	316	316	730	150	40	N	N
Vacant	Regular Classroom	3rd Floor	318	318	730	150	40	N	N
Vacant	Regular Classroom	3rd Floor	320	320	730	150	40	N	N
Vacant	Regular Classroom	3rd Floor	321	321	730	192	40	N	N
Vacant	Regular Classroom	3rd Floor	322	322	730	152	40	N	N