

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1916	3	80,659
Addition	1928	3	286,322
Campus Total			366,981

Category : Exterior Building : Main

Galego	Pategory . Exterior			unung	. Iviaiii			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Exterior Steel Door	11 - Tunnel North	3	EA	6	6-10 years		
	Exterior Doors - Transom Lite	11 - Tunnel North	2	EA	6	6-10 years		
	Exterior Stairs - Concrete	11 - Tunnel North	18	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	15 - Courtyard	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	15 - Courtyard	2	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	16 - Fire Escape	1	EA	6	6-10 years		
	Exterior Doors - Transom Lite	16 - Fire Escape	1	EΑ	6	6-10 years		
	Exterior Doors - Exterior Steel Door	17 - Fire Escape	1	EA	6	6-10 years	Top/Highest	
	Exterior Doors - Transom Lite	17 - Fire Escape	1	EA	6	6-10 years	Top/Highest	
	Exterior Doors - Overhead Rolling/ Garage	18- OVH Tunnel	1	EA	6	6-10 years	. •	
	Door					•		
	Exterior Doors - Exterior Steel Door	19 - Tunnel	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	20 - Tunnel	1	EΑ	6	6-10 years		
	Exterior Doors - Exterior Steel Door	21 - Tunnel	1	EΑ	6	6-10 years		
	Exterior Doors - Exterior Steel Door	22 - North	9	EA	6	6-10 years		
	Exterior Doors - Transom Lite	22 - North	6	EA	6	6-10 years		
	Exterior Stairs - Concrete	22 - North	90	LF	5	10+ years	Significant Damage- Cracked/Broken	
	Exterior Doors - Exterior Steel Door	23 (14) - West	2	EΑ	6	6-10 years		
	Exterior Stairs - Concrete	23 (14) - West	10	LF	7	10+ years	Under construction. Assumed to be in	
							new condition when finished.	
	Ramp Handrail - Steel_Ramp Handrail	23 (14) - West	25	LF	6	6-10 years		
	Ramps - Concrete	23 (14) - West	12	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	23 (14) - West	10	LF	6	6-10 years		



Calegor	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	24 (15) - West	2	EA	6	6-10 years	
ire Esca	ane						
IIO LOCC	Fire Escape	East Façade	99	LF	4	0-1 year	Contact Weld and Mechanical
	·	•				Ţ	Fastener Failed/Missing - Hanging Tread. 7th Tread From Top Landing
oundation	on						
	Foundation - Concrete	Entire Building	909	LF	7	10+ years	
	Foundation - Concrete	Entire Building	50	LF	5	2-5 years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	80,659	SF	7	10+ years	
ighting_	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years	
	Exterior Lighting - wall wounted	Littile building	11	LA	Ü	0-10 years	
oof Sys	tem						
	Access Ladder - Metal	A - Northwest	2	EA	7	6-10 years	
	Coping - Metal	A - Northwest	346	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	A - Northwest	346	LF	6	6-10 years	
	Roof - Asphalt Shingle	A - Northwest	3,756	SF	7	6-10 years	
	Roof - Metal	A - Northwest	1,100	SF	7	10+ years	
	Roof - Modified Bitumen	A - Northwest	2,639	SF	7	10+ years	Under Repair
	Roof Structure - Steel with Clay Tile Arch	A - Northwest	7,495	SF	7	10+ years	·
	Access Ladder - Metal	B - WestCenter	, 1	ĒΑ	7	6-10 years	
	Coping - Metal	B - WestCenter	67	LF	6	6-10 years	
	Coping - Stone	B - WestCenter	90	LF	5	10+ years	
	Downspouts - Exterior Downspouts	B - WestCenter	132	LF	6	6-10 years	
	Parapet - 16" - 30" Height	B - WestCenter	10	LF	7	6-10 years	No Visible Masonry Parapet of 16" 30" Found.
	Parapet - 16" - 30" Height	B - WestCenter	44	LF	6	10+ years	Do.
	Parapet - Parapet < 16" Height	B - WestCenter	97	LF	6	10+ years	Б0.
	Roof - Modified Bitumen	B - WestCenter	4,296	SF	5	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	B - WestCenter	4,296	SF	7	10+ years	
	Access Ladder - Metal	C - Chimney	1	EA	7	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar	C - Chimney	75	LF	5		With Displaced Masonry/Missing
	Liner	•				2-5 years	Mortar - Air Joints
	Chimney - Brick Chimney- Concrete/ Mortar Liner	C - Chimney	10	LF	4	2-5 years	
	Coping - Metal	C - Chimney	199	LF	6	6-10 years	
	Parapet - 16" - 30" Height	C - Chimney	111	LF	6	10+ years	
	Parapet - Parapet < 16" Height	C - Chimney	88	LF	6	10+ years	



Catego	Category: Exterior			uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	C - Chimney	5,237	SF	5	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	C - Chimney	5,237	SF	7	10+ years	
	Coping - Metal	D - Southwest	32	LF	6	6-10 years	
	Coping - Stone	D - Southwest	14	LF	6	10+ years	
	Parapet - Parapet < 16" Height	D - Southwest	14	LF	6	10+ years	
	Parapet - Parapet > 30"	D - Southwest	32	LF	6	10+ years	
	Roof - Modified Bitumen	D - Southwest	252	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	D - Southwest	252	SF	7	10+ years	
	Coping - Metal	E - West	135	LF	7	10+ years	Changed to metal
	Downspouts - Exterior Downspouts	E - West	20	LF	6	6-10 years	
	Parapet - 16" - 30" Height	E - West	107	LF	6	10+ years	
	Parapet - Parapet < 16" Height	E - West	28	LF	6	10+ years	
	Roof - Modified Bitumen	E - West	2,366	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	E - West	2,366	SF	7	10+ years	
	Coping - Clay Tile	F - Southwest	35	LF	6	6-10 years	
	Coping - Stone	F - Southwest	118	LF	5	6-10 years	
	Parapet - Parapet < 16" Height	F - Southwest	118	LF	6	10+ years	
	Roof - Modified Bitumen	F - Southwest	2,600	SF	5	2-5 years	SF Data Adjusted - Roof With Skylights
	Roof Structure - Steel with Clay Tile Arch	F - Southwest	2,600	SF	7	10+ years	Do.
	Coping - Stone	F1 - South Center	205	LF	7	6-10 years	
	Downspouts - Exterior Downspouts	F1 - South Center	28	LF	7	6-10 years	Does not Exist
	Parapet - Parapet < 16" Height	F1 - South Center	205	LF	7	6-10 years	
	Roof - Modified Bitumen	F1 - South Center	1,800	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	F1 - South Center	1,800	SF	7	6-10 years	
	Coping - Metal	G - SouthCenter	69	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	G - SouthCenter	12	LF	6	6-10 years	
	Parapet - 16" - 30" Height	G - SouthCenter	69	LF	6	10+ years	
	Roof - Modified Bitumen	G - SouthCenter	1,080	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	G - SouthCenter	1,080	SF	7	10+ years	
	Coping - Metal	H - SouthCenter	52	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	H - SouthCenter	22	LF	6	6-10 years	
	Parapet - 16" - 30" Height	H - SouthCenter	52	LF	6	10+ years	
	Roof - Modified Bitumen	H - SouthCenter	480	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	H - SouthCenter	480	SF	7	10+ years	
	Coping - Clay Tile	L-Upper East Center	343	LF	6	10+ years	Quantity Adjusted - See Roof L
	Coping - Metal	L-Upper East Center	75	LF	7	10+ years	•
	Downspouts - Interior Downspouts	L-Upper East Center	180	LF	6	6-10 years	Item Typed Changed - LF Changed
	Parapet - 16" - 30" Height	L-Upper East Center	418	LF	6	10+ years	,, ,
	Roof - Modified Bitumen	L-Upper East Center	8,186	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	L-Upper East Center	8,186	SF	7	10+ years	
	Coping - Stone	O - Lower East Center	67	LF	5	6-10 years	Mildew/Moisture
	Parapet - 16" - 30" Height	O - Lower East Center	67	LF	6	10+ years	
	Roof - Modified Bitumen	O - Lower East Center	533	SF	5	6-10 years	Organic Vegetation growth/Tree
						,	



F Walls	Item - Type	Location				Recommend	
F Walls	· ·	i ocanon	Oughtit	UOM	Donk	Poplacement	Commonto
Walls E		2004.1011	Quantity	UOW	Rank	Replacement	Comments Overhang on Roof
Walls E	Roof Structure - Steel with Clay Tile Arch	O - Lower East Center	533	SF	7	10+ years	Overhalig on Rooi
E	,				-	, , , , , , , , , , , , , , , , , , , ,	
-	Exterior Walls - Brick	Entire Building	52,273	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	750	SF	4	1-2 years	Missing Mortar/Air Joints
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Missing Mortar/Air Joints
	Exterior Walls - Brick	Entire Building	115	SF	4	1-2 years	Missing Mortar/Air Joints
	Exterior Walls - Brick	Entire Building	800	SF	4	2-5 years	Missing Mortar/Air Joints
F	Exterior Walls - Prefabricated Metal Panel	Entire Building	725	SF	7	2-5 years	Being Repaired - Per Site
V	Wall						Construction Site Superintendent "Ice
							and Water applied at Perimeter of
							Metal Panel Wall under Shingled
							Roof.
E	Exterior Walls - Stone-Cast	Entire Building	2,112	SF	6	10+ years	
Mindows							
Windows	Guard - Guards perforated	Entire Building	960	SF	7	10+ years	
	Lintels - Steel	Entire Building	882	LF	6	10+ years	
	Lintels - Stone	Entire Building	27	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	498	SF	6	10+ years	
	Storefront Windows	Entire Building	72	SF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	540	SF	6	6-10 years	
	pane	Entire Ballating	040	O.	O	o to years	
	Windows - Decorative	Entire Building	648	SF	6	6-10 years	
	Windows - Louver	Entire Building	66	SF	6	6-10 years	Verify Fasteners/Attachment - Scrape
·	Williadws Eduvei	Little Ballaing	00	O.	O	o ro years	and Minor Paint.
V	Windows - Sash Aluminum Double-pane	Entire Building	2,660	SF	6	6-10 years	
Category	/ : Electrical		В	uilding	: Main		
				_		Recommend	
<u>'</u>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergency		Fating Desilations				0.40	
	Exit Signs - Corridors and Stairs	Entire Building	33	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	5	EΑ	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	21,639	SF	6	6-10 years	Runs off of generator
	Emergency A/C Power - Gym	Entire Building	5,918	SF	6	6-10 years	Runs off of generator
	Security System - CCTV	Entire Building	366,981	SF	6	6-10 years	, , g
	Security System - Intrusion Detection	Entire Building	366,981	SF	6	6-10 years	
	Emergency Generator- Outdoor- Diesel -	Site North	1	EA	7	10+ years	Tested monthly. Works well



	ry : Electrical		В	uilding	: Main		
	И Т	Lagathan	0	HOM	DI-	Recommend	0
roup	Item - Type 101 - 150 KW	Location	Quantity	UOM	Rank	Replacement	Comments
	101 - 150 KW						
ain Se	rvice						
<u> </u>	PA System	Entire Building	366,981	SF	6	6-10 years	
	Gyoto	g	333,33	Ο.	· ·	0 .0 ,00.0	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	11	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	2-5 years	
	amp	3			-	7	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	2-5 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EΑ	6	2-5 years	
	Transionners - 277/400 - 120/200	Entire Banding	'	LA	O	2-5 years	
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
re Alaı	m						
	Fire Alarm Panel	Entire Building	1	EA	2	0-1 year	Does not pass inspection
	Fire Alarm_System	Entire Building	366,981	SF	4	1-2 years	
Catego	rv : Mechanical		В	uildina	: Main		
atego	ry : Mechanical		В	uilding	: Main	Recommend	
	ry : Mechanical Item - Type	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
roup		Location		_			Comments
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone-	Location 1st Floor		_			Comments
roup	Item - Type Iling Systems		Quantity	UOM	Rank	Replacement 6-10 years	
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone-		Quantity	UOM	Rank	Replacement	Dampers have been repaired
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	1st Floor	Quantity	UOM	Rank 5	Replacement 6-10 years	
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	1st Floor 1st Floor	Quantity 1	UOM EA EA	Rank 5 5	6-10 years 6-10 years 2-5 years	Dampers have been repaired Frames all look good
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts-	1st Floor 1st Floor 1st Floor	Quantity 1 1 1	UOM EA EA EA	Rank 5 5 5 5	Replacement 6-10 years 6-10 years	Dampers have been repaired
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	1st Floor 1st Floor 1st Floor 1st Floor	Quantity 1 1 1 1 100	EA EA EA LF	5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years	Dampers have been repaired Frames all look good
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 1 1 1	EA EA EA LF	5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years	Dampers have been repaired Frames all look good
roup	Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone-	1st Floor 1st Floor 1st Floor 1st Floor	Quantity 1 1 1 100 17	EA EA EA LF	5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years	Dampers have been repaired Frames all look good
roup	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement	Quantity 1 1 1 100 17	EA EA EA LF EA EA	5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good
roup	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm Air Intake	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement Basement	Quantity 1 1 1 100 17	EA EA EA LF EA EA	5 5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good
roup	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement Basement Basement	Quantity 1 1 1 100 17 1 1 1	EA EA LF EA EA EA	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good Repaired since last survey
roup	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm Air Intake	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement Basement	Quantity 1 1 1 100 17 1	EA EA EA LF EA EA	5 5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good Repaired since last survey On construction side of building.
roup r Hand	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement Basement Basement	Quantity 1 1 1 100 17 1 1 1	EA EA LF EA EA EA	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good Repaired since last survey On construction side of building. Engineer reports that there are no
roup	Item - Type Illing Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm Air Intake Auxiliaries - 25001 - 35000 cfm Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor Basement Basement Basement	Quantity 1 1 1 100 17 1 1 1	EA EA LF EA EA EA	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	6-10 years 6-10 years 2-5 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years	Dampers have been repaired Frames all look good Repaired since last survey On construction side of building. Engineer reports that there are no



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Pressure Boiler - 76 - 100 HP					•	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	Only one of these
	Steam- Low Pressure Boiler - 76 - 100 HP		-		•	- · · · · · · · · · · · · · · · · · · ·	,
	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	5	6-10 years	
	Pressure Boiler - Greater than 300 HP	Ziimo Zananig	_	_, `	Ū	o ro youro	
	Chemical Feed System	Entire Building	1	EA	6	10+ years	
	Combustion Dampers	Entire Building	2	EA	6	6-10 years	
	Condensate Pump	Entire Building	1	EA	6	10+ years	
	•	· ·	1	EA	4	2-5 years	
	Condensate Pump	Entire Building	•			•	
	Feed Water Pumps and Tank	Entire Building	1	EΑ	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	2	EA	5	6-10 years	
	Steam- Low Pressure Boiler - Greater than						
	300 HP						
	Piping - Condensate Pipe- Steel	Entire Building	300	LF	4	2-5 years	
	Piping - Steam Pipe- Steel	Entire Building	300	LF	4	2-5 years	
	Steam Traps	Entire Building	29	EA	4	2-5 years	
eating	Devices						
	Radiators - Steam	Entire Building	12	EA	5	6-10 years	
	Unit Heater - Steam	Entire Building	2	EΑ	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	4	EA	5	6-10 years	
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	
	Similifolds Gas	Zimio Bananig	·	_, 、	Ü	o io youio	
empera	ature Control						
	Pneumatic System	Entire Building	80,659	SF	3	0-1 year	Not working. Manually controlled
	Thermostats - Pneumatic	Entire Building	18	EA	4	0-1 year	Not working.
entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Fan is above ceiling
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	3
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	4	2-5 years	Fans are dangerous to access
	CFM	g	_		•	_ 0 ,00.0	i and and danigorous to access
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	7	6-10 years	Fan has recently been repaired
	500 CFM	J				,	,
atego	ry : Plumbing		В	uilding	: Main		
	.,		_			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	3	EA	7	10+ years	
	Hot Water Storage Tank_Gas - 501 - 1000	Boiler Room	2	EA	6	6-10 years	
	Gallons					,	



Catego	Category : Plumbing			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	80,659	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	80,659	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	80,659	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	80,659	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	80,659	SF	6	10+ years	Risers are galvanized
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	80,659	SF	6	10+ years	Risers are galvanized
	Sanitary Piping	Entire Building	80,659	SF	6	10+ years	
	Storm Piping	Entire Building	80,659	SF	6	10+ years	Much piping has been replaced. Engineer reports that all roofs drain well.
	Vent Piping	Entire Building	80,659	SF	6	10+ years	
Pumps							
	Pumps - Sump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	5	2-5 years	

Category : Room **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices	20041011	Qualitity		Rank	Ropidocinicit	
	Ceiling - Plaster/Drywall	012-3 Gym Office	416	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	012-3 Gym Office	1	EA	6	6-10 years	
	Floor - Wood	012-3 Gym Office	416	SF	6	6-10 years	
	Lighting - Pendent/Surface	012-3 Gym Office	6	EA	6	6-10 years	
	Power Distribution	012-3 Gym Office	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	012-3 Gym Office	1,008	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	176.1 Dressing Room Basement - used as construction material storage during renovation	117	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	176.1 Dressing Room Basement - used as construction material storage during renovation	1	EA	7	6-10 years	
	Floor - Concrete	176.1 Dressing Room Basement - used as construction material storage during renovation	117	SF	7	6-10 years	
	Lighting - Pendent/Surface	176.1 Dressing Room Basement - used as construction material	1	EA	6	6-10 years	



Categor	ategory : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		storage during renovation			_			
	Walls - Plaster/Drywall	176.1 Dressing Room Basement -	374	SF	7	10+ years		
		used as construction material						
	Marila Olada	storage during renovation	4	_^	7	0.40		
	Work SInk	176.1 Dressing Room Basement -	1	EA	7	6-10 years		
		used as construction material storage during renovation						
	Ceiling - Plaster/Drywall	176.2 Dressing Room Basement	117	SF	7	6-10 years		
	Celling - Flaster/Drywan	Used As Storage durable no	117	OI.	,	0-10 years		
		renovation						
	Doors - Wood Doors inclu hw	176.2 Dressing Room Basement	1	EA	7	6-10 years		
	Doord Wood Doord mold in	Used As Storage durable no	•	_, `	•	o to youro		
		renovation						
	Floor - Concrete	176.2 Dressing Room Basement	117	SF	7	6-10 years		
		Used As Storage durable no				,		
		renovation						
	Lighting - Pendent/Surface	176.2 Dressing Room Basement	2	EA	6	6-10 years		
		Used As Storage durable no						
		renovation						
	Walls - Plaster/Drywall	176.2 Dressing Room Basement	374	SF	7	10+ years		
		Used As Storage durable no						
	4011.	renovation			_	0.40		
	AC Unit	210 Office	1 450	EA SF	7	6-10 years		
	Ceiling - Lay-in Doors - Wood Doors inclu hw	210 Office 210 Office	450	SF EA	7	10+ years		
	Floor - Tile	210 Office	444	SF	7 7	10+ years 10+ years		
	Floor - Tile	210 Office	6	SF	4	0-1 year	Damaged flooring	
	Lighting - Lay-in	210 Office	6	EA	7	10+ years	Damaged nooring	
	Power Distribution	210 Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	210 Office	877	SF	6	10+ years		
	Walls - Plaster/Drywall	210 Office	2	SF	4	0-1 year	Damaged wall	
	AC Unit	210A Office	1	EA	7	6-10 years	G	
	Ceiling - Lay-in	210A Office	238	SF	7	10+ years		
	Doors - Side-lite	210A Office	12	SF	7	10+ years		
	Doors - Transom Window	210A Office	45	SF	7	10+ years		
	Doors - Wood Doors inclu hw	210A Office	1	EA	7	10+ years		
	Floor - Wood	210A Office	238	SF	7	10+ years		
	Lighting - Lay-in	210A Office	4	EΑ	7	10+ years		
	Power Distribution	210A Office	6	EA	7	10+ years		
	Walls - Plaster/Drywall	210A Office	644	SF	7	10+ years	Observed AO weed	
	AC Unit	310A Office - Attic	1	EA	7	6-10 years	Observed AC working properly	
	Ceiling - Lay-in	310A Office - Attic	234	SF EA	7	10+ years		
	Doors - Wood Doors inclu hw Floor - Wood	310A Office -Attic 310A Office -Attic	1 234	SF	7 6	10+ years		
	FIOUI - WOOU	STUA Office -AUIC	234	ЭF	O	10+ years		



Catego	ry : Room		В	uilding	: Main		_
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	310A Office -Attic	4	EA	7	10+ years	
	Power Distribution	310A Office -Attic	4	EA	7	10+ years	
	Walls - Plaster/Drywall	310A Office -Attic	724	SF	7	10+ years	
	Walls - Plaster/Drywall	310A Office -Attic	8	SF	6	10+ years	
	AC Unit	Basement Engineer's Office A	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement Engineer's Office A	264	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Basement Engineer's Office A	3	EA	6	6-10 years	
	Floor - Tile	Basement Engineer's Office A	264	SF	7	6-10 years	
	Lighting - Lay-in	Basement Engineer's Office A	2	EA	6	6-10 years	
	Power Distribution	Basement Engineer's Office A	2	EA	7	10+ years	
	Walls - Masonry	Basement Engineer's Office A	340	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement Engineer's Office A	340	SF	7	10+ years	
	Ceiling - Lay-in	Basement Engineer's Office B	135	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Basement Engineer's Office B	1	ĒΑ	7	6-10 years	
	Floor - Tile	Basement Engineer's Office B	135	SF	7	6-10 years	
	Lighting - Lay-in	Basement Engineer's Office B	2	ĒΑ	6	6-10 years	
	Power Distribution	Basement Engineer's Office B	6	EA	7	10+ years	
	Walls - Masonry	Basement Engineer's Office B	560	SF	7	10+ years	
	wane massing			О.	•	. o · you.o	
Auditoriu	ım & Theater						
	Balcony Seating	Basement	342	EA	7	10+ years	Under renovation
	Balcony Seating	Basement	450	EA	7	10+ years	Under renovation
	Ceiling - Plaster/Drywall	Basement	13,568	SF	7	10+ years	Under renovation
	Doors - Wood Doors inclu hw	Basement	12	EA	7	10+ years	Under renovation
	Floor - Concrete	Basement	3,325	SF	7	10+ years	Under renovation
	Floor - Tile	Basement	1,925	SF	7	10+ years	Under renovation
	Floor - Wood	Basement	8,320	SF	7	10+ years	Under renovation
	Lighting - Pendent/Surface	Basement	55	ĒΑ	6	10+ years	Under renovation
	Lighting - Wall Mounted	Basement	17	ΕA	6	10+ years	Under renovation
	Main Floor Seating	Basement	648	EA	7	6-10 years	Under renovation
	Sound System	Basement	1	EΑ	7	6-10 years	Under renovation
	Stage	Basement	1,995	SF	7	10+ years	Under renovation
	Stage Curtain	Basement	3	EA	7	10+ years	Under renovation
	Stage Lighting System	Basement	1	EΑ	7	6-10 years	Under renovation
	Stage-Stairs - Wood	Basement	48	LF	7	10+ years	Under renovation
	Stairs - Wood	Basement	400	LF	7	10+ years	Under renovation
	Stairs - Wood	Basement	802	LF	7	10+ years	Under renovation
	Walls - Plaster/Drywall	Basement	21,790	SF	7	10+ years	Under renovation
	vvalio i laotoi/Diywaii	Bacomon	21,700	O.	•	To Tyouro	Chach removation
Gymnas	ia						
,	Ceiling - Plaster/Drywall	12 Basement Girls Gym	5,918	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	12 Basement Girls Gym	7	ĒΑ	7	6-10 years	
	Floor - Tile	12 Basement Girls Gym	1,500	SF	7	6-10 years	
	Floor - Wood	12 Basement Girls Gym	4,418	SF	7	6-10 years	
		· ,	,			,	



atego	ry : Room		В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	12 Basement Girls Gym	42	EA	7	6-10 years			
	Scoreboards	12 Basement Girls Gym	1	EΑ	7	6-10 years			
	Storage/ Closet	12 Basement Girls Gym	192	SF	7	6-10 years			
	Walls - Metal Panel	12 Basement Girls Gym	3,375	SF	7	10+ years			
	Walls - Structural Glazed Tile	12 Basement Girls Gym	4,125	SF	7	10+ years			
echani	ical/ Service Rooms								
	Janitor's Closet	1st Floor	16	SF	7	10+ years			
	Janitor's Closet	1st Floor	4	SF	4	0-1 year	Missing ceiling tile		
	Janitor's Closet	2nd Floor	20	SF	7	10+ years	whoshing coming the		
	Storage Room	2nd Floor	10	SF	7	10+ years			
	Storage Room	2nd Floor	368	SF	7	10+ years			
	Janitor's Closet	3rd Floor	20	SF	7	10+ years			
	Storage Room	3rd Floor	368	SF	7	10+ years			
		3rd Floor	10	SF	7	10+ years			
	Storage Room			SF					
	Air Tunnel	Main Building Mechanical/Storage	770		7	6-10 years			
	Boiler Room	Main Building Mechanical/Storage	3,850	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	999	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	832	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	104	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	1,088	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	230	SF	7	6-10 years			
	Mechanical/ Service Rooms	Main Building Mechanical/Storage	441	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	192	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	420	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	110	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	540	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	100	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	56	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	384	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	384	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	384	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	56	SF	7	6-10 years			
	Storage Room	Main Building Mechanical/Storage	242	SF	7	6-10 years			
estroor	m								
2211001		4at Floor France and Tallet Da	00		7	0.40			
	Accessories	1st Floor Engineer's Toilet Room	30	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor Engineer's Toilet Room	30	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Engineer's Toilet Room	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Engineer's Toilet Room	30	SF	6	6-10 years			
	Lavatory	1st Floor Engineer's Toilet Room	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor Engineer's Toilet Room	1	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor Engineer's Toilet Room	195	SF	6	10+ years			
	Water Closet	1st Floor Engineer's Toilet Room	1	EΑ	6	6-10 years			



	ry : Room		Building : Main						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	210B Unisex	189	SF	7	10+ years			
	Ceiling - Lay-in	210B Unisex	189	SF	6	10+ years			
	Doors - Transom Window	210B Unisex	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	210B Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	210B Unisex	189	SF	7	10+ years			
	Lavatory	210B Unisex	2	EA	7	10+ years			
	Lighting - Lay-in	210B Unisex	3	EA	7	10+ years			
	Partitions	210B Unisex	2	EA	7	10+ years			
	Walls - Plaster/Drywall	210B Unisex	833	SF	7	10+ years			
	Walls - Plaster/Drywall	210B Unisex	20	SF	6	10+ years			
	Walls - Plaster/Drywall	210B Unisex	4	SF	5	1-2 years	Damaged wall		
	Water Closet	210B Unisex	2	ĒΑ	7	10+ years			
	Accessories	Auditorium Lobby	254	SF	7	6-10 years	Under renovation		
	Ceiling - Plaster/Drywall	Auditorium Lobby	254	SF	6	6-10 years	Under renovation		
	Doors - Wood Doors inclu hw	Auditorium Lobby	1	EA	6	6-10 years	Under renovation		
	Floor - Tile Ceramic/ Porcelain	Auditorium Lobby	254	SF	6	6-10 years	Under renovation		
	Floor Drain	Auditorium Lobby	1	EA	7	6-10 years	Under renovation		
	Lavatory	Auditorium Lobby	2	EA	6	6-10 years	Under renovation		
	Lighting - Pendent/Surface	Auditorium Lobby	4	EA	6	6-10 years	Under renovation		
	Partitions	Auditorium Lobby	2	EA	7	6-10 years	Under renovation		
	Urinals	Auditorium Lobby	3	EA	6	6-10 years	Under renovation		
	Walls - Concrete Block	Auditorium Lobby	320	SF	6	10+ years	Under renovation		
	Water Closet	Auditorium Lobby Auditorium Lobby	2	EA	6	6-10 years	Under renovation		
	Accessories	Auditorium Lobby Auditorium Lobby	254	SF	7	6-10 years	Under Renovation		
				SF					
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	Auditorium Lobby	254	SF EA	6	10+ years	Under renovation		
	Floor - Tile Ceramic/ Porcelain	Auditorium Lobby Auditorium Lobby	1 254	SF	6 6	6-10 years	Under renovation		
				SF EA		6-10 years	Under renovation		
	Lavatory	Auditorium Lobby	2		6	6-10 years	Under renovation		
	Lighting - Pendent/Surface	Auditorium Lobby	•	EΑ	6	6-10 years	Under renovation		
	Partitions	Auditorium Lobby	4	EA	7	6-10 years	Under renovation		
	Walls - Concrete Block	Auditorium Lobby	320	SF	7	10+ years	Under renovation		
	Water Closet	Auditorium Lobby	4	EA	7	6-10 years	Under renovation		
	Accessories	Basement Unisex Service	498	SF	7	6-10 years			
	0 111	Locker/Toilet Room	077	0=	•	0.40			
	Ceiling - Plaster/Drywall	Basement Unisex Service	275	SF	6	6-10 years			
	.	Locker/Toilet Room			_				
	Ceiling - Plaster/Drywall	Basement Unisex Service	223	SF	6	6-10 years			
		Locker/Toilet Room							
	Doors - Steel Doors incl hw	Basement Unisex Service	1	EA	6	6-10 years			
		Locker/Toilet Room							
	Doors - Wood Doors inclu hw	Basement Unisex Service	1	EA	6	6-10 years			
		Locker/Toilet Room							
	Floor - Tile Ceramic/ Porcelain	Basement Unisex Service	498	SF	6	6-10 years			
		Locker/Toilet Room							



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Basement Unisex Service Locker/Toilet Room	1	EA	7	6-10 years	
	Lavatory	Basement Unisex Service Locker/Toilet Room	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement Unisex Service Locker/Toilet Room	7	EA	6	6-10 years	
	Partitions	Basement Unisex Service Locker/Toilet Room	2	EA	7	6-10 years	
	Showers	Basement Unisex Service Locker/Toilet Room	1	EA	7	6-10 years	
	Student Lockers - One Tier	Basement Unisex Service Locker/Toilet Room	32	EA	6	6-10 years	
	Urinals	Basement Unisex Service Locker/Toilet Room	1	EA	4	0-1 year	Damaged urinal & pipe connections
	Walls - Concrete Block	Basement Unisex Service Locker/Toilet Room	210	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Basement Unisex Service Locker/Toilet Room	1,240	SF	6	10+ years	
	Water Closet	Basement Unisex Service Locker/Toilet Room	2	EA	6	6-10 years	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Special Program)						
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	573	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Missing tiles
	Doors - Side-lite	1st Floor	30	SF	7	10+ years	-
	Doors - Transom Window	1st Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	585	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Dislodged lens
	Marker Board	1st Floor	21	LF	7	6-10 years	· ·
	Walls - Plaster/Drywall	1st Floor	893	SF	7	10+ years	
_Classroo	om #118 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	863	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	0-1 year	Damaged tile
	Doors - Side-lite	1st Floor	60	SF	7	10+ years	-
	Doors - Transom Window	1st Floor	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	

Campus Name: Marshall HS Page : 12 of 72 Assessment Date: 10/05/2021



Catego	ry : Classroom		В	uilding	: Main		
			0		D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	27	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,052	SF	7	10+ years	
Classroo	om #212 (Store Room)						
	Casework	2nd Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	771	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Damaged tile
	Chalk Board	2nd Floor	8	LF	4	2-5 years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	779	SF	7	10+ years	
	Gas Line	2nd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	7	10+ years	
	Work Sink	2nd Floor	1,124	EA	5	1-2 years	Damaged fixtures
	WORK SILIK	2110 F1001	'	LA	5	1-2 years	Damaged lixtures
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	32	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	845	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	845	SF	7	10+ years	
	Gas Line	2nd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	5	1-2 years	Damaged fixtures
Classroo	om #216 (Office)						
Classiul	Casework	2nd Floor	14	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor		SF	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1,128			•	
			1 100	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,128	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	20	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,143	SF	7	10+ years	
Classroo	om #218 (Office)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	871	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	871	SF	7	10+ years	
			37.1	٥.	•	. o . youro	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	15	EΑ	7	10+ years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,046	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	1-2 years	Damaged wall
Classroo	om #310 (Office)						
	Casework	Attic	8	LF	7	10+ years	
	Ceiling - Lay-in	Attic	652	SF	7	10+ years	
	Ceiling - Lay-in	Attic	8	SF	5	1-2 years	Damaged tile
	Doors - Transom Window	Attic	9	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	Attic	1	ĒA	7	10+ years	
	Floor - Wood	Attic	660	SF	7	10+ years	
	Lighting - Lay-in	Attic	9	EA	7	10+ years	
	Marker Board	Attic	26	LF	7	6-10 years	
	Walls - Plaster/Drywall	Attic	1,043	SF	6	10+ years	
Classroo	om #312 (Computer Lab)						
	AC Units	Attic	1	EA	7	6-10 years	
	Ceiling - Lay-in	Attic	777	SF	7	10+ years	
	Ceiling - Lay-in	Attic	2	SF	4	0-1 year	Missing tile
	Doors - Transom Window	Attic	9	SF	7	10+ years	Wildowig tild
	Doors - Wood Doors inclu hw	Attic	1	EA	7	10+ years	
	Floor - Tile	Attic	779	SF	7	10+ years	
	Lighting - Lay-in	Attic	12	EA	7	10+ years	
	Marker Board	Attic	21	LF	7	6-10 years	
	Walls - Plaster/Drywall	Attic	1,124	SF	6	10+ years	
Classroo	om #314 (Science Lab Level 3)						
	Casework	Attic	23	LF	7	10+ years	
	Ceiling - Lay-in	Attic	845	SF	7	10+ years	
	Doors - Transom Window	Attic	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Attic	2	EA	7	10+ years	
	Eye Wash Station	Attic	1	EA	7	10+ years	
	Floor - Tile	Attic	845	SF	7	10+ years	
	Gas Line	Attic	1	EA	7	10+ years	
	Lighting - Lay-in	Attic	15	EA	7	•	
	Marker Board	Attic	10	LF	7	10+ years 6-10 years	
	Walls - Plaster/Drywall	Attic	1,090	SF	7		
	Work Sink	Attic	1,090	EA	7	10+ years 10+ years	
Classroo	om #316 (Computer Lab)						
	Casework	Attic	8	LF	7	10+ years	
	Ceiling - Lay-in	Attic	1,128	SF	7	10+ years	
	Jenning - Lay-III	Auc	1,120	OI.	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Attic	2	EΑ	7	10+ years	
	Floor - Tile	Attic	1,128	SF	7	10+ years	
	Lighting - Lay-in	Attic	18	EA	7	10+ years	
	Marker Board	Attic	16	LF	7	6-10 years	
	Storage/ Closet	Attic	56	SF	7	10+ years	
	Storage/ Closet	Attic	8	SF	5	1-2 years	Dislodged lens
	Walls - Plaster/Drywall	Attic	1,046	SF	7	10+ years	
	Walls - Plaster/Drywall	Attic	8	SF	5	1-2 years	Damaged wall
	Work Sink	Attic	2	EA	7	10+ years	
Classroc	om #318 (Computer Lab)						
	AC Units	Attic	1	EA	7	6-10 years	
	Casework	Attic	8	LF	7	10+ years	
	Ceiling - Lay-in	Attic	871	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Attic	2	EΑ	7	10+ years	
	Floor - Wood	Attic	871	SF	7	10+ years	
	Lighting - Lay-in	Attic	12	EA	7	10+ years	
	Marker Board	Attic	36	LF	7	6-10 years	
	Walls - Plaster/Drywall	Attic	1,052	SF	7	10+ years	
	Wireless System	Attic	1	EA	7	10+ years	
Catogo	ry · Interior		D	uildina	. Main		

Category : Interior **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	item - Type	Location	Qualitity	CON	Mank	Replacement	Comments
Comaoi	Ceiling - Plaster/Drywall	171 - Auditorium	78	SF	7	10+ years	
	Floor - Asphalt Floor	171 - Auditorium	78	SF	7	10+ years	
	Lighting - Pendent/Surface	171 - Auditorium	1	ĒΑ	7	10+ years	
	Stairs - Concrete Stairs	171 - Auditorium	24	LF	7	10+ years	
	Walls - Masonry	171 - Auditorium	494	SF	7	10+ years	
	Ceiling - Plaster/Drywall	175 (on plan) Assembly Hall Behind Stage	876	SF	7	10+ years	
	Doors - Wood Doors include hw	175 (on plan) Assembly Hall Behind Stage	2	EA	7	10+ years	
	Floor - Asphalt Floor	175 (on plan) Assembly Hall Behind Stage	876	SF	7	10+ years	
	Lighting - Pendent/Surface	175 (on plan) Assembly Hall Behind Stage	4	EA	7	10+ years	
	Stairs - Concrete Stairs	175 (on plan) Assembly Hall Behind Stage	32	LF	7	10+ years	
	Walls - Plaster/Drywall	175 (on plan) Assembly Hall Behind Stage	1,870	SF	7	10+ years	
	Ceiling - Plaster/Drywall	176 - Assembly Hall Basement	312	SF	7	10+ years	
	Doors - Wood Doors include hw	176 - Assembly Hall Basement	2	EA	7	10+ years	



Catego	ry : Interior		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Asphalt Floor	176 - Assembly Hall Basement	312	SF	7	10+ years				
	Lighting - Pendent/Surface	176 - Assembly Hall Basement	2	EA	7	10+ years				
	Stairs - Concrete Stairs	176 - Assembly Hall Basement	42	LF	7	10+ years				
	Walls - Plaster/Drywall	176 - Assembly Hall Basement	1,650	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor Main	858	SF	7	10+ years				
	Floor - Tile/Sheet	1st Floor Main	844	SF	7	10+ years				
	Floor - Tile/Sheet	1st Floor Main	12	SF	5	1-2 years	Damaged baseboards			
	Floor - Tile/Sheet	1st Floor Main	2	SF	4	0-1 year	Damaged tile			
	Lighting - Lay-in	1st Floor Main	8	EA	7	6-10 years				
	Walls - Plaster/Drywall	1st Floor Main	616	SF	6	6-10 years				
	Ceiling - Lay-in	2nd Floor Main	1,461	SF	7	10+ years	5			
	Ceiling - Lay-in	2nd Floor Main	35	SF	4	0-1 year	Damaged tiles			
	Doors - Wood Doors include hw	2nd Floor Main	2	EA	7	10+ years				
	Floor - Tile/Sheet	2nd Floor Main	1,496	SF	7	10+ years				
	Lighting - Lay-in	2nd Floor Main	18	EA	7	6-10 years				
	Student Lockers - One Tier	2nd Floor Main	68	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor Main	1,621	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor Main	20	SF	6	1-2 years				
	Walls - Structural Glazed Tile	2nd Floor Main	904	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor Main and Balcony Lobby- Assembly	1,496	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor Main and Balcony Lobby- Assembly	1,500	SF	7	10+ years				
	Doors - Wood Doors include hw	3rd Floor Main and Balcony Lobby- Assembly	2	EA	7	10+ years				
	Doors - Wood Doors include hw	3rd Floor Main and Balcony Lobby- Assembly	12	EA	7	10+ years				
	Floor - Tile/Sheet	3rd Floor Main and Balcony Lobby- Assembly	1,496	SF	7	10+ years				
	Floor - Wood	3rd Floor Main and Balcony Lobby- Assembly	1,500	SF	7	10+ years				
	Lighting - Lay-in	3rd Floor Main and Balcony Lobby- Assembly	16	EA	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor Main and Balcony Lobby- Assembly	16	EA	7	10+ years				
	Student Lockers - One Tier	3rd Floor Main and Balcony Lobby- Assembly	71	EA	7	10+ years				
	Walls - Masonry	3rd Floor Main and Balcony Lobby- Assembly	904	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor Main and Balcony Lobby- Assembly	1,700	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor Main and Balcony Lobby- Assembly	2,545	SF	7	10+ years				
	Ceiling - Plaster/Drywall	Assembly Hall Lobby (floor plans rm.	1,458	SF	7	10+ years	Under renovation			



Catego	ry : Interior		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors include hw	165) Assembly Hall Lobby (floor plans rm. 165)	12	EA	7	10+ years	Under renovation
	Doors - Wood Doors include hw	Assembly Hall Lobby (floor plans rm. 165)	8	EA	7	10+ years	Under renovation
	Drinking Fountains - Single Fountain	Assembly Hall Lobby (floor plans rm. 165)	1	EA	7	10+ years	Under renovation
	Floor - Tile Ceramic/ Porcelain	Assembly Hall Lobby (floor plans rm. 165)	1,458	SF	7	10+ years	Under renovation
	Lighting - Pendent/Surface	Assembly Hall Lobby (floor plans rm. 165)	10	EA	7	10+ years	Under renovation
	Walls - Plaster/Drywall	Assembly Hall Lobby (floor plans rm. 165)	2,400	SF	7	10+ years	Under renovation
	Ceiling - Plaster/Drywall	Assembly Hall Vestibule (floor plan rm. 162)	900	SF	7	10+ years	Under renovation
	Floor - Tile Ceramic/ Porcelain	Assembly Hall Vestibule (floor plan rm. 162)	900	SF	7	10+ years	Under renovation
	Lighting - Pendent/Surface	Assembly Hall Vestibule (floor plan rm. 162)	6	EA	7	10+ years	Under renovation
	Walls - Plaster/Drywall	Assembly Hall Vestibule (floor plan rm. 162)	532	SF	7	10+ years	Under renovation
	Walls - Plaster/Drywall	Assembly Hall Vestibule (floor plan rm. 162)	952	SF	7	10+ years	Under renovation
	Ceiling - Lay-in	Attic E/W	718	SF	7	10+ years	
	Doors - Transom Window	Attic E/W	4	SF	7	10+ years	
	Doors - Wood Doors include hw	Attic E/W	2	EA	7	10+ years	
	Floor - Tile/Sheet	Attic E/W	718	SF	7	10+ years	
	Lighting - Lay-in	Attic E/W	12	EA	7	10+ years	
	Student Lockers - One Tier	Attic E/W	38	EA	7	6-10 years	
	Walls - Plaster/Drywall	Attic E/W	1,965	SF	7	10+ years	
	Ceiling - Lay-in	Attic South	883	SF	7	10+ years	
	Doors - Steel Doors incl hw	Attic South	2	EA	7	10+ years	
	Doors - Transom Window	Attic South	4	SF	7	10+ years	
	Floor - Tile/Sheet	Attic South	883	SF	7	10+ years	
	Lighting - Lay-in	Attic South	14	EA	7	10+ years	
	Student Lockers - One Tier	Attic South	33	EA	7	6-10 years	
	Walls - Plaster/Drywall	Attic South	1,774	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Balcony - Second floor-Assembly	480	SF	7	10+ years	
	Floor - Asphalt Floor	Balcony - Second floor-Assembly	480	SF	7	10+ years	
	Lighting - Pendent/Surface	Balcony - Second floor-Assembly	3	EA	7	10+ years	
	Stairs - Concrete Stairs	Balcony - Second floor-Assembly	12	LF	7	10+ years	
	Walls - Plaster/Drywall	Balcony - Second floor-Assembly	960	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement Gym Vestibule	42	SF	7	10+ years	
	Floor - Concrete	Basement Gym Vestibule	42	SF	7	10+ years	



Catego	Category : Interior		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs - Concrete Stairs	Basement Gym Vestibule	21	LF	7	10+ years			
	Walls - Structural Glazed Tile	Basement Gym Vestibule	144	SF	7	10+ years			
	Ceiling - Exposed	Basement corridor by Boiler and	350	SF	7	10+ years			
		Gymnasium							
	Ceiling - Plaster/Drywall	Basement corridor by Boiler and	726	SF	7	10+ years			
		Gymnasium							
	Doors - Wood Doors include hw	Basement corridor by Boiler and	2	EA	7	10+ years			
		Gymnasium							
	Floor - Asphalt Floor	Basement corridor by Boiler and	1,066	SF	6	10+ years			
		Gymnasium							
	Floor - Asphalt Floor	Basement corridor by Boiler and	10	SF	5	1-2 years	Water damage		
		Gymnasium							
	Lighting - Pendent/Surface	Basement corridor by Boiler and	5	EA	7	10+ years			
		Gymnasium							
	Walls - Masonry	Basement corridor by Boiler and	772	SF	7	10+ years			
		Gymnasium							
	Walls - Masonry	Basement corridor by Boiler and	4	SF	5	1-2 years	Spalling		
		Gymnasium							
	Walls - Structural Glazed Tile	Basement corridor by Boiler and	1,100	SF	7	10+ years			
		Gymnasium							
	Ceiling - Plaster/Drywall	Upper Balcony 4th Floor- aAssembly	585	SF	7	10+ years			
	Doors - Wood Doors include hw	Upper Balcony 4th Floor- aAssembly	4	EA	7	10+ years			
	Floor - Asphalt Floor	Upper Balcony 4th Floor- aAssembly	585	SF	7	10+ years			
	Lighting - Pendent/Surface	Upper Balcony 4th Floor- aAssembly	4	EA	7	10+ years			
	Walls - Plaster/Drywall	Upper Balcony 4th Floor- aAssembly	1,430	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Vestibule #12	84	SF	7	6-10 years			
	Doors - Side-lite	Vestibule #12	28	SF	7	6-10 years			
	Doors - Wood Doors include hw	Vestibule #12	4	EA	6	6-10 years			
	Floor - Asphalt Floor	Vestibule #12	84	SF	7	6-10 years			
	Walls - Plaster/Drywall	Vestibule #12	132	SF	6	10+ years			
Stairs									
	Ceiling - Exposed	#8	511	SF	7	10+ years			
	Ceiling - Lay-in	#8	1,044	SF	7	10+ years			
	Ceiling - Lay-in	#8	36	SF	4	0-1 year			
	Ceiling - Plaster/Drywall	#8	225	SF	7	10+ years			
	Floor - Epoxy/ Painted	#8	1,812	SF	7	10+ years			
	Floor - Epoxy/ Painted	#8	4	SF	4	1-2 years	Damaged		
	Handrails	#8	134	LF	7	10+ years	ŭ		
	Handrails	#8	12	LF	5	2-5 years	Hand rail support resumed to wall		
	Lighting - Pendent/Surface	#8	17	EA	7	10+ years	••		
	Stairs - Asphalt	#8	511	LF	7	10+ years			
	Walls - Plaster/Drywall	#8	4,320	SF	7	10+ years			
	Ceiling - Exposed	165.1 - Balcony Stairs Assembly	456	SF	7	10+ years			
		•				·			



Catego	ry : Interior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	a	Hall			_		
	Ceiling - Plaster/Drywall	165.1 - Balcony Stairs Assembly	937	SF	7	10+ years	
	Floor - Asphalt	Hall 165.1 - Balcony Stairs Assembly	937	SF	7	10+ years	
	ricor riophan	Hall	00.	O.	•	.o. youro	
	Floor - Tile Ceramic/ Porcelain	165.1 - Balcony Stairs Assembly	72	SF	7	10+ years	
		Hall					
	Handrails	165.1 - Balcony Stairs Assembly Hall	220	LF	7	10+ years	
	Lighting - Pendent/Surface	165.1 - Balcony Stairs Assembly Hall	6	EA	7	10+ years	
	Stairs - Asphalt	165.1 - Balcony Stairs Assembly	546	LF	7	10+ years	
	•	Hall				,	
	Walls - Plaster/Drywall	165.1 - Balcony Stairs Assembly	2,795	SF	7	10+ years	
	- ··· - ·	Hall			_		
	Ceiling - Exposed	165.2 - Balcony Stairs Assembly Hall	456	SF	7	10+ years	
	Ceiling - Plaster/Drywall	165.2 - Balcony Stairs Assembly	937	SF	7	10+ years	
	Coming Thation/Drywan	Hall	001	O.	•	101 youro	
	Floor - Asphalt	165.2 - Balcony Stairs Assembly	937	SF	7	10+ years	
		Hall					
	Floor - Tile Ceramic/ Porcelain	165.2 - Balcony Stairs Assembly	72	SF	7	10+ years	
	l londroile	Hall	220		7	10	
	Handrails	165.2 - Balcony Stairs Assembly Hall	220	LF	7	10+ years	
	Lighting - Pendent/Surface	165.2 - Balcony Stairs Assembly	6	EA	7	10+ years	
	3 . 3	Hall				,	
	Stairs - Asphalt	165.2 - Balcony Stairs Assembly	546	LF	7	10+ years	
		Hall					
	Walls - Plaster/Drywall	165.2 - Balcony Stairs Assembly	2,795	SF	7	10+ years	
		Hall					



Category : Exterior **Building: Addition**

Calegor	y . Exterior			ununig	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group		Location	Quantity	OOM	Railk	Replacement	Comments
_Entrance							
	Entrance Control - Audio and Video	1 - Main South	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	1 - Main South	3	EA	6	6-10 years	
	Exterior Doors - Side lite	1 - Main South	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main South	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	1 - Main South	40	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	1 - Main South	8	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	10 - North and OVH	2	EA	6	6-10 years	
	Exterior Doors - Overhead Rolling/ Garage	10 - North and OVH	1	EA	6	6-10 years	Steel Frame - Rusted at Bottom West
	Door						
	Exterior Doors - Transom Lite	10 - North and OVH	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	10 - North and OVH	18	LF	5	1-2 years	Weather Exposure - Cracked Stone
	Exterior Doors - Exterior Steel Door	12 - Courtyard	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	12 - Courtyard	2	EA	6	6-10 years	
	Ramps - Concrete	12 - Courtyard	8	LF	4	1-2 years	Ramp Masonry Substrate- Significant
	·	•				-	Damage/Deteriorated
	Exterior Doors - Exterior Steel Door	12a - Courtyard Basement	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	12a - Courtyard Basement	20	LF	3	0-1 year	Significant Damage: Failed, Cracked
		•				•	Broken Concrete - Aggregate
							Exposed/Trip Hazard
	Exterior Stairs - Concrete	12a - Courtyard Basement	80	LF	3	0-1 year	Do Significant Damage.
	Stair Handrail - Steel_Stair Handrail	12a - Courtyard Basement	34	LF	5	2-5 years	Paint
	Exterior Doors - Exterior Steel Door	13 - Courtyard	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	13 - Courtyard	8	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	14 - Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	14 - Courtyard	1	EA	7	10+ years	
	Exterior Stairs - Concrete	14 - Courtyard	30	LF	5	2-5 years	Concrete - Significant Damage at
					•	,	Edges
	Exterior Doors - Exterior Steel Door	2 - East	3	EA	6	6-10 years	900
	Exterior Doors - Side lite	2 - East	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 - East	4	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	2 - East	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	25 (16) - South	3	EA	6	6-10 years	
	Exterior Doors - Side lite	25 (16) - South	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	25 (16) - South	2	EA	6	6-10 years	
	Exterior Stairs - Stone	25 (16) - South	50	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	26 - Fire Escape 2nd Flr	1	EA	7	10+ years	See Fire Escape South Photos
	Exterior Stairs - Concrete	26 - Fire Escape 2nd Fir	3	LF	7	10+ years	Do.
	Exterior Doors - Exterior Steel Door	27 - Fire Escape 3rd Flr	1	EA	7	10+ years	See Fire Escape South Facade for
	EVICTION DOOLS - EVICTION SIGGI DOOL	ZI - I lie Locape olu Fil	ı	LA	,	TOT YEARS	Photo
	Exterior Stairs - Concrete	27 - Fire Escape 3rd Flr	3	LF	7	10+ years	Do.
				EA		•	DO.
	Exterior Doors - Exterior Steel Door Exterior Doors - Side lite	3 - East 3 - East	2 2	EA EA	6 6	6-10 years	
	EVICUOI DO012 - SIDE IIIE	3 - East	2	EA	Ü	10+ years	



Catego	ry : Exterior	Building : Addition					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	3 - East	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	3 - East	8	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	4 - East	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	4 - East	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	4 - East	4	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	5 - East	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	5 - East	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	5 - East	4	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	6 - East	2	EA	6	6-10 years	
	Exterior Doors - Side lite	6 - East	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6 - East	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	6 - East	10	LF	6	10+ years	
	Entrance Control - Audio and Video	7 - North	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	7 - North	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7 - North	2	EΑ	6	6-10 years	-
	Ramp Handrail - Steel_Ramp Handrail	7 - North	45	LF . –	5	2-5 years	Rust - Scrape/Paint
	Ramps - Concrete	7 - North	21	LF	6	10+ years	
	Entrance Control - Audio and Video	8 - North	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	8 - North	3	EA	6	6-10 years	
	Exterior Doors - Side lite	8 - North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	8 - North	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	8 - North	60	LF	6	10+ years	5 1
	Power Door Operator and Controls	8 - North	1	EΑ	4	6-10 years	Disrepair- Significant Damage
	Ramp Handrail - Steel_Ramp Handrail	8 - North	150	LF . –	5	6-10 years	0: " . 5
	Ramps - Concrete	8 - North	75	LF . –	5	1-2 years	Significant Damage
	Stair Handrail - Steel_Stair Handrail	8 - North	15	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	9 - North	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	9 - North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	9 - North	2	EA	6	6-10 years	O
	Exterior Stairs - Concrete	9 - North	36	LF	4	1-2 years	Significant Damage
_Fire Esca	ana						
	Fire Escape	South Façade	60	LF	6	6-10 years	
			00	<u></u> .	ū	2 . 2 , 202	
Foundati							
	Foundation - Masonry	Entire Building	1,843	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	286,322	SF	7	10+ years	
Lighting							
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	16	EA	7	10+ years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	6-10 years	
	Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted	Entire Building Entire Building		EA	7	10+ years	
	Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted		14 17	EA EA	<i>7</i> 6		
	Exterior Lighting - wall Mounted	Entire Building	17	EA	О	6-10 years	



Group Roof Syst	Item - Type						
•	Item - Type					Recommend	
Roof Syst	nom Typo	Location	Quantity	UOM	Rank	Replacement	Comments
roor cyo	tem						
	Coping - Metal	1	54	LF	7	6-10 years	
	Downspouts - Exterior Downspouts	i	24	LF	7	10+ years	
	Parapet - Parapet < 16" Height	i	54	LF	7	10+ years	
	Roof - Modified Bitumen	i	320	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	i	320	SF	7	6-10 years	
	Coping - Stone	J - Center	120	LF	6	10+ years	
	Parapet - Parapet < 16" Height	J - Center	120	LF	6	10+ years	
	Roof - Modified Bitumen	J - Center	738	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	J - Center	738	SF	7	10+ years	
	Coping - Metal	K	116	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	K	116	LF	6	6-10 years	
	Roof - Modified Bitumen	K	720	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	K	720	SF	7	10+ years	
	Coping - Stone	M	229	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	M	45	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	M	229	LF	6	10+ years	
	Roof - Modified Bitumen	M	8,768	SF	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	M	8,768	SF	7	10+ years	
	Coping - Metal	N - Main East	17	LF	7	6-10 years	
	Coping - Stone	N - Main East	163	LF	6	10+ years	
	Downspouts - Exterior Downspouts	N - Main East	455	LF	6	6-10 years	
	Downspouts - Exterior Downspouts Downspouts - Interior Downspouts	N - Main East	650	LF	6	6-10 years	
	Parapet - 16" - 30" Height	N - Main East N - Main East	763	LF	6	10+ years	
	Parapet - Parapet > 30"	N - Main East	17	LF	6	•	
				SF	6	10+ years	Missing bushed and damage
	Roof - Asphalt Shingle	N - Main East	1,500		-	1-2 years	Missing, buckled and damage shingles. Active leaks
	Roof - Asphalt Shingle	N - Main East	25,095	SF	6	6-10 years	
	Roof - Modified Bitumen	N - Main East	38,366	SF	6	6-10 years	
	Roof - Modified Bitumen	N - Main East	5,000	SF	3	1-2 years	Open joints, cracks, active leaks
	Roof Structure - Steel with Clay Tile Arch	N - Main East	69,961	SF	7	10+ years	
	Coping - Metal	P	100	LF	7	10+ years	Metal Coping
	Parapet - Parapet < 16" Height	P	100	LF	7	10+ years	Metal Coping - No Parapet
	Roof - Modified Bitumen	Р	595	SF	5	6-10 years	Quantity Data Adjusted: High Roof 375 sf, Low Roof - 250 sf
	Roof Structure - Steel with Clay Tile Arch	Р	595	SF	7	10+ years	
Valls							
	Cheek-Wall - Stone	Entire Building	114	SF	6	2-5 years	
	Cheek-Wall - Stone	Entire Building	20	SF	5	1-2 years	Significant Damage in Cheek Wall - Photo in other "Cheek Wall" Asset.
	Cheek-Wall - Stone	Entire Building	12	SF	4	1-2 years	Significant Damage
	Cornice - Cast Stone	Entire Building	333	LF	6	6-10 years	Organicant Damage



Catego	ry : Exterior		В	uilding	: Addition		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cornice - Metal Projecting	Entire Building	636	LF	6	2-5 years	
	Exterior Walls - Brick	Entire Building	67,337	SF	4	2-5 years	Mortar Displaced/Missing. Air Joint
	Exterior Walls - Stone-Cast	Entire Building	10,820	SF	6	10+ years	
	Exterior Walls - Stucco	Entire Building	2,720	SF	6	6-10 years	
	Exterior Walls - Stucco	Entire Building	100	SF	4	10+ years	Cracked/Open/Exposed
/indow	S						
	Guard - Guards perforated	Entire Building	2,916	SF	6	6-10 years	
	Lintels - Brick	Entire Building	130	LF	7	10+ years	
	Lintels - Steel	Entire Building	1,894	LF	6	6-10 years	Rust
	Skylite - Glass Double-Pane	<u> </u>	626	SF	7	•	Nust
		Entire Building				10+ years	
	Skylite - Glass Single-Pane	Entire Building	630	SF	6	6-10 years	
	Windows - Decorative	Entire Building	1,844	SF	6	6-10 years	
	Windows - Louver	Entire Building	76	SF	5	2-5 years	Scrape/Paint.
	Windows - Sash Aluminum Double-pane	Entire Building	15,320	SF	6	6-10 years	
atego	ory : Electrical		В	uilding	: Additio	on	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merge	ncy System						
	Automatic Transfer Switch	Basement	2	EA	7	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	36,855	SF	6	6-10 years	Fed from generator
	Emergency A/C Power - Gym	Entire Building	19,197	SF	6	6-10 years	Fed from generator
	Emergency A/C Power - Lunchrooms	Entire Building	13,504	SF	6	6-10 years	Fed from generator
	Emergency A/C Power - Students Toilets	Entire Building	3,388	SF	6	6-10 years	Fed from generator
	Exit Signs - Corridors and Stairs	•	78	EA	6	6-10 years	r ed from generator
		Entire Building					
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	5	2-5 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	Needs LED upgrade
	Exit Signs - Lunchroom	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	2	EA	5	2-5 years	Needs new front and LED update
		Entire Building		EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Littile ballaling	5	LA			
lain Se	Stairs	Entire Building	5	LA			
lain Se	Stairs rvice Main Electrical Service - 1000 A	Basement	1	EA	6	2-5 years	
lain Se	Stairs				6	2-5 years 10+ years	

Campus Name: Marshall HS Page : 23 of 72 Assessment Date: 10/05/2021



Catego	ry : Electrical		E	Building	: Additi		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - 100 A	Entire Building	5	EΑ	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	26	EΑ	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EΑ	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	8	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	4	EA	4	2-5 years	
Catego	ry : Fire Protection		В	Building	: Additi	on	
C =====	Many Trung	Location	Overetites	ном	Donk	Recommend	Community
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarr	Fire Alarm Strobe Lights	Entire Building	286,322	SF	7	10+ years	Strobes have been installed in some
	The filam elice Lighte	Z.m.o Danamy	200,022	O.	·	ro r youro	areas. Engineer reports that fire system is not entirely functional and that much of it is outdated
	Fire Alarm_System	Entire Building	286,322	SF	4	0-1 year	Main system is out of date/failing
Catego	ry : Mechanical		Е	Building	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Basement	2	EA	5	6-10 years	
	Air Intake	Basement	2	EA	5	2-5 years	
	Auxiliaries - 8001 - 15000 cfm	Basement	2	EA	5	2-5 years	
	Return Duct Work - Masonry and Ducts-	Basement	200	LF	5	6-10 years	
	Missing or Existing Shaft Zone Dampers	Basement	17	EA	5	6-10 years	New controllers
	Air Handling Unit- Built Up- Single Zone w/	Basement	2	EA	5	6-10 years	Steam coil controller is new
	Air Tunnel- Steam Coils - 15001 - 25000 cfm	Dasement	2	EA	5	6-10 years	Steam con controller is new
	Air Intake	Basement	2	EA	5	2-5 years	
	Auxiliaries - 15001 - 25000 cfm	Basement	2	EA	5	2-5 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	9	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	200	LF	5	6-10 years	
	Zone Dampers	Basement	31	EA	5	6-10 years	Controlers in good repair
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	New valves on coils



Catego	Category : Mechanical		Building : Addition						
						Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Intake	Basement	1	EA	5	2-5 years			
	Auxiliaries - 25001 - 35000 cfm	Basement	1	EA	5	2-5 years			
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	9	EA	5	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	5	6-10 years			
	Zone Dampers	Basement	31	EA	5	6-10 years	New controlers		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - Greater than 35000 cfm	Basement	1	EA	5	6-10 years			
	Air Intake	Basement	1	EA	5	2-5 years			
	Auxiliaries - Greater than 35000 cfm	Basement	1	EA	5	2-5 years			
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	10	EA	5	6-10 years			
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	5	6-10 years	Adjusted manually		
	Zone Dampers	Basement	31	EA	5	6-10 years			
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	ΕA	5	6-10 years	Engineer reports that system works		
	Gas Heating Coils - 10 - 20 tons					, , , , , , , , , , , , , , , , , , ,	well		
Boiler Sy									
	Condensate Pump	Basement	3	EΑ	6	10+ years			
	Piping - Condensate Pipe- Steel	Basement	1,400	LF	4	2-5 years			
	Piping - Steam Pipe- Steel	Basement	1,400	LF	4	2-5 years			
	Steam Traps	Basement	162	EA	4	2-5 years	Same as above		
Heating	Devices								
	Radiators - Steam	Entire Building	63	EΑ	5	6-10 years			
	Cabinet Heaters - With Steam Coil	Entire Building	10	EA	5	6-10 years			
	Fin Tube - Steam	Entire Building	171	LF	6	10+ years			
	Unit Heater - Electric	Entire Building	2	EA	5	2-5 years			
_Tempera	ture Control								
	Pneumatic System	Entire Building	286,322	SF	4	0-1 year	System manually controlled.		
	Thermostats - Pneumatic	Entire Building	104	EA	4	0-1 year	Most do not work		
Unit Ven									
	Unit Ventilators- Floor Mounted- Steam Heating w/ DX Cooling Coil & w/ Self Contained Compressors	1st Floor	4	EA	5	2-5 years			
_Ventilation	on								
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Pool vent		

Campus Name: Marshall HS Page : 25 of 72 Assessment Date: 10/05/2021



Exchanger

John Marshall Metropolitan High School 3250 W Adams STREET, Chicago, IL 60624

the pool is operational\\n

NO.	ocnoois					3	250 W Adams STREET, Chicago, IL 60624	
Catego	ry : Mechanical		B	Building : Addition				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years		
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	6-10 years	New fan	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	7	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	6	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	5	2-5 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	5	2-5 years		
	Lab Exhaust Hood	Entire Building	2	EA	7	10+ years		
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	10+ years		
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years		
Catego	ry : Plumbing		В	Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wate	er							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years		
_Piping								
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	286,322	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	286,322	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	286,322	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	286,322	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	286,322	SF	6	10+ years		

	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	286,322	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	286,322	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	286,322	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	286,322	SF	6	10+ years	
	Sanitary Piping	Entire Building	286,322	SF	6	10+ years	
	Storm Piping	Entire Building	286,322	SF	6	10+ years	
	Vent Piping	Entire Building	286,322	SF	6	10+ years	
Pool Sys	stems						
·	Pool Drain Piping	Basement	100	LF	7	6-10 years	I am told by the building engineer that the pool is operational
	Pool Filtration System including Pump	Basement	1	EA	7	6-10 years	I am told by the building engineer that the pool is operational\\n
	Pool Hot Water Heater - Steam Heat	Basement	1	EA	6	6-10 years	I am told by the building engineer that

Page : 26 of 72 Campus Name: Marshall HS Assessment Date: 10/05/2021



Catego	ry : Plumbing		Building : A	Addition	
Group	Item - Type	Location	Quantity UOM	Recommend Rank Replacement	Comments
	Pool Supply and Return Piping	Basement	400 LF	7 6-10 years	I am told by the building engineer that the pool is operational\\n
Pumps					
·	Pumps - Ejector-Duplex	Basement	3 EA	6 6-10 years	Motor is being changed
	Pumps - Sump-Duplex	Basement	1 EA	6 6-10 years	

Category: Room **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	123 Office	97	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	123 Office	1	EA	6	6-10 years	
	Floor - Tile/Sheet	123 Office	97	SF	7	6-10 years	
	Lighting - Lay-in	123 Office	2	EA	7	6-10 years	
	Power Distribution	123 Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	123 Office	253	SF	7	6-10 years	
	Ceiling - Lay-in	123A Office	142	SF	7	6-10 years	
	Doors - Side-lite	123A Office	24	SF	7	6-10 years	
	Doors - Transom Window	123A Office	27	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	123A Office	2	EA	7	6-10 years	
	Floor - Carpet	123A Office	142	SF	6	6-10 years	
	Lighting - Lay-in	123A Office	4	EA	6	6-10 years	
	Power Distribution	123A Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	123A Office	351	SF	7	10+ years	
	Ceiling - Lay-in	123B Copy Room	177	SF	7	6-10 years	
	Doors - Steel Doors incl hw	123B Copy Room	1	EA	7	6-10 years	
	Doors - Wood Doors inclu hw	123B Copy Room	1	EA	6	6-10 years	
	Floor - Carpet	123B Copy Room	177	SF	6	6-10 years	
	Lighting - Lay-in	123B Copy Room	4	EA	6	6-10 years	
	Power Distribution	123B Copy Room	6	EA	7	6-10 years	
	Storage/ Closet	123B Copy Room	228	SF	7	10+ years	
	Walls - Plaster/Drywall	123B Copy Room	502	SF	7	10+ years	
	Work Sink	123B Copy Room	1	EA	7	6-10 years	
	AC Unit	124 Office	4	EA	7	6-10 years	
	Ceiling - Lay-in	124 Office	1,488	SF	7	6-10 years	
	Doors - Transom Window	124 Office	[′] 18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	124 Office	2	EA	6	6-10 years	
	Floor - Tile/Sheet	124 Office	1,488	SF	7	6-10 years	
	Lighting - Lay-in	124 Office	24	ĒΑ	7	6-10 years	
	Storage/ Closet	124 Office	41	SF	7	6-10 years	
	Walls - Plaster/Drywall	124 Office	1,454	SF	7	10+ years	
	Ceiling - Plaster/Drywall	124A Office	126	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	124A Office	1	ĒΑ	7	6-10 years	



Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile/Sheet	124A Office	126	SF	7	6-10 years			
	Lighting - Pendent/Surface	124A Office	2	EA	7	6-10 years			
	Power Distribution	124A Office	4	EA	7	10+ years			
	Walls - Plaster/Drywall	124A Office	459	SF	7	6-10 years			
	AC Unit	125 Main Office	2	EA	7	6-10 years			
	Ceiling - Lay-in	125 Main Office	787	SF	7	6-10 years			
	Doors - Side-lite	125 Main Office	32	SF	7	6-10 years			
	Doors - Transom Window	125 Main Office	54	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	125 Main Office	2	EA	7	6-10 years			
	Doors - Wood Doors inclu hw	125 Main Office	2	EA	7	6-10 years			
	Floor - Carpet	125 Main Office	428	SF	6	6-10 years			
	Floor - Tile/Sheet	125 Main Office	359	SF	7	6-10 years			
	Lighting - Lay-in	125 Main Office	21	EA	6	6-10 years			
	Power Distribution	125 Main Office	10	EA	7	10+ years			
	Walls - Plaster/Drywall	125 Main Office	901	SF	7	10+ years			
	AC Unit	125-1 Principal's Conference Room	1	ĒΑ	7	6-10 years			
	Ceiling - Lay-in	125-1 Principal's Conference Room	431	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	125-1 Principal's Conference Room	5	ĒΑ	7	6-10 years			
	Floor - Carpet	125-1 Principal's Conference Room	431	SF	7	6-10 years			
	Lighting - Lay-in	125-1 Principal's Conference Room	6	ĒΑ	7	6-10 years			
	Power Distribution	125-1 Principal's Conference Room	4	EA	7	10+ years			
	Storage/ Closet	125-1 Principal's Conference Room	8	SF	7	6-10 years			
	Walls - Plaster/Drywall	125-1 Principal's Conference Room	581	SF	7	10+ years			
	Work Sink	125-1 Principal's Conference Room	1	EA	7	10+ years			
	Ceiling - Lay-in	125-1A Principal's Office	214	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	125-1A Principal's Office	2	EA	7	6-10 years			
	Floor - Carpet	125-1A Principal's Office	214	SF	6	6-10 years			
	Lighting - Lay-in	125-1A Principal's Office	4	EA	6	6-10 years			
	Power Distribution	125-1A Principal's Office	6	EA	7	10+ years			
	Storage/ Closet	125-1A Principal's Office	30	SF	7	6-10 years			
	Walls - Plaster/Drywall	125-1A Principal's Office	482	SF	7	10+ years			
	AC Unit	126 Waiting Room	2	EA	7	6-10 years			
	Ceiling - Lay-in	126 Waiting Room	103	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	126 Waiting Room	103	EA	7	6-10 years			
	Floor - Wood	126 Waiting Room	103	SF	7	6-10 years			
	Lighting - Lay-in	126 Waiting Room	2	EA	7	6-10 years			
	Power Distribution	126 Waiting Room	12	EA	7	6-10 years			
	Walls - Plaster/Drywall	126 Waiting Room	320	SF	7	10+ years			
	AC Unit	126 Walting Room 126A Office -Asst Principal	320 1	EA	7	6-10 years			
	Ceiling - Lay-in	126A Office -Asst Principal	225	SF	6	6-10 years			
	Doors - Side-lite	126A Office -Asst Principal	16	SF	6	6-10 years			
	Doors - Transom Window	126A Office -Asst Principal	45	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	126A Office -Asst Principal	45 2	Sr EA	6	6-10 years 6-10 years			
	Floor - Tile/Sheet	126A Office -Asst Principal	225	SF	7	6-10 years			
	1 1001 - 1 116/311661	120A Office -Asst Fillicipal	223	3F	,	0-10 years			



Category : Room			Building : Addition						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	126A Office -Asst Principal	6	EA	7	6-10 years			
	Power Distribution	126A Office -Asst Principal	4	EA	7	10+ years			
	Walls - Plaster/Drywall	126A Office -Asst Principal	492	SF	7	10+ years			
	AC Unit	127 Attendance Office	1	EA	7	6-10 years	Working properly		
	Ceiling - Lay-in	127 Attendance Office	570	SF	7	6-10 years			
	Doors - Transom Window	127 Attendance Office	18	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	127 Attendance Office	2	EA	7	6-10 years			
	Floor - Tile/Sheet	127 Attendance Office	570	SF	7	6-10 years			
	Lighting - Lay-in	127 Attendance Office	10	EA	6	6-10 years			
	Power Distribution	127 Attendance Office	12	EA	7	10+ years			
	Walls - Plaster/Drywall	127 Attendance Office	999	SF	7	10+ years			
	Walls - Plaster/Drywall	127 Attendance Office	60	SF	6	1-2 years	Damaged wall		
	AC Unit	127A Office	1	EΑ	7	6-10 years	G		
	Ceiling - Lay-in	127A Office	157	SF	6	6-10 years			
	Doors - Transom Window	127A Office	1	SF	6	10+ years			
	Floor - Tile/Sheet	127A Office	157	SF	7	6-10 years			
	Lighting - Lay-in	127A Office	2	ĒΑ	6	6-10 years			
	Power Distribution	127A Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	127A Office	353	SF	7	10+ years			
	Ceiling - Plaster/Drywall	131-1 Conference Room	500	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	131-1 Conference Room	1	EΑ	6	6-10 years			
	Floor - Tile/Sheet	131-1 Conference Room	500	SF	7	6-10 years			
	Lighting - Pendent/Surface	131-1 Conference Room	4	EΑ	6	6-10 years			
	Power Distribution	131-1 Conference Room	10	EΑ	7	6-10 years			
	Walls - Masonry	131-1 Conference Room	891	SF	7	10+ years			
	Walls - Plaster/Drywall	131-1 Conference Room	317	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	131-1A Conference Room	352	SF	7	6-10 years			
	Doors - Steel Doors incl hw	131-1A Conference Room	2	EA	7	10+ years			
	Floor - Tile/Sheet	131-1A Conference Room	352	SF	7	6-10 years			
	Lighting - Pendent/Surface	131-1A Conference Room	4	EA	6	6-10 years			
	Power Distribution	131-1A Conference Room	4	EΑ	7	10+ years			
	Walls - Masonry	131-1A Conference Room	405	SF	7	6-10 years			
	Walls - Plaster/Drywall	131-1A Conference Room	635	SF	7	10+ years			
	Ceiling - Plaster/Drywall	133-1 Pool Office	190	SF	6	10+ years			
	Doors - Steel Doors incl hw	133-1 Pool Office	130	EA	7	6-10 years			
	Doors - Transom Window	133-1 Pool Office	9	SF	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	133-1 Pool Office	190	SF	6	6-10 years			
	Lighting - Pendent/Surface	133-1 Pool Office	130	EA	6	6-10 years			
	Power Distribution	133-1 Pool Office	2	EA	7	6-10 years			
	Walls - Masonry	133-1 Pool Office	767	SF	7	6-10 years			
	Ceiling - Splined	134 Counseling Office	740	SF	7	6-10 years			
	Doors - Transom Window	134 Counseling Office	18	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	134 Counseling Office	2	EA	7	6-10 years			
	Floor - Tile/Sheet	134 Counseling Office	740	SF	7	6-10 years			
	11001 1110/011001	10+ Counseling Office	7-10	Oi.	,	o io years			



Catego	ry : Room		Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	134 Counseling Office	12	EA	6	6-10 years		
	Power Distribution	134 Counseling Office	20	EA	7	10+ years		
	Walls - Metal Panel	134 Counseling Office	448	SF	7	6-10 years		
	Walls - Plaster/Drywall	134 Counseling Office	1,250	SF	7	6-10 years		
	AC Unit	137 Security Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	137 Security Office	376	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	137 Security Office	1	EA	7	6-10 years		
	Floor - Carpet	137 Security Office	376	SF	6	6-10 years		
	Lighting - Lay-in	137 Security Office	6	EA	7	6-10 years		
	Power Distribution	137 Security Office	10	EA	7	10+ years		
	Walls - Plaster/Drywall	137 Security Office	799	SF	7	10+ years		
	Ceiling - Lay-in	141 Police room	240	SF	7	10+ years		
	Doors - Wood Doors inclu hw	141 Police room	1	EA	7	10+ years		
	Floor - Wood	141 Police room	240	SF	6	10+ years		
	Lighting - Lay-in	141 Police room	3	EA	7	10+ years		
	Power Distribution	141 Police room	6	EA	7	10+ years		
	Walls - Plaster/Drywall	141 Police room	678	SF	7	10+ years		
	AC Unit	141A Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	141A Office	486	SF	7	6-10 years		
	Doors - Transom Window	141A Office	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	141A Office	1	EA	7	6-10 years		
	Floor - Wood	141A Office	486	SF	6	6-10 years		
	Lighting - Lay-in	141A Office	9	EA	6	6-10 years		
	Power Distribution	141A Office	6	EA	7	10+ years		
	Walls - Plaster/Drywall	141A Office	825	SF	7	10+ years		
	Ceiling - Lay-in	150 Kitchen Office	129	SF	7	10+ years		
	Doors - Side-lite	150 Kitchen Office	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	150 Kitchen Office	1	EA	7	10+ years		
	Floor - Terrazzo	150 Kitchen Office	129	SF	7	10+ years		
	Lighting - Lay-in	150 Kitchen Office	2	EA	7	10+ years		
	Power Distribution	150 Kitchen Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	150 Kitchen Office	324	SF	7	10+ years		
	AC Unit	221 Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	221 Office	716	SF	7	10+ years		
	Doors - Transom Window	221 Office	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	221 Office	1	EA	7	6-10 years		
	Floor - Wood	221 Office	716	SF	7	6-10 years		
	Lighting - Lay-in	221 Office	12	EA	7	6-10 years		
	Power Distribution	221 Office	6	EA	7	10+ years		
	Walls - Plaster/Drywall	221 Office	980	SF	7	6-10 years		
	Ceiling - Lay-in	233-3 Gym Office	237	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	233-3 Gym Office	2	ĒΑ	6	6-10 years		
	Floor - Tile	233-3 Gym Office	237	SF	6	6-10 years		
	Lighting - Lay-in	233-3 Gym Office	3	ĒΑ	6	6-10 years		
	3 - 3,		· ·		-	, ,		



Category : Room			Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	233-3 Gym Office	1	EA	6	6-10 years	
	Power Distribution	233-3 Gym Office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	233-3 Gym Office	712	SF	7	6-10 years	
	Ceiling - Lay-in	233.5 Gym Office	161	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	233.5 Gym Office	25	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	233.5 Gym Office	2	EA	6	6-10 years	
	Floor - Tile	233.5 Gym Office	186	SF	6	6-10 years	
	Lighting - Lay-in	233.5 Gym Office	3	EA	6	6-10 years	
	Power Distribution	233.5 Gym Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	233.5 Gym Office	545	SF	7	10+ years	
	Ceiling - Lay-in	235-2 Gym Office	211	SF	6	6-10 years	
	Doors - Transom Window	235-2 Gym Office	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	235-2 Gym Office	1	EA	7	6-10 years	
	Floor - Tile	235-2 Gym Office	211	SF	6	6-10 years	
	Lighting - Lay-in	235-2 Gym Office	2	ĒΑ	6	6-10 years	
	Power Distribution	235-2 Gym Office	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	235-2 Gym Office	452	SF	7	10+ years	
	Ceiling - Lay-in	235-4 Gym Office	95	SF	7	6-10 years	
	Doors - Transom Window	235-4 Gym Office	6	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	235-4 Gym Office	1	ĒΑ	7	6-10 years	
	Floor - Tile	235-4 Gym Office	95	SF	6	6-10 years	
	Lighting - Lay-in	235-4 Gym Office	1	EΑ	6	6-10 years	
	Power Distribution	235-4 Gym Office	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	235-4 Gym Office	369	SF	6	10+ years	
	AC Unit	235.1A Office in Gym Faculty	1	ĒΑ	7	6-10 years	
		Lounge	•		•	0 10 700.0	
	Ceiling - Plaster/Drywall	235.1A Office in Gym Faculty	581	SF	6	6-10 years	
	coming in action 21, main	Lounge		٠.	•	0 10 700.0	
	Doors - Wood Doors inclu hw	235.1A Office in Gym Faculty	1	EA	6	6-10 years	
	Boolo Wood Boolo Illoid IIII	Lounge	•		·	o to youro	
	Floor - Tile	235.1A Office in Gym Faculty	500	SF	7	6-10 years	
	11001 1110	Lounge	000	O.	•	o to youro	
	Floor - Tile	235.1A Office in Gym Faculty	81	SF	6	6-10 years	Quantity changed to update current
	1 loor Tile	Lounge	01	O.	O	o to years	observation
	Lighting - Pendent/Surface	235.1A Office in Gym Faculty	8	EA	6	6-10 years	observation
	Lighting - I endembounde	Lounge	O	LA	O	0-10 years	
	Lighting - Wall Mounted	235.1A Office in Gym Faculty	6	EA	6	6-10 years	
	Lighting - wall wounted	Lounge	O	LA	O	0-10 years	
	Power Distribution	235.1A Office in Gym Faculty	16	EA	7	6-10 years	
	i ower distribution	Lounge	10	LA	'	0-10 years	
	Walls - Plaster/Drywall	235.1A Office in Gym Faculty	1,359	SF	6	6-10 years	
	vvans - r iasici/Drywan	Lounge	1,309	J-	O	u- iu yeais	
	Ceiling - Lay-in	237-1 Office	197	SF	6	6-10 years	
	Doors - Transom Window	237-1 Office 237-1 Office	21	SF SF	7	•	
	Doors - Harisoni Williauw	237-1 Office	۷۱	ЭF	,	6-10 years	



Category : Room			Building : Addition					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	237-1 Office	1	EA	7	6-10 years		
	Floor - Tile	237-1 Office	197	SF	7	6-10 years		
	Lighting - Lay-in	237-1 Office	3	EA	7	6-10 years		
	Power Distribution	237-1 Office	5	EA	7	6-10 years		
	Storage/ Closet	237-1 Office	54	SF	7	6-10 years		
	Walls - Plaster/Drywall	237-1 Office	552	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor SE Teachers Lounge	218	SF	7	6-10 years		
	Doors - Transom Window	2nd Floor SE Teachers Lounge	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor SE Teachers Lounge	1	EA	6	6-10 years		
	Floor - Carpet	2nd Floor SE Teachers Lounge	218	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor SE Teachers Lounge	2	EA	7	6-10 years		
	Power Distribution	2nd Floor SE Teachers Lounge	6	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor SE Teachers Lounge	688	SF	7	6-10 years		
	Ceiling - Lay-in	330 - Teachers Lounge	218	SF	7	10+ years		
	Doors - Transom Window	330 - Teachers Lounge	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	330 - Teachers Lounge	2	EA	7	10+ years		
	Floor - Tile	330 - Teachers Lounge	218	SF	7	10+ years		
	Lighting - Lay-in	330 - Teachers Lounge	2	EA	7	10+ years		
	Power Distribution	330 - Teachers Lounge	6	EA	7	10+ years		
	Walls - Plaster/Drywall	330 - Teachers Lounge	688	SF	7	10+ years		
	AC Unit	331.1 Technology Coordinator Office	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	331.1 Technology Coordinator Office	275	SF	7	10+ years		
	Doors - Wood Doors inclu hw	331.1 Technology Coordinator Office	1	EA	7	10+ years		
	Floor - Wood	331.1 Technology Coordinator Office	275	SF	7	10+ years		
	Lighting - Pendent/Surface	331.1 Technology Coordinator Office	2	EA	7	10+ years		
	Power Distribution	331.1 Technology Coordinator Office	2	EA	7	10+ years		
	Storage/ Closet	331.1 Technology Coordinator Office	10	SF	7	10+ years		
	Walls - Plaster/Drywall	331.1 Technology Coordinator Office	810	SF	7	10+ years		
	Ceiling - Lay-in	337-1 Office	125	SF	7	6-10 years		
	Doors - Side-lite	337-1 Office	36	SF	7	6-10 years		
	Doors - Transom Window	337-1 Office	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	337-1 Office	1	EA	6	6-10 years		
	Floor - Terrazzo	337-1 Office	125	SF	7	6-10 years		
	Lighting - Lay-in	337-1 Office	2	EA	7	6-10 years		
	Power Distribution	337-1 Office	6	EA	7	6-10 years		
	Walls - Plaster/Drywall	337-1 Office	394	SF	7	10+ years		
			001	٥.	•	,		



Category : Room			Building : Addition					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	337-2 Practice Room	304	SF	7	10+ years		
	Doors - Transom Window	337-2 Practice Room	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	337-2 Practice Room	1	EA	7	10+ years		
	Floor - Tile	337-2 Practice Room	304	SF	7	10+ years		
	Lighting - Lay-in	337-2 Practice Room	6	EA	4	0-1 year		
	Power Distribution	337-2 Practice Room	2	EA	7	10+ years		
	Walls - Plaster/Drywall	337-2 Practice Room	886	SF	7	10+ years		
	Ceiling - Lay-in	337-3 Practice Room	304	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	337-3 Practice Room	1	EA	7	6-10 years		
	Floor - Tile/Sheet	337-3 Practice Room	304	SF	7	6-10 years		
	Lighting - Pendent/Surface	337-3 Practice Room	6	EA	7	6-10 years		
	Power Distribution	337-3 Practice Room	4	EA	7	6-10 years		
	Walls - Plaster/Drywall	337-3 Practice Room	886	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor West Teachers Lounge (354)	285	SF	7	6-10 years		
	Doors - Transom Window	3rd Floor West Teachers Lounge (354)	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	3rd Floor West Teachers Lounge (354)	1	EA	7	6-10 years		
	Floor - Tile	3rd Floor West Teachers Lounge (354)	285	SF	6	6-10 years		
	Lighting - Lay-in	3rd Floor West Teachers Lounge (354)	4	EA	6	6-10 years		
	Power Distribution	3rd Floor West Teachers Lounge (354)	4	EA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor West Teachers Lounge (354)	335	SF	7	6-10 years		
	Ceiling - Splined	Counselor Office 132	791	SF	7	10+ years		
	Doors - Transom Window	Counselor Office 132	2	SF	7	10+ years		
	Floor - Tile	Counselor Office 132	791	SF	7	10+ years		
	Lighting - Pendent/Surface	Counselor Office 132	12	ĒΑ	7	10+ years		
	Power Distribution	Counselor Office 132	12	EA	7	6-10 years		
	Walls - Metal Panel	Counselor Office 132	450	SF	7	6-10 years		
	Walls - Plaster/Drywall	Counselor Office 132	1,149	SF	7	10+ years		
	Ceiling - Lay-in	YMCA- H Kitchen/Lounge	90	SF	7	6-10 years		
	Doors - Steel Doors incl hw	YMCA- H Kitchen/Lounge	1	EA	7	6-10 years		
	Floor - Tile/Sheet	YMCA- H Kitchen/Lounge	90	SF	7	6-10 years		
	Lighting - Lay-in	YMCA- H Kitchen/Lounge	1	EA	7	6-10 years		
	Power Distribution	YMCA- H Kitchen/Lounge	4	EA	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	YMCA- H Kitchen/Lounge	304	SF	7	6-10 years		
	Work SInk	YMCA- H Kitchen/Lounge	1	EA	7	6-10 years		
	Ceiling - Lay-in	YMCA-Office A	203	SF	7	6-10 years		
	Doors - Side-lite	YMCA-Office A	114	SF	7	6-10 years		
	Doors - Steel Doors incl hw	YMCA-Office A	1	EA	7	6-10 years		



Category : Room		Building : Addition				· • • • • • • • • • • • • • • • • • • •	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	YMCA-Office A	39	SF	7	6-10 years	
	Floor - Carpet	YMCA-Office A	203	SF	6	6-10 years	
	Lighting - Lay-in	YMCA-Office A	2	EA	6	6-10 years	
	Power Distribution	YMCA-Office A	5	EA	7	10+ years	
	Walls - Plaster/Drywall	YMCA-Office A	308	SF	7	10+ years	
	Ceiling - Lay-in	YMCA-Office B	70	SF	7	6-10 years	
	Doors - Side-lite	YMCA-Office B	138	SF	7	6-10 years	
	Doors - Steel Doors incl hw	YMCA-Office B	1	EA	7	6-10 years	
	Doors - Transom Window	YMCA-Office B	45	SF	7	6-10 years	
	Floor - Carpet	YMCA-Office B	70	SF	7	6-10 years	
	Lighting - Lay-in	YMCA-Office B	1	EA	7	6-10 years	
	Power Distribution	YMCA-Office B	3	EA	7	10+ years	
	Walls - Plaster/Drywall	YMCA-Office B	105	SF	7	10+ years	
	Ceiling - Lay-in	YMCA-Office C	70	SF	7	6-10 years	
	Doors - Side-lite	YMCA-Office C	153	SF	7	6-10 years	
	Doors - Steel Doors incl hw	YMCA-Office C	1	EA	7	6-10 years	
	Doors - Transom Window	YMCA-Office C	50	SF	7	6-10 years	
	Floor - Carpet	YMCA-Office C	70	SF	6	6-10 years	
	Lighting - Lay-in	YMCA-Office C	1	ĒΑ	6	6-10 years	
	Power Distribution	YMCA-Office C	3	EA	7	10+ years	
	Walls - Plaster/Drywall	YMCA-Office C	85	SF	7	6-10 years	
Auditorii	um & Theater						
	AC Unit	129 Ambercrombie Room (Little Theatre on plans)	3	EA	7	6-10 years	
	Ceiling - Lay-in	129 Ambercrombie Room (Little Theatre on plans)	1,936	SF	7	10+ years	Corrected quantities
	Ceiling - Plaster/Drywall	129 Ambercrombie Room (Little Theatre on plans)	512	SF	6	10+ years	
	Doors - Side-lite	129 Ambercrombie Room (Little Theatre on plans)	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	129 Ambercrombie Room (Little Theatre on plans)	6	EA	7	10+ years	
	Floor - Wood	129 Ambercrombie Room (Little Theatre on plans)	2,448	SF	7	10+ years	Quantity changed to update current observation
	Lighting - Lay-in	129 Ambercrombie Room (Little Theatre on plans)	28	EA	7	10+ years	observation
	Lighting - Pendent/Surface	129 Ambercrombie Room (Little Theatre on plans)	2	EA	7	10+ years	
	Lighting - Wall Mounted	129 Ambercrombie Room (Little Theatre on plans)	8	EA	7	10+ years	
	Sound System	129 Ambercrombie Room (Little Theatre on plans)	1	EA	7	10+ years	
	Stage	129 Ambercrombie Room (Little	378	SF	7	10+ years	



Category : Room			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		Theatre on plans)			_	4.0			
	Stage Curtain	129 Ambercrombie Room (Little	3	EA	7	10+ years			
	Stage-Stairs - Wood	Theatre on plans) 129 Ambercrombie Room (Little	20	LF	7	10+ years			
	Stage-Stalls - Wood	Theatre on plans)	20	LI	,	10+ years			
	Stairs - Wood	129 Ambercrombie Room (Little	20	LF	7	10+ years			
	C 1	Theatre on plans)			•	.o. you.o			
	Storage/ Closet	129 Ambercrombie Room (Little	62	SF	7	10+ years			
	Ğ	Theatre on plans)				j			
	Walls - Plaster/Drywall	129 Ambercrombie Room (Little	1,916	SF	6	10+ years			
		Theatre on plans)							
	Walls - Plaster/Drywall	129 Ambercrombie Room (Little	6	SF	4	1-2 years	Damaged wall		
		Theatre on plans)							
Green H	OUSE								
OIGGIIII	Finishes	246.3	510	SF	7	6-10 years			
	Glazing	246.3	789	SF	7	6-10 years			
	Mechanical	246.3	510	SF	7	6-10 years			
	Plumbing	246.3	510	SF	7	6-10 years			
	ŭ					,			
Gymnas									
	Ceiling - Splined	231 Girls' Gym South	4,634	SF	6	6-10 years			
	Doors - Hardware	231 Girls' Gym South	1	EA	6	6-10 years			
	Doors - Wood Doors inclu hw	231 Girls' Gym South	2	EA	6	6-10 years			
	Floor - Wood	231 Girls' Gym South	4,634	SF	6	6-10 years			
	Lighting - Metal Halide/ High Pressure Sodium	231 Girls' Gym South	12	EA	6	6-10 years			
	Sound System	231 Girls' Gym South	1	EA	7	6-10 years			
	Storage/ Closet	231 Girls Gym South	234	SF	7	6-10 years			
	Walls - Plaster/Drywall	231 Girls' Gym South	1,932	SF	6	6-10 years			
	Walls - Structural Glazed Tile	231 Girls' Gym South	4,331	SF	6	6-10 years			
	Ceiling - Splined	233 Girls Gym North	4,634	SF	7	6-10 years			
	Doors - Transom Window	233 Girls Gym North	18	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	233 Girls Gym North	2	EA	7	6-10 years			
	Doors - Wood Doors inclu hw	233 Girls Gym North	4	EΑ	7	6-10 years			
	Floor - Wood	233 Girls Gym North	4,634	SF	7	6-10 years			
	Lighting - Metal Halide/ High Pressure	233 Girls Gym North	11	EA	7	6-10 years			
	Sodium	200 3110 3711 110111	• • •	_, .	•	3 10 ,0010			
	Lighting - Metal Halide/ High Pressure	233 Girls Gym North	1	EA	6	6-10 years			
	Sodium	•			-	,			
	Sound System	233 Girls Gym North	1	EA	7	6-10 years			
	Storage/Closet	233 Girls Gym North	234	SF	7	6-10 years			
	Walls - Masonry	233 Girls Gym North	4,253	SF	6	10+ years			
	Walls - Plaster/Drywall	233 Girls Gym North	1,932	SF	6	10+ years			



Category : Room			Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	233-1 Weight Rom	1,178	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	233-1 Weight Rom	1	EA	6	6-10 years	
	Floor - Sport Flooring	233-1 Weight Rom	1,178	SF	7	6-10 years	
	Lighting - Pendent/Surface	233-1 Weight Rom	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	233-1 Weight Rom	1,605	SF	7	10+ years	
	Bleacher Seating	235 Boys Gym	250	EA	7	10+ years	
	Ceiling - Plaster/Drywall	235 Boys Gym	8,500	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	235 Boys Gym	196	SF	6	6-10 years	
	Doors - Transom Window	235 Boys Gym	12	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	235 Boys Gym	7	EA	7	6-10 years	
	Floor - Wood	235 Boys Gym	8,696	SF	7	6-10 years	
	Lighting - Metal Halide/ High Pressure Sodium	235 Boys Gym	24	EA	6	6-10 years	
	Lighting - Pendent/Surface	235 Boys Gym	3	EΑ	6	6-10 years	
	Scoreboards	235 Boys Gym	1	EΑ	7	10+ years	
	Sound System	235 Boys Gym	1	EA	7	10+ years	
	Storage/ Closet	235 Boys Gym	80	SF	7	6-10 years	
	Walls - Plaster/Drywall	235 Boys Gym	2,040	SF	7	10+ years	
	Walls - Structural Glazed Tile	235 Boys Gym	5,740	SF	7	6-10 years	
	Ceiling - Splined	235-1 Wrestling Gym	1,085	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	235-1 Wrestling Gym	1	EA	7	6-10 years	
	Floor - Wood	235-1 Wrestling Gym	1,085	SF	7	6-10 years	
	Lighting - Pendent/Surface	235-1 Wrestling Gym	6	EA	6	6-10 years	
	Walls - Structural Glazed Tile	235-1 Wrestling Gym	1,197	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	146 Kitchen	1,051	SF	7	10+ years	
	Doors - Transom Window	146 Kitchen	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	146 Kitchen	4	EA	7	10+ years	
	Floor - Terrazzo	146 Kitchen	1,101	SF	7	10+ years	
	Lighting - Pendent/Surface	146 Kitchen	12	EA	7	10+ years	
	Storage/ Closet	146 Kitchen	150	SF	7	10+ years	
	Storage/ Closet	146 Kitchen	184	SF	7	10+ years	
	Storage/ Closet	146 Kitchen	16	SF	5	1-2 years	
	Walls - Masonry	146 Kitchen	1,514	SF	7	10+ years	
	Ceiling - Plaster/Drywall	146A Prep Room	283	SF	7	10+ years	
	Doors - Transom Window	146A Prep Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	146A Prep Room	1	EA	7	10+ years	
	Floor - Terrazzo	146A Prep Room	275	SF	7	10+ years	
	Floor - Terrazzo	146A Prep Room	8	SF	5	1-2 years	
	Lighting - Pendent/Surface	146A Prep Room	4	EA	7	10+ years	
	Walls - Masonry	146A Prep Room	921	SF	7	10+ years	
	Ceiling - Plaster/Drywall	148 Dishwashing room	390	SF	7	10+ years	
	Doors - Wood Doors inclu hw	148 Dishwashing room	3	EA	7	10+ years	



Category : Room			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Terrazzo	148 Dishwashing room	382	SF	7	10+ years			
	Floor - Terrazzo	148 Dishwashing room	8	SF	5	1-2 years			
	Lighting - Pendent/Surface	148 Dishwashing room	8	EA	7	10+ years			
	Walls - Masonry	148 Dishwashing room	941	SF	7	10+ years			
	Walls - Masonry	148 Dishwashing room	1	SF	4	0-1 year			
Library									
•	AC Unit	227/229 - Library West & East	3	EA	7	6-10 years			
	Casework	227/229 - Library West & East	532	LF	6	6-10 years			
	Ceiling - Lay-in	227/229 - Library West & East	3,326	SF	6	6-10 years			
	Ceiling - Lay-in	227/229 - Library West & East	10	SF	4	1-2 years	Damaged tiles		
	Doors - Transom Window	227/229 - Library West & East	27	SF	7	6-10 years	Damagea tiles		
	Doors - Wood Doors inclu hw	227/229 - Library West & East	2	EA	7	6-10 years			
	Floor - Carpet	227/229 - Library West & East	3,336	SF	6	6-10 years			
	Lighting - Lay-in	227/229 - Library West & East		EA	6	•			
			92			6-10 years			
	Walls - Plaster/Drywall	227/229 - Library West & East	2,599	SF	7	10+ years	5		
	Walls - Plaster/Drywall	227/229 - Library West & East	100	SF	4	1-2 years	Damaged wall		
Locker/S	Shower Room								
	Accessories	131 Girls' Locker Room	235	SF	7	6-10 years			
	Benches, ped mounted	131 Girls' Locker Room	56	LF	6	6-10 years			
	Benches, ped mounted	131 Girls' Locker Room	41	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	131 Girls' Locker Room	4,904	SF	7	6-10 years			
	Doors - Transom Window	131 Girls' Locker Room	54	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	131 Girls' Locker Room	7	EA	6	6-10 years			
	Floor - Terrazzo	131 Girls' Locker Room	84	SF	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	131 Girls' Locker Room	4,820	SF	6	6-10 years			
	Floor Drain	131 Girls' Locker Room	25	ĒΑ	7	6-10 years			
	Floor Drain	131 Girls' Locker Room	1	EΑ	7	6-10 years			
	Hand Dryer	131 Girls' Locker Room	8	EA	7	6-10 years			
	Lavatory	131 Girls' Locker Room	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	131 Girls' Locker Room	58	EA	7	6-10 years			
	Lighting - Pendent/Surface	131 Girls' Locker Room	6	EA	7				
	• •					6-10 years			
	Lighting - Wall Mounted	131 Girls' Locker Room	2	EΑ	7	6-10 years			
	Lighting - Wall Mounted	131 Girls' Locker Room	3	EΑ	7	6-10 years			
	Partitions	131 Girls' Locker Room	53	EA	7	6-10 years			
	Showers	131 Girls' Locker Room	48	EA	7	6-10 years			
	Student Lockers - Two Tier	131 Girls' Locker Room	212	EA	6	6-10 years			
	Walls - Concrete Block	131 Girls' Locker Room	985	SF	7	10+ years			
	Walls - Masonry	131 Girls' Locker Room	5,898	SF	7	10+ years			
	Walls - Plaster/Drywall	131 Girls' Locker Room	745	SF	7	6-10 years			
	Water Closet	131 Girls' Locker Room	6	EA	6	6-10 years			
	Accessories	135 Boys' Locker Room	280	SF	7	6-10 years			
		135 Boys' Locker Room	120	LF	7				



Category : Room			Building : Addition						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	135 Boys' Locker Room	4,558	SF	7	6-10 years			
	Doors - Steel Doors incl hw	135 Boys' Locker Room	12	EΑ	6	6-10 years			
	Doors - Transom Window	135 Boys' Locker Room	36	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	135 Boys' Locker Room	3	EA	6	6-10 years			
	Floor - Terrazzo	135 Boys' Locker Room	72	SF	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	135 Boys' Locker Room	4,486	SF	5	2-5 years			
	Floor Drain	135 Boys' Locker Room	4	EA	7	6-10 years			
	Lavatory	135 Boys' Locker Room	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	135 Boys' Locker Room	24	EA	7	6-10 years			
	Lighting - Pendent/Surface	135 Boys' Locker Room	31	EA	7	6-10 years			
	Partitions	135 Boys' Locker Room	2	EA	7	6-10 years			
	Showers	135 Boys' Locker Room	11	EA	7	6-10 years			
	Showers	135 Boys' Locker Room	1	EA	5	2-5 years			
	Student Lockers - One Tier	135 Boys' Locker Room	50	EA	7	6-10 vears			
	Student Lockers - Two Tier	135 Boys' Locker Room	354	EA	7	6-10 years			
	Urinals	135 Boys' Locker Room	3	EA	6	6-10 years			
	Walls - Concrete Block	135 Boys' Locker Room	4,496	SF	7	10+ years			
	Walls - Masonry	135 Boys' Locker Room	3,064	SF	7	10+ years			
	Water Closet	135 Boys' Locker Room	2	EΑ	7	6-10 years			
	Accessories	146-1 Kitchen Staff	126	SF	7	10+ years			
	Ceiling - Plaster/Drywall	146-1 Kitchen Staff	126	SF	7	10+ years			
	Doors - Wood Doors inclu hw	146-1 Kitchen Staff	1	EA	7	10+ years			
	Floor - Tile/Sheet	146-1 Kitchen Staff	126	SF	7	10+ years			
	Lighting - Pendent/Surface	146-1 Kitchen Staff	1	EA	7	10+ years			
	Student Lockers - One Tier	146-1 Kitchen Staff	12	EΑ	7	10+ years			
	Walls - Plaster/Drywall	146-1 Kitchen Staff	550	SF	7	10+ years			
	Wallo Hadiol/21/Wall	rio i rittoriori Stari	000	0.	•	io. youro			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	138 Cafeteria	5,630	SF	7	10+ years			
	Ceiling - Lay-in	138 Cafeteria	20	SF	4	0-1 year			
	Doors - Wood Doors inclu hw	138 Cafeteria	4	EA	7	10+ years			
	Floor - Terrazzo	138 Cafeteria	5,578	SF	7	10+ years			
	Floor - Terrazzo	138 Cafeteria	72	SF	5	1-2 years			
	Lighting - Lay-in	138 Cafeteria	28	EA	7	10+ years			
	Walls - Masonry	138 Cafeteria	1,794	SF	7	10+ years			
	Walls - Plaster/Drywall	138 Cafeteria	1,251	SF	7	10+ years			
	Ceiling - Lay-in	140 Serving	2,800	SF	7	10+ years			
	Doors - Wood Doors inclu hw	140 Serving	, 4	EA	7	10+ years			
	Floor - Terrazzo	140 Serving	2,696	SF	7	10+ years			
	Floor - Terrazzo	140 Serving	84	SF	5	1-2 years			
	Floor - Terrazzo	140 Serving	20	SF	4	0-1 year			
	Lighting - Lay-in	140 Serving	20	EA	7	10+ years			
	Serving Line	140 Serving	70	LF	7	10+ years			
	Serving Line	140 Serving	10	LF	5	1-2 years	Various damage at serving line		
					ŭ	,	Tama an administration in the second		



Catego	ry : Room	Building : Addition						
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Masonry	140 Serving	1,200	SF	7	10+ years		
	Walls - Plaster/Drywall	140 Serving	700	SF	7	10+ years		
	Ceiling - Lay-in	142 Cafeteria	3,608	SF	7	10+ years		
	Doors - Wood Doors inclu hw	142 Cafeteria	2	EA	7	10+ years		
	Floor - Terrazzo	142 Cafeteria	3,544	SF	7	10+ years		
	Floor - Terrazzo	142 Cafeteria	16	SF	5	1-2 years		
	Floor - Terrazzo	142 Cafeteria	48	SF	4	0-1 year		
	Lighting - Lay-in	142 Cafeteria	17	EA	7	10+ years		
	Walls - Masonry	142 Cafeteria	1,464	SF	7	10+ years		
	Walls - Plaster/Drywall	142 Cafeteria	1,026	SF	7	10+ years		
	Ceiling - Lay-in	144 Teacher Lunchroom	1,056	SF	7	10+ years		
	Doors - Wood Doors inclu hw	144 Teacher Lunchroom	2	ĒΑ	7	10+ years		
	Floor - Terrazzo	144 Teacher Lunchroom	1,032	SF	7	10+ years		
	Floor - Terrazzo	144 Teacher Lunchroom	24	SF	5	1-2 years		
	Lighting - Pendent/Surface	144 Teacher Lunchroom	6	EA	7	10+ years		
	Walls - Masonry	144 Teacher Lunchroom	464	SF	7	10+ years		
	Walls - Plaster/Drywall	144 Teacher Lunchroom	927	SF	7	10+ years		
	Walls - Flaster/Drywall	144 Teacher Eurichioom	321	Oi	,	10+ years		
DF_IDI								
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years		
	Finishes	2nd Floor	265	SF	7	6-10 years	No damage observed	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	3	
chani	cal/ Service Rooms							
CHAILII	Janitor's Closet	1st Floor	126	SF	7	6-10 years		
	Janitor's Closet	1st Floor	119	SF	7	6-10 years		
	Mechanical/ Service Rooms	1st Floor	52	SF	7	•		
				SF SF	7	6-10 years		
	Storage Room	1st Floor	256			6-10 years		
	Storage Room	1st Floor	513	SF	7	6-10 years		
	Storage Room	1st Floor	92	SF	7	6-10 years	Not accessible. Dean Lane only person with a key, on vacation	
	Janitor's Closet	2nd FL Jan Cl @ SE Stairs	66	SF	5	10+ years	percent mand hey, on racation	
	Janitor's Closet	2nd FL NE 240-1	40	SF	7	10+ years		
	Janitor's Closet	2nd FL NE 248.2	60	SF	7	6-10 years		
	Janitor's Closet	3rd Floor	30	SF	7	,		
				SF SF		6-10 years		
	Janitor's Closet	3rd Floor	40		7	6-10 years		
	Mechanical/ Service Rooms	Basement	5,844	SF	7	6-10 years		
	Janitor's Closet	Corridor Norh by Boys Restroom 248.2	59	SF	5	6-10 years		
ol & N	atatorium							
	Accessories	133	1,124	SF	7	10+ years		



Catego	Category : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	133	4,298	SF	7	10+ years	
	Ceiling - Lay-in	133	40	SF	4	0-1 year	Water damaged
	Ceiling - Lay-in	133	26	SF	4	0-1 year	Broken
	Ceiling - Plaster/Drywall	133	168	SF	7	10+ years	
	Doors - Steel Doors incl hw	133	6	EA	7	10+ years	
	Doors - Transom Window	133	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	133	2	EA	7	10+ years	
	Floor - Epoxy/ Painted	133	2,372	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	133	17	EA	7	10+ years	
	Lighting - Pendent/Surface	133	3	EA	7	10+ years	
	Lighting - Wall Mounted	133	4	EA	7	10+ years	
	Pool Basin	133	2,160	SF	7	10+ years	
	Pool Deck	133	1,124	SF	7	10+ years	
	Pool Deck Drains	133	10	EA	7	10+ years	
	Walls - Concrete Block	133	560	SF	7	10+ years	
	Walls - Masonry	133	3,018	SF	7	10+ years	
	Walls - Plaster/Drywall	133	372	SF	7	10+ years	
	Walls - Flaster/Drywall	133	512	Oi.	,	10+ years	
Prep Ro	om						
	Casework	244-1	31	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	244-1	123	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	244-1	1	EA	7	6-10 years	
	Floor - Tile/Sheet	244-1	123	SF	7	6-10 years	
	Lighting - Pendent/Surface	244-1	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	244-1	435	SF	7	10+ years	
	Casework	244-2	40	LF	7	6-10 years	
	Ceiling - Lay-in	244-2	228	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	244-2	1	EA	7	6-10 years	
	Floor - Tile/Sheet	244-2	228	SF	7	6-10 years	
	Lighting - Pendent/Surface	244-2	3	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	244-2	500	SF	7	6-10 years	
	Walls - Plaster/Drywall	244-2	120	SF	6	6-10 years	
	Ceiling - Lay-in	246.1 Lab Prep	364	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	246.1 Lab Prep	1	EA	7	6-10 years	
	Floor - Tile	246.1 Lab Prep	364	SF	6	6-10 years	
	Lighting - Lay-in	246.1 Lab Prep	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	246.1 Lab Prep	760	SF	7	10+ years	
	Work Sink	246.1 Lab Prep	2	EA	7	6-10 years	
	Casework	344-1 Prep Room East	37	LF	7	<u>-</u>	
				SF		6-10 years	
	Ceiling - Plaster/Drywall	344-1 Prep Room East	123		6	6-10 years	
	Doors - Wood Doors inclu hw	344-1 Prep Room East	1	EA	7	6-10 years	
	Floor - Tile	344-1 Prep Room East	123	SF	6	6-10 years	
	Lighting - Pendent/Surface	344-1 Prep Room East	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	344-1 Prep Room East	393	SF	7	10+ years	



Group Item - Type Location Quantity UOM Rank Replacement Comments Work Sink 344-1 Prep Room East 1 EA 7 6-10 years Casework 344-2 West 33 LF 7 6-10 years Ceiling - Lay-in 344-2 West 162 SF 7 6-10 years Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years Walls - Plaster/Drywall 344-2 West 521 SF 7 10+ years	
Work Sink 344-1 Prep Room East 1 EA 7 6-10 years Casework 344-2 West 33 LF 7 6-10 years Ceiling - Lay-in 344-2 West 162 SF 7 6-10 years Doors - Wood Doors inclu hw 344-2 West 1 EA 7 6-10 years Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Casework 344-2 West 33 LF 7 6-10 years Ceiling - Lay-in 344-2 West 162 SF 7 6-10 years Doors - Wood Doors inclu hw 344-2 West 1 EA 7 6-10 years Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Ceiling - Lay-in 344-2 West 162 SF 7 6-10 years Doors - Wood Doors inclu hw 344-2 West 1 EA 7 6-10 years Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Doors - Wood Doors inclu hw 344-2 West 1 EA 7 6-10 years Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Floor - Tile 344-2 West 162 SF 7 6-10 years Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Lighting - Lay-in 344-2 West 4 EA 7 6-10 years	
Walls - Plaster/Drywall 344-2 West 521 SF 7 10+ vears	
Work Sink 344-2 West 1 EA 7 6-10 years	
Casework 348-1 37 LF 7 6-10 years	
Ceiling - Plaster/Drywall 348-1 123 SF 7 10+ years	
Doors - Wood Doors inclu hw 348-1 1 EA 7 6-10 years	
Floor - Tile/Sheet 348-1 123 SF 7 6-10 years	
Lighting - Pendent/Surface 348-1 3 EA 6 6-10 years	
Walls - Plaster/Drywall 348-1 393 SF 7 10+ years	
Casework 348-2 33 LF 7 6-10 years	
Ceiling - Plaster/Drywall 348-2 162 SF 6 6-10 years	
Doors - Wood Doors inclu hw 348-2 1 EA 7 6-10 years	
Floor - Tile/Sheet 348-2 162 SF 7 6-10 years	
Lighting - Lay-in 348-2 16 EA 7 6-10 years	
Walls - Plaster/Drywall 348-2 521 SF 7 10+ years	
Restroom	
Accessories 125 Principal's Toilet 37 SF 7 6-10 years	
Ceiling - Plaster/Drywall 125 Principal's Toilet 37 SF 6 6-10 years	
Doors - Wood Doors inclu hw 125 Principal's Toilet 3 EA 6 6-10 years	
Floor - Carpet 125 Principal's Toilet 25 SF 6 6-10 years	
Floor - Tile Ceramic/ Porcelain 125 Principal's Toilet 12 SF 6 6-10 years	
Lavatory 125 Principal's Toilet 1 EA 6 6-10 years	
Lighting - Pendent/Surface 125 Principal's Toilet 2 EA 7 6-10 years	
Lighting - Wall Mounted 125 Principal's Toilet 1 EA 6 6-10 years	
Showers 125 Principal's Toilet 1 EA 7 6-10 years	
Walls - Plaster/Drywall 125 Principal's Toilet 270 SF 7 10+ years	
Water Closet 125 Principal's Toilet 1 EA 7 6-10 years	
Accessories 128 South Mens 232 SF 7 6-10 years	
Ceiling - Lay-in 128 South Mens 232 SF 7 6-10 years	
Doors - Transom Window 128 South Mens 9 SF 7 6-10 years	
Doors - Wood Doors inclu hw 128 South Mens 1 EA 6 6-10 years	
Floor - Tile Ceramic/ Porcelain 128 South Mens 232 SF 7 6-10 years	
Lavatory 128 South Mens 2 EA 7 6-10 years	
Lighting - Lay-in 128 South Mens 5 EA 7 6-10 years	
Partitions 128 South Mens 2 EA 7 6-10 years	
Urinals 128 South Mens 2 EA 7 6-10 years	
Walls - Plaster/Drywall 128 South Mens 662 SF 6 10+ years	
Water Closet 128 South Mens 2 EA 7 6-10 years	
120 COUNT MONO	



Catego	ry : Room		Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Accessories	130A Womens in Faculty Lounge	106	SF	7	10+ years				
	Ceiling - Lay-in	130A Womens in Faculty Lounge	92	SF	7	10+ years				
	Ceiling - Lay-in	130A Womens in Faculty Lounge	14	SF	4	0-1 year	Water Damage			
	Ceiling - Plaster/Drywall	130A Womens in Faculty Lounge	47	SF	7	10+ years				
	Doors - Transom Window	130A Womens in Faculty Lounge	18	SF	7	10+ years				
	Doors - Wood Doors inclu hw	130A Womens in Faculty Lounge	2	EA	7	10+ years				
	Floor - Tile	130A Womens in Faculty Lounge	153	SF	7	10+ years				
	Lavatory	130A Womens in Faculty Lounge	2	EA	7	10+ years				
	Lighting - Lay-in	130A Womens in Faculty Lounge	2	EA	7	10+ years				
	Lighting - Pendent/Surface	130A Womens in Faculty Lounge	1	EA	7	10+ years				
	Partitions	130A Womens in Faculty Lounge	2	EA	7	10+ years				
	Walls - Plaster/Drywall	130A Womens in Faculty Lounge	575	SF	7	10+ years				
	Water Closet	130A Womens in Faculty Lounge	2	EA	7	10+ years				
	Accessories	146-1 Kitchen Unisex	59	SF	7	10+ years				
	Ceiling - Plaster/Drywall	146-1 Kitchen Unisex	59	SF	7	10+ years				
	Doors - Wood Doors inclu hw	146-1 Kitchen Unisex	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	146-1 Kitchen Unisex	57	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	146-1 Kitchen Unisex	2	SF	4	0-1 year	Missing tiles			
	Lavatory	146-1 Kitchen Unisex	1	EA	7	10+ years	o			
	Lighting - Pendent/Surface	146-1 Kitchen Unisex	1	EA	7	10+ years				
	Partitions	146-1 Kitchen Unisex	2	EA	7	10+ years				
	Walls - Plaster/Drywall	146-1 Kitchen Unisex	305	SF	6	10+ years				
	Water Closet	146-1 Kitchen Unisex	1	EA	7	10+ years				
	Water Closet	146-1 Kitchen Unisex	1	EA	6	10+ years				
	Accessories	1st Floor NE	283	SF	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor NE	283	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor NE	281	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor NE	2	SF	4	0-1 year	Damaged floor			
	Floor Drain	1st Floor NE	1	ĒΑ	7	10+ years				
	Hand Dryer	1st Floor NE	1	EA	7	6-10 years				
	Lavatory	1st Floor NE	4	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor NE	4	EA	7	10+ years				
	Partitions	1st Floor NE	4	EA	7	10+ years				
	Urinals	1st Floor NE	8	EA	7	10+ years				
	Walls - Concrete Block	1st Floor NE	885	SF	6	10+ years				
	Water Closet	1st Floor NE	4	ĒΑ	7	10+ years				
	Accessories	1st Floor SE	462	SF	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor SE	462	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor SE	460	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor SE	2	SF	4	0-1 year	Broken tiles			
	Floor Drain	1st Floor SE	1	EA	7	10+ years				
	Hand Dryer	1st Floor SE	1	EA	7	6-10 years				
	Lavatory	1st Floor SE	3	EΑ	7	10+ years				
	Lighting - Pendent/Surface	1st Floor SE	3	EA	7	10+ years				
	3 - 3		· ·		-	,				



Category : Room			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor SE	1	EA	5	1-2 years		
	Partitions	1st Floor SE	10	EA	7	10+ years		
	Walls - Concrete Block	1st Floor SE	1,115	SF	7	10+ years		
	Water Closet	1st Floor SE	10	EA	7	10+ years		
	Accessories	233-3A Toilet Room in Gym Office	110	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	233-3A Toilet Room in Gym Office	110	SF	7	10+ years		
	Doors - Wood Doors inclu hw	233-3A Toilet Room in Gym Office	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	233-3A Toilet Room in Gym Office	110	SF	7	10+ years		
	Floor Drain	233-3A Toilet Room in Gym Office	1	EA	7	10+ years		
	Lavatory	233-3A Toilet Room in Gym Office	1	EA	7	10+ years		
	Lighting - Pendent/Surface	233-3A Toilet Room in Gym Office	1	EA	6	6-10 years		
	Partitions	233-3A Toilet Room in Gym Office	1	EA	7	10+ years		
	Showers	233-3A Toilet Room in Gym Office	1	EA	7	10+ years		
	Walls - Plaster/Drywall	233-3A Toilet Room in Gym Office	439	SF	7	10+ years		
	Water Closet	233-3A Toilet Room in Gym Office	1	EA	6	10+ years		
	Accessories	235-2 Faculty Office Toilet Room	84	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	235-2 Faculty Office Toilet Room	84	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	235-2 Faculty Office Toilet Room	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	235-2 Faculty Office Toilet Room	84	SF	7	6-10 years		
	Floor Drain	235-2 Faculty Office Toilet Room	1	EΑ	7	6-10 years		
	Lavatory	235-2 Faculty Office Toilet Room	1	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	235-2 Faculty Office Toilet Room	1	EA	6	6-10 years		
	Partitions	235-2 Faculty Office Toilet Room	1	EΑ	7	6-10 years	Nint in	
	Showers	235-2 Faculty Office Toilet Room	1	EΑ	5	1-2 years	Not in use	
	Urinals	235-2 Faculty Office Toilet Room	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	235-2 Faculty Office Toilet Room	460	SF	6	6-10 years		
	Water Closet	235-2 Faculty Office Toilet Room	1	EA SF	6 7	6-10 years		
	Accessories	254W - Unisex 254W - Unisex	42 42	SF SF	7 7	6-10 years		
	Ceiling - Lay-in Doors - Wood Doors inclu hw	254W - Unisex 254W - Unisex	42	SF EA	7 7	10+ years		
	Floor - Tile Ceramic/ Porcelain	254W - Unisex 254W - Unisex	42	SF	7	10+ years		
	Floor Drain	254W - Unisex	1	EA	7	10+ years 10+ years		
	Hand Dryer	254W - Unisex	1	EA	7	6-10 years		
	Lavatory	254W - Unisex	1	EA	7	10+ years		
	Lighting - Lay-in	254W - Unisex	1	EA	7	10+ years		
	Walls - Plaster/Drywall	254W - Unisex	168	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	254W - Unisex	130	SF	7	10+ years		
	Water Closet	254W - Unisex	130	EA	7	10+ years		
	Accessories	254W - Offisex 254W- Women Faculty	72	SF	7	6-10 years		
	Ceiling - Lay-in	254W- Women Faculty	48	SF	7	10+ years		
	Ceiling - Lay-in	254W- Women Faculty	24	SF	5	1-2 years	Damaged tiles	
	Doors - Wood Doors inclu hw	254W- Women Faculty	1	EA	7	10+ years	Damaged iiios	
	Floor - Tile Ceramic/ Porcelain	254W- Women Faculty	72	SF	7	10+ years		
	Lavatory	254W- Women Faculty	1	EA	7	10+ years		
		25 TT Tromon Laboury	•	_, .	•	10. 300.0		



Catego	ry : Room		Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	254W- Women Faculty	1	EA	7	10+ years				
	Partitions	254W- Women Faculty	2	EA	7	6-10 years				
	Walls - Plaster/Drywall	254W- Women Faculty	400	SF	7	10+ years				
	Walls - Plaster/Drywall	254W- Women Faculty	40	SF	6	1-2 years	Damaged wall			
	Water Closet	254W- Women Faculty	2	EA	7	10+ years				
	Accessories	2nd Floor NE	231	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor NE	231	SF	7	6-10 years				
	Doors - Transom Window	2nd Floor NE	18	SF	7	6-10 years				
	Doors - Wood Doors inclu hw	2nd Floor NE	2	EA	7	6-10 years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor NE	231	SF	6	6-10 years				
	Floor Drain	2nd Floor NE	1	EA	7	6-10 years				
	Hand Dryer	2nd Floor NE	1	EA	7	6-10 years				
	Lavatory	2nd Floor NE	4	EA	6	6-10 years				
	Lighting - Pendent/Surface	2nd Floor NE	4	EA	6	6-10 years				
	Partitions	2nd Floor NE	4	EA	7	6-10 years				
	Urinals	2nd Floor NE	8	EA	7	6-10 years				
	Walls - Concrete Block	2nd Floor NE	660	SF	6	6-10 years				
	Water Closet	2nd Floor NE	4	EA	7	6-10 years				
	Accessories	2nd Floor NW	390	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor NW	390	SF	6	10+ years				
	Doors - Transom Window	2nd Floor NW	18	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor NW	2	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor NW	390	SF	6	6-10 years				
	Floor Drain	2nd Floor NW	1	EA	7	6-10 years				
	Lavatory	2nd Floor NW	4	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor NW	4	EA	6	6-10 years				
	Partitions	2nd Floor NW	4	EA	7	6-10 years				
	Urinals	2nd Floor NW	7	EA	6	6-10 years				
	Walls - Concrete Block	2nd Floor NW	650	SF	6	6-10 years				
	Water Closet	2nd Floor NW	4	ĒΑ	6	10+ years				
	Accessories	2nd Floor SE	12	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor SE	390	SF	7	6-10 years				
	Doors - Wood Doors inclu hw	2nd Floor SE	2	ĒΑ	7	6-10 years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor SE	390	SF	6	6-10 years				
	Floor Drain	2nd Floor SE	1	EA	7	6-10 years				
	Hand Dryer	2nd Floor SE	1	EA	7	6-10 years				
	Lavatory	2nd Floor SE	4	EA	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor SE	4	EA	6	6-10 years				
	Partitions	2nd Floor SE	12	EΑ	7	6-10 years				
	Walls - Concrete Block	2nd Floor SE	650	SF	7	10+ years				
	Water Closet	2nd Floor SE	12	EA	7	10+ years	Quantity changed to update current			
	114.01 010001	2110 1 1001 02	12	_/\	,	101 yours	observation			
	Accessories	2nd Floor SE Womens in Faculty	379	SF	7	10+ years	555517441011			
		Lounge	0.0	٥.	•	io. youro				
		Louingo								



Catego	ry : Room		Building : Addition						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	2nd Floor SE Womens in Faculty Lounge	379	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor SE Womens in Faculty Lounge	1	EA	6	6-10 years			
	Floor - Carpet	2nd Floor SE Womens in Faculty Lounge	94	SF	6	6-10 years			
	Floor - Tile/Sheet	2nd Floor SE Womens in Faculty Lounge	285	SF	7	10+ years	Quantity changed to update current observation		
	Lavatory	2nd Floor SE Womens in Faculty Lounge	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor SE Womens in Faculty Lounge	1	EA	6	6-10 years			
	Partitions	2nd Floor SE Womens in Faculty Lounge	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor SE Womens in Faculty Lounge	336	SF	6	6-10 years			
	Water Closet	2nd Floor SE Womens in Faculty Lounge	2	EA	7	10+ years			
	Accessories	2nd Floor West Womens (Multi User)	75	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor West Womens (Multi User)	75	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor West Womens (Multi User)	1	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor West Womens (Multi User)	75	SF	6	6-10 years			
	Lavatory	2nd Floor West Womens (Multi User)	1	EA	6	6-10 years			
	Lighting - Lay-in	2nd Floor West Womens (Multi User)	2	EA	6	6-10 years			
	Partitions	2nd Floor West Womens (Multi User)	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor West Womens (Multi User)	331	SF	5	6-10 years			
	Water Closet	2nd Floor West Womens (Multi User)	2	EA	6	6-10 years			
	Accessories	2nd Floor West Womens (Single User)	42	SF	7	6-10 years			
	Ceiling - Lay-in	2nd Floor West Womens (Single User)	42	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor West Womens (Single User)	1	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor West Womens (Single User)	42	SF	6	6-10 years			



Catego	Category : Room		В	uilding	: Addition	on	
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Hand Dryer	2nd Floor West Womens (Single User)	1	EA	7	6-10 years	
	Lavatory	2nd Floor West Womens (Single User)	1	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor West Womens (Single User)	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor West Womens (Single User)	130	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor West Womens (Single User)	135	SF	6	10+ years	
	Water Closet	2nd Floor West Womens (Single User)	1	EA	7	6-10 years	
	Accessories	3rd Floor NE	390	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NE	390	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor NE	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor NE	390	SF	6	6-10 years	
	Floor Drain	3rd Floor NE	1	EA	7	10+ years	
	Hand Dryer	3rd Floor NE	1	EA	7	6-10 years	
	Lavatory	3rd Floor NE	4	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor NE	4	EA	6	6-10 years	
	Partitions	3rd Floor NE	12	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor NE	650	SF	6	6-10 years	
	Water Closet	3rd Floor NE	12	EA	7	10+ years	
	Accessories	3rd Floor NE (336 B)	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NE (336 B)	231	SF	7	6-10 years	
	Doors - Hardware	3rd Floor NE (336 B)	2	EA	6	6-10 years	
	Doors - Transom Window	3rd Floor NE (336 B)	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor NE (336 B)	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor NE (336 B)	231	SF	6	6-10 years	
				EA			
	Floor Drain	3rd Floor NE (336 B)	1	EA	7	6-10 years	
	Hand Dryer	3rd Floor NE (336 B)	1		7	6-10 years	
	Lavatory	3rd Floor NE (336 B)	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor NE (336 B)	4	EA	7	6-10 years	
	Partitions	3rd Floor NE (336 B)	4	EA	7	6-10 years	
	Urinals	3rd Floor NE (336 B)	6	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor NE (336 B)	660	SF	6	6-10 years	
	Water Closet	3rd Floor NE (336 B)	4	EA	7	6-10 years	
	Accessories	3rd Floor NW	231	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NW	231	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor NW	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor NW	2	EΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor NW	231	SF	6	6-10 years	
	Floor Drain	3rd Floor NW	1	ĒΑ	7	6-10 years	
	Lavatory	3rd Floor NW	4	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor NW	4	EA	6	6-10 years	
	Partitions	3rd Floor NW	4	EA	7	10+ years	
	Urinals	3rd Floor NW	9	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor NW	660	SF	6	10+ years	
	Water Closet	3rd Floor NW	4	EA	6	6-10 years	
	Accessories	3rd Floor SE	390	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor SE	390	SF	7	10+ years	
	Doors - Transom Window	3rd Floor SE	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor SE	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor SE	390	SF	7	10+ years	
	Floor Drain	3rd Floor SE	1	EA	7	10+ years	
	Hand Dryer	3rd Floor SE	1	EA	7	6-10 years	
	Lavatory	3rd Floor SE	4	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor SE	4	EA	6	6-10 years	
	Partitions	3rd Floor SE	1	ΕA	7	6-10 years	
	Partitions	3rd Floor SE	11	EΑ	7	10+ years	
	Walls - Concrete Block	3rd Floor SE	650	SF	6	6-10 years	
	Water Closet	3rd Floor SE	12	EA	7	10+ years	
	Accessories	3rd Floor SE Mens in Faculty	42	SF	7	10+ years	
	710003301103	Lounge	72	Oi	,	101 years	
	Ceiling - Lay-in	3rd Floor SE Mens in Faculty	42	SF	6	6-10 years	
	Coming Lay in	Lounge	12	O.	· ·	o ro youro	
	Doors - Wood Doors inclu hw	3rd Floor SE Mens in Faculty	1	EA	7	6-10 years	
	Doors Wood Doors mold fiw	Lounge		L/\	,	o to years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor SE Mens in Faculty	42	SF	6	6-10 years	
	1 loor The Octamo, 1 orderan	Lounge	72	Oi	O	o to years	
	Lavatory	3rd Floor SE Mens in Faculty	1	EA	7	10+ years	
	Lavatory	Lounge	'	LA	,	10+ years	
	Lighting - Lay-in	3rd Floor SE Mens in Faculty	1	EA	6	6-10 years	
	Lighting - Lay-in	Lounge	'	LA	U	0-10 years	
	Partitions	3rd Floor SE Mens in Faculty	2	EA	7	6-10 years	
	Faitilions	Lounge	۷	LA	,	0-10 years	
	Walls - Plaster/Drywall	3rd Floor SE Mens in Faculty	230	SF	7	10 L Vooro	
	walls - Plaster/Drywall	The state of the s	230	SF	1	10+ years	
	Water Claset	Lounge	2	ГΛ	7	6.10 , , , , , , , ,	
	Water Closet	3rd Floor SE Mens in Faculty	2	EA	7	6-10 years	
	A	Lounge	070	0.5	7	40	
	Accessories	3rd Floor West Mens in Faculty	379	SF	7	10+ years	
	0 111	Lounge	070	0.5	_	0.40	
	Ceiling - Lay-in	3rd Floor West Mens in Faculty	379	SF	7	6-10 years	
	5	Lounge			_	0.40	
	Doors - Wood Doors inclu hw	3rd Floor West Mens in Faculty	1	EA	6	6-10 years	
	5 1 0 .	Lounge		0.5	_	0.40	
	Floor - Carpet	3rd Floor West Mens in Faculty	180	SF	6	6-10 years	
		Lounge					



	Catego	ry : Room		В	uilding	: Additi	on	-
Floor - Tile/Sheet					_			
Lavatory 3rd Floor West Mens in Faculty 2 EA 7 10+ years	Group							Comments
Layatory		Floor - Tile/Sheet		199	SF	7	10+ years	
Lounge				•		_	4.0	
Lighting - Lay-in		Lavatory		2	ΕA	7	10+ years	
Lounge Walls - Plaster/Drywall 3rd Floor West Mens in Faculty 56 SF 6 6-10 years Lounge Water Closet 3rd Floor West Mens in Faculty 2 EA 6 6-10 years Lounge Accessories Lounge YMCA E-1 Toilet 65 SF 7 10 + years Locked off, no key Ceiling - Lay-in YMCA E-1 Toilet 65 SF 6 6-10 years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 6 6-10 years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 7 10 + years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10 + years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10 + years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 2 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Ploor - Tile YMCA E-2 Toilet						_	4.0	
Partitions		Lighting - Lay-in		4	ΕA	1	10+ years	
Lounge Walls - Plaster/Drywall 3rd Floor West Mens in Faculty 56 SF 6 6-10 years Lounge Accessories Lounge Accessories YMCA E-1 Toilet 65 SF 7 10+ years Locked off, no key Doors - Wood Doors inclu hw YMCA E-1 Toilet 1 EA 6 6-10 years Locked off, no key Ploor - Tile YMCA E-1 Toilet 1 EA 6 6-10 years Locked off, no key Lighting - Lay-in YMCA E-1 Toilet 1 EA 6 6-10 years Locked off, no key Floor Drain YMCA E-1 Toilet 1 EA 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 1 EA 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 1 EA 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10+ years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Accessories YMCA E-2 Toilet 65 SF 7 6-10 years Locked off, no key Locked Doors - Wood Doors inclu hw YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting -				•		_	0.40	
Walls - Plaster/Drywall		Partitions		2	ΕA	7	6-10 years	
Lounge				=0	0=	_	0.40	
Water Closet		Walls - Plaster/Drywall		56	SF	6	6-10 years	
Lounge				_		_		
Accessories		Water Closet		2	EA	6	6-10 years	
Ceiling - Lay-in						_		
Doors - Wood Doors inclu hw								
Floor - Tile								
Floor Drain								
Lighting - Lay-in YMCA E-1 Toilet 2 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-1 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA E-2 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Floor - Tile YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Floor Drain YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 2 EA 7 6-10 years <								, ,
Walls - Concrete Block YMCA E-1 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-1 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA E-2 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Floor - Tile YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Floor Drain YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lavatory YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 6 SF 7 6-10 years Locked off, no ke								
Water Closet YMCA E-1 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA E-2 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Floor - Tile YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lavatory YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Water Closet YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7							6-10 years	Locked off, no key
Accessories			YMCA E-1 Toilet					
Ceiling - Lay-in YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA E-2 Toilet 1 EA 6 6-10 years Locked off, no key Floor - Title YMCA E-2 Toilet 70 SF 6 6-10 years Locked off, no key Floor Drain YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Water Closet YMCA B-2 Toilet 2 EA 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Floor Tille YMCA J-1 Toilet 1 EA 7 6-10 years Locked off,		Water Closet						
Doors - Wood Doors inclu hw								
Floor - Tile		Ceiling - Lay-in		70		6	6-10 years	Locked off, no key
Floor Drain		Doors - Wood Doors inclu hw	YMCA E-2 Toilet			6	6-10 years	Locked off, no key
Lavatory YMCA E-2 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Accessories YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Ploor - Tile YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lavatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Locked off, no key YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sh		Floor - Tile	YMCA E-2 Toilet	70		6	6-10 years	Locked off, no key
Lighting - Lay-in YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Cocked Soft SF 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Cocked Soft SF 7 6-10 years Locked off, no key Cocked Soft SF 7 6-10 years Locked off, no key Cocked SF SF 7 6-10 years Locked Off, no key Cocked SF SF 7 6-10 years Cocked SF SF SF 7 6-10 years SF SF SF SF 7 6-10 years SF		Floor Drain	YMCA E-2 Toilet	1	EA	7	6-10 years	Locked off, no key
Lighting - Lay-in YMCA E-2 Toilet 2 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA E-2 Toilet 265 SF 7 10+ years Locked off, no key Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 7 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA G 58 SF 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet		Lavatory	YMCA E-2 Toilet	1	EA	7	6-10 years	Locked off, no key
Walls - Concrete Block Water Closet YMCA E-2 Toilet YMCA I-1 T			YMCA E-2 Toilet	2	EA	6		
Water Closet YMCA E-2 Toilet 2 EA 7 6-10 years Locked off, no key Accessories YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile YMCA J-1 Toilet 67 SF 6 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lay-ing YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Locked off, no key <td></td> <td>Walls - Concrete Block</td> <td>YMCA E-2 Toilet</td> <td>265</td> <td>SF</td> <td>7</td> <td>10+ years</td> <td>Locked off, no key</td>		Walls - Concrete Block	YMCA E-2 Toilet	265	SF	7	10+ years	Locked off, no key
Accessories YMCA J-1 Toilet 65 SF 7 6-10 years Locked off, no key Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile YMCA J-1 Toilet 67 SF 6 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years		Water Closet	YMCA E-2 Toilet		EA	7		
Ceiling - Lay-in YMCA J-1 Toilet 70 SF 6 6-10 years Locked off, no key Doors - Wood Doors inclu hw YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Floor - Tile YMCA J-1 Toilet 67 SF 6 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Layatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 6 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years Locked off, no key TMCA-G 58 SF 7 6-10 years TM		Accessories			SF	7		· · · · · · · · · · · · · · · · · · ·
Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Floor - Tile Floor Drain		Ceiling - Lay-in		70	SF	6	6-10 years	Locked off, no key
Floor - Tile YMCA J-1 Toilet 67 SF 6 6-10 years Locked off, no key Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lavatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA-G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years				1	EA			
Floor Drain YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lavatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA-G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years		Floor - Tile		67	SF	6		
Lavatory YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA-G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years		Floor Drain						
Lighting - Lay-in YMCA J-1 Toilet 3 EA 6 6-10 years Locked off, no key Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA-G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years								
Walls - Concrete Block YMCA J-1 Toilet 345 SF 6 6-10 years Locked off, no key Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA-G 58 SF 7 6-10 years Ceiling - Lay-in YMCA-G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA-G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA-G 58 SF 7 6-10 years				3	EA			
Water Closet YMCA J-1 Toilet 1 EA 7 6-10 years Locked off, no key Accessories YMCA- G 58 SF 7 6-10 years Ceiling - Lay-in YMCA- G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA- G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA- G 58 SF 7 6-10 years								
Accessories YMCA- G 58 SF 7 6-10 years Ceiling - Lay-in YMCA- G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA- G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA- G 58 SF 7 6-10 years								
Ceiling - Lay-in YMCA- G 58 SF 6 6-10 years Doors - Steel Doors incl hw YMCA- G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA- G 58 SF 7 6-10 years								200.00 011, 110 110 1
Doors - Steel Doors incl hw YMCA- G 1 EA 6 6-10 years Floor - Tile/Sheet YMCA- G 58 SF 7 6-10 years								
Floor - Tile/Sheet YMCA- G 58 SF 7 6-10 years								
Floor Drain YMCA- G 1 FA 7 6-10 years		Floor Drain	YMCA- G	1	EA	7	6-10 years	
Lavatory YMCA- G 1 EA 6 6-10 years								
Lavatory Twon-O I Ln 0 0-10 years		Lavatory	I WOA- O	'	LA	U	o-10 years	



Category : Room			В	Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	YMCA- G	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	YMCA- G	244	SF	6	10+ years		
	Water Closet	YMCA- G	1	EA	6	6-10 years		
_								
Catego	ry : Classroom		В	uilding	: Additi			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	m #136 (Office)	Location	Quantity	OOM	IXAIIX	Replacement	Comments	
Classioo		4-4-51		Ε.Δ.	7	0.40		
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st Floor	726	SF	7	10+ years		
	Doors - Transom Window	1st Floor	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Wood	1st Floor	726	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	21	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	984	SF	7	10+ years		
Classroo	m #139 (Pre School)							
	Casework	1st Floor	29	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	817	SF	7	6-10 years		
	Floor - Carpet	1st Floor	322	SF	7	6-10 years		
	Floor - Tile	1st Floor	495	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	266	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	588	SF	7	10+ years		
	Work Sink	1st Floor	3	EA	7	6-10 years		
Classras	m #442 (Computer Leh)					·		
~ia>\$100	m #143 (Computer Lab) AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	20	LF	7	6-10 years		
	Casework Ceiling - Lay-in	1st Floor	1,468	SF	7	6-10 years		
	Doors - Steel Doors incl hw	1st Floor	1,400	EA	7	•		
	Doors - Steel Doors Inc. hw Doors - Transom Window	1st Floor	27	SF	7	6-10 years		
						6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	6-10 years		
	Floor - Carpet	1st Floor	172	SF	7	6-10 years		
	Floor - Tile	1st Floor	1,296	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years		
	Marker Board	1st Floor	5	LF	7	6-10 years		
	Storage/ Closet	1st Floor	10	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,447	SF	7	10+ years		
	Wireless System	1st Floor	1	EA	7	6-10 years		
	Work Sink	1st Floor	1	EΑ	7	6-10 years		



Catego	ry : Classroom	В	uilding	: Additi			
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #147 (Computer Lab)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	774	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	774	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	177	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
lassroo	m #147 CulArt Lab (Culinary)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,440	SF	7	10+ years	
	Culinary Exhaust Hood - Type I	1st Floor	1	EA	7	10+ years	
	Culinary Kitchen Equipment	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	1,430	SF	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	1st Floor	25	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,410	SF	7	10+ years	
	Work Sink	1st Floor	6	EA	7	10+ years	
lassroo	m #223 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	717	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Damaged tile
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
lassroo	m #224 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	952	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	28	SF	4	0-1 year	Damaged ceiling
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	-
	Floor - Wood	2nd Floor	980	SF	7	10+ years	



Category : Classroom			В	uilding			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,075	SF	7	10+ years	
lassroo	m #225 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	717	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Damaged tiles
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	g
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,026	SF	7	10+ years	
	Walls - Plaster/Drywall		1,020	SF	6	•	
	walls - Plastel/Drywall	2nd Floor	0	SF	б	10+ years	
lassroo	m #228 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	980	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	980	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,096	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #232 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
				SF		•	
	Floor - Wood	2nd Floor	725		6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	10+ years	
lassroo	m #234 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	6-10 years	
Classroc	om #236 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
		2nd Floor	1,032	SF	6		
	Walls - Plaster/Drywall	2110 F1001	1,032	SF	0	10+ years	
Classroc	om #237 (Music Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,736	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Carpet	2nd Floor	1,816	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	10+ years	
	Marker Board	2nd Floor	17	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	84	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,919	SF	6	10+ years	
Classroo	om #238 (Regular Classroom)						
CIGOOIOC	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	12	SF	7	•	
						6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board Walls - Plaster/Drywall	2nd Floor 2nd Floor	22 1,032	LF SF	7 7	6-10 years 6-10 years	
	·		,			,	
Classroc	om #241 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	



Catego	ry : Classroom		В	uildina	: Additi		230 W Adams STREET, Chicago, IL 60624
				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	725	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,026	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	4	0-1 year	Damaged wall
Classroo	om #243 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years	
Classroo	om #244 (Science Lab Level 3)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	65	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,121	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	6-10 years	
	Eye Wash Station	2nd Floor	1	EΑ	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,121	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,353	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
Classroo	om #245 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	10+ years	



Catego	ry : Classroom	В	uilding	: Additi		230 W Adams Office 1, Officego, 12 00024	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #246 (Science Lab Level 3)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	45	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,380	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Eye Wash Station	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,380	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	21	EΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,516	SF	7	10+ years	
	Work Sink	2nd Floor	3	EA	7	6-10 years	
Classroo	om #247 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years	
Classroo	om #249 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	6	10+ years	
_Classroc	om #250 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	6-10 years	
	Floor - Wood	2nd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
						•	



Category : Classroom			Building : Addition					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank		Comments	
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years		
Classro	om #251 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Wood	2nd Floor	725	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	10+ years		
	Marker Board	2nd Floor	22	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	32	SF	6	10+ years		
Classro	om #252 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years		
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years		
	Floor - Wood Doors Inclu Hw	2nd Floor 2nd Floor	725	SF	7	•		
						6-10 years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years		
Classro	om #253 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	8	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Wood	2nd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years		
Classro	om #254 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	2	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	725	SF	7	6-10 years		
	Doors - Transom Window	2nd Floor	18	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years		
	Floor - Wood	2nd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	22	LF	6	6-10 years		
	Market Board	2110 1 1001	22	LI	J	o io years		



Category : Classroom			В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Walls - Plaster/Drywall	2nd Floor	1,032	SF	7	10+ years	
Classroo	om #321 (Regular Classroom)						
Oldoorot	Casework	3rd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	
	Floor - Wood	3rd Floor	725	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	10+ years	
	wane racton by wan	614 1 1661	1,002	0.	•	ioi youro	
Classroo	om #323 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	986	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	986	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	986	SF	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	906	SF	7	10+ years	
Classroo	om #324 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	10+ years	
Clacoro	om #325 (Regular Classroom)						
CIASSIU	Casework	3rd Floor	8	LF	7	6.10 vooro	
				SF		6-10 years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	3rd Floor	498 1	SF EA	7 7	6-10 years	
		3rd Floor		SF		6-10 years	
	Floor - Tile	3rd Floor	498		7	6-10 years	
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	vvalis - Plaster/Drywall	310 F100f	840	2F	1	o-10 years	
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	840 840	SF	7	6-10 years 6-10 years	



Catego	ry : Classroom		В	uilding	: Additi		230 W Adams OTNEET, Onleago, 12 00024
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #326 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	5	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	6	6-10 years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classroo	om #327 (Science Lab Level 3)						
	Ceiling - Lay-in	3rd Floor	986	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	986	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	906	SF	7	6-10 years	
Classroo	om #328 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	6-10 years	
Classroo	om #329 (Computer Lab)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	2,697	SF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	2-5 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	-
	Floor - Wood	3rd Floor	2,697	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	39	EA	7	6-10 years	
						•	



Category : Classroom Building : Addition							
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	29	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	6	1-2 years	
	Walls - Plaster/Drywall	3rd Floor	1,464	SF	6	6-10 years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
Classroc	om #332 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7		
						6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	6-10 years	
Classroc	om #334 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
			22	LF	7	•	
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	1,032	SF	7	6-10 years 6-10 years	
21						·	
Classroc	om #336 (Regular Classroom)						
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	725	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Marker Board	3rd Floor	4	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	6	10+ years	
Classroo	om #337 (Music Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
						•	
	Ceiling - Lay-in	3rd Floor	2,467	SF	7	10+ years	\\/_t_n d_n_d_n_
	Ceiling - Lay-in	3rd Floor	74	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,077	SF	7	10+ years	



Catego	ry : Classroom	В	Building : Addition					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Floor buckling	
	Floor - Wood	3rd Floor	1,354	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	41	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	1	EA	5	1-2 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	2,040	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	4	SF	4	0-1 year	Holes in wall	
Classroo	om #338 (Regular Classroom)							
_ CIGOOI OC	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	725	SF	5	6-10 years		
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Wood	3rd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years		
	Marker Board	3rd Floor	22	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	6-10 years		
01	(1011 (A 1 B)							
Classroo	om #341 (Art Room)	0.15						
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	30	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	1,434	SF	6	6-10 years		
	Doors - Transom Window	3rd Floor	9	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years		
	Floor - Tile	3rd Floor	1,434	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years		
	Marker Board	3rd Floor	22	LF	6	6-10 years		
	Storage/ Closet	3rd Floor	360	SF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,143	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	6-10 years		
Classroo	om #342 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	715	SF	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	10	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	-	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	22	LF	7	6-10 years		
		3rd Floor	1,032	SF				



Item - Type n #343 (Regular Classroom)	Location	Quantity			Recommend	
n #343 (Regular Classroom)	Location		11014	D I-	D I	0
		Quantity	UOM	Rank	Replacement	Comments
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	22	LF	6	10+ years	
Ceiling - Lay-in	3rd Floor	905	SF	7	10+ years	
Ceiling - Lay-in	3rd Floor	8	SF	5	1-2 years	Cracked
	3rd Floor	_			10+ years	
Doors - Wood Doors inclu hw	3rd Floor	2			10+ years	
Floor - Wood	3rd Floor	913	SF		10+ years	
Lighting - Lay-in	3rd Floor	15	EA		10+ years	
Marker Board	3rd Floor	8	LF		6-10 years	
Walls - Plaster/Drywall	3rd Floor	1,010	SF	6	10+ years	
Walls - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Damaged
n #344 (Science Lab Level 3)						
,	3rd Floor	63	IF	7	6-10 years	
					•	
					•	
					•	
Work Sink	3rd Floor	3	EA	7	6-10 years	
n #345 (Pagular Classroom)						
	2rd Floor	1	ΕΛ	7	6 10 years	
				-	•	
						corrected augntity
				-	-	corrected quantity
					•	
				-	,	
					•	
					,	
		•				
Work Sink	3rd Floor	1	ΕA	1	6-10 years	
n #347 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	22	LF	6	6-10 years	
Ceiling - Lay-in	3rd Floor	903	SF	6	6-10 years	
Ceiling - Lay-in	3rd Floor	10	SF	5	1-2 years	Bowed, water damage
Doors - Transom Window	3rd Floor	9	SF	7	10+ years	•
	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Plaster/Drywall Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Gas Line Lighting - Lay-in Marker Board Walls - Plaster/Drywall Work Sink Description - Wood Word - Lay-in Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall Work Sink Description - Wood Word - Wood Word - Wood Walls - Plaster/Drywall Work Sink Description - Wood Walls - Plaster/Drywall Work Sink	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall Doors - Transom Window Doors - Transom Window Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor Marker Board Toor Marker Board Marker Board Marker Board Marker Board Marker Board Walls - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor Marker Board	Doors - Transom Window 3rd Floor 9 Doors - Wood Doors inclu hw 3rd Floor 2 Floor - Wood 3rd Floor 913 Lighting - Lay-in 3rd Floor 15 Marker Board 3rd Floor 1,010 Walls - Plaster/Drywall 3rd Floor 4 *** August - Walls - Plaster/Drywall 3rd Floor 63 Ceiling - Plaster/Drywall 3rd Floor 976 Casework 3rd Floor 976 Ceiling - Plaster/Drywall 3rd Floor 9 Doors - Wood Doors inclu hw 3rd Floor 9 Floor - Tile 3rd Floor 9 Gas Line 3rd Floor 1 Lighting - Lay-in 3rd Floor 1 Marker Board 3rd Floor 36 Walls - Plaster/Drywall 3rd Floor 1 Work Sink 3rd Floor 1 AC Units 3rd Floor 2 Casework 3rd Floor 9 Ceiling - Lay-in 3rd Floor 9	Doors - Transom Window 3rd Floor 9 SF Doors - Wood Doors inclu hw 3rd Floor 913 SF Lighting - Lay-in 3rd Floor 15 EA Marker Board 3rd Floor 8 LF Walls - Plaster/Drywall 3rd Floor 1,010 SF Walls - Plaster/Drywall 3rd Floor 4 SF 1#344 (Science Lab Level 3) 5 F F Casework 3rd Floor 976 SF Doors - Transom Window 3rd Floor 976 SF Doors - Wood Doors inclu hw 3rd Floor 9 SF Doors - Wood Doors inclu hw 3rd Floor 9 SF Gas Line 3rd Floor 1 EA Lighting - Lay-in 3rd Floor 1 EA Marker Board 3rd Floor 1 EA Walls - Plaster/Drywall 3rd Floor 1 EA Walls - Plaster/Drywall 3rd Floor 1 EA Ceiling - Lay-in 3rd Floor	Doors - Transom Window 3rd Floor 9 SF 7	Doors - Transom Window 3rd Floor 9 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 913 SF 7 10+ years Floor - Wood 3rd Floor 15 EA 7 10+ years Marker Board 3rd Floor 15 EA 7 10+ years Walls - Plaster/Drywall 3rd Floor 1,010 SF 6 10+ years Walls - Plaster/Drywall 3rd Floor 4 SF 5 1-2 years 1#344 (Science Lab Level 3) 2 2 2 4 SF 5 1-2 years 1#344 (Science Lab Level 3) 2 3rd Floor 63 LF 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor 976 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Floor 9 SF 7 6-10 years Doors - Wood Doors inclu hw 3rd Floor 9 SF 7 6-10 years Elos - Traissom Window 3rd Floor 15<



Catego	ry : Classroom		В	uilding	: Additi		230 W Adams STREET, Chicago, IL 60624
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	7	6-10 years	
	Floor - Tile	3rd Floor	913	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	212	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	100	SF	4	2-5 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
_Classroo	om #348 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	65	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,121	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	
	Eye Wash Station	3rd Floor	1	EΑ	7	6-10 years	
	Floor - Tile	3rd Floor	1,121	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,353	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroo	om #349 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	32	SF	4	2-5 years	Damaged wall
_Classroo	om #350 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	marror Board	014 1 1001	22	_,	•	o ro youro	



Catego	Category : Classroom		Building : Addition				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	32	SF	5	2-5 years	Hole in wall
Classroo	m #352 (Regular Classroom)						
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	6	6-10 years	
Classroo	m #354 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	725	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Wood	3rd Floor	725	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,032	SF	7	10+ years	
Classroo	m #Area A (Pre School)						
	Casework	1st Floor	18	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	374	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	374	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	144	SF	7	10+ years	Storefront glass partition
	Walls - Plaster/Drywall	1st Floor	384	SF	7	10+ years	Otorenoni glass partition
Classroo	m #Area B (Pre School)						
	Casework	1st Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,100	SF	7	10+ years	
	Floor - Tile	1st Floor	1,110	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	9	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	72	SF	7	10+ years	Storefront glass partition
	Walls - Plaster/Drywall	1st Floor	813	SF	7	10+ years	Glorenoni giass partition
	Work Sink	1st Floor	2	EA	7	10+ years	



Catego	ry : Classroom		Building : Addition						
Jaicgo	19 : 01033100111			ananig	. Additiv	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	om #Area C (Pre School)		quantity						
Olassioc	Casework	1st Floor	28	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,961	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1,901	EA	7	10+ years			
	Floor - Carpet	1st Floor	1,113	SF	7	10+ years			
	Floor - Tile	1st Floor	848	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years			
	Walls - Metal Panel	1st Floor	225	SF	7	10+ years	Storefront Glass Partition		
	Walls - Plaster/Drywall	1st Floor	675	SF	7	•	Storenoni Glass Farillion		
	Walls - Plaster/Drywall	151 F1001	675	SF	,	10+ years			
lassroc	om #Area D (Pre School)								
	Casework	1st Floor	20	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	1,103	SF	7	10+ years			
	Floor - Carpet	1st Floor	363	SF	7	6-10 years			
	Floor - Tile	1st Floor	740	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years			
	Walls - Masonry	1st Floor	525	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	324	SF	7	10+ years	Storefront glass partition		
	Walls - Plaster/Drywall	1st Floor	108	SF	7	10+ years	Green erri graee paramer.		
	Work Sink 1st Floor 1 EA 7 10+ years								
Catego		1st Floor				•			
Catego	Work Sink ry: Interior	1st Floor		EA uilding		•			
_		1st Floor Location				on	Comments		
roup	ry : Interior		В	uilding	: Additio	on Recommend	Comments		
roup	ry : Interior Item - Type	Location	B Quantity	uilding UOM	: Additio	Recommend Replacement	Comments		
roup	ry : Interior Item - Type Ceiling - Lay-in		Quantity	UOM SF	Rank	Recommend Replacement			
roup	ry : Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in	Location 1st Floor 1st Floor	Quantity 11,598 24	UOM SF SF	: Additio	Recommend Replacement 10+ years 1-2 years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in	Location 1st Floor	Quantity 11,598 24 54	UOM SF SF SF SF	Rank 7 5 4	Recommend Replacement 10+ years 1-2 years 0-1 year			
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite	Location 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 11,598 24 54 41	UOM SF SF SF SF SF	Rank 7 5 4 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in	Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	11,598 24 54 41 11	UOM SF SF SF SF SF EA	Rank 7 5 4 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window	Location 1st Floor	11,598 24 54 41 11 43	UOM SF SF SF SF EA SF	7 5 4 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 10+ years 10+ years 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw	Location 1st Floor	11,598 24 54 41 11 43 15	UOM SF SF SF SF EA SF EA	7 5 4 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	Location 1st Floor	11,598 24 54 41 11 43 15 6	UOM SF SF SF SF EA SF EA EA	7 5 4 7 7 7 7 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo	Location 1st Floor	Duantity 11,598 24 54 41 11 43 15 6 1,880	UOM SF SF SF SF EA SF EA SF EA SF	7 5 4 7 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years	Damaged tile Damaged tiles		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	Location 1st Floor	11,598 24 54 41 11 43 15 6 1,880 22	UOM SF SF SF SF EA SF EA SF EA SF EA	7 5 4 7 7 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years	Damaged tile		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732	UOM SF SF SF SF EA SF EA SF EA SF SF SF SF SF SF SF	7 5 4 7 7 7 7 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years	Damaged tile Damaged tiles Damaged floor		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44	UOM SF SF SF EA SF EA SF EA SF SF SF SF SF SF SF SF	7 5 4 7 7 7 7 7 7 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years 1-2 years	Damaged tile Damaged tiles Damaged floor Damaged floor		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44 10	UOM SF SF SF EA SF EA SF SF SF SF SF SF SF SF SF	7 5 4 7 7 7 7 7 7 7 7 7 5 4	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years 1-2 years 0-1 year	Damaged tile Damaged tiles Damaged floor		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44 10 123	UOM SF SF SF EA SF EA SF EA SF	7 5 4 7 7 7 7 7 7 7 7 7 5 4 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years	Damaged tile Damaged tiles Damaged floor Damaged floor		
roup	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Stairs - Terrazzo	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44 10 123 35	UOM SF SF SF EA SF EA SF	7 5 4 7 7 7 7 7 7 7 7 5 4 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years 1-2 years 10+ years 1-2 years 10+ years 10+ years 10+ years 10+ years	Damaged tile Damaged tiles Damaged floor Damaged floor		
Group	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Stairs - Terrazzo Student Lockers - One Tier	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44 10 123 35 386	UOM SF SF SF EA SF EA SF	7 5 4 7 7 7 7 7 7 7 5 4 7 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years 1-2 years 10+ years 1-2 years 10+ years 10+ years 10+ years 10+ years	Damaged tile Damaged tiles Damaged floor Damaged floor		
Catego Group Corridor	ry: Interior Item - Type Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Lay-in Stairs - Terrazzo	Location 1st Floor	B Quantity 11,598 24 54 41 11 43 15 6 1,880 22 9,732 44 10 123 35	UOM SF SF SF EA SF EA SF	7 5 4 7 7 7 7 7 7 7 7 5 4 7 7	Recommend Replacement 10+ years 1-2 years 0-1 year 10+ years 1-2 years 10+ years 1-2 years 10+ years 1-2 years 10+ years 10+ years 10+ years 10+ years	Damaged tile Damaged tiles Damaged floor Damaged floor		



Catego	gory : Interior			uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	1st Floor	2	SF	5	1-2 years	Damaged brick
	Walls - Plaster/Drywall	1st Floor	8,731	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1	SF	6	1-2 years	Damaged wall
	Ceiling - Lay-in	2nd Floor	10,944	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	48	SF	5	1-2 years	Damaged wall
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	-
	Doors - Steel Doors incl hw	2nd Floor	4	EΑ	7	10+ years	
	Doors - Transom Window	2nd Floor	58	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	6	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	1,336	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor	8	SF	5	1-2 years	Damaged floor
	Floor - Tile/Sheet	2nd Floor	9,592	SF	7	10+ years	. 9
	Floor - Tile/Sheet	2nd Floor	50	SF	5	1-2 years	Damaged floor
	Floor - Tile/Sheet	2nd Floor	6	SF	4	0-1 year	Damaged floor
	Lighting - Lay-in	2nd Floor	113	EΑ	7	10+ years	zamagea neer
	Lighting - Lay-in	2nd Floor	1	EΑ	5	1-2 years	Damaged lens
	Stairs - Terrazzo	2nd Floor	15	LF	7	10+ years	Damaged lone
	Student Lockers - One Tier	2nd Floor	635	EA	7	10+ years	
	Walls - Masonry	2nd Floor	7,505	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5,844	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	4	0-1 year	Damaged wall
	Ceiling - Lay-in	2nd Floor - Southwest (angled)	693	SF	7	10+ years	Damagea wan
	Doors - Steel Doors incl hw	2nd Floor - Southwest (angled)	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Southwest (angled)	693	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor - Southwest (angled)	8	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - Southwest (angled)	705	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor - Southwest (angled)	693	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor - Southwest (angled)	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor - Southwest (angled)	8	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor - Southwest (angled)	705	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor East corridor	3,135	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor East corridor	3,133	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor East corridor	510	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor East corridor	2,625	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor East corridor	40	SF	4	2-5 years	Damaged tile
	Lighting - Lay-in	3rd Floor East corridor	40	EA	7	10+ years	Damayeu lile
	Student Lockers - One Tier	3rd Floor East corridor	246	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor East corridor	1,435	SF	7	10+ years 10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	3rd Floor East corridor	1,700	SF	7	10+ years 10+ years	
	Ceiling - Lay-in	3rd Floor Past Corndor 3rd Floor North Corridor	6,720	SF SF	<i>7</i> 6	6-10 years	
	Floor - Terrazzo	3rd Floor North Corridor 3rd Floor North Corridor	480	SF SF	7	•	
	Floor - Tile/Sheet	3rd Floor North Corridor	6,240	SF SF	7	10+ years	
	1 1001 - Tile/Offeet	Sid i looi North Comaol	0,240	3F	,	10+ years	



Catego	ry : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	3rd Floor North Corridor	120	SF	4	2-5 years	Cracked, damaged
	Lighting - Lay-in	3rd Floor North Corridor	32	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor North Corridor	159	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor North Corridor	2,524	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor North Corridor	2,800	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor West corridor	2,220	SF	7	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor West corridor	2	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor West corridor	296	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor West corridor	1,844	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor West corridor	80	SF	4	1-2 years	Missing
	Lighting - Lay-in	3rd Floor West corridor	18	EA	7	10+ years	
	Stairs - Terrazzo	3rd Floor West corridor	10	LF	7	10+ years	
	Student Lockers - One Tier	3rd Floor West corridor	101	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor West corridor	1,602	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor West corridor	2,000	SF	7	10+ years	
	Ceiling - Lay-in	3rd floor south	8	SF	5	2-5 years	Cracked
	Ceiling - Lay-in	3rd floor south	1,910	SF	5	6-10 years	
	Drinking Fountains - Single Fountain	3rd floor south	2	EA	7	6-10 years	
	Floor - Terrazzo	3rd floor south	274	SF	7	10+ years	
	Floor - Tile/Sheet	3rd floor south	1,624	SF	7	10+ years	
	Floor - Tile/Sheet	3rd floor south	20	SF	4	2-5 years	Cracked, missing
	Lighting - Lay-in	3rd floor south	18	EA	7	6-10 years	•
	Student Lockers - One Tier	3rd floor south	91	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor south	1,522	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd floor south	1,800	SF	7	10+ years	
	Ceiling - Plaster/Drywall	First Floor Vestibules off of Corridors	317	SF	7	10+ years	
	Ceiling - Plaster/Drywall	First Floor Vestibules off of Corridors	247	SF	7	10+ years	
	Doors - Side-lite	First Floor Vestibules off of Corridors	35	SF	7	10+ years	
	Doors - Steel Doors incl hw	First Floor Vestibules off of Corridors	3	EA	7	10+ years	
	Doors - Transom Window	First Floor Vestibules off of Corridors	350	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Vestibules off of Corridors	3	EA	7	10+ years	
	Doors - Wood Doors include hw	First Floor Vestibules off of Corridors	7	EA	7	10+ years	
	Doors - Wood Doors include hw	First Floor Vestibules off of Corridors	8	EA	7	10+ years	
	Floor - Terrazzo	First Floor Vestibules off of Corridors	410	SF	7	10+ years	
	Floor - Terrazzo	First Floor Vestibules off of Corridors	92	SF	7	10+ years	
	Lighting - Pendent/Surface	First Floor Vestibules off of Corridors	2	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	First Floor Vestibules off of Corridors	8	EA	7	10+ years	
	Stairs - Terrazzo	First Floor Vestibules off of Corridors	60	LF	7	10+ years	
	Walls - Masonry	First Floor Vestibules off of Corridors	490	SF	7	10+ years	
	Walls - Plaster/Drywall	First Floor Vestibules off of Corridors	666	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Corridor	108	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Corridor	2	EA	7	10+ years	
	Doors - Transom Window	Kitchen Corridor	36	SF	7	10+ years	
	Doors - Wood Doors include hw	Kitchen Corridor	2	EA	7	10+ years	
	200.0 1100d 200.0 III0iddo 11W	. monon contact	_	_, .	•	io. youro	



Catego	ry : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete	Kitchen Corridor	108	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Corridor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Corridor	420	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Pool Vestibule	98	SF	7	10+ years	
	Floor - Terrazzo	Pool Vestibule	79	SF	7	10+ years	
	Lighting - Pendent/Surface	Pool Vestibule	1	EA	7	10+ years	
	Stairs - Terrazzo	Pool Vestibule	19	LF	7	10+ years	
	Walls - Masonry	Pool Vestibule	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Pool Vestibule	264	SF	7	10+ years	
	Ceiling - Lay-in	YMCA Corridor	349	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	YMCA Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	YMCA Corridor	349	SF	7	10+ years	
	Lighting - Lay-in	YMCA Corridor	4	EA	7	10+ years	
	Walls - Concrete Block	YMCA Corridor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	YMCA Corridor	323	SF	6	10+ years	
	Walls - Structural Glazed Tile	YMCA Corridor	323	SF	7	10+ years	Previously unassessed
	Ceiling - Lay-in	YMCA Exit #3 & #4 Vestibules	240	SF	7	10+ years	
	Doors - Steel Doors incl hw	YMCA Exit #3 & #4 Vestibules	3	ĒA	7	10+ years	
	Floor - Tile/Sheet	YMCA Exit #3 & #4 Vestibules	240	SF	7	10+ years	
	Lighting - Lay-in	YMCA Exit #3 & #4 Vestibules	2	ĒΑ	7	10+ years	
	Stairs - Concrete Stairs	YMCA Exit #3 & #4 Vestibules	76	LF	7	10+ years	
	Walls - Concrete Block	YMCA Exit #3 & #4 Vestibules	966	SF	7	10+ years	
	Ceiling - Plaster/Drywall	YMCA Exit #6 Vestibule	82	SF	7	10+ years	
	Ceiling - Plaster/Drywall	YMCA Exit #6 Vestibule	40	SF	7	10+ years	
	Doors - Wood Doors include hw	YMCA Exit #6 Vestibule	2	EA	7	10+ years	
	Floor - Terrazzo	YMCA Exit #6 Vestibule	122	SF	7	10+ years	
	Lighting - Pendent/Surface	YMCA Exit #6 Vestibule	2	EA	7	10+ years	
	Stairs - Terrazzo	YMCA Exit #6 Vestibule	30	LF	7	10+ years	
	Walls - Masonry	YMCA Exit #6 Vestibule	259	SF	7	10+ years	
	Walls - Plaster/Drywall	YMCA Exit #6 Vestibule	196	SF	7	10+ years	
	Wallo T lablel/DTyWall	TWO TEXIC NO VOOLDGIO	100	O.	•	101 youro	
Safety							
Salety	Security Cameras	Entire Facility- Main and Addition	68	EA	7	6-10 years	
	Security Carrieras	Entire Facility- Main and Addition	00	LA	,	0-10 years	
Stairs							
	Ceiling - Lay-in	No. 1 - NW	282	SF	7	10+ years	
	Ceiling - Lay-in	No. 1 - NW	8	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	No. 1 - NW	93	SF	7	10+ years	o
	Floor - Terrazzo	No. 1 - NW	238	SF	7	10+ years	
	Handrails	No. 1 - NW	136	LF	7	10+ years	
	Lighting - Lay-in	No. 1 - NW	2	EA	7	10+ years	
	Lighting - Pendent/Surface	No. 1 - NW	2	EA	7	10+ years	
	Stairs - Terrazzo	No. 1 - NW	396	LF	7	10+ years	
	Walls - Plaster/Drywall	No. 1 - NW	576	SF	7	10+ years	
	i idoton bi j irdii		0.0	٥.	•	.o. youro	



Catego	tegory : Interior			Building : Addition				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Structural Glazed Tile	No. 1 - NW	688	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 1 - NW	2	SF	5	1-2 years		
	Ceiling - Lay-in	No. 2 - NE	194	SF	7	10+ years		
	Ceiling - Plaster/Drywall	No. 2 - NE	93	SF	7	10+ years		
	Floor - Terrazzo	No. 2 - NE	238	SF	7	10+ years		
	Handrails	No. 2 - NE	136	LF	7	10+ years		
	Lighting - Lay-in	No. 2 - NE	2	EΑ	7	10+ years		
	Lighting - Pendent/Surface	No. 2 - NE	2	EA	7	10+ years		
	Stairs - Terrazzo	No. 2 - NE	395	LF	7	10+ years		
	Stairs - Terrazzo	No. 2 - NE	1	LF	5	1-2 years	Cracked	
	Walls - Plaster/Drywall	No. 2 - NE	576	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 2 - NE	690	SF	7	10+ years		
	Ceiling - Lay-in	No. 3 - East	290	SF	7	10+ years		
	Floor - Terrazzo	No. 3 - East	388	SF	7	10+ years		
	Handrails	No. 3 - East	136	LF	7	10+ years		
	Lighting - Lay-in	No. 3 - East	2	EA	7	10+ years		
	Lighting - Pendent/Surface	No. 3 - East	2	EA	7	10+ years		
	Lighting - Wall Mounted	No. 3 - East	2	EA	7	10+ years		
	Stairs - Terrazzo	No. 3 - East	396	LF	7	10+ years		
	Walls - Plaster/Drywall	No. 3 - East	456	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 3 - East	939	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 3 - East	1	SF	4	0-1 year	Missing	
	Ceiling - Lay-in	No. 4 - SE	210	SF	7	10+ years		
	Ceiling - Plaster/Drywall	No. 4 - SE	93	SF	7	10+ years		
	Floor - Terrazzo	No. 4 - SE	232	SF	7	10+ years		
	Floor - Terrazzo	No. 4 - SE	6	SF	5	1-2 years		
	Handrails	No. 4 - SE	136	LF	7	10+ years		
	Lighting - Lay-in	No. 4 - SE	2	EA	7	10+ years		
	Lighting - Pendent/Surface	No. 4 - SE	2	EA	7	10+ years		
	Stairs - Terrazzo	No. 4 - SE	396	LF	7	10+ years		
	Walls - Plaster/Drywall	No. 4 - SE	576	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 4 - SE	690	SF	7	10+ years		
	Ceiling - Plaster/Drywall	No. 5 - Boys' Gym NE	267	SF	7	10+ years		
	Ceiling - Plaster/Drywall	No. 5 - Boys' Gym NE	40	SF	6	10+ years		
	Floor - Terrazzo	No. 5 - Boys' Gym NE	290	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	No. 5 - Boys' Gym NE	170	SF	6	10+ years		
	Handrails	No. 5 - Boys' Gym NE	98	LF	7	10+ years		
	Handrails	No. 5 - Boys' Gym NE	12	LF	4	0-1 year	Missing handrails	
	Lighting - Pendent/Surface	No. 5 - Boys' Gym NE	1	EA	7	10+ years		
	Lighting - Wall Mounted	No. 5 - Boys' Gym NE	2	EA	7	10+ years		
	Stairs - Terrazzo	No. 5 - Boys' Gym NE	260	LF	7	10+ years		
	Walls - Plaster/Drywall	No. 5 - Boys' Gym NE	1,549	SF	7	10+ years		
	Walls - Structural Glazed Tile	No. 5 - Boys' Gym NE	1,933	SF	7	10+ years		
	Ceiling - Plaster/Drywall	No. 6 - Girls' Gym SE	512	SF	7	10+ years		



Catego	ry : Interior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	No. 6 - Girls' Gym SE	333	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	No. 6 - Girls' Gym SE	203	SF	6	10+ years	
	Handrails	No. 6 - Girls' Gym SE	124	LF	7	10+ years	
	Lighting - Pendent/Surface	No. 6 - Girls' Gym SE	2	EA	7	10+ years	
	Stairs - Terrazzo	No. 6 - Girls' Gym SE	221	LF	7	10+ years	
	Walls - Plaster/Drywall	No. 6 - Girls' Gym SE	342	SF	7	10+ years	
	Walls - Structural Glazed Tile	No. 6 - Girls' Gym SE	1,373	SF	7	10+ years	
	Ceiling - Lay-in	No. 7 - SW	915	SF	7	10+ years	
	Ceiling - Plaster/Drywall	No. 7 - SW	575	SF	7	10+ years	
	Floor - Terrazzo	No. 7 - SW	1,485	SF	7	10+ years	
	Handrails	No. 7 - SW	176	LF	7	10+ years	
	Lighting - Lay-in	No. 7 - SW	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	No. 7 - SW	6	EΑ	7	10+ years	
	Stairs - Terrazzo	No. 7 - SW	502	LF	7	10+ years	
	Stairs - Terrazzo	No. 7 - SW	5	LF	5	1-2 years	
	Walls - Plaster/Drywall	No. 7 - SW	2,627	SF	7	10+ years	
	Walls - Structural Glazed Tile	No. 7 - SW	2,813	SF	7	10+ years	
	Walls - Structural Glazed Tile	No. 7 - SW	6	SF	6	10+ years	
	Walls - Structural Glazed Tile	No. 7 - SW	8	SF	5	1-2 years	Cracked
	Ceiling - Plaster/Drywall	No. 7B - Kitchen	48	SF	7	10+ years	
	Floor - Concrete	No. 7B - Kitchen	12	SF	7	10+ years	
	Handrails	No. 7B - Kitchen	76	LF	7	10+ years	
	Lighting - Wall Mounted	No. 7B - Kitchen	1	EA	7	10+ years	
	Stairs - Concrete	No. 7B - Kitchen	72	LF	7	10+ years	
	Walls - Plaster/Drywall	No. 7B - Kitchen	210	SF	7	10+ years	



Category : Site Building : Site

Guicgo	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic	Curfo on Noticeal	Couldb	00.450	SF		10	Deschall Diamond mode
	Surface - Natural	South	66,456	SF	6	10+ years	Baseball Diamond needs Cleaning/Defined
	Metal Bleachers	West	360	LF	7	10+ years	Clearling/Delined
	Surface - Synthetic	West	80,452	SF	7	10+ years	
	Surface - Asphalt	West	34,152	SF	7	10+ years	
	·		,			·	
Civil/Dra	O .						
	Civil/ Drainage - Catch Basin	Entire Site	14	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	3	EA	3	2-5 years	Downpour not Observed During Downpour.
	Civil/ Drainage - Site Manhole	Entire Site	26	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	0-1 year	Drain Dysfunctional/Disrepair -
							Asphalt Covered. Roof
encing							
	Fencing - Chain Link	Entire Site	943	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	3,187	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	605	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	18	LF	5	2-5 years	Repair as Required
_andsca	pe						
	Benches	Entire Site	22	EA	7	6-10 years	
	Landscape - Grass	Entire Site	85,933	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	3,910	SF	4	0-1 year	
	Parkway trees	Entire Site	56	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	26,182	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	1,050	SF	6	10+ years	
	Trash Receptacles	Entire Site	5	EA	6	6-10 years	
Parking	Lot						
	Concrete Curbs	Site North and South	2,873	LF	7	10+ years	
	Interior Plantings	Site North and South	49	LF	7	10+ years	
	Lighting - Pole Mounted	Site North and South	4	EA	7	10+ years	
	Surface - Asphalt	Site North and South	61,818	SF	5	10+ years	Should Be De-Graded and Lowere to "2-5 Years"
	Vehicular Screening	Site North and South	530	LF	7	10+ years	
Sidewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	699	LF	6	10+ years	



John Marshall Metropolitan High School

3250 W Adams STREET, Chicago, IL 60624

Catego	ry : Site		В	uilding	: Site			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Sidewalks - Perimeter Sidewalks	Entire Site	18,103	SF	7	10+ years		
Signage								
	Flag Pole - Flag Pole	Entire Site	1	EA	5	6-10 years		
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years		

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Marshall HS Page : 70 of 72 Assessment Date: 10/05/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					. (- /				
Computer Lab	Laboratory/Shop	Attic	312	412	779	75	33	N	N
Computer Lab	Laboratory/Shop	Attic	316	416	1,128	200	88	N	N
Computer Lab	Regular Classroom	Attic	318	418	871	100	44	N	N
Office	Regular Classroom	2nd Floor	216	316A	1,128	225	99	N	N
Office	Regular Classroom	2nd Floor	218	318A	871	100	44	N	N
Office	Regular Classroom	Attic	310	410	660	114	33	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	871	100	8	Υ	N
Regular Classroom	Science Lab Level 3	2nd Floor	214	314A	845	125	55	N	N
Science Lab Level 3	Science Lab Level 3	Attic	314	414	845	125	55	N	N
Special Program	Regular Classroom	1st Floor	110	110	585	114	6	Υ	N
Store Room	Science Lab Level 3	2nd Floor	212	312B	779	75	33	N	N
Building : Addition									
Art Room	Art Room	3rd Floor	341	341	1,434	315	27	Υ	N
Computer Lab	Laboratory/Shop	1st Floor	147	151	774	128	8	Υ	N
Computer Lab	Other Instructional Use	1st Floor	143	143/145	1,468	396	24	Y	N
Computer Lab	Regular Classroom	2nd Floor	223	223	725	224	66	Y	N
Computer Lab	Regular Classroom	3rd Floor	326	326	725	224	66	N	N
Computer Lab	Regular Classroom	3rd Floor	329	329	2,697	564	48	Y	N
Culinary	Culinary	1st Floor	147 CulArt Lab	147	1,440	372	24	Y	N
Music Room	Music Room	2nd Floor	237	237	1,900	205	18	Y	N
Music Room	Regular Classroom	3rd Floor	337	337	2,541	96	48	Y	N
Office	Regular Classroom	1st Floor	136	136	726	198	12	Y	N
Pre School	Pre School	1st Floor	139	YMCA Classroom	817	105	6	Y	N
Pre School	Pre School	1st Floor	Area A	YMCA Area A	374	48	16		
Pre School	Pre School	1st Floor	Area B	YMCA Area B	1,110	120	48		
Pre School	Pre School	1st Floor	Area C	YMCA Area C	1,961	120	48		
Pre School	Pre School	1st Floor	Area D	YMCA Area D	1,103	120	48		
Regular Classroom	Art Room	3rd Floor	343	343	913	274	24	Υ	N
Regular Classroom	Art Room	3rd Floor	345	345	907	224	66	N	N
Regular Classroom	Art Room	3rd Floor	347	347	913	244	24	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	980	274	96	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	225	225	725	224	66	Υ	N





Classroom Summary

Olassicom Gammary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	228	228	980	274	96	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	232	232	725	224	66	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	234	234	725	224	66	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	236	236	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	238	238	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	241	241	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	243	243	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	245	245	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	247	247	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	249	249	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	250	250	725	224	66	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	251	251	725	224	66	N	N
Regular Classroom	Regular Classroom	2nd Floor	252	252	725	224	66	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	253	253	725	198	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	254	254	725	224	66	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	321	321	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	498	132	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	334	334	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	336	336	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	338	338	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	342	342	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	349	349	725	224	66	N	N
Regular Classroom	Regular Classroom	3rd Floor	350	350	725	224	66	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	352	352	725	204	54	Y	N
Regular Classroom	Regular Classroom	3rd Floor	354	354	725	224	66	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	244	244	1,121	385	156	Y	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	246	248	1,380	379	121	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	323	323	986	264	72	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	327	327	986	264	72	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	344	344	976	385	156	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	348	348	1,121	385	156	Y	N