

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1996	2	63,900
Campus Total			63,900

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			_			_	
	Entrance Control - Audio and Video	#1 E	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#1 E	2	EA	6	6-10 years	
	Exterior Doors - Side lite	#1 E	2	EΑ	7	10+ years	
	Exterior Doors - Side lite	#1 E	6	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#10 NW	1	EΑ	6	6-10 years	Deteriorated sealant
	Exterior Doors - Transom Lite	#10 NW	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 N	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#2 N	2	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 S	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#3 S	2	EΑ	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#3.1 S	2	EΑ	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#3.2 S	1	EΑ	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	#3.3 OHD S	1	EΑ	6	6-10 years	
	Door					-	
	Entrance Control - Audio and Video	#4 SW	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#4 SW	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#4 SW	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#5 W	1	EΑ	6	10+ years	
	Exterior Doors - Exterior FRP Door	#6 N	1	EΑ	6	6-10 years	Deteriorated sealant
	Exterior Doors - Transom Lite	#6 N	1	EA	6	10+ years	Deteriorated sealant
	Exterior Doors - Exterior FRP Door	#7 N	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#7 N	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#8 NW	1	EA	6	6-10 years	Deteriorated sealant
	Exterior Doors - Transom Lite	#8 NW	1	EA	6	6-10 years	
						•	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior FRP Door	#9 NW	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9 NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	11-Roof 7	1	EA	6	10+ years	
oundat	ion						
	Foundation - Concrete	Entire Building	1,000	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	400	SF	6	1-2 years	North and south stairs show signs o
	•	ű				,	settlement, cracking of cmu at joints
	Superstructure - Steel	Entire Building	63,500	SF	7	10+ years	,
ighting							
. g.	Exterior Lighting - Wall Mounted	Entire Building	22	EA	5	2-5 years	Old, obsolete lights, some are broke
Roof Sys	stem						
<u></u>	Coping - Metal	#2	90	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#2	10	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#2 #2	67	LF	6	10+ years	
	Roof - Modified Bitumen	#2 #2	507	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	#2 #2	507	SF	7	•	
	Concrete Topping	#2	307	SF	,	10+ years	
	Downspouts - Exterior Downspouts	#3	0	LF	6	10+ years	
	Roof - Metal	#3 #3	8 616	SF		-	
	Roof Structure - Steel / Metal Deck/	#3 #3		SF	6 7	10+ years	
	Concrete Topping	#3	616	SF	1	10+ years	
	Downspouts - Exterior Downspouts	#4	20	LF	6	10 L Vooro	
	Roof - Metal			SF		10+ years	
		#4	1,564	SF SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#4	1,564	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#5	12	LF	6	10+ years	
	Roof - Metal	#5	625	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	#5	625	SF	7	10+ years	
	Concrete Topping					•	
	Downspouts - Exterior Downspouts	#6	26	LF	6	6-10 years	
	Roof - Metal	#6	790	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	#6	790	SF	7	10+ years	
	Concrete Topping	6		•	•	. o . y ca. c	
	Coping - Metal	#7	66	LF	6	10+ years	Deteriorated sealant
	Downspouts - Interior Downspouts	#7	52	LF	6	6-10 years	
	Parapet - 16" - 30" Height	# 7	66	LF	7	10+ years	
	Roof - Modified Bitumen	#7	826	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	#7 #7	826	SF	7	10+ years	
	Concrete Topping	πι	020	JI	,	TOT years	
	•	#8	58	LF	6	10 Lyonra	
	Coping - Metal	#0	58	ᄕ	О	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	#8	26	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	#8	58	LF	6	10+ years	
	Roof - Modified Bitumen	#8	815	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#8	815	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	30	LF	6	10+ years	
	Coping - Metal	Main Roof	985	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	572	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	985	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	29,328	SF	6	6-10 years	
	Roof Hatch - Metal	Main Roof	25,526	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	29,328	SF	7	10+ years	
	Concrete Topping	Main Nooi	29,320	OI .	,	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	23,980	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	484	SF	5	10+ years	Deteriorated mortar
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Walls in the playground courtyard have open joints, broken bricks
	Exterior Walls - Brick	Entire Building	20	SF	3	0-1 year	Large crack near door seven in the playground area
	Exterior Walls - Stone-Cast	Entire Building	180	SF	6	10+ years	playground aroa
Vindows							
	Clerestory - Glass Double-Pane	Entire Building	588	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,100	SF	6	10+ years	
	Lintels - Steel	Entire Building	830	LF	7	10+ years	
	Lintels - Stone	Entire Building	9	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	725	SF	4	2-5 years	Old, worn out windows. Balancers broken, windows screwed shut for safety
	Windows - Sash Aluminum Double-pane	Entire Building	1,100	SF	4	2-5 years	Old, worn out windows. Balancers broken, windows screwed shut for safety
	Windows - Sash Aluminum Double-pane	Entire Building	450	SF	4	0-1 year	Old, worn out windows. Balancers broken, windows screwed shut for safety
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emorgon	ncy System						



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Automatic Transfer Switch	1st Floor	1	EΑ	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	30	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EΑ	6	6-10 years	
	Exit Signs - Lunchroom Security System - CCTV	Entire Building	62,000	EA SF	6 6	6-10 years	
	Security System - Corv Security System - Intrusion Detection	Entire Building Entire Building	63,900 63,900	SF SF	5	6-10 years 2-5 years	
	Emergency A/C Power - Corridors and	Entire Building Entire Building	8,925	SF	6	10+ years	
	Stairs	Entire Building	0,923	SI	O	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,724	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,270	SF	6	10+ years	
			_,			, , , , , , , , , , , , , , , , , , , ,	
Main Ser	vice						
	Independent Electrical Service for	1st Floor	1	EA	7	10+ years	For Fire
	emergency power	4 of Floor		- ^	7	40	
	Independent Electrical Service for	1st Floor	1	EA	7	10+ years	
	emergency power Main Electrical Service - 1200 A	1st Floor	1	EA	7	10+ years	
	277/480/3PH	13(1100)	1	LA	,	10+ years	
	PA System	Entire Building	63,900	SF	5	2-5 years	Interference with sound of
	.,,	g	33,333	О.	ŭ	_ 0 ,000	transformer humming into the PA
							system. Outdated wiring, no
							insulation.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EΑ	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	7	EΑ	6	10+ years	400/000
	Transformers - 277/480 - 120/240	Entire Building Entire Building	4	EA EA	6 6	10+ years	460/266
	Transformers - 277/480 - 120/240	Entire Building	I	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	63,900	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	63,900	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
Pump Ro	oom Assembly						
ипр к	Fire Pump - 25-50 hp	1st Floor	1	EA	6	6-10 years	
	·					•	



Catego	ry : Fire Protection		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Jockey Pump	1st Floor	1	EA	6	6-10 years	
nrinklar	System						
philipper	Sprinkler Heads	Entire Building	63,900	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	63,900	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	63,900	SF	6	10+ years	
	•	g				.o. yeare	
atego	ry : Mechanical		В	uilding	: Main	Decemmend	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	itioning	20041011	quantity	00	rank	rtopiaoomont	Commonic
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	6-10 years	
	tons						
	Condensing Unit- Roof Mounted - 21-30	Roof	1	EA	2	0-1 year	Damaged beyond repair, out of
	tons Condensing Unit Boof Mounted Creater	Doof	4	ГΛ	6	6.10 vooro	service Unit 1
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	6	6-10 years	Unit 1
	Condensing Unit- Roof Mounted - Greater	Roof	1	EA	5	6-10 years	Unit 2 Compressor down
	than 50 tons					,	
ir Hand	ling Customs						
ir Hand	ling Systems Air Handling Unit-Package Single Zone-	1st Floor - AHU1	1	EA	5	6-10 years	
	Indoor- Hot Water and DX Cooling Coils -	15t F1001 - Al 10 1	Į	LA	3	0-10 years	
	12001-20000 cfm						
	Air Intake	1st Floor - AHU1	1	EA	6	6-10 years	
	VAV Box	1st Floor - AHU1	9	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone-	2nd Floor - AHU2	1	EA	2	0-10 years 0-1 year	Grounded out
	Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	2110 1 1001 7 1102	•	L/(۷	o i yeai	Crounded out
	Air Intake	2nd Floor - AHU2	2	EA	6	6-10 years	
	VAV Box	2nd Floor - AHU2	9	ΕA	6	6-10 years	
	Fan Power Box - Fan Power Box with Hot	Entire Building	26	EA	5	6-10 years	All having issues with valves and
	Water Coil	g			-	,	valve actuators, located above
							ceilings
	Air Handling Unit-Package Single Zone-	Gym - AHU4	1	EA	2	0-1 year	Grounded out
	Indoor- Hot Water and DX Cooling Coils -						
	Less than 4000 cfm				_		
	Air Intake	Gym - AHU4	1	EΑ	6	6-10 years	
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Lower Roof	1	EA	5	2-5 years	
	Air Handling Unit-Package Single Zone-	Lunchroom - AHU3	1	EA	5	6-10 years	
	Indoor- Hot Water and DX Cooling Coils -				-	,	
	Less than 4000 cfm						



Catego	ry : Mechanical		В	uilding	: Main		0 3 Lawridale AVENUE, Chicago, IL 60623
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake	Lunchroom - AHU3	1	EA	6	6-10 years	
	VAV Box	Lunchroom - AHU3	2	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	Not accessible at time of assessment
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	Not accessible at time of assessment
Boiler S	ystems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Hot Water Pump	Boiler Room	1	EΑ	6	6-10 years	
	Hot Water Pump	Boiler Room	1	EΑ	4	0-1 year	Disconnected
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	5	6-10 years	Upgrade to controls
	Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH		_		-	,	
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
Heating	Devices						
_	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	294	LF	6	10+ years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - 10 - 20 HP	Entire Building	2	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	4	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	500	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	10+ years	
_Tempera	ature Control						
	DDC System	Entire Building	63,900	SF	5	6-10 years	System not communicating well or at all with older equipment
	Electric Thermostat	Entire Building	5	EA	6	6-10 years	i i -
	Thermostats - DDC	Entire Building	46	EA	7	6-10 years	
_Ventilati	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	Damaged covers



Group	y: Mechanical Item - Type Exhaust Fans- Roof Mounted - Greater than 8000 CFM Exhaust Fans- Roof Mounted - Greater than	Location Entire Building	Quantity	uilding		Recommend	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM Exhaust Fans- Roof Mounted - Greater than		Quantity	LION			
	8000 CFM Exhaust Fans- Roof Mounted - Greater than	Entire Building		UOM	Rank	Replacement	Comments
		-	1	EA	6	6-10 years	
	8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	
ategory	y : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Water							
	Gas Heater - 150000 - 300000 BTU/HR	2nd Floor	2	EA	6	6-10 years	
iping							
	Domestic Piping-Hot Water Return Lines	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	63,900	SF	6	10+ years	
	Sanitary Piping	Entire Building	63,900	SF	7	10+ years	
	Storm Piping	Entire Building	63,900	SF	7	10+ years	
	Vent Piping	Entire Building	63,900	SF	7	10+ years	
umps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	Repaired
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
ategory	y : Room		В	uilding	: Main		
				_		Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ative Suites/Offices						
	Ceiling - Lay-in	102 Faculty Center & principal office	865	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 Faculty Center & principal office	2	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	102 Faculty Center & principal office	865	SF	6	10+ years	
	Lighting - Lay-in	102 Faculty Center & principal office	12	EA	7	6-10 years	
	Power Distribution	102 Faculty Center & principal office	16	EA	7	10+ years	
	Walls - Concrete Block	102 Faculty Center & principal office	530	SF	7	10+ years	
	Walls - Plaster/Drywall	102 Faculty Center & principal office	530	SF	6	10+ years	
	Work Sink	102 Faculty Center & principal office	1	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor-100 Counselor's Office	380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-100 Counselor's Office	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor-100 Counselor's Office	380	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-100 Counselor's Office	6	ĒΑ	7	6-10 years	
	Power Distribution	1st Floor-100 Counselor's Office	24	EA	7	10+ years	
	Storage/ Closet	1st Floor-100 Counselor's Office	2	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-100 Counselor's Office	265	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-100 Counselor's Office	465	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-101 Faculty Lounge	380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-101 Faculty Lounge	1	EA	7	10+ years	
	Floor - Tile	1st Floor-101 Faculty Lounge	380	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-101 Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	1st Floor-101 Faculty Lounge	24	EA	7	10+ years	
	Storage/ Closet	1st Floor-101 Faculty Lounge	4	SF	7	10+ years	
	Walls - Concrete Block		265	SF	7	•	
		1st Floor-101 Faculty Lounge		SF SF		10+ years	
	Walls - Plaster/Drywall	1st Floor-101 Faculty Lounge	465		6	10+ years	
	Ceiling - Lay-in	1st Floor-103 Office, Main Office Suite	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-103 Office, Main Office Suite	1	EA	7	10+ years	
	Floor - Tile	1st Floor-103 Office, Main Office Suite	140	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-103 Office, Main Office Suite	2	EA	7	6-10 years	
	Power Distribution	1st Floor-103 Office, Main Office Suite	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-103 Office, Main Office Suite	86	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-103 Office, Main Office Suite	340	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-104 Main Office Suite	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-104 Main Office Suite	1	EA	7	10+ years	
	Floor - Tile	1st Floor-104 Main Office Suite	140	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-104 Main Office Suite	2	EA	7	10+ years	
	Power Distribution	1st Floor-104 Main Office Suite	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-104 Main Office Suite	86	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-104 Main Office Suite	340	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-105 Nurse's Office	140	SF	7	10+ years	
					-	,	



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	1st Floor-105 Nurse's Office	1	EA	7	10+ years			
	Floor - Tile	1st Floor-105 Nurse's Office	140	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-105 Nurse's Office	2	EA	7	6-10 years			
	Power Distribution	1st Floor-105 Nurse's Office	8	EA	7	10+ years			
	Walls - Concrete Block	1st Floor-105 Nurse's Office	86	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor-105 Nurse's Office	340	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-109 Office Ass't principal	160	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-109 Office Ass't principal	2	EA	7	10+ years			
	Floor - Tile	1st Floor-109 Office Ass't principal	160	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-109 Office Ass't principal	2	EA	7	6-10 years			
	Power Distribution	1st Floor-109 Office Ass't principal	8	EA	7	10+ years			
	Walls - Concrete Block	1st Floor-109 Office Ass't principal	155	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor-109 Office Ass't principal	360	SF	6	10+ years			
	Work SInk	1st Floor-109 Office Ass't principal	1	EA	7	10+ years			
	Ceiling - Lay-in	1st Floor-110 Office, Main Office Suite	175	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-110 Office, Main Office Suite	2	EA	7	10+ years			
	Floor - Tile	1st Floor-110 Office, Main Office Suite	175	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-110 Office, Main Office Suite	3	EA	7	6-10 years			
	Power Distribution	1st Floor-110 Office, Main Office Suite	8	EA	7	10+ years			
	Walls - Concrete Block	1st Floor-110 Office, Main Office Suite	155	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor-110 Office, Main Office Suite	340	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-111 Copy Room	220	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-111 Copy Room	1	EA	7	10+ years			
	Floor - Tile	1st Floor-111 Copy Room	220	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-111 Copy Room	3	EA	7	6-10 years			
	Power Distribution	1st Floor-111 Copy Room	6	EA	7	10+ years			
	Walls - Concrete Block	1st Floor-111 Copy Room	180	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor-111 Copy Room	380	SF	6	10+ years			
	Work SInk	1st Floor-111 Copy Room	1	EA	7	10+ years			
	Ceiling - Lay-in	1st Floor-Dietician Office	72	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor-Dietician Office	8	SF	4	1-2 years	Stain tile		
	Doors - Side-lite	1st Floor-Dietician Office	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor-Dietician Office	1	EA	7	10+ years			
	Floor - Tile	1st Floor-Dietician Office	80	SF	6	10+ years			
	Lighting - Lay-in	1st Floor-Dietician Office	2	EA	7	6-10 years			
	Power Distribution	1st Floor-Dietician Office	4	EA	7	10+ years			
	Walls - Concrete Block	1st Floor-Dietician Office	320	SF	7	10+ years			



Catego	ry : Room		В	uilding	: Main		o o cawildale Avenoe, officago, ie ooozo
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Lay-in	1st Floor-Engineer's Office	120	SF	7	10+ years	
	Doors - Side-lite	1st Floor-Engineer's Office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Engineer's Office	120	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Engineer's Office	2	ĒΑ	7	6-10 years	
	Power Distribution	1st Floor-Engineer's Office	10	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Engineer's Office	410	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Gym Teacher's Office	138	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Gym Teacher's Office	32	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	1st Floor-Gym Teacher's Office	10	SF	7	10+ years	zamagou mo
	Doors - Wood Doors inclu hw	1st Floor-Gym Teacher's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Gym Teacher's Office	170	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Gym Teacher's Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Gym Teacher's Office	10	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Gym Teacher's Office	490	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Main Office	825	SF	7	10+ years	
	Doors - Side-lite	1st Floor-Main Office	50	SF	7	10+ years	
	Doors - Transom Window	1st Floor-Main Office	5	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Main Office	825	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Main Office	11	EA	7	•	
	Power Distribution	1st Floor-Main Office	10	EA		6-10 years	
			-	SF	7 7	10+ years	
	Storage/ Closet	1st Floor-Main Office	15	SF SF	7 7	10+ years	
	Walls - Concrete Block	1st Floor-Main Office	350			10+ years	
	Walls - Plaster/Drywall	1st Floor-Main Office	1,420	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor-220 Library Workroom	287	SF	7	10+ years	Otalia tila
	Ceiling - Lay-in	2nd Floor-220 Library Workroom	8	SF	4	1-2 years	Stain tile
	Doors - Wood Doors inclu hw	2nd Floor-220 Library Workroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor-220 Library Workroom	295	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor-220 Library Workroom	3	EA	7	6-10 years	
	Power Distribution	2nd Floor-220 Library Workroom	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor-220 Library Workroom	180	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor-220 Library Workroom	530	SF	6	10+ years	
	Work Sink	2nd Floor-220 Library Workroom	1	EA	7	6-10 years	
•							
_Gymnas		4 - 4 - Flance 4 - F4 - Oc				40.	
	Bleacher Seating	1st Floor-151 Gym	3	EA	7	10+ years	
	Ceiling - Exposed	1st Floor-151 Gym	3,724	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-151 Gym	4	EA	7	10+ years	
	Floor - Tile	1st Floor-151 Gym	3,724	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor-151 Gym	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor-151 Gym	235	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-151 Gym	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-151 Gym	7,115	SF	7	10+ years	

Page: 10 of 30



Gatogo.	y : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Kitchen							
_KIICHEH	Ceiling - Plaster/Drywall	1st Floor-138 Kitchen	1,200	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-138 Kitchen	1,200	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-138 Kitchen	1,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-138 Kitchen	14	EΑ	7	6-10 years	
	Lighting - Lay-in	1st Floor-138 Kitchen	22	EA	7	6-10 years	
	Storage/ Closet	1st Floor-138 Kitchen	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-138 Kitchen	2,350	SF	7	10+ years	
						•	
Library							
	Ceiling - Lay-in	2nd Floor	1,975	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	25	SF	4	0-1 year	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Carpet	2nd Floor	2,000	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	700	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	864	SF	6	10+ years	
Locker/St	nower Room						
LOOKOI7OI	Accessories	1st Floor Unisex	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Unisex	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex	130	SF	6	10+ years	
	Floor Drain	1st Floor Unisex	1	EA	7	10+ years	
	Hand Dryer	1st Floor Unisex	1	EA	7	6-10 years	
	Lavatory	1st Floor Unisex	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Unisex	3	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor Unisex	3	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor Unisex	545	SF	7	10+ years	
	Water Closet	1st Floor Unisex	1	EA	7	10+ years	
	Accessories	1st Floor-Men's Faculty Locker Room	175	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Men's Faculty Locker	35	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 1st Floor-Men's Faculty Locker	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 1st Floor-Men's Faculty Locker	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 1st Floor-Men's Faculty Locker Room	140	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor-Men's Faculty Locker Room	35	SF	7	10+ years	



Catego	Category : Room		Building : Main					
				<u> </u>		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor Drain	1st Floor-Men's Faculty Locker Room	1	EA	7	10+ years		
	Hand Dryer	1st Floor-Men's Faculty Locker Room	1	EA	7	6-10 years		
	Lavatory	1st Floor-Men's Faculty Locker Room	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor-Men's Faculty Locker Room	3	EA	7	6-10 years		
	Partitions	1st Floor-Men's Faculty Locker Room	1	EA	7	6-10 years		
	Student Lockers - Two Tier	1st Floor-Men's Faculty Locker Room	2	EA	7	10+ years		
	Urinals	1st Floor-Men's Faculty Locker Room	1	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-Men's Faculty Locker Room	106	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor-Men's Faculty Locker Room	570	SF	6	10+ years		
	Water Closet	1st Floor-Men's Faculty Locker Room	1	EA	7	10+ years		
	Accessories	1st Floor-Staff Shower Room	60	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-Staff Shower Room	60	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-Staff Shower Room	1	EA	7	10+ years		
	Floor - Terrazzo	1st Floor-Staff Shower Room	15	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor-Staff Shower Room	45	SF	7	10+ years		
	Floor Drain	1st Floor-Staff Shower Room	2	EA	7	10+ years		
	Lighting - Lay-in	1st Floor-Staff Shower Room	1	EA	7	6-10 years		
	Showers	1st Floor-Staff Shower Room	1	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-Staff Shower Room	300	SF	7	10+ years		
	Accessories	1st Floor-Women's Faculty Locker Room	312	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor-Women's Faculty Locker Room	172	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor-Women's Faculty Locker Room	140	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-Women's Faculty Locker Room	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Faculty Locker Room	140	SF	6	10+ years		
	Floor - Tile/Sheet	1st Floor-Women's Faculty Locker Room	172	SF	5	10+ years		
	Floor Drain	1st Floor-Women's Faculty Locker Room	1	EA	7	10+ years		
	Hand Dryer	1st Floor-Women's Faculty Locker	1	EA	5	1-2 years	Not operational	



Catego	ry : Room		В	uilding	: Main		
0	H	Landin	0 :::	11014	D	Recommend	0
Group	Item - Type	Location Room	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st Floor-Women's Faculty Locker Room	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Women's Faculty Locker Room	4	EA	7	6-10 years	
	Partitions	1st Floor-Women's Faculty Locker Room	2	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor-Women's Faculty Locker Room	14	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Women's Faculty Locker Room	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Women's Faculty Locker Room	785	SF	6	10+ years	
	Water Closet	1st Floor-Women's Faculty Locker Room	2	EA	7	10+ years	
	Accessories	1st Floor-Women's Locker Room, near Stair #3	140	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Women's Locker Room, near Stair #3	35	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Women's Locker Room, near Stair #3	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Locker Room, near Stair #3	140	SF	6	10+ years	
	Floor Drain	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Women's Locker Room, near Stair #3	1	EA	5	0-1 year	Does not work
	Lavatory	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Women's Locker Room, near Stair #3	3	EA	7	6-10 years	
	Partitions	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor-Women's Locker Room, near Stair #3	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Women's Locker Room, near Stair #3	595	SF	7	10+ years	
	Water Closet	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor-137 Dining/Multipurpose	2,655	SF	7	10+ years	



Catego	Category : Room		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor-137 Dining/Multipurpose	4	EA	7	10+ years	
	Floor - Tile	1st Floor-137 Dining/Multipurpose	2,655	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-137 Dining/Multipurpose	31	EA	7	6-10 years	
	Serving Line	1st Floor-137 Dining/Multipurpose	18	LF		10+ years 10+ years	
	Storage/ Closet	1st Floor-137 Dining/Multipurpose	25	SF			
	Walls - Concrete Block	1st Floor-137 Dining/Multipurpose	2,515		7	10+ years	
	Walls - Plaster/Drywall	1st Floor-137 Dining/Multipurpose	480	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	125	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EΑ	7	6-10 years	No cooling unit
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,185	SF	7	10+ years	
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	825	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	178	SF	7	10+ years	
	Storage Room	1st Floor	125	SF	7	10+ years	
	Storage Room	1st Floor	18	SF	7		
	Vaults	1st Floor	150	SF	7	10+ years	Panast room conjer room
	Janitor's Closet	2nd Floor	32	SF		10+ years	Repeat room copier room
					7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	38	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	672	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
Restroor							
	Accessories	1st Floor-Boy's Restroom	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	380	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	380	SF	6	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	2	EA	7	6-10 years	
	Lavatory	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Boy's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boy's Restroom	890	SF	7	10+ years	



Catego	Category : Room		В	uilding	: Main		· •
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Accessories	1st Floor-Classroom 112/113	85	SF	7	6-10 years	
		Restroom					
	Ceiling - Plaster/Drywall	1st Floor-Classroom 112/113	85	SF	6	10+ years	
		Restroom					
	Doors - Wood Doors inclu hw	1st Floor-Classroom 112/113	2	EA	7	10+ years	
		Restroom					
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 112/113	85	SF	7	10+ years	
		Restroom					
	Floor Drain	1st Floor-Classroom 112/113	1	EA	7	10+ years	
		Restroom			_		
	Hand Dryer	1st Floor-Classroom 112/113	1	EA	7	6-10 years	
		Restroom			_	4.0	
	Lavatory	1st Floor-Classroom 112/113	1	EA	7	10+ years	
	Lighting Lawin	Restroom	4	Ε.	7	0.40	
	Lighting - Lay-in	1st Floor-Classroom 112/113	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom 1st Floor-Classroom 112/113	329	SF	6	10	
	Walls - Plastel/Drywall	Restroom	329	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Classroom 112/113	6	SF	5	1-2 years	Water damage
	Walls - Flaster/Drywall	Restroom	U	Oi	3	1-2 years	water damage
	Water Closet	1st Floor-Classroom 112/113	1	EA	7	10+ years	
	Trailor Groots	Restroom	•	_, 、	•	ioi youlo	
	Accessories	1st Floor-Classroom 114/115	85	SF	7	6-10 years	
		Restroom				, , ,	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 114/115	85	SF	6	10+ years	
	,	Restroom				•	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 114/115	2	EA	7	10+ years	
		Restroom					
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 114/115	85	SF	7	10+ years	
		Restroom					
	Floor Drain	1st Floor-Classroom 114/115	1	EA	7	10+ years	
		Restroom			_		
	Hand Dryer	1st Floor-Classroom 114/115	1	EA	7	6-10 years	
		Restroom	4	_ ^	-	40	
	Lavatory	1st Floor-Classroom 114/115	1	EA	7	10+ years	
	Lighting - Lay-in	Restroom	1	EA	7	6 10 vooro	
	Lighting - Lay-in	1st Floor-Classroom 114/115 Restroom	Į.	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 114/115	335	SF	6	10+ years	
	Trans Tractor/Dry Wall	Restroom	555	51	J	ioi youis	
	Water Closet	1st Floor-Classroom 114/115	1	EA	7	10+ years	
		Restroom	•		•	,	
	Accessories	1st Floor-Classroom 116/118	85	SF	7	6-10 years	
						,	



Catego	Category : Room		Building : Main			· • • • • • • • • • • • • • • • • • • •	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Restroom	-				
	Ceiling - Plaster/Drywall	1st Floor-Classroom 116/118	85	SF	6	10+ years	
		Restroom					
	Doors - Hardware	1st Floor-Classroom 116/118	1	EA	6	1-2 years	Hole through door from lock
		Restroom					
	Doors - Wood Doors inclu hw	1st Floor-Classroom 116/118	2	EA	7	10+ years	
		Restroom					
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 116/118	85	SF	7	10+ years	
		Restroom					
	Floor Drain	1st Floor-Classroom 116/118	1	EA	7	10+ years	
		Restroom			_		
	Hand Dryer	1st Floor-Classroom 116/118	1	EA	7	6-10 years	
		Restroom			_	4.0	
	Lavatory	1st Floor-Classroom 116/118	1	EA	7	10+ years	
	Limbition - Lauria	Restroom	4	_^	7	0.40	
	Lighting - Lay-in	1st Floor-Classroom 116/118	1	EA	7	6-10 years	
	Malla Diagtor/Drawall	Restroom	225	C.E.	•	10	
	Walls - Plaster/Drywall	1st Floor-Classroom 116/118	335	SF	6	10+ years	
	Water Closet	Restroom 1st Floor-Classroom 116/118	4	EA	7	10	
	Water Closet	Restroom	1	EA	/	10+ years	
	Accessories	1st Floor-Classroom 120 Restroom	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 120 Restroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 120 Restroom	50	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Classroom 120 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 120 Restroom	1	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor-Classroom 120 Restroom	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 120 Restroom	255	SF	6	10+ years	
	Water Closet	1st Floor-Classroom 120 Restroom	1	ĒΑ	7	10+ years	
	Accessories	1st Floor-Classroom 132/133	85	SF	7	6-10 years	
		Restroom				, , , , , , ,	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 132/133	85	SF	6	10+ years	
	ů ,	Restroom				,	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 132/133	2	EA	7	10+ years	
		Restroom				•	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 132/133	85	SF	7	10+ years	
		Restroom				•	
	Floor Drain	1st Floor-Classroom 132/133	1	EA	7	10+ years	
		Restroom				•	
	Hand Dryer	1st Floor-Classroom 132/133	1	EA	7	6-10 years	
	-	Restroom				•	
	Lavatory	1st Floor-Classroom 132/133	1	EA	7	10+ years	



Group Item - Type Location Quantity UOM Rank Replacement Comment Restroom Lighting - Lay-in 1st Floor-Classroom 132/133 1 EA 7 6-10 years Restroom	S
Restroom Lighting - Lay-in 1st Floor-Classroom 132/133 1 EA 7 6-10 years Restroom	5
Lighting - Lay-in 1st Floor-Classroom 132/133 1 EA 7 6-10 years Restroom	
Restroom	
Walls - Plaster/Drywall 1st Floor-Classroom 132/133 325 SF 6 10+ years	
Restroom	
Walls - Plaster/Drywall 1st Floor-Classroom 132/133 10 SF 5 1-2 years Plaster da	mage
Restroom	
Water Closet 1st Floor-Classroom 132/133 1 EA 7 10+ years	
Restroom	
Accessories 1st Floor-Classroom 134/136 85 SF 7 6-10 years	
Restroom	
Ceiling - Plaster/Drywall 1st Floor-Classroom 134/136 85 SF 6 10+ years	
Restroom	
Doors - Wood Doors inclu hw 1st Floor-Classroom 134/136 2 EA 7 10+ years	
Restroom Floor Tile Constrict Bostolein Add Floor Classes and 404/400	
Floor - Tile Ceramic/ Porcelain 1st Floor-Classroom 134/136 85 SF 7 10+ years	
Restroom Floor Drain 1st Floor-Classroom 134/136 1 EA 7 10+ years	
Floor Drain 1st Floor-Classroom 134/136 1 EA 7 10+ years Restroom	
Hand Dryer 1st Floor-Classroom 134/136 1 EA 7 6-10 years	
Restroom	
Lavatory 1st Floor-Classroom 134/136 1 EA 7 10+ years	
Restroom	
Lighting - Lay-in 1st Floor-Classroom 134/136 1 EA 7 6-10 years	
Restroom	
Walls - Plaster/Drywall 1st Floor-Classroom 134/136 335 SF 6 10+ years	
Restroom	
Water Closet 1st Floor-Classroom 134/136 1 EA 7 10+ years	
Restroom	
Accessories 1st Floor-Girl's Restroom 380 SF 7 6-10 years	
Ceiling - Plaster/Drywall 1st Floor-Girl's Restroom 380 SF 6 10+ years	
Floor - Tile Ceramic/ Porcelain 1st Floor-Girl's Restroom 380 SF 6 10+ years Floor Drain 1st Floor-Girl's Restroom 1 EA 7 10+ years	
Floor Drain 1st Floor-Girl's Restroom 1 EA 7 10+ years Hand Dryer 1st Floor-Girl's Restroom 2 EA 7 6-10 years	
Lavatory 1st Floor-Girl's Restroom 2 EA 7 6-10 years Lavatory 1st Floor-Girl's Restroom 3 EA 7 10+ years	
Lighting - Lay-in 1st Floor-Girl's Restroom 5 EA 7 6-10 years	
Partitions 1st Floor-Girl's Restroom 6 EA 7 10+ years	
Walls - Concrete Block 1st Floor-Girl's Restroom 890 SF 7 10+ years	
Water Closet 1st Floor-Girl's Restroom 6 EA 7 10+ years	
Accessories 2nd Floor-Boys Restroom 380 SF 7 6-10 years	
Ceiling - Plaster/Drywall 2nd Floor-Boys Restroom 380 SF 6 10+ years	
Floor - Tile Ceramic/ Porcelain 2nd Floor-Boys Restroom 380 SF 7 10+ years	
Floor Drain 2nd Floor-Boys Restroom 1 EA 7 10+ years	
Hand Dryer 2nd Floor-Boys Restroom 2 EA 7 6-10 years	



Catego	y : Room		В	uilding	: Main	3000 S Lawridale AVENUE, Chicago, it 60023		
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	2nd Floor-Boys Restroom	3	EΑ	7	10+ years		
	Lighting - Lay-in	2nd Floor-Boys Restroom	5	EA	7	6-10 years		
	Partitions	2nd Floor-Boys Restroom	3	EA	7	10+ years		
	Urinals	2nd Floor-Boys Restroom	3	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor-Boys Restroom	890	SF	7	10+ years		
	Water Closet	2nd Floor-Boys Restroom	3	EA	7	10+ years		
	Accessories	2nd Floor-Girls Restroom	380	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Girls Restroom	380	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	380	SF	7	10+ years		
	Floor Drain	2nd Floor-Girls Restroom	1	EA	7	10+ years		
	Hand Dryer	2nd Floor-Girls Restroom	2	EA	7	10+ years		
	Lavatory	2nd Floor-Girls Restroom	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor-Girls Restroom	4	EA	7	6-10 years		
	Partitions	2nd Floor-Girls Restroom	6	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor-Girls Restroom	882	SF	7	10+ years		
	Water Closet	2nd Floor-Girls Restroom	6	ĒΑ	7	10+ years		
	Accessories	2nd Floor-Men's Restroom	40	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Men's Restroom	40	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor-Men's Restroom	1	ĒΑ	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Men's Restroom	40	SF	6	10+ years		
	Floor Drain	2nd Floor-Men's Restroom	1	ĒΑ	7	10+ years		
	Hand Dryer	2nd Floor-Men's Restroom	1	EA	7	6-10 years		
	Lavatory	2nd Floor-Men's Restroom	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor-Men's Restroom	1	ĒΑ	6	6-10 years		
	Walls - Concrete Block	2nd Floor-Men's Restroom	205	SF	7	10+ years		
	Water Closet	2nd Floor-Men's Restroom	1	EΑ	7	10+ years		
	Accessories	2nd Floor-Women's Restroom	71	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Women's Restroom	71	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor-Women's Restroom	1	EΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Women's Restroom	71	SF	7	10+ years		
	Floor Drain	2nd Floor-Women's Restroom	1	EA	7	10+ years		
	Hand Dryer	2nd Floor-Women's Restroom	1	EΑ	7	6-10 years		
	Lavatory	2nd Floor-Women's Restroom	1	EΑ	7	10+ years		
	Lighting - Lay-in	2nd Floor-Women's Restroom	1	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor-Women's Restroom	315	SF	7	10+ years		
	Water Closet	2nd Floor-Women's Restroom	1	EA	7	10+ years		
			•		-	, , , , , , , , , , , , , , , , , , , ,		
atego	ry : Classroom		В	uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lassroo	m #112 (Regular Classroom)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st Floor	950	SF EA	7 7	10+ years		



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	950	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #113 (Regular Classroom)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	942	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	ŭ
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	10+ years	
Classroo	om #114 (Regular Classroom)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #115 (Regular Classroom)						
21000100	Casework	1st Floor	40	LF	7	10+ years	
	Casework	1st Floor	4	LF	6	1-2 years	Water damage
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	Updated to match current
						•	observations
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	om #116 (Kindergarten)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	920	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	675	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #118 (Kindergarten)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	920	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	675	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #120 (Kindergarten)						
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,230	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	, 1	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,230	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	, 14	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	985	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	275	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #132 (Regular Classroom)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	942	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	6-10 years	Sagging tiles
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	

Page : 20 of 30



Catego	Category : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Marker Board	1st Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	548	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	2	SF	6	10+ years	Plaster damaged	
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroo	om #133 (Regular Classroom)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	950	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	10	ĒΑ	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years		
	Work Sink	1st Floor	2	ĒΑ	7	10+ years		
Classroo	om #134 (Pre School)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,166	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1,100	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,166	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	EΑ	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	535	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	om #136 (Pre School)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,166	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1,100	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,166	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	535	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years	Stuck dripping	
	WORK OHIK	1301 1001	'	LA	,	TOT years	Stack dripping	



Category	Category : Classroom		В	uilding	: Main		o o cawindaic Avenoe, officago, ie 60025
				_		Recommend	
Group I	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom	#200 (Regular Classroom)						
(Casework	2nd Floor	36	LF	7	10+ years	
(Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
(Chalk Board	2nd Floor	8	LF	4	2-5 years	
[Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
F	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
N	Marker Board	2nd Floor	12	LF	7	6-10 years	
\	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
١	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroom	#201 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
(Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
F	Floor - Tile	2nd Floor	835	SF	6	10+ years	
L	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
\	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
\	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroom	#202 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroom	#203 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
•			100	-	ŭ	,	



Category : Classroom		В	uilding	: Main			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	823	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	o
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroo	om #205 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	12	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	

Page : 23 of 30



Catego	Category : Classroom		В	uilding	: Main		o o Lawridaic Avenoe, officago, ie 00023
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #208 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	465	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Cracking
_Classroc	om #209 (Faculty Lounge)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
_Classroo	om #211 (Laboratory/Shop)						
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	960	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Cracking plaster
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	- ··· 9 [-······
	Floor - Carpet	2nd Floor	980	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	8	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	6	6-10 years	Relamp
	Marker Board	2nd Floor	8	LF	7	6-10 years	r
			•			,	



Catego	Category : Classroom		Building : Main				o o Lawridaic Avervoe, Orlicago, ie 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	700	SF	7	10+ years	
_Classroo	om #216 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classro	om #217 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	12	LF	7	6-10 years	Relatify
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classro	om #221 (Computer Lab)						
Classici	Ceiling - Lay-in	2nd Floor	1,077	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	1,077	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	1,077	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	525	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
Classro	om #222 (Play Room)						
_UIGSSIU	Ceiling - Lay-in	2nd Floor	1,170	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	0	EA	7	2-5 years 10+ years	
	Floor - Tile	2nd Floor	1,170	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	1,170	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	8	LF	7	•	
	Storage/ Closet	2nd Floor 2nd Floor	60	SF	7 7	6-10 years	
	Storage/ Closet Storage/ Closet	2nd Floor 2nd Floor	36	SF SF	7 7	10+ years	
	Storage/ Cluser	ZHU FIUUI	30	ЗF	,	10+ years	

Page : 25 of 30



Catego	ory : Classroom		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	920	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classro	om #223 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,131	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,131	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	444	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	6	SF	6	6-10 years	Mortar cracking
	Walls - Plaster/Drywall	2nd Floor	630	SF	6	10+ years	Wortan ordoning
lacero	om #224 (Art Room)						
<u> </u>	Casework	2nd Floor	17	LF	7	10+ years	
		2nd Floor 2nd Floor	980	SF	7		
	Ceiling - Lay-in					10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	980	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	540	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Catego	ory : Interior		В	uilding	: Main		
`	Hom. Time	Lagation	Quantity	HOM	Donk	Recommend	Comments
Froup Corridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
JIIIGOI	Ceiling - Lay-in	1st Floor	3,868	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	0-1 year	Water stain tile
	Ceiling - Plaster/Drywall	1st Floor	846	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	640	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,966	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	40	EΑ	7	6-10 years	
		1st Floor	3	EΑ	7	6-10 years	
	Lighting - Pendent/Surface		0		7	10+ years	
	Lighting - Pendent/Surface Walls - Concrete Block		8 575	SE			
	Walls - Concrete Block	1st Floor	8,575 3,560	SF SE			
	Walls - Concrete Block Walls - Plaster/Drywall	1st Floor 1st Floor	3,560	SF	6	10+ years	
	Walls - Concrete Block	1st Floor					Water damaged tile

Page : 26 of 30



Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	2nd Floor	289	SF	6	10+ years			
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years			
	Floor - Tile/Sheet	2nd Floor	4,016	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	37	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	7,300	SF	7	10+ years			
Safety									
-	Camera Viewing Station	1st Floor	2	EA	5	1-2 years	Reboot system. Cannot view camera		
	Security Cameras	1st Floor	7	EA	7	6-10 years	Apart of MEP assessment		
Stairs									
	Ceiling - Plaster/Drywall	N Stair #1	210	SF	6	10+ years			
	Floor - Tile	N Stair #1	65	SF	6	10+ years			
	Handrails	N Stair #1	85	LF	7	10+ years			
	Lighting - Pendent/Surface	N Stair #1	1	EA	7	6-10 years			
	Stairs - Tile	N Stair #1	30	LF	6	10+ years			
	Walls - Concrete Block	N Stair #1	1,450	SF	7	10+ years			
	Walls - Concrete Block	N Stair #1	7	SF	5	1-2 years	Cracking through middle of block		
	Ceiling - Plaster/Drywall	S Stair #2	160	SF	7	10+ years			
	Floor - Tile	S Stair #2	65	SF	6	10+ years			
	Handrails	S Stair #2	85	LF	7	10+ years			
	Lighting - Lay-in	S Stair #2	2	EA	7	6-10 years			
	Stairs - Tile	S Stair #2	30	LF	6	10+ years			
	Walls - Concrete Block	S Stair #2	1,400	SF	7	10+ years			
	Walls - Concrete Block	S Stair #2	8	SF	6	6-10 years	Cracking and falling mortar		
	Walls - Concrete Block	S Stair #2	30	SF	5	1-2 years	Cracked cmu		
	Ceiling - Plaster/Drywall	W Stair #3	210	SF	6	10+ years			
	Floor - Tile	W Stair #3	65	SF	6	10+ years			
	Handrails	W Stair #3	85	LF	7	10+ years			
	Lighting - Pendent/Surface	W Stair #3	1	EA	7	6-10 years			
	Stairs - Tile	W Stair #3	24	LF	7	10+ years			
	Stairs - Tile	W Stair #3	6	LF	5	1-2 years	Rubber detached from stair		
	Walls - Concrete Block	W Stair #3	1,458	SF	7	10+ years			
	Walls - Concrete Block	W Stair #3	10	SF	6	6-10 years	Mortar cracking		
Vertical 0	Conveyance								
	Elevator - Elevator- Roped Holeless Hydraulic	1st to 2nd floor	1	EA	6	10+ years			



Category: Site **Building: Site**

Group							
~						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Asphalt	South Courtyard	15,016	SF	6	10+ years	
	Surface - Asphalt	South Courtyard	8	SF	5	1-2 years	Pothole
	Lighting	South Courtyard	4	EA	6	10+ years	1 outloic
	Surface - Synthetic	South Courtyard	100	SF	5	0-1 year	Ripped up surfaces near goal Posts
	Surface - Synthetic including exc & retention	South Courtyard	49,085	SF	6	2-5 years	Ripped up surfaces flear goal Fost
	Surface - Synthetic including exc & retention	South Courtyard	49,085	SF	ь	2-5 years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	6	10+ years	
encina							
	Fencing - Chain Link	Entire Site	240	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,475	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	5	1-2 years	Fence rails are disconnected
andscar	oe.						
	Benches	Entire Site	7	EA	7	10+ years	
	Landscape - Grass	Entire Site	13,600	SF	6	6-10 years	
	Parkway trees	Entire Site	24	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	9,800	SF	6	6-10 years	
	Trash Receptacles	Entire Site	6	EΑ	4	10+ years	Corroded, or otherwise old or
	Tradit Nesspiasies		· ·	_, ,	·	ioi youlo	temporary cans
Parking L	ot						
ŭ	Concrete Curbs	Parking Lot- North	145	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- North	4	ĒΑ	6	10+ years	
	Surface - Asphalt	Parking Lot- North	1,262	SF	5	1-2 years	Disintegrated asphalt, alligatored
	Carrago / Aprilan	r anding Lot Horar	1,202	O.	O	1 2 youro	surface, potholes
	Surface - Concrete	Parking Lot- North	2,321	SF	6	10+ years	ounded, pounded
	Trash Enclosure - Chain Links	Parking Lot- North	425	SF	6	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- North	400	SF	5	1-2 years	Deteriorated mortar and open joint
	Trasti Efficiosure - Masority	r arking Lot- North	400	OI.	3	1-2 years	Deteriorated mortal and open joints
Playgrou							
	Equipment - Pre K 3-5	NW	1	EA	7	10+ years	
	Surface - Poured Surface	NW	2,340	SF	7	10+ years	
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	215	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,500	SF	6	10+ years	
				SF			

Page : 28 of 30



Josefa Ortiz De Dominguez Elementary School

3000 S Lawndale AVENUE, Chicago, IL 60623

Catego	Category : Site			Building : Site						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
_Signage										
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years				
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years				

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Olassi ooni oanina y				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Science Classroom	2nd Floor	224	224	980	56	26	N	N
Computer Lab	Computer Lab	2nd Floor	221	221	1,077	56	26	N	N
Faculty Lounge	Regular Classroom	2nd Floor	209	209	835	84	42	N	N
Kindergarten	Kindergarten	1st Floor	116	116	920	126	68	N	Υ
Kindergarten	Kindergarten	1st Floor	118	118	920	126	68	N	N
Kindergarten	Regular Classroom	1st Floor	120	120	1,230	84	42	N	N
Laboratory/Shop	Regular Classroom	2nd Floor	211		980	28	0		1
Play Room	Regular Classroom	2nd Floor	222	222	1,170	56	26	N	N
Pre School	Pre School	1st Floor	134	134	1,166	112	56	N	N
Pre School	Pre School	1st Floor	136	136	1,166	112	56	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	950	84	42	N	Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	950	84	42	N	Υ
Regular Classroom	Regular Classroom	1st Floor	114	114	950	84	42	N	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	950	84	42	N	N
Regular Classroom	Regular Classroom	1st Floor	132	132	950	84	42	N	N
Regular Classroom	Regular Classroom	1st Floor	133	133	950	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	835	84	42	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	1,131	98	46	N	N