

1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1915	3	59,563
Addition	1999	2	71,850
Branch	2021	1	8,350
Field House	1924	1	1,825
Campus Total			141,588

Category : Exterior Building : Main

Julogo	iy i Extorior			anang			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ntrance			quanti		- tunit	Портисотноги	
	Entrance Control - Audio	#1 N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#1 N	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 N	4	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10 S	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 S	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10 S	60	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10.1_Exit E	2	EA	6	2-5 years	Rusted and needs paint
	Exterior Doors - Exterior Steel Door	#10.2 E	1	EA	6	6-10 years	Pealing paint
	Exterior Doors - Transom Lite	#10.2 E	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#11 N	4	EA	5	2-5 years	
	Exterior Doors - Transom Lite	#11 N	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#11 N	72	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#11 N	50	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#7 W	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#8 W	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#8 W	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8 W	12	LF	5	6-10 years	Cracking
	Exterior Doors - Exterior Steel Door	#9 W	4	EA	6	6-10 years	-
	Exterior Doors - Transom Lite	#9 W	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9 W	26	LF	5	2-5 years	Chipped
	Exterior Doors - Exterior Steel Door	#9.1_Exit W	1	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	#9.1_Exit W	6	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9.1_Exit W	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#9.2_Exit W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9.2_Exit W	5	LF	6	10+ years	
Foundati	ion						
	Foundation - Masonry	Entire Building	29,016	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	59,563	SF	7	10+ years	
Lighting							
- 0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	11	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	6	6-10 years	
Roof Sys	stem						
,	Access Ladder - Metal	Roof #1	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #1	80	LF	6	10+ years	
	Liner					·	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #1	5	LF	5	2-5 years	Cracking
	Coping - Terra Cotta	Roof #1	599	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #1	560	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #1	299	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #1	300	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #1	16,519	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof #1	250	SF	4	0-1 year	Per engineer, Leaks reported above room 110
	Roof Hatch - Metal	Roof #1	1	EA	5	2-5 years	100111 110
	Roof Hatch - Metal	Roof #1	1	EΑ	3	0-1 year	Not in use
	Roof Structure - Steel with Clay Tile Arch	Roof #1	16,519	SF	7	10+ years	
	Chimney - Metal Flue	Roof #2	7	LF	6	6-10 years	
	Coping - Stone	Roof #2	188	LF	6	10+ years	
	Coping - Terra Cotta	Roof #2	165	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #2	12	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof #2	80	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #2	80	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof #2	273	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #2	10,534	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof #2	10,534	SF	7	10+ years	
	Coping - Stone	Roof #3	120	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #3	40	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof #3	192	LF	6	10+ years	
	Roof - Metal	Roof #3	1,200	SF	3	1-2 years	severely rusted.
	Roof - Modified Bitumen	Roof #3	1,900	SF	6	6-10 years	•



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel with Clay Tile Arch	Roof #3	1,900	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	122	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	607	LF	5	2-5 years	Rusted throughout
	Exterior Walls - Brick	Entire Building	33,738	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	768	SF	6	10+ years	
	Wall						
	Exterior Walls - Stone-Cast	Entire Building	7,125	SF	6	10+ years	
Windows		Finding Divilations	2.024			0.40	
	Guard - Guards perforated	Entire Building	3,921	SF	6	6-10 years	
	Lintels - Steel	Entire Building	936	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	26	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,853	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	Part of the obsolete UPS system.
	Emergency A/C Power - Auditoium and	Entire Building	6,620	SF	6	6-10 years	Served by Addition
	Aisle Lighting	· ·				•	•
	Emergency A/C Power - Corridors and	Entire Building	10,786	SF	6	6-10 years	Served by Addition
	Stairs	· ·				·	•
	Emergency Battery Packs - Auditoium and	Entire Building	3	EA	6	6-10 years	Auditorium and gym are one and the
	Aisle Lighting	_				-	same space
	Emergency Battery Packs - Corridors and	Entire Building	6	EA	6	6-10 years	A total of six emergency battery
	Stairs						packs in the corridors and stairs of
							this building. Quantity changed to
							match current observations.
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	6	2-5 years	
	Exit Signs - Gym	Entire Building	6	EA	6	6-10 years	Auditorium and gym are one and the
	3	3				,	same space. Upgraded since last
							assessment, all signs appropriately
							legible at the time of assessment wit
							Rank accordingly changed.
			1	EA	5	6-10 years	Sign is functional but lens is incorrect
	Exit Signs - Gvm	Entire Buildina	l l		-	,	o contract of the contract of
	Exit Signs - Gym	Entire Building	ı				size
		-			6	6-10 years	size
	Security System - CCTV	Entire Building	59,563	SF	6 6	6-10 years 6-10 years	size
		-			6 6	6-10 years 6-10 years	size

Campus Name: Peirce Page : 3 of 59 Assessment Date: 02/09/2022



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Electrical		R	uilding	: Main		W Bryn Mawr AVENUE, Chicago, IL 60660
Jaiogo	y . Electrical			unung	· Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	Serves Main
	120/208/3PH					•	
	PA System	Entire Building	59,563	SF	6	6-10 years	Served by Addition
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Quantity changed as total has been
							divided/aggregated. Panel is older
							but not materially deteriorated and is fully operational. Rank, Reason and
							Priority Rep adjusted based on
							current observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	current observations.
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	2	1-2 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	Inside Room 206A
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	Quantity changed as total has been
							divided/aggregated
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	Quantity changed per Building
							Engineer and based on current
	Main Distribution Densels 400, 000 ann	Entire Delilation	0	_^	7	40	observations
	Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600	Entire Building Entire Building	2	EA EA	7 7	10+ years	
	amp	Entire Building	ı	EA	,	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	114116161111616 2717 166 1267266	Zimio Zanamg	·	_, 、	ŭ	ioi youlo	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	3	2-5 years	Serves Main and Addition. Panel is
							functional but approaching the end of
		Machanical Dage	50.500	C.E.	0	0.40	its service life.
		Mechanical Room	59,563	SF	6 6	6-10 years 6-10 years	
	Fire Alarm System	Machanical Poom	50 562				
	Fire Alarm Strobe Lights Fire Alarm_System	Mechanical Room	59,563	SF	U	0 .0 ,00.0	
Catego	Fire Alarm_System	Mechanical Room	,			c re years	
Catego		Mechanical Room	,	SF uilding		Recommend	
Catego Group	Fire Alarm_System	Mechanical Room Location	,				Comments
	Fire Alarm_System ry: Mechanical Item - Type		В	uilding	: Main	Recommend	Comments
Group	Fire Alarm_System ry: Mechanical Item - Type itioning		В	uilding	: Main	Recommend Replacement	Comments Installed in 1998 and has been out of
Group	Fire Alarm_System ry: Mechanical Item - Type	Location	Quantity	uilding UOM	: Main Rank	Recommend	



Category : Mechanical		В	Building : Main			W BIJII WaW AVENOE, Onleage, in 00000
g ,			_		Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Handling Systems						
Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Attic	2	EA	6	10+ years	
Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	2	EA	6	10+ years	With the exception of the gym/auditorium (served by AHU-3), AHU-1 serves the north part of the building and AHU-2 serves the south part of the building.
Air Intake	Mechanical Room	2	EA	7	10+ years	
Auxiliaries - 25001 - 35000 cfm	Mechanical Room	2	EA	6	10+ years	
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	2	LF	7	10+ years	
Zone Dampers	Mechanical Room	17	EA	6	10+ years	For AHU-2. Actuators are functional but are inside a ceiling panel not safely accessible at the time of assessment.
Zone Dampers	Mechanical Room	17	EA	6	10+ years	For AHU-1. Actuators are functional but are inside a ceiling panel not safely accessible at the time of assessment. Quantity changed to match current observations.
Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-3 serves gym/auditorium
Air Intake	Mechanical Room	1	EA	6	10+ years	
Auxiliaries - 4000 - 8000 cfm	Mechanical Room	1	EA	6	10+ years	
Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	7	10+ years	
Boiler Systems						
Boiler Auxiliary- Scotch Marine- Steam Lo Pressure Boiler - 101 - 150 HP	ow Boiler Room	2	EA	6	10+ years	
Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
Chemical Feeder	Boiler Room	2	EA	6	6-10 years	
Combustion Dampers	Boiler Room	2	EA	6	10+ years	
Condensate Pump	Boiler Room	1	EA	6	10+ years	
Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
Non Condensing- Fire Tube- Scotch Mari Steam- Low Pressure Boiler - 101 - 150 H	ne- Boiler Room	2	EA	6	10+ years	Serves Main
Piping - Condensate Pipe- Steel	Boiler Room	500	LF	6	10+ years	
Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	
Steam Traps	Boiler Room	20	EΑ	5	10+ years	
_Gas Booster						



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

	Schools					1423	W Bryn Mawr AVENUE, Chicago, IL 60660
Catego	ry : Mechanical		В	uilding	: Main	_	
0	Have Torre	Lagation	Ouantitu.	LIOM	Dank	Recommend	Commonto
Group	Item - Type	Location Beiler Boom	Quantity	UOM	Rank	Replacement	Comments
	Gas Booster	Boiler Room	1	EA	6	10+ years	
Heating	Devices						
	Unit Heater - Electric	Entire Building	17	EA	6	6-10 years	Quantity is 17 per Building Engineer
	Unit Heater - Gas	Entire Building	1	EA	6	6-10 years	Quantity changed per Building Engineer and to match current observations.
	Unit Heater - Steam	Entire Building	1	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	7	10+ years	
	Wall Heater - Electric	Entire Building	1	EA	7	10+ years	
	Wall Heater - Electric	Entire Building	1	EA	7	10+ years	
	Radiators - Steam	Room 110	3	EA	5	6-10 years	
Tempera	ture Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Controls the unit heaters
	Electric Thermostat	Entire Building	34	EA	6	10+ years	DDC thermostats per Building
		ū				•	Engineer and based on current observations via DDC system.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls the exhaust fan
	Hybrid Pneumatic/DDC System	Entire Building	59,563	SF	6	10+ years	System is operational but needs upgrading per Building Engineer
Ventilatio							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	Older unit, operational but approaching the end of its service life
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	Older unit, operational but approaching the end of its service life
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	0
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	20	LF	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
		Laastian				Recommend	Comments
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	1	EA	6	2-5 years	Serves Main. Older unit with no leak or appreciable deterioration but approaching the end of its service life
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	59,563	SF	6	6-10 years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Plumbing		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Risers	Entire Building	59,563	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	59,563	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	59,563	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	59,563	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	59,563	SF	6	6-10 years	
	Sanitary Piping	Entire Building	59,563	SF	6	6-10 years	
	Storm Piping	Entire Building	59,563	SF	6	6-10 years	
	Vent Piping	Entire Building	59,563	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EΑ	6	6-10 years	

Catego	ry : Room		В	uilding	: Main		
0	Mana Tana	Landon	0	LIONA	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor Engineers Office	96	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor Engineers Office	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Engineers Office	2	EΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor Engineers Office	96	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Engineers Office	3	EA	7	6-10 years	
	Power Distribution	1st Floor Engineers Office	6	EA	7	10+ years	
	Storage/ Closet	1st Floor Engineers Office	30	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor Engineers Office	576	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Gym Office inside Gym	415	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Gym Office inside Gym	1	EA	7	10+ years	
	Floor - Tile	1st Floor Gym Office inside Gym	415	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Gym Office inside Gym	2	EA	7	6-10 years	
	Power Distribution	1st Floor Gym Office inside Gym	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Gym Office inside Gym	850	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Storage/Mail Room	52	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Storage/Mail Room	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor Storage/Mail Room	52	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Storage/Mail Room	2	EA	7	6-10 years	
	Power Distribution	1st Floor Storage/Mail Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Storage/Mail Room	288	SF	7	10+ years	
	Ceiling - Lay-in	1st floor NW corner	557	SF	7	10+ years	
	Doors - Side-lite	1st floor NW corner	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor NW corner	1	EA	7	10+ years	
	Floor - Tile	1st floor NW corner	557	SF	7	10+ years	

Campus Name: Peirce Page : 7 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

or	ry : Room		В	uilding	: Main		
	_					Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st floor NW corner	6	EA	7	6-10 years	
	Lighting - Wall Mounted	1st floor NW corner	1	EA	7	6-10 years	
	Power Distribution	1st floor NW corner	18	EA	7	10+ years	
	Storage/ Closet	1st floor NW corner	56	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor NW corner	1,042	SF	7	10+ years	
	Ceiling - Lay-in	206A at north end of corridor	211	SF	7	10+ years	
	Doors - Wood Doors inclu hw	206A at north end of corridor	1	EA	7	10+ years	
	Floor - Carpet	206A at north end of corridor	211	SF	7	6-10 years	
	Lighting - Lay-in	206A at north end of corridor	2	EA	7	6-10 years	
	Power Distribution	206A at north end of corridor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	206A at north end of corridor	646	SF	7	10+ years	
	Ceiling - Lay-in	306A - Counselor room	357	SF	7	10+ years	
	Ceiling - Lay-in	306A - Counselor room	3	SF	4	1-2 years	Cracked tile
	Doors - Wood Doors inclu hw	306A - Counselor room	1	ĒΑ	7	10+ years	
	Floor - Carpet	306A - Counselor room	360	SF	7	6-10 years	
	Lighting - Lay-in	306A - Counselor room	3	EA	7	6-10 years	
	Power Distribution	306A - Counselor room	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	306A - Counselor room	884	SF	7	10+ years	
	AC Unit	312	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	312	302	SF	6	10+ years	
	Doors - Transom Window	312	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	312	1	EA	7	10+ years	
	Floor - Wood	312	302	SF	6	10+ years	
	Lighting - Pendent/Surface	312	302 4	EA	7	6-10 years	
	Power Distribution	312	6	EA	7	10+ years	
	Walls - Plaster/Drywall	312	722	SF	6	10+ years	
	AC Unit	313	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	313	276	SF	7		
	Ceiling - Plaster/Drywall		26	SF	, 5	10+ years	Water demand
		313		SF SF		0-1 year	Water damage
	Doors - Transom Window	313	9		7	10+ years	
	Doors - Wood Doors inclu hw	313	=	EΑ	7	10+ years	
	Lighting - Pendent/Surface	313	4	EΑ	7	6-10 years	
	Power Distribution	313	6	EA	7	10+ years	
	Walls - Plaster/Drywall	313	718	SF	7	10+ years	10/-4
	Walls - Plaster/Drywall	313	4	SF	5	0-1 year	Water damage
	Ceiling - Plaster/Drywall	Dressing room in gymnasium	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Dressing room in gymnasium	15	SF	5	0-1 year	Peeling
	Doors - Wood Doors inclu hw	Dressing room in gymnasium	1	EA	7	10+ years	
	Floor - Concrete	Dressing room in gymnasium	135	SF	7	10+ years	
	Lighting - Pendent/Surface	Dressing room in gymnasium	2	EA	7	6-10 years	
	Power Distribution	Dressing room in gymnasium	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Dressing room in gymnasium	368	SF	7	10+ years	

<u>Gymnasia</u>



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	6,600	SF	7	10+ years	
	Doors - Transom Window	1st Floor	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EΑ	7	10+ years	
	Floor - Wood	1st Floor	6,600	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	25	EA	7	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	3	EA	5	1-2 years	Do not work
	Lighting - Pendent/Surface	1st Floor	21	EΑ	7	6-10 years	
	Main Floor Seating	1st Floor	320	EΑ	7	10+ years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	578	SF	7	10+ years	
	Stage Curtain	1st Floor	2	EA	7	6-10 years	
	Stage Lift	1st Floor	_ 1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	10	LF	7	10+ years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Storage/ Closet	1st Floor	56	SF	7	10+ years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,686	SF	7	10+ years	
	Walls - Flastel/Drywall	151 [100]	0,000	SI	,	10+ years	
MDF_ID	F						
_	Doors - Steel Doors incl hw	In 206A	1	EA	7	10+ years	
	Finishes	In 206A	527	SF	7	10+ years	
	Window AC Unit	In 206A	1	ĒΑ	7	6-10 years	
Mechani	ical/ Service Rooms						
IVICCITATI	Boiler Room	Entire Building	1,790	SF	7	10+ years	
	Coal Room	Entire Building	468	SF	7	10+ years	
	Janitor's Closet	Entire Building	30	SF	5	10+ years	
		3		SF	5 5	,	
	Janitor's Closet	Entire Building	30	SF SF		10+ years	
	Mechanical/ Service Rooms	Entire Building	196	SF SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	3,326		7	10+ years	
	Storage Room	Entire Building	45	SF	7	10+ years	
	Storage Room	Entire Building	72	SF	7	10+ years	
	Storage Room	Entire Building	40	SF	5	10+ years	
_Restroo	m						
_176311001	Accessories	1st floor boys	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys	186	SF	7	10+ years	
	Ceiling - Plaster/Drywall	_	80	SF SF			Dooling
	Doors - Wood Doors inclu hw	1st floor boys	2	SF EA	4	1-2 years	Peeling Missing doors
		1st floor boys			4	1-2 years	Missing doors
	Floor - Tile Ceramic/ Porcelain	1st floor boys	266	SF	7	10+ years	
	Floor Drain	1st floor boys	1	EA	7	10+ years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Category : Room			Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	1st floor boys	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st floor boys	5	EA	7	6-10 years		
	Partitions	1st floor boys	3	EA	7	10+ years		
	Urinals	1st floor boys	5	EA	7	10+ years		
	Walls - Plaster/Drywall	1st floor boys	315	SF	7	10+ years		
	Walls - Plaster/Drywall	1st floor boys	110	SF	4	1-2 years	Peeling	
	Walls - Structural Glazed Tile	1st floor boys	425	SF	7	10+ years		
	Water Closet	1st floor boys	3	EA	7	10+ years		
	Accessories	1st floor girls	203	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st floor girls	125	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st floor girls	78	SF	4	1-2 years	Peeling	
	Doors - Wood Doors inclu hw	1st floor girls	4	EA	4	1-2 years	Missing	
	Floor - Tile Ceramic/ Porcelain	1st floor girls	203	SF	7	10+ years		
	Floor Drain	1st floor girls	1	EA	7	10+ years		
	Lavatory	1st floor girls	3	EA	7	10+ years		
	Lighting - Pendent/Surface	1st floor girls	5	EA	7	6-10 years		
	Partitions	1st floor girls	5	EA	7	10+ years		
	Walls - Plaster/Drywall	1st floor girls	388	SF	5	1-2 years	Peeling	
	Walls - Structural Glazed Tile	1st floor girls	388	SF	7	10+ years		
	Water Closet	1st floor girls	5	EA	7	10+ years		
	Accessories	1st floor inside office at NW corner	67	SF	7	6-10 years		
	Ceiling - Lay-in	1st floor inside office at NW corner	67	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st floor inside office at NW corner	1	EA	7	10+ years		
	Floor - Tile	1st floor inside office at NW corner	67	SF	7	10+ years		
	Lavatory	1st floor inside office at NW corner	1	EA	7	10+ years		
	Lighting - Lay-in	1st floor inside office at NW corner	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st floor inside office at NW corner	307	SF	7	10+ years		
	Water Closet	1st floor inside office at NW corner	1	EA	7	10+ years		
	Accessories	1st floor next to girls restroom	38	SF	7	6-10 years		
	Ceiling - Lay-in	1st floor next to girls restroom	38	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st floor next to girls restroom	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor next to girls restroom	38	SF	7	10+ years		
	Lavatory	1st floor next to girls restroom	1	EA	7	10+ years		
	Lighting - Lay-in	1st floor next to girls restroom	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st floor next to girls restroom	165	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st floor next to girls restroom	165	SF	7	10+ years		
	Water Closet	1st floor next to girls restroom	1	EA	7	10+ years		
	Accessories	2nd Floor unisex	44	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor unisex	35	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor unisex	9	SF	5	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	2nd Floor unisex	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor unisex	44	SF	7	10+ years		
	Floor Drain	2nd Floor unisex	1	EA	7	10+ years		
	Lavatory	2nd Floor unisex	1	EA	7	10+ years		

Campus Name: Peirce Page: 10 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor unisex	250	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor unisex	46	SF	7	10+ years	
	Water Closet	2nd Floor unisex	1	EA	7	10+ years	
	Accessories	2nd floor boys	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	266	SF	7	10+ years	
	Floor Drain	2nd floor boys	1	EA	7	10+ years	
	Lavatory	2nd floor boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor boys	5	EA	7	6-10 years	
	Partitions	2nd floor boys	2	EA	7	10+ years	
	Urinals	2nd floor boys	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor boys	425	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor boys	425	SF	7	10+ years	
	Water Closet	2nd floor boys	2	EA	7	10+ years	
	Accessories	2nd floor girls	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls	266	SF	7	10+ years	
	Floor Drain	2nd floor girls	1	EA	7	10+ years	
	Lavatory	2nd floor girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor girls	5	EA	7	6-10 years	
	Partitions	2nd floor girls	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor girls	425	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor girls	425	SF	7	10+ years	
	Water Closet	2nd floor girls	5	EA	7	10+ years	
	Accessories	3rd Floor Staff Restroom inside girls	83	SF	7	6-10 years	
		restroom				•	
	Ceiling - Plaster/Drywall	3rd Floor Staff Restroom inside girls	83	SF	7	10+ years	
	· ·	restroom				•	
	Doors - Wood Doors inclu hw	3rd Floor Staff Restroom inside girls	1	EA	7	10+ years	
		restroom				•	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Staff Restroom inside girls	83	SF	7	10+ years	
		restroom				•	
	Lavatory	3rd Floor Staff Restroom inside girls	1	EA	7	10+ years	
	•	restroom				,	
	Lighting - Pendent/Surface	3rd Floor Staff Restroom inside girls	2	EA	7	6-10 years	
	0 0	restroom				,	
	Partitions	3rd Floor Staff Restroom inside girls	1	EA	7	10+ years	
		restroom				,	
	Walls - Plaster/Drywall	3rd Floor Staff Restroom inside girls	82	SF	6	10+ years	
	,	restroom		-	-	- ,	
	Walls - Plaster/Drywall	3rd Floor Staff Restroom inside girls	5	SF	5	1-2 years	Crack by door jam
	•	3 3				,	•

Campus Name: Peirce Page : 11 of 59 Assessment Date: 02/09/2022



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		restroom					
	Walls - Structural Glazed Tile	3rd Floor Staff Restroom inside girls	200	SF	7	10+ years	
		restroom					
	Water Closet	3rd Floor Staff Restroom inside girls	1	EA	7	10+ years	
		restroom					
	Accessories	3rd floor boys	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys	266	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys	2	EA	4	1-2 years	Missing doors
	Floor - Tile Ceramic/ Porcelain	3rd floor boys	266	SF	7	10+ years	
	Floor Drain	3rd floor boys	1	EA	7	10+ years	
	Lavatory	3rd floor boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd floor boys	5	EA	7	6-10 years	
	Partitions	3rd floor boys	3	EA	7	10+ years	
	Urinals	3rd floor boys	5	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	420	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	5	SF	5	1-2 years	Damaged
	Walls - Structural Glazed Tile	3rd floor boys	425	SF	7	10+ years	g
	Water Closet	3rd floor boys	3	EΑ	7	10+ years	
	Accessories	3rd floor girls	266	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls	266	SF	5	1-2 years	Chipped ceiling with cracks
	Doors - Wood Doors inclu hw	3rd floor girls	2	EA	4	1-2 years	Doors are missing
	Floor - Tile Ceramic/ Porcelain	3rd floor girls	266	SF	7	10+ years	Doors are missing
	Floor Drain	3rd floor girls	1	EA	7	10+ years	
	Lavatory	3rd floor girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd floor girls	5	EA	7	6-10 years	
	Partitions	3rd floor girls	7	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd floor girls	425	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd floor girls	425	SF	7	10+ years	
	Water Closet	3rd floor girls	7	EA	7	10+ years	
	Accessories	In 110	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In 110	44	SF	7	•	
	Doors - Wood Doors inclu hw	In 110 In 110	1	EA	7	10+ years	
	Floor - Tile	In 110 In 110		SF	7	10+ years	
			44			10+ years	
	Lavatory	In 110	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	In 110	1	EA SF	7	6-10 years	
	Walls - Plaster/Drywall	In 110	250		7	10+ years	Deterioreted
	Walls - Plaster/Drywall	In 110	4	SF	4	0-1 year	Deteriorated
	Water Closet	In 110	2	EA	7	10+ years	
atego	ry : Classroom		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	888	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	868	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Cracked
	Lighting - Lay-in	1st Floor	21	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,070	SF	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	938	SF	7	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	938	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,232	SF	7	10+ years	
	·					•	
Classroc	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	938	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	938	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,223	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9	SF	5	1-2 years	Peeling
	Work Sink	1st Floor	1	EA	7	10+ years	3
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	934	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
		1001	J	<u> </u>	•	ioi youid	



Catego	ry : Classroom		В	uilding	: Main	·	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	934	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	21	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,249	SF	7	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	910	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	910	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,249	SF	7	10+ years	
Classroo	om #109 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	333	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Carpet	1st Floor	333	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	6	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	72	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	890	SF	6	10+ years	
Classroo	om #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,300	SF	7	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	434	SF	7	10+ years	
	Floor - Wood	1st Floor	866	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	5	10+ years	
	Walls - Masonry	1st Floor	898	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,426	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	18	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #200 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	10+ years		
	Ceiling - Lay-in	2nd Floor	415	SF	7	10+ years		
	Chalk Board	2nd Floor	24	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	60	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Carpet	2nd Floor	415	SF	6	2-5 years		
	Lighting - Lay-in	2nd Floor	3	EΑ	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	850	SF	7	10+ years		
Classroo	m #201 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	888	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	888	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,059	SF	7	10+ years		
Classroo	m #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	903	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	903	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,127	SF	7	10+ years		
Classroo	m #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	909	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Wood	2nd Floor	909	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years		



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	908	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	908	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,129	SF	7	10+ years	
Classroo	om #205 (Dance Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	866	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	866	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,687	SF	7	10+ years	
Classroo	om #206B (Kindergarten)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	554	SF	7	6-10 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	554	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,003	SF	7	10+ years	
Classro	om #207 (Regular Classroom)						
SIGGOI O	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	927	SF	7	10+ years	
	Chalk Board	2nd Floor 2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	12	SF	7	2-5 years 10+ years	
			12		7	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main		W BIYII MAWI AVENUE, CHICAGO, IL 60000
o ano go	,,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor - Wood	2nd Floor	927	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,406	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	881	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	881	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,524	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	935	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	1-2 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,017	SF	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	879	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	879	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,038	SF	7	10+ years	
Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	415	SF	7	10+ years	
	· · · · · · · · · · · · · · · · · ·	2.22.		<u> </u>	•	,	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Carpet	3rd Floor	415	SF	7	6-10 years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
<u> </u>	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	888	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,070	SF	7	10+ years	
_Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	938	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
_Classroo	om #303 (Science)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	909	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	909	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
				SF		,	

Campus Name: Peirce Page: 18 of 59 Assessment Date: 02/09/2022



Catego	ry : Classroom		В	uilding	: Main	1120	W BIYII Mawi AVENOE, Chicago, it 60060
Culogo	. ,		_	aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #304 (Regular Classroom)					•	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	938	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	7	10+ years	
Classroo	om #305 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	888	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	
Classroo	m #306B (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	602	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	602	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	887	SF	7	10+ years	
_Classroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	938	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Classroom		В	uilding	: Main		
- a.ogo	. ,			u.i.g	· Mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Marker Board	3rd Floor	24	LF	7	6-10 years	Comments
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	7	10+ years	
	walls - Flastel/Drywall	314 F1001	1,232	SF	,	10+ years	
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	938	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	7	10+ years	
laceroo	om #309 (Regular Classroom)						
<u> </u>	AC Units	3rd Floor	1	EA	7	6-10 years	
			8	LF	7	•	
	Casework	3rd Floor				10+ years	
	Ceiling - Lay-in	3rd Floor	938	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	938	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	7	10+ years	
Classroc	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	888	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	888	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,150	SF	7	10+ years	
O-4	·		·			,	
Jatego	ry : Interior		В	uilding	: wain	Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,157	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Interior		В	uilding	: Main	20	W BIJIT Maw AVENUE, Officago, IE 00000
				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors include hw	1st Floor	15	EΑ	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	4,700	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	678	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	39	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	6	LF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,807	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	612	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,554	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,349	SF	4	0-1 year	Cracking
	Floor - Terrazzo	2nd Floor	205	SF	7	10+ years	· ·
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,707	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,554	SF	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,300	SF	6	10+ years	
	Floor - Asphalt Floor	3rd Floor	49	SF	4	0-1 year	Cracking throughout
	Floor - Terrazzo	3rd Floor	205	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	27	EA	7	6-10 years	
	Stairs - Concrete Stairs	3rd Floor	10	LF	6	10+ years	
	Student Lockers - One Tier	3rd Floor	18	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	324	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,707	SF	6	10+ years	
Safety							
	Security Cameras	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	ĒΑ	7	6-10 years	
		g				,	
Stairs							
	Ceiling - Lay-in	North stair	40	SF	7	10+ years	
	Floor - Asphalt	North stair	150	SF	6	10+ years	
	Handrails	North stair	162	LF	7	10+ years	
	Lighting - Lay-in	North stair	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	North stair	2	EA	7	6-10 years	
	Stairs - Asphalt	North stair	57	LF	6	10+ years	
	Walls - Plaster/Drywall	North stair	2,415	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South stair	40	SF	6	10+ years	
	Floor - Asphalt	South stair	150	SF	6	10+ years	

Campus Name: Peirce Page : 21 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Interior		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Handrails	South stair	162	LF	7	10+ years				
	Lighting - Lay-in	South stair	3	EA	7	6-10 years				
	Lighting - Pendent/Surface	South stair	2	EA	7	6-10 years				
	Stairs - Asphalt	South stair	57	LF	6	10+ years				
	Walls - Plaster/Drywall	South stair	2,415	SF	7	10+ years				
_Vertical	Conveyance									
	Wheelchair Lift - Platform Lift	Na	1	EA	7	6-10 years				

Campus Name: Peirce Page: 22 of 59 Assessment Date: 02/09/2022





Category : Exterior Building : Addition

	ry . Exterior			ananig	. Additi		
0	Ham. Time	Location	O	LION	Dani	Recommend	C
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Exterior Doors - Exterior Steel Door	#2_Exit N	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3_Exit N	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 S	2	EA	5	2-5 years	Rusted
	Exterior Doors - Exterior Steel Door	#4.1_Exit S	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#5_Exit S	2	EA	7	10+ years	
	Exterior Stairs - Concrete	#5_Exit S	45	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#5_Exit S	15	LF	6	6-10 years	
	Ramps - Concrete	#5_Exit S	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5_Exit S	15	LF	6	6-10 years	
	Exterior Doors - Store Front	#6 S	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 S	25	LF	6	10+ years	
	Exterior Stairs - Concrete	#6 S	5	LF	5	2-5 years	Cracking
	Stair Handrail - Steel_Stair Handrail	#6 S	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	2.1	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	2.1	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Roof 2	1	EA	4	0-1 year	Rusted and missing exterior side
							hardware
oundat	ion						
	Foundation - Concrete	Entire Building	835	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	71,850	SF	7	10+ years	
	Topping .	C				·	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	22	EA	6	6-10 years	
		· ·				•	
Roof Sys	stem						
	Access Ladder - Metal	Roof #1	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof #1	3	LF	6	6-10 years	
	Coping - Stone	Roof #1	800	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof #1	480	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #1	652	LF	6	10+ years	
			400	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #1	183		U		
	Parapet - Parapet > 30" Parapet - Parapet > 30"	Roof #1 Roof #1		LF LF	_		
	Parapet - Parapet > 30" Parapet - Parapet > 30" Roof - Modified Bitumen		35		6 4	10+ years	Severe Bubbling, blisters and oper
	Parapet - Parapet > 30"	Roof #1		LF	6		Severe Bubbling, blisters and oper seams throughout
	Parapet - Parapet > 30"	Roof #1	35	LF	6	10+ years 0-1 year	
	Parapet - Parapet > 30" Roof - Modified Bitumen	Roof #1 Roof #1	35 21,310 1	LF SF	6 4	10+ years 0-1 year 10+ years	
	Parapet - Parapet > 30" Roof - Modified Bitumen Roof Hatch - Metal Roof Structure - Steel / Metal Deck/	Roof #1 Roof #1 Roof #1	35 21,310	LF SF EA	6 4 7	10+ years 0-1 year	
	Parapet - Parapet > 30" Roof - Modified Bitumen Roof Hatch - Metal	Roof #1 Roof #1 Roof #1	35 21,310 1	LF SF EA	6 4 7	10+ years 0-1 year 10+ years	Severe Bubbling, blisters and open seams throughout

Campus Name: Peirce Page: 23 of 59 Assessment Date: 02/09/2022



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Exterior	B	uilding	: Additi	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Roof #2	228	LF	6	10+ years	
	Roof - Modified Bitumen	Roof #2	5,763	SF	4	0-1 year	Severe Bubbling, blisters and open seams throughout
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof #2	5,743	SF	7	10+ years	Ü
Valls							
	Exterior Walls - Brick	Entire Building	31,159	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	11,016	SF	6	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	1,465	SF	6	6-10 years	
	Lintels - Steel	Entire Building	782	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,660	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
- merger	ncy System					•	
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Room 130
	Security System - CCTV	Entire Building	71,850	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	71,850	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	13,400	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	6,280	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations
//ain Se	rvice						
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years	Room 130
		Electrical Room	1	EA	7	10+ years	Room 130. Serves Addition and
	Independent Electrical Service for emergency power	Electrical Room	·				Main.

Campus Name: Peirce Page : 24 of 59 Assessment Date: 02/09/2022



0 - 1	Schools 1423 W Bryn Mawr AVENUE, Chicago, IL 60						
Category : Electrical			В	uilding	: Addition	on	
			.			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						-
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Room 222
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Room 130
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	Room 230
	Transformers - 277/480 - 120/208	Entire Building	3	EA	6	10+ years	Room 130
Category : Fire Protection			В	uilding	: Additio		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Electrical Room	71,850	SF	6	6-10 years	FACP is in Main
	Fire Alarm_System	Electrical Room	71,850	SF	6	6-10 years	FACP is in Main
	Fire Pump Controller	Electrical Room	1	EA	7	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Room 131	1	EA	6	10+ years	
	Jockey Pump	Room 131	1	EA	6	6-10 years	
Sprinkler	r System						
	Sprinkler Heads	Entire Building	71,850	SF	7	10+ years	
	Sprinkler Piping	Entire Building	71,850	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	71,850	SF	6	6-10 years	
atego	ry : Mechanical		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Chemical Pot Feeder	Entire Building	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Entire Building	2	EA	6	10+ years	Serves Addition
	Mounted - 101 - 200 tons	3				•	
	Glycol Feed	Entire Building	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Steel	Entire Building	600	LF	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	Based on current observations and
	than 5 tons		·		Č	,	per Building Engineer, there is one a conditioning condensing unit, hence

Campus Name: Peirce Page : 25 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

tego	ry : Mechanical		В	uilding	: Additi		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hand	ling Systems						
110110	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	26	EA	5	6-10 years	
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-1 serves multipurpose room
	Air Intake	Mechanical Room	1	EA	6	10+ years	Location changed per Building Engineer and based on current observations.
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	
	Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less than 6000 cfm	Mechanical Room	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-4 serves 1st floor (except for kitchen area and multipurpose ro
	Air Intake	Mechanical Room	1	EA	6	10+ years	Location changed per Building Engineer and based on current observations.
	VAV Box	Mechanical Room	5	EA	6	6-10 years	Quantity changed per Building Engineer and based on current observations via DDC system.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-3 serves 2nd and 3rd floors
	Air Intake	Mechanical Room	1	EA	6	10+ years	Location changed per Building Engineer and based on current observations.
	VAV Box	Mechanical Room	5	EA	6	6-10 years	Quantity changed per Building Engineer and based on current observations via DDC system.
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-2 serves kitchen area
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	5	EA	6	6-10 years	
or Sv	stems						
ود تع	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	3	EA	6	10+ years	

Campus Name: Peirce Page: 26 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Group	y: Mechanical Item - Type - 3001 - 4000 MBH Chemical Pot Feeder	Location	Quantity	_	: Additi	Recommend	
	- 3001 - 4000 MBH	Location	Quantity				
				UOM	Rank	Replacement	Comments
	Chemical Pot Feeder	Dellas Danas	4	Ε.	0	0.40	
	On the section Demands	Boiler Room	1	EA EA	6	6-10 years	
	Combustion Dampers	Boiler Room Boiler Room	3	EA EA	6 6	6-10 years 10+ years	
	Glycol Feed System Non Condensing- Water Tube- Flexible	Boiler Room	3	EA	6		
	Tube- Force Draft- Hot Water Boiler - 3001	Bollet Room	3	EA	О	10+ years	
	- 4000 MBH						
Gas Boost	ter						
	Gas Booster	Boiler Room	1	EA	6	10+ years	
Heating De	levices						
-	Unit Heater - Electric	Entire Building	4	EA	6	6-10 years	Quantity changed based on current observations.
	Unit Heater - Hot Water	Entire Building	8	EA	6	6-10 years	oboci valiono.
	Cabinet Heaters - With Hot Water Coil	Entire Building	8	EΑ	6	6-10 years	Quantity changed to match current
		g			•	,	observations
	Radiator Panels - Hot Water	Entire Building	17	EA	6	6-10 years	
_Mechanica	al Plumbing						
	Chilled Water Pump - 10 - 20 HP	Boiler Room	3	EA	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	3	EA	6	10+ years	
	Hydronic Supply and Return - Copper	Entire Building	750	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	250	LF	6	10+ years	
	ure Control						
	DDC System	Entire Building	71,850	SF	6	10+ years	Installed in 1999 and upgraded in 2012. Another upgrade is now needed per Building Engineer.
	Electric Thermostat	Entire Building	20	EA	6	6-10 years	Temperature control for cabinet heaters, unit heaters, and indoor exhaust fans. Quantity as observed
	Thermostats - DDC	Entire Building	42	EA	6	6-10 years	at the time of assessment. Quantity changed per Building Engineer and based on current observations via DDC system.
Ventilation	1						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	5	EA	6	10+ years	Quantity changed per Building Engineer and based on current observations.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	

Campus Name: Peirce Page: 27 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Mechanical		В	uilding	: Additi	on	-
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	6	6-10 years	
	500 CFM	Emilio Ballallig	·	_, .	Ü	o ro youro	
	Roof Mounted Duct Work	Entire Building	10	LF	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	7	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 300001 - 600000 BTU/HR	3rd Floor	2	EA	6	10+ years	
	Hot Water Storage Tank_Gas - 201 - 500	3rd Floor	1	EA	7	10+ years	
	Gallons						
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	71,850	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	71,850	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	71,850	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	71,850	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	71,850	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	71,850	SF	6	10+ years	
	Sanitary Piping	Entire Building	71,850	SF	6	10+ years	
	Storm Piping	Entire Building	71,850	SF	6	10+ years	
	Vent Piping	Entire Building	71,850	SF	6	10+ years	
Dumne							
Pumps	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	6-10 years	Located at the bottom of the elevator
	, amps camp complex		·		· ·	c .c years	pit. Inaccessible at the time of assessment.
Catego	ry : Room		В	uildina	: Additi	on	
Jalogo	.,			anding	. , taditi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices		•			_	
	Ceiling - Exposed Doors - Steel Doors incl hw	3rd FIr- engineers office 3rd FIr- engineers office	1,092 1	SF EA	7 7	10+ years 10+ years	
Campus	Name: Peirce	Page	: 28 of 59				Assessment Date: 02/09/202

Campus Name: Peirce Page: 28 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete Epoxy/ Painted	3rd Flr- engineers office	1,092	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Flr- engineers office	6	EA	7	6-10 years	
	Power Distribution	3rd Flr- engineers office	8	EA	7	10+ years	
	Walls - Concrete Block	3rd Flr- engineers office	1,618	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Flr- engineers office	1,228	SF	7	10+ years	
	Work SInk	3rd Flr- engineers office	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 120- main office	763	SF	7	10+ years	
	Doors - Side-lite	Rm 120- main office	81	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 120- main office	2	EA	7	10+ years	
	Floor - Tile	Rm 120- main office	763	SF	7	10+ years	
	Lighting - Lay-in	Rm 120- main office	17	EA	7	6-10 years	
	Power Distribution	Rm 120- main office	22	EA	7	10+ years	
	Storage/ Closet	Rm 120- main office	28	SF	7	10+ years	
	Walls - Concrete Block	Rm 120- main office	1,105	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 120- main office	770	SF	7	10+ years	
	Ceiling - Lay-in	Rm 120B- Principal in main office	105	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 120B- Principal in main office	1	EΑ	7	10+ years	
	Floor - Tile	Rm 120B- Principal in main office	105	SF	7	10+ years	
	Lighting - Lay-in	Rm 120B- Principal in main office	1	EA	7	6-10 years	
	Power Distribution	Rm 120B- Principal in main office	1	EA	7	10+ years	
	Walls - Concrete Block	Rm 120B- Principal in main office	105	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 120B- Principal in main office	135	SF	6	10+ years	
	Ceiling - Lay-in	Rm 120C Work Rm in main office	120	SF	7	10+ years	
	Doors - Steel Doors incl hw	Rm 120C Work Rm in main office	1	EA	7	10+ years	
	Floor - Tile	Rm 120C Work Rm in main office	120	SF	7	10+ years	
	Lighting - Lay-in	Rm 120C Work Rm in main office	4	EA	7	6-10 years	
	Power Distribution	Rm 120C Work Rm in main office	8	EA	7	10+ years	
	Walls - Concrete Block	Rm 120C Work Rm in main office	287	SF	7	10+ years	
	Work SInk	Rm 120C Work Rm in main office	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 124A- Teacher's Lounge	283	SF	7	10+ years	
	Ceiling - Lay-in	Rm 124A- Teacher's Lounge	2	SF	4	1-2 years	Missing
	Doors - Wood Doors inclu hw	Rm 124A- Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile	Rm 124A- Teacher's Lounge	287	SF	7	10+ years	
	Lighting - Lay-in	Rm 124A- Teacher's Lounge	4	EA	7	6-10 years	
	Power Distribution	Rm 124A- Teacher's Lounge	6	EA	7	10+ years	
	Walls - Concrete Block	Rm 124A- Teacher's Lounge	708	SF	7	10+ years	
	Work SInk	Rm 124A- Teacher's Lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 125E- Kitchen manager office	73	SF	7	10+ years	
	Doors - Side-lite	Rm 125E- Kitchen manager office	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 125E- Kitchen manager office	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Rm 125E- Kitchen manager office	73	SF	7	10+ years	
	Lighting - Lay-in	Rm 125E- Kitchen manager office	1	ĒΑ	7	6-10 years	
	Power Distribution	Rm 125E- Kitchen manager office	2	EA	7	10+ years	
	Walls - Concrete Block	Rm 125E- Kitchen manager office	320	SF	7	10+ years	
		· ·				·	

Campus Name: Peirce Page: 29 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Room		В	uilding	: Additi	on	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Rm 220A- library workroom/office	200	SF	7	10+ years	
	Doors - Side-lite	Rm 220A- library workroom/office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 220A- library workroom/office	1	EA	7	10+ years	
	Floor - Tile	Rm 220A- library workroom/office	200	SF	7	10+ years	
	Lighting - Lay-in	Rm 220A- library workroom/office	2	EA	7	6-10 years	
	Power Distribution	Rm 220A- library workroom/office	6	EA	7	10+ years	
	Storage/ Closet	Rm 220A- library workroom/office	22	SF	7	10+ years	
	Walls - Concrete Block	Rm 220A- library workroom/office	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 220A- library workroom/office	580	SF	7	10+ years	
	Work SInk	Rm 220A- library workroom/office	1	EA	7	10+ years	
	Ceiling - Lay-in	Rm 227, teacher resource room	448	SF	7	10+ years	
	Doors - Side-lite	Rm 227, teacher resource room	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 227, teacher resource room	1	EA	7	10+ years	
	Floor - Tile	Rm 227, teacher resource room	448	SF	7	10+ years	
	Lighting - Lay-in	Rm 227, teacher resource room	6	EA	7	6-10 years	
	Power Distribution	Rm 227, teacher resource room	14	EA	7	10+ years	
	Walls - Concrete Block	Rm 227, teacher resource room	630	SF	7	10+ years	
	Walls - Plaster/Drywall	Rm 227, teacher resource room	310	SF	7	10+ years	
	Ceiling - Lay-in	Rm 237- Speech & Language Office	174	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 237- Speech & Language Office	1	EA	7	10+ years	
	Floor - Tile	Rm 237- Speech & Language Office	174	SF	7	10+ years	
	Lighting - Lay-in	Rm 237- Speech & Language Office	1	EA	7	6-10 years	
	Power Distribution	Rm 237- Speech & Language Office	2	EA	7	10+ years	
	Walls - Concrete Block	Rm 237- Speech & Language Office	418	SF	7	10+ years	
	Ceiling - Lay-in	Rm 337- Counseling Office	211	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 337- Counseling Office	1	EA	7	10+ years	
	Floor - Tile	Rm 337- Counseling Office	211	SF	7	10+ years	
	Lighting - Lay-in	Rm 337- Counseling Office	1	EA	7	6-10 years	
	Power Distribution	Rm 337- Counseling Office	2	EA	7	10+ years	
	Walls - Concrete Block	Rm 337- Counseling Office	599	SF	7	10+ years	
<u>Kitchen</u>							
	Ceiling - Lay-in	1st Floor	817	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	817	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Storage/ Closet	1st Floor	393	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,442	SF	7	10+ years	
						-	
Library							
	Ceiling - Lay-in	2nd Floor	2,459	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	2,463	SF	6	6-10 years	
						•	

Campus Name: Peirce Page : 30 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	Category : Room		R	uildina	: Additi		W BIJII Mawi AVENOE, Chicago, it 60060
Jalego				anding	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00.0	Lighting - Lay-in	2nd Floor	28	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,978	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	326	SF	6	10+ years	
	vvalio i laotoi/Brywaii	2114 1 1001	020	O.	J	To Tyouro	
_Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Rm 124/125- Cafeteria & Servery	6,280	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 124/125- Cafeteria & Servery	8	ĒΑ	7	10+ years	
	Floor - Tile	Rm 124/125- Cafeteria & Servery	6,280	SF	7	10+ years	
	Lighting - Lay-in	Rm 124/125- Cafeteria & Servery	12	ĒΑ	7	6-10 years	
	Market Board	Rm 124/125- Cafeteria & Servery	12	LF	7	6-10 years	
	Serving Line	Rm 124/125- Cafeteria & Servery	28	LF	7	10+ years	
	Storage/ Closet	Rm 124/125- Cafeteria & Servery	373	SF	7	10+ years	
	Walls - Concrete Block	Rm 124/125- Cafeteria & Servery	10,046	SF	7	10+ years	
	200.000 20000		. 0,0 . 0	О.	•	. o v y cano	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	Rm 222	1	EA	7	10+ years	
	Finishes	Rm 222	145	SF	7	10+ years	
	Other Cooling Unit	Rm 222	1	EA	7	6-10 years	
Maahani	cal/ Service Rooms						
_iviechani		1st Floor	47		7	10	
	Janitor's Closet	1st Floor 1st Floor	47 593	SF SF	7	10+ years	
	Mechanical/ Service Rooms			SF SF	7	10+ years	
	Storage Room	1st Floor	454	SF SF	7 7	10+ years	
	Janitor's Closet	2nd Floor	27 337	SF SF	-	10+ years	
	Mechanical/ Service Rooms	2nd Floor		SF SF	7 7	10+ years	
	Storage Room	2nd Floor	66		-	10+ years	
	Boiler Room	3rd Floor	1,891	SF	7	10+ years	
	Janitor's Closet	3rd Floor	27	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	2,667	SF	7	10+ years	
	Storage Room	3rd Floor	431	SF	7	10+ years	
Prep Ro	om						
	Ceiling - Lay-in	Rm 125A- Dishwashing Rm	157	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 125A- Dishwashing Rm	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Rm 125A- Dishwashing Rm	157	SF	7	10+ years	
	Lighting - Lay-in	Rm 125A- Dishwashing Rm	3	EA	7	6-10 years	
	Walls - Concrete Block	Rm 125A- Dishwashing Rm	545	SF	7	10+ years	
	Work Sink	Rm 125A- Dishwashing Rm	1	EA	7	10+ years	
Deates	_						
Restroor	n Accessories	1st Flr- In kitchen	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fir- in kitchen	42	SF SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Fir- in kitchen	42	EA	7	10+ years 10+ years	
	Doors - Wood Doors Ilicia IIW	13t I II- III NITOTION	ı	ĽA	,	10+ years	

Campus Name: Peirce Page : 31 of 59 Assessment Date: 02/09/2022



Catego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete Epoxy/ Painted	1st Flr- In kitchen	42	SF	7	10+ years	
	Floor Drain	1st Flr- In kitchen	1	EA	7	10+ years	
	Lavatory	1st Flr- In kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st Flr- In kitchen	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Flr- In kitchen	208	SF	6	10+ years	
	Water Closet	1st FIr- In kitchen	1	EA	6	10+ years	
	Accessories	2nd floor Unisex- Across from Library	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor Unisex- Across from Library	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor Unisex- Across from Library	1	EA	7	10+ years	
	Floor - Terrazzo	2nd floor Unisex- Across from Library	45	SF	7	10+ years	
	Floor Drain	2nd floor Unisex- Across from Library	1	EA	7	10+ years	
	Lavatory	2nd floor Unisex- Across from Library	1	EA	7	10+ years	
	Lighting - Lay-in	2nd floor Unisex- Across from Library	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd floor Unisex- Across from Library	210	SF	7	10+ years	
	Water Closet	2nd floor Unisex- Across from Library	1	EA	7	10+ years	
	Accessories	2nd floor- Across from Library	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor- Across from Library	210	SF	7	10+ years	
	Floor - Terrazzo	2nd floor- Across from Library	210	SF	7	10+ years	
	Floor Drain	2nd floor- Across from Library	1	EA	7	10+ years	
	Lavatory	2nd floor- Across from Library	3	EΑ	7	10+ years	
	Lighting - Lay-in	2nd floor- Across from Library	5	EΑ	7	6-10 years	
	Partitions	2nd floor- Across from Library	2	EΑ	7	10+ years	
	Urinals	2nd floor- Across from Library	2	EΑ	7	10+ years	
	Walls - Concrete Block	2nd floor- Across from Library	592	SF	7	10+ years	
	Water Closet	2nd floor- Across from Library	2	EA	7	10+ years	
	Accessories	2nd floor- Across from Library	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor- Across from Library	210	SF	7	10+ years	
	Floor - Terrazzo	2nd floor- Across from Library	210	SF	7	10+ years	
	Floor Drain	2nd floor- Across from Library	1	EA	7	10+ years	
	Lavatory	2nd floor- Across from Library	3	EA	7	10+ years	
	Lighting - Lay-in	2nd floor- Across from Library	5	EA	7	6-10 years	
	Partitions	2nd floor- Across from Library	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd floor- Across from Library	600	SF	7	10+ years	
	Water Closet	2nd floor- Across from Library 2nd floor- Across from Library	4	EA	7	10+ years	
	Accessories	3rd floor Unisex- Across from 320	45	SF	7	6-10 years	
	, 10000001100	314 11001 011130A- A01033 110111 320	73	Oi.	,	o io years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Room		В	uilding	: Additi	on	<u> </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd floor Unisex- Across from 320	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor Unisex- Across from 320	1	EA	7	10+ years	
	Floor - Terrazzo	3rd floor Unisex- Across from 320	45	SF	7	10+ years	
	Floor Drain	3rd floor Unisex- Across from 320	1	EA	7	10+ years	
	Lavatory	3rd floor Unisex- Across from 320	1	EA	7	10+ years	
	Lighting - Lay-in	3rd floor Unisex- Across from 320	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd floor Unisex- Across from 320	210	SF	7	10+ years	
	Water Closet	3rd floor Unisex- Across from 320	1	EA	7	10+ years	
	Accessories	3rd floor- Across from 320	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor- Across from 320	210	SF	7	10+ years	
	Floor - Terrazzo	3rd floor- Across from 320	210	SF	7	10+ years	
	Floor Drain	3rd floor- Across from 320	1	EA	7	10+ years	
	Lavatory	3rd floor- Across from 320	3	EA	7	10+ years	
	Lighting - Lay-in	3rd floor- Across from 320	5	EA	7	6-10 years	
	Partitions	3rd floor- Across from 320	2	EA	7	10+ years	
	Urinals	3rd floor- Across from 320	2	EA	7	10+ years	
	Walls - Concrete Block	3rd floor- Across from 320	592	SF	7	10+ years	
	Water Closet	3rd floor- Across from 320	2	EA	7	10+ years	
	Accessories	3rd floor- Across from 320	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor- Across from 320	210	SF	7	10+ years	
	Floor - Terrazzo	3rd floor- Across from 320	210	SF	7	10+ years	
	Floor Drain	3rd floor- Across from 320	1	EA	7	10+ years	
	Lavatory	3rd floor- Across from 320	3	EA	7	10+ years	
	Lighting - Lay-in	3rd floor- Across from 320	5	EA	7	6-10 years	
	Partitions	3rd floor- Across from 320	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd floor- Across from 320	600	SF	6	10+ years	
	Water Closet	3rd floor- Across from 320	4	ĒA	6	10+ years	
	Accessories	First floor Unisex- Across from Main	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor Unisex- Across from Main	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor Unisex- Across from Main	1	ĒA	7	10+ years	
	Floor - Terrazzo	First floor Unisex- Across from Main	45	SF	7	10+ years	
	Floor Drain	First floor Unisex- Across from Main	1	ĒA	7	10+ years	
	Lavatory	First floor Unisex- Across from Main	1	EA	7	10+ years	
	Lighting - Lay-in	First floor Unisex- Across from Main	1	EA	7	6-10 years	
	Walls - Concrete Block	First floor Unisex- Across from Main	210	SF	7	10+ years	
	Water Closet	First floor Unisex- Across from Main	1	ĒA	7	10+ years	
	Accessories	First floor- Across from Main	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor- Across from Main	210	SF	7	10+ years	
	Floor - Terrazzo	First floor- Across from Main	210	SF	7	10+ years	
	Floor Drain	First floor- Across from Main	1	EA	7	10+ years	
	Lavatory	First floor- Across from Main	3	EΑ	7	10+ years	
	Lighting - Lay-in	First floor- Across from Main	5	EA	7	6-10 years	
	Partitions	First floor- Across from Main	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	First floor- Across from Main	592	SF	7	10+ years	
					-	,	

Campus Name: Peirce Page : 33 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	First floor- Across from Main	4	EA	7	10+ years	
	Accessories	First floor- Across from Main Office	210	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor- Across from Main Office	210	SF	7	10+ years	
	Floor - Terrazzo	First floor- Across from Main Office	210	SF	6	10+ years	
	Floor Drain	First floor- Across from Main Office	1	EA	7	10+ years	
	Lavatory	First floor- Across from Main Office	3	EA	6	10+ years	
	Lighting - Lay-in	First floor- Across from Main Office	5	EA	7	6-10 years	
	Partitions	First floor- Across from Main Office	2	EA	7	10+ years	
	Urinals	First floor- Across from Main Office	2	EA	7	10+ years	
	Walls - Concrete Block	First floor- Across from Main Office	592	SF	7	10+ years	
	Water Closet	First floor- Across from Main Office	2	EA	7	10+ years	
	Accessories	Rm 120D, In main office	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 120D, In main office	51	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 120D, In main office	1	EA	7	10+ years	
	Floor - Tile	Rm 120D, In main office	51	SF	7	10+ years	
	Floor Drain	Rm 120D, In main office	1	EA	7	10+ years	
	Lavatory	Rm 120D, In main office	1	EA	7	10+ years	
	Lighting - Lay-in	Rm 120D, In main office	1	EA	7	6-10 years	
	Walls - Concrete Block	Rm 120D, In main office	284	SF	7	10+ years	
	Water Closet	Rm 120D, In main office	1	EA	7	10+ years	
	Accessories	first floor, class 121	38	SF	7	6-10 years	
	Ceiling - Lay-in	first floor, class 121	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	first floor, class 121	1	EA	7	10+ years	
	Floor - Tile	first floor, class 121	38	SF	7	10+ years	
	Floor Drain	first floor, class 121	1	EA	7	10+ years	
	Lavatory	first floor, class 121	1	EA	7	10+ years	
	Lighting - Lay-in	first floor, class 121	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	first floor, class 121	196	SF	6	10+ years	
	Water Closet	first floor, class 121	1	EA	6	10+ years	
	Accessories	first floor, class 122	38	SF	7	6-10 years	
	Ceiling - Lay-in	first floor, class 122	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	first floor, class 122	1	EA	7	10+ years	
	Floor - Tile	first floor, class 122	38	SF	7	10+ years	
	Floor Drain	first floor, class 122	1	EA	7	10+ years	
	Lavatory	first floor, class 122	1	EA	7	10+ years	
	Lighting - Lay-in	first floor, class 122	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	first floor, class 122	196	SF	6	10+ years	
	Water Closet	first floor, class 122	1	EA	6	10+ years	
	Accessories	first floor, class 123	38	SF	7	6-10 years	
	Ceiling - Lay-in	first floor, class 123	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	first floor, class 123	1	EA	7	10+ years	
	Floor - Tile	first floor, class 123	38	SF	7	10+ years	
	Floor Drain	first floor, class 123	1	EA	7	10+ years	
	Lavatory	first floor, class 123	1	EA	7	10+ years	
	•					•	

Campus Name: Peirce Page : 34 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Category : Room		В							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	first floor, class 123	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	first floor, class 123	196	SF	7	10+ years			
	Water Closet	first floor, class 123	1	EA	7	10+ years			
	Accessories	first floor, class 126	38	SF	7	6-10 years			
	Ceiling - Lay-in	first floor, class 126	38	SF	7	10+ years			
	Doors - Wood Doors inclu hw	first floor, class 126	1	EA	7	10+ years			
	Floor - Tile	first floor, class 126	38	SF	7	10+ years			
	Floor Drain	first floor, class 126	1	EΑ	7	10+ years			
	Lavatory	first floor, class 126	1	EA	7	10+ years			
	Lighting - Lay-in	first floor, class 126	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	first floor, class 126	196	SF	7	10+ years			
	Water Closet	first floor, class 126	1	EΑ	7	10+ years			
	Accessories	first floor, class 128	38	SF	7	6-10 years			
	Ceiling - Lay-in	first floor, class 128	38	SF	7	10+ years			
	Doors - Wood Doors inclu hw	first floor, class 128	1	EA	7	10+ years			
	Floor - Tile	first floor, class 128	38	SF	7	10+ years			
	Floor Drain	first floor, class 128	1	EA	7	10+ years			
	Lavatory	first floor, class 128	1	EA	7	10+ years			
	Lighting - Lay-in	first floor, class 128	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	first floor, class 128	196	SF	7	10+ years			
	Water Closet	first floor, class 128	1	EA	7	10+ years			

Category : Classroom Building : Addition

Category . Classicom		ט						
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroom #120C (Kindergarten)								
	Ceiling - Lay-in	1st Floor	337	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	337	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Marker Board	1st Floor	10	LF	7	6-10 years		
	Storage/ Closet	1st Floor	20	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	680	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
_Classroo	om #121 (Pre School)							
	Casework	1st Floor	66	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,073	SF	7	10+ years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,073	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years		
	Storage/ Closet	1st Floor	43	SF	7	10+ years		
	S .					,		

Campus Name: Peirce Page : 35 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Category : Classroom			В	uilding			
_			0	HOM	D	Recommend	•
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	504	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	504	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #122 (Pre School)						
	Casework	1st Floor	66	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,073	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,073	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	. 17	EA	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	616	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	504	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
`lassroo	m #123 (Pre School)						
71000100	Casework	1st Floor	66	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,098	SF	7	10+ years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,098	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	17,030	EA	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	876	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	247	SF	6	10+ years	
	Work Sink	1st Floor	247	EA	7	10+ years	
Nagaraa	m #126 (Kindergarten)						
<u> 1492100</u>	m #126 (Kindergarten) Casework	1st Floor	66	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,098	SF	7	10+ years 10+ years	
	Chalk Board	1st Floor	1,096	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	6	SF	7	10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years 10+ years	
	Floor - Tile	1st Floor	1,098	SF	7	10+ years 10+ years	
	Lighting - Lay-in	1st Floor	1,096	EA	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	876	SF SF	7		
		1st Floor		SF SF		10+ years	
	Walls - Plaster/Drywall		252		7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
locaroo	m #128 (Kindergarten)						

Campus Name: Peirce Page : 36 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Classroom		В	uilding	: Additi		W BIJIT Maw AVENUE, Officago, IE 00000
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	66	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,098	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,098	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	EA	7	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	876	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	252	SF	7	10+ years	
	Work Sink	1st Floor	2	ĒΑ	7	10+ years	
Classroo	om #220B (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	918	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	918	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	896	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	200	SF	6	10+ years	
Classroo	om #223 (Regular Classroom)						
Classiuc	Casework	2nd Floor	24	LF	7	10+ years	
		2nd Floor	852	SF	7	•	
	Ceiling - Lay-in				-	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	852	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	673	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #224 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	852	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	852	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	673	SF	7	10+ years	

Campus Name: Peirce Page : 37 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Category : Classroom		В	uilding	: Addition			
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroc	m #225 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	852	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	852	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	901	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	252	SF	7	10+ years	
	Work Sink	2nd Floor	1	EΑ	7	10+ years	
Classroc	m #228 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	852	SF	7	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	852	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	673	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	504	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
:lassroc	m #229 (Computer Lab)						
21400100	Casework	2nd Floor	6	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,019	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	•	
			· · · · · · · · · · · · · · · · · · ·	SF	7	10+ years	
	Floor - Tile	2nd Floor	1,019		7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA		10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	707	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	579	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroc	m #231 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	852	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	

Campus Name: Peirce Page : 38 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	852	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,177	SF	7	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
			1	EA		•	
	Doors - Wood Doors inclu hw	3rd Floor 3rd Floor	900	SF	7	10+ years	
	Floor - Tile				7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	841	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	251	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroc	om #321 (Regular Classroom)						
	Casework	3rd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	900	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Walls - Concrete Block	3rd Floor	767	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	502	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #322 (Regular Classroom)						
	Casework	3rd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile			SF	7		
		3rd Floor	900			10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	841	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	251	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	

Campus Name: Peirce Page : 39 of 59 Assessment Date: 02/09/2022



Category : Classroom			В	Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
01	#000 (D)							
Classroo	m #323 (Regular Classroom)	0.151	<u> </u>			40		
	Casework	3rd Floor	51	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	900	SF	6	10+ years		
	Chalk Board	3rd Floor	18	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	841	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	251	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	m #324 (Regular Classroom)							
	Casework	3rd Floor	51	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years		
	Chalk Board	3rd Floor	18	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	662	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	502	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
21								
Jassroo	m #325 (Regular Classroom)	0.151	5.4			40		
	Casework	3rd Floor	51	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	900	SF	7	10+ years		
	Chalk Board	3rd Floor	18	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	900	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Storage/ Closet	3rd Floor	841	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	969	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	40	SF	4	0-1 year	Major crack	
	Walls - Plaster/Drywall	3rd Floor	251	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	m #328 (Art Room)							
	Casework	3rd Floor	56	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,053	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	6	SF	6	10+ years		



Category : Classroom			В	Building : Addition					
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years			
	Floor - Tile	3rd Floor	1,053	SF	6	10+ years			
	Kiln	3rd Floor	1	EA	7	6-10 years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	18	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	156	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	767	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	502	SF	7	10+ years			
	Work Sink	3rd Floor	2	ĒΑ	7	10+ years			
lassroo	m #329 (Science Lab Level 1)								
	Casework	3rd Floor	56	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	1,044	SF	7	10+ years			
	Doors - Side-lite	3rd Floor	1,044	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,044	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	12	LF	7	6-10 years			
	Science Lab Elements	3rd Floor	18	SF	7	•			
	Storage/ Closet	3rd Floor	21	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	767	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	502	SF	7	10+ years			
	Work Sink	3rd Floor	302	EA	7	10+ years			
	WORK SILIK	314 11001	3	EA	,	10+ years			
lassroo	m #331 (Regular Classroom)								
	Casework	3rd Floor	48	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	848	SF	7	10+ years			
	Chalk Board	3rd Floor	18	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	848	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Walls - Concrete Block	3rd Floor	1,125	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	10+ years			
atego	ry : Interior		В	uilding	: Additi				
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
orridor		2000.011	Quantity	00	- tuint	. topiasomont			
OTHOOF	Calling Lavin	4 at Flags	4.000	C.E.	7	40			
	Ceiling - Lay-in	1st Floor	4,062	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	11	EΑ	7	10+ years			
	Doors - Wood Doors include hw	1st Floor	4	EΑ	7	10+ years			



Catego	ry : Interior		В	uildina	: Additi		W Bryll Maw Avenue, Officago, 12 00000
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	10+ years	
	Floor - Terrazzo	1st Floor	4,068	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	142	EA	7	6-10 years	
	Stairs - Concrete Stairs	1st Floor	23	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,434	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,304	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,000	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3,606	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	143	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor	6	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	4,714	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	, 116	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	5,207	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	3,616	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	143	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	4	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	3,616	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	116	ĒA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	52	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	5,207	SF	7	10+ years	
			-, -			, , , , , ,	
Safety							
,	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	5	6-10 years	
	Security Cameras	1st Floor	5	EA	5	6-10 years	
	·					•	
Stairs							
	Ceiling - Lay-in	By Door # 6 (SE)	315	SF	7	10+ years	
	Floor - Terrazzo	By Door # 6 (SE)	334	SF	7	10+ years	
	Handrails	By Door # 6 (SE)	108	LF	7	10+ years	
	Lighting - Lay-in	By Door # 6 (SE)	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	By Door # 6 (SE)	1	EA	7	6-10 years	
	Stairs - Terrazzo	By Door # 6 (SE)	54	LF	7	10+ years	
	Walls - Concrete Block	By Door # 6 (SE)	3,402	SF	7	10+ years	
	Ceiling - Lay-in	By Door #1 (NE)	315	SF	7	10+ years	
	Floor - Terrazzo	By Door #1 (NE)	334	SF	7	10+ years	
	Handrails	By Door #1 (NE)	108	LF	7	10+ years	
	Lighting - Lay-in	By Door #1 (NE)	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	By Door #1 (NE)	1	EA	7	6-10 years	
	Stairs - Terrazzo	By Door #1 (NE)	54	LF	7	10+ years	



Catego	ry : Interior		Building : Addition							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	By Door #1 (NE)	3,402	SF	7	10+ years				
	Ceiling - Lay-in	By Door #5 (SW)	315	SF	7	10+ years				
	Floor - Terrazzo	By Door #5 (SW)	334	SF	7	10+ years				
	Handrails	By Door #5 (SW)	108	LF	7	10+ years				
	Lighting - Lay-in	By Door #5 (SW)	6	EA	7	6-10 years				
	Lighting - Pendent/Surface	By Door #5 (SW)	1	EA	7	6-10 years				
	Stairs - Terrazzo	By Door #5 (SW)	54	LF	7	10+ years				
	Walls - Concrete Block	By Door #5 (SW)	3,402	SF	7	10+ years				
Vertical 0	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years				





Category : Exterior Building : Branch

	y i =xioiio.		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	· ·	Location	Quantity	OOM	Italik	Replacement	Comments
Еппапсе	Entrance Control - Audio and Video	1 Main	1	EA	7	6-10 years	
	Exterior Doors - Exterior AMP Door	1 Main	2	EA	7	•	
	Exterior Doors - Side lite	1 Main	2	EA	7	10+ years 10+ years	
	Power Door Operator and Controls	1 Main	1	EA	7	10+ years	
	Exterior Doors - Side lite		2	EA	7	•	
	Exterior Doors - Store Front	2	2		7 7	10+ years	
	Exterior Doors - Store Front Exterior Doors - Exterior Steel Door	2	2	EA EA	6	10+ years	Rusted at bottom
	Entrance Control - Audio and Video	3	1	EA	7	2-5 years	Rusieu ai bollom
		4	ı		7	10+ years	
	Exterior Doors - Side lite	4	2	EΑ	-	10+ years	
	Exterior Doors - Store Front	4	1	EA	7	10+ years	
Foundati	on						
	Foundation - Concrete	Throughout	8,350	LF	7	10+ years	
	Superstructure - Slab on Grade	Throughout	8,350	SF	7	10+ years	
Roof Sys	stem						
	Coping - Metal	Main Roof	380	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	380	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	8,350	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	ĒΑ	7	10+ years	Ladder doesn't extend to the floor.
	Roof Structure - Steel / Metal Deck/	Main Roof	8,350	SF	7	10+ years	
	Concrete Topping	Maii Rooi	0,000	O.	•	.o. youro	
\							
_Walls	Cutorion Walls Driek	Fatina Divildia a	F 000			10	
	Exterior Walls - Brick	Entire Building	5,000	SF	6	10+ years	
	Exterior Walls - Vinyl Siding	Entire Building	10,000	SF	7	10+ years	
Windows	3						
	Windows - Sash Aluminum Double-pane	Entire Building	200	SF	7	10+ years	

Category : Electrical Building : Branch

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Emerger	ncy System						
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	7	10+ years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	7	10+ years	
	Security System - CCTV	Entire Building	8,350	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	8,350	SF	7	6-10 years	



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Electrical		В	uilding	: Brancl	h	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Exit Signs - Corridors and Stairs	Entire Building	8	EA	7	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	7	6-10 years	
∕ain Se	nico						
nain se		Floatrical Doom	4	ГΛ	7	10	Doom 117
	Main Electrical Service - 800 A and Less than 120/208/3PH	Electrical Room	1	EA	7	10+ years	Room 117
	PA System	Entire Building	8,350	SF	7	6-10 years	
Ower D	vistribution						
OWCI D	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Room 116B
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	ROOM TIOB
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	•	Room 117
	Main Distribution Panels - 400 - 600 amp	Entire building	ı	EA	/	10+ years	Room 117
Catego	ry : Fire Protection		В	uilding	: Brancl		
_						Recommend	
Froup Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Room 116B
	Fire Alarm Strobe Lights	Entire Building	8,350	SF	7	10+ years	1100111 1102
	Fire Alarm_System	Entire Building	8,350	SF	7	10+ years	
	/a		0,000	О.	-	.o. yea.e	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	8,350	SF	7	10+ years	
	Sprinkler Piping	Entire Building	8,350	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	8,350	SF	7	10+ years	
_	· · · · ·	, , , , , , , , , , , , , , , , , , ,				-	
Catego	ry : Mechanical		В	uilding	: Brancl		
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Conc	litioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	10+ years	
Air Hand	lling Systems						
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10	Roof	1	EA	6	6-10 years	RTU-2, serves Room 103
	tons Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10+ years	RTU-5, serves Room 101
	tons	Roof	1	EA EA	6	10+ years	RTU-5, serves Room 101 RTU-6, serves Room 100



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Mechanical		В	uilding	: Branc		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heating and DX Cooling Coil - 5 - 10						
	tons				_		
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-1 serves front office area,
	Gas Heating and DX Cooling Coil - 5 - 10						kitchen, corridors, and north closet
	tons						spaces
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	10+ years	RTU-4, serves Room 102
	Gas Heating and DX Cooling Coil - 5 - 10						
	tons						
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	RTU-3, serves Room 104
	Gas Heating and DX Cooling Coil - 5 - 10					•	
	tons						
leating	Devices						
	Wall Heater - Electric	Entire Building	10	EA	7	10+ years	
	Radiator Panels - Electric	Entire Building	15	EA	7	10+ years	
		G				j	
empera	ture Control						
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-1
	Electric Thermostat	Entire Building	6	EA	7	10+ years	Temperature control for the radiate
							panels
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-2
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-4
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-5
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-6
	Electric Thermostat	Entire Building	1	EA	7	10+ years	Room 116B
	Electric Thermostat	Entire Building	1	EA	7	10+ years	For RTU-3
entilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	Room 121
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	6	EA	7	10+ years	Restroom exhaust fans
`ataga	ru i Diumbina		ь	uildina	. Pranc	h	
alego	ry : Plumbing		D	unung	: Branc	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Room 118	1	EA	7	10+ years	Inside unisex restroom (Room 119) Installed in 2021.
Piping							
, -9	Domestic Piping-Hot Water Return Lines	Entire Building	8,350	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	8,350	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	8,350	SF	7	10+ years	
	Fixtures	.	2,000	-		- ,	
							A . D . 00/00/

Campus Name: Peirce Page: 46 of 59 Assessment Date: 02/09/2022



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Plumbing		В	uilding	: Branc	h	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	8,350	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	8,350	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	8,350	SF	7	10+ years	
	Sanitary Piping	Entire Building	8,350	SF	7	10+ years	
	Storm Piping	Entire Building	8,350	SF	7	10+ years	
	Vent Piping	Entire Building	8,350	SF	7	10+ years	
Catego	ry : Room		В	uildina	: Branc	h	
o ano go	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	Meeting Room 113	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Meeting Room 113	1	EA	7	6-10 years	
	Floor - Tile	Meeting Room 113	80	SF	7	10+ years	
	Lighting - Lay-in	Meeting Room 113	1	EA	7	6-10 years	
	Power Distribution	Meeting Room 113	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Meeting Room 113	210	SF	7	10+ years	
	Ceiling - Lay-in	Office 112	85	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office 112	1	EA	7	6-10 years	
	Floor - Tile	Office 112	85	SF	7	10+ years	
	Lighting - Lay-in	Office 112	2	EA	7	6-10 years	
	Power Distribution	Office 112	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Office 112	210	SF	7	10+ years	
_Kitchen							
	Ceiling - Exposed	1st Floor	328	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	328	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
_MDF_ID	<u> </u>						
	Doors - Steel Doors incl hw	116B	1	EA	7	10+ years	
	Finishes	116B	100	SF	7	10+ years	
Mechani	cal/ Service Rooms					•	
_wechall	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	62	SF SF	7	10+ years 10+ years	
	Storage Room	1st Floor	130	SF	7	10+ years 10+ years	
	Storage Room	1st Floor	130	SF	7	10+ years 10+ years	
	Glorage Room	13(1100)	130	OI.	,	10+ years	

Campus Name: Peirce Page: 47 of 59 Assessment Date: 02/09/2022



atego	ategory : Room		В	Building : Branch				
	H T	I di	0	11015	D !	Recommend	0	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
estroor	~							
esirooi	Accessories	121A	50	SF	7	6-10 years		
	Ceiling - Lay-in	121A	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	121A	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	121A	50	SF	7	10+ years		
	Floor Drain	121A	1	EA	7	10+ years		
	Hand Dryer	121A 121A	1	EA	7	6-10 years		
	Lavatory	121A 121A	1	EA	7	10+ years		
	Lighting - Lay-in	121A 121A	2	EA	7			
			35	SF	7	6-10 years		
	Walls - Plaster/Drywall	121A				10+ years		
	Walls - Tile Ceramic/ Porcelain	121A	40	SF	7	10+ years		
	Water Closet	121A	1	EA	7	10+ years		
	Accessories	In 101	50	SF	7	10+ years		
	Ceiling - Plaster/Drywall	In 101	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	In 101	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	In 101	50	SF	7	10+ years		
	Floor Drain	In 101	1	EA	7	10+ years		
	Lavatory	In 101	1	EA	7	6-10 years		
	Lighting - Lay-in	In 101	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	In 101	60	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	In 101	180	SF	7	10+ years		
	Water Closet	In 101	1	EA	7	10+ years		
	Accessories	In 102	50	SF	7	10+ years		
	Ceiling - Plaster/Drywall	In 102	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	In 102	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	In 102	50	SF	7	10+ years		
	Floor Drain	In 102	1	EA	7	10+ years		
	Lavatory	In 102	1	EA	7	6-10 years		
	Lighting - Lay-in	In 102	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	In 102	60	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	In 102	180	SF	7	10+ years		
	Water Closet	In 102	1	EA	7	6-10 years		
	Accessories	Inside 103	70	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Inside 103	70	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Inside 103	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Inside 103	70	SF	7	10+ years		
	Floor Drain	Inside 103	1	EA	7	10+ years		
	Hand Dryer	Inside 103	1	EA	7 7	-		
	•	Inside 103				6-10 years		
	Lavatory		1	EΑ	7	10+ years		
	Lighting - Lay-in	Inside 103	2	EA	7	6-10 years		
	Walls - Plaster/Drywall	Inside 103	30	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Inside 103	90	SF	7	10+ years		
	Water Closet	Inside 103	1	EA	7	10+ years		



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Room		В	uilding	: Branc	h	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Inside 104	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Inside 104	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside 104	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside 104	70	SF	7	10+ years	
	Floor Drain	Inside 104	1	EA	7	10+ years	
	Hand Dryer	Inside 104	1	EA	7	6-10 years	
	Lavatory	Inside 104	1	EA	7	10+ years	
	Lighting - Lay-in	Inside 104	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Inside 104	30	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Inside 104	90	SF	7	10+ years	
	Water Closet	Inside 104	1	EA	7	10+ years	
	Accessories	Unisex 119	80	SF	7	6-10 years	
	Ceiling - Exposed	Unisex 119	40	SF	7	10+ years	
	Ceiling - Lay-in	Unisex 119	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex 119	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex 119	80	SF	7	10+ years	
	Floor Drain	Unisex 119	1	EA	7	10+ years	
	Hand Dryer	Unisex 119	1	EA	7	6-10 years	
	Lavatory	Unisex 119	1	EA	7	10+ years	
	Lighting - Lay-in	Unisex 119	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex 119	120	SF	7	10+ years	
	Water Closet	Unisex 119	1	EA	7	10+ years	

Category : Classroom Building : Branch

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #101 (Regular Classroom)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	920	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,525	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
_Classro	om #102 (Regular Classroom)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years	
	Floor - Tile	1st Floor	920	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	

Campus Name: Peirce Page : 49 of 59 Assessment Date: 02/09/2022



Helen Peirce International Studies ES 1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Classroom		B	uildina	: Branc	<u></u> h	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,525	SF	7	10+ years	
	Work Sink	1st Floor		EA	7	6-10 years	
						,	
lassroo	om #103 (Kindergarten)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	920	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,360	SF	7	10+ years	
	Work Sink	1st Floor	1,300	EA	7	6-10 years	
	WORK OHIK	13(1100)			,	o io years	
lassroc	om #104 (Kindergarten)						
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	920	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,360	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
lassroc	om #Playroom 100 (Play Room)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	850	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
atego	ry : Interior		В	uildina	: Branc	h	
J-						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	1,120	SF	7	10+ years	
	Doors - Store Front	1st Floor	4	EA	7	10+ years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Interior		Building : Branch						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years			
	Floor - Tile/Sheet	1st Floor	1,120	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	25	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,790	SF	7	10+ years			
Safety									
•	Security Cameras	1st Floor	3	EA	7	6-10 years			

Campus Name: Peirce Page : 51 of 59 Assessment Date: 02/09/2022





Category : Exterior		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#1 E	1	EA	7	6-10 years	
	Exterior Stairs - Concrete	#1 E	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2 E	1	EA	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#2 E	86	LF	6	6-10 years	
	Ramps - Concrete	#2 E	45	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3 W	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4 W	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5 W	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6 E	8	LF	6	6-10 years	
	Extend Grane Controls	,, o _	· ·		Ü	o lo youlo	
Foundati		Fatire Desiration	4.057	LF		40	
	Foundation - Concrete	Entire Building	1,857	LF	7	10+ years	
Roof Sys							
	Downspouts - Exterior Downspouts	Entire Building	80	LF	6	6-10 years	
	Roof - Metal	Entire Building	1,857	SF	4	0-1 year	Severely rusted throughout
	Roof Structure - Steel / Metal Deck/	Entire Building	1,857	SF	7	10+ years	
	Concrete Topping	•				•	
Walls							
	Exterior Walls - Brick	Entire Building	18,570	SF	5	10+ years	Cracked/ chipped bricks
	Exterior Walls - Stone-Cut	Entire Building	828	SF	6	10+ years	
		g	020	.	· ·	.o. yea.e	
Windows		Fatina Divilation	200			0.40	
	Guard - Guards perforated	Entire Building	336	SF	6	6-10 years	
	Lintels - Brick	Entire Building	122	LF	6	10+ years	
	Lintels - Stone	Entire Building	4	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	336	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Field I		
0	Hama Tama	Landlan	• "	11014	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	6	6-10 years	One unit needs new bulb(s) but otherwise units have been upgrade since last assessment and meet

Campus Name: Peirce Page: 52 of 59 Assessment Date: 02/09/2022



XP.	Schools						W Bryn Mawr AVENUE, Chicago, IL 60660
Catego	ry : Electrical		В	uilding	: Field F		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
							legibility requirements. Quantity changed to match current observations.
	Security System - Intrusion Detection	Entire Building	1,825	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	Quantity changed to match current observations.
Main Se	rvice						
	Main Electrical Service - 800 A and 120/208/3PH	1st Floor	1	EA	4	2-5 years	Vintage equipment; deteriorated.
Catego	ry : Mechanical		В	uilding	: Field H		
_			• 414			Recommend	
Group	Item - Type Devices	Location	Quantity	UOM	Rank	Replacement	Comments
<u>leaung</u>	Gas/ Natural Draft Furnace - 101 - 200 MBH	1st Floor	1	EA	6	10+ years	Unit is three years old per Building Engineer
Tempera	ature Control						
	Electric Controls	1st Floor	1,825	SF	6	2-5 years	Control circuits are internal to the furnace
	Electric Thermostat	1st Floor	1	EA	6	2-5 years	
/entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	3	0-1 year	Located in the attic space above the restrooms and not accessible in a safe manner at the time of assessment. Based on current observations and per Building Engineer, units have been nonfunctional for several years.
Catego	ry : Plumbing		В	uildina	: Field H	louse	
30						Recommend	
Group Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ioi vvali	Gas Heater - Less than 150000 BTU/HR	1st Floor	1	EA	5	2-5 years	Older unit with no leaks or severe deterioration observed, but approaching the end of its service life
Piping							
F8	Domestic Piping-Hot Water Return Lines	Entire Building	1,825	SF	6	10+ years	
			D				A

Campus Name: Peirce Page : 53 of 59 Assessment Date: 02/09/2022



Group

Category : Plumbing

Item - Type

Domestic Piping-Hot Water from Risers to

Helen Peirce International Studies ES

Building: Field House

Rank

6

UOM

SF

Quantity

1,825

Recommend

10+ years

Replacement Comments

1423 W Bryn Mawr AVENUE, Chicago, IL 60660

	Fixtures	3	,	_		, , , , , ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	1,825	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	1,825	SF	6	10+ years	
	(from Risers to Fixtures)				_		
	Sanitary Piping	Entire Building	1,825	SF	6	10+ years	
	Storm Piping	Entire Building	1,825	SF	6	10+ years	One section has fallen away from the
							building exterior and is being stored inside.
	Vent Piping	Entire Building	1,825	SF	6	10+ years	inside.
	vent i ping	Littine Building	1,020	Oi	O	10+ years	
Catego	ry : Classroom		В	uilding	: Field H	louse	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #North (Play Room)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	450	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	798	SF	7	10+ years	
Classroo	om #South (Play Room)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	450	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	798	SF	7	10+ years	
Catego	ry : Room		В	uildina	: Field H	louse	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	ical/ Service Rooms		•				
	Mechanical/ Service Rooms	1st Floor	95	SF	5	10+ years	
Restroor	m						
	Accessories	In North classroom	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In North classroom	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In North classroom	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	In North classroom	45	SF	4	0-1 year	Chipping throughout
	Floor Drain	In North classroom	1	EA	7	10+ years	5 5
			_				
Campus I	Name: Peirce		Page : 54 of 59				Assessment Date: 02/09/202

Location

Entire Building



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	Category : Room				Building : Field House						
			Recommend								
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Lavatory	In North classroom	1	EA	4	0-1 year	Crack				
	Lighting - Pendent/Surface	In North classroom	1	EA	7	6-10 years					
	Partitions	In North classroom	1	EA	4	0-1 year	Missing door				
	Walls - Structural Glazed Tile	In North classroom	238	SF	7	10+ years					
	Water Closet	In North classroom	1	EA	7	10+ years					
	Accessories	In South classroom	45	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	In South classroom	45	SF	7	10+ years					
	Doors - Wood Doors inclu hw	In South classroom	1	EA	7	10+ years					
	Floor - Epoxy/ Painted	In South classroom	45	SF	4	1-2 years	Chipping				
	Floor Drain	In South classroom	1	EA	7	10+ years					
	Lavatory	In South classroom	1	EA	4	0-1 year	Cracked				
	Lighting - Pendent/Surface	In South classroom	1	EA	7	6-10 years					
	Partitions	In South classroom	1	EA	4	0-1 year	Damaged and door missing				
	Urinals	In South classroom	2	EA	7	10+ years	-				
	Walls - Structural Glazed Tile	In South classroom	238	SF	7	10+ years					
	Water Closet	In South classroom	1	EA	7	10+ years					

Category : Interior Building : Field House

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	299	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	299	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	657	SF	7	10+ years	





Category : Site Building : Site

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	item - Type	Location	Quantity	OOW	Italik	Replacement	Comments
hletic	0 () 1 1	0 1 10 1	10.010				
	Surface - Asphalt	Central Courtyard	13,613	SF	4	0-1 year	Cracking throughout. Partially
		0 1 15 11 11/0	10.474	05	-	40	covered with snow.
	Surface - Synthetic including exc & retention	Courtyard Football/Soccer	16,174	SF	7	10+ years	
Civil/Draii	nage						
<i>31</i> V 11/ L2 1 (21)	Civil/ Drainage - Catch Basin	Entire Site	11	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	10+ years	
	Trainings The maintener	5 5			· ·	.o. you.o	
encing							
	Fencing - Guard Rail	Entire Site	60	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,932	LF	6	6-10 years	
	Fencing - Old Standard Ornamental	Entire Site	500	LF	6	6-10 years	
	Fencing - Old Standard Ornamental	Entire Site	10	LF	4	0-1 year	Bent
Landscap	De Benches	Entire Site	19	EA	6	10+ years	
	Irrigation	Entire Site	29,835	SF	5	2-5 years	
	Landscape - Grass	Entire Site	34,607	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	15,479	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,879	SF	5	6-10 years	
	Landscape - Hardscape - Pavers	Entire Site	304	SF	6	10+ years	
	Landscape - Hardscape - Pavers	Entire Site	30	SF	4	0-1 year	Missing, cracked and separating
	Lighting - Pole Mounted	Entire Site	14	EA	6	6-10 years	wissing, cracked and separating
	Parkway trees	Entire Site	32	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	6,425	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	6,239	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	100	SF	6	10+ years	
	Trash Receptacles	Entire Site	8	EA	6	10+ years	
	Trasif Receptacies	Little Site	0	LA	Ü	10+ years	
Parking L							
	Concrete Curbs	East	388	LF	6	10+ years	
	Lighting - Pole Mounted	East	21	EA	6	6-10 years	
	Surface - Asphalt	East	15,489	SF	6	10+ years	
	Surface - Concrete	East	1,661	SF	6	10+ years	
	Trash Compactor	East	1	EA	6	6-10 years	
	Vehicular Screening	East	304	LF	6	10+ years	
Playgrour	nd						
aygroui	Equipment - School Age 5-12	Entire Site	3	EA	6	6-10 years	
			U	EA	•	6-10 years	



1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Catego	ry : Site		Building : Site					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Surface - Poured Surface	Entire Site	6,239	SF	6	6-10 years		
Sidewalk	KS.							
	Sidewalks - Internal Walks	Entire Site	594	LF	6	10+ years		
	Sidewalks - Internal Walks	Entire Site	100	LF	4	0-1 year	Cracking	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,342	SF	6	10+ years	-	
Signage								
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years		
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years		
	Monument - Sign	Entire Site	1	EA	6	10+ years		

Definitions

- · Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Peirce Page: 57 of 59 Assessment Date: 02/09/2022

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	mionada coago	ittom zocanon	- Tunnon	Turibo.	(0. /	700	711.00	Clop	
Dance Room	Regular Classroom	2nd Floor	205	205	866	76	40	Y	N
Kindergarten	Kindergarten	1st Floor	110	Kindergarten	1,300	420	225	Υ	N
Kindergarten	Regular Classroom	2nd Floor	206B	206	554	82	44	Υ	Υ
Music Room	Regular Classroom	3rd Floor	305	305	888	168	90	Υ	Y
Office	Faculty Lounge	1st Floor	109	NA - Teacher Rm	333	224	120	Y	N
Regular Classroom	Library	3rd Floor	306B	306	602	168	90	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	888	224	120	Ý	N
Regular Classroom	Regular Classroom	1st Floor	102	102	938	168	90	Y	N
Regular Classroom	Regular Classroom	1st Floor	103	103	938	168	90	Y	N
Regular Classroom	Regular Classroom	1st Floor	104	104	934	168	90	Ý	N
Regular Classroom	Regular Classroom	1st Floor	105	105	910	168	90	Y	N
Regular Classroom	Regular Classroom	2nd Floor	200	NA	415	84	45	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	888	168	90	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	903	168	90	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	909	168	90	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	908	168	90	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	927	134	70	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	881	114	59	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	938	168	90	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	879	168	90	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	300	NA	415	84	45	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	888	224	120	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	938	168	90	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	938	168	90	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	938	168	90	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	938	168	90	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	938	168	90	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	888	224	120	Y	Υ
Science	Regular Classroom	3rd Floor	303	303	909	168	90	Υ	Υ
Building : Addition									
Art Room	Art Room	3rd Floor	328	3-11	1,053	98	42	Υ	Y
Computer Lab	Computer Lab	2nd Floor	229	2-13	1,019	89	45	Υ	N
Kindergarten	Kindergarten	1st Floor	126	1-21	1,098	164	56	Υ	N
Kindergarten	Kindergarten	1st Floor	128	I-25	1,098	164	56	N	N
Kindergarten	Regular Classroom	1st Floor	120C	120C	337	164	56		
Pre School	Kindergarten	1st Floor	121	1-11	1,073	164	56	Υ	N





Play Room

Play Room

1423 W Bryn Mawr AVENUE, Chicago, IL 60660

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Pre School	Kindergarten	1st Floor	122	1-14	1,073	164	56	Y	N
Pre School	Kindergarten	1st Floor	123	1-17	1,098	164	56	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	220B	220B	918	89	45		
Regular Classroom	Regular Classroom	2nd Floor	223	2-07	852	89	45	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	224	2-08	852	89	45	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	225	2-09	852	113	57	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	228	2-12	852	89	45	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	231	2-17	852	89	45	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	320	3-02	900	155	28	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	321	3-03	900	98	42	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	322	3-04	900	155	28	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	323	3-05	900	155	28	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	324	3-06	900	98	42	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	325	3-07	900	155	28	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	331	3-16	848	98	42	Y	Υ
Science Lab Level 1	Regular Classroom	3rd Floor	329	3-12	1,044	98	42	Υ	Υ
Building : Branch									
Kindergarten	Kindergarten	1st Floor	103	103	920	120	0		
Kindergarten	Kindergarten	1st Floor	104	104	920	120	0		Υ
Play Room	Play Room	1st Floor	Playroom 100	100	850	800	0		
Regular Classroom	Regular Classroom	1st Floor	101	101	920	45	10		
Regular Classroom	Regular Classroom	1st Floor	102	102	920	45	10		
Building : Field House									
Play Room	Play Room	1st Floor	North	NA	450	165	83	N	N
	1 * _	<u> </u>			 	1	t	1	

1st Floor

South

NA

450

165

83

Ν

Ν