**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1958	2	25,067
Addition	1962	2	32,440
Campus Total			57,507

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Entrance Control - Audio and Video 1 S 1 EΑ 7 10+ years Exterior Doors - Exterior FRP Door 1 S 3 FΑ 7 10+ years Exterior Doors - Side lite 1 S 2 EΑ 7 10+ years 1 S Exterior Doors - Transom Lite 3 EΑ 7 10+ years Exterior Stairs - Concrete 1 S 12 LF 10+ years Exterior Doors - Exterior Steel Door 11 - Boiler Room 2 EΑ 4 0-1 year Dents/RustHardware Exterior Doors - Transom Lite 11 - Boiler Room 1 FΑ 6 6-10 years 8 F 2 7 Exterior Doors - Exterior FRP Door FΑ 10+ years 2 Exterior Doors - Side lite 8 F FΑ 10+ years Exterior Doors - Transom Lite 8 E 2 FΑ 7 10+ years ΙF Exterior Stairs - Concrete 8 F 24 10+ years Foundation Foundation - Concrete **Entire Building** 552 LF 7 10+ years Superstructure - Concrete **Entire Building** 25.067 SF 7 10+ years \_Liahtina Exterior Lighting - Wall Mounted **Entire Building** 6 EΑ 6 2-5 years Roof System Access Ladder - Metal 5 6-10 years Roof D 1 EΑ 1 F Coping - Metal Roof D 200 6 6-10 years



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	Roof D	15	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof D	2,331	SF	4	2-5 years	
	Roof Structure - Concrete	Roof D	2,331	SF	7	10+ years	
	Chimney - Metal Flue	Roof E	17	ĹF	7	6-10 years	
	Coping - Metal	Roof E	203	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof E	24	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof E	4,070	SF	4	2-5 years	Ballast is not covering Completely-
	Noor Noprial Graver Ballage	11001 2	1,070	O.	•	2 o youro	Missing in Spots.
	Roof Structure - Concrete	Roof E	4,070	SF	7	10+ years	wildowing in Opolo.
	Access Ladder - Metal	Roof F	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof F	28	LF	6	•	
	Liner	ROOI F	20	LF	O	10+ years	
	Coping - Metal	Roof F	428	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof F	72	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof F	9,333	SF	4	2-5 years	
	Roof Structure - Concrete	Roof F	9,333	SF	7	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	192	SF	6	10+ years	
	Canopy - Fabric	Entire Building	60	SF	6	2-5 years	Awning.
	Exterior Walls - Brick	Entire Building	5,522	SF	6	10+ years	3
	Exterior Walls - Brick	Entire Building	20	SF	4	1-2 years	Mortar Deterioration near Door #11 North Boiler Rm Tuck Point.
Vindows							
	Curtain wall - Glazed Double Pane	Entire Building	1,002	SF	6	6-10 years	
	Curtain wall - Insulated Panel	Entire Building	273	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	3,647	SF	6	6-10 years	
	Lintels - Steel	Entire Building	282	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	5,158	SF	5	2-5 years	
	pane	Entire Ballating	3,130	Oi.	0	2 0 years	
	Windows - Louver	Entire Building	73	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	cy System						
	Security System - CCTV	Entire Building	57,507	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	57,507	SF	5	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
	- 14	Entire Building	2	ΓΛ	6	C 10 veers	2 found
	Emergency Battery Packs - Lunchrooms	Entire Dullaina	2	EA	6	6-10 years	2 found



Catego	ry : Electrical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Room						
	Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,426	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,310	SF	6	10+ years	
Main Sei	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	25,067	SF	6	6-10 years	Connected to addition building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	7	10+ years	Functional panels rated 7
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EΑ	7	10+ years	Functional panels rated 7
	Main Bleanbauerri ariole 100 000 amp	Zimio Dananig	·	_, 、	•	101 youro	Tanononal pariolo ratoa r
Catego	ry : Fire Protection		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	Also serves addition building
	Fire Alarm Strobe Lights	Electrical Room	25,067	SF	6	10+ years	3
	Fire Alarm_System	Electrical Room	25,067	SF	6	10+ years	
			_0,00.	О.	· ·	.o. you.o	
Catego	ry : Mechanical		В	uilding	: Main		
Crown	Itam Type	Logotion	Ougatitu	UOM	Rank	Recommend	Comments
Group	Item - Type	Location	Quantity	UUIVI	Rdlik	Replacement	Comments
AIT Hand	lling Systems	Б. (				40	DTILO I I I I I I I I I I I I I I I I I I
	Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Electric and DX Cooling Coil - 4000-8000 cfm	Roof	1	EA	6	10+ years	RTU 2, serves lunchroom a d kitcher 2019 installation
	Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Electric and DX	Roof	1	EA	6	10+ years	RTU 1, serves gym, 2019 installation
	Cooling Coil - 8001-12000 cfm				_	4.0	D : (0040: : !! !!
	Air Intake	Roof	2	EA	6	10+ years	Part of 2019 installation



Catego	ry : Mechanical		В	uilding	: Main		004 E 00th 0111EE1, 01110ago, 1E 00010	
Calogo	. y · moonamoa.		_	unung		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Boiler Room	2	EA	6	10+ years		
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years		
	Combustion Dampers	Boiler Room	1	EA	6	10+ years		
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	6	10+ years	Serve main building, 2019 installation	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	2019 installation, connected in parallel with boiler in addition building	
_Heating	Devices							
	Fin Tube - Hot Water	Entire Building	154	LF	5	6-10 years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	2	EA	5	6-10 years		
_Mechani	cal Plumbing							
	Hydronic Supply and Return - Galvanized	Entire Building	400	LF	5	10+ years		
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	10+ years	2019 installation	
_Tempera	ature Control							
·	DDC System	Entire Building	25,227	SF	6	10+ years	Also serves addition building. Server located in addition building	
	Electric Thermostat	Entire Building	6	EA	5	6-10 years	Serve some cabinet heaters in corridors	
	Thermostats - DDC	Entire Building	19	EA	6	10+ years	Serve univents	
Unit Ven	tilation							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	19	EA	6	10+ years	2019 installation	
_Ventilatio	on							
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	10+ years	In kitchen	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	10+ years		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	10+ years		
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire supression	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years		
	Roof Mounted Duct Work	Roof	30	LF	6	10+ years		



Catego	ry : Plumbing		В	uilding	: Main		834 E 50th STREET, Chicago, IL 60615
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves main building, 2019 installation
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	25,067	SF	6	10+ years	Some Restrooms recently remodeled piping in restroom updated
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	25,067	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	25,067	SF	6	10+ years	
	Sanitary Piping	Entire Building	25,067	SF	6	10+ years	
	Storm Piping	Entire Building	25,067	SF	6	10+ years	
	Vent Piping	Entire Building	25,067	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	Counselors Office	188	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselors Office	1	EA	6	10+ years	
	Floor - Tile	Counselors Office	188	SF	6	10+ years	
	Lighting - Lay-in	Counselors Office	4	EA	6	6-10 years	
	Walls - Concrete Block	Counselors Office	486	SF	6	10+ years	
	AC Unit	Main office	2	EA	7	6-10 years	
		NA=:ff:				10	
	Ceiling - Lay-in	Main office	412	SF	6	10+ years	
	Doors - Steel Doors incl hw	Main office	2	EA	6	10+ years	
	Doors - Steel Doors incl hw Floor - Tile			EA SF	6 6	,	
	Doors - Steel Doors incl hw	Main office	2	EA SF EA	6	10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet	Main office Main office	2 412	EA SF EA SF	6 6	10+ years 10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in	Main office Main office Main office	2 412 7 8 547	EA SF EA SF SF	6 6 6	10+ years 10+ years 6-10 years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block Ceiling - Lay-in	Main office Main office Main office Main office	2 412 7 8	EA SF EA SF	6 6 6 7	10+ years 10+ years 6-10 years 10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block	Main office Main office Main office Main office Main office	2 412 7 8 547	EA SF EA SF SF SF EA	6 6 6 7 6	10+ years 10+ years 6-10 years 10+ years 10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile	Main office Main office Main office Main office Main office Main office Principal's Office Principal's Office Principal's Office	2 412 7 8 547 325	EA SF EA SF SF	6 6 7 6 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	Main office Main office Main office Main office Main office Main office Principal's Office Principal's Office	2 412 7 8 547 325 2	EA SF EA SF SF EA SF EA	6 6 7 6 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile	Main office Main office Main office Main office Main office Main office Principal's Office Principal's Office Principal's Office	2 412 7 8 547 325 2 325	EA SF EA SF SF EA SF	6 6 7 6 6 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Kitchen	Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Concrete Block Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	Main office Main office Main office Main office Main office Main office Principal's Office Principal's Office Principal's Office Principal's Office	2 412 7 8 547 325 2 325 6	EA SF EA SF SF EA SF EA	6 6 7 6 6 6 6	10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Tile	1st Floor	606	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Serving Line	1st Floor	19	LF	6	10+ years	
	Walls - Tile	1st Floor	890	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	Kitchen Locker Room/Restroom	63	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Locker Room/Restroom	41	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Locker Room/Restroom	22	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Locker Room/Restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Kitchen Locker Room/Restroom	22	SF	6	10+ years	
	Floor - Tile/Sheet	Kitchen Locker Room/Restroom	41	SF	7	10+ years	
	Lavatory	Kitchen Locker Room/Restroom	1	EA	6	10+ years	
	Lighting - Lay-in		2	EA	6	6-10 years	
	Walls - Concrete Block	Kitchen Locker Room/Restroom		SF			
		Kitchen Locker Room/Restroom	216		6	10+ years	
	Walls - Structural Glazed Tile	Kitchen Locker Room/Restroom	153	SF	6	10+ years	
	Water Closet	Kitchen Locker Room/Restroom	1	EA	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,310	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Tile	1st Floor	1,310	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	607	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	303	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	303	SF	6	10+ years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	489	SF	7	10+ years	
	Janitor's Closet	1st Floor	39	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	15	SF	7	10+ years	
	Storage Room	1st Floor	60	SF	7	10+ years	
	Storage Room	1st Floor	65	SF	7	10+ years	
	Vaults	1st Floor	40	SF	5	10+ years	
	Janitor's Closet	2nd Floor	38	SF	7	10+ years	
	Storage Room	2nd Floor 2nd Floor	33	SF	7	10+ years	
	Storage Room	2110 F1001	33	SF	,	10+ years	
Restroor							
	Accessories	101A	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	101A	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101A	1	EA	6	10+ years	
	Floor - Tile	101A	20	SF	6	10+ years	





Calegor	ry : Room		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	101A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	101A	1	EA	6	6-10 years	
	Walls - Concrete Block	101A	144	SF	6	10+ years	
	Water Closet	101A	1	EA	6	10+ years	
	Accessories	102A	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	102A	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	102A	1	EA	6	10+ years	
	Floor - Tile	102A	20	SF	6	10+ years	
	Lavatory	102A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	102A	1	EA	6	6-10 years	
	Walls - Concrete Block	102A	144	SF	6	10+ years	
	Water Closet	102A	1	EA	6	10+ years	
	Accessories	109A	61	SF	7	10+ years	
	Ceiling - Plaster/Drywall	109A	61	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	109A	61	SF	7	10+ years	
	Floor Drain	109A	1	EA	7	10+ years	
	Hand Dryer	109A	1	EA	7	10+ years	
	Lavatory	109A	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	109A	2	EA	7	10+ years	
	Walls - Plaster/Drywall	109A	142	SF	7	10+ years	
	Walls - Structural Glazed Tile	109A	96	SF	7	10+ years	
	Water Closet	109A	1	EA	7	10+ years	
	Accessories	1st Floor Boys	175	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Boys	155	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Boys	20	SF	5	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	5	10+ years	
	Floor - Terrazzo	1st Floor Boys	175	SF	6	10+ years	
	Floor Drain	1st Floor Boys	1	EA	7	10+ years	
	Lavatory	1st Floor Boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	3	EA	6	6-10 years	
	Partitions	1st Floor Boys	2	EA	7	10+ years	
	Urinals	1st Floor Boys	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Boys	234	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	234	SF	6	10+ years	
	Water Closet	1st Floor Boys	2	EA	6	10+ years	
	Accessories	1st Floor Girls	189	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Girls	189	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	5	10+ years	
	Floor - Terrazzo	1st Floor Girls	189	SF	6	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Lavatory	1st Floor Girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	3	EA	7	6-10 years	
	Partitions	1st Floor Girls	6	EA	7	10+ years	



Catego	ry : Room	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor Girls	161	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	161	SF	6	10+ years	
	Water Closet	1st Floor Girls	1	EA	6	10+ years	
	Accessories	1st Floor Unisex East	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Unisex East	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex East	1	EA	6	10+ years	
	Floor - Tile	1st Floor Unisex East	20	SF	6	10+ years	
	Lavatory	1st Floor Unisex East	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex East	1	EΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor Unisex East	144	SF	6	10+ years	
	Water Closet	1st Floor Unisex East	1	EΑ	6	10+ years	
	Accessories	1st Floor Unisex West	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Unisex West	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex West	1	EA	6	10+ years	
	Floor - Tile	1st Floor Unisex West	20	SF	6	10+ years	
	Lavatory	1st Floor Unisex West	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Unisex West	1	EΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor Unisex West	144	SF	6	10+ years	
	Water Closet	1st Floor Unisex West	1	EΑ	6	10+ years	
	Accessories	2nd Floor Boys	175	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Boys	175	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor Boys	175	SF	5	10+ years	
	Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
	Lavatory	2nd Floor Boys	3	EA	6	10+ years	Quantity changed to update current
							observation
	Lighting - Pendent/Surface	2nd Floor Boys	3	EΑ	6	6-10 years	
	Partitions	2nd Floor Boys	1	EA	7	10+ years	Quantity changed to update current
							observation
	Urinals	2nd Floor Boys	4	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor Boys	236	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Boys	236	SF	7	10+ years	
	Water Closet	2nd Floor Boys	1	EΑ	6	10+ years	Quantity changed to update current
							observation
	Accessories	2nd Floor Girl's	181	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's	181	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girl's	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor Girl's	181	SF	6	10+ years	
	Floor Drain	2nd Floor Girl's	1	EΑ	7	10+ years	
	Lavatory	2nd Floor Girl's	3	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girl's	3	EA	6	6-10 years	
	Partitions	2nd Floor Girl's	5	EA	7	10+ years	Quantity changed to update current
							observation
	Walls - Concrete Block	2nd Floor Girl's	240	SF	6	10+ years	

Campus Name: Reavis Page : 8 of 34 Assessment Date: 10/13/2021



Catego	ry : Room	В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	2nd Floor Girl's	240	SF	6	10+ years	
	Water Closet	2nd Floor Girl's	5	EA	6	10+ years	Quantity changed to update current observation
	Accessories	Counselor's Office	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counselor's Office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office	1	EA	6	10+ years	
	Floor - Tile	Counselor's Office	20	SF	6	10+ years	
	Lavatory	Counselor's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Counselor's Office	1	EA	6	6-10 years	
	Walls - Concrete Block	Counselor's Office	144	SF	6	10+ years	
	Water Closet	Counselor's Office	1	EA	6	10+ years	
	Accessories	Principal's Office	20	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	10+ years	
	Floor - Tile	Principal's Office	20	SF	6	10+ years	
	Lavatory	Principal's Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office	1	EA	6	6-10 years	
	Walls - Concrete Block	Principal's Office	158	SF	6	10+ years	
	Water Closet	Principal's Office	1	EA	6	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	847	SF	6	10+ years	
	Doors - Transom Window	1st Floor	96	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	

Group	item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	29	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	847	SF	6	10+ years	
	Doors - Transom Window	1st Floor	96	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	847	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	17	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	888	SF	6	10+ years	
_Classroo	om #102 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	5	10+ years	
	Ceiling - Lay-in	1st Floor	996	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	6	10+ years	
	Doors - Transom Window	1st Floor	13	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	996	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	6	6-10 years	

Campus Name: Reavis Page : 9 of 34 Assessment Date: 10/13/2021





C-4	m Classus and		D	ما الماني	. Mair		834 E 50th STREET, Chicago, IL 606
Catego	ry : Classroom		В	uilding	: Main	Б	
0	Hama Tura	Lastin	0	11014	Dani	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	17	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	956	SF	6	10+ years	
Classroc	om #103 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	779	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	787	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
Classroc	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	5	10+ years	
	Ceiling - Lay-in	1st Floor	787	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	787	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	17	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
laceroo	om #107 (Regular Classroom)						
21233100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	5	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	786	SF	6	10+ years	
	Doors - Transom Window	1st Floor	700	SF	6	10+ years 10+ years	
		1st Floor	1				
	Doors - Wood Doors inclu hw	1st Floor	•	EA SF	6 6	10+ years	
	Floor - Tile	1st Floor	786			10+ years	
	Lighting - Lay-in		12	EA LF	7	6-10 years	
	Marker Board	1st Floor	20		6	6-10 years	
	Walls - Concrete Block	1st Floor	779	SF	6	10+ years	
lassroc	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	785	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	785	SF	6	10+ years	



Categor	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	779	SF	6	10+ years	
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	24	LF	5	10+ years	
	Ceiling - Lay-in	1st Floor	787	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	777	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	10+ years	
Classroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	5	10+ years	
	Ceiling - Lay-in	1st Floor	786	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	776	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	779	SF	6	10+ years	
Classron	m #112 (Regular Classroom)						
Ciassico	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	788	SF	6	10+ years	
	Doors - Transom Window	1st Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	788	SF	6	•	
		1st Floor	12	EA	6	10+ years	
	Lighting - Lay-in				-	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	779	SF	6	10+ years	
Classroo	m #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	787	SF	6	10+ years	
	Doors - Transom Window	1st Floor	72	SF	6	10+ years	





Cataga	ry : Classroom		В	uilding	· Main		834 E 50th STREET, Chicago, IL 60615
Catego	ry : Classroom			ullaing	: wain	December	
Craum	Hom Type	Location	Quantitu	LIOM	Donk	Recommend	Comments
Group	Item - Type Doors - Wood Doors inclu hw	Location 1st Floor	Quantity 1	UOM EA	Rank 6	Replacement 10+ years	Comments
	Floor - Tile	1st Floor		SF	6	•	
			787		-	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	780	SF	6	10+ years	
Classroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
	Walls - Collete Block	2110 1 1001	700	OI.	O	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
Classice	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	700	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	•	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
					-	10+ years	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	12 20	EA LF	6 6	6-10 years	
			-	SF	-	6-10 years	
	Walls - Concrete Block	2nd Floor	788	SF.	6	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	3				-	<b>,</b>	





`atoao	ry : Classroom		D	uilding	· Main		
Jalego	ry . Classiooni		В	unung			
- Parim	Hom. Tyme	Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type Doors - Transom Window	2nd Floor		SF	Rank	Replacement	Comments
			72		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	7	10+ years	
lassroc	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	No counter observed
	Ceiling - Lay-in	2nd Floor	788	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
lassroc	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	7	10+ years	No counter observed
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
Classroc	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
				-	-	- <b>,</b>	
Classroc	m #208 (Regular Classroom)	0.15					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	788	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	

Campus Name: Reavis Page: 13 of 34 Assessment Date: 10/13/2021



## William C Reavis Math & Science Specialty ES 834 E 50th STREET, Chicago, IL 60615

		Category : Classroom			: Main		
·						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	788	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	786	SF	6	10+ years	
ategory	y : Interior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	nom Typo	Location	Quantity	oo	rtanit	пориссинент	
	Ceiling - Lay-in	1st Floor	2,312	SF	7	10+ years	
	Doors - Store Front	1st Floor	9	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years	New asset
	Floor - Tile/Sheet	1st Floor	2,312	SF	7	10+ years	Square footage adjustment
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	847	SF	6	10+ years	
	Walls - Masonry	1st Floor	300	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	847	SF	6	10+ years	
	Ceiling - Splined	1st Floor West	701	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor West	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor West	1	EA	7	6-10 years	New asset
	Floor - Tile/Sheet	1st Floor West	701	SF	7	10+ years	Observed- in good condition
	Lighting - Lay-in	1st Floor West	6	EA	6	6-10 years	· ·
	Walls - Masonry	1st Floor West	890	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,457	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,457	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	, 14	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	588	SF	6	10+ years	
	Walls - Masonry	2nd Floor	300	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,177	SF	6	10+ years	
afety							
	Security Cameras	1st Floor	10	EA	7	6-10 years	
tairs							
	Ceiling - Lay-in	East	419	SF	6	10+ years	
	Ceiling - Plaster/Drywall	East	90	SF	6	10+ years	
	Floor - Tile	East	486	SF	6	10+ years	
	Handrails	East	48	LF	7	10+ years	
	Lighting - Lay-in	East	3	EA	6	10+ years	
	Stairs - Tile	East	107	LF	6	10+ years	
	Walls - Masonry	East	878	SF	6	10+ years	
	Ceiling - Lay-in	West	295	SF	7	10+ years	
	,					•	

Campus Name: Reavis Page : 14 of 34 Assessment Date: 10/13/2021



Catego	ry : Interior	Building : Main						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	West	91	SF	6	10+ years		
	Ceiling - Splined	West	122	SF	6	10+ years		
	Floor - Tile	West	485	SF	6	10+ years		
	Handrails	West	48	LF	7	10+ years		
	Lighting - Lay-in	West	3	EA	6	10+ years		
	Stairs - Tile	West	107	LF	6	6-10 years		
	Walls - Masonry	West	927	SF	6	10+ years		

Campus Name: Reavis Page : 15 of 34 Assessment Date: 10/13/2021





Category : Exterior **Building: Addition** 

exterior Doors - Exterior FRP Door exterior Doors - Transom Lite exterior Doors - Exterior FRP Door	Location 10 E	Quantity	UOM	Rank	Recommend Replacement	Comments
exterior Doors - Exterior FRP Door exterior Doors - Transom Lite	10 E	_	UOW	Kank	Replacement	Comments
xterior Doors - Transom Lite						
xterior Doors - Transom Lite						
		2	EA	6	6-10 years	
Exterior Doors - Exterior FRP Door	10 E	1	EA	6	6-10 years	
	2 S	2	EA	7	10+ years	
exterior Doors - Side lite	2 S	2	EA	7	10+ years	
xterior Doors - Transom Lite	2 S	2	EA	7	10+ years	
xterior Doors - Exterior FRP Door	3 N	2	EA	7	10+ years	
xterior Doors - Transom Lite	3 N	1	EA	7	10+ years	
xterior Doors - Exterior FRP Door		4				
xterior Doors - Transom Lite		4	EA	7		
xterior Stairs - Concrete		12	LF	6	10+ years	
xterior Doors - Exterior FRP Door		2	EΑ	7	10+ years	
xterior Doors - Side lite	5 W - Boiler Room Entrance	1	EA	7	10+ years	
xterior Doors - Transom Lite	5 W - Boiler Room Entrance	1	EA	7	10+ years	
xterior Doors - Exterior FRP Door	6 N	4	EA	7	10+ years	
xterior Doors - Transom Lite	6 N	4	EA	7	10+ years	
xterior Stairs - Concrete	6 N	12	LF	6	10+ years	
xterior Doors - Exterior FRP Door	7 E	4	EA	7	10+ years	
xterior Doors - Transom Lite	7 E	4	EA	7	10+ years	
oundation - Concrete	Entire Building	635	LF	7	10+ years	
Superstructure - Concrete	Entire Building	32,440	SF	7	10+ years	
exterior Lighting - Wall Mounted	Entire Building	13	EA	6	2-5 years	
m	D4 A		Ε.Δ.	7	0.40	
						Creaks and Failure in Marter laints
•	ROOT A	39	LF	5	1-2 years	Cracks and Failure in Mortar Joints -
	D (A	470	. –	•	0.40	Structure Integrity Failed/Damaged.
						0.60
Roof - Asphalt Gravel Ballast	Roof A	12,480	SF	4	1-2 years	Soft Spots, Missing Ballast with Water Puddling.
Roof Hatch - Metal	Roof A	1	EA	7	6-10 years	-
Roof Structure - Concrete	Roof A	12,480	SF	7	10+ years	
Access Ladder - Metal	Roof B	1	EA	7	10+ years	
Coping - Metal	Roof B	280	LF	6		
	Roof B	144	LF			
				5		No Skylights Present on Roof.
Roof Structure - Concrete	Roof B			7		, 3
	exterior Stairs - Concrete exterior Doors - Exterior FRP Door exterior Doors - Side lite exterior Doors - Transom Lite exterior Doors - Exterior FRP Door exterior Doors - Transom Lite exterior Stairs - Concrete exterior Doors - Exterior FRP Door exterior Doors - Exterior FRP Door exterior Doors - Transom Lite exterior Doors - Transom Lite exterior Lighting - Wall Mounted exterior Downspouts exterior Concrete / Concrete / Mortar / Mort	xterior Doors - Transom Lite	A	A	Atterior Doors - Transom Lite	xterior Doors - Transom Lite         4 - Parking Lot, Staff Entrance         4 EA         7 10+ years           xterior Stairs - Concrete         4 - Parking Lot, Staff Entrance         12 LF         6 10+ years           xterior Doors - Exterior FRP Door         5 W - Boiler Room Entrance         2 EA         7 10+ years           xterior Doors - Side lite         5 W - Boiler Room Entrance         1 EA         7 10+ years           xterior Doors - Side lite         5 W - Boiler Room Entrance         1 EA         7 10+ years           xterior Doors - Exterior FRP Door         6 N         4 EA         7 10+ years           xterior Doors - Exterior FRP Door         6 N         4 EA         7 10+ years           xterior Doors - Exterior FRP Door         7 E         4 EA         7 10+ years           xterior Doors - Exterior FRP Door         7 E         4 EA         7 10+ years           xterior Doors - Exterior FRP Door         7 E         4 EA         7 10+ years           xterior Doors - Exterior FRP Door         7 E         4 EA         7 10+ years           xterior Lighting - Wall Mounted         Entire Building         635 LF         7 10+ years           xterior Lighting - Wall Mounted         Entire Building         1 EA         7 6-10 years           xterior Lighting - Wall Mounted         Roof A </td

Campus Name: Reavis Page : 16 of 34 Assessment Date: 10/13/2021



Catego	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Roof C	1	EΑ	7	6-10 years	
	Coping - Metal	Roof C	65	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof C	48	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof C	3,557	SF	4	2-5 years	
	Roof Hatch - Metal	Roof C	1	EA	7	6-10 years	
	Roof Structure - Concrete	Roof C	3,557	SF	7	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	452	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,113	SF	6	10+ years	
Vindows	3						
	Curtain wall - Glazed Double Pane	Entire Building	416	SF	6	6-10 years	
	Curtain wall - Glazed Double Pane	Entire Building	8	SF	5	0-1 year	Significant Damage-Cracked/Holes
	Curtain wall - Insulated Panel	Entire Building	98	SF	6	6-10 years	Ç Ç
	Guard - Guards perforated	Entire Building	2,252	SF	6	6-10 years	
	Lintels - Steel	Entire Building	289	LF	7	10+ years	
	Skylite - Lexan	Entire Building	60	SF	4	0-1 year	Roofed Over/Removed, No SkyLts See Roof Photos
	Windows - Casement Aluminum Double- pane	Entire Building	3,316	SF	5	2-5 years	No Air Leaks per "POC".
	Windows - Decorative	Entire Building	483	SF	6	2-5 years	
	Windows - Louver	Entire Building	107	SF	5	2-5 years	
atego	ry : Electrical		В	uildina	: Additio	on	
alogo	. y . 2.1001.10u1			anamg	. / taarti	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EΑ	6	6-10 years	
	Exit Signs - Gym	Entire Building	5	EA	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	5,778	SF	6	10+ years	
	Stairs	· ·	,		-	•	
	Emergency A/C Power - Gym	Entire Building	4,219	SF	6	10+ years	_
	Security System - CCTV	Entire Building	32,440	SF	5	6-10 years	Some cameras do not work
	Security System - Intrusion Detection	Entire Building	32,440	SF	5	6-10 years	
lain Sei	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves main and addition buildings



Catego	ry : Electrical		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	PA System	Entire Building	32,440	SF	5	6-10 years	Connected to main building
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	Functional panels are rated 7
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	•
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	ŭ				•	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	
	amp	•				•	
Catego	ry : Fire Protection		R	uildina	: Additio	n .	
Oulogo				ananig	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alaı	· -		•			•	
	Fire Alarm Strobe Lights	Main	32,440	SF	6	10+ years	
			o=,				
	Fire Alarm System	Main	32.440	SF	6	10+ vears	
	Fire Alarm_System	Main	32,440	SF	6	10+ years	
Catego	Fire Alarm_System  ry : Mechanical	Main			6 : Addition	-	
Catego	ry : Mechanical		В	uilding	: Additio	on Recommend	
Group	ry : Mechanical Item - Type	Main Location				on	Comments
Group	ry : Mechanical Item - Type		В	uilding	: Additio	on Recommend	Comments
Group	ry : Mechanical  Item - Type  vstems  Boiler Auxiliary- Scotch Marine- Hot Water		В	uilding	: Additio	on Recommend	Comments
Group	ry: Mechanical  Item - Type  vstems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH	<b>Location</b> Boiler Room	Quantity	UOM EA	: Addition	Recommend Replacement	Comments
Group	ry: Mechanical  Item - Type  vstems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder	Location  Boiler Room  Boiler Room	Quantity  1	UOM  EA  EA	: Addition Rank	Recommend Replacement  6-10 years  10+ years	Comments
Group	ry: Mechanical  Item - Type  Astems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers	Location  Boiler Room Boiler Room Boiler Room	Quantity  1 1 2	UOM  EA  EA  EA  EA	: Addition Rank	Recommend Replacement  6-10 years  10+ years 10+ years	
Group	ry: Mechanical  Item - Type  stems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water	Location  Boiler Room  Boiler Room	Quantity  1	UOM  EA  EA	: Addition Rank	Recommend Replacement  6-10 years  10+ years	Per engineer, The 3 boilers in 2 boil
Group	ry: Mechanical  Item - Type  Astems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH  Chemical Pot Feeder  Combustion Dampers  Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH	Location  Boiler Room Boiler Room Boiler Room Boiler Room	Quantity  1 1 2	UOM  EA  EA  EA  EA  EA	5 6 5 5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years	Per engineer, The 3 boilers in 2 boilerooms are connected in parallel
Group	ry: Mechanical  Item - Type  stems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water	Location  Boiler Room Boiler Room Boiler Room	Quantity  1 1 2 1	UOM  EA  EA  EA  EA	: Addition Rank	Recommend Replacement  6-10 years  10+ years 10+ years	Per engineer, The 3 boilers in 2 boil
<b>Group</b> Boiler S	Item - Type Vistems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System	Location  Boiler Room Boiler Room Boiler Room Boiler Room	Quantity  1 1 2 1	UOM  EA  EA  EA  EA  EA	5 6 5 5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years	Per engineer, The 3 boilers in 2 boilerooms are connected in parallel Served from others boiler room, 3
<b>Group</b> Boiler S	Item - Type  Vistems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	Quantity  1 1 2 1 1	UOM  EA  EA  EA  EA  EA	## Addition    **Rank**  5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3
Group Boiler S	Item - Type Vistems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices Unit Heater - Electric	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room  Soiler Room	Quantity  1 1 2 1 1	UOM  EA  EA  EA  EA  EA	## Addition    **Rank**  5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3
Catego Group Boiler St	Item - Type Vistems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices Unit Heater - Electric Fin Tube - Hot Water	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room  Soiler Room Boiler Room	Quantity  1  1 2 1 1 1 57	UOM  EA  EA  EA  EA  LF	5 6 5 5 6 5 5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years  10+ years 6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3
<b>Group</b> Boiler S	Item - Type Vistems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices Unit Heater - Electric	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room  Soiler Room	Quantity  1 1 2 1 1	UOM  EA  EA  EA  EA  EA	## Addition    **Rank**  5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3
Group Boiler St	Item - Type  Istems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room  Tst Floor Entire Building Entire Building	Quantity  1  1 2 1 1 1 57	UOM  EA  EA  EA  EA  LF	5 6 5 5 6 5 5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years  10+ years 6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3
Group Boiler St	Item - Type  Istems  Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Chemical Pot Feeder Combustion Dampers Non Condensing- Scotch Marine- Hot Water Boiler - 3001 - 4000 MBH Water Fill System  Devices Unit Heater - Electric Fin Tube - Hot Water Cabinet Heaters - With Hot Water Coil	Location  Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room  Soiler Room Boiler Room	Quantity  1  1 2 1 1 1 57	UOM  EA  EA  EA  EA  LF	5 6 5 5 6 5 5	Recommend Replacement  6-10 years  10+ years 10+ years 6-10 years  6-10 years  10+ years 6-10 years	Per engineer, The 3 boilers in 2 boiler rooms are connected in parallel Served from others boiler room, 3

Campus Name: Reavis Page: 18 of 34 Assessment Date: 10/13/2021



Catego	ry : Mechanical		В	uilding	: Additi	on	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	DDC System	Entire Building	32,440	SF	6	10+ years	2019 installation
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Control cabinet heaters in corridors
	Thermostats - DDC	Entire Building	15	EA	6	10+ years	Serve univents, through BAS
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	15	EA	6	10+ years	2019 installation
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	5	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	5	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	3	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	2019 installation
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	32,440	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	32,440	SF	6	10+ years	
	Sanitary Piping	Entire Building	32,440	SF	6	10+ years	
	Storm Piping	Entire Building	32,440	SF	6	10+ years	
	Vent Piping	Entire Building	32,440	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Additi	on	



					Replacement	
Administrative Suites/Offices						
AC Unit	Engineers Office	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Engineers Office	53	SF	5	10+ years	
Doors - Side-lite	Engineers Office	35	SF	6	10+ years	
Doors - Transom Window	Engineers Office	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	Engineers Office	1	ĒΑ	6	10+ years	
Floor - Tile/Sheet	Engineers Office	53	SF	7	10+ years	
Lighting - Pendent/Surface	Engineers Office	1	ĒΑ	7	6-10 years	
Walls - Concrete Block	Engineers Office	225	SF	6	10+ years	
Ceiling - Lay-in	Health Center - Conference Room	6	SF	7	10+ years	
Ceiling - Lay-in	Health Center - Conference Room	274	SF	6	10+ years	
Doors - Wood Doors inclu hw	Health Center - Conference Room	1	EA	7	10+ years	
Floor - Carpet	Health Center - Conference Room	280	SF	7	6-10 years	
Lighting - Lay-in	Health Center - Conference Room	6	EA	7	6-10 years	
Walls - Plaster/Drywall	Health Center - Conference Room	406	SF	7	10+ years	
Ceiling - Lay-in	Health Center - Office A	108	SF	7	10+ years	
Doors - Wood Doors inclu hw	Health Center - Office A	1	EA	7	10+ years	
Floor - Carpet	Health Center - Office A	108	SF	6	6-10 years	
Lighting - Lay-in	Health Center - Office A	3	EA	7	6-10 years	
Walls - Plaster/Drywall	Health Center - Office A	272	SF	6	10+ years	
Ceiling - Lay-in	Health Center - Office B	165	SF	7	10+ years	
Doors - Wood Doors inclu hw	Health Center - Office B	1	EA	6	10+ years	
Floor - Carpet	Health Center - Office B	165	SF	6	6-10 years	
Lighting - Lay-in	Health Center - Office B	6	EA	7	6-10 years	
Walls - Plaster/Drywall	Health Center - Office B	290	SF	7	10+ years	
Ceiling - Lay-in	Health Center Office	170	SF	7	10+ years	
Ceiling - Plaster/Drywall	Health Center Office	213	SF	7	10+ years	
Doors - Side-lite	Health Center Office	9	SF	6	10+ years	
Doors - Transom Window	Health Center Office	13	SF	6	10+ years	
Doors - Wood Doors inclu hw	Health Center Office	1	EA	6	10+ years	
Floor - Carpet	Health Center Office	170	SF	7	6-10 years	
Floor - Tile/Sheet	Health Center Office	213	SF	7	10+ years	
Lighting - Lay-in	Health Center Office	2	EA	7	6-10 years	
Lighting - Lay-in	Health Center Office	9	EA	7	6-10 years	
Storage/ Closet	Health Center Office	41	SF	7	10+ years	
Walls - Plaster/Drywall	Health Center Office	684	SF	7	10+ years	
·					-	
Clinic						
Ceiling - Lay-in	Exam Room 1	153	SF	7	10+ years	
Doors - Wood Doors inclu hw	Exam Room 1	1	ĒΑ	7	10+ years	
Floor - Tile/Sheet	Exam Room 1	153	SF	7	10+ years	
Lighting - Lay-in	Exam Room 1	2	EA	7	6-10 years	
Walls - Plaster/Drywall	Exam Room 1	343	SF	7	10+ years	
Ceiling - Lay-in	Exam Room 2	100	SF	7	10+ years	
Doors - Wood Doors inclu hw	Exam Room 2	1	EA	7	10+ years	
Floor - Tile/Sheet	Exam Room 2	100	SF	7	10+ years	
					-	



L						Replacement	
L	Liahtina - Lav-in	Exam Room 2	2	EA	7	6-10 years	
	Lighting - Lay-in		_				
	Walls - Plaster/Drywall	Exam Room 2	320	SF	6	10+ years	
	Ceiling - Lay-in	Exam Room 3	123	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam Room 3	1	EA	7	10+ years	
	Floor - Tile/Sheet	Exam Room 3	123	SF	7	10+ years	
I	Lighting - Lay-in	Exam Room 3	2	EΑ	7	6-10 years	
1	Walls - Plaster/Drywall	Exam Room 3	302	SF	7	10+ years	
(	Ceiling - Lay-in	Laboratory - Health Clinic	114	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Laboratory - Health Clinic	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	Laboratory - Health Clinic	114	SF	7	10+ years	
-	Lighting - Lay-in	Laboratory - Health Clinic	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Laboratory - Health Clinic	309	SF	7	10+ years	
`	walls - Flaster/Drywall	Laboratory - Health Clinic	309	SF	,	10+ years	
_Gymnasia_							
	Ceiling - Exposed	1st Floor	4,219	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	120	SF	6	10+ years	
Γ	Doors - Steel Doors incl hw	1st Floor	6	EΑ	6	10+ years	
Г	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
r	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	4,219	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EΑ	6	6-10 years	
	Stage	1st Floor	280	SF	6	10+ years	
	Stage Curtain	1st Floor	3	EA	7	•	
		1st Floor	3 1	EA	7	10+ years	
	Stage Lighting System		=			10+ years	
	Stage-Stairs - Tile	1st Floor	20	LF	7	10+ years	
	Stage-Stairs - Wood	1st Floor	20	LF	6	10+ years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,690	SF	6	10+ years	
1	Walls - Structural Glazed Tile	1st Floor	1,653	SF	6	10+ years	
Lunch & M	ultipurpose Room						
	AC Unit	Teacher's Room	1	EA	7	6-10 years	
(	Ceiling - Plaster/Drywall	Teacher's Room	630	SF	5	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Room	1	ĒΑ	6	10+ years	
	Floor - Tile	Teacher's Room	630	SF	6	10+ years	
	Lighting - Pendent/Surface	Teacher's Room	10	EA	7	6-10 years	
١	Walls - Concrete Block	Teacher's Room	743	SF	6	10+ years	
`	Walls - Coliciete Block	reacher's Room	743	SF	O	10+ years	
MDF_IDF							
Γ	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	New asset
F	Finishes	2nd Floor	144	SF	7	10+ years	New asset
1	Window AC Unit	2nd Floor	1	EA	5	2-5 years	New asset
Mechanica	I/ Service Rooms						
wischanica	Janitor's Closet	1st Floor	23	SF	7	10+ years	



						634 E 30(11 3 TREET, Chicago, IL 60)
					Replacement	
Mechanical/ Service Rooms	1st Floor	280	SF	7	10+ years	
Storage Room	1st Floor	60	SF	7	10+ years	
Boiler Room	1st Floor	550	SF	7	10+ years	
Storage Room	1st Floor	35	SF	7	10+ years	
Janitor's Closet	2nd Floor	70	SF	7	10+ years	
Storage Room	2nd Floor	190	SF	7	10+ years	
Storage Room	211d F1001	190	SF	,	10+ years	
room						
Accessories	1st Floor - Men's	60	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor - Men's	60	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor - Men's	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor - Men's	60	SF	6	10+ years	
Lavatory	1st Floor - Men's	1	ĒΑ	6	10+ years	
Lighting - Lay-in	1st Floor - Men's	1	EΑ	6	6-10 years	
Partitions	1st Floor - Men's	1	EA	7	10+ years	
Walls - Concrete Block	1st Floor - Men's	133	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor - Men's	133	SF	6	10+ years	
				-	•	
Water Closet	1st Floor - Men's	1	EA	6	10+ years	
Accessories	1st Floor - Women's Restroom	85	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor - Women's Restroom	85	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor - Women's Restroom	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor - Women's Restroom	85	SF	6	10+ years	
Floor Drain	1st Floor - Women's Restroom	1	EA	7	10+ years	
Lavatory	1st Floor - Women's Restroom	1	EΑ	6	10+ years	
Lighting - Lay-in	1st Floor - Women's Restroom	2	EΑ	6	6-10 years	
Partitions	1st Floor - Women's Restroom	2	EA	7	10+ years	
Walls - Concrete Block	1st Floor - Women's Restroom	160	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor - Women's Restroom	160	SF	6	10+ years	
Water Closet	1st Floor - Women's Restroom	2	EA	6	10+ years	
Accessories	1st Floor Boys	188	SF	5	6-10 years	
Ceiling - Plaster/Drywall	1st Floor Boys	188	SF	_		
				6	10+ years	
Doors - Wood Doors inclu hw	1st Floor Boys	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor Boys	188	SF	6	10+ years	
Floor Drain	1st Floor Boys	1	EA	7	10+ years	
Lavatory	1st Floor Boys	4	EA	6	10+ years	
Lighting - Pendent/Surface	1st Floor Boys	2	EA	6	6-10 years	
Partitions	1st Floor Boys	3	EΑ	7	10+ years	
Urinals	1st Floor Boys	3	EA	6	10+ years	
Walls - Concrete Block	1st Floor Boys	236	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor Boys	236	SF	6	10+ years	
Water Closet	1st Floor Boys	3	ĒΑ	6	10+ years	
Accessories	1st Floor Girls	188	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor Girls	188	SF	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor Girls	188	SF	6	10+ years	
Floor Drain	1st Floor Girls	100	EA	7	-	
		•		-	10+ years	
Lavatory	1st Floor Girls	4	EA	6	10+ years	



					Replacement	
Lighting - Lay-in	1st Floor Girls	2	EA	6	6-10 years	
Lighting - Pendent/Surface	1st Floor Girls	1	EA	6	6-10 years	
Partitions	1st Floor Girls	6	EA	7	10+ years	
Walls - Concrete Block	1st Floor Girls	236	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor Girls	236	SF	6	10+ years	
Water Closet	1st Floor Girls	6	EΑ	6	10+ years	
Accessories	2nd Floor - Men's Toilet - All-Gender	40	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor - Men's Toilet - All-Gender	40	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor - Men's Toilet - All-Gender	1	ĒΑ	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor - Men's Toilet - All-Gender	40	SF	6	10+ years	
Lavatory	2nd Floor - Men's Toilet - All-Gender	1	ĒΑ	6	10+ years	
Lighting - Pendent/Surface	2nd Floor - Men's Toilet - All-Gender	1	EΑ	6	6-10 years	
Partitions	2nd Floor - Men's Toilet - All-Gender	1	ΕA	7	10+ years	
Walls - Concrete Block	2nd Floor - Men's Toilet - All-Gender	116	SF	7	10+ years	
Walls - Structural Glazed Tile	2nd Floor - Men's Toilet - All-Gender	116	SF	7	10+ years	
Water Closet	2nd Floor - Men's Toilet - All-Gender	1	EA	6	10+ years	
Accessories	2nd Floor Boys	307	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Boys	307	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Boys	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	307	SF	6	10+ years	
Floor Drain	2nd Floor Boys	1	EA	7	10+ years	
Lavatory	2nd Floor Boys	3	EA	6	10+ years	Quantity changed to update current
Lavatory	Zha i looi boys	0	L/\	J	101 years	observation
Lighting - Lay-in	2nd Floor Boys	3	EA	6	6-10 years	
Lighting - Pendent/Surface	2nd Floor Boys	4	EA	6	6-10 years	
Partitions	2nd Floor Boys	3	EA	7	10+ years	Quantity changed to update current
	·				j	observation
Urinals	2nd Floor Boys	3	EA	6	10+ years	
Walls - Concrete Block	2nd Floor Boys	257	SF	6	10+ years	
Walls - Structural Glazed Tile	2nd Floor Boys	386	SF	6	10+ years	
Water Closet	2nd Floor Boys	2	EA	7	10+ years	Quantity changed to update current
						observation
Water Closet	2nd Floor Boys	1	EA	4	1-2 years	Sign on Partition: Not in Use
Accessories	2nd Floor Girl's	273	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Girl's	273	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Girl's	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Girl's	273	SF	6	10+ years	
Floor Drain	2nd Floor Girl's	1	EΑ	7	10+ years	
Lavatory	2nd Floor Girl's	3	EA	7	10+ years	Quantity changed to update current
		_		_		observation
Lighting - Lay-in	2nd Floor Girl's	4	EA	6	6-10 years	
Lighting - Pendent/Surface	2nd Floor Girl's	3	EA	7	6-10 years	
Partitions	2nd Floor Girl's	3	EA	7	10+ years	Quantity changed to update current observation
Walls - Concrete Block	2nd Floor Girl's	257	SF	6	10+ years	observation
Walls - Structural Glazed Tile	2nd Floor Girl's	386	SF	6	10+ years	
Water Closet	2nd Floor Girl's	3	EA	6	10+ years	Quantity changed to update current
Water Gloset	210 1 1001 01113	3	LA	J	TOT years	Quantity changed to appeare current

Campus Name: Reavis Page : 23 of 34 Assessment Date: 10/13/2021



00110010						634 E 30(11 31 KEE1, Chicago, 12 00013
					Replacement	
					<u> </u>	observation
Accessories	2nd Floor Women's	90	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Women's	90	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Women's	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Women's	90	SF	6	10+ years	
Floor Drain	2nd Floor Women's	1	EΑ	7	10+ years	
Lavatory	2nd Floor Women's	1	EΑ	6	10+ years	
Lighting - Pendent/Surface	2nd Floor Women's	2	EΑ	6	6-10 years	
Walls - Concrete Block	2nd Floor Women's	170	SF	6	10+ years	
Walls - Structural Glazed Tile	2nd Floor Women's	170	SF	6	10+ years	
Water Closet	2nd Floor Women's	1	EA	7	10+ years	Quantity changed to update current observation
Accessories	Engineer's Locker Room	90	SF	7	6-10 years	
Ceiling - Plaster/Drywall	Engineer's Locker Room	90	SF	5	10+ years	
Doors - Wood Doors inclu hw	Engineer's Locker Room	2	EΑ	6	10+ years	
Floor - Tile	Engineer's Locker Room	48	SF	6	10+ years	
Floor - Tile Ceramic/ Porcelain	Engineer's Locker Room	42	SF	6	10+ years	
Floor Drain	Engineer's Locker Room	1	EA	7	10+ years	
Lavatory	Engineer's Locker Room	1	EA	6	10+ years	
Lighting - Lay-in	Engineer's Locker Room	1	EA	7	6-10 years	
Lighting - Pendent/Surface	Engineer's Locker Room	2	EA	6	6-10 years	
Showers	Engineer's Locker Room	1	EA	7	10+ years	
Walls - Concrete Block	Engineer's Locker Room	180	SF	6	10+ years	
Walls - Structural Glazed Tile	Engineer's Locker Room	90	SF	6	10+ years	
Walls - Tile Ceramic/ Porcelain	Engineer's Locker Room	90	SF	6	10+ years	
Water Closet	Engineer's Locker Room	1	EA	6	10+ years	
Accessories	Health Center	59	SF	7	6-10 years	
Ceiling - Lay-in	Health Center	59	SF	7	10+ years	
Doors - Steel Doors incl hw	Health Center	1	EΑ	6	10+ years	
Floor - Tile Ceramic/ Porcelain	Health Center	59	SF	6	10+ years	
Floor Drain	Health Center	1	EΑ	7	10+ years	
Hand Dryer	Health Center	1	EΑ	7	6-10 years	
Lavatory	Health Center	1	EΑ	7	10+ years	
Lighting - Lay-in	Health Center	1	EΑ	7	6-10 years	
Walls - Plaster/Drywall	Health Center	105	SF	6	10+ years	
Walls - Tile Ceramic/ Porcelain	Health Center	105	SF	6	10+ years	
Water Closet	Health Center	1	EΑ	6	10+ years	
					•	

Category : Classroom

**Building: Addition** 

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #2 (Office)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	24	LF	6	10+ years	
Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	
Doors - Side-lite	1st Floor	7	SF	6	10+ years	



atego	ry : Classroom		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update currer
	-					-	observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Observed metal frame in good condition.
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update currer observation
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
assroo	nm #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update currer observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	55501 Valio11
	Doors - Transom Window	2nd Floor	48	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	40	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor 2nd Floor	813	SF	7	10+ years	Quantity changed to update currer
						-	observation
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	

Campus Name: Reavis Page : 25 of 34 Assessment Date: 10/13/2021



Catego	ry : Classroom		В	uilding	: Additi		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	Asset has been refurbished
	Ceiling - Lay-in	2nd Floor	813	SF	7	10+ years	Quantity changed to update current observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update current observation
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update current observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update current observation
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update current observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update current observation

Campus Name: Reavis Page : 26 of 34 Assessment Date: 10/13/2021



Catego	ry : Classroom		В	uilding	: Addition	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
Classroo	om #216 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update currer observation
	Doors - Side-lite	2nd Floor	7	SF	6	10 L Vooro	ODSEIVALIOIT
			7		6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update currer observation
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	om #217 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update currer
	•				-	•	observation
	Doors - Side-lite	2nd Floor	7	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	10+ years	Quantity changed to update currer observation
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
Classroo	om #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Cascwork	Z110 1 1001	10	니	U	TOT years	
	Ceiling - Lay-in	2nd Floor	813	SF	7	10+ years	Quantity changed to update curren



atego	ry : Classroom		В	uilding	: Addition		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	813	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	460	SF	6	10+ years	
						, , , , ,	
assroc	om #219 (Store Room)						
	AC Units	2nd Floor	1	EA	4	0-1 year	AC unit is disconnected
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	813	SF	6	10+ years	Quantity changed to update currer observation
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	813	SF	6		
	Lighting - Pendent/Surface	2nd Floor	22	EA	6	10+ years 6-10 years	
					_		
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	10	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	645	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	215	SF	6	10+ years	
assroc	om #220 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	412	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	412	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
		2nd Floor 2nd Floor	20	LF		•	
	Marker Board				6	6-10 years	
	Storage/ Closet	2nd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	715	SF	6	10+ years	
assroc	om #3 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	
	Cellilu - Lav-III						

Campus Name: Reavis Page : 28 of 34 Assessment Date: 10/13/2021



Catego	ry : Classroom		В	uilding	: Additi	on	004 E 30th OTREET, Officago, ie 00010
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	460	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #4 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	6	10+ years	
	Doors - Transom Window	1st Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	802	SF	6	10+ years	
	Floor - Tile	1st Floor	1	SF	4	0-1 year	
	Lighting - Lay-in	1st Floor	13	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	10+ years	
Classroo	om #5 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	6	10+ years	
	Doors - Transom Window	1st Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	670	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #6 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	83	LF	6	10+ years	
	2.55				•	,	



Catego	ry : Classroom	·	В	uilding	: Additi	on	
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	803	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	6	10+ years	
	Doors - Transom Window	1st Floor	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	803	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	10+ years	
lassroc	m #8 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	6	10+ years	
	Doors - Transom Window	1st Floor	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	803	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	719	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	190	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
atego	ry : Interior		В	uildina	: Additi	on	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	7100						
	Ceiling - Lay-in	1st Floor	2,268	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	10+ years	
	Doors - Store Front	1st Floor	6	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	Quantity changed to update current observation
	Floor - Tile/Sheet	1st Floor	2,268	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	60	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	7	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	2,883	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,530	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,530	SF	7	10+ years	Observed- in good condition
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	-

Campus Name: Reavis Page : 30 of 34 Assessment Date: 10/13/2021



Catego	ry : Interior		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Masonry	2nd Floor	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,869	SF	6	10+ years	
	Ceiling - Lay-in	Health Clinic	16	SF	7	10+ years	
	Ceiling - Lay-in	Health Clinic	392	SF	6	10+ years	
	Doors - Steel Doors incl hw	Health Clinic	1	EA	6	10+ years	
	Doors - Wood Doors include hw	Health Clinic	1	EA	7	10+ years	
	Floor - Tile/Sheet	Health Clinic	408	SF	7	10+ years	
	Lighting - Lay-in	Health Clinic	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	Health Clinic	684	SF	6	10+ years	
Stairs							
	Ceiling - Splined	North East	663	SF	6	10+ years	
	Floor - Tile	North East	663	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North East	93	SF	6	10+ years	
	Handrails	North East	50	LF	7	10+ years	
	Lighting - Lay-in	North East	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North East	4	EA	7	6-10 years	
	Stairs - Tile	North East	126	LF	6	10+ years	
	Walls - Masonry	North East	1,664	SF	6	10+ years	
	Ceiling - Splined	North West	663	SF	7	10+ years	
	Floor - Tile	North West	663	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North West	93	SF	6	10+ years	
	Handrails	North West	50	LF	7	10+ years	
	Lighting - Lay-in	North West	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	North West	5	EA	6	6-10 years	
	Stairs - Tile	North West	126	LF	6	10+ years	
	Walls - Masonry	North West	1,662	SF	6	10+ years	

Campus Name: Reavis Page : 31 of 34 Assessment Date: 10/13/2021





Category : Site **Building: Site** 

				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	3	1-2 years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	6-10 years	
encing	Fencing - Chain Link	Entire Site	405	LF		2 E veere	
				LF LF	5	2-5 years	Foot Designator Chair Link Devale
	Fencing - Chain Link	Entire Site	598	LF	4	1-2 years	East Perimeter - Chain Link Panels Missing. Wood Fencing Placed as Perimeter/Guard. Discard Chain Lin Components.
	Fencing - Guard Rail	Entire Site	111	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	48	LF	6	6-10 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	223	LF	5	1-2 years	Displaced Wood/Damaged Fence
						·	Panels.
_andsca	pe						
	Benches	Entire Site	11	EA	6	6-10 years	
	Landscape - Grass	Entire Site	7,666	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,740	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	612	SF	5	1-2 years	Significant Damage.
	Parkway trees	Entire Site	7	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,419	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	6,304	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	130	SF	6	10+ years	Non- impact But Damaged Asset.
Parking I	ot						
	Concrete Curbs	Site West	190	LF	6	6-10 years	
	Concrete Curbs	Site West	100	LF	4	0-1 year	Cracked/Broken/Exposed Rebar -
						,	Significant Damage.
	Surface - Asphalt	Site West	2,432	SF	4	0-1 year	Significant Damage.
Sidewalk	rs.						
	Sidewalks - Internal Walks	Entire Site	12	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	6	LF	4	0-1 year	Disrepair - Significant Damage. Did
			_			5 · J · 5 · ·	Not Observe Plywood On Sidewalk.
	Sidewalks - Perimeter Sidewalks	Entire Site	8,464	SF	6	10+ years	
Signage							
Arrada	Flag Pole - Flag Pole	South	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	South	1	EA	6	10+ years	
	Marques 1 100 Otananig Back Eighted	Codui	ı	L/\	J	101 yours	



#### William C Reavis Math & Science Specialty ES

Recommend

834 E 50th STREET, Chicago, IL 60615

Category : Site Building : Site

Group Item - Type Location Quantity UOM Rank Replacement Comments

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Reavis Page : 33 of 34 Assessment Date: 10/13/2021



**Classroom Summary** 

Classiconi Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Kindergarten	Kindergarten	1st Floor	101	101	864	145	14	N	N
Pre School	Pre School	1st Floor	102	102	1,013	118	6	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	787	165	14	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	786	165	15	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	785	165	14	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	787	165	14	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	786	165	14	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	788	165	14	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	787	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	788	165	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	788	165	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	788	165	14	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	788	165	14	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	788	165	14	N	N
Store Room	Regular Classroom	1st Floor	103	103	787	165	14	N	N
D. T. P. A. L. P. C.									
Building : Addition		I de la Fi	1 .	1 .	0.10	100			
Computer Lab	Regular Classroom	1st Floor	4	4	813	108	6	N	N
Computer Lab	Regular Classroom	2nd Floor	216	216	813	118	6	N	Υ
Library	Regular Classroom	1st Floor	6	6	813	118	6	N	N
Office	Regular Classroom	1st Floor	2	2	813	118	6	N	N
Office	Regular Classroom	2nd Floor	217	217	813	118	6	N	N
Regular Classroom	Regular Classroom	1st Floor	3	3	813	118	6	N	N
Regular Classroom	Regular Classroom	1st Floor	5	5	813	118	6	N	N
Regular Classroom	Regular Classroom	1st Floor	8	8	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	813	118	6	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	813	118	6	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	813	118	6	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	427	92	6	N	N
Store Room	Regular Classroom	2nd Floor	219	219	813	118	6	N	N