

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1914	3	75,830
Linked Addition	1995	2	34,776
Modular 1 (2-Classroom)	2000	1	1,632
Modular 2 (2-Classroom)	2000	1	1,632
Campus Total			113,870

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Exterior Doors - Exterior Steel Door	10 SW - Main	4	EA	6	10+ years	Wood Frames - Scrape/Paint
	Exterior Doors - Transom Lite	10 SW - Main	4	EA	6	10+ years	
	Exterior Stairs - Concrete	10 SW - Main	72	LF	5	1-2 years	
	Exterior Doors - Exterior Wood Door	6 SW - Main	4	EA	5	1-2 years	
	Exterior Doors - Transom Lite	6 SW - Main	4	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	6 SW - Main	154	LF	5	1-2 years	
	Stair Handrail - Steel_Stair Handrail	6 SW - Main	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	7 West - Main	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	7 West - Main	5	EA	6	6-10 years	
	Exterior Stairs - Concrete	7 West - Main	32	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	8 N - Main	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	8 N - Main	2	EA	7	6-10 years	
	Exterior Stairs - Concrete	8 N - Main	6	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	9 NEMain	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	9 NEMain	5	EA	6	6-10 years	
	Exterior Stairs - Concrete	9 NEMain	32	LF	7	6-10 years	
_Foundat	ion						
	Foundation - Masonry	Entire Building	715	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	75,830	SF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		-
C	Ham Time	Lagation	Overtitue	HOM	Donk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	5	2-5 years 2-5 years	
	Exterior Eighting Wall Wounted	Entire Building	J		J	2 o years	
Roof Sys	stem						
•	Access Ladder - Metal	A	4	EA	7	10+ years	
	Access Ladder - Metal	A	1	EA	7	10+ years	Dangerous - 1st rung's height above
		•	40	. –		4.0	roof
	Chimney - Brick Chimney- Concrete/ Mortar	A	40	LF	6	10+ years	
	Liner Coping - Stone	A	503	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	74	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	503	LF	7	10+ years	
	Roof - Modified Bitumen	A	18,920	SF	6	10+ years	
	Roof Hatch - Metal	A	2	EΑ	7	10+ years	2 - Roof Hatches: Roof Hatch on
						·	Southeast Corner of Roof A is
							inaccessible from below. (Closed in
							Photos) Roof Hatch on Southwest
							corner of Roof A is functioning and
	Doof Chryster Chool with Clay Tile Arch	۸	40.000	C.E.	7	40	accessible. (Open in Photos)
	Roof Structure - Steel with Clay Tile Arch Coping - Stone	A B	18,920 235	SF LF	7 6	10+ years 10+ years	
	Downspouts - Exterior Downspouts	В	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	235	LF	5	6-10 years	
	Roof - Modified Bitumen	В	4,788	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	В	4,788	SF	7	10+ years	
	Chimney - Metal Flue	С	40	LF	7	10+ years	
	Downspouts - Interior Downspouts	С	34	LF	6	10+ years	
	Roof - Modified Bitumen	С	3,127	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	C	3,127	SF	7	10+ years	
	Downspouts - Exterior Downspouts	D	24	LF	6	6-10 years	
	Roof - Modified Bitumen	D	1,003 1,003	SF SF	6 7	10+ years	
	Roof Structure - Steel with Clay Tile Arch Coping - Stone	D E	35	LF	7	10+ years 10+ years	
	Downspouts - Interior Downspouts	E	15	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Ē	34	LF	7	10+ years	
	Roof - Modified Bitumen	Ē	288	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Ē	288	SF	7	10+ years	
	Coping - Stone	F	34	LF	7	10+ years	
	Downspouts - Interior Downspouts	F	15	LF	6	6-10 years	
	Parapet - 16" - 30" Height	F	34	LF	7	10+ years	
	Roof - Modified Bitumen	F	288	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	F	288	SF	7	10+ years	



Category : Exterior

Group Item - Type

Frank W Reilly Elementary School 3650 W School STREET, Chicago, IL 60618

Group	iteiii - Type	Location	Quantity	OOW	IValik	Replacement	Comments
Walls							
	Cheek-Wall - Stone	Entire Building	200	SF	5	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	906	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	600	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	16,882	SF	6	10+ years	
				SF			
	Exterior Walls - Brick	Entire Building	1,635		5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	5	SF	7	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	3,810	SF	6	10+ years	
Vindows	S						
	Guard - Guards perforated	Entire Building	2,323	SF	6	10+ years	
	Lintels - Steel	Entire Building	856	LF	6	10+ years	
	Lintels - Stone	Entire Building	30	LF	6	10+ years	
	Windows - Decorative	Entire Building	192	SF	6	6-10 years	
			8,350	SF	6		
	Windows - Sash Aluminum Double-pane	Entire Building	8,350	SF	б	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
meraer	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves main building, AC generato
	Automatic Transfer Switch	Electrical Room	1	EA		2-5 years	Older, not reliable
			1		4		Older, not reliable
	Exit Signs - Auditoium	Entire Building	6	EA	6	6-10 years	D 11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Exit Signs - Corridors and Stairs	Entire Building	19	EA	6	6-10 years	Building has AC generator
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	75,830	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	75,830	SF	5	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	5,530	SF	6	10+ years	
	Emergency A/C Power - Corridors and	Entire Building	15,126	SF	6	10+ years	
	Stairs		0.440	05	•	0.40	
	Emergency A/C Power - Gym	Entire Building	3,146	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	
		Site North	1	EΑ	6	10+ years	Serves main and addition buildings
	Emergency Generator- Outdoor- Natural Gas - Below 60 KW	Site North	ı	LA	Ü	,	emergency systems
1ain Sei	Gas - Below 60 KW	Site North	1	LA		,	
lain Sei	Gas - Below 60 KW rvice Main Electrical Service - 1600 A	Electrical Room	1	EA	6	10+ years	~
lain Se	Gas - Below 60 KW				-		emergency systems

Location

Building : Main

UOM Rank

Quantity

Recommend

Replacement Comments

Campus Name: Reilly Page : 3 of 53 Assessment Date: 08/23/2021



Categoi	y : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	· ·		•				buildings
ower Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	Serves main building
ategoi	ry : Fire Protection		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ire Aları			•			•	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main building only, reliable
	Fire Alarm Strobe Lights	Entire Building	75,830	SF	6	10+ years	
	Fire Alarm_System	Entire Building	75,830	SF	5	6-10 years	
ategoi	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Hand	ing Systems	A					Diff. It.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Attic	2	EA	6	10+ years	Difficult to access, not safe attic
	Air Handling Unit- Built Up- Multi Zone- Double Delivery- Hot Water Coils - Greater than 60000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU 1, serves main building
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - Greater than 60000 cfm	Mechanical Room	1	EA	5	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	50	LF	6	10+ years	Common return
	Zone Dampers	Mechanical Room	46	EA	5	6-10 years	
oiler Sy	stems						
	Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Condensing- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	10+ years	Serves main building, B1, B2
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
as Boo	ster						



Category : Mechanical

Frank W Reilly Elementary School 3650 W School STREET, Chicago, IL 60618

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_	Gas Booster	Boiler Room	2	EA	6	10+ years	Serve 2 boilers in main building
eating	Devices						
J	Wall Heater - Electric	Entire Building	12	EA	6	10+ years	
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	10+ years	
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	10+ years	
echani	cal Plumbing						
	Hydronic Supply and Return - Steel	Basement	200	LF	6	10+ years	
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	10+ years	Serve air handler HW and unit heaters
empera	ture Control						
	DDC System	Entire Building	75,830	SF	5	10+ years	2015 updated software, also serve annex. 1995 installation
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve unit heaters
	Thermostats - DDC	Entire Building	46	EA	6	10+ years	
entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Through window
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	10+ years	•
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	4	EA	6	10+ years	
	Roof Mounted Duct Work	Entire Building	125	LF	6	10+ years	
atego	ry : Plumbing		В	uilding	: Main		
						Recommend	
					Rank	Replacement	Comments
roup	Item - Type	Location	Quantity	UOM	Italik	rtopiacomont	
•	er					·	
•		Boiler Room	Quantity 1	EA	5	6-10 years	Serves main building
Group Hot Wate Piping	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
lot Wate	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines	Boiler Room Entire Building	75,830	EA SF	5	6-10 years 10+ years	
ot Wate	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Boiler Room Entire Building Entire Building	75,830 75,830	EA SF SF	5 6 6	6-10 years 10+ years 10+ years	
lot Wate	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures	Boiler Room Entire Building Entire Building Entire Building	75,830 75,830 75,830	EA SF SF SF	5 6 6 6	6-10 years 10+ years 10+ years 10+ years	Serves main building
lot Wate	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Boiler Room Entire Building Entire Building Entire Building Entire Building	75,830 75,830 75,830 75,830	EA SF SF SF	5 6 6 6	6-10 years 10+ years 10+ years	Serves main building Pressure is good
lot Wate	Gas Heater - 150000 - 300000 BTU/HR Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Boiler Room Entire Building Entire Building Entire Building	75,830 75,830 75,830	EA SF SF SF	5 6 6 6	6-10 years 10+ years 10+ years 10+ years	Serves main building

Building: Main

Campus Name: Reilly Page : 5 of 53 Assessment Date: 08/23/2021



Catego	ry : Plumbing	Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	(from Risers to Fixtures)		·			·	
	Sanitary Piping	Entire Building	75,830	SF	6	10+ years	
	Storm Piping	Entire Building	75,830	SF	6	10+ years	
	Vent Piping	Entire Building	75,830	SF	6	10+ years	
Catama	rv · Poom		D	uildina	. Main		

Catego	ry : Room		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	107 Support Services- under renovation	635	SF	7	10+ years	
	Doors - Side-lite	107 Support Services- under renovation	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107 Support Services- under renovation	1	EA	7	10+ years	
	Floor - Tile	107 Support Services- under renovation	635	SF	7	10+ years	
	Lighting - Pendent/Surface	107 Support Services- under renovation	8	EA	7	10+ years	
	Power Distribution	107 Support Services- under renovation	5	EA	7	10+ years	
	Storage/ Closet	107 Support Services- under renovation	125	SF	7	10+ years	
	Walls - Plaster/Drywall	107 Support Services- under renovation	728	SF	7	10+ years	
	Ceiling - Plaster/Drywall	107A Small Office in 107- under renovation	180	SF	7	10+ years	
	Doors - Side-lite	107A Small Office in 107- under renovation	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107A Small Office in 107- under renovation	1	EA	7	10+ years	
	Floor - Tile	107A Small Office in 107- under renovation	180	SF	7	10+ years	
	Lighting - Pendent/Surface	107A Small Office in 107- under renovation	2	EA	7	10+ years	
	Power Distribution	107A Small Office in 107- under renovation	2	EA	7	10+ years	
	Walls - Plaster/Drywall	107A Small Office in 107- under renovation	250	SF	7	10+ years	
	Walls - Plaster/Drywall	107A Small Office in 107- under renovation	210	SF	7	10+ years	
	Ceiling - Plaster/Drywall	211 or 201 A	295	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	211 or 201 A	1	EA	6	6-10 years	
	Floor - Tile	211 or 201 A	295	SF	4	1-2 years	Gouges in tiles throughout

Campus Name: Reilly Page : 6 of 53 Assessment Date: 08/23/2021



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	211 or 201 A	3	EA	7	6-10 years	
	Power Distribution	211 or 201 A	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	211 or 201 A	850	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	301A Office (above stair)	202	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	301A Office (above stair)	1	EA	6	6-10 years	
	Floor - Wood	301A Office (above stair)	202	SF	6	6-10 years	
	Lighting - Pendent/Surface	301A Office (above stair)	2	EA	7	6-10 years	
	Power Distribution	301A Office (above stair)	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	301A Office (above stair)	510	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	302A Office (above stair)	202	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	302A Office (above stair)	1	EA	6	6-10 years	
	Floor - Wood	302A Office (above stair)	202	SF	6	6-10 years	
	Lighting - Pendent/Surface	302A Office (above stair)	1	EA	7	6-10 years	
	Power Distribution	302A Office (above stair)	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	302A Office (above stair)	505	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	310 Gym Office	655	SF	6	6-10 years	
	Doors - Transom Window	310 Gym Office	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	310 Gym Office	1	EA	6	6-10 years	
	Floor - Tile	310 Gym Office	625	SF	6	6-10 years	
	Floor - Tile	310 Gym Office	30	SF	6	6-10 years	
	Lighting - Pendent/Surface	310 Gym Office	5	ĒΑ	7	6-10 years	
	Power Distribution	310 Gym Office	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	310 Gym Office	1,100	SF	6	6-10 years	
	Walls - Plaster/Drywall	310 Gym Office	200	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	311 Copy Room + Office	285	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	311 Copy Room + Office	1	EA	6	6-10 years	
	Floor - Tile	311 Copy Room + Office	295	SF	6	6-10 years	
	Lighting - Pendent/Surface	311 Copy Room + Office	3	EA	5	6-10 years	
	Power Distribution	311 Copy Room + Office	10	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	311 Copy Room + Office	850	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	312 (Peer Jury)	440	SF	7	10+ years	
	Doors - Transom Window	312 (Peer Jury)	56	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	312 (Peer Jury)	1	EA	6	6-10 years	
	Floor - Tile	312 (Peer Jury)	70	SF	6	6-10 years	
	Floor - Tile	312 (Peer Jury)	370	SF	6	6-10 years	
	Lighting - Pendent/Surface	312 (Peer Jury)	5	EA	6	6-10 years	
	Power Distribution	312 (Peer Jury)	10	EA	7	6-10 years	
			-	SF		•	
	Walls - Plaster/Drywall Work SInk	312 (Peer Jury)	1,010 1	EA	6 7	6-10 years	
	AC Unit	312 (Peer Jury)	1	EA	7	6-10 years	
		engineer's office		SF		6-10 years	
	Ceiling - Plaster/Drywall	engineer's office	655		6	6-10 years	
	Doors - Wood Doors inclu hw	engineer's office	1	EA	6	6-10 years	
	Floor - Tile	engineer's office	655	SF	7	6-10 years	
	Lighting - Pendent/Surface	engineer's office	3	EA	7	6-10 years	

Campus Name: Reilly Page: 7 of 53 Assessment Date: 08/23/2021



Group Item - Type Location					
Group Item - Type Location				Recommend	
	Quantity	UOM	Rank	Replacement	Comments
Power Distribution engineer's office	1	EΑ	6	6-10 years	
Storage/ Closet engineer's office	18	SF	7	6-10 years	
Walls - Concrete Block engineer's office	1,100	SF	6	6-10 years	
Auditorium & Theater					
	470	ΕΛ	7	0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Balcony Seating 1st Floor	172	EA	7	6-10 years	
Balcony Seating 1st Floor	2	EA SF	7	6-10 years	
Ceiling - Plaster/Drywall 1st Floor	5,360		6	6-10 years	
Doors - Wood Doors inclu hw 1st Floor	16	EA	6	6-10 years	
Floor - Tile/Sheet 1st Floor	760	SF	7	6-10 years	
Floor - Wood 1st Floor	1,600	SF	6	6-10 years	
Floor - Wood 1st Floor	3,000	SF	6	6-10 years	
Lighting - Pendent/Surface 1st Floor	2	EA	7	6-10 years	
Lighting - Pendent/Surface 1st Floor	2	EA	7	6-10 years	
Lighting - Pendent/Surface 1st Floor	1	EA	7	6-10 years	
Lighting - Pendent/Surface 1st Floor	14	EA	7	6-10 years	
Lighting - Pendent/Surface 1st Floor	4	EA	7	6-10 years	
Lighting - Wall Mounted 1st Floor	12	EA	7	6-10 years	
Lighting - Wall Mounted 1st Floor	2	EA	7	6-10 years	
Main Floor Seating 1st Floor	50	EΑ	7	6-10 years	
Main Floor Seating 1st Floor	50	EA	7	6-10 years	
Main Floor Seating 1st Floor	514	EΑ	7	6-10 years	
Sound System 1st Floor	1	EA	7	6-10 years	
Stage 1st Floor	1,010	SF	6	6-10 years	
Stage Curtain 1st Floor	3	EA	7	6-10 years	
Stage Curtain 1st Floor	1	EΑ	7	6-10 years	
Stage Lighting System 1st Floor	1	EΑ	5	2-5 years	
Stage-Stairs - Wood 1st Floor	25	LF	6	2-5 years	
Walls - Plaster/Drywall 1st Floor	8,160	SF	6	6-10 years	
Gymnasia					
Bleacher Seating 3rd Floor	42	EA	7	6-10 years	
Ceiling - Plaster/Drywall 3rd Floor	6	SF	7	10+ years	
Ceiling - Plaster/Drywall 3rd Floor	2,690	SF	6	6-10 years	
Doors - Transom Window 3rd Floor	56	SF	6	6-10 years	
Doors - Wood Doors inclu hw 3rd Floor	2	EA	6	6-10 years	
Doors - Wood Doors inclu hw 3rd Floor	2	EA	6	6-10 years	
Floor - Wood Boors mold flw 3rd Floor	3,146	SF	6	6-10 years	
Lighting - Metal Halide/Sodium Vapor 3rd Floor	16	EA	7	6-10 years	
Scoreboards 3rd Floor	10	EA	7	6-10 years	
Walls - Plaster/Drywall 3rd Floor	4,450	SF	7	6-10 years	
· · · · · · · · · · · · · · · · · · ·	4,450	SF SF	7	•	
Walls - Plaster/Drywall 3rd Floor	50	ЗF	1	10+ years	



Catego	ry : Room		В	uilding	: Main		<u> </u>
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library	1011.7	0.15				0.40	
	AC Unit	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	42	LF	6	6-10 years	
	Casework	2nd Floor	48	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,500	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,500	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	200	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	950	SF	6	6-10 years	
MDF_ID	F						
_	Doors - Wood Doors inclu hw	in Room 300 (former storage)	1	EA	6	6-10 years	
	Finishes	in Room 300 (former storage)	140	SF	7	6-10 years	
	Other Cooling Unit	in Room 300 (former storage)	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
_WOOHGIT	Boiler Room	1st Floor	1,327	SF	5	6-10 years	
	Janitor's Closet	1st Floor	1,527	SF	5	6-10 years	
	Janitor's Closet	1st Floor	14	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	755	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	500	SF	5	6-10 years	
	Storage Room	1st Floor	60	SF	5	6-10 years	
	Vaults	1st Floor	375	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	14	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	14	SF	5	6-10 years	
	Storage Room	2nd Floor	180	SF	5	6-10 years	
	Storage Room	2nd Floor	76	SF	5	6-10 years	
	Storage Room	2nd Floor	180	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	14	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	14	SF	5	6-10 years	
Daata						,	
_Restroor	n Accessories	105A	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A 105A	65	SF SF	<i>7</i> 6	6-10 years 6-10 years	
	Doors - Wood Doors inclu hw	105A 105A	1	Sr EA			
				SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	105A	65		6	6-10 years	
	Lavatory	105A	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	105A	1	EA EA	7	6-10 years	
	Partitions	105A	1	ĽΑ	7	6-10 years	



Catego	Category : Room Building : Main						
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	105A	285	SF	6	6-10 years	
	Water Closet	105A	1	EA	6	6-10 years	
	Accessories	1st Floor	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	380	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	380	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	230	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	530	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	320	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	10	SF	6	6-10 years	
	Water Closet	1st Floor	6	EA	7	6-10 years	
	Accessories	1st Floor	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	380	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	380	SF	6	6-10 years	
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	6-10 years	
	Urinals	1st Floor	5	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	280	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	530	SF	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	5	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	75	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	200	SF	6	6-10 years	
	Water Closet	1st Floor	2	EA	7	6-10 years	
	Accessories	1st Floor NW Women	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor NW Women	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor NW Women	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor NW Women	30	SF	7	6-10 years	
	Hand Dryer	1st Floor NW Women	1	ĒΑ	7	6-10 years	
	Lavatory	1st Floor NW Women	1	EΑ	6	6-10 years	
	Lighting - Wall Mounted	1st Floor NW Women	1	EA	7	6-10 years	
	Partitions	1st Floor NW Women	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor NW Women	200	SF	6	6-10 years	
	Water Closet	1st Floor NW Women	1	EA	6	6-10 years	
	Accessories	211A Unisex Toilet	64	SF	7	6-10 years	
	, 13333301103	ZTIA OTHOOK TOHOL	04	J1	•	o to yours	

Campus Name: Reilly Page : 10 of 53 Assessment Date: 08/23/2021



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	211A Unisex Toilet	64	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	211A Unisex Toilet	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	211A Unisex Toilet	13	SF	7	6-10 years	
	Floor - Tile	211A Unisex Toilet	51	SF	6	6-10 years	
	Lavatory	211A Unisex Toilet	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	211A Unisex Toilet	1	EA	6	6-10 years	
	Partitions	211A Unisex Toilet	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	211A Unisex Toilet	384	SF	6	6-10 years	
	Water Closet	211A Unisex Toilet	1	ĒΑ	6	6-10 years	
	Accessories	2nd Floor	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	380	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	380	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	5	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	280	SF	6		
			530	SF	-	6-10 years	
	Walls - Plaster/Drywall	2nd Floor			6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	280	SF	6	6-10 years	
	Water Closet	2nd Floor	2	EA	7	6-10 years	
	Accessories	2nd Floor	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	380	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	380	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	230	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	530	SF	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	290	SF	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	30	SF	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	10	SF	6	6-10 years	
	Water Closet	2nd Floor	6	EA	6	6-10 years	
	Accessories	311A Unisex Toilet	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	311A Unisex Toilet	64	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	311A Unisex Toilet	1	EA	6	6-10 years	
	Floor - Tile	311A Unisex Toilet	64	SF	6	6-10 years	
	Lavatory	311A Unisex Toilet	1	ĒΑ	6	6-10 years	
	•				-	,	

Campus Name: Reilly Page : 11 of 53 Assessment Date: 08/23/2021



Category : Room			Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	311A Unisex Toilet	1	EA	5	6-10 years		
	Partitions	311A Unisex Toilet	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	311A Unisex Toilet	384	SF	6	6-10 years		
	Water Closet	311A Unisex Toilet	1	EA	6	6-10 years		
	Accessories	3rd Floor	380	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	7	10+ years	Ceiling repaired	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	380	SF	6	6-10 years		
	Floor Drain	3rd Floor	1	EA	7	6-10 years		
	Hand Dryer	3rd Floor	1	EA	7	6-10 years		
	Lavatory	3rd Floor	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years		
	Partitions	3rd Floor	2	EA	7	6-10 years		
	Urinals	3rd Floor	5	EA	7	6-10 years		
	Walls - Concrete Block	3rd Floor	280	SF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	530	SF	6	6-10 years		
	Walls - Structural Glazed Tile	3rd Floor	280	SF	6	6-10 years		
	Water Closet	3rd Floor	2	EA	7	6-10 years		
	Accessories	3rd Floor	380	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	380	SF	6	6-10 years		
	Floor Drain	3rd Floor	1	EA	7	6-10 years		
	Hand Dryer	3rd Floor	1	EA	7	6-10 years		
	Lavatory	3rd Floor	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years		
	Partitions	3rd Floor	6	EA	5	6-10 years		
	Walls - Concrete Block	3rd Floor	230	SF	6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	530	SF	6	6-10 years		
	Walls - Structural Glazed Tile	3rd Floor	30	SF	6	6-10 years		
	Walls - Structural Glazed Tile	3rd Floor	330	SF	6	6-10 years		
	Water Closet	3rd Floor	6	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement North (Pump Room on plan) Toilet	25	SF	6	6-10 years		
	Doors - Transom Window	Basement North (Pump Room on plan) Toilet	10	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Basement North (Pump Room on plan) Toilet	1	EA	6	6-10 years		
	Floor - Concrete Epoxy/ Painted	Basement North (Pump Room on plan) Toilet	25	SF	7	6-10 years		
	Lighting - Wall Mounted	Basement North (Pump Room on plan) Toilet	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	Basement North (Pump Room on plan) Toilet	200	SF	6	6-10 years		

Campus Name: Reilly Page : 12 of 53 Assessment Date: 08/23/2021



	ry : Room		P	uilding	· Main		650 W SCHOOLSTREET, CHICAGO, IL 60618
Calego	ry . Room		Ь	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Water Closet	Basement North (Pump Room on	Quantity 1	EA	7	6-10 years	Comments
	Water Closet	plan) Toilet	'	LA	,	0-10 years	
		plany rollet					
Catego	ry : Classroom		В	uilding	: Main		
Guiogo	i y i Gidooroom			anamg	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #101 (Regular Classroom)						
Classion	AC Units	1st Floor	1	EA	7	6-10 years	
			9	LF		6-10 years	
	Casework	1st Floor			6		
	Ceiling - Plaster/Drywall	1st Floor	868	SF	7	6-10 years	
	Chalk Board	1st Floor	20	LF CF	4	2-5 years	
	Doors - Transom Window	1st Floor	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	868	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Marker Board	1st Floor	7	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years	
Classro	om #102 (Art Room)						
Classion	AC Units	1st Floor		ГΛ	7	6.10 years	
		1st Floor	1	EA LF	7	6-10 years	
	Casework		9		6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	868	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	867	SF	6	6-10 years	
	Floor - Tile	1st Floor	1	SF	5	1-2 years	Missing drain cover
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor	815	SF	7	6-10 years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years	
		1st Floor	1	SF EA			
	Doors - Wood Doors inclu hw				6	6-10 years	
	Floor - Tile	1st Floor	815	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	11	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	

Campus Name: Reilly Page: 13 of 53 Assessment Date: 08/23/2021



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Marker Board	1st Floor	9	LF	7	6-10 years			
	Storage/ Closet	1st Floor	60	SF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	6-10 years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
Classroc	om #104 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	876	SF	7	6-10 years			
	Chalk Board	1st Floor	9	ĹF	4	2-5 years			
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	6-10 years			
	Floor - Wood	1st Floor	876	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	13	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Fixture not working		
	Marker Board	1st Floor	9	LF	6	6-10 years	Tixture flot working		
	Storage/ Closet	1st Floor	60	SF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	6-10 years			
	vvalis - i lastei/Diywali	13(1100)	1,200	OI .	U	0-10 years			
Classroc	om #105 (Kindergarten)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	18	LF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	880	SF	7	6-10 years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	7	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	6-10 years			
	Floor - Tile	1st Floor	880	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Marker Board	1st Floor	18	LF	7	6-10 years			
	Storage/ Closet	1st Floor	60	SF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	6-10 years			
Classroc	om #106 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	855	SF	6	6-10 years			
	Chalk Board	1st Floor	9	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	7	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years			
	Floor - Wood Doors Inclu IIW	1st Floor	855	SF	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	13	Sr EA	7 7				
						6-10 years	Missing lone		
	Lighting - Pendent/Surface	1st Floor	1	EA LF	5	0-1 year	Missing lens		
	Marker Board	1st Floor	19	ᄕ	7	6-10 years			



Catego	Category : Classroom		В	uilding	: Main			
<u> </u>				Ĭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage/ Closet	1st Floor	60	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,220	SF	7	6-10 years		
Classroo	om #108 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	868	SF	7	6-10 years		
	Chalk Board	1st Floor	16	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	14	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile	1st Floor	868	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	60	SF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,310	SF	6	6-10 years		
_Classroo	om #201 (Computer Lab)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	7	6-10 years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	14	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	6-10 years		
	Floor - Wood	2nd Floor	852	SF	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	7	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	6-10 years		
	Wireless System	2nd Floor	1	EA	7	6-10 years		
Classroc	om #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	6	6-10 years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Wood	2nd Floor	852	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	6-10 years		



Category : Classroom			В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	m #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	873	SF	7	6-10 years		
	Chalk Board	2nd Floor	7	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor	863	SF	6	6-10 years		
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Cracked & missing tiles	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	15	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	58	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	7	6-10 years		
Classroo	m #204 (Science Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	14	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	6-10 years		
	Chalk Board	2nd Floor	5	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Wood	2nd Floor	880	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	60	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	6-10 years		
	Work Sink	2nd Floor	1,200	EA	7	6-10 years		
	Work Girik	2110 1 1001	•	L/\	,	o ro years		
Classroc	m #205 (Regular Classroom)	0 15				0.40		
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	875	SF LF	6	6-10 years		
	Chalk Board	2nd Floor	7		4	2-5 years		
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Wood	2nd Floor	875	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	13	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	4	1-2 years	Lens not installed properly	
	Marker Board	2nd Floor	7	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	65	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,182	SF	6	6-10 years		

Campus Name: Reilly Page : 16 of 53 Assessment Date: 08/23/2021



Catego	ry : Classroom		В	uilding	: Main		650 W School STREET, Chicago, IL 60616
Juliogo	.,		_	<u>.</u>	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	865	SF	6	6-10 years	
	Chalk Board	2nd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	865	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,230	SF	6	6-10 years	
Classroo	om #207 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	6	6-10 years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,297	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Holes in gyp bd
_Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	852	SF	7	6-10 years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	852	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	6-10 years	
Classroo	om #300 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	914	SF	7	10+ years	
						•	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Tile	3rd Floor	854	SF	6	6-10 years	
	Floor - Tile	3rd Floor	60	SF	4	0-1 year	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	82	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,500	SF	6	6-10 years	
	Work Sink	3rd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,182	SF	6	6-10 years	
Classroo	om #303 (Regular Classroom)						
21000100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	762	SF	6	6-10 years	
	Chalk Board	3rd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	DUUIS - HAIISUH WIHUUW	31U F1001	14	ЭF	U	0-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	0-1 year	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
Classroo	om #304 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Transom Window			SF		-	
		3rd Floor	14		6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroc	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Chalk Board	3rd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood Boors inclu riw	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface			EA	7		
		3rd Floor	14			6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
Classroc	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	6	6-10 years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Doors Wood Doors Illoid IIW	010 1 1001	·		J	o io years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	812	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	6	6-10 years	
Classro	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	7	6-10 years	
	Chalk Board	3rd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,282	SF	7	6-10 years	
Classro	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	7	10+ years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	808	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	6-10 years	
۵.	om #326 (Special Education)						
Classro	Ceiling - Plaster/Drywall	3rd Floor	330	SF	6	6-10 years	
Classroo		3rd Floor	2	EA	6	6-10 years	
Classroo							
Classro	Doors - Wood Doors inclu hw		330	SF	6	p-10 years	
Classroo	Doors - Wood Doors inclu hw Floor - Tile	3rd Floor	330	SF FA	6 7	6-10 years 6-10 years	
Classro	Doors - Wood Doors inclu hw		330 3 10	SF EA LF	6 7 7	6-10 years 6-10 years 6-10 years	



egory : Interior			В	uilding	: Main	Dagaman	
	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
p	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
idor							
	Ceiling - Plaster/Drywall	2nd Floor	4,860	SF	6	6-10 years	
	Drinking Fountains - Triple Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	2nd Floor	4,860	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	34	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	7,530	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	4,866	SF	7	6-10 years	
	Drinking Fountains - Triple Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	3rd Floor	4,866	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	33	EA	7	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	158	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	7,880	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	NE Vestibule	50	SF	6	6-10 years	
	Doors - Transom Window	NE Vestibule	28	SF	6	6-10 years	
	Doors - Wood Doors include hw	NE Vestibule	4	EΑ	6	6-10 years	
	Floor - Tile Quarry	NE Vestibule	50	SF	6	6-10 years	
	Lighting - Pendent/Surface	NE Vestibule	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	NE Vestibule	22	SF	6	6-10 years	
	Walls - Structural Glazed Tile	NE Vestibule	60	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	NW Vestibule	50	SF	6	6-10 years	
	Doors - Transom Window	NW Vestibule	30	SF	6	6-10 years	
	Doors - Wood Doors include hw	NW Vestibule	4	EA	6	6-10 years	
	Floor - Tile Quarry	NW Vestibule	50	SF	6	6-10 years	
	Lighting - Pendent/Surface	NW Vestibule	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	NW Vestibule	25	SF	6	6-10 years	
	Walls - Structural Glazed Tile	NW Vestibule	55	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SE Vestibule (Link to Annex)	200	SF	6	6-10 years	
	Doors - Side-lite	SE Vestibule (Link to Annex)	24	SF	6	6-10 years	
	Doors - Transom Window	SE Vestibule (Link to Annex)	64	SF	6	6-10 years	
	Doors - Wood Doors include hw	SE Vestibule (Link to Annex)	3	EA	6	6-10 years	
	Floor - Tile Quarry	SE Vestibule (Link to Annex)	200	SF	6	6-10 years	
	Lighting - Pendent/Surface	SE Vestibule (Link to Annex)	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	SE Vestibule (Link to Annex)	95	SF	6	6-10 years	
	Walls - Structural Glazed Tile	SE Vestibule (Link to Annex)	115	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SW Vestibule	255	SF	6	6-10 years	
	Doors - Side-lite	SW Vestibule	24	SF	6	6-10 years	
	Doors - Transom Window	SW Vestibule	64	SF	6	6-10 years	
	Doors - Wood Doors include hw	SW Vestibule	3	ĒΑ	6	6-10 years	
	Floor - Tile Quarry	SW Vestibule	255	SF	6	6-10 years	
	Lighting - Pendent/Surface	SW Vestibule	3	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	SW Vestibule	115	SF	6	6-10 years	
	Walls - Structural Glazed Tile	SW Vestibule	160	SF	6	6-10 years	

Campus Name: Reilly Page : 21 of 53 Assessment Date: 08/23/2021



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	East Stair	640	SF	7	6-10 years	
	Floor - Asphalt	East Stair	780	SF	7	6-10 years	
	Handrails ·	East Stair	146	LF	7	6-10 years	
	Lighting - Pendent/Surface	East Stair	5	EA	7	6-10 years	
	Lighting - Wall Mounted	East Stair	1	EA	7	6-10 years	
	Stairs - Asphalt	East Stair	416	LF	7	6-10 years	
	Walls - Plaster/Drywall	East Stair	2,800	SF	6	6-10 years	
	Walls - Plaster/Drywall	East Stair	200	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	NW Stairs	650	SF	6	6-10 years	
	Floor - Asphalt	NW Stairs	800	SF	7	6-10 years	
	Handrails .	NW Stairs	152	LF	7	6-10 years	
	Lighting - Pendent/Surface	NW Stairs	6	EA	7	6-10 years	
	Stairs - Asphalt	NW Stairs	425	LF	7	6-10 years	
	Walls - Plaster/Drywall	NW Stairs	3,000	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SE Stairs	420	SF	6	6-10 years	
	Floor - Asphalt	SE Stairs	718	SF	7	6-10 years	
	Handrails	SE Stairs	62	LF	7	6-10 years	
	Lighting - Pendent/Surface	SE Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	SE Stairs	380	LF	7	6-10 years	
	Walls - Plaster/Drywall	SE Stairs	1,910	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	SW Stair	430	SF	6	6-10 years	
	Floor - Asphalt	SW Stair	735	SF	7	6-10 years	
	Handrails .	SW Stair	65	LF	7	6-10 years	
	Lighting - Pendent/Surface	SW Stair	10	EA	7	6-10 years	
	Stairs - Asphalt	SW Stair	400	LF	7	6-10 years	
	Walls - Plaster/Drywall	SW Stair	2,000	SF	6	6-10 years	



Building: Linked Addition

Catego	Category : Exterior			Building : Linked Addition						
						Recommend	_			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
_Entrance										
	Entrance Control - Audio and Video	1 S - Addition	1	EA	7	6-10 years				
	Exterior Doors - Side lite	1 S - Addition	2	EΑ	6	6-10 years				
	Exterior Doors - Store Front	1 S - Addition	2	EΑ	6	6-10 years				
	Exterior Doors - Transom Lite	1 S - Addition	2	EΑ	6	6-10 years				
	Power Door Operator and Controls Exterior Doors - Exterior Steel Door	1 S - Addition 11	1	EΑ	7	6-10 years				
	Exterior Doors - Exterior Steel Door	12 NE Addition	1 2	EA EA	6 6	6-10 years 10+ years				
	Exterior Doors - Exterior Steel Door	13 NE - Addition	1	EA	7	6-10 years				
	Exterior Doors - Exterior Steel Door	14	1	EA	6	6-10 years				
	Exterior Doors - Exterior Steel Door	15 - 2nd Floor Fire Escape	1	EA	6	10+ years				
	Exterior Doors - Transom Lite	15 - 2nd Floor Fire Escape	1	EA	7	10+ years				
	Exterior Stairs - Steel or Aluminum	15 - 2nd Floor Fire Escape	1	LF	5	10+ years				
	Stair Handrail - Steel Stair Handrail	15 - 2nd Floor Fire Escape	1	LF	5	10+ years				
	Exterior Doors - Store Front	2 W - Addition	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	2 W - Addition	2	ΕA	6	6-10 years				
	Exterior Doors - Exterior Steel Door	3 NW - Addition	1	EA	5	6-10 years				
	Exterior Doors - Transom Lite	3 NW - Addition	1	EA	6	6-10 years				
	Exterior Doors - Exterior Steel Door	4 N Addition	1	EA	6	6-10 years				
	Exterior Doors - Transom Lite	4 N Addition	1	EA	6	6-10 years				
	Entrance Control - Audio and Video	5 N - Addition	1	EA	7	6-10 years				
	Exterior Doors - Store Front	5 N - Addition	1	EA	6	6-10 years				
_Fire Esca	аре									
	Fire Escape	North Façade	63	LF	6	6-10 years	See Entrance #15			
_Foundati	on									
	Foundation - Concrete	Entire Building	685	LF	7	0-1 year	Slab Heave/Cracking at Door #14 - Multi-Purpose Room			
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	33,646	SF	7	10+ years				
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	1,130	SF	7	10+ years				
Lighting										
	Exterior Lighting - Wall Mounted	Entire Building	21	EA	6	6-10 years				
Roof Sys	stem									
-	Access Ladder - Metal	G	1	EA	7	10+ years				
	Coping - Stone	G	648	LF	7	2-5 years				
	Downspouts - Interior Downspouts	G	153	LF	6	6-10 years				
	Parapet - 16" - 30" Height	G	648	LF	6	6-10 years				

Campus Name: Reilly Page : 23 of 53 Assessment Date: 08/23/2021



Catego	ry : Exterior		В	Building : Linked Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Roof - Modified Bitumen	G	16,808	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/	G	16,808	SF	7	10+ years			
	Concrete Topping								
	Downspouts - Exterior Downspouts	Н	48	LF	6	10+ years			
	Roof - Metal	Н	1,408	SF	6	10+ years			
	Roof Structure - Steel / Metal Deck/	Н	1,408	SF	7	10+ years			
	Concrete Topping		40	. –	•	0.40			
	Downspouts - Exterior Downspouts	1	12	LF	6	6-10 years			
	Roof - Metal	1	264	SF SF	6	10+ years			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	ı	264	SF	7	10+ years			
	Downspouts - Exterior Downspouts	J	12	LF	6	10+ years			
	Roof - Metal	J	288	SF	6	10+ years			
	Roof Structure - Steel / Metal Deck/	J	288	SF	7	10+ years			
	Concrete Topping	-				, , , , ,			
	Downspouts - Exterior Downspouts	K	16	LF	6	6-10 years			
	Roof - Metal	K	1,160	SF	6	10+ years			
	Roof Structure - Steel / Metal Deck/	K	1,160	SF	7	10+ years			
	Concrete Topping								
Valls									
	Exterior Walls - Concrete Block	Entire Building	10,000	SF	6	10+ years			
	Exterior Walls - Concrete Block	Entire Building	1,173	SF	5	2-5 years			
	Exterior Walls - Terra Cotta	Entire Building	1,700	SF	6	10+ years			
Vindows	3								
	Clerestory - Glass Double-Pane	Entire Building	640	SF	7	10+ years			
	Guard - Guards perforated	Entire Building	3,158	SF	6	6-10 years			
	Lintels - Steel	Entire Building	846	LF	6	10+ years			
	Windows - Decorative	Entire Building	1,683	SF	6	10+ years			
	Windows - Louver	Entire Building	432	SF	6	10+ years			
	Windows - Sash Aluminum Double-pane	Entire Building	4,632	SF	6	10+ years			
atego	ry : Electrical		В	uilding	: Linked	d Addition			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
merger	ncy System								
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	Serves addition. School has AC generator, 1995 installation		
	Security System - CCTV	Entire Building	34,776	SF	6	6-10 years	Connected to monitor in main building		
	Security System - Intrusion Detection	Entire Building	34,776	SF	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	10	ĒΑ	6	6-10 years			
	Exit Signs - Gym	Entire Building	2	ĒΑ	6	6-10 years	Building has AC generator		

Campus Name: Reilly Page : 24 of 53 Assessment Date: 08/23/2021



Catego	ry : Electrical		В	Building : Linked Addition					
					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years			
	Emergency Battery Packs - Gym	Entire Building	1	EA	6	6-10 years	Building also served by AC generator		
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,561	SF	6	10+ years	Building has an EM panel		
	Emergency A/C Power - Gym	Entire Building	1,654	SF	6	10+ years			
	Emergency A/C Power - Lunchrooms	Entire Building	2,242	SF	6	10+ years			
Main Se									
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	Serves addition		
	Main Electrical Service - 800 A and 277/480/3PH	Electrical Room	1	EA	7	10+ years	Serves addition		
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	ATS, serves addition		
	PA System	Entire Building	34,776	SF	6	6-10 years	Connected to main building and modular buildings. Some rooms have damaged units, repair needed.		
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	2	EΑ	7	10+ years	1995 installation		
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years			
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years			
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years			
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years			
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years			
Catego	ry : Fire Protection		В	uilding	: Linked	Addition			
Srou-	Itom Tuno	Location	Ougntitue	LIOM	Donk	Recommend	Comments		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar		Fating Desiration				0.5.	O a manage and altaking		
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	Serves addition		
	Fire Alarm Strobe Lights	Entire Building	34,776	SF	6	6-10 years	0 1100		
	Fire Alarm_System Fire Pump Controller	Entire Building Entire Building	34,776	SF EA	5 6	2-5 years 6-10 years	Serves addition		
		Entiro Diuldina	1						

Campus Name: Reilly Page : 25 of 53 Assessment Date: 08/23/2021



Catego	ry : Fire Protection		В	uilding	: Linked	d Addition	
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Mechanical Room	1	EA	5	6-10 years	Serves addition building
	Jockey Pump	Mechanical Room	1	EA	5	10+ years	
Carialda	Custom						
_Sprinkle	Sprinkler Heads	Entire Building	34,776	SF	7	10 L VOORO	1995 installation
	Sprinkler Piping	Entire Building Entire Building	34,776	SF	7	10+ years 10+ years	1995 Installation
	Wet Sprinkler System	Entire Building	34,776	SF	7	10+ years	
		g	2 1,1 1 2		-	, , , , , , , , , , , , , , , , , , , ,	
Catego	ry : Mechanical		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	S .						
	Chemical Pot Feeder	Roof	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	5	6-10 years	Serves addition, CH 1, with many
	Mounted - 101 - 200 tons	Doof	1	ГΛ	E	6.10 vooro	replaced parts.
	Glycol Feed Pressure Fill System	Roof Roof	1	EA EA	5 5	6-10 years 6-10 years	1995 installation
	r ressure r iii Oysterii	Rooi		LA	3	0-10 years	1999 Installation
_Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Inline -	Mechanical Room	1	EA	5	10+ years	RF 1, serves addition
	5000 - 10000 CFM					-	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	AHU 1, serves addition
	Indoor- Hot Water and Chilled Water Coils -						
	20001-30000 cfm Air Intake	Mechanical Room	1	EA	6	10+ years	
	VAV Box	Mechanical Room	21	EA	6	10+ years	Above ceilings
	VAV BOX	Weenaneartoom	۷.	L/\	O	TOT years	Above centings
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	5	6-10 years	
	- 2001 - 3000 MBH					-	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Dual Temperature Pump Glycol Feed System	Boiler Room Boiler Room	2 1	EA EA	5 5	6-10 years 6-10 years	
	Non Condensing- Water Tube- Flexible	Boiler Room	2	EA	6	6-10 years	B1, B2, serve addition
	Tube- Force Draft- Hot Water Boiler - 2001	Bollet Room	2	LA	U	0-10 years	D1, D2, Serve addition
	- 3000 MBH						
_Heating							
	Fin Tube - Hot Water	Entire Building	170	LF	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	

Campus Name: Reilly Page : 26 of 53 Assessment Date: 08/23/2021



Catego	ry : Mechanical		В	uilding	: Linked	l Addition	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Electric	Mechanical Room	1	EΑ	6	6-10 years	
	Unit Heater - Hot Water	Mechanical Room	1	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	10+ years	
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	5	2-5 years	Serve addition
	Hydronic Supply and Return - Steel	Entire Building	1,600	LF	6	10+ years	There are a few pipe clamps
Tempera	ature Control						
	DDC System	Entire Building	34,776	SF	6	10+ years	1995, 2015 software update, served from main building
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serve unit heaters
	Thermostats - DDC	Entire Building	21	EA	6	10+ years	21 VAVs, zones
	Memosiais - DDC	Littile building	21	LA	U	10+ years	21 VAVS, 201165
Unit Ven							
	Unit Ventilators- Floor Mounted- Hot Water & Chilled Water Coils	Entire Building	19	EA	5	6-10 years	Integral temperature controls
	a crimoa Water Conc						
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	Serves kitchen
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		R	uildina	· I inkod	I Addition	
Catego	ry . r lumbing			ununig	. Lilikee	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	-		,				
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serve addition
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serve addition
Pining							
Piping	Domestic Piping-Hot Water Return Lines	Entire Building	34,776	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	34,776	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	34,776	SF	7	10+ years	
	Fixtures	Little Danding	07,170	51	•	ioi youis	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,776	SF	7	10+ years	

Campus Name: Reilly Page : 27 of 53 Assessment Date: 08/23/2021



Catego	Category : Plumbing				Building : Linked Addition				
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	(Horizontal Lines)								
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,776	SF	7	10+ years			
	(Risers)								
	Domestic Piping-Hot/Cold Water Supply	Entire Building	34,776	SF	7	10+ years			
	(from Risers to Fixtures)								
	Sanitary Piping	Entire Building	34,776	SF	7	10+ years			
	Storm Piping	Entire Building	34,776	SF	7	10+ years			
	Vent Piping	Entire Building	34,776	SF	7	10+ years			
Pumps									
•	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	6-10 years	Serves annex and main building, PB		
					•	,	1		
	Pumps - Ejector-Simplex	Mechanical Room	2	EA	5	6-10 years	Mechanical room		
	Pumps - Sump-Simplex	Mechanical Room	1	ĒΑ	5	10+ years	Under elevator		
	- I F - F				-	. ,			

Category : Room **Building: Linked Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor Faculty Lounge	598	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor Faculty Lounge	1	EA	7	6-10 years	
	Floor - Tile	1st Floor Faculty Lounge	598	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	1st Floor Faculty Lounge	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Faculty Lounge	339	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor Faculty Lounge	798	SF	6	6-10 years	
	Work SInk	1st Floor Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Lay-in	221- office second floor	460	SF	6	6-10 years	
	Doors - Side-lite	221- office second floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	221- office second floor	1	EA	6	6-10 years	
	Floor - Tile	221- office second floor	460	SF	7	6-10 years	
	Lighting - Lay-in	221- office second floor	6	EA	7	6-10 years	
	Power Distribution	221- office second floor	14	EA	7	6-10 years	
	Walls - Concrete Block	221- office second floor	512	SF	6	6-10 years	
	Walls - Plaster/Drywall	221- office second floor	352	SF	6	6-10 years	
	Ceiling - Lay-in	Assistant Principal's Office North	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office North	1	EA	7	6-10 years	
	Floor - Tile	Assistant Principal's Office North	144	SF	7	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office North	1	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office North	8	EA	7	6-10 years	
	Walls - Concrete Block	Assistant Principal's Office North	20	SF	6	6-10 years	
	Walls - Plaster/Drywall	Assistant Principal's Office North	459	SF	6	6-10 years	
	Ceiling - Lay-in	Assistant Principal's Office South	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office South	1	EA	6	6-10 years	

Campus Name: Reilly Page : 28 of 53 Assessment Date: 08/23/2021



Catego	Category : Room			uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Assistant Principal's Office South	144	SF	7	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office South	1	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office South	8	EA	7	6-10 years	
	Walls - Concrete Block	Assistant Principal's Office South	20	SF	7	6-10 years	
	Walls - Plaster/Drywall	Assistant Principal's Office South	459	SF	6	6-10 years	
	Ceiling - Lay-in	Basement Engineer's Office	60	SF	7	6-10 years	
	Doors - Steel Doors incl hw	Basement Engineer's Office	1	EA	7	6-10 years	
	Floor - Tile	Basement Engineer's Office	60	SF	7	6-10 years	
	Lighting - Lay-in	Basement Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Basement Engineer's Office	2	EA	7	6-10 years	
	Walls - Concrete Block	Basement Engineer's Office	198	SF	7	6-10 years	
	Ceiling - Lay-in	Conference Room	292	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Conference Room	1	EA	6	6-10 years	
	Floor - Tile	Conference Room	292	SF	7	6-10 years	
	Lighting - Lay-in	Conference Room	3	ĒΑ	7	6-10 years	
	Power Distribution	Conference Room	8	EA	7	6-10 years	
	Walls - Concrete Block	Conference Room	120	SF	7	6-10 years	
	Walls - Plaster/Drywall	Conference Room	579	SF	7	6-10 years	
	Ceiling - Lay-in	Kitchen Office	113	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Kitchen Office	1	ĒΑ	6	6-10 years	
	Floor - Tile	Kitchen Office	113	SF	7	6-10 years	
	Lighting - Lay-in	Kitchen Office	2	EA	7	6-10 years	
	Power Distribution	Kitchen Office	6	EΑ	7	6-10 years	
	Walls - Concrete Block	Kitchen Office	363	SF	7	6-10 years	
	Ceiling - Lay-in	Main Office	503	SF	6	6-10 years	
	Doors - Store Front	Main Office	1	EA	6	6-10 years	
	Floor - Tile	Main Office	503	SF	6	6-10 years	
	Lighting - Lay-in	Main Office	6	EA	7	6-10 years	
	Power Distribution	Main Office	12	EA	7	6-10 years	
	Storage/ Closet	Main Office	12	SF	7	6-10 years	
	Walls - Concrete Block	Main Office	380	SF	6	6-10 years	
	Walls - Plaster/Drywall	Main Office	354	SF	6	6-10 years	
	Ceiling - Lay-in	Main Office- Vault/Work	158	SF	7	6-10 years	
	Celling - Lay-III	Room/Storage	130	Oi	,	0-10 years	
	Doors - Steel Doors incl hw	Main Office- Vault/Work	1	EA	7	6-10 years	
	Doors - Steel Doors Inc. IIW	Room/Storage	'	LA	,	0-10 years	
	Floor - Tile	Main Office- Vault/Work	158	SF	7	6-10 years	
	11001 - 1116	Room/Storage	130	31	'	0-10 years	
	Lighting - Lay-in	Main Office- Vault/Work	3	EA	7	6-10 years	
	Lighting - Lay-in	Room/Storage	3	LA	'	0-10 years	
	Power Distribution	Main Office- Vault/Work	10	EA	7	6-10 years	
	I OWEL DISHIBUTION	Room/Storage	10	EA	,	o-10 years	
	Walls - Concrete Block	Main Office- Vault/Work	395	SF	6	6-10 years	
	vvalis - Collete Block	Room/Storage	393	JF	O	U-10 years	
		110011#Otorage					



Catego	ry : Room		В	uilding	: Linked	d Addition	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work SInk	Main Office- Vault/Work	1	EA	7	6-10 years	
		Room/Storage					
	Ceiling - Lay-in	Principal's Office	144	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	6-10 years	
	Floor - Tile	Principal's Office	144	SF	7	6-10 years	
	Lighting - Lay-in	Principal's Office	1	EA	7	6-10 years	
	Power Distribution	Principal's Office	6	EA	7	6-10 years	
	Walls - Concrete Block	Principal's Office	20	SF	6	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	459	SF	6	6-10 years	
	Ceiling - Lay-in	Student Services	103	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Student Services	1	EA	6	6-10 years	
	Floor - Tile	Student Services	103	SF	7	6-10 years	
	Lighting - Lay-in	Student Services	1	EA	7	6-10 years	
	Power Distribution	Student Services	4	EA	7	6-10 years	
	Walls - Concrete Block	Student Services	219	SF	7	6-10 years	
	Walls - Plaster/Drywall	Student Services	59	SF	7	6-10 years	
	Work SInk	Student Services	1	EA	7	6-10 years	
	Ceiling - Lay-in	office1- Library Office / Work Room	142	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	office1- Library Office / Work Room	1	EA	7	6-10 years	
	Floor - Tile	office1- Library Office / Work Room	142	SF	7	6-10 years	
	Lighting - Lay-in	office1- Library Office / Work Room	2	EA	7	6-10 years	
	Power Distribution	office1- Library Office / Work Room	6	EA	7	6-10 years	
	Walls - Concrete Block	office1- Library Office / Work Room	104	SF	6	6-10 years	
	Walls - Plaster/Drywall	office1- Library Office / Work Room	300	SF	6	6-10 years	
	Work SInk	office1- Library Office / Work Room	1	EA	7	6-10 years	
_Gvmnas	ia						
	Ceiling - Lay-in	1st Floor	1,000	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	654	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	6-10 years	
	Floor - Tile	1st Floor	1,654	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	7	ΕA	7	10+ years	
	Walls - Concrete Block	1st Floor	2,635	SF	6	6-10 years	
	Walls - Metal Panel	1st Floor	702	SF	6	6-10 years	
IZitala a :-							
Kitchen	Ceiling - Plaster/Drywall	first floor near mechanical room	940	SF	7	6-10 years	
	Doors - Steel Doors incl hw	first floor near mechanical room	3	Sr EA	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	first floor near mechanical room	940	SF	7 7	,	
	Lighting - Lay-in	first floor near mechanical room	15	Sr EA	7 7	6-10 years 6-10 years	
	Serving Line	first floor near mechanical room	12	LF	7 7	6-10 years	
	Walls - Concrete Block	first floor near mechanical room	1,550	SF	7	6-10 years	
	Walls - Colloiete Dlock	mat noor near mechanical room	1,550	OI.	,	U-10 years	



Catego	ry : Room		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library							
	Casework	2nd Floor	57	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,551	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,551	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	526	SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	160	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	494	SF	6	6-10 years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,500	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	742	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	6-10 years	
	Floor - Tile	1st Floor	2,242	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	30	EA	7	6-10 years	
	Serving Line	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	982	SF	6	6-10 years	
	Walls - Metal Panel	1st Floor	702	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	470	SF	6	6-10 years	
MDF ID	F						
	Doors - Wood Doors inclu hw	Storage Room next to Classroom	1	EA	7	6-10 years	
		114. Not in the Basement				,	
	Finishes	Storage Room next to Classroom	22	SF	7	6-10 years	
		114. Not in the Basement				•	
	Other Cooling Unit	Storage Room next to Classroom	1	EA	7	6-10 years	
	Ç	114. Not in the Basement				•	
Machani	cal/ Service Rooms						
_ivicciialii	Janitor's Closet	2nd Floor	15	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	425	SF	7	10+ years	
	Storage Room	2nd Floor	82	SF	7	10+ years	
	Storage Room	2nd Floor	30	SF	7	10+ years	
	Janitor's Closet	Basement	16	SF	5	6-10 years	
	Janitor's Closet	Basement	30	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	352	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	31	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	510	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	208	SF	5	6-10 years	
	Storage Room	Basement	150	SF	5	6-10 years	
	Storage Room	Basement	90	SF	5	6-10 years	
					-	, ,	



Category : Room			Building : Linked Addition						
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
estroor	_								
esilooi	Accessories	111A- under renovation	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	111A- under renovation	30	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	111A- under renovation	1	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	111A- under renovation	30	SF	7	6-10 years			
	Lavatory	111A- under renovation	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	111A- under renovation	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	111A- under renovation	155	SF	7	6-10 years			
	Water Closet	111A- under renovation	155	EA	7	6-10 years			
	Accessories	113/112 Shared	57	SF	7	•			
				SF SF		6-10 years			
	Ceiling - Plaster/Drywall	113/112 Shared	57		7	6-10 years			
	Doors - Wood Doors inclu hw	113/112 Shared	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	113/112 Shared	57	SF	7	6-10 years			
	Lavatory	113/112 Shared	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	113/112 Shared	2	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	113/112 Shared	192	SF	7	6-10 years			
	Water Closet	113/112 Shared	1	EA	7	6-10 years			
	Accessories	114A	30	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	114A	30	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	114A	1	EA	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	114A	30	SF	7	6-10 years			
	Lavatory	114A	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	114A	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	114A	155	SF	7	6-10 years			
	Water Closet	114A	1	EA	7	6-10 years			
	Accessories	1st Floor Mens	131	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Mens	131	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Mens	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Mens	131	SF	6	6-10 years			
	Floor Drain	1st Floor Mens	131	EA	7	6-10 years			
	Lavatory	1st Floor Mens	2	EA	7	6-10 years			
	Lighting - Lay-in	1st Floor Mens	2	EA	7	6-10 years			
	Lighting - Lay-in Lighting - Pendent/Surface	1st Floor Mens	5	EA	7	6-10 years			
	Partitions	1st Floor Mens	1	EA	7	,			
			-			6-10 years			
	Urinals	1st Floor Mens	1	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor Mens	294	SF	6	6-10 years			
	Walls - Tile Ceramic/ Porcelain	1st Floor Mens	117	SF	6	6-10 years			
	Water Closet	1st Floor Mens	1	EA	7	6-10 years			
	Accessories	1st Floor Womens	131	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Womens	131	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor Womens	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Womens	131	SF	7	6-10 years			
	Floor Drain	1st Floor Womens	1	EA	7	6-10 years			

Campus Name: Reilly Page : 32 of 53 Assessment Date: 08/23/2021



Category : Room			Building : Linked Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	1st Floor Womens	2	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor Womens	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor Womens	4	EA	7	6-10 years		
	Partitions	1st Floor Womens	2	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor Womens	294	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	1st Floor Womens	117	SF	7	6-10 years		
	Water Closet	1st Floor Womens	2	EA	6	6-10 years		
	Accessories	2nd Floor	262	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	6	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	6	6-10 years		
	Lighting - Lay-in	2nd Floor	4	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	6-10 years		
	Urinals	2nd Floor	4	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	475	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	6-10 years		
	Water Closet	2nd Floor	2	EA	7	6-10 years		
	Accessories	2nd Floor	262	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	262	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	262	SF	7	6-10 years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	6	6-10 years		
	Lighting - Lay-in	2nd Floor	5	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years		
	Partitions	2nd Floor	5	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor	479	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	250	SF	6	6-10 years		
	Water Closet	2nd Floor	5	EA	7	6-10 years		
	Accessories	2nd Floor Unisex	73	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Unisex	73	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor Unisex	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex	73	SF	7	6-10 years		
	Floor Drain	2nd Floor Unisex	1	ĒΑ	7	6-10 years		
	Hand Dryer	2nd Floor Unisex	1	EA	7	6-10 years		
	Lavatory	2nd Floor Unisex	1	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor Unisex	4	EΑ	7	6-10 years		
	Walls - Concrete Block	2nd Floor Unisex	242	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor Unisex	165	SF	7	6-10 years		

Campus Name: Reilly Page : 33 of 53 Assessment Date: 08/23/2021



Category : Room			Building : Linked Addition					
_				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Water Closet	2nd Floor Unisex	1	EΑ	7	6-10 years		
	Accessories	Basement Engineer's Toilet Room	34	SF	7	6-10 years		
	Ceiling - Lay-in	Basement Engineer's Toilet Room	34	SF	7	6-10 years		
	Doors - Steel Doors incl hw	Basement Engineer's Toilet Room	1	EA	6	6-10 years		
	Floor - Tile	Basement Engineer's Toilet Room	34	SF	7	6-10 years		
	Lavatory	Basement Engineer's Toilet Room	1	EA	6	6-10 years		
	Lighting - Lay-in	Basement Engineer's Toilet Room	1	EΑ	7	6-10 years		
	Walls - Concrete Block	Basement Engineer's Toilet Room	131	SF	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Basement Engineer's Toilet Room	40	SF	6	6-10 years		
	Water Closet	Basement Engineer's Toilet Room	1	EA	7	6-10 years		
	Accessories	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Faculty Lounge Toilet	1	EA	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Faculty Lounge Toilet	61	SF	7	6-10 years		
	Hand Dryer	Faculty Lounge Toilet	1	EΑ	7	6-10 years		
	Lavatory	Faculty Lounge Toilet	1	EA	7	6-10 years		
	Lighting - Pendent/Surface	Faculty Lounge Toilet	2	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Faculty Lounge Toilet	267	SF	7	6-10 years		
	Water Closet	Faculty Lounge Toilet	1	EΑ	7	6-10 years		
	Accessories	Kitchen Women	102	SF	7	6-10 years		
	Ceiling - Lay-in	Kitchen Women	102	SF	6	6-10 years		
	Doors - Steel Doors incl hw	Kitchen Women	2	EA	6	6-10 years		
	Floor - Tile	Kitchen Women	102	SF	7	6-10 years		
	Floor Drain	Kitchen Women	1	EA	7	6-10 years		
	Lavatory	Kitchen Women	1	EΑ	7	6-10 years		
	Lighting - Lay-in	Kitchen Women	2	EΑ	7	6-10 years		
	Student Lockers - One Tier	Kitchen Women	8	EA	7	6-10 years		
	Student Lockers - Two Tiers	Kitchen Women	6	EΑ	7	6-10 years		
	Walls - Concrete Block	Kitchen Women	175	SF	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Kitchen Women	175	SF	7	6-10 years		
	Water Closet	Kitchen Women	1	EA	7	6-10 years		
	Accessories	Main Office Toilet	48	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Main Office Toilet	48	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Main Office Toilet	1	EΑ	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Main Office Toilet	48	SF	7	6-10 years		
	Hand Dryer	Main Office Toilet	1	EA	7	6-10 years		
	Lavatory	Main Office Toilet	1	EA	7	6-10 years		
	Lighting - Wall Mounted	Main Office Toilet	2	EA	6	6-10 years		
	Walls - Tile Ceramic/ Porcelain	Main Office Toilet	265	SF	7	6-10 years		
	Water Closet	Main Office Toilet	1	EA	7	6-10 years		



Category : Classroom		Building : Linked Addition					
			•	11614		Recommend	
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	n #111 (Pre School)						
	Casework	1st Floor	50	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,130	SF	7	6-10 years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	6-10 years	
	Floor - Tile	1st Floor	1,130	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	24	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	745	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	495	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroom	n #112 (Pre School)						
	Casework	1st Floor	61	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,072	SF	6	6-10 years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,072	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	67	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	745	SF	6	6-10 years	
,	Walls - Plaster/Drywall	1st Floor	421	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroom	n #113 (Kindergarten)						
	Casework	1st Floor	40	LF	7	6-10 years	
	Casework Ceiling - Lay-in	1st Floor	1,072	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1,072	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,072	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	67	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	555	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	654	SF	6	6-10 years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Clooses	a #44.4 (Vindorgarter)						
	n #114 (Kindergarten)	4 . =!		. –			
	Casework	1st Floor	40	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,075	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	



Category : Classroom			В	Building : Linked Addition				
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	1st Floor	1,050	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Storage/ Closet	1st Floor	25	SF	7	6-10 years		
	Walls - Concrete Block	1st Floor	550	SF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	125	SF	6	6-10 years		
	Work Sink	1st Floor	2	EA	7	6-10 years		
Classroo	om #220 (Regular Classroom)							
	Casework	2nd Floor	35	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	40	SF	7	6-10 years	Repaired	
	Ceiling - Lay-in	2nd Floor	660	SF	6	6-10 years		
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor	700	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	664	SF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	342	SF	6	6-10 years		
	Work Sink	2nd Floor	1	EA	7	6-10 years		
Classroo	om #222 (Regular Classroom)							
0.000.00	Casework	2nd Floor	42	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	4	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	862	SF	6	6-10 years		
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor 2nd Floor	866	SF	6	6-10 years		
			1	EA	7	•		
	Lighting - Lay-in Lighting - Lay-in	2nd Floor 2nd Floor	11	EA	6	6-10 years 6-10 years		
	Marker Board	2nd Floor 2nd Floor	8	LF	6			
	Student Lockers - One Tier		-		_	6-10 years		
		2nd Floor	2	EΑ	6	6-10 years		
	Student Lockers - Two Tiers	2nd Floor	4	EA	6	6-10 years		
	Walls - Concrete Block	2nd Floor	600	SF	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	6-10 years		
Classroc	m #223 (Office)							
	Casework	2nd Floor	42	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	866	SF	6	6-10 years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years		
	Floor - Tile	2nd Floor	866	SF	7	6-10 years		



Catego	ry : Classroom		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	573	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	565	SF	6	6-10 years	
Classroc	om #224 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	12	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	854	SF	6	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	866	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #225 (Regular Classroom)						
	Casework	2nd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	6	SF	7	6-10 years	Repaired
	Ceiling - Lay-in	2nd Floor	860	SF	6	6-10 years	1,
	Chalk Board	2nd Floor	12	ĹF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	6-10 years	
	Floor - Tile/Sheet	2nd Floor	866	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	2	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	12	SF	7	6-10 years	Repaired
	Walls - Plaster/Drywall	2nd Floor	640	SF	6	6-10 years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
Classroc	om #226 (Regular Classroom)						
	Casework	2nd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	866	SF	6	6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Linked	d Addition	-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	866	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #227 (Regular Classroom)						
	Casework	2nd Floor	42	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	40	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	826	SF	6	6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	866	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	455	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	662	SF	6	6-10 years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #228 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	14	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	850	SF	6	6-10 years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	6-10 years	
	Floor - Tile	2nd Floor	864	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EΑ	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	785	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	296	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EΑ	7	6-10 years	
			·		•	- 1- ,00.0	



Catego	ry : Classroom		R	uildina	· I inker	l Addition	1650 W School STREET, Chicago, IL 60618
Catego	y . Classicom			unung	. LIIIKEC	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	m #229 (Regular Classroom)	Location	quantity	00111	Raine	Ropidoomont	Comments
Classico	Casework	2nd Floor	27	LF	6	6-10 years	
	Ceiling - Exposed	2nd Floor	187	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	15	SF	7	,	
	Ceiling - Lay-in	2nd Floor	810	SF SF	6	10+ years 6-10 years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	11	SF	6	6-10 years	
					_		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	1,012	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	10	EΑ	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor	3	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	621	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	772	SF	6	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #Computer Room (Computer Lab)						
	Casework	2nd Floor	72	LF	7	6-10 years	
	Casework	2nd Floor	70	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,100	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile	2nd Floor	1,100	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	500	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	609	SF	7	6-10 years	
	•	2nd Floor	1	EA	7	6-10 years	
	Wireless System	2110 F1001	1	EA	,	6-10 years	
Catego	ry : Interior		В	uilding	: Linked	l Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Exposed	1st Floor	200	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,832	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,991	SF	6	6-10 years	
	Doors - Store Front	1st Floor	9	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	290	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3,733	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	24	EA	7	6-10 years	
	Lighting - Metal Halide/ High Pressure	1st Floor	6	EA	7	6-10 years	
	Sodium					•	



Catego	ry : Interior		В	uilding	: Linked	d Addition	-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	70	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,032	SF	7	6-10 years	
	Ceiling - Exposed	2nd Floor	1,124	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,210	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	3,284	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	40	EA	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	70	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	3,250	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	560	SF	6	6-10 years	
	Ceiling - Lay-in	Admin Corridor	192	SF	7	6-10 years	
	Doors - Wood Doors include hw	Admin Corridor	2	ĒΑ	7	6-10 years	
	Floor - Tile/Sheet	Admin Corridor	192	SF	7	6-10 years	
	Lighting - Lay-in	Admin Corridor	4	ĒΑ	7	6-10 years	
	Walls - Concrete Block	Admin Corridor	238	SF	7	6-10 years	
	Walls - Plaster/Drywall	Admin Corridor	234	SF	7	6-10 years	
		, • •	_0.	О.	•	0 .0 you.o	
Safety							
•	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	3	EA	7	6-10 years	
Stairs	Ceiling - Lay-in	East Stair	277	SF		6.10 years	
					6	6-10 years	
	Floor - Rubber Floor	East Stair	56	SF LF	6	6-10 years	
	Handrails	East Stair	68		7	6-10 years	
	Lighting - Lay-in	East Stair	4	EA	6	6-10 years	
	Stairs - Rubber	East Stair	126	LF	6	6-10 years	
	Walls - Concrete Block	East Stair	1,188	SF	6	6-10 years	
	Ceiling - Exposed	East Stair to Basement	155	SF	7	6-10 years	
	Floor - Concrete	East Stair to Basement	76	SF	7	6-10 years	
	Handrails	East Stair to Basement	48	LF	7	6-10 years	
	Lighting - Wall Mounted	East Stair to Basement	3	EΑ	7	6-10 years	
	Stairs - Concrete	East Stair to Basement	63	LF	6	2-5 years	
	Walls - Concrete Block	East Stair to Basement	929	SF	6	6-10 years	
	Ceiling - Lay-in	West Stair	272	SF	7	6-10 years	
	Floor - Rubber Floor	West Stair	92	SF	7	6-10 years	
	Handrails	West Stair	68	LF	7	6-10 years	
	Lighting - Lay-in	West Stair	4	EA	6	6-10 years	
	Stairs - Rubber	West Stair	196	LF	7	6-10 years	
	Walls - Concrete Block	West Stair	1,222	SF	6	6-10 years	
	Walls - Plaster/Drywall	West Stair	75	SF	6	6-10 years	
	Ceiling - Exposed	West Stair to Basement	59	SF	7	6-10 years	



Catego	ry : Interior		В	uilding	: Linked	l Addition		, <u> </u>	
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Concrete Epoxy/ Painted	West Stair to Basement	30	SF	7	6-10 years			
	Handrails	West Stair to Basement	48	LF	7	6-10 years			
	Lighting - Pendent/Surface	West Stair to Basement	2	EA	7	6-10 years			
	Stairs - Concrete	West Stair to Basement	72	LF	6	6-10 years			
	Walls - Concrete Block	West Stair to Basement	970	SF	6	6-10 years			
<u>Vertical</u>	Conveyance								
	Elevator - Hydraulic Elevator		1	EA	7	10+ years			

Page : 41 of 53 Campus Name: Reilly Assessment Date: 08/23/2021



Catego	ry : Exterior		В	uilding	: Modul	ar 1 (2-Classro	om)
O	Hann Toma	Lagation	Over the continue	HOM	Dank	Recommend	C
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance						0.40	
	Exterior Doors - Exterior Steel Door	4	1	EA	6	6-10 years	Door is unmarked. On west side of
	Ramp Handrail - Steel_Ramp Handrail	4	100	LF	6	6-10 years	Modular Unit.
	Ramps - Wood Ramp	4	50	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	5	1	EA	6	6-10 years	
	Exterior Stairs - Wood	5	20	LF	7	6-10 years	
	Stair Handrail - Steel_Stair Handrail	5	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	6	1	EA	6	6-10 years	
	Exterior Stairs - Wood	6	16	LF	6	6-10 years	
						, , , , , ,	
Foundati	ion Foundation - Concrete	Entire Building	184	LF	7	10	
	Superstructure - Steel with Clay Tile Arch	Entire Building Entire Building	1,632	SF	7 7	10+ years 10+ years	
	Superstructure - Steel with Glay The Arch	Little building	1,032	OI.	,	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	2-5 years	
Roof Sys	stem						
,	Downspouts - Exterior Downspouts	Entire Building	24	LF	4	6-10 years	
	Roof - Modified Bitumen	Entire Building	1,632	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Entire Building	1,632	SF	7	6-10 years	
	Concrete Topping	·				•	
Walls							
	Exterior Walls - Wood Siding	Entire Building	1,728	SF	6	10+ years	
	Exterior Walls - Wood Siding	Entire Building	40	SF	5	2-5 years	
	Exterior Walls - Wood Siding	Entire Building	184	SF	5	2-5 years	
Windows							
	Guard - Guards perforated	Entire Building	256	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	256	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (2-Classro	om)
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	1st Floor	3	EA	6	6-10 years	
	Stairs						

Campus Name: Reilly Page : 42 of 53 Assessment Date: 08/23/2021



	Schools						650 W School STREET, Chicago, IL 60618
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (2-Classro	oom)
0	U T	I a a dia u	0	11011	D	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (2-Classro	oom)
			.			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm_System	Entire Building	1,632	SF	5	2-5 years	Horn and sensors
Sprinkle	r System						
Оринис	Sprinkler Heads	Entire Building	1,632	SF	7	10+ years	2000 installation
	Sprinkler Piping	Entire Building	1,632	SF	7	10+ years	2000 motanation
	Wet Sprinkler System	Entire Building	1,632	SF	6	10+ years	City pressure
	voi opinido oyotom	Entire Ballating	1,002	O.	Ü	To Tyouro	City procedure
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Serve univents
Unit Ven	atilation						
OHIL VEI	Unit Ventilators - Vertical Package Electric	Entire Building	2	EA	5	2-5 years	
	Heat & Self Contained Cooling	Littile ballaring	2	LA	3	2-5 years	
Ventilation							
	Exhaust Fans- Roof Mounted - Less than	Roof	2	EA	5	6-10 years	Serve restrooms
	500 CFM						
Catego	ry : Plumbing		В	uildina	: Modul	ar 1 (2-Classro	oom)
	- ,		_			Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
Hot Wat			,				
TIOL Wat	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	2-5 years	Serves modular building
	Electric Fleater Leas than 20 KW	Wednamed Room	'	L/\	O	2 o yours	Serves modular building
Piping							
-,	Domestic Piping-Hot Water Return Lines	Entire Building	1,632	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	1,632	SF	6	10+ years	
	(Horizontal Lines)	9	.,502	٠.	•	,	
	Sanitary Piping	Entire Building	1,632	SF	6	10+ years	
	Storm Piping	Entire Building	1,632	SF	6	10+ years	
	Vent Piping	Entire Building	1,632	SF	6	10+ years	
		9	1,002	٥.	J	io. youro	

Campus Name: Reilly Page : 43 of 53 Assessment Date: 08/23/2021



Frank W Reilly Elementary School

3650 W School STREET, Chicago, IL 60618

Category : Plumbing Building : Modular 1 (2-Classroom)
Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

Category : Classroom Building : Modular 1 (2-Classroom)

	,					(· · · · /
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroor	n #001 (Store Room)						
	Ceiling - Plaster/Drywall	1st Floor	630	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	6-10 years	
	Floor - Tile	1st Floor	630	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	7	6-10 years	
ssroor	n #002 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	9	SF	7	6-10 years	Repaired
	Ceiling - Lay-in	1st Floor	621	SF	6	6-10 years	·
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	630	SF	6	2-5 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	6	6-10 years	

Category : Room Building : Modular 1 (2-Classroom)

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Restroon	n						
	Accessories	Unisex North	54	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex North	54	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Unisex North	1	EA	6	6-10 years	
	Floor - Tile	Unisex North	54	SF	6	6-10 years	
	Floor Drain	Unisex North	1	EA	7	6-10 years	
	Lavatory	Unisex North	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Unisex North	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Unisex North	224	SF	6	6-10 years	
	Water Closet	Unisex North	1	EA	6	6-10 years	
	Accessories	Unisex South	54	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex South	54	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Unisex South	1	EA	6	6-10 years	
	Floor - Tile	Unisex South	54	SF	6	6-10 years	
	Floor Drain	Unisex South	1	EA	7	6-10 years	
	Lavatory	Unisex South	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Unisex South	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Unisex South	224	SF	6	6-10 years	
	Water Closet	Unisex South	1	EA	6	6-10 years	

Campus Name: Reilly Page: 44 of 53 Assessment Date: 08/23/2021



Building: Modular 1 (2-Classroom) Category : Room

Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments

Campus Name: Reilly Page: 45 of 53 Assessment Date: 08/23/2021



Catego	ry : Exterior		В	uilding	: Modul	ar 2 (2-Classro	oom)
Graun	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOIVI	Kalik	Replacement	Comments
Entrance	Exterior Doors - Exterior Steel Door	1	1	EA	6	10+ years	Door is unmarked on West Side of Modular Unit.
	Ramp Handrail - Steel_Ramp Handrail	1	100	LF	6	10+ years	
	Ramps - Wood Ramp	1	50	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	10+ years	Door marked as #M-3 (North Door of South Modular Unit)
	Exterior Stairs - Wood	2	16	LF	6	10+ years	,
	Stair Handrail - Steel_Stair Handrail	2	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3	1	EA	6	10+ years	Door Marked as #M-4. South door of South Modular Unit)
	Exterior Stairs - Wood	3	16	LF	6	10+ years	,
	Stair Handrail - Steel_Stair Handrail	3	5	LF	6	10+ years	
oundat							
	Foundation - Concrete	Entire Building	184	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	1,632	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	2-5 years	
Roof Sys	stem						
-	Downspouts - Exterior Downspouts	Entire Building	24	LF	6	6-10 years	PVC Downspout
	Roof - EPDM/ Synthetic Rubber	Entire Building	1,632	SF	7	10+ years	·
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	1,632	SF	6	10+ years	
<i>N</i> alls							
	Exterior Walls - Wood Siding	Entire Building	1,768	SF	4	1-2 years	
Vindows							
	Guard - Guards perforated	Entire Building	256	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	256	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Modul	ar 2 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-merger	ncy System	4.5				0.10	
	Exit Signs - Corridors and Stairs	1st Floor	5	EΑ	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	2	EA	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Modul	ar 2 (2-Classro	om)
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	1	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	1	SF	5	6-10 years	
Main Se	rvice						
	PA System	1st Floor	1	SF	5	6-10 years	Connected to main and addition
	i A dystem	13(1100)	1	Oi.	3	0-10 years	buildings
Dawar D	lietrikution						
Power D	listribution Lighting and Power Panels - Above 100 A	1st Floor	2	EA	7	10+ years	
		10(1100)				•	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 2 (2-Classro	om)
Group	Itom Tuno	Location	Quantity	UOM	Donk	Recommend	Comments
Group Fire Alar	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
i ile Aidi	Fire Alarm_System	Entire Building	1,632	SF	5	2-5 years	Horns and sensor
	,	.	.,302	٥.	J	7 , 5 4. 5	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	1,632	SF	7	10+ years	
	Sprinkler Piping	Entire Building	1,632	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	1,632	SF	6	10+ years	City pressure, 2000 installation
Catego	ry : Mechanical		В	uildina	: Modul	ar 2 (2-Classro	oom)
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	For univents
	Alleste a						
Unit Ven	Unit Ventilators - Vertical Package Electric	Entire Building	2	EA	5	2-5 years	
	Heat & Self Contained Cooling	Entire Building	2	EA	5	2-5 years	
	riodi di con contamod coomig						
Ventilation							
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Modul	ar 2 (2-Classro	oom)
						Recommend	
Group	7.	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat		Della a Deces				0.40	0
	Electric Heater - Less than 20 KW	Boiler Room	1	EA	6	6-10 years	Serves modular building



Catego	ry : Plumbing		В	uilding	: Modul	ar 2 (2-Classro	om)
0	Hama Tama	Lasatian	0	LIOM	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	1,632	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	1,632	SF	6	10+ years	
	(Horizontal Lines)				_		
	Sanitary Piping	Entire Building	1,632	SF	6	10+ years	
	Storm Piping	Entire Building	1,632	SF	6	10+ years	
	Vent Piping	Entire Building	1,632	SF	6	10+ years	
			_			0 (0 0)	
Catego	ry : Classroom		В	uilding	: Modul	ar 2 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #003 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	630	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	630	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	6	6-10 years	
Classroo	m #004 (Regular Classroom)						
21000100	Ceiling - Lay-in	1st Floor	4	SF	4	1-2 years	Stained tiles
	Ceiling - Plaster/Drywall	1st Floor	626	SF	6	6-10 years	Otalited tiles
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	630	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	770	SF	6	6-10 years	
	Walls Villyl Coaled Cypsull' Lanci	13(1100)	110	O.	O	o ro years	
Catego	ry : Room		В	uilding	: Modul	ar 2 (2-Classro	om)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Restroon	· ·	Location	Quantity	O O III	rtaint	rtopidoomont	Comments
	Accessories	Unisex North	54	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex North	54	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Unisex North	1	EA	6	6-10 years	
	Floor - Tile	Unisex North	54	SF	6	6-10 years	
	Floor Drain	Unisex North	1	EA	7	6-10 years	
	Lavatory	Unisex North	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Unisex North	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Unisex North	224	SF	6	6-10 years	
	Water Closet	Unisex North	1	EA	6	6-10 years	
	Accessories	Unisex South	54	SF	7	6-10 years	

Campus Name: Reilly Page : 48 of 53 Assessment Date: 08/23/2021



Building: Modular 2 (2-Classroom) Category: Room

	- 7						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Unisex South	54	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Unisex South	1	EA	6	6-10 years	
	Floor - Tile	Unisex South	54	SF	6	6-10 years	
	Floor Drain	Unisex South	1	EA	7	6-10 years	
	Lavatory	Unisex South	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Unisex South	1	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Unisex South	224	SF	6	6-10 years	
	Water Closet	Unisex South	1	EA	6	6-10 years	

Campus Name: Reilly Page : 49 of 53 Assessment Date: 08/23/2021





Category : Site **Building: Site**

						Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	7	ΕA	6	6-10 years	
					•	5 . 5 , 5	
encina							
J	Fencing - Chain Link	Entire Site	148	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	222	LF	5	1-2 years	
	Fencing - Guard Rail	Entire Site	54	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,231	LF	6	10+ years	
andsca	Landscape - Hardscape- Asphalt	Entire Site	1,500	SF	4	1-2 years	
	Landscape - Hardscape- Concrete	Entire Site	2,792	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	60	SF	5	1-2 years	
	Landscape - Mulch	Entire Site	2,000	SF	6	6-10 years	
	Parkway trees	Entire Site	28	EA	6	6-10 years	
	Planting Beds/ Area	Entire Site	2,832	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	14,003	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	249	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	4	SF	4	0-1 year	
	Trash Receptacles	Entire Site	1	EA	6	2-5 years	
						-	
arking I	Concrete Curbs	Leased - St. Wencelaus	470	LF	7	10+ years	
	Interior Plantings	Leased - St. Wencelaus	2,500	LF	7	6-10 years	
	Lighting - Pole Mounted	Leased - St. Wencelaus	2,300	EA	7	10+ years	
	Surface - Asphalt	Leased - St. Wencelaus	24,534	SF	7	10+ years	
	Vehicular Screening	Leased - St. Wencelaus	176	LF	7	10+ years	
	Concrete Curbs	North	160	LF	6	2-5 years	
	Interior Plantings	North	79	LF	6	6-10 years	
	Lighting - Lighting	North	3	EA	6	6-10 years	
	Surface - Asphalt	North	20,880	SF	7	6-10 years	
	Trash Enclosure - Chain Links	North	1,078	SF	6	6-10 years	
	Vehicular Screening	North	77	LF	6	6-10 years	
	•					•	
Playgrou	nd Equipment - Pre K 3-5	West		ΓΛ	7	6.10 4005	
	Equipment - Pre K 3-5 Equipment - School Age 5-12	West	1	EA EA	7 7	6-10 years	
	Surface - Poured Surface	West	1,500	SF	7 7	6-10 years	
	Surface - Foured Sufface	VVESI	1,500	SE	1	10+ years	

Page : 50 of 53 Campus Name: Reilly Assessment Date: 08/23/2021



Catego	ry : Site		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	7,999	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	5	0-1 year	
Signage							
_ Cignage	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	6-10 years	
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Reilly Page: 51 of 53 Assessment Date: 08/23/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			+				•	1	
Art Room	Regular Classroom	1st Floor	102	102	868	240	58	N	N
Computer Lab	Office	2nd Floor	201	201	852	240	58	N	N
Kindergarten	Kindergarten	1st Floor	105	105	880	240	58	N	Y
Music Room	Regular Classroom	2nd Floor	207	207	852	240	58	N	N
Regular Classroom	Faculty Lounge	3rd Floor	301	301	852	240	58	N	N
Regular Classroom	Lunch Room	1st Floor	108	108	868	240	58	N	Υ
Regular Classroom	Other Instructional Use	2nd Floor	203	203	873	240	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	868	240	58	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	815	240	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	876	240	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	855	240	58	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	852	240	58	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	875	240	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	865	240	58	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	852	240	58	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	852	240	58	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	872	240	50	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	872	240	50	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	872	240	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	852	240	58	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	852	320	58	N	Υ
Science Classroom	Regular Classroom	2nd Floor	204	204	880	240	58	N	Υ
Science Classroom	Regular Classroom	3rd Floor	300	Household	996	300	103	N	Υ
				Arts					
Science Classroom	Regular Classroom	3rd Floor	304	304	872	240	50	N	Υ
Special Education	Laboratory/Shop	3rd Floor	326	Shop	330	80	16	N	N

Building : Linked Addition	on								
Computer Lab	Computer Lab	2nd Floor	Computer Room	211	1,100	200	100	N	N
Kindergarten	Kindergarten	1st Floor	113	104	1,072	180	60	N	Υ
Kindergarten	Kindergarten	1st Floor	114	105	1,075	180	60	N	Y
Office	Regular Classroom	2nd Floor	223	206	866	150	75	N	N
Pre School	Pre School	1st Floor	111	111	1,130	200	100	N	Y
Pre School	Pre School	1st Floor	112	101	1,072	300	100	N	Y
Regular Classroom	Regular Classroom	2nd Floor	220	211	700	150	75	N	Y
Regular Classroom	Regular Classroom	2nd Floor	222	201	866	250	125	N	Y
Regular Classroom	Regular Classroom	2nd Floor	224	202	866	150	75	N	Y



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	225	207	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	203	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	227	208	866	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	228	204	864	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	229	209	1,012	234	33	N	Υ

Building : Modular 1 (2-Classroom)													
Regular Classroom	Regular Classroom	1st Floor	002	002	630	52	25	N	N				
Store Room	Regular Classroom	1st Floor	001	001	630	52	25	N	N				

Building : Modular 2 (2-Classroom)													
Regular Classroom	Regular Classroom	1st Floor	003	003	630	52	25	N	N				
Regular Classroom	Regular Classroom	1st Floor	004	004	630	52	25	N	Ν				

Campus Name: Reilly Page : 53 of 53 Assessment Date: 08/23/2021