

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1927	1	54,500
Addition	1975	1	17,400
Modular 1 (4-Classroom)	2002	1	4,900
Campus Total			76,800

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - Southeast	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 1 - Southeast	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 1 - Southeast	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 1 - Southeast	51	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - Southeast	5	LF	5	1-2 years	Cracked concrete at landing and steps
	Power Door Operator and Controls	Door 1 - Southeast	1	EΑ	7	10+ years	·
	Ramp Handrail - Steel_Ramp Handrail	Door 1 - Southeast	156	LF	6	10+ years	
	Ramps - Concrete	Door 1 - Southeast	78	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 1 - Southeast	16	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 10 - North courtyard	2	EΑ	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 10 - North courtyard	80	LF	5	10+ years	
	Ramps - Concrete	Door 10 - North courtyard	28	LF	6	10+ years	
	Ramps - Concrete	Door 10 - North courtyard	12	LF	5	1-2 years	spalled, broken concrete at rail post bases
	Exterior Doors - Exterior FRP Door	Door 10A - North	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 11 - North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 11 - North	34	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 11 - North	16	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 12 - Northeast	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 12 - Northeast	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 12 - Northeast	36	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stair Handrail - Steel_Stair Handrail	Door 12 - Northeast	25	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 12A - East north	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 12A - East north	2	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 13 - Northeast	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 13 - Northeast	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 13 - Northeast	50	LF	7	10+ years	
	Exterior Stairs - Concrete	Door 13 - Northeast	6	LF	5	1-2 years	Cracked concrete along all steps
	Power Door Operator and Controls	Door 13 - Northeast	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 13 - Northeast	70	LF	6	10+ years	
	Ramps - Concrete	Door 13 - Northeast	32	LF	6	10+ years	
	Ramps - Concrete	Door 13 - Northeast	3	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	Door 13 - Northeast	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 14 - East center	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 14 - East center	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 14 - East center	40	LF	7	10+ years	
	Exterior Stairs - Concrete	Door 14 - East center	4	LF	5	1-2 years	Cracked, broken concrete at steps
	Stair Handrail - Steel Stair Handrail	Door 14 - East center	25	LF	7	10+ years	,
	Exterior Doors - Exterior FRP Door	Door 15 - East center	2	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 15 - East center	4	ΕA	7	10+ years	
	Exterior Stairs - Concrete	Door 15 - East center	40	LF	7	10+ years	
	Stair Handrail - Steel Stair Handrail	Door 15 - East center	25	LF	7	10+ years	
	Exterior Doors - Store Front	Door 16 E - Center courtyard	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16 E - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Side lite	Door 16- Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 16- Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16- Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 16A - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16A - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 16B - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16B - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 16C - Center courtyard	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 16C - Center courtyard	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 16D - Center courtyard	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 16D - Center courtyard	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 16F - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16F - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite Exterior Doors - Exterior FRP Door	Door 16G - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	Door 16G - Center courtyard Door 16G - Center courtyard	1	EA	7	•	
	Exterior Doors - Transom Lite Exterior Doors - Exterior FRP Door	Door 16H - Center courtyard Door 16H - Center courtyard	1	EA	7	10+ years	
	Exterior Doors - Transom Lite		1	EA	7	10+ years	
		Door 6 Southwest	· · · · · · · · · · · · · · · · · · ·			10+ years	
	Exterior Doors - Exterior FRP Door	Door 6 - Southwest	1	EΑ	6	10+ years	
	Exterior Doors - Side lite	Door 6 - Southwest	2	EΑ	7	10+ years	
	Exterior Doors - Transom Lite	Door 6 - Southwest	2	EA	7	10+ years	
	Ramps - Concrete	Door 6 - Southwest	27	LF	6	10+ years	

Campus Name: Christopher Page : 2 of 39 Assessment Date: 10/12/2023



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	Door 6 - Southwest	3	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior Steel Door	Door 6A	1	EA	6	6-10 years	
	Exterior Doors - Side lite	Door 6A	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 6A	2	EA	6	6-10 years	
	Ramps - Concrete	Door 6A	20	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 7 - Southwest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 7 - Southwest	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 7 - Southwest	56	LF	7	10+ years	
	Power Door Operator and Controls	Door 7 - Southwest	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 7 - Southwest	70	LF	5	10+ years	
	Ramps - Concrete	Door 7 - Southwest	30	LF	6	10+ years	
	Ramps - Concrete	Door 7 - Southwest	5	LF	5	1-2 years	And broken curbs/foundation at post
	•					,	bases
	Stair Handrail - Steel_Stair Handrail	Door 7 - Southwest	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 8 - Northwest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 8 - Northwest	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 8 - Northwest	50	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 8 - Northwest	6	LF	5	1-2 years	Broken step, cracked landing
	Ramp Handrail - Steel_Ramp Handrail	Door 8 - Northwest	70	LF	5	10+ years	
	Ramps - Concrete	Door 8 - Northwest	35	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 8 - Northwest	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 8A - Northwest	1	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 8A - Northwest	1	EΑ	5	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 9 - North courtyard	1	EA	6	10+ years	
Foundati	on						
	Foundation - Concrete	Entire Building	1,060	LF	7	10+ years	
	Foundation - Concrete	Entire Building	500	LF	5	1-2 years	Water seepage and cracks
					-	,	throughout scary tunnels, and basement.
	Superstructure - Concrete	Entire Building	53,970	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	30	SF	5	1-2 years	Broken concrete with exposed reinforcement under parking lot, in boiler room area. There is also severe damage behind an overhead rolling door that cannot be opened.
Lighting							rolling door that cannot be opened.
<u> Ligitiirig</u>	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	1-2 years	Broken glass enclosure and/or bulb
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	4	EA	7	10+ years	

Campus Name: Christopher Page : 3 of 39 Assessment Date: 10/12/2023



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	Roof 1	1,066	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	62	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	252	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	1,066	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	33,508	SF	5	2-5 years	
	Roof - Modified Bitumen	Roof 1	1,000	SF	4	0-1 year	Ponding, buckling blistering, worn surfaces, and soft spots
	Roof Hatch - Metal	Roof 1	1	EA	7	6-10 years	τι τ
	Roof Hatch - Metal	Roof 1	3	EA	3	2-5 years	Stainless steel roof, hatches, screwd shut
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	34,508	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	380	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 2	10,067	SF	6	2-5 years	
	Roof - Metal	Roof 2	75	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 2	10,142	SF	7	10+ years	
	Concrete Topping				-	•	
	Access Ladder - Metal	Roof 3	1	EA	7	6-10 years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 3	60	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 3	15	LF	5	1-2 years	Open joints and cracks
	Coping - Stone	Roof 3	60	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	12	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	60	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	982	SF	6	2-5 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3	982	SF	7	10+ years	
		Doof 4	20		6	10	
	Coping - Stone	Roof 4	28	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	37	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	28	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	303	SF	6	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 4	303	SF	7	10+ years	
	Concrete Topping						
Valls							
	Canopy - Concrete/ Stucco	Entire Building	964	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	96	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,100	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	36,400	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	5	1-2 years	Open joints, repairs to previous assessment report data



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Guard - Guards perforated	Entire Building	5,000	SF	6	10+ years	
	Lintels - Brick	Entire Building	152	LF	7	10+ years	
	Lintels - Steel	Entire Building	452	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	1,300	SF	6	6-10 years	
	Skylite - Glass Single-Pane	Entire Building	200	SF	5	2-5 years	Impacted, repaired with silicone, cracked
	Windows - Louver	Entire Building	12	SF	5	6-10 years	
	Windows - Sash Aluminum	Entire Building	6,000	SF	6	10+ years	
Catego	ory : Electrical		В	uilding	: Main		
carego	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System						
	Exit Signs - Auditoium	1st Floor	12	EA	7	10+ years	
	Exit Signs - Corridors and Stairs	1st Floor	52	EA	7	10+ years	
	Exit Signs - Lunchroom	1st Floor	4	EA	7	10+ years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	1st Floor	13	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	62	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	1st Floor	4	EA	7	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	1st Floor	2,370	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	1st Floor	5,450	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	1st Floor	1,800	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	1st Floor	730	SF	6	6-10 years	
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	54,500	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	54,500	SF	6	6-10 years	
Main Co	n ion						
Main Se	Main Electrical Service - 1600 A 120/208/3PH	Basement	1	EA	6	6-10 years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Basement	1	EA	6	10+ years	
	PA System	Entire Building	54,500	SF	4	1-2 years	Not connecting to modular building, dated system
Power P	Distribution						•
TOWELL	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building	5	EA	6	2-5 years 2-5 years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
		Ŭ				·	



	70110013					30	142 3 Artesian Avenue, Chicago, il 6003
Catego	ry : Electrical		В	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Fariers - 400 - 600 amp	Entire building	2	EA	,	10+ years	
Catego	ry : Fire Protection		В	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	
	Fire Alarm Strobe Lights	Entire Building	54,500	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	54,500	SF	5	2-5 years	
	/	g	0.,000	<u>.</u>	· ·	_ 0 ,000	
Catego	ry : Mechanical		В	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted	10111001	·	_, `	•	ioi youro	
	Compressor - 4 - 5 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10 L V00r0	
		151 F1001	1	EA	1	10+ years	
	Heating & DX Cooling- Remote Mounted						
	Compressor - 4 - 5 tons				_		
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted						
	Compressor - 4 - 5 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted					, , , , , ,	
	Compressor - 4 - 5 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted	13(1100)	1	LA	,	10+ years	
	Compressor - 4 - 5 tons	4 . 5	_	_ ^	_	40	
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted						
	Compressor - 4 - 5 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted					·	
	Compressor - 4 - 5 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted	1301 1001	'	∟ ∧	,	10+ years	
	Compressor - Less than 3 tons	4 . =	_		_	4.0	
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted						
	Heating & DX Cooling- Remote Mounted						



Catego	ry : Mechanical		В	uilding	: Main	•	<u> </u>
					_	Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Compressor - Less than 3 tons Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted	180 11001	ı	LA	,	10+ years	
	Compressor - Less than 3 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted					•	
	Compressor - Less than 3 tons						
	Heat Pump- Ceiling Mounted- Electric	1st Floor	1	EA	7	10+ years	
	Heating & DX Cooling- Remote Mounted						
	Compressor - Less than 3 tons Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons	Kooi	I	EA	O	10+ years	
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons					, , , , , , , , , , , , , , , , , , , ,	
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons						
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons	Kooi	ı	LA	O	10+ years	
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons					,	
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons	Б. (4	^	•	40	
	Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	10+ years	
	tons Condensing Unit- Roof Mounted - 5-10	Roof	1	EA	6	10+ years	
	tons	11001			Ü	101 youro	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	
	than 5 tons					-	
_Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	136	1	EA	6	6-10 years	
	Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self	Roof	1	EA	6	10+ years	
	Contained Compressor - 10 - 20 tons						
	Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	10+ years	
	Gas Heating and DX Cooling w/ Self		•		· ·	.o. you.o	
	Contained Compressor - 21 - 30 tons						
	Make Up Air Unit- Roof Mounted- Gas	Roof - East	1	EA	6	10+ years	
	Heating and DX Cooling with Self Contained						
	Compressor - 10,001 - 20,000 cfm Make Up Air Unit- Roof Mounted- Gas	Roof - North	1	ΕΛ	6	10 L 2/00r0	
	Heating and DX Cooling with Self Contained	KOOI - NOITH	1	EA	6	10+ years	
	risating and bit cooming with cen contained						



Categor	y : Mechanical		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Compressor - 6000 - 10,000 cfm				_				
	Make Up Air Unit- Roof Mounted- Gas	Roof - South	1	EA	5	2-5 years			
	Heating - Less than 6000 cfm								
Boiler Sy	stems								
,	Boiler Auxiliary- Scotch Marine- Steam Low	Entire Building	2	EA	6	6-10 years			
	Pressure Boiler - 101 - 150 HP	9	_		Ū	o .o you.o			
	Chemical Feed System	Entire Building	1	EA	6	6-10 years			
	Combustion Dampers	Entire Building	2	EA	6	6-10 years			
	Condensate Pump	Entire Building	1	EΑ	6	6-10 years			
	Condensate Pump	Entire Building	1	EA	6	6-10 years			
	Feed Water Pumps and Tank	Entire Building	1	EA	6	6-10 years			
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years			
	Steam- Low Pressure Boiler - 101 - 150 HP	Little building	ı		J	o- io yeais			
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years			
	Steam- Low Pressure Boiler - 101 - 150 HP	Littile Ballaling	ı	LA	U	0-10 years			
	Piping - Condensate Pipe- Steel	Entire Building	800	LF	6	10 L Vooro			
	Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Entire Building Entire Building	800	LF	6	10+ years			
		· ·	75	EA	6	10+ years			
	Steam Traps	Entire Building	75	EA	0	6-10 years			
Heating [Devices								
	Wall Heater - Electric	1st Floor	9	EA	6	6-10 years			
	Wall Heater - Electric	1st Floor	7	EA	5	2-5 years			
	Radiators - Steam	1st Floor	46	EA	5	2-5 years			
	Fin Tube - Steam	1st Floor	30	LF	6	10+ years			
	Unit Heater - Electric	Entire Building	1	EA	6	2-5 years			
	Unit Heater - Gas	Entire Building	1	EA	5	2-5 years			
Tempera:	ture Control								
	DDC System	Entire Building	54,500	SF	6	10+ years			
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	Unit heaters		
	Electric Thermostat	Entire Building	2	EA	6	10+ years	RTUs		
	Electric Thermostat	Entire Building	1	EA	6	10+ years	11103		
	Thermostats - DDC	Entire Building	54,500	EA	7	10+ years			
	Thermostats DDC	Little Ballanig	04,000	L/\	•	101 years			
/entilatio									
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years			
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years			
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years			
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years			
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	10+ years			
	CFM	5				,			



Catego	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	Wall mounted
	Roof Mounted Duct Work	Entire Building	160	LF	7	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	High-Temp equipment but no fire
	•	Ç .				•	suppression
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	2-5 years	
	Gas Heater - Less than 150000 BTU/HR	Kitchen	1	EA	6	2-5 years	
Piping							
_г.ршу	Domestic Piping-Hot Water Return Lines	Entire Building	54,500	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	54,500	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	54,500	SF	6	10+ years	
	Fixtures	Little Ballaing	04,000	O.	O	101 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	54,500	SF	6	10+ years	
	(Horizontal Lines)	g	2 1,2 2 2	-	•	, , , , , , , , , , , , , , , , , , , ,	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	54,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	54,500	SF	6	10+ years	
	Sanitary Piping	Entire Building	54,500	SF	6	10+ years	
	Storm Piping	Entire Building	54,500	SF	6	10+ years	
	Vent Piping	Entire Building	54,500	SF	6	10+ years	
	3 1 3	3	,,,,,,,			, , , , ,	
<u>Pumps</u>						0.10	
	Pumps - Sump-Duplex	Basement	1	EA	6	6-10 years	For interpretable of
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	Far into crawl space, assessment based off engineer's knowledge
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Plaster/Drywall	136 Office	240	SF	7	10+ years	
	Doors - Transom Window	136 Office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	136 Office	2	ĒΑ	7	10+ years	
	Floor - Tile	136 Office	236	SF	7	10+ years	
	Floor - Tile	136 Office	4	SF	5	1-2 years	Cracking
						•	•



Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 136 Office 2 EΑ 6-10 years 7 Power Distribution 6 EΑ 7 6-10 years 136 Office Walls - Masonry 136 Office 508 SF 7 10+ years SF 7 Walls - Plaster/Drywall 136 Office 338 10+ years AC Unit 137 Technology Coordinator Office 1 EΑ 4 0-1 year Nonfunctional & Copy Room Ceiling - Lay-in 137 Technology Coordinator Office 347 SF 7 10+ years & Copy Room Doors - Transom Window 137 Technology Coordinator Office 6 SF 7 10+ years & Copy Room Doors - Wood Doors inclu hw 137 Technology Coordinator Office EΑ 7 1 10+ years & Copy Room 137 Technology Coordinator Office SF 7 Floor - Tile 347 10+ years & Copy Room 137 Technology Coordinator Office Lighting - Lay-in 5 EΑ 7 6-10 years & Copy Room 137 Technology Coordinator Office Power Distribution 6 EΑ 7 10+ years & Copy Room 137 Technology Coordinator Office SF Walls - Plaster/Drywall 1.260 6 10+ years & Copy Room Walls - Plaster/Drywall 137 Technology Coordinator Office 14 SF 5 1-2 years Cracking & Copy Room SF Ceiling - Lay-in 138 Special Needs Class 1.145 6-10 years SF Doors - Transom Window 138 Special Needs Class 18 7 10+ years Doors - Wood Doors inclu hw 138 Special Needs Class EΑ 7 10+ years 3 Floor - Tile 138 Special Needs Class 1.133 SF 7 10+ years SF Floor - Tile 138 Special Needs Class 5 0-1 year Broken and missing tile 12 138 Special Needs Class 19 EΑ 7 Lighting - Lay-in 10+ years 138 Special Needs Class 7 Power Distribution 10 EΑ 10+ years Storage/ Closet 138 Special Needs Class 56 SF 7 10+ years Walls - Plaster/Drywall SF 138 Special Needs Class 2.320 7 10+ years Work SInk 138 Special Needs Class EΑ 7 10+ years Ceiling - Lay-in SF 7 138/134 Teacher Mail Room 251 10+ years Doors - Wood Doors inclu hw 138/134 Teacher Mail Room EΑ 7 10+ years 1 Floor - Tile 7 138/134 Teacher Mail Room 231 SF 10+ years SF Floor - Tile 138/134 Teacher Mail Room 20 4 1-2 years Missing tiles Lighting - Lay-in 138/134 Teacher Mail Room 4 EΑ 7 10+ years Power Distribution 4 7 138/134 Teacher Mail Room EΑ 10+ years SF Walls - Plaster/Drywall 138/134 Teacher Mail Room 858 7 10+ years SF Ceiling - Lav-in 139 speech 265 7 6-10 years Doors - Wood Doors inclu hw 139 speech EΑ 7 10+ years 1 265 SF 7 Floor - Tile Ceramic/ Porcelain 139 speech 10+ years Lighting - Lay-in 139 speech 3 EΑ 7 10+ years Power Distribution 139 speech 6 EΑ 7 10+ years

Campus Name: Christopher Page : 10 of 39 Assessment Date: 10/12/2023



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	139 speech	904	SF	7	10+ years	
	Ceiling - Lay-in	140 Office	130	SF	7	10+ years	
	Doors - Transom Window	140 Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	140 Office	1	EA	7	10+ years	
	Floor - Tile	140 Office	130	SF	7	10+ years	
	Lighting - Lay-in	140 Office	2	EA	7	6-10 years	
	Power Distribution	140 Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	140 Office	440	SF	7	10+ years	
	Ceiling - Exposed	142 Office	130	SF	7	10+ years	
	Doors - Transom Window	142 Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	142 Office	1	EA	6	10+ years	
	Floor - Tile	142 Office	130	SF	7	10+ years	
	Lighting - Lay-in	142 Office	1	EA	7	10+ years	
	Power Distribution	142 Office	3	EA	7	10+ years	
	Walls - Plaster/Drywall	142 Office	450	SF	7	10+ years	
	Ceiling - Lay-in	Book Room next to 137	117	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Book Room next to 137	1	ĒΑ	7	6-10 years	
	Floor - Tile	Book Room next to 137	117	SF	7	6-10 years	
	Lighting - Lay-in	Book Room next to 137	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Book Room next to 137	430	SF	7	10+ years	
	Walls - Plaster/Drywall	Book Room next to 137	10	SF	4	0-1 year	Hole through plaster
	Ceiling - Plaster/Drywall	Engineer's Office	147	SF	7	10+ years	riole an eagir placter
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Engineer's Office	147	SF	7	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	6-10 years	
	Power Distribution	Engineer's Office	6	EA	7	10+ years	
	Storage/ Closet	Engineer's Office	16	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	548	SF	7	10+ years	
	Work Sink	Engineer's Office	1	EA	7	10+ years	
	Ceiling - Lay-in	Main Office	411	SF	7	10+ years	
	Doors - Transom Window	Main Office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	391	SF	6	6-10 years	
	Floor - Tile	Main Office	20	SF	4	1-2 years	Chipped and cracked, quantity
	1 loor - Tile	waiii Onice	20	Si	4	1-2 years	updated to match current observations
	Lighting - Lay-in	Main Office	6	EA	7	10+ years	
	Power Distribution	Main Office	6	EA	7	10+ years	
	Storage/ Closet	Main Office	155	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	973	SF	7	10+ years	
	AC Unit	Principal	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal	1	EA	7	10+ years	
	Floor - Tile	Principal	130	SF	4	1-2 years	Chipped, cracked, and worn
	1 1001 - 1 116	Πιτιοιραί	130	OI.	7	1-2 years	Ompped, Glacked, and World

Campus Name: Christopher Page: 11 of 39 Assessment Date: 10/12/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							throughout. Quantity changed to
					_		match current observations
	Lighting - Lay-in	Principal	3	EA	7	10+ years	
	Power Distribution	Principal	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal	560	SF	6	10+ years	
Auditoriu	m & Theater						
	Balcony Seating	Main Auditorium	60	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Auditorium	2,370	SF	7	10+ years	
	Doors - Store Front	Main Auditorium	2,570	EA	7	10+ years	
	Doors - Wood Doors inclu hw	Main Auditorium	20	EA	7	10+ years	
	Floor - Tile		2,370	SF	6	6-10 years	
		Main Auditorium	· ·	EA	7		
	Lighting - Chandelier, Incandescent	Main Auditorium	6			10+ years	
	Stage	Main Auditorium	34	SF	6	6-10 years	
	Stage Curtain	Main Auditorium	2	EA	7	6-10 years	
	Stage Lighting System	Main Auditorium	1	EA	7	6-10 years	
	Stairs - Wood	Main Auditorium	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	Main Auditorium	5,700	SF	7	10+ years	
itchen							
	Ceiling - Plaster/Drywall	1st Floor	835	SF	7	10+ years	
	Doors - Transom Window	1st Floor	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	835	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	292	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,525	SF	7	10+ years	
ibrarv							
ibiaiy	AC Unit	301 Library	1	EA	7	6-10 years	
	Casework	301 Library	33	LF	7	10+ years	
	Ceiling - Lay-in	301 Library	8	SF	7	10+ years	
	Ceiling - Lay-in	301 Library	775	SF	7	10+ years	
	Doors - Transom Window	301 Library	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	301 Library	2	EA	7	10+ years	
	Floor - Tile	301 Library	783	SF	7	6-10 years	
	Lighting - Lay-in	301 Library	18	EA	7	6-10 years	
				SF	7	•	
	Walls - Plaster/Drywall	301 Library	1,107	SF	/	10+ years	
unch &	Multipurpose Room						
	Ceiling - Lay-in	140 - Sensory Room	314	SF	7	10+ years	
	Doors - Transom Window	140 - Sensory Room	6	SF	7	10+ years	



atego	ry : Room		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	140 - Sensory Room	314	SF	7	10+ years	
	Lighting - Lay-in	140 - Sensory Room	4	EA	7	10+ years	
	Power Distribution	140 - Sensory Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	140 - Sensory Room	743	SF	6	10+ years	
	Ceiling - Lay-in	141	1,800	SF	7	10+ years	
	Doors - Transom Window	141	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	141	3	EA	7	10+ years	
	Floor - Tile	141	1,800	SF	7	10+ years	
	Lighting - Lay-in	141	42	EA	7	6-10 years	
	Serving Line	141	12	LF	7	10+ years	
	Walls - Plaster/Drywall	141	2,016	SF	7	10+ years	
	Ceiling - Lay-in	Teacher's Lounge/ lunchroom	318	SF	7	10+ years	
	Doors - Transom Window	Teacher's Lounge/ lunchroom	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge/ lunchroom	1	EA	7	10+ years	
	Floor - Tile	Teacher's Lounge/ lunchroom	318	SF	7	10+ years	
	Lighting - Lay-in	Teacher's Lounge/ lunchroom	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Teacher's Lounge/ lunchroom	844	SF	7	10+ years	
	Walls - Flastel/Drywall	reacher's Lourige/ function	044	OI.	,	10+ years	
F_ID							
	Doors - Wood Doors inclu hw	Inside classroom 135	1	EA	7	10+ years	
	Finishes	Inside classroom 135	95	SF	5	1-2 years	Missing floor tiles, ceiling tile displaced
	Other Cooling Unit	Inside classroom 135	2	EA	7	6-10 years	·
chani	ical/ Service Rooms						
CHAIN	Janitor's Closet	1st Floor	62	SF	7	10+ years	
		Basement	2,370	SF			
	Auditorium Plenums			SF SF	7	6-10 years	Motor conjugate mulliper on floor
	Boiler Room	Basement	1,215		5	10+ years	Water seeping in, pulling on floor
	Coal Room	Basement	1,196	SF	5	10+ years	Water seeping in, pooling on floo
	Crawl Space - Unfinished	Basement	17,342	SF	7	6-10 years	
	Mechanical/ Service Rooms	Basement	1,771	SF	7	6-10 years	
	Mechanical/ Service Rooms	Basement	771	SF	7	10+ years	
	Vaults	Basement	770	SF	7	6-10 years	
stroor	m						
	Accessories	139	34	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	139	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	139	1	EA	7	10+ years	
	Floor - Tile	139	34	SF	7	10+ years	
	Lavatory	139	1	EA	7	6-10 years	
	Lighting - Wall Mounted	139	2	EA	5	1-2 years	Missing covers
	Walls - Plaster/Drywall	139	259	SF	7	10+ years	Wildding GOVCIO
	Walls - Plaster/Drywall	139	259 5	SF	, 5	,	Damage around yest
	vvalis - Flastel/DLYWall	199	5	SF	Э	1-2 years	Damage around vent



Catego	ry : Room		В	uilding	: Main		· 5 ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	139	1	EA	7	10+ years	
	Accessories	155 Girl's (Next to 104)	322	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	155 Girl's (Next to 104)	322	SF	6	10+ years	
	Doors - Transom Window	155 Girl's (Next to 104)	12	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	155 Girl's (Next to 104)	2	EA	6	2-5 years	
	Floor - Tile/Sheet	155 Girl's (Next to 104)	322	SF	7	10+ years	
	Floor Drain	155 Girl's (Next to 104)	1	EA	7	10+ years	
	Lavatory	155 Girl's (Next to 104)	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	155 Girl's (Next to 104)	5	EA	7	6-10 years	
	Partitions	155 Girl's (Next to 104)	4	EΑ	5	2-5 years	
	Walls - Plaster/Drywall	155 Girl's (Next to 104)	620	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	155 Girl's (Next to 104)	590	SF	7	10+ years	
	Water Closet	155 Girl's (Next to 104)	3	ĒΑ	7	10+ years	
	Accessories	Across classroom 121	322	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Across classroom 121	322	SF	6	6-10 years	
	Doors - Transom Window	Across classroom 121	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Across classroom 121	2	EΑ	7	10+ years	
	Floor - Tile/Sheet	Across classroom 121	322	SF	7	10+ years	
	Floor Drain	Across classroom 121	1	EA	7	10+ years	
	Hand Dryer	Across classroom 121	1	EA	7	6-10 years	
	Lavatory	Across classroom 121	3	EA	7	6-10 years	Updated quantity
	Lighting - Pendent/Surface	Across classroom 121	5	EA	7	6-10 years	opadiod quartity
	Partitions	Across classroom 121	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Across classroom 121	620	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Across classroom 121	590	SF	7	10+ years	
	Water Closet	Across classroom 121	5	EA	7	10+ years	Updated quantity
	Accessories	Boy's Across from Main Office	322	SF	5	2-5 years	opulated qualitity
	Ceiling - Plaster/Drywall	Boy's Across from Main Office	322	SF	7	10+ years	
	Doors - Transom Window	Boy's Across from Main Office	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boy's Across from Main Office	2	EA	6	6-10 years	
	Floor - Tile/Sheet	Boy's Across from Main Office	322	SF	7	10+ years	
	Floor Drain	Boy's Across from Main Office	1	EA	7	10+ years	
	Hand Dryer	Boy's Across from Main Office	1	EA	7	6-10 years	
	Lavatory	Boy's Across from Main Office	2	EA	7	6-10 years	
	Lighting - Wall Mounted	Boy's Across from Main Office	4	EA	7	6-10 years	
	Partitions	Boy's Across from Main Office	3	EA	5	2-5 years	
	Urinals	Boy's Across from Main Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Boy's Across from Main Office	620	SF	6	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	Boy's Across from Main Office	590	SF	7	10+ years	
	Water Closet	Boy's Across from Main Office	2	EA	7	6-10 years	
	Accessories	Engineers toilet	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineers toilet Engineers toilet	27 27	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Engineers toilet Engineers toilet	1	EA	6	6-10 years	
	Floor - Tile	Engineers toilet Engineers toilet	27	SF	6	•	
	1 1001 - 1 11 0	Engineers wilet	21	J۲	O	6-10 years	

Campus Name: Christopher Page : 14 of 39 Assessment Date: 10/12/2023





Catego	Category : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Engineers toilet	1	EA	7	6-10 years	
	Walls - Concrete Block	Engineers toilet	77	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineers toilet	10	SF	5	1-2 years	Cracking
	Water Closet	Engineers toilet	1	EA	7	6-10 years	•
	Accessories	Near 129	294	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Near 129	294	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Near 129	294	SF	7	10+ years	
	Floor Drain	Near 129	1	ĒΑ	7	10+ years	
	Hand Dryer	Near 129	1	EA	7	6-10 years	
	Lavatory	Near 129	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Near 129	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Near 129	1	EA	7	6-10 years	
	Partitions	Near 129	3	EA	7	6-10 years	
	Urinals	Near 129	2	EA	7	10+ years	Updated quantity
	Walls - Structural Glazed Tile	Near 129	690	SF	7	10+ years	Opuated quantity
	Walls - Structural Glazed Tile Walls - Tile Ceramic/ Porcelain	Near 129	550	SF	7		
	Water Closet	Near 129		EA		10+ years	Undated quantity
			3		7	10+ years	Updated quantity
	Accessories	Near 137	182	SF	7	6-10 years	
	Ceiling - Lay-in	Near 137	142	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Near 137	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Near 137	2	EA	7	10+ years	
	Floor - Tile	Near 137	182	SF	7	10+ years	
	Floor Drain	Near 137	1	EA	7	10+ years	
	Lavatory	Near 137	1	EA	7	6-10 years	
	Lighting - Lay-in	Near 137	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	Near 137	1	EA	7	6-10 years	
	Partitions	Near 137	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Near 137	722	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Near 137	540	SF	7	10+ years	
	Water Closet	Near 137	2	EA	7	10+ years	
	Accessories	Near 405	238	SF	7	6-10 years	Updated to match current
						•	observations
	Ceiling - Lay-in	Near 405	238	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Near 405	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Near 405	238	SF	7	10+ years	
	Lavatory	Near 405	3	ĒΑ	7	10+ years	
	Lighting - Lay-in	Near 405	4	EA	6	6-10 years	
	Partitions	Near 405	3	EA	7	6-10 years	Updated to match current
			•			-	observations
	Walls - Plaster/Drywall	Near 405	712	SF	7	10+ years	
	Water Closet	Near 405	2	EA	7	6-10 years	Updated quantity
	Accessories	Principal's Office	34	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	6-10 years	
		·				•	

Campus Name: Christopher Page: 15 of 39 Assessment Date: 10/12/2023



A11	3010013					50	142 S Artesian AVENUE, Chicago, IL 60632
Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Principal's Office	34	SF	6	6-10 years	
	Lavatory	Principal's Office	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Principal's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	264	SF	7	10+ years	
	Water Closet	Principal's Office	1	EA	7	10+ years	
	Accessories	Staff RR Near 136 Office	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff RR Near 136 Office	245	SF	7	10+ years	
	Doors - Transom Window	Staff RR Near 136 Office	7	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff RR Near 136 Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	Staff RR Near 136 Office	245	SF	7	10+ years	
	Floor Drain	Staff RR Near 136 Office	1	EA	7	10+ years	
	Hand Dryer	Staff RR Near 136 Office	1	EA	7	6-10 years	
	Lavatory	Staff RR Near 136 Office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Staff RR Near 136 Office	4	EA	7	6-10 years	
	Walls - Masonry	Staff RR Near 136 Office	223	SF	7	10+ years	
	Walls - Plaster/Drywall	Staff RR Near 136 Office	445	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Staff RR Near 136 Office	223	SF	7	10+ years	
	Water Closet	Staff RR Near 136 Office	1	EA	7	10+ years	
	Accessories	Teacher's Toilet across main office	43	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Teacher's Toilet across main office	43	SF	7	10+ years	
	Doors - Steel Doors incl hw	Teacher's Toilet across main office	1	EA	6	6-10 years	
	Floor - Tile/Sheet	Teacher's Toilet across main office	43	SF	7	10+ years	
	Lavatory	Teacher's Toilet across main office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Teacher's Toilet across main office	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Teacher's Toilet across main office	1	EA	7	6-10 years	
				~-	_		

Category : Classroom Building : Main

Teacher's Toilet across main office

Teacher's Toilet across main office

Walls - Plaster/Drywall

Water Closet

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #101 (Regular Classroom)						
	Casework	1st Floor	7	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	25	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,107	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	2-5 years	

SF

EΑ

7

7

10+ years

6-10 years

309

1



Catego	ry : Classroom		В	uilding	: Main		3042 S AITESIAN AVENUE, CHICAGO, IL 60632		
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroc	om #103 (Regular Classroom)								
	Casework	1st Floor	7	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	783	SF	7	10+ years			
	Chalk Board	1st Floor	25	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years			
	Floor - Tile	1st Floor	783	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,107	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
Classroo	om #104 (Regular Classroom)								
	Casework	1st Floor	9	LF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	815	SF	7	10+ years			
	Chalk Board	1st Floor	29	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	815	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	18	EΑ	7	6-10 years			
	Marker Board	1st Floor	17	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,112	SF	7	10+ years			
	Work Sink	1st Floor	, 1	EA	7	10+ years			
Classroo	om #105 (Special Education)								
	Casework	1st Floor	6	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	820	SF	7	10+ years			
	Chalk Board	1st Floor	34	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	820	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,107	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classroo	om #106 (Regular Classroom)								
<u> </u>	Casework	1st Floor	6	LF	7	10+ years			
	Casework Ceiling - Lay-in	1st Floor	722	SF	7	6-10 years			
	Chalk Board	1st Floor	19	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	6	SF	7	2-5 years 10+ years			
	Doors - Transom Window Doors - Wood Doors inclu hw	1st Floor	1	SF EA	7 7	10+ years 10+ years			
			•	SF	7	•			
	Floor - Tile	1st Floor	710	3 F	′	6-10 years			



Category : Classroom			В	uilding	: Main		
						Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	12	SF	4	0-1 year	Holes in floor
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,032	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	m #107 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	820	SF	7	10+ years	
	Chalk Board	1st Floor	44	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	820	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
		1st Floor		SF		•	
	Walls - Plaster/Drywall		1,107		7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	60	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
lassroc	m #108/110 (Regular Classroom)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	791	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	791	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,007	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	5	6-10 years	
Classroc	m #111 (Regular Classroom)						
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	783	SF	7	10+ years	
	Chalk Board	1st Floor	25	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
				SF			
	Floor - Tile/Sheet	1st Floor	783		7	6-10 years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,107	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroc	m #113 (Regular Classroom)						
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	796	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		<u> </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	48	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	796	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,113	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classroo	om #115 (Regular Classroom)						
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	796	SF	6	10+ years	
	Chalk Board	1st Floor	48	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	796	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years	
			_	SF	-	•	
	Walls - Plaster/Drywall	1st Floor	1,118		6 7	10+ years	
	Work Sink	1st Floor	1	EA	/	6-10 years	
Classroo	om #117/119 (Regular Classroom)						
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	796	SF	7	10+ years	
	Chalk Board	1st Floor	48	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	796	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #121/123 (Regular Classroom)						
	Casework	1st Floor	3	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	28	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	780	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,100	SF	7	10+ years	
	Work Sink	1st Floor	1,100	EA	7	6-10 years	
Classro	om #125/127 (Regular Classroom)						
CIGSSIUL	Ceiling - Lay-in	1st Floor	764	SF	7	6-10 years	
	Ceiling - Lay-III	151 F1001	704	SF	,	0-10 years	



Catego	Category : Classroom		В	uilding				
2 9 0				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor	764	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	18	ĒΑ	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,107	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	om #128 (Regular Classroom)							
	Casework	1st Floor	8	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	791	SF	7	6-10 years		
	Chalk Board	1st Floor	31	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	791	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Walls - Metal Panel	1st Floor	1,107	SF	7	•		
	Work Sink	1st Floor	1,107	EA	7	10+ years 6-10 years		
Classroo	om #129/131 (Regular Classroom)							
	Casework	1st Floor	6	LF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	764	SF	7	10+ years		
	Chalk Board	1st Floor	45	LF	4	2-5 years		
	Doors - Transom Window	1st Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	764	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,203	SF	7	10+ years		
	Work Sink	1st Floor	1,203	EA	7	6-10 years		
Classroo	om #130 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	620	SF	7	6-10 years		
	Doors - Transom Window	1st Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor		SF	7 7	•		
		1st Floor 1st Floor	620	SF EA	<i>7</i> 6	10+ years		
	Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor	12	SF		6-10 years		
	Work Sink	1st Floor	1,417 1	EA	7 7	10+ years 6-10 years		
Classics	om #132 (Office)							
Ciassio		1st Floor	750	C.E.	7	6.10		
	Ceiling - Lay-in		750	SF	7	6-10 years		
	Doors - Transom Window	1st Floor	6	SF	7	10+ years		



	ry : Classroom		В	uilding	: Main		42 S Artesian Avenue, Chicago, il 60632
Guiogo	, , , , , , , , , , , , , , , , , , ,			anamg	· Maii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Missing
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	3
	Walls - Plaster/Drywall	1st Floor	1,250	SF	7	10+ years	
Classro	om #133 (Office)						
Classion	Casework	1st Floor	0	LF	7	10+ years	
		1st Floor	8	SF			
	Ceiling - Lay-in Doors - Transom Window	1st Floor	547	SF SF	6 7	6-10 years	
			10			10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	547	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	13	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #135 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	955	SF	7	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	955	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	ĒΑ	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,457	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #143 (Regular Classroom)						
Oldoorox	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	530	SF	7	6-10 years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	6-10 years	
	Floor - Tile	1st Floor	530	SF	7	6-10 years	
		1st Floor					
	Lighting - Lay-in		12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
Classroo	om #401/403 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	720	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,320	SF	7	10+ years	
	Work Sink	1st Floor	1	EΑ	7	10+ years	
						-	
Classroo	om #405/407 (Art Room)						
	Ceiling - Lay-in	1st Floor	638	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	638	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,320	SF	7	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
			•		•	,	
Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Exposed	1st Floor	678	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	8,760	SF	6	6-10 years	
	Doors - Side-lite	1st Floor	24	SF	7	10+ years	
	Doors - Transom Window	1st Floor	188	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	10	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EΑ	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years	
	Floor - Concrete	1st Floor	678	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	8,760	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	80	EA	7	6-10 years	
	Walls - Masonry	1st Floor	3,096	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,805	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	10,805	SF	7	10+ years	
	Ceiling - Exposed	Basement	8,760	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	0,700	EA	7	10+ years	
	Floor - Concrete	Basement	8,660	SF	7	10+ years	
	Floor - Concrete	Basement	100	SF	5	1-2 years	Standing water
	Lighting - Pendent/Surface	Basement	27	EA	7	10+ years	Standing water
	Stairs - Concrete Stairs	Basement	27 27	LF	7	10+ years	
	Walls - Concrete Block	Basement	21,610	SF	7	10+ years	
	Walls - Colloided Diock	Dascinciii	21,010	JI-	,	10+ years	
Safety							
<u> </u>	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	3	EΑ	7	6-10 years	
			· ·		•	5 .5 jours	



Catego	ry : Interior		Building : Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Stairs									
	Ceiling - Plaster/Drywall	Auditorium Balcony	120	SF	6	10+ years			
	Floor - Tile	Auditorium Balcony	72	SF	7	10+ years			
	Handrails	Auditorium Balcony	70	LF	7	10+ years			
	Lighting - Pendent/Surface	Auditorium Balcony	2	EA	7	10+ years			
	Stairs - Tile	Auditorium Balcony	48	LF	7	10+ years			
	Walls - Plaster/Drywall	Auditorium Balcony	470	SF	7	10+ years			
	Walls - Plaster/Drywall	Auditorium Balcony	30	SF	5	1-2 years	Crumbling plaster		

Campus Name: Christopher Page : 23 of 39 Assessment Date: 10/12/2023





Building: Addition Category: Exterior

Catego	ry : Exterior		В	unuing	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	5	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 2 - Northeast	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 2 - Northeast	12	ĒΑ	7	10+ years	
	Exterior Stairs - Concrete	Door 2 - Northeast	30	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 2 - Northeast	74	LF	5	10+ years	
	Ramps - Concrete	Door 2 - Northeast	36	LF	7	10+ years	
	Ramps - Concrete	Door 2 - Northeast	1	LF	5	1-2 years	Broken concrete
	Exterior Doors - Exterior FRP Door	Door 2A - Northeast	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 2A - Northeast	19	LF	6	10+ years	
	Exterior Stairs - Concrete	Door 2A - Northeast	1	LF	5	1-2 years	Broken chunk of concrete
	Stair Handrail - Steel_Stair Handrail	Door 2A - Northeast	30	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 3 - South center	2	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 3 - South center	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 3 - South center	80	LF	5	10+ years	
	Ramps - Concrete	Door 3 - South center	38	LF	6	10+ years	
	Ramps - Concrete	Door 3 - South center	2	LF	5	1-2 years	Broken off chunk of concrete
	Exterior Doors - Exterior FRP Door	Door 4 - Southwest	_ 1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 4 - Southwest	60	LF	6	10+ years	
	Ramps - Concrete	Door 4 - Southwest	15	LF	7	10+ years	
	Ramps - Concrete	Door 4 - Southwest	15	LF	5	1-2 years	Broken off chunks of concrete at post
	Trainpo Conoroto	Boot i Godainoot			Ü	. <i>-</i> youro	bases
Foundati	on						
_ r oundan	Foundation - Concrete	Entire Building	380	LF	7	10+ years	
	Foundation - Concrete	Entire Building	120	LF	5	1-2 years	Reports are that pool leakage over
	1 dandation Condicte	Littire Dallaring	120		0	1 Z yours	the years has undermined the
							foundation. There are cracks
							throughout the structure of the pool,
							as well as the exterior walls and
							foundation.
	Superstructure - Metal Deck/ Concrete	Entire Building	17,400	SF	7	10+ years	iodildation.
	Topping	Littile building	17,400	OI.	,	10+ years	
	Торріпід						
Lighting							
Lighting	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building Entire Building	15	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire building	15	LA	O	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 1	4	LF	6	10+ years	
	Coping - Metal	Roof 1	552	LF	6	10+ years	
			002		Ü	10. 300.0	

Campus Name: Christopher Page : 24 of 39 Assessment Date: 10/12/2023



Category : Exterior

Walter S Christopher Elementary School 5042 S Artesian AVENUE, Chicago, IL 60632

Building : Addition

	ry : Exterior				: Additio		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	Roof 1	130	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 1	11,888	SF	5	2-5 years	Ponding, blistering, soft spots
			,			,	throughout
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	ougout
	Roof Structure - Steel / Metal Deck/	Roof 1	11,888	SF	7	10+ years	
	Concrete Topping	11001 1	11,000	Oi.	,	101 years	
	Coping - Metal	Roof 2	42	LF	6	10 L Vooro	
						10+ years	
	Downspouts - Interior Downspouts	Roof 2	16	LF	6	10+ years	144 6 115 6 6
	Roof - Modified Bitumen	Roof 2	1,333	SF	4	1-2 years	Worn surface, blistering, soft spot
	Roof Structure - Steel / Metal Deck/	Roof 2	1,333	SF	7	10+ years	
	Concrete Topping						
	Chimney - Metal Flue	Roof 3	5	LF	6	10+ years	
	Coping - Metal	Roof 3	100	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3	32	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	1,355	SF	6	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 3	1,355	SF	7	10+ years	
	Concrete Topping	110010	1,000	O.	•	ioi youlo	
	Control Copping						
Valls							
	Exterior Walls - Brick	Entire Building	12,500	SF	7	10+ years	
	Exterior Trails Brief	Zimio Bananig	12,000	O.	•	ioi youlo	
Vindow	S						
	Guard - Guards perforated	Entire Building	120	SF	6	10+ years	
	Lintels - Steel	Entire Building	24	LF	7	10+ years	
	Windows - Sash Aluminum	Entire Building	240	SF	6	10+ years	
	Williaows - Sasii Aluminum	Little building	Z 1 0	31	U	TOT years	
Catego	ry : Electrical		В	uilding	: Additio	on	
Catego	ry : Electrical		В	uilding	: Additio	on Recommend	
		Location	B	uilding UOM	: Additio		Comments
Froup	Item - Type	Location		_		Recommend	Comments
roup	Item - Type ncy System		Quantity	UOM	Rank	Recommend Replacement	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and	Location Entire Building		_		Recommend	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs	Entire Building	Quantity	UOM	Rank 7	Recommend Replacement 6-10 years	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building Entire Building	Quantity 5	UOM EA EA	Rank 7 7	Recommend Replacement 6-10 years 6-10 years	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool	Entire Building Entire Building Entire Building	Quantity 5 3 3	EA EA EA	7 7 6	Recommend Replacement 6-10 years 6-10 years 6-10 years	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building Entire Building	Quantity 5 3 3 2	EA EA EA EA	7 7 6 7	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 5 3 3 2 5	EA EA EA EA EA	7 7 6 7 7 7	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Comments
roup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym	Entire Building	Quantity 5 3 3 2 5 3	EA EA EA EA EA EA	7 7 6 7 7 7 7	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
Froup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool	Entire Building	Quantity 5 3 3 2 5	EA EA EA EA EA EA	7 7 6 7 7 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6	6-10 years 2-5 years	Comments Needs new bulbs
Froup	Item - Type Incy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool Security System - CCTV	Entire Building	Quantity 5 3 3 2 5 3	EA EA EA EA EA EA	7 7 6 7 7 7 7	Recommend Replacement 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
Froup	Item - Type ncy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool	Entire Building	Quantity 5 3 3 2 5 3 3 3	EA EA EA EA EA EA	7 7 6 7 7 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6	6-10 years 2-5 years	
roup	Item - Type Incy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool Security System - CCTV	Entire Building	Quantity 5 3 3 2 5 3 17,400	EA EA EA EA EA EA EA EA SF	7 7 6 7 7 6 5 5	6-10 years 2-5 years 6-10 years	
Group Emerge	Item - Type Incy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool Security System - CCTV Security System - Intrusion Detection	Entire Building	Quantity 5 3 3 2 5 3 17,400	EA EA EA EA EA EA SF SF	7 7 6 7 7 6 5 6	6-10 years 2-5 years 6-10 years	
Group	Item - Type Incy System Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Pool Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Pool Security System - CCTV Security System - Intrusion Detection	Entire Building	Quantity 5 3 3 2 5 3 17,400	EA EA EA EA EA EA EA EA SF	7 7 6 7 7 6 5 5	6-10 years 2-5 years 6-10 years	

Campus Name: Christopher Page : 25 of 39 Assessment Date: 10/12/2023



	ry : Electrical		D	uildina	. A dditi		142 S Artesian AVENUE, Chicago, IL 60632
Calego	ry . Electrical		D	unung	: Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	120/208/3PH	Location	quantity	OOM	Italik	rtopiacomont	Commonto
	PA System	Entire Building	17,400	SF	5	2-5 years	
	,	3	,			,	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	2-5 years	Not labeled proper
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	2-5 years	Not labeled proper
Catego	ry : Fire Protection		В	uilding	: Additi		
_			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	17,400	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	17,400	SF	5	2-5 years	
Catego	ry : Mechanical		R	uildina	: Additi	on	
Calcgo	ry . Mcchanica			unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc			,				
7.11. 00110	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	5	2-5 years	Dated with fan cover rusting
	than 5 tons		·			,	g
Air Hand	lling Systems						
	Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	5	2-5 years	
	Indoor- Electric Coil - Less than 4000 cfm						
	Air Intake	Mechanical Room	1	EA	6	2-5 years	
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	
	Cage - Greater than 20000 CFM	Maskarias Dana	4	_^	0	0.5	
	Air Handling Unit- Package Single Zone- Indoor- Electric Coil - Less than 4000 cfm	Mechanical Room	1	EA	6	2-5 years	
	Air Intake	Mechanical Room	1	EA	6	2-5 years	Reseal air intake
	Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	2-5 years	Neseai ali lillake
	Indoor- Electric and DX Cooling Coil - Less	meenamear reem	·	_, \	Ü	2 o youro	
	than 4000 cfm						
	Air Intake	Mechanical Room	1	EA	6	2-5 years	
						•	
Heating	Devices						
	Wall Heater - Electric	Entire Building	16	EA	6	2-5 years	
	Duct Heater - Electric	Mechanical Room	3		6	2-5 years	
Tempera	ature Control						
	Electric Thermostat	1st Floor	3	EA	5	2-5 years	

Campus Name: Christopher Page : 26 of 39 Assessment Date: 10/12/2023



Walter S Christopher Elementary School

XIII.	Schools					50	042 S Artesian AVENUE, Chicago, IL 60632
Catego	ry : Mechanical		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
.,							
Ventilati							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	2	EA	5	2-5 years	
Dining							
Piping	D. C. D.: HAWA DA II	E C D TE	47.400	05		0.40	
	Domestic Piping-Hot Water Return Lines	Entire Building	17,400	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	17,400	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	17,400	SF	6	6-10 years	
	Demonstra Diminary Hat/Oald Water Organia	Factor Districtions	47 400	0.5	^	0.40	

, ,	Domestic Piping-Hot Water Return Lines	Entire Building	17,400	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	17,400	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	17,400	SF	6	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	17,400	SF	6	6-10 years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	17,400	SF	6	6-10 years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	17,400	SF	6	6-10 years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	17,400	SF	5	6-10 years	
	Storm Piping	Entire Building	17,400	SF	5	6-10 years	
	Vent Piping	Entire Building	17,400	SF	5	6-10 years	
Pool Syst	tems						
,	Pool Drain Piping	Pool	80	LF	3	0-1 year	Pool no longer in use, piping old and
					_		corroded
	Pool Filtration System including Pump	Pool	1	EA	3	0-1 year	Pool no longer in use, piping and pump old and corroded
	Pool Hot Water Heater - Gas Fired	Pool	1	EA	2	0-1 year	Pool no longer in use, heater dated and rusting



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	201 Case Manager	250	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	201 Case Manager	1	EA	7	10+ years	
	Floor - Tile	201 Case Manager	250	SF	7	6-10 years	
	Lighting - Lay-in	201 Case Manager	2	EA	7	6-10 years	
	Power Distribution	201 Case Manager	4	EA	7	10+ years	
	Storage/ Closet	201 Case Manager	31	SF	7	10+ years	
	Walls - Concrete Block	201 Case Manager	509	SF	7	10+ years	
	Ceiling - Lay-in	P.E. Office	250	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	P.E. Office	1	EΑ	6	6-10 years	
	Floor - Tile	P.E. Office	250	SF	7	6-10 years	
	Lighting - Lay-in	P.E. Office	2	EA	7	6-10 years	
	Power Distribution	P.E. Office	4	EΑ	7	10+ years	
	Storage/ Closet	P.E. Office	31	SF	7	6-10 years	
	Walls - Concrete Block	P.E. Office	509	SF	7	10+ years	
	Ceiling - Lay-in	Pool Office	250	SF	7	10+ years	
	Doors - Steel Doors incl hw	Pool Office	1	EA	7	10+ years	
	Floor - Tile	Pool Office	250	SF	6	6-10 years	
	Lighting - Lay-in	Pool Office	2	EA	7	6-10 years	
	Power Distribution	Pool Office	4	EA	7	10+ years	
	Storage/ Closet	Pool Office	10	SF	7	10+ years	
	Walls - Concrete Block	Pool Office	511	SF	7	10+ years	
Gymnas	ia						
	Ceiling - Lay-in	1st Floor	3,546	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Sport Flooring	1st Floor	3,546	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	56	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,745	SF	7	10+ years	
Locker/S	Shower Room						
	Accessories	Pool Boy's Locker	520	SF	7	6-10 years	
	Benches, ped mounted	Pool Boy's Locker	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Pool Boy's Locker	520	SF	6	10+ years	
	Doors - Steel Doors incl hw	Pool Boy's Locker	1	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	Pool Boy's Locker	1	EA	6	6-10 years	
	Floor - Concrete	Pool Boy's Locker	247	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Pool Boy's Locker	271	SF	6	6-10 years	
	Floor Drain	Pool Boy's Locker	3	EA	7	6-10 years	
	Hand Dryer	Pool Boy's Locker	2	EA	7	6-10 years	
	Lavatory	Pool Boy's Locker	1	EA	7	•	
		Pool Boy's Locker	8		, 6	6-10 years 6-10 years	
	Lighting - Pendent/Surface	POULDOY'S LOCKER	8	EA	О	o- io years	



Catego	ry : Room		В	uilding	: Additi	on	
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	Pool Boy's Locker	2	EA	7	6-10 years	
	Showers	Pool Boy's Locker	8	EA	7	6-10 years	
	Student Lockers - One Tier	Pool Boy's Locker	30	EA	6	6-10 years	
	Urinals	Pool Boy's Locker	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Pool Boy's Locker	1,457	SF	6	10+ years	
	Water Closet	Pool Boy's Locker	1	EA	6	6-10 years	
	Accessories	Pool Girl's Locker (Not in Use)	520	SF	7	6-10 years	
	Benches, ped mounted	Pool Girl's Locker (Not in Use)	1	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Pool Girl's Locker (Not in Use)	520	SF	6	10+ years	
	Doors - Steel Doors incl hw Doors - Wood Doors inclu hw	Pool Girl's Locker (Not in Use)	1	EΑ	6	6-10 years	
	Floor - Concrete	Pool Girl's Locker (Not in Use) Pool Girl's Locker (Not in Use)	1 247	EA SF	7 7	10+ years	
	Floor - Concrete Floor - Tile Ceramic/ Porcelain		247 271	SF SF	7	10+ years	
	Floor Drain	Pool Girl's Locker (Not in Use) Pool Girl's Locker (Not in Use)		SF EA	7	10+ years	
	Hand Dryer	Pool Girl's Locker (Not in Use)	3 4	EA EA	, 5	10+ years 2-5 years	
	Lavatory	Pool Girl's Locker (Not in Use)	2	EA	5 6	6-10 years	
	Lighting - Pendent/Surface	Pool Girl's Locker (Not in Use)	8	EA	6	6-10 years	
	Partitions	Pool Girl's Locker (Not in Use)	1	EA	7	10+ years	
	Showers	Pool Girl's Locker (Not in Use)	8	EA	7	6-10 years	
	Student Lockers - One Tier	Pool Girl's Locker (Not in Use)	30	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Pool Girl's Locker (Not in Use)	1,457	SF	6	10+ years	
	Water Closet	Pool Girl's Locker (Not in Use)	1,437	EA	6	6-10 years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	113	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	374	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	136	SF	7	10+ years	
Pool & N	latatorium						
	Accessories	1st Floor	4,928	SF	5	2-5 years	
	Ceiling - Exposed	1st Floor	4,928	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	3,025	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	16	EA	7	10+ years	
	Pool Basin	1st Floor	1,800	SF	6	6-10 years	
	Pool Deck	1st Floor	1,000	SF	6	6-10 years	
	Pool Deck	1st Floor	1,800	SF	6	6-10 years	
	Pool Deck Drains	1st Floor	6	EA	5	2-5 years	
	Walls - Masonry	1st Floor	86	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	6,415	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	50	SF	4	1-2 years	Large crack



Category : Room			Building : Addition				
_					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
estroor	n						
	Accessories	201 Case Manager	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	201 Case Manager	26	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	201 Case Manager	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	201 Case Manager	26	SF	7	6-10 years	
	Lavatory	201 Case Manager	1	EA	7	10+ years	
	Lighting - Pendent/Surface	201 Case Manager	1	EA	7	6-10 years	
	Walls - Concrete Block	201 Case Manager	213	SF	7	10+ years	
	Water Closet	201 Case Manager	1	EA	7	10+ years	
	Accessories	203	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	203	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	203	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	203	26	SF	7	6-10 years	
	Lavatory	203	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	203	1	EA	7	6-10 years	
	Walls - Concrete Block	203	123	SF	7	10+ years	
	Water Closet	203	1	ĒΑ	7	10+ years	
	Accessories	Gym Boy's	310	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Gym Boy's	310	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Boy's	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym Boy's	310	SF	7	6-10 years	
	Floor Drain	Gym Boy's	1	EΑ	7	10+ years	
	Lavatory	Gym Boy's	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Gym Boy's	4	EΑ	7	6-10 years	
	Partitions	Gym Boy's	2	EΑ	7	10+ years	
	Urinals	Gym Boy's	2	EΑ	7	10+ years	
	Walls - Concrete Block	Gym Boy's	630	SF	7	10+ years	
	Water Closet	Gym Boy's	1	EA	7	10+ years	
	Accessories	Gym Girl's	310	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Girl's	310	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Gym Girl's	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Gym Girl's	310	SF	7	6-10 years	
	Floor Drain	Gym Girl's	1	EA	7	10+ years	
	Lavatory	Gym Girl's	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Gym Girl's	4	EΑ	7	6-10 years	
	Partitions	Gym Girl's	3	EA	7	10+ years	
	Walls - Concrete Block	Gym Girl's	630	SF	7	10+ years	
	Water Closet	Gym Girl's	3	EA	7	10+ years	
	Accessories	P.E. Office	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	P.E. Office	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	P.E. Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	P.E. Office	70	SF	7	10+ years	
	Lavatory	P.E. Office	1	EA	6	6-10 years	
	Lavatory	P.E. Office	1	EA	6	6-10 years	



AUD .							42 S Artesian AVENUE, Chicago, IL 60632
Catego	ry : Room		В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Showers	P.E. Office	1	EA	7	6-10 years	
	Walls - Concrete Block	P.E. Office	306	SF	6	10+ years	
	Water Closet	P.E. Office	1	EA	7	6-10 years	
	Accessories	Pool Office	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Pool Office	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Pool Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Pool Office	26	SF	7	10+ years	
	Lavatory	Pool Office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Pool Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Pool Office	123	SF	7	10+ years	
	Water Closet	Pool Office	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #203 (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	300	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	8	ĒΑ	7	10+ years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	576	SF	7	10+ years	
Catego	ry : Interior		В	uildina	: Additio	on	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,332	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	25	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	106	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,462	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	46	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	2,680	SF	7	10+ years	
	Walls - Masonry	1st Floor	255	SF	7	10+ years	





Category: Exterior Building: Modular 1 (4-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Group Rank Entrance Entrance Control - Audio and Video FΑ 7 Door 5 - South 1 10+ years 2 FΑ Exterior Doors - Exterior Steel Door Door 5 - South 6 10+ years 7 Power Door Operator and Controls Door 5 - South 1 EΑ 10+ years Ramp Handrail - Steel_Ramp Handrail Door 5 - South 100 LF 5 10+ years ΙF 7 Ramps - Concrete Door 5 - South 47 10+ years Ramps - Concrete Door 5 - South LF 3 5 1-2 years Broken ramp wall at rail posts Exterior Doors - Exterior FRP Door Door 5A - West 1 FΑ 7 10+ years Exterior Stairs - Concrete Door 5A - West 16 LF 7 10+ years LF Stair Handrail - Steel Stair Handrail Door 5A - West 24 7 10+ years Not yet installed Foundation Foundation - Concrete 290 LF 7 **Entire Building** 10+ years SF Superstructure - Concrete **Entire Building** 4.475 7 10+ years Lighting 8 EΑ 7 Exterior Lighting - Wall Mounted **Entire Building** 10+ years Roof System LF Downspouts - Exterior Downspouts Roof 1 190 7 10+ years Not yet installed Roof - Modified Bitumen 4.230 SF 2-5 years Roof 1 6 Roof Structure - Steel / Metal Deck/ Roof 1 4,230 SF 7 10+ years **Concrete Topping** Coping - Metal LF 7 Roof 2 20 10+ years Downspouts - Exterior Downspouts LF Roof 2 12 7 10+ years Roof - Modified Bitumen Roof 2 245 SF 6 2-5 years SF Roof Structure - Steel / Metal Deck/ Roof 2 245 10+ years Concrete Topping Walls Exterior Walls - Hardie Board **Entire Building** 420 SF 7 10+ years No more brick walls, numbers given to hardie board Exterior Walls - Prefabricated Metal Panel **Entire Building** 2.590 SF 7 New 10+ years Wall Windows SF 7 Guard - Guards perforated **Entire Building** 255 10+ years SF 7 Windows - Sash Aluminum Double-pane **Entire Building** 240 10+ years Category: Electrical Building: Modular 1 (4-Classroom) Group Item - Type Location Quantity **UOM** Rank Recommend Comments

Campus Name: Christopher Page : 32 of 39 Assessment Date: 10/12/2023



, ,	3CI 100IS						142 S Artesian AVENUE, Chicago, IL 6
						Replacement	
Emerge	ncy System						
	Emergency A/C Power - Corridors and Stairs	1st Floor	1,050	SF	7	10+ years	
	Security System - CCTV	Entire Building	4,900	SF	7	6-10 years	
	Security System - Intrusion Detection	Entire Building	4,900	SF	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	7	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	7	10+ years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	
Main Se	ervice						
	PA System	1st Floor	4,900	SF	5	10+ years	Not connected to main building
	Main Electrical Service - 800 A and Less than 120/208/3PH	East Facade	1	EA	6	6-10 years	Meter only
Power [Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	7	10+ years	
Catego	ory : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Ala							
	Fire Alarm Strobe Lights	Entire Building	4,900	SF	7	10+ years	
	Fire Alarm_System	Entire Building	4,900	SF	7	10+ years	
Sprinkle	er System						
•	Sprinkler Heads	Entire Building	4,900	SF	7	10+ years	
	Sprinkler Piping	Entire Building	4,900	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	4,900	SF	7	10+ years	
Catego	ory : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	oom)
J	•			J		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Temper	ature Control						
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	
11:41/-	ntilation						
<u>Unit ver</u>		Exterior Walls	4	EA	7	10+ years	
Unit ver	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling						
Ventilati	Heat & Self Contained Cooling						

Campus Name: Christopher Page : 33 of 39 Assessment Date: 10/12/2023



Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	7	10+ years	
Piping							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	4,900	SF	7	10+ years	
	(Horizontal Lines)	•				•	
	Sanitary Piping	Entire Building	4,900	SF	7	10+ years	
	Storm Piping	Entire Building	4,900	SF	7	10+ years	
	Vent Piping	Entire Building	4,900	SF	7	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	304A Breakout Room	90	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	304A Breakout Room	1	EA	7	10+ years	
	Floor - Tile	304A Breakout Room	90	SF	7	6-10 years	
	Lighting - Lay-in	304A Breakout Room	2	ĒΑ	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	304A Breakout Room	293	SF	7	10+ years	
	Work SInk	304A Breakout Room	1	EA	7	10+ years	
						•	
Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	83	SF	7	10+ years	
						,	
Restroor	n						
	Accessories	304A	75	SF	7	6-10 years	
	Ceiling - Lay-in	304A	75	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	304A	1	ĒΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	304A	75	SF	7	6-10 years	
	Floor Drain	304A	1	ĒΑ	7	6-10 years	
	Hand Dryer	304A	1	EA	7	6-10 years	
	Lavatory	304A	1	EA	7	6-10 years	
	Lighting - Lay-in	304A	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	304A	160	SF	7	6-10 years	
	Water Closet	304A	100	EA	7	6-10 years	
	Accessories	306A	72	SF	7	6-10 years	
	Ceiling - Lay-in	306A	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	306A 306A	1	EA	7	•	
	Floor - Tile Ceramic/ Porcelain	306A 306A	72	SF	7	6-10 years 10+ years	
			1		7	-	
	Floor Drain	306A	-	EΑ		10+ years	
	Lavatory	306A	1	EΑ	7	6-10 years	
	Lighting - Lay-in Walls - Tile Ceramic/ Porcelain	306A	1	EA SF	7 7	6-10 years	
	vvalis - Tile Geraffiic/ Porcelain	306A	145	3 F	1	10+ years	

Campus Name: Christopher Page : 34 of 39 Assessment Date: 10/12/2023



Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	om)
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	306A	1	EA	7	10+ years	
	Accessories	By 306	63	SF	7	6-10 years	
	Ceiling - Lay-in	By 306	63	SF	7	10+ years	
	Doors - Wood Doors inclu hw	By 306	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	By 306	63	SF	7	10+ years	
	Hand Dryer	By 306	1	EA	7	6-10 years	
	Lavatory	By 306	1	EA	7	10+ years	
	Lighting - Lay-in	By 306	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	By 306	146	SF	7	10+ years	
	Water Closet	By 306	1	EA	7	6-10 years	
	Accessories	Next to 304	37	SF	7	6-10 years	
	Ceiling - Lay-in	Next to 304	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next to 304	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to 304	37	SF	7	10+ years	
	Floor Drain	Next to 304	1	EA	7	10+ years	
	Hand Dryer	Next to 304	1	EA	7	10+ years	
	•		1	EA	7	-	
	Lavatory	Next to 304	1			10+ years	
	Lighting - Lay-in	Next to 304	2	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Next to 304	197	SF	7	10+ years	
	Water Closet	Next to 304	1	EA	7	10+ years	
	Accessories	Next to 305	37	SF	7	10+ years	
	Ceiling - Lay-in	Next to 305	37	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next to 305	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to 305	37	SF	7	10+ years	
	Floor Drain	Next to 305	1	EA	7	10+ years	
	Hand Dryer	Next to 305	1	EA	7	6-10 years	
	Lavatory	Next to 305	1	EA	7	6-10 years	
	Lighting - Lay-in	Next to 305	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Next to 305	197	SF	7	10+ years	
	Water Closet	Next to 305	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #Modular 304 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	697	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	697	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	85	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	720	SF	7	10+ years	
				J.			



Category : Classroom			В	Building : Modular 1 (4-Classroom)					
		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Ceiling - Lay-in	1st Floor	697	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	697	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	85	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	720	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	6-10 years			
lassroo	m #Modular 306 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	697	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	697	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Storage/ Closet	1st Floor	85	SF	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	720	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
lassroo	m #Modular 307 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	697	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	697	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years			
	Storage/ Closet	1st Floor	85	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	720	SF	7	10+ years			
	Work Sink	1st Floor	1	ĒΑ	7	10+ years			
atego	ry : Interior		Building : Modular 1 (4-Classroom)						
				Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor									
	Ceiling - Lay-in	1st Floor	1,121	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years			
	Floor - Tile/Sheet	1st Floor	1,121	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	13	EΑ	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,502	SF	7	10+ years			



Category: Site **Building: Site**

	ry : Site			ullaing	. 0		
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	7	10+ years	
						, , , , ,	
encina							
	Fencing - Chain Link	Entire Site	120	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	429	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	195	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	195	LF	6	10+ years	
	Tonoming Trood Forming the Crook Frame				ŭ	.o. you.o	
andsca	oe .						
	Benches	Entire Site	8	EA	6	10+ years	
	Landscape - Grass	Entire Site	8,000	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	3,091	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,755	SF	6	10+ years	
	Parkway trees	Entire Site	29	EA	7	10+ years	
	Parkway trees	Entire Site	4	EA	7	10+ years	
	Retaining Wall - Concrete	Entire Site	600	SF	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I							
	Concrete Curbs	Entire Site	350	LF	7	10+ years	
	Interior Plantings	Entire Site	35	LF	7	10+ years	
	Lighting - Pole Mounted	Entire Site	2	EA	7	10+ years	
	Surface - Asphalt	Entire Site	3,400	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	8,700	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	100	SF	5	1-2 years	Potholes
	Surface - Concrete	Entire Site	1,100	SF	6	6-10 years	
	Surface - Concrete	Entire Site	100	SF	5	1-2 years	Spalled, potholes, cracks
	Trash Enclosure - Chain Links	Entire Site	810	SF	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	150	SF	4	1-2 years	bent, distorted area of fencing
	Vehicular Screening	Entire Site	160	LF	7	10+ years	
21	I						
Playgrou	nd Equipment - School Age 5-12	Central Courtyard	1	EA	7	10 L VOORS	
	Surface - Poured Surface	Central Courtyard Central Courtyard	2,008	SF	7 7	10+ years	
	Surface - Poured Surface	Central Courtyard	∠,008	31	1	10+ years	
Sidewalk	s						
	Sidewalks - Internal Walks	Entire Site	210	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,660	SF	6	10+ years	
	Sidewaiks - i ellilletei Sidewaiks						



Category : Site			В						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
_Signage									
- 0 0	Flag Pole - Flag Pole Monument - Sign	Entire Site Entire Site	1 2	EA EA	6 6	10+ years 10+ years			

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Christopher Page: 38 of 39 Assessment Date: 10/12/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main		·							
Art Room	Computer Lab	1st Floor	405/407	129/131	638	64	32	N	Υ
Office	Play Room	1st Floor	133	Playroom	547	0	0		
Office	Regular Classroom	1st Floor	132	132	750	18	0		
Regular Classroom	Art Room	1st Floor	104	104	815	95	41		Υ
Regular Classroom	Kindergarten	1st Floor	125/127	121	764	42	40		Υ
Regular Classroom	Laboratory/Shop	1st Floor	108/110	108	791	109	82	N	N
Regular Classroom	Play Room	1st Floor	135	Playroom	955	0	0		Υ
Regular Classroom	Play Room	1st Floor	401/403	129/131	720	64	32		Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	783	89	82		Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	783	89	82		Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	722	95	41		Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	820	113	69	N	Υ
Regular Classroom	Regular Classroom	1st Floor	111	109	783	89	82		Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	796	109	82		Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	796	109	82		Υ
Regular Classroom	Regular Classroom	1st Floor	117/119	117	796	109	82		Υ
Regular Classroom	Regular Classroom	1st Floor	121/123	119	780	94	61		Υ
Regular Classroom	Regular Classroom	1st Floor	128	124	791	109	82		Υ
Regular Classroom	Regular Classroom	1st Floor	129/131	Nursery / P. T.	764	42	41		Y
Regular Classroom	Regular Classroom	1st Floor	130	126	620	180	60		Υ
Regular Classroom	Regular Classroom	1st Floor	143	143	530	30	10		
Special Education	Regular Classroom	1st Floor	105	105	820	113	69	N	Υ
Building : Addition									
Other Instructional Use	Office	1st Floor	203	Exam Room	300	72	36	Υ	N
Building : Modular 1 (4-Cla	ssroom)								
Regular Classroom	Regular Classroom	1st Floor	Modular 304	Modular 304	697	48	46	N	Y
Regular Classroom	Regular Classroom	1st Floor	Modular 305	Modular 305	697	48	46	N	Y
Regular Classroom	Regular Classroom	1st Floor	Modular 306	Modular 306	697	48	46	N	Y
Regular Classroom	Regular Classroom	1st Floor	Modular 307	Modular 307	697	48	46	N	Y