

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1972	2	150,700
Campus Total			150,700

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - Main N	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	1 - Main N	4	EA	6	10+ years	
	Exterior Doors - Side lite	1 - Main N	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main N	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	10 - W	1	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Side lite	10 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	11- W	1	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Side lite	11- W	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	12 - NE	4	EA	6	10+ years	
	Exterior Doors - Side lite	12 - NE	4	EA	6	10+ years	
	Exterior Doors - Side lite	12 - NE	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	12 - NE	4	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	13 - N	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	14 - N	1	EA	6	6-10 years	Changed to match current observations
	Exterior Doors - Exterior Steel Door	15 - E Court NE	1	EA	6	10+ years	
	Exterior Doors - Side lite	15 - E Court NE	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	16 - E Court SE	1	EA	6	10+ years	
	Exterior Doors - Side lite	16 - E Court SE	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	17 - E Court N	1	EA	6	10+ years	
	Exterior Doors - Side lite	17 - E Court N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	18 - E Court S	2	EA	6	6-10 years	Peeling paint, rust spots



						51	U1 W Harrison STREET, Chicago, IL 60644
Catego	ry : Exterior		В	uilding	: Main	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	18 - E Court S	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	19 - W Court SW	1	EA	6	2-5 years	
	Exterior Doors - Side lite	19 - W Court SW	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	2 - E	1	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Side lite	2 - E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	20 - W Court NW	1	EA	6	10+ years	
	Exterior Doors - Side lite	20 - W Court NW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	21 - W Court N	1	EA	6	2-5 years	
	Exterior Doors - Side lite	21 - W Court N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	22 - W Court E	2	EA	6	2-5 years	
	Exterior Doors - Side lite	22 - W Court E	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	23 - Penthouse N	1	EA	5	2-5 years	Rusting frame and door
	Exterior Doors - Exterior Steel Door	24 - Penthouse E	2	EA	5	6-10 years	
	Exterior Doors - Exterior Steel Door	25 - Penthouse-South	- 1	EA	5	6-10 years	
	Entrance Control - Audio and Video	2A - East	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	2A - East	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	3 - E	1	EA	6	10+ years	Changed to match current
	Exterior Doors - Side lite	3 - E	1	EA	6	10+ years	observations
	Exterior Doors - Exterior FRP Door	4 - South	2	EA	6	10+ years	Changed to match current
		4 - South			0	-	observations
	Exterior Doors - Side lite	4 - South	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 - E Loading	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	5 - E Loading	1	EA	5	2-5 years	Peeling paint, rotting panel and frame
	Exterior Doors - Overhead Rolling/ Garage Door	6 - Loading OVH	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	6A - Loading	2	EA	7	10+ years	Changed to match current observations
	Exterior Doors - Overhead Rolling/ Garage Door	6B - Loading OVH	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	7 - S	1	EA	6	10+ years	
	Exterior Doors - Side lite	7 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	7 - S	6	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	7A - S	2	EA	6	10+ years	Changed to match current
						-	observations
	Exterior Doors - Exterior FRP Door	8 - S	1	EA	6	10+ years	
	Exterior Doors - Side lite	8 - S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	8 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	8 - S	5	LF	6	6-10 years	
	Exterior Doors - Exterior FRP Door	9 - S	2	EA	6	6-10 years	
	Exterior Doors - Side lite	9 - S	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	9A - SE	2	EA	6	10+ years	



	ry : Exterior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Foundatio							
	Foundation - Concrete	Entire Building	1,330	LF	7	10+ years	
	Foundation - Concrete	Entire Building	70	LF	5	1-2 years	Cracking/seeping water
	Superstructure - Metal Deck/ Concrete	Entire Building	150,700	SF	7	10+ years	
	Topping						
lighting							
Lighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	34	EA	7	6-10 years	
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	11	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	7	6-10 years	
	Extendi Lighting - Wair Mounted	Entire Building	I	EA	1	0-10 years	
Roof Sys	tem						
	Coping - Metal	Roof F - Lower South	80	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof F - Lower South	14	LF	7	10+ years	
	Roof - Modified Bitumen	Roof F - Lower South	474	SF	7	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof F - Lower South	474	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof A - Main	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof A - Main	12	LF	6	6-10 years	Not previously assessed
	Coping - Metal	Roof A - Main	806	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof A - Main	576	LF	6	10+ years	
	Roof - Modified Bitumen	Roof A - Main	80	SF	6	1-2 years	Ponding south of penthouse
	Roof - Modified Bitumen	Roof A - Main	43,268	SF	6	6-10 years	
	Roof Hatch - Metal	Roof A - Main	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof A - Main	43,348	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof B - West	613	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof B - West	120	LF	6	10+ years	
	Roof - Modified Bitumen	Roof B - West	16,200	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof B - West	16,200	SF	7	10+ years	
	Concrete Topping					-	
	Coping - Metal	Roof C - East	613	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof C - East	120	LF	7	10+ years	
	Roof - Modified Bitumen	Roof C - East	16,200	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof C - East	16,200	SF	7	10+ years	
	Concrete Topping					-	
	Access Ladder - Metal	Roof D - High South	1	EA	7	10+ years	
	Coping - Metal	Roof D - High South	360	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof D - High South	72	LF	6	10+ years	
	Roof - Modified Bitumen	Roof D - High South	7,492	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof D - High South	7,492	SF	7	10+ years	
	Coping - Metal	Roof E - Penthouse	141	LF	5	2-5 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Metal	Roof E - Penthouse	1,100	SF	5	2-5 years	Rusted throughout
	Roof Structure - Steel / Metal Deck/	Roof E - Penthouse	1,100	SF	7	10+ years	
	Concrete Topping						
Walls							
	Canopy - Metal	Entire Building	600	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,675	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	19,300	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	745	SF	7	10+ years	
	Wall						
	Exterior Walls - Prefabricated Metal Panel	Entire Building	2,565	SF	6	10+ years	
	Wall						
	Exterior Walls - Prefabricated Metal Panel	Entire Building	840	SF	6	6-10 years	
	Wall						
Windows	5						
	Curtain wall - Glazed Double Pane	Entire Building	21,300	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	18,420	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	150	SF	6	10+ years	
	Curtain wall - Windows	Entire Building	1,080	SF	6	10+ years	
	Lintels - Steel	Entire Building	45	LF	7	10+ years	
	Skylite - Lexan	Entire Building	1,400	SF	6	10+ years	
0							
Catego	ry : Electrical		В	uilding	: Main	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	<u>, , , , , , , , , , , , , , , , , , , </u>	Location	Quantity		INAIIK	Replacement	Comments
Emerger	ncy System Automatic Transfer Switch	Basement	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	150,700	SF	6	6-10 years	
				SF	6		
	Security System - Intrusion Detection Exit Signs - Auditoium	Entire Building Entire Building	150,700 4	EA	6 7	6-10 years 6-10 years	
	Exit Signs - Corridors and Stairs		36	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building Entire Building	30 4	EA	7	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	7	6-10 years	
	Exit Signs - Pool	Entire Building	4	EA	7	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	5,751	SF	6	6-10 years	
	Aisle Lighting		5,751	эг	U	0-10 years	
	Emergency A/C Power - Corridors and	Entire Building	27,155	SF	6	6-10 years	
	Stairs		21,100	ЗГ	U	0-10 years	
	Emergency A/C Power - Gym	Entire Building	5,504	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,160	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms Emergency A/C Power - Pool	Entire Building	4,160	SF	6	6-10 years	
	Emergency A/C Power - Pool Emergency A/C Power - Students Toilets	Entire Building	4,220 2,151	SF	6	6-10 years	
	Emergency A/C Fower - Students Tollets	Entire Building	∠,151	эг	U	0-10 years	



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	Site South	1	EA	5	1-2 years	Rust and deterioration on outside shell period. Per engineer operationa
Main Se	rvice						
	Main Electrical Service - 1000 A 277/480/3PH	Entire Building	1	EA	6	2-5 years	
	Main Electrical Service - 2000 A 277/480/3PH	Entire Building	2	EA	6	2-5 years	
	PA System	Entire Building	150,700	SF	6	6-10 years	
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	23	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	12	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
•		1 d				Recommend	2
Group Fire Alaı	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
FILE AIAI	Fire ALarm Anunciator	Basement	1	EA	7	6-10 years	
	Fire Alarm Panel	Basement	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Basement	150,700	SF	7	6-10 years	
	Fire Alarm_System	Basement	150,700	SF	6	6-10 years	
	Fire Pump Controller	Basement	1	EA	7	6-10 years	
Pump R	oom Assembly						
	Fire Pump - 25-50 hp	Basement	1	EA	6	6-10 years	
	Jockey Pump	Basement	1	EA	6	6-10 years	
Sprinkle	r System						
- F	Sprinkler Heads	Entire Building	150,700	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	150,700	SF	6	6-10 years	
	Wet Sprinkler System	Entire Building	150,700	SF	6	6-10 years	



Category : Mechanical

Group Item - Type

Michele Clark Academic Prep Magnet High School 5101 W Harrison STREET, Chicago, IL 60644

Building : Main Recommend Quantity UOM Rank **Replacement** Comments

sloup item - Type	Location	Quantity		Nalik	Replacement	Comments
Air Conditioning						
Condensing Unit- Roof Mounted - 11-20	Roof	1	EA	6	6-10 years	
tons			_/ `	Ū.	0.0900.0	
Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
than 5 tons			_/ `	Ū.	0.0900.0	
Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
than 5 tons				-	· · , · · · ·	
Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
than 5 tons					,	
Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
than 5 tons					,	
Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	
than 5 tons					,	
Air Handling Systems						
Fan Coil Unit- Celing Mounted - Electric	Offices	1	EA	6	6-10 years	230
Fan Coil Unit- Celing Mounted - Electric	Offices	1	EA	6	6-10 years	227
Fan Coil Unit- Celing Mounted - Electric	Offices	1	EA	6	6-10 years	252
Fan Coil Unit- Celing Mounted - Electric	Offices	1	EA	6	6-10 years	205
Fan Coil Unit- Celing Mounted - Electric	Offices	1	EA	2	0-1 year	109. Per engineer unit is an operat
5					,	In need of repair.
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	AHU-1
Electric and DX Cooling w/ Self Contained					-	
Compressor - 21 - 30 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	10+ years	AHU-5
Electric and DX Cooling w/ Self Contained						
Compressor - 21 - 30 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	10+ years	AHU-15
Electric and DX Cooling w/ Self Contained						
Compressor - 21 - 30 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	10+ years	AHU-16
Electric and DX Cooling w/ Self Contained						
Compressor - 21 - 30 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	AHU-6
Electric and DX Cooling w/ Self Contained						
Compressor - 21 - 30 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	AHU-8
Electric and DX Cooling w/ Self Contained						
Compressor - 31 - 45 tons						
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	6-10 years	AHU-13
Electric and DX Cooling w/ Self Contained						
Compressor - 31 - 45 tons	- /			-		
Roof Top Unit-Multi Zone-Roof Mounted-	Roof	1	EA	6	10+ years	AHU-11
Electric and DX Cooling w/ Self Contained						

Location



Catego	ry : Mechanical		В	uilding	: Main	01	51 W Hamson STREET, Chicago, ie 00044
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	10+ years	AHU-12
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	10+ years	AHU-20
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	6-10 years	AHU-14
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	10+ years	AHU-18
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	6-10 years	AHU-10
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	10+ years	AHU-17
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained	Roof	1	EA	6	6-10 years	AHU-4
	Compressor - 31 - 45 tons Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained Compressor - 31 - 45 tons	Roof	1	EA	6	6-10 years	AHU-9
	Roof Top Unit-Multi Zone-Roof Mounted- Electric and DX Cooling w/ Self Contained Compressor - 31 - 45 tons	Roof	1	EA	6	10+ years	AHU-19
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 21 - 30 tons	Roof	1	EA	6	6-10 years	AHU-2
	Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 21 - 30 tons	Roof	1	EA	6	6-10 years	AHU-3
	Zone Dampers	Roof	116	EA	6	6-10 years	On RTU's
	Dehumidification Unit-Outdoor- Gas Heating- DX Cooling with Self Contained Compressor - 4001 - 8000 cfm	Roof	1	EA	2	0-1 year	Drain line cracked off. Is operable, we cannot be ran without drain line repair. Work order is in place for repair, per engineer.
Heating I	Devices						
	Cabinet Heaters - With Electric Coil	1st Floor	7	EA	6	6-10 years	
	Fin Tube - Electric	Entire Building	2,296	LF	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main	_	
C	Here True	Lesstian	Overstitue	UOM	Denk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Tempera	ture Control						
	DDC System	Entire Building	150,700	SF	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	MDF Room
	Electric Thermostat	Entire Building	5	EA	7	6-10 years	For ceiling mounted fan coil units
	Electric Thermostat	Entire Building	10	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	119	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Per observation and engineer, only one
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	4	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
				-		Recommend	
							•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group Hot Wate	<u>, , , , , , , , , , , , , , , , , , , </u>	Location	Quantity	UOM	Rank	Replacement	Comments
	er					•	Comments
-	<u>, , , , , , , , , , , , , , , , , , , </u>	Location Basement Basement	Quantity 1 1	EA EA	Rank 6 4	6-10 years 2-5 years	Unit is functional show signs of deterioration on shell
	er Gas Heater - 150000 - 300000 BTU/HR	Basement		EA	6	6-10 years	Unit is functional show signs of
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than	Basement Basement		EA EA	6 4	6-10 years 2-5 years	Unit is functional show signs of
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than	Basement Basement		EA EA	6 4	6-10 years 2-5 years	Unit is functional show signs of
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons	Basement Basement Basement Entire Building	1 1 1	EA EA EA	6 4 6	6-10 years 2-5 years 6-10 years	Unit is functional show signs of
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines	Basement Basement Basement	1 1 1 150,700	EA EA EA SF	6 4 6	6-10 years 2-5 years 6-10 years 6-10 years	Unit is functional show signs of
lot Wat	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to	Basement Basement Basement Entire Building Entire Building	1 1 1 150,700 150,700	EA EA EA SF SF	6 4 6 6 6	6-10 years 2-5 years 6-10 years 6-10 years 6-10 years	Unit is functional show signs of
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply	Basement Basement Basement Entire Building Entire Building Entire Building	1 1 1 150,700 150,700 150,700	EA EA EA SF SF SF	6 4 6 6 6 6	6-10 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years	Unit is functional show signs of
lot Wat	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Basement Basement Basement Entire Building Entire Building Entire Building Entire Building	1 1 1 150,700 150,700 150,700 150,700	EA EA SF SF SF SF SF SF SF	6 4 6 6 6 6	6-10 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Unit is functional show signs of deterioration on shell
lot Wat	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Basement Basement Basement Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 1 1 150,700 150,700 150,700 150,700 150,700	EA EA SF SF SF SF SF	6 4 6 6 6 6 6	6-10 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years	Unit is functional show signs of deterioration on shell
-	Gas Heater - 150000 - 300000 BTU/HR Gas Heater - Greater than 600000 BTU/HR Hot Water Storage Tank_Gas - Greater than 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Basement Basement Basement Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 1 1 150,700 150,700 150,700 150,700 150,700 150,700	EA EA SF SF SF SF SF SF SF	6 4 6 6 6 6 6 6	6-10 years 2-5 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 6-10 years	Unit is functional show signs of deterioration on shell



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pool Drain Piping	Basement	300	LF	6	6-10 years	
	Pool Filtration System including Pump	Basement	1	EA	5	2-5 years	
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	5	2-5 years	Very old.
	Pool Supply and Return Piping	Basement	100	LF	4	1-2 years	Corroded piping
Pumps							
umps	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	ĒA	6	6-10 years	No access
Catego	ry : Room		в	uilding	• Main		
oulogo				unung	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	102 Assistant Principal	143	SF	6	10+ years	
	Doors - Side-lite	102 Assistant Principal	11	SF	7	10+ years	
	Doors - Transom Window	102 Assistant Principal	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 Assistant Principal	1	EA	6	10+ years	
	Floor - Carpet	102 Assistant Principal	143	SF	6	2-5 years	
	Lighting - Pendent/Surface	102 Assistant Principal	6	EA	7	6-10 years	
	Walls - Concrete Block	102 Assistant Principal	98	SF	7	10+ years	
	Walls - Metal Panel	102 Assistant Principal	325	SF	7	10+ years	
	Ceiling - Lay-in	125 Security Office	218	SF	6	10+ years	
	Doors - Steel Doors incl hw	125 Security Office	2	EA	7	10+ years	
	Floor - Carpet	125 Security Office	218	SF	6	2-5 years	
	Lighting - Lay-in	125 Security Office	4	EA	7	6-10 years	
	Power Distribution	125 Security Office	6	EA	6	10+ years	
	Walls - Concrete Block	125 Security Office	25	SF	6	10+ years	
	Walls - Metal Panel	125 Security Office	520	SF	6	10+ years	
	Ceiling - Lay-in	127 Attendants Office	790	SF	6	10+ years	
	Doors - Side-lite	127 Attendants Office	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	127 Attendants Office	2	EA	6	10+ years	
	Doors - Transom Window	127 Attendants Office	14	SF	6	10+ years	
	Floor - Carpet		790	SF	6	-	
		127 Attendants Office				6-10 years	
	Lighting - Lay-in	127 Attendants Office	26	EA	7	6-10 years	
	Power Distribution	127 Attendants Office	12	EA	6	10+ years	
	Walls - Concrete Block	127 Attendants Office	430	SF	6	10+ years	
	Walls - Metal Panel	127 Attendants Office	515	SF	6	10+ years	
	Work SInk	127 Attendants Office	1	EA	7	10+ years	
	Ceiling - Lay-in	128 Office (former Counselor)	206	SF	6	10+ years	
	Doors - Side-lite	128 Office (former Counselor)	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	128 Office (former Counselor)	1	EA	6	10+ years	
	Doors - Transom Window	128 Office (former Counselor)	14	SF	6	10+ years	



Category : Room Building Recomments Group tern - Type Cacation Quantity VM Recomments Comments Floor - Carpet 128 Office former Counselor) 14 SF 6 2.9 years 6 10 years Information 128 Office former Counselor) 44 SF 6 2.9 years 6 10 years Walls - Concrete Block 128 Office former Counselor) 300 SF 6 10 years Moved from Classrooms, recalculated quantity Valls - Concrete Block 128 Office former Counselor) 200 SF 7 10 + years Moved from Classrooms, net previously assessed Doors - Side-lite 141/143 11 SF 7 10 + years Moved from Classrooms, net previously assessed Poor - Carpet 141/143 16 SF 7 6 + 10 years Moved from Classrooms Poor - Carpet 141/143 10 SF 7 6 + 10 years Moved from Classrooms Poor - Side-lite 141/143 10 SF 7 6 +	Catego			R	uilding	• Main	51	01 W Hamson STREET, Chicago, iL 60644																																																																																																																																																																		
Group tern - Type Location Quantity VOW Rank Replacement Comments Floor - Carpet 128 Office (former Counselor) 44 SF 6 2-3 years Power Distribution 128 Office (former Counselor) 44 SF 6 2-3 years Power Distribution 128 Office (former Counselor) 4 EA 6 6-10 years Walls - Concrete Block 128 Office (former Counselor) 260 SF 6 10+ years Moved from Classrooms, recalculated quantity 260 SF 7 10+ years Moved from Classrooms, net previously assessed Doors - Side-lite 141/143 1 SF 7 10+ years Moved from Classrooms, net previously assessed Doors - Transon Window 141/143 20 SF 7 10+ years Moved from Classrooms, net previously assessed Power Distribution 141/143 20 SF 7 10+ years Moved from Classrooms, net previously assessed Uptim - Lay-in 141/143 20 SF 7 10+ years	Jacyo				anang	. mani	Recommend																																																																																																																																																																			
Floor - Carpet 128 Office (former Counselor) 162 SF 6 6 ⁻¹ 0 years Floor - Carpet 128 Office (former Counselor) 7 EA 7 6 ⁻¹⁰ years Power Distribution 128 Office (former Counselor) 7 EA 7 6 ⁻¹⁰ years Walls - Concrete Block 128 Office (former Counselor) 310 SF 6 104 years Walls - Concrete Block 128 Office (former Counselor) 310 SF 6 104 years Celling - Lay-in 141/143 900 SF 7 104 years quantity Doors - Transom Window 141/143 1 SF 7 104 years previously assessed Doors - Wood Doors inclu hw 141/143 1 SF 7 104 years Moved from Classrooms, not previously assessed Lighting - Lay-in 141/143 1 SF 7 104 years Moved from Classrooms, not previously assessed Walls - Plaset(Distribution 141/143 20 EA 7 104 years Rower Side-lite 14	Group	Item - Type	Location	Quantity	UOM	Rank		Comments																																																																																																																																																																		
Floor - Carriet 128 Office (former Counselor) 44 SF 6 2-5 years Lighting - Lay-in 128 Office (former Counselor) 4 EA 6 6-10 years Walls - Concrete Block 128 Office (former Counselor) 310 SF 6 10+ years Ceiling - Lay-in 141/143 200 SF 7 10+ years Moved from Classrooms, necalculated quantity Doors - Side-lite 141/143 11 SF 7 10+ years Moved from Classrooms, not previously assessed Doors - Vice of Doors inclu hw 141/143 14 SF 7 10+ years Moved from Classrooms, not previously assessed Picor - Carpet 141/143 900 SF 7 10+ years Moved from Classrooms Walls - Plaster/Drywall 14/1/143 900 SF 7 10+ years Moved from Classrooms, not previously assessed Walls - Plaster/Drywall 14/1/43 900 SF 7 10+ years Ours - Steel-lite 141/143 1500 SF 7 10+ years	0.000																																																																																																																																																																									
Lighting - Lay-in 128 Office (former Counselor) 7 EA 7 6 - 10 years Power Distribution 128 Office (former Counselor) 310 SF 6 10+ years Walls - Concrete Block 128 Office (former Counselor) 310 SF 6 10+ years Ceiling - Lay-in 141/143 90 SF 7 10+ years Doors - Side-life 141/143 1 SF 7 10+ years Doors - Transom Window 141/143 1 SF 7 10+ years Doors - Vood Doors inclu hw 141/143 20 SF 7 10+ years Doors - Vood Doors inclu hw 141/143 20 SF 7 10+ years Walls - Plaster/Drywall 141/143 20 SF 7 10+ years Walls - Plaster/Drywall 141/143 20 SF 7 10+ years Ceiling - Lay-in 1441/A 18 SF 7 10+ years Doors - Side-life 141/A 18 SF 7<																																																																																																																																																																										
Power Distribution 128 Office (former Counselor) 4 EA 6 6 - 10 years Walls - Metal Panel 128 Office (former Counselor) 260 SF 6 10+ years Ceiling - Lay-in 141/143 260 SF 7 10+ years Doors - Side-life 141/143 11 SF 7 10+ years Doors - Transom Window 141/143 14 SF 7 10+ years Doors - Wood Doors inclu hw 141/143 1 EA 7 10+ years Power Distribution 141/143 29 EA 7 6-10 years Power Distribution 141/143 20 EA 7 10+ years Walls - Baster/Drywall 141/143 20 EA 7 10+ years Ceiling - Lay-in 141/143 100 SF 7 10+ years Doors - Side-life 141/A 160 SF 7 10+ years Doors - Side-life 141/A 160 SF 7 10+ years							•																																																																																																																																																																			
Walls - Concrete Block 128 Office (former Counselor) 310 SF 6 10+ years Ceiling - Lay-in 141/143 900 SF 7 10+ years Moved from Classrooms, recalculated quantity Doors - Side-lite 141/143 11 SF 7 10+ years Moved from Classrooms, not proviously assessed Doors - Transom Window 141/143 1 SF 7 10+ years Moved from Classrooms, not proviously assessed Doors - Carpet 141/143 1 SF 7 10+ years Moved from Classrooms, not proviously assessed Power Distribution 141/143 20 SF 7 10+ years Moved from Classrooms Power Distribution 141/143 20 SF 7 10+ years Moved from Classrooms Walls - Plaster/Drywall 141/143 108 SF 7 10+ years Moved from Classrooms Doors - Siteel boors incl hw 141/143 108 SF 7 10+ years Doors - Siteel boors incl hw 141/14 18 SF 7							,																																																																																																																																																																			
Walls - Metal Panel128 Office (former Counselor)260SF610 + yearsMoved from Classrooms, necalculated quantityDoors - Side-lite141/14311SF710 + yearsMoved from Classrooms, not previously assessedDoors - Transom Window141/14314SF710 + yearsMoved from Classrooms, not previously assessedDoors - Wood Doors inclu hw141/1431EA710 + yearsMoved from Classrooms, not previously assessedDoors - Wood Doors inclu hw141/14320EA76-10 yearsMoved from Classrooms, not previously assessedCeiling - Lay-in141/14320EA76-10 yearsMoved from Classrooms, not previously assessedCeiling - Lay-in141/14310 BSF710 + yearsDoors - Steel Doors incl hw141/14310 BSF710 + yearsDoors - Steel Doors incl hw141/14310 BSF710 + yearsPower Distribution141A10 BSF710 + yearsDoors - Steel Doors incl hw141A18SF710 + yearsPower Distribution141B18SF710 + yearsDoors - Steel Doors incl hw141B18SF710 + yearsDoors - Steel Doors incl hw141B18SF710 + yearsPower Distribution141B18SF710 + yearsDoors - Steel Doors incl hw141B18 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>																																																																																																																																																																										
Ceiling - Lay-in141/143900SF710 - years quantity Moved from Classrooms, not previously assessedDoors - Stade-life141/14311SF710 - yearsMoved from Classrooms, not previously assessedDoors - Transom Window141/14314SF710 - yearsMoved from Classrooms, not previously assessedDoors - Vood Doors inclu hw141/1431EA710 - yearsMoved from ClassroomsFloor - Carpet141/14320EA76 - 10 yearsMoved from ClassroomsPower Distribution141/14320EA710 + yearsWalls - Plaster/Drywall141/14320EA710 + yearsDoors - Side-life141/18SF710 + yearsDoors - Side-life141/18SF710 + yearsDoors - Side-life141/18SF710 + yearsDoors - Side-life141/A18SF710 + yearsDoors - Side-life141/A18SF710 + yearsPower Distribution141/A18SF710 + yearsPower Distribution141/A18SF710 + yearsDoors - Side-life141/A18SF710 + yearsDoors - Side-life141/A18SF710 + yearsDoors - Side-life141/A19SF710 + yearsDoors - Side-life141/A19 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>-</td><td></td><td></td></td<>						-																																																																																																																																																																				
Lighting - Lay-in141/14311SF710+ years 10+ yearsMoved from Classrooms, not previously assessed Moved from Classrooms, not previously assessed Moved from ClassroomsMoved from Classrooms, not previously assessed Moved from ClassroomsDoors - Wood Doors inclu hw141/1431EA710+ yearsMoved from ClassroomsLighting - Lay-in141/14320EA76-10 yearsMoved from ClassroomsPower Distribution141/14320EA710+ yearsWalls - Plaster/Dryvall141/14320EA710+ yearsCeiling - Lay-in141/143108SF710+ yearsDoors - Side-lite141/A18SF710+ yearsDoors - Side-lite141/A108SF710+ yearsDoors - Side-lite141/A18SF710+ yearsDoors - Side-lite141/A18SF710+ yearsUghting - Lay-in141/A18SF710+ yearsUghting - Lay-in141/A18SF710+ yearsDoors - Side-lite141/A18SF710+ yearsDoors - Side-lite141/B18SF710+ yearsDoors - Side-lite141/B18SF710+ yearsDoors - Side-lite141/B18SF710+ yearsDoors - Side-lite141/B18SF710+ yearsDoors - Side-lite <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td> <td>Moved from Classrooms, recalculated</td>						-		Moved from Classrooms, recalculated																																																																																																																																																																		
Doors - Side-life141/14311SF710 + yearsMoved from Classrooms, not previously assessed moved from Classrooms, not previously assessed moved from ClassroomsDoors - Wood Doors inclu hw141/1431EA710 + yearsMoved from ClassroomsDoors - Wood Doors inclu hw141/14329SF76-10 yearsMoved from ClassroomsEighting - Lay-in141/14329EA710 + yearsMoved from ClassroomsPower Distribution141/14320EA710 + yearsCeiling - Lay-in141A108SF710 + yearsDoors - Side Doors incl hw141A18SF710 + yearsDoors - Side Doors incl hw141A18SF710 + yearsFloor - Carpet141A198SF710 + yearsUrighting - Lay-in141A18SF710 + yearsPower Distribution141A18SF710 + yearsPower Distribution141A18SF710 + yearsWalls - Plaster/Drywall141A19SF710 + yearsUrighting - Lay-in141A18SF710 + yearsDoors - Side-Doors incl hw141B1EA710 + yearsDoors - Side-Doors incl hw141B1SF710 + yearsDoors - Side-Doors incl hw141B1SF710 + yearsDoors - Side-Doors incl hw<				000	01	,	ior youro																																																																																																																																																																			
Doors - Transom Window141/14314SF710 + yearsMoved from Classrooms, not previously assessedDoors - Wood Doors inclu hw141/143900SF76-10 yearsMoved from ClassroomsFloor - Carpet141/14320EA76-10 yearsMoved from ClassroomsPower Distribution141/14320EA710- yearsMoved from ClassroomsPower Distribution141/14320EA710- yearsMoved from ClassroomsWalls - Plaster/Drywall141/143108SF710- yearsMoved from Classrooms, recalculated quantities, corrected item typeCeiling - Lay-in141A108SF710- yearsDoors - Side-lite141A18SF710- yearsDoors - Side-lite141A18SF710- yearsDoors - Side-lite141A18SF710- yearsDoors - Side-lite141A18SF710- yearsWalls - Plaster/Drywall141A18SF710- yearsWalls - Plaster/Drywall141A18SF710- yearsDoors - Side-lite141B18SF710- yearsDoors - Side-loors incl hw141B18SF710- yearsDoors - Side-loors incl hw141B18SF710- yearsDoors - Side-loors incl hw141B18SF710- yearsDoors - Side-loors incl		Doors - Side-lite	141/143	11	SF	7	10+ vears																																																																																																																																																																			
Doors - Transom Window141/14314SF710- years previously assessed previously assessed moved from Classrooms, not previously assessed Moved from ClassroomsDoors - Carpet141/143900SF76-10 years 6-10 yearsMoved from ClassroomsLighting - Lay-in141/14329EA76-10 years 6-10 yearsMoved from ClassroomsWalls - Plaster/Dywall141/14320EA710- years 6-10 yearsMoved from Classrooms, recalculated quantities, corrected item typeCeiling - Lay-in141A18SF710- yearsDoors - Side-Iboors incl hw141A18SF710- yearsDoors - Side-Iboors incl hw141A18SF710- yearsPower Distribution141A198SF710- yearsPower Distribution141A198SF710- yearsPower Distribution141A199SF710- yearsWalls - Plaster/Drywall141B199SF710- yearsDoors - Side-Iboors incl hw141B18SF710- yearsDoors - Side-Iboors incl hw141C <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>, , , , , , , , , , , , , , , , , , ,</td> <td></td>							, , , , , , , , , , , , , , , , , , ,																																																																																																																																																																			
Doors - Wood Doors inclu hw141/1431EA710+ years 100 wed from ClassroomsFloor - Carpet141/14320EA76-10 yearsMoved from ClassroomsPower Distribution141/14320EA76-10 yearsMoved from ClassroomsPower Distribution141/14320EA710+ yearsMoved from ClassroomsWalis - Plaster/Dywall141/143108SF710+ yearsMoved from Classrooms, ecalculatedCelling - Lay-in141A108SF710+ yearsMoved from Classrooms, ecalculatedDoors - Side-lite141A108SF710+ yearsFloor - Carpet141A108SF710+ yearsLighting - Lay-in141A2EA76-10 yearsPower Distribution141A108SF710+ yearsWalis - Plaster/Drywall141A18710+ yearsDoors - Side-lite141B12SF710+ yearsDoors - Side-lite141B12SF710+ yearsDoors - Side-lite141B12SF710+ yearsDoors - Side-lite141B12SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141C		Doors - Transom Window	141/143	14	SF	7	10+ vears																																																																																																																																																																			
Doors - Wood Doors inclu hw 11/143 1 EA 7 10+ years Moved from Classrooms Floor - Carpet 141/143 20 EA 7 6-10 years Moved from Classrooms Power Distribution 141/143 20 EA 7 10+ years Moved from Classrooms Walls - Plaster/Drywall 141/143 20 EA 7 10+ years Ceiling - Lay-in 141/143 108 SF 7 10+ years Doors - Side-lite 141/A 18 SF 7 10+ years Doors - Side-lite 141/A 18 SF 7 10+ years Doors - Side-lite 141/A 18 SF 7 6-10 years Floor - Carpet 141/A 108 SF 7 6-10 years Valls - Plaster/Drywall 141/A 19 SF 7 10+ years Power Distribution 1418 18 SF 7 10+ years Doors - Side-lite 141B 18 SF					-		-)																																																																																																																																																																			
Floor - Carpet141/143900SF76-10 years 6-10 yearsMoved from Classrooms Moved from Classrooms Moved from ClassroomsWalls - Plaster/Drywall141/14320EA710+ years10+ yearsCeiling - Lay-in141A108SF710+ yearsMoved from Classrooms, recalculated quantities, corrected item typeCeiling - Lay-in141A108SF710+ yearsDoors - Side-lite141A18SF710+ yearsDoors - Side-lite141A18SF710+ yearsDoors - Carpet141A18SF76-10 yearsLighting - Lay-in141A18SF76-10 yearsPower Distribution141A19SF710+ yearsPower Distribution141A19SF710+ yearsCeiling - Lay-in141A19SF710+ yearsPower Distribution141B1EA710+ yearsDoors - Side-lite141B1EA710+ yearsDoors - Sidel Doors inch hw141B1EA710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141B19SF710+ yearsDoors - Side-lite141B19SF710+ yearsDoors - Side-lite141B18SF		Doors - Wood Doors inclu hw	141/143	1	EA	7	10+ vears																																																																																																																																																																			
Lighting - Lay-in141/14329EA76-10 yearsMoved from ClassroomsWale - Plaster/Drywall141/1431,500SF710+ yearsMoved from Classrooms, recalculated quantities, corrected item typeCelling - Lay-in141A108SF710+ yearsDoors - Side-lite141A18SF710+ yearsDoors - Side-lite141A18SF710+ yearsDoors - Side-lite141A18SF76-10 yearsFloor - Carpet141A18SF76-10 yearsLighting - Lay-in141A2EA76-10 yearsPower Distribution141A18SF710+ yearsPower Distribution141A18SF710+ yearsWalls - Plaster/Drywall141A18SF710+ yearsDoors - Side-lite141B172SF710+ yearsDoors - Steel Doors incl hw141B1EA710+ yearsLighting - Lay-in141B1EA710+ yearsHor- Carpet141B1EA710+ yearsLighting - Lay-in141B1EA710+ yearsHow - Distribution141B1EA710+ yearsWalls - Plaster/Drywall141B1EA710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsDoors - Steel Doors																																																																																																																																																																										
Power Distribution141/14320EA710+ yearsNoved from Classrooms, recalculated quantities, corrected item typeCeiling - Lay-in141A108SF710+ yearsDoors - Side-lite141A108SF710+ yearsDoors - Side-lite141A18SF710+ yearsDoors - Steel Doors incl hw141A1EA710+ yearsFloor - Carpet141A108SF76-10 yearsLighting - Lay-in141A2EA76-10 yearsPower Distribution141A198SF710+ yearsCeiling - Lay-in141B72SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Side-lite141B199SF710+ yearsDoors - Side-lite141B199SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF71							•																																																																																																																																																																			
Walls - Plaster/Drywall141/1431,500SF710 + ýears yearsMoved from Classrooms, recalculated quantities, corrected item typeCeiling - Lay-in141A108SF710+ yearsDoors - Steel Doors incl hw141A1EA710+ yearsFloor - Carpet141A108SF76-10 yearsLighting - Lay-in141A2EA76-10 yearsPower Distribution141A199SF710+ yearsCeiling - Lay-in141A199SF710+ yearsDoors - Sitel Doors incl hw141B18SF710+ yearsDoors - Sitel Doors incl hw141B199SF710+ yearsUighting - Lay-in141B199SF710+ yearsWalls - Plaster/Drywall141C108SF710+ yearsDoors - Side Itic141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsHower Distribution141C8EA7 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>,</td> <td></td>							,																																																																																																																																																																			
Ceiling - Lay-in 141A 108 SF 7 10+ years Doors - Side-lite 141A 18 SF 7 10+ years Doors - Side-lite 141A 18 SF 7 10+ years Doors - Steel Doors incl hw 141A 18 SF 7 10+ years Floor - Carpet 141A 108 SF 7 6-10 years Lighting - Lay-in 141A 2 EA 7 6-10 years Power Distribution 141A 199 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 2 EA 7 6-10 years Lighting - Lay-in 141B 199 SF 7 10+ years Power Distribution 141B 199				-				Moved from Classrooms, recalculated																																																																																																																																																																		
Ceiling - Lay-in141A108SF710+ yearsDoors - Stele Doors incl hw141A1BSF710+ yearsFloor - Carpet141A108SF76-10 yearsLighting - Lay-in141A2EA76-10 yearsPower Distribution141A6EA76-10 yearsWalls - Plaster/Drywall141A199SF710+ yearsCeiling - Lay-in141B72SF710+ yearsDoors - Side-lite141B72SF710+ yearsDoors - Side-lite141B72SF710+ yearsDoors - Steel Doors incl hw141B72SF76-10 yearsLighting - Lay-in141B72SF710+ yearsDoors - Steel Doors incl hw141B72SF76-10 yearsUighting - Lay-in141B72SF710+ yearsDoors - Steel Doors incl hw141B19SF710+ yearsUighting - Lay-in141B19SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Side-lite141C18SF710+ yearsHighting - Lay-in141C18SF710+ yearsPower Distri		Walls Tlaster/Drywall		1,000	01	'	Tor years																																																																																																																																																																			
Doors - Side-lite 141A 18 SF 7 10+ years Doors - Steel Doors incl hw 141A 1 EA 7 10+ years Floor - Carpet 141A 108 SF 7 6-10 years Lighting - Lay-in 141A 2 EA 7 6-10 years Walls - Plaster/Drywall 141A 2 EA 7 10+ years Ceiling - Lay-in 141B 199 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Steel Doors incl hw 141B 12 EA 7 6-10 years Lighting - Lay-in 141B 12 EA 7 6-10 years Power Distribution 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Steel Doors incl hw		Ceiling - Lav-in	141A	108	SF	7	10+ vears	qualitatee, concerce territype																																																																																																																																																																		
Doors - Steel Doors incl hw 141A 1 EA 7 10+ years Floor - Carpet 141A 108 SF 7 6-10 years Down Distribution 141A 2 EA 7 6-10 years Power Distribution 141A 6 EA 7 6-10 years Walls - Plaster/Drywall 141A 199 SF 7 10+ years Ceiling - Lay-in 141B 12 SF 7 10+ years Doors - Steel Doors incl hw 141B 18 SF 7 10+ years Doors - Steel Doors incl hw 141B 1 EA 7 10+ years Power Distribution 141B 2 EA 7 6-10 years Power Distribution 141B 2 EA 7 6-10 years Power Distribution 141B 199 SF 7 10+ years Ceiling - Lay-in 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Side-life		Doors - Side-lite																																																																																																																																																																								
Floor - Carpet 141A 108 SF 7 6-10 years Lighting - Lay-in 141A 2 EA 7 6-10 years Walls - Plaster/Drywall 141A 6 EA 7 6-10 years Walls - Plaster/Drywall 141A 199 SF 7 10+ years Ceiling - Lay-in 141B 72 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side-lite 141B 1 EA 7 10+ years Floor - Carpet 141B 1 EA 7 6-10 years Power Distribution 141B 2 EA 7 6-10 years Power Distribution 141B 8 EA 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td>							-																																																																																																																																																																			
Lighting - Lay-in141A2EA76-10 yearsPower Distribution141A6EA76-10 yearsWalls - Plaster/Drywall141A199SF710+ yearsCeiling - Lay-in141B72SF710+ yearsDoors - Side-lite141B18SF710+ yearsDoors - Steel Doors incl hw141B72SF76-10 yearsFloor - Carpet141B72SF76-10 yearsLighting - Lay-in141B2EA76-10 yearsPower Distribution141B2EA76-10 yearsUalls - Plaster/Drywall141B199SF710+ yearsDoors - Side-lite141B199SF710+ yearsCeiling - Lay-in141B199SF710+ yearsDoors - Side-lite141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C18SF710+ yearsDoors - Steel Doors incl hw141C18EA710+ yearsLighting - Lay-in141C19SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite <td></td> <td></td> <td></td> <td>108</td> <td></td> <td></td> <td></td> <td></td>				108																																																																																																																																																																						
Power Distribution 141A 6 EA 7 6-10 years Walls - Plaster/Drywall 141A 199 SF 7 10+ years Ceiling - Lay-in 141B 72 SF 7 10+ years Doors - Side-lite 141B 1 EA 7 10+ years Doors - Steel Doors incl hw 141B 1 EA 7 10+ years Floor - Carpet 141B 72 SF 7 6-10 years Lighting - Lay-in 141B 2 EA 7 6-10 years Power Distribution 141B 2 EA 7 6-10 years Power Distribution 141B 2 EA 7 6-10 years Power Distribution 141B 8 EA 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Stele Doors incl hw 141C 1 EA 7 6-10 years Lighting - Lay-in 141C 1 EA 7 6-10 years Power Distribution 141C </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>																																																																																																																																																																										
Walls - Plaster/Drywall 141A 199 SF 7 10+ years Ceiling - Lay-in 141B 72 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Side Doors incl hw 141B 1 EA 7 10+ years Floor - Carpet 141B 72 SF 7 6-10 years Lighting - Lay-in 141B 72 SF 7 6-10 years Power Distribution 141B 8 EA 7 10+ years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Power Distribution 141B 199 SF 7 10+ years Doors - Side-lite 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 6-10 years Floor - Carpet 141C 18 SF 7 10+ years Floor - Carpet 141C																																																																																																																																																																										
Ceiling - Lay-in 141B 72 SF 7 10+ years Doors - Side-lite 141B 18 SF 7 10+ years Doors - Steel Doors incl hw 141B 1 EA 7 10+ years Floor - Carpet 141B 72 SF 7 6-10 years Lighting - Lay-in 141B 2 EA 7 6-10 years Power Distribution 141B 8 EA 7 10+ years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Doors - Side-lite 141C 108 SF 7 10+ years Doors - Side-lite 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 6-10 years Lighting - Lay-in 141C 18 SF 7 10+ years Floor - Carpet 141C 18 SF 7 10+ years Walls - Plaster/Drywall 141C							•																																																																																																																																																																			
Doors - Side-lite 141B 18 SF 7 10+ years Doors - Steel Doors incl hw 141B 1 EA 7 10+ years Floor - Carpet 141B 72 SF 7 6-10 years Lighting - Lay-in 141B 2 EA 7 6-10 years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Steel Doors incl hw 141C 18 SF 7 10+ years Doors - Steel Doors incl hw 141C 18 SF 7 10+ years Floor - Carpet 141C 18 SF 7 10+ years Floor - Carpet 141C 18 SF 7 10+ years Floor - Carpet 141C 18 SF 7 10+ years Valls - Plaster/Drywall 141C 18 SF 7 6-10 years Walls - Plaster/Drywall 141C 199 SF 7 10+ years Ceiling - Lay-in																																																																																																																																																																										
Doors - Steel Doors incl hw141B1EA710+ yearsFloor - Carpet141B72SF76-10 yearsLighting - Lay-in141B2EA76-10 yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C108SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C18SF710+ yearsPower Distribution141C2EA76-10 yearsLighting - Lay-in141C198SF710+ yearsValls - Plaster/Drywall141C2EA76-10 yearsWalls - Plaster/Drywall141C199SF710+ yearsOors - Side-lite141D150SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D150SF710+ years <tr <tr="">Doors - Side-lite<t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<></tr> <tr><td>Floor - Carpet141B72SF76-10 yearsLighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA76-10 yearsValls - Plaster/Drywall141C198SF710+ yearsCeiling - Lay-in141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Lighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Siteel Doors incl hw141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Siteel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td>,</td><td></td></tr> <tr><td>Power Distribution 141B 8 EA 7 10+ years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Steel Doors incl hw 141C 1 EA 7 10+ years Floor - Carpet 141C 108 SF 7 6-10 years Lighting - Lay-in 141C 2 EA 7 6-10 years Power Distribution 141C 8 EA 7 10+ years Walls - Plaster/Drywall 141C 2 EA 7 6-10 years Walls - Plaster/Drywall 141C 199 SF 7 10+ years Geiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw</td><td></td><td></td><td></td><td></td><td></td><td></td><td>2</td><td></td></tr> <tr><td>Walls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D10SF710+ yearsDoors - Side-lite141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Ceiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF710+ yearsFloor - Carpet141D150SF710+ years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Doors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td>-</td><td></td></tr> <tr><td>Doors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Floor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Lighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Power Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Walls - Plaster/Drywall 141C 199 SF 7 10+ years Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years</td><td></td><td>Lighting - Lay-In Dower Distribution</td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td>•</td><td></td></tr> <tr><td>Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Doors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Floor - Carpet 141D 150 SF 7 6-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>Lighting - Lay-in 141D 1 EA / 6-10 years</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td></td><td>Lignung - Lay-in</td><td>141D</td><td>1</td><td>EA</td><td>1</td><td>o-TO years</td><td></td></tr>									Floor - Carpet141B72SF76-10 yearsLighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA76-10 yearsValls - Plaster/Drywall141C198SF710+ yearsCeiling - Lay-in141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite									Lighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Siteel Doors incl hw141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Siteel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 years							,		Power Distribution 141B 8 EA 7 10+ years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Steel Doors incl hw 141C 1 EA 7 10+ years Floor - Carpet 141C 108 SF 7 6-10 years Lighting - Lay-in 141C 2 EA 7 6-10 years Power Distribution 141C 8 EA 7 10+ years Walls - Plaster/Drywall 141C 2 EA 7 6-10 years Walls - Plaster/Drywall 141C 199 SF 7 10+ years Geiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw							2		Walls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D10SF710+ yearsDoors - Side-lite141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Ceiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF710+ yearsFloor - Carpet141D150SF710+ years									Doors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years							-		Doors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Floor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Lighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Power Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Walls - Plaster/Drywall 141C 199 SF 7 10+ years Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years		Lighting - Lay-In Dower Distribution							Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years							•		Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years									Doors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years									Floor - Carpet 141D 150 SF 7 6-10 years																		Lighting - Lay-in 141D 1 EA / 6-10 years											Lignung - Lay-in	141D	1	EA	1	o-TO years	
Floor - Carpet141B72SF76-10 yearsLighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA76-10 yearsValls - Plaster/Drywall141C198SF710+ yearsCeiling - Lay-in141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite141D150SF76-10 yearsDoors - Side-lite																																																																																																																																																																										
Lighting - Lay-in141B2EA76-10 yearsPower Distribution141B8EA710+ yearsWalls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C18SF710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C2EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141C199SF710+ yearsDoors - Side-lite141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Siteel Doors incl hw141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Siteel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF76-10 years							,																																																																																																																																																																			
Power Distribution 141B 8 EA 7 10+ years Walls - Plaster/Drywall 141B 199 SF 7 10+ years Ceiling - Lay-in 141C 108 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Side-lite 141C 18 SF 7 10+ years Doors - Steel Doors incl hw 141C 1 EA 7 10+ years Floor - Carpet 141C 108 SF 7 6-10 years Lighting - Lay-in 141C 2 EA 7 6-10 years Power Distribution 141C 8 EA 7 10+ years Walls - Plaster/Drywall 141C 2 EA 7 6-10 years Walls - Plaster/Drywall 141C 199 SF 7 10+ years Geiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw							2																																																																																																																																																																			
Walls - Plaster/Drywall141B199SF710+ yearsCeiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C199SF710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D10SF710+ yearsDoors - Side-lite141D150SF710+ yearsFloor - Carpet141D150SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Ceiling - Lay-in141C108SF710+ yearsDoors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 yearsFloor - Carpet141D150SF710+ yearsFloor - Carpet141D150SF710+ years																																																																																																																																																																										
Doors - Side-lite141C18SF710+ yearsDoors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years							-																																																																																																																																																																			
Doors - Steel Doors incl hw141C1EA710+ yearsFloor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Floor - Carpet141C108SF76-10 yearsLighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Lighting - Lay-in141C2EA76-10 yearsPower Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Power Distribution141C8EA710+ yearsWalls - Plaster/Drywall141C199SF710+ yearsCeiling - Lay-in141D150SF710+ yearsDoors - Side-lite141D25SF710+ yearsDoors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Walls - Plaster/Drywall 141C 199 SF 7 10+ years Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years		Lighting - Lay-In Dower Distribution																																																																																																																																																																								
Ceiling - Lay-in 141D 150 SF 7 10+ years Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years							•																																																																																																																																																																			
Doors - Side-lite 141D 25 SF 7 10+ years Doors - Steel Doors incl hw 141D 1 EA 7 10+ years Floor - Carpet 141D 150 SF 7 6-10 years																																																																																																																																																																										
Doors - Steel Doors incl hw141D1EA710+ yearsFloor - Carpet141D150SF76-10 years																																																																																																																																																																										
Floor - Carpet 141D 150 SF 7 6-10 years																																																																																																																																																																										
Lighting - Lay-in 141D 1 EA / 6-10 years																																																																																																																																																																										
		Lignung - Lay-in	141D	1	EA	1	o-TO years																																																																																																																																																																			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	141D	1	EA	6	6-10 years	
	Power Distribution	141D	10	EA	7	10+ years	
	Walls - Plaster/Drywall	141D	450	SF	7	10+ years	
	Ceiling - Lay-in	145	214	SF	7	10+ years	
	Doors - Steel Doors incl hw	145	1	EA	7	10+ years	
	Floor - Carpet	145	214	SF	7	6-10 years	
	Lighting - Lay-in	145	6	EA	7	6-10 years	
	Walls - Concrete Block	145	56	SF	7	10+ years	
	Walls - Plaster/Drywall	145	460	SF	6	10+ years	
	Ceiling - Lay-in	147 Break Room	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	147 Break Room	1	EA	7	10+ years	
	Floor - Tile	147 Break Room	70	SF	7	10+ years	
	Lighting - Lay-in	147 Break Room	2	EA	7	6-10 years	
	Power Distribution	147 Break Room	4	EA	7	10+ years	
	Storage/ Closet	147 Break Room	15	SF	7	10+ years	
	Walls - Concrete Block	147 Break Room	140	SF	7	10+ years	
	Walls - Plaster/Drywall	147 Break Room	200	SF	7	10+ years	
	Work SInk	147 Break Room	1	EA	7	10+ years	
	Ceiling - Lay-in	148 - Office	207	SF	6	10+ years	
	Doors - Side-lite	148 - Office	11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	148 - Office	1	EA	7	10+ years	
	Doors - Transom Window	148 - Office	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	148 - Office	157	SF	6	2-5 years	
	Floor - Tile	148 - Office	50	SF	7	10+ years	
	Lighting - Lay-in	148 - Office	2	EA	7	6-10 years	
	Lighting - Lay-in	148 - Office	4	EA	6	6-10 years	
	Power Distribution	148 - Office	6	EA	7	10+ years	Not previously assessed
	Walls - Concrete Block	148 - Office	311	SF	6	10+ years	
	Walls - Metal Panel	148 - Office	261	SF	6	10+ years	
	Ceiling - Plaster/Drywall	200 Office (former Classroom)	445	SF	6	10+ years	
	Doors - Steel Doors incl hw	200 Office (former Classroom)	1	EA	6	10+ years	
	Doors - Transom Window	200 Office (former Classroom)	9	SF	7	10+ years	Not previously assessed
	Floor - Carpet	200 Office (former Classroom)	445	SF	6	6-10 years	
	Lighting - Pendent/Surface	200 Office (former Classroom)	7	EA	7	6-10 years	Downlights Qty and type updated
	Lighting - Pendent/Surface	200 Office (former Classroom)	4	EA	6	6-10 years	0 7 7 1
	Power Distribution	200 Office (former Classroom)	8	EA	6	10+ years	
	Walls - Concrete Block	200 Office (former Classroom)	424	SF	6	10+ years	
	Walls - Masonry	200 Office (former Classroom)	132	SF	6	10+ years	
			144	SF	6		
		212 Counseling Office	800	SF	6	10+ years	
	Doors - Side-lite		11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw		4	EA	7		
	Doors - Transom Window	212 Counseling Office	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	212 Counseling Office	800	SF	7	6-10 years	· ·
	Walls - Plaster/Drywall Ceiling - Lay-in Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window	200 Office (former Classroom) 212 Counseling Office 212 Counseling Office 212 Counseling Office 212 Counseling Office 212 Counseling Office	144 800 11 4 14	SF SF SF EA SF	6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	Not previously assessed Not previously assessed



Catego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	212 Counseling Office	11	EA	7	6-10 years	
	Lighting - Lay-in	212 Counseling Office	1	EA	6	6-10 years	
	Power Distribution	212 Counseling Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	212 Counseling Office	1,250	SF	7	10+ years	
	Ceiling - Lay-in	212A	90	SF	7	6-10 years	
	Doors - Steel Doors incl hw	212A	1	EA	7	6-10 years	
	Floor - Carpet	212A	90	SF	7	6-10 years	
	Lighting - Lay-in	212A	2	EA	7	6-10 years	
	Lighting - Lay-in	212A	1	EA	6	6-10 years	
	Power Distribution	212A	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	212A	304	SF	7	6-10 years	
	Ceiling - Lay-in	212B	90	SF	7	6-10 years	
	Doors - Steel Doors incl hw	212B	1	EA	7	6-10 years	
	Floor - Carpet	212B	90	SF	7	6-10 years	
	Lighting - Lay-in	212B	3	EA	7	6-10 years	
	Power Distribution	212B	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	212B	304	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	212C	90	SF	7	6-10 years	
	Doors - Steel Doors incl hw	212C	1	EA	7	6-10 years	
	Floor - Carpet	212C	90	SF	7	6-10 years	
	Lighting - Lay-in	212C	3	EA	6	6-10 years	Qty updated
	Power Distribution	212C	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	212C	304	SF	7	6-10 years	
	Ceiling - Lay-in	214 Office	80	SF	6	10+ years	
	Doors - Side-lite	214 Office	16	SF	4	0-1 year	Cracked glass
	Doors - Steel Doors incl hw	214 Office	1	EA	7	10+ years	-
	Floor - Carpet	214 Office	80	SF	7	6-10 years	
	Lighting - Lay-in	214 Office	4	EA	7	6-10 years	
	Power Distribution	214 Office	4	EA	7	10+ years	
	Walls - Metal Panel	214 Office	324	SF	7	10+ years	
	Ceiling - Lay-in	220A Teachers Resource Center	500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	220A Teachers Resource Center	48	SF	6	10+ years	
	Doors - Side-lite	220A Teachers Resource Center	11	SF	6	2-5 years	
	Doors - Steel Doors incl hw	220A Teachers Resource Center	1	EA	6	10+ years	
	Doors - Transom Window	220A Teachers Resource Center	14	SF	6	10+ years	
	Floor - Carpet	220A Teachers Resource Center	548	SF	6	6-10 years	
	Lighting - Lay-in	220A Teachers Resource Center	9	EA	7	6-10 years	
	Power Distribution	220A Teachers Resource Center	22	EA	7	10+ years	
	Walls - Masonry	220A Teachers Resource Center	98	SF	7	10+ years	
	Walls - Plaster/Drywall	220A Teachers Resource Center	386	SF	6	10+ years	
	Ceiling - Lay-in	225	207	SF	7	10+ years	
	Doors - Steel Doors incl hw	225	1	EA	7	10+ years	
	Floor - Carpet	225	207	SF	7	2-5 years	
	Lighting - Lay-in	225	10	EA	7	6-10 years	



Catego	ery : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	225	98	SF	6	10+ years	
	Walls - Metal Panel	225	211	SF	7	10+ years	
	Walls - Plaster/Drywall	225	310	SF	6	10+ years	
	Work SInk	225	1	EA	7	10+ years	
	Ceiling - Lay-in	226 Office	206	SF	6	10+ years	
	Doors - Side-lite	226 Office	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	226 Office	1	EA	6	10+ years	
	Doors - Transom Window	226 Office	14	SF	6	10+ years	
	Floor - Carpet	226 Office	206	SF	6	2-5 years	
	Lighting - Lay-in	226 Office	7	EA	7	6-10 years	
	Power Distribution	226 Office	6	EA	6	10+ years	
	Walls - Concrete Block	226 Office	300	SF	6	10+ years	
	Walls - Metal Panel	226 Office	250	SF	6	10+ years	
	Ceiling - Lay-in	240 Teachers Resource	500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	240 Teachers Resource	48	SF	7	10+ years	
	Doors - Side-lite	240 Teachers Resource	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	240 Teachers Resource	1	EA	6	10+ years	
	Doors - Transom Window	240 Teachers Resource	14	SF	7	10+ years	
	Floor - Carpet	240 Teachers Resource	548	SF	6	2-5 years	
	Lighting - Lay-in	240 Teachers Resource	9	EA	7	6-10 years	
	Power Distribution	240 Teachers Resource	22	EA	7	10+ years	
	Walls - Masonry	240 Teachers Resource	98	SF	6	10+ years	
	Walls - Plaster/Drywall	240 Teachers Resource	386	SF	7	10+ years	
	Ceiling - Lay-in	245	209	SF	7	10+ years	
	Doors - Side-lite	245	11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	245	1	EA	6	10+ years	
	Doors - Transom Window	245	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	245	209	SF	6	2-5 years	
	Lighting - Lay-in	245	8	ĒA	7	6-10 years	
	Walls - Concrete Block	245	100	SF	7	10+ years	
	Walls - Plaster/Drywall	245	572	SF	6	10+ years	
	Work SInk	245	1	EA	7	10+ years	
	Ceiling - Lay-in	248 Office	207	SF	6	10+ years	
	Doors - Side-lite	248 Office	11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	248 Office	1	EA	7	10+ years	
	Doors - Transom Window	248 Office	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	248 Office	157	SF	6	2-5 years	
	Floor - Tile	248 Office	50	SF	7	10+ years	
	Lighting - Lay-in	248 Office	8	EA	7	6-10 years	
	Walls - Concrete Block	248 Office	311	SF	6	10+ years	
	Walls - Metal Panel	248 Office	246	SF	6	10+ years	
	Ceiling - Lay-in	248 Office	323	SF	6	10+ years	
	Doors - Side-lite	249A Office	525 11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	249A Office	1	EA	7	10+ years	not previously assessed
			1	LA	'	IUT years	



Catego	ry : Room		Building : Main						
_				-		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	249A Office	323	SF	7	10+ years			
	Lighting - Lay-in	249A Office	6	EA	7	6-10 years			
	Walls - Concrete Block	249A Office	220	SF	7	10+ years			
	Walls - Plaster/Drywall	249A Office	335	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor VIP Conference Room	458	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor VIP Conference Room	1	EA	6	10+ years			
	Floor - Carpet	2nd Floor VIP Conference Room	458	SF	6	2-5 years			
	Lighting - Lay-in	2nd Floor VIP Conference Room	10	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor VIP Conference Room	424	SF	6	10+ years			
	Walls - Masonry	2nd Floor VIP Conference Room	159	SF	6	10+ years			
	Ceiling - Lay-in	Coach office	350	SF	6	10+ years			
	Doors - Side-lite	Coach office	11	SF	7	10+ years			
	Doors - Transom Window	Coach office	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Coach office	1	EA	7	10+ years			
	Floor - Carpet	Coach office	350	SF	6	6-10 years			
	Lighting - Lay-in	Coach office	11	EA	7	10+ years			
	Walls - Concrete Block	Coach office	146	SF	7	10+ years			
	Walls - Metal Panel	Coach office	334	SF	6	10+ years			
	Walls - Plaster/Drywall	Coach office	236	SF	7	10+ years			
	Ceiling - Lay-in	Copy room inside main office	95	SF	6	10+ years			
	Doors - Side-lite	Copy room inside main office	11	SF	7	10+ years			
	Doors - Transom Window	Copy room inside main office	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Copy room inside main office	1	EA	6	10+ years			
	Floor - Carpet	Copy room inside main office	95	SF	7	2-5 years			
	Lighting - Pendent/Surface	Copy room inside main office	2	EA	7	6-10 years			
	Walls - Concrete Block	Copy room inside main office	204	SF	6	10+ years			
	Walls - Plaster/Drywall	Copy room inside main office	204	SF	6	10+ years			
	Work Sink	Copy room inside main office	203	EA	7	•			
		Dean office	188	SF	7	10+ years			
	Ceiling - Lay-in Doors - Side-lite	Dean office		SF		10+ years			
	Doors - Transom Window	Dean office	11	SF	7 7	10+ years			
	Doors - Wood Doors inclu hw	Dean office	14 2	EA	6	10+ years			
		Dean office		SF		10+ years			
	Floor - Tile		188		6	6-10 years			
	Lighting - Lay-in	Dean office	8	EA	7	10+ years			
	Power Distribution	Dean office	4	EA	7	10+ years			
	Walls - Concrete Block	Dean office	200	SF	7	10+ years			
	Walls - Metal Panel	Dean office	437	SF	6	10+ years			
	Ceiling - Lay-in	Engineer's Office (former Nurse)	424	SF	6	10+ years			
	Doors - Side-lite	Engineer's Office (former Nurse)	11	SF	6	10+ years			
	Doors - Transom Window	Engineer's Office (former Nurse)	14	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Engineer's Office (former Nurse)	2	EA	6	10+ years			
	Floor - Carpet	Engineer's Office (former Nurse)	424	SF	6	2-5 years			
	Lighting - Lay-in	Engineer's Office (former Nurse)	17	EA	7	6-10 years			
	Power Distribution	Engineer's Office (former Nurse)	22	EA	6	10+ years			



Catego	ry : Room		В	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Engineer's Office (former Nurse)	416	SF	6	10+ years	
	Walls - Metal Panel	Engineer's Office (former Nurse)	438	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office (former Nurse)	350	SF	6	10+ years	
	Work SInk	Engineer's Office (former Nurse)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Gym Office	63	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym Office	1	EA	7	10+ years	
	Floor - Tile	Gym Office	63	SF	6	10+ years	
	Lighting - Lay-in	Gym Office	2	EA	7	6-10 years	
	Walls - Concrete Block	Gym Office	256	SF	7	10+ years	
	Ceiling - Splined	Kitchen Office	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen Office	42	SF	6	10+ years	
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	2	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Office	130	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	130	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Laundry Room off Natatorium	100	SF	7	10+ years	
	Doors - Steel Doors incl hw	Laundry Room off Natatorium	1	EA	6	10+ years	
	Doors - Transom Window	Laundry Room off Natatorium	11	SF	7	10+ years	Not previously assessed
	Floor - Tile Ceramic/ Porcelain	Laundry Room off Natatorium	100	SF	6	10+ years	
	Lighting - Lay-in	Laundry Room off Natatorium	2	EA	7	10+ years	
	Power Distribution	Laundry Room off Natatorium	6	EA	7	10+ years	Not previously assessed
	Walls - Concrete Block	Laundry Room off Natatorium	379	SF	6	10+ years	
	Ceiling - Lay-in	Librarian in 117 Library/Media	215	SF	6	10+ years	
	Doors - Side-lite	Librarian in 117 Library/Media	110	SF	7	10+ years	
	Doors - Transom Window	Librarian in 117 Library/Media	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Librarian in 117 Library/Media	1	EA	6	10+ years	
	Floor - Carpet	Librarian in 117 Library/Media	215	SF	7	6-10 years	
	Lighting - Pendent/Surface	Librarian in 117 Library/Media	7	EA	7	6-10 years	
	Power Distribution	Librarian in 117 Library/Media	8	EA	7	10+ years	
	Walls - Concrete Block	Librarian in 117 Library/Media	148	SF	6	10+ years	
	Walls - Metal Panel	Librarian in 117 Library/Media	420	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	609	SF	7	10+ years	
	Doors - Side-lite	Main Office	122	SF	7	10+ years	
	Doors - Transom Window	Main Office	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Tile	Main Office	609	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	22	EA	7	10+ years	
	Power Distribution	Main Office	16	EA	7	10+ years	
	Storage/ Closet	Main Office	213	SF	7	10+ years	
	Walls - Concrete Block	Main Office	200	SF	7	10+ years	
	Walls - Metal Panel	Main Office	448	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	416	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Natatorium Office	96	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Steel Doors incl hw	Natatorium Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Natatorium Office	96	SF	6	10+ years	
	Lighting - Lay-in	Natatorium Office	4	EA	7	6-10 years	
	Power Distribution	Natatorium Office	8	EA	6	10+ years	
	Walls - Concrete Block	Natatorium Office	392	SF	6	10+ years	
	Ceiling - Lay-in	Nurse office	130	SF	7	10+ years	
	Doors - Side-lite	Nurse office	11	SF	7	10+ years	
	Doors - Transom Window	Nurse office	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse office	1	EA	7	10+ years	
	Floor - Carpet	Nurse office	130	SF	4	1-2 years	Worn, torn, and stained carpet throughout
	Lighting - Lay-in	Nurse office	4	EA	7	6-10 years	linoughout
	Power Distribution	Nurse office	3	EA	7	10+ years	
	Storage/ Closet	Nurse office	84	SF	7	10+ years	
	Walls - Metal Panel	Nurse office	430	SF	7	10+ years	
	Work SInk	Nurse office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Office 1 inside open office	210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office 1 inside open office	1	EA	7	10+ years	
	Floor - Carpet	Office 1 inside open office	210	SF	6	6-10 years	
	Lighting - Lay-in	Office 1 inside open office	6	EA	7	6-10 years	
	Lighting - Lay-in	Office 1 inside open office	2	EA	6	6-10 years	
	Power Distribution	Office 1 inside open office	12	EA	7	10+ years	
	Walls - Concrete Block	Office 1 inside open office	190	SF	7	10+ years	
	Walls - Metal Panel	Office 1 inside open office	400	SF	7	10+ years	
	Ceiling - Lay-in	Office 2 inside open office	75	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office 2 inside open office	1	EA	7	10+ years	
	Floor - Carpet	Office 2 inside open office	75	SF	6	2-5 years	
	Lighting - Lay-in	Office 2 inside open office	4	EA	7	6-10 years	
	Power Distribution	Office 2 inside open office	10	EA	7	10+ years	Corrected quantity
	Walls - Metal Panel	Office 2 inside open office	420	SF	7	10+ years	
	Ceiling - Lay-in	Open Office	322	SF	7	10+ years	
	Doors - Side-lite	Open Office	11	SF	7	10+ years	
	Doors - Transom Window	Open Office	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Open Office	14	EA			
		Open Office	322	SF	6 4	10+ years	Frayed, worn, stained carpet
	Floor - Carpet				·	1-2 years	throughout
	Lighting - Lay-in	Open Office	13	EA	7	6-10 years	
	Power Distribution	Open Office	8	EA	7	10+ years	
	Storage/ Closet	Open Office	185	SF	7	10+ years	
	Walls - Concrete Block	Open Office	252	SF	7	10+ years	
	Walls - Plaster/Drywall	Open Office	525	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Office 1	211	SF	7	10+ years	
	Doors - Side-lite	Principal's Office 1	11	SF	7	10+ years	Not previously assessed
	Doors - Transom Window	Principal's Office 1	14	SF	7	10+ years	Not previously assessed



Catego	ry : Room		В	uilding	: Main		
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Principal's Office 1	2	EA	6	10+ years	
	Floor - Carpet	Principal's Office 1	211	SF	6	2-5 years	
	Lighting - Pendent/Surface	Principal's Office 1	5	EA	7	6-10 years	
	Power Distribution	Principal's Office 1	5	EA	7	10+ years	
	Storage/ Closet	Principal's Office 1	140	SF	7	10+ years	
	Walls - Concrete Block	Principal's Office 1	370	SF	7	10+ years	
	Walls - Metal Panel	Principal's Office 1	100	SF	6	10+ years	
	Ceiling - Lay-in	Principal's office 2	139	SF	7	10+ years	
	Doors - Side-lite	Principal's office 2	11	SF	7	10+ years	
	Doors - Transom Window	Principal's office 2	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's office 2	1	EA	7	10+ years	
	Floor - Carpet	Principal's office 2	139	SF	6	2-5 years	
	Lighting - Pendent/Surface	Principal's office 2	2	EA	7	6-10 years	
	Power Distribution	Principal's office 2	10	EA	7	10+ years	Not previously assessed
	Walls - Concrete Block	Principal's office 2	100	SF	7	10+ years	
	Walls - Metal Panel	Principal's office 2	371	SF	6	10+ years	
	Ceiling - Lay-in	Radio room inside library	146	SF	7	10+ years	
	Doors - Side-lite	Radio room inside library	50	SF	7	10+ years	
	Doors - Transom Window	Radio room inside library	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Radio room inside library	1	EA	7	10+ years	
	Floor - Carpet	Radio room inside library	146	SF	7	6-10 years	
	Lighting - Lay-in	Radio room inside library	4	EA	7	6-10 years	
	Power Distribution	Radio room inside library	4	EA	7	10+ years	
	Walls - Concrete Block	Radio room inside library	250	SF	7	10+ years	
	Walls - Metal Panel	Radio room inside library	190	SF	7	10+ years	
	Ceiling - Lay-in	in 117 Library/Media	144	SF	6	10+ years	
	Doors - Side-lite	in 117 Library/Media	11	SF	7	10+ years	
	Doors - Transom Window	in 117 Library/Media	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	in 117 Library/Media	1	EA	6	10+ years	
	Floor - Carpet	in 117 Library/Media	144	SF	7	6-10 years	
	Lighting - Pendent/Surface	in 117 Library/Media	6	EA	7	6-10 years	
	Power Distribution	in 117 Library/Media	6	EA	6	10+ years	
	Walls - Concrete Block	in 117 Library/Media	98	SF	6	10+ years	
	Walls - Metal Panel	in 117 Library/Media	370	SF	6	10+ years	
Auditoriu	ım & Theater						
	Ceiling - Plaster/Drywall	Activity Center	5,751	SF	7	10+ years	
	Doors - Steel Doors incl hw	Activity Center	3	EA	6	10+ years	
	Floor - Carpet	Activity Center	5,751	SF	6	6-10 years	
	Lighting - Lay-in	Activity Center	53	EA	7	6-10 years	
	Lighting - Pendent/Surface	Activity Center	24	EA	6	6-10 years	
	Main Floor Seating	Activity Center	245	EA	7	10+ years	
	Sound System	Activity Center	1	EA	7	6-10 years	
	Stage Lift	Activity Center	1	EA	7	10+ years	
			1	-/ \	'	ior yours	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage Lighting System	Activity Center	1	EA	7	6-10 years	
	Walls - Concrete Block	Activity Center	2,317	SF	6	10+ years	
	Walls - Plaster/Drywall	Activity Center	425	SF	6	10+ years	
Symnasi							
	Bleacher Seating	2nd Floor	60	EA	7	10+ years	Not previously assessed
	Ceiling - Exposed	2nd Floor	5,334	SF	7	10+ years	Max occupancy sign not posted
	Ceiling - Plaster/Drywall	2nd Floor	170	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	8	EA	6	10+ years	
	Floor - Tile	2nd Floor	170	SF	7	10+ years	
	Floor - Wood	2nd Floor	5,334	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	2nd Floor	32	EA	7	6-10 years	
	Scoreboards	2nd Floor	1	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	280	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	5,838	SF	6	10+ years	
Kitchen							
	Ceiling - Splined	1st Floor	1,480	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,480	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	39	EA	7	10+ years	
	Storage/ Closet	1st Floor	340	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,720	SF	6	10+ years	
ibrary							
,	Casework	117 Library/Media Center	120	LF	6	10+ years	
	Ceiling - Lay-in	117 Library/Media Center	3,470	SF	6	10+ years	
	Doors - Side-lite	117 Library/Media Center	112	SF	7	10+ years	
	Doors - Transom Window	117 Library/Media Center	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	117 Library/Media Center	3	EA	5	10+ years	
	Floor - Carpet	117 Library/Media Center	3,470	SF	7	6-10 years	
	Lighting - Pendent/Surface	117 Library/Media Center	119	EA	6	6-10 years	
	Storage/ Closet	117 Library/Media Center	744	SF	7	10+ years	
	Walls - Concrete Block	117 Library/Media Center	724	SF	7	10+ years	
	Walls - Metal Panel	117 Library/Media Center	468	SF	7	10+ years	
	Walls - Plaster/Drywall	117 Library/Media Center	1,060	SF	7	10+ years	
			1,000	0.	•	lot youro	
ocker/S	hower Room						
	Accessories	1st Floor - Natatorium	1,270	SF	7	10+ years	
	Benches, ped mounted	1st Floor - Natatorium	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Natatorium	1,250	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Natatorium	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor - Natatorium	1	EA	6	10+ years	-



Catego	ory : Room		В	uilding	: Main		
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor - Natatorium	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Natatorium	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Natatorium	1,270	SF	6	10+ years	
	Floor Drain	1st Floor - Natatorium	7	EA	7	10+ years	
	Hand Dryer	1st Floor - Natatorium	9	EA	7	6-10 years	
	Lavatory	1st Floor - Natatorium	2	EA	6	10+ years	
	Lighting - Lay-in	1st Floor - Natatorium	17	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Natatorium	1	EA	7	6-10 years	
	Partitions	1st Floor - Natatorium	4	EA	7	10+ years	
	Partitions	1st Floor - Natatorium	18	EA	5	10+ years	
	Showers	1st Floor - Natatorium	11	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor - Natatorium	52	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Natatorium	2,200	SF	6	10+ years	
	Water Closet	1st Floor - Natatorium	4	EA	6	10+ years	
	Accessories	1st floor natatorium	1,270	SF	7	6-10 years	
	Benches, ped mounted	1st floor natatorium	20	LF	6	10+ years	
	Doors - Steel Doors incl hw	1st floor natatorium	1	EA	7	10+ years	
	Doors - Transom Window	1st floor natatorium	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor natatorium	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor natatorium	1,265	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor natatorium	5	SF	5	0-1 year	Damaged tiles
	Floor Drain	1st floor natatorium	7	ĒA	7	10+ years	
	Lavatory	1st floor natatorium	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor natatorium	14	EA	7	10+ years	
	Lighting - Lay-in	1st floor natatorium	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st floor natatorium	-	EA	5	1-2 years	Missing cover
	Partitions	1st floor natatorium	2	EA	7	10+ years	
	Showers	1st floor natatorium	8	EA	7	10+ years	
	Student Lockers - One Tier	1st floor natatorium	38	EA	7	10+ years	
	Urinals	1st floor natatorium	2	EA	7	10+ years	
	Walls - Concrete Block	1st floor natatorium	2,050	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st floor natatorium	150	SF	7	10+ years	
	Water Closet	1st floor natatorium	2	EA	7	6-10 years	
	Accessories	2nd Floor	519	SF	7	6-10 years	
	Benches, ped mounted	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	519	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	89	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	430	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	
		211011001	2	LA	0	0-10 years	



Category : Room			Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2nd Floor	1	EA	7	10+ years			
	Student Lockers - One Tier	2nd Floor	30	EA	6	10+ years			
	Student Lockers - One Tier	2nd Floor	3	EA	5	1-2 years	damaged		
	Urinals	2nd Floor	1	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	1,070	SF	7	10+ years			
	Water Closet	2nd Floor	1	EA	7	10+ years			
	Accessories	2nd Floor	530	SF	7	6-10 years			
	Benches, ped mounted	2nd Floor	15	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	530	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	530	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	1	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years			
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years			
	Partitions	2nd Floor	1	EA	7	10+ years			
	Student Lockers - One Tier	2nd Floor	32	EA	7	10+ years			
	Student Lockers - One Tier	2nd Floor	1	EA	5	1-2 years	Broken lock		
	Walls - Concrete Block	2nd Floor	1,275	SF	7	10+ years			
	Water Closet	2nd Floor	1	ĒA	7	10+ years			
						,			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	110 Faculty Lounge	775	SF	6	10+ years	Moved from Classrooms		
	Doors - Side-lite	110 Faculty Lounge	11	SF	7	10+ years	Moved from Classrooms		
	Doors - Transom Window	110 Faculty Lounge	14	SF	7	10+ years	Moved from Classrooms		
	Doors - Wood Doors inclu hw	110 Faculty Lounge	1	EA	7	10+ years	Moved from Classrooms		
	Floor - Tile	110 Faculty Lounge	775	SF	7	10+ years	Moved from Classrooms		
	Lighting - Pendent/Surface	110 Faculty Lounge	22	ĒA	7	6-10 years	Moved from Classrooms		
	Walls - Concrete Block	110 Faculty Lounge	946	SF	7	10+ years	Moved from Classrooms		
	Walls - Metal Panel	110 Faculty Lounge	146	SF	7	10+ years	Moved from Classrooms		
	Ceiling - Lay-in	1st Floor East - Commons	2,080	SF	6	10+ years	No occupancy signage		
	Floor - Tile	1st Floor East - Commons	2,070	SF	6	10+ years	no coupancy signage		
	Floor - Tile	1st Floor East - Commons	10	SF	5	1-2 years	Damaged tiles		
	Lighting - Lay-in	1st Floor East - Commons	36	EA	7	6-10 years	Damagea meo		
	Serving Line	1st Floor East - Commons	20	LF	6	10+ years			
	Walls - Concrete Block	1st Floor East - Commons	580	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor West - Commons	1,960	SF	6	10+ years	No occupancy		
	Ceiling - Plaster/Drywall	1st Floor West - Commons	1,900	SF	6	10+ years	No occupancy		
	Floor - Tile	1st Floor West - Commons	2,070	SF	6	•			
	Floor - Tile Floor - Tile		2,070	SF	-	10+ years	Damaged tiles		
		1st Floor West - Commons		EA	4 7	0-1 year	Damaged tiles		
	Lighting - Lay-in	1st Floor West - Commons	36		-	6-10 years			
	Serving Line	1st Floor West - Commons	20	LF	6	10+ years			
	Walls - Concrete Block	1st Floor West - Commons	580	SF	6	10+ years			



Catego	ry : Room		В	uilding	: Main		
C	How True	Location	Overstitue		Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
MDF ID	F						
	Doors - Steel Doors incl hw	Inside Weight Room	1	EA	7	10+ years	
	Finishes	Inside Weight Room	185	SF	7	10+ years	
	Other Cooling Unit	Inside Weight Room	1	EA	7	6-10 years	CRAC Unit
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Janitor's Closet	1st Floor	27	SF	5	10+ years	
	Storage Room	1st Floor	305	SF	7	10+ years	
	Vaults	1st Floor	80	SF	7	10+ years	
	Janitor's Closet	2nd Floor	32	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	210	SF	7	10+ years	
	Storage Room	2nd Floor	220	SF	7	10+ years	
	Storage Room	2nd Floor	246	SF	7	10+ years	
	Boiler Room	Basement	1,300	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	145	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	135	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	350	SF	5	10+ years	
	Storage Room	Basement	400	SF	5	10+ years	
	Storage Room	Basement	217	SF	5	10+ years	
	Storage Room	Basement	8	SF	5	10+ years	
	Storage Room	Basement	450	SF	5	10+ years	
	Storage Room	Basement	217	SF	5	10+ years	
2001 & N	atatorium						
	Accessories	Pool	4,226	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Pool	4,226	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Pool	6	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Pool	4,222	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Pool	4	SF	4	0-1 year	Chipped
	Lighting - Lay-in	Pool	30	EA	7	10+ years	
	Pool Basin	Pool	1,200	SF	6	10+ years	
	Pool Deck	Pool	3,026	SF	6	10+ years	
	Walls - Concrete Block	Pool	1,727	SF	7	10+ years	
rep Ro	om						
-	Casework	221A	12	LF	6	10+ years	
	Ceiling - Lay-in	221A	220	SF	7	10+ years	
	Doors - Wood Doors inclu hw	221A	2	EA	7	10+ years	
	Floor - Tile	221A	220	SF	7	10+ years	
	Lighting - Lay-in	221A	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	221A	456	SF	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Work Sink 221A EΑ 10+ vears 7 1 241A 12 LF 6 Casework 10+ years Ceiling - Lav-in 241A 220 SF 7 10+ years Doors - Steel Doors incl hw 2 ΕA 7 241A 10+ years SF 7 Floor - Tile/Sheet 241A 220 10+ years ΕA 7 Lighting - Lay-in 241A 4 6-10 years Walls - Plaster/Drywall 241A SF 7 10+ years 456 Work Sink 241A 1 EΑ 7 10+ years Restroom SF 7 6-10 years Accessories 1st Floor - south center (Women) 332 Ceiling - Lay-in 1st Floor - south center (Women) 332 SF 6 10+ years 1st Floor - south center (Women) SF Doors - Transom Window 6 10+ vears 10 Doors - Wood Doors inclu hw 1st Floor - south center (Women) 1 EΑ 6 10+ years 332 SF 6 Floor - Tile Ceramic/ Porcelain 1st Floor - south center (Women) 10+ vears Floor Drain 1st Floor - south center (Women) 1 FΑ 7 10+ years 7 Hand Dryer 1st Floor - south center (Women) 1 FΑ 6-10 years 6 Lavatory 1st Floor - south center (Women) EΑ 6 10+ years 5 7 Lighting - Lay-in 1st Floor - south center (Women) EΑ 6-10 years Partitions 1st Floor - south center (Women) 7 ΕA 7 10+ years SF Walls - Concrete Block 1st Floor - south center (Women) 850 6 10+ years Water Closet 1st Floor - south center (Women) 7 ΕA 7 10+ vears SF Accessories 1st Floor - south east 206 7 6-10 years Ceiling - Plaster/Drvwall 1st Floor - south east 206 SF 6 10+ vears Floor - Tile Ceramic/ Porcelain 1st Floor - south east 205 SF 6 10+ years Floor - Tile Ceramic/ Porcelain SF 4 1-2 years 1st Floor - south east 1 Damaged or missing tiles 7 Floor Drain 1st Floor - south east 1 EΑ 10+ years Hand Drver 7 1st Floor - south east 1 EΑ 6-10 years 5 FΑ Lavatory 1st Floor - south east 6 10+ years 3 7 Lighting - Lay-in 1st Floor - south east EΑ 6-10 years Partitions 1st Floor - south east 5 EΑ 7 10+ years SF Walls - Concrete Block 1st Floor - south east 650 6 10+ vears Water Closet 1st Floor - south east 5 EΑ 6 10+ years Accessories 1st Floor - south west 206 SF 7 6-10 years Ceiling - Plaster/Drywall 206 SF 7 1st Floor - south west 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st Floor - south west 206 10+ years Floor Drain 1st Floor - south west FΑ 7 10+ years 1 Hand Dryer 2 FΑ 7 1st Floor - south west 6-10 years Lavatorv 1st Floor - south west 4 FΑ 6 10+ vears 3 Lighting - Lay-in ΕA 7 10+ years 1st Floor - south west Partitions 5 ΕA 7 1st Floor - south west 10+ years 650 SF Walls - Concrete Block 1st Floor - south west 7 10+ years Water Closet 1st Floor - south west 5 ΕA 7 10+ years SF 7 Accessories 1st Floor SW Boys Toilet Room 337 6-10 years



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drvwall 1st Floor SW Boys Toilet Room 337 SF 10+ vears 7 Floor - Tile Ceramic/ Porcelain 1st Floor SW Boys Toilet Room 337 SF 6 10+ years Floor Drain 1st Floor SW Boys Toilet Room 1 FΑ 7 10+ years Hand Drver 1st Floor SW Boys Toilet Room 2 7 EΑ 6-10 years 2 Lavatory 1st Floor SW Boys Toilet Room EΑ 6 10+ years 2 1st Floor SW Boys Toilet Room 7 Lighting - Lay-in EΑ 6-10 years Partitions 1st Floor SW Boys Toilet Room 2 ΕA 7 10+ years 1st Floor SW Boys Toilet Room 5 Urinals ΕA 7 10+ years SF Walls - Concrete Block 1st Floor SW Boys Toilet Room 468 7 10+ years ΕA Water Closet 1st Floor SW Boys Toilet Room 2 7 10+ vears Accessories 1st floor boys SE 206 SF 7 6-10 years Ceiling - Plaster/Drywall 1st floor boys SE 206 SF 7 10+ years Doors - Wood Doors inclu hw 1st floor boys SE ΕA 7 1 10+ years SF 7 Floor - Tile Ceramic/ Porcelain 1st floor boys SE 206 10+ years Floor Drain ΕA 7 1st floor boys SE 1 10+ years FΑ 7 Hand Dryer 1st floor boys SE 1 6-10 years 3 7 Lavatory 1st floor boys SE ΕA 10+ vears Lighting - Lay-in 1st floor boys SE 2 ΕA 6 10+ years Partitions 1st floor boys SE 1 ΕA 7 10+ vears Partitions 1st floor boys SE 1 ΕA 5 0-1 year Missing door Urinals 1st floor boys SE 6 ΕA 7 10+ years 1st floor boys SE SF 7 10+ years Walls - Concrete Block 650 2 ΕA 7 Water Closet 1st floor boys SE 10+ years SF 7 Accessories 1st floor south center boys 230 6-10 years 1st floor south center boys 230 SF 7 Ceiling - Splined 10+ years Doors - Steel Doors incl hw 1st floor south center boys 1 ΕA 7 10+ vears SF Floor - Tile Ceramic/ Porcelain 1st floor south center boys 230 7 10+ years Floor Drain 1st floor south center boys ΕA 7 1 10+ years Hand Dryer 1st floor south center boys 1 EΑ 7 6-10 years Lavatory 1st floor south center boys 4 ΕA 7 10+ years Lighting - Lay-in 4 ΕA 7 10+ vears 1st floor south center boys Partitions 3 ΕA 7 10+ vears 1st floor south center boys FΑ 7 Urinals 4 1st floor south center boys 10+ years Walls - Concrete Block 1st floor south center boys 742 SF 6 10+ vears 3 7 Water Closet 1st floor south center boys EΑ 6-10 years SF 7 Accessories 2nd Floor - SE - Girls Toilet 206 6-10 years Ceiling - Plaster/Drywall SF 2nd Floor - SE - Girls Toilet 206 7 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor - SE - Girls Toilet SF 206 6 10+ years Floor Drain 2nd Floor - SE - Girls Toilet 1 EΑ 7 10+ years Hand Drver 2nd Floor - SE - Girls Toilet 1 ΕA 7 6-10 years Lavatory 2nd Floor - SE - Girls Toilet 6 ΕA 6 10+ years 2nd Floor - SE - Girls Toilet 3 FΑ 6 Lighting - Lay-in 6-10 years Partitions 2nd Floor - SE - Girls Toilet 5 EΑ 7 10+ years 2nd Floor - SE - Girls Toilet SF Walls - Concrete Block 650 6 10+ years



Catego	ry : Room		В	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd Floor - SE - Girls Toilet	5	EA	7	10+ years	
	Water Closet	2nd Floor - SE - Girls Toilet	1	EA	4	0-1 year	Out of order
	Accessories	2nd Floor Men's Faculty (between locker rooms)	132	SF	7	6-10 years	
	Benches	2nd Floor Men's Faculty (between locker rooms)	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Men's Faculty (between locker rooms)	132	SF	7	10+ years	
	Doors - Transom Window	2nd Floor Men's Faculty (between locker rooms)	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Men's Faculty (between locker rooms)	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Men's Faculty (between locker rooms)	132	SF	7	10+ years	
	Floor Drain	2nd Floor Men's Faculty (between locker rooms)	2	EA	7	10+ years	
	Hand Dryer	2nd Floor Men's Faculty (between locker rooms)	1	EA	7	6-10 years	
	Lavatory	2nd Floor Men's Faculty (between locker rooms)	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor Men's Faculty (between locker rooms)	2	EA	7	6-10 years	
	Showers	2nd Floor Men's Faculty (between locker rooms)	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Men's Faculty (between locker rooms)	300	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Men's Faculty (between locker rooms)	124	SF	7	10+ years	
	Water Closet	2nd Floor Men's Faculty (between locker rooms)	1	EA	7	10+ years	
	Accessories	2nd Floor SE Corner Boys Toilet Room	184	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor SE Corner Boys Toilet Room	184	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor SE Corner Boys Toilet Room	184	SF	7	10+ years	
	Floor Drain	2nd Floor SE Corner Boys Toilet Room	1	EA	7	10+ years	
	Hand Dryer	2nd Floor SE Corner Boys Toilet Room	1	EA	7	6-10 years	
	Lavatory	2nd Floor SE Corner Boys Toilet Room	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor SE Corner Boys Toilet Room	2	EA	6	6-10 years	



Catego	ery : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor SE Corner Boys Toilet	2	EA	7	10+ years	
		Room					
	Urinals	2nd Floor SE Corner Boys Toilet	6	EA	6	10+ years	
		Room					
	Walls - Concrete Block	2nd Floor SE Corner Boys Toilet	540	SF	6	10+ years	
		Room					
	Water Closet	2nd Floor SE Corner Boys Toilet	2	EA	6	10+ years	
		Room					
	Accessories	2nd Floor SW Boys Toilet Room	337	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor SW Boys Toilet Room	337	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor SW Boys Toilet Room	337	SF	6	10+ years	
	Floor Drain	2nd Floor SW Boys Toilet Room	1	EA	7	10+ years	
	Hand Dryer	2nd Floor SW Boys Toilet Room	2	EA	7	6-10 years	
	Lavatory	2nd Floor SW Boys Toilet Room	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor SW Boys Toilet Room	4	EA	7	6-10 years	
	Partitions	2nd Floor SW Boys Toilet Room	2	EA	7	10+ years	
	Urinals	2nd Floor SW Boys Toilet Room	5	EA	7	10+ years	Qty 5
	Walls - Concrete Block	2nd Floor SW Boys Toilet Room	468	SF	7	10+ years	
	Water Closet	2nd Floor SW Boys Toilet Room	2	EA	7	10+ years	
	Accessories	2nd Floor South Center Boys Toilet	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor South Center Boys Toilet	230	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor South Center Boys Toilet	230	SF	6	10+ years	
	Floor Drain	2nd Floor South Center Boys Toilet	1	EA	7	10+ years	
	Hand Dryer	2nd Floor South Center Boys Toilet	1	EA	7	6-10 years	
	Lavatory	2nd Floor South Center Boys Toilet	4	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor South Center Boys Toilet	4	EA	7	6-10 years	
	Partitions	2nd Floor South Center Boys Toilet	2	EA	7	10+ years	
	Urinals	2nd Floor South Center Boys Toilet	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor South Center Boys Toilet	742	SF	6	10+ years	
	Water Closet	2nd Floor South Center Boys Toilet	2	EA	7	10+ years	
	Accessories	2nd Floor South Center Girls Toilet	228	SF	7	6-10 years	
	Accessories	Room	220	0	1	0-10 years	
	Ceiling - Plaster/Drywall	2nd Floor South Center Girls Toilet	228	SF	6	10+ years	
	Celling - Flastel/Drywall	Room	220	35	0	TOT years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor South Center Girls Toilet	228	SF	6	10+ years	
	FIGUR - The Ceramic/ Forcelain	Room	220	35	0	TOT years	
	Floor Drain	2nd Floor South Center Girls Toilet	1	EA	7	10	
	Floor Drain	Room	I	EA	7	10+ years	
	Hand Druge	2nd Floor South Center Girls Toilet	1		7	6 10 vooro	
	Hand Dryer		1	EA	7	6-10 years	
	L oveten/	Room	4	Γ^	~	10,	
	Lavatory	2nd Floor South Center Girls Toilet	4	EA	6	10+ years	
	Linkting Lowin	Room		Γ^	7	0 10	
	Lighting - Lay-in	2nd Floor South Center Girls Toilet	4	EA	7	6-10 years	
		Room					



Catego	ry : Room		В	uilding	: Main		
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor South Center Girls Toilet Room	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor South Center Girls Toilet Room	993	SF	6	10+ years	
	Water Closet	2nd Floor South Center Girls Toilet Room	6	EA	7	10+ years	
	Accessories	2nd Floor Women's Faculty (between locker rooms)	132	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Women's Faculty (between locker rooms)	132	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor Women's Faculty (between locker rooms)	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor Women's Faculty (between locker rooms)	9	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Women's Faculty (between locker rooms)	132	SF	6	10+ years	
	Floor Drain	2nd Floor Women's Faculty (between locker rooms)	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Women's Faculty (between locker rooms)	1	EA	7	6-10 years	
	Lavatory	2nd Floor Women's Faculty (between locker rooms)	1	EA	6	10+ years	
	Lavatory	2nd Floor Women's Faculty (between locker rooms)	1	EA	5	1-2 years	Out of order
	Lighting - Lay-in	2nd Floor Women's Faculty (between locker rooms)	2	EA	7	6-10 years	
	Partitions	2nd Floor Women's Faculty (between locker rooms)	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Women's Faculty (between locker rooms)	398	SF	7	10+ years	
	Water Closet	2nd Floor Women's Faculty (between locker rooms)	2	EA	7	10+ years	
	Accessories	2nd floor SW Girls Toilet	217	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor SW Girls Toilet	217	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor SW Girls Toilet	217	SF	7	10+ years	
	Floor Drain	2nd floor SW Girls Toilet	1	EA	7	10+ years	
	Hand Dryer	2nd floor SW Girls Toilet	2	EA	7	6-10 years	
	Lavatory	2nd floor SW Girls Toilet	4	EA	7	10+ years	Qty 4
	Lighting - Lay-in	2nd floor SW Girls Toilet	4	EA	7	6-10 years	
	Partitions	2nd floor SW Girls Toilet	5	EA	7	10+ years	
	Walls - Concrete Block	2nd floor SW Girls Toilet	484	SF	7	10+ years	
			-			,	Oth (E
	Water Closet	2nd floor SW Girls Toilet	5	EA	7	10+ years	Qty 5
	Accessories	Inside 143	110	SF	7	6-10 years	
	Ceiling - Lay-in	Inside 143	110	SF	7	10+ years	



Catego	ry : Room		Building : Main						
	,			J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Steel Doors incl hw	Inside 143	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Inside 143	110	SF	7	10+ years			
	Floor Drain	Inside 143	1	EA	7	10+ years			
	Lavatory	Inside 143	1	EA	7	10+ years			
	Lighting - Lay-in	Inside 143	2	EA	7	6-10 years			
	Walls - Concrete Block	Inside 143	200	SF	7	10+ years			
	Walls - Plaster/Drywall	Inside 143	220	SF	7	10+ years			
	Water Closet	Inside 143	1	EA	7	10+ years			
	Accessories	Principals Washroom	16	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Principals Washroom	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Principals Washroom	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Principals Washroom	16	SF	7	10+ years			
	Floor Drain	Principals Washroom	1	EA	7	10+ years			
	Lavatory	Principals Washroom	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Principals Washroom	1	EA	7	10+ years			
	Walls - Plaster/Drywall	Principals Washroom	139	SF	6	10+ years			
	Water Closet	Principals Washroom	1	EA	7	10+ years			
	Accessories	Staff restroom inside main office	16	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Staff restroom inside main office	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Staff restroom inside main office	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Staff restroom inside main office	16	SF	6	10+ years			
	Lavatory	Staff restroom inside main office	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Staff restroom inside main office	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Staff restroom inside main office	60	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	Staff restroom inside main office	79	SF	6	10+ years			
	Water Closet	Staff restroom inside main office	1	EA	6	10+ years			
	Accessories	in Engineer's Office	50	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	in Engineer's Office	50	SF	7	10+ years			
	Doors - Wood Doors inclu hw	in Engineer's Office	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	in Engineer's Office	50	SF	7	10+ years			
	Lavatory	in Engineer's Office	1	EA	7	10+ years	N #:		
	Lighting - Pendent/Surface	in Engineer's Office	1	EA	5	1-2 years	Missing cover		
	Walls - Plaster/Drywall	in Engineer's Office	280	SF	7	10+ years			
	Water Closet	in Engineer's Office	1	EA	7	10+ years			

Category : Classroom

Building : Main

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #109 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	1,830	SF	6	10+ years	
Doors - Transom Window	1st Floor	9	SF	6	10+ years	
Doors - Transom Window	1st Floor	9	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Tile	1st Floor	1,830	SF	7	10+ years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 1st Floor 82 ΕA 6-10 vears 7 Marker Board 1st Floor 8 LF 6 6-10 years Storage/ Closet 1st Floor 200 SF 5 10+ years Storage/ Closet 595 SF 5 1st Floor 10+ years 7 Student Lockers - One Tier 1st Floor 6 EΑ 10+ years Walls - Concrete Block SF 7 1st Floor 1,950 10+ years Walls - Plaster/Drywall 183 SF 7 1st Floor 10+ years Classroom #121 (Computer Lab) Ceiling - Lay-in 1st Floor SF 840 6 10+ years Doors - Side-lite 1st Floor SF 11 6 10+ years Doors - Transom Window 1st Floor 14 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 6 10+ years 1 Floor - Epoxy/ Painted 1st Floor 840 SF 7 6-10 years Lighting - Pendent/Surface 7 1st Floor 29 ΕA 6-10 years Marker Board 1st Floor 15 LF 6 6-10 years SF Walls - Concrete Block 1st Floor 218 6 10+ years Walls - Metal Panel 1st Floor 673 SF 6 10+ years Classroom #122 (Art Room) 977 Ceiling - Lay-in 1st Floor SF 7 10+ years LF Chalk Board 1st Floor 4 2-5 years 4 Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years SF Floor - Carpet 1st Floor 977 4 1-2 years Worn and stained throughout and not appropriate for an art room Lighting - Pendent/Surface ΕA 7 1st Floor 31 6-10 years LF Marker Board 1st Floor 15 6 6-10 years SF 7 Walls - Concrete Block 1st Floor 218 10+ years Walls - Metal Panel 1st Floor 740 SF 7 10+ years Classroom #123 (Art Room) Ceiling - Lay-in SF 1st Floor 795 6 10+ years Doors - Side-lite 1st Floor SF 6 10+ years 11 SF Doors - Transom Window 1st Floor 14 6 10+ years Doors - Wood Doors inclu hw 1st Floor EΑ 6 10+ years 1 Floor - Epoxy/ Painted 1st Floor 795 SF 7 6-10 years Lighting - Pendent/Surface 1st Floor 29 ΕA 7 6-10 years Walls - Metal Panel 1st Floor 908 SF 6 10+ years Classroom #124 (Faculty Lounge) 1st Floor LF Casework 13 7 10+ years Ceiling - Lay-in 1st Floor 650 SF 6 10+ years Chalk Board LF 1st Floor 6 4 2-5 years



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Side-lite 1st Floor SF 10+ vears 11 7 Doors - Transom Window 1st Floor SF 7 14 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years Floor - Carpet SF 6 1st Floor 650 6-10 years 7 Lighting - Pendent/Surface 1st Floor 18 EΑ 6-10 years Walls - Metal Panel SF 1st Floor 867 6 10+ years Work Sink ΕA 7 1st Floor 1 10+ years Classroom #130 (Regular Classroom) Ceiling - Lay-in 1st Floor 830 SF 7 10+ years Doors - Side-lite 1st Floor SF 7 11 10+ years Doors - Transom Window 1st Floor 14 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor ΕA 7 10+ years 1 Floor - Carpet 1st Floor 830 SF 6 2-5 years Lighting - Pendent/Surface ΕA 7 6-10 vears 1st Floor 29 Marker Board 1st Floor 15 LF 6 6-10 years SF Walls - Concrete Block 1st Floor 470 7 10+ years Walls - Metal Panel 1st Floor 467 SF 7 10+ years Classroom #131 (Regular Classroom) Ceiling - Lay-in 1st Floor 786 SF 6 10+ years Doors - Side-lite SF 1st Floor 6 10+ years 11 SF Doors - Transom Window 1st Floor 14 6 10+ years Doors - Wood Doors inclu hw 6 10+ years 1st Floor 1 EΑ Floor - Carpet 1st Floor 786 SF 6 2-5 years Lighting - Pendent/Surface 1st Floor 29 ΕA 7 6-10 years LF Marker Board 1st Floor 18 7 6-10 years SF Walls - Metal Panel 1st Floor 933 6 10+ years Classroom #132 (Regular Classroom) Ceiling - Lay-in 1st Floor SF 6 795 10+ years Doors - Side-lite SF 1st Floor 11 7 10+ years Doors - Transom Window 1st Floor 14 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years SF Floor - Carpet 1st Floor 795 6 2-5 years Lighting - Pendent/Surface 1st Floor 29 EΑ 7 6-10 years Marker Board LF 1st Floor 15 6 6-10 years Walls - Metal Panel 1st Floor 910 SF 6 10+ years Classroom #133 (Regular Classroom) Ceiling - Lay-in 1st Floor 10+ years 834 SF 6 Doors - Side-lite 1st Floor 11 SF 7 10+ years Doors - Transom Window SF 1st Floor 14 7 10+ years



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw 1st Floor EΑ 10+ vears 7 1 1st Floor 834 SF 6 2-5 vears Floor - Carpet Lighting - Pendent/Surface 1st Floor 28 EΑ 6 6-10 years Marker Board 15 LF 7 1st Floor 6-10 years SF Walls - Concrete Block 1st Floor 218 6 10+ years SF Walls - Metal Panel 1st Floor 668 6 10+ years Classroom #134 (Regular Classroom) Ceiling - Lay-in SF 1st Floor 839 6 10+ vears Doors - Side-lite SF 1st Floor 11 6 10+ years Doors - Transom Window SF 6 1st Floor 14 10+ years Doors - Wood Doors inclu hw 1st Floor 1 ΕA 6 10+ years Floor - Carpet 1st Floor SF 6 6-10 years 839 Lighting - Pendent/Surface 1st Floor 29 ΕA 7 6-10 years Marker Board 15 LF 6 1st Floor 6-10 years Walls - Concrete Block 1st Floor 218 SF 6 10+ years SF Walls - Metal Panel 1st Floor 669 6 10+ years Classroom #142 (Other Instructional Use) Ceiling - Lay-in 1st Floor 977 SF 7 10+ years SF Doors - Side-lite 1st Floor 11 7 10+ years SF Doors - Transom Window 1st Floor 14 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 7 10+ years 977 SF 7 6-10 years Floor - Carpet 1st Floor Lighting - Pendent/Surface 1st Floor 33 EΑ 7 6-10 years Walls - Concrete Block 1st Floor SF 7 236 10+ years SF Walls - Metal Panel 1st Floor 731 7 10+ years Classroom #144 (Other Instructional Use) Ceiling - Lay-in 1st Floor SF 674 7 10+ years Doors - Side-lite SF 7 1st Floor 12 10+ years Doors - Transom Window 75 SF 7 1st Floor 10+ years Doors - Wood Doors inclu hw EΑ 6 1st Floor 1 10+ years SF Floor - Carpet 1st Floor 674 7 6-10 years Lighting - Pendent/Surface ΕA 1st Floor 24 7 10+ years LF Marker Board 1st Floor 4 7 6-10 years Walls - Metal Panel 731 SF 1st Floor 6 10+ years Classroom #150 (Regular Classroom) Casework 1st Floor 12 LF 7 10+ vears SF Ceiling - Lay-in 1st Floor 831 6 10+ years Doors - Side-lite 1st Floor 11 SF 7 10+ years Doors - Transom Window SF 7 1st Floor 14 10+ years



Catego	ry : Classroom		В	Building : Main					
_						Recommend	_		
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Carpet	1st Floor	831	SF	6	6-10 years			
	Lighting - Lay-in	1st Floor	28	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Student Lockers - One Tier	1st Floor	25	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	545	SF	6	10+ years			
	Walls - Metal Panel	1st Floor	320	SF	6	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
lassroo	om #151 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	811	SF	7	10+ years			
	Chalk Board	1st Floor	6	LF	4	2-5 years			
	Doors - Side-lite	1st Floor	11	SF	7	10+ years			
	Doors - Transom Window	1st Floor	14	SF	7	10+ years			
		1st Floor							
	Doors - Wood Doors inclu hw		1	EA	6	10+ years			
	Floor - Carpet	1st Floor	811	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Walls - Metal Panel	1st Floor	768	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	95	SF	6	10+ years			
lassroo	om #152 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	811	SF	7	10+ years			
	Doors - Side-lite	1st Floor	11	SF	7	10+ years			
	Doors - Transom Window	1st Floor	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Carpet	1st Floor	811	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	29	EA	7				
						6-10 years			
	Walls - Metal Panel	1st Floor	742	SF	6	10+ years			
lassroo	om #153 (Regular Classroom)								
	Ceiling - Lay-in	1st Floor	834	SF	6	10+ years			
	Doors - Side-lite	1st Floor	11	SF	7	10+ years			
	Doors - Transom Window	1st Floor	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Carpet	1st Floor	834	SF	6	2-5 years			
	Lighting - Lay-in	1st Floor	28	EA	7	6-10 years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	1st Floor	222	SF	6	10+ years			
	Walls - Metal Panel	1st Floor	511	SF	6	10+ years			
laceror	om #154 (Regular Classroom)								
1922100	Ceiling - Lay-in	1st Floor	833	SF	7	10+ years			



Building : Main Category : Classroom Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Doors - Side-lite 1st Floor SF 10+ vears 11 7 Doors - Transom Window 1st Floor SF 7 14 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years Floor - Carpet SF 7 1st Floor 833 6-10 years Lighting - Pendent/Surface 1st Floor 29 EΑ 7 6-10 years LF Marker Board 15 1st Floor 6 6-10 years Walls - Concrete Block 1st Floor 223 SF 6 10+ years SF Walls - Metal Panel 1st Floor 460 6 10+ years Classroom #201 (Regular Classroom) Ceiling - Lay-in 2nd Floor 918 SF 6 10+ years Doors - Side-lite 2nd Floor 11 SF 6 10+ years Doors - Transom Window 2nd Floor SF 7 10+ years 14 Not previously assessed Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 6 10+ years 2nd Floor 918 SF 6 6-10 vears Floor - Carpet Lighting - Lay-in 2nd Floor 33 FΑ 7 6-10 years 2 Lighting - Lay-in 2nd Floor FΑ 5 6-10 years Damaged or loose covers LF Marker Board 2nd Floor 10 6 6-10 years SF Walls - Concrete Block 2nd Floor 521 6 10+ years Walls - Metal Panel 2nd Floor 791 SF 6 10+ years Classroom #202 (Regular Classroom) Ceiling - Lay-in 2nd Floor SF 918 6 10+ years Doors - Side-lite 2nd Floor SF 7 11 10+ years Doors - Transom Window 2nd Floor 14 SF 7 10+ years Not previously assessed Doors - Wood Doors inclu hw 2nd Floor ΕA 7 10+ years 1 Floor - Carpet 2nd Floor 918 SF 6 2-5 years 2nd Floor ΕA 7 6-10 vears Lighting - Lay-in 35 Marker Board 2nd Floor 10 LF 6 6-10 years SF Walls - Metal Panel 2nd Floor 791 6 10+ years Classroom #203 (Vacant) Ceiling - Lav-in 2nd Floor 918 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 6 10+ years SF Floor - Tile 2nd Floor 918 6 10+ years Lighting - Lav-in 2nd Floor 35 EΑ 7 6-10 years Marker Board LF 2nd Floor 10 6 6-10 years Walls - Concrete Block 2nd Floor 521 SF 6 10+ years SF Walls - Metal Panel 2nd Floor 791 6 10+ years Classroom #204 (Regular Classroom) Ceiling - Lay-in 2nd Floor 918 SF 6 10+ years Doors - Side-lite 2nd Floor SF 7 11 10+ years



Catego	ry : Classroom		B	Building : Main			
5	-			_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	918	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	35	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	35	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	521	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	791	SF	6	10+ years	
Classroo	om #205 (Other Instructional Use)						
	Ceiling - Lay-in	2nd Floor	1,010	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	0
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Floor - Tile	2nd Floor	1,020	SF	7	10+ years	1 5
	Lighting - Lay-in	2nd Floor	46	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	6	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	500	SF	7	10+ vears	
	Walls - Plaster/Drywall	2nd Floor	320	SF	7	10+ years	
Classroo	m #207 (Store Room)						
	Ceiling - Lay-in	2nd Floor	971	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	971	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	32	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	3	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,284	SF	6	10+ years	
	Work Sink	2nd Floor	· 1	EA	5	1-2 years	Loose fixture
Classroo	m #208 - Band Room (Band Room)						
	Ceiling - Lay-in	2nd Floor	2,325	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	5	SF	5	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	2,326	SF	6	10+ years	
	Floor - Tile	2nd Floor	4	SF	5	0-1 year	Chipped
	Instrument Storage Casework	2nd Floor	20	LF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	84	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	5	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	2,080	SF	6	10+ years	



Category : Classroom			В	uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroc	om #209 (Other Instructional Use)								
	Ceiling - Lay-in	2nd Floor	767	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	Not previously assessed		
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Carpet	2nd Floor	767	SF	5	1-2 years	Rippled, torn and damaged throughout		
	Lighting - Lay-in	2nd Floor	31	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years	Not previously assessed		
	Walls - Concrete Block	2nd Floor	422	SF	7	10+ years			
	Walls - Metal Panel	2nd Floor	522	SF	6	10+ years			
Classroc	om #210 (Other Instructional Use)								
	Ceiling - Lay-in	2nd Floor	799	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Not previously assessed		
	Floor - Carpet	2nd Floor	799	SF	6	1-2 years	Stained and worn throughout		
	Lighting - Lay-in	2nd Floor	31	EA	7	6-10 years	Stanica and Worn throughout		
	Marker Board	2nd Floor	13	LF	6	6-10 years			
	Walls - Metal Panel	2nd Floor	413	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	308	SF	6	10+ years			
			500	36	0	TO+ years			
Classroc	om #211 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	865	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Carpet	2nd Floor	865	SF	6	2-5 years			
	Lighting - Pendent/Surface	2nd Floor	35	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	503	SF	6	10+ years			
	Walls - Metal Panel	2nd Floor	203	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	274	SF	6	10+ years			
Classroc	om #213 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	730	SF	4	1-2 years	Worn and stained throughout		
	Lighting - Lay-in	2nd Floor	35	EA	7	6-10 years	wom and stamed throughout		
	Lighting - Lay-III			EA	1	0-10 years			



Category : Classroom		В	Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	891	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	276	SF	6	10+ years	
lassror	om #215 (Office)						
01233100	Ceiling - Lay-in	2nd Floor	625	SF	6	10+ years	
				SF			
	Ceiling - Plaster/Drywall	2nd Floor	250		6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	370	SF	7	10+ years	Locked
	Walls - Concrete Block	2nd Floor	275	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	510	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	253	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroc	m #216 (Other Instructional Use)						
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	773	SF	6	10+ years	
	Chalk Board	2nd Floor	7	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor		SF	6		
	•		773			2-5 years	
	Lighting - Lay-in	2nd Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	28	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	601	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	601	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	m #217 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	764	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	200	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	964	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	304	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	792	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	411	SF	6	10+ years	
Classroc	m #218 (Other Instructional Use)						
	Ceiling - Lay-in	2nd Floor	773	SF	6	10+ years	



Jatego	Category : Classroom			uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	773	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	28	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,202	SF	7	10+ years	
lassroc	m #220 (Exclusively Used by Outside O	rganization)					
	Ceiling - Lay-in	2nd Floor	1,011	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	ĒA	6	10+ years	
	Floor - Carpet	2nd Floor	1,011	SF	4	0-1 year	Torn and stained throughout
	Lighting - Lay-in	2nd Floor	35	ĒA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	276	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	830	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Damaged drywall
	-		-	0.	Ũ	1 _ youro	Damagoa arywan
assroc	om #221 (Science Lab Level 1)						
	Casework	2nd Floor	80	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,220	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,220	SF	7	10+ years	
	Gas Line	2nd Floor	8	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	41	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Science Lab Fume Hood	2nd Floor	1	EA	7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	220	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	478	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
lassroc	om #222 (Other Instructional Use)						
	Ceiling - Lay-in	2nd Floor	976	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor	976	SF	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	6-10 years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	270	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	488	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	7	10+ years	
lassroc	om #223 (Science Lab Level 3)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	961	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	961	SF	7	10+ years	
	Gas Line	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	224	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	540	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
lassroc	om #224 (Office) Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	660	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	660	SF	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Walls - Metal Panel	2nd Floor	623	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	65	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroc	om #227 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,257	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,257	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	30	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	510	SF	7	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	510	SF			
				EA	7 7	10+ years	
	Wireless System	2nd Floor	1	EA	1	10+ years	

Classroom #230 (Other Instructional Use)



Recommend Replacement 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	Comments
10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	Comments
10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	
10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
10+ years 6-10 years 6-10 years 10+ years 10+ years	
6-10 years 6-10 years 10+ years 10+ years	
6-10 years 10+ years 10+ years	
10+ years 10+ years	
10+ years	
10+ vears	
10+ vears	
10+ years	
10+ years	
10+ years	
2-5 years	
6-10 years	
6-10 years	
10+ years	
10+ years	
10+ vears	
	Not previously assessed
•	
10+ years	
10+ vears	
•	
•	
•	
6-10 years 10+ years	
	10+ years 10+ years 10+ years 10+ years 10+ years 2-5 years 6-10 years 6-10 years



Category : Classroom			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	
Classroo	om #234 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	837	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	2nd Floor	837	SF	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	29	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	219	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	460	SF	6	10+ years	
		2110 1 1001	100	0.	Ũ	io: youro	
Classroo	om #241 (Science Lab Level 3)						
	Casework	2nd Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,215	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	22	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	20	SF	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,215	SF	6	10+ years	
	Gas Line	2nd Floor	1,213	EA	7	6-10 years	Not previously assessed
	Lighting - Lay-in	2nd Floor	38	EA	7	6-10 years	Not previously assessed
				LF	6		
	Marker Board	2nd Floor	10			6-10 years	
	Walls - Concrete Block	2nd Floor	220	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	520	SF	6	10+ years	
	Work Sink	2nd Floor	5	EA	7	10+ years	
lassro	om #242 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	965	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Floor - Carpet	2nd Floor	965	SF	6		
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	905 31	EA	6 7	2-5 years 6-10 years	
	Marker Board	2nd Floor 2nd Floor	16		6		
	Warker Board Walls - Concrete Block	2nd Floor 2nd Floor	235	LF SF	-	6-10 years	
					6	10+ years	
	Walls - Metal Panel	2nd Floor	478	SF	6	10+ years	
Classroo	om #243 (Science Lab Level 3)						
	Casework	2nd Floor	13	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	910	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	55	SF	7	10+ years	
	Coming - I laster/Drywall	21011001	55	01	'	TOT years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	965	SF	7	10+ years	
	Gas Line	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	6-10 years	
	Marker Board	2nd Floor	17	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	965	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	224	SF	6	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
Classroo	om #244 (Store Room)						
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	658	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	Not previously assessed
	Floor - Carpet	2nd Floor	658	SF	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	648	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #249B (Art Room)						
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	924	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	924	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	26	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor		EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	290	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	620	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #250 (Store Room)						
	Ceiling - Lay-in	2nd Floor	833	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Floor - Carpet	2nd Floor	833	SF	6	2-5 years	
			633	3F	U	2-0 years	



Category : Classroom Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	29	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	470	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor	306	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #251 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	812	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	15	SF	7	10+ years	
	Floor - Carpet	2nd Floor	812	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	698	SF	6	10+ years	
Classroo	om #252 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Floor - Tile	2nd Floor	795	SF	7	10+ years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	-
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	395	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	280	SF	7	10+ years	
Classroo	m #253 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	807	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	33	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	11	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Floor - Carpet	2nd Floor	840	SF	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	220	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	251	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	7	10+ years	



Building : Main Category : Classroom Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Classroom #254 (Regular Classroom) Ceiling - Lay-in 2nd Floor SF 7 830 10+ years Doors - Side-lite 2nd Floor 10 SF 7 10+ years Doors - Steel Doors incl hw 2nd Floor 1 EΑ 6 10+ years Doors - Transom Window SF 7 10+ years 2nd Floor 14 SF 7 10+ years Floor - Tile 2nd Floor 830 Lighting - Lay-in 2nd Floor 29 FΑ 7 6-10 years LF Marker Board 2nd Floor 15 6 6-10 years SF 7 Walls - Concrete Block 2nd Floor 270 10+ years SF Walls - Metal Panel 2nd Floor 202 7 10+ years Walls - Plaster/Drywall SF 7 2nd Floor 270 10+ years Classroom #Weight Room 1st (Weight) LF Casework 1st Floor 12 7 10+ vears Ceiling - Lay-in SF 1st Floor 1,865 7 10+ years Doors - Side-lite 1st Floor 64 SF 7 10+ years Doors - Transom Window SF 7 1st Floor 46 10+ years Doors - Wood Doors inclu hw ΕA 7 1st Floor 10+ years 4 SF 7 Floor - Sport Flooring 1st Floor 1.380 10+ years Floor - Tile/Sheet 485 SF 7 10+ years 1st Floor Lighting - Lay-in 1st Floor 16 EΑ 7 10+ years Lighting - Lay-in 1st Floor 19 ΕA 7 6-10 years SF Wall Mirrors 1st Floor 420 7 10+ years Walls - Concrete Block SF 7 1st Floor 2,280 10+ years Walls - Metal Panel 1st Floor 420 SF 7 10+ years Work Sink ΕA 7 1st Floor 1 10+ years **Category : Interior Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Corridor SF Ceiling - Lay-in 1st Floor Corridor 14.951 6 10+ years SF Doors - Side-lite 7 10+ years Not previously assessed 1st Floor Corridor 400 ΕA Not previously assessed Doors - Steel Doors incl hw 1st Floor Corridor 8 7 10+ vears

Doors - Transom Window

Student Lockers - One Tier

Walls - Concrete Block

Walls - Plaster/Drywall

Floor - Tile/Sheet

Floor - Tile/Sheet

Lighting - Lay-in

Walls - Masonrv

Drinking Fountains - Single Fountain

1st Floor Corridor

SF

ΕA

SF

SF

ΕA

ΕA

SF

SF

SF

7

7

7

4

7

6

6

7

6

10+ years

6-10 years

10+ years

1-2 years

10+ years

10+ years

10+ years

10+ years

10+ years

72

4

10

294

356

300

5,502

10,437

14,941

Not previously assessed

Damaged tiles



Category : Interior		Interior		uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor Corridor	5	SF	4	0-1 year	Damage at gyp enclosed column
	Ceiling - Lay-in	2nd Floor Corridor	12,204	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor Corridor	8	EA	7	10+ years	Not previously assessed
	Drinking Fountains - Single Fountain	2nd Floor Corridor	5	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor Corridor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor Corridor	12,204	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Corridor	294	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor Corridor	356	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor Corridor	5,502	SF	6	10+ years	
	Walls - Metal Panel	2nd Floor Corridor	10,437	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire building	2	EA	7	6-10 years	Assistant principal and principal laptops
	Metal Detector	Entire building	2	EA	7	6-10 years	
	Security Cameras	Entire building	21	EA	7	6-10 years	
	Security Cameras	Entire building	4	EA	7	10+ years	
stairs							
	Ceiling - Plaster/Drywall	Stair 1	195	SF	6	10+ years	
	Floor - Terrazzo	Stair 1	195	SF	7	10+ years	
	Handrails	Stair 1	56	LF	7	10+ years	
	Lighting - Lay-in	Stair 1	6	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 1	160	LF	6	10+ years	
	Walls - Masonry	Stair 1	572	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 2	132	SF	6	10+ years	
	Floor - Terrazzo	Stair 2	138	SF	6	10+ years	
	Handrails	Stair 2	112	LF	7	10+ years	
	Lighting - Lay-in	Stair 2	5	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 2	160	LF	6	10+ years	
	Walls - Concrete Block	Stair 2	781	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 3	240	SF	7	10+ years	
	Floor - Terrazzo	Stair 3	240	SF	6	10+ years	
	Handrails	Stair 3	240	LF	7	10+ years	
	Lighting - Lay-in	Stair 3	5	EA	7	6-10 years	
	Lighting - Lay-in	Stair 3	1	EA	6	6-10 years	
	Stairs - Terrazzo	Stair 3	192	LF	6	10+ years	
		Stair 3	920	SF	6 7		
	Walls - Masonry			SF		10+ years	
	Ceiling - Lay-in	Stair 4	240	SF SF	6	10+ years	
	Floor - Terrazzo	Stair 4	240		6	10+ years	
	Handrails	Stair 4	28	LF	7	10+ years	
	Lighting - Lay-in	Stair 4	6	EA	7	6-10 years	
	Stairs - Terrazzo	Stair 4	104	LF	6	10+ years	
	Walls - Masonry	Stair 4	920	SF	6	10+ years	



Michele Clark Academic Prep Magnet High School

SCHOOIS		5101 W Harrison STREET, Chicago, IL 60644
Category : Interior		Building : Main
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments
Vertical Conveyance		
Elevator - Hydraulic Elevator	1st Floor	1 EA 6 10+ years



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Athletic FΑ 7 South 10+ years Lighting 4 Surface - Asphalt 6,372 SF 7 South 10+ years New Lighting South 4 EΑ 7 10+ years Metal Bleachers South 540 LF 7 10+ years Under construction 2024 SF Surface - Synthetic South 75,827 7 10+ years Still under construction 2024 ΕA 7 10+ years Lighting West 2 LF Metal Bleachers West 44 7 10+ years Surface - Asphalt West 20.125 SF 7 10+ years New Lighting West 2 FΑ 7 10+ years New. Quantity changed to match current observations LF Metal Bleachers West 132 7 10+ years SF 7 Surface - Asphalt West 6,490 10+ years New 2024 Civil/Drainage Civil/ Drainage - Catch Basin Entire Site ΕA 6 13 10+ years Civil/ Drainage - Site Manhole Entire Site 11 ΕA 7 10+ years Fencina LF Fencing - Chain Link Entire Site 7 New 2024 834 10+ years LF Fencing - New Standard Ornamental Entire Site 1.573 7 10+ years New 2024 Fencing - New Standard Ornamental Entire Site 1.735 LF 6 10+ years Fencing - New Standard Ornamental 20 LF 1-2 years Entire Site 4 Bent/broken Landscape Benches Entire Site 16 ΕA 7 10+ vears Benches Entire Site 8 ΕA 6 10+ years Landscape - Grass Entire Site 38.136 SF 6 10+ years Quantity changed to match current observations Entire Site 600 SF 5 2-5 years Landscape - Hardscape- Asphalt Landscape - Hardscape- Concrete Entire Site 24,337 SF 6 10+ years Landscape - Hardscape- Concrete Entire Site SF 725 4 0-1 year Cracking/sinking SF Landscape - Hardscape- Pavers 1.200 4 Displaced/broken in both courtyards Entire Site 1-2 years Quantity changed to match current observations. Parkway trees **Entire Site** 35 ΕA 7 10+ years Quantity changed to match current observations Planting Beds/ Area Entire Site SF 4,120 5 6-10 years Play Area - Synthetic Turf Entire Site SF 7 29,565 10+ years New 2024 Retaining Wall - Concrete Entire Site 180 SF 6 10+ years **Trash Receptacles** Entire Site 2 FΑ 6 10+ years



Catego	ry : Site		В	uilding	: Site	0.1	
caloge	.,		_	anang		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Parking	Lot					-	
0	Interior Plantings	Parking Lot- South	50	LF	7	10+ years	
	Surface - Asphalt	Parking Lot- South	6,115	SF	4	1-2 years	Cracking/potholes
	Surface - Concrete	Parking Lot- South	300	SF	7	10+ years	51
	Trash Enclosure - Chain Links	Parking Lot- South	260	SF	7	10+ years	
	Concrete Curbs	Parking Lot- West	548	LF	7	10+ years	
	Interior Plantings	Parking Lot- West	80	LF	7	10+ years	
	Lighting - Pole Mounted	Parking Lot- West	6	EA	7	10+ years	New 2024 Quantity changed to match
							current observations
	Surface - Asphalt	Parking Lot- West	10,372	SF	7	10+ years	New 2024
	Vehicular Screening	Parking Lot- West	280	LF	7	10+ years	Under construction
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	892	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	20	LF	4	0-1 year	Cracking/sinking
	Sidewalks - Internal Walks	Entire Site	6	LF	4	0-1 year	Cracking/sinking
	Sidewalks - Internal Walks	Entire Site	12	LF	4	0-1 year	Cracking/sinking
	Sidewalks - Perimeter Sidewalks	Entire Site	17,220	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	4	0-1 year	Fixed most for the sidewalk. Only
							small area is damaged (Cracking/sinking)
_Signage							
_0_0_	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	Entire Site	2	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	6	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

Current Usage		De em l'esertier	Room	Floor Plan Room	Area (SF)	Glazed Window	Operable Window	Window	Smart-
Building : Main	Intended Usage	Room Location	Number	Number	(55)	Area	Area	Stop	Board
Art Room	Art Room	2nd Floor	249B	NA	924	266	10	N	Y
Art Room	Regular Classroom	1st Floor	122	122	924	258	10	N	n N
Art Room	Regular Classroom	1st Floor	122	122	795	238	19	N	N
Band Room	Other Instructional Use	2nd Floor	208 - Band	208 - Band	2,330	152	7	N	Y
Banu Room			Room	Room	2,330	152	'		I
Computer Lab	Computer Lab	2nd Floor	227	227	1,257	361	14	N	Y
Computer Lab	Computer Lab	2nd Floor	252	252	800	228	19	N	N
Computer Lab	Regular Classroom	1st Floor	121	121	840	228	19	N	N
Exclusively Used by Outside Organization	Band Room	2nd Floor	220	220	1,011	0	0	N	N
Faculty Lounge	Regular Classroom	1st Floor	110 - NA moved	116	775	0	0	N	N
Faculty Lounge	Regular Classroom	1st Floor	124	124	650	170	19	N	Y
Office	Computer Lab	2nd Floor	215	215	875	80	0	N	N
Office	Regular Classroom	1st Floor	141 - NA moved	143	799	228	15	N	N
Office	Regular Classroom	2nd Floor	224	224	660	167	19	N	N
Other Instructional Use	Regular Classroom	1st Floor	142	142	977	243	30	N	N
Other Instructional Use	Regular Classroom	1st Floor	144	144	674	176	10	N	N
Other Instructional Use	Regular Classroom	2nd Floor	205	205	1,020	0	0		N
Other Instructional Use	Regular Classroom	2nd Floor	209	209	767	152	7	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	210	210	799	219	7	N	N
Other Instructional Use	Regular Classroom	2nd Floor	216	216	773	64	0	N	N
Other Instructional Use	Regular Classroom	2nd Floor	218	218	773	0	0	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	222	222	976	266	19	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	230	230	834	228	19	N	Y
Regular Classroom	Other Instructional Use	1st Floor	109	109	1,830	0	0	N	Y
Regular Classroom	Regular Classroom	1st Floor	130	130	830	228	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	131	131	786	205	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	132	132	795	228	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	133	133	834	228	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	134	134	839	228	19	N	Y
Regular Classroom	Regular Classroom	1st Floor	150	150	831	228	15	N	Y
Regular Classroom	Regular Classroom	1st Floor	151	151	811	200	15	N	Y
Regular Classroom	Regular Classroom	1st Floor	152	152	811	228	15	N	Y
Regular Classroom	Regular Classroom	1st Floor	153	153	834	228	15	N	Y
Regular Classroom	Regular Classroom	1st Floor	154	154	833	228	15	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	918	76	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	918	221	7	N	Y



Classroom Summary

			Dear	Floor Plan		Glazed	Operable		Ormant
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	204	204	918	138	7	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	211	865	63	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	212	730	128	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	964	0	0	N	Y
Regular Classroom	Regular Classroom	2nd Floor	231	231	785	205	19	N	Y
Regular Classroom	Regular Classroom	2nd Floor	232	232	794	228	19	N	Y
Regular Classroom	Regular Classroom	2nd Floor	233	233	833	228	19	N	Y
Regular Classroom	Regular Classroom	2nd Floor	234	234	837	228	14	N	Y
Regular Classroom	Regular Classroom	2nd Floor	242	242	965	266	29	N	Y
Regular Classroom	Regular Classroom	2nd Floor	251	251	812	220	19	N	Y
Regular Classroom	Regular Classroom	2nd Floor	253	253	840	228	19	N	Y
Regular Classroom	Regular Classroom	2nd Floor	254	254	830	228	19	N	Y
Science Lab Level 1	Science Lab Level 1	2nd Floor	221	221	1,220	342	28	N	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	223	223	961	266	28	N	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	241	241	1,215	342	29	N	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	243	243	965	266	29	N	N
Store Room	Computer Lab	2nd Floor	207	207	971	0	0	N	N
Store Room	Regular Classroom	2nd Floor	244	244	658	167	9	N	N
Store Room	Regular Classroom	2nd Floor	250	250	833	228	19	N	N
Vacant	Regular Classroom	2nd Floor	203	203	918	160	0	N	N
Weight	Library	1st Floor	Weight Room 1st	Library	1,865	0	0		