

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1905	3	54,868
Annex	1960	3	25,716
Campus Total			80,584

Catego	Category : Exterior Building : Main				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior FRP Door	#2 - W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - W	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#2 - W	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 - W	20	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - W	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#3 - W	40	LF	6	1-2 years	Broken concrete
	Stair Handrail - Steel_Stair Handrail	#3 - W	10	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - SW	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - SW	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#4 - SW	40	LF	5	1-2 years	Cracked concrete
	Stair Handrail - Steel_Stair Handrail	#4 - SW	8	LF	6	10+ years	
	Entrance Control - Audio and Video	#5 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - S	2	EA	6	10+ years	
	Power Door Operator and Controls	#5 - S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6 - SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - SE	5	LF	5	10+ years	
	Exterior Stairs - Steel or Aluminum	#6 - SE	40	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#6 - SE	40	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 - E	5	LF	5	10+ years	
	Exterior Stairs - Steel or Aluminum	#7 - E	40	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#7 - E	40	LF	5	6-10 years	



Catego	ory : Exterior		В	uilding	: Main		
-					-	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior FRP Door	#8 - Boiler Room - E	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#9 - E	2	EA	6	10+ years	
Foundat	ion						
	Foundation - Masonry	Entire Building	780	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	54,868	SF	7	10+ years	
ighting							
-0 -0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
Roof Sy	stem						
,	Chimney - Metal Flue	Low NE Roof	8	LF	7	10+ years	
	Coping - Metal	Low NE Roof	56	LF	7	10+ years	
	Coping - Stone	Low NE Roof	77	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low NE Roof	22	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Low NE Roof	77	LF	7	10+ years	
	Roof - Modified Bitumen	Low NE Roof	1,555	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Low NE Roof	1,555	SF	7	10+ years	
	Coping - Stone	Low SE Roof	115	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low SE Roof	11	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Low SE Roof	130	LF	7	10+ years	
	Roof - Modified Bitumen	Low SE Roof	1,030	SF	7	10+ years	
		Low SE Roof		SF	7	•	
	Roof Structure - Steel with Clay Tile Arch		1,030			10+ years	
	Coping - Terra Cotta	Low W Roof	23	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low W Roof	28	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low W Roof	16	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low W Roof	7	LF	6	10+ years	
	Roof - Modified Bitumen	Low W Roof	90	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Low W Roof	90	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Coping - Clay Tile	Main Roof	350	LF	7	10+ years	
	Coping - Stone	Main Roof	153	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	195	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	70	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	120	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	313	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	9,542	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	9,542	SF	7	10+ years	
	Coping - Clay Tile	Upper Roof	246	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Upper Roof	138	LF	7	10+ years	
	Parapet - 16" - 30" Height	Upper Roof	40	LF	7	-	
				LF		10+ years	
	Parapet - Parapet < 16" Height	Upper Roof	206		7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Upper Roof	3,755	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Upper Roof	3,755	SF	7	10+ years	
Valls							
	Cornice - Masonry Projecting Limestone	Entire Building	450	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	30,068	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	162	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	914	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	915	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	365	SF	6	10+ years	
Nindows	3						
	Guard - Guards perforated	Entire Building	89	SF	6	10+ years	
	Lintels - Brick	Entire Building	30	LF	6	10+ years	
	Lintels - Steel	Entire Building	347	LF	6	10+ years	
	Lintels - Stone	Entire Building	181	LF	6	10+ years	
	Windows - Louver	Entire Building	20	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,646	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Basement	3	EA	6	10+ years	
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Central Courtyard	1	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,770	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,532	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	3,800	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,378	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,689	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	7	EA	6	6-10 years	

Stairs

Emergency Battery Packs - Students Toilets Exit Signs - Auditoium

Exit Signs - Corridors and Stairs

6

7

13

ΕA

ΕA

ΕA

6

4

4

6-10 years

2-5 years

2-5 years

bulbs

bulbs

Entire Building

Entire Building

Entire Building

20+ years old and incandescent

20+ years old and incandescent



NIG S							
Catego	ry : Electrical		B	uilding	: Main		
	-			5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Security System - CCTV	Entire Building	54,862	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	54,862	SF	6	6-10 years	
	Security System - Initiasion Detection		54,002	36	0	0-10 years	
Main Sei	rvice						
	Main Electrical Service - 1200 A 120/208/3PH	Engineer's Office	1	EA	6	2-5 years	
		Engineer's Office	1	EA	6	6 10 vooro	
	Independent Electrical Service for	Engineer's Office	I	EA	6	6-10 years	
	emergency power		54.000	05	-	0.5	N / 11 1
	PA System	Entire Building	54,862	SF	5	2-5 years	Not working in common areas
<sup>2</sup> ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Missing breaker cover slots
	Lighting and Power Panels - Above 100 A	Entire Building	11	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	2-5 years	Corroded and dated
		5		EA	6	6-10 years	Conoded and dated
	Main Distribution Danala 100 600 amp						
	Main Distribution Panels - 400 - 600 amp	Entire Building	1		-		
	Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600 amp	Entire Building Entire Building	1 2	EA	6	2-5 years	
Catego	Main Distribution Panels - Greater than 600	9	2		6	2-5 years	
	Main Distribution Panels - Greater than 600 amp	9	2	EA	6		Comments
Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type	Entire Building	2 Bi	EA uilding :	6 : Main	2-5 years Recommend	Comments
Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m	Entire Building	2 Br Quantity	EA uilding : UOM	6 : Main Rank	2-5 years Recommend Replacement	Comments
Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel	Entire Building Location Entire Building	2 Br Quantity 1	EA uilding : UOM EA	6 : Main Rank	2-5 years Recommend Replacement 2-5 years	Comments
Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Location Entire Building Entire Building Entire Building	2 B Quantity 1 54,868	EA uilding : UOM EA SF	6 <b>: Main</b> Rank	2-5 years Recommend Replacement 2-5 years 2-5 years	Comments
Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel	Entire Building Location Entire Building	2 Br Quantity 1	EA uilding : UOM EA	6 : Main Rank	2-5 years Recommend Replacement 2-5 years	Comments
Group Fire Alar	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights	Entire Building Location Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868	EA uilding : UOM EA SF	6 : Main Rank 6 6 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years	Comments
Group Fire Alar Catego	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical	Entire Building Location Entire Building Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868 8	EA uilding UOM EA SF SF uilding	6 : Main Rank 6 6 5 : Main	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type	Entire Building Location Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868	EA uilding UOM EA SF SF	6 <b>: Main</b> Rank 6 6 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems	Entire Building Location Entire Building Entire Building Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868 B Quantity	EA uilding EA SF SF uilding UOM	6 : Main Rank 6 6 5 : Main Rank	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type	Entire Building Location Entire Building Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868 8	EA uilding UOM EA SF SF uilding	6 : Main Rank 6 6 5 : Main	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years Recommend Replacement 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone-	Entire Building Location Entire Building Entire Building Entire Building Entire Building Entire Building	2 Quantity 1 54,868 54,868 B Quantity	EA uilding EA SF SF uilding UOM	6 : Main Rank 6 6 5 : Main Rank	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years Recommend Replacement 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1	EA uilding EA SF SF uilding EA EA	6 Main Rank 6 6 5 Main Rank 5 6	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North Mechanical Room - North Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1 1 1 1	EA uilding UOM EA SF SF uilding EA EA EA	6 Main Rank 6 6 5 5 Main Rank 5 6 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1 1 1 1 1 100	EA uilding EA SF SF uilding EA EA EA EA LF	6 Main Rank 6 6 5 5 6 5 5 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North Mechanical Room - North Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1 1 1 1	EA uilding EA SF SF uilding EA EA EA LF EA	6 Main Rank 6 6 5 5 Main Rank 5 6 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1 1 1 1 1 100	EA uilding EA SF SF uilding EA EA EA EA LF	6 Main Rank 6 6 5 5 6 5 5 5	2-5 years Recommend Replacement 2-5 years 2-5 years	
Group Fire Alar Catego Group	Main Distribution Panels - Greater than 600 amp ry : Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry : Mechanical Item - Type Iling Systems Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm Air Intake Auxiliaries - 15001 - 25000 cfm Return Duct Work - Indoor- Vertical Shaft and Ducts	Entire Building  Location  Entire Building Entire Building Entire Building Entire Building Mechanical Room - North	2 Quantity 1 54,868 54,868 B Quantity 1 1 1 1 1 100 2	EA uilding EA SF SF uilding EA EA EA LF EA	6 Main Rank 6 6 5 5 6 5 5 5 5	2-5 years Recommend Replacement 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years 2-5 years	



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Air Intake	Mechanical Room - South	duantity 1	EA	6	2-5 years	Comments
	Auxiliaries - 30001 - 45000 cfm	Mechanical Room - South	1	EA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - South	100	LA	5	2-5 years	
	and Ducts	Mechanical Room - South	100	LF	5	2-5 years	
	Zone Dampers	Mechanical Room - South	30	EA	5	2-5 years	
	Zone Dampers	Mechanical Room - South	30	EA	5	2-5 years	
Boiler Sy	/stems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Basement	2	EA	6	6-10 years	
	Pressure Boiler - 76 - 100 HP						
	Chemical Feed System	Basement	1	EA	6	6-10 years	
	Chemical Feeder	Basement	1	EA	5	2-5 years	
	Combustion Dampers	Basement	3	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	7	10+ vears	
	Condensate Pump	Basement	1	EA	7	10+ years	
	Feed Water Pumps and Tank	Basement	1	EA	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Basement	1	EA	6	2-5 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	Basement		L/\	0	2 0 youro	
	Non Condensing- Fire Tube- Scotch Marine-	Basement	1	EA	6	2-5 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	Basement	1		0	2 0 yours	
	Piping - Condensate Pipe- Steel	Basement	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Basement	400	LF	6	6-10 years	
	Steam Traps	Basement	400 24	EA	6	•	
	Steam maps	Dasement	24	LA	0	6-10 years	
Heat Exc	changers						
	Heat Exchanger - Steam to Hot Water Shell	Boiler Room	1	EA	6	6-10 years	
	Туре						
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	4	2-5 years	Rusted and dated
	Wall Heater - Electric	Entire Building	7	EA	5	2-5 years	
	Fin Tube - Electric	Near Elevator	20	LF	6	6-10 years	
			20	LI	0	0-10 years	
Tempera	ature Control						
	Pneumatic System	Entire Building	54,868	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	30	EA	4	0-1 year	Not operational
Vontilati	~~						
Ventilatio	Exhaust Fans- Indoor - Less than 500 CFM	Kitchen, Elevator Machine Room,	1	EA	6	6-10 years	Not accessible at time of assessment
	Exhaust 1 ans- 110001 - Less than 500 CFM	Roof	1		0	0-10 years	due to asbestos abatement
	Exhaust Eans Indoor Loss than 500 CEM	Kitchen, Elevator Machine Room,	4	E ^	e	6 10 years	
	Exhaust Fans- Indoor - Less than 500 CFM		1	EA	6	6-10 years	
		Roof		<b>F</b> •	-	40.	
	Exhaust Fans- Roof Mounted - 500 - 1500	Kitchen, Elevator Machine Room,	1	EA	7	10+ years	
	CFM	Roof				•	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500	Kitchen, Elevator Machine Room,	2	EA	7	10+ years	
	CFM	Roof					
Catego	ry : Plumbing		В	uilding	: Main		
_						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
	Hot Water Storage Tank_Gas - Less than	Boiler Room	1	EA	3	0-1 year	Leaking and deteriorating
	200 Gallons						
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	54,868	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	54,868	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	54,868	SF	6	2-5 years	
	Fixtures	-				-	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	54,868	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	54,868	SF	6	2-5 years	
	(Risers)	ç					
	Domestic Piping-Hot/Cold Water Supply	Entire Building	54,868	SF	6	2-5 years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	54,868	SF	5	2-5 years	
	Storm Piping	Entire Building	54,868	SF	5	2-5 years	
	Vent Piping	Entire Building	54,868	SF	5	2-5 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Boiler Room and Basement	1	EA	5	2-5 years	
	Pumps - Ejector-Simplex	Boiler Room and Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Boiler Room and Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Boiler Room and Basement	1	EA	6	6-10 years	
Catego	ry : Room		B	uilding	• Main		
Juicgo				anung	. mant	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	rative Suites/Offices						
	AC Unit	1st Floor-Principal's Office-Room	1	EA	7	6-10 years	Principal has key, no access
	Ceiling - Plaster/Drywall	100 1st Floor-Principal's Office-Room	296	SF	6	10+ years	Principal has key, no access
		100				-	
	Doors - Transom Window	1st Floor-Principal's Office-Room 100	3	SF	6	6-10 years	Principal has key, no access
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office-Room	1	EA	6	6-10 years	Principal has key, no access



Catego	ry : Room		В	uilding	: Main		
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		100		0-		0.40	<u> </u>
	Floor - Tile	1st Floor-Principal's Office-Room	296	SF	6	6-10 years	Principal has key, no access
	Lighting - Pendent/Surface	100 1st Floor-Principal's Office-Room	2	EA	7	6-10 years	Principal has key, no access
	Lighting - Tenden/Sunace	100	2	LA	1	0-10 years	Thirdpartias key, no access
	Power Distribution	1st Floor-Principal's Office-Room	8	EA	6	6-10 years	Principal has key, no access
		100	-		-	,	
	Storage/ Closet	1st Floor-Principal's Office-Room	30	SF	7	6-10 years	Principal has key, no access
		100					
	Walls - Plaster/Drywall	1st Floor-Principal's Office-Room	650	SF	6	10+ years	Principal has key, no access
	Ceiling - Plaster/Drywall	100 Basement-Engineer's Office	298	SF	7	10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	Abstament in progress, no assess
	Doors - Wood Doors inclu hw	Basement-Engineer's Office	290	EA	6	10+ years 10+ years	Abatement in progress, no access.
	Floor - Tile	Basement-Engineer's Office	298	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Engineer's Office	3	EA	7	6-10 years	
	Power Distribution	Basement-Engineer's Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement-Engineer's Office	560	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Kitchen Office-B13	155	SF	7	10+ years	Abatement in progress, no access.
	Doors - Wood Doors inclu hw	Basement-Kitchen Office-B13	1	EA	6	10+ years	
	Floor - Tile	Basement-Kitchen Office-B13	155	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Kitchen Office-B13	1	EA	7	6-10 years	
	Power Distribution	Basement-Kitchen Office-B13	4	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Basement-Kitchen Office-B13	408	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Teacher's Lounge	855	SF	7	10+ years	Abatement in progress, no access.
	Doors - Wood Doors inclu hw	Basement-Teacher's Lounge	2	EA	6	10+ years	1 3 2
	Floor - Tile	Basement-Teacher's Lounge	855	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Teacher's Lounge	5	ĒA	7	6-10 years	
	Storage/ Closet	Basement-Teacher's Lounge	16	SF	7	6-10 years	
	Walls - Masonry	Basement-Teacher's Lounge	864	SF	6	10+ years	
	waiis - wasoni y	Dasement-reacher's Lounge	004	01	0	TOF years	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	54	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	730	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	3,770	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,885	SF	6	6-10 years	
	Floor - Tile	1st Floor	230	SF	6	10+ years	
	Floor - Wood	1st Floor	2,385	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	2,000	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	8 5	EA	6	6-10 years	
	Main Floor Seating	1st Floor	237	EA	7	6-10 years	
	Main Floor Seating	1st Floor	13	EA	4	0-1 year	Missing seats and seatbacks
	Stage	1st Floor	762	SF	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		21 O Halvald AVENOE, Officago, ie 00020
30.00 30						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Stage Curtain	1st Floor	4	EA	7	6-10 years	
	Stage Lift	1st Floor	1	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	10	LF	6	10+ years	
	Storage/ Closet	1st Floor	128	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	7,595	SF	6	10+ years	
Gymnas	ia						
,	Ceiling - Plaster/Drywall	3rd Floor	3,800	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	Occupancy limit not on display
	Floor - Wood	3rd Floor	3,800	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	3rd Floor	12	EA	7	6-10 years	
	Sodium					· · · · ·	
	Walls - Plaster/Drywall	3rd Floor	3,828	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,642	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	471	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	471	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement		EA	7	6-10 years	
	Walls - Concrete Block	Basement	180	SF	6	10+ years	
	Walls - Masonry	Basement	180	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	360	SF	6	10+ years	
lunch 9	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement-Lunchroom A	1,113	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Lunchroom A	3	EA	6	10+ years	
	Floor - Tile	Basement-Lunchroom A	1,113	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement-Lunchroom A	13	EA	7	6-10 years	
	Serving Line		10		6		
		Basement-Lunchroom A	678	SF		6-10 years	
	Walls - Masonry	Basement-Lunchroom A		SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Basement-Lunchroom A	555		6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Lunchroom B	1,113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement-Lunchroom B	2	EA	6	10+ years	
	Floor - Tile	Basement-Lunchroom B	1,113	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Lunchroom B	14	EA	7	6-10 years	
	Market Board	Basement-Lunchroom B	20	LF	7	6-10 years	
	Storage/ Closet	Basement-Lunchroom B	33	SF	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Lunchroom B	1,233	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Servery B02	1,152	SF	6	10+ years	
	Floor - Tile	Basement-Servery B02	1,152	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Servery B02	6	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main			
-				5		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Serving Line	Basement-Servery B02	10	LF	6	6-10 years		
	Walls - Masonry	Basement-Servery B02	630	SF	6	10+ years		
	Walls - Plaster/Drywall	Basement-Servery B02	630	SF	6	10+ years		
MDF ID	E							
טו_ וטו/	Doors - Steel Doors incl hw	Room 104A	1	EA	6	6-10 years		
	Finishes	Room 104A	158	SF	7	10+ years		
	Window AC Unit	Room 104A	130	EA	7	6-10 years		
					·	0.0,00.0		
1echani	cal/ Service Rooms							
	Janitor's Closet	3rd floor-Janitor's closet	25	SF	7	6-10 years		
	Boiler Room	Basement	1,654	SF	7	6-10 years		
	Mechanical/ Service Rooms	Basement	600	SF	7	6-10 years		
	Mechanical/ Service Rooms	Basement	86	SF	7	6-10 years		
	Mechanical/ Service Rooms	Basement	411	SF	7	6-10 years		
	Janitor's Closet	Janitor's Closet	25	SF	7	6-10 years	Ceiling repaired	
estroor	n							
	Accessories	1st Floor-Principal's Office Restroom	29	SF	5	6-10 years	Principal has key, no access	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office Restroom	29	SF	5	0-1 year	Principal has key, no access	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office Restroom		ĒA	6	6-10 years	Principal has key, no access	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Principal's Office Restroom	29	SF	6	6-10 years	Principal has key, no access	
	Lavatory	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	Principal has key, no access	
	Lighting - Pendent/Surface	1st Floor-Principal's Office Restroom	1	EA	7	6-10 years	Principal has key, no access	
	Walls - Plaster/Drywall	1st Floor-Principal's Office Restroom	110	SF	6	6-10 years	Principal has key, no access	
	Walls - Plaster/Drywall	1st Floor-Principal's Office Restroom	110	SF	6	6-10 years	Principal has key, no access	
	Walls - Flaster/Drywall Water Closet							
		1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	Principal has key, no access	
	Accessories	2nd Floor	230	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	230	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	230	SF	6	10+ years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	1-2 years	Relamp	
	Partitions	2nd Floor	3	EA	7	6-10 years		
	Partitions	2nd Floor	1	EA	5	1-2 years	Lock broken	
	Walls - Plaster/Drywall	2nd Floor	241	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	725	SF	7	10+ years		
	Water Closet	2nd Floor	4	EA	6	6-10 years		
	Accessories	2nd Floor	230	SF	7	6-10 years		
		2nd Floor	230	SF				
	Ceiling - Plaster/Drywall			SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	230		6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		



Catego	Category : Room				: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	1-2 years	Relamp
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	6-10 years	
	Urinals	2nd Floor	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	666	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	6-10 years	
	Water Closet	2nd Floor	1	EA	4	1-2 years	Out of order
	Accessories	Basement	718	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	718	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	718	SF	6	6-10 years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	Quantity changed to match current
		5	-			0.40	observations
	Lavatory	Basement	5	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	4	EA	7	6-10 years	
	Partitions	Basement	13	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Basement	1,700	SF	6	10+ years	
	Water Closet	Basement	2	EA	6	1-2 years	No water
	Water Closet	Basement	11	EA	6	6-10 years	
	Accessories	Basement	506	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	506	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	506	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	4	EA	6	6-10 years	
	Partitions	Basement	4	EA	7	6-10 years	
	Urinals	Basement	7	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Basement	819	SF	6	10+ years	
	Water Closet	Basement	4	EA	6	6-10 years	

Category : Classroom	B	Building : Main				
					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom #100 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	938	SF	6	10+ years	
Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
Floor - Wood	1st Floor	938	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,722	SF	6	10+ years	
Classroo	om #101 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	938	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Wood	1st Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,722	SF	6	10+ years	
Classro	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	832	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Wood	1st Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	158	SF	7	•	Updated to match current
	Storage/ Closer	151 F1001	150		/	6-10 years	observations
	Walls - Plaster/Drywall	1st Floor	1,419	SF	6	10+ years	
Classroo	om #103 (Store Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	832	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	158	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,419	SF	6	10+ years	
	Wireless System	1st Floor	, 1	EA	7	6-10 years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
			10	0.	U	ie. youro	



Building : Main         Group Item - Type       Recommend         Doors - Wood Doors inclu hw       2nd Floor       2       EA       6       10+ years         Floor - Tile       2nd Floor       884       SF       6       10+ years         Lighting - Pendent/Surface       2nd Floor       16       EA       7       6-10 years         Marker Board       2nd Floor       34       LF       6       6-10 years         Storage/ Closet       2nd Floor       176       SF       7       6-10 years         Walls - Plaster/Drywall       2nd Floor       1,398       SF       6       10+ years         Classroom #202 (Regular Classroom)       2       EA       7       6-10 years       Observations         AC Units       2nd Floor       2       EA       7       6-10 years       Observations         Doors - Transom Window       2nd Floor       2       EA       7       6-10 years       Observations         Doors - Wood Doors inclu hw       2nd Floor       2       EA       7       6-10 years       Observations         Classroom #202 (Regular Classroom)       2nd Floor       2       EA       7       6-10 years       Observations	
Doors - Wood Doors inclu hw2nd Floor2EA610+ yearsFloor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ yearsClassroom #202 (Regular Classroom)Classroom #202 (Regular Classroom) </th <th></th>	
Floor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ yearsClassroom #202 (Regular Classroom)Classroom #202 (Regular Classroom)Dors 2 EA 7 6-10 yearsDors 7 Transon Window2nd Floor10 Floor10 Floor10 Floor10 Floor10 Floor10 Floor10 Floor10 Floor10 Floor	
Lighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ yearsClassroom #202 (Regular Classroom)AC Units2nd Floor2EA76-10 yearsCeiling - Plaster/Drywall2nd Floor2EA76-10 yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor9SF610+ yearsFloor - Tile2nd Floor1EA76-10 yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsKarker Board2nd Floor1EA610+ yearsDoors - Transom Window2nd Floor16EA76-10 yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsKarker Board2nd Floor16EA76-10 yearsMarker Board2nd Floor16SF76-10 yearsKarker Board2nd Floor176SF76-10 yearsKarker Board2nd Floor176SF76-10 yearsKarker Board2nd Floor176SF76-10 yearsKarker Board2nd Floor176SF76-10 years	
Marker Board Storage/ Closet2nd Floor34LF66-10 years observationsUpdated to match current observationsWalls - Plaster/Drywall2nd Floor1,398SF610+ yearsUpdated to match current observationsClassroom #202 (Regular Classroom)AC Units2nd Floor2EA76-10 yearsAC Units2nd Floor2EA76-10 yearsDoors - Transom Window2nd Floor884SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA76-10 yearsFloor - Tile2nd Floor16EA76-10 yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor16EA76-10 yearsWalls - Plaster/Drywall2nd Floor16EA76-10 yearsWalls - Plaster/Drywall2nd Floor16EA76-10 yearsWalls - Plaster/Drywall2nd Floor16EA76-10 yearsWalls - Plaster/Drywall2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor176SF76-10 years	
Storage/ Closet2nd Floor176SF76-10 yearsUpdated to match current observationsWalls - Plaster/Drywall2nd Floor1,398SF610+ yearsAC Units2nd Floor2EA76-10 yearsCeiling - Plaster/Drywall2nd Floor2EA76-10 yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor9SF610+ yearsFloor - Tile2nd Floor1EA610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF6610+ yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1398SF610+ years	
Walls - Plaster/Drywall2nd Floor1,398SF610+ yearsClassroom #202 (Regular Classroom)AC Units2nd Floor2EA76-10 yearsCeiling - Plaster/Drywall2nd Floor884SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor1884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor176SF76-10 years	
Classroom #202 (Regular Classroom)AC Units2nd Floor2EA76-10 yearsCeiling - Plaster/Drywall2nd Floor884SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor16EA76-10 yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
AC Units2nd Floor2EA76-10 yearsCeiling - Plaster/Drywall2nd Floor884SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Ceiling - Plaster/Drywall2nd Floor884SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Doors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Doors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Floor - Tile2nd Floor884SF610+ yearsLighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Lighting - Pendent/Surface2nd Floor16EA76-10 yearsMarker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Marker Board2nd Floor34LF66-10 yearsStorage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Storage/ Closet2nd Floor176SF76-10 yearsWalls - Plaster/Drywall2nd Floor1,398SF610+ years	
Walls - Plaster/Drywall 2nd Floor 1,398 SF 6 10+ years	
_Classroom #203 (Regular Classroom)	
AC Units 2nd Floor 1 EA 7 6-10 years	
Ceiling - Plaster/Drywall 2nd Floor 832 SF 6 10+ years	
Doors - Transom Window 2nd Floor 9 SF 6 10+ years	
Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 10+ years	
Floor - Tile 2nd Floor 832 SF 6 6-10 years	
Lighting - Pendent/Surface 2nd Floor 17 EA 7 6-10 years	
Marker Board 2nd Floor 34 LF 6 6-10 years	
Storage/ Closet 2nd Floor 158 SF 7 6-10 years	
Walls - Plaster/Drywall 2nd Floor 1,304 SF 6 10+ years	
Walls - Plaster/Drywall2nd Floor15SF51-2 yearsCracking	
Classroom #204 (Music Room)	
AC Units 2nd Floor 1 EA 7 6-10 years	
AC Units 2nd Floor 1 EA 4 1-2 years Unit not working	
Ceiling - Plaster/Drywall 2nd Floor 832 SF 6 10+ years	
Doors - Transom Window 2nd Floor 1 SF 6 10+ years	
Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 10+ years	
Floor - Tile 2nd Floor 832 SF 6 10+ years	
Lighting - Pendent/Surface 2nd Floor 17 EA 7 6-10 years	
Marker Board 2nd Floor 34 LF 7 6-10 years	
Storage/ Closet 2nd Floor 158 SF 7 6-10 years	
Walls - Plaster/Drywall2nd Floor1,419SF610+ yearsStrong mildew smell from	



Category : Classroom			В	Building : Main			527 S Halvald AVENUE, Chicago, ie 00020
	<b>,</b>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #301 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	938	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	938	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,722	SF	6	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	938	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,722	SF	6	10+ years	
Classroo	m #303 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	621	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	621	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	234	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	651	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	651	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet			SF	7	6-10 years	



Catego	Category : Classroom		В	uilding	: Main				
_			•			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years			
Classroo	om #305 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	459	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years			
	Floor - Tile	3rd Floor	459	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	1-2 years	Relamp		
	Marker Board	3rd Floor	28	LF	7	6-10 years	Relation		
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	6	10+ years			
	Walls T laster/Drywall		1,202	01	Ū	for years			
Catego	ry : Interior		В	uilding	: Main				
	H					Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	1st Floor	2,190	SF	6	6-10 years			
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years			
	Floor - Asphalt Floor	1st Floor	2,190	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	4,508	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	2,190	SF	6	10+ years			
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years			
	Floor - Asphalt Floor	2nd Floor	2,190	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	4,508	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	2,190	SF	6	10+ years			
	Drinking Fountains - Single Fountain	3rd Floor	_,1	ĒA	7	6-10 years			
	Floor - Asphalt Floor	3rd Floor	2,190	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	18	ĒA	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	4,508	SF	6	10+ years			
	Ceiling - Lay-in	Basement - North East	224	SF	7	6-10 years			
	Floor - Tile/Sheet	Basement - North East	224	SF	7	6-10 years			
	Lighting - Pendent/Surface	Basement - North East	1	EA	7	6-10 years			
	Stairs - Concrete Stairs	Basement - North East	4	LF	6	10+ years			
	Walls - Plaster/Drywall	Basement - North East	600	SF	6	10+ years			
	Ceiling - Plaster/Drywall		214	SF	7				
		Basement - North West	214			10+ years			
		Pagament North West	1		6				
	Doors - Wood Doors include hw	Basement - North West	4	EA	6	10+ years			
	Doors - Wood Doors include hw Floor - Tile/Sheet	Basement - North West	4 214	SF	7	10+ years			
	Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Chandelier, Incandescent	Basement - North West Basement - North West	214 1	SF EA	7 7	10+ years 6-10 years			
	Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Chandelier, Incandescent Lighting - Pendent/Surface	Basement - North West Basement - North West Basement - North West	214 1 1	SF EA EA	7 7 7	10+ years 6-10 years 6-10 years			
	Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Chandelier, Incandescent	Basement - North West Basement - North West	214 1	SF EA	7 7	10+ years 6-10 years			



Catego	Category : Interior		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement - South East	150	SF	6	6-10 years	
	Floor - Tile/Sheet	Basement - South East	150	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement - South East	2	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement - South East	4	LF	6	10+ years	
	Walls - Masonry	Basement - South East	250	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - South East	250	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - South West	484	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement - South West	2	EA	6	10+ years	
	Floor - Tile/Sheet	Basement - South West	484	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement - South West	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - South West	440	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement - South West	440	SF	6	10+ years	
	Ceiling - Exposed	Basement - West	66	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement - West	2	EA	6	10+ years	
	Floor - Concrete	Basement - West	66	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - West	2	EA	7	6-10 years	
	Walls - Masonry	Basement - West	306	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - West	102	SF	6	10+ years	
Safetv							
	Security Cameras	entire Building	6	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North West	762	SF	6	10+ years	
	Floor - Asphalt	North West	510	SF	6	10+ years	
	Floor - Terrazzo	North West	252	SF	6	10+ years	
	Handrails	North West	224	LF	7	6-10 years	
	Lighting - Pendent/Surface	North West	8	EA	7	6-10 years	
	Stairs - Asphalt	North West	112	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	3,136	SF	6	10+ years	
	Walls - Structural Glazed Tile	North West	102	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Stair 1 - Southwest	762	SF	6	10+ years	
	Floor - Asphalt	Stair 1 - Southwest	480	SF	6	10+ years	
	Floor - Asphalt	Stair 1 - Southwest	30	SF	5	1-2 years	Chipped
	Floor - Tile	Stair 1 - Southwest	252	SF	6	10+ years	
	Handrails	Stair 1 - Southwest	224	LF	7	6-10 years	
	Lighting - Pendent/Surface	Stair 1 - Southwest	8	EA	7	6-10 years	
	Stairs - Asphalt	Stair 1 - Southwest	112	LF	6	10+ years	
	Walls - Plaster/Drywall	Stair 1 - Southwest	3,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	300	SF	6	10+ years	
	Floor - Asphalt	West	300	SF	6	10+ years	
	Handrails	West	45	LF	7	6-10 years	
	Lighting - Pendent/Surface	West	3	EA	7	6-10 years	
	Stairs - Asphalt	West	20	LF	6	10+ years	
	otario Applan		20	L1	0	ior years	



Catego	ory : Interior		Building : Main
Group	Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments
	Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain	West West	1,134 SF 6 10+ years 378 SF 6 10+ years
Vertical	Conveyance		
	Elevator - Hydraulic Elevator Wheelchair Lift - Platform Lift	1st Floor 1st Floor	1 EA 7 10+ years 1 EA 7 10+ years



Catego	Category : Exterior			uilding	: Annex		
-				•		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	ġ.						
	Entrance Control - Audio and Video	#1 - Main - W	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 - Main - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - W	4	EA	7	10+ years	
	Power Door Operator and Controls	#1 - Main - W	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#10 - E	2	EA	7	10+ years	
	Exterior Doors - Side lite	#10 - E	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#10 - E	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#11 - NE	2	EA	7	10+ years	
	Exterior Stairs - Stone	#11 - NE	6	LF	6	10+ years	
	Entrance Control - Audio and Video	#12 - W	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#12 - W	2	EA	7	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	620	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	25,716	SF	7	10+ years	
	Superstructure Solicite		20,710	01	,	for years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	
Roof Sy	stem						
	Access Ladder - Metal	Elevator Tower Roof	1	EA	7	10+ years	
	Coping - Stone	Elevator Tower Roof	55	LF	6	10+ years	
	Downspouts - Interior Downspouts	Elevator Tower Roof	57	LF	6	10+ years	
	Parapet - Parapet > 30"	Elevator Tower Roof	55	LF	6	10+ years	
	Roof - Modified Bitumen	Elevator Tower Roof	100	SF	6	2-5 years	
	Roof - Modified Bitumen	Elevator Tower Roof	84	SF	5	2-5 years	Worn out membrane
	Roof Structure - Steel / Metal Deck/	Elevator Tower Roof	184	SF	7	10+ years	
	Concrete Topping					,	
	Access Ladder - Metal	Link Roof	1	EA	7	10+ years	
	Coping - Stone	Link Roof	142	LF	6	10+ years	
	Downspouts - Interior Downspouts	Link Roof	29	LF	6	10+ years	
	Parapet - 16" - 30" Height	Link Roof	142	LF	6	10+ years	Covered in roofing membrane
	Roof - Modified Bitumen	Link Roof	732	SF	6	2-5 years	Repaired
	Roof Structure - Steel / Metal Deck/	Link Roof	732	SF	7	10+ years	
	Concrete Topping				-	,	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	Unable to access routes through this ladder. Locked cage with no key on aita
	Chimnoy Motol Elug	Main Roof	27	LF	e	10, 10000	site.
	Chimney - Metal Flue	Main Roof Main Roof	27 509	LF LF	6	10+ years	
	Coping - Metal	Main Roof Main Roof		LF	7 7	6-10 years	New
	Downspouts - Interior Downspouts		92	LF	1	10+ years	New



Catego	Category : Exterior			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Main Roof	11,668	SF	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Concrete	Main Roof	11,668	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	20	SF	6	10+ years	These cracks have been repaired
	Canopy - Concrete/ Stucco	Entire Building	58	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	1,000	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	9,723	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	109	SF	6	10+ years	
Window	s						
	Clerestory - Glass Double-Pane	Entire Building	26	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	96	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	792	SF	6	10+ years	
	Curtain wall - Louver	Entire Building	90	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	362	SF	6	10+ years	
	Lintels - Steel	Entire Building	396	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,910	SF	6	10+ years	

**Building : Annex** 

### **Category : Electrical**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
U	Emergency A/C Power - Corridors and Stairs	Entire Building	5,665	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	880	SF	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	5	2-5 years	
	Security System - CCTV	Entire Building	25,716	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	25,716	SF	6	6-10 years	
	Automatic Transfer Switch	Mechanical Room	1	EA	6	10+ years	
_Main Se	rvice						
	PA System	Entire Building	25,716	SF	5	2-5 years	Not working in common areas
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	6	6-10 years	-
	Main Electrical Service - 800 A and Less than 120/208/3PH	Mechanical Room	1	EA	4	1-2 years	Dated and deteriorating, exposed live parts
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	2-5 years	



Catego	ry : Electrical		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Fire Protection		В	uilding			
outogo				anang	. /	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
Fire Alar						-	
	Fire Alarm Strobe Lights	Entire Building	25,716	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	25,716	SF	5	2-5 years	
Catego	ry : Mechanical		В	uildina	: Annex	·	
	,					Recommend	
Group		Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Dual Temperature Coil	1st Floor	1	EA	6	6-10 years	
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	20	EA	5	2-5 years	
	Fin Tube - Electric	Entire Building	50	LF	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	40	LF	5	2-5 years	
	Wall Heater - Electric	Entire Building	8	EA	5	6-10 years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	600	LF	5	2-5 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	4	2-5 years	Heavily corroded
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	4	2-5 years	Heavily corroded
Tempera	ture Control						
·	Pneumatic System	Entire Building	25,716	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	15	EA	4	0-1 year	Not operational
Jnit Ven	tilation						
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	15	EA	5	2-5 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	3	EA	7	10+ years	



#### John Harvard Elementary School of Excellence

7527 S Harvard AVENUE, Chicago, IL 60620

Catego	Category : Mechanical				Building : Annex					
Group Item - Type Location			Quantity	UOM	Rank	Recommend Replacement	Comments			
Croup	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	1	EA	7	10+ years	Comments			
	CFM					-				
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	7	10+ years				

#### **Category : Plumbing Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR Mechanical Room 1 ΕA 5 2-5 years Pipina **Domestic Piping-Hot Water Return Lines** Entire Building 25,716 SF 6 2-5 years Domestic Piping-Hot Water Return Risers Entire Building 25,716 SF 6 2-5 years Domestic Piping-Hot Water from Risers to Entire Building 25,716 SF 6 2-5 years Fixtures Domestic Piping-Hot/Cold Water Supply SF Entire Building 25,716 6 2-5 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply Entire Building 25.716 SF 6 2-5 years (Risers) Domestic Piping-Hot/Cold Water Supply Entire Building 25.716 SF 6 2-5 years (from Risers to Fixtures) Sanitary Piping Entire Building 25,716 SF 5 2-5 years Storm Piping SF Entire Building 25,716 5 2-5 years Vent Piping 25,716 SF 5 Entire Building 2-5 years

#### Category : Room **Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Administrative Suites/Offices ΕA AC Unit 1st Floor-Assistant Principal's 1 7 6-10 years Office-107A Ceiling - Plaster/Drywall 1st Floor-Assistant Principal's 180 SF 10+ years 6 Office-107A Doors - Wood Doors inclu hw 1st Floor-Assistant Principal's ΕA 1 6 10+ years Office-107A 1st Floor-Assistant Principal's SF Floor - Tile 180 6 10+ years Office-107A Lighting - Pendent/Surface 1st Floor-Assistant Principal's 2 ΕA 6 6-10 years Office-107A Power Distribution 1st Floor-Assistant Principal's ΕA 8 6 6-10 years Office-107A Storage/ Closet 1st Floor-Assistant Principal's SF 7 6-10 years 18



Catego	ory : Room		Building : Annex				
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Office-107A					
	Walls - Concrete Block	1st Floor-Assistant Principal's	486	SF	6	10+ years	
		Office-107A					
	AC Unit	1st Floor-Main Office-107	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Main Office-107	365	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office-107	2	EA	6	10+ years	
	Floor - Tile	1st Floor-Main Office-107	365	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Main Office-107	6	EA	6	6-10 years	
	Power Distribution	1st Floor-Main Office-107	10	EA	6	6-10 years	
	Storage/ Closet	1st Floor-Main Office-107	21	SF	5	6-10 years	
	Walls - Concrete Block	1st Floor-Main Office-107	1,280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor-Room 213A-Teacher	238	SF	6	10+ years	
		Resource Room					
	Doors - Wood Doors inclu hw	2nd Floor-Room 213A-Teacher	1	EA	6	10+ years	
		Resource Room					
	Floor - Tile	2nd Floor-Room 213A-Teacher	238	SF	6	10+ years	
		Resource Room					
	Lighting - Pendent/Surface	2nd Floor-Room 213A-Teacher	4	EA	6	6-10 years	
		Resource Room			-		
	Power Distribution	2nd Floor-Room 213A-Teacher	4	EA	6	6-10 years	
		Resource Room		05		4.0	
	Walls - Concrete Block	2nd Floor-Room 213A-Teacher	558	SF	6	10+ years	
		Resource Room			-	0.40	
	Work SInk	2nd Floor-Room 213A-Teacher	1	EA	7	6-10 years	
		Resource Room					
ibrary							
lorary	AC Unit	2nd Floor-Room 205	2	EA	7	6-10 years	
	Casework	2nd Floor-Room 205	54	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor-Room 205	1,164	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor-Room 205	2	EA	6	10+ years	
	Floor - Carpet	2nd Floor-Room 205	1,164	SF	5	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Room 205	20	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor-Room 205	1,287	SF	6	10+ years	
			.,	•	U U	let jeare	
/IDF_ID							
	Doors - Steel Doors incl hw	1sr Floor-105C	1	EA	6	10+ years	
	Finishes	1sr Floor-105C	123	SF	4	6-10 years	Re-lamp fixture
	Window AC Unit	1sr Floor-105C	1	EA	4	1-2 years	Unit not working
lechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	23	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	331	SF	5	6-10 years	
			001	5	0	o io youio	



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Vaults	1st Floor	50	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	23	SF	5	6-10 years	
estroor	n						
	Accessories	105A-1st Floor-Kindergarten	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A-1st Floor-Kindergarten	52	SF	6	10+ years	
	Doors - Transom Window	105A-1st Floor-Kindergarten	1	SF	6	10+ years	
	Floor - Tile	105A-1st Floor-Kindergarten	52	SF	6	10+ years	
	Floor Drain	105A-1st Floor-Kindergarten	1	EA	7	10+ years	
	Hand Dryer	105A-1st Floor-Kindergarten	1	EA	7	6-10 years	
	Lavatory	105A-1st Floor-Kindergarten	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	105A-1st Floor-Kindergarten	1	EA	7	6-10 years	
	Walls - Concrete Block	105A-1st Floor-Kindergarten	261	SF	6	10+ years	
	Water Closet	105A-1st Floor-Kindergarten	1	EA	6	6-10 years	
	Accessories	107C-1st Floor-Principal's Office	61	SF	7	6-10 years	
		Restroom	01		'	-	
	Ceiling - Plaster/Drywall	107C-1st Floor-Principal's Office Restroom	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	107C-1st Floor-Principal's Office Restroom	1	EA	6	10+ years	
	Floor - Tile	107C-1st Floor-Principal's Office Restroom	61	SF	6	10+ years	
	Lavatory	107C-1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	107C-1st Floor-Principal's Office Restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	107C-1st Floor-Principal's Office Restroom	279	SF	6	10+ years	
	Water Closet	107C-1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	5	6-10 years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Partitions	1st Floor	1	EA	7	6-10 years	
	Urinals	1st Floor	2	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	2 513	SF	-	•	
	Walls - Structural Glazed Tile Water Closet	1st Floor	513	EA	6	10+ years	
			-	SF	6	6-10 years	
	Accessories	1st Floor	220		7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	6	10+ years	



Catego	Category : Room		В	uildina	: Annex		
0	, ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor	1	EA	7	6-10 years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	513	SF	6	10+ years	
	Water Closet	1st Floor	3	EA	6	6-10 years	
	Accessories	1st Floor - Unisex	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Unisex	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor - Unisex	1	EA	6	10+ years	
	Lavatory	1st Floor - Unisex	1	EA	6	2-5 years	
	Lighting - Pendent/Surface	1st Floor - Unisex	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor - Unisex	207	SF	6	10+ years	
	Water Closet	1st Floor - Unisex	1	EA	6	6-10 years	
	Accessories	1st Floor-Room 111B	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Room 111B	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Room 111B	-0	EA	6	10+ years	
	Floor - Tile	1st Floor-Room 111B	48	SF	6	10+ years	
	Hand Dryer	1st Floor-Room 111B	40	EA	7	6-10 years	
	Lavatory	1st Floor-Room 111B	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Room 111B	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor-Room 111B	252	SF	6	10+ years	
	Walls - Concrete Block Water Closet	1st Floor-Room 111B	252	EA	6	6-10 years	
	Accessories	211B	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	211B 211B	40 48	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	211B 211B	40	EA	7	6-10 years	
	Floor - Wood Doors Inclu nw	211B 211B	48	SF	7	6-10 years	
	Hand Dryer	211B 211B	40	EA	7		
	•	211B 211B	1	EA	7	6-10 years 6-10 years	
	Lavatory	211B 211B	1	EA	7	•	
	Lighting - Pendent/Surface Walls - Concrete Block	211B 211B	252	SF	7	6-10 years 6-10 years	
	Walls - Concrete Block Water Closet	211B 211B	252	EA	7	•	
				SF		6-10 years	
	Accessories	2nd Floor	220 220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall Floor - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	220	SF	6 6	10+ years	
					-	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	1	EA	7	6-10 years	
		2nd Floor	2	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	513	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	6-10 years	
	Accessories	2nd Floor	220	SF	7	6-10 years	



### John Harvard Elementary School of Excellence

7527 S Harvard AVENUE, Chicago, IL 60620 **Category : Room Building : Annex** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Ceiling - Plaster/Drywall 2nd Floor SF 220 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor 220 SF 6 10+ years Floor Drain 2nd Floor ΕA 7 6-10 years 1 Hand Dryer 2nd Floor ΕA 7 6-10 years 1 2 ΕA Lavatory 2nd Floor 6 6-10 years Lighting - Pendent/Surface 3 2nd Floor ΕA 6-10 years 6 Partitions 2nd Floor 3 ΕA 7 6-10 years Walls - Structural Glazed Tile 513 SF 2nd Floor 6 10+ years Water Closet 2nd Floor 3 ΕA 6 6-10 years 2nd Floor - Unisex 42 SF 7 Accessories 6-10 years Ceiling - Plaster/Drywall SF 2nd Floor - Unisex 42 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor - Unisex 1 ΕA 6 10+ years 6-10 years Floor - Tile 2nd Floor - Unisex 42 SF 7 Deficiency fixed ΕA Lavatory 2nd Floor - Unisex 1 6 6-10 years Lighting - Pendent/Surface 2nd Floor - Unisex 1 ΕA 6 6-10 years Walls - Concrete Block 2nd Floor - Unisex 234 SF 6 10+ years Water Closet 2nd Floor - Unisex ΕA 6 1 6-10 years

**Building : Annex** 

#### Category : Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #105 (Pre School)		-				
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	876	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	876	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	56	SF	5	6-10 years	
	Walls - Concrete Block	1st Floor	1,521	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	744	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	744	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	990	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	



Marker Board

Classroom #111 (Regular Classroom) AC Units

Work Sink

Casework

Lighting - Pendent/Surface

Lighting - Pendent/Surface

Walls - Concrete Block

Ceiling - Plaster/Drywall

### John Harvard Elementary School of Excellence

Catego	ry : Classroom		В	uilding	: Annex	[	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	744	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	990	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	744	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	990	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	- 5	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	651	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	651	SF	6	10+ years	
					-	,	

8

8

20

1

2

5

651

936

ΕA

ΕA

LF

SF

ΕA

EΑ LF

SF

EΑ

SF

ΕA

LF

SF

7

6

7

7

7

7

6

6

6

6

7

7

6

6-10 years

6-10 years

6-10 years

10+ years

6-10 years

6-10 years

6-10 years

10+ years

10+ years

10+ years

6-10 years

6-10 years

10+ years

**Re-lamp fixture** 

1st Floor



Catego	ry : Classroom		В	uilding	: Annex	·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #112 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	651	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	651	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	744	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	990	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #207 (Regular Classroom)						
01000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16		6	6-10 years	
				SF	-	•	
	Walls - Concrete Block	2nd Floor	845		6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years	
Classroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	744	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	990	SF	6	10+ years	
Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	



Catego	ategory : Classroom			uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years	
Classroo	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	7	•	
		2nd Floor	112	SF	6	10+ years	
	Walls - Plaster/Drywall	2110 F1001	112	SF	0	10+ years	
Classroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	745	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Quarry	2nd Floor	745	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Doors - Store Front	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years	
	Walls - Plastel/Drywall		112	SF	0	10+ years	
Catego	ry : Interior		В	uilding	: Annex		
Group	Itom - Typo	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity		Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,667	SF	6	6-10 years	
	Doors - Store Front	1st Floor	4	EA	6	10+ years	
	Doors - Transom Window	1st Floor	205	SF	6	10+ years	
					-	<b>,</b>	



	Interior		D	uilding			
						Recommend	
	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	oors - Wood Doors include hw	1st Floor	6	EA	6	10+ years	
Dri	rinking Fountains - Double Fountain	1st Floor	1	EA	5	6-10 years	Quantity changed to match current observations
Dri	rinking Fountains - Single Fountain	1st Floor	2	EA	5	6-10 years	Quantity changed to match current observations
Flc	oor - Tile Quarry	1st Floor	116	SF	6	10+ years	
Flc	oor - Tile/Sheet	1st Floor	2,553	SF	5	2-5 years	
Lig	ghting - Lay-in	1st Floor	12	EA	7	6-10 years	
	ghting - Pendent/Surface	1st Floor	23	EA	6	6-10 years	
	alls - Concrete Block	1st Floor	5,295	SF	6	10+ years	
	alls - Tile Ceramic/ Porcelain	1st Floor	478	SF	6	10+ years	
	eiling - Splined	2nd Floor	2,596	SF	6	6-10 years	
	pors - Wood Doors include hw	2nd Floor	2,000	EA	6	10+ years	
	rinking Fountains - Double Fountain	2nd Floor	1	EA	5	6-10 years	
	rinking Fountains - Single Fountain	2nd Floor	2	EA	5	6-10 years	
	oor - Terrazzo	2nd Floor	144	SF	6	10+ years	
	oor - Tile/Sheet	2nd Floor	2,452	SF	7		
				-		10+ years	
Lig	ghting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	ghting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	airs - Concrete Stairs	2nd Floor	22	LF	6	10+ years	
	alls - Concrete Block	2nd Floor	5,180	SF	7	10+ years	
	alls - Masonry	2nd Floor	864	SF	7	10+ years	
Wa	alls - Tile Ceramic/ Porcelain	2nd Floor	356	SF	7	10+ years	
Safety							
	amera Viewing Station	entire building	1	EA	7	6-10 years	
Se	ecurity Cameras	entire building	5	EA	7	6-10 years	
Se	ecurity Cameras	entire building	3	EA	5	6-10 years	
Stairs							
Ce	eiling - Plaster/Drywall	North East	209	SF	6	10+ years	
	oor - Terrazzo	North East	100	SF	6	10+ years	
На	andrails	North East	64	LF	7	6-10 years	
Lic	ghting - Pendent/Surface	North East	3	EA	7	6-10 years	
	airs - Terrazzo	North East	32	LF	6	10+ years	
	alls - Concrete Block	North East	794	SF	6	10+ years	
	alls - Tile Ceramic/ Porcelain	North East	88	SF	6	10+ years	
	eiling - Plaster/Drywall	South West	209	SF	6	10+ years	
	oor - Terrazzo	South West	100	SF	6	10+ years	
	andrails	South West	64	LF	7	•	
		South West		EA		6-10 years	
	ghting - Pendent/Surface		3		6	6-10 years	
	airs - Terrazzo	South West	32	LF	6	10+ years	
	alls - Concrete Block	South West	794	SF	6	10+ years	
VVa	alls - Tile Ceramic/ Porcelain	South West	88	SF	6	10+ years	



SCI IOOIS		7527 S Harvard AVENUE, Chicago, IL 60620
Category : Interior		Building : Annex
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments
Vertical Conveyance		
Elevator - Elevator- Machine Roomless	1st Floor	1 EA 6 6-10 years



					: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	South	4,869	SF	7	10+ years	
	Surface - Asphalt	South	1,672	SF	6	10+ years	
						-	
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	6	10+ years	
encina							
<u>shong</u>	Fencing - Chain Link	West, North Courtyard and South	26	LF	6	6-10 years	
	Fencing - Chain Link	West, North Courtyard and South	200	LF	6	10+ years	
	Fencing - Chain Link	West, North Courtyard and South	20	LF	5	1-2 years	Bent posts, missing top rail
	Fencing - Iron and Concrete Post	West, North Courtyard and South	173	LF	6	10+ years	
	Fencing - New Standard Ornamental	West, North Courtyard and South	32	LF	6	10+ years	
	Fencing - New Standard Ornamental	West, North Courtyard and South	10	LF	4	1-2 years	damaged gate and fence
	Fencing - Old Standard Ornamental	West, North Courtyard and South	342	LF	6	10+ years	
	Fencing - Old Standard Ornamental	West, North Courtyard and South	10	LF	4	1-2 years	Fence impacted out of shape
andscar	De						
	Landscape - Grass	Entire Site	7,128	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	238	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,364	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,124	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	1	EA	6	10+ years	
	Parkway trees	Entire Site	29	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	2,750	SF	6	10+ years	
	Trash Receptacles	Entire Site	6	EA	6	10+ years	
Parking L	ot						
	Concrete Curbs	South	316	LF	6	10+ years	
	Interior Plantings	South	242	LF	6	10+ years	
	Lighting - Pole Mounted	South	6	EA	6	10+ years	
	Pavers	South	21,141	SF	6	10+ years	
	Surface - Asphalt	South	10,486	SF	6	10+ years	
	Trash Enclosure - Chain Links	South	300	SF	6	10+ years	
Playgrou	ind						
	Equipment - Pre K 3-5	N Courtyard	1	EA	6	10+ years	
	Surface - Poured Surface	N Courtyard	685	SF	6	10+ years	
					-	<b>,</b>	



_							2. e na ra a n 2. e no ge, 12 e e e 2
Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	S Playground	1,320	SF	6	6-10 years	
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	245	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	27,618	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	4	1-2 years	Upheaved sidewalk
_Signage							
0 0	Flag Pole - Flag Pole	Northwest and Main Entrance	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Northwest and Main Entrance	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Northwest and Main Entrance	1	EA	7	10+ years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



### **Classroom Summary**

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	3rd Floor	301	301	938	198	99	N	N
Music Room	Regular Classroom	2nd Floor	204	204	832	133	58	N	N
Office	Regular Classroom	1st Floor	101	102	938	198	99	N	N
Regular Classroom	Regular Classroom	1st Floor	100	101	938	198	99	N	N
Regular Classroom	Regular Classroom	1st Floor	102	103	832	204	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	884	204	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	884	204	68	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	832	133	58	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	938	198	99	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	651	198	99	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	459	132	66	N	N
Science Classroom	Regular Classroom	3rd Floor	303	303	621	198	99	N	Y
Store Room	Regular Classroom	1st Floor	103	104	832	204	104	N	Ν
Building : Annex									
Kindergarten	Regular Classroom	1st Floor	106	106	744	156	78	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	744	156	78	N	N
Pre School	Kindergarten	1st Floor	105	105	876	231	115	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	744	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	651	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	651	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	651	98	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	744	156	78	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	745	184	96	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	208	208	744	156	78	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	745	184	96	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	210	745	184	96	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	211	211	745	184	96	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	745	184	96	N	Ν