

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1980	2	67,900
Campus Total			67,900

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			·			<u> </u>	
	Entrance Control - Audio and Video	#1 N	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 N	4	EΑ	6	10+ years	
	Power Door Operator and Controls	#1 N	2	EΑ	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2 Exit N	2	EA	4	1-2 years	Some dents, door showing signs of corrosion
	Ramps - Concrete	#2 Exit N	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 Exit W	2	EΑ	5	6-10 years	Minor rusting.
	Ramp Handrail - Steel_Ramp Handrail	#3 Exit W	12	LF	6	10+ years	-
	Ramps - Concrete	#3 Exit W	12	LF	6	10+ years	
	Entrance Control - Audio and Video	#4 S	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#4 S	2	EA	6	10+ years	
	Ramps - Concrete	#4 S	16	LF	5	6-10 years	Cracked concrete
	Exterior Doors - Overhead Rolling/ Garage Door	#4.1 OHD S	1	EA	6	6-10 years	
	Ramps - Concrete	#4.1 OHD S	8	LF	5	0-1 year	Cracked concrete
	Exterior Doors - Overhead Rolling/ Garage Door	#4.2 OHD S	1	EA	6	10+ years	
	Ramps - Concrete	#4.2 OHD S	8	LF	5	0-1 year	Cracked concrete
	Exterior Doors - Exterior Steel Door	#5 Exit S	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6 Exit S	1	EA	4	0-1 year	Door and frame showing signs of corrosion
	Exterior Doors - Exterior Steel Door	#7 S	2	EA	5	1-2 years	Corroding door and frames
	Exterior Doors - Exterior Steel Door	#8 N	2	EA	6	10+ years	C
	Exterior Stairs - Concrete	#8 N	10	LF	5	1-2 years	Large crack on concrete



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Foundati	on						
	Foundation - Concrete	Entire Building	772	LF	7	10+ years	
	Superstructure - Steel	Entire Building	67,900	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	23	EA	6	10+ years	
Roof Sys	tem						
	Access Ladder - Metal	High Roof	1	EA	7	10+ years	
	Coping - Metal	High Roof	324	LF	7	10+ years	
	Downspouts - Interior Downspouts	High Roof	60	LF	6	10+ years	
	Roof - Modified Bitumen	High Roof	6,138	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	High Roof	6,138	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EΑ	7	10+ years	
	Coping - Metal	Main Roof	776	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	260	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	776	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	29,148	SF	7	6-10 years	
	Roof Hatch - Metal	Main Roof	1	ĒΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	29,148	SF	7	10+ years	
Walls							
· · · · · ·	Exterior Walls - Brick	Entire Building	1,970	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	500	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	17,700	SF	6	10+ years	
Windows							
	Clerestory - Glass Double-Pane	Entire Building	768	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	150	SF	7	10+ years	
	Lintels - Steel	Entire Building	96	LF	6	10+ years	
	Skylite - Glass Double-Pane	Entire Building	200	SF	7	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	2,510	SF	7	10+ years	
	Windows - Louver	Entire Building	250	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	UUIVI	Kalik	Replacement	Comments
<u>Emerger</u>	cy System						



Catego	ry : Electrical		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Automatic Transfer Switch	Electrical Room	1	EΑ	4	2-5 years	Vibrating noise, dated
	Emergency A/C Power - Corridors and	Entire Building	9,955	SF	6	6-10 years	
	Stairs						
	Emergency A/C Power - Gym	Entire Building	2,588	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,562	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	
	Security System - CCTV	Entire Building	67,900	SF	6	2-5 years	
	Security System - Intrusion Detection	Entire Building	67,900	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	3	EA	4	2-5 years	Over 20 years old and incandescent bulbs
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	4	2-5 years	Over 20 years old and incandescent bulbs
	Exit Signs - Gym	Entire Building	2	EA	4	2-5 years	Over 20 years old and incandescent bulbs
	Exit Signs - Lunchroom	Entire Building	2	EA	4	2-5 years	Over 20 years old and incandescent bulbs
_Main Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 800 A and 277/480/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	67,900	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Live front
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	6-10 years	

Campus Name: Kanoon Page : 3 of 27 Assessment Date: 08/23/2023



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Aları							
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	
	Fire Alarm Strobe Lights	Entire Building	67,900	SF	6	2-5 years	
	Fire Alarm_System	Entire Building	67,900	SF	6	2-5 years	
Catego	ry : Mechanical		R	uilding	· Main		
Outogo	y : mediamoui			unung	. wan	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond			•			•	
<u> </u>	Condensing Unit- Roof Mounted - 31-50	Roof - South	1	EA	5	2-5 years	#7
	tons		·		ŭ	_ 0 ,00.0	
	Condensing Unit- Roof Mounted - 21-30	Roof - Southwest	1	EA	4	2-5 years	Heavy damage to fins, excessive
	tons					•	vibration. ACC-1
	Condensing Unit- Roof Mounted - 21-30	Roof - Southwest	1	EA	4	2-5 years	Heavy damage to fins and rusting
	tons						
	Condensing Unit- Roof Mounted - 31-50	Roof - Southwest	1	EA	4	1-2 years	Unit currently down, engineer unsure
	tons Condensing Unit- Roof Mounted - 31-50	Roof - West	1	EA	5	6-10 years	if fixable. ACC-#4 #6 - ACC-2
	tons	Nooi - West	'	LA	3	0-10 years	#0 - ACC-2
	Condensing Unit- Roof Mounted - Less	Roof - West	1	EA	6	6-10 years	PPA - 2A
	than 5 tons	11001 11001	•	_, `	Ŭ	o io youio	1177 277
	Condensing Unit- Roof Mounted - 21-30	Roof - West	1	EA	4	1-2 years	Heavy damage to fins, one
	tons					•	condenser fan not working. ACC-8
	Condensing Unit- Roof Mounted - 31-50	Upper Roof	1	EA	6	6-10 years	ACC-2
	tons						
Air Hand	ling Customs						
_Air Hand	ling Systems Air Handling Unit- Package Multi Zone-	1st Floor AU1	1	EA	5	2 E veere	AH1
	Indoor- Electric and DX Cooling Coil -	1st Floor - AH1	ı	EA	5	2-5 years	АПІ
	20001-30000 cfm						
	Air Intake	1st Floor - AH1	1	EA	6	6-10 years	
	Zone Dampers	1st Floor - AH1	8	EA	6	6-10 years	
	Air Handling Unit- Package Multi Zone-	2nd Floor - AH2	1	EA	5	2-5 years	AH2
	Indoor- Electric and DX Cooling Coil -		•		•	,	· · · · -
	Greater than 30,000 cfm						
	Air Intake	2nd Floor - AH2	1	EA	6	6-10 years	
	Zone Dampers	2nd Floor - AH2	8	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-	2nd Floor - AH3	1	EA	5	2-5 years	AH-3
	Indoor- Electric and DX Cooling Coil -					-	
	20001-30000 cfm						
	Air Intake	2nd Floor - AH3	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-	2nd Floor - AH4	1	EA	5	2-5 years	AH4
	Indoor- Electric and DX Cooling Coil -						



Catego	ry : Mechanical		В	uilding	: Main		. <u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	12001-20000 cfm						
	Air Intake	2nd Floor - AH4	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-	2nd Floor - AH5	1	EA	5	2-5 years	AH-5
	Indoor- Electric and DX Cooling Coil - Less						
	than 4000 cfm						
	Air Intake	2nd Floor - AH5	1	EA	6	6-10 years	
	Air Handling Unit- Package Single Zone-	2nd Floor - AH6	1	EA	5	2-5 years	AH6
	Indoor- Electric and DX Cooling Coil - 4000-						
	8000 cfm						
	Air Intake	2nd Floor - AH6	1	EA	6	6-10 years	
	Zone Dampers	2nd Floor - AH6	4	EA	6	6-10 years	
	Air Handling Unit- Package Multi Zone-	2nd Floor - AH7	1	EA	5	2-5 years	AH7
	Indoor- Electric and DX Cooling Coil -						
	Greater than 30,000 cfm				_		
	Air Intake	2nd Floor - AH7	1	ΕA	6	6-10 years	
	Zone Dampers	2nd Floor - AH7	9	EΑ	6	6-10 years	
	Air Handling Unit- Package Multi Zone-	2nd Floor - AH8	1	EA	5	2-5 years	Very tight space requiring to crawl to
	Indoor- Electric and DX Cooling Coil - 6000-						do maintenance, unsafe transition
	10000 cfm	Ond Floor ALIO	4	Γ.	0	0.40	onto unit's platform. AH8
	Air Intake	2nd Floor - AH8	1	EΑ	6	6-10 years	
	Zone Dampers	2nd Floor - AH8	6 1	EA EA	6	6-10 years	A110
	Air Handling Unit- Package Single Zone- Indoor- Electric Coil - 4000-8000 cfm	2nd Floor - AH9	1	EA	5	2-5 years	AH9
	Air Intake	2nd Floor - AH9	1	⊏∧	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline -	Entire Building	1	EA EA	5	6-10 years	
	10001 - 20000 CFM	Entire Building	ı	EA	3	0-10 years	
	Indoor Return Fans- Centrifugal Inline -	Entire Building	6	EA	5	6-10 years	
	10001 - 20000 CFM	Entire Building	0	LA	5	0-10 years	
	Indoor Return Fans- Centrifugal Inline -	Entire Building	1	EA	5	6-10 years	
	5000 - 10000 CFM	Entire Building	1	LA	5	0-10 years	
	3000 - 10000 CI W						
_Heating	Devices						
Treating	Wall Heater - Electric	Entire Building	5	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Cover falling off.
	Wall Floator Elocato	Entire Ballating	•	_/、	•	o i youi	cover raining on.
_Tempera	ture Control						
	Electric Thermostat	Entire Building	2	EA	4	0-1 year	Radiator panels removed
	Pneumatic System	Entire Building	67,900	SF	5	2-5 years	- I I I I I I I I I I I I I I I I I I I
	Thermostats - Pneumatic	Entire Building	67	ĒΑ	5	2-5 years	
		Ŭ				,	
_Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	4	EA	5	6-10 years	
	CFM	<u> </u>				•	



Catego	ry : Mechanical		E	Building	: Main		233 S Redzie AVENUE, Chicago, iL 60623
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	4	1-2 years	Damaged and rattling noise
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	2-5 years	
Catego	ry : Plumbing		E	Building	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OCIVI	IVALIK	Replacement	Comments
Hot Wat	Electric Heater - Greater than 50 KW	Mechanical Room	1	EA	6	6-10 years	
5						•	
Piping	Demostic Dining Llet Water Deturn Lines	Entire Building	67,000	SF		2 F voore	
	Domestic Piping-Hot Water Return Lines	Entire Building	67,900		6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	67,900	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	67,900	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	67,900	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,900	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	67,900	SF	6	2-5 years	
	Sanitary Piping	Entire Building	67,900	SF	6	2-5 years	
	Storm Piping	Entire Building	67,900	SF	6	2-5 years	
	Vent Piping	Entire Building	67,900	SF	6	2-5 years	
	vent i ping	Littile Building	07,300	Oi	U	2-5 years	
Pumps	Dumpa Figetor Cimpley	140		ΓΛ		2 E vecere	
	Pumps - Ejector-Simplex	140	1	EA	5	2-5 years	
Catego	ry : Room		E	Building	: Main		
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	106 C & D	270	SF	6	10+ years	
	Doors - Steel Doors incl hw	106 C & D	1	EA	6	6-10 years	
	Floor - Carpet	106 C & D	135	SF	6	6-10 years	
	Floor - Tile	106 C & D	135		6	6-10 years	
	Lighting - Lay-in	106 C & D	4	EA	7	10+ years	
	Power Distribution	106 C & D	4	EA	7	10+ years	
	Walls - Concrete Block	106 C & D	375	SF	6	10+ years	
			Page : 6 of 27				Assessment Date: 08/23/20
∟amnus I	Name: Kanoon		Faue . P Ot 31				466666Webt 1 1946: (18/23/2)

Campus Name: Kanoon Page : 6 of 27 Assessment Date: 08/23/2023



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor - 170 Engineer's Office	152	SF	6	6-10 years	
	Doors - Side-lite	1st Floor - 170 Engineer's Office	16	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor - 170 Engineer's Office	1	EA	6	6-10 years	
	Floor - Tile	1st Floor - 170 Engineer's Office	152	SF	6	10+ years	
	Lighting - Lay-in	1st Floor - 170 Engineer's Office	2	EA	6	10+ years	
	Power Distribution	1st Floor - 170 Engineer's Office	6	EA	6	6-10 years	
	Storage/ Closet	1st Floor - 170 Engineer's Office	25	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor - 170 Engineer's Office	350	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor - Conference Room (Main Office)	255	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor - Conference Room (Main Office)	1	EA	6	6-10 years	
	Floor - Carpet	1st Floor - Conference Room (Main Office)	255	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor - Conference Room (Main Office)	4	EA	6	10+ years	
	Power Distribution	1st Floor - Conference Room (Main Office)	8	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor - Conference Room (Main Office)	285	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Conference Room (Main Office)	115	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor - Coordinator's Office	440	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor - Coordinator's Office	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor - Coordinator's Office	440	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor - Coordinator's Office	6	EA	7	10+ years	
	Power Distribution	1st Floor - Coordinator's Office	8	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor - Coordinator's Office	755	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Coordinator's Office	188	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor - Faculty Lounge 106	1,493	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Faculty Lounge 106	2	EΑ	6	6-10 years	
	Floor - Carpet	1st Floor - Faculty Lounge 106	1,386	SF	6	6-10 years	
	Floor - Tile	1st Floor - Faculty Lounge 106	57	SF	7	10+ years	
	Floor - Tile	1st Floor - Faculty Lounge 106	50	SF	6	10+ years	
	Lighting - Lay-in	1st Floor - Faculty Lounge 106	13	EΑ	7	10+ years	
	Power Distribution	1st Floor - Faculty Lounge 106	8	EA	6	10+ years	
	Walls - Concrete Block	1st Floor - Faculty Lounge 106	1,890	SF	6	10+ years	
	Work SInk	1st Floor - Faculty Lounge 106	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Guidance Office (Main Office)	315	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor - Guidance Office (Main Office)	1	EA	6	6-10 years	
	Floor - Carpet	1st Floor - Guidance Office (Main Office)	315	SF	6	6-10 years	



Catego	Category : Room		В	uilding	: Main			
J						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st Floor - Guidance Office (Main Office)	4	EA	7	10+ years		
	Power Distribution	1st Floor - Guidance Office (Main Office)	8	EA	6	6-10 years		
	Walls - Concrete Block	1st Floor - Guidance Office (Main Office)	525	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor - Guidance Office (Main Office)	145	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor - Main Office 100	842	SF	6	10+ years		
	Doors - Side-lite	1st Floor - Main Office 100	96	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor - Main Office 100	2	EA	6	6-10 years		
	Floor - Carpet	1st Floor - Main Office 100	592	SF	6	6-10 years		
	Floor - Tile	1st Floor - Main Office 100	250	SF	6	10+ years		
	Lighting - Lay-in	1st Floor - Main Office 100	13	ĒΑ	6	10+ years		
	Power Distribution	1st Floor - Main Office 100	18	ΕA	6	10+ years		
	Walls - Concrete Block	1st Floor - Main Office 100	1,590	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor - Principal's Office	322	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor - Principal's Office	2	EA	6	6-10 years		
	Floor - Tile	1st Floor - Principal's Office	322	SF	6	10+ years		
	Lighting - Lay-in	1st Floor - Principal's Office	6	EA	7	10+ years		
	Power Distribution	1st Floor - Principal's Office	12	EA	6	6-10 years		
	Walls - Concrete Block	1st Floor - Principal's Office	630	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor-102 Office	110	SF	6	6-10 years		
	Doors - Side-lite	1st Floor-102 Office	16	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor-102 Office	1	EA	6	6-10 years		
	Floor - Carpet	1st Floor-102 Office	110	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor-102 Office	2	EA	6	10+ years		
	Power Distribution	1st Floor-102 Office	6	EA	6	10+ years		
	Walls - Concrete Block	1st Floor-102 Office	305	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor-Kitchen Office	145	SF	6	6-10 years		
	Doors - Steel Doors incl hw	1st Floor-Kitchen Office	145	EA	6	6-10 years		
	Floor - Tile	1st Floor-Kitchen Office	145	SF	6	•		
	Lighting - Lay-in	1st Floor-Kitchen Office		EA	6	6-10 years		
	Power Distribution	1st Floor-Kitchen Office	4	EA	6	10+ years		
	Walls - Concrete Block	1st Floor-Kitchen Office	245	SF	6	10+ years		
			272	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor - Office (221)			_	6-10 years	\Matan dama an	
	Ceiling - Lay-in	2nd Floor - Office (221)	40	SF	4	1-2 years	Water damage	
	Doors - Side-lite	2nd Floor - Office (221)	88	SF	6	6-10 years		
	Doors - Steel Doors incl hw	2nd Floor - Office (221)	1	EA	6	6-10 years		
	Floor - Tile	2nd Floor - Office (221)	312	SF	6	6-10 years		
	Lighting - Lay-in	2nd Floor - Office (221)	6	EΑ	6	6-10 years		
	Power Distribution	2nd Floor - Office (221)	8	EA	6	6-10 years		
	Walls - Concrete Block	2nd Floor - Office (221)	544	SF	6	10+ years		
	Ceiling - Lay-in	Nurse Office	256	SF	6	6-10 years		



Catego	ategory : Room		В	uilding	: Main				
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	Nurse Office	8	SF	4	1-2 years	Water damage		
	Doors - Side-lite	Nurse Office	64	SF	6	6-10 years			
	Doors - Steel Doors incl hw	Nurse Office	1	EA	6	6-10 years			
	Floor - Tile	Nurse Office	264	SF	7	10+ years			
	Lighting - Lay-in	Nurse Office	3	EA	7	10+ years			
	Power Distribution	Nurse Office	8	EA	6	6-10 years			
	Walls - Concrete Block	Nurse Office	585	SF	6	10+ years			
Auditoriu	m & Theater								
7.00.00	Ceiling - Exposed	1st Floor-142 Auditorium	2,388	SF	6	10+ years			
	Ceiling - Lay-in	1st Floor-142 Auditorium	72	SF	6	6-10 years			
	Doors - Steel Doors incl hw	1st Floor-142 Auditorium	6	EA	6	6-10 years			
	Floor - Carpet	1st Floor-142 Auditorium	2,010	SF	6	6-10 years			
	Floor - Tile	1st Floor-142 Auditorium	450	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor-142 Auditorium	22	EA	6	10+ years			
				EA	7				
	Stage Curtain	1st Floor-142 Auditorium	2			6-10 years			
	Stage Lighting System	1st Floor-142 Auditorium	•	EA	7	10+ years			
	Stage-Stairs - Tile	1st Floor-142 Auditorium	16	LF	6	10+ years			
	Storage/ Closet	1st Floor-142 Auditorium	72	SF	7	6-10 years			
	Walls - Concrete Block	1st Floor-142 Auditorium	4,428	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor-142 Auditorium	492	SF	6	10+ years			
Gymnas	ia.								
-	Ceiling - Exposed	1st Floor	2,512	SF	6	6-10 years			
	Ceiling - Exposed	1st Floor	50	SF	3	1-2 years	Condensation buildup on ductwork leading to active water dripping and gathering on the floor		
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	6-10 years			
	Floor - Wood	1st Floor	2,562	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	15	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	5,361	SF	6	6-10 years			
Kitchen									
	Ceiling - Lay-in	1st Floor	560	SF	6	6-10 years			
	Doors - Side-lite	1st Floor	32	SF	6	6-10 years			
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	560	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	8	EA	6	10+ years			
	Serving Line	1st Floor	8	LF	6	6-10 years			
	Walls - Concrete Block	1st Floor	850	SF	6	10+ years			
	Traile Sollorete Block	1301	330	0.	J	ioi youio			
Library									



Catego	ory : Room		Building : Main						
						Recommend	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Ceiling - Lay-in	Room 225	1,428	SF	6	6-10 years			
	Doors - Side-lite	Room 225	10	SF	6	6-10 years			
	Doors - Steel Doors incl hw	Room 225	2	ĒΑ	6	6-10 years			
	Floor - Carpet	Room 225	1,428	SF	6	6-10 years			
	Lighting - Lay-in	Room 225	27	EA	7	6-10 years			
	Walls - Concrete Block	Room 225	2,280	SF	6	10+ years			
ockor/S	Shower Room								
ockei/s		4-4 Flags 407 Marsell asker Dagge	0.5			0.40			
	Accessories	1st Floor - 127 Mens' Locker Room	65	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor - 127 Mens' Locker Room	65	SF	6	6-10 years			
	Doors - Steel Doors incl hw	1st Floor - 127 Mens' Locker Room	1	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - 127 Mens' Locker Room	30	SF	6	6-10 years			
	Floor - Tile/Sheet	1st Floor - 127 Mens' Locker Room	35	SF	7	10+ years			
	Lavatory	1st Floor - 127 Mens' Locker Room	1	EA	6	6-10 years			
	Lighting - Lay-in	1st Floor - 127 Mens' Locker Room	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor - 127 Mens' Locker Room	1	EA	6	10+ years			
	Lighting - Wall Mounted	1st Floor - 127 Mens' Locker Room	1	EA	6	10+ years			
	Student Lockers - One Tier	1st Floor - 127 Mens' Locker Room	1	EA	6	6-10 years			
	Walls - Concrete Block			SF					
		1st Floor - 127 Mens' Locker Room	125		6	10+ years			
	Water Closet	1st Floor - 127 Mens' Locker Room	1	EA	6	6-10 years			
	Accessories	1st Floor - 128 Women's Locker Room	75	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor - 128 Women's Locker Room	75	SF	6	6-10 years			
	Doors - Steel Doors incl hw	1st Floor - 128 Women's Locker Room	2	EA	6	6-10 years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - 128 Women's Locker	25	SF	6	6-10 years			
	Floor - Tile/Sheet	Room 1st Floor - 128 Women's Locker	50	SF	7	6-10 years			
	Lavatory	Room 1st Floor - 128 Women's Locker	1	EA	6	6-10 years			
	Lighting - Lay-in	Room 1st Floor - 128 Women's Locker	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Room 1st Floor - 128 Women's Locker	1	EA	6	10+ years			
	Lighting - Wall Mounted	Room 1st Floor - 128 Women's Locker	1	EA	6	10+ years			
	Student Lockers - Two Tier	Room 1st Floor - 128 Women's Locker	6	EA	6	6-10 years			
	Walls - Concrete Block	Room 1st Floor - 128 Women's Locker Room	125	SF	6	10+ years			
	Water Closet	1st Floor - 128 Women's Locker Room	1	EA	6	6-10 years			

Campus Name: Kanoon Page : 10 of 27 Assessment Date: 08/23/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
unch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,596	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	6-10 years	
	Floor - Tile	1st Floor	2,596	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	32	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,956	SF	6	10+ years	
	_						
DF_ID		0.151.040.0				0.40	
	Doors - Steel Doors incl hw	2nd Floor-218 Computer Lab	1	EA	7	6-10 years	
	Finishes	2nd Floor-218 Computer Lab	300	SF	7	6-10 years	
	Window AC Unit	2nd Floor-218 Computer Lab	1	EA	7	6-10 years	
lechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	48	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	32	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	333	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	208	SF	7	6-10 years	
	Storage Room	1st Floor	45	SF	7	6-10 years	
	Storage Room	1st Floor	56	SF	7	6-10 years	
	Storage Room	1st Floor	190	SF	7	6-10 years	
	Storage Room	1st Floor	255	SF	7	6-10 years	
	Storage Room	1st Floor	650	SF	5	10+ years	Water damage to ceiling tiles
	Janitor's Closet	2nd Floor	25	SF	7	6-10 years	Trate: damage to coming mos
	Mechanical/ Service Rooms	2nd Floor	1,030	SF	7	10+ years	Quantity updated to match current
			,,,,,			, , , , , , , , , , , , , , , , , , , ,	observations
	Storage Room	2nd Floor	406	SF	7	6-10 years	
estroor	n						
-Su UUI	Accessories	1st Floor (120)	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor (120)	34	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor (120)	8	SF	4	1-2 years	Ceiling tile sagging
	Doors - Steel Doors incl hw	1st Floor (120)	1	ĒΑ	6	6-10 years	3 33 3
	Floor - Tile Ceramic/ Porcelain	1st Floor (120)	42	SF	7	10+ years	
	Floor Drain	1st Floor (120)	1	ĒΑ	7	6-10 years	
	Lavatory	1st Floor (120)	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor (120)	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor (120)	74	SF	6	10+ years	
	Walls - Concrete Block	1st Floor (120)	10	SF	5	1-2 years	Water damage, bubbling paint
	Water Closet	1st Floor (120)	1	ĒΑ	6	6-10 years	3 , 3 ,
	Accessories	1st Floor (122)	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor (122)	36	SF	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor (122)	6	SF	4	1-2 years	Water damaged.
	Doors - Steel Doors incl hw	1st Floor (122)	1	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor (122)	42	SF	7	10+ years	
	Floor Drain	1st Floor (122)	1	EΑ	7	6-10 years	
	Lavatory	1st Floor (122)	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor (122)	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor (122)	84	SF	6	10+ years	
	Water Closet	1st Floor (122)	1	EA	6	6-10 years	
	Accessories	1st Floor - Boys Toilet, East	140	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Boys Toilet, East	140	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Boys Toilet, East	140	SF	6	6-10 years	
	Floor Drain	1st Floor - Boys Toilet, East	140	EA	7	6-10 years	
	Hand Dryer	1st Floor - Boys Toilet, East	1	EA	7		
						6-10 years	
	Lavatory	1st Floor - Boys Toilet, East	2	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor - Boys Toilet, East	3	EΑ	7	10+ years	
	Partitions	1st Floor - Boys Toilet, East	1	EA	7	6-10 years	
	Urinals	1st Floor - Boys Toilet, East	3	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor - Boys Toilet, East	352	SF	6	10+ years	
	Water Closet	1st Floor - Boys Toilet, East	1	EA	6	6-10 years	
	Accessories	1st Floor - Boys Toilet, West	125	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Boys Toilet, West	125	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Boys Toilet, West	125	SF	6	10+ years	
	Floor Drain	1st Floor - Boys Toilet, West	1	EA	7	6-10 years	
	Hand Dryer	1st Floor - Boys Toilet, West	1	EA	7	6-10 years	
	Lavatory	1st Floor - Boys Toilet, West	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Boys Toilet, West	4	EΑ	7	10+ years	
	Partitions	1st Floor - Boys Toilet, West	1	EΑ	7	6-10 years	
	Urinals	1st Floor - Boys Toilet, West	2	EΑ	6	6-10 years	
	Walls - Concrete Block	1st Floor - Boys Toilet, West	274	SF	6	10+ years	
	Water Closet	1st Floor - Boys Toilet, West	1	EA	6	6-10 years	
	Accessories	1st Floor - Boys Tollet, West	28	SF	7	6-10 years	
			28	SF	6		
	Ceiling - Lay-in	1st Floor - Principal's Office				10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal's Office	28	SF	6	10+ years	
	Lavatory	1st Floor - Principal's Office	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor - Principal's Office	_1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Principal's Office	75	SF	6	10+ years	
	Water Closet	1st Floor - Principal's Office	1	EA	6	6-10 years	
	Accessories	1st Floor - Staff Washroom (Main Office)	35	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor - Staff Washroom (Main Office)	35	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Staff Washroom (Main Office)	1	EA	6	6-10 years	

Campus Name: Kanoon Page : 12 of 27 Assessment Date: 08/23/2023



Catego	ry : Room		В	uilding	: Main		. 5 :
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st Floor - Staff Washroom (Main Office)	35	SF	6	10+ years	
	Lavatory	1st Floor - Staff Washroom (Main Office)	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor - Staff Washroom (Main Office)	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor - Staff Washroom (Main Office)	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Staff Washroom (Main Office)	77	SF	6	10+ years	
	Water Closet	1st Floor - Staff Washroom (Main Office)	1	EA	6	6-10 years	
	Accessories	1st Floor-Girl's Restroom, West	256	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Girl's Restroom, West	256	SF	6	6-10 years	
	Floor - Tile	1st Floor-Girl's Restroom, West	28	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom, West	228	SF	6	10+ years	
	Floor Drain	1st Floor-Girl's Restroom, West	1	EΑ	7	6-10 years	
	Hand Dryer	1st Floor-Girl's Restroom, West	1	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom, West	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom, West	4	EA	6	10+ years	
	Partitions	1st Floor-Girl's Restroom, West	5	EA	7	-	
				SF		6-10 years	
	Walls - Concrete Block	1st Floor-Girl's Restroom, West	860		6	10+ years	
	Water Closet	1st Floor-Girl's Restroom, West	5	EA	6	6-10 years	
	Accessories	1st Floor-Girl's Restroom, near Classroom 105	110	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Girl's Restroom, near Classroom 105	110	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom, near Classroom 105	110	SF	6	10+ years	
	Floor Drain	1st Floor-Girl's Restroom, near Classroom 105	1	EA	7	6-10 years	
	Hand Dryer	1st Floor-Girl's Restroom, near Classroom 105	1	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom, near Classroom 105	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom, near Classroom 105	4	EA	7	10+ years	
	Partitions	1st Floor-Girl's Restroom, near Classroom 105	4	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor-Girl's Restroom, near Classroom 105	270	SF	6	10+ years	
	Water Closet	1st Floor-Girl's Restroom, near Classroom 105	4	EA	6	6-10 years	
	Accessories	2nd Floor - Boys Toilet	205	SF	7	6-10 years	

Campus Name: Kanoon Page : 13 of 27 Assessment Date: 08/23/2023



• • • • • • • • • • • • • • • • • • • •	y : Room		В	uilding	: wain		
_				_		Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor - Boys Toilet	205	SF	7	6-10 years	
	Floor - Tile	2nd Floor - Boys Toilet	205	SF	7	10+ years	
	Floor Drain	2nd Floor - Boys Toilet	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor - Boys Toilet	1	EA	7	6-10 years	
	Lavatory	2nd Floor - Boys Toilet	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Boys Toilet	3	EA	7	6-10 years	
	Partitions	2nd Floor - Boys Toilet	1	EA	7	6-10 years	
	Urinals	2nd Floor - Boys Toilet	4	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	448	SF	7	10+ years	
	Water Closet	2nd Floor - Boys Toilet	2	EA	7	6-10 years	
	Accessories	2nd Floor-Girl's Restroom	270	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-Girl's Restroom	270	SF	7	6-10 years	
	Floor - Tile	2nd Floor-Girl's Restroom	230	SF	7	10+ years	
	Floor Drain	2nd Floor-Girl's Restroom	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Girl's Restroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor-Girl's Restroom	4	EA	7	6-10 years	
	Partitions	2nd Floor-Girl's Restroom	6	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girl's Restroom	595	SF	7	10+ years	
	Water Closet	2nd Floor-Girl's Restroom	6	EA	7	10+ years	
	Accessories	2nd Floor-Unisex Staff Restroom	25	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor-Unisex Staff Restroom	25	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor-Unisex Staff Restroom	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Unisex Staff Restroom	25	SF	6	6-10 years	
	Lavatory	2nd Floor-Unisex Staff Restroom	1	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Unisex Staff Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	2nd Floor-Unisex Staff Restroom	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor-Unisex Staff Restroom	55	SF	6	10+ years	
	Water Closet	2nd Floor-Unisex Staff Restroom	1	EA	6	6-10 years	
	Accessories	Men - Faculty Lounge	25	SF	7	6-10 years	
	Ceiling - Lay-in	Men - Faculty Lounge	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Men - Faculty Lounge	1	EA SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Men - Faculty Lounge	25		6	10+ years	
	Hand Dryer	Men - Faculty Lounge	1	EΑ	7	6-10 years	
	Lavatory	Men - Faculty Lounge	1	EΑ	6	6-10 years	
	Lighting - Lay-in	Men - Faculty Lounge	1	EΑ	7	10+ years	
	Lighting - Wall Mounted	Men - Faculty Lounge	1	EA	7	10+ years	
	Walls - Concrete Block	Men - Faculty Lounge	80	SF	6	10+ years	
	Water Closet	Men - Faculty Lounge Nurse Office	1 64	EA SF	6	6-10 years	
	Accessories	Nurse Office		SF SF	7	6-10 years	
	Ceiling - Lay-in		54	SF SF	6	6-10 years	Water damage
	Ceiling - Lay-in Doors - Steel Doors incl hw	Nurse Office	10		4	1-2 years	Water damage
	Floor - Tile Ceramic/ Porcelain	Nurse Office Nurse Office	1 64	EA SF	6 6	6-10 years	
	1 1001 - THE CETAITHE/ FUICEIAIT	Nuise Office	04	ЭF	O	10+ years	

Campus Name: Kanoon Page : 14 of 27 Assessment Date: 08/23/2023



Catego	ry : Room		В	uilding	: Main	_	233 O Reazie Avenoe, officago, le 00023
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Floor Drain	Nurse Office	1	EA	7	6-10 years	
	Lavatory	Nurse Office	1	EA	6	6-10 years	
	Lighting - Lay-in	Nurse Office	1	EA	6	10+ years	
	Showers	Nurse Office	1	EA	7	6-10 years	
	Walls - Concrete Block	Nurse Office	164	SF	6	10+ years	
	Water Closet	Nurse Office	1	EA	6	10+ years	
	Accessories	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	120	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	120	SF	7	10+ years	
	Floor Drain	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	1	EA	7	10+ years	
	Hand Dryer	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	1	EA	7	10+ years	
	Lavatory	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	88	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	152	SF	7	10+ years	
	Water Closet	Unisex RR next to Faculty Lounge UNDER CONSTRUCTION	1	EA	7	10+ years	
	Accessories	Women - Faculty Lounge	25	SF	7	6-10 years	
	Ceiling - Lay-in	Women - Faculty Lounge	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Women - Faculty Lounge	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Women - Faculty Lounge	25	SF	6	10+ years	
	Hand Dryer	Women - Faculty Lounge	1	EA	7	6-10 years	
	Lavatory	Women - Faculty Lounge	1	EA	5	1-2 years	Stuck running
	Lighting - Lay-in	Women - Faculty Lounge	1	EA	7	10+ years	
	Lighting - Wall Mounted	Women - Faculty Lounge	1	EA	7	6-10 years	
	Walls - Concrete Block	Women - Faculty Lounge	80	SF	6	10+ years	
	Water Closet	Women - Faculty Lounge	1	EA	6	6-10 years	
Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #105 (Kindergarten)						
	Casework	1st Floor	22	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	725	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	



	Category : Classroom		Bu	uilding	: Main		
Floor Tile 1st Floor 725 SF 6 10+ years							
Lighting - Lay-in	roup Item - Type		Quantity		Rank	Replacement	Comments
Marker Board	Floor - Tile		725	SF	6	10+ years	
Storage Closet	Lighting - Lay-in	1st Floor	15	EΑ	6	10+ years	
Storage Closet	Marker Board	1st Floor	16	LF	7	6-10 years	
Walls - Concrete Block 1st Floor 986 SF 6 10+ years				SF	7		
Work Sink		1st Floor	986	SF	6		
Casework						•	
Casework	classroom #108 (Regular Classroom)						
Ceiling - Lay-in		1st Floor	6	ΙF	6	6-10 years	
Doors - Steel Doors incl hw							
Floor - Tile							
Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 885 SF 6 10+ years Walls - Concrete Block 1st Floor 1 EA 7 6-10 years Work Sink 1st Floor 6 LF 6 6-10 years Classroom #110 (Regular Classroom) 790 SF 6 10+ years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 15 EA 6 10+ years Work Sink 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 1 EA 7 6-10 years Classroom #112 (Regular Classroom) 2 EA 6 10+ years Ceiling - Lay-in 1st Floor							
Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 1 EA 7 6-10 years Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 790 SF 6 10+ years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 1 EA 7 6-10 years Classroom #112 (Regular Classroom) 1 EA 7 6-10 years Ceiling - Lay-in 1st Floor					_	•	
Walls - Concrete Block 1st Floor 885 SF 6 10+ years Classroom #110 (Regular Classroom) Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Walls - Concrete Block 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 885 SF 6 10+ years Classroom #112 (Regular Classroom) 1 EA 7 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 790 SF 6 10+ years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 790 SF <			_		_		
Stassroom #110 (Regular Classroom) Casework						•	
Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 790 SF 6 10+ years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 15 EA 6 10+ years Work Sink 1st Floor 12 LF 7 6-10 years Work Sink 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 EA 7 6-10 years Casework 1st Floor 1 EA 7 6-10 years Casework 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 1 EA 6 6-10 years							
Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 12 LF 7 6-10 years Work Sink 1st Floor 885 SF 6 10+ years Walls - Concrete Block 1st Floor 6 LF 6 6-10 years Casework 1st Floor 790 SF 6 10+ years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor<	Work Sink	1St Floor	1	EA	7	6-10 years	
Ceiling - Lay-in	` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `						
Doors - Steel Doors incl hw					6		
Floor - Tile			790	SF	6	10+ years	
Floor - Tile	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 1 EA 7 6-10 years Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 1st	Floor - Tile	1st Floor	790	SF	6	-	
Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years Work Sink 1st Floor 1 EA 7 6-10 years Classroom #112 (Regular Classroom) Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years	Lighting - Lay-in	1st Floor	15	EA	6	10+ years	
Walls - Concrete Block Work Sink 1st Floor 885 SF 6 10+ years Classroom #112 (Regular Classroom) Casework Ceiling - Lay-in 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in Doors - Steel Doors incl hw 1st Floor 790 SF 6 10+ years Floor - Tile Lighting - Lay-in Marker Board Walls - Concrete Block 1st Floor 15 EA 6 10+ years Walls - Concrete Block 1st Floor 18 LF 7 6-10 years				LF			
Work Sink 1st Floor 1 EA 7 6-10 years Classroom #112 (Regular Classroom) Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years	Walls - Concrete Block				6	•	
Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years						•	
Casework 1st Floor 6 LF 6 6-10 years Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years	classroom #112 (Regular Classroom)						
Ceiling - Lay-in 1st Floor 790 SF 6 10+ years Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years		1st Floor	6	IF	6	6-10 years	
Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years						•	
Floor - Tile 1st Floor 790 SF 6 10+ years Lighting - Lay-in 1st Floor 15 EA 6 10+ years Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years						•	
Lighting - Lay-in1st Floor15EA610+ yearsMarker Board1st Floor18LF76-10 yearsWalls - Concrete Block1st Floor885SF610+ years					-		
Marker Board 1st Floor 18 LF 7 6-10 years Walls - Concrete Block 1st Floor 885 SF 6 10+ years							
Walls - Concrete Block 1st Floor 885 SF 6 10+ years							
			_			•	
Work Sink 1st Floor 1 EA 7 6-10 years							
	vvork Sink	1st Floor	1	ΕA	7	6-10 years	
Classroom #114 (Regular Classroom)	,						
Casework 1st Floor 6 LF 6 6-10 years					6		
Ceiling - Lay-in 1st Floor 790 SF 6 6-10 years			790	SF	6	6-10 years	
Doors - Steel Doors incl hw 1st Floor 1 EA 6 6-10 years		1st Floor		EA	6		
Floor - Tile 1st Floor 790 SF 6 10+ years			790	SF			
Lighting - Lay-in 1st Floor 15 EA 6 10+ years					_		
	<i>3 3 7</i>					·	

Campus Name: Kanoon Page : 16 of 27 Assessment Date: 08/23/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	885	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	1-2 years	Water dripping
Classroc	m #116 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	790	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	790	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	ĒΑ	6	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	885	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #118 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	790	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	15	EA	6	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	510	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	510	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #120 (Kindergarten)						
21000100	Casework	1st Floor	24	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	912	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	912	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	6	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	170	SF	7		
			_			6-10 years	
	Walls - Concrete Block	1st Floor	1,205	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	m #122 (Kindergarten)	4 . =1		. –		0.40	
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,122	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,122	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	29	EA	7	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	170	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,370	SF	6	10+ years	
	Work Sink	1st Floor	1	EΑ	7	6-10 years	
	Work on it	1001	•		•	o ro youro	
Claceroo	om #140 (Art Room)						
JIASSIUU	,	1st Floor	10	LF	6	6.10 voore	
	Casework				6	6-10 years	
	Ceiling - Lay-in	1st Floor	610	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	610	SF	6	6-10 years	
	Kiln	1st Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	1st Floor	17	EA	6	6-10 years	
	Storage/ Closet	1st Floor	208	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,120	SF	6	10+ years	
	Work Sink	1st Floor	4	EA	7	6-10 years	Updated quantity, one more sink in
							storage closet
Classroc	om #144 (Multi Purpose Room)						
	Ceiling - Plaster/Drywall	1st Floor	805	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	6-10 years	
	Floor - Wood	1st Floor	805	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	7	EA	6	10+ years	
	Marker Board	1st Floor	4	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years	
Classroc	om #200 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	15	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	672	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	224	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	TOTA ON IN	2110 1 1001	'	_/ \	,	o io youis	
Claseron	om #201 (Science Classroom)						
Jidaaliuu	Casework	2nd Floor	40	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	905	SF	6	6-10 years 6-10 years	
		2nd Floor 2nd Floor				•	
	Doors - Steel Doors incl hw		1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	905	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,934	SF	6	10+ years	

Campus Name: Kanoon Page : 18 of 27 Assessment Date: 08/23/2023



				uilding	. IVIAIII		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	2nd Floor	3	EA	7	6-10 years	
Classroo	m #202 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	692	SF	6	6-10 years	
	Floor - Tile	2nd Floor	98	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	672	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	224	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
			·		•	0 .0 ,00.0	
lassroo	m #203 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	585	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	585	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,240	SF	6	10+ years	
			·			•	
Classroo	m #204 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	672	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	224	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #205 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	576	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	576	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	768	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	

Campus Name: Kanoon Page : 19 of 27 Assessment Date: 08/23/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	672	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	224	SF	6	10+ years	
	Work Sink	2nd Floor	6	EA	7	6-10 years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	14	EA	6	1-2 years	Re-lamp fixture
	Marker Board	2nd Floor	8	LF	7	•	Re-lamp lixture
				SF		6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	885 1	SF EA	6 7	10+ years 6-10 years	
	Work Sink	211d F1001	1	EA	,	6-10 years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #212 (Counseling Room)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor 2nd Floor	885	SF	6	10+ years	
	Work Sink	2nd Floor	000	EA	7	6-10 years	

Campus Name: Kanoon Page : 20 of 27 Assessment Date: 08/23/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #214 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroc	om #218 (Computer Lab)						
	Casework	2nd Floor	22	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	2	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	8	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,170	SF	6	6-10 years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	835	SF	6	6-10 years	
	Floor - Tile	2nd Floor	345	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	27	EA	6	6-10 years	
			6	LF	6	-	
	Marker Board Walls - Concrete Block	2nd Floor 2nd Floor	985	SF	6	6-10 years	
			290	SF	_	10+ years	
	Walls - Plaster/Drywall	2nd Floor			6	10+ years	
	Wireless System	2nd Floor	1	EΑ	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #220 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
:lassror	om #221 (Multi Purpose Room)						
	Ceiling - Lay-in	2nd Floor	1,428	SF	6	6-10 years	
	Doors - Side-lite	2nd Floor	40	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor 2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor		SF			
	Lighting - Lay-in		1,428		6	6-10 years	
		2nd Floor	27	EA SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,776	or.	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
				<u> </u>		Recommend	
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	-		_			_	
lassroc	m #222 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	Work on it	2.10 1 1001	·	_, ,	•	o io youio	
lassroc	m #224 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
laceroo	m #226 (Regular Classroom)						
JIASSIUU	Ceiling - Lay-in	2nd Floor	790	SF	6	6 10 voore	
	Doors - Steel Doors incl hw					6-10 years 6-10 years	
	Floor - Tile	2nd Floor	1	EA SF	6	•	
		2nd Floor	790		7	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA LF	6	6-10 years	
	Marker Board	2nd Floor	12	SF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
lassroc	m #228 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	895	SF	6	10+ years	
	Walls - Concrete Block	2nd Floor	25	SF	6	6-10 years	
Naaana -							
Jassroc	m #230 (Regular Classroom)	2nd Floor	700	C.		6.10	
	Ceiling - Lay-in		790	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	985	SF	6	10+ years	

Campus Name: Kanoon Page : 22 of 27 Assessment Date: 08/23/2023



Catego	ry : Classroom		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
			4.0				
lassro	om #232 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	622	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	168	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	975	SF	6	10+ years	
Classroo	om #234 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	640	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	150	SF	4	0-1 year	Water damaged tiles
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	Trator damaged mee
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	885	SF	6	10+ years	
			_				
Catego	ry : Interior		В	uilding	: Main		
Catego	ry : Interior		В	uilding	: Main	Recommend	
	ry : Interior Item - Type	Location	B Quantity	uilding	: Main Rank	Recommend Replacement	Comments
Group	Item - Type	Location		_			Comments
Group	Item - Type	Location 1st Floor		_		Replacement	Comments
Group	Item - Type Ceiling - Lay-in		Quantity 5,570	UOM SF	Rank	Replacement 6-10 years	
Group	Item - Type Ceiling - Lay-in Ceiling - Lay-in	1st Floor 1st Floor	Quantity 5,570 50	UOM	Rank 6 4	6-10 years 1-2 years	Comments Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor	Quantity 5,570	UOM SF SF	Rank 6	6-10 years 1-2 years 6-10 years	
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor	Quantity 5,570 50 16 4	UOM SF SF EA EA	6 4 6 7	6-10 years 1-2 years 6-10 years 6-10 years	
Group	Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor	Quantity 5,570 50 16 4 2	SF SF EA	6 4 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years	
Group	Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	5,570 50 16 4 2 5,620	SF SF EA EA	6 4 6 7 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	
Group	Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Quantity 5,570 50 16 4 2	SF SF EA EA EA SF	6 4 6 7 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	
Group	Item - Type Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	5,570 50 16 4 2 5,620 68 28	UOM SF SF EA EA EA EA SF EA	6 4 6 7 7 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 6-10 years	
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block	1st Floor	5,570 50 16 4 2 5,620 68 28 8,460	UOM SF SF EA EA EA SF EA SF EA SF	6 4 6 7 7 7 7 6 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in	1st Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341	UOM SF SF EA EA EA SF EA SF EA SF EA SF SF	6 4 6 7 7 7 7 6 6 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years	Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in	1st Floor 2nd Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30	UOM SF SF EA EA EA SF EA SF SF SF SF	6 4 6 7 7 7 7 6 6 6 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor 2nd Floor 2nd Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10	UOM SF SF EA EA EA SF EA SF EA EA SF SF SF SF	6 4 6 7 7 7 7 6 6 6 6 4 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10 4	UOM SF SF EA EA SF EA SF EA EA SF SF SF EA EA	Rank 6 4 6 7 7 7 6 6 6 4 6 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10 4	UOM SF SF EA EA SF EA EA SF SF SF SF EA EA SF	Rank 6 4 6 7 7 7 6 6 6 4 6 7 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10 4	UOM SF SF EA EA SF EA SF EA EA SF SF SF EA EA	Rank 6 4 6 7 7 7 6 6 6 4 6 7	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years	Water damage
Group Corridor	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10 4 4,371 44	UOM SF SF EA EA SF EA SF SF EA EA SF EA EA SF EA	Rank 6 4 6 7 7 7 6 6 6 7 7 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years	Water damage
Group	Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Water Cooler Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 2nd Floor	5,570 50 16 4 2 5,620 68 28 8,460 4,341 30 10 4 4,371 44	UOM SF SF EA EA SF EA SF SF EA EA SF EA EA SF EA	Rank 6 4 6 7 7 7 6 6 6 7 7 6	6-10 years 1-2 years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years	Water damage

Campus Name: Kanoon Page : 23 of 27 Assessment Date: 08/23/2023



Category : Interior		Building : Main							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Security Cameras	Entire Building	5	EΑ	7	6-10 years			
Stairs									
	Ceiling - Lay-in	North East	210	SF	6	10+ years			
	Floor - Concrete	North East	50	SF	7	6-10 years			
	Floor - Tile	North East	120	SF	7	6-10 years			
	Handrails	North East	64	LF	7	6-10 years			
	Lighting - Lay-in	North East	3	EA	6	6-10 years			
	Lighting - Wall Mounted	North East	1	EA	6	6-10 years			
	Stairs - Concrete	North East	32	LF	6	6-10 years			
	Walls - Concrete Block	North East	1,126	SF	6	10+ years			
	Walls - Plaster/Drywall	North East	216	SF	6	10+ years			
	Ceiling - Lay-in	North West	210	SF	6	6-10 years			
	Floor - Concrete	North West	50	SF	7	6-10 years			
	Floor - Tile	North West	120	SF	7	6-10 years			
	Handrails	North West	64	LF	7	6-10 years			
	Lighting - Lay-in	North West	3	EA	6	6-10 years			
	Lighting - Wall Mounted	North West	1	EA	6	6-10 years			
	Stairs - Concrete	North West	32	LF	6	6-10 years			
	Walls - Concrete Block	North West	1,126	SF	6	10+ years			
	Walls - Plaster/Drywall	North West	216	SF	6	10+ years			
	Ceiling - Lay-in	South West	180	SF	6	10+ years			
	Ceiling - Lay-in	South West	30	SF	4	1-2 years	Water damage		
	Floor - Concrete	South West	50	SF	7	6-10 years	· ·		
	Floor - Tile	South West	120	SF	7	6-10 years			
	Handrails	South West	64	LF	7	6-10 years			
	Lighting - Lay-in	South West	3	EA	6	6-10 years			
	Lighting - Wall Mounted	South West	1	EA	6	6-10 years			
	Stairs - Concrete	South West	32	LF	6	6-10 years			
	Walls - Concrete Block	South West	1,126	SF	6	10+ years			
	Walls - Plaster/Drywall	South West	216	SF	6	10+ years			
\/ortios!	Conveyance					-			
_verucal		1st Floor	4	ΕΛ	6	10 L Voors			
	Elevator - Hydraulic Elevator Wheelchair Lift - Platform Lift	1st Floor 1st Floor	1	EA EA	6 7	10+ years			
	Wileciciali Liit - Flatioiiii Liit	121 11001	I	EA	′	10+ years			



Category : Site **Building: Site**

Categor	y . Site		Bulluling				
0	Name Time	Lasation	0	11084	Danil	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	10+ years	
Fencing							
	Fencing - Guard Rail	Entire Site	30	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	605	LF	7	10+ years	New
	Fencing - New Standard Ornamental	Entire Site	133	LF	4	0-1 year	Confirmed linear feet at Kedzie
							Avenue. Heavily corroded fence wit
							warped steel
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	277	LF	7	10+ years	New
Landscar	oe						
	Benches	Entire Site	7	EA	6	10+ years	
	Landscape - Grass	Entire Site	10,570	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	5,000	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,760	SF	6	10+ years	
	Parkway trees	Entire Site	17	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	200	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	20,900	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
Parking L	ot						
<u> </u>	Concrete Curbs	South Courtyard	638	LF	6	10+ years	
	Surface - Asphalt	South Courtyard	6,500	SF	7	6-10 years	
	Surface - Asphalt	South Courtyard	10,460	SF	4	1-2 years	Alligatoring throughout, large
	Carrage / toprian	Country and	10,100	O.	•	. L youro	potholes, cracks, and several
							depressions with upheaved asphalt
							surface
	Trash Enclosure - Chain Links	South Courtyard	150	SF	6	10+ years	
		·				•	
Playgrou							
	Equipment - Combo 3-12	NE Courtyard	1	EA	4	2-5 years	Obsolete, dirty equipment with
							missing pieces
	Surface - Poured Surface	NE Courtyard	2,650	SF	4	1-2 years	Large cracks and holes throughout
0.1							
Sidewalk	s Sidewalks - Internal Walks	Entire Site	460	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	20	LF	4	1-2 years	Upheaved sidewalk sections, near
	Sidewains - Iliterilai Wains	Little Site	20	LF	4	1-2 years	play area
	Sidewalks - Perimeter Sidewalks	Entire Site	10,570	SF	6	10+ years	play alea
	Oldowallto - I Gillietel Oldewallto	Littie Oile	10,570	Oi.	U	10+ years	
	Sidewains - Ferifficiel Sidewains	LIMITE SILE	10,370	ЗF	Ü	IUT YEAIS	

Campus Name: Kanoon Page : 25 of 27 Assessment Date: 08/23/2023



Gerald Delgado Kanoon Elementary Magnet School

2233 S Kedzie AVENUE, Chicago, IL 60623

Category : Site			В	uilding :	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	4	1-2 years	Upheaved, broken sidewalk
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Kanoon Page: 26 of 27 Assessment Date: 08/23/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classicolli Sullillary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	1st Floor	140	NA	610	0	0	N	Υ
Computer Lab	Regular Classroom	2nd Floor	218	NA	1,180	184	20	N	N
Counseling Room	Regular Classroom	2nd Floor	212	NA	790	90	10	N	N
Kindergarten	Kindergarten	1st Floor	120	120	912	90	10	N	N
Kindergarten	Kindergarten	1st Floor	122	122	1,122	90	10	N	N
Kindergarten	Other Instructional Use	1st Floor	105	Parent's Room	725	0	0	N	Y
Multi Purpose Room	Gymnasium	1st Floor	144	Handball Court	805	0	0	N	N
Multi Purpose Room	Special Program	2nd Floor	221	221	1,428	200	0	N	N
Regular Classroom	Computer Lab	2nd Floor	203	NA	585	106	20	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	NA	790	90	10	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	790	90	10	N	N
Regular Classroom	Regular Classroom	1st Floor	112	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	1st Floor	114	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	1st Floor	116	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	1st Floor	118	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	576	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	790	90	10	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	NA	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	NA	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	NA	790	90	10	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	NA	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	224	NA	790	90	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	NA	790	90	5	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	228	228	790	76	2	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	230	230	790	0	0	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	232	NA	790	0	0	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	234	NA	790	90	10	N	Υ
Science Classroom	Science Classroom	2nd Floor	201	201	905	90	10	N	Υ