

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1894	3	33,297
Addition	1953	2	58,876
Campus Total			92,173

Catego	ry : Exterior		В	uilding	: Main	Building : Main				
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Entrance	1									
	Exterior Doors - Exterior Steel Door	13	1	EA	4	1-2 years	Corroding door and frame			
	Exterior Doors - Transom Lite	13	1	EA	6	6-10 years	•			
	Exterior Doors - Exterior FRP Door	6 - East	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	6 - East	2	EA	6	6-10 years				
	Exterior Stairs - Concrete	6 - East	6	LF	5	1-2 years	Cracked concrete			
	Entrance Control - Audio and Video	7 - North	1	EA	6	2-5 years				
	Exterior Doors - Exterior FRP Door	7 - North	2	EA	6	6-10 years				
	Exterior Doors - Transom Lite	7 - North	2	EA	6	6-10 years				
Foundati	on									
	Foundation - Concrete	Entire Building	358	LF	7	10+ years				
	Foundation - Masonry	Entire Building	10	LF	6	10+ years				
	Superstructure - Heavy Timber	Entire Building	35,896	SF	7	10+ years				
	Superstructure - Steel with Clay Tile Arch	Entire Building	330	SF	7	10+ years				
Lighting										
0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	2-5 years				
Roof Sys	stem									
	Access Ladder - Metal	A	1	EA	4	0-1 year	Ladder shakes when you climb up.			
	Access Ladder - Wood	A	1	EA	5	2-5 years	, ,			
	Coping - Metal	A	186	LF	6	6-10 years				



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Roof - Metal	A	125	SF	7	10+ years	
	Roof - Modified Bitumen	Α	50	SF	5	1-2 years	Open seams
	Roof - Modified Bitumen	Α	1,965	SF	5	2-5 years	·
	Roof Hatch - Metal	Α	1	EA	4	2-5 years	Old hatch with small opening
	Roof Structure - Heavy Timber	Α	2,090	SF	7	10+ years	
	Downspouts - Exterior Downspouts	В	224	LF	6	6-10 years	
	Roof - Metal	В	6,512	SF	6	10+ years	
	Roof Structure - Heavy Timber	В	6,512	SF	7	10+ years	
	Coping - Metal	С	110	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	С	30	LF	6	6-10 years	
	Roof - Modified Bitumen	C	496	SF	6	6-10 years	
	Roof Structure - Heavy Timber	C	496	SF	7	10+ years	
	Coping - Terra Cotta	D	52	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	D	16	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	D	12	LF	5	1-2 years	Missing section of downspout
	Parapet - Parapet < 16" Height	D	52	LF	6	10+ years	impoing deduction of downloads
	Roof - Modified Bitumen	D	330	SF	5	2-5 years	Worn out roof, some vegetation
	rtoor mouniou Bitamen		000	O.	Ŭ	20 ,00.0	growth
	Roof Structure - Steel with Clay Tile Arch	D	330	SF	7	10+ years	g.o.u
	The conditions of the conditio	_		О.	•	.o. you.o	
Valls							
	Cornice - Metal Projecting	Entire Building	323	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	13,548	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	225	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	2,000	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	288	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	100	SF	6	10+ years	
		g		О.	· ·	.o. you.o	
Vindows	3						
	Guard - Guards perforated	Entire Building	536	SF	6	6-10 years	
	Lintels - Brick	Entire Building	79	LF	6	6-10 years	
	Lintels - Stone	Entire Building	244	LF	6	6-10 years	
	Windows - Insulated Panel	Entire Building	36	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	485	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,939	SF	3	1-2 years	Balancers not working
			_				
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System	Loudion	Quantity	00111	Rain	Replacement	Comments
-merger	Exit Signs - Corridors and Stairs	Entire Building	17	EA	5	2-5 years	
	Emergency Battery Packs - Corridors and	Entire Building	18	EA	6	6-10 years	
	Emergency Dattery r dons - Comitons and	Little Dallality	10		U	U- IU VEAIS	



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Stairs	Location	Quantity	COM	IXAIIX	Replacement	Comments
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	33,297	SF	6	6-10 years	Served by addition
	Security System - Intrusion Detection	Entire Building	33,297	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	4,372	SF	6	10+ years	
	Stairs	3	, -			, , , , , ,	
	Emergency A/C Power - Students Toilets	Entire Building	3,537	SF	6	10+ years	
Main Se	rvice						
	PA System	Entire Building	36,226	SF	6	2-5 years	Served by addition
	Independent Electrical Service for	Mechanical Room	1	EA	6	6-10 years	Fire Pump
	emergency power	West and Tree in	•	_, .	Ü	o ro youro	The Camp
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	2-5 years	
Catego	ry : Fire Protection		B	uilding	· Main		
Calego	ry . I lie i lotection			unung	. Iviaiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	33,297	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	33,297	SF	7	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	7	10+ years	
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp	Pump Room	1	EA	6	6-10 years	
Consideration	2 Country of						
<u>obnukie</u> i	<u>r System</u> Dry Sprinkler System	Entire Building	36,226	SF	4	2-5 years	Over 50 years old, requires very long
	Dry Spillikier System	Entire Building	30,220	SF	4	2-5 years	hose to be laid through basement to outside just for testing
	Sprinkler Heads	Entire Building	36,226	SF	7	6-10 years	outside just for testiffy
	Sprinkler Piping	Entire Building	36,226	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems Air Handling Unit- Built Up-Multi Zone-			EA	6		
		Basement	1			6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake	Basement	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Basement		EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	6	6-10 years	
	Zone Dampers	Basement	23	EA	6	6-10 years	
Boiler S	ystems						
	Condensate Pump	Entire Building	1	EA	5	2-5 years	
	Condensate Pump	Entire Building	1	EΑ	5	2-5 years	
	Piping - Condensate Pipe- Steel	Entire Building	125	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Entire Building	125	LF	6	6-10 years	
	Steam Traps	Entire Building	12	EA	5	6-10 years	
Heating	Devices						
	Unit Heater - Electric	3rd Floor	1	EA	6	6-10 years	
	Cabinet Heaters - With Electric Coil	Elevator Equipment Room	1	EΑ	5	2-5 years	
	PTAC - Electric Heating and Self Contained Cooling	Elevator Equipment Room	1	EA	6	6-10 years	
	Radiators - Steam	Entire Building	6	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	17	EA	5	2-5 years	
Temper	ature Control						
•	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Pneumatic System	Entire Building	32,297	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	14	EA	5	2-5 years	
Ventilati	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Lower Roof	1	EA	5	2-5 years	

Category: Plumbing Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	2-5 years	
Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	36,226	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	36,226	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	36,226	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	36,226	SF	6	2-5 years	



Catego	ry : Plumbing		В	uilding	: Main			<u>, </u>
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	36,226	SF	6	2-5 years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,226	SF	6	2-5 years		
	Sanitary Piping	Entire Building	36,226	SF	5	2-5 years		
	Storm Piping	Entire Building	36,226	SF	5	2-5 years		
	Vent Piping	Entire Building	36,226	SF	5	2-5 years		
Pumps								
	Pumps - Sump-Simplex	Under elevator	1	EA	6	6-10 years		

			Building : Main						
						Recommend			
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ministra	tive Suites/Offices								
	AC Unit	220 Teachers Lounge	1	EA	7	6-10 years			
(Ceiling - Plaster/Drywall	220 Teachers Lounge	685	SF	6	10+ years			
	Doors - Wood Doors inclu hw	220 Teachers Lounge	1	EA	7	10+ years			
	Floor - Tile	220 Teachers Lounge	685	SF	4	1-2 years	Cracked throughout		
	Lighting - Pendent/Surface	220 Teachers Lounge	15	EA	7	10+ years	•		
	Power Distribution	220 Teachers Lounge	10	EA	7	10+ years			
;	Storage/ Closet	220 Teachers Lounge	184	SF	7	10+ years			
	Walls - Plaster/Drywall	220 Teachers Lounge	704	SF	6	10+ years			
	AC Unit	Branch Office 1st Floor	1	EA	5	2-5 years			
(Ceiling - Plaster/Drywall	Branch Office 1st Floor	640	SF	7	10+ years			
	Doors - Transom Window	Branch Office 1st Floor	14	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Branch Office 1st Floor	1	EA	7	10+ years			
	Floor - Carpet	Branch Office 1st Floor	640	SF	6	6-10 years			
	Lighting - Pendent/Surface	Branch Office 1st Floor	12	EA	7	10+ years			
	Power Distribution	Branch Office 1st Floor	8	EA	7	10+ years			
;	Storage/ Closet	Branch Office 1st Floor	10	SF	7	10+ years			
,	Walls - Plaster/Drywall	Branch Office 1st Floor	1,332	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Copy Room #1 at .5 Level	500	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Copy Room #1 at .5 Level	1	EA	7	10+ years			
	Floor - Tile	Copy Room #1 at .5 Level	500	SF	7	10+ years			
	Lighting - Wall Mounted	Copy Room #1 at .5 Level	6	EA	7	10+ years			
	Power Distribution	Copy Room #1 at .5 Level	10	EA	7	10+ years			
,	Walls - Masonry	Copy Room #1 at .5 Level	136	SF	7	10+ years			
,	Walls - Plaster/Drywall	Copy Room #1 at .5 Level	552	SF	6	10+ years			
	al/ Service Rooms								
,	Janitor's Closet	1F, 2F, 3F Janitorial Closets	60	SF	7	1-2 years	Extensive paint peeling and water		

Campus Name: Lasalle II Page : 5 of 40 Assessment Date: 08/03/2023



tego	ry : Room		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							damage
	Janitor's Closet	1F, 2F, 3F Janitorial Closets	60	SF	5	1-2 years	Extensive water damage and
							cracking
	Janitor's Closet	1F, 2F, 3F Janitorial Closets	60	SF	5	10+ years	
	Storage Room	Basement	225	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,000	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	200	SF	7	10+ years	
stroon	n						
	Accessories	122A Branch Office Restroom 1st Fl.	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	122A Branch Office Restroom 1st Fl.	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	122A Branch Office Restroom 1st Fl.	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	122A Branch Office Restroom 1st Fl.	45	SF	7	10+ years	
	Lavatory	122A Branch Office Restroom 1st Fl.	1	EA	7	10+ years	
	Lighting - Pendent/Surface	122A Branch Office Restroom 1st Fl.	1	EA	7	10+ years	
	Walls - Plaster/Drywall	122A Branch Office Restroom 1st Fl.	170	SF	6	10+ years	
	Water Closet	122A Branch Office Restroom 1st Fl.	1	ĒΑ	7	10+ years	
	Accessories	220A - Faculty 2nd Floor	62	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	220A - Faculty 2nd Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	220A - Faculty 2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	220A - Faculty 2nd Floor	62	SF	6	10+ years	
	Lavatory	220A - Faculty 2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	220A - Faculty 2nd Floor	1	EA	6	10+ years	
	Partitions	220A - Faculty 2nd Floor	1	EA	5	10+ years	
	Walls - Plaster/Drywall	220A - Faculty 2nd Floor	272	SF	6	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	220A - Faculty 2nd Floor	180	SF	6	-	
				SF		10+ years	Tiles missing and fallin
	Walls - Tile Ceramic/ Porcelain	220A - Faculty 2nd Floor	8		4	1-2 years	Tiles missing and fallin
	Water Closet	220A - Faculty 2nd Floor	1	EA	6	10+ years	
	Accessories	320A	96	SF	5	6-10 years	B. 41
	Ceiling - Splined	320A	66	SF	6	6-10 years	Missing tiles
	Ceiling - Splined	320A	30	SF	4	1-2 years	Missing tiles
	Doors - Wood Doors inclu hw	320A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	320A	84	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	320A	12	SF	5	1-2 years	Missing tiles
	Lavatory	320A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	320A	1	EA	6	10+ years	
	Walls - Plaster/Drywall	320A	130	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	320A	213	SF	6	10+ years	
	Water Closet	320A	1	EA	6	10+ years	
	Accessories	Boys - Basement	528	SF	7	6-10 years	Updated to match current observations
	Ceiling - Plaster/Drywall	Boys - Basement	528	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys - Basement	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys - Basement	528	SF	6	10+ years	



Recommend

nissing tiles
1

Building: Main Category : Classroom

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #120 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	990	SF	6	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	990	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	Re-lamp fixture
	Lighting - Pendent/Surface	1st Floor	2	EA	6	1-2 years	Missing bulbs
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years	
	Marker Board	1st Floor	32	LF	6	6-10 years	
	Storage/ Closet	1st Floor	90	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,306	SF	6	10+ years	
Classro	om #121 (Store Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	878	SF	6	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	869	SF	6	10+ years	
	Floor - Tile	1st Floor	9	SF	4	0-1 year	Chipping tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	

Campus Name: Lasalle II Page : 7 of 40 Assessment Date: 08/03/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	Re-lamp fixture
	Lighting - Pendent/Surface	1st Floor	1	EA	6	1-2 years	No bulbs
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	162	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,508	SF	6	10+ years	
Classroo	m #123 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	6	10+ years	
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	780	SF	4	0-1 year	Chipping, hole through tile to subfloor
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	Chipping, note through the to subhoof
	Marker Board	1st Floor	32	LF	6	6-10 years	
	Storage/ Closet	1st Floor	156	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,330	SF	6	•	
	walls - Plaster/Drywall	TSI FIOOI	1,330	SF	б	10+ years	
Classroo	m #124 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	940	SF	4	0-1 year	Large cracks, part of ceiling falling
	Doors - Transom Window	1st Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	940	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,448	SF	4	0-1 year	Large cracking
Classroo	m #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Chipped tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	Onipped tiles
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor		SF	7		
			165			10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,480	SF	6	10+ years	
Classroo	m #222 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	605	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		, ,
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	605	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,290	SF	6	10+ years	
_Classroo	om #223 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	165	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	1,450	SF	6	10+ years	
			,			,	
_Classroo	om #224 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	938	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	156	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,332	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	4	0-1 year	Large cracks
Classroo	om #320 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	870	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	870	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,476	SF	6	10+ years	
Classro	om #321 (Regular Classroom)						
Ciassiul	AC Units	3rd Floor	1	EA	7	6-10 years	
	AC UIIIS	SIU FIOOI	1	ĽΑ	,	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		146 N HOHOLE STREET, CHICAGO, IL 60622
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,465	SF	6	10+ years	
Classroo	om #322 (Other Instructional Use)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	650	SF	6	10+ years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	650	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,376	SF	6	10+ years	
Classroo	om #323 (Store Room)						
	Casework	3rd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	1-2 years	Finish installation
	Doors - Transom Window	3rd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,460	SF	6	10+ years	
Classroo	om #324 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	2-5 years	Deficiency fixed
	Ceiling - Plaster/Drywall	3rd Floor	938	SF	6	10+ years	•
	Doors - Transom Window	3rd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
		3rd Floor		SF	7	•	
	Storage/ Closet	310 F1001	156	ЭF	1	10+ years	



ategor	y : Classroom			Building	: Main	_	
	Ham Toma	Landin	0	HOM	Devi	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #B-2 (Art Room)						
	AC Units	Basement	1		7	6-10 years	
	Casework	Basement	6		6	6-10 years	
	Ceiling - Lay-in	Basement	832		6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	6-10 years	
	Floor - Tile	Basement	832	SF	6	6-10 years	Updated to match current
	Lighting - Lay-in	Basement	12	EA	6	6-10 years	observations
	Storage/ Closet	Basement	313		7	10+ years	
	Walls - Plaster/Drywall	Basement	744		6	10+ years	
	Work Sink	Basement	3		7	6-10 years	
ategor	y : Interior		ı	Building	: Main		
	•			J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Plaster/Drywall	1st Floor	1,085		6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2		6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2		7	6-10 years	
	Floor - Wood	1st Floor	1,085		7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10		7	10+ years	
	Student Lockers - Two Tiers	1st Floor	33		7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,620		6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,095		7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2		7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	230		5	10+ years	
	Floor - Wood	2nd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10		7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	52		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,622		6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,067		7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2		5	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,067	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	58	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,615	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10		5	1-2 years	Cracked plaster and peeling paint
	Ceiling - Exposed	Basement	1,125		7	10+ years	
	Doors - Steel Doors incl hw	Basement	, 2	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	Basement	1		7	10+ years	Updated quantity
	Floor - Asphalt Floor	Basement	1,125		6	10+ years	. ,
	Lighting - Pendent/Surface	Basement	10		6	10+ years	



Catego	ry : Interior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement	1,725	SF	7	10+ years	
Safety							
•	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	5	EΑ	7	6-10 years	
	Security Cameras	Entire Building	32	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	2,490	SF	7	10+ years	
	Floor - Tile	North	2,490	SF	7	10+ years	
	Handrails	North	165	LF	7	10+ years	
	Lighting - Pendent/Surface	North	9	EΑ	7	10+ years	
	Stairs - Tile	North	60	LF	7	10+ years	
	Walls - Plaster/Drywall	North	4,330	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East	1,985	SF	7	10+ years	
	Floor - Tile	South East	1,985	SF	7	10+ years	
	Handrails	South East	142	LF	5	10+ years	
	Lighting - Pendent/Surface	South East	9	EΑ	7	10+ years	
	Stairs - Tile	South East	90	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	3,845	SF	7	10+ years	
Vertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	





Category : Exterior **Building: Addition**

OdicyOry . Exterior		_		. Additiv	Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance		·			_	
Entrance Control - Audio	1	1	EA	5	2-5 years	
Exterior Doors - Exterior FRP Door	1	4	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	i 1	4	EΑ	6	6-10 years	
Exterior Stairs - Concrete	1	100	LF	5	1-2 years	Cracked concrete
Ramp Handrail - Steel_Ramp Handrail	1	60	LF	6	6-10 years	Gracitos concrete
Ramps - Concrete	1	30	LF	6	6-10 years	
Stair Handrail - Steel_Stair Handrail	i	16	LF	6	6-10 years	
Exterior Doors - Exterior FRP Door	10	1	EA	7	10+ years	
Exterior Stairs - Concrete	10	4	LF	5	1-2 years	cracked concrete
Exterior Stairs - Steel or Aluminum	10	8	LF	5	6-10 years	ordened correlate
Stair Handrail - Steel_Stair Handrail	10	10	LF	6	6-10 years	
Exterior Doors - Exterior Steel Door	11 - Basement	1	EA	6	6-10 years	
Exterior Stairs - Concrete	11 - Basement	68	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	11 - Basement	22	LF	6	10+ years	
Exterior Doors - Exterior FRP Door	12	1	ĒΑ	6	6-10 years	
Exterior Doors - Exterior FRP Door	2	2	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	2	4	EA	6	6-10 years	
Exterior Stairs - Stone	2	30	LF	6	10+ years	
Exterior Stairs - Stone	2	10	LF	5	1-2 years	Cracked stone
Stair Handrail - Steel_Stair Handrail	2	10	LF	6	10+ years	Crucked storie
Exterior Doors - Exterior FRP Door	3	2	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	3	4	EΑ	6	6-10 years	
Exterior Stairs - Concrete	3	40	LF	6	10+ years	
Stair Handrail - Steel_Stair Handrail	3	30	LF	7	10+ years	
Exterior Doors - Exterior FRP Door	4	2	EΑ	6	6-10 years	
Exterior Doors - Transom Lite	4	2	ĒΑ	6	6-10 years	
Exterior Stairs - Concrete	Δ	16	LF	5	1-2 years	Cracked concrete steps and landing
Ramps - Concrete	Δ	20	LF	6	10+ years	Cracked correlate stope and landin
Stair Handrail - Steel_Stair Handrail	4	10	LF	6	6-10 years	
Exterior Doors - Exterior FRP Door	5 - North	2	ĒΑ	6	6-10 years	
Exterior Stairs - Concrete	5 - North	16	LF	6	10+ years	
Exterior Doors - Exterior FRP Door	8 - North	1	EA	6	6-10 years	
Exterior Stairs - Concrete	8 - North	3	LF	6	10+ years	
Exterior Stairs - Concrete Exterior Doors - Exterior FRP Door	9 - North	3 1	EA	6	6-10 years	Lintel has been repaired
Exterior Stairs - Concrete	9 - North	3	LF	6	10+ years	Linter has been repaired
Exterior Stairs - Contrete	9 - 1101111	3	LI	O	10+ years	
oundation						
Foundation - Concrete	Entire Building	1,030	LF	7	10+ years	
Superstructure - Concrete	Entire Building	58,876	SF	7	10+ years	
ighting						



atego	ry : Exterior		В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	2-5 years	Older fixture
oof Sys	stem						
	Coping - Metal	E	100	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	E	15	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Ē	16	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Ē	100	LF	6	10+ years	
	Roof - Modified Bitumen	Ē	600	SF	5	-	
						2-5 years	
	Roof Structure - Concrete	E	600	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	F	52	LF	7	10+ years	
	Coping - Stone	F	160	LF	6	10+ years	
	Downspouts - Interior Downspouts	F	53	LF	6	6-10 years	
	Parapet - 16" - 30" Height	F	155	LF	6	10+ years	
	Parapet - Parapet > 30"	F	5	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	F	3,075	SF	5	2-5 years	Blistering throughout, deteriorated
	1001 - Aspirali Gravei Ballast	•	3,073	OI.	3	2-5 years	sealant at flashing
	Roof - Asphalt Gravel Ballast	F	125	SF	2	1-2 years	No ballast, leaking to classrooms below
	Roof Structure - Concrete	F	3,200	SF	7	10+ years	25.511
	Access Ladder - Metal	G	2	EA	4	0-1 year	Engineer has noted that the ladde are loose, outdated, and there is a dangerous transition between the ceiling and the roof itself. There is also no floor support only drywall.
	Access Ladder - Metal	G	6	EA	3	2-5 years	Only two ladders seen
	Coping - Metal	G	516	LF	6	6-10 years	,
	Coping - Metal	G	6	LF	4	1-2 years	Smashed coping, open seams
	Coping - Stone	G	336	LF	6	10+ years	Citiastica coping, open scams
	Downspouts - Interior Downspouts	G	1	LF	6	10+ years	Misalignment is not affecting drainage
	Downspouts - Interior Downspouts	G	148	LF	6	10+ years	
	Parapet - 16" - 30" Height	G	337	LF	6	10+ years	
	Parapet - 16" - 30" Height	G	5	LF	5	10+ years	
	Parapet - Parapet < 16" Height	G	516	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	G	23,538	SF	4	2-5 years	Open seams at parapet, bolstered
	Roof - Asphalt Gravel Ballast	G	1,000	SF	3	1-2 years	roof, deteriorated sealant at flashing Soft spots throughout the roof
							Son spois unoughout the roof
	Roof - Metal	G	80	SF	6	6-10 years	
	Roof Hatch - Metal	G	4	EA	5	2-5 years	
	Roof Structure - Concrete	G	24,538	SF	7	10+ years	

Page: 14 of 40 Campus Name: Lasalle II Assessment Date: 08/03/2023



Catego	ry : Exterior		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Valls							
VOIIO	Canopy - Concrete/ Stucco	Entire Building	80	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	12	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	12	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	17,825	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,400	SF	4	1-2 years	Open joints @ perimeter, above
	Exterior Wallo Briok	Entire Ballating	1,100	O.	•	1 2 youro	windows, typically
	Exterior Walls - Brick	Entire Building	300	SF	4	1-2 years	Spalled brick, Open joints @ perimeter, above windows, typicall
	Exterior Walls - Stone-Cut	Entire Building	300	SF	6	10+ years	permitter, above rimidente, typicam
	Exterior Walls - Terra Cotta	Entire Building	300	SF	6	10+ years	
	Zatorior Walle Forma Coda	Littiio Ballallig	333	0.	Ü	io: youro	
/indows		F (0.440				
	Guard - Guards perforated	Entire Building	3,142	SF	6	10+ years	
	Lintels - Concrete	Entire Building	24	LF	6	10+ years	
	Lintels - Steel	Entire Building	1,090	LF	6	2-5 years	Minor corrosion, verified
	Lintels - Stone	Entire Building	27	LF	6	10+ years	
	Windows - Decorative	Entire Building	49	SF	6	6-10 years	
	Windows - Insulated Panel	Entire Building	432	SF	6	6-10 years	
	Windows - Louver	Entire Building	56	SF	6	6-10 years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	1,269	SF	6	6-10 years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	2,057	SF	6	6-10 years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	4,900	SF	3	1-2 years	Broken balancers
	·	Littiio Ballallig				•	Dienen Balaneere
atego	ry : Electrical		В	uilding	: Additi		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_	ncy System		,				
-	Exit Signs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	22	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	6	6-10 years	
	Security System - CCTV	Entire Building	58,876	SF	6	6-10 years	
	OFCULIA OASIELLI - COLLA	5 5 4 11 4 11 19		SF	6	6-10 years	
		Entire Building	58 876	O.L.			
	Security System - Intrusion Detection	Entire Building	58,876 13,827			<u>-</u>	
	Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs	Entire Building	58,876 13,827	SF	6	10+ years	
	Security System - Intrusion Detection Emergency A/C Power - Corridors and		,			<u>-</u>	

Campus Name: Lasalle II Page : 15 of 40 Assessment Date: 08/03/2023



Catego	ry : Electrical		В	uildina	: Addition		146 N Horiore STREET, Chicago, IL 60622
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Students Toilets	Entire Building	3,682	SF	7	10+ years	
Main Se	rvice						
	Main Electrical Service- Live Front - 2000 A 120/208/3PH	Electrical Room	1	EA	4	2-5 years	Live front
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	2-5 years	
	PA System	Entire Building	58,876	SF	6	2-5 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	2-5 years	Live front
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	4	2-5 years	Live front
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	58,876	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	58,876	SF	5	6-10 years	
	File Alaini_System	Entire Building	56,676	SI	3	0-10 years	
Catego	ry : Mechanical		В	uilding	: Addition		
Group	Itom - Typo	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Air Cond	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments
All Conc	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	10+ years	
	Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted	Lunchroom	1	EA	6	6-10 years	
	Compressor - Less than 3 tons Heat Pump- Floor Mounted- Electric Heating	Lunchroom	1	EA	6	6-10 years	
	& DX Cooling- Remote Mounted Compressor - Less than 3 tons	Lanomoon	!	LA	J	o io years	
	Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted	Lunchroom	1	EA	6	6-10 years	
	Compressor - Less than 3 tons						

Page : 16 of 40 Campus Name: Lasalle II Assessment Date: 08/03/2023



Catego	ry : Mechanical		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Compressor - Less than 3 tons						
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Dual	Entire Building	1	EA	5	2-5 years	
	Temperature Coil	3			-	, , , , , ,	
	Fan Coil Unit- Celing Mounted - Dual	Entire Building	1	EA	5	2-5 years	
	Temperature Coil	G				•	
	Fan Coil Unit- Celing Mounted - Dual	Entire Building	1	EΑ	5	2-5 years	
	Temperature Coil	· ·				•	
	Fan Coil Unit- Celing Mounted - Dual	Entire Building	1	EA	5	2-5 years	
	Temperature Coil						
	Indoor Return Fans- Centrifugal Squirrel	Gym	1	EA	5	2-5 years	
	Cage - 10001 - 20000 CFM						
	Air Handling Unit- Package Multi Zone-	Gym	1	EA	6	6-10 years	
	Indoor- Steam Coils - 6000-10000 cfm						
	Air Intake	Gym	1	EA	6	6-10 years	
	Zone Dampers	Gym	7	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/	Mechanical Room	1	EA	6	10+ years	
	Air Tunnel- Steam Coils - 25001 - 35000 cfm						
	Air Intake	Mechanical Room	1	EA	6	2-5 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	9	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	6	10+ years	
	Missing or Existing Shaft				-	, , , , ,	
	Zone Dampers	Mechanical Room	23	EA	6	6-10 years	
	·					-	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 151 - 200 HP	5 " 5			_	4.0	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EΑ	6	6-10 years	
	Condensate Pump	Boiler Room	1	EΑ	5	2-5 years	
	Condensate Pump	Boiler Room	1	EΑ	5	2-5 years	
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 151 - 200 HP					-	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	50	EΑ	5	6-10 years	

Campus Name: Lasalle II Page : 17 of 40 Assessment Date: 08/03/2023



- Type um Pump			unung	: Addition	on	
			_		Recommend	
ım Pump	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Room	2	EA	6	10+ years	
Booster	Boiler Room	2	EA	6	6-10 years	
3						
tors - Steam	Entire Building	6	EA	6	6-10 years	
Heater - Electric	Entire Building	12	EA	5	2-5 years	
et Heaters - With Steam Coil	Entire Building	14	EA	6	6-10 years	
ontrol						
matic System	Entire Building	61,088	SF	5	6-10 years	
nostats - Pneumatic	Entire Building	46	EA	5	2-5 years	
entilators- Floor Mounted- Steam og Coils Only	Entire Building	16	EA	5	2-5 years	
ust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	Based on last assessment
ust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	
ust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	5	2-5 years	
ust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	10+ years	
ust Fans- Roof Mounted - 1501 - 8000	Entire Building	3	EA	5	6-10 years	
ust Fans- Roof Mounted - 500 - 1500	Entire Building	4	EA	3	0-1 year	No longer in use
II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
umbing		В	uilding	: Additio	on	
					Recommend	
- Туре	Location	Quantity	UOM	Rank	Replacement	Comments
1					40	
Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EΑ	6	10+ years	
Heater - 150000 - 300000 BTU/HR /ater Storage Tank_Gas - Less than	Boiler Room Boiler Room	1 2	EA EA	6 4	6-10 years 2-5 years	Old and deteriorating
Callons						
	Entire Building	58,876	SF	6	2-5 years	
					s	s

Campus Name: Lasalle II Page: 18 of 40 Assessment Date: 08/03/2023



Catego	ry : Plumbing		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	58,876	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	58,876	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	58,876	SF	6	2-5 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	58,876	SF	6	2-5 years	
	Sanitary Piping	Entire Building	58,876	SF	5	2-5 years	
	Storm Piping	Entire Building	58,876	SF	5	2-5 years	
	Vent Piping	Entire Building	58,876	SF	5	2-5 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	

Category: Room **Building: Addition**

aicgo	ry . ixooiii			۳ع	. Additi	•	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Plaster/Drywall	209A Teacher's Resource Office	243	SF	7	10+ years	
	Doors - Wood Doors inclu hw	209A Teacher's Resource Office	1	EA	6	10+ years	
	Floor - Carpet	209A Teacher's Resource Office	243	SF	7	6-10 years	
	Lighting - Pendent/Surface	209A Teacher's Resource Office	4	EΑ	7	10+ years	
	Power Distribution	209A Teacher's Resource Office	4	EΑ	7	10+ years	
	Walls - Concrete Block	209A Teacher's Resource Office	680	SF	7	10+ years	
	Ceiling - Plaster/Drywall	209B Teacher's Resources Office	333	SF	7	10+ years	
	Doors - Wood Doors inclu hw	209B Teacher's Resources Office	1	EA	6	10+ years	
	Floor - Tile	209B Teacher's Resources Office	333	SF	7	10+ years	
	Lighting - Pendent/Surface	209B Teacher's Resources Office	5	EΑ	7	10+ years	
	Power Distribution	209B Teacher's Resources Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	209B Teacher's Resources Office	696	SF	7	10+ years	
	Ceiling - Splined	Kitchen Office	68	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Office	68	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Office	1	EΑ	7	10+ years	
	Power Distribution	Kitchen Office	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Office	280	SF	6	10+ years	
	AC Unit	Main Office	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	368	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	6-10 years	
	Floor - Carpet	Main Office	186	SF	6	6-10 years	
	Floor - Tile	Main Office	182	SF	7	6-10 years	

Campus Name: Lasalle II Page : 19 of 40 Assessment Date: 08/03/2023



Category : Room			В	uilding	: Additi	on	-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Main Office	8	EA	7	10+ years	
	Power Distribution	Main Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office	560	SF	7	10+ years	
	AC Unit	Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	180	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office	180	SF	6	6-10 years	
	Lighting - Pendent/Surface	Principal's Office	4	EA	7	10+ years	
	Power Distribution	Principal's Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	380	SF	7	10+ years	
	AC Unit	Rm 111 - Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Rm 111 - Assistant Principal	333	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Rm 111 - Assistant Principal	1	EA	7	6-10 years	
	Floor - Tile	Rm 111 - Assistant Principal	333	SF	7	6-10 years	
	Lighting - Pendent/Surface	Rm 111 - Assistant Principal	5	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	Rm 111 - Assistant Principal	696	SF	7	10+ years	
	Work SInk	Rm 111 - Assistant Principal	1	ĒΑ	7	10+ years	
	Ceiling - Splined	Teacher's Lunchroom Basement	447	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lunchroom Basement	1	EΑ	7	10+ years	
	Floor - Tile	Teacher's Lunchroom Basement	447	SF	7	10+ years	
	Lighting - Pendent/Surface	Teacher's Lunchroom Basement	7	EA	7	10+ years	
	Walls - Plaster/Drywall	Teacher's Lunchroom Basement	798	SF	7	10+ years	
	vvalio i laotoli bi y vali	rodonor o Ednomodin Badomoni	700	O.	•	101 youro	
_Gymnas	ia						_
,	Ceiling - Splined	1st Floor	2,840	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	6	ĒΑ	7	6-10 years	
	Floor - Wood	1st Floor	2,356	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor	12	ĒΑ	7	10+ years	
	Sodium				•	.o. you.o	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	484	SF	6	10+ years	
	Stage Curtain	1st Floor	1	EA	7	10+ years	
	Storage/ Closet	1st Floor	194	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,168	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,400	SF	6	10+ years	
						•	
Kitchen							
	Ceiling - Splined	Basement	526	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Tile	Basement	526	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	10+ years	
	Serving Line	Basement	22	LF	7	10+ years	
	Storage/ Closet	Basement	121	SF	7	10+ years	
	Walls - Structural Glazed Tile	Basement	612	SF	7	10+ years	
						-	



Category : Room			Building : Addition					
J			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Library	AO II S	040				0.40		
	AC Unit	218	2	EA	7	6-10 years		
	Casework	218	93	LF	6	10+ years		
	Ceiling - Splined	218	1,116	SF	6	10+ years		
	Doors - Wood Doors inclu hw	218	2	EA	5	10+ years		
	Floor - Carpet	218	1,116	SF	7	6-10 years		
	Lighting - Lay-in	218	31	EΑ	7	10+ years	De lever festives	
	Lighting - Lay-in	218	5	EA	6	6-10 years	Re-lamp fixture	
	Walls - Plaster/Drywall	218	1,157	SF	7	10+ years		
unch &	Multipurpose Room							
	Ceiling - Splined	Basement	1,593	SF	7	10+ years		
	Doors - Steel Doors incl hw	Basement	1	EΑ	7	10+ years		
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years		
	Floor - Tile	Basement	1,593	SF	7	10+ years		
	Lighting - Pendent/Surface	Basement	40	ĒΑ	7	10+ years		
	Walls - Concrete Block	Basement	1,062	SF	7	10+ years		
MDF_IDI	=							
וטוב_וטואו	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Finishes	2nd Floor	109	SF	7	10+ years		
	Other Cooling Unit	2nd Floor	103	EA	7	10+ years		
	Other Cooling Offic	2110 1 1001	ı	LA	,	10+ years		
Mechanio	cal/ Service Rooms							
	Janitor's Closet	2nd Floor	84	SF	7	10+ years	Inaccessible. Key does not work	
	Janitor's Closet	2nd Floor	186	SF	5	10+ years		
	Boiler Room	Basement	1,598	SF	7	6-10 years		
	Air Tunnel	Basement	1,920	SF	7	10+ years		
	Mechanical/ Service Rooms	Basement	1,687	SF	7	10+ years		
Restroon	n							
	Accessories	104A	80	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	104A	80	SF	7	10+ years		
	Doors - Wood Doors inclu hw	104A	1	EA	6	10+ years		
	Floor - Tile	104A	80	SF	6	6-10 years		
	Lavatory	104A	1	ĒΑ	7	6-10 years		
	Lighting - Lay-in	104A	1	EA	7	10+ years		
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years		
	Walls - Concrete Block	104A	267	SF	7	10+ years		
	Water Closet	104A	1	EA	7	10+ years		
	Accessories	108A	55	SF	7	6-10 years		
			00	SF	•	5 . 5 y 5 G 1 5		



Catego	ry : Room		Building : Addition						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	108A	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	108A	55	SF	7	6-10 years			
	Lavatory	108A	1	EA	7	10+ years			
	Lighting - Lay-in	108A	1	EA	7	10+ years			
	Walls - Concrete Block	108A	223	SF	7	10+ years			
	Water Closet	108A	1	EA	7	10+ years			
	Accessories	110A	21	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	110A	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	110A	1	EA	7	6-10 years			
	Floor - Tile	110A	21	SF	7	6-10 years			
	Lavatory	110A	1	EA	6	10+ years			
	Lighting - Pendent/Surface	110A	1	EA	7	10+ years			
	Walls - Plaster/Drywall	110A	151	SF	7	10+ years			
	Water Closet	110A	1	EA	7	10+ years			
	Accessories	209C Unisex	68	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	209C Unisex	68	SF	7	10+ years			
	Doors - Wood Doors inclu hw	209C Unisex	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	209C Unisex	68	SF	7	10+ years			
	Lavatory	209C Unisex	1	EA	6	10+ years			
	Lighting - Pendent/Surface	209C Unisex	2	EA	7	10+ years			
	Lighting - Wall Mounted	209C Unisex	1	EA	7	10+ years			
	Partitions	209C Unisex	1	EA	7	10+ years			
	Walls - Plaster/Drywall	209C Unisex	282	SF	7	10+ years			
	Water Closet	209C Unisex	1	EA	7	10+ years			
	Accessories	209D Unisex	40	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	209D Unisex	40	SF	6	10+ years			
	Doors - Wood Doors inclu hw	209D Unisex	1	EA	6	10+ years			
	Floor - Tile	209D Unisex	40	SF	7	10+ years			
	Lavatory	209D Unisex	1	EA	6	10+ years			
	Lighting - Wall Mounted	209D Unisex	1	EA	7	10+ years			
	Partitions	209D Unisex	1	EA	7	10+ years			
	Urinals	209D Unisex	1	EA	7	10+ years			
	Walls - Concrete Block	209D Unisex	188	SF	7	10+ years			
	Water Closet	209D Unisex	1	EA	7	10+ years			
	Accessories	Boys North 1st Fl	268	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Boys North 1st Fl	252	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Boys North 1st FI	16	SF	5	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Boys North 1st Fl	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Boys North 1st FI	268	SF	7	10+ years			
	Floor Drain	Boys North 1st Fl	1	EA	7	10+ years			
	Lavatory	Boys North 1st FI	2	EA	7	10+ years			
	Lighting - Lay-in	Boys North 1st Fl	1	EA	7	6-10 years			
	Lighting - Pendent/Surface	Boys North 1st FI	3	EA	7	10+ years			
	Partitions	Boys North 1st Fl	2	EA	7	10+ years	Updated to match current		
		-				-			



	Category : Room			Building : Addition						
Urinals							Recommend			
Urinals	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement			
Walls - Concrete Block Boys North 1st Fl 100 SF 7 10+ years Walls - Structural Glazed Tile Boys North 1st Fl 2 EA 7 10+ years Accessories Boys North 2nd Fl 28 SF 7 10+ years Ceiling - Plaster/Drywall Boys North 2nd Fl 28 SF 6 10+ years Doors - Wood Doors inclu hw Boys North 2nd Fl 2 EA 5 10+ years Floor - Tile Caramic/ Porcelain Boys North 2nd Fl 28 SF 7 10+ years Floor Drain Boys North 2nd Fl 1 EA 7 10+ years Laystroy Boys North 2nd Fl 2 EA 6 10+ years Lighting - Lay-in Boys North 2nd Fl 4 EA 7 10+ years Lighting - Lay-in Boys North 2nd Fl 4 EA 7 10+ years Lighting - Pendent/Surface Boys North 2nd Fl 4 EA 7 10+ years Walls - Placetr/Drywall Boys North 2nd Fl		I late a la	Davis Namb 4-4 El	0	_^	7	40	observations		
Walls - Structural Glazed Tile Boys North 1st FI 27 7 10+ years Water Closet Boys North 2nd FI 268 SF 7 6-10 years Ceiling - Plaster/Drywall Boys North 2nd FI 268 SF 6 6-10 years Doors - Wood Doors inclu hw Boys North 2nd FI 28 SF 6 10+ years Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 28 SF 7 10+ years Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 1 EA 7 10+ years Lighting - Lay-in Boys North 2nd FI 1 EA 7 10+ years Lighting - Pendent/Surface Boys North 2nd FI 2 EA 7 10+ years Partitions Boys North 2nd FI 1 EA 7 10+ years Walls - Structural Glazed Tile										
Water Closet			•				•			
Accessories Ceiling - Plaster/Drywall Boys North 2nd FI 268 SF 6 10+ years Doors - Wood Doors inclu hw Boys North 2nd FI 268 SF 6 10+ years Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 128 Floor - Tile Ceramic/ Porcelain Boys North 2nd FI 138 Floor Drain Boys North 2nd FI 148 Layatory Boys North 2nd FI 159 Lighting - Lay-in Lighting - Lay-in Lighting - Pendent/Surface Boys North 2nd FI 150 Boys South 1st FI 150 Boys South 2nd FI Boys South 2nd FI Boys South 2nd FI Boys Sout			•							
Ceiling - Plaster/Drywall			•							
Doors - Wood Doors inclu hw Boys North 2nd F			,				•			
Floor - Tile Ceramic/ Porcelain							,			
Floor Drain							,			
Layatory							,			
Lighting - Lay-in										
Lighting - Pendent/Surface										
Partitions										
Urinals							•			
Walls - Plaster/Drywall Boys North 2nd FI 100 SF 7 10+ years Walls - Structural Glazed Tile Boys North 2nd FI 471 SF 7 10+ years Water Closet Boys South 1st FI 2 EA 7 10+ years Accessories Boys South 1st FI 235 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 1st FI 235 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 1st FI 40 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Boys South 1st FI 2 EA 7 6-10 years Water damage Floor Drain Boys South 1st FI 2 EA 7 10+ years Floor Drain Boys South 1st FI 1 EA 7 10+ years Floor Drain Boys South 1st FI 3 EA 7 6-10 years Floor Drain Boys South 1st FI 3 EA 7 6-10 years Floor Prain Boys South 1st FI 4 EA <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>,</td><td></td></t<>							,			
Walls - Structural Glazed Tile Boys North 2nd FI 471 SF 7 10+ years Water Closet Boys North 2nd FI 2 EA 7 10+ years Accessories Boys South 1st FI 275 SF 7 6-10 years Celling - Plaster/Drywall Boys South 1st FI 235 SF 7 10+ years Celling - Plaster/Drywall Boys South 1st FI 40 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Boys South 1st FI 2 EA 7 6-10 years Floor - Tille Ceramic/ Porcelain Boys South 1st FI 2 EA 7 10+ years Floor Drain Boys South 1st FI 3 EA 7 6-10 years Lavatory Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 3 EA 7 6-10 years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Structural Glazed Tile			•				•			
Water Closet Boys North 2nd FI 2 EA 7 10+ years Accessories Boys South 1st FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 1st FI 235 SF 7 10+ years Ceiling - Plaster/Drywall Boys South 1st FI 40 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Boys South 1st FI 2 EA 7 6-10 years Floor Tile Ceramic/ Porcelain Boys South 1st FI 2 EA 7 6-10 years Floor Drain Boys South 1st FI 1 EA 7 6-10 years Layatory Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 3 EA 7 6-10 years Partitions Boys South 1st FI 4 EA 7 10+ years Urinals Boys South 1st FI </td <td></td> <td></td> <td>Boys North 2nd Fl</td> <td></td> <td></td> <td></td> <td></td> <td></td>			Boys North 2nd Fl							
Accessories			,	471			10+ years			
Ceiling - Plaster/Drywall Boys South 1st FI 235 SF 7 10+ years Ceiling - Plaster/Drywall Boys South 1st FI 40 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Boys South 1st FI 2 EA 7 6-10 years Floor - Tile Ceramic/ Porcelain Boys South 1st FI 1 EA 7 10+ years Floor Drain Boys South 1st FI 3 EA 7 6-10 years Layatory Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 2 EA 7 10+ years Lighting - Pendent/Surface Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Concrete Block Boys South 1st FI 234 SF 7 10+ years Water Closet Boys South 2nd FI 275 SF 7 10+ years Accessories Boys So		Water Closet				7				
Ceiling - Plaster/Drywall Boys South 1st FI 40 SF 5 1-2 years Water damage Doors - Wood Doors inclu hw Boys South 1st FI 2 EA 7 6-10 years Floor - Tile Ceramic/ Porcelain Boys South 1st FI 275 SF 7 10+ years Floor Drain Boys South 1st FI 3 EA 7 6-10 years Layatory Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 3 EA 7 6-10 years Partitions Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Concrete Block Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 2nd FI 2 EA 7 10+ years Water Closet Boys South 2nd FI <td< td=""><td></td><td></td><td>Boys South 1st FI</td><td></td><td></td><td></td><td>6-10 years</td><td></td></td<>			Boys South 1st FI				6-10 years			
Doors - Wood Doors inclu hw Boys South 1st Fl 2		Ceiling - Plaster/Drywall	Boys South 1st FI	235		7	10+ years			
Floor - Tile Ceramic/ Porcelain		Ceiling - Plaster/Drywall	Boys South 1st FI	40	SF	5	1-2 years	Water damage		
Floor Drain		Doors - Wood Doors inclu hw	Boys South 1st FI	2	EA	7	6-10 years			
Floor Drain		Floor - Tile Ceramic/ Porcelain		275	SF	7	10+ years			
Layatory Boys South 1st FI 3 EA 7 6-10 years Lighting - Pendent/Surface Boys South 1st FI 3 EA 7 6-10 years Partitions Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Concrete Block Boys South 1st FI 234 SF 7 10+ years Walls - Structural Glazed Tile Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 1st FI 2 EA 7 10+ years Accessories Boys South 2nd FI 2 EA 7 10+ years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd FI 2 EA 5 10+ years Floor - Tile Ceramic/ Porcelain Boys South 2nd FI 2 EA 5 10+ years Floor Drain Boys South 2nd FI 3		Floor Drain	Boys South 1st FI	1	EA	7				
Lighting - Pendent/Surface Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Concrete Block Boys South 1st FI 234 SF 7 10+ years Walls - Structural Glazed Tile Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 1st FI 22 EA 7 10+ years Water Closet Boys South 2nd FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Floor - Tile Ceramic/ Porcelain Boys South 2nd FI 275 SF 7 10+ years Floor Drain Boys South 2nd FI 275 SF 7 10+ years Floor Drain Boys South 2nd FI 275 SF 7 10+ years Lavatory Boys South 2nd FI 1 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd FI 1 EA 7 10+ years Partitions Boys South 2nd FI 1 EA 7 10+ years Urinals Boys South 2nd FI 1 EA 7 10+ years Walls - Concrete Block Boys South 2nd FI 1 EA 7 10+ years Walls - Structural Glazed Tile Boys South 2nd FI 100 SF 7 10+ years Walls - Structural Glazed Tile Boys South 2nd FI 196 SF 7 10+ years Water Closet Boys South 2nd FI 196 SF 7 10+ years Water Closet Boys South 2nd FI 197 Sears Water Closet Boys South 2nd FI 2 EA 7 10+ years		Lavatory		3	EΑ	7	6-10 years			
Partitions Boys South 1st FI 2 EA 7 10+ years Urinals Boys South 1st FI 4 EA 7 10+ years Walls - Concrete Block Boys South 1st FI 234 SF 7 10+ years Walls - Structural Glazed Tile Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 1st FI 2 EA 7 10+ years Accessories Boys South 2nd FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd FI 2 EA 5 10+ years Floor - Tile Ceramic/ Porcelain Boys South 2nd FI 275 SF 7 10+ years Floor Drain Boys South 2nd FI 1 EA 7 10+ years Lavatory Boys South 2nd FI 3 EA 7 10+ years Partitions Boys South 2nd FI 2 EA			Boys South 1st FI	3	EA	7				
Urinals Walls - Concrete Block Boys South 1st FI Walls - Concrete Block Boys South 1st FI Boys South 2nd FI Boys South 2			Boys South 1st FI	2	EA	7				
Walls - Concrete Block Walls - Structural Glazed Tile Boys South 1st FI 498 SF 7 10+ years Water Closet Boys South 1st FI 2 EA 7 10+ years Accessories Boys South 2nd FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 10+ years Partitions Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 275 SF 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 1 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 1 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 2 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 2 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 2 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 4 EA 7 10+ years Poors - Wood Doors inclu hw Boys South 2nd FI 100 SF 7 10+ years Walls - Concrete Block Boys South 2nd FI 496 SF 7 10+ years Water Closet Boys South 2nd FI 2 EA 7 10+ years		Urinals	Boys South 1st FI	4	EA	7				
Walls - Structural Glazed Tile Water Closet Boys South 1st FI Boys South 1st FI Boys South 1st FI Boys South 2nd FI Boys		Walls - Concrete Block	Boys South 1st FI	234	SF	7	-			
Water Closet Accessories Boys South 1st FI 2 EA 7 10+ years Accessories Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 6-10 years Ceiling - Plaster/Drywall Boys South 2nd FI 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd FI 2 EA 5 10+ years Floor - Tile Ceramic/ Porcelain Boys South 2nd FI 275 SF 7 10+ years Floor Drain Boys South 2nd FI 1 EA 7 10+ years Layatory Boys South 2nd FI 1 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd FI 1 EA 7 10+ years Partitions Boys South 2nd FI 2 EA 7 10+ years Urinals Boys South 2nd FI 4 EA 7 10+ years Walls - Concrete Block Boys South 2nd FI 100 SF 7 10+ years Walls - Structural Glazed Tile Boys South 2nd FI 4 96 SF 7 10+ years Water Closet		Walls - Structural Glazed Tile		498	SF	7	•			
Accessories Ceiling - Plaster/Drywall Boys South 2nd Fl 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd Fl 275 SF 7 10+ years Doors - Wood Doors inclu hw Boys South 2nd Fl 2 EA 5 10+ years Floor - Tile Ceramic/ Porcelain Boys South 2nd Fl 275 SF 7 10+ years Floor Drain Boys South 2nd Fl 1 EA 7 10+ years Lavatory Boys South 2nd Fl 3 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd Fl 4 EA 7 10+ years Partitions Urinals Boys South 2nd Fl 4 EA 7 10+ years Walls - Concrete Block Boys South 2nd Fl 100 SF 7 10+ years Walls - Structural Glazed Tile Boys South 2nd Fl 496 SF 7 10+ years Water Closet Boys South 2nd Fl 496 SF 7 10+ years		Water Closet			EA	7	•			
Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Floor Drain Boys South 2nd Fl Lavatory Boys South 2nd Fl Lighting - Pendent/Surface Boys South 2nd Fl Boys		Accessories		275	SF	7				
Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Boys South 2nd Fl 275 SF 7 10+ years Floor Drain Boys South 2nd Fl 1 EA 7 10+ years Lavatory Boys South 2nd Fl 3 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd Fl 4 EA 7 10+ years Partitions Boys South 2nd Fl 2 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd Fl 4 EA 7 10+ years Urinals Boys South 2nd Fl 4 EA 7 10+ years Walls - Concrete Block Boys South 2nd Fl 4 EA 7 10+ years Walls - Structural Glazed Tile Boys South 2nd Fl 496 SF 7 10+ years Water Closet Boys South 2nd Fl 496 SF 7 10+ years		Ceiling - Plaster/Drywall		275	SF	7				
Floor - Tile Ceramic/ Porcelain Boys South 2nd Fl				2	EA	5				
Floor Drain Boys South 2nd Fl Lavatory Boys South 2nd Fl										
Lavatory Boys South 2nd FI 3 EA 7 10+ years Lighting - Pendent/Surface Boys South 2nd FI 4 EA 7 10+ years Partitions Boys South 2nd FI 2 EA 7 10+ years Urinals Boys South 2nd FI 4 EA 7 10+ years Walls - Concrete Block Boys South 2nd FI 100 SF 7 10+ years Walls - Structural Glazed Tile Boys South 2nd FI 496 SF 7 10+ years Water Closet Boys South 2nd FI 2 EA 7 10+ years		Floor Drain		1						
Lighting - Pendent/Surface Boys South 2nd FI Partitions Boys South 2nd FI Urinals Boys South 2nd FI Boys South 2nd FI Boys South 2nd FI 4 EA 7 10+ years 5 T 10+ years 6 SF 7 10+ years 7 TO+ years 8 SP 7 TO+ years 8 SP 7 TO+ years 9 SP 7 TO+ years				3						
Partitions Boys South 2nd FI 2 EA 7 10+ years Urinals Boys South 2nd FI 4 EA 7 10+ years Walls - Concrete Block Boys South 2nd FI 100 SF 7 10+ years Walls - Structural Glazed Tile Boys South 2nd FI 496 SF 7 10+ years Water Closet Boys South 2nd FI 2 EA 7 10+ years				4	EA					
UrinalsBoys South 2nd FI4EA710+ yearsWalls - Concrete BlockBoys South 2nd FI100SF710+ yearsWalls - Structural Glazed TileBoys South 2nd FI496SF710+ yearsWater ClosetBoys South 2nd FI2EA710+ years										
Walls - Concrete BlockBoys South 2nd Fl100SF710+ yearsWalls - Structural Glazed TileBoys South 2nd Fl496SF710+ yearsWater ClosetBoys South 2nd Fl2EA710+ years		Urinals		4	EA					
Walls - Structural Glazed Tile Boys South 2nd Fl 496 SF 7 10+ years Water Closet Boys South 2nd Fl 2 EA 7 10+ years		Walls - Concrete Block		100						
Water Closet Boys South 2nd Fl 2 EA 7 10+ years							-			
= = = = = = = = = = = = =										
			3 			-	,			

Campus Name: Lasalle II Page : 23 of 40 Assessment Date: 08/03/2023



Catego	ry : Room	-	Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Plaster/Drywall	Engineer's Basment	145	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Engineer's Basment	2	EA	6	6-10 years				
	Floor - Concrete	Engineer's Basment	145	SF	7	10+ years				
	Floor Drain	Engineer's Basment	1	EA	7	10+ years				
	Lavatory	Engineer's Basment	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	Engineer's Basment	3	EA	7	6-10 years				
	Walls - Concrete Block	Engineer's Basment	60	SF	7	10+ years				
	Walls - Concrete Block	Engineer's Basment	169	SF	6	10+ years				
	Water Closet	Engineer's Basment	1	EA	6	10+ years				
	Accessories	Girls 2nd Fl North	268	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Girls 2nd Fl North	268	SF	5	1-2 years	Minor water damage, bubbling and peeling paint throughout			
	Doors - Wood Doors inclu hw	Girls 2nd Fl North	2	EA	5	10+ years	peeiing paint throughout			
	Floor - Tile Ceramic/ Porcelain	Girls 2nd Fl North	268	SF	5	10+ years				
	Floor Drain	Girls 2nd Fl North	1	EA	7	10+ years				
	Lavatory	Girls 2nd F1 North	2	EA	6	10+ years				
	Lighting - Lay-in	Girls 2nd F1 North	1	EA	7	10+ years				
	Lighting - Lay-in Lighting - Pendent/Surface	Girls 2nd F1 North	4	EA	7	10+ years				
	Partitions	Girls 2nd Fl North	6	EA	7	10+ years				
	Walls - Plaster/Drywall	Girls 2nd Fl North	100	SF	6	,				
	Walls - Plaster/Drywaii Walls - Structural Glazed Tile		471	SF SF		10+ years				
		Girls 2nd Fl North			7	10+ years				
	Water Closet	Girls 2nd Fl North	6	EA	7	10+ years				
	Accessories	Girls North 1st Fl	268	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Girls North 1st Fl	268	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Girls North 1st Fl	1	EA	7	6-10 years				
	Floor - Tile Ceramic/ Porcelain	Girls North 1st Fl	268	SF	7	10+ years				
	Floor Drain	Girls North 1st Fl	1	EA	7	10+ years				
	Lavatory	Girls North 1st Fl	2	EA	7	10+ years				
	Lighting - Lay-in	Girls North 1st Fl	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Girls North 1st Fl	3	EA	7	10+ years				
	Partitions	Girls North 1st Fl	5	EA	7	10+ years				
	Walls - Plaster/Drywall	Girls North 1st Fl	100	SF	7	10+ years				
	Walls - Structural Glazed Tile	Girls North 1st Fl	471	SF	7	10+ years				
	Water Closet	Girls North 1st Fl	5	EA	7	10+ years				
	Accessories	Girls South 1st FI	275	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Girls South 1st Fl	275	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Girls South 1st Fl	5	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Girls South 1st Fl	275	SF	7	10+ years				
	Floor Drain	Girls South 1st Fl	1	EA	7	10+ years				
	Lavatory	Girls South 1st FI	3	EA	7	10+ years				
	Lighting - Lay-in	Girls South 1st FI	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Girls South 1st Fl	4	EA	7	10+ years				
	Partitions	Girls South 1st Fl	5	EA	7	10+ years				
	Walls - Concrete Block	Girls South 1st FI	234	SF	7	10+ years				
						,				

Page : 24 of 40 Campus Name: Lasalle II Assessment Date: 08/03/2023



Catego	Category : Room			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Structural Glazed Tile	Girls South 1st Fl	498	SF	7	10+ years		
	Water Closet	Girls South 1st Fl	5	EA	7	10+ years		
	Accessories	Girls South 2nd Fl	275	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Girls South 2nd Fl	275	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Girls South 2nd Fl	2	EA	5	10+ years		
	Floor - Tile Ceramic/ Porcelain	Girls South 2nd Fl	275	SF	7	10+ years		
	Floor Drain	Girls South 2nd Fl	1	EΑ	7	10+ years		
	Lavatory	Girls South 2nd Fl	3	EΑ	7	10+ years		
	Lighting - Lay-in	Girls South 2nd Fl	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	Girls South 2nd Fl	3	EA	7	10+ years		
	Lighting - Pendent/Surface	Girls South 2nd Fl	1	EA	6	6-10 years	Re-lamp fixture	
	Partitions	Girls South 2nd Fl	5	EA	7	10+ years	·	
	Walls - Concrete Block	Girls South 2nd Fl	234	SF	7	10+ years		
	Walls - Structural Glazed Tile	Girls South 2nd Fl	498	SF	7	10+ years		
	Water Closet	Girls South 2nd Fl	5	ĒΑ	7	10+ years		
	Accessories	Main Office 1st FI	30	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Main Office 1st FI	30	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Main Office 1st FI	1	ĒΑ	7	6-10 years		
	Floor - Tile	Main Office 1st FI	30	SF	7	6-10 years		
	Lavatory	Main Office 1st Fl	1	ĒΑ	7	10+ years		
	Lighting - Chandelier, Incandescent	Main Office 1st FI	2	EA	6	1-2 years	Relamp	
	Lighting - Pendent/Surface	Main Office 1st FI	1	EA	7	6-10 years	,	
	Lighting - Pendent/Surface	Main Office 1st FI	1	EA	6	1-2 years	Relamp	
	Partitions	Main Office 1st FI	1	ĒΑ	7	10+ years		
	Walls - Plaster/Drywall	Main Office 1st FI	180	SF	7	10+ years		
	Water Closet	Main Office 1st Fl	1	ĒΑ	7	10+ years		
	Accessories	Men's North 1st FI (Teacher's	83	SF	7	6-10 years		
		Lounge)		_		,		
	Ceiling - Plaster/Drywall	Men's North 1st FI (Teacher's	83	SF	7	10+ years		
	- coming of the control of the contr	Lounge)				, , , , , , , , , , , , , , , , , , , ,		
	Doors - Wood Doors inclu hw	Men's North 1st FI (Teacher's	1	EA	7	10+ years		
		Lounge)				, , , , , , , , , , , , , , , , , , , ,		
	Floor - Tile Ceramic/ Porcelain	Men's North 1st FI (Teacher's	83	SF	7	10+ years		
		Lounge)		О.	-	.o. you.o		
	Lavatory	Men's North 1st FI (Teacher's	1	EA	7	10+ years		
	_a.a.a.e.y	Lounge)	·		-	.o. you.o		
	Lighting - Chandelier, Incandescent	Men's North 1st FI (Teacher's	1	EA	7	10+ years		
	=igg • • · · · · · · · · · · · · · · · · ·	Lounge)	·		•	.o. you.o		
	Lighting - Wall Mounted	Men's North 1st FI (Teacher's	1	EA	7	10+ years	Updated quantity	
	ggaaa.	Lounge)	·		-	.o. you.o	opuatou quantity	
	Partitions	Men's North 1st FI (Teacher's	1	EA	7	10+ years		
		Lounge)	•		•	,		
	Urinals	Men's North 1st FI (Teacher's	2	EA	7	10+ years		
	- · · · · · · · · · · · · · · · · · · ·	Lounge)	_		•	,		
		· 9 - /						



Catego	ry : Room		Building : Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Men's North 1st FI (Teacher's Lounge)	77	SF	7	10+ years	
	Walls - Structural Glazed Tile	Men's North 1st FI (Teacher's Lounge)	230	SF	7	10+ years	
	Water Closet	Men's North 1st Fl (Teacher's Lounge)	1	EA	7	10+ years	
	Accessories	Women's North 1st FI (Teacher's Lounge)	119	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's North 1st FI (Teacher's Lounge)	119	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's North 1st FI (Teacher's Lounge)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's North 1st FI (Teacher's Lounge)	119	SF	7	10+ years	
	Lavatory	Women's North 1st FI (Teacher's Lounge)	1	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	Women's North 1st FI (Teacher's Lounge)	2	EA	7	10+ years	
	Partitions	Women's North 1st FI (Teacher's Lounge)	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's North 1st FI (Teacher's Lounge)	99	SF	7	10+ years	
	Walls - Structural Glazed Tile	Women's North 1st FI (Teacher's Lounge)	295	SF	7	10+ years	
	Water Closet	Women's North 1st FI (Teacher's Lounge)	2	EA	7	10+ years	

Category: Classroom Building: Addition

oup Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ssroom #101 (Pre School)		•				
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	10	LF	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	766	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Tile	1st Floor	766	SF	6	6-10 years	
Lighting - Pendent/Surface	1st Floor	16	EΑ	6	6-10 years	
Marker Board	1st Floor	20	LF	6	6-10 years	
Storage/ Closet	1st Floor	12	SF	7	10+ years	
Walls - Concrete Block	1st Floor	840	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	80	SF	7	10+ years	
Work Sink	1st Floor	1	EA	7	6-10 years	

Classroom #102 (Regular Classroom)



Catego	ry : Classroom		В	uilding	: Additi		146 N HOHOTE STREET, CHICAGO, IL 60022
				Ĭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	766	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	900	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #103 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	730	SF	4	0-1 year	Suspect asbestos tiles damaged
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	Cuopedi abbotico inco damagea
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	880	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #104/106 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,046	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,046	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,075	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #105 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
	Chalk Board	1st Floor	17	LF	4	2-5 years	
	Chair Boald	13(1100)	17	L	4	2-5 years	



Catego	ory : Classroom		В	uilding	: Additi	on	· 5 ·
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	6-10 years	
	Floor - Tile	1st Floor	730	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	880	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	5	1-2 years	Stuck running
Classro	om #107 (Kindergarten)						
Classion	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw			SF EA		•	
		1st Floor	1		6	10+ years	
	Floor - Tile	1st Floor	742	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	12	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	880	SF	7	10+ years	
_Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EΑ	7	6-10 years	
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,078	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,078	SF	4	1-2 years	Suspect asbestos tile
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	•
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,063	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	6-10 years	
	Casework Ceiling - Plaster/Drywall	1st Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	100	EA	6	6-10 years	
	Floor - Tile	1st Floor	•	SF			
			761		6	10+ years	Organism minaina (II
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Cracking, missing tiles
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	980	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	980	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	63	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,061	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	6-10 years	
	Floor - Tile	1st Floor	1,061	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	6	6-10 years	
	Marker Board	1st Floor	22	LF	6	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,362	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	718	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	718	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Student Lockers - One Tier	1st Floor	11	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years	
Classroo	om #113 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	718	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	718	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	1-2 years	Relamp
	Lighting - Lay-in	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	950	SF	6	10+ years	
Classroo	om #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	56	LF	7	10+ years	
	Casework	1st Floor	2	LF	6	1-2 years	Trim missing
	Ceiling - Plaster/Drywall	1st Floor	718	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	718	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	6	6-10 years	



Category : Classroom			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Student Lockers - One Tier	1st Floor	11	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years		
Classro	om #115 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	8	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	718	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	6-10 years		
	Floor - Tile	1st Floor	718	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor	16	EΑ	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	950	SF	7	10+ years		
Classro	om #116 (Special Education)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	5	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	345	SF	7	10+ years		
	Chalk Board	1st Floor	28	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Carpet	1st Floor	172	SF	6	6-10 years		
	Floor - Tile	1st Floor	173	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	688	SF	7	10+ years		
Classro	om #201 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Tile	2nd Floor	766	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	12	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years		
Classro	om #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	10	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years		
	Chalk Board	2nd Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	2nd Floor		EA	6	6-10 years		
	Floor - Tile	2nd Floor	766	SF	6	10+ years		
	Floor - Tile	2nd Floor	12	SF	4	1-2 years	Chipped tiles	
			12	٥.	•	,		



Catego	ategory : Classroom		В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	16	EΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #203 (Kindergarten)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF		-	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor		SF EA	6	10+ years	
			16		6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	17	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor 2nd Floor	12	LF	4	•	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor		EA	6	2-5 years	
			1	SF		10+ years	
	Floor - Tile	2nd Floor	730		6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years	



Catego	ry : Classroom		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #206 (Computer Lab)								
Classioo	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	3	LF	7				
	Casework Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years			
				LF		10+ years			
	Chalk Board	2nd Floor	12		4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	12	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years			
Classroo	m #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	20	LF	7				
	Storage/ Closet			SF	7	6-10 years			
		2nd Floor	12	SF SF	-	10+ years			
	Walls - Concrete Block	2nd Floor	880		7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years			
Classroo	m #208 (Special Education)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years			
	Chalk Board	2nd Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	730	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	12	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	80	SF	7	10+ years			
	•					,			
Classroo	m #210 (Science Lab Level 3)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	62	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	1,140	SF	7	10+ years			



Calego	Category : Classroom		В	uilding	: Addition		
_			Recomm			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,140	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	24	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,214	SF	7	10+ years	
	Work Sink	2nd Floor	4	EA	7	10+ years	
Classroo	m #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	Re-lamp fixture
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	Tto lamp lixture
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	950	SF	7	•	
	Walls - Plaster/Drywall		30	SF	4	10+ years	Cracked and spalling drywall
	walls - Plaster/Drywall	2nd Floor	30	SF	4	1-2 years	Cracked and spanning drywan
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroc	m #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	716	SF	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	50	SF	4	1-2 years	Cracked tile
		2nd Floor 2nd Floor	16	SF EA	6	6-10 years	Cracked tile
	Lighting - Lay-in			LF	_		
	Marker Board	2nd Floor	18	SF	6 7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	51	1	10+ years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Catego	Category : Classroom		В	uilding			
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	2	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF			
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	980	SF	6 7	6-10 years	
	Walls - Flaster/Drywall	2110 F1001	900	SF	,	10+ years	
Classroc	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	766	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	7	10+ years	
Classroc	om #217 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	718	SF	5	10+ years	Small cracks and peeling paint
	Chalk Board	2nd Floor	6	LF	4	2-5 years	throughout
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
			· · · · · · · · · · · · · · · · · · ·	SF	6		
	Floor - Tile	2nd Floor	718		_	10+ years	
	Lighting - Lay-in	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	



Catego	Category : Interior			uilding			
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,305	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,090	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	9	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,086	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	29	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	213	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,438	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,155	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	10	SF	5	1-2 years	Cracking tiles
	Ceiling - Plaster/Drywall	2nd Floor	4,086	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	EA	5	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,086	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	43	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	251	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	2,841	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,841	SF	7	10+ years	
	Ceiling - Exposed	Basement	283	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	9	EA	6	10+ years	
	Floor - Tile/Sheet	Basement	283	SF	7	10+ years	
	Lighting - Lay-in	Basement	4	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	10+ years	
	Stairs - Terrazzo	Basement	81	LF	6	10+ years	
	Walls - Masonry	Basement	1,491	SF	7	10+ years	
Safety	Camera Viewing Station	Entire Building	1	EA	7	6 10 years	Viewing station attached to a laptop
	Camera viewing Station	Entire Building	ı	EA	,	6-10 years	which was not present during assessment
	Security Cameras	Entire Building	8	EA	7	6-10 years	
_Stairs							
	Ceiling - Plaster/Drywall	Center Stairs	582	SF	7	10+ years	
	Floor - Terrazzo	Center Stairs	370	SF	7	10+ years	
	Handrails	Center Stairs	35	LF	7	10+ years	
	Lighting - Pendent/Surface	Center Stairs	8	EA	7	10+ years	
	Stairs - Terrazzo	Center Stairs	103	LF	7	10+ years	
	Walls - Concrete Block	Center Stairs	799	SF	7	10+ years	
	Walls - Structural Glazed Tile	Center Stairs	799	SF	7	10+ years	
			. 00	٥.	•	,	



Catego	ry : Interior		В	Building : Addition				
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	North	697	SF	7	10+ years		
	Floor - Terrazzo	North	622	SF	7	10+ years		
	Handrails	North	40	LF	7	10+ years		
	Lighting - Lay-in	North	8	EA	7	10+ years		
	Stairs - Terrazzo	North	110	LF	7	10+ years		
	Walls - Plaster/Drywall	North	827	SF	7	10+ years		
	Walls - Structural Glazed Tile	North	827	SF	7	10+ years		
	Ceiling - Plaster/Drywall	South	432	SF	7	10+ years		
	Floor - Terrazzo	South	432	SF	7	10+ years		
	Handrails	South	37	LF	7	10+ years		
	Lighting - Pendent/Surface	South	6	EA	7	10+ years		
	Stairs - Terrazzo	South	110	LF	7	10+ years		
	Walls - Concrete Block	South	754	SF	7	10+ years		
	Walls - Structural Glazed Tile	South	754	SF	7	10+ years		



Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Natural	Entire Site	21,128	SF	5	1-2 years	Large areas of bare soil and weeds
Civil/Dra	O						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	6-10 years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	6-10 years	
_Fencina							
	Fencing - Chain Link	Entire Site	105	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	8	LF	5	1-2 years	Damaged fence, how to plumb, bent
							posts
	Fencing - New Standard Ornamental	Entire Site	1,531	LF	6	6-10 years	
Landsca	pe						
	Benches	Entire Site	9	EA	6	6-10 years	
	Landscape - Grass	Entire Site	9,432	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	14,133	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	100	SF	5	1-2 years	Upheaved, cracked concrete
	Landscape - Mulch	Entire Site	7,000	SF	6	6-10 years	•
	Parkway trees	Entire Site	30	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	5	1-2 years	Not parkway trees-Trees damaging bathroom plumbing lines, per
							Assistant Principal. Major work done
							by building engineer
	Parkway trees	Entire Site	2	EA	4	1-2 years	Dead tree, missing tree
	Planting Beds/ Area	Entire Site	200	SF	6	6-10 years	Dead tree, missing tree
	Planting Beds/ Area	Entire Site	60	SF	4	1-2 years	Broken planter bed
	Play Area - Hardscape- Asphalt	Entire Site	11,006	SF	6	6-10 years	Broken planter bed
	Play Area - Hardscape- Asphalt	Entire Site	1,000	SF	5	1-2 years	Large cracks, upheaved surface
	Retaining Wall - Concrete	Entire Site	700	SF	7	10+ years	Large cracks, uprieaved surface
	Trash Receptacles	Entire Site	2	EA	6	6-10 years	
	Trasif Neceptacies	Little Site	2	LA	O	0-10 years	
Parking							
	Surface - Asphalt	Entire Site	11,482	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	2,000	SF	5	1-2 years	Potholes, cracks, alligatoring
	Surface - Concrete	Entire Site	2,418	SF	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	1,200	SF	7	6-10 years	
_Playgrou	und						
	Equipment - Combo 3-12	East	1	EA	6	6-10 years	
						,	



Catego	ry : Site		В	Building : Site			•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	East	1,603	SF	5	1-2 years	Missing, broken surface
	Equipment - School Age 5-12	West	1	EA	6	6-10 years	
	Surface - Poured Surface	West	2,226	SF	5	0-1 year	Worn out, torn surface, large tears with missing surface and exposed concrete
_Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	140	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	17,262	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	400	SF	6	10+ years	
_Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	There are no cut letter signs at this school

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Lasalle II Page: 38 of 40 Assessment Date: 08/03/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary									
Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main	interiaca ecago	1100111 200411011	Hambon	Traines.	(0. /	700	71100	Clop	
Art Room	Regular Classroom	Basement	B-2	B-2	832	160	50	N	N
Other Instructional Use	Regular Classroom	3rd Floor	322	304	650	150	30	N	N
Regular Classroom	Regular Classroom	1st Floor	120	102	990	336	140	N	Y
Regular Classroom	Regular Classroom	1st Floor	123	103	780	200	90	N	Y
Regular Classroom	Regular Classroom	1st Floor	124	106	940	252	64	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	221	201	850	120	50	N	Y
Regular Classroom	Regular Classroom	2nd Floor	222	204	605	72	20	N	Y
Regular Classroom	Regular Classroom	2nd Floor	223	203	832	120	50	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	224	206	938	252	65	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	302	870	152	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	321	301	845	120	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	306	938	252	65	N	Y
Store Room	Regular Classroom	1st Floor	121	101	878	120	40	N	N
Store Room	Regular Classroom	3rd Floor	323	303	845	120	50	N	N
	1 3	1							
Building : Addition									
Computer Lab	Regular Classroom	2nd Floor	206	206	730	188	54	N	N
Kindergarten	Kindergarten	1st Floor	108	106	1,078	288	99	N	Υ
Kindergarten	Kindergarten	1st Floor	110	108	1,061	288	99	N	Υ
Kindergarten	Regular Classroom	1st Floor	107	105	730	188	63	N	Υ
Kindergarten	Regular Classroom	2nd Floor	203	201	730	188	63	N	Y
Pre School	Regular Classroom	1st Floor	101	100	766	188	63	N	N
Pre School	Regular Classroom	1st Floor	103	101	730	188	63	N	N
Pre School	Regular Classroom	1st Floor	104/106	104	1,046	288	99	N	N
Pre School	Regular Classroom	1st Floor	105	103	730	188	63	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	766	188	63	N	Y
Regular Classroom	Regular Classroom	1st Floor	109	107	766	188	63	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	110	718	188	63	N	Y
Regular Classroom	Regular Classroom	1st Floor	113	111	718	188	63	N	N
Regular Classroom	Regular Classroom	1st Floor	114	112	718	188	63	N	N
Regular Classroom	Regular Classroom	1st Floor	115	113	718	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	200	766	188	63	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	730	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	203	730	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	205	730	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	211	207	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	766	188	63	N	Y



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	213	209	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	215	211	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	766	188	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217		718	188	63	N	Y
Science Lab Level 3	Other Instructional Use	2nd Floor	210	210	1,140	288	99	N	Y
Special Education	Office	1st Floor	116	114	345	100	36	N	N
Special Education	Regular Classroom	2nd Floor	208	208	730	188	63	N	Υ