

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1911	3	56,765
Linked Addition	1996	2	35,600
Campus Total			92,365

itegoi	ry : Exterior	B	uilding	: Main			
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
trance							
	Entrance Control - Audio and Video	#1- NE- Main Accessible	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#1- NE- Main Accessible	3	EA	7	10+ years	
	Exterior Doors - Side lite	#1- NE- Main Accessible	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	#1- NE- Main Accessible	5	EA	7	10+ years	
	Exterior Stairs - Concrete	#1- NE- Main Accessible	12	LF	5	1-2 years	Missing chunk of concrete
	Exterior Doors - Exterior FRP Door	#2- E	4	EA	7	10+ years	C C
	Exterior Doors - Transom Lite	#2- E	4	EA	7	10+ years	
	Exterior Stairs - Concrete	#2- E	6	LF	6	10+ years	
	Exterior Stairs - Concrete	#2- E	6	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior FRP Door	#3- SE	3	EA	6	10+ years	
	Exterior Doors - Side lite	#3- SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3- SE	5	EA	6	10+ years	
	Exterior Stairs - Concrete	#3- SE	12	LF	5	1-2 years	Cracked concrete
	Exterior Doors - Exterior FRP Door	#4- S	3	EA	6	10+ years	
	Exterior Doors - Side lite	#4- S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4- S	5	EA	6	10+ years	
	Exterior Stairs - Concrete	#4- S	12	LF	5	1-2 years	Cracked concrete, failing repairs
	Exterior Doors - Exterior FRP Door	#5- NW- Boiler Room	1	EA	6	10+ years	······································
	Exterior Doors - Transom Lite	#5- NW- Boiler Room	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5- NW- Boiler Room	3	LF	5	1-2 years	Cracked concrete
undati	on						
	Foundation - Masonry	Entire Building	798	LF	7	10+ years	



Categor	y : Exterior		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Heavy Timber	Entire Building	56,765	SF	7	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	9	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	
oof Sys	tem						
,	Coping - Stone	Auditorium roof	607	LF	7	10+ years	
	Downspouts - Interior Downspouts	Auditorium roof	6	LF	7	10+ years	
	Parapet - 16" - 30" Height	Auditorium roof	607	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Auditorium roof	9,600	SF	5	2-5 years	Blistering throughout, soft spots. Engineer reports ongoing roof leal
	Roof Structure - Steel with Clay Tile Arch	Auditorium roof	9,600	SF	7	10+ years	
	Chimney - Metal Flue	Boiler room roof	<sup>′</sup> 15	LF	7	10+ years	
	Coping - Stone	Boiler room roof	86	LF	7	10+ years	
	Downspouts - Interior Downspouts	Boiler room roof	3	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Boiler room roof	86	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Boiler room roof	942	SF	5	2-5 years	Blistering throughout. Engineer reports ongoing roof leaks
	Roof Structure - Steel with Clay Tile Arch	Boiler room roof	942	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	6	EA	7	10+ years	Repaired
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	40	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	63	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	24	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	5	LF	5	10+ years	Open joints
	Chimney - Metal Flue	Main Roof	25	LF	7	10+ years	
	Coping - Metal	Main Roof	250	LF	7	10+ years	
	Coping - Stone	Main Roof	4	LF	7	10+ years	
	Coping - Stone	Main Roof	1,130	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	58	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	434	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	300	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	267	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	50	LF	7	10+ years	
	Parapet - Parapet > 30"	Main Roof	517	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	25,306	SF	4	2-5 years	Blistering throughout, soft spots. Engineer reports ongoing roof lea
	Roof - Metal	Main Roof	115	SF	5	2-5 years	Corroding , section missing
		Main Roof	1	EA	7	10+ years	contraining, section missing
	Roof Hatch - Metal						



Catego	ry : Exterior		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Roof Structure - Steel with Clay Tile Arch	Main Roof	25,421	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Upper auditorium roof	180	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	Upper auditorium roof	1,625	SF	5	2-5 years	Blistering throughout. Engineer
							reports ongoing roof leaks
	Roof Structure - Heavy Timber	Upper auditorium roof	1,625	SF	7	10+ years	
	Coping - Stone	West auditorium roof	63	LF	7	10+ years	
	Downspouts - Exterior Downspouts	West auditorium roof	17	LF	7	10+ years	
	Parapet - Parapet > 30"	West auditorium roof	63	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	West auditorium roof	260	SF	5	2-5 years	Blistering throughout. Engineer
	Deaf Medified Differences		000	05	7	0.40	reports ongoing roof leaks
	Roof - Modified Bitumen	West auditorium roof	200	SF SF	7 7	6-10 years	
	Roof Structure - Heavy Timber	West auditorium roof	460	SF	1	10+ years	
/alls							
	Cheek-Wall - Stone	Entire Building	5	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	3	LF	5	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,474	LF	5	10+ years	
	Cornice - Metal Projecting	Entire Building	<sup>′</sup> 10	LF	5	1-2 years	Holes, tears, damaged, joint overlag
	Exterior Walls - Brick	Entire Building	42,427	SF	5	2-5 years	
	Exterior Walls - Brick	Entire Building	300	SF	4	1-2 years	Cracked brick open joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,000	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	4,786	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2	SF	4	1-2 years	Crack stone with chunk missing
Vindows	3						
	Guard - Guards perforated	Entire Building	2,146	SF	7	6-10 years	
	Guard - Guards wire guard	Entire Building	80	SF	6	10+ years	
	Lintels - Steel	Entire Building	873	LF	7	10+ years	
	Lintels - Steel	Entire Building	12	LF	6	10+ years	No buckling seen. Minor corrosion
	Lintels - Stone	Entire Building	606	LF	7	10+ years	
	Skylite - Glass Single-Pane	Entire Building	140	SF	6	10+ years	
	Windows - Louver	Entire Building	32	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	111	SF	7	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,881	SF	7	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
		Location	Quantity		Donk	Recommend	Commonte
Group	Item - Type	LUGALION	Quantity	UOM	Rank	Replacement	Comments
merger	Automatic Transfer Switch	1st Floor	1	EA	4	1-2 years	More than 40 years old, deteriorated serves independent service, functional



	ry : Electrical		В	uilding	: Main		
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	10	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	56,765	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	56,765	SF	5	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,288	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,691	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	5,672	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,719	SF	6	6-10 years	
1ain Se							
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	56,765	SF	6	6-10 years	
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Repaired
			1	EA EA	-	6-10 years	Repaired
	Lighting and Power Panels - 100 A	Entire Building	1 1 1		6	6-10 years 6-10 years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	Entire Building	1 1 1 4	EA	-	6-10 years 6-10 years 2-5 years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building	1 1 1 4 1	EA EA EA	6 6 7	6-10 years 6-10 years 2-5 years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building Entire Building	1 1 1 4 1 1	EA EA EA EA	6 6 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1	EA EA EA EA EA	6 6 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 1	EA EA EA EA EA	6 6 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 1	EA EA EA EA EA EA	6 6 7 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 1 2	EA EA EA EA EA EA EA	6 7 7 7 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 1	EA EA EA EA EA EA	6 6 7 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600 amp Main Distribution Panels - Greater than 600	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 1 2 2	EA EA EA EA EA EA EA EA	6 7 7 7 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Repaired
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600 amp	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 4 1 1 1 2 2 1	EA EA EA EA EA EA EA EA	6 7 7 7 7 7 7 7 7	6-10 years 6-10 years 2-5 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Repaired



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
re Aları	m						
	Fire ALarm Anunciator	1st Floor	1	EA	3	1-2 years	Old annunciator
	Fire Alarm Panel	1st Floor	1	EA	3	2-5 years	Old; not reliable, using relay logic
	Fire Alarm_System	1st Floor	56,765	SF	5	6-10 years	
ategoi	ry : Mechanical		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	1st Floor	1	EA	5	6-10 years	AHU1, AHU 2, AHU 3, serves mair building
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	1st Floor	1	EA	5	6-10 years	AHU1, AHU 2, AHU 3, serves mai building
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	1st Floor	1	EA	5	6-10 years	AHU1, AHU 2, AHU 3, serves mai building
	Air Intake	1st Floor	3	EA	6	6-10 years	5
	Auxiliaries - 15001 - 25000 cfm	1st Floor	3	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor	300	LF	5	6-10 years	
	Zone Dampers	1st Floor	31	EA	5	6-10 years	
iler Sy	stems						
-	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	Serves main building
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	Serves main building
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Steam Traps	Boiler Room	400	EA	7	6-10 years	Repaired
	Steam Traps	Boiler Room	55	EA	5	6-10 years	τοραιιου
ating [	Devices						
	Unit Heater - Steam	Boiler Room	3	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	4	EA	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Radiators - Steam	Entire Building	2	EA	3	0-1 year	Unit doesn't work. Room is very cold
	Fin Tube - Steam	Entire Building	20	LF	5	6-10 years	
_Tempera	ature Control						
	Electric Thermostat	Entire Building	3	EA	5	6-10 years	Serves unit heater
	Pneumatic System	Entire Building	56,765	SF	4	2-5 years	Serves main building
	Thermostats - Pneumatic	Entire Building	10	EA	5	6-10 years	C C
	Thermostats - Pneumatic	Entire Building	21	EA	4	2-5 years	Do not work/damaged
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor and Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st Floor and Roof	2	EA	5	6-10 years	

Catego	tegory : Plumbing			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Wate</u>	er Electric Heater  - 20 - 50 KW Gas Heater  - 150000 - 300000 BTU/HR	1st Floor Boiler Room	1 1	EA EA	5 7	6-10 years 10+ years	New unit
	Domestic Piping-Hot Water Return Lines	Entire Building	56,765	SF	4	2-5 years	Leaks are frequently repaired
	Domestic Piping-Hot Water Return Risers	Entire Building	56,765	SF	4	2-5 years	Pressure is low on top floor
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	56,765	SF	4	2-5 years	Many pipe clamps
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	56,765	SF	4	2-5 years	1911 installation, occasionally leaks
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	56,765	SF	4	2-5 years	Leaks frequently repaired
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	56,765	SF	4	2-5 years	There are pipe clamps
	Sanitary Piping	Entire Building	56,765	SF	5	6-10 years	
	Storm Piping	Entire Building	56,765	SF	5	6-10 years	
	Vent Piping	Entire Building	56,765	SF	5	6-10 years	
Pumps							
-	Pumps - Domestic Booster Pump-Simplex	Boiler Room	1	EA	7	6-10 years	New unit



GroupItem - TypeLocationQuantityUOMRankReplayAdministrative Suites/OfficesAC Unit1st Floor - Engineer Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Engineer Office361SF710+Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF61-2Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+Mork Slnk1st Floor - Engineer Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	nmend cement Comments years Years Ye
GroupItem - TypeLocationQuantityUOMRankReplayAdministrative Suites/OfficesAC Unit1st Floor - Engineer Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Engineer Office361SF710+Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+Mork Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA710+Doors - Side-lite1st Floor - Main Office1EA710+Doors - Side-lite1st Floor - Main Office58SF710+Doors - Side-lite1st Floor - Main Office58<	cement Comments years
Administrative Suites/OfficesAC Unit1st Floor - Engineer Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Engineer Office361SF710+Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office361SF610+Newer Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office285710+Doors - Side-lite1st Floor - Main Office58SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years years years years years years Deficiency priority changed to reflect current observations years
AC Unit1st Floor - Engineer Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Engineer Office361SF710+Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office361SF610+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years years years years years Deficiency priority changed to reflect current observations years
Ceiling - Plaster/Drywall1st Floor - Engineer Office361SF710+Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years years years years years Deficiency priority changed to reflect current observations years
Doors - Wood Doors inclu hw1st Floor - Engineer Office2EA710+Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years years years Deficiency priority changed to reflect current observations years
Floor - Tile1st Floor - Engineer Office361SF610+Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work Slnk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years years Deficiency priority changed to reflect current observations years
Lighting - Pendent/Surface1st Floor - Engineer Office4EA710+Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years years years Deficiency priority changed to reflect current observations years
Power Distribution1st Floor - Engineer Office4EA710+Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years years Deficiency priority changed to reflect current observations years
Storage/ Closet1st Floor - Engineer Office140SF510+Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years Deficiency priority changed to reflect current observations years
Walls - Plaster/Drywall1st Floor - Engineer Office691SF710+Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	current observations years
Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	
Walls - Plaster/Drywall1st Floor - Engineer Office50SF61-2Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	
Work SInk1st Floor - Engineer Office1EA710+AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	
AC Unit1st Floor - Main Office1EA76-10Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years
Ceiling - Plaster/Drywall1st Floor - Main Office287SF710+Doors - Side-lite1st Floor - Main Office58SF710+	years
Doors - Side-lite1st Floor - Main Office58SF710+	
	years
Doors - Transom Window 1st Floor - Main Office 16 SF 7 10+	years
	years
,	-
106B	years
Doors - Transom Window 1st Floor - Teacher's Lunchroom 12 SF 7 10+ 106B	years
Doors - Wood Doors inclu hw       1st Floor - Teacher's Lunchroom       1       EA       7       10+         106B	years
Floor - Tile 1st Floor - Teacher's Lunchroom 471 SF 7 10+ 106B	years
	years Cracking
	years



Catego	ry : Room		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
p	Ceiling - Plaster/Drywall	Auditorium/Gym - Office at back of	15	SF	4	1-2 years	Water damage
		stage			-	,	
	Doors - Wood Doors inclu hw	Auditorium/Gym - Office at back of	1	EA	7	10+ years	
		stage				, ,	
	Floor - Tile	Auditorium/Gym - Office at back of	118	SF	7	10+ years	
		stage					
	Floor - Tile	Auditorium/Gym - Office at back of	21	SF	5	1-2 years	Broken tiles
		stage				-	
	Lighting - Pendent/Surface	Auditorium/Gym - Office at back of	2	EA	7	10+ years	
		stage					
	Lighting - Pendent/Surface	Auditorium/Gym - Office at back of	1	EA	6	1-2 years	Re-lamp fixture
		stage					
	Power Distribution	Auditorium/Gym - Office at back of	2	EA	7	10+ years	
		stage					
	Walls - Plaster/Drywall	Auditorium/Gym - Office at back of	679	SF	7	10+ years	
		stage					
	AC Unit	Main Office - Principal	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office - Principal	164	SF	7	10+ years	
	Doors - Side-lite	Main Office - Principal	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office - Principal	2	EA	7	10+ years	
	Floor - Wood	Main Office - Principal	164	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Principal	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office - Principal	1	EA	6	1-2 years	Re-lamp fixture
	Power Distribution	Main Office - Principal	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office - Principal	723	SF	7	10+ years	
Symnas							
	Ceiling - Plaster/Drywall	1st Floor	5,472	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	200	SF	6	10+ years	
	Doors - Transom Window	1st Floor	98	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	7	10+ years	
	Floor - Concrete	1st Floor	1,852	SF	7	10+ years	
	Floor - Tile	1st Floor	308	SF	7	10+ years	<b>—</b>
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Broken tiles
	Floor - Wood	1st Floor	3,412	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	20	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	5	EA	7	10+ years	
	Main Floor Seating	1st Floor	397	EA	7	10+ years	
	Stage	1st Floor	721	SF	7	10+ years	
	Stage Curtain	1st Floor	2	EA	7	10+ years	
	Stage Lighting System	1st Floor	102	EA	7	10+ years	
	Stage-Stairs - Wood		50	LF	7	10+ years	



calego	ry : Room		B	uilding	: Main		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	817	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,373	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,211	SF	7	10+ years	
	,		,			,	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor - 101	920	SF	7	10+ years	
	Doors - Transom Window	1st Floor - 101	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - 101	1	EA	7	10+ years	
	Floor - Tile	1st Floor - 101	920	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - 101	13	ĒA	7	10+ years	
	Storage/ Closet	1st Floor - 101	203	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - 101	1,691	SF	7	10+ years	
			1,001	0.	•	let youro	
unch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor	1,691	SF	7	10+ years	
	Chalk Board	1st Floor	69	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Transom Window	1st Floor	23	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,669	SF	7	10+ years	
	Floor - Tile	1st Floor	22	SF	5	1-2 years	Worn and cracking
	Lighting - Pendent/Surface	1st Floor	28	ĒA	7	10+ years	
	Storage/ Closet	1st Floor	64	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,627	SF	7	10+ years	
			_,	•	•	let jeare	
MDF_ID							
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	414	SF	7	10+ years	
	Window AC Unit	1st Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Air Intake Plenums	1st Floor	586	SF	7	10+ years	
	Boiler Room	1st Floor	1,469	SF	7	10+ years	
	Coal Room	1st Floor	468	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	2.163	SF	7	10+ years	
	Storage Room	1st Floor	2,103	SF	7	10+ years	
	Janitor's Closet	2nd Floor	17	SF	5	10+ years	Relamp
	Janitor's Closet	3rd Floor	16	SF	5 7	10+ years	Reality
	Storage Room	3rd Floor	82	SF	7	•	
		3rd Floor 3rd Floor	82 80	SF	7	10+ years	
	Storage Room	310 1001	80	55	1	10+ years	
Restroor	n						
	Accessories	1st Floor	316	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	316	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	316	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	Re-lamp fixture
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	347	SF	7	10+ years	
	Walls - Masonry	1st Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	645	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	316	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	316	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	347	SF	7	10+ years	
	Walls - Masonry	1st Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	651	SF	7	10+ years	
	Water Closet	1st Floor	6	EA	7	10+ years	
	Accessories	1st Floor - inside Boys vestibule	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - inside Boys vestibule	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - inside Boys vestibule	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor - inside Boys vestibule	45	SF	7	10+ years	
	Lavatory	1st Floor - inside Boys vestibule	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - inside Boys vestibule	1	EA	7	10+ years	
	Partitions	1st Floor - inside Boys vestibule	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - inside Boys vestibule	214	SF	7	10+ years	
	Water Closet	1st Floor - inside Boys vestibule	1	EA	7	10+ years	
	Accessories	1st Floor - inside Main Office	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - inside Main Office	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - inside Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - inside Main Office	35	SF	7	10+ years	
	Lavatory	1st Floor - inside Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - inside Main Office	2	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor - inside Main Office	1	EA	7	10+ years	
	Partitions	1st Floor - inside Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - inside Main Office	190	SF	7	10+ years	
	Water Closet	1st Floor - inside Main Office	1	ĒA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Accessories	2nd Floor	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	316	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	316	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	5	1-2 years	Continually dripping
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	347	SF	7	10+ years	
	Walls - Masonry	2nd Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	645	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	316	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	316	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	347	SF	7	10+ years	
	Walls - Masonry	2nd Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	651	SF	7	10+ years	
	Water Closet	2nd Floor	6	EA	7	10+ years	
	Accessories	2nd Floor - inside Girls vestibule	59	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - inside Girls vestibule	59	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - inside Girls vestibule	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - inside Girls vestibule	59	SF	7	10+ years	
	Lavatory	2nd Floor - inside Girls vestibule	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - inside Girls vestibule	1	EA	7	10+ years	
	Partitions	2nd Floor - inside Girls vestibule	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - inside Girls vestibule	118	SF	7	10+ years	
	Water Closet	2nd Floor - inside Girls vestibule	1	EA	7	10+ years	
	Accessories	3rd Floor	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	316	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	316	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	7	10+ years	



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	3rd Floor	347	SF	7	10+ years				
	Walls - Masonry	3rd Floor	96	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	645	SF	7	10+ years				
	Water Closet	3rd Floor	2	EA	7	10+ years				
	Accessories	3rd Floor	316	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	311	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor	314	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor	2	SF	5	0-1 year	Missing tiles			
	Floor Drain	3rd Floor	1	EA	7	10+ years				
	Hand Dryer	3rd Floor	2	EA	7	6-10 years				
	Lavatory	3rd Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years				
	Partitions	3rd Floor	6	EA	7	10+ years				
	Walls - Concrete Block	3rd Floor	347	SF	7	10+ years				
	Walls - Masonry	3rd Floor	75	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	651	SF	7	10+ years				
	Water Closet	3rd Floor	6	EA	7	10+ years				
	Accessories	3rd Floor - inside Girls vestibule	59	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor - inside Girls vestibule	59	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor - inside Girls vestibule	1	EA	7	10+ years				
	Floor - Tile	3rd Floor - inside Girls vestibule	59	SF	7	10+ years				
	Lavatory	3rd Floor - inside Girls vestibule	1	EA	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor - inside Girls vestibule	1	EA	7	10+ years				
	Partitions	3rd Floor - inside Girls vestibule	1	EA	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor - inside Girls vestibule	118	SF	7	10+ years				
	Water Closet	3rd Floor - inside Girls vestibule	1	EA	7	10+ years				

Category	Classroom
Caleuory	CI222100111

Catego	Category : Classroom			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	m #104 (Music Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	812	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	762	SF	7	10+ years	
	Floor - Wood	1st Floor	50	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	52	LF	7	6-10 years	
	Storage/ Closet	1st Floor	63	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,494	SF	7	10+ years	



Catego	ry : Classroom		B	uilding	: Main		
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #105 (Dance Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	844	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	844	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Wall Mirrors	1st Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,515	SF	7	10+ years	
			1,010	0.	•	io: youro	
Classroo	om #106 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	892	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	912	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,583	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
						5	
Classroc	om #200 (Office)						
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	355	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	355	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	994	SF	7	10+ years	
Closers	m #201 (Begular Classroom)						
	om #201 (Regular Classroom) AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	882	SF	7	10+ years	
	Chalk Board	2nd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	19	SF			
					7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



-	200 N Hamlin AVENUE, Chicago, IL 606						
atego	ry : Classroom		В	uilding	: Main		
	Name Tema	Leastlen	Owentites		Daula	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	873	SF	7	10+ years	One ship a such as here tills a
	Floor - Tile	2nd Floor	9	SF	4	0-1 year	Cracking and broken tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,564	SF	7	10+ years	
assroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	882	SF	7	10+ years	
	Chalk Board	2nd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	882	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,564	SF	7	10+ years	
assroo	om #203 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	794	SF	7	10+ years	
	Floor - Tile	2nd Floor	18	SF	5	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,443	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	
			50	0	0	IOF years	
assroo	m #204 (Regular Classroom)	- · · -·					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	770	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	6	10+ years	
	Chalk Board	2nd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	



<u> </u>	Schools					2	200 N Hamlin AVENUE, Chicago, IL 6064
Catego	ry : Classroom		В	Building : Main			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,497	SF	7	10+ years	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	6	10+ years	
	Chalk Board	2nd Floor	17	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,489	SF	6	10+ years	
	om #206 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor	1 7	EA LF	7 7	6-10 years 10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	800	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,450	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	7	10+ years	
	Chalk Board	2nd Floor	39	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	812	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Lighting - I endent/ourlace	211011001	14	LA	'	ior years	



Catego	ry : Classroom		B	uilding	: Main		
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	2	EA	6	6-10 years	Relamp fixtures
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,385	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	10+ years	
lassroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	796	SF	6	10+ years	
	Chalk Board	2nd Floor	23	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	796	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,480	SF	7	10+ years	
	m #209 (Regular Classroom) AC Units Casework	2nd Floor 2nd Floor	2 10	EA LF	7 7	6-10 years 10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	804	SF	7	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,480	SF	7	10+ years	
Classroo	m #210 (Regular Classroom)	- · · -·					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	7	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,502	SF	7	10+ years	



Catego	ry : Classroom		В	Building : Main				
-						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #211 (Office)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	14	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	327	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	28	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	89	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	2nd Floor	327	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	1-2 years	Missing covers	
	Marker Board	2nd Floor	6	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	939	SF	7	10+ years		
lassroo	om #300 (Office)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	17	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	371	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	3rd Floor	371	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years		
	Marker Board	3rd Floor	4	LA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,005	SF	7	•		
	Walls - Flastel/Drywall	310 1001	1,005	SF	/	10+ years		
lassroo	om #301 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	7	SF	5	1-2 years	Bubbling from water damage	
	Chalk Board	3rd Floor	37	LF	4	2-5 years		
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Wood	3rd Floor	817	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	7	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	52	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,446	SF	6	10+ years		
lassroo	om #302 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	7	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	803	SF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water staining	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	water starning	
	Chair Board		20	LI	-	2 0 years		



Catego	Category : Classroom			uilding	• Main	2	2200 N Hamlin AVENUE, Chicago, IL 60647
Calego	y . Classicolli			Building : Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	Commente
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	808	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,432	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Cracked
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	813	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	813	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,421	SF	7	10+ years	
Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	812	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,613	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	30	SF	6	10+ years	
Classroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	812	SF	7	10+ years	
	Chalk Board	3rd Floor	17	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	812	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
<b>O</b>	Items Truns	Leastien	Quantitu		Dank	Recommend	Commente
Group	Item - Type Marker Board	Location 3rd Floor	Quantity	UOM LF	Rank 7	Replacement 6-10 years	Comments
	Storage/ Closet	3rd Floor	6 54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,450	SF	7	10+ years	
	Walls - Plastel/Drywall	310 11001	1,450	35	1	TO+ years	
Classroc	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	806	SF	7	10+ years	
	Chalk Board	3rd Floor	23	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	806	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,450	SF	7	10+ years	
Classroc	m #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	821	SF	7	10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	821	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	7	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,648	SF	6	10+ years	
			1,040	56	0	IUT years	
Classroc	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	814	SF	7	10+ years	
	Chalk Board	3rd Floor	23	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	814	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	10+ years	
	Work Sink	3rd Floor	· 1	EA	7	10+ years	



Cataga	ry : Classroom		D	uilding	· Main		2200 N Hamlin AVENUE, Chicago, IL 606	
alego	ry . Classiooili		В	unung				
	Hom Turne	Location	Quantity		Donk	Recommend	Commente	
iroup	Item - Type AC Units	3rd Floor	Quantity	UOM EA	Rank 7	Replacement 6-10 years	Comments	
			2 7		7	•		
	Casework	3rd Floor		SF		10+ years		
	Ceiling - Plaster/Drywall Chalk Board	3rd Floor 3rd Floor	811	SF LF	7	10+ years		
	Doors - Transom Window	3rd Floor	15 12	SF	4	2-5 years		
					7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Wood	3rd Floor	811	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	6	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	54	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,452	SF	6	10+ years		
lassroc	m #310 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	5	1-2 years	Units covered	
	Casework	3rd Floor	7	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	806	SF	7	10+ years		
	Chalk Board	3rd Floor	25	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Wood	3rd Floor	806	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	8	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	51	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,447	SF	7	10+ years		
lassroc	m #311 (Special Program)							
	Casework	3rd Floor	11	LF	7	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	371	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	3rd Floor	371	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	2	EA	5	1-2 years	Missing covers	
	Marker Board	3rd Floor	2		5 7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,001	SF	7	10+ years		
• oto a o	n Intorior		Р	سنامانهم	Main			
alego	ry : Interior		В	uilding		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	1st Floor	3,520	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	150	SF	5	1-2 years	Water damage	
			100	~ -	_			

Doors - Transom Window

Doors - Wood Doors include hw

Drinking Fountains - Double Fountain

1st Floor

1st Floor

1st Floor

SF

ΕA

EΑ

120

12

2

7

7

7

10+ years

10+ years

6-10 years



Catego	ry : Interior		В	uilding	: Main		
U	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	3,500	SF	7	10+ years	
	Floor - Asphalt Floor	1st Floor	20	SF	5	1-2 years	Cracks
	Lighting - Pendent/Surface	1st Floor	64	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	1-2 years	Re-lamp fixture
	Lighting - Wall Mounted	1st Floor	4	EA	7	10+ years	
	Stairs - Concrete Stairs	1st Floor	23	LF	7	10+ years	
	Walls - Masonry	1st Floor	450	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	8,819	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	527	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,156	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	150	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,306	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,342	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,587	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	2,587	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	94	EA	7	10+ years	Not previously assessed
	Walls - Plaster/Drywall	3rd Floor	4,828	SF	7	10+ years	
afety							
-	Camera Viewing Station	1st Floor	3	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
	Security Cameras	1st Floor	5	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	8	EA	7	6-10 years	
stairs							
	Ceiling - Plaster/Drywall	North	325	SF	7	10+ years	
	Floor - Asphalt	North	165	SF	6	10+ years	
	Handrails	North	159	LF	7	10+ years	
	Lighting - Pendent/Surface	North	3	EA	7	10+ years	
	Lighting - Wall Mounted	North	2	EA	7	10+ years	
	Stairs - Asphalt	North	336	LF	7	10+ years	
	Walls - Plaster/Drywall	North	1,494	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	325	SF	7	10+ years	
	Floor - Asphalt	South	165	SF	6	10+ years	
	Handrails	South	159	LF	7	10+ years	
	Lighting - Pendent/Surface	South	3	EA	7	10+ years	
	Lighting - Wall Mounted	South	2	EA	7	10+ years	



Category : Interior			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Asphalt	South	56	LF	7	10+ years	
	Walls - Plaster/Drywall	South	1,494	SF	7	10+ years	



**Category : Exterior** 

**Building : Linked Addition** 

Recommend

Location Replacement Item - Type Quantity UOM Comments Group Rank Entrance FΑ 7 Exterior Doors - Exterior Steel Door #10- NW- Kitchen marked as 8 1 10+ years 2 FΑ Exterior Doors - Exterior Steel Door #10.5- NW- Yard Storage 1-2 vears Corroded door and frames 4 7 Exterior Doors - Exterior Steel Door #11- NW- Elec 1 EΑ 10+ years Exterior Doors - Side lite #12- NE marked as 9 2 ΕA 6 10+ years Exterior Doors - Store Front #12- NE marked as 9 2 EΑ 6 10+ years Exterior Doors - Transom Lite #12- NE marked as 9 1 EA 6 10+ years Entrance Control - Audio and Video #13- E marked as 10 1 FΑ 7 6-10 years Exterior Doors - Side lite #13- E marked as 10 2 ΕA 6 10+ vears Exterior Doors - Store Front #13- E marked as 10 2 FΑ 6 10+ years Exterior Doors - Transom Lite FΑ #13- E marked as 10 1 6 10+ vears 2 Exterior Doors - Side lite #14- SE EΑ 6 10+ years Exterior Doors - Store Front #14- SE ΕA 6 1 10+ years Exterior Doors - Transom Lite #14- SE 1 FA 6 10+ years #15- SE 2 Exterior Doors - Side lite EΑ 6 10+ years #15- SE Exterior Doors - Store Front 1 FΑ 6 10+ years Exterior Doors - Transom Lite #15- SE FΑ 6 10+ years 1 Exterior Doors - Store Front #16- SE marked 14 1 ΕA 6 10+ vears Exterior Doors - Transom Lite #16- SE marked 14 1 FΑ 6 10+ vears **Entrance Control - Audio** #17- SE marked 11 1 ΕA 7 6-10 years 2 ΕA Exterior Doors - Store Front #17- SE marked 11 6 10+ years Exterior Doors - Transom Lite #17- SE marked 11 1 ΕA 6 10+ vears 7 Power Door Operator and Controls #17- SE marked 11 1 FΑ 6-10 years Exterior Doors - Side lite #6- SW 2 FΑ 6 10+ years Exterior Doors - Store Front #6- SW 1 FΑ 6 10+ years Exterior Doors - Transom Lite #6- SW 1 FΑ 6 10+ vears Exterior Doors - Side lite #7- SW 2 EA 6 10+ years #7- SW Exterior Doors - Store Front 1 EA 6 10+ years Exterior Doors - Transom Lite #7- SW 1 EΑ 6 10+ years Exterior Doors - Side lite #8- SW 2 ΕA 10+ years 6 Exterior Doors - Store Front #8- SW 1 ΕA 6 10+ years #8- SW Exterior Doors - Transom Lite 1 EΑ 6 10+ years Exterior Doors - Store Front #9- NW numbered as 7 4 FΑ 6 10+ vears 3 #9- NW numbered as 7 FΑ 6 Exterior Doors - Transom Lite 10+ years **Exterior Stairs - Concrete** #9- NW numbered as 7 22 1 F 6 6-10 years LF Exterior Stairs - Concrete #9- NW numbered as 7 8 5 1-2 years Cracked stone Foundation LF Foundation - Concrete Entire Building 390 7 10+ years Superstructure - Steel Entire Building 35.600 SF 7 10+ vears Lighting



Stairs

Room

Stairs

	Schools					2	200 N Hamlin AVENUE, Chicago, IL 60647
Catego	ry : Exterior		В	uilding	: Linke	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	7	6-10 years	
Roof Sy	stem						
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	40	LF	7	10+ years	
	Coping - Stone	Main Roof	640	LF	7	10+ years	
	Downspouts - Interior Downspouts	Main Roof	405	LF	7	10+ years	
	Parapet - 16" - 30" Height	Main Roof	622	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	18	LF	7	10+ years	
	Roof - Modified Bitumen	Main Roof	1,332	SF	5	2-5 years	No access. Worn old roof. Blistering throughout
	Roof - Modified Bitumen	Main Roof	16,477	SF	5	2-5 years	Worn surface blistering throughout
	Roof Hatch - Metal	Main Roof	10,11	EA	7	10+ years	Worn Bundeb Biotering Inbughout
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	17,809	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	18,430	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	300	SF	5	1-2 years	Disintegrated sealant at control joints
	Exterior Walls - Stone-Cast	Entire Building	672	SF	6	10+ years	
Window	S						
	Curtain wall - Louver	Entire Building	378	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	2,268	SF	7	10+ years	
	Lintels - Steel	Entire Building	672	LF	7	10+ years	
	Windows - Casement Steel Double-pane	Entire Building	5,103	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
2	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	7	EA	6	6-10 years	
					-		

Security System - CCTV

Emergency Battery Packs - Corridors and

Emergency Battery Packs - Multipurpose

Security System - Intrusion Detection

Emergency A/C Power - Corridors and

Emergency Battery Packs - Students Toilets

6

2

1

35,600

35,600

7,272

ΕA

ΕA

ΕA

SF

SF

SF

6

6

6

6

6

6

6-10 years

6-10 years

10+ years

6-10 years

6-10 years

6-10 years

Entire Building

**Entire Building** 

Entire Building

Entire Building

Entire Building

Entire Building

Connected to main building



	Schools					2	200 N Hamlin AVENUE, Chicago, IL 60647
Catego	ry : Electrical		B	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Lunchrooms	Entire Building	1,245	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,909	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	744	SF	6	6-10 years	
	Automatic Transfer Switch	Mechanical Room	1	EA	6	6-10 years	
Main Se	rvice						
	PA System	1st Floor	35,600	SF	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Mechanical Room	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Linked	d Addition	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Mechanical Room	1	EA	6	6-10 years	
	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Mechanical Room	35,600	SF	6	10+ years	
	Fire Alarm_System	Mechanical Room	35,600	SF	6	10+ years	
	Fire Pump Controller	Mechanical Room	1	EA	6	10+ years	
Pump R	oom Assembly						
	Fire Pump - 51-75hp	Mechanical Room	1	EA	6	10+ years	
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	

r Svstem						
Sprinkler Heads	Entire Building	35,600	SF	7	10+ years	
Sprinkler Piping	Entire Building	35,600	SF	6	10+ years	
Wet Sprinkler System	Entire Building	35,600	SF	6	10+ years	



							200 N Hamlin AVENUE, Chicago, IL 60647		
Catego	ry : Mechanical		В	Building : Linked Addition					
0	14 <b>T</b>	I a a a d'a m	Owentites		Daula	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Conc		Dest	4	Ε Δ		0.40			
	Chemical Pot Feeder	Roof	1	EA EA	5	6-10 years			
	Chiller-Air Cooled-Screw Type-Roof Mounted - 101 - 200 tons	Roof	1	EA	5	6-10 years			
	Glycol Feed	Roof	1	EA	6	6-10 years			
	Pipes - Chilled Water Pipe- Steel	Roof	200	LF	6	10+ years			
	Pressure Fill System	Roof	1	EA	6	6-10 years			
Air Hanc	lling Systems								
	Fan Power Box - Fan Power Box with Hot	Entire Building	26	EA	5	6-10 years	Above ceiling, difficult to access		
	Water Coil	Entre Dananig	20	<b>_</b> / (	Ũ	e re jeure	, loove coming, amount to accese		
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	AHU-1		
	Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm								
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years	AHU-2		
	Indoor- Hot Water and Chilled Water Coils -								
	8001-12000 cfm								
	Air Intake	Mechanical Room	2	EA	6	6-10 years			
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	5	6-10 years			
	Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm								
	Air Intake	Mechanical Room	1	EA	6	6-10 years			
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	5	6-10 years			
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	2	EA	5	6-10 years			
Boiler S	vstems								
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	5	6-10 years			
	- 500 - 1000 MBH			Ξ.	-	0.40			
	Chemical Pot Feeder	Mechanical Room	1	EA	5	6-10 years			
	Combustion Dampers	Mechanical Room	2	EA EA	6 5	6-10 years			
	Glycol Feed System	Mechanical Room	1	EA		6-10 years			
	Hot Water Pump	Mechanical Room	1	EA	5	6-10 years			
	Hot Water Pump	Mechanical Room	1		5	6-10 years			
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Mechanical Room	1	EA	5	6-10 years			
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 -	Mechanical Room	1	EA	5	6-10 years			
	1000 MBH								
	Water Fill System	Mechanical Room	1	EA	6	6-10 years			



Catego	ry : Mechanical		Building : Linked Addition					
0	tions Toma		•		D. 1	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Heating	Devices							
	Unit Heater - Electric	1st Floor	1	EA	5	10+ years		
	Fin Tube - Hot Water	Entire Building	42	LF	6	10+ years		
	Fin Tube - Hot Water	Entire Building	8	LF	5	1-2 years	Corroded	
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	10+ years		
Mechani	cal Plumbing							
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years		
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	5	6-10 years		
Tompor	ature Control							
тетрек	DDC System	Entire Building	35,600	SF	5	6-10 years		
	Electric Thermostat	Entire Building	33,000	EA	6	10+ years		
	Thermostats - DDC	Entire Building	26	EA	6	6-10 years		
	memosiais - DDC		20	LA	0	0-10 years		
Ventilati								
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	roof and 1st fl	3	EA	5	6-10 years		
Catego	ry : Plumbing		В	uilding	I Addition			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Hot Wat	er							
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	5	6-10 years		
Piping								
- ping_	Domestic Piping-Hot Water Return Lines	Entire Building	35,600	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	35,600	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to	Entire Building	35,600	SF	6	10+ years		
	Fixtures	5			-	IUT years		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,600	SF	6	10+ years		
		Fatine Duilding	25 600	SF	6	10+ years		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	35,600	01	0	for youro		
	Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply	Entire Building	35,600	SF	6	10+ years		



**Building : Linked Addition Category : Plumbing** Recommend Group Quantity Location UOM Item - Type Rank **Replacement** Comments (from Risers to Fixtures) Sanitary Piping Entire Building 35,600 SF 6 10+ years Storm Piping 35,600 SF 10+ years Entire Building 6 Vent Piping Entire Building 35,600 SF 6 10+ years Pumps Pumps - Domestic Booster Pump-Duplex Mechanical Room 1 ΕA 5 6-10 years Pumps - Sump-Simplex ΕA 6 10+ years Mechanical Room 1

**Building : Linked Addition** 

#### Category : Room

J	, , , , , , , , , , , , , , , , , , ,			Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
dminis	rative Suites/Offices								
	Ceiling - Lay-in	400 Counselor's Office	198	SF	7	10+ years			
	Doors - Wood Doors inclu hw	400 Counselor's Office	1	EA	7	10+ years			
	Floor - Carpet	400 Counselor's Office	198	SF	7	6-10 years			
	Lighting - Lay-in	400 Counselor's Office	3	EA	7	6-10 years			
	Power Distribution	400 Counselor's Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	400 Counselor's Office	587	SF	7	10+ years			
	Ceiling - Lay-in	400 Nurse's Office	140	SF	7	10+ years			
	Doors - Wood Doors inclu hw	400 Nurse's Office	2	EA	7	10+ years			
	Floor - Tile	400 Nurse's Office	140	SF	7	6-10 years			
	Lighting - Lay-in	400 Nurse's Office	2	EA	7	6-10 years			
	Power Distribution	400 Nurse's Office	4	EA	7	10+ years			
	Walls - Plaster/Drywall	400 Nurse's Office	480	SF	7	10+ years			
	Work SInk	400 Nurse's Office	1	EA	7	10+ years			
	Ceiling - Lay-in	400 Office	628	SF	7	10+ years			
	Doors - Wood Doors inclu hw	400 Office	1	EA	7	10+ years			
	Floor - Carpet	400 Office	478	SF	7	6-10 years			
	Floor - Tile	400 Office	150	SF	7	10+ years			
	Lighting - Lay-in	400 Office	8	EA	7	6-10 years			
	Power Distribution	400 Office	12	EA	7	10+ years			
	Walls - Concrete Block	400 Office	933	SF	7	10+ years			
	Walls - Plaster/Drywall	400 Office	822	SF	7	10+ years			
	Ceiling - Lay-in	400 Office Vault	153	SF	7	10+ years			
	Doors - Steel Doors incl hw	400 Office Vault	1	EA	7	10+ years			
	Floor - Tile	400 Office Vault	153	SF	7	6-10 years			
	Lighting - Lay-in	400 Office Vault	2	EA	7	6-10 years			
	Power Distribution	400 Office Vault	6	EA	7	10+ years			
	Walls - Concrete Block	400 Office Vault	582	SF	7	10+ years			
	Work SInk	400 Office Vault	1	EA	7	10+ years			
	Ceiling - Lay-in	400 Principal's Office	124	SF	7	10+ years			
	Doors - Wood Doors inclu hw	400 Principal's Office	1	EA	7	10+ years			
	Floor - Carpet	400 Principal's Office	124	SF	7	6-10 years			



Catego	ry : Room		В	Building : Linked Addition					
Ŭ	•		Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Lighting - Lay-in	400 Principal's Office	2	EA	7	6-10 years			
	Power Distribution	400 Principal's Office	6	EA	7	10+ years			
	Walls - Concrete Block	400 Principal's Office	62	SF	7	10+ years			
	Walls - Plaster/Drywall	400 Principal's Office	332	SF	7	10+ years			
	Ceiling - Lay-in	400 Sensory Room	194	SF	7	10+ years			
	Doors - Wood Doors inclu hw	400 Sensory Room	2	EA	7	10+ years			
	Floor - Carpet	400 Sensory Room	194	SF	7	6-10 years			
	Lighting - Lay-in	400 Sensory Room	3	EA	7	6-10 years			
	Power Distribution	400 Sensory Room	6	EA	7	10+ years			
	Walls - Plaster/Drywall	400 Sensory Room	194	SF	7	10+ years			
	Ceiling - Lay-in	Rm 509 2nd Floor Faculty	574	SF	7	10+ years			
	Ceiling - Lay-in	Rm 509 2nd Floor Faculty	8	SF	4	1-2 years	Water damage		
	Doors - Hardware	Rm 509 2nd Floor Faculty	1	EA	6	1-2 years	Hardware sticks		
	Doors - Side-lite	Rm 509 2nd Floor Faculty	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Rm 509 2nd Floor Faculty	1	EA	7	10+ years			
	Floor - Carpet	Rm 509 2nd Floor Faculty	458	SF	7	6-10 years			
	Floor - Tile	Rm 509 2nd Floor Faculty	124	SF	7	6-10 years			
	Lighting - Lay-in	Rm 509 2nd Floor Faculty	8	EA	7	6-10 years			
	Power Distribution	Rm 509 2nd Floor Faculty	8	EA	7	10+ years			
	Walls - Concrete Block	Rm 509 2nd Floor Faculty	258	SF	7	10+ years			
	Walls - Plaster/Drywall	Rm 509 2nd Floor Faculty	564	SF	7	10+ years			
	Work SInk	Rm 509 2nd Floor Faculty	1	EA	7	10+ years			
Kitchen									
	Ceiling - Plaster/Drywall	1st Floor	1,194	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	1st Floor	1,194	SF	7	6-10 years			
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years			
	Serving Line	1st Floor	14	LF	7	10+ years			
	Storage/ Closet	1st Floor	133	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	1,402	SF	7	10+ years			
ibrary									
-	Casework	507 2nd Floor	155	LF	7	10+ years			
	Ceiling - Lay-in	507 2nd Floor	2,106	SF	7	10+ years			
	Ceiling - Lay-in	507 2nd Floor	36	SF	4	1-2 years	Water damage		
	Doors - Transom Window	507 2nd Floor	88	SF	7	10+ years	-		
	Doors - Wood Doors inclu hw	507 2nd Floor	2	EA	7	10+ years			
	Floor - Carpet	507 2nd Floor	2,142	SF	7	6-10 years			
	Lighting - Lay-in	507 2nd Floor	29	EA	7	6-10 years			
	Walls - Concrete Block	507 2nd Floor	1,435	SF	7	10+ years			
	Walls - Concrete Block	507 2nd Floor	15	SF	6	1-2 years	Cracking mortar		
	Walls - Plaster/Drywall	507 2nd Floor	508	SF	7	10+ years	3		



Catego	ry : Room		B	Building : Linked Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Locker/S	Shower Room								
	Accessories	Kitchen Locker room	34	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Kitchen Locker room	34	SF	7	10+ years			
	Doors - Steel Doors incl hw	Kitchen Locker room	1	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	Kitchen Locker room	34	SF	7	6-10 years			
	Floor Drain	Kitchen Locker room	1	EA	7	10+ years			
	Lavatory	Kitchen Locker room	1	EA	7	10+ years			
	Lighting - Lay-in	Kitchen Locker room	1	EA	7	6-10 years			
	Student Lockers - Two Tier	Kitchen Locker room	8	EA	7	10+ years			
	Walls - Concrete Block	Kitchen Locker room	202	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	406	1,245	SF	7	10+ years			
	Doors - Side-lite	406	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	406	2	EA	7	10+ years			
	Floor - Tile	406	1,243	SF	7	6-10 years			
	Floor - Tile	406	2	SF	5	1-2 years	Chipped		
	Lighting - Lay-in	406	13	ĒA	7	6-10 years	- 11		
	Lighting - Lay-in	406	3	EA	6	6-10 years	Lay-in		
	Walls - Concrete Block	406	1,028	SF	7	10+ years			
	Ceiling - Exposed	408 1st Floor	1,909	SF	7	10+ years			
	Doors - Wood Doors inclu hw	408 1st Floor	2	EA	7	10+ years			
	Floor - Tile	408 1st Floor	1,909	SF	7	6-10 years			
	Lighting - Pendent/Surface	408 1st Floor	24	ĒA	7	6-10 years			
	Market Board	408 1st Floor	5	LF	7	10+ years			
	Walls - Concrete Block	408 1st Floor	2,217	SF	7	10+ years			
	Walls - Concrete Block	408 1st Floor	277	SF	7	10+ years			
MDF_ID	F								
_	Doors - Wood Doors inclu hw	2nd Floor inside Fan Room	1	EA	7	10+ years			
	Finishes	2nd Floor inside Fan Room	491	SF	7	10+ years			
	Window AC Unit	2nd Floor inside Fan Room	1	EA	7	6-10 years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	120	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	250	SF	7	10+ years	Deficiency fixed		
	Mechanical/ Service Rooms	1st Floor	267	SF	7	10+ years			
	Storage Room	1st Floor	100	SF	7	10+ years	Deficiency fixed		
	Mechanical/ Service Rooms	2nd Floor	1,745	SF	7	10+ years			
Restroor	n								
	Accessories	1st Floor	39	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	39	SF	7	10+ years			
	<u> </u>				-	,			



Catego	ry : Room		R	uilding	·Linker	Addition	200 N Hamiin AVENUE, Chicago, IL 60647
Calego			D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	39	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	204	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	42	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	210	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	186	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	186	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Urinals	1st Floor	3	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	549	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	186	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	186	SF	7	6-10 years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	549	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	
	Accessories	2nd Floor - Boy's Restroom 513	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boy's Restroom 513	186	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Boy's Restroom 513	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boy's Restroom 513	186	SF	7	6-10 years	
	Floor Drain	2nd Floor - Boy's Restroom 513	1	EA	7	10+ years	



Category : Room **Building : Linked Addition** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments 2nd Floor - Boy's Restroom 513 Hand Drver ΕA 10+ vears 7 1 2nd Floor - Boy's Restroom 513 2 ΕA 7 Lavatorv 10+ years Updated to match current observations 3 ΕA 7 Lighting - Lay-in 2nd Floor - Boy's Restroom 513 6-10 years Partitions 2nd Floor - Boy's Restroom 513 1 EA 7 10+ years 3 2nd Floor - Boy's Restroom 513 7 Urinals EΑ 10+ years Walls - Tile Ceramic/ Porcelain 2nd Floor - Boy's Restroom 513 549 SF 7 10+ years 10+ years Water Closet 2nd Floor - Boy's Restroom 513 1 EΑ 7 Accessories 2nd Floor - Girl's Restroom 512 186 SF 7 6-10 years SF Ceiling - Plaster/Drvwall 2nd Floor - Girl's Restroom 512 186 7 10+ vears Doors - Wood Doors inclu hw 2nd Floor - Girl's Restroom 512 1 EΑ 7 10+ vears Floor - Tile Ceramic/ Porcelain 2nd Floor - Girl's Restroom 512 186 SF 7 6-10 years Hand Dryer ΕA 7 2nd Floor - Girl's Restroom 512 1 10+ years 7 Lavatory 2nd Floor - Girl's Restroom 512 2 EΑ 10+ years Lighting - Lay-in 5 2nd Floor - Girl's Restroom 512 1 EΑ 1-2 years Cover loose Lighting - Pendent/Surface 2 FΑ 7 2nd Floor - Girl's Restroom 512 6-10 years 7 Partitions 2nd Floor - Girl's Restroom 512 4 EΑ 10+ vears SF Walls - Tile Ceramic/ Porcelain 2nd Floor - Girl's Restroom 512 549 7 10+ years ΕA Water Closet 2nd Floor - Girl's Restroom 512 4 7 10+ vears 40 Accessories 400 Office SF 7 6-10 years Ceiling - Plaster/Drywall 400 Office 40 SF 7 10+ years 7 Doors - Wood Doors inclu hw 400 Office 1 EΑ 10+ years 40 SF 7 Floor - Tile Ceramic/ Porcelain 400 Office 6-10 years Floor Drain 400 Office FΑ 7 10+ years 1 FΑ 7 Lavatory 400 Office 1 10+ years Lighting - Lav-in 400 Office 1 ΕA 7 10+ vears Walls - Tile Ceramic/ Porcelain SF 400 Office 204 7 10+ years Water Closet 400 Office ΕA 7 1 10+ years SF Accessories 401 36 7 6-10 years Ceiling - Plaster/Drywall 401 36 SF 7 6-10 years Doors - Wood Doors inclu hw 401 1 FΑ 7 10+ vears Floor - Tile Ceramic/ Porcelain 401 36 SF 7 6-10 years FΑ 7 Floor Drain 401 1 10+ years 401 FΑ 7 10+ vears Lavatorv 1 7 Lighting - Lay-in 401 1 EΑ 6-10 years Walls - Tile Ceramic/ Porcelain SF 7 401 191 10+ years Water Closet 401 1 EΑ 7 10+ years SF 7 Accessories 402/403 36 6-10 years SF Ceiling - Plaster/Drywall 402/403 36 7 10+ years ΕA Doors - Wood Doors inclu hw 402/403 1 7 10+ vears SF Floor - Tile Ceramic/ Porcelain 402/403 36 7 6-10 years FΑ 7 Floor Drain 402/403 1 10+ vears Lavatory 402/403 EΑ 7 10+ years 1 Lighting - Lay-in 402/403 1 EΑ 7 6-10 years



Category : Room		В	uilding	: Linked	Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	402/403	191	SF	7	10+ years	
	Water Closet	402/403	1	EA	7	10+ years	
	Accessories	404/405	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	404/405	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	404/405	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	404/405	36	SF	7	6-10 years	
	Floor Drain	404/405	1	EA	7	10+ years	
	Lavatory	404/405	1	EA	7	10+ years	
	Lighting - Lay-in	404/405	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	404/405	191	SF	7	10+ years	
	Water Closet	404/405	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Linked	Addition	
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #401 (Kindergarten)						
	Casework	2nd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,130	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
				-			

	Casework	211011001	40		'	IUT years	
	Ceiling - Lay-in	2nd Floor	1,130	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,130	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	3	EA	6	6-10 years	Re-lamp fixture
	Walls - Concrete Block	2nd Floor	659	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	344	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
						,	
C	lassroom #402 (Kindergarten)						
	Casework	1st Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,130	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,130	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	2	EA	6	6-10 years	Re-lamp fixture
	Walls - Concrete Block	1st Floor	839	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	344	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_C	lassroom #403 (Kindergarten)						
	Casework	1st Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,125	SF	7	10+ years	
			,	-			



Catego	ry : Classroom		Building : Linked Addition					
caloge			_	anang		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	1st Floor	5	SF	5	1-2 years	Water damage	
	Chalk Board	1st Floor	20	LF	4	2-5 years	C	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,130	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	859	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	344	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroc	om #404 (Pre School)							
	Casework	1st Floor	30	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	845	SF	7	10+ years		
	Chalk Board	1st Floor	20	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	845	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor	788	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroc	om #405 (Pre School)							
	Casework	1st Floor	38	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years		
	Doors - Side-lite	1st Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	. <u>-</u> 1	EA	7	10+ years		
	Floor - Tile	1st Floor	890	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
	Marker Board	1st Floor		LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	608	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	330	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroc	om #500 (Regular Classroom)							
	Casework	2nd Floor	50	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	890	SF	7	6-10 years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	12	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	12	EA	6	10+ years		
	Floor - Tile	2nd Floor	890	SF	6	6-10 years		
			090	5	0	U- IU years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		



Catego	ry : Classroom		В	Building : Linked Addition					
-						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
-	Walls - Concrete Block	2nd Floor	411	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	523	SF	6	10+ years			
assroo	om #501 (Other Instructional Use)								
	Ceiling - Lay-in	2nd Floor	326	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage		
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	C C		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	336	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	4	EA	7	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	690	SF	7	10+ years			
lassroo	om #502 (Regular Classroom)								
	Casework	2nd Floor	50	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	872	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage		
	Chalk Board	2nd Floor	20	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	880	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	395	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	614	SF	7	10+ years			
lassroo	om #503 (Regular Classroom)								
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years			
	Chalk Board	2nd Floor	30	LF	4	2-5 years			
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	880	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	395	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	614	SF	7	10+ years			
lassroo	om #504 (Regular Classroom)								
	Casework	2nd Floor	52	LF	7	10+ years			
		2nd Floor	1,180	SF	7	10+ years			
	Ceiling - Lav-in				•	10. 300.0			
	Ceiling - Lay-in Chalk Board			IF	4	2-5 years			
	Chalk Board	2nd Floor	10	LF SF	4 7	2-5 years 10+ years			
				LF SF EA	4 7 7	2-5 years 10+ years 10+ years			



atego	ry : Classroom		В	uilding	: Linked	Addition	
_	-			_		Recommend	
Foup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	676	SF	7	10+ years	
lassroo	m #505 (Regular Classroom)						
	Casework	2nd Floor	52	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,172	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	, 8	SF	4	1-2 years	Water stains
	Doors - Side-lite	2nd Floor	24	SF	7	10+ vears	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	1,180	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	 16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	676	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	530	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	5	1-2 years	Continually dripping
lassroo	m #506 (Regular Classroom)						
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water stains
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	396	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	615	SF	7	10+ years	
assroo	m #508 (Music Room)						
	Ceiling - Lay-in	2nd Floor	1,110	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	, 10 10	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,120	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	336	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	537	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
assroo	m #510 (Special Education)						
	Casework	2nd Floor	23	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	488	SF	6	10+ years	



atego	ry : Classroom		B	Building : Linked Addition					
						Recommend			
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	2nd Floor	2	SF	4	1-2 years	Water stains		
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	490	SF	7	6-10 years			
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	270	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	450	SF	7	10+ years			
		21011001	400	0i	1	TOF years			
lassroo	m #511 (Special Program)				7	-			
lassroo	m #511 (Special Program) Casework	2nd Floor	23	LF	7	10+ years			
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in	2nd Floor 2nd Floor	23 470	LF SF	7 7 4	10+ years 10+ years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in	2nd Floor 2nd Floor 2nd Floor	23 470 20	LF SF SF	7 7 4 7	10+ years 10+ years 1-2 years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	23 470	LF SF SF SF	7 7 4 7 7	10+ years 10+ years 1-2 years 10+ years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	2nd Floor 2nd Floor 2nd Floor	23 470 20 12 1	LF SF SF SF EA	7 7 4 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	23 470 20	LF SF SF EA SF	7 7 4 7 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	23 470 20 12 1 490	LF SF SF EA SF EA	7 7 4 7 7 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years 6-10 years	Water stains		
lassroo	m #511 (Special Program) Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Lighting - Lay-in	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	23 470 20 12 1 490 6	LF SF SF EA SF	7 7 4 7 7 7 7 7 7	10+ years 10+ years 1-2 years 10+ years 10+ years 6-10 years	Water stains		

### **Category : Interior**

### Building : Linked Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	4,379	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	5	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	264	SF	7	10+ years	
	Doors - Side-lite	1st Floor	90	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Doors - Store Front	1st Floor	8	EA	7	10+ years	
	Doors - Transom Window	1st Floor	64	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	3	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,699	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	2,954	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Broken tiles
	Lighting - Lay-in	1st Floor	55	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,839	SF	7	10+ years	
	Walls - Masonry	1st Floor	300	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,009	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,874	SF	6	10+ years	Updated to match current observations
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	



Catego	ory : Interior		Building : Linked Addition				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile/Sheet	2nd Floor	2,872	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2	SF	5	1-2 years	Cracking tiles
	Lighting - Lay-in	2nd Floor	44	EA	7	6-10 years	C
	Walls - Structural Glazed Tile	2nd Floor	3,549	SF	7	10+ years	
Safety							
	Security Cameras	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
Stairs							
	Floor - Rubber Floor	East	18	SF	7	6-10 years	
	Handrails	East	62	LF	7	10+ years	
	Stairs - Rubber	East	26	LF	7	10+ years	
	Walls - Structural Glazed Tile	East	200	SF	7	10+ years	
	Floor - Rubber Floor	North West	14	SF	7	6-10 years	
	Handrails	North West	62	LF	7	10+ years	
	Stairs - Rubber	North West	26	LF	7	10+ years	
	Walls - Structural Glazed Tile	North West	200	SF	7	10+ years	
	Floor - Rubber Floor	South West	14	SF	7	6-10 years	
	Handrails	South West	62	LF	7	10+ years	
	Stairs - Rubber	South West	26	LF	7	10+ years	
	Walls - Structural Glazed Tile	South West	200	SF	7	10+ years	
Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	7	10+ years	



Catego	ry : Site		В	uilding	: Site		
Group	Hom Tune	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	Item - Type	Location	Quantity		Ralik	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	7	10+ years	
Fencina							
0	Fencing - Iron and Concrete Post	Entire Site	21	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,210	LF	6	6-10 years	
Landsca	pe						
	Benches	Entire Site	7	EA	7	10+ years	
	Irrigation	Entire Site	2,800	SF	7	10+ years	
	Landscape - Grass	Entire Site	5,500	SF	6	10+ years	Not previously assessed
	Landscape - Hardscape- Concrete	Entire Site	5,396	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1	SF	4	0-1 year	Hole in the pavement near door three
	Landscape - Hardscape- Pavers	Entire Site	3,085	SF	7	10+ years	
	Landscape - Mulch	Entire Site	2,500	SF	6	6-10 years	Not previously assessed
	Parkway trees	Entire Site	2,000	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,500	SF	7	10+ years	Corrected quantity
	Trash Receptacles	Entire Site	2	EA	7	10+ years	Corrected quantity
			_	_/ .	-	let yeare	
Parking							
	Concrete Curbs	Parking Lot- North	250	LF	7	10+ years	
	Surface - Asphalt	Parking Lot- North	690	SF	7	10+ years	
	Surface - Asphalt	Parking Lot- North	3,967	SF	4	1-2 years	Large cracks in the asphalt, crushed surface, alligatoring, potholes
	Trash Enclosure - Chain Links	Parking Lot- North	536	SF	5	6-10 years	Corroding, missing slats
	Concrete Curbs	Parking Lot- West	250	LF	7	10+ years	<b>3</b> / <b>3</b>
	Interior Plantings	Parking Lot- West	20	LF	7	10+ years	
	Surface - Asphalt	Parking Lot- West	3,333	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- West	100	SF	5	1-2 years	Large cracks in the asphalt
	Surface - Concrete	Parking Lot- West	1,200	SF	6	10+ years	
	Trash Compactor	Parking Lot- West	1,200	EA	7	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- West	778	SF	7	10+ years	
	Vehicular Screening	Parking Lot- West	20	LF	5	1-2 years	Missing plantings
	Concrete Curbs	SW Site	20 70	LF	7	10+ years	Missing plantings
	Surface - Asphalt	SW Site	3,302	SF	5	•	Some alligatoring and areaks
		SW Site	3,302	SF	5 4	6-10 years	Some alligatoring and cracks
	Surface - Asphalt	Svv Sile	4,000	Эг	4	1-2 years	Disintegrated surface, alligatoredthroughout
	Vehicular Screening	SW Site	39	LF	7	10+ years	
Playgrou							
	Equipment - Pre K 3-5	SE site	1	EA	6	6-10 years	



)	561666					Ζ.	200 N Hamin AVENUE, Chicago, iL 60647		
Catego	ry : Site		Building : Site						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Equipment - School Age 5-12 Surface - Poured Surface	SE site SE site	1 3,302	EA SF	6 6	6-10 years 2-5 years			
Sidewall	KS								
	Sidewalks - Internal Walks	Entire Site	200	LF	7	10+ years			
	Sidewalks - Internal Walks	Entire Site	35	LF	5	1-2 years	Broken, cracked		
	Sidewalks - Perimeter Sidewalks	Entire Site	5,815	SF	7	10+ years	900 linear feet times 6 feet wide sidewalk quantity in square feet		
	Sidewalks - Perimeter Sidewalks	Entire Site	125	SF	5	1-2 years	Broken, cracked		
Signage									
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years			
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	7	10+ years			
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	7	10+ years			

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated

• Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



### Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Intended Usage	Koom Location	Number	Number		Alea	Alea	3.00	Duaru
Art Room	Regular Classroom	1st Floor	106	106	912	156	78	N	Y
Dance Room	Regular Classroom	1st Floor	105	105	844	120	60	N	N
Music Room	Regular Classroom	1st Floor	103	103	812	120	60	N	Y
Office	Regular Classroom	2nd Floor	200	NA	355	84	42	N	N
Office	Regular Classroom	2nd Floor	200	204	812	120	60	N	Y
Office	Regular Classroom	2nd Floor	211	NA	327	84	42	N	N
Office	Regular Classroom	3rd Floor	300	NA	371	84	42	N	N
Regular Classroom	Art Room	3rd Floor	305	305	812	120	60	N	Y
Regular Classroom	Laboratory/Shop	3rd Floor	308	307	814	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	882	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	201	882	120	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	810	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	205	810	98	49	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	800	120	49 60	N	Y
		2nd Floor	206	208	812	120	60	N	Y
Regular Classroom	Regular Classroom Regular Classroom	2nd Floor	207	208	796	120	60	N	Y Y
Regular Classroom		2nd Floor	208	207	804	120	60	N	Y Y
Regular Classroom	Regular Classroom								Y Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	810	120	60	N	Y Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	817	120	60	N	
Regular Classroom	Regular Classroom	3rd Floor	302	302	808	120	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	304	813	120	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	303	812	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	806	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	305	821	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	811	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	806	120	60	N	Y
Special Program	Regular Classroom	3rd Floor	311	311	371	84	42	Ν	Ν
Building : Linked Addition									
Kindergarten	Kindergarten	1st Floor	402	134	1,130	180	42	N	Y
Kindergarten	Kindergarten	1st Floor	403	135	1,130	180	42	N	Ν
Kindergarten	Kindergarten	2nd Floor	401	136	1,130	360	84	N	Y
Music Room	Computer Lab	2nd Floor	508	209	1,120	240	56	N	Ν
Other Instructional Use	Other Instructional Use	2nd Floor	501	218	336	80	18	Y	Y
Pre School	Pre School	1st Floor	404	124	845	120	28	N	Y
Pre School	Pre School	1st Floor	405	123	890	300	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	500	202	890	180	42	N	Y
Regular Classroom	Regular Classroom	2nd Floor	502	217	880	180	42	N	Ý



### **Classroom Summary**

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	503	216	880	180	42	N	Y
Regular Classroom	Regular Classroom	2nd Floor	504	215	1,180	240	84	N	Y
Regular Classroom	Regular Classroom	2nd Floor	505	214	1,180	240	84	N	Y
Regular Classroom	Regular Classroom	2nd Floor	506	211	890	180	42	N	N
Special Education	Special Education	2nd Floor	510	204	490	120	128	N	Y
Special Program	Special Education	2nd Floor	511	203	490	120	28	N	N