



### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1999	4	92,500
Linked Addition-Athletic	1999	2	63,900
Campus Total			156,400

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Entrance Control - Audio and Video #1 Main Entrance 1 EΑ 6 10+ years Exterior Doors - Side lite #1 Main Entrance 8 EΑ 6 10+ years Exterior Doors - Store Front #1 Main Entrance 4 EΑ 6 10+ years 6 Exterior Doors - Transom Lite #1 Main Entrance EΑ 6 10+ years Exterior Doors - Exterior Steel Door #2 EΑ 7 6-10 years Exterior Doors - Exterior Steel Door #3 EΑ 7 6-10 years Exterior Doors - Exterior Steel Door #4 2 FΑ 6 10+ vears Entrance Control - Audio #5 FΑ 6 10+ years 1 2 Exterior Doors - Store Front #5 FΑ 10+ years Exterior Doors - Transom Lite #5 1 FΑ 6 10+ years Exterior Doors - Side lite #6 4 EΑ 6 10+ years 2 Exterior Doors - Store Front #6 EΑ 5 2-5 years Exterior Doors - Transom Lite 3 #6 EΑ 6 10+ years 2 Exterior Doors - Store Front #7 EΑ 6 10+ years Exterior Doors - Transom Lite #7 1 EΑ 6 10+ years Exterior Doors - Side lite #8 8 FΑ 6 10+ years Exterior Doors - Store Front 2 EΑ #8 6 10+ years 2 Exterior Doors - Transom Lite #8 FΑ 6 10+ years Exterior Doors - Exterior Steel Door Roof Access 2 EΑ 7 10+ years Exterior Stairs - Steel or Aluminum 1 F 7 Roof Access 12 10+ years Foundation Foundation - Concrete **Entire Building** 992 LF 7 10+ years



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Superstructure - Steel	Entire Building	92,500	SF	7	10+ years	
Lighting							
Lighting	Exterior Lighting - Wall Mounted	Entire Building	36	EA	6	10+ years	
Roof Sy	stem						
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	12	LF	6	10+ years	Corrected quantity
	Coping - Metal	Main Roof	25	LF	6	2-5 years	,
	Coping - Stone	Main Roof	1,189	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	1,360	LF	6	10+ years	Recalculated quantity
	Parapet - Parapet < 16" Height	Main Roof	861	LF	6	10+ years	, , , , , , , , , , , , , , , , , , , ,
	Parapet - Parapet > 30"	Main Roof	353	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	31,742	SF	5	1-2 years	Bubbling, worn, frequent patching, evidence of active roof leaks
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	31,742	SF	7	10+ years	
	Concrete Topping	Maii 1 too.	0.,	٥.	•	io. youro	
	Coping - Metal	Main Roof - North	294	LF	7	6-10 years	
	Downspouts - Interior Downspouts	Main Roof - North	168	LF	7	6-10 years	
	Roof - Modified Bitumen	Main Roof - North	4,887	SF	4	1-2 years	No access ladder
	Roof Structure - Steel / Metal Deck/	Main Roof - North	4,887	SF	7	6-10 years	140 400000 144401
	Concrete Topping	Wall Roof Roll	4,007	Oi.	•	o to years	
_Walls							
	Canopy - Metal	Entire Building	324	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	992	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,020	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,016	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	3,550	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	3,307	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	6,613	SF	6	10+ years	
_Window:	s						
	Curtain wall - Glazed Double Pane	Entire Building	4,428	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	1,472	SF	6	10+ years	Repaired
	Curtain wall - Louver	Entire Building	1,656	SF	6	10+ years	I 2
	Guard - Guards perforated	Entire Building	2,940	SF	6	10+ years	
	Lintels - Steel	Entire Building	920	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,160	SF	6	10+ years	
	2 3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	<b>y</b>	2,.00	٥.	•	121 300.0	



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Security System - CCTV	Entire Building	92,500	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	92,500	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	32	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	20	EΑ	6	6-10 years	
	Stairs						
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose	Entire Building	5	EA	6	6-10 years	No battery back up
	Room						
	Emergency A/C Power - Corridors and	Entire Building	22,900	SF	6	6-10 years	
	Stairs	· ·				•	
	Emergency A/C Power - Lunchrooms	Entire Building	586	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose	Entire Building	3,796	SF	6	6-10 years	
	Room	3	,			,	
	Emergency A/C Power - Students Toilets	Entire Building	2,504	SF	6	6-10 years	
	3,	3	,			, , , , , , , , , , , , , , , , , , ,	
Main Se	rvice						
	Main Electrical Service - 1600 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH	Elocalical Room	·	_, 、	Ŭ	io. youro	
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	6	10+ years	
	277/480/3PH	Licothical Room	•	L/\	O	101 yours	
	PA System	Entire Building	92,500	SF	6	6-10 years	
	17. Gyolom	Entire Banding	02,000	O.	J	o ro youro	
Power D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	12	ΕA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp  Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	•	
		Entire building	1	EA	1	10+ years	
	amp Main Distribution Banala Creater than 600	Entire Building	4	⊏^	7	101 2000	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	
	amp	Entiro Duildica	4	Г^	^	10	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Fire Alar	· •	2004.1011	quantity		rtaint	- Ropidoomont	
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	Annunciator Panel
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	92,500	SF	6	6-10 years	
	Fire Alarm_System	Electrical Room	92,500	SF	6	6-10 years	
Pumn R	oom Assembly						
	Fire Pump - 51-75hp	Mechanical Building/Central Plant	1	EA	6	6-10 years	
	Jockey Pump	Mechanical Building/Central Plant	1	EA	6	6-10 years	
	ookey i ump	Weenamear Building/Central Flam	'	LA	O	0-10 years	
Sprinkle							
	Sprinkler Heads	Entire Building	92,500	SF	7	10+ years	
	Sprinkler Piping	Entire Building	92,500	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	92,500	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	litioning						
	Chemical Pot Feeder	Roof	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	6	2-5 years	Compressor recently replaced for
	Mounted - 201 - 300 tons						chiller #2. Chiller #2 is running and
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	5	6-10 years	second chiller is in working progress
	Mounted - 201 - 300 tons	Kooi	ı	LA	3	0-10 years	
	Glycol Feed	Roof	1	EA	5	6.10 years	
	Pipes - Chilled Water Pipe- Steel	Roof	600	LF	5 6	6-10 years 10+ years	
	Pressure Fill System	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA EA	5	2-5 years	Served MDF
	than 5 tons	Rooi	'	EA	5	2-5 years	Served MDF
Air Hand	lling Systems						
- MI HAIIC	Indoor Return Fans- Centrifugal Inline -	Entire Building	1	EA	6	6-10 years	RF - 1
	Greater than 20000 CFM	Entire Building	'	LA	U	o To years	131 1
	Croator than 20000 Of W						



Category : Mechanical			В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Entire Building	2	EA	5	6-10 years	RF - 2
	Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM	Entire Building	1	EA	5	6-10 years	RF - 3
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	38	EA	6	6-10 years	Served by AHU 2
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	30	EA	6	6-10 years	Served by AHU1
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	4	EA	6	6-10 years	Served by AHU 3
	Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water	Entire Building	1	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Fan Room 1 - AHU 3	1	EA	6	6-10 years	AHU 3, serves kitchen and lunchroom
	Air Intake	Fan Room 1 - AHU 3	1	EA	6	6-10 years	
	VAV Box	Fan Room 1 - AHU 3	5	EΑ	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Penthouse - AHU 1	1	EA	6	6-10 years	
	Air Intake	Penthouse - AHU 1	1	EΑ	5	6-10 years	
	Energy Recovery Unit	Penthouse - AHU 1	1	EΑ	5	6-10 years	
	Energy Recovery Unit	Penthouse - AHU 1	1	EΑ	5	6-10 years	
	VAV Box	Penthouse - AHU 1	8	EΑ	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Penthouse - AHU 2	1	EA	6	6-10 years	
	Air Intake	Penthouse - AHU 2	1	EΑ	6	6-10 years	
	Energy Recovery Unit	Penthouse - AHU 2	1	EA	5	2-5 years	
	Energy Recovery Unit	Penthouse - AHU 2	1	EA	5	2-5 years	
	VAV Box	Penthouse - AHU 2	5	EA	5	6-10 years	Served by AHU 2
Boiler Sy	stems						
	Boiler Auxiliary- Non Condensing Hot Water - Greater than 4000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EΑ	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EΑ	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	5	6-10 years	Not used to
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH	Boiler Room	1	EA	6	6-10 years	Boiler 2
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH	Boiler Room	1	EA	6	6-10 years	Boiler 1



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
Heating I	Dovingo						
reaung i		Entire Duilding	250	LF		0.40	
	Fin Tube - Hot Water	Entire Building	250		5	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	8	EΑ	6	6-10 years	December of all
	Unit Heater - Electric	Entire Building	1	EΑ	2	0-1 year	Doesn't work at all
	Unit Heater - Hot Water	Entire Building	1	EA	5	6-10 years	
	Radiator Panels - Hot Water	Entire Building	10	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	Pump has been disconnected
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	,
	Hot Water Pump - Less than 10	Boiler Room	1	ΕA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	1,500	LF	6	10+ years	
	Chilled Water Pump - 10 - 20 HP	Penthouse	1	EA	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Penthouse	i	EΑ	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Penthouse	1	EA	6	6-10 years	
Tomporo	ture Control						
rempera	DDC System	Entire Building	92,500	SF	4	2-5 years	Software is outdated and doesn't
	•	· ·				•	function properly
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	90	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	5	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	5	6-10 years	
		> = ananig		-/ \	-	o io youro	



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	3	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	3	EA	6	6-10 years	
Piping							
- 1 0	Domestic Piping-Hot Water Return Lines	Entire Building	92,500	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	92,500	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	92,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	92,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	92,500	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	92,500	SF	6	10+ years	
	Sanitary Piping	Entire Building	92,500	SF	6	10+ years	
	Storm Piping	Entire Building	92,500	SF	6	10+ years	
	Vent Piping	Entire Building	92,500	SF	6	10+ years	
_Pumps_							
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	

Category : Room **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices		Quantity			риссински	
	Ceiling - Lay-in	105 UIC Health clinic open office and waiting	350	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105 UIC Health clinic open office and waiting	1	EA	7	10+ years	
	Floor - Tile	105 UIC Health clinic open office and waiting	350	SF	7	10+ years	
	Lighting - Lay-in	105 UIC Health clinic open office and waiting	6	EA	7	10+ years	
	Storage/ Closet	105 UIC Health clinic open office and waiting	43	SF	7	10+ years	
	Walls - Concrete Block	105 UIC Health clinic open office and waiting	336	SF	7	10+ years	
	Walls - Plaster/Drywall	105 UIC Health clinic open office and waiting	1,068	SF	7	10+ years	
	Ceiling - Lay-in	1st- Asst Principal	216	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Asst Principal	1	EA	7	10+ years	



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	1st- Asst Principal	216	SF	7	6-10 years	
	Lighting - Lay-in	1st- Asst Principal	4	EA	7	6-10 years	
	Power Distribution	1st- Asst Principal	10	EA	7	10+ years	
	Walls - Concrete Block	1st- Asst Principal	177	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Asst Principal	531	SF	7	10+ years	
	Ceiling - Lay-in	1st- Conference Rm in Main Office Suite	205	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Conference Rm in Main Office Suite	1	EA	7	10+ years	
	Floor - Carpet	1st- Conference Rm in Main Office Suite	205	SF	7	6-10 years	
	Lighting - Lay-in	1st- Conference Rm in Main Office Suite	4	EA	7	6-10 years	
	Power Distribution	1st- Conference Rm in Main Office Suite	12	EA	7	10+ years	
	Walls - Concrete Block	1st- Conference Rm in Main Office Suite	345	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Conference Rm in Main Office Suite	345	SF	7	10+ years	
	Ceiling - Lay-in	1st- Faculty Lounge	586	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Faculty Lounge	1	EΑ	7	10+ years	
	Floor - Tile	1st- Faculty Lounge	586	SF	7	10+ years	
	Lighting - Lay-in	1st- Faculty Lounge	8	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st- Faculty Lounge	597	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Faculty Lounge	597	SF	7	10+ years	
	Work Sink	1st- Faculty Lounge	1	ĒΑ	7	10+ years	Not previously assessed
	Ceiling - Lay-in	1st- Inside Rm 109	169	SF	7	10+ years	The provided of the provided o
	Doors - Wood Doors inclu hw	1st- Inside Rm 109	1	ĒΑ	7	10+ years	
	Floor - Tile	1st- Inside Rm 109	169	SF	7	6-10 years	
	Lighting - Lay-in	1st- Inside Rm 109	2	ĒΑ	7	6-10 years	
	Power Distribution	1st- Inside Rm 109	6	EA	7	10+ years	
	Walls - Concrete Block	1st- Inside Rm 109	156	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Inside Rm 109	468	SF	7	10+ years	
	Ceiling - Lay-in	1st- Kitchen Manager	107	SF	7	10+ years	
	Doors - Side-lite	1st- Kitchen Manager	11	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st- Kitchen Manager	1	EA	6	6-10 years	Broken hardware causing door to not to close properly
	Floor - Concrete Epoxy/ Painted	1st- Kitchen Manager	107	SF	7	10+ years	p p,
	Lighting - Lay-in	1st- Kitchen Manager	2	ĒΑ	6	10+ years	
	Power Distribution	1st- Kitchen Manager	6	EA	7	10+ years	
	Walls - Concrete Block	1st- Kitchen Manager	200	SF	7	10+ years	
	Ceiling - Lay-in	1st- Main Office	584	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st- Main Office	171	SF	7	10+ years	
	Doors - Side-lite	1st- Main Office	82	SF	7	10+ years	
				٠.	•	, , , , , , , , , , , , , , , , , , , ,	



Category : Room			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st- Main Office	2	EA	7	10+ years	
	Floor - Carpet	1st- Main Office	564	SF	7	6-10 years	
	Floor - Carpet	1st- Main Office	20	SF	5	0-1 year	Worn and buckling creating a tripping hazard
	Floor - Terrazzo	1st- Main Office	171	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st- Main Office	8	ĒA	7	6-10 years	
	Lighting - Lay-in	1st- Main Office	12	EA	7	6-10 years	
	Power Distribution	1st- Main Office	18	EA	7	10+ vears	
	Storage/ Closet	1st- Main Office	26	SF	7	10+ years	
	Walls - Concrete Block	1st- Main Office	829	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Main Office	828	SF	7	10+ years	
	Ceiling - Lay-in	1st- Observation/Parent Room	423	SF	7	10+ years	
	Ceiling - Lay-in	1st- Observation/Parent Room	16	SF	5	1-2 years	Water stained ceiling tiles
	Doors - Wood Doors inclu hw	1st- Observation/Parent Room	1	ĒΑ	7	10+ years	3
	Floor - Tile	1st- Observation/Parent Room	439	SF	7	10+ years	
	Lighting - Lay-in	1st- Observation/Parent Room	6	ĒΑ	7	10+ years	
	Power Distribution	1st- Observation/Parent Room	26	EA	7	10+ years	
	Walls - Concrete Block	1st- Observation/Parent Room	524	SF	7	10+ years	
	Walls - Concrete Block	1st- Observation/Parent Room	10	SF	7	10+ years	Rank changed to update/correct to match current observation
	Walls - Plaster/Drywall	1st- Observation/Parent Room	540	SF	7	10+ years	materi carrent escertation
	Ceiling - Lay-in	1st- Principal	247	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Principal	1	ĒΑ	7	10+ years	
	Floor - Carpet	1st- Principal	247	SF	7	6-10 years	
	Lighting - Lay-in	1st- Principal	4	ĒΑ	7	6-10 years	
	Power Distribution	1st- Principal	12	EA	7	10+ years	
	Walls - Concrete Block	1st- Principal	189	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Principal	567	SF	7	10+ years	
	Ceiling - Lay-in	1st- Rm 107 Office used by Health & Wellness Center	280	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Rm 107 Office used by Health & Wellness Center	1	EA	7	10+ years	
	Floor - Tile	1st- Rm 107 Office used by Health & Wellness Center	280	SF	7	6-10 years	
	Lighting - Lay-in	1st- Rm 107 Office used by Health & Wellness Center	4	EA	7	6-10 years	
	Power Distribution	1st- Rm 107 Office used by Health & Wellness Center	6	EA	7	10+ years	
	Walls - Concrete Block	1st- Rm 107 Office used by Health & Wellness Center	405	SF	7	10+ years	
	Walls - Plaster/Drywall	1st- Rm 107 Office used by Health & Wellness Center	405	SF	7	10+ years	
	Ceiling - Lay-in	1st- Work Rm in Main Office Suite	169	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st- Work Rm in Main Office Suite	1	EA	7	10+ years	



 				uilding			
 	14 · · · · · · · · · · · · · · · · · · ·					Recommend	
-    -   	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
) )	Floor - Tile	1st- Work Rm in Main Office Suite	169	SF	7	10+ years	
) )	Lighting - Lay-in	1st- Work Rm in Main Office Suite	2	EA	7	6-10 years	
(	Power Distribution	1st- Work Rm in Main Office Suite	10	EA	7	10+ years	
(	Walls - Concrete Block	1st- Work Rm in Main Office Suite	642	SF	7	10+ years	
(	Work SInk	1st- Work Rm in Main Office Suite	1	EA	7	6-10 years	Rank changed to update/correct to match current observation
	Ceiling - Lay-in	2nd Floor Observation	435	SF	7	10+ years	
ŀ	Ceiling - Lay-in	2nd Floor Observation	4	SF	4	0-1 year	Damaged
	Doors - Wood Doors inclu hw	2nd Floor Observation	1	EA	7	10+ years	
ŀ	Floor - Tile	2nd Floor Observation	439	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor Observation	6	EA	7	10+ years	
ľ	Power Distribution	2nd Floor Observation	26	EA	7	10+ years	
,	Walls - Concrete Block	2nd Floor Observation	540	SF	7	10+ years	
,	Walls - Plaster/Drywall	2nd Floor Observation	540	SF	7	10+ years	
(	Ceiling - Lay-in	2nd- Inside Rm 207	170	SF	7	10+ years	
(	Ceiling - Lay-in	2nd- Inside Rm 207	12	SF	4	0-1 year	Water damaged tile
!	Doors - Wood Doors inclu hw	2nd- Inside Rm 207	1	EΑ	7	10+ years	
,	Floor - Tile	2nd- Inside Rm 207	182	SF	7	10+ years	
	Lighting - Lay-in	2nd- Inside Rm 207	2	EΑ	7	10+ years	
	Power Distribution	2nd- Inside Rm 207	4	EA	7	10+ years	
,	Walls - Concrete Block	2nd- Inside Rm 207	270	SF	7	10+ years	
1	Walls - Plaster/Drywall	2nd- Inside Rm 207	270	SF	7	10+ years	
	Ceiling - Lay-in	2nd- Rm 205 Office	282	SF	7	10+ years	
	Ceiling - Lay-in	2nd- Rm 205 Office	8	SF	4	0-1 year	Water damaged tile
	Doors - Wood Doors inclu hw	2nd- Rm 205 Office	1	EΑ	7	10+ years	•
ļ	Floor - Tile	2nd- Rm 205 Office	290	SF	7	10+ years	
	Lighting - Lay-in	2nd- Rm 205 Office	4	EΑ	7	10+ years	
	Power Distribution	2nd- Rm 205 Office	12	EA	7	10+ years	
1	Walls - Concrete Block	2nd- Rm 205 Office	276	SF	7	10+ years	
1	Walls - Plaster/Drywall	2nd- Rm 205 Office	331	SF	7	10+ years	
	Casework	2nd- Work Room	10	LF	7	10+ years	
(	Ceiling - Lay-in	2nd- Work Room	216	SF	7	10+ years	
	Ceiling - Lay-in	2nd- Work Room	4	SF	4	0-1 year	Water damaged tile
	Doors - Side-lite	2nd- Work Room	32	SF	7	10+ years	ŭ
	Doors - Wood Doors inclu hw	2nd- Work Room	2	ĒΑ	7	10+ years	
ŗ	Floor - Tile	2nd- Work Room	220	SF	7	10+ years	
	Lighting - Lay-in	2nd- Work Room	4	ĒΑ	7	10+ years	
	Storage/ Closet	2nd- Work Room	109	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd- Work Room	610	SF	7	10+ years	
	Ceiling - Lay-in	307	292	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307	1	EA	7	10+ years	
	Floor - Tile	307	292	SF	7	10+ years	
	Lighting - Lay-in	307	4	EA	7	10+ years	
	Power Distribution	307	4	EA	7	10+ years	



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	307	259	SF	7	10+ years				
	Walls - Plaster/Drywall	307	423	SF	7	10+ years				
	Ceiling - Lay-in	309	170	SF	7	10+ years	Quantity changed to update/correct to match current observation			
	Ceiling - Lay-in	309	10	SF	4	1-2 years	Water damaged ceiling tiles			
	Doors - Wood Doors inclu hw	309	1	EA	7	10+ years				
	Floor - Tile	309	180	SF	7	10+ years				
	Lighting - Lay-in	309	2	EA	7	10+ years				
	Power Distribution	309	4	EA	7	10+ years				
	Walls - Concrete Block	309	108	SF	7	10+ years				
	Walls - Plaster/Drywall	309	352	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor Observation Room 3	455	SF	7	10+ years				
	Doors - Transom Window	3rd Floor Observation Room 3	88	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Observation Room 3	1	EA	7	10+ years				
	Floor - Tile	3rd Floor Observation Room 3	455	SF	7	10+ years				
	Lighting - Lay-in	3rd Floor Observation Room 3	6	EA	6	10+ years				
	Power Distribution	3rd Floor Observation Room 3	4	EA	7	10+ years				
	Walls - Concrete Block	3rd Floor Observation Room 3	318	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor Observation Room 3	560	SF	7	10+ years				
	Ceiling - Lay-in	403	292	SF	7	10+ years				
	Doors - Wood Doors inclu hw	403	1	EA	7	10+ years				
	Floor - Tile	403	292	SF	7	10+ years				
	Lighting - Lay-in	403	4	ĒΑ	7	10+ years				
	Power Distribution	403	4	EA	7	10+ years				
	Walls - Concrete Block	403	259	SF	7	10+ years				
	Walls - Plaster/Drywall	403	423	SF	7	10+ years				
	Ceiling - Lay-in	4th Floor Observation Room 4	455	SF	7	10+ years				
	Doors - Transom Window	4th Floor Observation Room 4	88	SF	7	10+ years				
	Doors - Wood Doors inclu hw	4th Floor Observation Room 4	1	ĒΑ	7	10+ years				
	Floor - Tile	4th Floor Observation Room 4	455	SF	7	10+ years				
	Lighting - Lay-in	4th Floor Observation Room 4	6	ĒA	7	10+ years				
	Power Distribution	4th Floor Observation Room 4	2	EΑ	7	10+ years				
	Walls - Concrete Block	4th Floor Observation Room 4	318	SF	7	10+ years				
	Walls - Plaster/Drywall	4th Floor Observation Room 4	560	SF	7	10+ years				
	Ceiling - Lay-in	Exam room 2 First floor UIC Health clinic	92	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Exam room 2 First floor UIC Health clinic	1	EA	7	10+ years				
	Floor - Tile	Exam room 2 First floor UIC Health clinic	92	SF	7	10+ years				
	Lighting - Lay-in	Exam room 2 First floor UIC Health clinic	2	EA	7	10+ years				
	Walls - Concrete Block	Exam room 2 First floor UIC Health clinic	192	SF	7	10+ years				



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	Exam room 2 First floor UIC Health clinic	350	SF	7	10+ years				
	Work Slnk	Exam room 2 First floor UIC Health clinic	1	EA	7	10+ years				
	Ceiling - Lay-in	Exam room 3 First floor UIC Health clinic	91	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Exam room 3 First floor UIC Health clinic	1	EA	7	10+ years				
	Floor - Tile	Exam room 3 First floor UIC Health clinic	91	SF	7	10+ years				
	Lighting - Lay-in	Exam room 3 First floor UIC Health clinic	2	EA	7	10+ years				
	Walls - Concrete Block	Exam room 3 First floor UIC Health clinic	240	SF	7	10+ years				
	Walls - Plaster/Drywall	Exam room 3 First floor UIC Health clinic	240	SF	7	10+ years				
	Work SInk	Exam room 3 First floor UIC Health clinic	1	EA	7	10+ years				
	Ceiling - Lay-in	Exam room room 1 First floor UIC Health clinic	92	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Exam room room 1 First floor UIC Health clinic	1	EA	7	10+ years				
	Floor - Tile	Exam room room 1 First floor UIC Health clinic	92	SF	7	10+ years				
	Lighting - Lay-in	Exam room room 1 First floor UIC Health clinic	2	EA	7	10+ years				
	Walls - Plaster/Drywall	Exam room room 1 First floor UIC Health clinic	350	SF	7	10+ years				
	Work SInk	Exam room room 1 First floor UIC Health clinic	1	EA	7	10+ years				
	Ceiling - Plaster/Drywall	Lab First floor UIC Health clinic	86	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Lab First floor UIC Health clinic	1	ĒA	7	10+ years				
	Floor - Tile	Lab First floor UIC Health clinic	86	SF	7	10+ years				
	Lighting - Pendent/Surface	Lab First floor UIC Health clinic	2	EΑ	7	10+ years				
	Walls - Concrete Block	Lab First floor UIC Health clinic	132	SF	7	10+ years				
	Walls - Plaster/Drywall	Lab First floor UIC Health clinic	316	SF	7	10+ years				
	Work Sink	Lab First floor UIC Health clinic	1	EA	7	10+ years				
	Ceiling - Lay-in	Next to Door #8	140	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Next to Door #8	140	Sr EA	7	10+ years 10+ years				
			-	SF		-				
	Floor - Tile	Next to Door #8	140		7	10+ years				
	Lighting - Lay-in	Next to Door #8	2	EA	7	10+ years	De alian a sint			
	Walls - Concrete Block	Next to Door #8	576	SF	6	10+ years	Peeling paint			
	Work SInk	Next to Door #8	1	EA	5	0-1 year	Missing sink faucets			
	Ceiling - Lay-in	Office in 405	334	SF	7	10+ years				



Category : Room			В	uilding	: Main		33 W German NGAB, Griedge, in 600 To
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Office in 405	1	EA	7	10+ years	
	Floor - Tile	Office in 405	334	SF	7	10+ years	
	Lighting - Lay-in	Office in 405	2	ĒA	7	10+ years	
	Power Distribution	Office in 405	6	EΑ	7	10+ years	
	Walls - Concrete Block	Office in 405	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Office in 405	376	SF	7	10+ years	
Kitchen							
AICHCH	Ceiling - Lay-in	1st Floor	1,604	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	ĒΑ	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	1,604	SF	7	10+ years	Quantity changed as total has been aggregated/divided.
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	aggrogatoa/arviaca.
	Storage/ Closet	1st Floor	144	SF	7		
				SF SF		10+ years	
	Walls - Concrete Block	1st Floor	2,328		7	10+ years	
	Ceiling - Lay-in	1st Floor - Dishwashing Rm	174	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Dishwashing Rm	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor - Dishwashing Rm	174	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - Dishwashing Rm	2	EA	7	6-10 years	
	Serving Line	1st Floor - Dishwashing Rm	5	LF	7	10+ years	
	Walls - Concrete Block	1st Floor - Dishwashing Rm	550	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Servery	641	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Servery	2	EA	7	10+ years	
		•		SF		•	
	Floor - Tile	1st Floor - Servery	641		7	10+ years	
	Lighting - Lay-in	1st Floor - Servery	6	EA	7	6-10 years	
	Serving Line	1st Floor - Servery	30	LF	7	10+ years	
	Storage/ Closet	1st Floor - Servery	137	SF	7	10+ years	
	Walls - Concrete Block	1st Floor - Servery	1,020	SF	7	10+ years	
ibrary							
	Casework	2nd Floor	147	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,559	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Carpet	2nd Floor	2,549	SF	6	6-10 years	
	Floor - Carpet	2nd Floor	10	SF	5	1-2 years	Damaged
	Lighting - Lay-in	2nd Floor	30	EA	7	-	Damaged
						10+ years	
	Walls - Concrete Block	2nd Floor	2,190	SF	7	10+ years	
	Casework	2nd- Young Readers Rm	6	LF	7	10+ years	
	Ceiling - Lay-in	2nd- Young Readers Rm	1,081	SF	7	10+ years	
	Doors - Side-lite	2nd- Young Readers Rm	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd- Young Readers Rm	1	EA	7	10+ years	
	Floor - Carpet	2nd- Young Readers Rm	1,081	SF	7	6-10 years	
	Lighting - Lay-in	2nd- Young Readers Rm	•		7	•	

Page : 13 of 56



Category : Room			Building : Main				<u> </u>	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	2nd- Young Readers Rm	1,029	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd- Young Readers Rm	293	SF	7	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Lay-in	1st Floor	3,046	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EΑ	7	10+ years		
	Drinking Fountains - Single Water Cooler	1st Floor	1	EΑ	7	6-10 years		
	Floor - Tile/Sheet	1st Floor	3,794	SF	7	10+ years		
	Floor - Tile/Sheet	1st Floor	2	SF	4	1-2 years	Broken and cracked floor tiles	
	Lighting - Lay-in	1st Floor	16	EA	7	10+ years	2. Onto 1. dana oragina a masi masi	
	Lighting - Pendent/Surface	1st Floor	44	EA	7	10+ years		
	Stage	1st Floor	667	SF	7	10+ years		
	Storage/ Closet	1st Floor	230	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	6,691	SF	7	10+ years		
	Walls - Concrete Block	13(1100)	0,031	Oi	,	10+ years		
MDF_ID	F Doors - Steel Doors incl hw							
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Not previously assessed	
		- ·						
	Finishes	2nd Floor	375	SF	7	10+ years		
		2nd Floor 2nd Floor	375 1	SF EA	7	6-10 years	Dedicated computer room cooling unite	
Mechani	Finishes Other Cooling Unit cal/ Service Rooms	2nd Floor	1	EA	7	6-10 years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet	2nd Floor  1st Floor	30	EA SF	7	6-10 years 10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet	2nd Floor  1st Floor 1st Floor	30 30	SF SF	7 7 7	6-10 years 10+ years 10+ years	•	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor	30 30 175	SF SF SF	7 7 7 7	6-10 years 10+ years 10+ years 10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	30 30 175 70	SF SF SF SF SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	30 30 175 70 20	SF SF SF SF SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	30 30 175 70 20 110	SF SF SF SF SF SF	7 7 7 7 7 7	10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	30 30 175 70 20 110 30	SF SF SF SF SF SF SF	7 7 7 7 7 7	10+ years	·	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor	30 30 175 70 20 110 30 2,888	SF SF SF SF SF SF SF	7 7 7 7 7 7 7	10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	30 30 175 70 20 110 30 2,888 110	SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7	10+ years	·	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	30 30 175 70 20 110 30 2,888 110 97	SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7	10+ years	·	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	30 30 175 70 20 110 30 2,888 110 97	SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7	10+ years	·	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor	30 30 175 70 20 110 30 2,888 110 97 12 30	SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years	•	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110	SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years	•	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Janitor's Closet	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 4th Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110 30	SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years	·	
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110 30	SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years	•	
∕lechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Janitor's Closet	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 4th Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110 30	SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years		
	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 4th Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110 30	SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years		
Mechani	Finishes Other Cooling Unit  cal/ Service Rooms Janitor's Closet Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Storage Room Storage Room Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Janitor's Closet Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms Mechanical/ Service Rooms	2nd Floor  1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 4th Floor	30 30 175 70 20 110 30 2,888 110 97 12 30 110 30	SF SF SF SF SF SF SF SF SF SF SF SF SF	7 7 7 7 7 7 7 7 7 7 7	10+ years	Dedicated computer room cooling unite	



Group         Item - Type         Location         Quarticle           Doors - Wood Doors inclu hw         301-303         301-303         150-		UOM EA SF EA SF EA SF EA	Rank 7 7 7 7 7 7 7 7 7	Recommend Replacement  10+ years	Comments
Doors - Wood Doors inclu hw Floor - Tile Superior - Terrazzo Floor - Terrazzo Floor Drain Hand Dryer Superior - Tile Superior	1 455 3 150 687 1 313 313 313 2 2	EA SF EA SF EA SF SF EA	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments
Doors - Wood Doors inclu hw Floor - Tile 301-303 Lighting - Lay-in Walls - Concrete Block Walls - Plaster/Drywall Work Sink  Restroom  Accessories Ceiling - Plaster/Drywall Floor - Terrazzo Floor Drain Hand Dryer  301-303 Sold-303 Sold-3	455 3 150 687 1 313 313 313 2 2	SF EA SF EA SF SF SF EA	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
Lighting - Lay-in       301-303         Walls - Concrete Block       301-303         Walls - Plaster/Drywall       301-303         Work Sink       301-303         Restroom         Accessories       1st Floor         Ceiling - Plaster/Drywall       1st Floor         Floor - Terrazzo       1st Floor         Floor Drain       1st Floor         Hand Dryer       1st Floor	3 150 687 1 313 313 313 2 2	EA SF SF EA SF SF SF EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
Lighting - Lay-in 301-303 Walls - Concrete Block 301-303 Walls - Plaster/Drywall 301-303 Work Sink 301-303  Restroom  Accessories 1st Floor Ceiling - Plaster/Drywall 1st Floor Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	3 150 687 1 313 313 313 2 2	EA SF SF EA SF SF SF EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years	
Walls - Concrete Block       301-303         Walls - Plaster/Drywall       301-303         Work Sink       301-303         Restroom         Accessories       1st Floor         Ceiling - Plaster/Drywall       1st Floor         Floor - Terrazzo       1st Floor         Floor Drain       1st Floor         Hand Dryer       1st Floor	313 313 313 2 2	SF SF EA SF SF SF EA	7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years	
Walls - Plaster/Drywall       301-303         Work Sink       301-303         Restroom         Accessories       1st Floor         Ceiling - Plaster/Drywall       1st Floor         Floor - Terrazzo       1st Floor         Floor Drain       1st Floor         Hand Dryer       1st Floor	313 313 313 2 2	SF EA SF SF SF EA	7 7 7 7 7	10+ years 10+ years 6-10 years 10+ years	
Work Sink 301-303  Restroom  Accessories 1st Floor Ceiling - Plaster/Drywall 1st Floor Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	313 313 313 2 2	SF SF SF EA	7 7 7 7	10+ years 6-10 years 10+ years	
Accessories 1st Floor Ceiling - Plaster/Drywall 1st Floor Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	313 313 2 2	SF SF EA	7 7	10+ years	
Accessories 1st Floor Ceiling - Plaster/Drywall 1st Floor Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	313 313 2 2	SF SF EA	7 7	10+ years	
Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	313 2 2	SF SF EA	7	10+ years	
Floor - Terrazzo 1st Floor Floor Drain 1st Floor Hand Dryer 1st Floor	313 2 2	SF EA		•	
Hand Dryer 1st Floor	2 2	EA		10+ years	
Hand Dryer 1st Floor	2		7	10+ years	
·		EΑ	7	10+ years	
Lavaiui y 15t F100i		EΑ	7	10+ years	
Lighting - Lay-in 1st Floor	6	EA	7	6-10 years	
Partitions 1st Floor	7	EΑ	7	10+ years	
Walls - Structural Glazed Tile 1st Floor	885	SF	7	10+ years	
Water Closet 1st Floor	7	ĒΑ	7	10+ years	
Accessories 1st Floor	313	SF	7	10+ years	
Ceiling - Plaster/Drywall 1st Floor	313	SF	7	10+ years	
Floor - Terrazzo 1st Floor	313	SF	7	6-10 years	
Floor Drain 1st Floor	2	ĒΑ	7	10+ years	
Hand Dryer 1st Floor	2	EA	7	10+ years	
Lavatory 1st Floor	3	ΕA	7	10+ years	
Lighting - Lay-in 1st Floor	6	ΕA	7	6-10 years	
Partitions 1st Floor	3	ΕA	7	6-10 years	
Urinals 1st Floor	4	ΕA	7	10+ years	
Walls - Structural Glazed Tile 1st Floor	885	SF	7	10+ years	
Water Closet 1st Floor	3	ĒΑ	7	10+ years	
Accessories 1st Floor Across 108	45	SF	7	6-10 years	
Ceiling - Lay-in 1st Floor Across 108	45	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st Floor Across 108	1	ĒΑ	7	10+ years	
Floor - Terrazzo 1st Floor Across 108	45	SF	7	10+ years	
Floor Drain 1st Floor Across 108	1	ĒΑ	7	10+ years	
Lavatory 1st Floor Across 108	1	EΑ	7	10+ years	
Lighting - Lay-in 1st Floor Across 108	1	EA	7	10+ years	
Walls - Structural Glazed Tile 1st Floor Across 108	255	SF	7	10+ years	
Water Closet 1st Floor Across 108	1	EA	7	10+ years	
Accessories 1st Floor Next to 109	45	SF	7	6-10 years	
Ceiling - Lay-in 1st Floor Next to 109	45	SF	7	10+ years	
Doors - Wood Doors inclu hw 1st Floor Next to 109	1	EA	7	10+ years	
Floor - Terrazzo 1st Floor Next to 109	45	SF	7	10+ years	
Floor Drain 1st Floor Next to 109	1	EA	7	10+ years	
Lavatory 1st Floor Next to 109	1	EA	7	ioi years	



Catego	Category : Room		В				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor Next to 109	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor Next to 109	255	SF	7	10+ years	
	Water Closet	1st Floor Next to 109	1	EA	7	10+ years	
	Accessories	1st- Faculty Toilet (across from Principal)	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st- Faculty Toilet (across from Principal)	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Faculty Toilet (across from Principal)	1	EA	7	10+ years	
	Floor - Terrazzo	1st- Faculty Toilet (across from Principal)	42	SF	7	6-10 years	
	Floor Drain	1st- Faculty Toilet (across from Principal)	1	EA	7	10+ years	
	Lavatory	1st- Faculty Toilet (across from Principal)	1	EA	7	6-10 years	
	Lighting - Lay-in	1st- Faculty Toilet (across from Principal)	1	EA	7	6-10 years	
	Showers	1st- Faculty Toilet (across from Principal)	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st- Faculty Toilet (across from Principal)	212	SF	7	10+ years	
	Water Closet	1st- Faculty Toilet (across from Principal)	1	EA	7	10+ years	
	Accessories	1st- Inside Rm 105 - UIC Health & Wellness Center	41	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st- Inside Rm 105 - UIC Health & Wellness Center	41	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 105 - UIC Health & Wellness Center	1	EA	7	10+ years	
	Floor - Tile	1st- Inside Rm 105 - UIC Health & Wellness Center	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 105 - UIC Health & Wellness Center	1	EA	7	10+ years	
	Lavatory	1st- Inside Rm 105 - UIC Health & Wellness Center	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st- Inside Rm 105 - UIC Health & Wellness Center	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st- Inside Rm 105 - UIC Health &	230	SF	7	10+ years	
	Water Closet	Wellness Center 1st- Inside Rm 105 - UIC Health &	1	EA	7	10+ years	
	Accessories	Wellness Center 1st- Inside Rm 108	41	SF	7	10+ years	
	Ceiling - Lay-in	1st- Inside Rm 108	37	SF	7 7	10+ years	
	Ceiling - Lay-in	1st- Inside Riff 106	4	SF	4	0-1 year	Water stained tile
	Johning - Lay-III	13t- III3ius IVIII 100	4	Oi.	-	o-i yeai	vvator stained tile





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st- Inside Rm 108	1	EA	7	10+ years	
	Floor - Terrazzo	1st- Inside Rm 108	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 108	1	EA	7	10+ years	
	Lavatory	1st- Inside Rm 108	1	EΑ	7	10+ years	
	Lighting - Lay-in	1st- Inside Rm 108	1	EA	7	6-10 years	
	Walls - Concrete Block	1st- Inside Rm 108	204	SF	7	10+ years	
	Water Closet	1st- Inside Rm 108	1	EA	7	10+ years	
	Accessories	1st- Inside Rm 110	41	SF	7	10+ years	
	Ceiling - Lay-in	1st- Inside Rm 110	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 110	1	EA	7	10+ years	
	Floor - Terrazzo	1st- Inside Rm 110	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 110	1	ĒΑ	7	10+ years	
	Lavatory	1st- Inside Rm 110	1	EA	7	10+ years	
	Lighting - Lay-in	1st- Inside Rm 110	1	EA	7	6-10 years	
	Walls - Concrete Block	1st- Inside Rm 110	204	SF	7	10+ years	
	Water Closet	1st- Inside Rm 110	1	EA	7	10+ years	
	Accessories	1st- Inside Rm 111	41	SF	7	6-10 years	
	Ceiling - Lay-in	1st- Inside Rm 111	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 111	1	EA	7	10+ years	
	Floor - Terrazzo	1st- Inside Rm 111	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 111	1	EA	7	10+ years	
	Lavatory	1st- Inside Rm 111	1	EA	7	10+ years	
	Lighting - Lay-in	1st- Inside Rm 111	1	EA	7	6-10 years	
	Walls - Concrete Block	1st- Inside Rm 111	204	SF	7	10+ years	
	Water Closet	1st- Inside Rm 111	1	EA	7	10+ years	
	Accessories	1st- Inside Rm 112	41	SF	7	10+ years	
	Ceiling - Lay-in	1st- Inside Rm 112	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 112	1	EA	7	10+ years	
	Floor - Terrazzo	1st- Inside Rm 112	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 112	1	EA	7	10+ years	
	Lavatory	1st- Inside Rm 112	1	EA	7	10+ years	
	Lighting - Lay-in	1st- Inside Rm 112	1	EA	7	6-10 years	
	Walls - Concrete Block	1st- Inside Rm 112	204	SF	7	10+ years	
	Water Closet	1st- Inside Rm 112	20 <del>4</del> 1	EA	7	10+ years 10+ years	
		1st- Inside Rm 113	41	SF	7		
	Accessories		41	SF	7	6-10 years	
	Ceiling - Lay-in	1st- Inside Rm 113		SF EA		6-10 years	
	Doors - Wood Doors inclu hw	1st- Inside Rm 113	1		7	10+ years	
	Floor - Terrazzo	1st- Inside Rm 113	41	SF	7	6-10 years	
	Floor Drain	1st- Inside Rm 113	1	EΑ	7	10+ years	
	Lavatory	1st- Inside Rm 113	1	EA	7	10+ years	
	Lighting - Lay-in	1st- Inside Rm 113	1	EA	7	10+ years	
	Walls - Concrete Block	1st- Inside Rm 113	204	SF	7	10+ years	
	Water Closet	1st- Inside Rm 113	1	EA	7	10+ years	
	Accessories	1st- Inside of Rm 106	41	SF	7	10+ years	





Catego	ry : Room		В	uilding	: Main	Building : Main						
_						Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments					
	Ceiling - Lay-in	1st- Inside of Rm 106	41	SF	7	10+ years						
	Doors - Wood Doors inclu hw	1st- Inside of Rm 106	1	EA	7	10+ years						
	Floor - Terrazzo	1st- Inside of Rm 106	41	SF	7	6-10 years						
	Floor Drain	1st- Inside of Rm 106	1	EA	7	10+ years						
	Lavatory	1st- Inside of Rm 106	1	EA	7	10+ years						
	Lighting - Lay-in	1st- Inside of Rm 106	1	EA	7	6-10 years						
	Walls - Concrete Block	1st- Inside of Rm 106	204	SF	7	10+ years						
	Water Closet	1st- Inside of Rm 106	1	EA	7	10+ years						
	Accessories	1st- Kitchen Staff	43	SF	7	6-10 years						
	Ceiling - Lay-in	1st- Kitchen Staff	43	SF	7	10+ years						
	Doors - Steel Doors incl hw	1st- Kitchen Staff	1	ĒΑ	7	10+ years						
	Floor - Concrete Epoxy/ Painted	1st- Kitchen Staff	43	SF	7	10+ years						
	Floor Drain	1st- Kitchen Staff	1	ĒΑ	7	10+ years						
	Lavatory	1st- Kitchen Staff	1	ΕA	7	10+ years						
	Lighting - Lay-in	1st- Kitchen Staff	1	EA	7	6-10 years						
	Walls - Concrete Block	1st- Kitchen Staff	265	SF	7	10+ years						
	Water Closet	1st- Kitchen Staff	1	EΑ	7	10+ years						
	Accessories	2nd Floor	312	SF	7	10+ years						
	Ceiling - Plaster/Drywall	2nd Floor	312	SF	7	10+ years						
	Floor - Terrazzo	2nd Floor	312	SF	7	10+ years						
	Floor Drain	2nd Floor	2	EA	7	10+ years						
	Lavatory	2nd Floor	3	EA	7	10+ years						
	Lighting - Lay-in	2nd Floor	6	EA	7	10+ years						
	Partitions	2nd Floor	3	EA	7	6-10 years						
	Urinals	2nd Floor	4	EΑ	7	10+ years						
	Walls - Structural Glazed Tile	2nd Floor	885	SF	7	10+ years						
	Water Closet	2nd Floor	3	EA	7	10+ years						
	Accessories	2nd Floor	312	SF	7	10+ years						
	Ceiling - Plaster/Drywall	2nd Floor	312	SF	7	6-10 years						
	Floor - Terrazzo	2nd Floor	312	SF	7	10+ years						
	Floor Drain	2nd Floor	2	EA	7	10+ years						
	Lavatory	2nd Floor	3	EA	7	10+ years						
	Lighting - Lay-in	2nd Floor	6	EA	7	10+ years						
	Partitions	2nd Floor	7	EA	7	•						
	Walls - Structural Glazed Tile	2nd Floor	990	SF	7	10+ years						
	Water Closet	2nd Floor	990 7	EA	7	10+ years						
				SF		10+ years						
	Accessories	2nd Floor Across from 208	57 57		7	10+ years						
	Ceiling - Lay-in	2nd Floor Across from 208	57	SF	7	10+ years						
	Doors - Wood Doors inclu hw	2nd Floor Across from 208	1	EA	7	10+ years						
	Floor - Terrazzo	2nd Floor Across from 208	57	SF	7	10+ years						
	Floor Drain	2nd Floor Across from 208	1	EΑ	7	10+ years						
	Lavatory	2nd Floor Across from 208	1	EΑ	7	10+ years						
	Lighting - Lay-in	2nd Floor Across from 208	1	EA	7	6-10 years						
	Walls - Structural Glazed Tile	2nd Floor Across from 208	300	SF	7	10+ years						





Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Closet	2nd Floor Across from 208	1	EA	7	10+ years				
	Accessories	2nd Floor Next to 207	57	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor Next to 207	57	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor Next to 207	1	EA	7	10+ years				
	Floor - Terrazzo	2nd Floor Next to 207	57	SF	6	10+ years				
	Floor Drain	2nd Floor Next to 207	1	EA	7	10+ years				
	Lavatory	2nd Floor Next to 207	1	EA	7	10+ years				
	Lighting - Lay-in	2nd Floor Next to 207	1	EA	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor Next to 207	300	SF	7	10+ years				
	Water Closet	2nd Floor Next to 207	1	EA	7	10+ years				
	Accessories	3rd Floor	317	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	317	SF	7	10+ years				
	Floor - Terrazzo	3rd Floor	317	SF	7	10+ years				
	Floor Drain	3rd Floor	2	EA	7	10+ years				
	Lavatory	3rd Floor	3	EΑ	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years				
	Partitions	3rd Floor	7	EA	7	10+ years				
	Walls - Structural Glazed Tile	3rd Floor	712	SF	7	10+ years				
	Water Closet	3rd Floor	7 12	EA	7	10+ years				
	Accessories	3rd Floor	317	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	317	SF	7	•				
	Floor - Terrazzo		317	SF	7	10+ years				
		3rd Floor		EA	7	10+ years				
	Floor Drain	3rd Floor	2			10+ years				
	Lavatory	3rd Floor	3	EΑ	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor	6	EΑ	7	10+ years				
	Partitions	3rd Floor	3	EΑ	7	10+ years				
	Urinals	3rd Floor	4	EA	7	10+ years	Quantity changed as total has been aggregated/divided.			
	Walls - Structural Glazed Tile	3rd Floor	712	SF	7	10+ years				
	Water Closet	3rd Floor	3	EA	7	10+ years				
	Accessories	3rd Floor Next to 307	59	SF	7	6-10 years				
	Ceiling - Lay-in	3rd Floor Next to 307	55	SF	7	10+ years				
	Ceiling - Lay-in	3rd Floor Next to 307	4	SF	5	1-2 years	Cracked ceiling tile			
	Doors - Wood Doors inclu hw	3rd Floor Next to 307	1	EA	7	10+ years				
	Floor - Terrazzo	3rd Floor Next to 307	59	SF	7	10+ years				
	Floor Drain	3rd Floor Next to 307	1	EA	7	10+ years				
	Lavatory	3rd Floor Next to 307	1	EA	7	10+ years				
	Lighting - Lay-in	3rd Floor Next to 307	1	EA	7	10+ years				
	Walls - Structural Glazed Tile	3rd Floor Next to 307	275	SF	7	10+ years				
	Water Closet	3rd Floor Next to 307	1	ĒA	7	10+ years				
	Accessories	3rd Floor Next to 309	59	SF	7	6-10 years				
	Ceiling - Lay-in	3rd Floor Next to 309	59	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Next to 309	1	EA	7	10+ years				
	Floor - Terrazzo	3rd Floor Next to 309	59	SF	7	10+ years				
	cc	314 1 1001 110/4 10 000	00	٥.	•	10. 300.0				





Catego	ry : Room	<u>-                                    </u>	В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	3rd Floor Next to 309	1	EA	7	10+ years	
	Lavatory	3rd Floor Next to 309	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor Next to 309	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Next to 309	275	SF	7	10+ years	
	Water Closet	3rd Floor Next to 309	1	EA	7	10+ years	
	Accessories	4th Floor	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	317	SF	7	10+ years	
	Floor - Terrazzo	4th Floor	317	SF	7	10+ years	
	Floor Drain	4th Floor	2	EA	7	10+ years	
	Lavatory	4th Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	4th Floor	7	EΑ	7	10+ years	
	Partitions	4th Floor	7	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	4th Floor	1,108	SF	7	10+ years	
	Water Closet	4th Floor	7	EΑ	7	10+ years	
	Accessories	4th Floor	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	317	SF	7	10+ years	
	Floor - Terrazzo	4th Floor	317	SF	7	10+ years	
	Floor Drain	4th Floor	2	EA	7	10+ years	
	Lavatory	4th Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	4th Floor	6	EA	7	10+ years	
	Partitions	4th Floor	3	EA	7	10+ years	
	Urinals	4th Floor	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	4th Floor	1,108	SF	7	10+ years	
	Water Closet	4th Floor	3	EA	7	10+ years	
	Accessories	4th Floor Across 408	59	SF	7	6-10 years	
	Ceiling - Lay-in	4th Floor Across 408	59	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor Across 408	1	EA	7	10+ years	
	Floor - Terrazzo	4th Floor Across 408	59	SF	7	10+ years	
	Floor Drain	4th Floor Across 408	1	EA	7	10+ years	
	Lavatory	4th Floor Across 408	1	EA	7	10+ years	
	Lighting - Lay-in	4th Floor Across 408	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	4th Floor Across 408	275	SF	7	10+ years	
	Water Closet	4th Floor Across 408	1	EA	7	10+ years	
	Accessories	4th Floor Next to 405	59	SF	7	6-10 years	
	Ceiling - Lay-in	4th Floor Next to 405	59	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor Next to 405	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	4th Floor Next to 405	59	SF	7	10+ years	
	Floor Drain	4th Floor Next to 405	1	ĒΑ	7	10+ years	
	Lavatory	4th Floor Next to 405	1	ΕA	7	10+ years	
	Lighting - Lay-in	4th Floor Next to 405	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	4th Floor Next to 405	275	SF	7	10+ years	
	Water Closet	4th Floor Next to 405	1	EA	7	10+ years	
			•		•	,	



Catego	Category : Classroom		В	uilding	: Main		33 W Comar NOAD, Chicago, 12 00010
carego	,,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #106 (Pre School)					•	
	Ceiling - Lay-in	1st Floor	1,210	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	5	SF	4	0-1 year	Water stained
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	Trator stanrou
	Doors - Wood Doors inclu hw	1st Floor	 1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	160	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,247	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	415	SF	7	10+ years	
	Work Sink	1st Floor	2	EΑ	7	10+ years	
	Tronk Gillik	10111001	_	_, 、	•	io. youro	
Classroc	om #108 (Kindergarten)						
	Casework	1st Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,211	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	,	SF	4	0-1 year	Water stained
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	168	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	852	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	852	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #109 (Regular Classroom)						
	Casework	1st Floor	63	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,114	SF	7	6-10 years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,114	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	1,114	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	147	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,247	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	415	SF	7	10+ years	
	vvano i laston brywan	1301 1001	410	01	,	ioi yeais	
Classroo	om #110 (Kindergarten)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
						•	



Catego	ry : Classroom		В	uilding	: Main		33 W German NGAB, Grincago, 12 00010
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	13	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	166	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,264	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	422	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #111 (Regular Classroom)						
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	118	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,264	SF	7	10+ years	
				SF SF		•	
	Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor	422 2	Sr EA	7 7	10+ years	
	WORK SINK	151 F1001	2	EA	,	10+ years	
_Classroo	om #112 (Kindergarten)						
	Casework	1st Floor	51	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	<sup>'</sup> 13	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	152	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,264	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	422	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #113 (Regular Classroom)						
	Casework	1st Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Marker Doard	13(1100)	24	LI	,	o- io yeais	



Assessment Date: 10/30/2023

Category : Classroom			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	104	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,264	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	422	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #202 (Other Instructional Use)						
	Casework	2nd Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,142	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,142	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	71	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,350	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
_Classroo	om #203 (Multi Purpose Room)						
	Casework	2nd Floor	49	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	858	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	908	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	11	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	908	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Casework	2110 1 1001	31	LF	,	TOT years	



Catego	Category : Classroom		В	uilding	33 W Cerman NOAD, Crincago, IL 000 To		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	856	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	ŭ
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	908	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
_Classroo	m #207 (Vacant)						
	Casework	2nd Floor	63	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	 1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,000	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	365	SF	7	10+ years	
	Traile Tractor, 21, Trail	2110 1 1001	000	O.	•	.o. youro	
_Classroo	m #208 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	864	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	605	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
_Classroo	m #209 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	908	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
	•					,	





Catego	ry : Classroom		R	55 W Cermak ROAD, Chicago, IL 60616			
Calego	ily . Classicolli			uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Commonts
Group	item - Type	Location	Quantity	UOIVI	Kalik	Replacement	Comments
01	(1040 /P						
Classro	om #210 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	605	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
Classia	#244 (Deculer Classes)						
	om #211 (Regular Classroom)	0-15	F.4			40	
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	605	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	605	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
	Walls - Flaster/Drywall	2110 1 1001	003	OI .	,	10+ years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	605	SF	7	10+ years	
						·	



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	605	SF	7	10+ years	
Classro	om #214 (Regular Classroom)						
	Casework	2nd Floor	51	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	905	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	288	SF	7	10+ years	
Classro	om #301 (Science Classroom)						
	Casework	3rd Floor	80	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,445	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	 1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,445	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,481	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	460	SF	7	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
Classro	om #303 (Science Classroom)						
	Casework	3rd Floor	80	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,345	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,345	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	12	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,445	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	400	SF	7	10+ years	
	Work Sink	3rd Floor	5	EA	7	6-10 years	
Classro	om #305 (Regular Classroom)						
<u> </u>	Casework	3rd Floor	48	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	916	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Water damaged ceiling tiles
	Johning Lay III	01011001	7	Oi.	7	1 2 yours	Trate: damaged coming mes



Catego	ry : Classroom		В	uilding	: Main		, ,	
3						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Side-lite	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years		
	Floor - Tile	3rd Floor	920	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EΑ	7	10+ years		
	Marker Board	3rd Floor	32	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	813	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	282	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
Classroo	om #306 Compter Lab (Other Instruction	nal Use)						
	Casework	3rd Floor	18	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	1,204	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years	Not previously assessed	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Not providuoly accessed	
	Floor - Tile	3rd Floor	1,204	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	9	EA	7	10+ years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	98	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	2,304	SF	7	10+ years		
Classro	om #308 (Regular Classroom)							
Classion	Casework	3rd Floor	60	LF	7	10+ years		
	Casework Ceiling - Lay-in	3rd Floor	1,385	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,385	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	1,363	EA	7	10+ years		
	Marker Board	3rd Floor	32	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	767	SF	7	•		
	Walls - Plaster/Drywall	3rd Floor	566	SF	7	10+ years 10+ years		
	vvalis - Plastei/Drywali	310 F1001	300	SF	1	10+ years		
Classroo	om #309 (Vacant)	0.15						
	Casework	3rd Floor	64	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,014	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Water damaged ceiling tiles	
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,020	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	10	EA	7	10+ years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	945	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	198	SF	7	10+ years		

Page : 27 of 56




Category : Classroom			В				
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #310 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	866	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Water damaged ceiling tiles
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	190	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Damaged drywall
Classroo	m #311 (Regular Classroom)						
CIGSSIUU	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	21	SF	7		
	Doors - Side-life Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	870	SF	7	10+ years 10+ years	
		3rd Floor	12	EA	7	•	
	Lighting - Lay-in Marker Board	3rd Floor	32	LF	7	10+ years	
				SF		6-10 years	
	Walls - Concrete Block Walls - Plaster/Drywall	3rd Floor 3rd Floor	934 239	SF	7 7	10+ years 10+ years	
Classias							
Classroo	m #312 (Regular Classroom)	0.15	10		-	40	
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years	Quantity changed as total has been aggregated/divided.
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	195	SF	7	10+ years	
Classroo	m #313 (Store Room)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Lighting - Lay-III	314 1 1001	12	LA	,	10+ years	

Page : 28 of 56



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	239	SF	7	10+ years	
Classroo	om #314 (Regular Classroom)						
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	864	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Water damaged ceiling tiles
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	The state of the s
	Doors - Wood Doors inclu hw	3rd Floor	 1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	239	SF	7	10+ years	
	vvalio i lactor/brywan	010 1 1001	200	O.	•	101 yours	
Classroo	om #315 (Regular Classroom)	0.151	10	. –			
	Casework	3rd Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	868	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Rank changed to update/correct to match current observation
	Floor - Tile	3rd Floor	870	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	934	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	239	SF	7	10+ years	
Classroo	om #400 (Art Room)						
	Casework	4th Floor	58	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	1,250	SF	7	6-10 years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Transom Window	4th Floor	117	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	1,250	SF	7	10+ years	
	Kiln	4th Floor	1,200	EA	7	10+ years	
	Lighting - Lay-in	4th Floor	14	EA	7	10+ years	
	Storage/ Closet	4th Floor	131	SF	5	10+ years	Water damage
	Walls - Concrete Block	4th Floor	2,655	SF	7	10+ years	Trator damago
	Work Sink	4th Floor	2,000	EA	7	6-10 years	
Classro	om #401 (Music Room)						
JIGGGIO	Casework	4th Floor	38	LF	7	10+ years	
	Casework	401 F1001	30	LF	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	4th Floor	1,602	SF	7	10+ years	
	Ceiling - Lay-in	4th Floor	8	SF	4	0-1 year	Damaged
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	· ·
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	1,610	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	22	EA	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Sound Panels	4th Floor	21	EA	7	6-10 years	
	Storage/ Closet	4th Floor	131	SF	7	10+ years	
	Walls - Concrete Block	4th Floor	6	SF	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	610	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	0-1 year	Damaged
	valle i lacion biy wall	14111661	.0	O.	ŭ	o i youi	Damagea
Classroo	m #401B (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	ĒΑ	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	777	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	280	SF	7	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
	#404 (D						
Classroc	m #404 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	4	EA	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	777	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	208	SF	7	10+ years	
`laceroo	m #405 (Regular Classroom)						
الاقتانات	Casework	4th Floor	69	LF	7	10+ years	
	Casework Ceiling - Lay-in	4th Floor	1,020	SF	7	10+ years	
	Doors - Side-lite			SF SF	7 7		
	Doors - Side-lite Doors - Wood Doors inclu hw	4th Floor	21	SF EA		10+ years	
		4th Floor	1 020		7	10+ years	
	Floor - Tile	4th Floor	1,020	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	10	EA	7	10+ years	

Page : 30 of 56



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	4th Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	945	SF	7	10+ years	
Classro	om #406 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	ĒΑ	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	459	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	560	SF	7	10+ years	
Classro	om #408 (Regular Classroom)						
Classiu	Casework	4th Floor	54	LF	7	10+ years	
	Casework Ceiling - Lay-in	4th Floor	830	SF	7		
				SF SF		10+ years	
	Doors - Side-lite	4th Floor	21		7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	EA	7	10+ years	
	Marker Board	4th Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	459	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	506	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	1-2 years	Damaged
Classro	om #409 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	ĒA	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	777	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	280	SF	7	10+ years	
Classroo	om #410 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	6	6-10 years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
			1	_	7		
			=			-	
	Doors - Wood Doors inclu hw Floor - Tile	4th Floor 4th Floor	830	EA SF	7	10+ years 10+ years	



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	4th Floor	12	EΑ	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	459	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	516	SF	7	10+ years	
_Classroo	om #411 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	EΑ	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	459	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	560	SF	7	10+ years	
Classro	om #412 (Regular Classroom)						
Oldosio	Casework	4th Floor	48	LF	7	10+ years	
	Casework Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7		
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
				SF		10+ years	
	Floor - Tile	4th Floor	830	SF EA	7	10+ years	
	Lighting - Lay-in	4th Floor	12		7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	459	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	560	SF	7	10+ years	
Classroo	om #413 (Regular Classroom)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	822	SF	7	10+ years	
	Ceiling - Lay-in	4th Floor	8	SF	4	0-1 year	Damaged
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	7	10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	12	EA	7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	451	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	560	SF	7	10+ years	
Classroo	om #414 (Multi Purpose Room)						
	Casework	4th Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	830	SF	7	10+ years	
	Doors - Side-lite	4th Floor	21	SF	7	10+ years	
		<del></del>			-	- ,	



Group

Category: Classroom

Item - Type

Doors - Wood Doors inclu hw

### National Teachers Elementary Academy 55 W Cermak ROAD, Chicago, IL 60616

**Building: Main** 

Rank

7

UOM

EΑ

Quantity

Recommend

10+ years

Replacement Comments

	Doors - wood Doors Inclu flw	4111 F1001				10+ years	
	Floor - Tile	4th Floor	830	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	8		7	10+ years	
	Marker Board	4th Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	777	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	280	SF	7	10+ years	
atego	ry : Interior		i	Building	: Main		
				Ĭ		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	4,026	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	10		4	0-1 year	Damaged
	Ceiling - Plaster/Drywall	1st Floor	1,303		7	10+ years	3
	Doors - Side-lite	1st Floor	196		7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2		7	10+ years	
	Doors - Store Front	1st Floor	_ 6	EA	7	10+ years	
	Doors - Transom Window	1st Floor	86	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3		7	10+ years	
	Floor - Terrazzo	1st Floor	5,351	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	25		7	6-10 years	
	Lighting - Lay-in	1st Floor	26		7	6-10 years	
	Lighting - Lay-in Lighting - Pendent/Surface	1st Floor	176		7	6-10 years	
	Walls - Concrete Block	1st Floor	9,498		7	10+ years	
	Ceiling - Lay-in	2nd Floor	4,137	SF	7	10+ years	
		2nd Floor			7		
	Ceiling - Plaster/Drywall		438			10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6		7	10+ years	Composto di succeptito
	Drinking Fountains - Single Fountain	2nd Floor	2		7	10+ years	Corrected quantity
	Floor - Terrazzo	2nd Floor	4,575		7	10+ years	
	Lighting - Lay-in	2nd Floor	4		7	10+ years	
	Lighting - Lay-in	2nd Floor	29	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	148		7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	280	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	8,129		7	10+ years	
	Ceiling - Lay-in	3rd Floor	4,475		7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	241	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	Quantity changed as total has bee aggregated/divided.
	Floor - Terrazzo	3rd Floor	4,716	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	141	EA	7	10+ years	Quantity changed as total has bee aggregated/divided.
	Student Lockers - Two Tiers	3rd Floor	195	EA	7	10+ years	aggiogatod/dividod.

Location

4th Floor



Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Concrete Block	3rd Floor	6,760	SF	7	10+ years			
	Ceiling - Lay-in	4th Floor	4,470	SF	7	10+ years	Quantity changed as total has been aggregated/divided.		
	Ceiling - Lay-in	4th Floor	8	SF	5	1-2 years	Water damaged ceiling tiles		
	Ceiling - Plaster/Drywall	4th Floor	238	SF	7	10+ years	0 0		
	Doors - Steel Doors incl hw	4th Floor	6	EΑ	7	10+ years			
	Drinking Fountains - Single Fountain	4th Floor	2	EA	7	10+ years			
	Floor - Terrazzo	4th Floor	4,716	SF	7	10+ years			
	Lighting - Pendent/Surface	4th Floor	141	ĒΑ	7	10+ years			
	Student Lockers - Two Tiers	4th Floor	279	EA	7	10+ years			
	Walls - Concrete Block	4th Floor	6,760	SF	7	10+ years			
Safety									
,	Camera Viewing Station	Entire Building	1	EA	7	6-10 years			
	Metal Detector	Entire Building	2	EΑ	7	6-10 years			
	Security Cameras	Entire Building	12	EΑ	7	6-10 years			
	Security Cameras	Entire Building	4	EΑ	7	6-10 years			
	Security Cameras	Entire Building	4	EΑ	7	6-10 years			
	Security Cameras	Entire Building	5	EΑ	7	6-10 years			
	Security Cameras	Exterior	8	EA	7	6-10 years			
Stairs									
	Ceiling - Plaster/Drywall	Stair 1A	893	SF	7	10+ years			
	Floor - Terrazzo	Stair 1A	735	SF	7	10+ years			
	Handrails	Stair 1A	220	LF	7	10+ years			
	Lighting - Chandelier, Incandescent	Stair 1A	18	EA	7	10+ years			
	Lighting - Pendent/Surface	Stair 1A	4	EA	7	10+ years			
	Stairs - Terrazzo	Stair 1A	107	LF	7	10+ years			
	Walls - Structural Glazed Tile	Stair 1A	20,121	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Stair 1B	858	SF	7	10+ years			
	Floor - Terrazzo	Stair 1B	1,052	SF	7	10+ years			
	Handrails	Stair 1B	300	LF	7	10+ years			
	Lighting - Chandelier, Incandescent	Stair 1B	16	EA	7	10+ years			
	Lighting - Pendent/Surface	Stair 1B	8	EA	7	10+ years			
	Stairs - Terrazzo	Stair 1B	72	LF	7	10+ years			
	Walls - Structural Glazed Tile	Stair 1B	33,596	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Stair 1C	1,380	SF	7	10+ years			
	Floor - Terrazzo	Stair 1C	1,755	SF	7	10+ years			
	Handrails	Stair 1C	215	LF	7	10+ years			
	Lighting - Lay-in	Stair 1C	22	EA	7	10+ years			
	Lighting - Wall Mounted	Stair 1C	12	EA	7	10+ years			
	Stairs - Terrazzo	Stair 1C	104	LF	7	10+ years			
	Walls - Structural Glazed Tile	Stair 1C	14,455	SF	7	10+ years			



Category : Interior	Building : Main				
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments			
Vertical Conveyance					
Elevator - Hydraulic Elevator	1st Floor	1 EA 7 10+ years			



Category: Exterior **Building: Linked Addition-Athletic** Recommend Location Replacement Comments Item - Type Quantity **UOM** Rank Group Entrance Exterior Doors - Side lite #10 FΑ 6 4 10+ years #10 2 FΑ 6 Exterior Doors - Store Front 10+ years 6 Exterior Doors - Transom Lite #10 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #11 2 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #12 2 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #13 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #14 1 EΑ 6 10+ years Exterior Doors - Store Front #15 2 EΑ 6 6-10 years Missing door handle Exterior Doors - Transom Lite #15 1 FΑ 7 6-10 years Entrance Control - Audio and Video #9 1 FΑ 6 10+ years #9 Exterior Doors - Side lite 4 EΑ 6 10+ years Exterior Doors - Store Front #9 2 EΑ 6 10+ years Exterior Doors - Transom Lite #9 6 EΑ 6 10+ years Exterior Doors - Exterior Steel Door Roof Access 1 EΑ 6 10+ years LF Exterior Stairs - Steel or Aluminum Roof Access 6 7 10+ years Foundation Foundation - Concrete LF 7 **Entire Building** 909 10+ years Superstructure - Steel 63,900 SF **Entire Building** 7 10+ years Liahtina Exterior Lighting - Wall Mounted **Entire Building** 36 EΑ 6 10+ years Roof System Access Ladder - Metal **Entire Building** 1 EΑ 7 10+ years LF Chimney - Metal Flue **Entire Building** 12 6 10+ years Recalculated quantity Coping - Metal **Entire Building** 356 LF 6 10+ years LF 10+ years Coping - Stone **Entire Building** 787 6 Downspouts - Interior Downspouts **Entire Building** 1,016 LF 6 10+ years LF Parapet - 16" - 30" Height **Entire Building** 361 6 10+ years LF Parapet - Parapet > 30" **Entire Building** 953 6 10+ years SF Roof - Modified Bitumen 5 2-5 years **Entire Building** 31.493 SF Roof Structure - Steel / Metal Deck/ **Entire Building** 31.493 10+ years Concrete Topping Walls LF Cornice - Masonry Projecting Limestone **Entire Building** 909 6 10+ years Exterior Walls - Brick **Entire Building** 11.821 SF 6 10+ years Repaired SF Exterior Walls - Brick **Entire Building** 11.820 6 10+ years Exterior Walls - Prefabricated Metal Panel SF **Entire Building** 800 6 10+ years Wall



Category : Exterior			E	Building : Linked Addition-Athletic					
A contract to the second of th						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exterior Walls - Stone-Cast	Entire Building	4,545	SF	6	10+ years			
Vindow	S								
	Clerestory - Glass Double-Pane	Entire Building	2,646	SF	6	10+ years			
	Curtain wall - Glazed Double Pane	Entire Building	164	SF	6	10+ years			
	Curtain wall - Louver	Entire Building	200	SF	6	10+ years			
	Guard - Guards perforated	Entire Building	2,062	SF	6	10+ years			
	Lintels - Stone	Entire Building	294	LF	6	10+ years			
	Windows - Insulated Panel	Entire Building	64	SF	6	10+ years			
	Windows - Sash Aluminum Double-pane	Entire Building	714	SF	6	10+ years			
atego	ry : Electrical		E	Buildina	: Linked	d Addition-Athl	letic		
	.,					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
merge	ncy System	Fatina Duildin	00.000			0.40			
	Security System - CCTV	Entire Building	63,900	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	63,900	SF	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,894	SF	6	6-10 years			
	Emergency A/C Power - Gym	Entire Building	5,330	SF	6	6-10 years			
	Emergency A/C Power - Pool	Entire Building	6,189	SF	6	6-10 years			
	Emergency A/C Power - Students Toilets	Entire Building	1,764	SF	6	6-10 years			
	Emergency Battery Packs - Corridors and	Entire Building	10	ĒΑ	6	6-10 years			
	Stairs	9			-	- · · · · · · · · · · · · · · · · · · ·			
	Emergency Battery Packs - Gym	Entire Building	4	EA	6	6-10 years			
	Emergency Battery Packs - Pool	Entire Building	4	EA	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years			
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years			
	Exit Signs - Pool	Entire Building	3	EA	6	6-10 years			
	-	g	_		-	5 . 5 <b>,</b> 5			
/lain Se									
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years			
	PA System	Entire Building	63,900	SF	6	6-10 years			
	<b>&gt;</b>		23,000		-	<b>,</b>			
ower D	Distribution								
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years			
	Lighting and Power Panels - 100 A	Entire Building	9	EA	7	10+ years			
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years			
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years			
	amp								
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years			
20000110	Name: National Tacabara		Dogo : 27 of FC				Assessment Date: 10/2		



Category : Electrical

#### National Teachers Elementary Academy 55 W Cermak ROAD, Chicago, IL 60616

**Building: Linked Addition-Athletic** 

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	amp						
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		F	Buildina	: Linked	d Addition-Athl	letic
Guiogo	.,			, and and		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m		•				
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Annunciator Panel
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	63,900	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	63,900	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
		g	•			5 . c , c c	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Fire Pump Room	1	EA	6	6-10 years	
	Jockey Pump	Fire Pump Room	1	EA	6	6-10 years	
Sprinkler	•						
	Sprinkler Heads	Entire Building	63,900	SF	7	10+ years	
	Sprinkler Piping	Entire Building	63,900	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	63,900	SF	6	10+ years	
Catego	ry : Mechanical		F	Ruildina	·linker	d Addition-Athl	letic .
	.,			·		Recommend	
					Rank	Replacement	Comments
Group	Item - Type	Location	Quantity	UOM	Ralik	Replacement	Odimionto
<b>Group</b> Air Cond		Location	Quantity	UOM	Kalik	Replacement	
•		<b>Location</b> Roof	Quantity 1	<b>UOM</b> EA	6	6-10 years	
•	litioning					•	
•	litioning Chemical Pot Feeder	Roof	1	EA	6	6-10 years	
•	litioning  Chemical Pot Feeder  Chiller-Air Cooled-Screw Type-Roof  Mounted - 50 - 100 tons  Glycol Feed	Roof	1	EA	6	6-10 years 6-10 years	
•	litioning  Chemical Pot Feeder  Chiller-Air Cooled-Screw Type-Roof  Mounted - 50 - 100 tons  Glycol Feed	Roof Roof	1	EA EA	6 5	6-10 years 6-10 years 6-10 years	
•	litioning Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons	Roof Roof	1 1	EA EA	6 5	6-10 years 6-10 years	
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System	Roof Roof Roof Roof	1 1 1 1 100	EA EA EA LF	6 5 6 6	6-10 years 6-10 years 6-10 years 10+ years	
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System	Roof Roof Roof Roof Roof	1 1 1 100 1	EA EA LF EA	6 5 6 6 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System	Roof Roof Roof Roof	1 1 1 1 100	EA EA EA LF	6 5 6 6	6-10 years 6-10 years 6-10 years 10+ years	
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot	Roof Roof Roof Roof Roof	1 1 1 100 1	EA EA LF EA	6 5 6 6 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Chilled water cooling
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted	Roof Roof Roof Roof Roof	1 1 1 100 1	EA EA LF EA	6 5 6 6 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	
Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - Greater than 8000 cfm	Roof Roof Roof Roof Roof	1 1 1 100 1	EA EA LF EA	6 5 6 6 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	Chilled water cooling
_Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted	Roof Roof Roof Roof Roof	1 1 1 100 1	EA EA LF EA	6 5 6 6 6	6-10 years 6-10 years 6-10 years 10+ years 6-10 years	
_Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - Greater than 8000 cfm	Roof Roof Roof Roof Roof Roof Roof Mechanical Room	1 1 1 100 1 14	EA EA LF EA	6 5 6 6 6 5	6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Chilled water cooling
_Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - Greater than 8000 cfm Indoor Return Fans- Centrifugal Inline -	Roof Roof Roof Roof Roof Roof Roof Mechanical Room	1 1 1 100 1 14	EA EA LF EA	6 5 6 6 6 5	6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Chilled water cooling  RF - 3 is located in main building,
_Air Cond	Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof Mounted - 50 - 100 tons Glycol Feed Pipes - Chilled Water Pipe- Steel Pressure Fill System  Hing Systems Fan Power Box - Fan Power Box with Hot Water Coil Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - Greater than 8000 cfm Indoor Return Fans- Centrifugal Inline -	Roof Roof Roof Roof Roof Roof Roof Mechanical Room	1 1 1 100 1 14	EA EA LF EA	6 5 6 6 6 5	6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years	Chilled water cooling  RF - 3 is located in main building,



Catego	ry : Mechanical		Building : Linked Addition-Athletic					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	6-10 years	RF - 4	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU 5	1	EA	6	6-10 years	AHU 5, served gym	
	Air Intake	Mechanical Room - AHU 5	1	EA	6	6-10 years		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Less than 4000 cfm	Mechanical Room - AHU 7	1	EA	6	6-10 years	AHU 7, served locker rooms	
	Air Intake	Mechanical Room - AHU 7	1	EA	6	6-10 years		
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room AHU 4	1	EA	6	6-10 years	AHU 4, serves classrooms and daycare	
	Air Intake	Mechanical Room AHU 4	1	EA	6	6-10 years		
	VAV Box	Mechanical Room AHU 4	8	EA	6	6-10 years		
Heating								
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years		
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years		
	Fin Tube - Hot Water	Entire Building	90	LF	6	6-10 years		
	Radiator Panels - Hot Water	Entire Building	3	EΑ	6	6-10 years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	6	6-10 years		
Mechani	cal Plumbing							
	Hot Water Pump - Less than 10	Entire Building	1	EΑ	6	10+ years		
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	10+ years		
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	10+ years		
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years		
Tempera	ture Control							
	DDC System	Entire Building	63,900	SF	4	2-5 years	Software not upgraded, controls are unreliable and dampers need to be operated manually	
	Electric Thermostat	Entire Building	2	EΑ	6	6-10 years		
	Thermostats - DDC	Entire Building	25	EA	6	6-10 years		
Ventilatio								
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	3	EA	6	6-10 years		

Page : 39 of 56



	55 W Cermak ROAD, Chicago, IL 60616  Category: Mechanical  Building: Linked Addition-Athletic							
Catego	ry : Mechanical		В	uliaing	: Linked		etic	
Croup	Itom Tuno	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	Item - Type CFM	Location	Quantity	UOW	Kank	Replacement	Comments	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	5	EA	6	6-10 years		
	500 CFM	Entire Building	5	EA	O	6-10 years		
	500 Crivi							
Catogo	ry : Plumbing		D	uildina	· I inko	d Addition-Athl	otio	
Calego	ry . Fluinbing		В	unung	. LIIIKE	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_	nem - Type	Location	Qualitity	CON	IVAIIN	Replacement	Comments	
_Piping	B. d. Bit. H. W. C. B. d. H.	E # B ##	22.222					
	Domestic Piping-Hot Water Return Lines	Entire Building	63,900	SF	6	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	63,900	SF	6	10+ years		
	Domestic Piping-Hot Water from Risers to	Entire Building	63,900	SF	6	10+ years		
	Fixtures	Fating Dediction	00.000	0.	0	40		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	63,900	SF	6	10+ years		
	(Horizontal Lines)	Entire Duilding	00.000	C.E.	^	10		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	63,900	SF	6	10+ years		
	(Risers)	Entire Building	62.000	SF	6	10		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	63,900	SF	6	10+ years		
	(from Risers to Fixtures)	Entire Building	63,900	SF	6	10 L Vooro		
	Sanitary Piping Storm Piping	Entire Building Entire Building	63,900	SF	6 6	10+ years 10+ years		
	Vent Piping	Entire Building	63,900	SF	6	10+ years		
	vent riping	Entire Building	03,900	SF	O	10+ years		
Pool Sys	stems							
	Pool Drain Piping	Mechanical Room	100	LF	6	6-10 years		
	Pool Filtration System including Pump	Mechanical Room	1	EA	5	6-10 years		
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	5	6-10 years		
	Pool Supply and Return Piping	Mechanical Room	200	LF	6	6-10 years		
	11.7					•		
Pumps								
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	7	10+ years		
	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	5	6-10 years	Filter Pump	
	Pumps - Ejector-Duplex	Mechanical Room	1	EA	5	6-10 years		
	Pumps - Ejector-Duplex	Mechanical Room	1	EA	5	6-10 years		
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	10+ years		
	Pumps - Sump-Simplex	Mechanical Room	1	EA	6	10+ years		
Catego	ry : Room		В	uildina	: Linked	d Addition-Athl	etic	
	Recomme							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	Ceiling - Lay-in	1st Floor - Case Manager	155	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Case Manager	1	EA	7	10+ years		
	Floor - Carpet	1st Floor - Case Manager	155	SF	7	6-10 years		
	•		, ,			<b>,</b>		
0	Name, National Tarchers		40 of E6				Accommont Data: 10/20/2022	



Category : Room			Building : Linked Addition-Athletic					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	1st Floor - Case Manager	2	EA	7	10+ years		
	Power Distribution	1st Floor - Case Manager	6	EA	7	10+ years		
	Walls - Concrete Block	1st Floor - Case Manager	231	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Case Manager	308	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Engineer's Office	227	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Engineer's Office	4	SF	4	0-1 year	Damaged	
	Doors - Wood Doors inclu hw	1st Floor - Engineer's Office	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Engineer's Office	231	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - Engineer's Office	4	EA	7	6-10 years		
	Power Distribution	1st Floor - Engineer's Office	8	EA	7	10+ years		
	Walls - Concrete Block	1st Floor - Engineer's Office	734	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Gym Office	168	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Gym Office	4	SF	4	0-1 year	water damaged tile	
	Doors - Steel Doors incl hw	1st Floor - Gym Office	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Gym Office	172	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - Gym Office	3	EA	7	6-10 years		
	Power Distribution	1st Floor - Gym Office	10	EA	7	10+ years		
	Walls - Concrete Block	1st Floor - Gym Office	490	SF	7	10+ years		
	Walls - Concrete Block	1st Floor - Gym Office	4	SF	5	1-2 years	Damaged	
	Ceiling - Lay-in	1st Floor - psychologist	151	SF	7	10+ years	-	
	Ceiling - Lay-in	1st Floor - psychologist	4	SF	4	0-1 year	Water damaged tiles	
	Doors - Wood Doors inclu hw	1st Floor - psychologist	1	EA	7	10+ years	-	
	Floor - Tile	1st Floor - psychologist	155	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - psychologist	2	EA	7	6-10 years		
	Power Distribution	1st Floor - psychologist	4	EA	7	10+ years		
	Walls - Concrete Block	1st Floor - psychologist	231	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - psychologist	283	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor-Pool Office	158	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor-Pool Office	3	EA	7	10+ years		
	Floor - Terrazzo	1st Floor-Pool Office	158	SF	7	10+ years		
	Lighting - Lay-in	1st Floor-Pool Office	4	ĒA	7	6-10 years		
	Power Distribution	1st Floor-Pool Office	10	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-Pool Office	377	SF	7	10+ years		
	Ceiling - Lay-in	Main Office	524	SF	7	10+ years		
	Ceiling - Lay-in	Main Office	8	SF	4	1-2 years	Water damaged tile	
	Doors - Transom Window	Main Office	60	SF	7	10+ years	Trailer damaged inc	
	Doors - Wood Doors inclu hw	Main Office	3	EA	7	10+ years		
	Floor - Carpet	Main Office	532	SF	6	2-5 years		
	Lighting - Lay-in	Main Office	7	EA	7	6-10 years		
	Power Distribution	Main Office	6	EA	7	10+ years		
	Walls - Concrete Block	Main Office	654	SF	7	10+ years		
	Walls - Plaster/Drywall	Main Office	520	SF	7	10+ years		
	Ceiling - Lay-in	Nurse	128	SF	7	10+ years		
	Ceiling - Lay-in	Nurse	2	SF	4	0-1 year	Water damaged tile	
	Coming Lay III	110100	۷	01	7	o i yeai	Trator damaged tile	



Catego	ry : Room		Building : Linked Addition-Athletic				
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Nurse	1	EA	7	10+ years	
	Floor - Carpet	Nurse	130	SF	6	2-5 years	
	Lighting - Lay-in	Nurse	1	EA	7	6-10 years	
	Power Distribution	Nurse	4	EΑ	7	10+ years	
	Walls - Concrete Block	Nurse	134	SF	7	10+ years	
	Walls - Plaster/Drywall	Nurse	326	SF	7	10+ years	
	Ceiling - Lay-in	Teacher's Conference Room	244	SF	7	10+ years	
	Ceiling - Lay-in	Teacher's Conference Room	8	SF	4	0-1 year	Water damaged tile
	Doors - Side-lite	Teacher's Conference Room	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Conference Room	1	EA	7	10+ years	
	Floor - Tile	Teacher's Conference Room	252	SF	7	10+ years	
	Lighting - Lay-in	Teacher's Conference Room	4	EΑ	7	6-10 years	
	Power Distribution	Teacher's Conference Room	6	EA	7	10+ years	
	Walls - Concrete Block	Teacher's Conference Room	580	SF	7	10+ years	
_Gymnas	ia						
	Bleacher Seating	1st Floor	111	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	5,330	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EΑ	7	10+ years	
	Floor - Wood	1st Floor	5,330	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	1st Floor	30	EΑ	7	6-10 years	
	Sodium						
	Scoreboards	1st Floor	1	EΑ	7	10+ years	
	Storage/ Closet	1st Floor	316	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	18,122	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	2nd Floor	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	267	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	643	SF	7	10+ years	
_Locker/S	Shower Room						
	Accessories	1st Floor	765	SF	7	10+ years	
	Benches, ped mounted	1st Floor	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	765	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	765	SF	7	10+ years	
	Floor Drain	1st Floor	8	EΑ	7	10+ years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
						-	



Category : Room			Building : Linked Addition-Athletic					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Showers	1st Floor	6	EA	7	6-10 years		
	Student Lockers - Two Tier	1st Floor	50	EΑ	7	10+ years	Corrected quantity	
	Walls - Structural Glazed Tile	1st Floor	1,110	SF	7	10+ years		
	Water Closet	1st Floor	4	EA	7	10+ years		
	Accessories	1st Floor	765	SF	7	10+ years		
	Benches, ped mounted	1st Floor	50	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	765	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years		
	Floor - Terrazzo	1st Floor	765	SF	7	10+ years		
	Floor Drain	1st Floor	8	EA	7	10+ years		
	Lavatory	1st Floor	3	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years		
	Partitions	1st Floor	4	EA	7	10+ years		
	Showers	1st Floor	6	EA	7	10+ years		
	Student Lockers - Two Tier	1st Floor	50	EΑ	7	10+ years	Corrected quantity	
	Urinals	1st Floor	3	EΑ	7	10+ years	corrected quartity	
	Urinals	1st Floor	1	EΑ	5	10+ years		
	Walls - Structural Glazed Tile	1st Floor	1,110	SF	7	10+ years		
	Water Closet	1st Floor	4	EA	7	10+ years		
	Benches, ped mounted	1st Floor - In Pool Office	5	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - In Pool Office	46	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor - In Pool Office	1	EA	7	10+ years		
	Floor - Terrazzo	1st Floor - In Pool Office	46	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - In Pool Office	1	EA	7	6-10 years		
	Student Lockers - Two Tier	1st Floor - In Pool Office	6	EA	7	10+ years	Corrected quantity	
	Walls - Concrete Block	1st Floor - In Pool Office	232	SF	7	10+ years	Corrected quartity	
	Walls - Coliciete block	1st Floor - III Fool Office	232	SF	,	10+ years		
MDF_IDI								
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Finishes	1st Floor	172	SF	7	10+ years		
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Dedicated computer room cooling	
	•					·	unit	
Mechanio	cal/ Service Rooms							
	Mechanical/ Service Rooms	1st Floor	48	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	390	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	61	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	263	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	40	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	106	SF	7	10+ years		
	Janitor's Closet	2nd Floor	43	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	107	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	4,391	SF	7	10+ years		
	Medianical, Corvide Rooms	2114 1 1001	7,001	01	,	ioi youis		



Category : Room			Building : Linked Addition-Athletic					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Pool & N	atatorium							
	Accessories	1st Floor	6,189	SF	7	6-10 years		
	Bleachers Seating/Plank Seating	1st Floor	60	EA	7	10+ years	Corrected quantity	
	Ceiling - Exposed	1st Floor	6,189	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	11	EA	7	10+ years		
	Floor - Concrete	1st Floor	6,189	SF	7	10+ years		
	Lighting - Wall Mounted	1st Floor	36	EA	7	6-10 years		
	Pool Basin	1st Floor	2,000	SF	7	10+ years		
	Pool Deck	1st Floor	4,189	SF	7	10+ years		
	Pool Deck Drains	1st Floor	6	EA	7	10+ years		
	Storage/ Closet	1st Floor	440	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	12,378	SF	7	10+ years		
Restroor	n							
	Accessories	1st Floor - In Pool Office	55	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - In Pool Office	55	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor - In Pool Office	1	EA	7	10+ years		
	Floor - Terrazzo	1st Floor - In Pool Office	55	SF	7	10+ years		
	Floor Drain	1st Floor - In Pool Office	2	EA	7	10+ years		
	Lavatory	1st Floor - In Pool Office	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor - In Pool Office	1	EA	7	6-10 years		
	Showers	1st Floor - In Pool Office	1	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor - In Pool Office	290	SF	7	10+ years		
	Water Closet	1st Floor - In Pool Office	1	EA	7	10+ years		
	Accessories	1st Floor - Men's next to Elevator Mechanical Room	41	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Men's next to Elevator Mechanical Room	27	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - Men's next to Elevator Mechanical Room	14	SF	4	0-1 year	Water damaged tiles	
	Doors - Steel Doors incl hw	1st Floor - Men's next to Elevator Mechanical Room	1	EA	7	10+ years		
	Floor - Terrazzo	1st Floor - Men's next to Elevator Mechanical Room	41	SF	7	10+ years		
	Floor Drain	1st Floor - Men's next to Elevator Mechanical Room	1	EA	7	10+ years		
	Lavatory	1st Floor - Men's next to Elevator Mechanical Room	1	EA	6	10+ years		
	Lighting - Lay-in	1st Floor - Men's next to Elevator Mechanical Room	1	EA	6	6-10 years		
	Walls - Structural Glazed Tile	1st Floor - Men's next to Elevator Mechanical Room	240	SF	7	10+ years		
	Water Closet	1st Floor - Men's next to Elevator Mechanical Room	1	EA	7	10+ years		



Catego	Category : Room			uilding	: Linked	Addition-Athl	etic
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor - Next to Elevator by	44	SF	7	10+ years	
		Daycare					
	Ceiling - Lay-in	1st Floor - Next to Elevator by	44	SF	7	10+ years	
		Daycare	_		_		
	Doors - Steel Doors incl hw	1st Floor - Next to Elevator by	1	EA	7	10+ years	
		Daycare			_		
	Floor - Terrazzo	1st Floor - Next to Elevator by	44	SF	7	10+ years	
	Elana Dania	Daycare	4	_^	7	40	
	Floor Drain	1st Floor - Next to Elevator by	1	EA	7	10+ years	
	Lavatani	Daycare	4	EA	7	10	
	Lavatory	1st Floor - Next to Elevator by	1	EA	7	10+ years	
	Lighting - Lay-in	Daycare 1st Floor - Next to Elevator by	1	EA	7	6-10 years	
	Lighting - Lay-in	Daycare	'	EA	,	0-10 years	
	Walls - Structural Glazed Tile	1st Floor - Next to Elevator by	245	SF	7	10+ years	
	Walls - Structural Glazed Tile	Daycare	240	OI.	,	10+ years	
	Water Closet	1st Floor - Next to Elevator by	1	EA	7	10+ years	
	Water Gloset	Daycare		L/\	,	101 years	
	Accessories	1st Floor - Women's next to MDF	41	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Women's next to MDF	41	SF	7	10+ years	Corrected quantity
	Doors - Steel Doors incl hw	1st Floor - Women's next to MDF	1	EA	7	10+ years	Corrected quartity
	Floor - Terrazzo	1st Floor - Women's next to MDF	41	SF	7	10+ years	
	Floor Drain	1st Floor - Women's next to MDF	1	EA	7	10+ years	
	Lavatory	1st Floor - Women's next to MDF	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor - Women's next to MDF	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor - Women's next to MDF	240	SF	7	10+ years	
	Water Closet	1st Floor - Women's next to MDF	240 1	EA			
				SF	7	10+ years	
	Accessories	2nd Floor - Near Fan Room	44		7	10+ years	
	Ceiling - Lay-in	2nd Floor - Near Fan Room	44	SF	7	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor - Near Fan Room	1	EΑ	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Near Fan Room		EA	7	10+ years	
	Floor - Terrazzo	2nd Floor - Near Fan Room	44	SF	7	10+ years	
	Floor Drain	2nd Floor - Near Fan Room	1	EA	7	10+ years	
	Lavatory	2nd Floor - Near Fan Room	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - Near Fan Room	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Near Fan Room	250	SF	7	10+ years	
	Water Closet	2nd Floor - Near Fan Room	1	EA	7	10+ years	
	Accessories	2nd Floor - Next to Elevator by Daycare	88	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - Next to Elevator by Daycare	88	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor - Next to Elevator by Daycare	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor - Next to Elevator by	88	SF	7	10+ years	



Category : Room			Building : Linked Addition-Athletic						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		Daycare			_				
	Floor Drain	2nd Floor - Next to Elevator by	1	EA	7	10+ years			
	Lavatani	Daycare	4	EA	7	40			
	Lavatory	2nd Floor - Next to Elevator by	1	EA	7	10+ years			
	Lighting Lovin	Daycare 2nd Floor - Next to Elevator by	1	EA	7	10 . vooro			
	Lighting - Lay-in	Daycare	ı	EA	,	10+ years			
	Walls - Structural Glazed Tile	2nd Floor - Next to Elevator by	468	SF	7	10+ years			
	Walls - Structural Glazed Tile	Daycare	400	Oi	,	10+ years			
	Water Closet	2nd Floor - Next to Elevator by	1	EA	7	10+ years			
	valor olosot	Daycare	•		•	To Tyouro			
	Accessories	Room 1	38	SF	7	10+ years			
	Ceiling - Lay-in	Room 1	38	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 1	1	EA	7	10+ years			
	Floor - Tile	Room 1	38	SF	7	10+ years			
	Floor Drain	Room 1	1	ĒA	7	10+ years			
	Lavatory	Room 1	1	EA	7	10+ years			
	Lighting - Lay-in	Room 1	1	EA	7	6-10 years			
	Walls - Concrete Block	Room 1	214	SF	7	10+ years			
	Water Closet	Room 1	1	EA	7	10+ years			
	Accessories	Room 2	34	SF	7	10+ years			
	Ceiling - Lay-in	Room 2	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 2	1	EA	7	10+ years			
	Floor - Tile	Room 2	34	SF	7	6-10 years			
	Floor Drain	Room 2	1	EA	7	10+ years			
	Lavatory	Room 2	1	EA	7	10+ years			
	Lighting - Lay-in	Room 2	1	EA	7	6-10 years			
	Walls - Concrete Block	Room 2	131	SF	7	10+ years			
	Water Closet	Room 2	1	EA	4	0-1 year	Not working		
	Accessories	Room 3	38	SF	7	10+ years			
	Ceiling - Lay-in	Room 3	38	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 3	1	EA	7	10+ years			
	Floor - Tile	Room 3	38	SF	7	6-10 years			
	Floor Drain	Room 3	1	EA	7	10+ years			
	Lavatory	Room 3	1	EA	7	10+ years			
	Lighting - Lay-in	Room 3	1	EA	7	6-10 years			
	Walls - Concrete Block	Room 3	131	SF	7	10+ years			
	Water Closet	Room 3	1	EA	7	10+ years			
	Accessories	Room 4	34	SF	7	10+ years			
	Ceiling - Lay-in	Room 4	30	SF	7	10+ years			
	Ceiling - Lay-in	Room 4	4	SF	4	1-2 years	Damaged		
	Doors - Wood Doors inclu hw	Room 4	1	EA	7	10+ years	<del></del>		
	Floor - Tile	Room 4	34	SF	7	6-10 years			
	Floor Drain	Room 4	1	EA	7	10+ years			



Catego	ry : Room	Building : Linked Addition-Athletic					
			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Room 4	1	EA	7	10+ years	
	Lighting - Lay-in	Room 4	1	EA	7	6-10 years	
	Walls - Concrete Block	Room 4	214	SF	7	10+ years	
	Water Closet	Room 4	1	EA	7	10+ years	
	Accessories	Room 5	34	SF	7	10+ years	
	Ceiling - Lay-in	Room 5	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 5	1	EA	7	10+ years	
	Floor - Tile	Room 5	34	SF	7	10+ years	
	Floor Drain	Room 5	1	EA	7	10+ years	
	Lavatory	Room 5	1	EA	7	10+ years	
	Lighting - Lay-in	Room 5	1	EA	7	6-10 years	
	Walls - Concrete Block	Room 5	131	SF	7	10+ years	
	Water Closet	Room 5	2	EA	7	10+ years	
	Accessories	Room 6	34	SF	7	10+ years	
	Ceiling - Lay-in	Room 6	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 6	1	EA	7	10+ years	
	Floor - Tile	Room 6	34	SF	7	10+ years	
	Floor Drain	Room 6	1	EA	7	10+ years	
	Lavatory	Room 6	1	EA	7	10+ years	
	Lighting - Lay-in	Room 6	1	EA	7	10+ years	
	Walls - Concrete Block	Room 6	214	SF	7	10+ years	
	Water Closet	Room 6	1	EA	7	10+ years	
	Accessories	Room 7	34	SF	7	10+ years	
	Ceiling - Lay-in	Room 7	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 7	1	EA	7	10+ years	
	Floor - Tile	Room 7	34	SF	7	10+ years	
	Floor Drain	Room 7	1	EA	7	10+ years	
	Lavatory	Room 7	1	EA	7	10+ years	
	Lighting - Lay-in	Room 7	1	EA	7	6-10 years	
	Walls - Concrete Block	Room 7	131	SF	7	10+ years	
	Water Closet	Room 7	2	EA	7	10+ years	
	Accessories	Room 8B	38	SF	7	10+ years	
	Ceiling - Lay-in	Room 8B	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 8B	1	ĒΑ	7	10+ years	
	Floor - Tile	Room 8B	38	SF	7	10+ years	
	Floor Drain	Room 8B	1	ĒΑ	7	10+ years	
	Lavatory	Room 8B	1	EA	7	10+ years	
	Lighting - Lay-in	Room 8B	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 8B	214	SF	7	10+ years	
	Water Closet	Room 8B	1	EA	7	10+ years	
		1.00 02	•	_, .	•	10. 30010	



Category : Classroom			В	uilding	: Linked	d Addition-Athl	etic
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #1 (Pre School)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	874	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	874	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,222	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	159	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #2 (Store Room)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	907	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	10+ years	
	Floor - Tile	1st Floor	907	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,279	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	159	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #3 (Pre School)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	874	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	874	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,222	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	m #4 (Pre School)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	984	SF	7	10+ years	
	Doors - Side-lite	1st Floor	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	984	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	



Catego	ry : Classroom	В	Building : Linked Addition-Athletic						
		Recommend Item - Type Location Quantity UOM Rank Replacement Comments							
Group							Comments		
	Walls - Concrete Block	1st Floor	1,329	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	159	SF	7	10+ years			
	Work Sink	1st Floor	2	EA	7	10+ years			
Classroo	m #5 (Pre School)								
	Casework	2nd Floor	18	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	892	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	 1	EΑ	7	10+ years			
	Floor - Tile	2nd Floor	892	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	785	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years			
	Work Sink	2nd Floor	2 2	EA	7	10+ years			
	Wein Gillin	2110 1 1001	_		•	io. you.o			
lassroc	m #6 (Pre School)	0.151	40			40			
	Casework	2nd Floor	18	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	892	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	892	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	785	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years			
	Work Sink	2nd Floor	2	EA	7	10+ years			
Classroc	m #7 (Pre School)								
	Casework	2nd Floor	18	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	892	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	21	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	892	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	10+ years			
	Marker Board	2nd Floor	10	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	629	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	150	SF	7	10+ years			
	Work Sink	2nd Floor	2	EA	7	10+ years			
lassroo	m #8A (Kindergarten)								
2.400100	Casework	2nd Floor	10	LF	7	10+ years			
		2nd Floor 2nd Floor	875	SF	7	•			
	Ceiling - Lay-in	ZIIU [100]	6/5	ЭF	,	10+ years			



omments
omments
:
omments
amaged
or



Catego	ry : Interior		В	uilding	: Linked	d Addition-Athl	letic
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor-Bridge Corridor	1,430	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Bridge Corridor	4	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Bridge Corridor	1,430	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor-Bridge Corridor	10	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Bridge Corridor	452	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Daycare Corridor	1,033	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Daycare Corridor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor-Daycare Corridor	2	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor-Daycare Corridor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Daycare Corridor	1,043	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor-Daycare Corridor	7	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor-Daycare Corridor	30	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Daycare Corridor	12,516	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Main Athletic Corridor	728	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Main Athletic Corridor	10	SF	5	1-2 years	Damaged
	Doors - Steel Doors incl hw	2nd Floor-Main Athletic Corridor	2	EA	7	10+ years	<b>G</b>
	Floor - Terrazzo	2nd Floor-Main Athletic Corridor	738	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor-Main Athletic Corridor	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Main Athletic Corridor	7,011	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Natatorium Corridor	768	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor-Natatorium Corridor	196	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Natatorium Corridor	4	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Natatorium Corridor	988	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor-Natatorium Corridor	28	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Natatorium Corridor	1,690	SF	7	10+ years	
Safety							
Curcy	Security Cameras	Entire Building	5	EA	7	6-10 years	
	Security Cameras	Entire Building	19	EΑ	7	6-10 years	
	Security Cameras	Exterior	10	EA	7	10+ years	
	occurry carrieras	Exterior	10	L/ \	,	101 years	
Stairs							
	Ceiling - Plaster/Drywall	Stair 2C	672	SF	7	10+ years	
	Floor - Terrazzo	Stair 2C	582	SF	7	10+ years	
	Handrails	Stair 2C	87	LF	7	10+ years	
	Lighting - Lay-in	Stair 2C	18	EA	7	10+ years	
	Stairs - Terrazzo	Stair 2C	37	LF	7	10+ years	
	Walls - Structural Glazed Tile	Stair 2C	9,744	SF	7	10+ years	
	Ceiling - Lay-in	Stair CA5	751	SF	7	10+ years	
	Floor - Terrazzo	Stair CA5	751	SF	7	10+ years	
	Handrails	Stair CA5	74	LF	7	10+ years	
	Lighting - Lay-in	Stair CA5	12	EA	7	10+ years	
	Stairs - Terrazzo	Stair CA5	37	LF	7	10+ years	
	Walls - Structural Glazed Tile	Stair CA5	6,244	SF	7	10+ years	
						•	



Category : Interior Building : Linked Addition-Athletic										
				Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Exposed	Stair CA6/CA3	311	SF	7	10+ years				
	Floor - Concrete	Stair CA6/CA3	370	SF	7	10+ years				
	Handrails	Stair CA6/CA3	87	LF	7	10+ years				
	Lighting - Wall Mounted	Stair CA6/CA3	10	EA	7	10+ years				
	Stairs - Concrete	Stair CA6/CA3	41	LF	7	10+ years				
	Walls - Concrete Block	Stair CA6/CA3	4,976	SF	7	10+ years				
Vertical (	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years				

Campus Name: National Teachers Page : 52 of 56 Assessment Date: 10/30/2023



Category : Site	Building : Site
-----------------	-----------------

Juliogo	iy. Oile			unung	· Oite	December	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Athletic_							
	Surface - Asphalt	Asphalt Track	16,612	SF	7	10+ years	
			300	SF	5		
			. 4	EA			
	3 * 3	Track				, , , , ,	
	Surface - Synthetic	Turf Football and Soccer Field with	109.760	SF	7	6-10 years	
						5 15 J 5 3 11 5	
_Civil/Dra	inage						
		Entire Site	11	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	6	10+ years	
	· ·						
_Fencing							
	Fencing - New Standard Ornamental	Entire Site	1,929	LF	6	10+ years	
_Landsca	pe						
	Benches		5	EA	6	10+ years	
	Irrigation	Entire Site		SF	6	10+ years	
		Entire Site			6		
	Landscape - Hardscape- Concrete	Entire Site			6	10+ years	
		Entire Site	1,494	SF	6		
	Lighting - Pole Mounted	Entire Site	5	EA	6	2-5 years	Not previously assessed
	Parkway trees	Entire Site	11		6	10+ years	
	Planting Beds/ Area	Entire Site	7,543		6	10+ years	
	Retaining Wall - Concrete	Entire Site	372		6	10+ years	
	Retaining Wall - Masonry	Entire Site	900	SF	6	10+ years	
	Trash Receptacles	Entire Site	6	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	3,978	SF	6	10+ years	
Surface - Asphalt			Described recollect to the 19				
							Recalculated quantity
							Drainage addressed and patched
					_		Patched holes
						,	
	Vehicular Screening	Southwest and Southeast	40	LF	6	10+ years	



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Vehicular Screening	Southwest and Southeast	160	LF	6	10+ years	
Playgrou	ınd						
	Equipment - School Age 5-12	NE site	1	EA	6	10+ years	
	Surface - Poured Surface	NE site	4,377	SF	6	2-5 years	
	Equipment - Pre K 3-5	NW site	1	EΑ	6	10+ years	
	Surface - Poured Surface	NW site	1,652	SF	6	2-5 years	
_Sidewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	2,166	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	125	LF	4	0-1 year	Deteriorated concrete, potholes
	Sidewalks - Perimeter Sidewalks	Entire Site	9,875	SF	6	10+ years	Recalculated quantity
Signage							
	Flag Pole - Flag Pole	North	2	EA	6	10+ years	
	Monument - Sign	North	1	EA	6	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





**Classroom Summary** 

Classiconi Summary			_	Floor Plan	_	Glazed	Operable		
0	Internal ad Harma	Barra Laradian	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Art Room	44b Floor	400	400	4.050	796	4	l N	N.
Art Room		4th Floor	400		1,250		4	N	N
Kindergarten	Kindergarten	1st Floor	108	NA NA	1,215	198	18	Y	N
Kindergarten	Kindergarten	1st Floor	110	NA	1,215	198	18	Y	N
Kindergarten	Kindergarten	1st Floor	112	NA	1,215	198	18	Y	N
Multi Purpose Room	Regular Classroom	2nd Floor	203	NA	870	108	4	Y	N
Multi Purpose Room	Regular Classroom	4th Floor	414	NA	830	140	7	Y	N
Music Room	Music Room	4th Floor	401	401	1,610	678	6	N	N
Other Instructional Use	Computer Lab	3rd Floor	306	NA	1,204	231	36	N	N
			Compter						
		0.15	Lab		4 4 4 0	400			
Other Instructional Use	Other Instructional Use	2nd Floor	202	Media Room	1,142	120	8	N	N
Pre School	Kindergarten	1st Floor	106	NA	1,215	198	18	Υ	N
Regular Classroom	Kindergarten	1st Floor	111	NA	1,215	198	18	Υ	Y
Regular Classroom	Kindergarten	1st Floor	113	NA	1,215	198	18	Υ	N
Regular Classroom	Office	4th Floor	405	NA	1,020	211	6	N	N
Regular Classroom	Regular Classroom	1st Floor	109	NA	1,114	198	18	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	NA	870	108	4	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	NA	870	108	4	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	NA	870	108	4	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	305	NA	920	140	7	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	NA	1,385	211	10	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	NA	870	140	7	Y	N
Regular Classroom	Regular Classroom	3rd Floor	311	NA	870	140	7	Y	N
Regular Classroom	Regular Classroom	3rd Floor	312	NA	870	140	7	Y	N
Regular Classroom	Regular Classroom	3rd Floor	314	NA	870	140	7	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	315	NA	870	140	7	Υ	N
Regular Classroom	Regular Classroom	4th Floor	401B	NA	830	140	7	Υ	N
Regular Classroom	Regular Classroom	4th Floor	404	NA	830	140	7	Y	N
Regular Classroom	Regular Classroom	4th Floor	406	NA	830	140	7	Y	N
Regular Classroom	Regular Classroom	4th Floor	408	NA	830	140	7	Y	N
Regular Classroom	Regular Classroom	4th Floor	409	NA	830	140	7	Y	N
Regular Classroom	Regular Classroom	4th Floor	410	NA	830	140	7	Y	N





**Classroom Summary** 

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	4th Floor	411	NA	830	140	7	Υ	N
Regular Classroom	Regular Classroom	4th Floor	412	NA	830	140	7	Υ	N
Regular Classroom	Regular Classroom	4th Floor	413	NA	830	140	7	Υ	N
Science Classroom	Science Classroom	3rd Floor	301	NA	1,445	210	10	Υ	N
Science Classroom	Science Classroom	3rd Floor	303	NA	1,345	140	7	Y	N
Store Room	Regular Classroom	3rd Floor	313	NA	870	140	7	Υ	N
Vacant	Regular Classroom	2nd Floor	207	NA	1,050	162	6	Y	N
Vacant	Regular Classroom	3rd Floor	309	NA	1,020	211	6	Υ	N

Kindergarten	Multi Purpose Room	2nd Floor	8A	NA	875	140	1	Y	N
Multi Purpose Room	Multi Purpose Room	2nd Floor	8B	NA	875	140	1	Υ	N
Pre School	Pre School	1st Floor	1	C151	874	156	75	Y	N
Pre School	Pre School	1st Floor	3	C124	874	156	1	Y	N
Pre School	Pre School	1st Floor	4	C134	984	156	1	Y	N
Pre School	Pre School	2nd Floor	5	C213	892	140	1	Y	N
Pre School	Pre School	2nd Floor	6	C213	892	140	1	Y	N
Pre School	Pre School	2nd Floor	7	C221	892	140	7	Y	N
Store Room	Pre School	1st Floor	2	C133	907	156	1	Υ	N