

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1996	2	63,900
Campus Total			63,900

GroupItem - TypeLocationQuantityUOMRankRecommend ReplacementCommentsEntranceEntranceEntrance Control - Audio and Video#1 E1EA710+ yearsExterior Doors - Exterior FRP Door#1 E2EA66-10 yearsExterior Doors - Side lite#1 E6EA610+ yearsExterior Doors - Side lite#1 E6EA66-10 yearsExterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
EntranceEntrance Control - Audio and Video#1 E1EA710+ yearsExterior Doors - Exterior FRP Door#1 E2EA66-10 yearsExterior Doors - Side lite#1 E6EA610+ yearsExterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Entrance Control - Audio and Video#1 E1EA710+ yearsExterior Doors - Exterior FRP Door#1 E2EA66-10 yearsExterior Doors - Side lite#1 E6EA610+ yearsExterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA66-10 yearsExterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	•
Exterior Doors - Exterior FRP Door#1 E2EA66-10 yearsExterior Doors - Side lite#1 E6EA610+ yearsExterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA66-10 yearsExterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA610+ yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Side lite#1 E6EA610+ yearsExterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA610+ yearsExterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA66-10 yearsExterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Exterior FRP Door#10 NW1EA66-10 yearsExterior Doors - Transom Lite#10 NW1EA610+ yearsExterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA610+ yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Transom Lite#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Transom Lite#10 NW1EA610+ yearsExterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA610+ yearsExterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Exterior FRP Door#2 N2EA66-10 yearsExterior Doors - Transom Lite#2 N2EA610+ yearsExterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Transom Lite#2 N2EA610+ yearsExterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Exterior FRP Door#3 S2EA66-10 yearsExterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Transom Lite#3 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Exterior FRP Door#3.1 S2EA66-10 yearsExterior Doors - Exterior FRP Door#3.2 S1EA610+ years	
Exterior Doors - Exterior FRP Door #3.2 S 1 EA 6 10+ years	
Exterior Doors - Overhead Rolling/ Garage #3.3 OHD S 1 EA 6 6-10 years	
Door	
Entrance Control - Audio and Video #4 SW 1 EA 7 6-10 years	
Exterior Doors - Exterior FRP Door #4 SW 2 EA 6 6-10 years	
Exterior Doors - Transom Lite #4 SW 2 EA 7 10+ years	
Exterior Doors - Exterior FRP Door #5 W 1 EA 6 10+ years	
Exterior Doors - Exterior FRP Door #6 N 1 EA 6 6-10 years	
Exterior Doors - Transom Lite #6 N 1 EA 6 10+ years	
Exterior Doors - Exterior FRP Door #7 N 1 EA 6 6-10 years	
Exterior Doors - Transom Lite #7 N 1 EA 6 10+ years	
Exterior Doors - Exterior FRP Door #8 NW 1 EA 6 6-10 years	
Exterior Doors - Transom Lite #8 NW 1 EA 6 6-10 years	
Exterior Doors - Exterior FRP Door #9 NW 1 EA 6 6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#9 NW	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	11-Roof 7	1	EA	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	1,000	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	400	SF	6	1-2 years	North and south stairs show signs of
		g		•	U U)	settlement. Cracks at the walls.
	Superstructure - Steel	Entire Building	63,500	SF	7	10+ years	
_Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	22	EA	5	2-5 years	
Roof Sy	Coping - Metal	#2	90	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#2	90 10	LF	6	10+ years	
						•	
	Parapet - Parapet < 16" Height	#2	67	LF	6	10+ years	
	Roof - Modified Bitumen	#2	507	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#2	507	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#3	8	LF	6	10+ years	
	Roof - Metal			SF			
		#3	616		6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#3	616	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#4	20	LF	6	10+ years	
	Roof - Metal	#4	1,564	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#4	1,564	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#5	12	LF	6	10+ years	
	Roof - Metal	#5 #5	625	SF	-		
		-			6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#5	625	SF	7	10+ years	
	Downspouts - Exterior Downspouts	#6	26	LF	6	6-10 years	
	Roof - Metal	#6	790	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	#6	790	SF	7	10+ years	
	Concrete Topping	#0	790	ЪГ	1	10+ years	
	Coping - Metal	#7	66	LF	6	10+ years	
	Downspouts - Interior Downspouts	#7	52	LF	6	6-10 years	
	Parapet - 16" - 30" Height	#7	52 66	LF	7	10+ years	
				SF			
	Roof - Modified Bitumen	#7 	826		6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#7	826	SF	7	10+ years	
	Coping - Metal	#8	58	LF	6	10+ years	
	Downspouts - Interior Downspouts	#8	26	LF	6	6-10 years	
		πο	20		0	0-10 years	



Catego	ry : Exterior		В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet < 16" Height	#8	58	LF	6	10+ years	
	Roof - Modified Bitumen	#8	815	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	#8	815	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	30	LF	6	10+ years	
	Coping - Metal	Main Roof	985	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	572	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	985	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	29,328	SF	6	6-10 years	
	Roof Hatch - Metal	Main Roof	[′] 1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Main Roof	29,328	SF	7	10+ years	
	Concrete Topping					-	
Walls							
	Exterior Walls - Brick	Entire Building	23,940	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	484	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Open joints
	Exterior Walls - Brick	Entire Building	40	SF	4	1-2 years	Wall crack where control joint has been covered by mosaic
	Exterior Walls - Brick	Entire Building	20	SF	3	0-1 year	Large crack above windows
	Exterior Walls - Stone-Cast	Entire Building	180	SF	6	10+ years	
Windows							
	Clerestory - Glass Double-Pane	Entire Building	588	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,070	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	30	SF	4	1-2 years	Dented
	Lintels - Steel	Entire Building	830	LF	7	10+ years	
	Lintels - Stone	Entire Building	9	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,275	SF	4	0-1 year	Windows falling out of frames. Many
	•	5					windows are screwed shut for safety
							concerns for this reason. Most
							teachers do not open their windows
							for fear of windows falling on them.
							Balancers is not working.
							Consolidated numbers.
Catego	ry : Electrical		R	uilding	• Main		

Calegory . Electrical	Dullully . Mall					
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System						
Automatic Transfer Switch	1st Floor	1	EA	6	6-10 years	
Exit Signs - Corridors and Stairs	Entire Building	30	EA	6	6-10 years	



Categor	y : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	63,900	SF	5	6-10 years	Exterior only
	Security System - Intrusion Detection	Entire Building	63,900	SF	6	2-5 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,925	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,724	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,270	SF	6	10+ years	
lain Serv	vice						
	Independent Electrical Service for emergency power	1st Floor	1	EA	7	10+ years	Serves ATS
	Independent Electrical Service for emergency power	1st Floor	1	EA	7	10+ years	For fire equipment
	Main Electrical Service - 1200 A 277/480/3PH	1st Floor	1	EA	7	10+ years	
	PA System	Entire Building	63,900	SF	6	10+ years	Replaced new in 2022
ower Dis	stribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	PP-K2 HP-1 New A Gary 1 (RP-M) i MDF room Quantity updated to refle observed conditions
	Lighting and Power Panels - Above 100 A	Entire Building	15	EA	7	10+ years	Quantity updated to reflect observed conditions
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel in first floor. Electrica closet has open sockets presenting live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	10+ years	MSP-1 (2) MSP-2 (2)
	Transformers - 277/480 - 120/208	Entire Building	7	EA	6	10+ years	
	Transformers - 277/480 - 120/240	Entire Building	1	EA	6	10+ years	West Mech room
	Transformers - 277/480 - 120/240	Entire Building	4	EA	6	10+ years	460 Delta - 460Y/266
ategor	y : Fire Protection		В	uilding	: Main		
-	-			Ū		Recommend	

oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
e Aları	n						
	Fire ALarm Anunciator	Entire Building	1	EA	6	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	63,900	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	63,900	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	

Pump Room Assembly



Catego	ry : Fire Protection		В	uilding	: Main		0 S Lawndale AVENUE, Chicago, IL 60623
2						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Pump - 25-50 hp	1st Floor	1	EA	6	6-10 years	
	Jockey Pump	1st Floor	1	EA	6	6-10 years	
Sprinklo	r Svstem						
Sphinkle	Sprinkler Heads	Entire Building	63,900	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	63,900	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	63,900	SF	6	10+ years	
Cotogo				uilding	Main	- j	
Calego	ry : Mechanical		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc							
	Condensing Unit- Roof Mounted - 11-20 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	7	10+ years	Replaced new since last assessment 2023
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	5	6-10 years	Unit 2- Compressor replaced in 2023
	Condensing Unit- Roof Mounted - Greater than 50 tons	Roof	1	EA	5	6-10 years	Unit 1- Compressor replaced in 2023
Air Hand	lling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 12001-20000 cfm	1st Floor - AHU1	1	EA	5	6-10 years	
	Air Intake	1st Floor - AHU1	1	EA	6	6-10 years	Shared with AHU-2
	VAV Box	1st Floor - AHU1	9	EA	6	6-10 years	Not accessible during time of assessment, mounted above acoustic tile ceiling
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	2nd Floor - AHU2	1	EA	6	6-10 years	
	Air Intake	2nd Floor - AHU2	2	EA	6	6-10 years	Shared with AHU-1
	VAV Box	2nd Floor - AHU2	9	EA	6	6-10 years	Not accessible during time of
			0	L/	0	o to years	assessment, mounted above acoustic tile ceiling
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	26	EA	5	6-10 years	Not accessible during time of assessment, mounted above acoustic tile ceiling. All fan power boxes having trouble communicating with BAS. Manual control.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils -	Gym - AHU4	1	EA	5	6-10 years	Serves gymnasium



Catego	ry : Mechanical		В	uilding	: Main		o o Lawildaic Avenue, officago, le 00025
_			• •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Less than 4000 cfm		4	Ξ.	0	0.40	
	Air Intake	Gym - AHU4	1	EA	6	6-10 years	Common air intake with AHU-3
	VAV Box	Gym - AHU4	1	EA	3	1-2 years	Nonfunctional
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Lower Roof	1	EA	5	2-5 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - Less than 4000 cfm	Lunchroom - AHU3	1	EA	5	6-10 years	
	Air Intake	Lunchroom - AHU3	1	EA	6	6-10 years	Common air intake with AHU-4
	VAV Box	Lunchroom - AHU3	2	EA	6	6-10 years	Not accessible during time of
							assessment, mounted above acoustic tile ceiling
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	6	10+ years	Quantity updated to reflect observed conditions
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Hot Water Pump	Boiler Room	1	EA	6	6-10 years	Serves B-2
	Hot Water Pump	Boiler Room	1	EA	6	6-10 years	Serves B-1
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	6-10 years	B-1, factory installed controls
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	1	EA	5	6-10 years	B-2, upgrade to Honeywell controls
	Water Fill System	Boiler Room	1	EA	6	6-10 years	
Heating	Devices						
U	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	6	6-10 years	
	Fin Tube - Hot Water	Entire Building	294	LF	6	10+ years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - 10 - 20 HP	Entire Building	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Entire Building	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Serves AHU-4
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Serves AHU-1



	Schools					300	0 S Lawndale AVENUE, Chicago, IL 60623
Catego	ry : Mechanical		B	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Entire Building	1	EA	6	6-10 years	Serves AHU-3
	Hydronic Supply and Return - Copper	Entire Building	500	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	7	10+ years	
Tempera	ature Control						
·	DDC System	Entire Building	63,900	SF	5	6-10 years	Software graphics updated, system not communicating properly
	Electric Thermostat	Entire Building	5	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	46	EA	7	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Quantity updated to reflect observed capacities
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	5	EA	6	6-10 years	Quantity updated to reflect observe capacities
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	Exhaust return ductwork for air handler 1 and 2
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	2nd Floor	2	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	63,900	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	63,900	SF	6	10+ years	
	Sanitary Piping	Entire Building	63,900	SF	7	10+ years	



Category : Plumbing Building : Main Recommend UOM Group Quantity Item - Type Location Rank **Replacement** Comments Storm Piping Entire Building 63,900 10+ years SF 7 Vent Piping Entire Building 63,900 SF 7 10+ years Pumps Pumps - Domestic Booster Pump-Duplex Entire Building ΕA 6-10 years 1 6 Pumps - Sump-Simplex Entire Building 1 ΕA 6 6-10 years Beneath elevator, not accessible at time of assessment

Catego	ry : Room				: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices	Location	Quantity	0011	Kank	Replacement	comments
	Ceiling - Lay-in	1st Floor-100 Counselor's Office	380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-100 Counselor's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-100 Counselor's Office	380	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-100 Counselor's Office	6	EA	7	6-10 years	
	Power Distribution	1st Floor-100 Counselor's Office	24	EA	7	10+ years	
	Storage/ Closet	1st Floor-100 Counselor's Office	2	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-100 Counselor's Office	265	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-100 Counselor's Office	465	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-101 Faculty Lounge	380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-101 Faculty Lounge	1	EA	7	10+ years	
	Floor - Tile	1st Floor-101 Faculty Lounge	380	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-101 Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	1st Floor-101 Faculty Lounge	24	EA	7	10+ years	
	Storage/ Closet	1st Floor-101 Faculty Lounge	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-101 Faculty Lounge	265	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-101 Faculty Lounge	465	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-103 Office, Main Office Suite	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-103 Office, Main Office Suite	1	EA	7	10+ years	
	Floor - Tile	1st Floor-103 Office, Main Office Suite	140	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-103 Office, Main Office Suite	2	EA	7	6-10 years	
	Power Distribution	1st Floor-103 Office, Main Office Suite	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-103 Office, Main Office Suite	86	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-103 Office, Main Office Suite	340	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor-104 Main Office Suite	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-104 Main Office Suite	1	EA	7	10+ years	



Group

Category : Room **Building : Main** Recommend Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile 1st Floor-104 Main Office Suite 140 SF 6 10+ vears 2 ΕA 7 Lighting - Lay-in 1st Floor-104 Main Office Suite 10+ years Power Distribution 1st Floor-104 Main Office Suite 8 EΑ 7 10+ years SF 7 Walls - Concrete Block 1st Floor-104 Main Office Suite 86 10+ years SF Walls - Plaster/Drywall 1st Floor-104 Main Office Suite 340 6 10+ years SF 7 Ceiling - Lay-in 1st Floor-105 Principal's Office 140 10+ years Doors - Wood Doors inclu hw 1st Floor-105 Principal's Office ΕA 7 1 10+ years SF Floor - Tile 1st Floor-105 Principal's Office 140 6 10+ years Lighting - Lay-in 1st Floor-105 Principal's Office 2 EΑ 7 6-10 vears Power Distribution 1st Floor-105 Principal's Office 8 EΑ 7 10+ years Walls - Concrete Block 1st Floor-105 Principal's Office 86 SF 7 10+ vears Walls - Plaster/Drywall 1st Floor-105 Principal's Office 340 SF 6 10+ years 1st Floor-109 Nurse's Office SF 7 Ceiling - Lay-in 160 10+ years ΕA 7 Doors - Wood Doors inclu hw 1st Floor-109 Nurse's Office 2 10+ years Floor - Tile SF 1st Floor-109 Nurse's Office 160 6 10+ years FΑ 7 Lighting - Lay-in 1st Floor-109 Nurse's Office 2 6-10 years 7 Power Distribution 1st Floor-109 Nurse's Office 8 EΑ 10+ vears SF Walls - Concrete Block 1st Floor-109 Nurse's Office 155 7 10+ years SF Walls - Plaster/Drvwall 1st Floor-109 Nurse's Office 360 6 10+ vears Work SInk 1st Floor-109 Nurse's Office 1 EΑ 7 10+ years Ceiling - Lay-in 1st Floor-110 Office, Main Office 175 SF 7 10+ years Suite Doors - Wood Doors inclu hw 1st Floor-110 Office, Main Office 2 EA 7 10+ years Suite Floor - Tile 1st Floor-110 Office, Main Office SF 175 6 10+ years Suite Lighting - Lay-in 1st Floor-110 Office, Main Office 3 EA 7 6-10 years Suite **Power Distribution** 1st Floor-110 Office, Main Office 8 EΑ 7 10+ years Suite SF Walls - Concrete Block 1st Floor-110 Office. Main Office 155 7 10+ years Suite SF Walls - Plaster/Drywall 1st Floor-110 Office. Main Office 340 6 10+ years Suite SF Ceiling - Lay-in 1st Floor-111 Copy Room 220 7 10+ years Doors - Wood Doors inclu hw ΕA 7 1st Floor-111 Copy Room 10+ years 1 SF Floor - Tile 1st Floor-111 Copy Room 220 6 10+ years 1st Floor-111 Copy Room ΕA 7 6-10 years Lighting - Lay-in 3 Power Distribution 1st Floor-111 Copy Room 6 EΑ 7 10+ years SF Walls - Concrete Block 1st Floor-111 Copy Room 180 7 10+ vears SF Walls - Plaster/Drywall 1st Floor-111 Copy Room 380 6 10+ years 1st Floor-111 Copy Room FΑ 7 Work SInk 10+ vears 1 Ceiling - Lay-in 1st Floor-Dietician Office 80 SF 7 10+ years Doors - Side-lite SF 1st Floor-Dietician Office 7

24

10+ years



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor-Dietician Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Dietician Office	80	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Dietician Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Dietician Office	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Dietician Office	320	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Engineer's Office	112	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Engineer's Office	8	SF	5	1-2 years	
	Doors - Side-lite	1st Floor-Engineer's Office	15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Engineer's Office	120	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Engineer's Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Engineer's Office	10	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Engineer's Office	410	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Gym Teacher's Office	170	SF	7	10+ years	
	Doors - Side-lite	1st Floor-Gym Teacher's Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Gym Teacher's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Gym Teacher's Office	170	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Gym Teacher's Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Gym Teacher's Office	10	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Gym Teacher's Office	490	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-Main Office	825	SF	7	10+ years	
	Doors - Side-lite	1st Floor-Main Office	50	SF	7	10+ years	
	Doors - Transom Window	1st Floor-Main Office	5	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-Main Office	825	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-Main Office	11	EA	7	6-10 years	
	Power Distribution	1st Floor-Main Office	10	EA	7	10+ years	
	Storage/ Closet	1st Floor-Main Office	15	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Main Office	350	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Main Office	1,420	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor - 220 Library Workroom	295	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - 220 Library Workroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor - 220 Library Workroom	295	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor - 220 Library Workroom	3	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor - 220 Library Workroom	1	EA	5	1-2 years	Light strobing
	Power Distribution	2nd Floor - 220 Library Workroom	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - 220 Library Workroom	180	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - 220 Library Workroom	530	SF	6	10+ years	
	Work SInk	2nd Floor - 220 Library Workroom	1	EA	7	6-10 years	
Gymnas	ia						
-	Bleacher Seating	1st Floor-151 Gym	3	EA	7	10+ years	
	Ceiling - Exposed	1st Floor-151 Gym	3,724	SF	6	10+ years	



					N	300	0 S Lawndale AVENUE, Chicago, IL 60623
Catego	ry : Room		В	uilding	: Main	_	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor-151 Gym	3,724	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor-151 Gym	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor-151 Gym	235	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-151 Gym	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-151 Gym	7,115	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	1st Floor-138 Kitchen	1,200	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-138 Kitchen	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-138 Kitchen	1,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-138 Kitchen	22	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor-138 Kitchen	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor-138 Kitchen	80	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-138 Kitchen	2,350	SF	7	10+ years	
Library							
	Ceiling - Lay-in	2nd Floor	2,000	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Carpet	2nd Floor	2,000	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	5	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	700	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	864	SF	6	10+ years	
Locker/S	Shower Room						
	Accessories	1st Floor Unisex	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Unisex	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Unisex	130	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex	128	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex	2	SF	5	1-2 years	Cracked
	Floor Drain	1st Floor Unisex	2	EA	7	10+ years	Clacked
	Hand Dryer		1	EA	7		
		1st Floor Unisex	1	EA	7	6-10 years	
	Lavatory	1st Floor Unisex	•			10+ years	
	Lighting - Lay-in	1st Floor Unisex	3	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor Unisex	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Unisex	545	SF	7	10+ years	
	Water Closet	1st Floor Unisex	1	EA	7	10+ years	
	Accessories	1st Floor-Men's Faculty Locker Room	175	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Men's Faculty Locker Room	35	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Men's Faculty Locker Room	140	SF	6	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw 1st Floor-Men's Faculty Locker 2 ΕA 7 10+ years Room Floor - Tile Ceramic/ Porcelain 1st Floor-Men's Faculty Locker 140 SF 7 10+ years Room Floor - Tile/Sheet 1st Floor-Men's Faculty Locker 35 SF 7 10+ years Room Floor Drain ΕA 1st Floor-Men's Faculty Locker 1 7 10+ years Room Hand Dryer 1st Floor-Men's Faculty Locker 1 ΕA 7 6-10 years Room 1st Floor-Men's Faculty Locker 1 ΕA 7 Lavatory 10+ years Room 7 Lighting - Lay-in 1st Floor-Men's Faculty Locker 3 EΑ 6-10 years Room Partitions 1st Floor-Men's Faculty Locker 1 ΕA 7 6-10 years Room Student Lockers - Two Tier 1st Floor-Men's Faculty Locker 2 ΕA 7 10+ years Room Urinals 1st Floor-Men's Faculty Locker ΕA 7 1 10+ years Room Walls - Concrete Block 1st Floor-Men's Faculty Locker 106 SF 7 10+ years Room Walls - Plaster/Drywall 1st Floor-Men's Faculty Locker 570 SF 6 10+ years Room Water Closet ΕA 1st Floor-Men's Faculty Locker 1 7 10+ years Room SF Accessories 1st Floor-Staff Shower Room 60 7 6-10 years Ceiling - Plaster/Drywall 1st Floor-Staff Shower Room 60 SF 6 10+ years 7 Doors - Wood Doors inclu hw 1st Floor-Staff Shower Room 1 EΑ 10+ years Floor - Terrazzo 1st Floor-Staff Shower Room 15 SF 7 10+ years SF Floor - Tile Ceramic/ Porcelain 1st Floor-Staff Shower Room 45 7 10+ years Floor Drain 1st Floor-Staff Shower Room 2 ΕA 7 10+ vears Lighting - Lay-in 7 1st Floor-Staff Shower Room 1 FΑ 6-10 years Showers 1st Floor-Staff Shower Room 1 ΕA 7 10+ years Walls - Concrete Block 1st Floor-Staff Shower Room 300 SF 7 10+ years SF 7 Accessories 1st Floor-Women's Faculty Locker 312 6-10 years Room Ceiling - Lay-in 1st Floor-Women's Faculty Locker 172 SF 7 10+ years Room SF Ceiling - Plaster/Drywall 1st Floor-Women's Faculty Locker 140 6 10+ years Room Doors - Wood Doors inclu hw 1st Floor-Women's Faculty Locker 2 FΑ 7 10+ years Room Floor - Tile Ceramic/ Porcelain 1st Floor-Women's Faculty Locker 140 SF 6 10+ years



Catego	ry : Room		D	uilding	· Main	300	0 S Lawndale AVENUE, Chicago, IL 60623
Calego	ry . Room		D	unung	. Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ereup		Room	Quantity			noplacomon	
	Floor - Tile/Sheet	1st Floor-Women's Faculty Locker Room	172	SF	5	10+ years	
	Floor Drain	1st Floor-Women's Faculty Locker Room	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Women's Faculty Locker Room	1	EA	7	6-10 years	Deficiency fixed
	Lavatory	1st Floor-Women's Faculty Locker Room	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Women's Faculty Locker Room	4	EA	7	6-10 years	
	Partitions	1st Floor-Women's Faculty Locker Room	2	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor-Women's Faculty Locker Room	14	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Women's Faculty Locker Room	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Women's Faculty Locker Room	785	SF	6	10+ years	
	Water Closet	1st Floor-Women's Faculty Locker Room	2	EA	7	10+ years	
	Accessories	1st Floor-Women's Locker Room, near Stair #3	140	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-Women's Locker Room, near Stair #3	35	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Women's Locker Room, near Stair #3	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Locker Room, near Stair #3	140	SF	6	10+ years	
	Floor Drain	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	Deficiency fixed
	Lavatory	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Women's Locker Room, near Stair #3	3	EA	7	6-10 years	
	Partitions	1st Floor-Women's Locker Room, near Stair #3	1	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor-Women's Locker Room, near Stair #3	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Women's Locker Room,	595	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		near Stair #3					
	Water Closet	1st Floor-Women's Locker Room,	1	EA	7	10+ years	
		near Stair #3					
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor-137 Dining/Multipurpose	2,655	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-137 Dining/Multipurpose	2,000	EA	7	10+ years	
	Floor - Tile	1st Floor-137 Dining/Multipurpose	2,655	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-137 Dining/Multipurpose	2,000	EA	7	6-10 years	
	Serving Line	1st Floor-137 Dining/Multipurpose	18	LF	7	10+ years	
	Storage/ Closet	1st Floor-137 Dining/Multipurpose	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-137 Dining/Multipurpose	2,515	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-137 Dining/Multipurpose	480	SF	6	10+ years	
	Walls - Tlastel/Drywall		400	01	0	IUT years	
_MDF_ID	F						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	125	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	No unit, central air
Mechani	ical/ Service Rooms						
moonan	Boiler Room	1st Floor	1.185	SF	7	10+ years	
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	178	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	825	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Storage Room	1st Floor	125	SF	7	10+ years	
	Storage Room	1st Floor	18	SF	7	10+ years	
	Janitor's Closet	2nd Floor	32	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	38	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	672	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	50	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	18	SF	7	10+ years	
D (-					-	
Restroo	M Accessories	1st Floor-Boy's Restroom	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	380	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	380	SF	6	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	360	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	2	EA	7	6-10 years	
		13(1100)-20) 3 1(53(100))	2	LA	I	0-10 years	



Catego	ry : Room		В	uilding	· Main		o o Lawindale AVENOL, Officago, il 00025
outego				anang	· man	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	Lavatory	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Boy's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boy's Restroom	890	SF	7	10+ years	
	Water Closet	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Accessories	1st Floor-Classroom 112/113 Restroom	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 112/113 Restroom	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 112/113 Restroom	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 112/113 Restroom	85	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 112/113 Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Classroom 112/113 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 112/113 Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Classroom 112/113 Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 112/113 Restroom	335	SF	6	10+ years	
	Water Closet	1st Floor-Classroom 112/113 Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Classroom 114/115 Restroom	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 114/115 Restroom	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 114/115 Restroom	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 114/115 Restroom	85	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 114/115 Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Classroom 114/115 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 114/115 Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Classroom 114/115 Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 114/115 Restroom	335	SF	6	10+ years	



Catego	ry : Room		B	uilding	Main	300	U S Lawndale AVENUE, Chicago, IL 60623
Calego			Б	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Water Closet	1st Floor-Classroom 114/115 Restroom	1	EA	7	10+ years	Comments
	Accessories	1st Floor-Classroom 116/118 Restroom	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 116/118 Restroom	85	SF	6	10+ years	
	Doors - Hardware	1st Floor-Classroom 116/118 Restroom	1	EA	6	1-2 years	No lock
	Doors - Wood Doors inclu hw	1st Floor-Classroom 116/118 Restroom	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 116/118 Restroom	85	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 116/118 Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Classroom 116/118 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 116/118 Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Classroom 116/118 Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 116/118 Restroom	335	SF	6	10+ years	
	Water Closet	1st Floor-Classroom 116/118 Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Classroom 120 Restroom	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 120 Restroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 120 Restroom	50	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Classroom 120 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Classroom 120 Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Classroom 120 Restroom	255	SF	6	10+ years	
	Water Closet	1st Floor-Classroom 120 Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Classroom 132/133 Restroom	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 132/133 Restroom	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 132/133 Restroom	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 132/133 Restroom	85	SF	7	10+ years	
	Floor Drain	1st Floor-Classroom 132/133 Restroom	1	EA	7	10+ years	



	ry : Room		P	uilding	·Main	300	0 S Lawndale AVENUE, Chicago, IL 60623
Calego			В	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Hand Dryer	1st Floor-Classroom 132/133	2000 1	EA	7	6-10 years	Comments
		Restroom		_/ \			
	Lavatory	1st Floor-Classroom 132/133	1	EA	7	10+ years	
		Restroom					
	Lighting - Lay-in	1st Floor-Classroom 132/133	1	EA	7	6-10 years	
		Restroom		~-	-		
	Walls - Plaster/Drywall	1st Floor-Classroom 132/133	335	SF	6	10+ years	
	Water Classet	Restroom	4		7	10	
	Water Closet	1st Floor-Classroom 132/133 Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-Classroom 134/136	85	SF	7	6-10 years	
	Accessories	Restroom	00	01	'		
	Ceiling - Plaster/Drywall	1st Floor-Classroom 134/136	85	SF	6	10+ years	
		Restroom		-	-	,	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 134/136	2	EA	7	10+ years	
		Restroom					
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 134/136	85	SF	7	10+ years	
		Restroom			_		
	Floor Drain	1st Floor-Classroom 134/136	1	EA	7	10+ years	
	Lland Dryer	Restroom	4	EA	7	0.40	
	Hand Dryer	1st Floor-Classroom 134/136 Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Classroom 134/136	1	EA	7	10+ years	
	Lavalory	Restroom		LA	'	TO+ years	
	Lighting - Lay-in	1st Floor-Classroom 134/136	1	EA	7	6-10 years	
		Restroom					
	Walls - Plaster/Drywall	1st Floor-Classroom 134/136	335	SF	6	10+ years	
		Restroom					
	Water Closet	1st Floor-Classroom 134/136	1	EA	7	10+ years	
		Restroom					
	Accessories	1st Floor-Girl's Restroom	380	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	380	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	380	SF	6	10+ years	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Girl's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-Girl's Restroom	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Girl's Restroom	890	SF	7	10+ years	
	Water Closet	1st Floor-Girl's Restroom	6	EA	7	10+ years	
	Accessories	2nd Floor - Unisex Staff Restroom	201	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor - Unisex Staff Restroom	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Unisex Staff Restroom	111	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Unisex Staff Restroom	3	EA	7	10+ years	



Group

Building : Main Category : Room Recommend Location Item - Type Quantity UOM Rank Replacement Comments Floor - Tile 2nd Floor - Unisex Staff Restroom 90 SF 10+ vears 6 Floor - Tile Ceramic/ Porcelain SF 7 2nd Floor - Unisex Staff Restroom 111 10+ years Floor Drain 2nd Floor - Unisex Staff Restroom 2 FΑ 7 10+ years Hand Drver 2 7 2nd Floor - Unisex Staff Restroom EΑ 6-10 years 2 Lavatory 2nd Floor - Unisex Staff Restroom EΑ 7 10+ years 4 ΕA 7 Lighting - Lay-in 2nd Floor - Unisex Staff Restroom 6-10 years Student Lockers - One Tier 2nd Floor - Unisex Staff Restroom 1 ΕA 7 10+ years Student Lockers - Two Tiers 2nd Floor - Unisex Staff Restroom 5 ΕA 7 6-10 years SF Walls - Concrete Block 2nd Floor - Unisex Staff Restroom 856 7 10+ years ΕA Water Closet 2nd Floor - Unisex Staff Restroom 2 7 10+ vears Accessories 2nd Floor-Boys Restroom 380 SF 7 6-10 vears Ceiling - Plaster/Drywall 2nd Floor-Boys Restroom 370 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Boys Restroom SF 5 1-2 years 10 Water damage SF 7 Floor - Tile Ceramic/ Porcelain 2nd Floor-Boys Restroom 380 10+ years Floor Drain 2nd Floor-Boys Restroom ΕA 7 1 10+ years Hand Dryer 2nd Floor-Boys Restroom 2 FΑ 7 6-10 years 3 7 Lavatory 2nd Floor-Boys Restroom ΕA 10+ years 5 Lighting - Lay-in 2nd Floor-Boys Restroom ΕA 7 6-10 years Partitions 3 2nd Floor-Boys Restroom ΕA 7 10+ vears Urinals 2nd Floor-Boys Restroom 4 EΑ 7 10+ years Updated quantity Walls - Concrete Block 2nd Floor-Boys Restroom 890 SF 7 10+ years 2 ΕA 7 Water Closet 2nd Floor-Boys Restroom 10+ years Updated quantity SF 7 Accessories 2nd Floor-Girls Restroom 380 6-10 years 2nd Floor-Girls Restroom SF Ceiling - Plaster/Drywall 380 6 10+ years Floor - Tile Ceramic/ Porcelain 380 SF 7 2nd Floor-Girls Restroom 10+ years Floor Drain 2nd Floor-Girls Restroom 1 ΕA 7 10+ vears 2 Hand Dryer 2nd Floor-Girls Restroom ΕA 7 10+ years 3 ΕA 7 Lavatory 2nd Floor-Girls Restroom 10+ years Lighting - Lay-in 4 2nd Floor-Girls Restroom ΕA 7 6-10 years Partitions 2nd Floor-Girls Restroom 6 ΕA 7 10+ years SF Walls - Concrete Block 2nd Floor-Girls Restroom 882 7 10+ years Water Closet 2nd Floor-Girls Restroom 6 ΕA 7 10+ years

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	n #102 (Other Instructional Use)						
	Casework	1st Floor	9	LF	6	10+ years	Not previously assessed
	Ceiling - Lay-in	1st Floor	865	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	865	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	530	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	530	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	: Main		
3				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #112 (Kindergarten)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #113 (Kindergarten)						
010030100	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	6		
						10+ years	
	Lighting - Lay-in Marker Doord	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #114 (Kindergarten)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classror	om #115 (Kindergarten)						
	Casework	1st Floor	44	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	950	EA	7		
						10+ years	
	Floor - Tile	1st Floor	950	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	om #116 (Pre School)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	920	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	675	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	om #118 (Pre School)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	920	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	920	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	675	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	om #120 (Kindergarten)						
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,230	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	, 1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,230	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	985	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	275	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	om #132 (Regular Classroom)						
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	: Main	Cool & Lawindaie AVENCE, Childago, ie 00020		
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	950	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Marker Board	1st Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	550	SF	7	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
Classroo	om #133 (Regular Classroom)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	950	SF	7	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	950	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	570	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	550	SF	6	10+ years		
	Work Sink	1st Floor	2	EA	7	10+ years		
	WOR SHR	151 1001	2	EA	'	TUT years		
Classroo	om #134 (Pre School)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,166	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,166	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	535	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	om #136 (Pre School)							
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,166	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1,100	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,166	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Storage/ Closet	1st Floor	4	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	535	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Work Sink	1st Floor	120	EA	0 7	10+ years		
			I	EA	1	ior years		



Catego	ry : Classroom		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #200 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classror	om #201 (Regular Classroom)						
_1000100	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classro	om #202 (Regular Classroom)						
CIASSIU	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
~.	-					-	
Classroo	om #203 (Regular Classroom)				-	40	
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	



Catego	Category : Classroom			uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
N							
Jassroo	om #204 (Regular Classroom)				_		
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classroc	om #205 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
		2nd Floor					
	Lighting - Lay-in		12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
Classroc	om #206 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	•	
				SF		10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	55	6	10+ years	
Classroc	om #207 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
	wans - i laster/Drywall	21011001	408	0	0	ior years	



Catego	ry : Classroom		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #208 (Regular Classroom)								
	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	835	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years			
Classroo	m #209 (Other Instructional Use)								
	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years	Updated quantity		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ vears			
	Floor - Tile	2nd Floor	835	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years			
Classroo	m #210 (Regular Classroom)								
	Casework	2nd Floor	8	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	835	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years			
Classroo	vm #211 (Office)								
	Casework	2nd Floor	30	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	980	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Carpet	2nd Floor	980	SF	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years			
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years			



Catego	ry : Classroom		В	uilding			
Ŭ				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Walls - Plaster/Drywall	2nd Floor	700	SF	7	10+ years	
	·					·	
Classroc	m #216 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
			400	51	0	TOF years	
Classroc	m #217 (Regular Classroom)						
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	835	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	835	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	575	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	468	SF	6	10+ years	
						5	
Classroc	m #221 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,077	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,077	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	525	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
Classroo	m #222 (Play Room)						
0///	Ceiling - Lay-in	2nd Floor	1,170	SF	7	10+ years	
	Chalk Board	2nd Floor		LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	8			•	
			1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,170	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	914	SF	7	10+ years	



	Schools		3000 S Lawndale AVENUE, Chicago, IL 60623							
Catego	ory : Classroom		B	uilding						
_			- · ·			Recommend	_			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Concrete Block	2nd Floor	6	SF	5	1-2 years	Cracking block			
	Walls - Plaster/Drywall	2nd Floor	300	SF	6	10+ years				
	Work Sink	2nd Floor	1	EA	7	6-10 years				
lassro	om #223 (Regular Classroom)									
	Ceiling - Lay-in	2nd Floor	1,131	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	. 1	EA	7	10+ years				
	Floor - Tile	2nd Floor	1,131	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years				
	Marker Board	2nd Floor	16	LF	7	6-10 years				
	Walls - Concrete Block	2nd Floor	444	SF	7	10+ years				
	Walls - Concrete Block	2nd Floor	6	SF	6	6-10 years				
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	630	SF	6	•				
	Walls - Flastel/Drywall		030	SF	0	10+ years				
lassro	om #224 (Regular Classroom)									
	Casework	2nd Floor	17	LF	7	10+ years				
	Ceiling - Lay-in	2nd Floor	980	SF	7	10+ years				
	Chalk Board	2nd Floor	16	LF	4	2-5 years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years				
	Floor - Tile	2nd Floor	980	SF	6	10+ years				
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years				
	Storage/ Closet	2nd Floor	125	SF	7	10+ years				
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor	540	SF	6	10+ years				
	Work Sink	2nd Floor	1	EA	7	6-10 years				
ateac	ory · Interior		B	uilding	• Main					
Category : Interior			anang	. mann	Decommond					
						Recommend				
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Ceiling - Lay-in	Location 1st Floor	3,884	SF	Rank 7	Replacement 10+ years	Comments			
-	Ceiling - Lay-in Ceiling - Plaster/Drywall					Replacement	Comments			
-	Ceiling - Lay-in	1st Floor	3,884	SF	7	Replacement 10+ years	Comments			
-	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 1st Floor	3,884 846	SF SF	7 6	Replacement 10+ years 10+ years	Comments			
-	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor	3,884 846 2	SF SF EA	7 6 7	Replacement 10+ years 10+ years 10+ years 6-10 years	Comments			
-	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,884 846 2 2 2 640	SF SF EA EA SF	7 6 7 7 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,884 846 2 2 640 3,966	SF SF EA EA SF SF	7 6 7 7 7 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,884 846 2 2 640 3,966 40	SF SF EA SF SF EA	7 6 7 7 7 7 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,884 846 2 2 640 3,966 40 3	SF SF EA EA SF EA EA	7 6 7 7 7 7 7 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,884 846 2 2 640 3,966 40 3 8,575	SF SF EA SF SF EA EA SF	7 6 7 7 7 7 7 7 7	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 10+ years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block Walls - Plaster/Drywall	1st Floor 1st Floor	3,884 846 2 2 640 3,966 40 3 8,575 3,560	SF SF EA SF EA SF EA SF SF	7 6 7 7 7 7 7 7 7 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Comments			
	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 2nd Floor	3,884 846 2 2 640 3,966 40 3,966 40 3 8,575 3,560 3,872	SF SF EA SF EA SF EA SF SF SF	7 6 7 7 7 7 7 7 6 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ ye	Comments			
Group Corridor	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Walls - Concrete Block Walls - Plaster/Drywall	1st Floor 1st Floor	3,884 846 2 2 640 3,966 40 3 8,575 3,560	SF SF EA SF EA SF EA SF SF	7 6 7 7 7 7 7 7 7 6	Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Comments			



Catego	ategory : Interior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,016	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	37	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	7,290	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	10	SF	5	1-2 years	Cracking
Safety							
,	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	Deficiency fixed
	Security Cameras	1st Floor	7	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North (Stair 1)	210	SF	6	10+ years	
	Floor - Tile	North (Stair 1)	65	SF	6	10+ years	
	Handrails	North (Stair 1)	85	LF	7	10+ years	
	Lighting - Pendent/Surface	North (Stair 1)	1	EA	7	6-10 years	
	Stairs - Tile	North (Stair 1)	30	LF	6	10+ years	
	Walls - Concrete Block	North (Stair 1)	1,457	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South (Stair 2)	160	SF	7	10+ years	
	Floor - Tile	South (Stair 2)	65	SF	6	10+ years	
	Handrails	South (Stair 2)	85	LF	7	10+ years	
	Lighting - Lay-in	South (Stair 2)	2	EA	7	6-10 years	
	Stairs - Tile	South (Stair 2)	30	LF	6	10+ vears	
	Walls - Concrete Block	South (Stair 2)	1,400	SF	7	10+ years	
	Walls - Concrete Block	South (Stair 2)	8	SF	6	6-10 years	
	Walls - Concrete Block	South (Stair 2)	30	SF	5	1-2 years	Cracking
	Ceiling - Plaster/Drywall	West (Stair 3)	210	SF	6	10+ years	5
	Floor - Tile	West (Stair 3)	65	SF	6	10+ years	
	Handrails	West (Stair 3)	85	LF	7	10+ years	
	Lighting - Pendent/Surface	West (Stair 3)	1	EA	7	6-10 years	
	Stairs - Tile	West (Stair 3)	18	LF	7	10+ years	
	Stairs - Tile	West (Stair 3)	6	LF	5	1-2 years	Tread caps, breaking and cracking
	Walls - Concrete Block	West (Stair 3)	1,458	SF	7	10+ years	······································
	Walls - Concrete Block	West (Stair 3)	10	SF	6	6-10 years	
/ertical	Conveyance						
	Elevator - Elevator- Roped Holeless	1st to 2nd floor	1	EA	6	10+ years	
	Hydraulic						



Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	South Courtyard	15,004	SF	6	6-10 years	
	Surface - Asphalt	South Courtyard	20	SF	5	1-2 years	Depression, pooling
	Lighting	South Courtyard	4	EA	6	10+ years	
	Surface - Synthetic including exc & retention	South Courtyard	50,085	SF	6	6-10 years	Verified that surface is in good condition
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	6	10+ years	
					-	, ,	
Fencing							
	Fencing - Chain Link	Entire Site	240	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	1,480	LF	6	10+ years	
Landsca	De						
	Benches	Entire Site	7	EA	7	10+ years	
	Landscape - Grass	Entire Site	12,800	SF	6	6-10 years	
	Landscape - Grass	Entire Site	800	SF	4	1-2 years	Bare soil
	Landscape - Hardscape- Concrete	Entire Site	12.950	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	150	SF	4	1-2 years	Missing concrete, cracked concrete
	Parkway trees	Entire Site	24	EA	6	10+ years	0
	Planting Beds/ Area	Entire Site	9,800	SF	6	6-10 years	
	Retaining Wall - Masonry	Entire Site	300	SF	6	6-10 years	
	Trash Receptacles	Entire Site	1	EA	7	6-10 years	
	Trash Receptacles	Entire Site	5	EA	4	1-2 years	Corroded receptacles
Parking I	ot						
	Concrete Curbs	Parking Lot- North	145	LF	6	10+ years	
	Lighting - Pole Mounted	Parking Lot- North	4	EA	6	10+ years	
	Surface - Asphalt	Parking Lot- North	1,262	SF	4	1-2 years	Disintegrated surface, alligatored
		0					surface, potholes, and large cracks
							throughout
	Surface - Concrete	Parking Lot- North	2,321	SF	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- North	425	SF	6	6-10 years	
	Trash Enclosure - Masonry	Parking Lot- North	400	SF	5	1-2 years	Open joints and deteriorated morta
Playgrou	nd						
-,	Equipment - Pre K 3-5	NW	1	EA	7	6-10 years	
	Surface - Poured Surface	NW	2,340	SF	7	6-10 years	



Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	211	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	4	LF	4	1-2 years	Shattered concrete
	Sidewalks - Perimeter Sidewalks	Entire Site	13,500	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	5	1-2 years	Upheaved, cracked concrete
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

•			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			001	004	4.077	50			J
Computer Lab	Computer Lab	2nd Floor	221	221	1,077	56	26	N	N
Kindergarten	Regular Classroom	1st Floor	112	112	950	84	42	N	1
Kindergarten	Regular Classroom	1st Floor	113	113	950	84	42	N	Y
Kindergarten	Regular Classroom	1st Floor	114	114	950	84	42	N	1
Kindergarten	Regular Classroom	1st Floor	115	115	950	84	42	N	N
Kindergarten	Regular Classroom	1st Floor	120	120	1,230	84	42	N	N
Office	Regular Classroom	2nd Floor	211	211	980	28	0		ļ!
Other Instructional Use	Faculty Lounge	1st Floor	102	NA	865	78	39		ļ!
Other Instructional Use	Regular Classroom	2nd Floor	209	209	835	84	42	N	N
Play Room	Regular Classroom	2nd Floor	222	222	1,170	56	26	N	N
Pre School	Kindergarten	1st Floor	116	116	920	126	68	N	Y
Pre School	Kindergarten	1st Floor	118	118	920	126	68	N	N
Pre School	Pre School	1st Floor	134	134	1,166	112	56	N	N
Pre School	Pre School	1st Floor	136	136	1,166	112	56	N	N
Regular Classroom	Regular Classroom	1st Floor	132	132	950	84	42	N	N
Regular Classroom	Regular Classroom	1st Floor	133	133	950	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	835	84	42	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	835	84	42	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	210	210	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	835	84	42	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	1,131	98	46	N	N
Regular Classroom	Science Classroom	2nd Floor	224	224	980	56	26	N	N