

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1901	4	79,788
Annex	1996	3	76,800
Modular 1 (6-Classroom)	2003	1	6,720
Campus Total			163,308

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Store Front	1 - Main Entrance	3	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - Main Entrance	60	LF	6	10+ years	
	Exterior Doors - Store Front	2 - South	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 - South	4	EA	6	10+ years	
	Exterior Doors - Store Front	3 - South	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 - South	4	EA	6	10+ years	
	Ramps - Concrete	3 - South	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4 - Auditorium west	1	EA	6	10+ years	
	Exterior Stairs - Stone	4 - Auditorium west	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	5 - Storage West	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 - Boiler Room	2	EA	6	6-10 years	
	Entrance Control - Audio and Video	7 - NW	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	7 - NW	1	EA	6	10+ years	
	Exterior Doors - Store Front	8 - NE	4	EA	6	10+ years	
	Ramps - Concrete	8 - NE	12	LF	6	10+ years	
_Foundati	on						
	Foundation - Masonry	Entire Building	718	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	79,788	SF	7	10+ years	
Lighting							



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	7	6-10 years	
oof Sys	stem						
JOI Oye	Access Ladder - Metal	A - South	1	EA	7	10+ years	
	Coping - Clay Tile	A - South	20	LF	6	10+ years	
	Coping - Terra Cotta	A - South	104	LF	6	10+ years	
	Parapet - Parapet < 16" Height	A - South	124	LF	6	10+ years	
	Roof - Modified Bitumen	A - South	6,210	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	A - South	6,210	SF	7	10+ years	
	Access Ladder - Metal	B - High Roof	0,210	EA	7	10+ years	
	Access Ladder - Metal	B - High Roof	1	EA	4	•	Platform not attached and unstable
	Access Lauder - Metal	B - High Rooi	ı	EA	4	0-1 year	
	Coning Clay Tile	D. High Doof	405		•	40	access unsafe
	Coping - Clay Tile	B - High Roof	165	LF	6	10+ years	
	Coping - Terra Cotta	B - High Roof	301	LF	6	10+ years	
	Downspouts - Interior Downspouts	B - High Roof	180	LF	6	10+ years	
	Parapet - 16" - 30" Height	B - High Roof	211	LF	6	10+ years	
	Parapet - Parapet < 16" Height	B - High Roof	255	LF	6	10+ years	
	Roof - Modified Bitumen	B - High Roof	10,060	SF	7	10+ years	
	Roof Hatch - Metal	B - High Roof	2	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	B - High Roof	10,060	SF	7	10+ years	
	Access Ladder - Metal	C - North	1	EA	4	0-1 year	Access involves climbing over ductwork and unattached planks the attic. There is an alternate ceiling hatch access but no ladder near the main hatch.
	Coping - Clay Tile	C - North	139	LF	6	10+ years	
	Coping - Terra Cotta	C - North	216	LF	6	10+ years	
	Downspouts - Exterior Downspouts	C - North	138	LF	6	10+ years	
	Parapet - 16" - 30" Height	C - North	187	LF	6	10+ years	
	Parapet - Parapet < 16" Height	C - North	168	LF	6	10+ years	
	Roof - Modified Bitumen	C - North	6,522	SF	7	10+ years	
	Roof Hatch - Metal	C - North	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	C - North	6,522	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	D - Low West	80	LF	6	10+ years	
	Liner	D - LOW West	00		U	10+ years	
	Coping - Clay Tile	D - Low West	121	LF	6	10+ years	
	Downspouts - Exterior Downspouts	D - Low West	24	LF	6	10+ years	
	Parapet - 16" - 30" Height	D - Low West	121	LF	6	10+ years	
	Roof - Metal	D - Low West	30	SF	7	10+ years	
	Roof - Modified Bitumen	D - Low West	308	SF	7	10+ years	
	Roof - Modified Bitumen	D - Low West	2,132	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	D - Low West	2,470	SF	7	10+ years	
	Coping - Metal	E - Low West	35	LF	7	10+ years	
	Parapet - 16" - 30" Height	E - Low West	35	LF	6	10+ years	



Julego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	E - Low West	152	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	E - Low West	152	SF	7	10+ years	
	Trees enderer Steel with Glay The Trees	2 25W WOOL	102	O.	•	101 youro	
Valls							
valis	Canopy - Fabric	Entire Building	112	SF	7	6-10 years	
	Cornice - Masonry Projecting Limestone	Entire Building	36	LF	6	10+ years	
	Cornice - Masoniy Projecting Limestone Cornice - Metal Projecting	Entire Building	710	LF	6	6-10 years	
			-				Halas Jasas
	Cornice - Metal Projecting	Entire Building	40	LF	5	2-5 years	Holes, loose
	Exterior Walls - Brick	Entire Building	29,054	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	216	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	5,620	SF	6	10+ years	
Vindows	3						
	Guard - Guards perforated	Entire Building	560	SF	6	10+ years	
	Lintels - Brick	Entire Building	80	LF	6	10+ years	
	Lintels - Steel	Entire Building	313	LF	6	10+ years	
	Lintels - Stone	•	233	LF	6		
		Entire Building	233 247			10+ years	
	Windows - Decorative	Entire Building		SF	6	10+ years	
	Windows - Louver	Entire Building	84	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,580	SF	6	10+ years	
Catego	ry : Electrical		R	uilding	: Main		
July	i y . Electricai						
Julogo						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Froup	Item - Type	Location	Quantity	UOM		Replacement	
Froup	Item - Type	Location Basement		_			Comments Location changed for clarification.
Froup	Item - Type ncy System Automatic Transfer Switch	Basement	Quantity 2	UOM	Rank	Replacement 6-10 years	Location changed for clarification.
Froup	Item - Type		Quantity	UOM	Rank	Replacement	Location changed for clarification. Location changed for clarification a
Froup	Item - Type ncy System Automatic Transfer Switch	Basement	Quantity 2	UOM	Rank	Replacement 6-10 years	Location changed for clarification. Location changed for clarification at the auditorium occupies space on
Froup	Item - Type ncy System Automatic Transfer Switch	Basement	Quantity 2	UOM	Rank	Replacement 6-10 years	Location changed for clarification. Location changed for clarification a the auditorium occupies space on multiple floors. Quantity changed
Froup	Item - Type ncy System Automatic Transfer Switch	Basement	Quantity 2	UOM	Rank	Replacement 6-10 years	Location changed for clarification. Location changed for clarification a the auditorium occupies space on multiple floors. Quantity changed match current observations and as
roup	Item - Type ncy System Automatic Transfer Switch Exit Signs - Auditoium	Basement Entire Building	Quantity 2 12	UOM EA EA	7 7	Replacement 6-10 years 10+ years	Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Quantity changed match current observations and as
Froup	Item - Type Incy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs	Basement Entire Building Entire Building	Quantity 2 12	UOM EA EA	7 7 7	6-10 years 10+ years 6-10 years	Location changed for clarification. Location changed for clarification at the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated
Froup	Item - Type Incy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym	Basement Entire Building Entire Building Entire Building Entire Building	Quantity 2 12	UOM EA EA	7 7 7 7 7	Replacement 6-10 years 10+ years	Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification.
roup	Item - Type Incy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs	Basement Entire Building Entire Building	Quantity 2 12	UOM EA EA	7 7 7	6-10 years 10+ years 6-10 years	Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification.
Froup	Item - Type Incy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym	Basement Entire Building Entire Building Entire Building Entire Building	Quantity 2 12	UOM EA EA	7 7 7 7 7	6-10 years 10+ years 6-10 years 6-10 years	Location changed for clarification. Location changed for clarification a the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification. Location changed for clarification a the auditorium occupies space on
Froup	Item - Type Incy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and	Basement Entire Building Entire Building Entire Building Entire Building	Quantity 2 12	UOM EA EA	7 7 7 7 7	6-10 years 10+ years 6-10 years 6-10 years	Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification. Location changed for clarification of the control of the cont
Group	Item - Type Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs	Basement Entire Building Entire Building Entire Building Entire Building	Quantity 2 12 14 2 4,919 16,175	EA EA SF	7 7 7 7 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Location changed for clarification. Location changed for clarification at the auditorium occupies space on multiple floors. Quantity changed match current observations and at total has been divided/aggregated Location changed for clarification. Location changed for clarification at the auditorium occupies space on
Group	Item - Type Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and	Basement Entire Building Entire Building Entire Building Entire Building	Quantity 2 12 14 2 4,919	EA EA EA SF	7 7 7 7 6	6-10 years 10+ years 6-10 years 6-10 years 10+ years	Location changed for clarification. Location changed for clarification at the auditorium occupies space on multiple floors. Quantity changed match current observations and at total has been divided/aggregated Location changed for clarification. Location changed for clarification at the auditorium occupies space on
Group	Item - Type Icy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Basement Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 2 12 14 2 4,919 16,175 5,912	EA EA SF	7 7 7 6 6 6 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Location changed for clarification. Location changed for clarification a the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification. Location changed for clarification a the auditorium occupies space on multiple floors. Location changed for clarification.
Group	Item - Type Icy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Basement Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 2 12 14 2 4,919 16,175 5,912 1,355	EA EA SF SF SF SF	7 7 7 6 6 6 6 6 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 10+ years 10+ years	Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Quantity changed match current observations and astotal has been divided/aggregated. Location changed for clarification. Location changed for clarification of the auditorium occupies space on multiple floors. Location changed for clarification.
Group	Item - Type Icy System Automatic Transfer Switch Exit Signs - Auditoium Exit Signs - Corridors and Stairs Exit Signs - Gym Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Basement Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 2 12 14 2 4,919 16,175 5,912	EA EA SF	7 7 7 6 6 6 6	6-10 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years	Location changed for clarification. Location changed for clarification at the auditorium occupies space on multiple floors. Quantity changed match current observations and as total has been divided/aggregated Location changed for clarification. Location changed for clarification at the auditorium occupies space on multiple floors.



Catego	ry : Electrical		В	uilding	: Main	<u> </u>	242 S Sawyer AVENUE, Chicago, IL 60632		
Julogo	. y . Eloctrical		_	unung	· Wani	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Security System - Intrusion Detection	Entire Building	79,788	SF	6	6-10 years			
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	Site North	1	EA	6	6-10 years			
lain Se	rvice								
	Main Electrical Service - 1600 A 277/480/3PH	Electrical Room	2	EA	6	6-10 years			
	Main Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	7	10+ years			
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Location changed for clarification.		
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Location changed for clarification		
	PA System	Entire Building	79,788	SF	6	6-10 years	Served by Annex		
ower D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	Location changed for clarification.		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Location changed for clarification.		
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM fuse panel has open fuse receptacles which expose live conductors presenting a live front condition.		
	Lighting and Power Panels - Above 100 A	Entire Building	21	EA	7	10+ years			
	Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600	Entire Building Entire Building	2	EA EA	7 6	10+ years 6-10 years			
	amp Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years			
atego	ry : Fire Protection		В	uilding	: Main				
						Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ire Alar	m Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	System is functional and passes		
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	inspection but is almost 30 years ole employs unreliable and antiquated technology, and has reached the er of its anticipated service life. No CF Asset Tag present. Serves Main. Rank adjusted based on current observations and per		
							review with Building Engineer. Pan is functional and passes inspection but is almost 30 years old, employs		



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	79,788	SF	6	2-5 years	unreliable and antiquated technology and has reached the end of its anticipated service life. Location changed for clarification. Reason and Priority Rep changed based on current observations and per review with Building Engineer. System is functional and passes
	Fire Alarm_System	Entire Building	79,788	SF	4	2-5 years	inspection but is almost 30 years old, employs unreliable and antiquated technology, and has reached the enc of its anticipated service life. Serves Main. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer. System is functional and passes inspection but is almost 30 years old, employs unreliable and antiquated technology
	Fire Pump Controller	Entire Building	1	EA	7	6-10 years	and has reached the end of its anticipated service life. Location changed for clarification.
Pump Ro	oom Assembly						
	Fire Pump - Less than 25hp Jockey Pump	Basement Basement	1 1	EA EA	6 6	6-10 years 6-10 years	
Snrinklar	System						
ринке	Combination Wet and Dry Sprinkler System	Entire Building	79,788	SF	6	6-10 years	
	Sprinkler Heads	Entire Building	79,788	SF	7	10+ years	
	Sprinkler Piping	Entire Building	79,788	SF	7	10+ years	
`ataga	ry : Mechanical		D	uilding	· Main		
Jaiego	ı y . Mechanicai			unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond						•	
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	6-10 years	No CPS Asset Tag present. Component of a ductless split syster serving the MDF Room.
	Condensing Unit- Ground Mounted - 5-10 tons	Site - East	1	EA	3	0-1 year	Rank changed as the equipment is nonfunctional and out of service; deemed obsolete and abandoned in



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							deterioration. No CPS Asset Tag present.
	Chemical Pot Feeder	Site North	1	EA	6	6-10 years	Location changed for clarification.
	Chiller-Air Cooled-Screw Type-Ground Mounted - 301 - 400 tons	Site North	1	EA	6	10+ years	J
	Glycol Feed	Site North	1	EA	6	6-10 years	Location changed for clarification.
	Pipes - Chilled Water Pipe- Copper	Site North	400	LF	6	10+ years	Location changed for clarification.
	Pipes - Chilled Water Pipe- Steel	Site North	800	LF	6	10+ years	Location changed for clarification.
	Pressure Fill System	Site North	1	EA	6	6-10 years	Location changed for clarification.
Air Hand	ling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 8001-12000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-2, serves gym. No CPS Asset Tag present.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	2	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Location changed for clarification.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils and Chilled Water Coils - Greater than 35000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-MZ. Serves Main except gym and auditorium. Includes dual supply fans. No CPS Asset Tag present.
	Air Intake	Mechanical Room	1	EA	7	10+ years	01
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room	100	LF	7	10+ years	
	Zone Dampers	Mechanical Room	36	EA	7	10+ years	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	10+ years	AHU-1, serves auditorium. No CPS Asset Tag present.
	Air Intake	Mechanical Room	1	EA	7	10+ years	
Boiler Sy	estems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Entire Building	2	EA	6	10+ years	
	Chemical Feed System	Entire Building	1	EA	7	6-10 years	
	Combustion Dampers	Entire Building	3	EA	7	6-10 years	
	Condensate Pump	Entire Building	1	EA	7	10+ years	Location changed for clarification. No CPS Asset Tag present.
	Feed Water Pumps and Tank	Entire Building	1	EA	7	10+ years	.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Entire Building	1	EA	6	10+ years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Entire Building	1	EA	6	10+ years	B-2

Campus Name: Sawyer Page : 6 of 64 Assessment Date: 06/26/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Entire Building Entire Building	400	LF LF	4	2-5 years 2-5 years	Quantity changed as total has been divided/aggregated. Leak-free with approx. 75% of the piping being unlabeled, greater than 40 years old, and approaching the end of its anticipated service life. Quantity changed as total has been divided/aggregated. Leak-free with approx. 75% of the piping being unlabeled, greater than 40 years old, and approaching the end of its anticipated service life.
	Steam Traps	Entire Building	21	EA	6	6-10 years	
Gas Boo	ester						
	Gas Booster	Boiler Room	2	EA	6	10+ years	
_Heating							
	Unit Heater - Gas	Boiler Room	1	EΑ	6	6-10 years	
	Radiators - Steam	Entire Building	7	EA	5	6-10 years	
	Fin Tube - Electric	Entire Building	18	LF	6	6-10 years	EL . 16 . 1 . 20
	Fin Tube - Steam	Entire Building	24	LF	6	6-10 years	Elevated fin tube without cover.
	Fin Tube - Steam	Entire Building	48	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.
	Wall Heater - Electric	Entire Building	7	EA	5	2-5 years	Quantity changed to match current observations. Vintage units approaching the end of their anticipated service life.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Missing electrical compartment cover exposes live conductors presenting a live front condition.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Missing cover exposes hot and moving parts presenting a risk of personal injury and exposes live conductors presenting a live front condition.
_Mechani	cal Plumbing						
	Chilled Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	10+ years	
	Chilled Water Pump - 21 - 50 HP	Boiler Room	1	EA	6	10+ years	
Tompor	ature Control						
rember	aure common						



Category : Mechanical

Sidney Sawyer Elementary School 5242 S Sawyer AVENUE, Chicago, IL 60632

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	DDC System	Entire Building	79,788	SF	7	10+ years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls unit heater.
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Controls venting dampers.
	Thermostats - DDC	Entire Building	38	EA	7	10+ years	
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	EF-3. Location changed for clarification.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Roof Mounted Duct Work	Entire Building	600	LF	7	10+ years	Location changed for clarification.
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Serves Main. Unit is 28 years old and has reached the end of its anticipated service life.
_Piping	Domestic Piping-Hot Water Return Lines	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is
		·			7	·	operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Domestic Piping-Hot Water Return Risers	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is

Building: Main



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Risers)						operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	79,788	SF	4	2-5 years	Domestic plumbing system is operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Sanitary Piping	Entire Building	79,788	SF	5	2-5 years	Domestic plumbing system is operational and leak-free but is over 40 years old and approaching the end of its anticipated service life.
	Storm Piping	Entire Building	79,788	SF	6	2-5 years	•
	Vent Piping	Entire Building	79,788	SF	6	2-5 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	1-2 years	Pump has been inoperative for several years but per review with Building Engineer it is scheduled for replacement in August, 2024.

Category : Room Building: Main

Calego	ry:Room	Building: Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	rative Suites/Offices						
	Ceiling - Exposed	005 Counselor Office	750	SF	6	10+ years	
	Doors - Wood Doors inclu hw	005 Counselor Office	3	EA	7	10+ years	
	Floor - Wood	005 Counselor Office	750	SF	6	10+ years	
	Lighting - Pendent/Surface	005 Counselor Office	14	EA	6	6-10 years	
	Power Distribution	005 Counselor Office	24	EA	7	10+ years	
	Storage/ Closet	005 Counselor Office	91	SF	7	10+ years	
	Walls - Plaster/Drywall	005 Counselor Office	1,102	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1.5 East Office on landing Counselor	206	SF	6	10+ years	
	Doors - Side-lite	1.5 East Office on landing Counselor	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1.5 East Office on landing Counselor	1	EA	7	10+ years	
	Floor - Carpet	1.5 East Office on landing Counselor	206	SF	6	6-10 years	
	Lighting - Pendent/Surface	1.5 East Office on landing Counselor	3	EA	6	6-10 years	
	Power Distribution	1.5 East Office on landing Counselor	2	EA	7	10+ years	
	Storage/ Closet	1.5 East Office on landing Counselor	3	SF	7	10+ years	
	Walls - Plaster/Drywall	1.5 East Office on landing Counselor	259	SF	6	10+ years	
	Ceiling - Exposed	Basement Engineer's Office	157	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Engineer's Office	1	EA	7	10+ years	
	Floor - Wood	Basement Engineer's Office	157	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement Engineer's Office	3	EA	6	6-10 years	
	Power Distribution	Basement Engineer's Office	8	EA	7	10+ years	

Campus Name: Sawyer Page : 9 of 64 Assessment Date: 06/26/2024



Catego	ry : Room		R	uilding	: Main	-	242 O Gawyer Avenoe, Officago, in 00032
Guiogo				anamg		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	Basement Engineer's Office	1	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement Engineer's Office	577	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	1,007	SF	6	10+ years	
	Doors - Transom Window	Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Carpet	Main Office	1,007	SF	6	6-10 years	
	Lighting - Pendent/Surface	Main Office	14	EA	6	6-10 years	
	Power Distribution	Main Office	24	EA	7	10+ years	
	Storage/ Closet	Main Office	105	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	1,149	SF	6	10+ years	
	Work Sink	Main Office	1,149			•	
	Ceiling - Plaster/Drywall		•	EA SF	7 6	10+ years	
		Staff lounge	625	_	-	10+ years	
	Doors - Wood Doors inclu hw	Staff lounge	2	EA	7	10+ years	
	Floor - Wood	Staff lounge	625	SF	6	10+ years	
	Lighting - Pendent/Surface	Staff lounge	6	EΑ	6	6-10 years	
	Power Distribution	Staff lounge	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff lounge	900	SF	6	10+ years	
	Work Sink	Staff lounge	1	EA	7	10+ years	
Δuditoriu	ım & Theater						
_Additione	Balcony Seating	Basement	140	EA	7	10 Lyone	
	Ceiling - Plaster/Drywall	Basement	3,893	SF		10+ years	
					6	10+ years	
	Doors - Wood Doors inclu hw	Basement	7	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	3,893	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	25	EA	6	6-10 years	
	Main Floor Seating	Basement	535	EA	7	10+ years	
	Sound System	Basement	1	EA	7	6-10 years	
	Stage	Basement	800	SF	7	10+ years	
	Stage Curtain	Basement	10	EA	7	10+ years	
	Stage Lighting System	Basement	1	EA	7	6-10 years	
	Stage-Stairs - Wood	Basement	64	LF	6	10+ years	
	Stairs - Asphalt	Basement	132	LF	6	10+ years	
	Stairs - Wood	Basement	132	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement	5,030	SF	6	10+ years	
_Gvmnas	in						
_ Суппаѕ	Bleacher Seating	2nd Floor	92	EA	7	101.1/2272	
					7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5,912	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	7	10+ years	
	Floor - Wood	2nd Floor	5,912	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	2nd Floor	15	EA	6	6-10 years	
	Scoreboards	2nd Floor	1	EA	7	6-10 years	
			•		-	,	



Category : Room			В	uilding	: Main		242 3 Sawyer AVENUE, Chicago, iL 6063
carego	.,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	2nd Floor	108	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5,826	SF	6	10+ years	
Kitchen							
MICHELL	Ceiling - Plaster/Drywall	Basement	201	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	ĒΑ	7	10+ years	
	Floor - Tile Quarry	Basement	201	SF	6	6-10 years	
	Lighting - Pendent/Surface	Basement	4	EΑ	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Basement	563	SF	6	6-10 years	
Lunah 9	Multipurpose Room						
Lunch &	Ceiling - Exposed	017	1,355	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	017	1,355	SF	7	10+ years	
	Lighting - Pendent/Surface	017	1,333	EA	6	6-10 years	
	Walls - Masonry	017	735	SF	6	10+ years	
	Walls - Plaster/Drywall	017	735 735	SF	6	10+ years	
	walls - Flastel/Drywall	017	733	SF	b	10+ years	
MDF_ID							
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Finishes	Basement	127	SF	5	10+ years	
	Other Cooling Unit	Basement	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	20	SF	7	10+ years	
	Janitor's Closet	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	160	SF	7	10+ years	
	Storage Room	1st Floor	140	SF	7	10+ years	
	Storage Room	1st Floor	200	SF	7	10+ years	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	200	SF	7	10+ years	
	Janitor's Closet	3rd Floor	40	SF	7	10+ years	
	Air Tunnel	Basement	874	SF	7	10+ years	
	Boiler Room	Basement	2,450	SF	7	6-10 years	
	Janitor's Closet	Basement	60	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	200	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	360	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	240	SF	7	10+ years	
	Storage Room	Basement	1,300	SF	7	10+ years	
Deet	_						
Restroor	n Accessories	1.5 Floor South Unisex	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1.5 Floor South Unisex 1.5 Floor South Unisex	58 58	SF SF	<i>7</i> 6	•	
	Ceiling - Flastel/Diywall	1.5 Floor South Offisex	36	SF	Ü	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1.5 Floor South Unisex	1	EA	7	10+ years	
	Floor - Tile	1.5 Floor South Unisex	57	SF	6	6-10 years	
	Floor - Tile	1.5 Floor South Unisex	1	SF	4	1-2 years	Cracked
	Hand Dryer	1.5 Floor South Unisex	1	EA	7	6-10 years	
	Lavatory	1.5 Floor South Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1.5 Floor South Unisex	1	EA	6	6-10 years	
	Partitions	1.5 Floor South Unisex	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 Floor South Unisex	294	SF	6	10+ years	
	Water Closet	1.5 Floor South Unisex	1	EA	7	10+ years	
	Accessories	101A	55	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	101A	55	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101A	1	EA	7	10+ years	
	Floor - Tile	101A	55	SF	6	10+ years	
	Lavatory	101A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	101A	1	EA	6	6-10 years	
	Partitions	101A	1	EA	7	10+ years	
	Walls - Plaster/Drywall	101A	225	SF	5	10+ years	
	Water Closet	101A	1	ĒΑ	7	10+ years	
	Accessories	1st Floor	379	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	379	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	379	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EΑ	6	6-10 years	
	Partitions	1st Floor	6	EΑ	7	10+ years	
	Walls - Masonry	1st Floor	350	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	343	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	245	SF	6	10+ years	
	Water Closet	1st Floor	6	EA	7	10+ years	
	Accessories	1st Floor	337	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	337	SF	6	10+ years	
	Doors - Transom Window	1st Floor	23	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	337	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	5	EA	7	10+ years	
	Walls - Masonry	1st Floor	350	SF	6	10+ years	
	Walls - Masonry Walls - Plaster/Drywall	1st Floor	343	SF SF	6	10+ years 10+ years	
	Walls - Flaster/Drywall Walls - Structural Glazed Tile	1st Floor	245	SF	6	-	
	vvans - Structural Glazeu Tile	13(1100)	240	JF	O	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	2.5 Floor South Unisex	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2.5 Floor South Unisex	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2.5 Floor South Unisex	1	EA	7	10+ years	
	Floor - Tile	2.5 Floor South Unisex	64	SF	7	6-10 years	
	Floor - Tile	2.5 Floor South Unisex	1	SF	4	1-2 years	Cracked
	Hand Dryer	2.5 Floor South Unisex	1	EA	7	6-10 years	
	Lavatory	2.5 Floor South Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2.5 Floor South Unisex	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	2.5 Floor South Unisex	235	SF	6	10+ years	
	Water Closet	2.5 Floor South Unisex	1	ĒΑ	7	10+ years	
	Accessories	2nd Floor	337	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	337	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	23	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	337	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7		
			5	EA EA		10+ years	
	Lighting - Pendent/Surface	2nd Floor			6	6-10 years	
	Partitions	2nd Floor	2	EΑ	7	10+ years	
	Urinals	2nd Floor	5	EA	7	10+ years	
	Walls - Masonry	2nd Floor	350	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	569	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	204	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	329	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	329	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor	329	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	6	6-10 years	
	Partitions	2nd Floor	6	EA	7	10+ years	
	Walls - Masonry	2nd Floor	343	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	569	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	204	SF	6	10+ years	
	Water Closet	2nd Floor	6	EA	7	10+ years	
	Accessories	Basement	337	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	337	SF	6	10+ years	
	Doors - Transom Window	Basement	23	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	337	SF	6	6-10 years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	51,01	Bacomon	2	_, .	•	o io youio	



Category : Room

Classroom #003 (Computer Lab)

Ceiling - Lay-in Doors - Transom Window

Sidney Sawyer Elementary School 5242 S Sawyer AVENUE, Chicago, IL 60632

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Basement	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	5	EA	6	6-10 years	
	Partitions	Basement	2	EΑ	7	10+ years	
	Urinals	Basement	5	EA	7	10+ years	
	Walls - Masonry	Basement	350	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	343	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	245	SF	6	10+ years	
	Water Closet	Basement	2	EA	6	10+ years	
	Accessories	Basement	379	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	379	SF	6	10+ years	
	Doors - Transom Window	Basement	23	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	379	SF	7	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	5	EA	7	6-10 years	
	Partitions	Basement	6	EA	7	10+ years	
	Walls - Masonry	Basement	350	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	343	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	245	SF	6	10+ years	
	Water Closet	Basement	6	EA	7	10+ years	
	Accessories	Boiler room	32	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Boiler room	32	SF	5	6-10 years	
	Doors - Wood Doors inclu hw	Boiler room	1	EA	7	6-10 years	
	Floor - Concrete	Boiler room	32	SF	5	6-10 years	
	Lighting - Pendent/Surface	Boiler room	1	EA	7	6-10 years	
	Walls - Concrete Block	Boiler room	300	SF	7	10+ years	
	Water Closet	Boiler room	1	EA	7	10+ years	
						,	
Catego	ry : Classroom		В	uilding	: Main		
g•	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	om #002 (Regular Classroom)						
<u> </u>	Ceiling - Lay-in	Basement	900	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	900	SF	7	10+ years	
	Lighting - Lay-in	Basement	12	EA	7	6-10 years	
	Marker Board	Basement	5	LF	7	6-10 years	
	Walls - Masonry	Basement	784	SF	7	-	
	vvalis - iviasuriry	Dasement	764	SI	,	10+ years	

Building: Main

Recommend

Basement Basement 1,600

4

SF SF

7

7

10+ years

10+ years



Catego	ry : Classroom		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	Basement	1,600	SF	6	10+ years	
	Lighting - Lay-in	Basement	23	EA	6	6-10 years	
	Marker Board	Basement	6	LF	7	6-10 years	
	Storage/ Closet	Basement	125	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,068	SF	6	10+ years	
	Wireless System	Basement	1	EA	7	6-10 years	
Classroo	om #101 (Science Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	875	SF	5	10+ years	
	Chalk Board	1st Floor	9	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	875	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Storage/ Closet			SF	7	•	
	Walls - Plaster/Drywall	1st Floor	50	SF	6	10+ years	
	walls - Plaster/Drywall	1st Floor	1,265	SF	б	10+ years	
Classroc	om #102 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	775	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	755	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Worn out and chipped
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	775	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall		1,110	SF SF		,	
		1st Floor			6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #104 (Regular Classroom)						
	Casework	1st Floor	9	LF	7	10+ years	
						-	



Catego	ry : Classroom		В	uilding	: Main		242 O dawyer Av ENOL, Officago, IL 00002
22.090	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Plaster/Drywall	1st Floor	775	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	675	SF	7	6-10 years	
	Floor - Tile	1st Floor	100	SF	4	0-1 year	Cracked
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
_Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	797	SF	6	6-10 years	
	Floor - Tile	1st Floor	3	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	oppou
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	800	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	800	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	28	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
Classroo	om #109 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	925	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Boors med nw	1st Floor	925	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	42	LF	7	6-10 years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years	
	vvans - i lastei/Diywan	13111001	1,200	OI	U	10+ years	



Catego	Category : Classroom		В	uilding	: Main		242 O dawyer Avenoe, omeago, ie 00002
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Regular Classroom)						
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	775	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	755	SF	6	6-10 years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	0pp00
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
	•		,			,	
_Classroo	om #111 (Regular Classroom)						
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	775	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,110	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
Classion	Casework	2nd Floor	9	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	,	
	Doors - Transom Window	2nd Floor 2nd Floor		SF SF	7	10+ years	
			9		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA SF		10+ years	
	Floor - Wood	2nd Floor	775	_	6	10+ years	
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	14 38	EA LF	6 7	6-10 years	
		2nd Floor 2nd Floor	50	SF		6-10 years	
	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor		SF SF	7	10+ years	
	walls - Plaster/Drywall	2110 F1001	1,145	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	: : : : : : : : : : : : : : : : :		00	٥.	•	,	



Catego	ory : Classroom		В	uilding	: Main		242 O Gawyer Avenue, Gilleage, in 60002
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
Classro	om #203 (Regular Classroom)						
<u> </u>	Casework	2nd Floor	9	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Books inclu hw	2nd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	,	
	Walls - Plaster/Drywall	ZIId FIOOI	1,110	SF	0	10+ years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
Classro	om #205 (Special Education)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	400	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	400	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	950	SF	6	10+ years	
_Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Wood	2nd Floor	925	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	26	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	67	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
			0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	m #207 (Science Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	790	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	
						, , , , ,	
Classroo	m #208 (Regular Classroom)	0.15					
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	800	SF	6	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	6-10 years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	6	10+ years	
Classroo	m #209 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	917	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	925	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main	<u> </u>	242 3 Sawyer AVENUE, Chicago, IL 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	771	SF	6	6-10 years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	23	EA	6	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
_Classroo	om #211 (Regular Classroom)						
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	775	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	774	SF	6	6-10 years	
	Floor - Tile	2nd Floor	1	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	42	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,110	SF	6	10+ years	
_Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
_Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	775	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	



Category : Classroom			В	uilding	: Main		242 O Gawyer Avenoe, omeago, ie 60002
	.,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
_Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,275	SF	6	10+ years	
_Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	38	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,275	SF	6	10+ years	
_Classroo	om #305 (Store Room)						
	Ceiling - Plaster/Drywall	3rd Floor	393	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	393	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	6	6-10 years	
	Marker Board	3rd Floor	4	LF	7	6-10 years	
	Walls - Masonry	3rd Floor	340	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	320	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	240	SF	6	10+ years	
_Classroo	om #306 (Other Instructional Use)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	400	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	399	SF	6	10+ years	
	Floor - Wood	3rd Floor	1	SF	5	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Masonry	3rd Floor	343	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	240	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	38	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
	Walls Tlaster/DryWall	01011001	1,110	O.	O	101 years	
Classroo	om #311 (Regular Classroom)						
	Casework	3rd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	10+ years	
	Chalk Board	3rd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	775	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,110	SF	6	10+ years	
_Classroo	om #B- 209 (Store Room)						
	Ceiling - Plaster/Drywall	Basement	185	SF	7	10+ years	
	Chalk Board	Basement	12	LF	4	1-2 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Wood	Basement	185	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement	390	SF	7	10+ years	
	·	2305	000	- .	•	,	
_Classroo	om #B-1- 206 (Regular Classroom)						



Catego	ry : Classroom		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Exposed	Basement	850	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years		
	Floor - Tile	Basement	850	SF	6	6-10 years		
	Lighting - Pendent/Surface	Basement	18	EA	6	6-10 years		
	Marker Board	Basement	32	LF	7	6-10 years		
	Storage/ Closet	Basement	125	SF	7	10+ years		
	Walls - Plaster/Drywall	Basement	1,325	SF	6	10+ years		
	Work Sink	Basement	1	EA	7	10+ years		

Category : Interior **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,500	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	1st Floor	3,500	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	54	EA	6	6-10 years	
	Student Lockers - Two Tiers	1st Floor	204	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,380	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,765	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EΑ	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	3	EA	7	6-10 years	
	Floor - Asphalt Floor	2nd Floor	3,765	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	32	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,640	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,449	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	3rd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	6-10 years	
	Floor - Asphalt Floor	3rd Floor	2,449	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,594	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Auditorium Vestibule	210	SF	6	10+ years	
	Doors - Steel Doors incl hw	Auditorium Vestibule	4	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium Vestibule	210	SF	6	6-10 years	
	Lighting - Pendent/Surface	Auditorium Vestibule	5	EA	6	6-10 years	
	Walls - Plaster/Drywall	Auditorium Vestibule	500	SF	6	10+ years	
	Ceiling - Exposed	Basement	3,285	SF	6	10+ years	
	Drinking Fountains - Double Water Cooler	Basement	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	Basement	1	EA	7	6-10 years	
	Floor - Asphalt Floor	Basement	3,285	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	25	EA	6	6-10 years	
	Student Lockers - One Tier	Basement	76	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	3,687	SF	6	10+ years	

Campus Name: Sawyer Page : 23 of 64 Assessment Date: 06/26/2024



Catego	ry : Interior		В	uilding	: Main		<u> </u>
J				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Central Vestibule	71	SF	6	10+ years	
	Doors - Steel Doors incl hw	Central Vestibule	6	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Central Vestibule	71	SF	7	6-10 years	
	Lighting - Pendent/Surface	Central Vestibule	1	EA	6	6-10 years	
	Walls - Masonry	Central Vestibule	110	SF	6	10+ years	
	Walls - Plaster/Drywall	Central Vestibule	25	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North Vestibule	61	SF	6	10+ years	
	Doors - Steel Doors incl hw	North Vestibule	3	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	North Vestibule	3	EΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	North Vestibule	61	SF	6	10+ years	
	Lighting - Pendent/Surface	North Vestibule	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	North Vestibule	200	SF	6	10+ years	
	Walls - Structural Glazed Tile	North Vestibule	120	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Vestibule	79	SF	6	10+ years	
	Doors - Steel Doors incl hw	South Vestibule	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South Vestibule	79	SF	6	6-10 years	
	Lighting - Pendent/Surface	South Vestibule South Vestibule	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	South Vestibule South Vestibule	48	SF			
	Walls - Plaster/Drywaii Walls - Structural Glazed Tile			SF SF	6 6	10+ years	
	vvalis - Structural Glazed Tile	South Vestibule	112	SF.	ь	10+ years	
Cofoty							
Safety	Camera Viewing Station	1st Floor	1	EA	7	10+ years	
	Security Cameras	1st Floor	10	EA	7	6-10 years	
	Security Cameras	1st Floor	20	EA	7	6-10 years	
	Security Cameras	13(1100)	20	LA	,	0-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Assembly hall East	280	SF	7	10+ years	
	Floor - Rubber Floor	Assembly hall East	12	SF	7	10+ years	
	Handrails	Assembly hall East	28	LF	7	10+ years	
	Lighting - Wall Mounted	Assembly hall East	1	EA	7	6-10 years	
	Stairs - Rubber	Assembly hall East	78	LF	7	10+ years	
	Walls - Plaster/Drywall	Assembly hall East	300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Assembly hall West	280	SF	7	10+ years	
	Floor - Rubber Floor	Assembly hall West	12	SF	7	10+ years	
	Handrails	Assembly hall West	28	LF	7	10+ years	
	Lighting - Wall Mounted	Assembly hall West	1	EA	7	6-10 years	
	Stairs - Rubber	Assembly hall West	78	LF	7	10+ years	
	Walls - Plaster/Drywall	Assembly hall West	300	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Central East Stair	449	SF	6	10+ years	
	Floor - Asphalt	Central East Stair	331	SF	6	10+ years	
	Handrails	Central East Stair	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Central East Stair	6	EA	6	6-10 years	
	Lighting - Pendent/Surface Lighting - Wall Mounted	Central East Stair	2	EA	6	6-10 years	
	Stairs - Asphalt	Central East Stair	174	LF	6	-	
	Stairs - Aspirati	Central East Stall	174	LF	O	10+ years	



Catego	ry : Interior		В	uilding	: Main	•	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Central East Stair	1,128	SF	6	10+ years	
	Ceiling - Exposed	Central West Stair	130	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Central West Stair	419	SF	6	10+ years	
	Floor - Asphalt	Central West Stair	889	SF	6	10+ years	
	Handrails	Central West Stair	196	LF	7	10+ years	
	Lighting - Pendent/Surface	Central West Stair	13	EA	6	6-10 years	
	Stairs - Asphalt	Central West Stair	480	LF	6	10+ years	
	Walls - Plaster/Drywall	Central West Stair	3,892	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North Stair	602	SF	6	10+ years	
	Floor - Asphalt	North Stair	518	SF	6	10+ years	
	Handrails	North Stair	114	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stair	4	EA	6	6-10 years	
	Stairs - Asphalt	North Stair	383	LF	6	10+ years	
	Walls - Plaster/Drywall	North Stair	2,556	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Stair	874	SF	6	10+ years	
	Floor - Asphalt	South Stair	547	SF	6	10+ years	
	Handrails	South Stair	194	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stair	7	EA	6	6-10 years	
	Stairs - Asphalt	South Stair	612	LF	6	10+ years	
	Walls - Plaster/Drywall	South Stair	2,168	SF	6	10+ years	





Category: Exterior **Building: Annex**

Category : Exterior			В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	7	6-10 years	
	Exterior Doors - Side lite	1 - Main	2	EA	6	10+ years	
	Exterior Doors - Store Front	1 - Main	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	4	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	32	LF	7	10+ years	
	Ramps - Concrete	1 - Main	16	LF	7	10+ years	
	Exterior Doors - Store Front	10 - NW	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	10 - NW	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	11 Gym	2	EA	6	6-10 years	Repaired
	Exterior Doors - Exterior Steel Door	12 - NE	1	EA	6	10+ years	·
	Entrance Control - Audio and Video	13 - E	1	EA	7	6-10 years	
	Exterior Doors - Store Front	13 - E	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	13 - E	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	14 - Kitchen	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	15 - S Lunchroom	2	EA	6	2-5 years	
	Exterior Doors - Store Front	16 SW	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	16 SW	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	17 - chiller house	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	18 - Chiller house	2	EA	6	10+ years	
Foundati							
	Foundation - Concrete	Entire Building	1,017	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	76,800	SF	7	10+ years	
	Topping						
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	11	EA	7	6-10 years	
Roof Sys							
	Access Ladder - Metal	A - South	1	EA	7	10+ years	
	Chimney - Metal Flue	A - South	35	LF	7	10+ years	
	Coping - Stone	A - South	262	LF	7	10+ years	
	Downspouts - Interior Downspouts	A - South	90	LF	7	10+ years	
	Parapet - Parapet > 30"	A - South	262	LF	7	10+ years	
	Roof - Modified Bitumen	A - South	6,600	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	A - South	6,600	SF	7	10+ years	
	Concrete Topping				_		
	Access Ladder - Metal	B - North	1	EA	7	10+ years	

Campus Name: Sawyer Page : 26 of 64 Assessment Date: 06/26/2024



Catego	ry : Exterior		B	uilding	: Annex	[
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	B - North	262	LF	7	10+ years	
	Downspouts - Interior Downspouts	B - North	90	LF	7	10+ years	
	Parapet - Parapet > 30"	B - North	262	LF	7	10+ years	
	Roof - Modified Bitumen	B - North	6,600	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	B - North	6,600	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	C - High South	1	EA	7	10+ years	
	Coping - Stone	C - High South	680	LF	7	10+ years	
	Downspouts - Interior Downspouts	C - High South	360	LF	7	10+ years	
	Parapet - Parapet > 30"	C - High South	680	LF	7	10+ years	
	Roof - Modified Bitumen	C - High South	19,988	SF	6	10+ years	
	Roof Hatch - Metal	C - High South	1	ĒΑ	7	10+ years	
	Roof Structure - Steel / Metal Deck/	C - High South	19,988	SF	7	10+ years	
	Concrete Topping	o ingricodari	10,000	٥.	•	io. youro	
	Coping - Stone	D - West	220	LF	7	10+ years	
	Downspouts - Interior Downspouts	D - West	120	LF	7	10+ years	
	Parapet - 16" - 30" Height	D - West	220	LF	7	10+ years	
	Roof - Modified Bitumen	D - West	1,718	SF	6	10+ years	
	Roof - Modified Bitumen	D - West	100	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	D - West	1,818	SF	7	10+ years	
	Concrete Topping	D - West	1,010	SF	,	10+ years	
	Controlle ropping						
/alls							
	Canopy - Fabric	Entire Building	672	SF	7	10+ years	
	Canopy - Metal	Entire Building	228	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	800	SF	7	10+ years	Chiller
	Exterior Walls - Brick	Entire Building	31,062	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	3,588	SF	7	10+ years	
/indows							
MICOWS	Lintels - Steel	Entire Building	988	LF	6	10+ years	
	Windows - Decorative	Entire Building	256	SF	6	10+ years	
	Windows - Louver	Entire Building	392	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,258	SF	6	10+ years	
, atouo	ry : Electrical		R	uildina	: Annex	,	
alogo	i y . Electrical			anding	. Alliex	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	



Catego	ry : Electrical		В	uilding	: Annex		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	12	EA	6	6-10 years	One located in each of the twelve student restrooms.
	Security System - CCTV	Entire Building	163,508	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	163,508	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	17,281	SF	7	10+ years	
	Emergency A/C Power - Gym	Entire Building	4,170	SF	7	10+ years	Location changed for clarification.
	Emergency A/C Power - Lunchrooms	Entire Building	3,910	SF	7	10+ years	Location changed for clarification.
Main Sei	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Main Electrical Service - 800 A and 277/480/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	76,800	SF	6	6-10 years	Also serves Main and Modular.
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Independent Electrical Service for emergency power	Entire Building	1	EA	7	10+ years	Location changed for clarification.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	EM fuse panel
	Lighting and Power Panels - Above 100 A	Entire Building	14	EA	7	10+ years	·
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Duct tape covers open breaker slots presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live conductors presenting a live front condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	MCC associated with the 800 A dea front switchboard.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	71		-				



Category : Fire Protection			В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	
	Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	Reason and Priority Rep changed based on current observations and per review with Building Engineer. System is functional and passes inspection but is almost 30 years old, employs unreliable and antiquated technology, and has reached the end of its anticipated service life. No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Rank adjusted based on current observations and per review with Building Engineer. Panel is functiona and passes inspection but is almost 30 years old, employs unreliable and antiquated technology, and has reached the end of its anticipated service life.
	Fire Alarm Strobe Lights	Entire Building	76,800	SF	6	2-5 years	Reason and Priority Rep changed based on current observations and per review with Building Engineer. System is functional and passes inspection but is almost 30 years old, employs unreliable and antiquated technology, and has reached the end of its anticipated service life.
	Fire Alarm_System	Entire Building	76,800	SF	4	2-5 years	Serves Annex. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer. System is functional and passes inspection but is almost 30 years old, employs unreliable and antiquated technology, and has reached the end of its anticipated service life.
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	antioipated service inc.
	·	-				-	
Pump R	oom Assembly						_
	Fire Pump - 25-50 hp Jockey Pump	Fire Pump Room Fire Pump Room	1 1	EA EA	6 6	6-10 years 6-10 years	
Sprinkle	r System						
•	Sprinkler Heads	Entire Building	76,800 76,800	SF SF	7	10+ years	
	Sprinkler Piping Wet Sprinkler System	Entire Building Entire Building	76,800 76,800	SF SF	6 6	10+ years 6-10 years	Location changed for clarification.
		5	1 3,000		-	3 12 , 22 2	

Campus Name: Sawyer Page : 29 of 64 Assessment Date: 06/26/2024



Catego	Category : Fire Protection		В	uilding	: Annex		242 & Gawyer Avenoe, Onleago, in 00032
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Mechanical		В	uildina	: Annex		
				•		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond							
	Chemical Pot Feeder	Entire Building	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons	Entire Building	1	EA	6	10+ years	
	Glycol Feed	Entire Building	1	EA	7	6-10 years	
	Pipes - Chilled Water Pipe- Steel	Entire Building	400	LF	6	10+ years	
	Pressure Fill System	Entire Building	1	EA	7	6-10 years	
	Condensing Unit- Roof Mounted - Less than 5 tons	West Lower Roof	1	EA	6	6-10 years	
_Air Hand	lling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	51	EA	5	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils -	Mechanical Room - AHU-1	1	EA	6	6-10 years	AHU-1, serves 1st floor. Location changed for clarification.
	12001-20000 cfm						changed for claimcation.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Induction Fan	Mechanical Room - AHU-1	1	ĒΑ	6	6-10 years	Location changed for clarification.
	Air Handling Unit-Package Single Zone-	Mechanical Room - AHU-2	1	EA	6	6-10 years	AHU-2, serves 2nd and 3rd floors.
	Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm					,	Location changed for clarification.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	
	Induction Fan	Mechanical Room - AHU-2	1	EA	6	6-10 years	Location changed for clarification.
	Air Handling Unit-Package Single Zone-	Mechanical Room - AHU-3	1	EA	6	6-10 years	AHU-3, serves lunchroom and
	Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm						kitchen spaces. Location changed for clarification.
	Air Intake	Mechanical Room - AHU-3	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room - AHU-4	1	EA	6	6-10 years	AHU-4, serves gym. Location changed for clarification.
	Air Intake	Mechanical Room - AHU-4	1	EA	7	10+ years	
	Indoor Return Fans- Centrifugal Inline -	Mechanical Rooms	1	EA	6	6-10 years	RF-3. Location changed for
	10001 - 20000 CFM		·			-	clarification.
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Rooms	1	EA	6	6-10 years	RF-1. Location changed for clarification.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Rooms	1	EA	6	6-10 years	RF-2. Location changed for clarification.
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	South Lower Roof	1	EA	5	2-5 years	KS-1. Reason and Priority Rep adjusted changed to reflect that the equipment is operational but is

Campus Name: Sawyer Page : 30 of 64 Assessment Date: 06/26/2024



Catego	ry : Mechanical		В	uilding	: Annex		
			0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments approaching the end of its anticipated
							service life.
Boiler Sy	rstems						
	Boiler Auxiliary- Condensing Hot Water - 1001 - 2000 HP	Mechanical Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Mechanical Room	1	EA	6	6-10 years	
	Condensing- Hot Water Boiler - 1001 - 2000 MBH	Mechanical Room	2	EA	6	10+ years	B-1 and B-2
	Glycol Feed System	Mechanical Room	1	EA	6	6-10 years	
	Water Fill System	Mechanical Room	1	EA	5	6-10 years	
Heating	Devices						
	Radiator Panels - Hot Water	Entire Building	12	EA	6	6-10 years	Ceiling mounted in each of the twelve student restrooms.
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	6-10 years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	600	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Rooms	1	EA	6	6-10 years	Location changed for clarification.
	Hot Water Pump - 10 - 20 HP	Mechanical Rooms	1	EA	6	6-10 years	Location changed for clarification.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Associated with AHU-4. No CPS Asset Tag present. Location changed for clarification.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Associated with AHU-3. Location changed for clarification.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Associated with AHU-2. No CPS Asset Tag present. Location changed for clarification.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Associated with AHU-1. No CPS Asset Tag present. Location changed for clarification.
	Chilled Water Pump - 10 - 20 HP	South Mechanical Room	1	EA	6	6-10 years	Location changed for clarification.
	Chilled Water Pump - 10 - 20 HP	South Mechanical Room	1	EA	6	6-10 years	Location changed for clarification.
Tempera	iture Control						
-	DDC System	Entire Building	76,800	SF	7	10+ years	Location changed for clarification.
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	-
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Electric Thermostat	Entire Building	2	EA	7	6-10 years	

Campus Name: Sawyer Page : 31 of 64 Assessment Date: 06/26/2024



Category : Mechanical				uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Thermostats - DDC	Entire Building	53	EA	7	6-10 years	
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Roof Mounted Duct Work	Entire Building	12	LF	6	6-10 years	Location changed for clarification.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	6	6-10 years	Ğ
Catego	ry : Plumbing		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
	Gas Heater - 150000 - 300000 BTU/HR	South Mechanical Room	1	EA	6	10+ years	
	Gas Heater - Less than 150000 BTU/HR	South Mechanical Room	1	EA	6	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	76,800	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	76,800	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	76,800	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	76,800	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	76,800	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	76,800	SF	6	10+ years	
	Sanitary Piping	Entire Building	76,800	SF	7	10+ years	
	Storm Piping	Entire Building	76,800	SF	7	10+ years	
	Vent Piping	Entire Building	76,800	SF	7	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Plumbing Room	1	EA	5	1-2 years	Reason and Priority Rep changed as only one of the two pump motor assemblies is operational.

Campus Name: Sawyer Page : 32 of 64 Assessment Date: 06/26/2024



Catego	ry : Room		В	uildina	: Annex		242 S Sawyer AVENUE, Chicago, IL 60632
3						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Lay-in	131	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	131	1	ĒΑ	7	10+ years	
	Floor - Tile	131	150	SF	7	10+ years	
	Lighting - Lay-in	131	2	ĒA	7	6-10 years	
	Power Distribution	131	8	EA	7	10+ years	
	Walls - Concrete Block	131	220	SF	7	10+ years	
	Walls - Plaster/Drywall	131	245	SF	7	10+ years	
	Work SInk	131	1	EA	7	6-10 years	
	Ceiling - Lay-in	133	313	SF	7	10+ years	
	Doors - Wood Doors inclu hw	133	1	EA	7	10+ years	
	Floor - Tile	133	313	SF	6	10+ years	
	Lighting - Lay-in	133	4	EA	7	6-10 years	
	Power Distribution	133	4	EA	7	10+ years	
	Storage/ Closet	133	23	SF	7	10+ years	
	Walls - Concrete Block	133	440	SF	7	10+ years	
	Walls - Plaster/Drywall	133	330	SF	6	10+ years	
	Ceiling - Lay-in	135 Library	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	135 Library	1	ĒΑ	7	10+ years	
	Floor - Carpet	135 Library	140	SF	7	6-10 years	
	Lighting - Lay-in	135 Library	2	ĒΑ	7	6-10 years	
	Power Distribution	135 Library	4	EA	7	10+ years	
	Walls - Concrete Block	135 Library	70	SF	7	10+ years	
	Walls - Plaster/Drywall	135 Library	385	SF	7	10+ years	
	Ceiling - Lay-in	137 Library	140	SF	7	10+ years	
	Doors - Wood Doors inclu hw	137 Library	1	ĒΑ	7	10+ years	
	Floor - Carpet	137 Library	140	SF	7	6-10 years	
	Lighting - Lay-in	137 Library	2	ĒΑ	7	6-10 years	
	Power Distribution	137 Library	4	EA	7	10+ years	
	Walls - Concrete Block	137 Library	110	SF	7	10+ years	
	Walls - Concrete Block	137 Library	345	SF	7	10+ years	
	Ceiling - Lay-in	224A Science Prep Room	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	224A Science Prep Room	1	ĒΑ	7	10+ years	
	Floor - Tile	224A Science Prep Room	200	SF	7	10+ years	
	Lighting - Lay-in	224A Science Prep Room	2	EA	7	6-10 years	
	Lighting - Lay-in	224A Science Prep Room	1	EA	6	2-5 years	Not working
	Power Distribution	224A Science Prep Room	4	ĒΑ	7	10+ years	. .
	Walls - Concrete Block	224A Science Prep Room	116	SF	7	10+ years	
	Walls - Plaster/Drywall	224A Science Prep Room	640	SF	7	10+ years	
	Ceiling - Lay-in	Assistant Principal's Office	202	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant Principal's Office	1	ĒΑ	7	10+ years	
	Floor - Carpet	Assistant Principal's Office	202	SF	7	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office	3	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office	6	EΑ	7	10+ years	
		, issue in this part of this	· ·		•	, care	



Catego	ry : Room	Building : Annex					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	Assistant Principal's Office	108	SF	7	10+ years	
	Walls - Plaster/Drywall	Assistant Principal's Office	380	SF	7	10+ years	
	Ceiling - Lay-in	Engineer's office	121	SF	7	10+ years	
	Doors - Side-lite	Engineer's office	20	SF	7	10+ years	
	Doors - Steel Doors incl hw	Engineer's office	1	EA	7	10+ years	
	Floor - Tile	Engineer's office	121	SF	7	10+ years	
	Lighting - Lay-in	Engineer's office	2	EA	7	6-10 years	
	Power Distribution	Engineer's office	8	EA	7	10+ years	
	Walls - Concrete Block	Engineer's office	339	SF	7	10+ years	
	Ceiling - Exposed	Gym Office	150	SF	7	10+ years	
	Doors - Steel Doors incl hw	Gym Office	2	EA	7	10+ years	
	Floor - Tile	Gym Office	150	SF	7	10+ years	
	Lighting - Pendent/Surface	Gym Office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Gym Office	1	EA	6	2-5 years	Not working
	Power Distribution	Gym Office	2	EA	7	10+ years	
	Walls - Concrete Block	Gym Office	665	SF	7	10+ years	
	Ceiling - Lay-in	In Comp 222 North of Workroom	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Comp 222 North of Workroom	1	EA	7	10+ years	
	Floor - Tile	In Comp 222 North of Workroom	100	SF	7	10+ years	
	Lighting - Lay-in	In Comp 222 North of Workroom	1	EA	7	6-10 years	
	Power Distribution	In Comp 222 North of Workroom	2	EA	7	10+ years	
	Walls - Concrete Block	In Comp 222 North of Workroom	150	SF	7	10+ years	
	Walls - Plaster/Drywall	In Comp 222 North of Workroom	226	SF	7	10+ years	
	Work SInk	In Comp 222 North of Workroom	1	EA	7	10+ years	
	Ceiling - Lay-in	Kitchen Office	56	SF	6	10+ years	
	Doors - Side-lite	Kitchen Office	18	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Office	56	SF	6	10+ years	
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	6	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Office	258	SF	7	10+ years	
	Ceiling - Lay-in	Main Office	782	SF	7	10+ years	
	Doors - Side-lite	Main Office	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	7	10+ years	
	Floor - Carpet	Main Office	647	SF	7	6-10 years	
	Floor - Terrazzo	Main Office	135	SF	7	10+ years	
	Lighting - Lay-in	Main Office	24	EA	7	6-10 years	
	Power Distribution	Main Office	24	EA	7	10+ years	
	Storage/ Closet	Main Office	18	SF	7	10+ years	
	Walls - Concrete Block	Main Office	800	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	450	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office	282	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	ĒΑ	7	10+ years	
	Floor - Carpet	Principal's Office	282	SF	7	6-10 years	
			_ 		-	y ,	



Category : Room			В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Principal's Office	3	EA	7	6-10 years	
	Lighting - Lay-in	Principal's Office	1	EA	6	2-5 years	Not working
	Power Distribution	Principal's Office	8	EA	7	10+ years	
	Walls - Concrete Block	Principal's Office	274	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office	316	SF	7	10+ years	
	Ceiling - Lay-in	Vault/Work Room in Main Office	216	SF	7	10+ years	
	Doors - Steel Doors incl hw	Vault/Work Room in Main Office	1	EA	7	10+ years	
	Floor - Tile	Vault/Work Room in Main Office	216	SF	7	10+ years	
	Lighting - Lay-in	Vault/Work Room in Main Office	4	EA	7	6-10 years	
	Power Distribution	Vault/Work Room in Main Office	4	EA	7	10+ years	
	Walls - Concrete Block	Vault/Work Room in Main Office	600	SF	7	10+ years	
	Work Slnk	Vault/Work Room in Main Office	1	ĒΑ	7	6-10 years	
	Ceiling - Lay-in	Work Room In Comp 222	112	SF	7	10+ years	
	Doors - Side-lite	Work Room In Comp 222	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Work Room In Comp 222	1	EA	7	10+ years	
	Floor - Tile	Work Room In Comp 222	112	SF	7	10+ years	
	Lighting - Lay-in	Work Room In Comp 222	1	EA	7	6-10 years	
	Walls - Concrete Block	Work Room In Comp 222	160	SF	7	10+ years	
	Walls - Plaster/Drywall	Work Room In Comp 222	200	SF	7	10+ years	
	Work Sink	Work Room In Comp 222	1	EA	7	6-10 years	
	Ceiling - Lay-in	YMCA Office in Class 141	223	SF	7	10+ years	
	Doors - Wood Doors inclu hw	YMCA Office in Class 141	1	EA	7	10+ years	
	Floor - Tile	YMCA Office in Class 141	223	SF	7	10+ years	
	Lighting - Lay-in	YMCA Office in Class 141	1	EA	7	6-10 years	
	Lighting - Lay-in	YMCA Office in Class 141	1	EA	6	2-5 years	Not working
	Power Distribution	YMCA Office in Class 141	4	EA	7	•	Not working
			94	SF	7	10+ years	
	Walls - Concrete Block	YMCA Office in Class 141	_	SF SF	7 7	10+ years	
	Walls - Plaster/Drywall	YMCA Office in Class 141	416	5F	/	10+ years	
Gymnas	ia						
•	Bleacher Seating	1st Floor	68	EA	6	10+ years	
	Ceiling - Exposed	1st Floor	4,155	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Sport Flooring	1st Floor	4,170	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	7,050	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	Kitchen & Dishwashing	1,310	SF	6	10+ years	
	Doors - Steel Doors incl hw	Kitchen & Dishwashing	3	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen & Dishwashing	1,310	SF	7	10+ years	
	Lighting - Lay-in	Kitchen & Dishwashing	14	EA	7	6-10 years	



Category : Room			В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	Kitchen & Dishwashing	190	SF	7	10+ years	
	Walls - Concrete Block	Kitchen & Dishwashing	2,480	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	1st Floor	3,308	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	594	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	_ 1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	3,910	SF	7	10+ years	
	Floor - Tile	1st Floor	7	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	2-5 years	Not working
	Serving Line	1st Floor	20	LF	7	10+ years	140t Working
	Walls - Concrete Block	1st Floor	6,374	SF	7	10+ years	
		1st Floor	165	SF	7	•	
	Walls - Plaster/Drywall	1st Floor	105	SF	,	10+ years	
MDF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	160	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	Entire Building	15	SF	7	10+ years	
	Janitor's Closet	Entire Building	25	SF	7	10+ years	
	Janitor's Closet	Entire Building	25	SF	7	10+ years	
	Janitor's Closet	Entire Building	25	SF	7	10+ years	
	Janitor's Closet	Entire Building	34	SF	7	10+ years	
	Janitor's Closet	Entire Building	15	SF	7	10+ years	
	Janitor's Closet	Entire Building	15	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	100	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building Entire Building	556	SF SF	7		
	Mechanical/ Service Rooms	Entire Building Entire Building	1,862	SF SF	7	10+ years	
	Mechanical/ Service Rooms Mechanical/ Service Rooms		1,862	SF SF	7	10+ years	
		Entire Building				10+ years	
	Mechanical/ Service Rooms	Entire Building	26	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	2,470	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	18	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	74	SF	7	10+ years	
	Mechanical/ Service Rooms	Entire Building	140	SF	7	10+ years	
	Storage Room	Entire Building	116	SF	7	10+ years	
	Storage Room	Entire Building	42	SF	7	10+ years	



Catego	ry : Room		Building : Annex						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Restroo	m					-			
	Accessories	128A	34	SF	7	6-10 years			
	Ceiling - Lay-in	128A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128A	1	EA	7	10+ years			
	Floor - Tile	128A	34	SF	6	10+ years			
	Floor Drain	128A	1	ĒΑ	7	10+ years			
	Lavatory	128A	1	EA	7	10+ years			
	Lighting - Lay-in	128A	1	EΑ	7	6-10 years			
	Walls - Structural Glazed Tile	128A	186	SF	7	10+ years			
	Water Closet	128A	1	EA	7	10+ years			
	Accessories	130A	34	SF	7	6-10 years			
	Ceiling - Lay-in	130A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	130A	1	EA	7	10+ years			
	Floor - Tile	130A	34	SF	6	10+ years			
	Floor Drain	130A	1	EA	7	10+ years			
	Lavatory	130A	1	EA	7	10+ years			
	Lighting - Lay-in	130A	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	130A	186	SF	7	10+ years			
	Water Closet	130A	100	EA	7	10+ years			
	Accessories	132A	34	SF	7	6-10 years			
	Ceiling - Lay-in	132A 132A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	132A 132A	1	EA	7	10+ years			
	Floor - Tile	132A 132A	34	SF	6	-			
	Floor Floor Drain	132A 132A	1	EA	7	10+ years			
		132A 132A	1	EA	7	10+ years			
	Lavatory Lighting - Lay-in	132A 132A	1	EA		10+ years			
	Walls - Structural Glazed Tile			SF	6	6-10 years			
	Water Closet	132A	186	SF EA	7	10+ years			
		132A	1		7	10+ years			
	Accessories	134A	34	SF	7	6-10 years			
	Ceiling - Lay-in	134A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	134A	1	EA	7	10+ years			
	Floor - Tile	134A	34	SF	6	10+ years			
	Floor Drain	134A	1	EΑ	7	10+ years			
	Lavatory	134A	1	EA	7	10+ years			
	Lighting - Lay-in	134A	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	134A	186	SF	7	10+ years			
	Water Closet	134A	1	EA	7	10+ years			
	Accessories	136A	34	SF	7	6-10 years			
	Ceiling - Lay-in	136A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	136A	1	EA	7	10+ years			
	Floor - Tile	136A	34	SF	6	10+ years			
	Floor Drain	136A	1	EA	7	10+ years			
	Lavatory	136A	1	EA	7	10+ years			
	Lighting - Lay-in	136A	1	EA	7	6-10 years			



Category : Room			Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Structural Glazed Tile	136A	186	SF	7	10+ years			
	Water Closet	136A	1	EA	7	10+ years			
	Accessories	138A	34	SF	7	6-10 years			
	Ceiling - Lay-in	138A	34	SF	7	10+ years			
	Doors - Wood Doors inclu hw	138A	1	EA	7	10+ years			
	Floor - Tile	138A	34	SF	6	10+ years			
	Floor Drain	138A	1	EA	7	10+ years			
	Lavatory	138A	1	EA	7	10+ years			
	Lighting - Lay-in	138A	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	138A	186	SF	7	10+ years			
	Water Closet	138A	1	EA	7	10+ years			
	Accessories	1st Floor North	186	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor North	186	SF	7	10+ years			
	Floor - Terrazzo	1st Floor North	186	SF	7	10+ years			
	Floor Drain	1st Floor North	1	EA	7	10+ years			
	Hand Dryer	1st Floor North	2	EA	7	6-10 years			
	Lavatory	1st Floor North	1	EA	7	10+ years			
	Lavatory	1st Floor North	2	EA	6	10+ years			
	Lighting - Lay-in	1st Floor North	5	EA	7	6-10 years			
	Partitions	1st Floor North	2	EA	7	10+ years			
	Urinals	1st Floor North	2	EA	7	10+ years			
	Walls - Concrete Block	1st Floor North	42	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor North	660	SF	7	10+ years			
	Water Closet	1st Floor North	2	EA	7	10+ years			
	Accessories	1st Floor North	174	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor North	174	SF	7	10+ years			
	Floor - Terrazzo	1st Floor North	174	SF	7	10+ years			
	Floor Drain	1st Floor North	1	EA	7	10+ years			
	Hand Dryer	1st Floor North	2	EA	7	6-10 years			
	Lavatory	1st Floor North	1	EA	7	10+ years			
	Lavatory	1st Floor North	1	EΑ	4	1-2 years	Out of service		
	Lighting - Lay-in	1st Floor North	5	EA	7	6-10 years			
	Partitions	1st Floor North	4	EA	7	10+ years			
	Walls - Concrete Block	1st Floor North	65	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor North	720	SF	7	10+ years			
	Water Closet	1st Floor North	4	EA	7	10+ years			
	Accessories	1st Floor South	174	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor South	174	SF	7	10+ years			
	Floor - Terrazzo	1st Floor South	174	SF	7	10+ years			
	Floor Drain	1st Floor South	1	EΑ	7	10+ years			
	Hand Dryer	1st Floor South	2	EΑ	7	6-10 years			
	Lavatory	1st Floor South	1	EΑ	7	10+ years			
	Lavatory	1st Floor South	2	EΑ	7	10+ years			
	Lighting - Lay-in	1st Floor South	5	EA	7	6-10 years			



Catego	Category : Room		В	uilding	: Annex		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor South	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor South	65	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor South	720	SF	7	10+ years	
	Water Closet	1st Floor South	4	EA	7	10+ years	
	Accessories	1st Floor South	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor South	186	SF	7	10+ years	
	Floor - Terrazzo	1st Floor South	186	SF	7	10+ years	
	Floor Drain	1st Floor South	1	EA	7	10+ years	
	Hand Dryer	1st Floor South	2	EA	7	6-10 years	
	Lavatory	1st Floor South	2	EA	7	10+ years	
	Lavatory	1st Floor South	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor South	5	EA	7	6-10 years	
	Partitions	1st Floor South	2	EA	7	10+ years	
	Urinals	1st Floor South	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor South	42	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor South	660	SF	7	6-10 years	
	Water Closet	1st Floor South	2	ĒΑ	7	10+ years	
	Accessories	1st Floor South Unisex	42	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor South Unisex	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor South Unisex	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor South Unisex	42	SF	7	10+ years	
	Floor Drain	1st Floor South Unisex	1	EA	7	10+ years	
	Hand Dryer	1st Floor South Unisex	1	EA	7	10+ years	Not previously assessed
	Lavatory	1st Floor South Unisex	1	EA	7	10+ years	Not previously assessed
	Lighting - Pendent/Surface	1st Floor South Unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor South Unisex	50	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor South Unisex	164	SF	7	10+ years	
	Water Closet	1st Floor South Unisex	104	EA	7	6-10 years	
	Accessories	2nd Floor North	174	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North	174	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor North	174	SF	7	10+ years	
	Floor Drain	2nd Floor North	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North	2	EA	7	6-10 years	
	•	2nd Floor North	3	EA	7		
	Lavatory Lighting - Lay-in	2nd Floor North	5 5	EA	7	10+ years 6-10 years	
	Partitions	2nd Floor North	4	EA	7		
			•			10+ years	
	Walls - Concrete Block	2nd Floor North	65	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor North	720	SF	7	10+ years	
	Water Closet	2nd Floor North	4	EA	7	10+ years	
	Accessories	2nd Floor North	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North	186	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor North	186	SF	7	10+ years	
	Floor Drain	2nd Floor North	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North	2	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor North	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor North	5	EA	7	6-10 years	
	Partitions	2nd Floor North	2	EA	7	10+ years	
	Urinals	2nd Floor North	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor North	42	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor North	660	SF	7	10+ years	
	Water Closet	2nd Floor North	2	EA	7	10+ years	
	Accessories	2nd Floor South	174	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor South	174	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor South	174	SF	7	10+ years	
	Floor Drain	2nd Floor South	1	EA	7	10+ years	
	Hand Dryer	2nd Floor South	2	EA	7	6-10 years	
	Lavatory	2nd Floor South	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor South	5	EA	7	6-10 years	
	Partitions	2nd Floor South	4	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor South	65	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor South	720	SF	7	10+ years	
	Water Closet	2nd Floor South	4	EA	7	10+ years	
	Accessories	2nd Floor South	186	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor South	186	SF	7	10+ years	
	Floor - Terrazzo	2nd Floor South	186	SF	7	10+ years	
	Floor Drain	2nd Floor South	1	EA	7	10+ years	
	Hand Dryer	2nd Floor South	2	EA	7	6-10 years	
	Lavatory	2nd Floor South	1	EA	7	10+ years	
	Lavatory	2nd Floor South	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor South	5	EA	7	6-10 years	
	Partitions	2nd Floor South	2	EA	7	10+ years	
	Urinals	2nd Floor South	2	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor South	42	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor South	660	SF	7	10+ years	
	Water Closet	2nd Floor South	2	EA	7	6-10 years	
	Accessories	2nd Floor South Unisex	42	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor South Unisex	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor South Unisex	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor South Unisex	42	SF	7	10+ years	
	Floor Drain	2nd Floor South Unisex	1	EA	7	10+ years	
	Lavatory	2nd Floor South Unisex	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor South Unisex	1	EA	7		
	Walls - Structural Glazed Tile	2nd Floor South Unisex 2nd Floor South Unisex	214	SF	7 7	6-10 years 10+ years	
	Water Closet	2nd Floor South Unisex	1	EA	7	•	
	Accessories	3rd Floor North	174	SF	7 7	10+ years	
			174	SF SF	7 7	6-10 years	
	Ceiling - Plaster/Drywall Floor - Terrazzo	3rd Floor North 3rd Floor North	174	SF SF	7 7	10+ years	
	Floor Drain	3rd Floor North	174	Sr EA	7	10+ years	
	FIUUI DIAIII	SIU FIOOI NOITI	I	EA	,	10+ years	



Category : Room			Building : Annex						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Hand Dryer	3rd Floor North	2	EA	7	6-10 years			
	Lavatory	3rd Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor North	5	EA	7	6-10 years			
	Partitions	3rd Floor North	4	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor North	65	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor North	720	SF	7	10+ years			
	Water Closet	3rd Floor North	3	EA	7	10+ years			
	Water Closet	3rd Floor North	1	EA	4	1-2 years	Out of service		
	Accessories	3rd Floor North	186	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor North	186	SF	7	10+ years			
	Floor - Terrazzo	3rd Floor North	186	SF	7	10+ years			
	Floor Drain	3rd Floor North	1	EA	7	10+ years			
	Hand Dryer	3rd Floor North	2	EΑ	7	6-10 years			
	Lavatory	3rd Floor North	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor North	5	EA	7	6-10 years			
	Partitions	3rd Floor North	2	EA	7	10+ years			
	Urinals	3rd Floor North	2	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor North	42	SF	7				
				SF SF		10+ years			
	Walls - Structural Glazed Tile	3rd Floor North	660		7	10+ years			
	Water Closet	3rd Floor North	2	EA	7	10+ years			
	Accessories	3rd Floor South	174	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor South	174	SF	7	10+ years			
	Floor - Terrazzo	3rd Floor South	174	SF	7	10+ years			
	Floor Drain	3rd Floor South	1	EA	7	10+ years			
	Hand Dryer	3rd Floor South	2	EA	7	1-2 years	Not in service		
	Lavatory	3rd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor South	4	EA	7	6-10 years			
	Lighting - Lay-in	3rd Floor South	1	EA	6	2-5 years	Not working		
	Partitions	3rd Floor South	4	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor South	65	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor South	720	SF	7	10+ years			
	Water Closet	3rd Floor South	4	EA	7	10+ years			
	Accessories	3rd Floor South	186	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor South	186	SF	6	10+ years			
	Floor - Terrazzo	3rd Floor South	186	SF	7	10+ years			
	Floor Drain	3rd Floor South	1	EA	7	10+ years			
	Hand Dryer	3rd Floor South	2	EA	7	6-10 years			
	Lavatory	3rd Floor South	3	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor South	5	EA	7	6-10 years			
	Partitions	3rd Floor South	2	EA	7	10+ years			
	Urinals	3rd Floor South	2	ΕA	7	10+ years			
	Walls - Concrete Block	3rd Floor South	42	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor South	660	SF	7	10+ years			
	Water Closet	3rd Floor South	2	EA	7	10+ years			
	114.0. 0.0001	314 1 1001 00411	2	L/\	,	ioi youis			



Category : Room			В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Floor South Unisex	42	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor South Unisex	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor South Unisex	1	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor South Unisex	42	SF	7	10+ years	
	Floor Drain	3rd Floor South Unisex	1	EA	7	10+ years	
	Lavatory	3rd Floor South Unisex	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor South Unisex	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Floor South Unisex	214	SF	7	10+ years	
	Water Closet	3rd Floor South Unisex	1	EA	7	10+ years	
	Accessories	Kitchen Men's	88	SF	7	2-5 years	
	Ceiling - Plaster/Drywall	Kitchen Men's	88	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Men's	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen Men's	88	SF	7	10+ years	
	Floor Drain	Kitchen Men's	1	EA	7	10+ years	
	Lavatory	Kitchen Men's	1	EA	7	10+ years	
	Lighting - Lay-in	Kitchen Men's	1	EA	7	10+ years	
	Partitions	Kitchen Men's	1	EA	7	10+ years	
	Student Lockers - Two Tiers	Kitchen Men's	10	EA	6	10+ years	
	Walls - Structural Glazed Tile	Kitchen Men's	388	SF	6	10+ years	
	Water Closet	Kitchen Men's	1	EA	7	10+ years	
	Accessories	Kitchen Women's	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen Women's	88	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Women's	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen Women's	88	SF	7	10+ years	
	Floor Drain	Kitchen Women's	1	EA	7	10+ years	
	Lavatory	Kitchen Women's	1	EΑ	7	10+ years	
	Lighting - Lay-in	Kitchen Women's	1	EA	7	6-10 years	
	Partitions	Kitchen Women's	1	EΑ	7	10+ years	
	Student Lockers - Two Tiers	Kitchen Women's	10	EA	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen Women's	388	SF	7	10+ years	
	Water Closet	Kitchen Women's	1	EA	7	10+ years	
	Accessories	Main Office Toilet	40	SF	7	6-10 years	
	Ceiling - Lay-in	Main Office Toilet	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office Toilet	1	EA	7	10+ years	
	Floor - Terrazzo	Main Office Toilet	40	SF	7	10+ years	
	Floor Drain	Main Office Toilet	1	EA	7	10+ years	
	Lavatory	Main Office Toilet	1	EA	7	10+ years	
	Lighting - Lay-in	Main Office Toilet	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Main Office Toilet	230	SF	7	10+ years	
	Water Closet	Main Office Toilet	1	EA	7	10+ years	
						- -	



atego	ry : Classroom		В	uilding	: Annex		
	_					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #128 (Kindergarten)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,040	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,040	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years	
	Storage/ Closet	1st Floor	74	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	120	SF	6	10+ years	
	Walls - Concrete Block	1st Floor	1,010	SF	6	10+ years	
	Walls - Concrete Block	1st Floor	80	SF	5	1-2 years	Cracking block wall
	Work Sink	1st Floor	2	EA	7	10+ years	· ·
assroc	om #129 (Special Program)						
	Casework	1st Floor	11	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	786	SF	6	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	696	SF	6	6-10 years	
	Floor - Tile	1st Floor	90	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	6	2-5 years	Not working
	Lighting - Lay-in	1st Floor	10	EA	6	6-10 years	Not Working
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	974	SF	6	10+ years	
	Walls - Concrete Block	1st Floor	20	SF	5	1-2 years	Cracking block wall
	Work Sink	1st Floor	1	EA	7	10+ years	Cracking block wall
esroc	om #130 (Kindergarten)						
100100	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,040	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,040	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	74	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,270	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	20	SF	, 5	1-2 years	Cracking block wall
	Work Sink	1st Floor	20 2	EA	7	10+ years	Cracking block wall
eeroo	om #132 (Kindergarten)						
الانتخابال	Casework	1st Floor	8	LF	7	10+ years	
		1st Floor	1,040	SF	7	-	
	Ceiling - Lay-in	121 LIOOI	1,040	SF	′	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,040	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	74	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #134 (Kindergarten)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,040	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	1,040	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1,040	EA	7	6-10 years	
	Marker Board	1st Floor		LF			
		1st Floor	18 74	SF	7	6-10 years	
	Storage/ Closet				7	10+ years	
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #136 (Kindergarten)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,040	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,030	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracking tile
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	Ç
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	74	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #138 (Kindergarten)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,040	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,040	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1,040	EA	7	6-10 years	
		1st Floor	12	LF			
	Marker Board			SF	7 7	6-10 years	
	Storage/ Closet	1st Floor	74	or.	1	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
assroc	om #140 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	6	2-5 years	Not working
	Marker Board	1st Floor	12	LF	7	6-10 years	3
	Walls - Concrete Block	1st Floor	780	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	230	SF	7	10+ years	
lassroc	om #141A (Other Instructional Use)						
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	3	EA	6	2-5 years	Not working
	Marker Board	1st Floor	18	LF	7	-	Not working
	Walls - Concrete Block	1st Floor	560	SF	7	6-10 years 10+ years	
	Walls - Plaster/Drywall	1st Floor	450	SF	7	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
lassroc	om #220 (Regular Classroom)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	950	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	950	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	570	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	30	SF	5	1-2 years	Cracking block wall
	Walls - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
assroc	om #222/223 (Computer Lab)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,360	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	2,300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	2,360	SF	7	,	
		2nd Floor	2,360	Sr EA	7	6-10 years	
	Lighting - Lay-in	2110 11001	19	EA	′	6-10 years	



Catego	ry : Classroom		B	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	960	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	530	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	m #222A (Store Room)						
	Ceiling - Lay-in	2nd Floor	365	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	365	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	546	SF	7	10+ years	
Classroo	m #224 (Regular Classroom)						
	Casework	2nd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,192	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Stained tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,180	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Chipped tile
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years	omprod mo
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	520	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	
Classroo	m #225 (Regular Classroom)						
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	728	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	728	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	11	ĒΑ	6	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	6	2-5 years	Not working
	Marker Board	2nd Floor	24	LF	7	6-10 years	- 3
	Storage/ Closet	2nd Floor	85	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	920	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #226 (Regular Classroom)						
	Casework	2nd Floor	38	LF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	1,200	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,170	SF	7	10+ years	
	Floor - Tile	2nd Floor	15	SF	4	1-2 years	Chipped tile
	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	520	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	
Classroo	om #227 (Regular Classroom)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	785	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	785	SF	7	10+ years	
		2nd Floor 2nd Floor		EA	6		
	Lighting - Lay-in		10			6-10 years	Naturalia
	Lighting - Lay-in	2nd Floor	2	EA LF	6	2-5 years	Not working
	Marker Board	2nd Floor	12		7	6-10 years	
	Storage/ Closet	2nd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	850	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #228 (Regular Classroom)						
	Casework	2nd Floor	38	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,215	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,205	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Chipped tile
	Lighting - Lay-in	2nd Floor	19	ĒΑ	6	6-10 years	oppod ino
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	515	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	20	SF	5	1-2 years	Cracking block wall
	Walls - Plaster/Drywall	2nd Floor	800	SF	7	10+ years	Ordoning blook wall
Classroo	om #229 (Regular Classroom)						
UGSSIUL	,	2nd Floor	26	LF	7	10 L Voors	
	Casework			SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Annex		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	730	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	87	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	815	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	10	SF	5	1-2 years	Cracking block wall
	Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #231 (Regular Classroom)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	1	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	55	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	850	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	7	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #233 (Regular Classroom)						
	Casework	2nd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	780	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	1	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	65	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	866	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	260	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #235 (Regular Classroom)						
	Casework	2nd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	760	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	200.0 0.00 11.0	2.13 . 1001	10	٥.	•	.o. youro	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	760	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	55	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	785	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	785	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	850	SF	7	10+ years	
				SF SF		•	
	Walls - Plaster/Drywall	3rd Floor	100		7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #322 (Regular Classroom)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	780	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	780	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	ĒΑ	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	Not working
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	842	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	110	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classron	om #324 (Regular Classroom)						
VIUSSIUC	Ceiling - Lay-in	3rd Floor	600	SF	7	10+ years	
	Doors - Side-lite				7		
		3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	600	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	452	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	452	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #325 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	60	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	952	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	156	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #326 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	450	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	450	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	5	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	500	SF	6	10+ years	
Classroo	om #327 (Regular Classroom)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	758	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	758	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	Not working
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	57	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	946	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	



Catego	Category : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #329 (Regular Classroom)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	850	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	100	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #330 (Regular Classroom)						
	Casework	3rd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,020	SF	7	10+ years	
	Chalk Board	3rd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,020	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	Not working
	Marker Board	3rd Floor	24	LF	7	6-10 years	110t Working
	Storage/ Closet	3rd Floor	90	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	876	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
01	(1004 (D I. Ol)						
Classroc	om #331 (Regular Classroom)	0-4 Fl	22	1.5	7	40	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	760	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	65	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	840	SF	7	10+ years	One older a blanch "
	Walls - Concrete Block	3rd Floor	10	SF	5	1-2 years	Cracking block wall
	Walls - Plaster/Drywall	3rd Floor	100	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #332 (Regular Classroom)						
	(3						



Catego	ry : Classroom		В	uilding	: Annex		242 3 Sawyer AVENUE, Chicago, iL 60632
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	780	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	780	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	Not working
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	90	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	755	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
_Classroo	om #333 (Regular Classroom)						
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	845	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	65	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	650	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	300	SF	6	10+ years	
	Work Sink	3rd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #334 (Regular Classroom)						
	Casework	3rd Floor	26	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	785	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	785	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	950	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	150	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #335 (Regular Classroom)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	776	SF	7	10+ years	
	Johning - Lay-III	310 1 1001	770	JI	,	10+ years	



Catego	ry : Classroom		В						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	776	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years			
	Marker Board	3rd Floor	12	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	66	SF	7	10+ years			
	Walls - Concrete Block	3rd Floor	946	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	6-10 years			

Category : Interior **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	420	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	420	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,350	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor 2	3,965	SF	7	10+ years	
	Doors - Side-lite	1st Floor 2	34	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor 2	8	EA	7	10+ years	
	Doors - Store Front	1st Floor 2	76	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor 2	4	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor 2	3,965	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor 2	32	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor 2	5,220	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor Vestibule	410	SF	7	10+ years	
	Doors - Side-lite	1st Floor Vestibule	34	SF	7	10+ years	
	Doors - Store Front	1st Floor Vestibule	76	EA	7	10+ years	
	Floor - Terrazzo	1st Floor Vestibule	410	SF	7	10+ years	
	Lighting - Lay-in	1st Floor Vestibule	4	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Vestibule	370	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	3,960	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	3,960	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	28	EΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor	4,996	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	3,960	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	3,960	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	28	EA	7	6-10 years	

Campus Name: Sawyer Page : 53 of 64 Assessment Date: 06/26/2024



Category : Interior			Building : Annex					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	3rd Floor	4,956	SF	7	10+ years		
Safety								
	Camera Viewing Station	N/A	1	EA	7	6-10 years		
	Security Cameras	N/A	77	EA	7	10+ years		
	Security Cameras	N/A	71	EA	7	10+ years	Exterior	
Stairs								
	Ceiling - Lay-in	Stair A	1,716	SF	7	10+ years		
	Floor - Terrazzo	Stair A	1,718	SF	7	10+ years		
	Handrails	Stair A	172	LF	7	10+ years		
	Lighting - Lay-in	Stair A	18	EA	7	6-10 years		
	Lighting - Lay-in	Stair A	1	EA	6	2-5 years	Not working	
	Lighting - Wall Mounted	Stair A	3	EA	7	6-10 years		
	Rescue Panel	Stair A	1	EA	7	10+ years		
	Stairs - Terrazzo	Stair A	364	LF	7	10+ years		
	Walls - Concrete Block	Stair A	4,580	SF	7	10+ years		
	Walls - Concrete Block	Stair A	20	SF	5	1-2 years	Cracking block wall	
	Walls - Plaster/Drywall	Stair A	50	SF	7	10+ years		
	Ceiling - Lay-in	Stair B	1,150	SF	7	10+ years		
	Floor - Terrazzo	Stair B	1,200	SF	7	10+ years		
	Handrails	Stair B	170	LF	7	10+ years		
	Lighting - Lay-in	Stair B	14	EA	7	6-10 years		
	Lighting - Wall Mounted	Stair B	3	EA	7	6-10 years		
	Rescue Panel	Stair B	1	EA	7	10+ years		
	Stairs - Terrazzo	Stair B	260	LF	7	10+ years		
	Walls - Concrete Block	Stair B	3,900	SF	7	10+ years		
	Walls - Plaster/Drywall	Stair B	40	SF	6	10+ years		
	Ceiling - Lay-in	Stair C	1,716	SF	7	10+ years		
	Floor - Terrazzo	Stair C	1,718	SF	7	10+ years		
	Handrails	Stair C	172	LF	7	10+ years		
	Lighting - Lay-in	Stair C	19	EA	7	6-10 years		
	Lighting - Wall Mounted	Stair C	3	EA	7	6-10 years		
	Rescue Panel	Stair C	1	EA	7	10+ years		
	Stairs - Terrazzo	Stair C	364	LF	7	10+ years		
	Walls - Concrete Block	Stair C	4,425	SF	7	10+ years		
	Walls - Plaster/Drywall	Stair C	50	SF	6	10+ years		
Vertical	Conveyance							
verucal		Ant to Ord flagge	4	ΓΛ	7	40		
	Elevator - Hydraulic Elevator	1st to 3rd floors	1	EA	7	10+ years		



battery packs on the opposite side of the wall in the respective adjacent

classrooms.

6-10 years

6-10 years

6



Security System - CCTV

Security System - Intrusion Detection

Category : Exterior			Building : Modular 1 (6-Classroom) Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door	1 - Main 2 - N	2 2	EA EA	5 6	2-5 years 6-10 years		
	Extends Book Extends clool Book		_	_, ,	Ü	o ro youro		
_Foundati	on							
	Foundation - Masonry	Entire Building	332	LF	7	10+ years		
	Superstructure - Slab on Grade	Entire Building	6,720	SF	7	10+ years		
Lighting								
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	6-10 years		
Roof Sys	stem							
,	Coping - Metal	A	332	LF	7	10+ years		
	Downspouts - Exterior Downspouts	A	24	LF	7	10+ years		
	Downspouts - Exterior Downspouts	A	12	LF	6	10+ years		
	Roof - Modified Bitumen	A	6,720	SF	5	2-5 years		
	Roof Structure - Heavy Timber	Α	6,720	SF	7	10+ years		
Walls								
	Exterior Walls - Hardie Board	Entire Building	3,013	SF	5	2-5 years		
	Exterior Walls - Hardie Board	Entire Building	500	SF	4	0-1 year	Holes, chipped, missing trim	
Windows	3							
	Guard - Guards wire guard	Entire Building	507	SF	6	10+ years		
	Windows - Sash Aluminum Double-pane	Entire Building	507	SF	6	10+ years		
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (6-Classro	oom)	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Emerger	ncy System							
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	7	6-10 years		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	3	EA	6	6-10 years		
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	Light fixtures are connected the	

Campus Name: Sawyer Page : 55 of 64 Assessment Date: 06/26/2024

6,720

6,720

SF

Entire Building

Entire Building



Category : Electrical			Building : Modular 1 (6-Classroom)						
0	Name Tame	Lagation	0	HOM	Danila	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Main Se		E (D) P	0.700			0.40	0 11 4		
	PA System Main Electrical Service - 800 A and Less than 120/208/3PH	Entire Building West Façade	6,720 1	SF EA	6 6	6-10 years 10+ years	Served by Annex		
Power D	istribution								
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	One panel inaccessible at the time of assessment due to excessive stored materials. Condition verified by Building Engineer.		
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (6-Classro	oom)		
						Recommend	,		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar	m								
	Fire Alarm_System	Entire Building	6,720	SF	6	6-10 years	Sprinkler system flow sensor activates audible fire alarm.		
Sprinkler	r System								
	Sprinkler Heads	Entire Building	6,720	SF	7	10+ years			
	Sprinkler Piping	Entire Building	6,720	SF	6	10+ years			
	Wet Sprinkler System	Entire Building	6,720	SF	6	10+ years	Location changed for clarification.		
Catego	ry : Mechanical		R	uildina	· Modul	ar 1 (6-Classro	nom)		
Calego	ry . Mechanical		ل	unung	. Wodu	Recommend	om)		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	ature Control					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
	Electric Thermostat	Entire Building	6	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.		
Unit Ven	tilation								
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	East and West Façades	6	EA	6	6-10 years			
Ventilation	nn								
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	7	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment due to unreliable ladder arrangement Condition verified by Building Engineer.		

Campus Name: Sawyer Page : 56 of 64 Assessment Date: 06/26/2024



Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (6-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	2-5 years	Reason adjusted as the unit is fully operational and free of leaks and undue corrosion, however it is 14 years old and approaching the end of its anticipated service life.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	6,720	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	6,720	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	6,720	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	6,720	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	6,720	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	6,720	SF	6	10+ years	
	Sanitary Piping	Entire Building	6,720	SF	6	10+ years	Routed inside the walls to sewer lines underneath the building.
	Storm Piping	Entire Building	6,720	SF	6	10+ years	S .
	Vent Piping	Entire Building	6,720	SF	6	10+ years	Routed inside the walls to roof- mounted discharge fittings.
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (6-Classro	oom)
						Recommend	, in the second

Item - Type	Location	Quantity	LION	D I-		
71	Location	Quantity	UOM	Rank	Replacement	Comments
m #401 (Regular Classroom)						
` •	1st Floor	800	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	770	SF	6	6-10 years	
Floor - Tile	1st Floor	30	SF	4	1-2 years	Cracked
Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
Marker Board	1st Floor	12	LF	7	6-10 years	
Storage/ Closet	1st Floor	70	SF	7	10+ years	
Walls - Vinyl Coated Gypsum Panel	1st Floor	780	SF	6	10+ years	
m #402 (Regular Classroom)						
Ceiling - Lay-in	1st Floor	800	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	794	SF	6	10+ years	
Floor - Tile	1st Floor	6	SF	4	1-2 years	Cracked
Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Marker Board Storage/ Closet Walls - Vinyl Coated Gypsum Panel ##402 (Regular Classroom) Ceiling - Lay-in Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	Ceiling - Lay-in 1st Floor Doors - Wood Doors inclu hw 1st Floor Floor - Tile 1st Floor Lighting - Lay-in 1st Floor Marker Board 1st Floor Storage/ Closet 1st Floor Walls - Vinyl Coated Gypsum Panel 1st Floor Ceiling - Lay-in 1st Floor M#402 (Regular Classroom) Ceiling - Lay-in 1st Floor Doors - Wood Doors inclu hw 1st Floor Floor - Tile 1st Floor Floor - Tile 1st Floor	Ceiling - Lay-in 1st Floor 800 Doors - Wood Doors inclu hw 1st Floor 1 Floor - Tile 1st Floor 770 Floor - Tile 1st Floor 30 Lighting - Lay-in 1st Floor 12 Marker Board 1st Floor 12 Storage/ Closet 1st Floor 70 Walls - Vinyl Coated Gypsum Panel 1st Floor 780 m #402 (Regular Classroom) 2 Ceiling - Lay-in 1st Floor 800 Doors - Wood Doors inclu hw 1st Floor 1 Floor - Tile 1st Floor 794 Floor - Tile 1st Floor 6	Ceiling - Lay-in 1st Floor 800 SF Doors - Wood Doors inclu hw 1st Floor 1 EA Floor - Tile 1st Floor 770 SF Floor - Tile 1st Floor 30 SF Lighting - Lay-in 1st Floor 12 EA Marker Board 1st Floor 12 LF Storage/ Closet 1st Floor 70 SF Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF m #402 (Regular Classroom) 2st Floor 1 EA Ceiling - Lay-in 1st Floor 1 EA Floor - Tile 1st Floor 794 SF Floor - Tile 1st Floor 6 SF	Ceiling - Lay-in 1st Floor 800 SF 7 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 Floor - Tile 1st Floor 770 SF 6 Floor - Tile 1st Floor 30 SF 4 Lighting - Lay-in 1st Floor 12 EA 7 Marker Board 1st Floor 12 LF 7 Storage/ Closet 1st Floor 70 SF 7 Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 6 m #402 (Regular Classroom) 2 SF 6 Ceiling - Lay-in 1st Floor 800 SF 6 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 Floor - Tile 1st Floor 794 SF 6 Floor - Tile 1st Floor 6 SF 4	Ceiling - Lay-in 1st Floor 800 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 770 SF 6 6-10 years Floor - Tile 1st Floor 30 SF 4 1-2 years Lighting - Lay-in 1st Floor 12 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Storage/ Closet 1st Floor 70 SF 7 10+ years Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 6 10+ years Ceiling - Lay-in 1st Floor 800 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 6 SF 4 1-2 years

Campus Name: Sawyer Page : 57 of 64 Assessment Date: 06/26/2024



Recomment Reco	Category : Classroom			[Building : Modular 1 (6-Classroom)				
Marker Board					<u> </u>			<u> </u>	
Storage Closet 1st Floor 80 SF 7 10+ years	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroom #403 (Regular Classroom)	-	Marker Board	1st Floor	12	LF	7	6-10 years		
Caling - Lay-in		Storage/ Closet	1st Floor			7			
Ceiling - Lay-in			1st Floor	780	SF	6			
Ceiling - Lay-in	Classro	om #403 (Regular Classroom)							
Doors - Wood Doors inclu hw	Ciassio		1st Floor	800	QE.	6	10± vears		
Floor - Tile									
Floor - Tile									
Lighting - Lay-in								Creaked	
Marker Board 1st Floor 24 LF 7 6-10 years Storage/ Closet 1st Floor 70 SF 7 10+ years Walls - Virryl Coated Gypsum Panel 1st Floor 800 SF 6 10+ years Celling - Lay-in 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 5 SF 6 10+ years Floor - Tile 1st Floor 5 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 5 SF 4 1-2 years Cracked Marker Board 1st Floor 27 LF 7 6-10 years Storage/ Closet 1st Floor 80 SF 7 10+ years Walls - Virnyl Coated Gypsum Panel 1st Floor 80 SF 6 10+ years Classroom #405 (Store Room) 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 20 SF 6 10								Cracked	
Storage/ Closet 1st Floor 70 SF 7 10+ years							•		
Walls - Vinyl Coated Gypsum Panel									
Calistroom #404 (Store Room)									
Ceiling - Lay-in		Walls - Vinyl Coated Gypsum Panel	1st Floor	780	SF	6	10+ years		
Doors - Wood Doors inclu hw	Classroo	,							
Floor - Tile				800		6			
Floor - Tile			1st Floor	1					
Lighting - Lay-in		Floor - Tile	1st Floor	795		6	10+ years		
Marker Board 1st Floor 27 LF 7 6-10 years Storage/ Closet 1st Floor 80 SF 7 10+ years Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 6 10+ years Classroom #405 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 800 SF 6 10+ years Floor - Tile 1st Floor 20 SF 4 0-1 year Chipped Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Chipped Walls - Vinyl Coated Gypsum Panel 1st Floor 27 LF 7 6-10 years To + years Walls - Vinyl Coated Gypsum Panel 1st Floor 820 SF 6 10+ years To + years Classroom #406 (Store Room) 820 SF 6 10+ years To + years Forest Cracked Floor - Tile 1st Floor 810 SF 6 10+ years Cracked Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked						-		Cracked	
Storage/ Closet 1st Floor 80 SF 7 10+ ýears 780 SF 6 10+ years 780 SF 7 10		Lighting - Lay-in	1st Floor			6			
Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 6 10+ years Classroom #405 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 800 SF 6 10+ years Floor - Tile 1st Floor 20 SF 4 0-1 year Chipped Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 7 10+ years Classroom #406 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years		Marker Board		27		7	6-10 years		
Ceiling - Lay-in		Storage/ Closet	1st Floor	80		7	10+ years		
Ceiling - Lay-in		Walls - Vinyl Coated Gypsum Panel	1st Floor	780	SF	6	10+ years		
Ceiling - Lay-in	Classroo	om #405 (Store Room)							
Doors - Wood Doors inclu hw			1st Floor	820	SF	6	10+ years		
Floor - Tile							•		
Floor - Tile		Floor - Tile		800	SF	6	•		
Lighting - Lay-in 1st Floor 12 EA 6 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 7 10+ years Classroom #406 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years		Floor - Tile						Chipped	
Marker Board 1st Floor 27 LF 7 6-10 years Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 7 10+ years Classroom #406 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years						6		- 11	
Walls - Vinyl Coated Gypsum Panel 1st Floor 780 SF 7 10+ years Classroom #406 (Store Room) Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years		• •							
Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years									
Ceiling - Lay-in 1st Floor 820 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years	Classroo	om #406 (Store Room)							
Doors - Wood Doors inclu hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years	2.00000		1st Floor	820	SF	- 6	10± vears		
Floor - Tile 1st Floor 810 SF 6 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years		Doors - Wood Doors inclu bw							
Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years				·					
Lighting - Lay-in 1st Floor 12 EA 6 6-10 years Marker Board 1st Floor 27 LF 7 6-10 years								Cracked	
Marker Board 1st Floor 27 LF 7 6-10 years							•	Olached	
walls - viriyi Coaled Gypsum Panel 1st Floor 801 SF 6 10+ years									
		vvalis - viriyi Coated Gypsum Panel	18t F100f	801	51	ь	10+ years		



Category : Room		Building : Modular 1 (6-Classroom)							
			Recommend						
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
_Mechanical/ Service Rooms									
Mechanical/ Service Rooms	1st Floor	50	SF	7	10+ years				
5									
Restroom	·								
Accessories	1st Floor	154	SF	7	10+ years				
Ceiling - Lay-in	1st Floor	154	SF	7	10+ years				
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
Floor - Tile/Sheet	1st Floor	154	SF	7	6-10 years				
Floor Drain	1st Floor	1	EΑ	7	10+ years				
Hand Dryer	1st Floor	1	EΑ	7	2-5 years				
Hand Dryer	1st Floor	1	EΑ	7	6-10 years				
Lavatory	1st Floor	2	EA	7	10+ years				
Lighting - Pendent/Surface	1st Floor	1	EΑ	7	6-10 years				
Partitions	1st Floor	3	EΑ	7	10+ years				
Urinals	1st Floor	2	EΑ	7	10+ years				
Walls - Metal Panel	1st Floor	340	SF	6	10+ years				
Walls - Metal Panel	1st Floor	70	SF	6	10+ years				
Water Closet	1st Floor	2	EΑ	7	10+ years				
Accessories	1st Floor	165	SF	7	6-10 years				
Ceiling - Lay-in	1st Floor	165	SF	7	10+ years				
Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years				
Floor - Tile/Sheet	1st Floor	165	SF	7	10+ years				
Floor Drain	1st Floor	1	ĒΑ	7	10+ years				
Hand Dryer	1st Floor	1	ΕA	7	6-10 years				
Hand Dryer	1st Floor	1	EA	5	2-5 years				
Lavatory	1st Floor	2	EΑ	7	10+ years				
Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years				
Partitions	1st Floor	<u>2</u> 1	EA	7	10+ years				
Walls - Metal Panel	1st Floor	440	SF	6	10+ years				
Water Closet	1st Floor	4	EA	7	10+ years				
Water Gloset	1301 1001	7	L/ \	,	ioi years				

Category : Interior **Building: Modular 1 (6-Classroom)**

		1			.	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	Modular	750	SF	7	10+ years	
	Drinking Fountains - Double Fountain	Modular	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Modular	630	SF	7	6-10 years	
	Floor - Tile/Sheet	Modular	120	SF	4	1-2 years	Cracked
	Lighting - Lay-in	Modular	8	EA	7	6-10 years	
	Walls - Metal Panel	Modular	1,350	SF	7	10+ years	
	Walls - Metal Panel	Modular	67	SF	6	10+ years	
	Ceiling - Lay-in	Vestibule North	56	SF	7	6-10 years	



Sidney Sawyer Elementary School

5242 S Sawyer AVENUE, Chicago, IL 60632

Building: Modular 1 (6-Classroom) **Category: Interior** Recommend Quantity UOM Location Group Item - Type Rank Replacement Comments Doors - Steel Doors incl hw Vestibule North 2 EΑ 10+ years 7 Floor - Tile/Sheet Vestibule North 56 SF 7 6-10 years 6-10 years Lighting - Lay-in Vestibule North 1 EΑ 7 Walls - Metal Panel Vestibule North 136 SF 7 10+ years Ceiling - Lay-in SF 7 Vestibule South 56 10+ years Doors - Steel Doors incl hw 2 Vestibule South EΑ 7 10+ years Floor - Tile/Sheet Vestibule South 56 SF 7 10+ years Lighting - Lay-in Vestibule South EΑ 1 5 6-10 years Walls - Metal Panel SF Vestibule South 136 7 10+ years

Campus Name: Sawyer Page: 60 of 64 Assessment Date: 06/26/2024





Category : Site **Building: Site**

ategor	y . Site		В	unung	. Site		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	3	0-1 year	Collapsed
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	7	10+ years	
encing							
•	Fencing - New Standard Ornamental	Entire Site	407	LF	6	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	1,624	LF	6	6-10 years	
	Fencing - Old Standard Ornamental	Entire Site	100	LF	5	6-10 years	
ndscar	oe						
	Benches	Entire Site	9	EA	7	10+ years	
	Benches	Entire Site	8	EA	4	0-1 year	Warped, exposed nails
	Landscape - Grass	Entire Site	10,560	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	9,000	SF	6	10+ years	Combined
	Landscape - Hardscape- Concrete	Entire Site	200	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	7,231	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	200	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	5	EA	6	6-10 years	
	Lighting - Pole Mounted	Entire Site	5	EA	6	6-10 years	
	Lighting - Pole Mounted	Entire Site	5	EA	6	6-10 years	
	Parkway trees	Entire Site	36	EA	6	10+ years	
	Parkway trees	Entire Site	2	EA	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	5,920	SF	6	10+ years	3
	Play Area - Hardscape- Asphalt	Entire Site	10,208	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	5,000	SF	4	0-1 year	Cracked, uneven
	Play Area - Synthetic Turf	Entire Site	1,200	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	530	SF	6	10+ years	
	Retaining Wall - Masonry	Entire Site	520	SF	6	10+ years	
	Trash Receptacles	Entire Site	1	EΑ	6	10+ years	
rking L							
	Concrete Curbs	Entire Site	1,063	LF	6	10+ years	
	Interior Plantings	Entire Site	27	LF	6	10+ years	
	Lighting - Pole Mounted	Entire Site	8	EA	6	6-10 years	
	Surface - Asphalt	Entire Site	48,730	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	2,000	SF	4	0-1 year	Spalling, large holes
	Trash Enclosure - Masonry	Entire Site	950	SF	6	10+ years	
	Vehicular Screening	Entire Site	380	LF	6	10+ years	
aygrou	nd						
ay gi UU	Equipment - Combo 3-12	North	1	EA	6	10+ years	



Category : Site Building : Site							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Surface - Poured Surface	North	2,475	SF	6	10+ years	
_Sidewall	KS .						
	Sidewalks - Internal Walks	Entire Site	2,500	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	5,000	LF	7	10+ years	Repairs
	Sidewalks - Perimeter Sidewalks	Entire Site	13,444	SF	7	10+ years	·
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	4	0-1 year	Cracked, spalling
_Signage							
	Flag Pole - Flag Pole	Entire Site	3	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	4	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

Definitions


- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Sawyer Page: 62 of 64 Assessment Date: 06/26/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Operable

Glazed





Classroom Summary

			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					(31)	1	1 11 2 21		
Computer Lab	Regular Classroom	Basement	003	003/004	1,600	240	120	N	Υ
Other Instructional Use	Store Room	3rd Floor	306	Girls RR	400	90	45	N	Y
Regular Classroom	Library	2nd Floor	209	209	925	140	70	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	775	210	105	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	775	210	105	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	775	210	105	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	800	120	60	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	800	160	80	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	925	160	80	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	775	210	105	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	775	140	70	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	775	175	88	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	775	210	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	775	210	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	775	210	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	925	140	70	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	800	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	775	210	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	775	140	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	775	175	88	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	775	210	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	775	210	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	775	210	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	775	210	105	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	775	140	70	N	N
Regular Classroom	Regular Classroom	Basement	002	002	900	120	60	N	N
Regular Classroom	Regular Classroom	Basement	B-1- 206	001	850	150	75	N	Υ
Science Classroom	Regular Classroom	1st Floor	101	101	875	150	75	N	N
Science Classroom	Regular Classroom	2nd Floor	207	207	800	120	60	N	Υ
Special Education	Choral Room	2nd Floor	205	205	400	90	45	N	N
Store Room	Dance Room	Basement	B- 209	NA	185	0	0	N	N
Store Room	Faculty Lounge	3rd Floor	305	305	393	80	20	N	N
Building : Annex									
Computer Lab	Computer Lab	2nd Floor	222/223	222/223	2,360	132	46	N	N
Kindergarten	Kindergarten	1st Floor	128	128	1,040	132	46	N	N
Kindergarten	Kindergarten	1st Floor	130	130	1,040	132	46	N	N
Kindergarten	Kindergarten	1st Floor	132	132	1,040	132	46	N	N

Floor Plan





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Kindergarten	1st Floor	134	134	1,040	132	46	N	N
Kindergarten	Kindergarten	1st Floor	136	136	1,040	132	46	N	N
Kindergarten	Kindergarten	1st Floor	138	138	1,040	132	46	N	N
Other Instructional Use	Regular Classroom	1st Floor	141A	141A	860	132	46	N	N
Regular Classroom	Regular Classroom	1st Floor	140	140	860	132	46	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	950	150	30	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	224	224	1,200	150	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	225	728	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	1,200	150	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	785	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	1,215	150	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	730	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	780	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	780	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	235	235	760	120	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	785	120	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	780	120	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	324	324	600	72	24	N	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	760	120	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	450	72	24	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	327	327	758	120	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	329	320	760	120	38	N	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	1,020	144	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	331	331	760	120	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	780	120	35	N	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	845	120	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	334	334	785	120	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	335	335	776	120	36	N	N
Special Program	Regular Classroom	1st Floor	129	129	786	132	46	N	N
Store Room	Special Program	2nd Floor	222A		365	90	25	N	N
Building : Modular 1 (6-Clas									
Regular Classroom	Regular Classroom	1st Floor	401	401	800	60	30	N	N
Regular Classroom	Regular Classroom	1st Floor	402	402	800	60	30	N	N
Regular Classroom	Regular Classroom	1st Floor	403	403	800	60	30	N	N
Store Room	Regular Classroom	1st Floor	404	404	800	60	30	N	N
Store Room	Regular Classroom	1st Floor	405	405	820	60	30	N	N
Store Room	Regular Classroom	1st Floor	406	406	820	60	30	N	N