

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2005	2	290,134
Campus Total			290,134

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - East Main entrance	1	EA	7	10+ years	
	Exterior Doors - Side lite	Door 1 - East Main entrance	2	EA	6	10+ years	
	Exterior Doors - Store Front	Door 1 - East Main entrance	5	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - East Main entrance	150	LF	6	10+ years	
	Power Door Operator and Controls	Door 1 - East Main entrance	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Door 1 - East Main entrance	120	LF	7	10+ years	
	Ramps - Concrete	Door 1 - East Main entrance	60	LF	5	2-5 years	
	Stair Handrail - Steel_Stair Handrail	Door 1 - East Main entrance	24	LF	7	10+ years	
	Exterior Doors - Store Front	Door 1.5 - Northeast	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 10 - West	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 10.2 - Dock	1	EA	6	10+ years	
	Entrance Control - Audio	Door 10.4 - Dock	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 10.4 - Dock	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 10.6 - Dock	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 10.6 - Dock	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 10.6 - Dock	24	LF	7	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	Door 10.8 - OVH South of dock	1	EA	6	10+ years	
	Door						
	Exterior Doors - Store Front	Door 11 - West	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 11 - West	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 12 - West	2	EA	6	10+ years	
	Exterior Doors - Exterior Stainless Steel	Door 13 - West pool	1	EA	6	10+ years	
	Door	·				•	
	Exterior Doors - Exterior Steel Door	Door 13.5 - West south	1	EA	6	10+ years	
						-	



Catego	ry : Exterior		Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exterior Doors - Exterior Steel Door	Door 14 - West small gym	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 15 - Southwest small gym	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 15.5 - South small gym	2	EA	6	10+ years			
	Entrance Control - Audio	Door 16 - Southwest	1	EA	6	10+ years			
	Exterior Doors - Side lite	Door 16 - Southwest	2	EA	7	10+ years			
	Exterior Doors - Store Front	Door 16 - Southwest	3	EA	6	10+ years			
	Exterior Doors - Transom Lite	Door 16 - Southwest	3	EA	7	10+ years			
	Power Door Operator and Controls	Door 16 - Southwest	1	EA	7	10+ years			
	Entrance Control - Audio	Door 17 - Southeast	1	EA	6	10+ years			
	Exterior Doors - Side lite	Door 17 - Southeast	2	EA	7	10+ years			
	Exterior Doors - Store Front	Door 17 - Southeast	3	EA	6	10+ years			
	Exterior Doors - Transom Lite	Door 17 - Southeast	3	EA	7	10+ years			
	Power Door Operator and Controls	Door 17 - Southeast	1	EA	7	10+ years			
	Exterior Doors - Store Front	Door 18 - Southeast	2	EA	6	10+ years			
	Exterior Doors - Transom Lite	Door 18 - Southeast	1	EA	7	10+ years			
	Exterior Doors - Exterior Steel Door	Door 19 - East south	1	ΕA	6	10+ years			
	Exterior Doors - Store Front	Door 2 - Northeast	2	EA	7	10+ years			
	Exterior Doors - Exterior Steel Door	Door 20 - Southeast auditorium	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 21 - East auditorium	1	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 22 - North courtyard	1	EΑ	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 23 - North courtyard	1	EΑ	6	10+ years			
	Exterior Doors - Exterior Steel Door	Door 24 - Center courtyard,	1	EΑ	6	10+ years			
	Extend Boold Extend Clour Bool	northwest	•		Ü	101 youro			
	Exterior Doors - Exterior Steel Door	Door 25 - Center courtyard,	1	EA	6	10+ years			
	Extend Boold Extend Clour Bool	southwest	•		Ü	101 youro			
	Exterior Doors - Side lite	Door 26 - Center courtyard link	1	EA	6	10+ years			
	Exterior Doors - Store Front	Door 26 - Center courtyard link	1	EA	6	10+ years			
	Exterior Doors - Store Front	Door 27 - south courtyard, northwest	1	EA	6	10+ years			
	Exterior Doors - Store Front	Door 28 - south courtyard,	1	EA	6	10+ years			
	Exterior Doors - Otore i Torit	southwest		LA	U	10+ years			
	Exterior Doors - Side lite	Door 3 - Northeast	2	EA	7	10+ years			
	Exterior Doors - Store Front	Door 3 - Northeast	3	EA	6	10+ years			
	Exterior Doors - Transom Lite	Door 3 - Northeast	3	EA	7	10+ years			
	Power Door Operator and Controls	Door 3 - Northeast	1	EA	7	10+ years			
	Exterior Doors - Store Front		2	EA	6	•			
	Exterior Doors - Store Front	Door 31 - South courtyard, southeast	2	EA	О	10+ years			
	Exterior Doors - Transam Lita		4	ГΛ	7	10			
	Exterior Doors - Transom Lite	Door 31 - South courtyard,	1	EA	7	10+ years			
	Futarias Dansa Ctara Frant	southeast	4	<b>-</b> ^	0	10			
	Exterior Doors - Store Front	Door 32 - south courtyard, east	1	EΑ	6	10+ years			
	Exterior Doors - Store Front	Door 33 - South courtyard, northeast	1	EΑ	6	10+ years			
	Exterior Doors - Store Front	Door 34 - Center courtyard,	2	EA	6	10+ years			
	F	southeast		_ ^	_	40			
	Exterior Doors - Transom Lite	Door 34 - Center courtyard,	1	EA	7	10+ years			
		southeast							



Catego	ry : Exterior		В	uilding	: Main		· <u> </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	Door 35 - Center courtyard,	1	EA	6	10+ years	
		southeast					
	Exterior Doors - Exterior Steel Door	Door 36 - Center courtyard,	1	EA	6	10+ years	
		northeast					
	Exterior Doors - Side lite	Door 37 - Center courtyard, link	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 37 - Center courtyard, link	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 38 - Center courtyard,	2	EA	6	10+ years	
		Northeast					
	Exterior Doors - Transom Lite	Door 38 - Center courtyard,	1	EA	6	10+ years	
		Northeast					
	Exterior Doors - Exterior Steel Door	Door 39 - North courtyard, southeast	1	EA	6	10+ years	
	Entrance Control - Audio	Door 4 - Northwest	1	EA	6	10+ years	
	Exterior Doors - Side lite	Door 4 - Northwest	2	EA	7	10+ years	
	Exterior Doors - Store Front	Door 4 - Northwest	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - Northwest	3	EA	7	10+ years	
	Power Door Operator and Controls	Door 4 - Northwest	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 40 - North courtyard, northeast	1	EA	6	10+ years	
	Exterior Doors - Store Front	Door 41 - North courtyard, northeast	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 41 - North courtyard, northeast	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 42 - 2nd floor roof	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 42 - 2nd floor roof	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5 - North gym	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6 - Northwest gym	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - West gym	2	EA	6	10+ years	
	Exterior Doors - Store Front	Door 8 - West	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 8 - West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 9 - West	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 9 - West	3	LF	6	10+ years	
_							
_Foundat		Fatina Duildina	4.000		7	40	
	Foundation - Concrete	Entire Building	1,920	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF SF	6	10+ years	
	Superstructure - Steel	Entire Building	290,134	SF	7	10+ years	
_Lighting							
_ <u>gruing</u>	Exterior Lighting - Wall Mounted	Entire Building	90	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	65	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Littile building	03		U	TOT years	
Roof Sys	stem						
	Access Ladder - Metal	Roof 1	3	EA	7	10+ years	
	Chimney - Metal Flue	Roof 1	24	LF	6	10+ years	
	Coping - Metal	Roof 1	1,380	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	1,680	LF	6	10+ years	
			,		-	<b>,</b>	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	Roof 1	982	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	162	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	236	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	36,250	SF	5	2-5 years	
	Roof - Modified Bitumen	Roof 1	8,500	SF	4	0-1 year	Bubbling, water under membrane
	Roof Hatch - Metal	Roof 1	2	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 1	44,750	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof 10	2	EA	7	10+ years	
	Coping - Metal	Roof 10	722	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 10	30	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 10	320	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 10	515	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 10	15,288	SF	5	2-5 years	
	Roof - Modified Bitumen	Roof 10	400	SF	4	1-2 years	Bubbling, cracking
	Roof Hatch - Metal	Roof 10	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 10	15,688	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof 11	1	EA	7	10+ years	
	Coping - Metal	Roof 11	500	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 11	480	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 11	315	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 11	185	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 11	14,212	SF	5	2-5 years	
	Roof Hatch - Metal	Roof 11	2	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 11	14,212	SF	7	10+ years	
	Concrete Topping		_		_		
	Access Ladder - Metal	Roof 12	2	EA	7	10+ years	
	Coping - Metal	Roof 12	371	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 12	240	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 12	371	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 12	5,611	SF	5	2-5 years	
	Roof - Modified Bitumen	Roof 12	5,000	SF	4	1-2 years	Bubbling, water under membrane
	Roof Hatch - Metal	Roof 12	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 12	10,611	SF	7	10+ years	
	Concrete Topping	D (10			_	4.0	
	Coping - Metal	Roof 13	62	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 13	120	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 13	62	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 13	554	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 13	554	SF	7	10+ years	
	Concrete Topping	D (111	22		•	40	
	Coping - Metal	Roof 14	62	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 14	120	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet < 16" Height	Roof 14	62	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 14	554	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 14	554	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 15 - Greenroof	200	LF	6	10+ years	
	Roof - Green Roof	Roof 15 - Greenroof	1,328	SF	6	6-10 years	Vegetation growth outside of planter
	Roof Structure - Steel / Metal Deck/	Roof 15 - Greenroof	1,328	SF	7	10+ years	
	Concrete Topping						
	Roof - Metal	Roof 16 - Cone	1,006	SF	6	10+ years	
	Roof - Metal	Roof 16 - Cone	120	SF	5	2-5 years	Patched
	Roof Structure - Steel / Metal Deck/	Roof 16 - Cone	1,126	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Metal	Roof 2	190	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	190	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	7,254	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 2	7,254	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 3 - Mech	93	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3 - Mech	120	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3 - Mech	93	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3 - Mech	3,160	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 3 - Mech	1,500	SF	5	0-1 year	Bubbling, plant growth
	Roof Structure - Steel / Metal Deck/	Roof 3 - Mech	4,660	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 4 - N	505	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4 - N	480	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 4 - N	505	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 4 - N	12,130	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof 4 - N	1,800	SF	4	0-1 year	Plant growth, exposed insulation
	Roof Hatch - Metal	Roof 4 - N	1	EA	7	10+ years	No ladder
	Roof Structure - Steel / Metal Deck/	Roof 4 - N	13,930	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof 5 - N Center	1	EA	7	10+ years	
	Coping - Metal	Roof 5 - N Center	505	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 5 - N Center	480	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 5 - N Center	505	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 5 - N Center	13,330	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof 5 - N Center	600	SF	4	0-1 year	Plant growth
	Roof Hatch - Metal	Roof 5 - N Center	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 5 - N Center	13,930	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof 6	1	EA	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Metal	Roof 6	505	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 6	480	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 6	505	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 6	13,430	SF	5	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 6	500	SF	4	0-1 year	Vegetative growth
	Roof Hatch - Metal	Roof 6	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 6	13,930	SF	7	10+ years	
	Concrete Topping						
	Coping - Metal	Roof 7	505	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 7	480	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 7	505	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 7	9,360	SF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof 7	5,500	SF	4	0-1 year	Vegetation, exposed insulation
	Roof Hatch - Metal	Roof 7	1	EA	7	10+ years	-
	Roof Structure - Steel / Metal Deck/	Roof 7	14,860	SF	7	10+ years	
	Concrete Topping		,			•	
	Coping - Metal	Roof 8	306	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 8	730	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 8	1,000	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 8	6,270	SF	5	2-5 years	
	Roof - Modified Bitumen	Roof 8	1,000	SF	4	0-1 year	Bubbling, cracking, water under
			,			, ,	membrane
	Roof Structure - Steel / Metal Deck/	Roof 8	8,270	SF	7	10+ years	
	Concrete Topping		5,	-	•	, , , , , , , , , , , , , , , , , , , ,	
	Coping - Metal	Roof 9	306	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 9	730	LF	6	10+ years	Repaired
	Roof - Modified Bitumen	Roof 9	8,270	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 9	8,270	SF	7	10+ years	
	Concrete Topping	. 100. 0	5,=: 5	О.	•	. o . y ca. c	
	Generate rapping						
Walls							
	Canopy - Concrete/ Stucco	Entire Building	192	SF	6	10+ years	
	Canopy - Metal	Entire Building	1,765	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	111,179	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	28,401	SF	6	10+ years	
	Wall	=	_3, 101	٥.	•	,	
	Exterior Walls - Stone-Cast	Entire Building	415	SF	6	10+ years	
		··· ······························		٥.	ŭ	,	
Windows							
	Curtain wall - Glazed Double Pane	Entire Building	18,373	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	200	SF	5	2-5 years	
	Curtain wall - Louver	Entire Building	1,660	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,232	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,875	LF	6	10+ years	
		3	,			•	



Category : Exterior

## Greater Lawndale High School For Social Justice 3120 S Kostner AVENUE, Chicago, IL 60623

**Building: Main** 

atego	ry : Exterior		В	ullaing	: wain		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Jup	Skylite - Glass Double-Pane	Entire Building	27	SF	6	10+ years	Comments
	Windows - Decorative	Entire Building	2,339	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,988	SF	6	10+ years	
	Windows - Sasti Aldminum Double-pane	Entire Building	0,900	SF	O	10+ years	
tego	ry : Electrical		В	uilding	: Main		
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System	Location	Qualitity	OOW	Italik	Replacement	Comments
erger		Floatrical Doom	1	ГΛ	6	10	Location changed for planification
	Emergency Generator- Indoor- Diesel - 201 - 250 KW	Electrical Room	-	EA	6	10+ years	Location changed for clarification.
	Automatic Transfer Switch	Electrical Room	3	EA	6	10+ years	
	Security System - CCTV	Entire Building	290,134	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	290,134	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	13	ĒΑ	6	6-10 years	Quantity changed to match currer
		g	.0		Ü	5 .5 Jours	observations.
	Exit Signs - Corridors and Stairs	Entire Building	110	EA	6	6-10 years	Quantity changed as total has been
							divided/aggregated.
	Exit Signs - Gym	Entire Building	12	EA	6	6-10 years	Includes both the north and south
	3	3				,	gyms
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	37
	Exit Signs - Pool	Entire Building	3	EA	6	6-10 years	Quantity changed to match currer
	Exit Signs 1 001	Entire Building	3	LA	J	o To years	observations.
	Emergency A/C Power - Auditoium and	Entire Building	2,829	SF	6	10+ years	Rank, Reason and Priority Rep
	Aisle Lighting	Entire Banding	2,020	O.	O	101 youro	changed based on current
	Alsic Lighting						observations and per review with
	Francisco A/C Davier Corridore and	Entire Duildies	F0 740	C.E.	•	40	Building Engineer.
	Emergency A/C Power - Corridors and	Entire Building	53,710	SF	6	10+ years	
	Stairs	F (	47.000	05	•	40	No. of the state of
	Emergency A/C Power - Gym	Entire Building	17,008	SF	6	10+ years	North and south gyms
	Emergency A/C Power - Lunchrooms	Entire Building	6,920	SF	6	10+ years	
	Emergency A/C Power - Pool	Entire Building	8,749	SF	6	10+ years	
in Se		Floatrical Boom		Γ^		10	
	Main Electrical Service - Greater than 3000	Electrical Room	2	EA	6	10+ years	
	A 277/480/3PH		_		_		
	Main Electrical Service - 1200 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH						
	Main Electrical Service - 2001 to 3000 A	Electrical Room	1	EA	6	10+ years	
	120/208/3PH						
	Independent Electrical Service for	Electrical Room, Pump Room.	1	EA	6	10+ years	
	emergency power	, - r			-	,	
	Independent Electrical Service for	Electrical Room, Pump Room.	1	EA	6	10+ years	Location changed for clarification
	emergency power	Zioonioai Room, i amp Room.	•	L, (	J	ioi youid	Location onangou for damidation
		Entiro Building	200 424	SF	7	6 10 years	
	PA System	Entire Building	290,134	SF	′	6-10 years	
npus I	Name: Little Village Multiplex	Page: 7	7 of 74				Assessment Date: 06/11/



Catego	ry : Electrical		В	uilding	: Main		
	<del></del>	I a said a s	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	vistribution						
1 OWCI D	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	62	EΑ	7	6-10 years	Quantity changed as total has been
		, and the second				•	divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	Open breaker slots expose live
							conductors presenting a live front
	Lighting and Dower Banala Above 100 A	Entire Building	2	EA	4	0.1 voor	condition.  Open fuse receptacles and a missing
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	interior cover expose live conductors
							presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep
							changed as a missing interior cover
							plate exposes live conductors
	Main Distribution Banala 400 600 amp	Entire Building	12	EA	7	6-10 years	presenting a live front condition.  Quantity changed based on current
	Main Distribution Panels - 400 - 600 amp	Entire Building	12	EA	,	0-10 years	observations and as total has been
							divided/aggregated.
	Main Distribution Panels - Greater than 600	Entire Building	6	EA	7	6-10 years	Quantity changed based on current
	amp	_				•	observations and as total has been
	M : B: ('I (' B   1 0 ) ( ) ( )	F (	,	_ ^	_	40	divided/aggregated.
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	Location changed for clarification.  Quantity changed as total has been
	amp						divided/aggregated.
	Main Distribution Panels - Less than 400	Entire Building	2	EA	7	6-10 years	arvidod/aggrogatod.
	amp	•				•	
	Transformers - 277/480 - 120/208	Entire Building	3	EA	6	6-10 years	
Catego	ry : Fire Protection		P	uilding	· Main		
Calcgo	Ty . The Frotection		<u> </u>	unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	290,134 290,134	SF SF	6 6	6-10 years 6-10 years	
	Fire Alarm_System Fire Pump Controller	Entire Building Entire Building	290,134	SF EA	6	6-10 years 6-10 years	Location changed for clarification.
	The Fully Controller	Entire Dulluling	'	L/ \	O	o io yours	Location onanged for diamidation.
Pump Re	oom Assembly						
	Fire Pump - 51-75hp	Pump Room	1	EA	6	6-10 years	Location changed for clarification.
	Jockey Pump	Pump Room	1	EA	6	6-10 years	Location changed for clarification.
	Jockey Pump	Pump Room	1	EA	6	6-10 years	Location changed for clarification.



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Sprinkler							
	Combination Wet and Dry Sprinkler System	Entire Building	290,134	SF	5	6-10 years	Location changed for clarification.
	Sprinkler Heads	Entire Building	290,134	SF	7	10+ years	
	Sprinkler Piping	Entire Building	290,134	SF	6	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Chemical Pot Feeder	Lower Roof	1	EA	7	10+ years	
	Chiller-Air Cooled-Screw Type-Roof	Lower Roof	1	EA	5	1-2 years	CH-2. Partially functional. CPS
	Mounted - 201 - 300 tons					-	Asset Tag not legible.
	Chiller-Air Cooled-Screw Type-Roof	Lower Roof	1	EA	5	1-2 years	CH-3. Partially functional.
	Mounted - 201 - 300 tons						
	Chiller-Air Cooled-Screw Type-Roof	Lower Roof	1	EA	2	1-2 years	CH-1. Inoperable CPS Asset Tag
	Mounted - 201 - 300 tons						not legible
	Glycol Feed	Lower Roof	_ 1	EΑ	6	6-10 years	Manual
	Pipes - Chilled Water Pipe- Copper	Lower Roof	500	LF	7	10+ years	Quantity changed as total has been divided/aggregated.
	Pipes - Chilled Water Pipe- Steel	Lower Roof	100	LF	7	10+ years	
	Pressure Fill System	Lower Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - 31-50 tons	Roof	1	EA	6	6-10 years	CU-3
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	3	1-2 years	Nonfunctional. Component of a ductless split system serving the MDF Room.
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	3	1-2 years	Rank and Priority Rep changed based on current observations and per review with Building Engineer that the unit is nonfunctional.
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	2	0-1 year	Rank, Reason and Priority Rep changed to reflect that the equipment is not in service, is nonfunctional, has been deemed obsolete, and has been abandoned in place. No CPS Asset Tag present.
_Air Hand	ling Systems						
	Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less than 6000 cfm	Boiler Room - AHU-17	1	EA	6	6-10 years	AHU-17, ceiling mounted. Dataplate and CPS Asset Tag not accessible due to lack of safe climbing equipment.
	Fan Coil Unit- Celing Mounted - Hot Water	Cone	1	EA	6	10+ years	Located above the suspended ceiling



Catego	ry : Mechanical		В	uilding	: Main		120 O Rosiner Avenue, Gilleage, in 00023
			_	_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Chilled Water  Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water	Cone	1	EA	6	10+ years	grid in the two Cone passageways.  No CPS Asset Tag present.  Located above the suspended ceiling grid in the two Cone passageways.  No CPS Asset Tag present.
	Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water	Cone	1	EA	6	10+ years	Located above the suspended ceiling grid in the two Cone passageways.  No CPS Asset Tag present.
	Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water	Cone	1	EA	6	10+ years	Located above the suspended ceiling grid in the two Cone passageways.  No CPS Asset Tag present.
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - Less than 4000 cfm	Cone - AHU-15 & AHU-16	1	EA	6	6-10 years	AHU-15 located inside a compartment above the Cone ceiling. Inaccessible in a safe manner at the time of assessment due to height and the need for specialized equipment. Condition verified by DDC System and per review with the Building Engineer. Location changed for clarification. No CPS Asset Tag available.
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - Less than 4000 cfm	Cone - AHU-15 & AHU-16	1	EA	6	6-10 years	AHU-16 located inside a compartment above the Cone ceiling. Inaccessible in a safe manner at the time of assessment due to height and the need for specialized equipment. Condition verified by DDC System and per review with the Building Engineer. Location changed for clarification. No CPS Asset Tag available.
	Air Intake	Cone - AHU-15 & AHU-16	2	EA	6	10+ years	Serve AHU-15 and AHU-16. Located in the Cone exterior soffits.
	Fan Coil Unit- Celing Mounted - Electric	Dimmer Room	1	EA	6	6-10 years	AC-2
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	154	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Generally located above the suspended ceiling grid throughout the building. Condition of all units verified by Building Engineer.
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-9; Item Type changed to match current observations.
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-14; Item Type changed to match current observations.

Page : 10 of 74



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-13
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-6; Item Type changed to match current observations.
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-10
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	1	EA	6	10+ years	RF-12
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	1	EA	6	10+ years	RF-7
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-11
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-2
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-1
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-3
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-4
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-1	1	EA	6	10+ years	AHU-1
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	Location changed for clarification.
	VAV Box	Mechanical Room - AHU-1	4	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU-10	1	EA	6	10+ years	AHU-10
	Air Intake	Mechanical Room - AHU-10	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-10	6	EΑ	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-11	1	EA	6	10+ years	
	Air Intake	Mechanical Room - AHU-11	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU-12	1	EA	6	10+ years	AHU-12
	Air Intake	Mechanical Room - AHU-12	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU-13	1	EA	6	10+ years	AHU-13
	Air Intake	Mechanical Room - AHU-13	1	EA	6	10+ years	Location changed for clarification.
	VAV Box	Mechanical Room - AHU-13	8	EA	6	6-10 years	A1111.44
	Air Handling Unit-Package Single Zone-	Mechanical Room - AHU-14	1	EA	6	10+ years	AHU-14



Catego	ry : Mechanical		В	uilding	: Main	•	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm						
	Air Intake	Mechanical Room - AHU-14	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-14	3	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-2	1	EA	6	10+ years	AHU-2
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-2	4	EΑ	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-3	1	ĒA	6	6-10 years	AHU-3
	Air Intake	Mechanical Room - AHU-3	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-3	4	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-4	1	EA	6	10+ years	AHU-4
	Air Intake	Mechanical Room - AHU-4	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-4	4	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-5	1	EA	6	10+ years	AHU-5
	Air Intake	Mechanical Room - AHU-5	1	EA	6	10+ years	Location changed for clarification.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-6	1	EA	6	6-10 years	AHU-6; Item Type changed to match current observations.
	Air Intake	Mechanical Room - AHU-6	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-6	4	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mechanical Room - AHU-7	1	EA	6	10+ years	AHU-7; Item Type changed to match current observations.
	Air Intake	Mechanical Room - AHU-7	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-7	1	EA	6	6-10 years	
	Dehumidification Unit- Indoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - Greater than 8000 cfm	Mechanical Room - AHU-8	1	EA	6	6-10 years	AHU-8. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that repairs were completed since previous assessment.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU-9	1	EA	6	10+ years	AHU-9
	Air Intake	Mechanical Room - AHU-9	1	EA	6	10+ years	
	VAV Box	Mechanical Room - AHU-9	3	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		. •
C	Item - Type	Location	Quantity	UOM	Donk	Recommend	Comments
Group	item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Boiler Sy	vstems						
•	Boiler Auxiliary- Non Condensing Hot Water - Greater than 4000 MBH	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	Serves B-1 and B-2.
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Manual
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH	Boiler Room	1	EA	6	10+ years	B-2
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - Greater than 4000 MBH	Boiler Room	1	EA	6	10+ years	B-1
_Heating	Devices						
	Duct Heater - Electric	Cone	5		6	10+ years	Located above the suspended ceiling grid in the two Cone passageways. Condition of all units verified by Building Engineer.
	Cabinet Heaters - With Hot Water Coil	Entire Building	28	EA	7	10+ years	
	Unit Heater - Electric	Entire Building	6	EA	5	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer.
	Unit Heater - Hot Water	Entire Building	14	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Unit Heater - Hot Water	Entire Building	1	EA	5	6-10 years	Functional but with considerable environment-related surface oxidation.
	Radiator Panels - Hot Water	Entire Building	24	EA	6	10+ years	Quantity changed to match current observations.
Mechani	cal Plumbing						
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	2,000	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	
			1				
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	•	EΑ	6	6-10 years	
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	6	6-10 years	

Page: 13 of 74



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Tempera	ature Control						
·	DDC System	Entire Building	290,134	SF	5	0-1 year	System is read-only; equipment does not respond to controls.
	Electric Thermostat Thermostats - DDC	Entire Building Entire Building	32 221	EA EA	6 6	6-10 years 10+ years	·
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	21	EA	6	6-10 years	Quantity changed based on current observations and per review with Building Engineer.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	16	EA	6	6-10 years	Dalianing Engineers
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years	Fan is noisy consistent with being unbalanced; Reason and Priority Rep adjusted based on current observations that the unit is fully operational and to coincide with the Rank.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	10	EA	6	6-10 years	T.Ca.ii.
	Type I Exhaust Hood- Kitchen	Entire Building	3	EA	6	10+ years	Quantity changed to match current observations. Two are located in the food preparation area and one is located in the servery.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	Located in the dishwasher room.
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	6-10 years	WH-1, WH-2. Priority Rep adjusted
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	2	EA	6	6-10 years	based on current observations. WH-3, WH-4. Priority Rep adjusted based on current observations.
Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	290,134	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	290,134	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	290,134	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	290,134	SF	6	10+ years	

Page : 14 of 74



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	290,134	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	290,134	SF	6	10+ years	
	Sanitary Piping	Entire Building	290,134	SF	6	10+ years	
	Storm Piping	Entire Building	290,134	SF	6	10+ years	
	Vent Piping	Entire Building	290,134	SF	6	10+ years	
Pool Svs	stems						
,	Pool Drain Piping	Entire Building	50	LF	6	6-10 years	Location changed for clarification.
	Pool Filtration System including Pump	Entire Building	1	ĒA	6	6-10 years	Priority Rep adjusted based on current observations. Location changed for clarification.
	Pool Hot Water Heater - Gas Fired	Entire Building	1	EA	6	6-10 years	Priority Rep adjusted based on current observations. Location changed for clarification.
	Pool Supply and Return Piping	Entire Building	150	LF	6	10+ years	Location changed for clarification.
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer. Location changed for clarification.
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer. Location changed for clarification.
	Pumps - Sump-Duplex	Entire Building	1	EA	6	6-10 years	Item Type and location changed to match current observations. Priority Rep adjusted based on current observations and per review with Building Engineer. Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Not directly accessible at the time of assessment No CPS Asset Tag available. Priority Rep adjusted with condition verified by Building Engineer. Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Not directly accessible at the time of assessment No CPS Asset Tag available. Priority Rep adjusted with condition verified by Building Engineer. Location



Recommend

**Building: Main Category: Plumbing** 

Item - Type Location Quantity UOM Rank Comments Replacement Group

changed for clarification.

**Building: Main** Category: Room

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	1st Floor Area B Office Suite at NE corner	3,114	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor Area B Office Suite at NE corner	16	SF	4	1-2 years	Stained tile
	Doors - Transom Window	1st Floor Area B Office Suite at NE corner	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Area B Office Suite at NE corner	10	EA	7	10+ years	
	Floor - Carpet	1st Floor Area B Office Suite at NE corner	3,130	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor Area B Office Suite at NE corner	63	EA	7	6-10 years	
	Power Distribution	1st Floor Area B Office Suite at NE corner	72	EA	7	10+ years	
	Storage/ Closet	1st Floor Area B Office Suite at NE corner	100	SF	7	10+ years	
	Walls - Concrete Block	1st Floor Area B Office Suite at NE corner	3,822	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Area B Office Suite at NE corner	3,822	SF	7	10+ years	
	Work Sink	1st Floor Area B Office Suite at NE corner	1	EA	7	10+ years	
	Ceiling - Lay-in	1st floor Area B Office suite at SE corner	3,050	SF	7	10+ years	
	Ceiling - Lay-in	1st floor Area B Office suite at SE corner	80	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st floor Area B Office suite at SE corner	13	SF	7	10+ years	
	Doors - Transom Window	1st floor Area B Office suite at SE corner	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor Area B Office suite at SE corner	10	EA	7	10+ years	
	Floor - Carpet	1st floor Area B Office suite at SE corner	3,130	SF	7	6-10 years	
	Lighting - Lay-in	1st floor Area B Office suite at SE corner	63	EA	7	6-10 years	
	Power Distribution	1st floor Area B Office suite at SE corner	72	EA	7	10+ years	



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Storage/ Closet	1st floor Area B Office suite at SE corner	100	SF	7	10+ years			
	Walls - Concrete Block	1st floor Area B Office suite at SE corner	3,822	SF	7	10+ years			
	Walls - Plaster/Drywall	1st floor Area B Office suite at SE corner	3,822	SF	7	10+ years			
	Work SInk	1st floor Area B Office suite at SE corner	1	EA	7	10+ years			
	Ceiling - Lay-in	1st floor Tickets Office	110	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor Tickets Office	1	EA	7	10+ years			
	Floor - Tile	1st floor Tickets Office	110	SF	6	10+ years			
	Lighting - Lay-in	1st floor Tickets Office	2	EA	7	6-10 years			
	Power Distribution	1st floor Tickets Office	2	EA	7	10+ years			
	Walls - Concrete Block	1st floor Tickets Office	220	SF	7	10+ years			
	Ceiling - Lay-in	1st floor across from 4-101	321	SF	7	10+ years			
	Ceiling - Lay-in	1st floor across from 4-101	4	SF	4	1-2 years	Minor water damage		
	Doors - Side-lite	1st floor across from 4-101	13	SF	7	10+ years	<b>G</b>		
	Doors - Steel Doors incl hw	1st floor across from 4-101	1	EA	7	10+ years			
	Doors - Transom Window	1st floor across from 4-101	13	SF	7	10+ years			
	Floor - Carpet	1st floor across from 4-101	325	SF	7	6-10 years			
	Lighting - Lay-in	1st floor across from 4-101	2	EA	7	6-10 years			
	Power Distribution	1st floor across from 4-101	4	EA	7	10+ years			
	Walls - Concrete Block	1st floor across from 4-101	770	SF	7	10+ years			
	Ceiling - Lay-in	1st floor area C SW corner engineer's office	162	SF	7	10+ years			
	Doors - Side-lite	1st floor area C SW corner engineer's office	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor area C SW corner engineer's office	1	EA	7	10+ years			
	Floor - Tile	1st floor area C SW corner engineer's office	162	SF	7	10+ years			
	Lighting - Lay-in	1st floor area C SW corner engineer's office	4	EA	7	6-10 years			
	Power Distribution	1st floor area C SW corner engineer's office	6	EA	7	10+ years			
	Walls - Concrete Block	1st floor area C SW corner engineer's office	478	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st floor area D north of pool female staff office	222	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st floor area D north of pool female staff office	2	EA	7	10+ years			
	Doors - Transom Window	1st floor area D north of pool female staff office	36	SF	7	10+ years			
	Floor - Tile	1st floor area D north of pool female	222	SF	7	10+ years			



Catego	ry : Room		Building : Main							
0.000	Itama Tuma	Location	0	11014	Dent	Recommend	Comments			
Group	Item - Type	Location staff office	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	1st floor area D north of pool female staff office	2	EA	7	6-10 years				
	Power Distribution	1st floor area D north of pool female staff office	6	EA	7	10+ years				
	Walls - Concrete Block	1st floor area D north of pool female staff office	511	SF	7	10+ years				
	Ceiling - Plaster/Drywall	1st floor area D north of pool male staff office	212	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st floor area D north of pool male staff office	10	SF	5	0-1 year	Minor cracking			
	Doors - Steel Doors incl hw	1st floor area D north of pool male staff office	2	EA	7	10+ years				
	Doors - Transom Window	1st floor area D north of pool male staff office	36	SF	7	10+ years				
	Floor - Tile	1st floor area D north of pool male staff office	222	SF	7	10+ years				
	Lighting - Lay-in	1st floor area D north of pool male staff office	2	EA	7	6-10 years				
	Power Distribution	1st floor area D north of pool male staff office	6	EA	7	10+ years				
	Walls - Concrete Block	1st floor area D north of pool male staff office	511	SF	7	10+ years				
	Ceiling - Lay-in	1st floor area D office suite at NE corner	3,130	SF	7	10+ years				
	Doors - Side-lite	1st floor area D office suite at NE corner	13	SF	7	10+ years				
	Doors - Transom Window	1st floor area D office suite at NE corner	36	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st floor area D office suite at NE corner	10	EA	7	10+ years				
	Floor - Carpet	1st floor area D office suite at NE corner	3,130	SF	7	6-10 years				
	Lighting - Lay-in	1st floor area D office suite at NE corner	63	EΑ	7	6-10 years				
	Power Distribution	1st floor area D office suite at NE corner	72	EA	7	10+ years				
	Storage/ Closet	1st floor area D office suite at NE corner	100	SF	7	10+ years				
	Storage/ Closet	1st floor area D office suite at NE corner	150	SF	7	10+ years				
	Walls - Concrete Block	1st floor area D office suite at NE corner	3,822	SF	7	10+ years				
	Walls - Plaster/Drywall	1st floor area D office suite at NE	3,822	SF	7	10+ years				



Category : Room			Building : Main						
Croun	Hom Tune	Location	Ouantitu	HOM	Donk	Recommend	Comments		
Group	Item - Type	corner	Quantity	UOM	Rank	Replacement	Comments		
	Work SInk	1st floor area D office suite at NE corner	1	EA	7	10+ years			
	Ceiling - Lay-in	1st floor area D office suite at SE corner	3,130	SF	7	10+ years			
	Doors - Side-lite	1st floor area D office suite at SE corner	13	SF	7	10+ years			
	Doors - Transom Window	1st floor area D office suite at SE corner	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor area D office suite at SE corner	10	EA	7	10+ years			
	Floor - Carpet	1st floor area D office suite at SE corner	3,130	SF	7	6-10 years			
	Lighting - Lay-in	1st floor area D office suite at SE corner	63	EA	7	6-10 years			
	Power Distribution	1st floor area D office suite at SE corner	48	EA	7	10+ years			
	Storage/ Closet	1st floor area D office suite at SE corner	150	SF	7	10+ years			
	Walls - Concrete Block	1st floor area D office suite at SE corner	3,822	SF	7	10+ years			
	Walls - Plaster/Drywall	1st floor area D office suite at SE corner	3,822	SF	7	10+ years			
	Work SInk	1st floor area D office suite at SE corner	1	EA	7	10+ years			
	Ceiling - Lay-in	1st floor office next to 4-100	286	SF	7	10+ years			
	Doors - Side-lite	1st floor office next to 4-100	13	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st floor office next to 4-100	1	EA	7	10+ years			
	Doors - Transom Window	1st floor office next to 4-100	13	SF	7	10+ years			
	Floor - Carpet	1st floor office next to 4-100	286	SF	7	6-10 years			
	Lighting - Lay-in	1st floor office next to 4-100	3	EA	7	6-10 years			
	Power Distribution	1st floor office next to 4-100	4	EA	7	10+ years			
	Walls - Concrete Block	1st floor office next to 4-100	740	SF	7	10+ years			
	Ceiling - Lay-in	1st floor teacher's lounge northwest of lunch room	251	SF	7	10+ years			
	Ceiling - Lay-in	1st floor teacher's lounge northwest of lunch room	12	SF	4	1-2 years	Active water leak damage tiles		
	Doors - Steel Doors incl hw	1st floor teacher's lounge northwest of lunch room	2	EA	7	10+ years			
	Floor - Tile	1st floor teacher's lounge northwest of lunch room	263	SF	7	10+ years			
	Lighting - Lay-in	1st floor teacher's lounge northwest of lunch room	3	EA	7	6-10 years			
	Power Distribution	1st floor teacher's lounge northwest	10	EA	7	10+ years			



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		of lunch room							
	Walls - Concrete Block	1st floor teacher's lounge northwest	627	SF	7	10+ years			
		of lunch room							
	Work SInk	1st floor teacher's lounge northwest	1	EΑ	7	10+ years			
		of lunch room							
	Ceiling - Lay-in	2-100	251	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2-100	1	EA	7	10+ years			
	Floor - Carpet	2-100	251	SF	7	10+ years			
	Lighting - Lay-in	2-100	4	EA	7	6-10 years			
	Power Distribution	2-100	12	EA	7	10+ years			
	Walls - Concrete Block	2-100	510	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor - Library Professional	261	SF	6	10+ years			
		Area Office							
	Doors - Wood Doors inclu hw	2nd Floor - Library Professional	1	EA	7	10+ years			
		Area Office							
	Floor - Carpet	2nd Floor - Library Professional	261	SF	6	6-10 years			
		Area Office							
	Lighting - Lay-in	2nd Floor - Library Professional	4	EA	7	6-10 years			
		Area Office							
	Power Distribution	2nd Floor - Library Professional	10	EA	7	10+ years			
		Area Office							
	Storage/ Closet	2nd Floor - Library Professional	55	SF	5	10+ years			
		Area Office							
	Walls - Concrete Block	2nd Floor - Library Professional	259	SF	7	10+ years			
		Area Office							
	Walls - Plaster/Drywall	2nd Floor - Library Professional	259	SF	7	10+ years			
		Area Office							
	Ceiling - Lay-in	2nd Floor-4-201A	155	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor-4-201A	1	EA	7	10+ years			
	Floor - Tile	2nd Floor-4-201A	155	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor-4-201A	2	EA	7	6-10 years			
	Power Distribution	2nd Floor-4-201A	6	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor-4-201A	480	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor-4-201B	155	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor-4-201B	1	EA	7	10+ years			
	Floor - Tile	2nd Floor-4-201B	155	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor-4-201B	2	EA	7	6-10 years			
	Power Distribution	2nd Floor-4-201B	6	EA	7	10+ years			
	Storage/ Closet	2nd Floor-4-201B	4	SF	7	6-10 years			
	Walls - Concrete Block	2nd Floor-4-201B	240	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor-4-201B	240	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor-4-201C	155	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor-4-201C	1	EA	7	10+ years			
	Floor - Tile	2nd Floor-4-201C	155	SF	7	10+ years			



Catego	ry : Room		Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Lay-in	2nd Floor-4-201C	2	EA	7	6-10 years				
	Power Distribution	2nd Floor-4-201C	6	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor-4-201C	120	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor-4-201C	360	SF	6	10+ years				
	Ceiling - Lay-in	2nd Floor-Library Office 207A	104	SF	7	10+ years				
	Doors - Side-lite	2nd Floor-Library Office 207A	10	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor-Library Office 207A	1	EA	7	10+ years				
	Floor - Carpet	2nd Floor-Library Office 207A	104	SF	6	6-10 years				
	Lighting - Lay-in	2nd Floor-Library Office 207A	2	EA	7	6-10 years				
	Power Distribution	2nd Floor-Library Office 207A	8	EA	7	10+ years				
	Walls - Concrete Block	2nd Floor-Library Office 207A	395	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor-Library Workroom	428	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor-Library Workroom	20	SF	4	0-1 year	Water damage			
	Doors - Side-lite	2nd Floor-Library Workroom	105	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor-Library Workroom	1	EA	7	10+ years				
	Floor - Tile	2nd Floor-Library Workroom	448	SF	7	10+ years				
	Lighting - Lay-in	2nd Floor-Library Workroom	8	EA	7	6-10 years				
	Power Distribution	2nd Floor-Library Workroom	8	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor-Library Workroom	565	SF	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor-Library Workroom	252	SF	7	10+ years				
	Work Sink	2nd Floor-Library Workroom	1	EA	7	10+ years				
	Ceiling - Lay-in	2nd floor Sound and Control room next to the elevator	375	SF	7	10+ years				
	Doors - Steel Doors incl hw	2nd floor Sound and Control room next to the elevator	2	EA	7	10+ years				
	Doors - Wood Doors inclu hw	2nd floor Sound and Control room next to the elevator	1	EA	7	10+ years				
	Floor - Tile	2nd floor Sound and Control room next to the elevator	375	SF	7	10+ years				
	Lighting - Lay-in	2nd floor Sound and Control room next to the elevator	4	EA	7	6-10 years				
	Power Distribution	2nd floor Sound and Control room next to the elevator	6	EA	7	10+ years				
	Walls - Concrete Block	2nd floor Sound and Control room next to the elevator	860	SF	7	10+ years				
	Ceiling - Lay-in	4-200A	155	SF	6	10+ years				
	Doors - Wood Doors inclu hw	4-200A	1	EΑ	7	10+ years				
	Floor - Tile	4-200A	155	SF	7	10+ years				
	Lighting - Lay-in	4-200A	2	ĒΑ	7	6-10 years				
	Power Distribution	4-200A	6	ΕA	7	10+ years				
	Walls - Concrete Block	4-200A	240	SF	7	10+ years				
	Walls - Plaster/Drywall	4-200A	240	SF	6	10+ years				
	Ceiling - Lay-in	4-200B	155	SF	6	10+ years				
	Doors - Wood Doors inclu hw	4-200B	1	EA	7	10+ years				
		. 2002	•		•	,				



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	4-200B	155	SF	7	10+ years			
	Lighting - Lay-in	4-200B	2	EA	7	6-10 years			
	Power Distribution	4-200B	6	EA	7	10+ years			
	Walls - Concrete Block	4-200B	240	SF	7	10+ years			
	Walls - Plaster/Drywall	4-200B	240	SF	7	10+ years			
	Ceiling - Lay-in	4-200C	155	SF	6	10+ years			
	Doors - Wood Doors inclu hw	4-200C	1	EA	7	10+ years			
	Floor - Tile	4-200C	155	SF	7	10+ years			
	Lighting - Lay-in	4-200C	2	EA	7	6-10 years			
	Power Distribution	4-200C	6	EA	7	10+ years			
	Walls - Concrete Block	4-200C	120	SF	7	10+ years			
	Walls - Plaster/Drywall	4-200C	360	SF	7	10+ years			
	Ceiling - Lay-in	A211 inside professional office	253	SF	7	10+ years			
	Ceiling - Lay-in	A211 inside professional office	8	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	A211 inside professional office	1	EA	7	10+ years			
	Floor - Carpet	A211 inside professional office	261	SF	7	10+ years			
	Lighting - Lay-in	A211 inside professional office	4	EA	7	10+ years			
	Power Distribution	A211 inside professional office	10	EΑ	7	6-10 years			
	Walls - Concrete Block	A211 inside professional office	259	SF	7	10+ years			
	Walls - Plaster/Drywall	A211 inside professional office	259	SF	7	10+ years			
	Ceiling - Lay-in	Admin in clinic	100	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Admin in clinic	1	EA	7	10+ years			
	Floor - Tile	Admin in clinic	100	SF	7	10+ years			
	Lighting - Lay-in	Admin in clinic	1	EA	7	10+ years			
	Power Distribution	Admin in clinic	4	EA	7	10+ years			
	Walls - Concrete Block	Admin in clinic	180	SF	7	10+ years			
	Ceiling - Lay-in	Area B SW corner (B123)	150	SF	7	10+ years			
	Doors - Steel Doors incl hw	Area B SW corner (B123)	1	EA	7	10+ years			
	Floor - Tile	Area B SW corner (B123)	150	SF	7	10+ years			
	Lighting - Lay-in	Area B SW corner (B123)	2	ĒΑ	7	6-10 years			
	Power Distribution	Area B SW corner (B123)	4	ĒΑ	7	10+ years			
	Walls - Concrete Block	Area B SW corner (B123)	412	SF	7	10+ years			
	Ceiling - Lay-in	Area of rescue beside the Elevator	64	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Area of rescue beside the Elevator	1	ĒΑ	7	10+ years			
	Floor - Tile	Area of rescue beside the Elevator	64	SF	7	10+ years			
	Lighting - Pendent/Surface	Area of rescue beside the Elevator	1	EA	7	10+ years			
	Power Distribution	Area of rescue beside the Elevator	1	EA	7	6-10 years			
	Walls - Concrete Block	Area of rescue beside the Elevator	150	SF	7	10+ years			
	Ceiling - Lay-in	Clinic Area A	616	SF	7	10+ years			
	Doors - Side-lite	Clinic Area A	65	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Clinic Area A	1	EA	7	10+ years			
	Floor - Carpet	Clinic Area A	616	SF	7	6-10 years			
	Lighting - Lay-in	Clinic Area A	8	EA	7	6-10 years			
	Lighting - Lay-in	Clinic Area A	2	EA	5	0-10 years	Not working		
	Lighting - Lay-in	Ollillo Alba A	2	LA	5	u-i yeai	THO E WORKING		



Category : Room		В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Clinic Area A	12	EA	7	10+ years	
	Storage/ Closet	Clinic Area A	78	SF	7	10+ years	
	Walls - Concrete Block	Clinic Area A	92	SF	7	10+ years	
	Walls - Plaster/Drywall	Clinic Area A	820	SF	7	10+ years	
	Ceiling - Lay-in	Dressing Room #1	336	SF	7	10+ years	
	Doors - Steel Doors incl hw	Dressing Room #1	1	EA	7	10+ years	
	Floor - Tile	Dressing Room #1	336	SF	7	10+ years	
	Lighting - Lay-in	Dressing Room #1	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	Dressing Room #1	9	EA	6	2-5 years	No bulbs
	Lighting - Wall Mounted	Dressing Room #1	30	EA	6	2-5 years	No bulbs
	Power Distribution	Dressing Room #1	60	EA	7	10+ years	
	Walls - Concrete Block	Dressing Room #1	609	SF	7	10+ years	
	Work SInk	Dressing Room #1	1	EA	7	10+ years	
	Ceiling - Lay-in	Dressing Room #2	320	SF	7	10+ years	
	Ceiling - Lay-in	Dressing Room #2	16	SF	4	1-2 years	Water stained tile
	Doors - Steel Doors incl hw	Dressing Room #2	1	EA	7	10+ years	
	Floor - Tile	Dressing Room #2	336	SF	7	10+ years	
	Lighting - Lay-in	Dressing Room #2	6	EA	7	6-10 years	
	Power Distribution	Dressing Room #2	6	EA	7	10+ years	
	Walls - Concrete Block	Dressing Room #2	609	SF	7	10+ years	
	Ceiling - Lay-in	Dressing Room #3	367	SF	7	10+ years	
	Doors - Steel Doors incl hw	Dressing Room #3	1	EA	7	10+ years	
	Floor - Tile	Dressing Room #3	367	SF	7	10+ years	
	Lighting - Lay-in	Dressing Room #3	3	EA	7	6-10 years	
	Lighting - Wall Mounted	Dressing Room #3	35	EA	7	6-10 years	
	Power Distribution	Dressing Room #3	60	EA	7	10+ years	
	Walls - Concrete Block	Dressing Room #3	641	SF	7	10+ years	
	Ceiling - Lay-in	Exam A	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam A	1	EA	7	10+ years	
	Floor - Tile	Exam A	100	SF	7	10+ years	
	Lighting - Lay-in	Exam A	1	EA	7	6-10 years	
	Power Distribution	Exam A	4	EA	7	10+ years	
	Walls - Concrete Block	Exam A	90	SF	7	10+ years	
	Walls - Plaster/Drywall	Exam A	160	SF	7	10+ years	
	Work SInk	Exam A	1	EA	7	10+ years	
	Ceiling - Lay-in	Exam B	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Exam B	1	EΑ	7	10+ years	
	Floor - Tile	Exam B	100	SF	7	10+ years	
	Lighting - Lay-in	Exam B	1	EA	7	6-10 years	
	Power Distribution	Exam B	4	EA	7	10+ years	
	Walls - Concrete Block	Exam B	90	SF	7	10+ years	
	Walls - Plaster/Drywall	Exam B	160	SF	7	10+ years	
	Work SInk	Exam B	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	Exam C	100	SF	7	10+ years	
	,	=::::::: =	.00	٠.	•	,	



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Exam C	1	EA	7	10+ years			
	Floor - Tile	Exam C	100	SF	7	10+ years			
	Lighting - Lay-in	Exam C	1	EA	7	6-10 years			
	Power Distribution	Exam C	4	EA	7	10+ years			
	Walls - Concrete Block	Exam C	90	SF	7	10+ years			
	Walls - Plaster/Drywall	Exam C	160	SF	7	10+ years			
	Work SInk	Exam C	1	EA	7	10+ years			
	Ceiling - Lay-in	Exam C	100	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Exam C	1	EA	7	10+ years			
	Floor - Tile	Exam C	100	SF	7	10+ years			
	Lighting - Lay-in	Exam C	2	EA	7	6-10 years			
	Power Distribution	Exam C	4	EA	7	10+ years			
	Walls - Plaster/Drywall	Exam C	220	SF	7	10+ years			
	Work SInk	Exam C	1	EA	7	10+ years			
	Ceiling - Lay-in	Kitchen Office	92	SF	7	10+ years			
	Doors - Side-lite	Kitchen Office	13	SF	7	10+ years			
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	7	10+ years			
	Doors - Transom Window	Kitchen Office	48	SF	7	10+ years			
	Floor - Tile	Kitchen Office	92	SF	7	10+ years			
	Lighting - Lay-in	Kitchen Office	2	EA	7	6-10 years			
	Power Distribution	Kitchen Office	4	EA	7	10+ years			
	Walls - Concrete Block	Kitchen Office	261	SF	7	10+ years			
	Ceiling - Lay-in	LAB inside clinic	186	SF	7	10+ years			
	Doors - Wood Doors inclu hw	LAB inside clinic	1	EA	7	10+ years			
	Floor - Tile	LAB inside clinic	186	SF	7	10+ years			
	Lighting - Lay-in	LAB inside clinic	3	EA	7	6-10 years			
	Power Distribution	LAB inside clinic	4	EA	7	10+ years			
	Walls - Concrete Block	LAB inside clinic	220	SF	7	10+ years			
	Walls - Plaster/Drywall	LAB inside clinic	200	SF	7	10+ years			
	Work SInk	LAB inside clinic	1	EA	7	10+ years			
	Ceiling - Lay-in	Main entrance, back of reception area	304	SF	7	10+ years			
	Doors - Side-lite	Main entrance, back of reception area	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Main entrance, back of reception area	1	EA	7	10+ years			
	Floor - Carpet	Main entrance, back of reception area	304	SF	7	6-10 years			
	Lighting - Lay-in	Main entrance, back of reception area	6	EA	7	6-10 years			
	Power Distribution	Main entrance, back of reception	10	EA	7	10+ years			
	Walls - Concrete Block	area Main entrance, back of reception area	560	SF	7	10+ years			
		arta							



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Ceiling - Lay-in	Main entrance, reception area	304	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Main entrance, reception area	1	EA	7	10+ years				
	Floor - Carpet	Main entrance, reception area	304	SF	7	6-10 years				
	Lighting - Lay-in	Main entrance, reception area	4	EA	7	6-10 years				
	Lighting - Pendent/Surface	Main entrance, reception area	6	EA	7	10+ years				
	Power Distribution	Main entrance, reception area	10	EA	7	10+ years				
	Walls - Masonry	Main entrance, reception area	280	SF	7	10+ years				
	Walls - Plaster/Drywall	Main entrance, reception area	280	SF	7	10+ years				
	Ceiling - Lay-in	Men's Gym Teacher's Office	281	SF	7	10+ years				
	Ceiling - Lay-in	Men's Gym Teacher's Office	12	SF	4	1-2 years	Water stained tile			
	Doors - Side-lite	Men's Gym Teacher's Office	13	SF	7	10+ years				
	Doors - Steel Doors incl hw	Men's Gym Teacher's Office	1	EA	7	10+ years				
	Floor - Tile	Men's Gym Teacher's Office	293	SF	7	10+ years				
	Lighting - Lay-in	Men's Gym Teacher's Office	3	EA	7	6-10 years				
	Power Distribution	Men's Gym Teacher's Office	8	EA	7	10+ years				
	Walls - Concrete Block	Men's Gym Teacher's Office	571	SF	7	10+ years				
	Ceiling - Lay-in	Office #2, 1st Floor at Main Entry	115	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office #2, 1st Floor at Main Entry	1	EA	7	10+ years				
	Floor - Carpet	Office #2, 1st Floor at Main Entry	115	SF	7	6-10 years				
	Lighting - Lay-in	Office #2, 1st Floor at Main Entry	2	EA	7	6-10 years				
	Power Distribution	Office #2, 1st Floor at Main Entry	8	EA	7	10+ years				
	Walls - Concrete Block	Office #2, 1st Floor at Main Entry	175	SF	7	10+ years				
	Walls - Plaster/Drywall	Office #2, 1st Floor at Main Entry	175	SF	7	10+ years				
	Ceiling - Lay-in	Office #3, 1st Floor at Main Entr	115	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office #3, 1st Floor at Main Entr	1	EA	7	10+ years				
	Floor - Carpet	Office #3, 1st Floor at Main Entr	115	SF	7	6-10 years				
	Lighting - Lay-in	Office #3, 1st Floor at Main Entr	2	EA	7	6-10 years				
	Power Distribution	Office #3, 1st Floor at Main Entr	8	EA	7	10+ years				
	Walls - Concrete Block	Office #3, 1st Floor at Main Entr	175	SF	7	10+ years				
	Walls - Plaster/Drywall	Office #3, 1st Floor at Main Entr	175	SF	7	10+ years				
	Ceiling - Lay-in	Office in Room 1-102	90	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office in Room 1-102	1	EA	7	10+ years				
	Floor - Carpet	Office in Room 1-102	90	SF	7	6-10 years				
	Lighting - Lay-in	Office in Room 1-102	1	EA	7	6-10 years				
	Power Distribution	Office in Room 1-102	6	EA	7	10+ years				
	Walls - Concrete Block	Office in Room 1-102	200	SF	7	10+ years				
	Ceiling - Lay-in	Office suite at main entrance, office	80	SF	7	10+ years				
	- · · · · · · · · · · · · · · · · · · ·	from storage			-	,				
	Doors - Wood Doors inclu hw	Office suite at main entrance, office	1	EA	7	10+ years				
		from storage			•	,				
	Floor - Tile	Office suite at main entrance, office	80	SF	7	10+ years				
		from storage	00	٥.	•	10. 300.0				
	Lighting - Lay-in	Office suite at main entrance, office	2	EA	7	10+ years				
	Lighting Lay III	from storage	2	_/\	,	ioi youis				
		nom storage								



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Power Distribution	Office suite at main entrance, office	6	EA	7	10+ years				
		from storage								
	Walls - Concrete Block	Office suite at main entrance, office	140	SF	7	10+ years				
		from storage								
	Ceiling - Lay-in	Office, 1st Floor at Main Entry	125	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Office, 1st Floor at Main Entry	1	EA	7	10+ years				
	Floor - Carpet	Office, 1st Floor at Main Entry	125	SF	7	6-10 years				
	Lighting - Lay-in	Office, 1st Floor at Main Entry	2	EA	7	6-10 years				
	Power Distribution	Office, 1st Floor at Main Entry	8	EA	7	10+ years				
	Walls - Concrete Block	Office, 1st Floor at Main Entry	175	SF	7	10+ years				
	Walls - Plaster/Drywall	Office, 1st Floor at Main Entry	175	SF	7	10+ years				
	Ceiling - Lay-in	Security Office main entrance	122	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Security Office main entrance	1	EA	7	10+ years				
	Floor - Carpet	Security Office main entrance	122	SF	7	6-10 years				
	Lighting - Lay-in	Security Office main entrance	2	EA	7	6-10 years				
	Power Distribution	Security Office main entrance	8	EA	7	10+ years				
	Walls - Concrete Block	Security Office main entrance	162	SF	7	10+ years				
	Walls - Plaster/Drywall	Security Office main entrance	162	SF	7	10+ years				
	Ceiling - Lay-in	Women's Gym Teacher's Office	293	SF	7	10+ years				
	Doors - Side-lite	Women's Gym Teacher's Office	13	SF	7	10+ years				
	Doors - Steel Doors incl hw	Women's Gym Teacher's Office	1	EA	7	10+ years				
	Floor - Tile	Women's Gym Teacher's Office	293	SF	7	10+ years				
	Lighting - Lay-in	Women's Gym Teacher's Office	4	EA	7	6-10 years				
	Power Distribution	Women's Gym Teacher's Office	8	EA	7	10+ years				
	Walls - Concrete Block	Women's Gym Teacher's Office	571	SF	7	10+ years				
	Ceiling - Lay-in	Workshop, next to the Stage	978	SF	7	10+ years				
	Doors - Steel Doors incl hw	Workshop, next to the Stage	1	EA	7	10+ years				
	Floor - Concrete	Workshop, next to the Stage	978	SF	7	10+ years				
	Lighting - Lay-in	Workshop, next to the Stage	11	EA	7	6-10 years				
	Lighting - Lay-in	Workshop, next to the Stage	1	EA	5	0-1 year	Not working			
	Power Distribution	Workshop, next to the Stage	10	EA	7	10+ years				
	Walls - Concrete Block	Workshop, next to the Stage	1,518	SF	7	10+ years				
	Work SInk	Workshop, next to the Stage	1	EA	7	10+ years				
A !!!	0. The attain									
_Auditorii	um & Theater	4 of Floor	0.000			40				
	Ceiling - Exposed	1st Floor	2,829	SF	7	10+ years				
	Doors - Steel Doors incl hw	1st Floor	6	EΑ	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years				
	Floor - Carpet	1st Floor	1,414	SF	7	6-10 years				
	Floor - Concrete	1st Floor	708	SF	7	10+ years				
	Floor - Tile	1st Floor	707	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	18	EΑ	7	6-10 years				
	Main Floor Seating	1st Floor	475	EΑ	7	10+ years				
	Sound System	1st Floor	1	EA	7	10+ years				



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage	1st Floor	3,248	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	16	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,644	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,644	SF	7	10+ years	
Gymnas	ia						
	Bleacher Seating	1st floor Area B	910	EA	5	1-2 years	Damaged bleachers
	Ceiling - Exposed	1st floor Area B	11,170	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor Area B	8	EΑ	7	10+ years	
	Floor - Wood	1st floor Area B	11,170	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st floor Area B	32	EA	7	6-10 years	
	Scoreboards	1st floor Area B	2	EA	7	10+ years	
	Sound System	1st floor Area B	1	EA	7	10+ years	
	Storage/ Closet	1st floor Area B	680	SF	7	10+ years	
	Storage/ Closet	1st floor Area B	85	SF	7	10+ years	
	Walls - Concrete Block	1st floor Area B	13,933	SF	7	10+ years	
	Ceiling - Exposed	1st floor area D at SW corner	5.838	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor area D at SW corner	4	ĒΑ	7	10+ years	
	Floor - Wood	1st floor area D at SW corner	5,838	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st floor area D at SW corner	24	ĒΑ	7	6-10 years	
	Scoreboards	1st floor area D at SW corner	1	EA	7	10+ years	
	Sound System	1st floor area D at SW corner	1	EA	7	10+ years	
	Storage/ Closet	1st floor area D at SW corner	220	SF	7	10+ years	
	Walls - Concrete Block	1st floor area D at SW corner	7,614	SF	7	10+ years	
	Walls - Plaster/Drywall	1st floor area D at SW corner	3,807	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st floor area C SW corner	2,014	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor area C SW corner	4	EA	7	10+ years	
	Floor - Tile Quarry	1st floor area C SW corner	2,014	SF	7	10+ years	
	Lighting - Lay-in	1st floor area C SW corner	18	EΑ	6	6-10 years	
	Storage/ Closet	1st floor area C SW corner	40	SF	7	10+ years	
	Storage/ Closet	1st floor area C SW corner	287	SF	7	10+ years	
	Walls - Concrete Block	1st floor area C SW corner	2,375	SF	7	10+ years	
Library							
,	Casework	2nd Floor-Library, Area A1	325	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Library, Area A1	5,630	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor-Library, Area A1	<sup>′</sup> 16	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor-Library, Area A1	224	SF	7	10+ years	Č
	Doors - Transom Window	2nd Floor-Library, Area A1	12	SF	7	10+ years	
		· <b>//</b>				,	



Catego	ry : Room		В	uilding	: Main			
	_				_	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	2nd Floor-Library, Area A1	4	EA	7	10+ years		
	Floor - Carpet	2nd Floor-Library, Area A1	5,646	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor-Library, Area A1	30	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor-Library, Area A1	78	EA	7	6-10 years		
	Storage/ Closet	2nd Floor-Library, Area A1	428	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor-Library, Area A1	2,312	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor-Library, Area A1	4,325	SF	7	10+ years		
ocker/S	Shower Room							
	Accessories	Men's PE Locker Room	2,245	SF	7	6-10 years		
	Benches, ped mounted	Men's PE Locker Room	220	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Men's PE Locker Room	2,245	SF	7	10+ years		
	Doors - Steel Doors incl hw	Men's PE Locker Room	2,243	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Men's PE Locker Room	1,860	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Men's PE Locker Room	385	SF	7	10+ years		
	Floor Drain	Men's PE Locker Room	14	EA	7	•		
						10+ years	Droken	
	Hand Dryer	Men's PE Locker Room	3	EΑ	5	1-2 years	Broken	
	Lavatory	Men's PE Locker Room	1	EA	7	10+ years		
	Lighting - Lay-in	Men's PE Locker Room	30	EΑ	7	10+ years		
	Partitions	Men's PE Locker Room	3	EA	7	10+ years		
	Showers	Men's PE Locker Room	6	EA	7	10+ years		
	Student Lockers - One Tier	Men's PE Locker Room	112	EA	7	10+ years		
	Student Lockers - Three Tiers	Men's PE Locker Room	161	EA	7	10+ years		
	Walls - Concrete Block	Men's PE Locker Room	2,469	SF	7	10+ years		
	Water Closet	Men's PE Locker Room	3	EA	7	10+ years		
	Benches, ped mounted	Men's Team Locker Room	140	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Men's Team Locker Room	1,445	SF	7	10+ years		
	Doors - Steel Doors incl hw	Men's Team Locker Room	2	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Men's Team Locker Room	1,445	SF	7	10+ years		
	Floor Drain	Men's Team Locker Room	4	EA	7	10+ years		
	Lighting - Lay-in	Men's Team Locker Room	14	EA	7	6-10 years		
	Student Lockers - One Tier	Men's Team Locker Room	108	EΑ	7	10+ years		
	Walls - Concrete Block	Men's Team Locker Room	2,011	SF	7	10+ years		
	Accessories	Pool Men's Locker Room	1,140	SF	7	6-10 years		
	Benches, ped mounted	Pool Men's Locker Room	273	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Pool Men's Locker Room	1,140	SF	7	10+ years		
	Doors - Steel Doors incl hw	Pool Men's Locker Room	2	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Pool Men's Locker Room	906	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Pool Men's Locker Room	234	SF	7	,		
	Floor Drain		23 <del>4</del> 10	SF EA	7	10+ years		
		Pool Men's Locker Room				10+ years	Prokon	
	Hand Dryer	Pool Men's Locker Room	3	EΑ	5	1-2 years	Broken	
	Lavatory	Pool Men's Locker Room	2	EΑ	7	10+ years		
	Lighting - Lay-in	Pool Men's Locker Room	16	EA	7	6-10 years		
	Partitions	Pool Men's Locker Room	3	EA	7	10+ years		



Catego	ry : Room		Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Showers	Pool Men's Locker Room	6	EA	7	10+ years				
	Student Lockers - One Tier	Pool Men's Locker Room	82	EA	7	10+ years				
	Student Lockers - One Tier	Pool Men's Locker Room	6	EA	5	1-2 years	Hardware missing			
	Walls - Concrete Block	Pool Men's Locker Room	3,911	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	Pool Men's Locker Room	394	SF	7	10+ years				
	Water Closet	Pool Men's Locker Room	3	EA	7	10+ years				
	Accessories	Pool women's locker room	1,140	SF	7	6-10 years				
	Benches, ped mounted	Pool women's locker room	273	LF	7	10+ years				
	Ceiling - Plaster/Drywall	Pool women's locker room	1,140	SF	7	10+ years				
	Doors - Steel Doors incl hw	Pool women's locker room	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Pool women's locker room	906	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Pool women's locker room	234	SF	7	10+ years				
	Floor Drain	Pool women's locker room	10	EA	7	10+ years				
	Hand Dryer	Pool women's locker room	2	EA	7	6-10 years				
	Hand Dryer	Pool women's locker room	1	EA	5	1-2 years	Broken			
	Lavatory	Pool women's locker room	2	EΑ	7	10+ years				
	Lighting - Lay-in	Pool women's locker room	16	EA	7	6-10 years				
	Partitions	Pool women's locker room	3	EA	7	10+ years				
	Showers	Pool women's locker room	6	EA	7	10+ years				
	Student Lockers - One Tier	Pool women's locker room	88	EΑ	7	10+ years				
	Walls - Concrete Block	Pool women's locker room	1,911	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	Pool women's locker room	394	SF	7	10+ years				
	Water Closet	Pool women's locker room	3	EA	7	10+ years				
	Benches, ped mounted	Women Team locker room	60	LF	7	10+ years				
	Ceiling - Plaster/Drywall	Women Team locker room	680	SF	7	10+ years				
	Doors - Steel Doors incl hw	Women Team locker room	2	EA	7	10+ years				
	Floor - Concrete Epoxy/ Painted	Women Team locker room	680	SF	7	10+ years				
	Floor Drain	Women Team locker room	2	EA	7	10+ years				
	Lighting - Lay-in	Women Team locker room	6	EΑ	7	10+ years				
	Student Lockers - One Tier	Women Team locker room	56	EΑ	7	10+ years				
	Walls - Concrete Block	Women Team locker room	640	SF	7	10+ years				
	Accessories	Women's PE Locker Room	2,245	SF	7	6-10 years				
	Benches, ped mounted	Women's PE Locker Room	220	LF	7	10+ years				
	Ceiling - Plaster/Drywall	Women's PE Locker Room	2,245	SF	7	10+ years				
	Doors - Steel Doors incl hw	Women's PE Locker Room	2,243	EA	7	10+ years				
	Floor - Concrete	Women's PE Locker Room	1,860	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Women's PE Locker Room	385	SF	7	10+ years				
	Floor Drain	Women's PE Locker Room	14	EA	7	10+ years				
	Hand Dryer	Women's PE Locker Room	3	EA	7	6-10 years				
		Women's PE Locker Room	1	EA	7					
	Lavatory	Women's PE Locker Room Women's PE Locker Room	30	EA	7	10+ years				
	Lighting - Lay-in					6-10 years				
	Partitions	Women's PE Locker Room	3	EA EA	7	10+ years				
	Showers	Women's PE Locker Room	6	EA EA	7 7	10+ years				
	Student Lockers - One Tier	Women's PE Locker Room	112	EA	1	10+ years				



Catego	ry : Room		В	uilding	: Main			
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Student Lockers - Three Tiers	Women's PE Locker Room	161	EA	7	10+ years		
	Walls - Concrete Block	Women's PE Locker Room	2,469	SF	7	10+ years		
	Water Closet	Women's PE Locker Room	3	EA	7	10+ years		
Lunch &	Multipurpose Room							
	Ceiling - Exposed	1st Floor	1,500	SF	7	10+ years	Not previously assessed	
	Ceiling - Lay-in	1st Floor	5,420	SF	7	10+ years	,	
	Doors - Steel Doors incl hw	1st Floor	8	ĒΑ	7	10+ years		
	Floor - Terrazzo	1st Floor	5,580	SF	7	10+ years		
	Floor - Tile Quarry	1st Floor	1,340	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	28	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	100	EΑ	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	10	EA	5	0-1 year	Not working	
	Serving Line	1st Floor	100	LF	7	10+ years	Not working	
	Walls - Concrete Block	1st Floor	4,666	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	6,316	SF	7	10+ years		
	Walls - Flastel/Drywall	151 11001	0,310	SI	,	10+ years		
MDF_ID								
	Doors - Steel Doors incl hw	2nd Floor	1	EΑ	6	10+ years		
	Finishes	2nd Floor	128	SF	7	10+ years		
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years		
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	55	SF	7	10+ years		
	Janitor's Closet	1st Floor	55	SF	7	10+ years		
	Janitor's Closet	1st Floor	26	SF	7	10+ years		
	Janitor's Closet	1st Floor	55	SF	7	10+ years		
	Janitor's Closet	1st Floor	26	SF	7	10+ years		
	Janitor's Closet	1st Floor	26	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	264	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	515	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	40	SF	7	10+ years		
	Boiler Room	2nd Floor	1,235	SF	7	10+ years		
	Janitor's Closet	2nd Floor	38	SF	7	10+ years		
	Janitor's Closet	2nd Floor	55	SF	7	10+ years		
	Janitor's Closet  Janitor's Closet	2nd Floor 2nd Floor	55 55	SF SF	7 7	10+ years 10+ years		
		2nd Floor 2nd Floor	55 55	SF SF	7	-		
	Janitor's Closet		55 55	SF SF		10+ years		
	Janitor's Closet	2nd Floor			7	10+ years		
	Janitor's Closet	2nd Floor	55	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	1,126	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	1,726	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	41	SF	7	10+ years		



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Mechanical/ Service Rooms	2nd Floor	41	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	1,810	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	36	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	1,120	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	650	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	36	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	2,025	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	148	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	2,434	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	325	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	1,132	SF	7	10+ years			
	Storage Room	2nd Floor	370	SF	7	10+ years			
	Storage Room	2110 1 1001	370	Oi.	,	10+ years			
Pool & N	latatorium								
	Accessories	1st Floor	8,749	SF	7	10+ years			
	Bleachers Seating/Plank Seating	1st Floor	72	EA	7	10+ years			
	Ceiling - Exposed	1st Floor	8,749	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	1st Floor	8,749	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	22	EA	7	6-10 years			
	Lighting - Wall Mounted	1st Floor	30	EA	7	6-10 years			
	Pool Basin	1st Floor	4,143	SF	7	10+ years			
	Pool Deck	1st Floor	2,926	SF	7	10+ years			
	Pool Deck Drains	1st Floor	3	ĒΑ	7	10+ years			
	Walls - Concrete Block	1st Floor	9,183	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	3,935	SF	7	10+ years			
Prep Ro	om								
	Casework	2nd Floor- serves 1-201 and 1-205	30	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor- serves 1-201 and 1-205	337	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor- serves 1-201 and 1-205	8	SF	4	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor- serves 1-201 and 1-205	13	SF	7	10+ years			
	Doors - Transom Window	2nd Floor- serves 1-201 and 1-205	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor- serves 1-201 and 1-205	1	EA	7	10+ years			
	Floor - Tile	2nd Floor- serves 1-201 and 1-205	345	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor- serves 1-201 and 1-205	4	EΑ	7	6-10 years			
	Walls - Concrete Block	2nd Floor- serves 1-201 and 1-205	160	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor- serves 1-201 and 1-205	225	SF	7	10+ years			
	Work Sink	2nd Floor- serves 1-201 and 1-205	2	EA	7	10+ years			
	Casework	2nd Floor- serves 2-201 and 2-203	30	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor-serves 2-201 and 2-203	337	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor- serves 2-201 and 2-203	8	SF	4	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor- serves 2-201 and 2-203 2nd Floor- serves 2-201 and 2-203	13	SF	7	10+ years	vvater damage		
	Doors - Wood Doors inclu hw	2nd Floor- serves 2-201 and 2-203	3	EA	7	10+ years			



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor- serves 2-201 and 2-203	345	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor- serves 2-201 and 2-203	4	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor- serves 2-201 and 2-203	160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor- serves 2-201 and 2-203	225	SF	6	10+ years	
	Work Sink	2nd Floor- serves 2-201 and 2-203	2	EA	7	10+ years	
	Casework	3- 204 serves 3-202 and 3-206	30	LF	6	10+ years	
	Ceiling - Lay-in	3- 204 serves 3-202 and 3-206	329	SF	6	10+ years	
	Ceiling - Lay-in	3- 204 serves 3-202 and 3-206	16	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3- 204 serves 3-202 and 3-206	3	EA	7	10+ years	3
	Floor - Tile	3- 204 serves 3-202 and 3-206	345	SF	6	10+ years	
	Lighting - Lay-in	3- 204 serves 3-202 and 3-206	2	ĒΑ	7	10+ years	
	Walls - Concrete Block	3- 204 serves 3-202 and 3-206	160	SF	6	10+ years	
	Walls - Plaster/Drywall	3- 204 serves 3-202 and 3-206	225	SF	6	10+ years	
	Work Sink	3- 204 serves 3-202 and 3-206	2	ĒΑ	7	10+ years	
	Casework	4-204 serves 4-202 and 4-206	30	LF	6	10+ years	
	Ceiling - Lay-in	4-204 serves 4-202 and 4-206	337	SF	6	10+ years	
	Ceiling - Lay-in	4-204 serves 4-202 and 4-206	8	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	4-204 serves 4-202 and 4-206	1	EA	6	10+ years	Trails, damage
	Floor - Tile	4-204 serves 4-202 and 4-206	345	SF	6	10+ years	
	Lighting - Lay-in	4-204 serves 4-202 and 4-206	2	EA	7	6-10 years	
	Walls - Concrete Block	4-204 serves 4-202 and 4-206	160	SF	6	10+ years	
	Walls - Plaster/Drywall	4-204 serves 4-202 and 4-206	225	SF	6	10+ years	
	Work Sink	4-204 serves 4-202 and 4-206	2	EA	7	10+ years	
_Restroon	ח						
	Accessories	1st Floor Boy's Room in Area A East (A120)	304	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Boy's Room in Area A East (A120)	304	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boy's Room in Area A East (A120)	304	SF	7	10+ years	
	Floor Drain	1st Floor Boy's Room in Area A East (A120)	1	EA	7	10+ years	
	Hand Dryer	1st Floor Boy's Room in Area A East (A120)	2	EA	7	6-10 years	
	Lavatory	1st Floor Boy's Room in Area A East (A120)	2	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Boy's Room in Area A East (A120)	10	EA	7	6-10 years	
	Partitions	1st Floor Boy's Room in Area A East (A120)	2	EA	5	2-5 years	Graffiti on stalls
	Urinals	1st Floor Boy's Room in Area A East (A120)	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boy's Room in Area A East	572	SF	7	10+ years	



Category : Room			Building : Main						
	_					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	(A120) 1st Floor Boy's Room in Area A East (A120)	2	EA	7	10+ years			
	Accessories	1st Floor Boy's Room in Area A West (A166)	304	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Boy's Room in Area A West (A166)	304	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Boy's Room in Area A West (A166)	304	SF	7	10+ years			
	Hand Dryer	1st Floor Boy's Room in Area A West (A166)	2	EA	7	6-10 years			
	Lavatory	1st Floor Boy's Room in Area A West (A166)	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor Boy's Room in Area A West (A166)	10	EA	7	6-10 years			
	Partitions	1st Floor Boy's Room in Area A West (A166)	2	EA	5	2-5 years	Graffiti on partitions		
	Urinals	1st Floor Boy's Room in Area A West (A166)	3	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor Boy's Room in Area A West (A166)	572	SF	7	10+ years			
	Water Closet	1st Floor Boy's Room in Area A West (A166)	2	EA	7	10+ years			
	Accessories	1st Floor Girl's Room in Area A East (A106)	304	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Girl's Room in Area A East (A106)	304	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's Room in Area A East (A106)	304	SF	7	10+ years			
	Floor Drain	1st Floor Girl's Room in Area A East (A106)	1	EA	7	10+ years			
	Hand Dryer	1st Floor Girl's Room in Area A East (A106)	2	EA	7	6-10 years			
	Lavatory	1st Floor Girl's Room in Area A East (A106)	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor Girl's Room in Area A East (A106)	10	EA	7	6-10 years			
	Partitions	1st Floor Girl's Room in Area A East (A106)	5	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor Girl's Room in Area A East (A106)	572	SF	7	10+ years			
	Water Closet	1st Floor Girl's Room in Area A East (A106)	5	EA	7	10+ years			
	Accessories	1st Floor Girl's Room in Area A	304	SF	7	6-10 years			



Category : Room			Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	West (A167) 1st Floor Girl's Room in Area A	304	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	West (A167) 1st Floor Girl's Room in Area A West (A167)	304	SF	7	10+ years			
	Floor Drain	1st Floor Girl's Room in Area A West (A167)	1	EA	7	10+ years			
	Hand Dryer	1st Floor Girl's Room in Area A West (A167)	2	EA	7	6-10 years			
	Lavatory	1st Floor Girl's Room in Area A West (A167)	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor Girl's Room in Area A West (A167)	10	EA	7	6-10 years			
	Partitions	1st Floor Girl's Room in Area A West (A167)	5	EA	5	2-5 years	Wearing finish on partitions		
	Walls - Structural Glazed Tile	1st Floor Girl's Room in Area A West (A167)	572	SF	7	10+ years			
	Water Closet	1st Floor Girl's Room in Area A West (A167)	4	EA	7	10+ years			
	Water Closet	1st Floor Girl's Room in Area A West (A167)	1	EA	4	1-2 years	Not in service		
	Accessories	1st floor Area D inside NE corner offices (D144)	63	SF	7	6-10 years			
	Ceiling - Lay-in	1st floor Area D inside NE corner offices (D144)	63	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor Area D inside NE corner offices (D144)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor Area D inside NE corner offices (D144)	63	SF	7	10+ years			
	Floor Drain	1st floor Area D inside NE corner offices (D144)	1	EA	7	10+ years			
	Lavatory	1st floor Area D inside NE corner offices (D144)	1	EA	7	10+ years			
	Lighting - Lay-in	1st floor Area D inside NE corner offices (D144)	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st floor Area D inside NE corner offices (D144)	96	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st floor Area D inside NE corner offices (D144)	66	SF	7	10+ years			
	Water Closet	1st floor Area D inside NE corner offices (D144)	1	EA	7	10+ years			
	Accessories	1st floor Boys area B north (B127)	366	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st floor Boys area B north (B127)	366	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor Boys area B north (B127)	366	SF	7	10+ years			



Category : Room			Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	1st floor Boys area B north (B127)	2	EA	7	10+ years				
	Hand Dryer	1st floor Boys area B north (B127)	2	EA	7	6-10 years				
	Lavatory	1st floor Boys area B north (B127)	2	EA	7	10+ years				
	Lighting - Lay-in	1st floor Boys area B north (B127)	16	EA	7	6-10 years	<b>6 4 1 1 1 1 1 1 1 1 1 1</b>			
	Partitions	1st floor Boys area B north (B127)	3	EΑ	5	2-5 years	Graffiti on partitions			
	Urinals	1st floor Boys area B north (B127)	5	EA	7	10+ years				
	Walls - Structural Glazed Tile	1st floor Boys area B north (B127)	812	SF EA	7	10+ years				
	Water Closet	1st floor Boys area B north (B127)	3	SF	7 7	10+ years				
	Accessories Ceiling - Plaster/Drywall	1st floor Men's next to Auditorium 1st floor Men's next to Auditorium	99 99	SF SF	7	6-10 years 10+ years				
	Doors - Wood Doors inclu hw	1st floor Men's next to Auditorium	1	EA	7	10+ years				
	Floor - Terrazzo	1st floor Men's next to Auditorium	99	SF	7	10+ years				
	Floor Drain	1st floor Men's next to Additorium	1	EA	7	10+ years				
	Lavatory	1st floor Men's next to Additorium	1	EA	7	10+ years				
	Lighting - Lay-in	1st floor Men's next to Auditorium	2	EA	7	6-10 years				
	Walls - Structural Glazed Tile	1st floor Men's next to Auditorium	210	SF	7	10+ years				
	Water Closet	1st floor Men's next to Auditorium	1	ĒΑ	7	10+ years				
	Accessories	1st floor area C all Gender next to	59	SF	7	6-10 years				
		kitchen (C118)				,				
	Ceiling - Plaster/Drywall	1st floor area C all Gender next to	59	SF	7	10+ years				
		kitchen (C118)								
	Doors - Wood Doors inclu hw	1st floor area C all Gender next to	1	EA	7	10+ years				
		kitchen (C118)								
	Floor - Tile Ceramic/ Porcelain	1st floor area C all Gender next to	59	SF	7	10+ years				
		kitchen (C118)								
	Floor Drain	1st floor area C all Gender next to	1	EA	7	10+ years				
		kitchen (C118)	4	_ ^	-	4.0				
	Lavatory	1st floor area C all Gender next to	1	EA	7	10+ years				
	Limbina Lavia	kitchen (C118)	4	EA	7	0.40				
	Lighting - Lay-in	1st floor area C all Gender next to kitchen (C118)	1	EA	7	6-10 years				
	Walls - Concrete Block	1st floor area C all Gender next to	187	SF	7	10+ years				
	Walls - Coliciete block	kitchen (C118)	107	SF	,	10+ years				
	Water Closet	1st floor area C all Gender next to	1	EA	7	10+ years				
	Water Gloset	kitchen (C118)	'	LA	,	10+ years				
	Accessories	1st floor area C men's next to	59	SF	7	6-10 years				
		kitchen (C115)		О.	•	o io you.o				
	Ceiling - Plaster/Drywall	1st floor area C men's next to	59	SF	7	10+ years				
	5 · · · · · · · · · · · · · · · · · · ·	kitchen (C115)			-	,				
	Doors - Steel Doors incl hw	1st floor area C men's next to	1	EA	7	10+ years				
		kitchen (C115)				·				
	Floor - Tile Ceramic/ Porcelain	1st floor area C men's next to	59	SF	7	10+ years				
		kitchen (C115)				•				
	Floor Drain	1st floor area C men's next to	1	EA	7	10+ years				



Category : Room			Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		kitchen (C115)			_			
	Lavatory	1st floor area C men's next to	1	EA	7	10+ years		
	Linkston Lavido	kitchen (C115)	4	_^	7	0.40		
	Lighting - Lay-in	1st floor area C men's next to	1	EA	7	6-10 years		
	Walls - Concrete Block	kitchen (C115) 1st floor area C men's next to	187	SF	7	10+ years		
	Walls - Concrete block	kitchen (C115)	101	SF	,	10+ years		
	Water Closet	1st floor area C men's next to	1	EA	7	10+ years		
	vvaler Gloset	kitchen (C115)		L/\	,	101 years		
	Accessories	1st floor area D Boy's (D156)	366	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st floor area D Boy's (D156)	366	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor area D Boy's (D156)	366	SF	7	10+ years		
	Floor Drain	1st floor area D Boy's (D156)	2	EA	7	10+ years		
	Hand Dryer	1st floor area D Boy's (D156)	2	EA	7	6-10 years		
	Lavatory	1st floor area D Boy's (D156)	2	EA	7	10+ years		
	Lighting - Lay-in	1st floor area D Boy's (D156)	6	EA	7	6-10 years		
	Lighting - Lay-in	1st floor area D Boy's (D156)	10	EA	5	0-1 year	Not working	
	Partitions	1st floor area D Boy's (D156)	3	EA	5	2-5 years	Graffiti on partitions	
	Urinals	1st floor area D Boy's (D156)	5	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st floor area D Boy's (D156)	812	SF	7	10+ years		
	Water Closet	1st floor area D Boy's (D156)	3	EA	7	10+ years		
	Accessories	1st floor area D Girl's (D127)	366	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st floor area D Girl's (D127)	366	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st floor area D Girl's (D127)	366	SF	7	10+ years		
	Floor Drain	1st floor area D Girl's (D127)	2	EA	7	10+ years		
	Hand Dryer	1st floor area D Girl's (D127)	2	EΑ	7	6-10 years		
	Lavatory	1st floor area D Girl's (D127)	2 16	EA EA	7	10+ years		
	Lighting - Lay-in Partitions	1st floor area D Girl's (D127) 1st floor area D Girl's (D127)		EA EA	7 5	6-10 years 2-5 years	Warn finish an nortition	
	Walls - Structural Glazed Tile	1st floor area D Girl's (D127)	8 812	SF	7	10+ years	Worn finish on partition	
	Water Closet	1st floor area D Girl's (D127)	8	EA	7	10+ years		
	Accessories	1st floor area D inside office suite at	63	SF	7	6-10 years		
	710003301103	SE corner (D173)	00	O1	'	o to years		
	Ceiling - Lay-in	1st floor area D inside office suite at	51	SF	7	10+ years		
	coming Lay in	SE corner (D173)	0.	O.	•	io. youro		
	Ceiling - Lay-in	1st floor area D inside office suite at	12	SF	4	1-2 years	Water Stained tile	
		SE corner (D173)		-		,		
	Doors - Wood Doors inclu hw	1st floor area D inside office suite at	1	EA	7	10+ years		
		SE corner (D173)	•			,		
	Floor - Tile Ceramic/ Porcelain	1st floor area D inside office suite at	63	SF	7	10+ years		
		SE corner (D173)				•		
	Floor Drain	1st floor area D inside office suite at	1	EA	7	10+ years		
		SE corner (D173)						
	Lavatory	1st floor area D inside office suite at	1	EA	7	10+ years		



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	11.12	SE corner (D173)		_^	-	0.40			
	Lighting - Lay-in	1st floor area D inside office suite at SE corner (D173)	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st floor area D inside office suite at	157	SF	7	10+ years			
	valie i lactor, bry wall	SE corner (D173)	107	O.	•	101 youro			
	Walls - Tile Ceramic/ Porcelain	1st floor area D inside office suite at	40	SF	7	10+ years			
		SE corner (D173)							
	Water Closet	1st floor area D inside office suite at	1	EA	7	10+ years			
	Accessories	SE corner (D173)  1st floor area D men's next to boy's	59	SF	7	6-10 years			
	Accessories	restroom (D153)	39	SI	,	0-10 years			
	Ceiling - Lay-in	1st floor area D men's next to boy's	23	SF	7	10+ years			
	-	restroom (D153)				•			
	Ceiling - Lay-in	1st floor area D men's next to boy's	36	SF	4	1-2 years	Water stained tile		
	Doors - Wood Doors inclu hw	restroom (D153) 1st floor area D men's next to boy's	4	EA	7	10			
	Doors - Wood Doors Inclu IIW	restroom (D153)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor area D men's next to boy's	59	SF	7	10+ years			
		restroom (D153)				, , , , , , , , , , , , , , , , , , , ,			
	Floor Drain	1st floor area D men's next to boy's	1	EA	7	10+ years			
		restroom (D153)			_	4.0			
	Lavatory	1st floor area D men's next to boy's restroom (D153)	1	EA	7	10+ years			
	Lighting - Lay-in	1st floor area D men's next to boy's	1	EA	7	6-10 years			
	gga,	restroom (D153)			•	0 10 700.0			
	Walls - Concrete Block	1st floor area D men's next to boy's	187	SF	7	10+ years			
		restroom (D153)			_	4.0			
	Water Closet	1st floor area D men's next to boy's restroom (D153)	1	EA	7	10+ years			
	Accessories	1st floor area D north of pool female	204	SF	7	6-10 years			
	710000001100	staff locker room (D106)	201	O.	•	o io youio			
	Benches	1st floor area D north of pool female	6	LF	7	10+ years			
		staff locker room (D106)			_				
	Ceiling - Plaster/Drywall	1st floor area D north of pool female	204	SF	7	10+ years			
	Doors - Steel Doors incl hw	staff locker room (D106) 1st floor area D north of pool female	2	EA	7	10+ years			
	Doors - Steel Doors mer nw	staff locker room (D106)	2	LA	,	10+ years			
	Floor - Tile	1st floor area D north of pool female	102	SF	7	10+ years			
		staff locker room (D106)				•			
	Floor - Tile Ceramic/ Porcelain	1st floor area D north of pool female	102	SF	7	10+ years			
	Floor Drain	staff locker room (D106) 1st floor area D north of pool female	2	⊏^	7	10			
	Floor Drain	staff locker room (D106)	3	EA	7	10+ years			
	Lavatory	1st floor area D north of pool female	1	EA	7	10+ years			
	·	,				,			



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		staff locker room (D106)					
	Lighting - Lay-in	1st floor area D north of pool female	4	EA	7	6-10 years	
	Okassa	staff locker room (D106)	4	_^	7	40	
	Showers	1st floor area D north of pool female	1	EA	7	10+ years	
	Student Lockers - One Tier	staff locker room (D106) 1st floor area D north of pool female	5	EA	7	10+ years	
	Student Lockers - One Her	staff locker room (D106)	5	LA	,	10+ years	
	Walls - Concrete Block	1st floor area D north of pool female	484	SF	7	10+ years	
	Walle Collecte Block	staff locker room (D106)	.01	O.	•	ioi youlo	
	Water Closet	1st floor area D north of pool female	1	EA	7	10+ years	
		staff locker room (D106)				•	
	Accessories	1st floor area D north of pool male	204	SF	7	6-10 years	
		staff locker room (D103)					
	Benches	1st floor area D north of pool male	6	LF	7	10+ years	
	0 '''	staff locker room (D103)	20.4	0=	_	4.0	
	Ceiling - Plaster/Drywall	1st floor area D north of pool male	204	SF	7	10+ years	
	Doors - Steel Doors incl hw	staff locker room (D103) 1st floor area D north of pool male	2	EA	7	10+ years	
	Doors - Steer Doors Inci nw	staff locker room (D103)	2	EA	,	10+ years	
	Floor - Tile	1st floor area D north of pool male	102	SF	7	10+ years	
	11001 1110	staff locker room (D103)	102	O.	•	101 youro	
	Floor - Tile Ceramic/ Porcelain	1st floor area D north of pool male	102	SF	7	10+ years	
		staff locker room (D103)				,	
	Floor Drain	1st floor area D north of pool male	3	EA	7	10+ years	
		staff locker room (D103)					
	Lavatory	1st floor area D north of pool male	1	EA	7	10+ years	
		staff locker room (D103)			_	0.40	
	Lighting - Lay-in	1st floor area D north of pool male	4	EA	7	6-10 years	
	Showers	staff locker room (D103) 1st floor area D north of pool male	1	EA	7	10+ years	
	Siloweis	staff locker room (D103)	ı	EA	,	10+ years	
	Student Lockers - One Tier	1st floor area D north of pool male	6	EA	7	10+ years	
	Cladem Edokore Che Her	staff locker room (D103)	ū	_, 、	•	ioi youlo	
	Walls - Concrete Block	1st floor area D north of pool male	484	SF	7	10+ years	
		staff locker room (D103)				,	
	Water Closet	1st floor area D north of pool male	1	EA	7	10+ years	
		staff locker room (D103)					
	Accessories	1st floor area D women's next to	59	SF	7	6-10 years	
		girl's restroom (B124)			_		
	Ceiling - Lay-in	1st floor area D women's next to	55	SF	7	10+ years	
	Cailing Lavin	girl's restroom (B124)	4	C.E.	E	0.1.4005	Matar atained tile
	Ceiling - Lay-in	1st floor area D women's next to girl's restroom (B124)	4	SF	5	0-1 year	Water stained tile
	Doors - Wood Doors inclu hw	1st floor area D women's next to	1	EA	7	10+ years	
	200.0 Wood 20010 III0id IIW	Tot hoof aroa b women's next to		_/\	,	ioi youis	



Category : Room			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	-	girl's restroom (B124)					
	Floor - Tile Ceramic/ Porcelain	1st floor area D women's next to girl's restroom (B124)	59	SF	7	10+ years	
	Floor Drain	1st floor area D women's next to girl's restroom (B124)	1	EA	7	10+ years	
	Lavatory	1st floor area D women's next to girl's restroom (B124)	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor area D women's next to girl's restroom (B124)	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor area D women's next to girl's restroom (B124)	187	SF	7	10+ years	
	Water Closet	1st floor area D women's next to girl's restroom (B124)	1	EA	7	10+ years	
	Accessories	1st floor men's next to auditorium (A168)	59	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor men's next to auditorium (A168)	35	SF	7	10+ years	
	Ceiling - Lay-in	1st floor men's next to auditorium	24	SF	4	1-2 years	Water stained tile
	Doors - Steel Doors incl hw	(A168) 1st floor men's next to auditorium	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	(A168) 1st floor men's next to auditorium (A168)	59	SF	7	10+ years	
	Floor Drain	1st floor men's next to auditorium (A168)	1	EA	7	10+ years	
	Lavatory	1st floor men's next to auditorium (A168)	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor men's next to auditorium (A168)	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor men's next to auditorium (A168)	187	SF	7	10+ years	
	Water Closet	1st floor men's next to auditorium (A168)	1	EA	7	10+ years	
	Accessories	1st floor women Area B (B185)	62	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor women Area B (B185)	62	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor women Area B (B185)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor women Area B (B185)	62	SF	7	10+ years	
	Floor Drain	1st floor women Area B (B185)	1	EA	4	0-1 year	Drain covered
	Lavatory	1st floor women Area B (B185)	1	EA	7	10+ years	Brain covered
	Lighting - Lay-in	1st floor women Area B (B185)	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor women Area B (B185)	156	SF	7	10+ years	
	Water Closet	1st floor women Area B (B185)	130	EA	7	10+ years	
	Accessories	1st floor women area B South	366	SF	7	6-10 years	
	ACCESSOTIES	(B182)	300	ΟΓ	ı	0-10 years	



Catego	Category : Room			Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st floor women area B South (B182)	366	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor women area B South (B182)	366	SF	7	10+ years	
	Floor Drain	1st floor women area B South (B182)	2	EA	7	10+ years	
	Hand Dryer	1st floor women area B South (B182)	2	EA	7	6-10 years	
	Lavatory	1st floor women area B South (B182)	2	EA	7	10+ years	
	Lighting - Lay-in	1st floor women area B South (B182)	16	EA	7	6-10 years	
	Partitions	1st floor women area B South (B182)	8	EA	5	2-5 years	Worn finish on partitions
	Walls - Structural Glazed Tile	1st floor women area B South (B182)	812	SF	7	10+ years	
	Water Closet	1st floor women area B South (B182)	8	EA	7	10+ years	
	Accessories	2nd Floor Boy's Room in Area B 205	420	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boy's Room in Area B 205	420	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boy's Room in Area B 205	420	SF	6	10+ years	
	Hand Dryer	2nd Floor Boy's Room in Area B 205	2	EA	7	10+ years	
	Lavatory	2nd Floor Boy's Room in Area B 205	6	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor Boy's Room in Area B 205	10	EA	6	6-10 years	
	Partitions	2nd Floor Boy's Room in Area B 205	3	EA	5	10+ years	
	Urinals	2nd Floor Boy's Room in Area B 205	5	EA	6		
						10+ years	
	Walls - Structural Glazed Tile	2nd Floor Boy's Room in Area B 205	700	SF	6	10+ years	
	Water Closet	2nd Floor Boy's Room in Area B 205	3	EA	6	10+ years	
	Accessories	2nd Floor Girl's Room in Area A East A224	304	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's Room in Area A East A224	304	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girl's Room in Area A East A224	304	SF	6	10+ years	
	Hand Dryer	2nd Floor Girl's Room in Area A East A224	2	EA	7	6-10 years	
	Lavatory	2nd Floor Girl's Room in Area A East A224	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor Girl's Room in Area A East A224	10	EA	6	6-10 years	
	Partitions	2nd Floor Girl's Room in Area A East A224	5	EA	5	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girl's Room in Area A East A224	572	SF	6	10+ years	



Catego	ry : Room		Building : Main								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Water Closet	2nd Floor Girl's Room in Area A East A224	5	EA	6	10+ years					
	Accessories	2nd Floor-Women's Restroom, Area B233	62	SF	7	6-10 years					
	Ceiling - Lay-in	2nd Floor-Women's Restroom, Area B233	62	SF	7	10+ years					
	Doors - Steel Doors incl hw	2nd Floor-Women's Restroom, Area B233	1	EA	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Women's Restroom, Area B233	62	SF	7	10+ years					
	Floor Drain	2nd Floor-Women's Restroom, Area B233	1	EA	7	10+ years					
	Lavatory	2nd Floor-Women's Restroom, Area B233	1	EA	7	10+ years					
	Lighting - Lay-in	2nd Floor-Women's Restroom, Area B233	1	EA	7	6-10 years					
	Walls - Concrete Block	2nd Floor-Women's Restroom, Area B233	156	SF	7	10+ years					
	Water Closet	2nd Floor-Women's Restroom, Area B233	1	EA	7	10+ years					
	Accessories	2nd floor area C women's next to girl's restroom D207	59	SF	7	6-10 years					
	Ceiling - Lay-in	2nd floor area C women's next to girl's restroom D207	51	SF	6	10+ years					
	Ceiling - Lay-in	2nd floor area C women's next to girl's restroom D207	8	SF	4	1-2 years	Water damage				
	Doors - Wood Doors inclu hw	2nd floor area C women's next to girl's restroom D207	1	EA	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	2nd floor area C women's next to girl's restroom D207	59	SF	6	10+ years					
	Floor Drain	2nd floor area C women's next to girl's restroom D207	1	EA	7	10+ years					
	Lavatory	2nd floor area C women's next to girl's restroom D207	1	EA	6	10+ years					
	Lighting - Lay-in	2nd floor area C women's next to girl's restroom D207	1	EA	7	6-10 years					
	Walls - Concrete Block	2nd floor area C women's next to girl's restroom D207	187	SF	6	10+ years					
	Water Closet	2nd floor area C women's next to girl's restroom D207	1	EA	6	10+ years					
	Accessories	2nd floor area D Boy's D224	366	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	2nd floor area D Boy's D224	366	SF	6	10+ years					
	Floor - Tile Ceramic/ Porcelain	2nd floor area D Boy's D224	366	SF	6	10+ years					
	Floor Drain	2nd floor area D Boy's D224	2	EA	7	10+ years					
						-					



Category : Room		B	uilding	: Main			
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd floor area D Boy's D224	2	EA	7	6-10 years	
	Lavatory	2nd floor area D Boy's D224	2	EA	6	10+ years	
	Lighting - Lay-in	2nd floor area D Boy's D224	16	EA	7	6-10 years	
	Partitions	2nd floor area D Boy's D224	3	EA	5	10+ years	
	Urinals	2nd floor area D Boy's D224	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor area D Boy's D224	811	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor area D Boy's D224	1	SF	4	0-1 year	Chipped
	Water Closet	2nd floor area D Boy's D224	3	EΑ	6	10+ years	
	Accessories	2nd floor area D girl's D210	366	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor area D girl's D210	366	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor area D girl's D210	366	SF	6	10+ years	
	Floor Drain	2nd floor area D girl's D210	2	EA	7	10+ years	
	Hand Dryer	2nd floor area D girl's D210	2	EΑ	7	6-10 years	
	Lavatory	2nd floor area D girl's D210	2	EA	6	10+ years	
	Lighting - Lay-in	2nd floor area D girl's D210	16	EA	6	6-10 years	
	Partitions	2nd floor area D girl's D210	8	EA	5	10+ years	
	Walls - Structural Glazed Tile	2nd floor area D girl's D210	812	SF	7	10+ years	
	Water Closet	2nd floor area D girl's D210	8	EA	7	10+ years	
	Accessories	2nd floor area D men's D221	59	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor area D men's D221	51	SF	7	10+ years	
	Ceiling - Lay-in	2nd floor area D men's D221	8	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd floor area D men's D221	1	EA	7	10+ years	-
	Floor - Tile Ceramic/ Porcelain	2nd floor area D men's D221	59	SF	7	10+ years	
	Floor Drain	2nd floor area D men's D221	1	EA	7	10+ years	
	Lavatory	2nd floor area D men's D221	1	EA	7	10+ years	
	Lighting - Lay-in	2nd floor area D men's D221	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd floor area D men's D221	187	SF	6	10+ years	
	Water Closet	2nd floor area D men's D221	1	EA	6	10+ years	
	Accessories	In dressing room #2	100	SF	7	6-10 years	
	Ceiling - Lay-in	In dressing room #2	88	SF	7	10+ years	
	Ceiling - Lay-in	In dressing room #2	12	SF	4	1-2 years	Water stained tile
	Doors - Steel Doors incl hw	In dressing room #2	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In dressing room #2	100	SF	7	10+ years	
	Floor Drain	In dressing room #2	1	EA	7	10+ years	
	Lavatory	In dressing room #2	1	EA	7	10+ years	
	Lighting - Lay-in	In dressing room #2	1	EA	7	6-10 years	
	Walls - Concrete Block	In dressing room #2	220	SF	7	10+ years	
	Water Closet	In dressing room #2	1	EA	7	10+ years	
	Accessories	In dressing room #3	100	SF	7	6-10 years	
	Ceiling - Lay-in	In dressing room #3	100	SF	7	10+ years	
	Doors - Steel Doors incl hw	In dressing room #3	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In dressing room #3	100	SF	7	10+ years	
	Floor Drain	In dressing room #3	1	ĒΑ	7	10+ years	
	Lavatory	In dressing room #3	1	EA	7	10+ years	



Category : Room			Building : Main						
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	In dressing room #3	1	EA	7	6-10 years			
	Walls - Concrete Block	In dressing room #3	220	SF	7	10+ years			
	Water Closet	In dressing room #3	1	EA	7	10+ years			
	Accessories	In main office north area B (B136)	64	SF	7	6-10 years			
	Ceiling - Lay-in	In main office north area B (B136)	64	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In main office north area B (B136)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	In main office north area B (B136)	64	SF	7	10+ years			
	Floor Drain	In main office north area B (B136)	1	EA	7	10+ years			
	Lavatory	In main office north area B (B136)	1	EA	7	10+ years			
	Lighting - Lay-in	In main office north area B (B136)	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	In main office north area B (B136)	96	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	In main office north area B (B136)	66	SF	7	10+ years			
	Water Closet	In main office north area B (B136)	1	EA	7	10+ years			
	Accessories	In the Main Office South of area B (B164)	64	SF	7	6-10 years			
	Ceiling - Lay-in	In the Main Office South of area B (B164)	64	SF	7	10+ years			
	Doors - Wood Doors inclu hw	In the Main Office South of area B (B164)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	In the Main Office South of area B (B164)	64	SF	7	10+ years			
	Floor Drain	In the Main Office South of area B (B164)	1	EA	7	10+ years			
	Lavatory	In the Main Office South of area B (B164)	1	EA	7	10+ years			
	Lighting - Lay-in	In the Main Office South of area B (B164)	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	In the Main Office South of area B (B164)	96	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	In the Main Office South of area B (B164)	66	SF	7	10+ years			
	Water Closet	In the Main Office South of area B (B164)	1	EA	7	10+ years			
	Accessories	Inside clinic (A112)	64	SF	7	6-10 years			
	Ceiling - Lay-in	Inside clinic (A112)	64	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Inside clinic (A112)	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Inside clinic (A112)	64	SF	7	10+ years			
	Floor Drain	Inside clinic (A112)	1	EA	7	10+ years			
	Lavatory	Inside clinic (A112)	1	EA	7	10+ years			
	Lighting - Lay-in	Inside clinic (A112)	1	EA	7	6-10 years			
	Walls - Concrete Block	Inside clinic (A112)	161	SF	7	10+ years			
	Water Closet	Inside clinic (A112)	1	EA	7	10+ years			
	Accessories	Men's Room in Gym area B (B102)	161	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Men's Room in Gym area B (B102)	161	SF	7	10+ years			



Catego	ry : Room		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Men's Room in Gym area B (B102)	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room in Gym area B (B102)	161	SF	7	10+ years	
	Floor Drain	Men's Room in Gym area B (B102)	2	EA	4	0-1 year	Drain covered
	Lavatory	Men's Room in Gym area B (B102)	1	EA	7	10+ years	
	Lighting - Lay-in	Men's Room in Gym area B (B102)	3	EA	7	6-10 years	
	Showers	Men's Room in Gym area B (B102)	1	EA	7	10+ years	
	Student Lockers - One Tier	Men's Room in Gym area B (B102)	8	EA	7	6-10 years	
	Walls - Concrete Block	Men's Room in Gym area B (B102)	320	SF	7	10+ years	
	Water Closet	Men's Room in Gym area B (B102)	1	EA	7	10+ years	
	Accessories	Men's Room, 1st Floor Area B in	62	SF	7	6-10 years	
	<b>.</b>	East Corridor (B129)			_		
	Ceiling - Lay-in	Men's Room, 1st Floor Area B in	62	SF	7	10+ years	
	5	East Corridor (B129)			_	40	
	Doors - Wood Doors inclu hw	Men's Room, 1st Floor Area B in	1	EA	7	10+ years	
	Floor Tile Commist Posselsia	East Corridor (B129)	00	SF	7	40	
	Floor - Tile Ceramic/ Porcelain	Men's Room, 1st Floor Area B in	62	SF	7	10+ years	
	Floor Drain	East Corridor (B129) Men's Room, 1st Floor Area B in	1	EA	7	10	
	FIOOI DIAIN	East Corridor (B129)	ı	EA	/	10+ years	
	Lavatory	Men's Room, 1st Floor Area B in	1	EA	7	10+ years	
	Lavatory	East Corridor (B129)	'	LA	,	10+ years	
	Lighting - Lay-in Men's Room, 1st Floor Area B in 1 EA 6	6-10 years					
	Lighting Lay in	East Corridor (B129)		_, ,	Ū	o to youro	
	Walls - Concrete Block	Men's Room, 1st Floor Area B in	156	SF	7	10+ years	
		East Corridor (B129)				,	
	Water Closet	Men's Room, 1st Floor Area B in	1	EA	7	10+ years	
		East Corridor (B129)					
	Accessories	Men's Room, 2nd Floor Area B in	62	SF	7	6-10 years	
		West Corridor B208					
	Ceiling - Lay-in	Men's Room, 2nd Floor Area B in	50	SF	7	10+ years	
		West Corridor B208					
	Ceiling - Lay-in	Men's Room, 2nd Floor Area B in	12	SF	4	0-1 year	Water damage
		West Corridor B208					
	Doors - Steel Doors incl hw	Men's Room, 2nd Floor Area B in	1	EA	7	10+ years	
	El T'l 0 : /D l :	West Corridor B208	00	05	•	40	
	Floor - Tile Ceramic/ Porcelain	Men's Room, 2nd Floor Area B in	62	SF	6	10+ years	
	Floor Drain	West Corridor B208	4	EA	7	40	
	Floor Drain	Men's Room, 2nd Floor Area B in West Corridor B208	1	EA	7	10+ years	
	Lavatory	Men's Room, 2nd Floor Area B in	1	EA	7	10+ years	
	Lavalory	West Corridor B208	'	LA	,	10+ years	
	Lighting - Lay-in	Men's Room, 2nd Floor Area B in	1	EA	7	6-10 years	
	Lighting Lay III	West Corridor B208	'	<u>-</u> A	'	o To years	
	Walls - Concrete Block	Men's Room, 2nd Floor Area B in	156	SF	7	10+ years	
					-	,	



Catego	ry : Room		Building : Main							
_						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		West Corridor B208								
	Water Closet	Men's Room, 2nd Floor Area B in	1	EA	7	10+ years				
		West Corridor B208								
	Accessories	Next to CR 2-102 (A121)	64	SF	7	6-10 years				
	Ceiling - Lay-in	Next to CR 2-102 (A121)	64	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Next to CR 2-102 (A121)	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Next to CR 2-102 (A121)	64	SF	7	10+ years				
	Floor Drain	Next to CR 2-102 (A121)	1	EA	7	10+ years				
	Lavatory	Next to CR 2-102 (A121)	1	EA	7	10+ years				
	Lighting - Lay-in	Next to CR 2-102 (A121)	2	EA	7	6-10 years				
	Walls - Concrete Block	Next to CR 2-102 (A121)	162	SF	7	10+ years				
	Water Closet	Next to CR 2-102 (A121)	1	EA SF	7 7	10+ years				
	Accessories	Women's Room in Gym area B (B122)	161		1	6-10 years				
	Ceiling - Plaster/Drywall	Women's Room in Gym area B (B122)	161	SF	7	10+ years				
	Doors - Steel Doors incl hw	Women's Room in Gym area B (B122)	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Women's Room in Gym area B (B122)	161	SF	7	10+ years				
	Floor Drain	Women's Room in Gym area B (B122)	2	EA	7	10+ years				
	Lavatory	Women's Room in Gym area B (B122)	1	EA	7	10+ years				
	Lighting - Lay-in	Women's Room in Gym area B (B122)	3	EA	7	6-10 years				
	Showers	Women's Room in Gym area B (B122)	1	EA	7	10+ years				
	Student Lockers - One Tier	Women's Room in Gym area B (B122)	8	EA	7	10+ years				
	Walls - Concrete Block	Women's Room in Gym area B (B122)	320	SF	7	10+ years				
	Water Closet	Women's Room in Gym area B (B122)	1	EA	7	10+ years				
	Accessories	Women's Room, 1st Floor Aera A in West Corridor (A169)	62	SF	7	6-10 years				
	Ceiling - Lay-in	Women's Room, 1st Floor Aera A in West Corridor (A169)	62	SF	7	10+ years				
	Doors - Steel Doors incl hw	Women's Room, 1st Floor Aera A in West Corridor (A169)	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Women's Room, 1st Floor Aera A in West Corridor (A169)	62	SF	7	10+ years				
	Floor Drain	Women's Room, 1st Floor Aera A in West Corridor (A169)	1	EA	7	10+ years				



Category : Room			Building : Main								
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Lavatory	Women's Room, 1st Floor Aera A in West Corridor (A169)	1	EA	7	6-10 years					
	Lighting - Lay-in	Women's Room, 1st Floor Aera A in West Corridor (A169)	1	EA	7	6-10 years					
	Walls - Concrete Block	Women's Room, 1st Floor Aera A in West Corridor (A169)	156	SF	7	10+ years					
	Water Closet	Women's Room, 1st Floor Aera A in West Corridor (A169)	1	EA	7	10+ years					
	Accessories	Women's Room, 1st Floor next to Auditorium	62	SF	7	6-10 years					
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor next to Auditorium	62	SF	7	10+ years					
	Doors - Wood Doors inclu hw	Women's Room, 1st Floor next to Auditorium	1	EA	7	10+ years					
	Floor - Terrazzo	Women's Room, 1st Floor next to Auditorium	62	SF	7	10+ years					
	Floor Drain	Women's Room, 1st Floor next to Auditorium	1	EA	7	10+ years					
	Lavatory	Women's Room, 1st Floor next to Auditorium	1	EA	7	10+ years					
	Lighting - Lay-in	Women's Room, 1st Floor next to Auditorium	2	EA	7	6-10 years					
	Walls - Structural Glazed Tile	Women's Room, 1st Floor next to Auditorium	156	SF	7	10+ years					
	Water Closet	Women's Room, 1st Floor next to Auditorium	1	EA	7	10+ years					
	Accessories	Women's Room, 2nd Floor Area A in East Corridor A226	62	SF	7	6-10 years					
	Ceiling - Lay-in	Women's Room, 2nd Floor Area A in East Corridor A226	58	SF	7	10+ years					
	Ceiling - Lay-in	Women's Room, 2nd Floor Area A in East Corridor A226	4	SF	4	1-2 years	Water damage				
	Doors - Wood Doors inclu hw	Women's Room, 2nd Floor Area A in East Corridor A226	1	EA	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	Women's Room, 2nd Floor Area A in East Corridor A226	62	SF	7	10+ years					
	Floor Drain	Women's Room, 2nd Floor Area A in East Corridor A226	1	EA	7	10+ years					
	Lavatory	Women's Room, 2nd Floor Area A in East Corridor A226	1	EA	7	10+ years					
	Lighting - Lay-in	Women's Room, 2nd Floor Area A in East Corridor A226	1	EA	7	10+ years					
	Walls - Concrete Block	Women's Room, 2nd Floor Area A in East Corridor A226	156	SF	7	10+ years					



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Women's Room, 2nd Floor Area A in East Corridor A226	1	EA	7	10+ years	
	Accessories	Women's Room, 2nd Floor Area A in West Corridor A213	62	SF	7	6-10 years	
	Ceiling - Lay-in	Women's Room, 2nd Floor Area A in West Corridor A213	62	SF	7	10+ years	
	Doors - Steel Doors incl hw	Women's Room, 2nd Floor Area A in West Corridor A213	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, 2nd Floor Area A in West Corridor A213	62	SF	7	10+ years	
	Floor Drain	Women's Room, 2nd Floor Area A in West Corridor A213	1	EA	7	10+ years	
	Lavatory	Women's Room, 2nd Floor Area A in West Corridor A213	1	EA	7	10+ years	
	Lighting - Lay-in	Women's Room, 2nd Floor Area A in West Corridor A213	1	EA	7	10+ years	
	Walls - Concrete Block	Women's Room, 2nd Floor Area A in West Corridor A213	156	SF	7	10+ years	
	Water Closet	Women's Room, 2nd Floor Area A in West Corridor A213	1	EA	7	10+ years	

Category: Classroom **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #1-101 (Computer Lab)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,180	SF	7	10+ years	
	Doors - Side-lite	1st Floor	26	SF	7	10+ years	
	Doors - Transom Window	1st Floor	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,180	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,021	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	340	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
Classroo	om #1-102 (Art Room)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,208	SF	7	10+ years	
	Doors - Side-lite	1st Floor	<sup>^</sup> 15	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,208	SF	7	10+ years	



Catego	tegory : Classroom			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	15	EΑ	7	6-10 years	
	Marker Board	1st Floor	4	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,464	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #1-103 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor	4	EA	5	0-1 year	Not working
	Marker Board	1st Floor	16	LF	7	6-10 years	Not working
	Walls - Concrete Block	1st Floor	717	SF	7	•	
		1st Floor	239	SF	7	10+ years	
	Walls - Plaster/Drywall	IST FIOOI	239	SF	,	10+ years	
Classroo	om #1-104 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	574	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	582	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classroo	om #1-105 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	717	SF	7	10+ years	
		1st Floor	239	SF	7	•	
	Walls - Plaster/Drywall	151 11001	239	SF	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		120 O ROSING! AVENUE, Officago, 12 00020
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #1-106 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	239	SF	7	10+ years	
Classroo	om #1-107 (Regular Classroom)						
CIGOSIOC	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	1-2 years	Door lock damaged
	Floor - Tile	1st Floor	890	SF	7	10+ years	2001 1001t damaged
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	239	SF	7	10+ years	
01						•	
_Classroo	om #1-108 (Regular Classroom)	A . FI					
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	715	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	240	SF	7	10+ years	
_Classroo	om #1-201 (Science Lab Level 1)						
	Casework	2nd Floor	64	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,211	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		120 O NOStrici AVENOE, Officago, 12 00025
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,211	SF	7	10+ years	
	Gas Line	2nd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,211	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	7	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,015	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	60	SF	7	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classroo	om #1-202 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	239	SF	6	10+ years	
Classroo	om #1-204 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	858	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	32	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	Water damage
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	239	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	200	SF	6	10+ years	
Classroo	om #1-205 (Science Lab Level 1)						
	Casework	2nd Floor	64	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,211	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	7	10+ years	
	Doors - Side-life Doors - Transom Window	2nd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Doors - Wood Doors IIIdia IIW	2110 1 1001	2	LA	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,211	SF	7	10+ years	
	Gas Line	2nd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,211	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	6	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,015	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classroo	om #1-206 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	866	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	3.
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	239	SF	7	10+ years	
_Classroo	om #1-207 (Science Classroom)						
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	18	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	717	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	239	SF	6	10+ years	
	Work Sink	2nd Floor	3	EΑ	7	10+ years	
Classro	om #1-208 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	872	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	18	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	vvaler uarriage
	DOOIS - Olde-life	2110 1 1001	12	JF.	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	717	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	239	SF	7	10+ years	
Classroo	om #2-101 (Computer Lab)						
	Casework	1st Floor	25	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,085	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	12	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	Bamagea ine
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,097	SF	7	10+ years	
		1st Floor		EA			
	Lighting - Lay-in Marker Board	1st Floor	16 16	LF	7 7	6-10 years	
				SF		6-10 years	
	Walls - Concrete Block	1st Floor	1,002		7	10+ years	
	Walls - Plaster/Drywall	1st Floor	334	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
Classroo	om #2-102 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	1,132	SF	7	10+ years	
	Doors - Side-lite	1st Floor	15	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,132	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	<sup>'</sup> 21	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	180	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,404	SF	7	10+ years	
Classroo	om #2-103 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	882	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	•	
	vvalis - Concrete block	ISLFIOOI	582	ЭF	1	10+ years	



Catego	Category : Classroom		В	uilding	: Main		120 o Rostilei Avervoe, Officago, le 00023
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classro	om #2-104 (Regular Classroom)						
	Ceiling - Lay-in	1st Floor	582	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	582	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classes	#2 405 (Parular Classes)						
_Ciassio	om #2-105 (Regular Classroom) Casework	1st Floor	16	LF	7	10 L Voors	
				SF		10+ years	
	Ceiling - Lay-in	1st Floor	890		7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	134	SF	7	10+ years	
_Classroo	om #2-106 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classro	om #2-107 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	874	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	Trator stanion the
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
			10	٥.	•	. c . y care	

Page : 53 of 74



Catego	ategory : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	890	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classroo	om #2-108 (Regular Classroom)						
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	840	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	50	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	Trater stamed the
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	13	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF	4	1-2 years	Chipped and cracked tile
				_			Chipped and cracked tile
	Lighting - Lay-in	1st Floor	14	EA LF	7	6-10 years	
	Marker Board	1st Floor	16		7	6-10 years	
	Walls - Concrete Block	1st Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	194	SF	7	10+ years	
Classroo	om #2-200 (Regular Classroom)						
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,147	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,147	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,166	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,166	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #2-201 (Science Lab Level 1)						
	Casework	2nd Floor	75	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,211	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
		2nd Floor 2nd Floor	1	EA	7		
	Eye Wash Station		· · · · · · · · · · · · · · · · · · ·			10+ years	
	Floor - Tile	2nd Floor	1,211	SF	7	10+ years	
	Gas Line	2nd Floor	14	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	

Page : 54 of 74



Catego	ory : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,211	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	6	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,015	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classro	om #2-202 (Regular Classroom)						
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	874	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	Water damage
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	890	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	•	
	Walls - Concrete Block	2nd Floor	582	SF	7	6-10 years 10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	194	SF	6	10+ years	
Classro	om #2-203 (Science Lab Level 1)						
_ OldSSIO	Casework	2nd Floor	75	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,211	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,211	SF	7	10+ years	
	Gas Line	2nd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,211	SF	7	6-10 years	
					6	•	
	Science Lab Fume Hood Science Lab Shower	2nd Floor 2nd Floor	1	EA EA	7	10+ years 10+ years	
	Walls - Concrete Block	2nd Floor	1,015	SF	7		
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	350	SF	6	10+ years	
	Walls - Plaster/Drywall Work Sink	2nd Floor	8	SF EA	7	10+ years 10+ years	
		2110 I 1001	O	_/ \	,	ioi youis	
Classroo	om #2-204 (Regular Classroom)	0.151					
	Casework	2nd Floor	22	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	890	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	13	EA	6	6-10 years			
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	194	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Damaged wallpaper		
Classro	om #2-205 (Regular Classroom)								
Classiu	Casework	2nd Floor	16	LF	6	10+ years			
				SF	-				
	Ceiling - Lay-in	2nd Floor	882		7	10+ years	NA		
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage.		
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	870	SF	7	10+ years			
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked		
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	585	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	194	SF	7	10+ years			
Classroo	om #2-206 (Regular Classroom)								
Oldoorox	Casework	2nd Floor	22	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	890	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	12	SF	7				
	Doors - Side-life Doors - Transom Window			SF SF		10+ years			
		2nd Floor	12		7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	880	SF	7	10+ years			
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Cracked		
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	194	SF	7	10+ years			
Classroo	om #2-208 (Regular Classroom)								
	Casework	2nd Floor	22	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	882	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage		
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	Tratol damage		
	Doors - Transom Window	2nd Floor 2nd Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	12	SF EA	7				
			•			10+ years			
	Floor - Tile	2nd Floor	880	SF	7	10+ years			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Chipped
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	582	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	194	SF	7	10+ years	
lassroo	om #3-102 (Computer Lab)						
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,185	SF	7	10+ years	
	Doors - Side-lite	1st Floor	26	SF	7	10+ years	
	Doors - Transom Window	1st Floor	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,185	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	
lassroo	om #3-104 (Regular Classroom)						
1000.00	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	867	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	water damage
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7		
	Marker Board	1st Floor	16	LF	7	6-10 years 6-10 years	
	Walls - Concrete Block	1st Floor	750	SF			
	Walls - Concrete Block Walls - Plaster/Drywall	1st Floor	250	SF SF	7 7	10+ years 10+ years	
	·	13(1100)	200	Oi.	,	101 years	
lassroc	om #3-105 (Office)	3rd Floor	10	LF	7	10+ years	
	Casework	3rd Floor	534	SF	7 7		
	Ceiling - Lay-in			SF SF		10+ years	
	Doors - Side-lite	3rd Floor	13		7	10+ years	
	Doors - Transom Window	3rd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	534	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	641	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	214	SF	7	10+ years	



	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	839	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	36	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
Classroc	om #3-107 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	19	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	•	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years 10+ years	
Classroc	om #3-108 (Regular Classroom)						
Classiou	` •	1st Floor	20	1.5	7	40	
	Casework		20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
Classroc	om #3-109 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	883	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	30	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	913	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	768	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	256	SF	7	10+ years	
lassroo	om #3-202 (Science Lab Level 3)						
<u> </u>	Casework	2nd Floor	65	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	26	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	26	SF SF		-	
					7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
	Eye Wash Station	2nd Floor	1 405	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,185	SF	6	10+ years	
	Gas Line	2nd Floor	13	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,185	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	6	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	884	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	295	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classroc	om #3-203 (Regular Classroom)						
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	water damage
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor			7		
			13	EA		6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	200	SF	6	10+ years	
Classroc	nm #3-205 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	875	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	200	SF	7	10+ years	
Classroo	m #3-206 (Science Lab Level 3)						
	Casework	2nd Floor	65	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	26	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	20	EA	7	10+ years	
			1			-	
	Eye Wash Station	2nd Floor	•	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,185	SF	7	10+ years	
	Gas Line	2nd Floor	13	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,185	SF	7	10+ years	
	Science Lab Fume Hood	2nd Floor	1	EA	6	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	884	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	295	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classroo	m #3-207 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	867	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	rrater damage
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7		
				SF		6-10 years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor 2nd Floor	750 250	SF SF	6 6	10+ years 10+ years	
Classes	m #3-208 (Regular Classroom)						
Classi00	,	0-15	22			40	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	875	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	6	10+ years	
Classroo	om #3-209 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	901	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	water damage
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	13	EA	7	10+ years	
	Floor - Tile	2nd Floor	913	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor 2nd Floor	13			6-10 years	
				EA LF	7		
	Marker Board	2nd Floor	16		7	6-10 years	
	Walls - Concrete Block	2nd Floor	768	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	256	SF	6	10+ years	
Classroc	nm #4-100 (Art Room)						
	Casework	1st Floor	48	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,156	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Floor - Tile	1st Floor	1,156	SF	7	10+ years	
	Instructional Surface	1st Floor	72	LF	7	10+ years	
	Kiln	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	19	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	92	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,100	SF	7	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroo	om #4-101 (Art Room)						
	Casework	1st Floor	32	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	26	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	20	EA	7	10+ years	
	Doors - Transom Window	1st Floor	26	SF	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	10+ years	
	Instructional Surface	1st Floor	1,213	LF	7	10+ years	
	manucuonai Sunace	151 [100]	42	L	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,420	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #4-102 (Computer Lab)						
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,185	SF	6	10+ years	
	Doors - Side-lite	1st Floor	26	SF	7	10+ years	
	Doors - Transom Window	1st Floor	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,185	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,290	SF	7	•	
		1st Floor		EA	7	10+ years	
	Wireless System	1St Floor	1	EA	/	6-10 years	
Classro	om #4-103 (Art Room)						
	Casework	1st Floor	32	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,215	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Floor - Tile	1st Floor	1,215	SF	7	10+ years	
	Instructional Surface	1st Floor	36	LF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	ĒΑ	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,420	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #4-104 (Regular Classroom)						
CIUSSIU	Casework	1st Floor	20	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	875	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF SF		,	
				SF SF	7	10+ years	
	Doors - Transom Window	1st Floor	13		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	1.11
	Lighting - Lay-in	1st Floor	13	EA	5	0-1 year	Lights came on but did not stay on from switch
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
	•					•	



Group	H T						
Group						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroor	m #4-105 (Counseling Room)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	534	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	534	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	641	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	214	SF	7	10+ years	
					-	, , , , , , , , , , , , , , , , , , , ,	
lassroor	m #4-106 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years	
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
	walls - Flastel/Drywall	151 11001	230	SI	,	10+ years	
lassrooi	m #4-107 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	827	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	48	SF	4	1-2 years	Water stained tile
	Doors - Side-lite	1st Floor	13	SF	7	10+ years	Trate: etaeae
	Doors - Transom Window	1st Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	875	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
		1st Floor		SF	7	10+ years	
	Walls - Concrete Block		750				
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
lassrooi	m #4-108 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	913	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	913	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	13	EΑ	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
Classroo	om #4-109 (Regular Classroom)						
	Casework	4th Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	913	SF	7	10+ years	
	Doors - Side-lite	4th Floor	13	SF	7	10+ years	
	Doors - Transom Window	4th Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	4th Floor	913	SF	7	10+ years	
	Lighting - Lay-in	4th Floor	13	EA	7	6-10 years	
	Marker Board	4th Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	4th Floor	768	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	256	SF	7	10+ years	
Classroo	om #4-200 (Band Room)						
	Ceiling - Lay-in	2nd Floor	1,652	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	24	SF	7	10+ years	Trator damage
	Doors - Transom Window	2nd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,660	SF	7	10+ years	
	Instrument Storage Casework	2nd Floor	40	LF	7	10+ years	
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Sound Panels	2nd Floor	35	EA	7	10+ years	
	Sound System	2nd Floor	1	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	314	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	3,636	SF	7	10+ years	
Classroo	nm #4-201 (Regular Classroom)						
	Ceiling - Lay-in	2nd Floor	1,660	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,660	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	20	LF	6	6-10 years	
	Sound Panels	2nd Floor 2nd Floor	21	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	3,234	SF	7	10+ years	
	vvalis - Collete Diock	Z110 1 1001	3,234	J۲	,	10+ years	



Catego	ry : Classroom		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	675	SF	6	10+ years	
Classroo	m #4-202 (Science Lab Level 3)						
	Casework	2nd Floor	65	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	26	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,185	SF	7	10+ years	
	Gas Line	2nd Floor	13	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	1,185	SF	7	6-10 years	
	Science Lab Fume Hood	2nd Floor	1	ĒΑ	6	10+ years	
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	884	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	295	SF	6	10+ years	
	Work Sink	2nd Floor	8	EA	7	10+ years	
Classroo	m #4-203 (Regular Classroom)						
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	867	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	rrater damage
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	200	SF	7	10+ years	
	•	2110 1 1001	200	O.	,	101 youro	
Classroo	m #4-205 (Regular Classroom)	01 51				40	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	875	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	875	SF	6	10+ years	
	Lighting Lay-in	2nd Floor	13	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	550	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	6	10+ years	



I Type s - Vinyl Coated Gypsum Panel 206 (Science Lab Level 3) ework ng - Lay-in ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	Location 2nd Floor  2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	Quantity 200  65 1,177 8 2 1,180 5 13 15 12 1,185 1	UOM SF LF SF SF EA SF EA LF SF	Rank 7  6 6 6 4 6 7 7	Recommend Replacement 10+ years 10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments  Water damage  Cracked
s - Vinyl Coated Gypsum Panel  206 (Science Lab Level 3)  ework  ng - Lay-in  rs - Wood Doors inclu hw  r - Tile  r - Tile  Line  ting - Lay-in  ker Board  nce Lab Elements  nce Lab Fume Hood  nce Lab Shower  s - Concrete Block  s - Plaster/Drywall	2nd Floor  2nd Floor	200 65 1,177 8 2 1,180 5 13 15 12 1,185	SF SF SF EA SF EA EA LF	7 6 6 4 6 6 4 6 7	10+ years 10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 1-2 years 10+ years	Water damage
s - Vinyl Coated Gypsum Panel  206 (Science Lab Level 3)  ework  ng - Lay-in  rs - Wood Doors inclu hw  r - Tile  r - Tile  Line  ting - Lay-in  ker Board  nce Lab Elements  nce Lab Fume Hood  nce Lab Shower  s - Concrete Block  s - Plaster/Drywall	2nd Floor  2nd Floor	200 65 1,177 8 2 1,180 5 13 15 12 1,185	SF SF SF EA SF EA EA LF	6 6 4 6 6 4 6 7	10+ years 10+ years 10+ years 1-2 years 10+ years 10+ years 10+ years 1-2 years 10+ years	· ·
ework ng - Lay-in ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	1,177 8 2 1,180 5 13 15 12 1,185	SF SF EA SF EA EA LF	6 4 6 4 6 7	10+ years 1-2 years 10+ years 10+ years 1-2 years 10+ years	· ·
ework ng - Lay-in ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	1,177 8 2 1,180 5 13 15 12 1,185	SF SF EA SF EA EA LF	6 4 6 4 6 7	10+ years 1-2 years 10+ years 10+ years 1-2 years 10+ years	· ·
ng - Lay-in ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	1,177 8 2 1,180 5 13 15 12 1,185	SF SF EA SF EA EA LF	6 4 6 4 6 7	10+ years 1-2 years 10+ years 10+ years 1-2 years 10+ years	· ·
ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile tine ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	8 2 1,180 5 13 15 12 1,185	SF EA SF SF EA EA LF	4 6 6 4 6 7	10+ years 1-2 years 10+ years 10+ years 1-2 years 10+ years	· ·
ng - Lay-in rs - Wood Doors inclu hw r - Tile r - Tile tine ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	8 2 1,180 5 13 15 12 1,185	SF EA SF SF EA EA LF	4 6 6 4 6 7	1-2 years 10+ years 10+ years 1-2 years 10+ years	· ·
rs - Wood Doors inclu hw r - Tile r - Tile tine ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	1,180 5 13 15 12 1,185	SF SF EA EA LF	6 4 6 7	10+ years 10+ years 1-2 years 10+ years	· ·
r - Tile Line Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	5 13 15 12 1,185	SF EA EA LF	4 6 7	10+ years 1-2 years 10+ years	Cracked
Line ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor	13 15 12 1,185	EA EA LF	6 7	1-2 years 10+ years	Cracked
ting - Lay-in ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	15 12 1,185 1	EA LF	7	10+ years	
ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	12 1,185 1	LF			
ker Board nce Lab Elements nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor 2nd Floor	12 1,185 1		7		
nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor	1	SF	,	6-10 years	
nce Lab Fume Hood nce Lab Shower s - Concrete Block s - Plaster/Drywall	2nd Floor 2nd Floor 2nd Floor	1		7	6-10 years	
s - Concrete Block s - Plaster/Drywall	2nd Floor	1	EA	6	10+ years	
s - Plaster/Drywall			EA	7	10+ years	
		884	SF	6	10+ years	
	2nd Floor	295	SF	6	10+ years	
k Sink	2nd Floor	8	ĒΑ	7	10+ years	
ework ng - Lay-in rs - Side-lite rs - Transom Window	2nd Floor 2nd Floor 2nd Floor 2nd Floor	20 875 13 13	LF SF SF SF	6 6 7 7	10+ years 10+ years 10+ years	
rs - Transom Window rs - Wood Doors inclu hw	2nd Floor 2nd Floor	13	SF EA	7 6	10+ years	
r - Tile	2nd Floor	855	SF		10+ years	
r - Tile r - Tile	2nd Floor	20	SF SF	6 4	10+ years 1-2 years	Cracked
ting - Lay-in	2nd Floor	13	EA	7	6-10 years	Cracked
ker Board	2nd Floor	16	LF	7	6-10 years	
		_		-		
					•	
5 - 1 lastel/Drywall	2110 1 1001	250	Si	U	10+ years	
208 (Regular Classroom)						
ework	2nd Floor	20	IF	6	10+ vears	
					•	
				-	,	Water damage
		1				Trate: damage
		•		-		
				-		
r - Tile						
r - Tile ting  - Lay-in						
r - Tile ting  - Lay-in ker Board		100	SF	6	10+ years	
s 20 ev no	g - Lay-in g - Lay-in - Wood Doors inclu hw - Tile ng - Lay-in	- Plaster/Drywall 2nd Floor  28 (Regular Classroom)  vork 2nd Floor g - Lay-in 2nd Floor - Wood Doors inclu hw 2nd Floor - Tile 2nd Floor g - Lay-in 2nd Floor	- Plaster/Drywall 2nd Floor 250  28 (Regular Classroom)  vork 2nd Floor 20  2 - Lay-in 2nd Floor 871  2 - Lay-in 2nd Floor 4  - Wood Doors inclu hw 2nd Floor 1  - Tile 2nd Floor 875  ng - Lay-in 2nd Floor 13  r Board 2nd Floor 16	- Plaster/Drywall 2nd Floor 250 SF  - Plaster/Drywall 2nd Floor 20 LF - Os (Regular Classroom)  - Work 2nd Floor 871 SF - G - Lay-in 2nd Floor 4 SF - Wood Doors inclu hw 2nd Floor 1 EA - Tile 2nd Floor 875 SF - ng - Lay-in 2nd Floor 13 EA - Tile 2nd Floor 13 EA - Toorete Block 2nd Floor 750 SF	- Plaster/Drywall 2nd Floor 250 SF 6  28 (Regular Classroom)  vork 2nd Floor 20 LF 6 g - Lay-in 2nd Floor 871 SF 6 g - Lay-in 2nd Floor 4 SF 4 - Wood Doors inclu hw 2nd Floor 1 EA 7 - Tile 2nd Floor 875 SF 7 ng - Lay-in 2nd Floor 13 EA 7 r Board 2nd Floor 16 LF 7 - Concrete Block 2nd Floor 750 SF 6	- Concrete Block 2nd Floor 750 SF 6 10+ years 2nd Floor 250 SF 6 10+ years 250 SF 7 10+ y



Catego	ry : Classroom		В	uilding	_		
0	Hama Tama	Landan	<b>a</b> 494	11614	D- 1	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #4-209 (Regular Classroom)						
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	901	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	13	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	13	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	913	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	768	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	256	SF	6	10+ years	
	•					•	
Classroo	m #Dance Studio (Dance Room)						
	Ceiling - Lay-in	2nd Floor	1,402	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	40	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,406	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Wall Mirrors	2nd Floor	375	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,468	SF	6	10+ years	
Classroo	om #Weight Room (Fitness Room)						
01000100	Ceiling - Lay-in	2nd Floor	1,576	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	24	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor	1,576	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	1,576	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	,	
		2nd Floor	205	SF	7	6-10 years	
	Storage/ Closet		245	SF SF	7	10+ years	
	Wall Mirrors	2nd Floor		SF SF		10+ years	
	Walls - Concrete Block	2nd Floor	2,683	5F	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor			-		·		
	Ceiling - Lay-in	1st Floor	25,762	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	40	SF	6	10+ years	No deficiencies noted
	Ceiling - Plaster/Drywall	1st Floor	8,015	SF	7	10+ years	



Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	50	EA	7	10+ years	
	Doors - Store Front	1st Floor	14	EΑ	7	10+ years	
	Doors - Transom Window	1st Floor	295	SF	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	7	EA	7	10+ years	
	Drinking Fountains - Triple Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	33,672	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	145	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	442	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	34	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	10	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	672	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	456	SF	7	10+ years	
	Walls - Masonry	1st Floor	13,786	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,160	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	25,540	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	22,406	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	28	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	2nd Floor	480	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	28	ĒΑ	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	8	ΕA	7	10+ years	
	Floor - Terrazzo	2nd Floor	22,934	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	340	ĒΑ	6	6-10 years	
	Rescue Panel	2nd Floor	1	ΕA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	672	ΕA	6	10+ years	
	Walls - Masonry	2nd Floor	12,510	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	19,739	SF	6	10+ years	
			. 3,1 33	О.	· ·	. o . y ca. c	
Safety							
,	Camera Viewing Station	1st Floor	5	EA	7	6-10 years	
	Metal Detector	1st Floor	3	EA	7	6-10 years	
	Security Cameras	1st Floor	133	EA	7	6-10 years	
	Security Cameras	1st Floor	13	EA	7	6-10 years	
Ctains							
_Stairs	Ceiling - Lay-in	A100 Stair	766	SF	6	10+ years	
	Floor - Terrazzo	A100 Stair	584	SF	7	10+ years	
	Handrails	A100 Stair	62	LF	7	10+ years	
	Lighting - Lay-in	A100 Stair	6	EA	6	6-10 years	
	Rescue Panel	A100 Stair	1	EA	7	10+ years	
	Stairs - Terrazzo	A100 Stair	126	LF	7	10+ years 10+ years	
	Walls - Structural Glazed Tile	A100 Stair	1,278	SF	7		
	vvalis - Structural Glazeu Tile	A 100 Stall	1,270	ЗF	1	10+ years	



Catego	Category : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	A132 Stair	470	SF	7	10+ years			
	Floor - Terrazzo	A132 Stair	234	SF	7	10+ years			
	Handrails	A132 Stair	98	LF	7	10+ years			
	Lighting - Pendent/Surface	A132 Stair	8	EA	6	6-10 years			
	Stairs - Terrazzo	A132 Stair	126	LF	7	10+ years			
	Walls - Masonry	A132 Stair	710	SF	7	10+ years			
	Ceiling - Lay-in	A161 Stair	718	SF	7	10+ years			
	Ceiling - Lay-in	A161 Stair	48	SF	4	0-1 year	Water damage		
	Floor - Terrazzo	A161 Stair	584	SF	7	10+ years			
	Handrails	A161 Stair	62	LF	7	10+ years			
	Lighting - Lay-in	A161 Stair	6	EΑ	7	6-10 years			
	Rescue Panel	A161 Stair	1	EA	7	10+ years			
	Stairs - Terrazzo	A161 Stair	156	LF	7	10+ years			
	Walls - Structural Glazed Tile	A161 Stair	1,278	SF	7	10+ years			
	Ceiling - Lay-in	B124 Stair	740	SF	7	10+ years			
	Ceiling - Lay-in	B124 Stair	24	SF	4	0-1 year	Water damage		
	Floor - Terrazzo	B124 Stair	584	SF	6	10+ years			
	Handrails	B124 Stair	62	LF	7	10+ years			
	Lighting - Lay-in	B124 Stair	6	EA	6	6-10 years			
	Rescue Panel	B124 Stair	1	EA	7	10+ years			
	Stairs - Terrazzo	B124 Stair	126	LF	7	10+ years			
	Walls - Structural Glazed Tile	B124 Stair	1,278	SF	7	10+ years			
	Ceiling - Lay-in	B149 Stair	482	SF	7	10+ years			
	Ceiling - Plaster/Drywall	B149 Stair	150	SF	6	10+ years			
	Floor - Terrazzo	B149 Stair	534	SF	7	10+ years			
	Handrails	B149 Stair	70	LF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	B149 Stair	12	EA	6	6-10 years			
	Stairs - Terrazzo	B149 Stair	126	LF	7	10+ years			
	Walls - Structural Glazed Tile	B149 Stair	1,200	SF	7	10+ years			
	Ceiling - Lay-in	B177 Stair	482	SF	6	10+ years			
	Ceiling - Plaster/Drywall	B177 Stair	150	SF	6	10+ years			
	Floor - Terrazzo	B177 Stair	534	SF	7	10+ years			
	Handrails	B177 Stair	70	LF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	B177 Stair	12	EΑ	7	6-10 years			
	Stairs - Terrazzo	B177 Stair	126	LF	7	10+ years			
	Walls - Structural Glazed Tile	B177 Stair	1,200	SF	7	10+ years			
	Ceiling - Lay-in	D101 Stair	300	SF	6	10+ years			
	Floor - Terrazzo	D101 Stair	164	SF	7	10+ years			
	Handrails	D101 Stair	58	LF	7	10+ years			
	Lighting - Lay-in	D101 Stair	5	EA	6	6-10 years			
	Stairs - Terrazzo	D101 Stair	126	LF	7	10+ years			
	Walls - Structural Glazed Tile	D101 Stair	710	SF	7	10+ years			
	Ceiling - Lay-in	D101 Stair	716 756	SF	6	10+ years			
	Ceiling - Lay-in	D123 Stair	10	SF	4	0-1 year	Water damage		
	Coming Lay-III	D 120 Otali	10	Oi	7	U- i yeai	Water damage		



Category : Interior		В	uilding	: Main		
			_		Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Floor - Terrazzo	D123 Stair	584	SF	7	10+ years	
Handrails	D123 Stair	62	LF	7	10+ years	
Lighting - Lay-in	D123 Stair	6	EΑ	7	6-10 years	
Rescue Panel	D123 Stair	1	EA	7	10+ years	
Stairs - Terrazzo	D123 Stair	156	LF	7	10+ years	
Walls - Structural Glazed Tile	D123 Stair	2,278	SF	7	10+ years	
Ceiling - Lay-in	D133 Stair	480	SF	6	10+ years	
Ceiling - Plaster/Drywall	D133 Stair	150	SF	6	10+ years	
Floor - Terrazzo	D133 Stair	534	SF	7	10+ years	
Handrails	D133 Stair	70	LF	5	10+ years	
Lighting - Lay-in	D133 Stair	12	EΑ	7	6-10 years	
Stairs - Terrazzo	D133 Stair	156	LF	7	10+ years	
Walls - Structural Glazed Tile	D133 Stair	1,200	SF	7	10+ years	
Ceiling - Lay-in	D182 Stair	482	SF	6	10+ years	
Ceiling - Plaster/Drywall	D182 Stair	150	SF	6	10+ years	
Floor - Terrazzo	D182 Stair	534	SF	7	10+ years	
Handrails	D182 Stair	70	LF	7	10+ years	
Lighting - Metal Halide/Sodium Vapor	D182 Stair	12	EA	7	6-10 years	
Stairs - Terrazzo	D182 Stair	156	LF	7	10+ years	
Walls - Structural Glazed Tile	D182 Stair	1,200	SF	7	10+ years	
ertical Conveyance						
Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years	
Elevator - Hydraulic Elevator	1st Floor	1	EΑ	6	10+ years	



Category : Site **Building: Site** 

Categor	y . Oilo			unung	· Oite	D	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Athletic							
	Lighting	North	10	EA	6	10+ years	
	Surface - Concrete	North	25,736	SF	6	10+ years	
	Metal Bleachers	South	40	LF	6	10+ years	
	Surface - Natural	South	143,949	SF	6	10+ years	
	Metal Bleachers	South	150	LF	6	10+ years	
	Surface - Natural	South	95,102	SF	6	10+ years	
	- Tatara		33,.32	О.	· ·	.o. you.o	
_Civil/Drai	nage						
	Civil/ Drainage - Bioswale	Entire Site	20,091	SF	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	17	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	19	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	6	10+ years	
	ŭ					,	
_Fencing							
	Fencing - Chain Link	Entire Site	848	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	3,450	LF	6	10+ years	
Landsca	oe .						
	Benches	Entire Site	20	EA	6	10+ years	
	Benches	Entire Site	3	EA	4	0-1 year	Loose, unstable
	Irrigation	Entire Site	327,199	SF	4	0-1 year	Not working
	Landscape - Grass	Entire Site	87,798	SF	6	10+ years	3
	Landscape - Hardscape- Concrete	Entire Site	21,991	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	450	SF	5	2-5 years	
	Landscape - Hardscape- Pavers	Entire Site	350	SF	6	10+ years	
	Landscape - Poured Rubber Surface	Entire Site	1,473	SF	6	6-10 years	Moved from playground
	Lighting - Lighting	Entire Site	28	EA	6	6-10 years	p.a., g. caa
	Parkway trees	Entire Site	36	EΑ	6	10+ years	
	Parkway trees	Entire Site	5	EA	4	0-1 year	Dead, dying trees
	Planting Beds/ Area	Entire Site	26,358	SF	6	10+ years	2 3 d d , d j g 3 d d
	Retaining Wall - Masonry	Entire Site	586	SF	5	2-5 years	
	Trash Receptacles	Entire Site	10	EA	6	10+ years	
	Tracii Necopiacios	Ziilli o ollo		_, ,	Ū	ioi youlo	
_Parking I	ot						
	Surface - Concrete	Dock/Driveway	1,986	SF	6	6-10 years	
	Trash Compactor	Dock/Driveway	,	EA	6	10+ years	
	Concrete Curbs	Faculty - Southeast	1,481	LF	6	10+ years	
	Interior Plantings	Faculty - Southeast	378	LF	6	10+ years	
	Lighting - Pole Mounted	Faculty - Southeast	16	EΑ	6	10+ years	
	Surface - Asphalt	Faculty - Southeast	30,463	SF	6	10+ years	
	Vehicular Screening	Faculty - Southeast	615	LF	6	10+ years	
	3	•			-	<b>,</b>	



Category : Site			В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Concrete Curbs	Front driveway	1,000	LF	6	10+ years	
	Lighting - Pole Mounted	Front driveway	8	EA	6	10+ years	
	Surface - Asphalt	Front driveway	12,920	SF	6	10+ years	
Sidewalk	is .						
	Sidewalks - Internal Walks	Entire Site	3,443	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	90	LF	5	2-5 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	22,632	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	300	SF	4	1-2 years	Cracking, spalling
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	3	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	· ·	•	•						
Art Room	Regular Classroom	1st Floor	1-102	A101	1,208	152	24	N	Υ
Art Room	Regular Classroom	1st Floor	4-100	A154	1,156	182	12		Υ
Art Room	Regular Classroom	1st Floor	4-101	A162	1,215	152	24		
Art Room	Regular Classroom	1st Floor	4-103	A164	1,215	156	24		Υ
Band Room	Music Room	2nd Floor	4-200	A230	1,660	240	0	N	Υ
Computer Lab	Computer Lab	1st Floor	1-101	B150	1,180	152	24	Υ	Υ
Computer Lab	Computer Lab	1st Floor	2-101	B180	1,097	152	24	Y	N
Computer Lab	Computer Lab	1st Floor	3-102	D132	1,185	112	16	Y	Υ
Computer Lab	Computer Lab	1st Floor	4-102	D161	1,185	112	16	Y	Υ
Counseling Room	Regular Classroom	1st Floor	4-105	D178	534	56	8	Y	Υ
Dance Room	Dance Room	2nd Floor	Dance	D203	1,406	140	0	N	N
			Studio						
Fitness Room	Fitness Room	2nd Floor	Weight	C203	1,576	140	0	N	N
			Room						
Office	Regular Classroom	3rd Floor	3-105	D149	534	56	8	Y	N
Regular Classroom	Faculty Lounge	1st Floor	N/A	C102	722	0	0	N	N
Regular Classroom	Music Room	2nd Floor	4-201	A235	1,660	60	0	N	N
Regular Classroom	Regular Classroom	1st Floor	1-103	B151	890	152	24	Y	N
Regular Classroom	Regular Classroom	1st Floor	1-104	B133	582	76	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	1-105	B152	890	152	24	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	1-106	B132	890	152	24	Y	N
Regular Classroom	Regular Classroom	1st Floor	1-107	B153	890	152	24	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	1-108	B131	890	144	32	N	Υ
Regular Classroom	Regular Classroom	1st Floor	2-102	A.8.1	1,132	152	24	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-103	B179	890	114	18	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-104	B161	582	76	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-105	B180	890	114	18	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-106	B160	890	114	18	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-107	B181	890	114	18	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	2-108	B160	890	114	18	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	3-104	D131	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	3-106	D130	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	3-107	D150	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	3-108	D129	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	3-109	D151	913	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	4-104	D160	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	4-106	D159	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	4-107	D179	875	84	12	Y	Υ



**Classroom Summary** 

			_	Floor Plan		Glazed	Operable		
Current Usage	Intended Hoose	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Regular Classroom	Intended Usage Regular Classroom	1st Floor	4-108	D158	913	84	12	Stop V	N
Regular Classroom	Regular Classroom	2nd Floor	1-202	B213	890	114	18	Y	N
Regular Classroom	Regular Classroom	2nd Floor	1-202	B213	890	114	18	Y	N
Regular Classroom	Regular Classroom	2nd Floor	1-204	B212	890	114	18	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	1-208	B210	890	114	18	Y	
0	Regular Classroom	2nd Floor	2-200	A212	1,147	112	16	T	I
Regular Classroom	5						18	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	2-202	B224	890	114			Y
Regular Classroom	Regular Classroom	2nd Floor	2-204	B223	890	114	18	Y	
Regular Classroom	Regular Classroom	2nd Floor	2-205	B229	890	114	18	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	2-206	B222	890	114	18	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	2-208	B221	890	114	18	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	3-203	D217	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	3-205	D218	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	3-207	D219	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	3-208	D212	875	84	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	3-209	D220	913	84	12	Υ	Ν
Regular Classroom	Regular Classroom	2nd Floor	4-203	D231	875	84	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	4-205	D232	875	84	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	4-207	D233	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	4-208	D226	875	84	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	4-209	D234	913	84	12	Υ	Υ
Regular Classroom	Regular Classroom	4th Floor	4-109	D180	913	84	12	Y	Υ
Science Classroom	Regular Classroom	2nd Floor	1-207	B219	890	114	18	Y	Υ
Science Lab Level 1	Science Lab Level 1	2nd Floor	1-201	B216	1,211	152	24	Y	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	1-205	B218	1,211	152	24	Y	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	2-201	B226	1,211	152	24	Y	N
Science Lab Level 1	Science Lab Level 1	2nd Floor	2-203	B228	1,211	152	24	Y	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	3-202	D215	1,185	112	16	Ý	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	3-206	D213	1,185	112	16	Ý	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	4-202	D229	1,185	112	16	Ý	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	4-206	D227	1,185	112	16	Ý	Y