

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1996	3	81,350
Campus Total			81,350

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance)						
	Exterior Doors - Exterior Steel Door	#A - N	1	EA	6	10+ years	Changed to match current observations
	Exterior Stairs - Concrete	#A - N	9	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#B - N	1	EA	6	6-10 years	Changed to match current observations
	Exterior Stairs - Concrete	#B - N	12	LF	6	10+ years	
	Exterior Doors - Side lite	#C - W	1	EA	6	10+ years	
	Exterior Doors - Store Front	#C - W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#C - W	3	EA	6	10+ years	
	Entrance Control - Audio and Video	#D Main - W	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#D Main - W	1	EA	6	10+ years	
	Exterior Doors - Store Front	#D Main - W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#D Main - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#D Main - W	1	EA	5	1-2 years	Broken glass
	Exterior Doors - Exterior Steel Door	#E - W	1	EA	4	0-1 year	Corroded
	Exterior Doors - Side lite	#F - W	1	EA	6	10+ years	
	Exterior Doors - Store Front	#F - W	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#F - W	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#G - S	1	EA	6	6-10 years	Changed to match current observations
	Exterior Doors - Exterior Steel Door	#H Exit - E	1	EA	4	0-1 year	Corrosion at the bottom of the door and the frame
	Exterior Doors - Exterior Steel Door	#I Exit - E	1	EA	5	1-2 years	Corroded
	Exterior Doors - Exterior Steel Door	#J - E	1	EA	5	0-1 year	Corroded



Exterior Doors - Transom Lite #K.5 - E 1 EA 6 10+ years Minor rust. C observations Exterior Doors - Exterior Steel Door #L - E 2 EA 4 0-1 year Corroded Exterior Doors - Exterior Steel Door #M - N 1 EA 5 0-1 year Corroded Exterior Stairs - Concrete #M - N 4 LF 6 10+ years Exterior Doors - Exterior Steel Door N (West Low Roof) 1 EA 4 1-2 years Corroded Exterior Stairs - Concrete N (West Low Roof) 4 LF 6 10+ years Exterior Stairs - Concrete N (West Low Roof) 5 Exterior Stairs - Concrete N (West Low Roof) 7 10+ years Superstructure - Metal Deck/ Concrete Entire Building 81,350 SF 7 10+ years Topping Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years	antity changed to mate
Exterior Doors - Exterior Steel Door	nantity changed to mate vations
Exterior Doors - Exterior Steel Door	nantity changed to mate vations
Exterior Doors - Exterior Steel Door	vations
Exterior Doors - Exterior Steel Door	vations
Exterior Doors - Exterior Steel Door #L - E 2 EA 4 0-1 year Corroded Exterior Stairs - Concrete #M - N 1 EA 5 0-1 year Corroded Exterior Stairs - Concrete #M - N 4 LF 6 10+ years Exterior Doors - Exterior Steel Door N (West Low Roof) 1 EA 4 1-2 years Corroded Exterior Stairs - Concrete N (West Low Roof) 4 LF 6 10+ years Exterior Stairs - Concrete N (West Low Roof) 4 LF 6 10+ years Exterior Stairs - Concrete N (West Low Roof) 4 LF 7 10+ years Exterior Stairs - Concrete Entire Building 920 LF 7 10+ years Superstructure - Metal Deck/ Concrete Entire Building 81,350 SF 7 10+ years Topping Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Downspouts - Interior Downspouts Main Roof 261 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced Main Roof 2 EA 7 10+ years Replaced Main Roof 2 EA 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	nanged to match curre
Exterior Doors - Exterior Steel Door	
Exterior Doors - Exterior Steel Door Exterior Stairs - Concrete #M - N	
Exterior Stairs - Concrete	
Exterior Doors - Exterior Steel Door Exterior Steel Door Exterior Stairs - Concrete N (West Low Roof) 1 EA 4 1-2 years Corroded N (West Low Roof) 4 LF 6 10+ years Foundation Foundation - Concrete Superstructure - Metal Deck/ Concrete Entire Building 81,350 SF 7 10+ years Topping Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Roof System Access Ladder - Metal Main Roof 2 EA 7 10+ years Quantity changes Chirmey - Metal Flue Main Roof 20 LF 6 10+ years Quantity changes Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced	
Exterior Stairs - Concrete N (West Low Roof) 4 LF 6 10+ years Foundation Foundation - Concrete Superstructure - Metal Deck/ Concrete Entire Building 81,350 SF 7 10+ years Topping Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Roof System Access Ladder - Metal Main Roof 2 EA 7 10+ years Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Modified Bitumen Main Roof 2 EA 7 10+ years Replaced Roof - Modified Bitumen Main Roof 2 EA 7 10+ years Replaced Roof - Modified Bitumen Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced Roof - Metal Main Roof 2 EA 7 10+ years Replaced	
Foundation - Concrete Superstructure - Metal Deck/ Concrete Entire Building Superstructure - Metal Deck/ Concrete Entire Building S1,350 SF 7 10+ years S1	
Foundation - Concrete Superstructure - Metal Deck/ Concrete Entire Building Superstructure - Metal Deck/ Concrete Entire Building S1,350 SF 7 10+ years S1	
Topping Lighting Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Roof System Access Ladder - Metal Main Roof Chimney - Metal Flue Main Roof Coping - Metal Main Roof Coping - Metal Main Roof Downspouts - Interior Downspouts Parapet - Parapet > 30" Main Roof Roof - Modified Bitumen Roof Main Roof Roof - Modified Bitumen Main Roof Main Roof Roof - Metal Main Roof Roof - Modified Bitumen Main Roof Main Roof Roof - Metal Main Roof Roof - Metal Main Roof Roof - Modified Bitumen Main Roof Roof - Metal Roof Roof Roof Roof Roof Roof Roof Roo	
Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Roof System Access Ladder - Metal Main Roof Chimney - Metal Flue Main Roof Coping - Metal Main Roof Coping - Metal Main Roof Downspouts - Interior Downspouts Parapet - Parapet > 30" Main Roof Roof Main Roo	
Exterior Lighting - Wall Mounted Entire Building 14 EA 6 10+ years Roof System Access Ladder - Metal Main Roof 2 EA 7 10+ years Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 261 LF 6 10+ years Parapet - Parapet > 30" Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Access Ladder - Metal Main Roof 2 EA 7 10+ years Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 261 LF 6 10+ years Parapet - Parapet > 30" Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Access Ladder - Metal Main Roof 2 EA 7 10+ years Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 261 LF 6 10+ years Parapet - Parapet > 30" Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Chimney - Metal Flue Main Roof 20 LF 6 10+ years Quantity cha observations Coping - Metal Main Roof 761 LF 7 10+ years Replaced Downspouts - Interior Downspouts Main Roof 261 LF 6 10+ years Parapet - Parapet > 30" Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Coping - MetalMain Roof761LF710+ yearsReplacedDownspouts - Interior DownspoutsMain Roof261LF610+ yearsParapet - Parapet > 30"Main Roof761LF710+ yearsReplacedRoof - Modified BitumenMain Roof24,424SF710+ yearsReplacedRoof Hatch - MetalMain Roof2EA710+ yearsReplaced	nged to match current
Downspouts - Interior DownspoutsMain Roof261LF610+ yearsParapet - Parapet > 30"Main Roof761LF710+ yearsReplacedRoof - Modified BitumenMain Roof24,424SF710+ yearsReplacedRoof Hatch - MetalMain Roof2EA710+ yearsReplaced	
Parapet - Parapet > 30" Main Roof 761 LF 7 10+ years Replaced Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Roof - Modified Bitumen Main Roof 24,424 SF 7 10+ years Replaced Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Roof Hatch - Metal Main Roof 2 EA 7 10+ years Replaced	
Concrete Topping	
Coping - Metal North Low Roof 206 LF 7 10+ years Replaced	
Downspouts - Interior Downspouts North Low Roof 36 LF 6 10+ years	
Parapet - Parapet > 30" North Low Roof 206 LF 7 10+ years Replaced	
Roof - Modified Bitumen North Low Roof 5,061 SF 7 10+ years Replaced	
Roof Structure - Steel / Metal Deck/ North Low Roof 5,061 SF 7 10+ years Concrete Topping	
Coping - Metal West Low Roof 126 LF 7 10+ years Replaced	
Downspouts - Interior Downspouts West Low Roof 26 LF 6 10+ years	
Parapet - Parapet > 30" West Low Roof 126 LF 7 10+ years Replaced	
Roof - Modified Bitumen West Low Roof 1,457 SF 6 10+ years Replaced	
Roof Structure - Steel / Metal Deck/ West Low Roof 1,457 SF 7 10+ years Replaced	
,, i.e	





Category : Exterior			Building : Main						
						Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Concrete Topping								
\/ - II -									
Valls	Cornica Magazza Draigating Limestone	Entire Duilding	725	LF		10			
	Cornice - Masonry Projecting Limestone	Entire Building	735	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	28,500		6	10+ years			
	Exterior Walls - Concrete Block	Entire Building	8,048	SF	6	10+ years			
	Exterior Walls - Concrete Block	Entire Building	2	SF	4	1-2 years	Cracking		
Vindow									
viridow.	Guard - Guards perforated	Entire Building	1,585	SF	6	6-10 years			
	Lintels - Steel	Entire Building	865	LF	6	6-10 years			
	Windows - Louver	Entire Building	272	SF	7	10+ years	Quantity changed to match current		
	Willdows - Louvei	Entire Building	212	SF	1	10+ years	observations		
	Windows - Sash Aluminum Double-pane	Entire Building	5,750	SF	6	6-10 years	oboot valienc		
	·	Ü				•			
Catego	ry : Electrical		В	uilding	: Main	D			
Sroup.	Itom Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Froup	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments		
merge	ncy System								
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years			
	Security System - CCTV	Entire Building	81,350	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	81,350	SF	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	2	0-1 year	No EM Generator or EM battery		
							packs		
	Exit Signs - Gym	Entire Building	3	EA	2	0-1 year	No EM Generator or EM battery		
							packs		
	Exit Signs - Lunchroom	Entire Building	7	EΑ	2	0-1 year	No EM Generator or EM battery		
							packs		
	Emergency A/C Power - Corridors and	Entire Building	7,045	SF	6	6-10 years			
	Stairs	•				•			
	Emergency A/C Power - Gym	Entire Building	3,861	SF	6	6-10 years			
					6	6-10 years			
	Emergency A/C Power - Lunchrooms	Entire Building	1,200	SF	O	o io years			
		Entire Building	1,200	SF	О	o to years			
/lain Se	rvice		·						
∕lain Se	rvice Main Electrical Service - 2000 A	Entire Building Electrical Room	1,200	EA	6	10+ years			
⁄/ain Se	rvice Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	6	10+ years			
⁄lain Se	rvice Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for		·						
∕lain Se	rvice Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for emergency power	Electrical Room Electrical Room	1	EA EA	6	10+ years			
1ain Se	rvice Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for	Electrical Room	1	EA	6	10+ years	Repaired.		
	Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for emergency power PA System	Electrical Room Electrical Room	1	EA EA	6	10+ years 10+ years	Repaired.		
Main Se	Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for emergency power PA System	Electrical Room Electrical Room Entire Building	1 1 81,350	EA EA SF	6 6 7	10+ years 10+ years 6-10 years	Repaired.		
	Main Electrical Service - 2000 A 277/480/3PH Independent Electrical Service for emergency power PA System	Electrical Room Electrical Room	1	EA EA	6	10+ years 10+ years	Repaired.		



West Park Elementary Academy

	Schools						1425 N Tripp AVENUE, Chicago, IL 60651
Catego	ry : Electrical		В	uilding	: Main		_
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting and Power Panels - Above 100 A	1st, 2nd Floor and Electrical Room	5	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	1st, 2nd Floor and Electrical Room	5	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st, 2nd Floor and Electrical Room	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	1st, 2nd Floor and Electrical Room	2	EA	6	10+ years	
	amp	4 at 20nd Floor and Flootrical Deam	0	Ε.	^	10	
	Transformers - 277/480 - 120/240	1st, 2nd Floor and Electrical Room	2 1	EA EA	6	10+ years	
	Transformers - 277/480 - 120/240	1st, 2nd Floor and Electrical Room	ı	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Calogo	.,		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m					-	
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	81,350	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	81,350	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	
	·	· ·				•	
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Pump Room	1	EA	4	0-1 year	Leaking. Needs replacement. Have
							failed last three city inspections. Per
							Engineer, work order in place for
					_		repairs/replacement.
	Jockey Pump	Pump Room	1	EA	6	6-10 years	
Carialda	Custom						
_Sprinkler	Sprinkler Heads	Pump Room and Entire Building	81,350	SF	7	10+ years	
	Sprinkler Piping	Pump Room and Entire Building	81,350	SF	6	10+ years	
	Wet Sprinkler System	Pump Room and Entire Building	81,350	SF	5	0-1 year	Leaking pump. Pump needs
	Wet Opinikier System	Tump Room and Entire Building	01,550	Oi	3	0-1 year	repair/replacement
							Торан/торносотнети
Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	litioning						
	Chemical Pot Feeder	Main Roof	1	EA	6	6-10 years	
	Chiller-Air Cooled-Screw Type-Roof	Main Roof	1	EA	6	6-10 years	2023 install
	Mounted - 201 - 300 tons						
	Glycol Feed	Main Roof	1	EA	6	6-10 years	Glycol is fed manually into the system
	Pipes - Chilled Water Pipe- Steel	Main Roof	400	LF	6	6-10 years	
	Pressure Fill System	Main Roof	1	EA	6	6-10 years	Glycol is fed manually into the system
	Condensing Unit- Roof Mounted - 5-10	Main Roof	1	EA	7	6-10 years	2019 install
	tons						



Category : Mechanical			Building : Main					
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
r Hand	ling Systems							
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	1st Floor - AHU-2	1	EA	7	6-10 years	AHU-2, serves offices	
	Air Intake	1st Floor - AHU-2	1	EA	6	6-10 years		
	VAV Box	1st Floor - AHU-2	8	EA	6	6-10 years		
	Indoor Return Fans- Centrifugal Inline -	1st Floor Mechanical Room	1	EA	6	6-10 years	RF-2	
	5000 - 10000 CFM	13t 1 loor Wednamear Room	•	L/\	O	o ro years	10. 2	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	3rd Floor Mechanical Room	1	EA	6	6-10 years	RF-1	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	3rd Floor Mechanical Room - AHU-1	1	EA	7	6-10 years	AHU-1; all classrooms, etc. throughout builing	
	Air Intake	3rd Floor Mechanical Room - AHU-1	1	EA	6	6-10 years		
	VAV Box	3rd Floor Mechanical Room - AHU-1	70	EA	6	10+ years		
	Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20	Lower Roof	1	EA	7	10+ years	2023 install	
	tons							
ler Sv	stems							
. 	Boiler Auxiliary- Non Condensing Hot Water - 3001 - 4000 MBH	Boiler Room	2	EA	5	6-10 years		
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years		
	Combustion Dampers	Boiler Room	2	ΕA	6	6-10 years		
	Hot Water Pump	Boiler Room	_ 1	EA	6	6-10 years	For water fill	
	Hot Water Pump	Boiler Room	i	EA	6	6-10 years	For water fill	
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	5	6-10 years	B-1	
	Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	Bolici Noom	·	L/X	J	o ro years		
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	5	6-10 years	B-2	
	Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH							
	Water Fill System	Boiler Room	2	EA	5	6-10 years	Pressure fill system off hot water pumps.	
ating [Devices							
_	Fin Tube - Hot Water	Entire Building	32	LF	6	6-10 years		
	Fin Tube - Hot Water	Entire Building	8	LF	6	6-10 years		
	Fin Tube - Hot Water	Entire Building	32	LF	6	6-10 years		
	riii lube - noi walei							
		Entire Building	7	EA	6	6-10 years		
	Cabinet Heaters - With Hot Water Coil Unit Heater - Hot Water		7 1	EA EA	6 6	6-10 years 6-10 years		



							1 120 11 111pp 7(1 21102; 01110ago; 12 00001
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	2	EΑ	6	6-10 years	
		g	_		-	5 · 6 , 5 · 6 · 6	
Mechani	ical Plumbing						
	Chilled Water Pump - 10 - 20 HP	3rd Floor Boiler Room	1	EA	6	10+ years	2023 install
	Chilled Water Pump - 10 - 20 HP	3rd Floor Boiler Room	1	EA	6	10+ years	P-1; 2023 install
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	1st floor
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	800	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	
		· ·				•	
Tempera	ature Control						
	DDC System	Entire Building	81,373	SF	7	10+ years	DDC/BAS upgraded in 2022
	Thermostats - DDC	Entire Building	76	EA	7	6-10 years	DDC/BAS upgraded in 2022
	Thermostats - DDC	Entire Building	2	EA	6	0-1 year	Not working. Room 114: Teacher's
							Lounge & Room 313
Ventilatio	on.						
ventilati	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	4	EA	6	10+ years	2023 upgrade
	CFM					,	1.5
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	2	EA	6	10+ years	2023 upgrade & install
	CFM					·	. 5
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	3	EA	6	10+ years	2023 upgrade
	CFM					·	. 5
	Exhaust Fans- Roof Mounted - Less than	Roof	2	EA	6	10+ years	2023 upgrade
	500 CFM						
Catoro	ry - Plumbing		ь	uildina	. Main		
Calego	ry : Plumbing		D	uilding	. Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat		20001011	quantity	00.0	Italik	. topiacomont	Commonto
i ioi vvali	Gas Heater - 150000 - 300000 BTU/HR	1st Floor Mech. Room	4	EA	6	10 L VOORS	
	Gas Heater - 300000 - 300000 BTU/HR Gas Heater - 300001 - 600000 BTU/HR	1st Floor Mech. Room	1	EA FA	6 6	10+ years 6-10 years	
	Cas dealer - SUUCUL - BUUCUU B LU/HK	ISLEIGOLIVIECH KOOM	1	EΑ	n	p- 10 vears	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Water	er						
	Gas Heater - 150000 - 300000 BTU/HR	1st Floor Mech. Room	1	EA	6	10+ years	
	Gas Heater - 300001 - 600000 BTU/HR	1st Floor Mech. Room	1	EA	6	6-10 years	
Pipina							
—	Domestic Piping-Hot Water Return Lines	Entire Building	81,350	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	81,350	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	81,350	SF	6	10+ years	





Catego	ry : Plumbing	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	81,350	SF	6	10+ years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	81,350	SF	6	10+ years	
	(Risers)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	81,350	SF	6	10+ years	
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	81,373	SF	6	10+ years	
	Storm Piping	Entire Building	81,373	SF	6	10+ years	
	Vent Piping	Entire Building	81,373	SF	6	10+ years	
_Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	In elevator pit. Not accessible.

Category: Room **Building: Main**

Jaiogo			Banany . Man					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lminist	rative Suites/Offices		·					
	Ceiling - Lay-in	100A - Gym	154	SF	7	10+ years		
	Doors - Side-lite	100A - Gym	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	100A - Gym	1	EA	7	10+ years		
	Floor - Tile	100A - Gym	154	SF	6	10+ years		
	Lighting - Lay-in	100A - Gym	2	EA	7	6-10 years		
	Power Distribution	100A - Gym	4	EA	7	10+ years		
	Walls - Concrete Block	100A - Gym	177	SF	7	10+ years		
	Ceiling - Exposed	103 Conference Room	220	SF	7	10+ years		
	Doors - Steel Doors incl hw	103 Conference Room	1	EA	7	10+ years		
	Floor - Tile	103 Conference Room	220	SF	6	10+ years		
	Lighting - Chandelier, Incandescent	103 Conference Room	3	EA	7	6-10 years		
	Power Distribution	103 Conference Room	10	EA	7	10+ years		
	Walls - Concrete Block	103 Conference Room	450	SF	7	10+ years		
	Ceiling - Lay-in	110 - Engineer	176	SF	7	10+ years		
	Doors - Side-lite	110 - Engineer	14	SF	7	10+ years		
	Doors - Steel Doors incl hw	110 - Engineer	1	EA	7	10+ years		
	Floor - Tile	110 - Engineer	176	SF	7	10+ years		
	Lighting - Lay-in	110 - Engineer	2	EΑ	7	6-10 years		
	Walls - Concrete Block	110 - Engineer	208	SF	7	10+ years		
	Ceiling - Lay-in	114 - Faculty Lounge	976	SF	7	10+ years		
	Doors - Side-lite	114 - Faculty Lounge	14	SF	7	10+ years		
	Doors - Wood Doors inclu hw	114 - Faculty Lounge	1	EA	7	10+ years		
	Floor - Tile	114 - Faculty Lounge	976	SF	7	10+ years		
	Lighting - Lay-in	114 - Faculty Lounge	9	EA	7	6-10 years		
	Power Distribution	114 - Faculty Lounge	8	EA	7	10+ years		





Catego	ry : Room		Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	114 - Faculty Lounge	566	SF	7	10+ years		
	Walls - Plaster/Drywall	114 - Faculty Lounge	510	SF	7	10+ years		
	Work SInk	114 - Faculty Lounge	1	EA	7	10+ years		
	Work SInk	114 - Faculty Lounge	1	EA	7	10+ years		
	Ceiling - Exposed	2nd Floor - S11	100	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - S11	1	EA	7	10+ years		
	Floor - Tile	2nd Floor - S11	100	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor - S11	2	EA	7	6-10 years		
	Power Distribution	2nd Floor - S11	2	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor - S11	163	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor - S11	178	SF	7	10+ years		
	Ceiling - Exposed	2nd Floor - S13	100	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - S13	1	EA	7	10+ years		
	Floor - Tile	2nd Floor - S13	100	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor - S13	2	EA	7	6-10 years		
	Power Distribution	2nd Floor - S13	2	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor - S13	163	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor - S13	178	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor - Seminar Room	700	SF	7	10+ years		
	Doors - Side-lite	2nd Floor - Seminar Room	14	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - Seminar Room	1	EA	7	10+ years		
	Floor - Tile	2nd Floor - Seminar Room	700	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor - Seminar Room	6	ĒA	7	6-10 years		
	Power Distribution	2nd Floor - Seminar Room	2	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor - Seminar Room	270	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor - Seminar Room	580	SF	6	10+ years		
	Ceiling - Lay-in	Clerk Office	207	SF	7	10+ years		
	Doors - Side-lite	Clerk Office	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Clerk Office	1	ĒA	7	10+ years		
	Floor - Tile/Sheet	Clerk Office	207	SF	7	2-5 years		
	Lighting - Lay-in	Clerk Office	2	ĒΑ	7	6-10 years		
	Power Distribution	Clerk Office	6	EA	7	10+ years		
	Walls - Concrete Block	Clerk Office	124	SF	7	10+ years		
	Walls - Plaster/Drywall	Clerk Office	124	SF	7	10+ years		
	Ceiling - Lay-in	Counselor Office	157	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Counselor Office	1	EΑ	7	10+ years		
	Floor - Tile/Sheet	Counselor Office	157	SF	7	10+ years		
	Lighting - Lay-in	Counselor Office	2	EA	7	6-10 years		
	Power Distribution	Counselor Office	6	EA	7	10+ years		
	Walls - Concrete Block	Counselor Office	100	SF	7	10+ years		
	Walls - Plaster/Drywall	Counselor Office	91	SF	7	10+ years		
	Ceiling - Lay-in	Kitchen Office Rm:111	104	SF	7	10+ years		
	Doors - Side-lite	Kitchen Office Rm:111	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Kitchen Office Rm:111	10	EA	7	10+ years		
	20010 Wood 20013 IIIold IIW	ratorion office rain. 111	'	L/\	,	TOT yours		





Category : Room			Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	Kitchen Office Rm:111	104	SF	7	10+ years		
	Lighting - Lay-in	Kitchen Office Rm:111	1	EA	7	6-10 years		
	Walls - Concrete Block	Kitchen Office Rm:111	142	SF	7	10+ years		
	Ceiling - Lay-in	Main Office	642	SF	7	10+ years		
	Doors - Side-lite	Main Office	54	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years		
	Floor - Carpet	Main Office	442	SF	6	2-5 years		
	Floor - Tile	Main Office	200	SF	6	6-10 years		
	Lighting - Lay-in	Main Office	9	ĒΑ	7	6-10 years		
	Power Distribution	Main Office	10	EA	7	10+ years		
	Walls - Concrete Block	Main Office	583	SF	7	10+ years		
	Walls - Plaster/Drywall	Main Office	200	SF	7	10+ years		
	Work SInk	Main Office	1	EΑ	7	10+ years		
	Ceiling - Lay-in	Main office Conference	289	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Main office Conference	1	EA	7	10+ years		
	Floor - Tile	Main office Conference	289	SF	7	6-10 years		
	Lighting - Lay-in	Main office Conference	4	EA	7	6-10 years		
	Power Distribution	Main office Conference	6	EA	7	10+ years		
	Walls - Concrete Block	Main office Conference	176	SF	7	•		
		Main office Conference	176	SF SF	7	10+ years		
	Walls - Plaster/Drywall	Nurses Office	167	SF SF		10+ years		
	Ceiling - Lay-in				7	10+ years		
	Doors - Wood Doors inclu hw	Nurses Office	2	EA	7	10+ years		
	Floor - Tile	Nurses Office	167	SF	7	10+ years		
	Lighting - Lay-in	Nurses Office	2	EΑ	7	6-10 years		
	Power Distribution	Nurses Office	6	EA	7	10+ years		
	Walls - Concrete Block	Nurses Office	196	SF	7	10+ years		
	Walls - Plaster/Drywall	Nurses Office	196	SF	7	10+ years		
	Work SInk	Nurses Office	1	EA	7	10+ years		
	Ceiling - Lay-in	Principal Office	161	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Principal Office	1	EA	7	10+ years		
	Floor - Tile/Sheet	Principal Office	161	SF	7	6-10 years		
	Lighting - Lay-in	Principal Office	2	EA	7	6-10 years		
	Power Distribution	Principal Office	6	EA	7	10+ years		
	Walls - Concrete Block	Principal Office	98	SF	7	10+ years		
	Walls - Plaster/Drywall	Principal Office	98	SF	7	10+ years		
	Ceiling - Lay-in	Room 300, Seminar Room	364	SF	7	10+ years		
	Doors - Side-lite	Room 300, Seminar Room	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Room 300, Seminar Room	1	EA	7	10+ years		
	Floor - Tile	Room 300, Seminar Room	364	SF	7	10+ years		
	Lighting - Lay-in	Room 300, Seminar Room	7	EA	7	6-10 years		
	Power Distribution	Room 300, Seminar Room	6	EA	7	10+ years		
	Walls - Concrete Block	Room 300, Seminar Room	104	SF	7	10+ years		
	Walls - Plaster/Drywall	Room 300, Seminar Room	313	SF	7	10+ years		
	Ceiling - Exposed	S-18	110	SF	7	10+ years		
	•					•		





Catego	ry : Room		В	uilding	: Main		1423 N THIPP AVENUE, Officago, IE 00001
290	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	S-18	1	EA	7	10+ years	
	Floor - Tile	S-18	110	SF	7	10+ years	
	Lighting - Pendent/Surface	S-18	2	EA	7	6-10 years	
	Power Distribution	S-18	6	EA	7	10+ years	
	Walls - Concrete Block	S-18	110	SF	7	10+ years	
	Walls - Plaster/Drywall	S-18	224	SF	7	10+ years	
	Ceiling - Exposed	S-20	110	SF	7	10+ years	
	Floor - Tile	S-20	110	SF	7	6-10 years	
	Lighting - Pendent/Surface	S-20	2	EA	7	6-10 years	
	Power Distribution	S-20	4	EA	7	10+ years	
	Walls - Concrete Block	S-20	110	SF	7	10+ years	
	Walls - Plaster/Drywall	S-20	124	SF	7	10+ years	
	Ceiling - Exposed	S-21-B	207	SF	7	10+ years	
	Doors - Steel Doors incl hw	S-21-B	1	EA	7	10+ years	
	Floor - Tile	S-21-B	207	SF	7	10+ years	
	Lighting - Pendent/Surface	S-21-B	3	EA	7	10+ years	
	Power Distribution	S-21-B	6	EA	7	10+ years	
	Walls - Concrete Block	S-21-B	180	SF	7	10+ years	
	Walls - Plaster/Drywall	S-21-B	250	SF	7	10+ years	
_Gvmnas	ia						
,	Ceiling - Exposed	100	3,861	SF	7	10+ years	
	Doors - Steel Doors incl hw	100	4	ĒΑ	7	10+ years	
	Floor - Epoxy/ Painted	100	3,861	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	100	10	ĒΑ	7	6-10 years	
	Storage/ Closet	100	97	SF	7	10+ years	
	Walls - Concrete Block	100	4,440	SF	7	10+ years	
Library							
	Casework	210	75	LF	7	10+ years	
	Ceiling - Plaster/Drywall	210	823	SF	7	10+ years	
	Ceiling - Splined	210	1,274	SF	7	10+ years	
	Ceiling - Splined	210	. 8	SF	4	1-2 years	Water damage
	Doors - Side-lite	210	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	210	2	ĒΑ	7	10+ years	
	Floor - Tile	210	2,105	SF	7	10+ years	
	Lighting - Lay-in	210	6	EA	7	6-10 years	
	Lighting - Lay-in	210	6	EA	6	6-10 years	
	Lighting - Pendent/Surface	210	20	EA	7	6-10 years	
	Storage/ Closet	210	139	SF	7	10+ years	
	Walls - Concrete Block	210	2,165	SF	7	10+ years	
	Walls - Plaster/Drywall	210	403	SF	7	10+ years	





	ry : Room		R	uilding	· Main		1425 N Tripp AVENUE, Chicago, IL 60651
Calego	iy . Koom		D	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Shower Room	Location	Quantity	00111	Italik	Replacement	Comments
LUCKEI/S	Accessories	1st Floor	96	SF	7	6-10 years	
		1st Floor	81	SF SF	7		
	Ceiling - Plaster/Drywall				7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	96	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Showers	1st Floor	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	5	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	189	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	50	SF	7	10+ years	
	Water Closet	1st Floor	1	EΑ	7	10+ years	
	Accessories	1st Floor	96	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	86	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	96	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	1	EA	7	10+ years	
	Showers	1st Floor	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	5	EA	7	10+ years	
	Student Lockers - Two Tier	1st Floor	6	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	189	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	50	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Water Closet	1601	•	_/ \	•	101 youro	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	Art & Music	5,390	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Art & Music	6	EA	7	10+ years	
	Floor - Tile	Art & Music	5,390	SF	7	10+ years	
	Lighting - Lay-in	Art & Music	80	EA	7	6-10 years	
	Storage/ Closet	Art & Music	99	SF	7	10+ years	
	Storage/ Closet	Art & Music	99	SF	7	10+ years	
	Storage/ Closet	Art & Music	99	SF	7	10+ years	
	Storage/ Closet	Art & Music	99	SF	7	10+ years	
	Walls - Concrete Block	Art & Music	5,470	SF	7	10+ years	
			5,470	SF SF		,	
	Walls - Plaster/Drywall Ceiling - Plaster/Drywall	Art & Music	1,210	SF SF	6 7	10+ years	No occupancy cianage
	Cening - Flaster/Drywan	Serving Area	1,210	SF	1	10+ years	No occupancy signage



Category : Room			В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	Serving Area	4	EA	7	10+ years	No occupancy signage		
	Floor - Concrete Epoxy/ Painted	Serving Area	1,210	SF	7	10+ years	No occupancy signage		
	Lighting - Pendent/Surface	Serving Area	11	EA	7	6-10 years	No occupancy signage		
	Serving Line	Serving Area	40	LF	7	10+ years	No occupancy signage		
	Storage/ Closet	Serving Area	140	SF	7	10+ years	No occupancy signage		
	Walls - Concrete Block	Serving Area	3,470	SF	7	10+ years	No occupancy signage		
MDF ID	F								
_	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Finishes	2nd Floor	83	SF	7	10+ years			
	Finishes	2nd Floor	16	SF	7	6-10 years			
	Other Cooling Unit	2nd Floor	1	EA	7	6-10 years	Ductless split system.		
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	45	SF	7	10+ years			
	Janitor's Closet	1st Floor	106	SF	7	10+ years			
	Loading Docks	1st Floor	671	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	1,063	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	590	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	60	SF	7	10+ years			
	Vaults	1st Floor	147	SF	7	10+ years			
	Janitor's Closet	2nd Floor	12	SF	7	10+ years			
	Mechanical/ Service Rooms	2nd Floor	45	SF	7	10+ years			
		2nd Floor 2nd Floor	943	SF	7	•			
	Storage Room			SF		10+ years			
	Boiler Room	3rd Floor	1,144	SF SF	7	10+ years			
	Janitor's Closet	3rd Floor	12		7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	1,320	SF	7	10+ years			
	Storage Room	3rd Floor	990	SF	7	10+ years			
Prep Ro									
	Casework	Room 310A. Science Work Room	45	LF	7	10+ years			
	Ceiling - Lay-in	Room 310A. Science Work Room	215	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Room 310A. Science Work Room	1	EA	7	10+ years			
	Floor - Tile	Room 310A. Science Work Room	215	SF	6	10+ years			
	Lighting - Lay-in	Room 310A. Science Work Room	3	EA	7	6-10 years			
	Walls - Concrete Block	Room 310A. Science Work Room	162	SF	7	10+ years			
	Walls - Plaster/Drywall	Room 310A. Science Work Room	100	SF	7	10+ years			
	Work Sink	Room 310A. Science Work Room	1	EA	7	10+ years			
Restroor	n								
	Accessories	1st Floor	118	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	48	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	70	SF	6	6-10 years			





Catego	Category : Room		Building : Main					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	118	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	2	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years		
	Partitions	1st Floor	1	EA	7	10+ years		
	Urinals	1st Floor	1	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	189	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	130	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		
	Accessories	2nd Floor	565	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	565	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	565	SF	7	10+ years		
	Floor Drain	2nd Floor	2	EA	7	10+ years		
	Lavatory	2nd Floor	2	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	23	EA	7	6-10 years		
	Partitions	2nd Floor	15	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	653	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	540	SF	7	10+ years		
	Water Closet	2nd Floor	14	ĒΑ	7	10+ years		
	Water Closet	2nd Floor	1	EA	4	1-2 years	Not working	
	Accessories	2nd Floor	527	SF	7	6-10 years	S .	
	Ceiling - Plaster/Drywall	2nd Floor	527	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	527	SF	7	10+ years		
	Floor Drain	2nd Floor	3	EA	7	10+ years		
	Lavatory	2nd Floor	2	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	23	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	10+ years		
	Urinals	2nd Floor	15	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	606	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	540	SF	7	10+ years		
	Water Closet	2nd Floor	2	EΑ	7	10+ years		
	Accessories	2nd Floor - Men	61	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Men	51	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor - Men	10	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - Men	1	ĒΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men	61	SF	7	10+ years		
	Floor Drain	2nd Floor - Men	1	ĒΑ	7	6-10 years		
	Lavatory	2nd Floor - Men	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor - Men	1	EA	7	6-10 years		
	Walls - Concrete Block	2nd Floor - Men	119	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor - Men	80	SF	7	10+ years		
	Water Closet	2nd Floor - Men	1	EA	7	10+ years		
	Accessories	2nd Floor - Women	61	SF	7	6-10 years		
	. 1333001100	2113 1 1331 1 1 1 1 1 1 1 1 1 1 1 1 1 1	01	٥.	•	o io youio		





Catego	Category : Room			uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor - Women	51	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Women	10	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor - Women	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Women	61	SF	7	10+ years	
	Floor Drain	2nd Floor - Women	1	EA	7	10+ years	
	Lavatory	2nd Floor - Women	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - Women	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor - Women	119	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Women	80	SF	7	10+ years	
	Water Closet	2nd Floor - Women	1	EA	7	10+ years	
	Accessories	3rd Floor	565	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	565	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	565	SF	7	10+ years	
	Floor Drain	3rd Floor	3	ĒΑ	7	10+ years	
	Lavatory	3rd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	22	ĒΑ	7	6-10 years	
	Partitions	3rd Floor	15	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	353	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	300	SF	7	10+ years	
	Water Closet	3rd Floor	15	EA	7	10+ years	
	Accessories	3rd Floor	527	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	527	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	527	SF	7	10+ years	
	Floor Drain	3rd Floor	3	EA	7	10+ years	
	Lavatory	3rd Floor	2	EΑ	7	10+ years	
	Lighting - Lay-in	3rd Floor	22	EΑ	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	13	EA	7	10+ years	
	Urinals	3rd Floor	2	EA	5	1-2 years	Out of order
	Walls - Concrete Block	3rd Floor	306	SF	7	10+ years	Out of order
	Walls - Structural Glazed Tile	3rd Floor	300	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Accessories	3rd Floor Staff Men Restroom	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Staff Men Restroom	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Staff Men Restroom	120	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Staff Men Restroom	120	SF	7	10+ years	
	Floor Drain	3rd Floor Staff Men Restroom	120	EA	7	10+ years	
			· · · · · · · · · · · · · · · · · · ·	EA	7		
	Lavatory Lighting - Lay-in	3rd Floor Staff Men Restroom 3rd Floor Staff Men Restroom	1	EA EA	7	10+ years 6-10 years	
	Walls - Concrete Block	3rd Floor Staff Men Restroom	160	SF	7	<u>-</u>	
	Walls - Concrete Block Walls - Structural Glazed Tile	3rd Floor Staff Men Restroom 3rd Floor Staff Men Restroom		SF SF	7 7	10+ years	
			160			10+ years	
	Water Closet	3rd Floor Staff Men Restroom	1	EA	7	10+ years	
	Accessories	3rd Floor Women Staff	110	SF SF	7	6-10 years	Cailing is stained
	Ceiling - Plaster/Drywall	3rd Floor Women Staff	110	SF	6	10+ years	Ceiling is stained





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor Women Staff	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Women Staff	110	SF	7	10+ years	
	Floor Drain	3rd Floor Women Staff	1	EA	7	10+ years	
	Lavatory	3rd Floor Women Staff	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor Women Staff	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor Women Staff	155	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Women Staff	155	SF	7	10+ years	
	Water Closet	3rd Floor Women Staff	1	ĒΑ	7	10+ years	
	Accessories	In Room 101/102	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 101/102	43	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 101/102	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 101/102	43	SF	7	10+ years	
	Floor Drain	In Room 101/102	1	EA	7	10+ years	
	Lavatory	In Room 101/102	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 101/102	1	EA	7	6-10 years	
	Walls - Concrete Block	In Room 101/102	39	SF	7	10+ years	
	Walls - Structural Glazed Tile	In Room 101/102	13	SF	7	•	
	Water Closet			EA		10+ years	
		In Room 101/102	1		7	10+ years	
	Accessories	In Room 108	50	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 108	50		7	10+ years	
	Doors - Wood Doors inclu hw	In Room 108	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 108	50	SF	7	10+ years	
	Floor Drain	In Room 108	1	EA	7	10+ years	
	Lavatory	In Room 108	1	EA	7	10+ years	
	Lighting - Lay-in	In Room 108	1	EA	7	6-10 years	
	Walls - Concrete Block	In Room 108	61	SF	7	10+ years	
	Walls - Structural Glazed Tile	In Room 108	25	SF	7	10+ years	
	Water Closet	In Room 108	1	EA	7	10+ years	
	Accessories	In the Main Office	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In the Main Office	53	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In the Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In the Main Office	53	SF	7	10+ years	
	Floor Drain	In the Main Office	1	EA	7	10+ years	
	Lavatory	In the Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	In the Main Office	1	EA	7	6-10 years	
	Walls - Concrete Block	In the Main Office	46	SF	7	10+ years	
	Walls - Structural Glazed Tile	In the Main Office	15	SF	7	10+ years	
	Water Closet	In the Main Office	1	EA	7	10+ years	
	Accessories	Restroom in 104/106	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 104/106	43	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 104/106	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in 104/106	43	SF	7	10+ years	
	Floor Drain	Restroom in 104/106	1	ĒΑ	7	10+ years	
	Lavatory	Restroom in 104/106	1	EΑ	7	10+ years	
	·· <i>-</i> ····· <i>y</i>		•		•	,	





Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	Restroom in 104/106	1	EA	7	6-10 years	
	Walls - Concrete Block	Restroom in 104/106	51	SF	7	10+ years	
	Walls - Structural Glazed Tile	Restroom in 104/106	51	SF	7	10+ years	
	Water Closet	Restroom in 104/106	1	EA	7	10+ years	
	Accessories	Women's Room, 1st Floor	115	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor	95	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Women's Room, 1st Floor	20	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Women's Room, 1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's Room, 1st Floor	115	SF	7	10+ years	
	Floor Drain	Women's Room, 1st Floor	1	EA	7	10+ years	
	Lavatory	Women's Room, 1st Floor	2	EΑ	7	10+ years	
	Lighting - Lay-in	Women's Room, 1st Floor	2	EA	7	6-10 years	
	Partitions	Women's Room, 1st Floor	2	EA	7	10+ years	
	Walls - Concrete Block	Women's Room, 1st Floor	105	SF	7	10+ years	
	Walls - Structural Glazed Tile	Women's Room, 1st Floor	35	SF	7	10+ years	
	Water Closet	Women's Room, 1st Floor	2	EA	7	10+ years	

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	Casework	1st Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,200	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	10+ years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,440	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
01	W400 (Kr. 1						
_Classroc	om #102 (Kindergarten)	4 . 🗖	45			10	
	Casework	1st Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,200	SF	<i>'</i>	10+ years	
	Doors - Side-lite	1st Floor	18	SF	<u>/</u>	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	_	10+ years	
	Floor - Tile	1st Floor	1,200	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,440	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	

Campus Name: West Park Page : 16 of 31 Assessment Date: 06/03/2024





Catego	Category : Classroom			uilding			
Outego	y . Glassi Goili			ananig	· Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
•	m #104 (Faculty Lounge)						
Classioo	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	7		
		1st Floor		EA	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	1st Floor	1 880	SF	7	10+ years 10+ years	
		1st Floor		EA	7		
	Lighting - Lay-in		9	LF	7	6-10 years	
	Marker Board	1st Floor	10		=	6-10 years	
	Storage/ Closet	1st Floor	87	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,012	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	m #106 (Office)						
	Casework	1st Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	880	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	880	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
				SF	7	•	
	Storage/ Closet	1st Floor	87	SF SF		10+ years	
	Walls - Concrete Block	1st Floor	1,012	SF EA	7 7	10+ years	
	Work Sink	1st Floor	2	EA	/	10+ years	
_Classroo	m #108 (Pre School)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,080	SF	7	10+ years	
	Doors - Side-lite	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,080	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	11	EA	7	6-10 years	
	Storage/ Closet	1st Floor	67	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	653	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	653	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
	WOIN OIL	13011001	2	L/\	,	101 years	
_Classroo	m #201 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
			• • • •			,	





Category : Classroom			B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	10	EΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	410	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	710	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	812	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	200	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	74	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,046	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	752	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	260	SF	7	10+ years	





Catego	ry : Classroom	R	uilding	1423 N THIPP AVENUE, Chicago, IL 60631			
Calego	iy . Glassioolii			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	om #205 (Regular Classroom)	2004.1011	Quantity	•	rtann	rtopiacomont	
Classiuc	Casework	2nd Floor	40	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,050	SF	7		
	Chalk Board	2nd Floor		LF	4	10+ years	
		2nd Floor 2nd Floor	24	SF		2-5 years	
	Doors - Side-lite	2nd Floor 2nd Floor	14		7 7	10+ years	
	Doors - Wood Doors inclu hw		1 050	EA		10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	149	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	971	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	502	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	510	SF	7	10+ years	
	·					,,,,,,	
_Classroo	om #207 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,046	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	149	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	971	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #208 (Other Instructional Use)						
_01000100	Casework	2nd Floor	55	LF	7	10+ years	
				SF		•	
	Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor	1,350	SF SF	7 7	10+ years	
			28 2	SF EA	7 7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	1	10+ years	





Category : Classroom			B	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
лопр	Floor - Tile	2nd Floor	1,350	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Wall Mirrors	2nd Floor	95	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	766	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	766	SF	6	10+ years	
:lassroc	om #209 (Art Room)						
71000100	Casework	2nd Floor	40	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	•	
						10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1 050	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	80	SF	7	10+ years	Qty updated
	Walls - Concrete Block	2nd Floor	99	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #211 (Music Room)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	Blocked
	Walls - Concrete Block	2nd Floor	99	SF	7	10+ years	2.00.104
	Walls - Plaster/Drywall	2nd Floor	971	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroc	om #212 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	7		
			880	SF		10+ years	
	Floor - Tile	2nd Floor			7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	





Catego	ry : Classroom		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	502	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	510	SF	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	99	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	880	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	762	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	7	10+ years	
Classroo	om #215 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	99	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
	Work Sink	2nd Floor	1,120	EA	7	10+ years	
Classroo	om #217 (Regular Classroom)						
	, -						





	SCHOOLS		D	uildina	. Mair		1425 N Tripp AVENUE, Chicago, IL 60651
Catego	ry : Classroom		В	uilding	: wam	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Casework	2nd Floor	40	LF	7	10+ years	Comments
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	1,030	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	14	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7		
		2nd Floor				10+ years	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	16	EA	7	6-10 years	
			12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	99	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #219 (Regular Classroom)						
	Casework	2nd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,050	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	399	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	721	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
						, , , , ,	
_Classroo	om #301 (Regular Classroom)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
01	(1000 (D I. Ol						
Classro	om #302 (Regular Classroom)						
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	





Catogo	ry : Classroom		В	uilding	· Main		1425 N THPP AVENUE, Chicago, IL 60651
Catego	ily . Classioolii		В	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Doors - Wood Doors inclu hw	3rd Floor	Qualitity	EA	7	10+ years	Comments
	Floor - Tile	3rd Floor	880	SF	7	•	
						10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	l calcad
	Storage/ Closet	3rd Floor	15	SF	7 7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	1,012	SF	/	10+ years	
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,050	SF	7	10+ years	
	Walls - Coliciete Block	314 1 1001	1,030	OI.	,	10+ years	
Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	4	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	1,012	SF	7	10+ years	
Classro	om #305 (Regular Classroom)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	1,030	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
			10	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	•				
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	· · · · · · · ·		300	٠.	•	,	





ALL A							1425 N Tripp AVENUE, Chicago, IL 60651
Catego	ry : Classroom		В	uilding	: Main		
	_				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	4	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	15	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,012	SF	7	10+ years	
Classroo	om #307 (Music Room)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
Classroo	om #308 (Store Room)						
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,095	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
Classroo	om #310 (Science Lab Level 3)						
	Casework	3rd Floor	56	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,177	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,177	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,435	SF	7	10+ years	
	Work Sink	3rd Floor	1,435	EA	7	10+ years	
	WOLK OILIK	31u i 1001	3	ĽA	,	TOT years	





Catego	ry : Classroom		R	uilding	· Main		1425 N Tripp AVENUE, Chicago, IL 60651
Calego	y . Classicolli			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Location	Quantity	00111	Marin	Replacement	Comments
Classroo	m #312 (Other Instructional Use)	0.151	4.5		-	40	
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	10+ years	Locked
	Walls - Concrete Block	3rd Floor	1,012	SF	7	10+ years	
_Classroo	m #313 (Regular Classroom)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
	Walls - Collete Block	314 1 1001	1,120	Oi	,	10+ years	
_Classroo	m #314 (Regular Classroom)						
	Casework	3rd Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	880	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	880	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	9	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,012	SF	7	10+ years	
01	"045 (O) D						
_Classroo	m #315 (Store Room)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	





Calego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
Classro	om #317 (Regular Classroom)						
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,120	SF	7	10+ years	
Classroo	om #319 (Regular Classroom)	0.151				40	
	Casework	3rd Floor	40	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,050	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,120	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Julogo						recommend	
_	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group			•			Replacement	Comments
Froup	Ceiling - Lay-in	1st Floor	2,628	SF	7	Replacement 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor 1st Floor	2,628 1,000	SF SF	7 7	Replacement 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor	2,628 1,000 8	SF SF EA	7 7 7	10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor 1st Floor	2,628 1,000 8 16	SF SF EA EA	7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,628 1,000 8 16 40	SF SF EA EA SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,628 1,000 8 16 40 4	SF SF EA EA SF EA	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,628 1,000 8 16 40	SF SF EA SF EA SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,628 1,000 8 16 40 4	SF SF EA EA SF EA	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	2,628 1,000 8 16 40 4 3,628	SF SF EA SF EA SF EA	7 7 7 7 7 7	10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor	2,628 1,000 8 16 40 4 3,628 20	SF SF EA SF EA SF EA SF	7 7 7 7 7 7 7	10+ years 6-10 years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Lighting - Lay-in	1st Floor	2,628 1,000 8 16 40 4 3,628 20 2	SF SF EA SF EA SF EA SF SF	7 7 7 7 7 7 7 7	10+ years 6-10 years 6-10 years	Comments
Group Corridor	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Lighting - Lay-in Walls - Concrete Block	1st Floor	2,628 1,000 8 16 40 4 3,628 20 2 3,940	SF SF EA SF EA SF EA SF	7 7 7 7 7 7 7 7 6	10+ years 6-10 years 6-10 years 10+ years	Comments
Group	Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Lighting - Lay-in Walls - Concrete Block Walls - Structural Glazed Tile	1st Floor	2,628 1,000 8 16 40 4 3,628 20 2 3,940 44	SF SF EA SF EA SF EA SF SF	7 7 7 7 7 7 7 7 6 7	10+ years 6-10 years 6-10 years 10+ years 10+ years	Comments





Catego	ry : Interior		В	uilding	: Main		1423 N THEP AVENUE, Officago, IE 00001
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	1,550	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,544	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	34	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,550	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	4	EA	7	10+ years	Qty updated
	Floor - Tile/Sheet	3rd Floor	1,550	SF	7	10+ years	, .1
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	1,544	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	34	SF	7	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Metal Detector	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	18	EA	7	6-10 years	
	Security Cameras	Entire Building	18	EA	7	6-10 years	
	Security Cameras	Entire Building	2	EA	5	1-2 years	Two inside cameras not working
	Security Cameras	Entire Building	1	EA	5	1-2 years	One outside camera not working
_Stairs	Osilia a Disstan/Durasali	NI	045	05		40	No atains also and
	Ceiling - Plaster/Drywall	North	315	SF SF	7	10+ years	No stains observed
	Floor - Concrete	North	315		7	10+ years	
	Handrails	North	357	LF	7	10+ years	
	Lighting - Pendent/Surface	North	12	EΑ	7	6-10 years	
	Lighting - Wall Mounted	North	2	EA	7	6-10 years	
	Stairs - Concrete	North	582	LF	7	10+ years	
	Walls - Concrete Block	North	387	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	315	SF	7	10+ years	
	Floor - Concrete	South	315	SF	7	10+ years	
	Handrails	South	357	LF	7	10+ years	
	Lighting - Pendent/Surface	South	12	EA	7	6-10 years	Qty updated
	Lighting - Wall Mounted	South	2	EA	7	6-10 years	
	Stairs - Concrete	South	582	LF	6	10+ years	
	Walls - Concrete Block	South	387	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	315	SF	7	10+ years	
	Floor - Concrete	West	315	SF	7	10+ years	
	Handrails	West	357	LF	7	10+ years	
	Lighting - Pendent/Surface	West	12	EA	7	6-10 years	
	Lighting - Wall Mounted	West	2	EA	7	6-10 years	
	Stairs - Concrete	West	582	LF	6	10+ years	
	Walls - Concrete Block	West	387	SF	7	10+ years	



Category : Interior	ry : Interior Building : Main					
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments				
Vertical Conveyance						
Elevator - Hydraulic Elevator	1st Floor	1 EA 7 10+ years				

Campus Name: West Park Page : 28 of 31 Assessment Date: 06/03/2024



Category : Site Building : Site

Catego	ry : Site		ь	uilding	. Site		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Lighting	Site - Northwest	10	EA	6	10+ years	
	Surface - Natural	Site - Northwest	13,050	SF	6	10+ years	
	Surface - Asphalt	West	3,000	SF	7	10+ years	
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	0-1 year	Sinking
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	10+ years	
Fencina							
· commig	Fencing - Chain Link	Entire Site	155	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	50	LF	4	0-1 year	Top rails missing/broken
	Fencing - Old Standard Ornamental	Entire Site	1,396	LF	6	10+ years	Changed to match current observations
Landsca	pe						
	Benches	Entire Site	7	EA	6	10+ years	
	Benches	Entire Site	2	EA	5	2-5 years	
	Benches	Entire Site	2	EA	4	0-1 year	Rotten wood/missing pieces
	Landscape - Grass	Entire Site	65,175	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	18,750	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	500	SF	5	1-2 years	Uneven/cracking
	Lighting - Pole Mounted	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	18	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	5,950	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I	Lot						
	Surface - Asphalt	NE courtyard	2,124	SF	4	1-2 years	Added to match current observations Cracking/potholes
	Surface - Concrete	NE courtyard	2,430	SF	6	10+ years	-
	Concrete Curbs	SW courtyard	558	LF	6	10+ years	
	Lighting - Pole Mounted	SW courtyard	4	EA	6	10+ years	
	Surface - Asphalt	SW courtyard	15,750	SF	6	6-10 years	
	Surface - Asphalt	SW courtyard	3,600	SF	4	0-1 year	Cracking/potholes. Quantity changed to match current observations
	Vehicular Screening	SW courtyard	228	LF	6	10+ years	
Playgrou	ınd						
, 0	Equipment - Pre K 3-5	NE courtyard	1	EA	7	10+ years	Added to match current observations

Campus Name: West Park Page : 29 of 31 Assessment Date: 06/03/2024



Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Equipment - School Age 5-12 Surface - Poured Surface	NE courtyard NE courtyard	1 3,050	EA SF	7 7	10+ years 6-10 years	
Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	454	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	3,980	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	300	SF	4	1-2 years	Deteriorating/uneven
_Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	2	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: West Park Page: 30 of 31 Assessment Date: 06/03/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

•				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	2nd Floor	209	215	1,050	126	54	N	Υ
Faculty Lounge	Pre School	1st Floor	104	129	880	120	60	N	Υ
Kindergarten	Kindergarten	1st Floor	101	122	1,200	120	60	N	Υ
Kindergarten	Kindergarten	1st Floor	102	125	1,200	120	60	N	Υ
Music Room	Regular Classroom	2nd Floor	211	213	1,050	78	39	N	Υ
Music Room	Regular Classroom	3rd Floor	307	314	1,050	126	54	N	Υ
Office	Kindergarten	1st Floor	106	133	880	120	60	N	Y
Other Instructional Use	Library	2nd Floor	208	232	1,350	120	60	N	Υ
Other Instructional Use	Regular Classroom	3rd Floor	312	333	880	78	39	N	Υ
Pre School	Kindergarten	1st Floor	108	138	1,080	90	45	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	226	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	228	880	78	39	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	223	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	230	880	78	39	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	220	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	231	880	78	39	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	216	1,050	126	54	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	235	880	78	39	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	213	210	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	236	880	78	39	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	215	207	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	204	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	219	219	1,050	78	126	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	324	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	326	880	78	39	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	321	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	328	880	78	39	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	318	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	329	880	78	39	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	313	309	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	334	880	78	39	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	317	317	1,050	126	54	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	319	300	1,050	126	54	N	Υ
Science Lab Level 3	Science Lab Level 3	3rd Floor	310	332	1,177	104	52	N	Υ
Store Room	Computer Lab	3rd Floor	308	330	880	78	39	N	N
Store Room	Regular Classroom	3rd Floor	315	306	1,050	126	54	N	Y