

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report) . Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|---------------------|------------------|------------------|-----------------------|--------------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1905 | 3 | 80,395 | \$4,055,442 |
| Addition | 1928 | 3 | 18,856 | \$931,242 |
| Linked Addition | 1996 | 1 | 18,200 | \$718,575 |
| SITE | | | | \$378,118 |
| Campus Total | | | 117,451 | \$6,083,376 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Entrance Control - Audio | 1 | EA | 6 | \$497 |
| | Exterior Doors - Exterior Steel Door | 19 | EA | 6 | \$9,130 |
| | Exterior Doors - Side lite | 1 | EA | 6 | \$313 |
| | Exterior Doors - Transom Lite | 16 | EA | 7 | \$0 |
| | Exterior Stairs - Concrete | 75 | LF | 5 | \$8,219 |
| | Exterior Stairs - Concrete | 95 | LF | 6 | \$7,768 |
| | Exterior Stairs - Concrete | 30 | LF | 7 | \$0 |
| | Exterior Stairs - Stone | 10 | LF | 6 | \$1,130 |
| Fire Escape | | | | | |
| | Fire Escape | 62 | LF | 6 | \$39,169 |
| Foundation | | | | | |
| | Foundation - Masonry | 890 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 80,395 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 9 | EA | 6 | \$4,829 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|-----------|
| Lighting | Exterior Lighting - Wall Mounted | 4 | EA | 6 | \$1,155 |
| Roof System | Chimney - Brick Chimney- Concrete/ Mortar Liner | 143 | LF | 6 | \$136,520 |
| | Coping - Clay Tile | 50 | LF | 5 | \$4,174 |
| | Coping - Clay Tile | 535 | LF | 6 | \$17,183 |
| | Coping - Stone | 560 | LF | 6 | \$17,986 |
| | Downspouts - Exterior Downspouts | 120 | LF | 5 | \$9,690 |
| | Downspouts - Exterior Downspouts | 130 | LF | 6 | \$4,320 |
| | Downspouts - Interior Downspouts | 260 | LF | 6 | \$8,641 |
| | Parapet - 16" - 30" Height | 105 | LF | 6 | \$4,195 |
| | Parapet - Parapet < 16" Height | 530 | LF | 6 | \$11,293 |
| | Parapet - Parapet > 30" | 510 | LF | 6 | \$32,600 |
| | Roof - Modified Bitumen | 24,620 | SF | 6 | \$231,659 |
| | Roof Structure - Steel with Clay Tile Arch | 24,620 | SF | 7 | \$0 |
| Walls | Cheek-Wall - Concrete | 10 | SF | 5 | \$236 |
| | Cheek-Wall - Concrete | 100 | SF | 7 | \$0 |
| | Cornice - Cast Stone | 416 | LF | 6 | \$14,426 |
| | Exterior Walls - Brick | 37,554 | SF | 6 | \$252,400 |
| | Exterior Walls - Prefabricated Metal Panel Wall | 250 | SF | 6 | \$1,419 |
| | Exterior Walls - Stone-Cast | 18 | SF | 5 | \$317 |
| | Exterior Walls - Stone-Cast | 3,800 | SF | 6 | \$25,540 |
| Windows | Guard - Guards perforated | 1,815 | SF | 6 | \$23,177 |
| | Guard - Guards wire guard | 624 | SF | 6 | \$7,968 |
| | Lintels - Brick | 20 | LF | 7 | \$0 |
| | Lintels - Steel | 714 | LF | 7 | \$0 |
| | Lintels - Stone | 214 | LF | 7 | \$0 |
| | Windows - Sash Aluminum Double-pane | 6,640 | SF | 5 | \$357,684 |
| | Windows - Sash Aluminum Double-pane | 1,657 | SF | 6 | \$12,369 |

Building Exterior Subtotal:

\$1,246,008

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------|---|----------|------|------|-----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Auditorium and Aisle Lighting | 4,563 | SF | 6 | \$2,414 |
| | Emergency A/C Power - Corridors and Stairs | 12,953 | SF | 6 | \$3,890 |
| | Emergency A/C Power - Gym | 3,839 | SF | 6 | \$1,427 |
| | Emergency A/C Power - Lunchrooms | 2,222 | SF | 6 | \$826 |
| | Emergency Battery Packs - Auditorium and Aisle Lighting | 5 | EA | 6 | \$1,013 |
| | Emergency Battery Packs - Corridors and Stairs | 6 | EA | 6 | \$1,215 |
| | Emergency Battery Packs - Gym | 2 | EA | 6 | \$405 |
| | Emergency Battery Packs - Lunchrooms | 1 | EA | 6 | \$203 |
| | Exit Signs - Auditorium | 12 | EA | 2 | \$6,546 |
| | Exit Signs - Corridors and Stairs | 10 | EA | 2 | \$5,455 |
| | Exit Signs - Corridors and Stairs | 7 | EA | 7 | \$0 |
| | Exit Signs - Gym | 2 | EA | 2 | \$1,157 |
| | Exit Signs - Lunchroom | 4 | EA | 2 | \$2,182 |
| | Security System - CCTV | 80,395 | SF | 4 | \$287,412 |
| | Security System - Intrusion Detection | 80,395 | SF | 6 | \$20,694 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 7 | \$0 |
| | Main Electrical Service - 1200 A 120/208/3PH | 1 | EA | 6 | \$5,078 |
| | PA System | 80,395 | SF | 6 | \$26,442 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 6 | \$299 |
| | Lighting and Power Panels - 100 A | 12 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 1 | EA | 4 | \$6,578 |
| | Lighting and Power Panels - Above 100 A | 6 | EA | 7 | \$0 |
| | Main Distribution Panels - 400 - 600 amp | 2 | EA | 7 | \$0 |

Electrical System Subtotal: \$373,642

Building: Main
Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 80,395 | SF | 6 | \$28,741 |
| | Fire Alarm_System | 80,395 | SF | 6 | \$39,088 |

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------|-------------|----------|------|------|-----------------|
| Safty System Subtotal: | | | | | \$74,235 |

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|---|----------|------|------|-----------|
| Air Handling Systems | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm | 1 | EA | 5 | \$24,083 |
| | Air Handling Unit- Built Up-Multi Zone-Double Delivery- Steam Coils - 45001 - 60000 cfm | 1 | EA | 5 | \$238,245 |
| | Air Intake | 2 | EA | 7 | \$0 |
| | Auxiliaries - 4000 - 8000 cfm | 1 | EA | 4 | \$25,511 |
| | Auxiliaries - 45001 - 60000 cfm | 2 | EA | 5 | \$45,732 |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 100 | LF | 7 | \$0 |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | 80 | LF | 7 | \$0 |
| | Zone Dampers | 52 | EA | 5 | \$99,504 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Non Condensing Steam Boiler - Greater than 200 HP | 2 | EA | 6 | \$4,093 |
| | Chemical Feed System | 1 | EA | 6 | \$1,078 |
| | Combustion Dampers | 2 | EA | 6 | \$818 |
| | Condensate Pump | 1 | EA | 6 | \$2,021 |
| | Feed Water Pumps and Tank | 1 | EA | 6 | \$2,545 |
| | Non Condensing- Cast Iron- Force Draft- Steam Boiler - Greater than 200 HP | 2 | EA | 6 | \$4,093 |
| | Piping - Condensate Pipe- Steel | 300 | LF | 5 | \$3,659 |
| | Piping - Steam Pipe- Steel | 300 | LF | 5 | \$4,226 |
| | Steam Traps | 35 | EA | 5 | \$46,021 |
| Gas Booster | | | | | |
| | Gas Booster | 2 | EA | 6 | \$998 |
| Heating Devices | | | | | |
| | Fin Tube - Electric | 20 | LF | 6 | \$189 |
| | Unit Heater - Gas | 1 | EA | 6 | \$278 |
| | Wall Heater - Electric | 12 | EA | 5 | \$6,439 |
| Temperature Control | | | | | |
| | Pneumatic System | 80,395 | SF | 5 | \$277,065 |
| | Thermostats - Pneumatic | 52 | EA | 6 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | 1 | EA | 6 | \$592 |

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|---------|
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 6 | \$1,185 |

Mechanical System Subtotal: \$788,375

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--|----------|------|------|-------|
| Hot Water | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | 1 | EA | 6 | \$310 |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | 1 | EA | 6 | \$678 |

| | | | | | |
|---------------|--|--------|----|---|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 80,395 | SF | 6 | \$16,095 |
| | Domestic Piping-Cold Water Horizontal Lines | 80,395 | SF | 6 | \$19,544 |
| | Domestic Piping-Cold Water Risers | 80,395 | SF | 6 | \$14,945 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 80,395 | SF | 6 | \$12,646 |
| | Domestic Piping-Hot Water Horizontal Lines | 80,395 | SF | 6 | \$14,945 |
| | Domestic Piping-Hot Water Return Lines | 80,395 | SF | 6 | \$11,496 |
| | Domestic Piping-Hot Water Return Risers | 80,395 | SF | 6 | \$11,496 |
| | Sanitary Piping | 80,395 | SF | 6 | \$73,578 |
| | Storm Piping | 80,395 | SF | 6 | \$70,129 |
| | Vent Piping | 80,395 | SF | 6 | \$54,033 |

| | | | | | |
|--------------|---------------------------------------|---|----|---|---------|
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | 1 | EA | 6 | \$1,446 |
| | Pumps - Ejector-Simplex | 1 | EA | 6 | \$745 |

Plumbing System Subtotal: \$302,088

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------|------------------|----------|------|------|---------|
| Art Room (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 10 | LF | 6 | \$253 |
| | Ceiling - Lay-in | 1,002 | SF | 6 | \$3,009 |
| | Chalk Board | 35 | LF | 6 | \$781 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------|-----------------------------|----------|------|------|---------|
| Art Room (1 room) | | | | | |
| | Doors - Transom Window | 8 | SF | 6 | \$135 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 1,002 | SF | 6 | \$7,064 |
| | Lighting - Lay-in | 14 | EA | 6 | \$1,666 |
| | Marker Board | 16 | LF | 6 | \$343 |
| | Storage/ Closet | 200 | SF | 6 | \$1,450 |
| | Walls - Plaster/Drywall | 1,222 | SF | 6 | \$3,373 |
| Computer Lab (2 rooms) | | | | | |
| | AC Units | 2 | EA | 5 | \$3,652 |
| | AC Units | 2 | EA | 6 | \$991 |
| | Casework | 18 | LF | 6 | \$455 |
| | Ceiling - Lay-in | 1,419 | SF | 6 | \$4,261 |
| | Charging Station | 1 | EA | 6 | \$485 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 608 | SF | 6 | \$609 |
| | Floor - Wood | 811 | SF | 6 | \$5,717 |
| | Lighting - Lay-in | 12 | EA | 6 | \$1,428 |
| | Lighting - Lay-in | 14 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 7 | \$0 |
| | Storage/ Closet | 5 | SF | 6 | \$36 |
| | Walls - Plaster/Drywall | 2,091 | SF | 6 | \$5,771 |
| | Wireless System | 1 | EA | 6 | \$372 |
| Kindergarten (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 21 | LF | 6 | \$530 |
| | Ceiling - Lay-in | 1,005 | SF | 6 | \$3,018 |
| | Doors - Transom Window | 8 | SF | 6 | \$135 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 1,005 | SF | 6 | \$7,085 |
| | Lighting - Lay-in | 14 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 2 | EA | 7 | \$0 |
| | Marker Board | 16 | LF | 7 | \$0 |
| | Storage/ Closet | 5 | SF | 6 | \$36 |
| | Walls - Plaster/Drywall | 1,695 | SF | 6 | \$4,678 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---|-----------------------------|----------|------|------|-----------|
| Physical Education Room (1 room) | | | | | |
| | Ceiling - Plaster/Drywall | 809 | SF | 6 | \$2,800 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 809 | SF | 6 | \$5,703 |
| | Lighting - Pendent/Surface | 13 | EA | 7 | \$0 |
| | Storage/ Closet | 156 | SF | 6 | \$1,131 |
| | Walls - Plaster/Drywall | 1,031 | SF | 5 | \$7,814 |
| Pre School (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 10 | LF | 6 | \$253 |
| | Ceiling - Lay-in | 916 | SF | 6 | \$2,751 |
| | Ceiling - Plaster/Drywall | 89 | SF | 6 | \$308 |
| | Chalk Board | 10 | LF | 4 | \$918 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 954 | SF | 6 | \$6,726 |
| | Lighting - Pendent/Surface | 15 | EA | 7 | \$0 |
| | Storage/ Closet | 104 | SF | 6 | \$754 |
| | Walls - Plaster/Drywall | 1,333 | SF | 6 | \$3,679 |
| | Work Sink | 2 | EA | 6 | \$758 |
| Regular Classroom (25 rooms) | | | | | |
| | AC Units | 1 | EA | 4 | \$6,086 |
| | AC Units | 26 | EA | 6 | \$12,885 |
| | Casework | 194 | LF | 6 | \$4,899 |
| | Ceiling - Lay-in | 20,998 | SF | 6 | \$63,057 |
| | Ceiling - Plaster/Drywall | 728 | SF | 5 | \$6,673 |
| | Ceiling - Plaster/Drywall | 385 | SF | 6 | \$1,332 |
| | Chalk Board | 157 | LF | 4 | \$14,414 |
| | Chalk Board | 36 | LF | 6 | \$803 |
| | Doors - Side-lite | 16 | SF | 6 | \$267 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Doors - Transom Window | 144 | SF | 6 | \$2,438 |
| | Doors - Wood Doors inclu hw | 27 | EA | 6 | \$8,127 |
| | Floor - Carpet | 963 | SF | 6 | \$2,052 |
| | Floor - Tile/Sheet | 1,831 | SF | 6 | \$1,833 |
| | Floor - Wood | 19,317 | SF | 6 | \$136,183 |
| | Lighting - Lay-in | 192 | EA | 6 | \$22,843 |
| | Lighting - Lay-in | 99 | EA | 7 | \$0 |

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------------|-----------------------------|----------|------|------|------------------|
| Regular Classroom (25 rooms) | | | | | |
| | Lighting - Pendent/Surface | 20 | EA | 7 | \$0 |
| | Marker Board | 243 | LF | 6 | \$5,205 |
| | Marker Board | 145 | LF | 7 | \$0 |
| | Storage/ Closet | 2,420 | SF | 6 | \$17,545 |
| | Walls - Masonry | 575 | SF | 6 | \$1,809 |
| | Walls - Plaster/Drywall | 34,687 | SF | 6 | \$95,733 |
| Science Classroom (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 60 | LF | 6 | \$1,515 |
| | Ceiling - Lay-in | 1,004 | SF | 6 | \$3,015 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 1,004 | SF | 6 | \$7,078 |
| | Lighting - Lay-in | 8 | EA | 7 | \$0 |
| | Walls - Masonry | 918 | SF | 6 | \$2,888 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Classrooms Subtotal: | | | | | \$514,376 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | AC Unit | 4 | EA | 5 | \$7,303 |
| | AC Unit | 2 | EA | 6 | \$991 |
| | Ceiling - Lay-in | 16 | SF | 5 | \$128 |
| | Ceiling - Lay-in | 2,482 | SF | 6 | \$7,453 |
| | Ceiling - Plaster/Drywall | 846 | SF | 6 | \$2,928 |
| | Doors - Side-lite | 40 | SF | 6 | \$669 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Transom Window | 48 | SF | 6 | \$813 |
| | Doors - Wood Doors inclu hw | 8 | EA | 6 | \$2,408 |
| | Floor - Carpet | 882 | SF | 6 | \$1,879 |
| | Floor - Concrete | 284 | SF | 6 | \$150 |
| | Floor - Tile/Sheet | 1,302 | SF | 6 | \$1,303 |
| | Floor - Wood | 876 | SF | 6 | \$6,176 |
| | Lighting - Lay-in | 26 | EA | 6 | \$3,093 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|--------------------------------------|----------|------|------|----------|
| Administrative Suites/Offices | | | | | |
| | Lighting - Lay-in | 16 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 2 | EA | 6 | \$248 |
| | Lighting - Pendent/Surface | 17 | EA | 7 | \$0 |
| | Power Distribution | 6 | EA | 6 | \$12,749 |
| | Power Distribution | 81 | EA | 7 | \$0 |
| | Storage/ Closet | 70 | SF | 6 | \$508 |
| | Walls - Masonry | 216 | SF | 6 | \$680 |
| | Walls - Plaster/Drywall | 6,658 | SF | 6 | \$18,375 |
| | Walls - Vinyl Coated Gypsum Panel | 710 | SF | 6 | \$1,960 |
| Auditorium & Theater | | | | | |
| | Balcony Seating | 120 | EA | 6 | \$20,870 |
| | Ceiling - Plaster/Drywall | 4,563 | SF | 6 | \$38,041 |
| | Doors - Wood Doors inclu hw | 10 | EA | 6 | \$3,010 |
| | Floor - Carpet | 1,958 | SF | 6 | \$4,172 |
| | Floor - Tile/Sheet | 648 | SF | 6 | \$649 |
| | Floor - Wood | 1,958 | SF | 6 | \$13,804 |
| | Lighting - Pendent/Surface | 11 | EA | 4 | \$5,947 |
| | Lighting - Wall Mounted | 7 | EA | 4 | \$2,752 |
| | Lighting - Wall Mounted | 2 | EA | 7 | \$0 |
| | Main Floor Seating | 288 | EA | 6 | \$50,088 |
| | Sound System | 1 | EA | 6 | \$10,721 |
| | Stage | 648 | SF | 6 | \$3,744 |
| | Stage Curtain | 2 | EA | 6 | \$0 |
| | Stage Lift | 1 | EA | 6 | \$6,510 |
| | Stage Lighting System | 1 | EA | 6 | \$8,077 |
| | Stage-Stairs - Wood | 20 | LF | 6 | \$235 |
| | Stairs - Wood | 31 | LF | 6 | \$364 |
| | Walls - Plaster/Drywall | 7,631 | SF | 6 | \$36,338 |
| Gymnasia | | | | | |
| | Ceiling - Plaster/Drywall | 3,839 | SF | 6 | \$21,191 |
| | Doors - Transom Window | 24 | SF | 6 | \$406 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Wood | 3,839 | SF | 6 | \$27,065 |
| | Lighting - Metal Halide/Sodium Vapor | 13 | EA | 6 | \$1,738 |
| | Walls - Plaster/Drywall | 4,952 | SF | 6 | \$13,667 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------------|----------|------|------|----------|
| Lunch & Multipurpose Room | | | | | |
| | Ceiling - Plaster/Drywall | 2,222 | SF | 6 | \$7,689 |
| | Floor - Concrete Epoxy/ Painted | 2,222 | SF | 6 | \$1,176 |
| | Lighting - Pendent/Surface | 10 | EA | 6 | \$1,239 |
| | Storage/ Closet | 164 | SF | 6 | \$1,189 |
| | Walls - Vinyl Coated Gypsum Panel | 3,366 | SF | 6 | \$9,290 |
| MDF_IDF | | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Finishes | 138 | SF | 6 | \$985 |
| | Ventilation and Cooling | 1 | EA | 6 | \$1,855 |
| Mechanical/ Service Rooms | | | | | |
| | Air Intake Plenums | 700 | SF | 6 | \$4,334 |
| | Boiler Room | 1,440 | SF | 6 | \$10,317 |
| | Coal Room | 482 | SF | 6 | \$3,453 |
| | Interior Stairs | 18 | LF | 6 | \$162 |
| | Janitor's Closet | 90 | SF | 6 | \$645 |
| | Mechanical/ Service Rooms | 2,205 | SF | 6 | \$15,797 |
| | Storage Room | 647 | SF | 5 | \$10,436 |
| | Storage Room | 1,137 | SF | 6 | \$8,146 |
| Restroom | | | | | |
| | Accessories | 2,821 | SF | 6 | \$26,019 |
| | Ceiling - Exposed | 18 | SF | 6 | \$27 |
| | Ceiling - Lay-in | 534 | SF | 6 | \$1,604 |
| | Ceiling - Plaster/Drywall | 2,269 | SF | 6 | \$7,852 |
| | Doors - Wood Doors inclu hw | 36 | EA | 6 | \$10,836 |
| | Floor - Concrete | 109 | SF | 6 | \$58 |
| | Floor - Tile Ceramic/ Porcelain | 2,073 | SF | 6 | \$4,387 |
| | Floor - Tile/Sheet | 470 | SF | 6 | \$470 |
| | Floor Drain | 8 | EA | 6 | \$8,473 |
| | Hand Dryer | 14 | EA | 6 | \$3,221 |
| | Lavatory | 14 | EA | 6 | \$4,474 |
| | Lighting - Lay-in | 4 | EA | 6 | \$476 |
| | Lighting - Lay-in | 1 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 4 | \$541 |
| | Lighting - Pendent/Surface | 23 | EA | 6 | \$2,850 |
| | Lighting - Pendent/Surface | 17 | EA | 7 | \$0 |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------|----------|------|------|----------|
| Restroom | | | | | |
| | Partitions | 36 | EA | 6 | \$10,689 |
| | Urinals | 19 | EA | 6 | \$6,384 |
| | Walls - Concrete Block | 1,613 | SF | 6 | \$4,729 |
| | Walls - Masonry | 162 | SF | 6 | \$510 |
| | Walls - Plaster/Drywall | 7,027 | SF | 6 | \$19,394 |
| | Walls - Structural Glazed Tile | 2,937 | SF | 6 | \$9,240 |
| | Water Closet | 39 | EA | 6 | \$13,103 |

Rooms (Other Than Classrooms) Subtotal:

\$553,852

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 9,310 | SF | 6 | \$27,958 |
| | Ceiling - Plaster/Drywall | 2,379 | SF | 6 | \$14,731 |
| | Doors - Side-lite | 90 | EA | 6 | \$1,505 |
| | Doors - Transom Window | 84 | EA | 6 | \$1,422 |
| | Doors - Wood Doors include hw | 19 | EA | 6 | \$5,719 |
| | Drinking Fountains - Single Fountain | 7 | EA | 6 | \$1,930 |
| | Floor - Asphalt Floor | 6,460 | SF | 6 | \$9,792 |
| | Floor - Concrete | 261 | SF | 6 | \$138 |
| | Floor - Concrete Epoxy/ Painted | 4,660 | SF | 6 | \$2,266 |
| | Floor - Tile Ceramic/ Porcelain | 260 | SF | 6 | \$725 |
| | Floor - Wood | 150 | SF | 6 | \$1,057 |
| | Lighting - Lay-in | 56 | EA | 6 | \$6,663 |
| | Lighting - Lay-in | 30 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 16 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 1 | EA | 4 | \$393 |
| | Stairs - Concrete Stairs | 34 | LF | 6 | \$282 |
| | Walls - Masonry | 345 | SF | 6 | \$1,085 |
| | Walls - Plaster/Drywall | 14,502 | SF | 6 | \$64,785 |
| | Walls - Structural Glazed Tile | 1,018 | SF | 6 | \$3,203 |
| | Walls - Vinyl Coated Gypsum Panel | 3,133 | SF | 6 | \$8,647 |
| Safety | | | | | |
| | Camera Viewing Station | 1 | EA | 5 | \$2,935 |

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|----------------------------|----------|------|------|----------|
| Safety | Security Cameras | 1 | EA | 4 | \$1,326 |
| Stairs | Ceiling - Lay-in | 832 | SF | 6 | \$2,498 |
| | Ceiling - Plaster/Drywall | 854 | SF | 6 | \$6,253 |
| | Floor - Asphalt | 1,162 | SF | 6 | \$9,006 |
| | Handrails | 420 | LF | 6 | \$3,640 |
| | Lighting - Pendent/Surface | 6 | EA | 6 | \$743 |
| | Lighting - Pendent/Surface | 8 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 2 | EA | 4 | \$786 |
| | Stairs - Asphalt | 30 | LF | 6 | \$278 |
| | Stairs - Concrete | 150 | LF | 6 | \$1,244 |
| | Walls - Plaster/Drywall | 7,919 | SF | 6 | \$21,856 |

Building Interior Subtotal:

\$202,866

Total Building Cost

\$4,055,442

Building: Addition

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|---------|
| Entrance | Exterior Doors - Exterior Steel Door | 3 | EA | 6 | \$1,442 |
| | Exterior Doors - Transom Lite | 4 | EA | 7 | \$0 |
| | Exterior Stairs - Concrete | 10 | LF | 6 | \$818 |
| | Exterior Stairs - Concrete | 30 | LF | 7 | \$0 |
| Foundation | Foundation - Concrete | 205 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 18,556 | SF | 7 | \$0 |
| Lighting | Exterior Lighting - Parapet or Roof Mounted | 3 | EA | 6 | \$1,610 |
| Roof System | Coping - Clay Tile | 30 | LF | 5 | \$2,505 |
| | Coping - Clay Tile | 125 | LF | 6 | \$4,015 |
| | Coping - Stone | 122 | LF | 6 | \$3,918 |

Building: Addition

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|---|----------|------|------|------------------|
| Roof System | | | | | |
| | Downspouts - Interior Downspouts | 128 | LF | 6 | \$4,254 |
| | Parapet - 16" - 30" Height | 194 | LF | 6 | \$7,751 |
| | Parapet - Parapet > 30" | 83 | LF | 6 | \$5,305 |
| | Roof - Modified Bitumen | 4,715 | SF | 6 | \$44,365 |
| | Roof Structure - Steel with Clay Tile Arch | 4,715 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cornice - Cast Stone | 122 | LF | 6 | \$4,231 |
| | Exterior Walls - Brick | 16,601 | SF | 6 | \$111,575 |
| | Exterior Walls - Prefabricated Metal Panel Wall | 220 | SF | 6 | \$1,249 |
| | Exterior Walls - Stone-Cast | 992 | SF | 6 | \$6,667 |
| Windows | | | | | |
| | Guard - Guards perforated | 280 | SF | 6 | \$3,576 |
| | Lintels - Steel | 95 | LF | 7 | \$0 |
| | Lintels - Stone | 225 | LF | 7 | \$0 |
| | Windows - Decorative | 20 | SF | 6 | \$149 |
| | Windows - Sash Aluminum Double-pane | 2,600 | SF | 5 | \$140,057 |
| | Windows - Sash Aluminum Double-pane | 700 | SF | 6 | \$5,225 |
| Building Exterior Subtotal: | | | | | \$348,712 |

Building: Addition

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Emergency A/C Power - Corridors and Stairs | 6,955 | SF | 6 | \$2,089 |
| | Emergency Battery Packs - Corridors and Stairs | 1 | EA | 6 | \$203 |
| | Exit Signs - Corridors and Stairs | 4 | EA | 2 | \$2,182 |
| | Security System - Intrusion Detection | 18,856 | SF | 6 | \$4,854 |
| Main Service | | | | | |
| | PA System | 18,856 | SF | 6 | \$6,202 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 2 | EA | 7 | \$0 |

Building: Addition

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|-------------|----------|------|------|-----------------|
| Electrical System Subtotal: | | | | | \$15,528 |

Building: Addition

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------|--------------------------|----------|------|------|-----------------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 18,856 | SF | 6 | \$6,741 |
| | Fire Alarm_System | 18,856 | SF | 6 | \$9,168 |
| Safty System Subtotal: | | | | | \$15,909 |

Building: Addition

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|---|----------|------|------|------------------|
| Air Conditioning | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 1 | EA | 4 | \$11,133 |
| Air Handling Systems | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm | 1 | EA | 6 | \$5,788 |
| | Air Intake | 1 | EA | 7 | \$0 |
| | Auxiliaries - 15001 - 25000 cfm | 1 | EA | 6 | \$5,788 |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 100 | LF | 7 | \$0 |
| Boiler Systems | | | | | |
| | Piping - Condensate Pipe- Steel | 180 | LF | 6 | \$340 |
| | Piping - Steam Pipe- Steel | 180 | LF | 6 | \$340 |
| | Steam Traps | 32 | EA | 5 | \$42,077 |
| Heating Devices | | | | | |
| | Radiators - Steam | 27 | EA | 5 | \$45,234 |
| | Wall Heater - Electric | 4 | EA | 5 | \$2,146 |
| Temperature Control | | | | | |
| | Pneumatic System | 18,856 | SF | 5 | \$64,983 |
| | Thermostats - Pneumatic | 1 | EA | 6 | \$0 |
| Mechanical System Subtotal: | | | | | \$177,828 |

Building: Addition

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------|---|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 18,856 | SF | 6 | \$4,584 |
| | Domestic Piping-Hot Water Horizontal Lines | 18,856 | SF | 6 | \$3,505 |
| | Domestic Piping-Hot Water Return Lines | 18,856 | SF | 6 | \$2,696 |
| | Sanitary Piping | 18,856 | SF | 6 | \$17,257 |
| | Storm Piping | 18,856 | SF | 6 | \$16,448 |
| | Vent Piping | 18,856 | SF | 6 | \$12,673 |
| Pumps | | | | | |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |

Plumbing System Subtotal: \$57,909

Building: Addition

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|-----------------------------|----------|------|------|----------|
| Kindergarten (1 room) | | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | Ceiling - Lay-in | 615 | SF | 6 | \$1,847 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 615 | SF | 6 | \$616 |
| | Lighting - Lay-in | 12 | EA | 7 | \$0 |
| | Marker Board | 18 | LF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,110 | SF | 6 | \$3,063 |
| Regular Classroom (8 rooms) | | | | | |
| | AC Units | 4 | EA | 5 | \$7,303 |
| | AC Units | 5 | EA | 6 | \$2,478 |
| | Casework | 118 | LF | 6 | \$2,980 |
| | Ceiling - Lay-in | 5,840 | SF | 6 | \$17,538 |
| | Chalk Board | 8 | LF | 4 | \$734 |
| | Doors - Transom Window | 112 | SF | 6 | \$1,896 |
| | Doors - Wood Doors inclu hw | 15 | EA | 6 | \$4,515 |
| | Floor - Carpet | 369 | SF | 6 | \$786 |
| | Floor - Tile/Sheet | 791 | SF | 6 | \$792 |
| | Floor - Wood | 4,680 | SF | 6 | \$32,994 |
| | Lighting - Lay-in | 62 | EA | 6 | \$7,377 |
| | Lighting - Lay-in | 42 | EA | 7 | \$0 |
| | Marker Board | 78 | LF | 6 | \$1,671 |

Building: Addition

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|-----------------------------|----------|------|------|----------|
| Regular Classroom (8 rooms) | | | | | |
| | Marker Board | 40 | LF | 7 | \$0 |
| | Storage/ Closet | 175 | SF | 6 | \$1,269 |
| | Walls - Plaster/Drywall | 8,655 | SF | 6 | \$23,887 |
| Science Classroom (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Casework | 40 | LF | 6 | \$1,010 |
| | Ceiling - Lay-in | 785 | SF | 6 | \$2,357 |
| | Doors - Transom Window | 16 | SF | 6 | \$271 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Wood | 785 | SF | 6 | \$5,534 |
| | Lighting - Lay-in | 14 | EA | 6 | \$1,666 |
| | Storage/ Closet | 40 | SF | 6 | \$290 |
| | Walls - Plaster/Drywall | 1,481 | SF | 6 | \$4,087 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Special Program (1 room) | | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Ceiling - Lay-in | 420 | SF | 6 | \$1,261 |
| | Chalk Board | 12 | LF | 6 | \$268 |
| | Doors - Transom Window | 8 | SF | 6 | \$135 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 420 | SF | 6 | \$2,961 |
| | Lighting - Lay-in | 6 | EA | 6 | \$714 |
| | Marker Board | 16 | LF | 6 | \$343 |
| | Walls - Plaster/Drywall | 902 | SF | 6 | \$2,489 |

Classrooms Subtotal:

\$139,532

Building: Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Ceiling - Plaster/Drywall | 670 | SF | 6 | \$2,319 |
| | Doors - Side-lite | 20 | SF | 6 | \$334 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Transom Window | 5 | SF | 6 | \$85 |

Building: Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | Floor - Tile/Sheet | 20 | SF | 5 | \$115 |
| | Floor - Tile/Sheet | 472 | SF | 6 | \$472 |
| | Floor - Wood | 160 | SF | 6 | \$1,128 |
| | Lighting - Pendent/Surface | 4 | EA | 4 | \$2,163 |
| | Power Distribution | 8 | EA | 7 | \$0 |
| | Walls - Masonry | 1,158 | SF | 6 | \$3,643 |
| | Work Slnk | 1 | EA | 6 | \$508 |
| Lunch & Multipurpose Room | | | | | |
| | AC Unit | 4 | EA | 6 | \$1,982 |
| | Ceiling - Plaster/Drywall | 1,606 | SF | 6 | \$5,558 |
| | Doors - Wood Doors inclu hw | 3 | EA | 6 | \$903 |
| | Floor - Tile/Sheet | 1,606 | SF | 6 | \$1,608 |
| | Lighting - Pendent/Surface | 12 | EA | 7 | \$0 |
| | Serving Line | 6 | LF | 6 | \$357 |
| | Walls - Vinyl Coated Gypsum Panel | 1,925 | SF | 6 | \$5,313 |
| Mechanical/ Service Rooms | | | | | |
| | Air Intake Plenums | 25 | SF | 6 | \$155 |
| | Mechanical/ Service Rooms | 397 | SF | 6 | \$2,844 |

Rooms (Other Than Classrooms) Subtotal:

\$30,584

Building: Addition

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 4,860 | SF | 6 | \$14,595 |
| | Ceiling - Plaster/Drywall | 1,685 | SF | 6 | \$10,433 |
| | Doors - Side-lite | 5 | EA | 6 | \$84 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Doors - Transom Window | 22 | EA | 6 | \$372 |
| | Doors - Wood Doors include hw | 3 | EA | 6 | \$903 |
| | Drinking Fountains - Double Fountain | 2 | EA | 6 | \$672 |
| | Drinking Fountains - Single Fountain | 2 | EA | 6 | \$551 |
| | Floor - Concrete Epoxy/ Painted | 1,220 | SF | 6 | \$593 |
| | Floor - Terrazzo | 1,300 | SF | 6 | \$10,912 |
| | Floor - Tile/Sheet | 3,204 | SF | 6 | \$1,741 |

Building: Addition

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------|--|----------|------|------|----------|
| Corridor | | | | | |
| | Floor - Weight/ Fitness Room Floor Matting | 700 | SF | 6 | \$1,512 |
| | Lighting - Lay-in | 36 | EA | 6 | \$4,283 |
| | Lighting - Lay-in | 26 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 9 | EA | 7 | \$0 |
| | Stairs - Concrete Stairs | 1 | LF | 6 | \$8 |
| | Walls - Concrete Block | 1,688 | SF | 6 | \$4,948 |
| | Walls - Plaster/Drywall | 10,479 | SF | 6 | \$46,453 |
| | Walls - Structural Glazed Tile | 860 | SF | 6 | \$2,706 |
| | Walls - Vinyl Coated Gypsum Panel | 1,890 | SF | 6 | \$5,216 |
| Stairs | | | | | |
| | Ceiling - Exposed | 416 | SF | 6 | \$619 |
| | Ceiling - Plaster/Drywall | 342 | SF | 6 | \$2,504 |
| | Floor - Terrazzo | 531 | SF | 6 | \$4,457 |
| | Handrails | 160 | LF | 6 | \$1,387 |
| | Lighting - Pendent/Surface | 6 | EA | 7 | \$0 |
| | Stairs - Concrete | 75 | LF | 6 | \$622 |
| | Walls - Plaster/Drywall | 3,561 | SF | 6 | \$9,828 |
| Vertical Conveyance | | | | | |
| | Elevator - Hydraulic Elevator | 1 | EA | 6 | \$19,238 |

Building Interior Subtotal:

\$145,240

Total Building Cost

\$931,242

Building: Linked Addition

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--------------------------------------|----------|------|------|---------|
| Entrance | | | | | |
| | Entrance Control - Audio | 3 | EA | 6 | \$1,491 |
| | Exterior Doors - Exterior Steel Door | 7 | EA | 6 | \$3,364 |
| Foundation | | | | | |
| | Foundation - Concrete | 650 | LF | 7 | \$0 |
| | Superstructure - Slab on Grade | 18,200 | SF | 7 | \$0 |

Building: Linked Addition

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|-----------|
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 1 | EA | 5 | \$427 |
| | Exterior Lighting - Wall Mounted | 5 | EA | 6 | \$1,444 |
| Roof System | | | | | |
| | Chimney - Metal Flue | 30 | LF | 6 | \$4,744 |
| | Coping - Metal | 30 | LF | 7 | \$0 |
| | Downspouts - Exterior Downspouts | 645 | LF | 6 | \$21,435 |
| | Downspouts - Interior Downspouts | 15 | LF | 6 | \$498 |
| | Parapet - 16" - 30" Height | 30 | LF | 6 | \$1,199 |
| | Roof - EPDM/ Synthetic Rubber | 916 | SF | 6 | \$7,754 |
| | Roof - Metal | 20,741 | SF | 6 | \$277,911 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 21,657 | SF | 7 | \$0 |
| Walls | | | | | |
| | Canopy - Metal | 120 | SF | 6 | \$2,577 |
| | Exterior Walls - Brick | 4,985 | SF | 7 | \$0 |
| | Exterior Walls - Prefabricated Metal Panel Wall | 1,300 | SF | 6 | \$7,380 |
| | Exterior Walls - Stone-Cast | 175 | SF | 7 | \$0 |
| | Exterior Walls - Stone-Cut | 165 | SF | 7 | \$0 |
| Windows | | | | | |
| | Guard - Guards perforated | 2,000 | SF | 6 | \$25,540 |
| | Lintels - Steel | 430 | LF | 7 | \$0 |
| | Windows - Louver | 50 | SF | 7 | \$0 |
| | Windows - Sash Aluminum Double-pane | 2,000 | SF | 6 | \$14,929 |

Building Exterior Subtotal:

\$370,695

Building: Linked Addition

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------|--|----------|------|------|---------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 2,855 | SF | 6 | \$857 |
| | Exit Signs - Corridors and Stairs | 6 | EA | 2 | \$3,273 |
| | Security System - Intrusion Detection | 18,200 | SF | 6 | \$4,685 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |

Building: Linked Addition

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------------|---|----------|------|------|---------|
| Main Service | | | | | |
| | Main Electrical Service - 800 A and 120/208/3PH | 1 | EA | 6 | \$3,570 |
| | PA System | 18,200 | SF | 6 | \$5,986 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 6 | \$299 |
| | Lighting and Power Panels - Above 100 A | 4 | EA | 6 | \$1,988 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 6 | \$528 |

Electrical System Subtotal: \$24,515

Building: Linked Addition

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------|--------------------------|----------|------|------|---------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 18,200 | SF | 6 | \$6,507 |
| | Fire Alarm_System | 18,200 | SF | 6 | \$8,849 |
| Sprinkler System | | | | | |
| | Sprinkler Heads | 18,200 | SF | 6 | \$0 |
| | Sprinkler Piping | 18,200 | SF | 6 | \$3,383 |
| | Wet Sprinkler System | 18,200 | SF | 6 | \$4,685 |

Safty System Subtotal: \$23,423

Building: Linked Addition

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|--|----------|------|------|---------|
| Air Handling Systems | | | | | |
| | Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less than 6000 cfm | 1 | EA | 6 | \$3,350 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH | 2 | EA | 6 | \$4,093 |
| | Chemical Pot Feeder | 1 | EA | 6 | \$725 |
| | Combustion Dampers | 4 | EA | 6 | \$1,636 |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH | 2 | EA | 6 | \$1,996 |
| | Water Fill System | 1 | EA | 6 | \$1,168 |

Building: Linked Addition

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------------------------|---|----------|------|------|-----------------|
| Gas Booster | | | | | |
| | Gas Booster | 1 | EA | 6 | \$499 |
| Heating Devices | | | | | |
| | Cabinet Heaters - With Hot Water Coil | 8 | EA | 6 | \$2,835 |
| | Unit Heater - Hot Water | 2 | EA | 6 | \$558 |
| Mechanical Plumbing | | | | | |
| | Hot Water Pump - Less than 10 | 2 | EA | 6 | \$2,222 |
| | Hydronic Supply and Return - Copper | 300 | LF | 6 | \$15,740 |
| | Hydronic Supply and Return - Steel | 100 | LF | 6 | \$7,678 |
| Temperature Control | | | | | |
| | Electric Controls | 500 | SF | 6 | \$0 |
| | Electric Thermostat | 2 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water w/ DX Cooling Coil & w/ Self Contained Compressors | 13 | EA | 7 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 1 | EA | 6 | \$296 |
| Mechanical System Subtotal: | | | | | \$43,980 |

Building: Linked Addition

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---|----------|------|------|----------|
| Hot Water | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | 1 | EA | 6 | \$310 |
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 18,200 | SF | 6 | \$4,424 |
| | Domestic Piping-Hot Water Horizontal Lines | 18,200 | SF | 6 | \$3,383 |
| | Domestic Piping-Hot Water Return Lines | 18,200 | SF | 6 | \$2,603 |
| | Sanitary Piping | 18,200 | SF | 6 | \$16,657 |
| | Storm Piping | 18,200 | SF | 6 | \$15,876 |
| | Vent Piping | 18,200 | SF | 6 | \$12,232 |

Building: Linked Addition

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------------|-------------|----------|------|------|-----------------|
| Plumbing System Subtotal: | | | | | \$55,485 |

Building: Linked Addition

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------------------|-----------------------------|----------|------|------|------------------|
| Regular Classroom (12 rooms) | | | | | |
| | Casework | 260 | LF | 6 | \$6,566 |
| | Ceiling - Lay-in | 10,404 | SF | 6 | \$31,243 |
| | Chalk Board | 28 | LF | 4 | \$2,571 |
| | Doors - Steel Doors incl hw | 12 | EA | 6 | \$3,612 |
| | Floor - Tile/Sheet | 10,404 | SF | 6 | \$10,414 |
| | Lighting - Lay-in | 108 | EA | 6 | \$12,849 |
| | Marker Board | 158 | LF | 6 | \$3,385 |
| | Walls - Concrete Block | 7,451 | SF | 6 | \$21,843 |
| | Walls - Plaster/Drywall | 4,892 | SF | 6 | \$13,501 |
| Classrooms Subtotal: | | | | | \$105,984 |

Building: Linked Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------------------------|-----------------------------|----------|------|------|---------|
| Administrative Suites/Offices | | | | | |
| | Ceiling - Lay-in | 558 | SF | 6 | \$1,676 |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 558 | SF | 6 | \$559 |
| | Lighting - Lay-in | 7 | EA | 6 | \$833 |
| | Power Distribution | 14 | EA | 7 | \$0 |
| | Walls - Concrete Block | 555 | SF | 6 | \$1,627 |
| | Walls - Plaster/Drywall | 722 | SF | 6 | \$1,993 |
| Mechanical/ Service Rooms | | | | | |
| | Janitor's Closet | 30 | SF | 6 | \$215 |
| | Mechanical/ Service Rooms | 950 | SF | 6 | \$6,806 |
| | Storage Room | 60 | SF | 6 | \$430 |
| Restroom | | | | | |
| | Accessories | 1,024 | SF | 6 | \$9,445 |
| | Ceiling - Plaster/Drywall | 1,024 | SF | 6 | \$3,544 |

Building: Linked Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---------------------------------|----------|------|------|---------|
| Restroom | | | | | |
| | Doors - Steel Doors incl hw | 2 | EA | 6 | \$602 |
| | Floor - Concrete Epoxy/ Painted | 938 | SF | 6 | \$496 |
| | Floor - Tile/Sheet | 86 | SF | 6 | \$86 |
| | Floor Drain | 6 | EA | 6 | \$6,355 |
| | Hand Dryer | 4 | EA | 6 | \$920 |
| | Lavatory | 10 | EA | 6 | \$3,196 |
| | Lighting - Lay-in | 12 | EA | 6 | \$1,428 |
| | Partitions | 14 | EA | 6 | \$4,157 |
| | Urinals | 8 | EA | 6 | \$2,688 |
| | Walls - Concrete Block | 3,056 | SF | 6 | \$8,959 |
| | Water Closet | 16 | EA | 6 | \$5,376 |

Rooms (Other Than Classrooms) Subtotal: \$61,990

Building: Linked Addition

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 2,855 | SF | 6 | \$8,574 |
| | Doors - Steel Doors incl hw | 8 | EA | 6 | \$2,408 |
| | Drinking Fountains - Single Fountain | 2 | EA | 6 | \$551 |
| | Floor - Sport Flooring | 750 | SF | 6 | \$1,619 |
| | Floor - Tile Ceramic/ Porcelain | 150 | SF | 6 | \$418 |
| | Floor - Tile/Sheet | 1,955 | SF | 6 | \$1,062 |
| | Lighting - Lay-in | 22 | EA | 6 | \$2,617 |
| | Lighting - Lay-in | 8 | EA | 7 | \$0 |
| | Stairs - Concrete Stairs | 1 | LF | 6 | \$8 |
| | Walls - Concrete Block | 5,200 | SF | 6 | \$15,244 |
| | Walls - Concrete Block | 1,105 | SF | 7 | \$0 |
| | Walls - Masonry | 260 | SF | 7 | \$0 |

Building Interior Subtotal: \$32,503

Total Building Cost \$718,575

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|---------------------------------------|----------|------|------|----------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 2 | EA | 5 | \$5,140 |
| | Civil/ Drainage - Catch Basin | 5 | EA | 6 | \$5,469 |
| | Civil/ Drainage - Site Drain | 3 | EA | 6 | \$931 |
| | Civil/ Drainage - Site Manhole | 7 | EA | 6 | \$10,449 |
| Fencing | | | | | |
| | Fencing - Chain Link | 370 | LF | 6 | \$6,947 |
| | Fencing - Iron and Concrete Post | 200 | LF | 5 | \$24,361 |
| | Fencing - Iron and Concrete Post | 1,010 | LF | 6 | \$37,046 |
| | Fencing - New Standard Ornamental | 100 | LF | 6 | \$3,190 |
| | Fencing - Wood Fencing w/ Steel Frame | 140 | LF | 6 | \$1,836 |
| Landscape | | | | | |
| | Landscape - Grass | 21,130 | SF | 6 | \$17,525 |
| | Landscape - Hardscape- Concrete | 1,200 | SF | 5 | \$13,162 |
| | Landscape - Hardscape- Concrete | 3,100 | SF | 6 | \$16,003 |
| | Parkway trees | 35 | EA | 6 | \$23,102 |
| | Planting Beds/ Area | 640 | SF | 6 | \$1,052 |
| | Play Area - Asphalt/ Hardscape | 15,455 | SF | 6 | \$37,350 |
| | Play Area - Synthetic Turf Play Field | 8,700 | SF | 7 | \$0 |
| Parking Lot | | | | | |
| | Surface - Asphalt | 1,000 | SF | 4 | \$10,596 |
| | Surface - Asphalt | 250 | SF | 5 | \$1,476 |
| | Surface - Asphalt | 18,182 | SF | 6 | \$43,940 |
| | Surface - Concrete | 1,500 | SF | 5 | \$16,452 |
| | Surface - Concrete | 2,800 | SF | 6 | \$6,767 |
| Playground | | | | | |
| | Equipment - Combo 3-12 | 1 | EA | 6 | \$7,092 |
| | Equipment - Pre K 3-5 | 1 | EA | 6 | \$3,546 |
| | Surface - Poured Surface | 4,655 | SF | 6 | \$34,082 |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 5 | LF | 5 | \$289 |
| | Sidewalks - Internal Walks | 740 | LF | 6 | \$8,889 |
| | Sidewalks - Perimeter Sidewalks | 20,840 | SF | 6 | \$41,424 |
| Signage | | | | | |
| | Flag Pole - Flag Pole | 1 | EA | 7 | \$0 |
| | Marquee - Free Standing Back Lighted | 1 | EA | 6 | \$0 |

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|-------------|----------|------|------|------------------|
| Site Subtotal: | | | | | \$378,118 |

| | | | | | |
|------------------------|--|--|--|--|------------------|
| Total Site Cost | | | | | \$378,118 |
|------------------------|--|--|--|--|------------------|

| | | | | | |
|------------------------------------|--|--|--|--|--------------------|
| Campus Total ^{2 3} | | | | | \$6,083,376 |
|------------------------------------|--|--|--|--|--------------------|

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart-Board |
|-------------------------|-------------------|---------------|-------------|------------------------|-----------|---------------|--------------|----------------|--------------------|----------------------|-------------|-------------|-------------|-------------|
| Main | | | | | | | | | | | | | | |
| Art Room | Regular Classroom | 2nd Floor | 203 | 203 | 1,002 | 0 | 0 | 8 | 150 | 70 | 40 | Y | Y | N |
| Computer Lab | Computer Lab | 1st Floor | 103 | 103 | 811 | 1 | 25 | 50 | 144 | 72 | 40 | Y | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 204 | 204 | 608 | 2 | 32 | 108 | 150 | 70 | 40 | Y | N | N |
| Kindergarten | Kindergarten | 1st Floor | 110 | 110 | 1,005 | 1 | 1 | 6 | 216 | 108 | 40 | Y | N | Y |
| Physical Education Room | Gymnasium | Basement | B100 | B100 | 809 | 1 | 1 | 6 | 120 | 60 | 40 | Y | N | N |
| Pre School | Pre School | Basement | 001 | 001 | 850 | 1 | 1 | 6 | 120 | 60 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | Basement | 005 | 005 | 576 | 1 | 1 | 8 | 40 | 20 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | Basement | 006 | 006 | 483 | 1 | 1 | 6 | 60 | 30 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | Basement | 007 | 007 | 480 | 1 | 1 | 16 | 40 | 20 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | Basement | 008 | 008 | 728 | 1 | 1 | 6 | 40 | 20 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | Basement | 010 | 010 | 385 | 1 | 1 | 6 | 40 | 20 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 100 | 1,005 | 1 | 1 | 6 | 216 | 108 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 1,127 | 1 | 1 | 6 | 180 | 90 | 40 | Y | N | Y |
| Regular Classroom | Library | | 104 | 104 | 623 | 1 | 5 | 10 | 144 | 72 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 1,066 | 1 | 1 | 6 | 180 | 90 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 1,066 | 1 | 1 | 6 | 180 | 90 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 200 | 200 | 985 | 0 | 0 | 8 | 150 | 70 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 1,095 | 0 | 0 | 10 | 135 | 63 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 1,095 | 0 | 0 | 10 | 135 | 63 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | | 208 | 208 | 1,122 | 0 | 0 | 10 | 75 | 35 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 1,122 | 0 | 0 | 8 | 75 | 35 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 985 | 0 | 0 | 8 | 150 | 70 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 300 | 300 | 1,032 | 1 | 4 | 20 | 133 | 49 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | N/A | 457 | 0 | 4 | 16 | 54 | 22 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301A | N/A | 457 | 2 | 0 | 7 | 54 | 22 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 1,137 | 1 | 4 | 21 | 117 | 47 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 1,032 | 1 | 4 | 20 | 133 | 49 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 632 | 0 | 0 | 8 | 137 | 57 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 1,097 | 1 | 4 | 21 | 111 | 41 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 309 | 1,097 | 1 | 4 | 21 | 111 | 41 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | 310 | 1,032 | 1 | 4 | 20 | 133 | 49 | 40 | N | Y | Y |
| Science Classroom | Science Classroom | Basement | 003 | 003 | 1,004 | 1 | 1 | 12 | 120 | 60 | 40 | Y | N | N |

Addition

| | | | | | | | | | | | | | | |
|-------------------|-------------------|-----------|-----|-----|-----|---|----|----|-----|----|----|---|---|---|
| Kindergarten | Regular Classroom | 1st Floor | 104 | 104 | 615 | 0 | 10 | 32 | 120 | 32 | 40 | Y | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 791 | 1 | 6 | 12 | 144 | 72 | 40 | Y | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 791 | 1 | 6 | 12 | 144 | 72 | 40 | Y | N | Y |

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart-Board |
|-------------------|-------------------|---------------|-------------|------------------------|-----------|---------------|--------------|----------------|--------------------|----------------------|-------------|-------------|-------------|-------------|
| Addition | | | | | | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 791 | 1 | 6 | 12 | 144 | 72 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 205 | 205 | 771 | 1 | 0 | 10 | 150 | 70 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 771 | 0 | 0 | 8 | 150 | 70 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 207 | 207 | 771 | 0 | 0 | 18 | 150 | 70 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | N/A | 369 | 1 | 2 | 8 | 57 | 19 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 785 | 3 | 3 | 18 | 154 | 76 | 40 | N | Y | Y |
| Science Classroom | Science Classroom | 3rd Floor | 305 | 305 | 785 | 0 | 1 | 14 | 115 | 38 | 40 | N | Y | Y |
| Special Program | Regular Classroom | 3rd Floor | 306B | N/A | 420 | 1 | 0 | 8 | 57 | 19 | 40 | N | Y | N |

Linked Addition

| | | | | | | | | | | | | | | |
|-------------------|-------------------|-----------|-----|-----|-----|---|----|----|-----|----|----|---|---|---|
| Regular Classroom | Regular Classroom | 1st Floor | 400 | 400 | 867 | 5 | 1 | 16 | 99 | 50 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 401 | 401 | 867 | 5 | 1 | 16 | 99 | 50 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 402 | 402 | 867 | 5 | 1 | 16 | 99 | 50 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 403 | 403 | 867 | 5 | 1 | 16 | 99 | 50 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 404 | 404 | 867 | 5 | 1 | 16 | 99 | 50 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 405 | 104 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 406 | 107 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 407 | 103 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 408 | 106 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 409 | 102 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 410 | 105 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 411 | 101 | 867 | 1 | 10 | 20 | 120 | 60 | 40 | Y | N | N |