



Sep 10, 2024

**BRONZEVILLE HS**

**4934 S WABASH AVE, Chicago IL 60615.**

Dear **BRONZEVILLE HS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit [www.cdc.gov/lead](http://www.cdc.gov/lead).

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



**Sep 10, 2024**

**BRONZEVILLE HS**

**4934 S WABASH AVE, Chicago IL 60615.**

Estimadas familias de **BRONZEVILLE HS:**

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer  
Director de Salud y Seguridad Ambientales  
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-1-CAF-BF01	1st Floor Cafeteria, South Wall, Bottle Filler	Flush	02-FEB-2024	1.900	ug/L
51580	51580-1-CAF-BF01	1st Floor Cafeteria, South Wall, Bottle Filler	Flush	02-FEB-2024	1.930	ug/L
51580	51580-1-CAF-BF01	1st Floor Cafeteria, South Wall, Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-BF01	1st Floor Cafeteria, South Wall, Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-BF01	1st Floor Cafeteria, South Wall, Bottle Filler	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-W-HAL-F01	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F01	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F01	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F01	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F01	Across from 319	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F06	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F06	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F05	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F05	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F05	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F05	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F06	Across from 102	Flush180	09-MAY-19	1.020	ug/L
51580	51580-1-N-HAL-F06	Across from 102	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F05	Across from 102	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-N-HAL-F06	Across from 102	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F09	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F09	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F09	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F10	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F10	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F10	Across from 148	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F09	Across from 148	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F10	Across from 148	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-N-HAL-F05	Across from 206, left (west)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-HAL-F05	Across from 206, left (west)	Flush180	09-MAY-19	1.320	ug/L
51580	51580-2-N-HAL-F05	Across from 206, left (west)	Flush180	09-MAY-19	1.040	ug/L
51580	51580-2-N-HAL-F05	Across from 206, left (west)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-HAL-F05	Across from 206, left (west)	Initial	09-MAY-19	1.210	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-2-N-HAL-F06	Across from 206, right (east)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-HAL-F06	Across from 206, right (east)	Flush180	09-MAY-19	1.130	ug/L
51580	51580-2-N-HAL-F06	Across from 206, right (east)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-HAL-F06	Across from 206, right (east)	Flush180	09-MAY-19	1.330	ug/L
51580	51580-2-N-HAL-F06	Across from 206, right (east)	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F03	Across from 213, left (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F03	Across from 213, left (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F03	Across from 213, left (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F03	Across from 213, left (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F03	Across from 213, left (south) fountain	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F04	Across from 213, right (north)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F04	Across from 213, right (north)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F04	Across from 213, right (north)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F04	Across from 213, right (north)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F04	Across from 213, right (north)	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F01	Across from 221, left fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F01	Across from 221, left fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F01	Across from 221, left fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F01	Across from 221, left fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F01	Across from 221, left fountain	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F02	Across from 221, right (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F02	Across from 221, right (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F02	Across from 221, right (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F02	Across from 221, right (south) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-W-HAL-F02	Across from 221, right (south) fountain	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F10	Across from 246	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F10	Across from 246	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F10	Across from 246	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F10	Across from 246	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F10	Across from 246	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F11	Across from 246, rightfountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F11	Across from 246, rightfountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F11	Across from 246, rightfountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F11	Across from 246, rightfountain	Initial	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F03	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F03	Across from 313	Flush180	09-MAY-19	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-3-W-HAL-F03	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F04	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F04	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F04	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F04	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F03	Across from 313	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F04	Across from 313	Initial	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F03	Across from 313	Initial	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F02	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F02	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F02	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F02	Across from 319	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-W-HAL-F02	Across from 319	Initial	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F08	Across from 346	Flush180	09-MAY-19	1.240	ug/L
51580	51580-3-E-HAL-F08	Across from 346	Flush180	09-MAY-19	1.020	ug/L
51580	51580-3-E-HAL-F08	Across from 346	Flush180	09-MAY-19	1.020	ug/L
51580	51580-3-E-HAL-F08	Across from 346	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F08	Across from 346	Initial	09-MAY-19	1.650	ug/L
51580	51580-3-E-HAL-F07	Across from 346, left (north)	Flush180	09-MAY-19	1.130	ug/L
51580	51580-3-E-HAL-F07	Across from 346, left (north)	Flush180	09-MAY-19	1.410	ug/L
51580	51580-3-E-HAL-F07	Across from 346, left (north)	Flush180	09-MAY-19	1.070	ug/L
51580	51580-3-E-HAL-F07	Across from 346, left (north)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F07	Across from 346, left (north)	Initial	09-MAY-19	1.680	ug/L
51580	51580-3-E-HAL-F05	Across from 354, north fountain (left)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F05	Across from 354, north fountain (left)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F05	Across from 354, north fountain (left)	Flush180	09-MAY-19	2.690	ug/L
51580	51580-3-E-HAL-F05	Across from 354, north fountain (left)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F05	Across from 354, north fountain (left)	Initial	09-MAY-19	1.010	ug/L
51580	51580-3-E-HAL-F06	Across from 354, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F06	Across from 354, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F06	Across from 354, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F06	Across from 354, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-3-E-HAL-F06	Across from 354, right fountain (south)	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-S-HAL-F07	Across from gymnasium	Flush180	09-MAY-19	1.860	ug/L
51580	51580-2-S-HAL-F07	Across from gymnasium	Flush180	09-MAY-19	2.060	ug/L
51580	51580-2-S-HAL-F07	Across from gymnasium	Flush180	09-MAY-19	1.880	ug/L
51580	51580-2-S-HAL-F07	Across from gymnasium	Flush180	09-MAY-19	1.950	ug/L
51580	51580-2-S-	Across from gymnasium	Initial	09-MAY-19	1.950	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F07					
51580	51580-1-E-HAL-F07	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F07	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F07	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F07	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F08	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F08	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F08	Across from room 154	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F08	Across from room 154	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-E-HAL-F07	Across from room 154	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-E-CAF-F01	Cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-CAF-F01	Cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-CAF-F01	Cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-CAF-F01	Cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-E-CAF-F01	Cafeteria, east wall	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-S-KIT-KS05	First floor kitchen, center island	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-S-KIT-KS05	First floor kitchen, center island	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-S-KIT-KS05	First floor kitchen, center island	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-S-KIT-KS05	First floor kitchen, center island	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-S-KIT-KS05	First floor kitchen, center island	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	15-APR-20	1.080	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Flush180	15-APR-20	1.680	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Initial	09-MAY-19	5.090	ug/L
51580	51580-1-N-KIT-KS06	First floor kitchen, south wall	Initial	15-APR-20	1.000	ug/L
51580	51580-1-W-HAL-F03	First floor, across from 113	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F03	First floor, across from 113	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F03	First floor, across from 113	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F03	First floor, across from 113	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F03	First floor, across from 113	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F04	First floor, across from 113, right (north) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-	First floor, across from 113, right	Flush180	09-MAY-19	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F04	(north) fountain				
51580	51580-1-W-HAL-F04	First floor, across from 113, right (north) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F04	First floor, across from 113, right (north) fountain	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F04	First floor, across from 113, right (north) fountain	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F01	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F01	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F01	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F01	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F02	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F02	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F02	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F02	First floor, across from 121	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F01	First floor, across from 121	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-W-HAL-F02	First floor, across from 121	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS03	First floor, kitchen, north wall, middle faucet second from right	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS03	First floor, kitchen, north wall, middle faucet second from right	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS03	First floor, kitchen, north wall, middle faucet second from right	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS03	First floor, kitchen, north wall, middle faucet second from right	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS03	First floor, kitchen, north wall, middle faucet second from right	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS01	First floor, kitchen, north wall, left faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS01	First floor, kitchen, north wall, left faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS01	First floor, kitchen, north wall, left faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS01	First floor, kitchen, north wall, left faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS01	First floor, kitchen, north wall, left faucet	Initial	09-MAY-19	1.250	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Flush180	15-APR-20	2.990	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Initial	09-MAY-19	5.070	ug/L
51580	51580-1-N-KIT-KS02	First floor, kitchen, north wall, middle faucet	Initial	15-APR-20	1.000	ug/L
51580	51580-1-N-KIT-KS04	Kitchen first floor, north wall, right faucet (east)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS04	Kitchen first floor, north wall, right faucet (east)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS04	Kitchen first floor, north wall, right faucet (east)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-1-N-KIT-KS04	Kitchen first floor, north wall, right faucet (east)	Flush180	09-MAY-19	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-1-N-KIT-KS04	Kitchen first floor, north wall, right faucet (east)	Initial	09-MAY-19	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush180	04-OCT-16	0.444	ppb
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush180	04-OCT-16	0.499	ppb
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush180	04-OCT-16	0.457	ppb
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush180	04-OCT-16	0.447	ppb
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Flush180	17-DEC-20	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Initial	04-OCT-16	0.513	ppb
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Initial	17-DEC-20	1.000	ug/L
51580	51580-1-CAF-F20	Main- 1st Floor Cafeteria, North Wall, Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush180	04-OCT-16	0.830	ppb
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush180	04-OCT-16	0.783	ppb
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush180	04-OCT-16	0.753	ppb
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Flush180	04-OCT-16	0.668	ppb
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Initial	04-OCT-16	0.447	ppb
51580	51580-1-CAF-F21	Main- 1st Floor Cafeteria, South Wall, Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush	02-FEB-2024	1.380	ug/L
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush	02-FEB-2024	1.260	ug/L
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush180	04-OCT-16	2.970	ppb
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush180	04-OCT-16	1.900	ppb
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush180	04-OCT-16	6.560	ppb
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Flush180	04-OCT-16	5.430	ppb
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Initial	04-OCT-16	6.390	ppb
51580	51580-1-KIT-KS17	Main- 1st Floor Kitchen, Center, Kettle Sink	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS18	Main- 1st Floor Kitchen, Center, Sink	Flush180	04-OCT-16	0.710	ppb
51580	51580-1-KIT-KS18	Main- 1st Floor Kitchen, Center, Sink	Flush180	04-OCT-16	1.000	ppb
51580	51580-1-KIT-KS18	Main- 1st Floor Kitchen, Center, Sink	Flush180	04-OCT-16	0.682	ppb
51580	51580-1-KIT-KS18	Main- 1st Floor Kitchen, Center, Sink	Flush180	04-OCT-16	0.467	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-1-KIT-KS18	Main- 1st Floor Kitchen, Center, Sink	Initial	04-OCT-16	1.000	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush180	04-OCT-16	0.617	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush180	04-OCT-16	0.631	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush180	04-OCT-16	0.715	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Flush180	04-OCT-16	0.930	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Initial	04-OCT-16	0.910	ppb
51580	51580-1-KIT-KS13	Main- 1st Floor Kitchen, North Double Basin, Left	Initial	02-FEB-2024	1.800	ug/L
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush180	04-OCT-16	1.110	ppb
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush180	04-OCT-16	1.080	ppb
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush180	04-OCT-16	3.200	ppb
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Flush180	04-OCT-16	1.470	ppb
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Initial	04-OCT-16	3.130	ppb
51580	51580-1-KIT-KS14	Main- 1st Floor Kitchen, North Double Basin, Right	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush180	04-OCT-16	0.598	ppb
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush180	04-OCT-16	0.615	ppb
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush180	04-OCT-16	0.623	ppb
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Flush180	04-OCT-16	0.608	ppb
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Initial	04-OCT-16	0.472	ppb
51580	51580-1-KIT-KS15	Main- 1st Floor Kitchen, South Double Basin, Left	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush180	04-OCT-16	0.652	ppb
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush180	04-OCT-16	0.620	ppb
51580	51580-1-KIT-	Main- 1st Floor Kitchen, South	Flush180	04-OCT-16	0.638	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	KS16	Double Basin, Right				
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Flush180	04-OCT-16	0.637	ppb
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Initial	04-OCT-16	0.620	ppb
51580	51580-1-KIT-KS16	Main- 1st Floor Kitchen, South Double Basin, Right	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush	02-FEB-2024	1.270	ug/L
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush	02-FEB-2024	1.260	ug/L
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush	02-FEB-2024	3.020	ug/L
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush	02-FEB-2024	3.400	ug/L
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush180	04-OCT-16	0.741	ppb
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush180	04-OCT-16	0.822	ppb
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush180	04-OCT-16	0.772	ppb
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Flush180	04-OCT-16	0.763	ppb
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Initial	04-OCT-16	1.010	ppb
51580	51580-1-KIT-KS19	Main- 1st Floor Kitchen, West Wall, Sink	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-KIT-KS14	Main- 2nd Floor Kitchen, Left Sink	Flush180	04-OCT-16	4.310	ppb
51580	51580-2-KIT-KS14	Main- 2nd Floor Kitchen, Left Sink	Flush180	04-OCT-16	4.040	ppb
51580	51580-2-KIT-KS14	Main- 2nd Floor Kitchen, Left Sink	Flush180	04-OCT-16	4.330	ppb
51580	51580-2-KIT-KS14	Main- 2nd Floor Kitchen, Left Sink	Flush180	04-OCT-16	3.670	ppb
51580	51580-2-KIT-KS14	Main- 2nd Floor Kitchen, Left Sink	Initial	04-OCT-16	5.670	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	04-OCT-16	3.950	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	04-OCT-16	4.420	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	04-OCT-16	3.530	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	04-OCT-16	4.220	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	8.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	12.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	13.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	8.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	11.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	12.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	11.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	07-DEC-16	13.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	09-MAR-17	2.850	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	09-MAR-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	09-MAR-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	09-MAR-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	25-JUL-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	25-JUL-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	25-JUL-17	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	KS15	Sink				
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Flush180	25-JUL-17	1.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Initial	04-OCT-16	16.500	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Initial	07-DEC-16	42.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Initial	07-DEC-16	42.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Initial	09-MAR-17	17.000	ppb
51580	51580-2-KIT-KS15	Main- 2nd Floor Kitchen, Right Sink	Initial	25-JUL-17	1.000	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush180	04-OCT-16	0.320	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush180	04-OCT-16	0.375	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush180	04-OCT-16	0.298	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Flush180	04-OCT-16	0.312	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Initial	04-OCT-16	0.316	ppb
51580	51580-1-HAL-F06	Main- Across From Room 106, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush180	04-OCT-16	0.318	ppb
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush180	04-OCT-16	0.448	ppb
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush180	04-OCT-16	0.527	ppb
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Flush180	04-OCT-16	0.560	ppb
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Initial	04-OCT-16	0.228	ppb
51580	51580-1-HAL-F05	Main- Across From Room 106, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	02-FEB-2024	1.130	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush180	04-OCT-16	0.566	ppb
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush180	04-OCT-16	0.539	ppb
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush180	04-OCT-16	0.523	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Flush180	04-OCT-16	0.511	ppb
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Initial	04-OCT-16	0.482	ppb
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Initial	02-FEB-2024	7.440	ug/L
51580	51580-1-HAL-F04	Main- Across From Room 113, Left Fountain	Initial	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush	02-FEB-2024	1.080	ug/L
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush180	04-OCT-16	0.478	ppb
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush180	04-OCT-16	0.672	ppb
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush180	04-OCT-16	0.651	ppb
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Flush180	04-OCT-16	0.580	ppb
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Initial	04-OCT-16	0.564	ppb
51580	51580-1-HAL-F03	Main- Across From Room 113, Right Fountain	Initial	02-FEB-2024	1.770	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	02-FEB-2024	2.090	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	02-FEB-2024	1.500	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	02-FEB-2024	1.630	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	02-FEB-2024	1.940	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush	27-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush180	04-OCT-16	0.536	ppb
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush180	04-OCT-16	0.548	ppb
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush180	04-OCT-16	0.537	ppb
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Flush180	04-OCT-16	0.494	ppb
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Initial	04-OCT-16	0.446	ppb
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Initial	02-FEB-2024	6.770	ug/L
51580	51580-1-HAL-F02	Main- Across From Room 121, Left Fountain	Initial	27-FEB-2024	1.370	ug/L
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush	02-FEB-2024	3.300	ug/L
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush	02-FEB-2024	2.310	ug/L
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush	02-FEB-2024	1.500	ug/L
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush	02-FEB-2024	1.630	ug/L
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush180	04-OCT-16	0.883	ppb
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush180	04-OCT-16	1.060	ppb
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush180	04-OCT-16	0.691	ppb
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Flush180	04-OCT-16	0.756	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Initial	04-OCT-16	0.794	ppb
51580	51580-1-HAL-F01	Main- Across From Room 121, Right Fountain	Initial	02-FEB-2024	3.490	ug/L
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush180	04-OCT-16	0.500	ppb
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush180	04-OCT-16	0.478	ppb
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush180	04-OCT-16	0.489	ppb
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Flush180	04-OCT-16	0.479	ppb
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Initial	04-OCT-16	0.450	ppb
51580	51580-1-HAL-F10	Main- Across From Room 146, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush180	04-OCT-16	0.720	ppb
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush180	04-OCT-16	0.817	ppb
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush180	04-OCT-16	0.840	ppb
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Flush180	04-OCT-16	1.160	ppb
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Initial	04-OCT-16	1.530	ppb
51580	51580-1-HAL-F09	Main- Across From Room 146, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush	02-FEB-2024	1.090	ug/L
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush	02-FEB-2024	1.200	ug/L
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush180	04-OCT-16	0.475	ppb
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush180	04-OCT-16	0.511	ppb
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush180	04-OCT-16	0.550	ppb
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Flush180	04-OCT-16	0.533	ppb
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Initial	04-OCT-16	0.458	ppb
51580	51580-1-HAL-F08	Main- Across From Room 154, Left Fountain	Initial	02-FEB-2024	2.460	ug/L
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush180	04-OCT-16	0.715	ppb
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush180	04-OCT-16	0.657	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F07	Right Fountain				
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush180	04-OCT-16	0.586	ppb
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Flush180	04-OCT-16	0.615	ppb
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Initial	04-OCT-16	0.697	ppb
51580	51580-1-HAL-F07	Main- Across From Room 154, Right Fountain	Initial	02-FEB-2024	1.190	ug/L
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush180	04-OCT-16	0.617	ppb
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush180	04-OCT-16	0.780	ppb
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush180	04-OCT-16	0.718	ppb
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Flush180	04-OCT-16	0.593	ppb
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Initial	04-OCT-16	0.339	ppb
51580	51580-2-HAL-F06	Main- Across From Room 206, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F05	Main- Across From Room 206, Right Fountain	Flush180	04-OCT-16	0.742	ppb
51580	51580-2-HAL-F05	Main- Across From Room 206, Right Fountain	Flush180	04-OCT-16	1.000	ppb
51580	51580-2-HAL-F05	Main- Across From Room 206, Right Fountain	Flush180	04-OCT-16	0.824	ppb
51580	51580-2-HAL-F05	Main- Across From Room 206, Right Fountain	Flush180	04-OCT-16	0.933	ppb
51580	51580-2-HAL-F05	Main- Across From Room 206, Right Fountain	Initial	04-OCT-16	0.844	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush180	04-OCT-16	0.705	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush180	04-OCT-16	0.753	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush180	04-OCT-16	0.631	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Flush180	04-OCT-16	0.829	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Initial	04-OCT-16	0.652	ppb
51580	51580-2-HAL-F04	Main- Across From Room 213, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-RBF01	Main- Across From Room 213, Retro Fit Bottle Filler, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-RBF01	Main- Across From Room 213, Retro Fit Bottle Filler, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-RBF01	Main- Across From Room 213, Retro Fit Bottle Filler, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-RBF01	Main- Across From Room 213, Retro Fit Bottle Filler, Right	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-RBF01	Main- Across From Room 213, Retro Fit Bottle Filler, Right	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F03	Main- Across From Room 213, Right Fountain	Flush180	04-OCT-16	0.947	ppb
51580	51580-2-HAL-F03	Main- Across From Room 213, Right Fountain	Flush180	04-OCT-16	0.797	ppb
51580	51580-2-HAL-	Main- Across From Room 213,	Flush180	04-OCT-16	0.794	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F03	Right Fountain				
51580	51580-2-HAL-F03	Main- Across From Room 213, Right Fountain	Flush180	04-OCT-16	0.851	ppb
51580	51580-2-HAL-F03	Main- Across From Room 213, Right Fountain	Initial	04-OCT-16	0.712	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush	02-FEB-2024	1.510	ug/L
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush	02-FEB-2024	1.530	ug/L
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush	02-FEB-2024	1.500	ug/L
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush	02-FEB-2024	1.290	ug/L
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush180	04-OCT-16	0.734	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush180	04-OCT-16	0.613	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush180	04-OCT-16	0.701	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Flush180	04-OCT-16	0.762	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Initial	04-OCT-16	0.441	ppb
51580	51580-2-HAL-F02	Main- Across From Room 221, Left Fountain	Initial	02-FEB-2024	2.230	ug/L
51580	51580-2-HAL-F01	Main- Across From Room 221, Right Fountain	Flush180	04-OCT-16	1.210	ppb
51580	51580-2-HAL-F01	Main- Across From Room 221, Right Fountain	Flush180	04-OCT-16	1.200	ppb
51580	51580-2-HAL-F01	Main- Across From Room 221, Right Fountain	Flush180	04-OCT-16	1.290	ppb
51580	51580-2-HAL-F01	Main- Across From Room 221, Right Fountain	Flush180	04-OCT-16	1.380	ppb
51580	51580-2-HAL-F01	Main- Across From Room 221, Right Fountain	Initial	04-OCT-16	1.120	ppb
51580	51580-2-HAL-F07	Main- Across From Room 225, Fountain	Flush180	04-OCT-16	2.450	ppb
51580	51580-2-HAL-F07	Main- Across From Room 225, Fountain	Flush180	04-OCT-16	13.900	ppb
51580	51580-2-HAL-F07	Main- Across From Room 225, Fountain	Flush180	04-OCT-16	2.910	ppb
51580	51580-2-HAL-F07	Main- Across From Room 225, Fountain	Flush180	04-OCT-16	2.680	ppb
51580	51580-2-HAL-F07	Main- Across From Room 225, Fountain	Initial	04-OCT-16	3.360	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush180	04-OCT-16	1.110	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush180	04-OCT-16	0.968	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush180	04-OCT-16	1.380	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Flush180	04-OCT-16	0.645	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Initial	04-OCT-16	1.150	ppb
51580	51580-2-HAL-F11	Main- Across From Room 246, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush180	04-OCT-16	0.715	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush180	04-OCT-16	0.774	ppb
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush180	04-OCT-16	1.450	ppb
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Flush180	04-OCT-16	0.862	ppb
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Initial	04-OCT-16	1.820	ppb
51580	51580-2-HAL-F10	Main- Across From Room 246, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F09	Main- Across From Room 254, Left Fountain	Flush180	04-OCT-16	1.040	ppb
51580	51580-2-HAL-F09	Main- Across From Room 254, Left Fountain	Flush180	04-OCT-16	1.060	ppb
51580	51580-2-HAL-F09	Main- Across From Room 254, Left Fountain	Flush180	04-OCT-16	1.270	ppb
51580	51580-2-HAL-F09	Main- Across From Room 254, Left Fountain	Flush180	04-OCT-16	2.060	ppb
51580	51580-2-HAL-F09	Main- Across From Room 254, Left Fountain	Initial	04-OCT-16	2.110	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush180	04-OCT-16	1.170	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush180	04-OCT-16	1.110	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush180	04-OCT-16	1.540	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush180	04-OCT-16	2.490	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Flush180	17-DEC-20	2.860	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Initial	04-OCT-16	4.440	ppb
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Initial	17-DEC-20	4.190	ug/L
51580	51580-2-HAL-F08	Main- Across From Room 254, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F04	Main- Across From Room 313, Left Fountain	Flush180	04-OCT-16	0.775	ppb
51580	51580-3-HAL-F04	Main- Across From Room 313, Left Fountain	Flush180	04-OCT-16	0.622	ppb
51580	51580-3-HAL-F04	Main- Across From Room 313, Left Fountain	Flush180	04-OCT-16	0.989	ppb
51580	51580-3-HAL-F04	Main- Across From Room 313, Left Fountain	Flush180	04-OCT-16	0.723	ppb
51580	51580-3-HAL-F04	Main- Across From Room 313, Left Fountain	Initial	04-OCT-16	0.679	ppb
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	21-NOV-2023	1.850	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	21-NOV-2023	1.630	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	21-NOV-2023	1.710	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	21-NOV-2023	1.780	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Initial	21-NOV-2023	1.600	ug/L
51580	51580-3-HAL-F11	Main- Across From Room 313, Left Fountain	Initial	02-FEB-2024	1.000	ug/L







Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F09	Left Fountain				
51580	51580-3-HAL-F09	Main- Across From Room 321, Left Fountain	Initial	21-NOV-2023	1.000	ug/L
51580	51580-3-HAL-F09	Main- Across From Room 321, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	21-NOV-2023	1.470	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	21-NOV-2023	1.400	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	21-NOV-2023	1.390	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	21-NOV-2023	1.350	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Initial	21-NOV-2023	1.460	ug/L
51580	51580-3-HAL-BF01	Main- Across From Room 321, Right Bottle Filler	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F01	Main- Across From Room 321, Right Fountain	Flush180	04-OCT-16	0.964	ppb
51580	51580-3-HAL-F01	Main- Across From Room 321, Right Fountain	Flush180	04-OCT-16	1.750	ppb
51580	51580-3-HAL-F01	Main- Across From Room 321, Right Fountain	Flush180	04-OCT-16	0.858	ppb
51580	51580-3-HAL-F01	Main- Across From Room 321, Right Fountain	Flush180	04-OCT-16	0.829	ppb
51580	51580-3-HAL-F01	Main- Across From Room 321, Right Fountain	Initial	04-OCT-16	1.980	ppb
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	21-NOV-2023	1.350	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	21-NOV-2023	1.400	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	21-NOV-2023	1.380	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	21-NOV-2023	1.410	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Initial	21-NOV-2023	1.290	ug/L
51580	51580-3-HAL-F10	Main- Across From Room 321, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.500	ppb
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.090	ppb
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.000	ppb
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Flush180	04-OCT-16	1.030	ppb
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Initial	04-OCT-16	1.400	ppb
51580	51580-3-HAL-F08	Main- Across From Room 346, Left Fountain	Initial	02-FEB-2024	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F08	Left Fountain				
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.780	ppb
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	0.919	ppb
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.580	ppb
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Flush180	04-OCT-16	1.720	ppb
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Initial	04-OCT-16	0.804	ppb
51580	51580-3-HAL-F07	Main- Across From Room 346, Right Fountain	Initial	02-FEB-2024	1.850	ug/L
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush180	04-OCT-16	1.080	ppb
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush180	04-OCT-16	0.957	ppb
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush180	04-OCT-16	0.970	ppb
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Flush180	04-OCT-16	0.985	ppb
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Initial	04-OCT-16	0.906	ppb
51580	51580-3-HAL-F06	Main- Across From Room 354, Left Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush	02-FEB-2024	1.000	ug/L
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush180	04-OCT-16	1.100	ppb
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush180	04-OCT-16	1.210	ppb
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush180	04-OCT-16	1.170	ppb
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Flush180	04-OCT-16	1.100	ppb
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Initial	04-OCT-16	1.240	ppb
51580	51580-3-HAL-F05	Main- Across From Room 354, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-CAF-F13	Main- Cafeteria, East Wall, Fountain	Flush180	04-OCT-16	0.974	ppb
51580	51580-2-CAF-F13	Main- Cafeteria, East Wall, Fountain	Flush180	04-OCT-16	1.060	ppb
51580	51580-2-CAF-F13	Main- Cafeteria, East Wall, Fountain	Flush180	04-OCT-16	1.110	ppb
51580	51580-2-CAF-F13	Main- Cafeteria, East Wall, Fountain	Flush180	04-OCT-16	0.910	ppb
51580	51580-2-CAF-F13	Main- Cafeteria, East Wall, Fountain	Initial	04-OCT-16	0.776	ppb
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush	02-FEB-2024	1.900	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush	02-FEB-2024	2.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush	02-FEB-2024	1.950	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush	02-FEB-2024	2.200	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	18-AUG-23	5.530	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	18-AUG-23	11.300	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	18-AUG-23	3.720	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	18-AUG-23	24.300	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	22-SEP-23	1.720	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	22-SEP-23	1.010	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Initial	18-AUG-23	3.190	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Initial	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF01	Music Room 342, Left Bottle Filler	Initial	02-FEB-2024	3.490	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush	02-FEB-2024	1.390	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush	02-FEB-2024	1.410	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush	02-FEB-2024	1.380	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush	02-FEB-2024	1.320	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush180	18-AUG-23	2.090	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush180	18-AUG-23	1.840	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush180	18-AUG-23	1.910	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Flush180	18-AUG-23	2.010	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Initial	18-AUG-23	3.290	ug/L
51580	51580-3-342-F01	Music Room 342, Left Fountain	Initial	02-FEB-2024	1.360	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush	02-FEB-2024	2.420	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush	02-FEB-2024	2.590	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush	02-FEB-2024	2.710	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush	02-FEB-2024	2.830	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	18-AUG-23	2.070	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	18-AUG-23	1.870	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	18-AUG-23	5.300	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	18-AUG-23	2.020	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	22-SEP-23	1.270	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Initial	18-AUG-23	1.700	ug/L
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Initial	22-SEP-23	2.060	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51580	51580-3-342-BF02	Music Room 342, Right Bottle Filler	Initial	02-FEB-2024	2.220	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush	02-FEB-2024	1.750	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush	02-FEB-2024	1.860	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush	02-FEB-2024	1.920	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush	02-FEB-2024	1.540	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	18-AUG-23	12.600	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	18-AUG-23	3.480	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	18-AUG-23	1.780	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	18-AUG-23	1.700	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Flush180	22-SEP-23	1.000	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Initial	18-AUG-23	1.990	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Initial	22-SEP-23	1.000	ug/L
51580	51580-3-342-F02	Music Room 342, Right Fountain	Initial	02-FEB-2024	1.000	ug/L
51580	51580-2-E-CAF-F01	Second floor cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-CAF-F01	Second floor cafeteria, east wall	Flush180	09-MAY-19	1.260	ug/L
51580	51580-2-E-CAF-F01	Second floor cafeteria, east wall	Flush180	09-MAY-19	1.390	ug/L
51580	51580-2-E-CAF-F01	Second floor cafeteria, east wall	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-CAF-F01	Second floor cafeteria, east wall	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS02	Second floor kitchen, east faucet	Flush180	09-MAY-19	3.170	ug/L
51580	51580-2-N-KIT-KS02	Second floor kitchen, east faucet	Flush180	09-MAY-19	1.040	ug/L
51580	51580-2-N-KIT-KS02	Second floor kitchen, east faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS02	Second floor kitchen, east faucet	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS02	Second floor kitchen, east faucet	Initial	09-MAY-19	2.060	ug/L
51580	51580-2-N-KIT-KS01	Second floor kitchen, west sink	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS01	Second floor kitchen, west sink	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS01	Second floor kitchen, west sink	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS01	Second floor kitchen, west sink	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-N-KIT-KS01	Second floor kitchen, west sink	Initial	09-MAY-19	2.440	ug/L
51580	51580-2-E-HAL-F09	Second floor, across from 254	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F09	Second floor, across from 254	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F09	Second floor, across from 254	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F09	Second floor, across from 254	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F09	Second floor, across from 254	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F08	Second floor, across from 254, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-	Second floor, across from 254,	Flush180	09-MAY-19	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F08	right fountain (south)				
51580	51580-2-E-HAL-F08	Second floor, across from 254, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F08	Second floor, across from 254, right fountain (south)	Flush180	09-MAY-19	1.000	ug/L
51580	51580-2-E-HAL-F08	Second floor, across from 254, right fountain (south)	Initial	09-MAY-19	1.000	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	09-MAY-19	2.500	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	09-MAY-19	2.200	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	09-MAY-19	2.060	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	09-MAY-19	2.020	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	15-APR-20	2.360	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	15-APR-20	2.630	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	15-APR-20	2.800	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Flush180	15-APR-20	3.140	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Initial	09-MAY-19	7.730	ug/L
51580	51580-2-N-GYM-F01	Second floor, gymnasium, north wall	Initial	15-APR-20	2.180	ug/L